



Status Report

FALCON 900B

S/N 091 N900KU

OWNER: IAL CORPORATION
ADDRESS: 16192 COASTAL HIGHWAY
LEWES DE 19958
OFFICE: 7858784000
FAX:

OPERATOR: IAL CORPORATION
ADDRESS: 16192 COASTAL HIGHWAY
LEWES DE 19958
OFFICE: 7858784000
FAX:

OPERATOR: IAL AIRCRAFT SALES
ADDRESS: 3511 SILVERSIDE ROAD
WILMINGTON DE 19810
OFFICE: 302-319-5563
FAX:

ANALYST: PAUL GILMAN
EMAIL: PGILMAN@CAMPSYSTEMS.COM

631-619-4594 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL / REGNO: 091/N900KU	MODEL: FALCON 900B	MANUFACTURER: DASSAULT AVIATION S.A.
CERTIFICATION DATE: 07-FEB-1991		LAST ACTUALS:	
		13896.3 A/C HRS	as of 27-MAR-2026
		7313 AFL	as of 27-MAR-2026
		6828.3 APH	as of 03-MAR-2026
APU	SERIAL / PART: P-125/3800188-2	MODEL: GTCP36-150(F)	MANUFACTURER: HONEYWELL
INSTALLED ON: 11-MAR-2006		LAST ACTUALS:	
3938 APU HRS 9207.9 A/C HRS		6757.3 APU HRS	as of 03-MAR-2026
0 APUS		0 APUS	as of 09-FEB-2015
ENGINE NO. 1	SERIAL / PART: P-98117C/3075370-2	MODEL: TFE731-5BR-2C	MANUFACTURER: HONEYWELL
INSTALLED ON: 04-OCT-2021		LAST ACTUALS:	
10373.1 ENG. HRS 13272.28 A/C HRS		10997.12 ENG. HRS	as of 27-MAR-2026
7792 ENC		8369 ENC	as of 27-MAR-2026
ENGINE NO. 2	SERIAL / PART: P-98124/3075370-2	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 04-OCT-2021		LAST ACTUALS:	
8048.1 ENG. HRS 13272.28 A/C HRS		8672.12 ENG. HRS	as of 27-MAR-2026
6859 ENC		7434 ENC	as of 27-MAR-2026
ENGINE NO. 3	SERIAL / PART: P-97343C/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 20-OCT-2021		LAST ACTUALS:	
11835.7 ENG. HRS 13272.28 A/C HRS		12459.72 ENG. HRS	as of 27-MAR-2026
5631 ENC		6206 ENC	as of 27-MAR-2026



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
6892-130901-L	- INFORMATION TO FALCON 900 / FALCON 900B OPERATOR							Service ATA:00
	MOS/MSC	EFF	-					INFORMATIONAL
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-150414-1	REVIEW DASSAULT AVIATION FALCON 900B MM CHAPTER 5-40 REVISION 21, DATED JANUARY 2015 - REQUIREMENT CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-150414-2	REVIEW DASSAULT AVIATION FALCON 900B MPD REVISION 5, DATED JANUARY 2015 - REQUIREMENT CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-150706	REVIEW FALCON 900 B SMM REV H & I - SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	28-Sep-15	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-151202	REVIEW FALCON 900B SMM REV J - SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	21-Jan-16	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
6892-160628-1	REVIEW DASSAULT AVIATION FALCON 900B MAINTENANCE MANUAL CHAPTER 5-40 REVISION 22 DATED DECEMBER 2015 - SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-160628-2	REVIEW DASSAULT AVIATION MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 6 DATED DECEMBER 2015 - SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-161220	REVIEW MPD CHAPTER 5 REVISION 7							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: AMM GENERIC 2, RCF 6892PROC. REF: AMM GENERIC 2, RCF 6892								
6892-170901	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 8-01 DATED SEPTEMBER 2017							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-170901A	REVIEW FALCON 900B MAINTENANCE MANUAL 5-40 REVISION 23 - SEPTEMBER 2017							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
6892-170901L	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 8-01 DATED SEPTEMBER 2017 (MPD EXTENSION) INCLUDED 5-40 REV 23							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892, RCF 6892								
6892-180205	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) DOCUMENT DISCREPANCY (DD) 1-309445121							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-180322	REVIEW DOCUMENT DISCREPANCIES 1-307191003 AND 1-303915014							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-180405	REVIEW FALCON 900 MPD DOCUMENT DISCREPANCY 1-310597778 CHANGES							Service ATA:00
	MOS/MSC	EFF	-					
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-180406	REVIEW FALCON 900B MPD DOCUMENT DISCREPANCY 1-311875774							Service ATA:00
	MOS/MSC	EFF	-					
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
6892-180901A	REVIEW MAINTENANCE MANUAL CHAPTER 5-40-00 AIRWORTHINESS LIMITATIONS REVISION 24 DATED SEPTEMBER 2018							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-190902	REVIEW MAINTENANCE PLANNING DOCUMENT (MPD) REVISION 10 - SEPTEMBER 2019							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-190902A	REVIEW MAINTENANCE MANUAL CHAPTER 5-40 REVISION 25 - SEPTEMBER 2019							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
6892-STORAGE	REVIEW STORAGE / RETURN TO SERVICE OF AIRCRAFT REQUIREMENTS							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 6892PROC. REF: RCF 6892								
A009-161102	APU - REVIEW SIL APU-56 REV 2							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF A009PROC. REF: RCF A009								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
A009-170112	APU - REVIEW GTPC36-150 (F) MM TR 49-40							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF A009PROC. REF: RCF A009								
A009-170607	APU - REVIEW GTCP36-150(F) MM REV 7							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF A009PROC. REF: RCF A009								
A009-171115	APU - REVIEW GTCP-150(F) EMM TR 49-42							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF A009PROC. REF: RCF A009								
A009-180112	APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF APU-SIL-49PROC. REF: RCF APU-SIL-49								
A009-190906	APU - REVIEW GTCP-150(F) EMM TR 49-43							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF A009PROC. REF: RCF A009								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
A009-200326	APU - REVIEW GTCP36-150(F) EMM TR 49-44							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF A009PROC. REF: RCF A009								
A009-200504	APU - REVIEW GTCP36-150(F) MM REV 8							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	APUS							
PROC. REF: RCF A009PROC. REF: RCF A009								
E006-170614 ^S	NO. 1 ENGINE - REVIEW TR 72-234							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006-170614PROC. REF: RCF E006-170614								
E006-170919 ^S	NO. 1 ENGINE - REVIEW TFE731-5BR LMM TR 72-232							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-170919	NO. 3 ENGINE - REVIEW TFE731-5BR LMM TR 72-232							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E006-170921	^S	NO. 1 ENGINE - REVIEW SB TFE731-72-3263 REV 16						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-170921		NO. 3 ENGINE - REVIEW SB TFE731-72-3263 REV 16						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-180801	^S	NO. 1 ENGINE - REVIEW TR 72-233						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-180828	^S	NO. 1 ENGINE - REVIEW SB TFE731-72-3263 REV 17						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-190130	^S	NO. 1 ENGINE - REVIEW SB TFE731-72-3236 REV 18						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E006-190218	^S	NO. 1 ENGINE - REVIEW TR 79-10						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-191029	^S	NO. 1 ENGINE - REVIEW TR 72-235						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-191029		NO. 3 ENGINE - REVIEW TR 72-235						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-201005		NO. 3 ENGINE - REVIEW TFE731-5BR LMM TR 72-238						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
E006-201102		NO. 3 ENGINE - REVIEW TFE731-5BR LMM TR 72-237						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E006-201102-1	NO. 3 ENGINE - REVIEW TFE731-5BR LMM TR 79-11							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF E006PROC. REF: RCF E006								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-00	INTERMEDIATE INSPECTION							Package ATA:05
	MOS/MSC		N/A					
	HRS							
	AFL							
	APH							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-08-00-200-800-05	12 M/800 FH INSPECTION							Package ATA:05
	MOS	17-Feb-26	12 (+1m)	Adj -70d	09-Dec-26	09-Jan-27	229 d (+31)	
	HRS	13885.3	800 (+40)		14685.3	14725.3	789 (+40)	
	AFL	7304						
								PKG:5
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-08-00-200-800-06	24 M/1600 FH INSPECTION							Package ATA:05
	MOS	17-Feb-26	24 (+1m)		17-Feb-28	17-Mar-28	664 d (+29)	
	HRS	13885.3	1600 (+40)		15485.3	15525.3	1589 (+40)	
	AFL	7304						
								PKG:6
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-08-00-200-800-07	36 M/2400 FH INSPECTION							Package ATA:05
	MOS	22-Dec-23	36 (+1m)		22-Dec-26	22-Jan-27	242 d (+31)	
	HRS	13641	2400 (+40)		16041	16081	2144.7 (+40)	
	AFL	7052						
								PKG:7
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-15	12 M INSPECTION							Package ATA:05
	MOS	17-Feb-26	12 (+1m)		17-Feb-27	17-Mar-27	299 d (+28)	
	HRS	13885.3						
	AFL	7304						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
05-08-00-200-800-16	24 M INSPECTION							Package ATA:05
	MOS	17-Feb-26	24 (+1m)		17-Feb-28	17-Mar-28	664 d (+29)	
	HRS	13885.3						
	AFL	7304						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
05-08-00-200-800-17	36 M INSPECTION							Package ATA:05
	MOS	22-Dec-23	36 (+1m)		22-Dec-26	22-Jan-27	242 d (+31)	
	HRS	13641						
	AFL	7052						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17
05-08-00-200-800-21	1B INSPECTION							Package ATA:05
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)		14875.5	14915.5	979.2 (+40)	
	AFL	6741						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
05-08-00-200-800-22	2B INSPECTION							Package ATA:05
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)		16475.5	16515.5	2579.2 (+40)	
	AFL	6741						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-23	3B INSPECTION							Package ATA:05
	MOS	22-Nov-07						
	HRS	10138.1	4800 (+40)		14938.1	14978.1	1041.8 (+40)	
	AFL	5422						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
05-08-00-200-800-31	1C INSPECTION							Package ATA:05
	MOS	19-Dec-21	72 (+2m)		19-Dec-27	19-Feb-28	604 d (+62)	
	HRS	13275.5						
	AFL	6741	3750		10491		3178	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:31
05-08-00-200-800-32	2C INSPECTION							Package ATA:05
	MOS	19-Dec-21	144 (+2m)		19-Dec-33	19-Feb-34	2796 d (+62)	
	HRS	13275.5						
	AFL	6741	7500		14241		6928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:32
05-08-00-200-800-33	3C INSPECTION							Package ATA:05
	MOS/MSC	12-Jun-09	N/A					
	HRS	10850.2						
	AFL	5878						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:33
05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 24.270	AFL	0						
PROC. REF: AMM 05-50-00-100-801PROC. REF: AMM 05-50-00-100-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-200-801-01		CHECK AFTER A TOWING INCIDENT						Service ATA:05
	MOS/MSC	26-Jun-09	A/R					
	HRS	10850.2						
WC#: 09.010	AFL	5878						
PROC. REF: AMM 05-50-00-200-801PROC. REF: AMM 05-50-00-200-801								
05-50-00-200-802-01		CHECK AFTER HAILSTORM						Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 51.110	AFL	0						
PROC. REF: AMM 05-50-00-200-802PROC. REF: AMM 05-50-00-200-802								
05-50-00-200-803-01		CHECK AFTER A LIGHTNING STRIKE						Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 51.100	AFL	0						
PROC. REF: AMM 05-50-00-200-803PROC. REF: AMM 05-50-00-200-803								
05-50-00-200-804-01		CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING						Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 32.880	AFL	0						
PROC. REF: AMM 05-50-00-200-804PROC. REF: AMM 05-50-00-200-804								
05-50-00-200-805-01		CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE						Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 51.120	AFL	0						
PROC. REF: AMM 05-50-00-200-805PROC. REF: AMM 05-50-00-200-805								
05-50-00-200-806-01		CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS						Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-806PROC. REF: AMM 05-50-00-200-806								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-200-809-01	INSPECTION AFTER SLAT OPERATION IN OVERSPEED CONDITION							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 57.305	AFL	0						
	APH	0						
PROC. REF: AMM 05-50-00-200-809PROC. REF: AMM 05-50-00-200-809								
05-50-00-200-810-01	INSPECTION AFTER FLAP OPERATION IN OVERSPEED CONDITION							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 57.310	AFL	0						
	APH	0						
PROC. REF: AMM 05-50-00-200-810PROC. REF: AMM 05-50-00-200-810								
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-812PROC. REF: AMM 05-50-00-200-812								
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING - CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE.							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-813PROC. REF: AMM 05-50-00-200-813								
05-50-00-200-817-01	CHECK AFTER COLLISION WITH FOREIGN OBJECT							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-817PROC. REF: AMM 05-50-00-200-817								
05-50-00-200-822-01	OPERATION TO BE PERFORMED AFTER VMO/MMO EXCEEDANCE							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
PROC. REF: AMM 05-50-00-200-822PROC. REF: AMM 05-50-00-200-822								
05-50-00-200-823-01	CHECK OF THE SLATS AFTER OVERHEATING - LH WING							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-823PROC. REF: AMM 05-50-00-200-823								
05-50-00-200-823-02	CHECK OF THE SLATS AFTER OVERHEATING - RH WING							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-823PROC. REF: AMM 05-50-00-200-823								
05-50-00-620-801-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-620-801PROC. REF: AMM 05-50-00-620-801								
05-50-00-620-803-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 05.020	AFL	0						
PROC. REF: AMM 05-50-00-620-803PROC. REF: AMM 05-50-00-620-803								
05-50-00-620-804-01	PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 51.130	AFL	0						
PROC. REF: AMM 05-50-00-620-804PROC. REF: AMM 05-50-00-620-804								
05-50-00-620-805-02	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
PROC. REF: AMM 05-50-00-620-805PROC. REF: AMM 05-50-00-620-805								
05-50-00-700-801-01CHECK AND DECONTAMINATION OF THE AIR CONDITIONING SYSTEM AFTER POLLUTION								Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 05-50-00-700-801PROC. REF: AMM 05-50-00-700-801								
05-50-00-700-803-01CHECK AFTER FIRE EXTINGUISHER PERCUSSION								Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 20.050	AFL	0						
PROC. REF: SL 20-350, AMM 05-50-00-700-803PROC. REF: SL 20-350, AMM 05-50-00-700-803								
05-50-00-700-806-01CHECK AFTER LANDING ON A TAR-MACADAM RUNWAY IN VERY HOT WEATHER								Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 05-50-00-700-806PROC. REF: AMM 05-50-00-700-806								
05-50-00-700-807-01CHECK AFTER LANDING ON A DRY AND DIRTY RUNWAY								Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 32.850	AFL	0						
PROC. REF: AMM 05-50-00-700-807PROC. REF: AMM 05-50-00-700-807								
05-50-00-700-808-01CHECK AFTER HARD / OVERWEIGHT LANDING								Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 32.840	AFL	0						
PROC. REF: AMM 05-50-00-700-808PROC. REF: AMM 05-50-00-700-808								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-700-810-01	CHECK AFTER SAND CONDITION - CHECKS AFTER EACH FLIGHT THROUGH SAND							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-810PROC. REF: AMM 05-50-00-700-810								
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-818PROC. REF: AMM 05-50-00-700-818								
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-822PROC. REF: AMM 05-50-00-700-822								
05-50-00-730-801-01	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - FILTER CLOGGING							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 29.290	AFL	0						
PROC. REF: AMM 05-50-00-730-801PROC. REF: AMM 05-50-00-730-801								
05-50-00-730-801-02	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - PUMP FAILURE							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 29.300	AFL	0						
PROC. REF: AMM 05-50-00-730-801PROC. REF: AMM 05-50-00-730-801								
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-730-802PROC. REF: AMM 05-50-00-730-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-860-801-01	CHECK AND PREPARATION FOR FLIGHT WITH ONE ENGINE INOPERATIVE							Service ATA:05
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-860-801PROC. REF: AMM 05-50-00-860-801								
05-50-00-910-801-01	AIRCRAFT CHECK FLIGHT							Service ATA:05
	MOS	22-Dec-23	72 (+2m)		22-Dec-29 (M)	22-Feb-30	1338 d (+62)	
	HRS	13641						
WC#: 51.070	AFL	7052	3750		10802 (M)		3489	
PROC. REF: AMM 05-50-00-910-801PROC. REF: AMM 05-50-00-910-801								
05-60-00-200-801-01	BASIC INSPECTION							Service ATA:05
	MOS	11-Dec-25	12 (+1m)	Adj -2d	09-Dec-26	09-Jan-27	229 d (+31)	
	HRS	13869.7	400 (+40)		14269.7	14309.7	373.4 (+40)	
WC#: 05.010	AFL	7285						
PROC. REF: AMM 05-60-00-200-801PROC. REF: AMM 05-60-00-200-801								
05-60-00-200-801-03	BASIC INSPECTION - GROUND SERVICING CHECKS							Service ATA:05
	MOS	11-Dec-25	12 (+1m)	Adj -2d	09-Dec-26	09-Jan-27	229 d (+31)	
	HRS	13869.7	400 (+40)		14269.7	14309.7	373.4 (+40)	
WC#: 05.010	AFL	7285						
PROC. REF: AMM 05-60-00-200-801PROC. REF: AMM 05-60-00-200-801								
057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION							Package ATA:05
	MOS	06-May-25						
	HRS	10937.02	250		(11187.02) 14086.2		189.9	
	ENC	8305						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								

PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057110	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION							Package ATA:05
	MOS	12-May-25						
	HRS	8612.02	150 (+100)		(8762.02) 13986.2	8862.02	89.9 (+100)	
	ENC	7370						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:1
057110	NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION							Package ATA:05
	MOS	12-May-25						
	HRS	12399.62	150 (+100)		(12549.62) 13986.2	12649.62	89.9 (+100)	
	ENC	6142						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:1
057120	NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION							Package ATA:05
	MOS	01-Mar-24						
	HRS	10773.12	400		(11173.12) 14072.3		176	
	ENC	8131						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:2
057120 ^U	NO. 1 NO.1 ENGINE 300/400 HOUR INSPECTION							Package ATA:05
	MOS	01-Mar-24						
	HRS	13672.3	400		14072.3		176	
	AFL	7075						
								PKG:42
057120	NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION							Package ATA:05
	MOS	12-May-25						
	HRS	8612.02	300 (+100)		(8912.02) 14136.2	9012.02	239.9 (+100)	
	ENC	7370						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057120 ^U	NO. 2 NO.2 ENGINE 300/400 HOUR INSPECTION							Package ATA:05
	MOS	01-Mar-24						
	HRS	13672.3	400	Adj -11.82	14060.48		164.2	
	AFL	7075						
								PKG:52
057120	NO. 3 ENGINE - 300 TO 400 HOUR INSPECTION							Package ATA:05
	MOS	02-Oct-23						
	HRS	12155.92	300 (+100)		(12455.92) 13892.5	12555.92	TOL (+96.2)	
	ENC	5896						
								PKG:2
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								
057120 ^U	NO. 3 NO.3 ENGINE 300/400 HOUR INSPECTION							Package ATA:05
	MOS	02-Oct-23						
	HRS	13592.5	400		13992.5		96.2	
	AFL							
								PKG:62
057140	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION							Package ATA:05
	MOS	11-Jan-21						
	HRS	10373.1	800 (+50)		(11173.1) 14072.28	11223.1	176 (+50)	
	ENC	7792						
								PKG:4
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								
057140	NO. 3 ENGINE - 500 TO 850 HOUR INSPECTION							Package ATA:05
	MOS	20-Jan-15						
	HRS	11672.88	800 (+50)		(12472.88) 13909.47	12522.88	13.2 (+50)	
	ENC	5594						
								PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								
057160	NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION							Package ATA:05
	MOS	11-Jan-21						
	HRS	10373.1	1400		(11773.1) 14672.28		776	
	ENC	7792						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								
057160	NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION							Package ATA:05
	MOS	16-Apr-19						
	HRS	8019.8	1200 (+200)		(9219.8) 14443.98	9419.8	547.7 (+200)	
	ENC	6841						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:3
057160	NO. 3 ENGINE - 1000 TO 1400 HOUR INSPECTION							Package ATA:05
	MOS	20-Jan-15						
	HRS	11672.88	1200 (+200)		(12872.88) 14309.47	13072.88	413.2 (+200)	
	ENC	5594						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								
057170	NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package ATA:05
	MOS	11-Jan-21						
	HRS	10373.1	1600 (+50)		(11973.1) 14872.28	12023.1	976 (+50)	
	ENC	7792						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057170	NO. 3 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package ATA:05
	MOS	20-Jan-15						
	HRS	11672.88	1600 (+50)		(13272.88) 14709.47	13322.88	813.2 (+50)	
	ENC	5594						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:5
ATA 09 - TOWING AND TAXING								
09-10-00-910-810-01	DEBOGGING THE AIRCRAFT							Service ATA:09
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 09-10-00-910-810PROC. REF: AMM 09-10-00-910-810								
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS							Service ATA:10
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 10-10-00-200-801PROC. REF: AMM 10-10-00-200-801								
10-10-00-550-801-10	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - NON-FLYING AND NON-STORED PERIOD							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								
10-10-00-550-801-11	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 2 MONTHS							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.090	AFL	0						
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10-00-550-801-12	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - ADDITIONAL OPERATIONS FOR STORAGE FROM 2 TO 12 MONTHS							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.090	AFL	0						
	APH	0						
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								
10-10-00-550-801-14	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY MONTH							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.090	AFL	0						
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								
10-10-00-550-801-15	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 2 MONTHS							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.090	AFL	0						
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								
10-10-00-550-801-16	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 6 MONTHS							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.090	AFL	0						
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								
10-10-00-550-801-17	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AT THE END OF THE 2 MONTHS OR LESS							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.090	AFL	0						
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								
10-10-00-550-801-18	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AFTER MORE THAN 2 MONTHS							Service ATA:10
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.090	AFL	0						
	APH	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
PROC. REF: AMM 10-10-00-550-801PROC. REF: AMM 10-10-00-550-801								
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL							Service ATA:10
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 10.010	AFL	0						
PROC. REF: AMM 10-20-00-910-802PROC. REF: AMM 10-20-00-910-802								
ATA 11 - PLACARDS AND MARKINGS								
11-00-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE INTERNAL AND EXTERNAL MARKINGS AND PLACARDS							Service ATA:11
	MOS	22-Dec-23	72 (+2m)					SMM
	HRS	13641						
	AFL	7052	3750					
PKG:31								
PROC. REF: AMM 11-00-00-210-801PROC. REF: AMM 11-00-00-210-801								
ATA 20 - STANDARD PRACTICES - AIRFRAME								
20-00-00-910-801-01	GENERAL MAINTENANCE AND SAFETY PRECAUTIONS							Service ATA:20
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 20.000	AFL	0						
PROC. REF: AMM 20-00-00-910-801PROC. REF: AMM 20-00-00-910-801								
20-00-00-910-803-01	USE OF THE AIRCRAFT MAINTENANCE PROCEDURES							Service ATA:20
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 20-00-00-910-803PROC. REF: AMM 20-00-00-910-803								
20-00-00-910-805-01	MAINTENANCE INSTRUCTION SPECIFIC TO S/N 1							Service ATA:20
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 20.030	AFL	0						
PROC. REF: AMM 20-00-00-910-805PROC. REF: AMM 20-00-00-910-805								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
20-00-00-910-806-01	MAINTENANCE INSTRUCTION SPECIFIC TO S/N 2							Service ATA:20
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 20.040	AFL	0						
PROC. REF: AMM 20-00-00-910-806PROC. REF: AMM 20-00-00-910-806								
20-30-00-330-801-01	TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT							Service ATA:20
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 51.090	AFL	0						
PROC. REF: AMM 20-30-00-330-801PROC. REF: AMM 20-30-00-330-801								
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.060	AFL	0						
	APH	0						
PROC. REF: SL 20-318, AMM 20-31-00-140-801PROC. REF: SL 20-318, AMM 20-31-00-140-801								
20-31-00-910-801-01	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - DE-ICING TREATMENT							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 20.070	AFL	0						
	APH	0						
PROC. REF: SL 20-625, AMM 20-31-00-910-801PROC. REF: SL 20-625, AMM 20-31-00-910-801								
20-33-00-300-804-01	TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS							Service ATA:20
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 20-33-00-300-804PROC. REF: AMM 20-33-00-300-804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
20-41-00-910-801-01	TIGHTENING TORQUES FOR SINGLE FLARE COUPLINGS							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-41-00-910-801PROC. REF: AMM 20-41-00-910-801								
20-60-00-370-813-01	APPLICATION OF THE PAINT SCHEME ON COMPOSITE COMPONENTS							Service ATA:20
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 20.080	AFL	0						
	APH	0						
PROC. REF: SL 20-615, AMM 20-60-00-370-813PROC. REF: SL 20-615, AMM 20-60-00-370-813								
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (L2GF)							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-60-00-370-816PROC. REF: AMM 20-60-00-370-816								
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (R2GF)							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-60-00-370-816PROC. REF: AMM 20-60-00-370-816								
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (L2GF5)							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-60-00-370-816PROC. REF: AMM 20-60-00-370-816								
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (R2GF5)							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-60-00-370-816PROC. REF: AMM 20-60-00-370-816								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (3GF)							Service ATA:20
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-60-00-370-816PROC. REF: AMM 20-60-00-370-816								
ATA 21 - AIR CONDITIONING								
21-20-00-900-801-01	REMOVAL / INSTALLATION OF THE CABIN AIR-CONDITIONING ELECTRIC VALVE - CABIN AIR CONDITIONING ELECTRIC VALVE (3HN2)							Component ATA:21
PN:BYLB51003	MOS/MSC	22-Jun-09	O/C	TSR 0				
SN:866	HRS	10851.7		TSR 0				
WC#: 21.140	AFL	5879		TSR 0				
PROC. REF: AMM 21-20-00-900-801PROC. REF: AMM 21-20-00-900-801								
21-20-01-350-801-01	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - LH FLOW LIMITER (L501HN)							Service ATA:21
PN:2742A020100	MOS	04-May-07					OVERHAUL	
SN:684	HRS	9577.2	4800 (+3%)		14377.2	14521.2	480.9 (+144)	
WC#: 21.020	AFL	5083						
PROC. REF: AMM 21-20-01-350-801PROC. REF: AMM 21-20-01-350-801								
21-20-01-350-801-02	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - RH FLOW LIMITER (R501HN)							Service ATA:21
PN:2742A020100	MOS	04-May-07					OVERHAUL	
SN:683	HRS	9577.2	4800 (+3%)		14377.2	14521.2	480.9 (+144)	
WC#: 21.020	AFL	5083						
PROC. REF: AMM 21-20-01-350-801PROC. REF: AMM 21-20-01-350-801								
21-20-01-900-801-01	REMOVAL / INSTALLATION OF THE FLOW LIMITERS - LH FLOW LIMITER (L501HN)							Component ATA:21
PN:2742A020100	MOS/MSC	04-May-07	O/C	TSO 0				
SN:684	HRS	9577.2		TSO 0				
WC#: 21.020	AFL	5083		TSO 0				
PROC. REF: AMM 21-20-01-900-801PROC. REF: AMM 21-20-01-900-801								
21-20-01-900-801-02	REMOVAL / INSTALLATION OF THE FLOW LIMITERS - RH FLOW LIMITER (R501HN)							Component ATA:21
PN:2742A020100	MOS/MSC	04-May-07	O/C	TSO 0				
SN:683	HRS	9577.2		TSO 0				
WC#: 21.020	AFL	5083		TSO 0				
PROC. REF: AMM 21-20-01-900-801PROC. REF: AMM 21-20-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-22-19-900-801-01		REMOVAL / INSTALLATION OF THE GASPER PRESSURE CONTROL VALVE - GASPER PRESSURE REGULATING VALVE (508HN)						Component ATA:21
PN:B17DA1002	MOS/MSC	14-Nov-99	O/C	TSN 0				
SN:T574	HRS			TSN 0				
WC#: 21.040	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21-28-00-710-801-01 ^S		OPERATIONAL TEST OF THE EFIS VENTILATION SYSTEM						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.175	AFL	6741						
PROC. REF: AMM 21-28-00-710-801PROC. REF: AMM 21-28-00-710-801								
21-30-00-790-802-01 ^S		IN-FLIGHT CHECK OF CABIN SEALING						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.180	AFL	6741						
PROC. REF: AMM 21-30-00-790-802PROC. REF: AMM 21-30-00-790-802								
21-30-01-900-801-01		REMOVAL / INSTALLATION OF THE AUTOMATIC PRESSURIZATION CONTROLLER - AUTOMATIC PRESSURIZATION CONTROLLER (3HP)						Component ATA:21
PN:22250J032100	MOS/MSC	09-Mar-12	O/C					
SN:266	HRS	11749.08						
WC#: 21.280	AFL	6227						
PROC. REF: AMM 21-30-01-900-801PROC. REF: AMM 21-30-01-900-801								
21-30-09-720-801-01		FUNCTIONAL TEST OF THE ALTITUDE ALERT OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (7HP)						Service ATA:21
PN:3311A-J44	MOS	09-Mar-12						
SN:176	HRS	11749.08	4000 (+3%)		15749.08	15869.08	1852.8 (+120)	
WC#: 21.290	AFL	6227						
PROC. REF: AMM 21-30-09-720-801PROC. REF: AMM 21-30-09-720-801								
21-30-09-900-801-01		REMOVAL / INSTALLATION OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (7HP)						Component ATA:21
PN:3311A-J44	MOS/MSC	07-Mar-08	O/C	TSR 0				
SN:176	HRS	10360.3		TSR 0				
WC#: 21.290	AFL	5544		TSR 0				
PROC. REF: AMM 21-30-09-900-801PROC. REF: AMM 21-30-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-00-720-801-01	S	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - PNEUMATIC ACTUATOR (506HP)						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
								PKG:21
PROC. REF: AMM 21-31-00-720-801PROC. REF: AMM 21-31-00-720-801								
21-31-00-720-801-02	S	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - PRESSURE RELIEF VALVE (507HP)						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
								PKG:21
PROC. REF: AMM 21-31-00-720-801PROC. REF: AMM 21-31-00-720-801								
21-31-01-720-801-01	S	FUNCTIONAL TEST OF THE NOSE CONE OVERHEAT INDICATING SYSTEM						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.150	AFL	6741						
								PKG:21
PROC. REF: AMM 21-31-01-720-801PROC. REF: AMM 21-31-01-720-801								
21-31-09-350-801-01		RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS) - NOSE CONE FAN (3HQ)						Service ATA:21
PN:011479502	MOS	25-Mar-10						
SN:C00090680	HRS	10865.5	3240		14105.5		209.2	
	AFL	5891						
PROC. REF: AMM 21-31-09-350-801PROC. REF: AMM 21-31-09-350-801								
21-31-09-350-802-01		RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS AND CHECK OF BRUSHES) - NOSE CONE FAN (3HQ)						Service ATA:21
PN:011479502	MOS/MSC	07-Feb-91	N/A					
SN:C00090680	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 21-31-09-350-802PROC. REF: AMM 21-31-09-350-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-09-710-801-01	OPERATIONAL TEST OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (3HQ)							Service ATA:21
	MOS/MSC	25-Mar-10	O/C					
	HRS	10865.5			TAC 10865.5			
WC#: 21.160	AFL	5891			TAC 5891			
PROC. REF: AMM 21-31-09-710-801PROC. REF: AMM 21-31-09-710-801								
21-31-09-900-801-01	REMOVAL / INSTALLATION OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (3HQ)							Component ATA:21
PN:011479502	MOS/MSC	25-Mar-10	O/C		TSO 9			
SN:C00090680	HRS	10865.5			TSO 0			
WC#: 21.160	AFL	5891			TSO 0			
PROC. REF: AMM 21-31-09-900-801PROC. REF: AMM 21-31-09-900-801								
21-31-25-220-801-01	CHECK / REPLACEMENT OF THE NOSE CONE VENTILATION FAN BRUSHES (TECHNOFAN P/N EVT608A) - NOSE CONE FAN (3HQ)							Service ATA:21
PN:011479502	MOS/MSC	07-Feb-91	N/A					
SN:C00090680	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 21-31-25-220-801PROC. REF: AMM 21-31-25-220-801								
21-32-00-710-801-01 ^S	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM							Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.200	AFL	6741						
PROC. REF: AMM 21-32-00-710-801PROC. REF: AMM 21-32-00-710-801								PKG:21
21-32-00-710-802-01 ^S	OPERATIONAL TEST OF THE PRESSURIZATION SYSTEM EMERGENCY SUPPLY							Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.190	AFL	6741						
PROC. REF: AMM 21-32-00-710-802PROC. REF: AMM 21-32-00-710-802								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-00-790-801-01	^S	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (L13FL)						Service ATA:21
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 21-32-00-790-801PROC. REF: AMM 21-32-00-790-801								PKG:16
21-32-00-790-801-02	^S	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (R13FL)						Service ATA:21
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 21-32-00-790-801PROC. REF: AMM 21-32-00-790-801								PKG:16
21-32-00-790-801-03	^S	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STAND-BY STATIC PRESSURE PROBE (L501FL)						Service ATA:21
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 21-32-00-790-801PROC. REF: AMM 21-32-00-790-801								PKG:16
21-32-00-790-801-04	^S	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STAND-BY STATIC PRESSURE PROBE (R501FL)						Service ATA:21
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 21-32-00-790-801PROC. REF: AMM 21-32-00-790-801								PKG:16
21-32-06-200-801-01		INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF ELECTROPNEUMATIC VALVE (4HP)						Service ATA:21
PN:2097D020700	MOS	21-Mar-16						
SN:167	HRS	13260.48	1640 (+3%)		14900.48	14949.68	1004.2 (+49.2)	
WC#: 21.260	AFL							
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-06-200-801-02		INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF PNEUMATIC VALVE (5HP)						Service ATA:21
PN:2099E010700	MOS	21-Mar-16						
SN:182	HRS	13260.48	1640 (+3%)		14900.48	14949.68	1004.2 (+49.2)	
WC#: 21.270	AFL							
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								
21-32-06-200-801-03		INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF ELECTROPNEUMATIC VALVE (4HP)						Service ATA:21
PN:2097D020700	MOS	21-Mar-16						
SN:167	HRS	13260.48	1640		14900.48		1004.2	
WC#: 21.260	AFL							
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								
21-32-06-200-801-03A		CHECK ELECTROPNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)						Service ATA:21
PN:2097D020700	MOS	21-Mar-16						MANDATORY 5-40
SN:167	HRS	13260.48	1640		14900.48		1004.2	
WC#: 21.260	AFL							
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								
21-32-06-200-801-04		INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF PNEUMATIC VALVE (5HP)						Service ATA:21
PN:2099E010700	MOS	21-Mar-16						
SN:182	HRS	13260.48	1640		14900.48		1004.2	
WC#: 21.270	AFL							
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								
21-32-06-200-801-04A		CHECK PNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)						Service ATA:21
PN:2099E010700	MOS	21-Mar-16						MANDATORY 5-40
SN:182	HRS	13260.48	1640		14900.48		1004.2	
WC#: 21.270	AFL							
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-06-200-801-05	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (975HP) AND (976HP)							Service ATA:21
	MOS	16-Jun-22						
	HRS	13419.3	1640		15059.3		1163	
WC#: 21.530	AFL	6854						
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								
21-32-06-200-801-05A	CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY 5-40)							Service ATA:21
	MOS	16-Jun-22						MANDATORY 5-40
	HRS	13419.3	7500		20919.3		7023	
WC#: 21.530	AFL	6854						
PROC. REF: AMM 21-32-06-200-801PROC. REF: AMM 21-32-06-200-801								
21-32-06-720-801-01	FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - ELECTROPNEUMATIC VALVE (4HP)							Service ATA:21
PN:2097D020700	MOS	07-Jan-12						
SN:167	HRS	11669.92	4840		16509.92		2613.6	
	AFL	6183						
PROC. REF: AMM 21-32-06-720-801PROC. REF: AMM 21-32-06-720-801								
21-32-06-720-801-01A	FUNCTIONAL TEST ELECTROPNEUMATIC VALVE (MANDATORY 5-40)							Service ATA:21
PN:2097D020700	MOS	07-Jan-12						MANDATORY 5-40
SN:167	HRS	11669.92	14300		25969.92		12073.6	
WC#: 21.260	AFL	6183						
PROC. REF: AMM 21-32-06-720-801PROC. REF: AMM 21-32-06-720-801								
21-32-06-720-801-02	FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - PNEUMATIC VALVE (5HP)							Service ATA:21
PN:2099E010700	MOS	07-Jan-12						
SN:182	HRS	11669.92	4840		16509.92		2613.6	
	AFL	6183						
PROC. REF: AMM 21-32-06-720-801PROC. REF: AMM 21-32-06-720-801								
21-32-06-720-801-02A	FUNCTIONAL TEST PNEUMATIC VALVE (MANDATORY 5-40)							Service ATA:21
PN:2099E010700	MOS	07-Jan-12						MANDATORY 5-40
SN:182	HRS	11669.92	14300		25969.92		12073.6	
WC#: 21.270	AFL	6183						
PROC. REF: AMM 21-32-06-720-801PROC. REF: AMM 21-32-06-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-06-720-802-01	^S	FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - ELECTROPNEUMATIC VALVE (4HP)						Service ATA:21
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 21-32-06-720-802PROC. REF: AMM 21-32-06-720-802								PKG:31
21-32-06-720-802-02	^S	FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - PNEUMATIC VALVE (5HP)						Service ATA:21
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 21-32-06-720-802PROC. REF: AMM 21-32-06-720-802								PKG:31
21-32-06-900-801-01		REMOVAL / INSTALLATION OF THE ELECTROPNEUMATIC VALVE - ELECTROPNEUMATIC VALVE (4HP)						Component ATA:21
PN:2097D020700	MOS/MSC	19-Dec-21	O/C	TSR 0				
SN:167	HRS	13275.5		TSR 0				
WC#: 21.260	AFL	6741		TSR 0				
PROC. REF: AMM 21-32-06-900-801PROC. REF: AMM 21-32-06-900-801								
21-32-06-900-802-01		REMOVAL / INSTALLATION OF THE PNEUMATIC VALVE - PNEUMATIC VALVE (5HP)						Component ATA:21
PN:2099E010700	MOS/MSC	19-Dec-21	O/C	TSO 119, TSR 0				
SN:182	HRS	13275.5		TSO 1605.58, TSR 0				
WC#: 21.270	AFL	6741		TSO 558, TSR 0				
PROC. REF: AMM 21-32-06-900-802PROC. REF: AMM 21-32-06-900-802								
21-32-17-200-801-01	^S	INSPECTION OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - PRESSURE-RELIEF VALVE (L505HP)						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.350	AFL	6741						
PROC. REF: AMM 21-32-17-200-801PROC. REF: AMM 21-32-17-200-801								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-17-200-801-02	^S	INSPECTION OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - PRESSURE-RELIEF VALVE (R505HP)						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.360	AFL	6741						
PROC. REF: AMM 21-32-17-200-801PROC. REF: AMM 21-32-17-200-801								PKG:21
21-32-33-710-801-01	^S	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION VALVE - BAGGAGE COMPARTMENT ISOLATION VALVE (24HP)						Service ATA:21
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
WC#: 21.120	AFL	7304						
PROC. REF: AMM 21-32-33-710-801PROC. REF: AMM 21-32-33-710-801								PKG:5
21-32-37-200-801-01	^S	INSPECTION OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - NEGATIVE PRESSURE RELIEF VALVES (L508HP) / (R508HP)						Service ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 21.370	AFL	6741						
PROC. REF: AMM 21-32-37-200-801PROC. REF: AMM 21-32-37-200-801								PKG:21
21-32-37-720-801-01		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - LH NEGATIVE PRESSURE RELIEF VALVE (L508HP)						Service ATA:21
PN:2827A01	MOS	12-Jun-09						
SN:253	HRS	10850.2	4000 (+3%)		14850.2	14970.2	953.9 (+120)	
WC#: 21.370	AFL	5878						
PROC. REF: AMM 21-32-37-720-801PROC. REF: AMM 21-32-37-720-801								
21-32-37-720-801-02		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - RH NEGATIVE PRESSURE RELIEF VALVE (R508HP)						Service ATA:21
PN:2827A01	MOS	12-Jun-09						
SN:247	HRS	10850.2	4000 (+3%)		14850.2	14970.2	953.9 (+120)	
WC#: 21.380	AFL	5878						
PROC. REF: AMM 21-32-37-720-801PROC. REF: AMM 21-32-37-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-37-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - LH NEGATIVE PRESSURE RELIEF VALVE (L508HP)						Component	ATA:21
PN:2827A01	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:253	HRS	10850.2		TSR 0				
WC#: 21.370	AFL	5878		TSR 0				
PROC. REF: AMM 21-32-37-900-801PROC. REF: AMM 21-32-37-900-801								
21-32-37-900-801-02	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - RH NEGATIVE PRESSURE RELIEF VALVE (R508HP)						Component	ATA:21
PN:2827A01	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:247	HRS	10850.2		TSR 0				
WC#: 21.380	AFL	5878		TSR 0				
PROC. REF: AMM 21-32-37-900-801PROC. REF: AMM 21-32-37-900-801								
21-32-41-200-801-01 ^S	INSPECTION OF THE NICOTINE FILTER CARTRIDGE - CABIN AIR FILTER (504HP)						Service	ATA:21
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 21.250	AFL	7052	3750					
PROC. REF: AMM 21-32-41-200-801PROC. REF: AMM 21-32-41-200-801								PKG:31
21-52-00-710-801-01 ^S	OPERATIONAL TEST OF THE WATER REINJECTION SYSTEM						Service	ATA:21
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 21.440	AFL	6741						
PROC. REF: AMM 21-52-00-710-801PROC. REF: AMM 21-52-00-710-801								PKG:22
21-52-05-350-801-01	RESTORATION OF THE TURBOCOOLER (OVERHAUL) - TURBOCOOLER (504HN)						Service	ATA:21
PN:3269B0102	MOS/MSC	29-Aug-08	O/C	TAC 0				
SN:191	HRS	10680.1		TAC 0				
WC#: 21.410	AFL	5757		TAC 0				
PROC. REF: AMM 21-52-05-350-801PROC. REF: AMM 21-52-05-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-05-610-801-01		TURBOCOOLER OIL SERVICING - TURBOCOOLER (504HN) OIL TOP-UP						Service ATA:21
	MOS	27-Sep-24						
	HRS	13765.3	200		13965.3		69	
	AFL	7169						
PROC. REF: AMM 21-52-05-610-801PROC. REF: AMM 21-52-05-610-801								
21-52-05-610-801-02 ^S		TURBOCOOLER OIL SERVICING - TURBOCOOLER (504HN) OIL DRAINING AND REFILLING						Service ATA:21
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 21-52-05-610-801PROC. REF: AMM 21-52-05-610-801								
21-52-05-900-801-01		REMOVAL / INSTALLATION OF THE TURBOCOOLER - TURBOCOOLER (504HN)						Component ATA:21
PN:3269B0102	MOS/MSC	29-Aug-08	H/T	TSO 0				
SN:191	HRS	10680.1		TSO 0				
WC#: 21.410	AFL	5757		TSO 0				
PROC. REF: AMM 21-52-05-900-801PROC. REF: AMM 21-52-05-900-801								
21-52-09-210-802-01		GENERAL VISUAL INSPECTION OF THE ECU HEAT EXCHANGER GRID						Service ATA:21
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 21.410	AFL	6673						
PROC. REF: AMM 21-52-09-210-802PROC. REF: AMM 21-52-09-210-802								
21-52-17-900-801-01		REMOVAL / INSTALLATION OF THE HP WATER SEPARATOR - HP WATER SEPARATOR (505HN)						Component ATA:21
PN:8903D03	MOS/MSC		O/C					
SN:182	HRS	2091						
WC#: 21.420	AFL							
PROC. REF: AMM 21-52-17-900-801PROC. REF: AMM 21-52-17-900-801								
21-52-18-100-801-01		CLEANING OF THE HP WATER SEPARATOR FILTER - HP WATER SEPARATOR (505HN)						Service ATA:21
	MOS	27-Mar-26	24 (+1m)	Adj -2d	25-Mar-28	25-Apr-28	701 d (+31)	
	HRS	13896.3	1200 (+40)		15096.3	15136.3	1200 (+40)	
WC#: 21.420	AFL	7313						
PROC. REF: AMM 21-52-18-100-801PROC. REF: AMM 21-52-18-100-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-19-200-801-01	^S	INSPECTION / CHECK OF THE LP WATER SEPARATOR COMPONENTS - LP WATER SEPARATOR (506HN)						Service ATA:21
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 21.430	AFL	7304						
PROC. REF: AMM 21-52-19-200-801PROC. REF: AMM 21-52-19-200-801								PKG:15
21-52-21-350-801-01		RESTORATION OF THE TURBOFAN (OVERHAUL) - TURBOFAN (23HN)						Service ATA:21
PN:TVT107-28H4	MOS	18-Oct-13						OVERHAUL
SN:00594	HRS	12430.13						
WC#: 21.400	AFL	6428	3000 (+3%)		9428	9518	2115 (+90)	
PROC. REF: AMM 21-52-21-350-801PROC. REF: AMM 21-52-21-350-801								
21-52-21-900-801-01		REMOVAL / INSTALLATION OF THE TURBOFAN - TURBOFAN (23HN)						Component ATA:21
PN:TVT107-28H4	MOS/MSC	18-Oct-13	H/T	TSO 1				
SN:00594	HRS	12430.13		TSO 0				
WC#: 21.400	AFL	6428		TSO 0				
PROC. REF: AMM 21-52-21-900-801PROC. REF: AMM 21-52-21-900-801								
21-52-21-900-802-01		REMOVAL / INSTALLATION OF THE TURBOFAN BY-PASS ELECTRIC VALVE - TURBOFAN BY-PASS ELECTRIC VALVE (22HN)						Component ATA:21
PN:BYLB51035-1	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:538	HRS	10850.2		TSR 0				
WC#: 21.460	AFL	5878		TSR 0				
PROC. REF: AMM 21-52-21-900-802PROC. REF: AMM 21-52-21-900-802								
21-71-01-350-801-01		RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - LH OZONE CONVERTER (L517HN)						Service ATA:21
PN:20-425-1	MOS	10-Aug-07						
SN:6139	HRS	9902.6	5000 (+3%)		14902.6	15052.6	1006.3 (+150)	
WC#: 36.030	AFL	5277						
PROC. REF: AMM 21-71-01-350-801PROC. REF: AMM 21-71-01-350-801								
21-71-01-350-801-02		RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - RH OZONE CONVERTER (R517HN)						Service ATA:21
PN:20-425-1	MOS	10-Aug-07						
SN:6162	HRS	9902.6	5000 (+3%)		14902.6	15052.6	1006.3 (+150)	
WC#: 36.030	AFL	5277						
PROC. REF: AMM 21-71-01-350-801PROC. REF: AMM 21-71-01-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-71-01-900-801-01 REMOVAL / INSTALLATION OF THE OZONE CONVERTERS - LH OZONE CONVERTER (L517HN)								Component ATA:21
PN:20-425-1	MOS/MSC	10-Aug-07	O/C					
SN:6139	HRS	9902.6						
WC#: 36.030	AFL	5277						
PROC. REF: AMM 21-71-01-900-801PROC. REF: AMM 21-71-01-900-801								
21-71-01-900-801-02 REMOVAL / INSTALLATION OF THE OZONE CONVERTERS - RH OZONE CONVERTER (R517HN)								Component ATA:21
PN:20-425-1	MOS/MSC	10-Aug-07	O/C	TSO 0				
SN:6162	HRS	9902.6		TSO 0				
WC#: 36.030	AFL	5277		TSO 0				
PROC. REF: AMM 21-71-01-900-801PROC. REF: AMM 21-71-01-900-801								
212121 LH COLD AIR CHECK VALVE								Component ATA:21
PN:CYLB50713-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212131 RH COLD AIR CHECK VALVE								Component ATA:21
PN:CYLB50713-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212151 AERATOR CHECK VALVE								Component ATA:21
PN:CYLB50712	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212161 PASSENGER COMPARTMENT COLD AIR CHECK VALVE								Component ATA:21
PN:CYLB51162	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212171	CREW COLD AIR CHECK VALVE							Component ATA:21
PN:CYLB51162	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212181	PILOT AERATOR							Component ATA:21
PN:2368	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212191	COPILOT AERATOR							Component ATA:21
PN:2368	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212251	PASSENGER COMPARTMENT AIR CONDITIONING CHECK VALVE							Component ATA:21
PN:CYLB51111	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212261	CREW AIR CONDITIONING CHECK VALVE							Component ATA:21
PN:CYLB51111	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212271	BAGGAGE COMPARTMENT ELECTRIC CHECK VALVE							Component ATA:21
PN:CYLB50414	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212281	FRONT PRECONDITIONING FLOOD DUCT							Component ATA:21
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212291	REAR PRECONDITIONING FLOOD DUCT							Component ATA:21
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212321	NOSE CONE ISOLATION RESTRICTOR VALVE							Component ATA:21
PN:BYLB51003	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212341	COCKPIT/CABIN SYSTEM INTERCONNECTION FLAP ASSEMBLY							Component ATA:21
PN:BYLB51603	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212361	BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE							Component ATA:21
PN:3188-000	MOS/MSC	07-Feb-91	O/C					
SN:122	HRS	0		TSN 0				
WC#: 21.120	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212381	BAGGAGE COMPARTMENT SUPPLY ELECTRIC VALVE							Component ATA:21
PN:B97-26-551	MOS/MSC	07-Feb-91	O/C					
SN:20174	HRS	0		TSN 0				
WC#: 21.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212401	COCKPIT CONDITIONING ELECTRIC VALVE							Component ATA:21
PN:BYLB51003	MOS/MSC	06-Jul-09	O/C		TSR 0			
SN:421	HRS	10853.9			TSR 0			
WC#: 21.140	AFL	5880			TSR 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212441	NOSE CONE THERMOSTAT							Component ATA:21
PN:784-756-1	MOS/MSC	07-Feb-91	O/C					
SN:205	HRS	0			TSN 0			
WC#: 21.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213101	NO. 1 ENGINE PRESSURE SUPPLY CHECK VALVE							Component ATA:21
PN:AR88-02-00-03	MOS/MSC	07-Feb-91	O/C					
SN:120	HRS	0			TSN 0			
WC#: 21.230	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213121	NO. 2 ENGINE PRESSURE SUPPLY CHECK VALVE							Component ATA:21
PN:AR88-02-00-03	MOS/MSC	07-Feb-91	O/C					
SN:121	HRS	0			TSN 0			
WC#: 21.230	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213127	APU SUPPLY PRESSURE CHECK VALVE							Component ATA:21
PN:AR88-02-00-03	MOS/MSC	07-Feb-91	O/C					
SN:131	HRS	0			TSN 0			
WC#: 21.230	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213131	PRESSURIZATION JET PUMP							Component ATA:21
PN:FGFB722602A2	MOS/MSC	07-Feb-91	O/C					
SN:078	HRS	0			TSN 0			
WC#: 21.240	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213141	ANTI-NICOTINE FILTER							Component ATA:21
PN:234A0101	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.250	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213281	EMERGENCY PRESSURIZATION PANEL							Component ATA:21
PN:911A0301	MOS/MSC	23-Sep-09	O/C	TSO 0				
SN:103	HRS	10853.9		TSO 0				
WC#: 21.300	AFL	5880		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213301	NOSE CONE PNEUMATIC ACTUATOR							Component ATA:21
PN:7021-000	MOS/MSC	25-Feb-11	O/C	TSO 0				
SN:128	HRS	11293.42		TSO 0				
WC#: 21.310	AFL	6006		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213321	PNEUMATIC ACTUATOR CONTROLLED VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.320	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213331	NOSE CONE PRESSURE RELIEF VALVE							Component ATA:21
PN:6025-300	MOS/MSC	27-Jan-06	O/C	TSN 0				
SN:C19151	HRS	8376.7		TSN 0				
WC#: 21.330	AFL	4401		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213351	NOSE CONE ISOLATION VALVE							Component ATA:21
PN:B97M19-203-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.335	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213501	NO. 1 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE							Component ATA:21
PN:985C63-21	MOS/MSC	03-Apr-03	O/C	TSN 0				
SN:173	HRS	5826.4		TSN 0				
WC#: 21.350	AFL	2849		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213531	NO. 2 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE							Component ATA:21
PN:985C63-21	MOS/MSC	03-Apr-03	O/C	TSN 0				
SN:191	HRS	5826.4		TSN 0				
WC#: 21.360	AFL	2849		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215101	PRIMARY HEAT EXCHANGER							Component ATA:21
PN:FGFB721591A1	MOS/MSC	30-Jan-07	O/C	TSR 0				
SN:70	HRS	9294.2		TSR 0				
WC#: 21.390	AFL	4969		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215181	NO. 1 HIGH PRESSURE/LOW PRESSURE TURBINE BRAKE CHECK VALVE							Component ATA:21
PN:AR88-02-00-03	MOS/MSC	07-Feb-91	O/C					
SN:129	HRS	0		TSN 0				
WC#: 21.405	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215191	NO. 2 HIGH PRESSURE/LOW PRESSURE TURBINE BRAKE CHECK VALVE							Component ATA:21
PN:AR88-02-00-03	MOS/MSC	07-Feb-91	O/C					
SN:109	HRS	0		TSN 0				
WC#: 21.405	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215271	LOW PRESSURE WATER SEPARATOR							Component ATA:21
PN:B31WA3023	MOS/MSC	07-Jul-04	O/C	TSO 0				
SN:00659	HRS	6599		TSO 0				
WC#: 21.430	AFL	3386		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215301	TURBINE ANTI-ICING AMPLIFIER							Component ATA:21
PN:784688-1	MOS/MSC	21-Aug-04	O/C					
SN:0389	HRS	6777.4						
WC#: 21.450	AFL	3502						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215311	TURBINE ANTI-ICING TUBING SENSOR							Component ATA:21
PN:784-646	MOS/MSC	17-Nov-99	O/C	TSN 0				
SN:224	HRS			TSN 0				
WC#: 21.450	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215321	TURBINE ANTI-ICING ELECTRIC VALVE							Component ATA:21
PN:784-723-2	MOS/MSC		O/C					
SN:234	HRS	1372						
WC#: 21.450	AFL							
PROC. REF: AMM 21-52-33-900-801PROC. REF: AMM 21-52-33-900-801								
215341	ECU OVERHEATING SENSOR							Component ATA:21
PN:RP129-02	MOS/MSC	11-Apr-00	O/C	TSN 0				
SN:2562	HRS			TSN 0				
WC#: 21.460	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216101	CONDITIONING BOX							Component ATA:21
PN:5897-655-80-13	MOS/MSC	11-Jan-02	O/C	TSR 0				
SN:107	HRS	5065.9		TSR 0				
WC#: 21.470	AFL	2342		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216111	COCKPIT THERMO RESISTOR							Component ATA:21
PN:HYLZ-50514-32	MOS/MSC	09-Feb-15	O/C	TSR 10				
SN:951H	HRS	13109.23		TSR 0				
WC#: 21.470	AFL	6701		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216121	CABIN THERMO RESISTOR							Component ATA:21
PN:HYLZ50414-031	MOS/MSC	11-Feb-12	O/C	TSR 35				
SN:892H	HRS	11716.5		TSR 0				
WC#: 21.470	AFL	6216		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216131	COCKPIT TEMPERATURE REGULATION DUAL ELECTRIC VALVE							Component ATA:21
PN:BYLB51034-003	MOS/MSC	27-Dec-09	O/C	TSR 1				
SN:458	HRS			TSR 0				
WC#: 21.480	AFL			TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216141	CABIN TEMPERATURE REGULATION DUAL ELECTRIC VALVE							Component ATA:21
PN:BYLB51226-002	MOS/MSC	25-May-01	O/C	TSR 0				
SN:247	HRS	4758		TSR 0				
WC#: 21.480	AFL	2148		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216151	COCKPIT SHEATH SENSOR							Component ATA:21
PN:AYLF50425	MOS/MSC	07-Feb-91	O/C					
SN:952	HRS	0		TSN 0				
WC#: 21.490	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216161	CABIN SHEATH SENSOR							Component ATA:21
PN:AYLF50425	MOS/MSC	07-Feb-91	O/C					
SN:979	HRS	0		TSN 0				
WC#: 21.490	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216171	COCKPIT THERMOSTAT							Component ATA:21
PN:150T346	MOS/MSC	07-Feb-91	O/C					
SN:569	HRS	0		TSN 0				
WC#: 21.500	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216191	CABIN THERMOSTAT							Component ATA:21
PN:150T346	MOS/MSC	07-Feb-91	O/C					
SN:564	HRS	0		TSN 0				
WC#: 21.500	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 22 - AUTO FLIGHT								
22-10-00-710-801-01	^S	OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)						Service ATA:22
	MOS	17-Feb-26	24 (+1m)				RVSM	
	HRS	13885.3						
WC#: 22.030	AFL	7304						
PROC. REF: AMM 22-10-00-710-801PROC. REF: AMM 22-10-00-710-801								
22-10-01-900-801-01		REMOVAL / INSTALLATION OF THE FLIGHT GUIDANCE CONTROLLER - GUIDANCE CONTROLLER (32CA)						Component ATA:22
PN:7003975-805	MOS/MSC	23-Jan-09	O/C	TSR 0				
SN:86120413	HRS	10827.3		TSR 0				
WC#: 22.010	AFL	5857		TSR 0				
PROC. REF: AMM 22-10-01-900-801PROC. REF: AMM 22-10-01-900-801								
22-10-07-700-801-01	^S	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - AILERON						Service ATA:22
	MOS	22-Dec-23	72 (+2m)				RVSM	
	HRS	13641						
WC#: 22.085	AFL	7052	3750					
PROC. REF: AMM 22-10-07-700-801PROC. REF: AMM 22-10-07-700-801								
22-10-07-700-801-02	^S	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - ELEVATOR						Service ATA:22
	MOS	22-Dec-23	72 (+2m)				RVSM	
	HRS	13641						
WC#: 22.085	AFL	7052	3750					
PROC. REF: AMM 22-10-07-700-801PROC. REF: AMM 22-10-07-700-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-13-01-900-801-01 REMOVAL / INSTALLATION OF THE YAW DAMPER ACTUATOR - YAW DAMPER LINEAR ACTUATOR (22CA)								Component ATA:22
PN:7002800-914	MOS/MSC	22-Nov-07	O/C					
SN:8610193	HRS	10138.1						
WC#: 22.050	AFL	5422						
PROC. REF: AMM 22-13-01-900-801PROC. REF: AMM 22-13-01-900-801								
221031 PILOT AUTOPILOT COMPUTER								Component ATA:22
PN:7003974-719	MOS/MSC	05-May-07	O/C					
SN:84070038	HRS	9489.2						
WC#: 22.020	AFL	5048						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221041 COPILOT AUTOPILOT COMPUTER								Component ATA:22
PN:7003974-719	MOS/MSC	12-Jun-08	O/C					
SN:92083384	HRS	10767.7						
WC#: 22.020	AFL	5817						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221101 AILERON AUTOPILOT SERVO MOTOR								Component ATA:22
PN:7002260-921	MOS/MSC	03-Oct-00	O/C					
SN:87051665	HRS	4446						
WC#: 22.040	AFL	2093						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221121 ELEVATOR AUTOPILOT SERVO MOTOR								Component ATA:22
PN:7002260-821	MOS/MSC	07-Feb-91	O/C					
SN:90023025	HRS	0		TSN 0				
WC#: 22.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221201 NO. 1 AUTOPILOT AILERON CABLE								Component ATA:22
PN:59054	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221211	NO. 2 AUTOPILOT AILERON CABLE							Component ATA:22
PN:59054	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221231	NO. 1 AUTOPILOT ELEVATOR CABLE							Component ATA:22
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221241	NO. 2 AUTOPILOT ELEVATOR CABLE							Component ATA:22
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221301	PILOT ADVISORY DISPLAY							Component ATA:22
PN:7003652-631	MOS/MSC	30-Jan-07	O/C					
SN:92051979	HRS	9294.33						
WC#: 22.090	AFL	4969						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221311	COPILOT ADVISORY DISPLAY							Component ATA:22
PN:7003652-631	MOS/MSC	07-Feb-91	O/C					
SN:89121409	HRS	0		TSN 0				
WC#: 22.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221701	AILERON AUTOPILOT CAPSTAN							Component ATA:22
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.100	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221711	ELEVATOR AUTOPILOT CAPSTAN							Component ATA:22
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.110	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 23 - COMMUNICATIONS								
23-11-05-900-801-01	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 1 ANTENNA (L5RC)							Component ATA:23
PN:ANV142SZ	MOS/MSC	07-Feb-91	O/C					
SN:634	HRS	0		TSN 0				
WC#: 23.020	AFL	0						
PROC. REF: AMM 23-11-05-900-801PROC. REF: AMM 23-11-05-900-801								
23-11-05-900-801-02	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 2 ANTENNA (R5RC)							Component ATA:23
PN:SG65-8280-10	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:31016357	HRS	10850.2		TSN 0				
WC#: 23.030	AFL	5878		TSN 0				
PROC. REF: AMM 23-11-05-900-801PROC. REF: AMM 23-11-05-900-801								
23-11-05-900-801-03	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF3 ANTENNA (25RC)							Component ATA:23
PN:S65-8280-19	MOS/MSC	07-Feb-91	O/C					
SN:392	HRS	0		TSN 0				
WC#: 23.035	AFL	0						
PROC. REF: AMM 23-11-05-900-801PROC. REF: AMM 23-11-05-900-801								
23-12-13-900-801-01	REMOVAL / INSTALLATION OF THE HF ANTENNA - HF ANTENNA (5RE)							Component ATA:23
PN:FGFB312001	MOS/MSC	07-Feb-91	O/C					
SN:20RA98	HRS	0		TSN 0				
WC#: 23.050	AFL	0						
PROC. REF: AMM 23-12-13-900-801PROC. REF: AMM 23-12-13-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-60-00-760-801-01	^S	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS						Service ATA:23
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 23.090	AFL	6741						
PROC. REF: AMM 23-60-00-760-801PROC. REF: AMM 23-60-00-760-801								PKG:21
231101	NO. 1 VHF CONTROL							Component ATA:23
PN:822-1120-005	MOS/MSC	08-Mar-13	O/C	TSO 2				
SN:7558	HRS	12150.15		TSO 0				
WC#: 23.020	AFL	6335		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231111	NO. 2 VHF CONTROL							Component ATA:23
PN:822-1120-005	MOS/MSC	21-Jul-10	O/C					
SN:8943	HRS	11009.58						
WC#: 23.030	AFL	5928						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231116	NO. 3 VHF CONTROL							Component ATA:23
PN:822-1120-006	MOS/MSC	28-Aug-12	O/C	TSO 0				
SN:9362	HRS	11975.42		TSO 0				
WC#: 23.035	AFL	6299		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231121	NO. 1 VHF TRANSCEIVER							Component ATA:23
PN:822-1114-001	MOS/MSC	22-Jun-09	O/C	TSR 21				
SN:21857	HRS	10851.7		TSR 864.5				
WC#: 23.020	AFL	5879		TSR 544				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231131	NO. 2 VHF TRANSCEIVER							Component ATA:23
PN:822-1114-001	MOS/MSC	11-Feb-00	O/C					
SN:27995	HRS							
WC#: 23.030	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231136	NO. 3 VHF TRANSCEIVER							Component ATA:23
PN:822-1114-001	MOS/MSC	22-Oct-99	O/C					
SN:28130	HRS							
WC#: 23.035	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231201	NO. 1 HF COUPLER AMPLIFIER							Component ATA:23
PN:064-1017-02	MOS/MSC	28-Aug-12	O/C					
SN:11329	HRS	11975.42						
WC#: 23.040	AFL	6299						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231206	NO. 2 HF COUPLER AMPLIFIER							Component ATA:23
PN:064-1017-02	MOS/MSC	07-Feb-91	O/C					
SN:12040	HRS	0		TSN 0				
WC#: 23.045	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231211	NO. 1 HF TRANSCEIVER							Component ATA:23
PN:064-1015-01	MOS/MSC	30-Aug-13	O/C					
SN:25777	HRS	12348.5						
WC#: 23.040	AFL	6402						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231216	NO. 2 HF TRANSCEIVER							Component ATA:23
PN:064-1015-01	MOS/MSC	30-Aug-13	O/C					
SN:32333	HRS	12348.5						
WC#: 23.045	AFL	6402						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231221	NO. 1 HF CONTROL							Component ATA:23
PN:064-1016-03	MOS/MSC	24-Mar-07	O/C					
SN:4278	HRS	9441						
WC#: 23.040	AFL	5025						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231226	NO. 2 HF CONTROL							Component ATA:23
PN:064-1016-03	MOS/MSC	24-Mar-07	O/C					
SN:6896	HRS	9441						
WC#: 23.045	AFL	5025						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231241	HF ANTENNA TUNING VARIABLE CAPACITOR							Component ATA:23
PN:071-1270-01	MOS/MSC	23-Jul-12	O/C					
SN:1818	HRS	11890.25						
WC#: 23.055	AFL	6271						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231711	NO. 1 VHF AUDIO INTERFACE							Component ATA:23
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.130	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231721	NO. 2 VHF AUDIO INTERFACE							Component ATA:23
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.140	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231A34 ^U	CONFIG SATCOM MODULE							Component ATA:23
PN:405033A-001	MOS/MSC	14-Mar-01	O/C					
SN:99793445	HRS	4661						
	AFL	2106						
231A50 ^U	SATELLITE DATA UNIT							Component ATA:23
PN:405033A-UAT-NRS	MOS/MSC	13-Oct-04	O/C	TSO 0				
SN:178	HRS	6929		TSO 0				
	AFL	3610		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231A52 ^U AMP LN SATCOM #1 DIPLEXER Component ATA:23								
PN:405012A-THR	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:06796536-06796544	HRS	10850.2		TSN 0				
	AFL	5878		TSN 0				
231A54 ^U SATCOM #1 ANTENNA Component ATA:23								
PN:10101-00	MOS/MSC	14-Sep-07	O/C	TSO 0				
SN:0P001101	HRS	9985		TSO 0				
	AFL	5332		TSO 0				
231A58 ^U HIGH POWER SAT AMPLIFIER Component ATA:23								
PN:405010A	MOS/MSC	20-Mar-01	O/C	TSN 0				
SN:00814832	HRS	4675.8		TSN 0				
	AFL	2111		TSN 0				
231A71 ^U CABIN SATCOM #1 CONTROL Component ATA:23								
PN:405620A-UAW	MOS/MSC	14-Mar-01	O/C					
SN:00826154	HRS	4661						
	AFL	2106						
231A72 ^U SATCOM CABIN #2 CONTROL Component ATA:23								
PN:405620A-UAW	MOS/MSC	14-Mar-01	O/C					
SN:00825937	HRS	4661						
	AFL	2106						
231A73 ^U SATCOM CABIN #3 CONTROL Component ATA:23								
PN:405620A-UAW	MOS/MSC	14-Mar-01	O/C					
SN:00827386	HRS	4661						
	AFL	2106						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232001	SELCAL RECEIVER							Component ATA:23
PN:SC2539A	MOS/MSC	18-Oct-13	O/C	TSR 6				
SN:206	HRS	12430.13						
WC#: 23.100	AFL	6428						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232101	COMMUNICATION ANNUNCIATOR PANEL							Component ATA:23
PN:872TS06Y	MOS/MSC		O/C					
SN:130	HRS	494						
WC#: 23.110	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233101	PILOT AUDIO CONTROL							Component ATA:23
PN:M1045FBAAHJB7	MOS/MSC	31-Mar-14	O/C					
SN:850535	HRS	12625.42						
WC#: 23.060	AFL	6516						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233121	COPILOT AUDIO CONTROL							Component ATA:23
PN:M1045FBAAHJB7	MOS/MSC	31-Mar-14	O/C					
SN:8912005	HRS	12625.42						
WC#: 23.060	AFL	6516						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233151	PUBLIC ADDRESS AMPLIFIER							Component ATA:23
PN:M2050C	MOS/MSC	07-Feb-91	O/C					
SN:9006211	HRS	0		TSN 0				
WC#: 23.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233201	PILOT LOUD SPEAKER							Component ATA:23
PN:5FU4-8	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233211		COPILOT LOUD SPEAKER					Component	ATA:23
PN:SFUA	MOS/MSC	22-Jun-09	O/C	TSN 0				
SN:081231052	HRS	10851.7		TSN 0				
WC#: 23.080	AFL	5879		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233A06 ^U		CASSETTE VIDEO PLAYER					Component	ATA:23
PN:VCP-014-01-2	MOS/MSC	14-Sep-01	O/C	TSR 0				
SN:120001000	HRS	4944.2		TSR 0				
	AFL	2276		TSR 0				
233A16 ^U		VIDEO CABIN FWD MONITOR-					Component	ATA:23
PN:8630-93C09A	MOS/MSC	01-Oct-04	O/C	TSN 0				
SN:UNKNOWN	HRS	6887.2		TSN 0				
	AFL	3580		TSN 0				
233A29 ^U		DISPLAY CABIN INTERFACE					Component	ATA:23
PN:920050	MOS/MSC	16-Jan-09	O/C	TSR 0				
SN:1557	HRS	10823		TSR 0				
	AFL	5854		TSR 0				
233A39 ^U		AUDIO 3RD CREW CONTROL					Component	ATA:23
PN:M1045FBAHJJ7	MOS/MSC	14-Mar-01	O/C					
SN:00120010328	HRS	4661						
	AFL	2106						
233A88 ^U		DISC VIDEO PLAYER					Component	ATA:23
PN:DVD-024-03-2	MOS/MSC	14-Mar-01	O/C					
SN:UNKNOWN	HRS	4661						
	AFL	2106						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-20-00-720-801-01	^S	FUNCTIONAL TEST OF THE PASSENGER AC ELECTRICAL DISTRIBUTION SYSTEM						Service ATA:24
	MOS							
	HRS		1600 (+40)		14875.5 (M)	14915.5	979.2 (+40)	
	AFL							
PROC. REF: AMM 24-20-00-720-801PROC. REF: AMM 24-20-00-720-801								PKG:21
24-20-05-710-801-01	^S	OPERATIONAL TEST OF THE GROUND FAULT INTERRUPTER (GFI)						Service ATA:24
	MOS	19-Dec-21						SMM
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 24-20-05-710-801PROC. REF: AMM 24-20-05-710-801								PKG:21
24-20-17-720-801-01	^S	FUNCTIONAL TEST OF THE AC CONTROL RELAY CUT-OFF POWER WITH CABIN ALTITUDE						Service ATA:24
	MOS	07-Feb-91						
	HRS	0	9600 (+40)		14875.5 (M)	14915.5	979.2 (+40)	
	AFL	0						
PROC. REF: AMM 24-20-17-720-801PROC. REF: AMM 24-20-17-720-801								PKG:21
24-30-00-710-801-01		OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 1						Service ATA:24
	MOS	11-Dec-25	12 (+1m)	Adj -2d	09-Dec-26	09-Jan-27	229 d (+31)	
	HRS	13869.7	400 (+40)		14269.7	14309.7	373.4 (+40)	
	AFL	7285						
PROC. REF: AMM 24-30-00-710-801PROC. REF: AMM 24-30-00-710-801								
24-30-00-710-801-02		OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 2						Service ATA:24
	MOS	11-Dec-25	12 (+1m)	Adj -2d	09-Dec-26	09-Jan-27	229 d (+31)	
	HRS	13869.7	400 (+40)		14269.7	14309.7	373.4 (+40)	
	AFL	7285						
PROC. REF: AMM 24-30-00-710-801PROC. REF: AMM 24-30-00-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-30-00-710-801-03	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 3							Service ATA:24
	MOS	11-Dec-25	12 (+1m)	Adj -2d	09-Dec-26	09-Jan-27	229 d (+31)	
	HRS	13869.7	400 (+40)		14269.7	14309.7	373.4 (+40)	
	AFL	7285						
PROC. REF: AMM 24-30-00-710-801PROC. REF: AMM 24-30-00-710-801								
24-30-00-710-801-04	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - APU							Service ATA:24
	MOS	11-Dec-25	12 (+1m)	Adj -2d	09-Dec-26	09-Jan-27	229 d (+31)	
	HRS	13869.7	400 (+40)		14269.7	14309.7	373.4 (+40)	
	AFL	7285						
PROC. REF: AMM 24-30-00-710-801PROC. REF: AMM 24-30-00-710-801								
24-30-00-710-802-01 ^S	OPERATIONAL TEST OF THE APU SHUTDOWN SAFETIES WITH "MASTER" APU CONTROL							Service ATA:24
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 24.180	AFL	6741						
PROC. REF: AMM 24-30-00-710-802PROC. REF: AMM 24-30-00-710-802								PKG:21
24-31-09-900-801-01	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - APU GCU (22PA)							Component ATA:24
PN:D22-600	MOS/MSC	28-Oct-05	O/C	TSR 0				
SN:2020	HRS	8112.6		TSR 0				
WC#: 24.120	AFL	4278		TSR 0				
PROC. REF: AMM 24-31-09-900-801PROC. REF: AMM 24-31-09-900-801								
24-31-09-900-801-02	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 1 (3PA1)							Component ATA:24
PN:D22-600	MOS/MSC	31-Mar-14	O/C					
SN:80445-07	HRS	12625.42						
WC#: 24.110	AFL	6516						
PROC. REF: AMM 24-31-09-900-801PROC. REF: AMM 24-31-09-900-801								
24-31-09-900-801-03	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 2 (3PA2)							Component ATA:24
PN:D22-501-1	MOS/MSC	28-Oct-05	O/C	TSR 0				
SN:80246-03	HRS	8112.6		TSR 0				
WC#: 24.120	AFL	4278		TSR 0				
PROC. REF: AMM 24-31-09-900-801PROC. REF: AMM 24-31-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-09-900-801-04 REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 3 (3PA3)								Component ATA:24
PN:D22-501-1	MOS/MSC	23-Oct-97	O/C	TSN 0				
SN:5216-160	HRS	3015		TSN 0				
WC#: 24.110	AFL			TSN 0				
PROC. REF: AMM 24-31-09-900-801PROC. REF: AMM 24-31-09-900-801								
24-31-13-350-801-01 RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 1 STARTER-GENERATOR (L1PA)								Service ATA:24
PN:8060-160	MOS/MSC	15-Apr-13	O/C					
SN:1748	HRS	12205.82						
WC#: 24.080	AFL	6354						
PROC. REF: AMM 24-31-13-350-801PROC. REF: AMM 24-31-13-350-801								
24-31-13-350-801-02 RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 2 STARTER-GENERATOR (M1PA)								Service ATA:24
PN:8060-160	MOS	17-Jul-14						OVERHAUL
SN:2911	HRS	12864.12	1240 (+3%)	TAC 0	14104.12	14141.32	207.8 (+37.2)	
WC#: 24.090	AFL	6621						
PROC. REF: AMM 24-31-13-350-801PROC. REF: AMM 24-31-13-350-801								
24-31-13-350-801-03 RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 3 STARTER-GENERATOR (R1PA)								Service ATA:24
PN:8060-160	MOS/MSC	23-Jan-13	O/C					
SN:2994	HRS	12049.92						
WC#: 24.080	AFL	6312						
PROC. REF: AMM 24-31-13-350-801PROC. REF: AMM 24-31-13-350-801								
24-31-13-350-801-04 RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - APU STARTER-GENERATOR (21PA)								Service ATA:24
PN:8060-150	MOS	17-Jul-14						OVERHAUL
SN:2391	HRS	12864.12						
WC#: 24.100	AFL	6621						
	APH	6254	900 (+3%)	TAC 0	7154	7181	325.7 (+27)	
PROC. REF: AMM 24-31-13-350-801PROC. REF: AMM 24-31-13-350-801								
24-31-13-900-803-01 REMOVAL / INSTALLATION OF THE ENGINES 1 AND 3 STARTER-GENERATORS - ENGINE 1 STARTER-GENERATOR (L1PA)								Component ATA:24
PN:8060-160	MOS/MSC	15-Apr-13	O/C	TSO 0				OVERHAUL
SN:1748	HRS	12205.82		TSO 0				
WC#: 24.080	AFL	6354		TSO 0				
PROC. REF: AMM 24-31-13-900-803PROC. REF: AMM 24-31-13-900-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-13-900-803-02 REMOVAL / INSTALLATION OF THE ENGINES 1 AND 3 STARTER-GENERATORS - ENGINE 3 STARTER-GENERATOR (R1PA)								Component ATA:24
PN:8060-160	MOS/MSC	23-Jan-13	O/C	TSO 0				
SN:2994	HRS	12049.92		TSO 0				
WC#: 24.080	AFL	6312		TSO 0				
PROC. REF: AMM 24-31-13-900-803PROC. REF: AMM 24-31-13-900-803								
24-31-13-900-804-01 REMOVAL / INSTALLATION OF THE ENGINE 2 STARTER-GENERATOR - ENGINE 2 STARTER-GENERATOR (M1PA)								Component ATA:24
PN:8060-160	MOS/MSC	17-Jul-14	O/C					
SN:2911	HRS	12864.12		TSO 361				
WC#: 24.090	AFL	6621						
PROC. REF: AMM 24-31-13-900-804PROC. REF: AMM 24-31-13-900-804								
24-31-17-220-803-01 CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (L1PA)								Service ATA:24
PN:8060-160	MOS/MSC	30-May-14	N/A					
SN:1748	HRS	12736.3						
	AFL	6551						
PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803								
24-31-17-220-803-02 CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (M1PA)								Service ATA:24
PN:8060-160	MOS/MSC	26-Nov-14	N/A					
SN:2911	HRS	13029.05						
	AFL	6673						
PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803								
24-31-17-220-803-03 CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (R1PA)								Service ATA:24
PN:8060-160	MOS/MSC	08-Aug-14	N/A					
SN:2994	HRS	12881.35						
	AFL	6629						
PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803								
24-31-17-220-804-01 CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - ENGINE 1 STARTER-GENERATOR (L1PA)								Service ATA:24
PN:8060-160	MOS	06-Apr-22						
SN:1748	HRS	13355.8	600 (+60)		13955.8	14015.8	59.5 (+60)	
	AFL	6803						
PROC. REF: AMM 24-31-17-220-804PROC. REF: AMM 24-31-17-220-804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-17-220-804-02		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - ENGINE 2 STARTER-GENERATOR (M1PA)						Service ATA:24
PN:8060-160	MOS	22-Dec-23						
SN:2911	HRS	13641	600 (+60)		14241	14301	344.7 (+60)	
	AFL	7052						
PROC. REF: AMM 24-31-17-220-804PROC. REF: AMM 24-31-17-220-804								
24-31-17-220-804-03		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - ENGINE 3 STARTER-GENERATOR (R1PA)						Service ATA:24
PN:8060-160	MOS	13-Jan-23						
SN:2994	HRS	13482.5	600 (+60)		14082.5	14142.5	186.2 (+60)	
	AFL	6909						
PROC. REF: AMM 24-31-17-220-804PROC. REF: AMM 24-31-17-220-804								
24-31-17-220-805-01		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 1 STARTER-GENERATOR (L1PA)						Service ATA:24
PN:8060-160	MOS	24-Apr-25						
SN:1748	HRS	13836.2	150		13986.2		89.9	
	AFL	7249						
PROC. REF: AMM 24-31-17-220-805PROC. REF: AMM 24-31-17-220-805								
24-31-17-220-805-02		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 2 STARTER-GENERATOR (M1PA)						Service ATA:24
PN:8060-160	MOS/MSC	26-Nov-14	N/A					
SN:2911	HRS	13029.05						
	AFL	6673						
PROC. REF: AMM 24-31-17-220-805PROC. REF: AMM 24-31-17-220-805								
24-31-17-220-805-03 ^S		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 3 STARTER-GENERATOR (R1PA)						Service ATA:24
PN:8060-160	MOS/MSC	08-Aug-14	N/A					
SN:2994	HRS	12881.35						
	AFL	6629						
PROC. REF: AMM 24-31-17-220-805PROC. REF: AMM 24-31-17-220-805								
24-32-01-350-801-01		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 1 (L1PE)						Service ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C					
SN:41216746	HRS	13433.7						
WC#: 24.030	AFL	6872						
PROC. REF: AMM 24-32-01-350-801PROC. REF: AMM 24-32-01-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-01-350-801-02		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 2 (R1PE)						Service ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C					
SN:41195029	HRS	13433.7						
WC#: 24.035	AFL	6872						
PROC. REF: AMM 24-32-01-350-801PROC. REF: AMM 24-32-01-350-801								
24-32-01-700-801-01		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 1 (L1PE)						Service ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C					
SN:41216746	HRS	13433.7						
WC#: 24.030	AFL	6872						
PROC. REF: AMM 24-32-01-700-801PROC. REF: AMM 24-32-01-700-801								
24-32-01-700-801-02		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 2 (R1PE)						Service ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C					
SN:41195029	HRS	13433.7						
WC#: 24.035	AFL	6872						
PROC. REF: AMM 24-32-01-700-801PROC. REF: AMM 24-32-01-700-801								
24-32-01-700-802-01		REGULAR CHECK OF A MAIN LEAD / ACID BATTERY - BATTERY 1 (L1PE)						Service ATA:24
PN:RG-380E/40B	MOS	27-Mar-26	6 (+1m)		27-Sep-26	27-Oct-26	156 d (+30)	
SN:41216746	HRS	13896.3						
WC#: 24.030	AFL	7313						
PROC. REF: AMM 24-32-01-700-802PROC. REF: AMM 24-32-01-700-802								
24-32-01-700-802-02		REGULAR CHECK OF A MAIN LEAD / ACID BATTERY - BATTERY 2 (R1PE)						Service ATA:24
PN:RG-380E/40B	MOS	27-Mar-26	6 (+1m)		27-Sep-26	27-Oct-26	156 d (+30)	
SN:41195029	HRS	13896.3						
WC#: 24.035	AFL	7313						
PROC. REF: AMM 24-32-01-700-802PROC. REF: AMM 24-32-01-700-802								
24-32-01-900-801-01		REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 1 (L1PE)						Component ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C	TSN 0				
SN:41216746	HRS	13433.7		TSN 0				
WC#: 24.030	AFL	6872		TSN 0				
PROC. REF: AMM 24-32-01-900-801PROC. REF: AMM 24-32-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-01-900-801-02	REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 2 (R1PE)							Component ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C	TSN 0				
SN:41195029	HRS	13433.7		TSN 0				
WC#: 24.035	AFL	6872		TSN 0				
PROC. REF: AMM 24-32-01-900-801PROC. REF: AMM 24-32-01-900-801								
24-32-01-960-801-01	DISCARD OF THE MAIN LEAD / ACID BATTERIES - BATTERY 1 (L1PE)							Service ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C					
SN:41216746	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 24-32-01-960-801PROC. REF: AMM 24-32-01-960-801								
24-32-01-960-801-02	DISCARD OF THE MAIN LEAD / ACID BATTERIES - BATTERY 2 (R1PE)							Service ATA:24
PN:RG-380E/40B	MOS/MSC	08-Aug-22	O/C					
SN:41195029	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 24-32-01-960-801PROC. REF: AMM 24-32-01-960-801								
24-32-09-610-801-01	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)							Service ATA:24
PN:100-0540-02	MOS/MSC		N/A					
SN:1986	HRS							
WC#: 24.210	AFL							
PROC. REF: AMM 24-32-09-610-801PROC. REF: AMM 24-32-09-610-801								
24-32-09-610-801-02	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)							Service ATA:24
PN:100-0540-02	MOS/MSC		N/A					
SN:1483	HRS							
WC#: 24.220	AFL							
PROC. REF: AMM 24-32-09-610-801PROC. REF: AMM 24-32-09-610-801								
24-32-09-610-801-03	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)							Service ATA:24
PN:100-0540-02	MOS/MSC	30-Oct-24	N/A					
SN:1483	HRS	13773.3						
WC#: 24.220	AFL	7183						
PROC. REF: AMM 24-32-09-610-801PROC. REF: AMM 24-32-09-610-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-610-801-04 SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 BATTERY (32FP)								Service ATA:24
PN:100-0540-02	MOS/MSC	26-Nov-14	N/A					
SN:0601765	HRS	13029.05						
WC#: 24.230	AFL	6673						
PROC. REF: AMM 24-32-09-610-801PROC. REF: AMM 24-32-09-610-801								
24-32-09-610-801-05 SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC)								Service ATA:24
PN:100-0540-02	MOS/MSC	31-Mar-14	N/A					
SN:2017	HRS	12625.42						
WC#: 24.250	AFL	6516						
PROC. REF: AMM 24-32-09-610-801PROC. REF: AMM 24-32-09-610-801								
24-32-09-610-801-06 SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - EMERGENCY BATTERY (123F)								Service ATA:24
PN:PN	MOS/MSC		N/A					
SN:NOT INSTALLED	HRS							
WC#: 24.240	AFL							
PROC. REF: AMM 24-32-09-610-801PROC. REF: AMM 24-32-09-610-801								
24-32-09-710-802-01 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)								Service ATA:24
PN:100-0540-02	MOS	17-Sep-25	12 (+3%)		17-Sep-26	27-Sep-26	146 d (+10)	
SN:1986	HRS							
WC#: 24.210	AFL							
PROC. REF: AMM 24-32-09-710-802PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-02 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)								Service ATA:24
PN:100-0540-02	MOS	09-Oct-25	12 (+3%)		09-Oct-26	20-Oct-26	168 d (+11)	
SN:1483	HRS							
WC#: 24.220	AFL							
PROC. REF: AMM 24-32-09-710-802PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-03 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)								Service ATA:24
PN:100-0540-02	MOS	17-Nov-25	12 (+3%)		17-Nov-26	27-Nov-26	207 d (+10)	
SN:1483	HRS	13859.6						
WC#: 24.220	AFL	7277						
PROC. REF: AMM 24-32-09-710-802PROC. REF: AMM 24-32-09-710-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-710-802-04 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 3 BATTERY (32FP)								Service ATA:24
PN:100-0540-02	MOS	24-Apr-25	12 (+3%)		24-Apr-26	04-May-26	0 d (+10)	
SN:0601765	HRS	13836.2						
WC#: 24.230	AFL	7249						
PROC. REF: AMM 24-32-09-710-802PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-05 OPERATIONAL TEST VHF 3 STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)								Service ATA:24
PN:100-0540-02	MOS	24-Apr-25	12 (+3%)		24-Apr-26	04-May-26	0 d (+10)	
SN:2017	HRS	13836.2						
WC#: 24.250	AFL	7249						
PROC. REF: AMM 24-32-09-710-802PROC. REF: AMM 24-32-09-710-802								
24-32-09-710-802-06 OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - EMERGENCY BATTERY (123F)								Service ATA:24
PN:PN	MOS/MSC		N/A					
SN:NOT INSTALLED	HRS							
WC#: 24.240	AFL							
PROC. REF: AMM 24-32-09-710-802PROC. REF: AMM 24-32-09-710-802								
24-32-09-900-801-01 REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)								Component ATA:24
PN:100-0540-02	MOS/MSC	17-Sep-25	H/T					
SN:1986	HRS	13856.1		TSR 0				
WC#: 24.210	AFL	7271		TSR 0				
PROC. REF: AMM 24-32-09-900-801PROC. REF: AMM 24-32-09-900-801								
24-32-09-900-801-02 REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)								Component ATA:24
PN:100-0540-02	MOS/MSC	09-Oct-25	H/T					
SN:1483	HRS	13859.6						
WC#: 24.220	AFL	7277						
PROC. REF: AMM 24-32-09-900-801PROC. REF: AMM 24-32-09-900-801								
24-32-09-900-801-03 REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)								Component ATA:24
PN:100-0540-02	MOS/MSC	30-Oct-24	H/T					
SN:1483	HRS	13773.3						
WC#: 24.220	AFL	7183						
PROC. REF: AMM 24-32-09-900-801PROC. REF: AMM 24-32-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-900-801-04 REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 3 BATTERY (32FP)							Component	ATA:24
PN:100-0540-02	MOS/MSC	26-Nov-14	H/T	TSR 5				
SN:0601765	HRS	13029.05						
WC#: 24.230	AFL	6673						
PROC. REF: AMM 24-32-09-900-801PROC. REF: AMM 24-32-09-900-801								
24-32-09-900-801-05 REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC)							Component	ATA:24
PN:100-0540-02	MOS/MSC	31-Mar-14	H/T	TSO 0				
SN:2017	HRS	12625.42		TSO 0				
WC#: 24.250	AFL	6516		TSO 0				
PROC. REF: AMM 24-32-09-900-801PROC. REF: AMM 24-32-09-900-801								
24-32-09-900-801-06 REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - EMERGENCY BATTERY (123F)							Component	ATA:24
PN:PN	MOS/MSC		O/C					
SN:NOT INSTALLED	HRS							
WC#: 24.240	AFL							
PROC. REF: AMM 24-32-09-900-801PROC. REF: AMM 24-32-09-900-801								
24-32-09-960-802-01 DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - STAND-BY HORIZON BATTERY (4FG)							Service	ATA:24
PN:100-0540-02	MOS	17-Sep-25	48	17-Sep-29		1242 d	LIFE LIMIT	
SN:1986	HRS							
WC#: 24.210	AFL							
PROC. REF: AMM 24-32-09-960-802PROC. REF: AMM 24-32-09-960-802								
24-32-09-960-802-02 DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 1 BATTERY (L12FP)							Service	ATA:24
PN:100-0540-02	MOS	09-Oct-25	48	09-Oct-29		1264 d	LIFE LIMIT	
SN:1483	HRS							
WC#: 24.220	AFL							
PROC. REF: AMM 24-32-09-960-802PROC. REF: AMM 24-32-09-960-802								
24-32-09-960-802-03 DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 2 BATTERY (R12FP)							Service	ATA:24
PN:100-0540-02	MOS	30-Oct-24	48	30-Oct-28		920 d	LIFE LIMIT	
SN:1483	HRS	13773.3						
WC#: 24.220	AFL	7183						
PROC. REF: AMM 24-32-09-960-802PROC. REF: AMM 24-32-09-960-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-960-802-04		DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 3 BATTERY (32FP)						Service ATA:24
PN:100-0540-02	MOS/MSC	25-Mar-22	O/C					CUSTOMER OPTION
SN:0601765	HRS	13349.6						
WC#: 24.230	AFL	6796						
PROC. REF: AMM 24-32-09-960-802PROC. REF: AMM 24-32-09-960-802								
24-32-09-960-802-05		DISCARD VHF 3 STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)						Service ATA:24
PN:100-0540-02	MOS/MSC	25-Mar-22	O/C					CUSTOMER OPTION
SN:2017	HRS	13349.6						
WC#: 24.250	AFL	6796						
PROC. REF: AMM 24-32-09-960-802PROC. REF: AMM 24-32-09-960-802								
24-32-09-960-802-06		DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - EMERGENCY BATTERY (123F)						Service ATA:24
PN:PN	MOS/MSC	N/A						
SN:NOT INSTALLED	HRS			TAC 0				
WC#: 24.240	AFL							
PROC. REF: AMM 24-32-09-960-802PROC. REF: AMM 24-32-09-960-802								
24-33-01-900-801-01		REMOVAL / INSTALLATION OF THE APU STARTER-GENERATOR - APU STARTER-GENERATOR (21PA)						Component ATA:24
PN:8060-150	MOS/MSC	17-Jul-14	O/C					
SN:2391	HRS	12864.12						
WC#: 24.100	AFL	6621						
	APH	6254	0	TSO 658				
PROC. REF: AMM 24-33-01-900-801PROC. REF: AMM 24-33-01-900-801								
24-33-05-220-803-01		CHECK OF THE APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (21PA)						Service ATA:24
PN:8060-150	MOS	09-Feb-24						
SN:2391	HRS	13667.4						
	AFL	7071						
	APH	6569.2	450 (+30)		7019.2	7049.2	190.9 (+30)	
PROC. REF: AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803PROC. REF: AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-33-05-220-804-01	CHECK OF THE APU STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - APU STARTER-GENERATOR (21PA)							Service ATA:24
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 24-33-05-220-804PROC. REF: AMM 24-33-05-220-804								
24-33-05-220-805-01	CHECK OF THE APU STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - APU STARTER-GENERATOR (21PA)							Service ATA:24
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 24-33-05-220-805PROC. REF: AMM 24-33-05-220-805								
24-40-00-720-801-01 ^S	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB - EXTERNAL POWER RECEPTACLE OVERVOLTAGE PCB (CI11)							Service ATA:24
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 24.170	AFL	6741						
PROC. REF: AMM 24-40-00-720-801PROC. REF: AMM 24-40-00-720-801								PKG:21
24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE CHARGING FUNCTION							Service ATA:24
	MOS/MSC	04-Mar-02	O/C					
	HRS	5149						
	AFL	2372						
PROC. REF: AMM 24-41-00-720-801PROC. REF: AMM 24-41-00-720-801								
24-41-00-720-801-02	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES							Service ATA:24
	MOS/MSC	04-Mar-02	O/C					
	HRS	5149						
	AFL	2372						
PROC. REF: AMM 24-41-00-720-801PROC. REF: AMM 24-41-00-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-61-01-900-801-01 REMOVAL / INSTALLATION OF THE MAIN ELECTRICAL BOX - MAIN ELECTRICAL BOX (6PA)								Component ATA:24
PN:671GC01Y02	MOS/MSC	07-Feb-91	O/C					
SN:190	HRS	0		TSN 0				
WC#: 24.165	AFL	0						
PROC. REF: AMM 24-61-01-900-801PROC. REF: AMM 24-61-01-900-801								
24-63-13-710-801-01 ^S OPERATIONAL TEST OF THE DOME LIGHT PCB - DOME LIGHT CONTROL PCB (CI12)								Service ATA:24
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 24.200	AFL	6741						
PROC. REF: AMM 24-63-13-710-801PROC. REF: AMM 24-63-13-710-801								
243000 ^{U S} STATIC INVERTER INVERTER								Component ATA:24
PN:SB100	MOS/MSC	17-Aug-11	T:O/C	TSR 0				COMPLIED WITH
SN:184	HRS	11507.83		TSR 0				
	AFL	6078		TSR 0				
PKG:21								
PROC. REF: AMM 24-63-13-710-801PROC. REF: AMM 24-63-13-710-801								
243191 NO. 1 BATTERY TEMPERATURE PROBE								Component ATA:24
PN:P600-14B	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243201 NO. 2 BATTERY TEMPERATURE PROBE								Component ATA:24
PN:P600-14B	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243211 BATTERY TEMPERATURE INDICATOR								Component ATA:24
PN:BTI600-3A1S1	MOS/MSC	28-Nov-91	O/C					
SN:6332	HRS	363						
WC#: 24.050	AFL	264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243221	BATTERY BLOWER							Component ATA:24
PN:VA0906XXA	MOS/MSC	07-Feb-91	O/C					
SN:10649	HRS	0		TSN 0				
WC#: 24.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243251	NO. 1 BATTERY REVERSE CURRENT RELAY							Component ATA:24
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243261	NO. 2 BATTERY REVERSE CURRENT RELAY							Component ATA:24
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243501	NO. 1 GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243511	NO. 2 GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243521	NO. 3 GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243531	APU GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243601	LH DC AMMETER							Component ATA:24
PN:2396-323-0	MOS/MSC	17-Mar-05	O/C					
SN:785	HRS	7344.5						
WC#: 24.150	AFL	3844						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243611	RH DC AMMETER							Component ATA:24
PN:K615-0-0	MOS/MSC	27-Jan-06	O/C	TSN 0				
SN:UNKNOWN	HRS	8376.7		TSN 0				
WC#: 24.150	AFL	4401		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243621	LH DC VOLTMETER							Component ATA:24
PN:2396-118-0	MOS/MSC	07-Feb-91	O/C					
SN:1242	HRS	0		TSN 0				
WC#: 24.160	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243631	RH DC VOLTMETER							Component ATA:24
PN:2396-118-0	MOS/MSC	07-Feb-91	O/C					
SN:1140	HRS	0		TSN 0				
WC#: 24.160	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
243701	UPPER ELECTRICAL PANEL							Component ATA:24
PN:401TS06Y01	MOS/MSC	07-Feb-91	O/C					
SN:195	HRS	0		TSN 0				
WC#: 24.165	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
244101	GROUND POWER RECEPTACLE							Component ATA:24
PN:280C	MOS/MSC	07-Feb-91	O/C					
SN:15120	HRS	0		TSN 0				
WC#: 24.170	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
ATA 25 - EQUIPMENT/FURNISHINGS								
25-00-01-200-801-01	INSPECTION OF THE ONBOARD KIT							Service ATA:25
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 25.065	AFL	6673						
PROC. REF: AMM 25-00-01-200-801PROC. REF: AMM 25-00-01-200-801								
25-00-05-200-801-01 ^S	INSPECTION OF THE CREW AND PASSENGER SEAT HARNESSSES AND SAFETY BELTS							Service ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 25.010	AFL	7052	3750					
PROC. REF: AMM 25-00-05-200-801PKG:31 PROC. REF: AMM 25-00-05-200-801								
25-11-01-900-801-01	REMOVAL / INSTALLATION OF THE PILOT SEATS - LH PILOT SEAT (L2MG)							Component ATA:25
PN:132051-100	MOS/MSC	21-Aug-04	O/C	TSR 0				
SN:95	HRS	6777.4		TSR 0				
WC#: 25.020	AFL	3502		TSR 0				
PROC. REF: AMM 25-11-01-900-801PROC. REF: AMM 25-11-01-900-801								
25-11-01-900-801-02	REMOVAL / INSTALLATION OF THE PILOT SEATS - RH PILOT SEAT (R2MG)							Component ATA:25
PN:132-050-100	MOS/MSC	07-Feb-91	O/C					
SN:92	HRS	0		TSN 0				
WC#: 25.020	AFL	0						
PROC. REF: AMM 25-11-01-900-801PROC. REF: AMM 25-11-01-900-801								
25-11-05-200-801-01A	VISUAL INSPECTION OF PASSENGER SEAT BELT BUCKLES (MANDATORY 5-40)							Service ATA:25
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 25.030	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-11-05-200-801PROC. REF: AMM 25-11-05-200-801								
25-11-13-640-801-01	^S	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - LH PILOT SEAT (L2MG)					Service	ATA:25
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 25.020	AFL	6741						
								PKG:21
PROC. REF: AMM 25-11-13-640-801PROC. REF: AMM 25-11-13-640-801								
25-11-13-640-801-02	^S	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - RH PILOT SEAT (R2MG)					Service	ATA:25
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 25.020	AFL	6741						
								PKG:21
PROC. REF: AMM 25-11-13-640-801PROC. REF: AMM 25-11-13-640-801								
25-11-19-960-801-01	^S	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - LH PILOT SEAT (L2MG)					Service	ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 25-11-19-960-801PROC. REF: AMM 25-11-19-960-801								
25-11-19-960-801-02	^S	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - RH PILOT SEAT (R2MG)					Service	ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 25-11-19-960-801PROC. REF: AMM 25-11-19-960-801								
25-11-25-200-801-01	^S	INSPECTION OF THE PILOT SEAT ROLLER PINS - LH PILOT SEAT (L2MG)					Service	ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 25-11-25-200-801PROC. REF: AMM 25-11-25-200-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-25-200-801-02	^S	INSPECTION OF THE PILOT SEAT ROLLER PINS - RH PILOT SEAT (R2MG)						Service ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 25-11-25-200-801PROC. REF: AMM 25-11-25-200-801								PKG:31
25-12-00-210-801-01	^S	GENERAL VISUAL INSPECTION OF THE THIRD CREW MEMBER SEAT - THIRD CREW MEMBER SEAT (M1001MP)						Service ATA:25
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 25-12-00-210-801PROC. REF: AMM 25-12-00-210-801								PKG:5
25-20-00-210-801-01	^S	GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - PASSENGER DOOR ASSIST HANDLE						Service ATA:25
	MOS	22-Dec-23	72 (+2m)					SMM
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 25-20-00-210-801PROC. REF: AMM 25-20-00-210-801								PKG:31
25-20-00-210-801-02		GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - AFT LAVATORY ASSIST HANDLE						Service ATA:25
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-20-00-210-801PROC. REF: AMM 25-20-00-210-801								
25-20-00-220-801-01		INSPECTION / TEST OF THE WASTE CONTAINERS - INSPECTION / TEST OF WASTE CONTAINERS						Service ATA:25
	MOS	17-Feb-26						
	HRS	13885.3	1000 (+40)	Adj -3.95	14881.35	14921.35	985.1 (+40)	
	AFL	7304						
PROC. REF: AMM 25-20-00-220-801PROC. REF: AMM 25-20-00-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-20-00-220-802-01	^S	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF DOORS, DRAWERS AND THEIR RESPECTIVE LATCHING MECHANISMS						Service ATA:25
	MOS	22-Dec-23	72 (+2m)					SMM
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 25-20-00-220-802PROC. REF: AMM 25-20-00-220-802								PKG:31
25-20-00-220-802-02	^S	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF THE POP OUT WORK SURFACE						Service ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 25-20-00-220-802PROC. REF: AMM 25-20-00-220-802								PKG:31
25-20-00-220-802-05	^S	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - OPERATIONAL TEST OF TAMBOUR DOOR POWER CUT OFF FUNCTION						Service ATA:25
	MOS	22-Dec-23	72 (+2m)					SMM
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 25-20-00-220-802PROC. REF: AMM 25-20-00-220-802								PKG:31
25-21-00-220-801-01	^S	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE SINGLE AND DOUBLE SEATS						Service ATA:25
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
	AFL	7052						
PROC. REF: AMM 25-21-00-220-801PROC. REF: AMM 25-21-00-220-801								PKG:7
25-21-00-220-801-02	^S	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE DIVAN						Service ATA:25
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
	AFL	7052						
PROC. REF: AMM 25-21-00-220-801PROC. REF: AMM 25-21-00-220-801								PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-22-01-210-801-01	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES - CONSOLE TABLES IN LOCATIONS OTHER THAN EMERGENCY EXIT							Service ATA:25
	MOS/MSC	19-Dec-21	O/C					
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 25-22-01-210-801PROC. REF: AMM 25-22-01-210-801								
25-22-01-210-801-02	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES - CONSOLE TABLE IN FRONT OF EMERGENCY EXIT (IF INSTALLED)							Service ATA:25
	MOS/MSC	19-Dec-21	O/C					
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 25-22-01-210-801PROC. REF: AMM 25-22-01-210-801								
25-22-01-210-801-03 ^S	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES							Service ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 25-22-01-210-801PROC. REF: AMM 25-22-01-210-801								PKG:31
25-22-05-220-802-01 ^S	DETAILED INSPECTION OF THE DINING TABLE							Service ATA:25
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 25-22-05-220-802PROC. REF: AMM 25-22-05-220-802								PKG:31
25-23-61-210-801-01	GENERAL VISUAL INSPECTION OF THE TRACKING MAGAZINE RACK - INSPECTION OF THE TRACKING MAGAZINE RACK							Service ATA:25
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-23-61-210-801PROC. REF: AMM 25-23-61-210-801								
25-33-09-210-801-01	INSPECTION OF THE COFFEE MAKER / ESPRESSO MACHINE							Service ATA:25
	MOS/MSC	08-Aug-14	A/R					
	HRS	12881.35						
	AFL	6629						
PROC. REF: AMM 25-33-09-210-801PROC. REF: AMM 25-33-09-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-33-17-210-801-01	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN							Service ATA:25
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 25-33-17-210-801PROC. REF: AMM 25-33-17-210-801								
25-60-00-200-801-02 ^S	INSPECTION OF THE SAFETY EQUIPMENT - SAFETY EQUIPMENT							Service ATA:25
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 25.060	AFL	7304						
PROC. REF: AMM 25-60-00-200-801PROC. REF: AMM 25-60-00-200-801								
25-60-00-200-801-03	INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT							Service ATA:25
	MOS/MSC	13-Jan-25	DUE		31-Jan-28 (M)		647 d	
	HRS	13790.5						
	AFL	7204						
Expiry Date: : 31-Jan-28								
PROC. REF: AMM 25-60-00-200-801PROC. REF: AMM 25-60-00-200-801								
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)							Service ATA:25
	MOS	11-Dec-25	12		11-Dec-26		231 d	MANDATORY
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT 96/97 UNIT CONTROLS							Service ATA:25
	MOS/MSC	05-Jun-13	O/C					
	HRS	12205.82						
WC#: 25.070	AFL	6354						
PROC. REF: AMM 25-61-00-710-801PROC. REF: AMM 25-61-00-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-00-710-801-02	^S	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT 96/97 COCKPIT CONTROLS						Service ATA:25
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 25-61-00-710-801PROC. REF: AMM 25-61-00-710-801								PKG:17
25-61-00-710-801-03		OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT 96/97						Service ATA:25
	MOS	27-Mar-26	6 (+1m)	Adj -8d	19-Sep-26	19-Oct-26	148 d (+30)	
	HRS	13896.3						
	AFL	7313						
PROC. REF: AMM 25-61-00-710-801PROC. REF: AMM 25-61-00-710-801								
25-61-00-710-801-04		OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - OPERATIONAL TEST OF ELT 90/91						Service ATA:25
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-61-00-710-801PROC. REF: AMM 25-61-00-710-801								
25-61-01-710-801-01		OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) G-SWITCH - ELT (32RC)						Service ATA:25
	MOS	23-Mar-22	60 (+3%)		23-Mar-27	17-May-27	333 d (+55)	
	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-61-01-710-801PROC. REF: AMM 25-61-01-710-801								
25-61-01-900-803-01		REMOVAL / INSTALLATION OF THE ELT AND REPLACEMENT OF THE ELT BATTERY PACKS (ELT 90 / 91 OR ELT 96 / 97) - ELT (32RC)						Component ATA:25
PN:ELT96A2560000000	MOS/MSC	31-Mar-14	O/C	TSN 162				
SN:2438	HRS	12625.42						
WC#: 25.070	AFL	6516						
PROC. REF: AMM 25-61-01-900-803PROC. REF: AMM 25-61-01-900-803								
25-61-13-960-801-01		DISCARD OF THE ELT BATTERY PACKS - ELT (32RC)						Service ATA:25
PN:ELT96A2560000000	MOS/MSC	31-Oct-23	DUE		03-May-27 (M)		374 d	LIFE LIMIT
SN:2438	HRS	13613						
WC#: 25.070	AFL	7027						
PROC. REF: AMM 25-61-13-960-801PROC. REF: AMM 25-61-13-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-21-900-801-01		REMOVAL / INSTALLATION OF THE ELT ANTENNA - ELT ANTENNA (34RC)						Component ATA:25
PN:62080	MOS/MSC	03-Dec-04	O/C					
SN:703	HRS	7002.4		TSN 0				
WC#: 25.170	AFL	3654						
PROC. REF: AMM 25-61-21-900-801PROC. REF: AMM 25-61-21-900-801								
25-62-00-900-801-01		REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (900RK)						Component ATA:25
PN:DK120/90	MOS/MSC	23-Mar-22	O/C	TSN 0				
SN:AT115147	HRS	13349.6		TSN 0				
WC#: 31.070	AFL	6796		TSN 0				
PROC. REF: AMM 25-62-00-900-801PROC. REF: AMM 25-62-00-900-801								
25-62-00-900-801-02		REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)						Component ATA:25
PN:DK120/90	MOS/MSC	09-Jun-25	O/C					
SN:AT150210	HRS	13844.3						
WC#: 31.100	AFL	7258						
PROC. REF: AMM 25-62-00-900-801PROC. REF: AMM 25-62-00-900-801								
25-62-01-720-801-01		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (900RK)						Service ATA:25
PN:DK120/90	MOS	16-Apr-24	25 (+3%)		16-May-26	08-Jun-26	22 d (+23)	
SN:AT115147	HRS	13715.9						
WC#: 31.070	AFL	7118						
PROC. REF: AMM 25-62-01-720-801PROC. REF: AMM 25-62-01-720-801								
25-62-01-720-801-02		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)						Service ATA:25
PN:DK120/90	MOS	09-Jun-25	25 (+3%)		09-Jul-27	01-Aug-27	441 d (+23)	
SN:AT150210	HRS							
WC#: 31.100	AFL							
PROC. REF: AMM 25-62-01-720-801PROC. REF: AMM 25-62-01-720-801								
25-62-05-960-801-01		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - CVR ULB BATTERY (900RK1)						Service ATA:25
PN:DK120/90	MOS/MSC	09-Jun-25	DUE		30-Jun-32 (M)		2259 d	LIFE LIMIT
SN:AT115147	HRS	13844.3						
WC#: 31.070	AFL	7258						
Expiry Date: : 30-Jun-32								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-62-05-960-801PROC. REF: AMM 25-62-05-960-801								
25-62-05-960-801-02	RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - FDR ULB BATTERY (900FZ1)							Service ATA:25
PN:DK120/90	MOS/MSC	09-Jun-25	DUE		30-May-27 (M)		401 d	LIFE LIMIT
SN:AT150210	HRS	13844.3						
WC#: 31.100	AFL	7258						
Expiry Date: : 30-May-27								
PROC. REF: AMM 25-62-05-960-801PROC. REF: AMM 25-62-05-960-801								
25-63-00-350-801-01	RESTORATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) (OVERHAUL) - PILOT EVAS UNIT (L9510MP)							Service ATA:25
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-63-00-350-801PROC. REF: AMM 25-63-00-350-801								
25-63-00-350-801-02	RESTORATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) (OVERHAUL) - COPILOT EVAS UNIT (R9510MP)							Service ATA:25
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-63-00-350-801PROC. REF: AMM 25-63-00-350-801								
25-63-01-960-801-01	DISCARD OF THE EVAS BATTERY - PILOT EVAS UNIT (L9510MP)							Service ATA:25
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-63-01-960-801PROC. REF: AMM 25-63-01-960-801								
25-63-01-960-801-02	DISCARD OF THE EVAS BATTERY - COPILOT EVAS UNIT (R9510MP)							Service ATA:25
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-63-01-960-801PROC. REF: AMM 25-63-01-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 1 LIFE RAFT							Service ATA:25
PN:1218FAUL-3J0-1-301	MOS	23-Jun-25	36 (+3%)		23-Jun-28	25-Jul-28	791 d (+32)	
SN:12UL-00294	HRS	13844.3						
	AFL	7258						
PROC. REF: AMM 25-64-13-200-801PROC. REF: AMM 25-64-13-200-801								
25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 2 LIFE RAFT							Service ATA:25
PN:1218FAUL-3J0-1-301	MOS	23-Jun-25	36 (+3%)		23-Jun-28	25-Jul-28	791 d (+32)	
SN:12UL-00295	HRS	13844.3						
	AFL	7258						
PROC. REF: AMM 25-64-13-200-801PROC. REF: AMM 25-64-13-200-801								
25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 3 LIFE RAFT							Service ATA:25
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 25-64-13-200-801PROC. REF: AMM 25-64-13-200-801								
25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 4 LIFE RAFT							Service ATA:25
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-64-13-200-801PROC. REF: AMM 25-64-13-200-801								
25-64-13-350-801-01	RESTORATION OF THE LIFE RAFT (OVERHAUL) - NO. 1 LIFE RAFT							Service ATA:25
PN:1218FAUL-3J0-1-301	MOS	17-May-22	72 (+3%)		17-May-28	21-Jul-28	754 d (+65)	
SN:12UL-00294	HRS	13406.8						
WC#: 25.130	AFL	6846						
PROC. REF: AMM 25-64-13-350-801PROC. REF: AMM 25-64-13-350-801								
25-64-13-350-801-01	RESTORATION OF THE LIFE RAFT (OVERHAUL) - NO. 2 LIFE RAFT							Service ATA:25
PN:1218FAUL-3J0-1-301	MOS	16-May-22	72 (+3%)		16-May-28	20-Jul-28	753 d (+65)	
SN:12UL-00295	HRS	13387						
WC#: 25.130	AFL	6826						
PROC. REF: AMM 25-64-13-350-801PROC. REF: AMM 25-64-13-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-13-900-801-01		NO. 1 LIFE RAFT					Component	ATA:25
PN:1218FAUL-3J0-1-301	MOS/MSC	17-May-22	O/C	TSO 0				
SN:12UL-00294	HRS	13406.8		TSO 0				
WC#: 25.130	AFL	6846		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-13-900-801-02		NO. 2 LIFE RAFT					Component	ATA:25
PN:1218FAUL-3J0-1-301	MOS/MSC	16-May-22	O/C	TSO 0				
SN:12UL-00295	HRS	13387		TSO 0				
WC#: 25.130	AFL	6826		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-13-960-801-01		DISCARD OF THE LIFE RAFT - NO. 1 LIFE RAFT					Service	ATA:25
PN:1218FAUL-3J0-1-301	MOS/MSC		O/C					
SN:12UL-00294	HRS							
	AFL							
PROC. REF: AMM 25-64-13-960-801PROC. REF: AMM 25-64-13-960-801								
25-64-13-960-801-01		DISCARD OF THE LIFE RAFT - NO. 2 LIFE RAFT					Service	ATA:25
PN:1218FAUL-3J0-1-301	MOS/MSC		O/C					
SN:12UL-00295	HRS							
	AFL							
PROC. REF: AMM 25-64-13-960-801PROC. REF: AMM 25-64-13-960-801								
25-64-13-960-801-01		DISCARD OF THE LIFE RAFT - NO. 3 LIFE RAFT					Service	ATA:25
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-64-13-960-801PROC. REF: AMM 25-64-13-960-801								
25-64-17-350-802-01		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - LH PILOT LIFE VEST (L10ME)					Service	ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:4-05-21335	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-802PROC. REF: AMM 25-64-17-350-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-350-802-02		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - RH PILOT LIFE VEST (R10ME)						Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:4-10-10765	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-802PROC. REF: AMM 25-64-17-350-802								
25-64-17-350-802-03		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - THIRD CREW MEMBER LIFE VEST (M10ME)						Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:3-11-10006-1660	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-802PROC. REF: AMM 25-64-17-350-802								
25-64-17-350-803-01		RESTORATION NO. 15 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)						Service ATA:25
PN:S-10002-1300-999002	MOS/MSC	25-Mar-22	O/C					
SN:11-09-12557	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 1 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:3-11-10016-1660	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 10 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:6-01-43055	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 11 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:3-11-9972-1660	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 12 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001		MOS/MSC	23-Mar-22	O/C				
SN:3-11-9981-1660		HRS	13349.6					
		AFL	6796					
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 13 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001		MOS/MSC	25-Mar-22	O/C				
SN:3-11-9930		HRS	13349.6					
		AFL	6796					
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 14 PASSENGER LIFE VEST						Service ATA:25
PN:S-51150-6300-999001		MOS/MSC	25-Mar-22	O/C				
SN:3-11-9987		HRS	13349.6					
		AFL	6796					
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 16 PASSENGER LIFE VEST						Service ATA:25
PN:S-10002-1300-999002		MOS/MSC	23-Mar-22	O/C				
SN:9-08-13081-1660		HRS	13349.6					
		AFL	6796					
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 17 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001		MOS/MSC	25-Mar-22	O/C				
SN:3-11-10048		HRS	13349.6					
		AFL	6796					
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 2 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001		MOS/MSC	23-Mar-22	O/C				
SN:5-98-30731		HRS	13349.6					
		AFL	6796					
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-350-803-01 RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 3 PASSENGER LIFE VEST								Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:12-04-71362	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 4 PASSENGER LIFE VEST								Service ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C					
SN:L28418	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 5 PASSENGER LIFE VEST								Service ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C					
SN:L28441	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 6 PASSENGER LIFE VEST								Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:4-10-10744	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 7 PASSENGER LIFE VEST								Service ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C					
SN:L247039	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-350-803-01 RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 8 PASSENGER LIFE VEST								Service ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C					
SN:L21327	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 9 PASSENGER LIFE VEST						Service ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C					
SN:3-11-9998-1660	HRS	13349.6						
	AFL	6796						
PROC. REF: AMM 25-64-17-350-803PROC. REF: AMM 25-64-17-350-803								
25-64-17-900-802-01		PILOT LIFE VEST						Component ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:4-05-21335	HRS	13349.6		TSO 0				
WC#: 25.080	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-802-02		COPILOT LIFE VEST						Component ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:4-10-10765	HRS	13349.6		TSO 0				
WC#: 25.080	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-802-03		THIRD CREW MEMBER LIFE VEST						Component ATA:25
PN:S51150-6300-999001	MOS/MSC	27-May-11	O/C	TSN 0				
SN:3-11-10006-1660	HRS	11414.25		TSN 0				
WC#: 25.085	AFL	6044		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-01		NO. 1 PASSENGER LIFE VEST						Component ATA:25
PN:S51150-6300-999001	MOS/MSC	27-May-11	O/C	TSN 0				
SN:3-11-10016-1660	HRS	11414.25		TSN 0				
WC#: 25.090	AFL	6044		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-02		NO. 2 PASSENGER LIFE VEST						Component ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:5-98-30731	HRS	13349.6		TSO 0				
WC#: 25.090	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-900-803-03		NO. 3 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:L2-04-71362	HRS	13349.6		TSO 0				
WC#: 25.095	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-04		NO. 4 PASSENGER LIFE VEST					Component	ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:L28418	HRS	13349.6		TSO 0				
WC#: 25.095	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-05		NO. 5 PASSENGER LIFE VEST					Component	ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:L28441	HRS	13349.6		TSO 0				
WC#: 25.100	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-06		NO. 6 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:4-10-10744	HRS	13349.6		TSO 0				
WC#: 25.100	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-07		NO. 7 PASSENGER LIFE VEST					Component	ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:L247039	HRS	13349.6		TSO 0				
WC#: 25.105	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-08		NO. 8 PASSENGER LIFE VEST					Component	ATA:25
PN:63600-101	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:L21327	HRS	13349.6		TSO 0				
WC#: 25.105	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-900-803-09		NO. 9 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	27-May-11	O/C	TSN 0				
SN:3-11-9998-1660	HRS	11414.25		TSN 0				
WC#: 25.110	AFL	6044		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-10		NO. 10 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	23-Mar-22	O/C	TSO 0				
SN:6-01-43055	HRS	13349.6		TSO 0				
WC#: 25.110	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-11		NO. 11 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	27-May-11	O/C	TSN 0				
SN:3-11-9972-1660	HRS	11414.25		TSN 0				
WC#: 25.120	AFL	6044		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-12		NO. 12 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	27-May-11	O/C	TSN 0				
SN:3-11-9981-1660	HRS	11414.25		TSN 0				
WC#: 25.120	AFL	6044		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-13		NO. 13 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	25-Mar-22	O/C	TSO 0				
SN:3-11-9930	HRS	13349.6		TSO 0				
WC#: 25.125	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-14		NO. 14 PASSENGER LIFE VEST					Component	ATA:25
PN:S-51150-6300-999001	MOS/MSC	25-Mar-22	O/C	TSO 0				
SN:3-11-9987	HRS	13349.6		TSO 0				
WC#: 25.125	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-900-803-15		NO. 15 PASSENGER LIFE VEST					Component	ATA:25
PN:S-10002-1300-999002	MOS/MSC	25-Mar-22	O/C	TSO 0				
SN:11-09-12557	HRS	13349.6		TSO 0				
WC#: 25.140	AFL	6796		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-16		NO. 16 PASSENGER LIFE VEST					Component	ATA:25
PN:S-10002-1300-999002	MOS/MSC	25-Mar-10	O/C					
SN:9-08-13081-1660	HRS	10865.5						
WC#: 25.140	AFL	5891						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
25-64-17-900-803-17		NO. 17 PASSENGER LIFE VEST					Component	ATA:25
PN:S51150-6300-999001	MOS/MSC	25-Mar-22	O/C	TSO 0				
SN:3-11-10048	HRS	13349.6		TSO 0				
WC#: 25.150	AFL	6796		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25-90-01-900-801-03		THIRD CREW MEMBER SEAT					Component	ATA:25
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
251141		PILOT SEAT BELT					Component	ATA:25
PN:1101167-09	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
251151		COPILOT SEAT BELT					Component	ATA:25
PN:1101168-18	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
251161	PILOT HARNESS							Component ATA:25
PN:2825A3X03	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.040	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
251171	COPILOT HARNESS							Component ATA:25
PN:2825A3X03	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.040	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
253A03 ^U	#1 OVEN							Component ATA:25
PN:400-1409-02-L	MOS/MSC	08-Jun-05	O/C	TSR 0				
SN:00-11-27910	HRS	7646.2		TSR 0				
	AFL	4010		TSR 0				
256010 ^U	FIRST AID KIT							Component ATA:25 O/C - ON CONDITION
PN:FL220-FAKFAA	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:0921-2236	HRS	13441.5		TSN 0				
	AFL	6881		TSN 0				
256391	LAVATORY BLOWER							Component ATA:25
PN:EVT205D	MOS/MSC	25-Mar-10	O/C	TSR 1				
SN:106	HRS	10865.5		TSR 0				
WC#: 25.160	AFL	5891		TSR 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
ATA 26 - FIRE PROTECTION								
26-10-00-720-801-01	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2WG)							Service ATA:26
PN:36017090040013	MOS/MSC	22-Nov-07	E/C					
SN:77065	HRS	10138.1	7500		17638.1		3741.8	
WC#: 26.020	AFL	5422						
PROC. REF: AMM 26-10-00-720-801PROC. REF: AMM 26-10-00-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-10-00-720-801-02		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2WG)						Service ATA:26
PN:3601-82-900/400-15	MOS/MSC	12-Jun-09	E/C					
SN:105245	HRS	10850.2	7500		18350.2		4453.9	
WC#: 26.020	AFL	5878						
PROC. REF: AMM 26-10-00-720-801PROC. REF: AMM 26-10-00-720-801								
26-10-00-720-801-03		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2WG)						Service ATA:26
PN:36017090040013	MOS/MSC	14-Nov-11	E/C					
SN:75942	HRS	11568.42	7500		19068.42		5172.1	
WC#: 26.030	AFL	6104						
PROC. REF: AMM 26-10-00-720-801PROC. REF: AMM 26-10-00-720-801								
26-10-00-720-801-04		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - APU FIRE DETECTOR (9WG)						Service ATA:26
PN:36018190040009	MOS/MSC	22-Nov-07	C/C					
SN:76751	HRS	10138.1						
WC#: 26.040	AFL	5422						
	APH	4687	5000		9687		2858.7	
PROC. REF: AMM 26-10-00-720-801PROC. REF: AMM 26-10-00-720-801								
26-10-00-720-801-05		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)						Service ATA:26
PN:300119800270-3	MOS/MSC	12-Jun-09	O/C	Adj -70d				
SN:66475	HRS	10850.2						
WC#: 26.050	AFL	5878						
PROC. REF: AMM 26-10-00-720-801PROC. REF: AMM 26-10-00-720-801								
26-10-00-720-801-06		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)						Service ATA:26
PN:300119800270-3	MOS	06-Apr-22	72 (+3%)		06-Apr-28	10-Jun-28	713 d (+65)	
SN:66477	HRS	13355.8						
WC#: 26.050	AFL	6803						
PROC. REF: AMM 26-10-00-720-801PROC. REF: AMM 26-10-00-720-801								
26-10-17-720-801-01		FUNCTIONAL TEST OF THE PINPOINT FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)						Service ATA:26
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 26.050	AFL	0						
PROC. REF: AMM 26-10-17-720-801PROC. REF: AMM 26-10-17-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-10-17-720-801-02	FUNCTIONAL TEST OF THE PINPOINT FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)							Service ATA:26
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 26.050	AFL	0						
PROC. REF: AMM 26-10-17-720-801PROC. REF: AMM 26-10-17-720-801								
26-10-17-900-801-01	REMOVAL / INSTALLATION OF THE MAIN LANDING GEAR BAY PINPOINT FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)							Component ATA:26
PN:300119800270-3	MOS/MSC	07-Feb-91	O/C					
SN:66475	HRS	0		TSN 0				
WC#: 26.050	AFL	0						
PROC. REF: AMM 26-10-17-900-801PROC. REF: AMM 26-10-17-900-801								
26-10-17-900-801-02	REMOVAL / INSTALLATION OF THE MAIN LANDING GEAR BAY PINPOINT FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)							Component ATA:26
PN:300119800270-3	MOS/MSC	07-Feb-91	O/C					
SN:66477	HRS	0		TSN 0				
WC#: 26.050	AFL	0						
PROC. REF: AMM 26-10-17-900-801PROC. REF: AMM 26-10-17-900-801								
26-10-19-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2WG)							Component ATA:26
PN:36017090040013	MOS/MSC	07-Feb-91	O/C					
SN:77065	HRS	0		TSN 0				
WC#: 26.020	AFL	0						
PROC. REF: AMM 26-10-19-900-801PROC. REF: AMM 26-10-19-900-801								
26-10-19-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2WG)							Component ATA:26
PN:3601-82-900/400-15	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:105245	HRS	10850.2		TSN 0				
WC#: 26.020	AFL	5878		TSN 0				
PROC. REF: AMM 26-10-19-900-801PROC. REF: AMM 26-10-19-900-801								
26-10-19-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2WG)							Component ATA:26
PN:36017090040013	MOS/MSC	07-Feb-91	O/C					
SN:75942	HRS	0		TSN 0				
WC#: 26.030	AFL	0						
PROC. REF: AMM 26-10-19-900-801PROC. REF: AMM 26-10-19-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-10-19-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - APU FIRE DETECTOR (9WG)							Component ATA:26
PN:36018190040009	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:76751	HRS	0		TSN 0				
WC#: 26.040	AFL	0		TSN 0				
PROC. REF: AMM 26-10-19-900-801PROC. REF: AMM 26-10-19-900-801								
26-20-00-760-801-01	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (L3WB) AND (L4WB)							Service ATA:26
	MOS/MSC	17-Sep-25	O/C					
	HRS	13856.1						
WC#: 26.080	AFL	7271						
PROC. REF: AMM 26-20-00-760-801PROC. REF: AMM 26-20-00-760-801								
26-20-00-760-801-02	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (R5WB) AND (R6WB)							Service ATA:26
	MOS/MSC	17-Sep-25	O/C					
	HRS	13856.1						
WC#: 26.090	AFL	7271						
PROC. REF: AMM 26-20-00-760-801PROC. REF: AMM 26-20-00-760-801								
26-20-00-760-801-03	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (L5WB) AND (L6WB)							Service ATA:26
	MOS/MSC	17-Sep-25	O/C					
	HRS	13856.1						
WC#: 26.100	AFL	7271						
PROC. REF: AMM 26-20-00-760-801PROC. REF: AMM 26-20-00-760-801								
26-20-00-760-801-04	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (R3WB) AND (R4WB)							Service ATA:26
	MOS/MSC	17-Sep-25	O/C					
	HRS	13856.1						
WC#: 26.110	AFL	7271						
PROC. REF: AMM 26-20-00-760-801PROC. REF: AMM 26-20-00-760-801								
26-20-00-760-801-05	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (9WB) AND (27WB)							Service ATA:26
	MOS/MSC	17-Sep-25	O/C					
	HRS	13856.1						
WC#: 26.120	AFL	7271						
PROC. REF: AMM 26-20-00-760-801PROC. REF: AMM 26-20-00-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-01-760-801-01	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 1 "DISCH" SWITCH (2WB9) (POSITION "1")					Service	ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-02	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 1 "DISCH" SWITCH (2WB9) (POSITION "2")					Service	ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-03	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 2 "DISCH" SWITCH (2WB14) (POSITION "1")					Service	ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-04	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 2 "DISCH" SWITCH (2WB14) (POSITION "2")					Service	ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-05	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 3 "DISCH" SWITCH (2WB19) (POSITION "1")					Service	ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-01-760-801-06	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 3 "DISCH" SWITCH (2WB19) (POSITION "2")						Service ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								PKG:31
26-20-01-760-801-07	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE APU" SWITCH (2WB3)						Service ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 26.180	AFL	7052	3750					
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								PKG:31
26-20-01-760-801-08	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE BAG COMP" SWITCH (2WB1)						Service ATA:26
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 26.180	AFL	7052	3750					
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								PKG:31
26-20-01-900-801-01		REMOVAL / INSTALLATION OF THE FIRE CONTROL PANEL - FIRE CONTROL PANEL (2WB)						Component ATA:26
PN:90350-1	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:168	HRS	0		TSN 0				
WC#: 26.010	AFL	0		TSN 0				
PROC. REF: AMM 26-20-01-900-801PROC. REF: AMM 26-20-01-900-801								
26-20-09-220-801-01		WEIGHING OF THE FIRE EXTINGUISHERS - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB)						Service ATA:26
PN:861630	MOS	17-Sep-25	12 (+1m)	18-Aug-26	18-Sep-26	116 d (+31)		
SN:56301	HRS	13856.1						
WC#: 26.120	AFL	7271						
WeightCheck Date : : 18-Aug-25								
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-09-220-801-02	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)							Service ATA:26
PN:861630	MOS	17-Sep-25	12 (+1m)		18-Aug-26	18-Sep-26	116 d (+31)	
SN:24941	HRS	13856.1						
WC#: 26.080	AFL	7271						
WeightCheck Date : : 18-Aug-25								
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								
26-20-09-220-801-03	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)							Service ATA:26
PN:861630	MOS	17-Sep-25	12 (+1m)		18-Aug-26	18-Sep-26	116 d (+31)	
SN:57543	HRS	13856.1						
WC#: 26.100	AFL	7271						
WeightCheck Date : : 18-Aug-25								
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								
26-20-09-220-801-04	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)							Service ATA:26
PN:861630	MOS	17-Sep-25	12 (+1m)		18-Aug-26	18-Sep-26	116 d (+31)	
SN:22585	HRS	13856.1						
WC#: 26.110	AFL	7271						
WeightCheck Date : : 18-Aug-25								
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								
26-20-09-220-801-05	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)							Service ATA:26
PN:863470-01	MOS	17-Sep-25	18 (+3%)		18-Feb-27	05-Mar-27	300 d (+15)	
SN:UE00703	HRS	13856.1						
WC#: 26.090	AFL	7271						
WeightCheck Date : : 18-Aug-25								
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								
26-20-09-350-801-01	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB)							Service ATA:26
PN:861630	MOS	12-Jul-21	60		12-Jul-26		79 d	MANDATORY
SN:56301	HRS							
WC#: 26.120	AFL							
HydroCheck Date: : 12-Jul-21								
PROC. REF: AMM 26-20-09-350-801PROC. REF: AMM 26-20-09-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-09-350-801-02	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)							Service ATA:26
PN:861630	MOS	23-Jul-21	60		23-Jul-26		90 d	MANDATORY
SN:24941	HRS							
WC#: 26.080	AFL							
HydroCheck Date: : 23-Jul-21								
PROC. REF: AMM 26-20-09-350-801PROC. REF: AMM 26-20-09-350-801								
26-20-09-350-801-03	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)							Service ATA:26
PN:861630	MOS	12-Jul-21	60		12-Jul-26		79 d	MANDATORY
SN:57543	HRS							
WC#: 26.100	AFL							
HydroCheck Date: : 12-Jul-21								
PROC. REF: AMM 26-20-09-350-801PROC. REF: AMM 26-20-09-350-801								
26-20-09-350-801-04	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)							Service ATA:26
PN:861630	MOS	01-Jul-21	60		31-Jul-26		98 d	MANDATORY
SN:22585	HRS							
WC#: 26.110	AFL							
HydroCheck Date: : 01-Jul-21								
PROC. REF: AMM 26-20-09-350-801PROC. REF: AMM 26-20-09-350-801								
26-20-09-350-801-05	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)							Service ATA:26
PN:863470-01	MOS	12-Jul-21	120		12-Jul-31		1905 d	MANDATORY
SN:UE00703	HRS							
WC#: 26.090	AFL							
HydroCheck Date: : 12-Jul-21								
PROC. REF: AMM 26-20-09-350-801PROC. REF: AMM 26-20-09-350-801								
26-20-09-900-801-01	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB)							Component ATA:26
PN:861630	MOS/MSC	19-Dec-21	H/T	TSO 0				
SN:56301	HRS	13275.5		TSO 0				
WC#: 26.120	AFL	6741		TSO 0				
PROC. REF: AMM 26-20-09-900-801PROC. REF: AMM 26-20-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-09-900-801-02	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)						Component	ATA:26
PN:861630	MOS/MSC	19-Dec-21	H/T	TSN 412, TSO 0				
SN:24941	HRS	13275.5	TSO 0					
WC#: 26.080	AFL	6741	TSO 0					
PROC. REF: AMM 26-20-09-900-801PROC. REF: AMM 26-20-09-900-801								
26-20-09-900-801-03	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)						Component	ATA:26
PN:861630	MOS/MSC	19-Dec-21	H/T	TSN 270, TSO 0				
SN:57543	HRS	13275.5	TSO 0					
WC#: 26.100	AFL	6741	TSO 0					
PROC. REF: AMM 26-20-09-900-801PROC. REF: AMM 26-20-09-900-801								
26-20-09-900-801-04	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)						Component	ATA:26
PN:861630	MOS/MSC	19-Dec-21	H/T	TSO 0				
SN:22585	HRS	13275.5	TSO 0					
WC#: 26.110	AFL	6741	TSO 0					
PROC. REF: AMM 26-20-09-900-801PROC. REF: AMM 26-20-09-900-801								
26-20-09-900-801-05	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)						Component	ATA:26
PN:863470-01	MOS/MSC	19-Dec-21	H/T	TSO 0				
SN:UE00703	HRS	13275.5	TSO 0					
WC#: 26.090	AFL	6741	TSO 0					
PROC. REF: AMM 26-20-09-900-801PROC. REF: AMM 26-20-09-900-801								
26-20-11-700-801-01	CHECKING OF THE APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER FOR CLOGGING						Service	ATA:26
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
	AFL	5878						
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-11-700-801-02	CHECKING OF THE NO. 1 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING							Service ATA:26
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
	AFL	5878						
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-11-700-801-03	CHECKING OF THE NO. 2 ENGINE FIRST-SHOOT, NO. 1 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING							Service ATA:26
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
	AFL	5878						
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-11-700-801-04	CHECKING OF THE NO. 3 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING							Service ATA:26
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
	AFL	5878						
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-11-700-801-05	CHECKING OF THE NO. 2 ENGINE FIRST-SHOOT, NO. 3 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING							Service ATA:26
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
	AFL	5878						
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-11-700-801-07 ^S	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE A							Service ATA:26
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								PKG:31
26-20-11-700-801-08 ^S	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE B							Service ATA:26
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-11-700-801-09	^S	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE C					Service	ATA:26
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-11-700-801-10	^S	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE D					Service	ATA:26
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-11-700-801-11	^S	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE E					Service	ATA:26
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-11-700-801-12	^S	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE F					Service	ATA:26
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 26-20-11-700-801PROC. REF: AMM 26-20-11-700-801								
26-20-12-900-801-01		REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 1 SHUTTLE VALVE (L509WB)					Component	ATA:26
PN:861585	MOS/MSC	30-Jan-07	H/T					
SN:4798	HRS	9294.2		TSN 0				
WC#: 26.200	AFL	4969						
PROC. REF: AMM 26-20-12-900-801PROC. REF: AMM 26-20-12-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-12-900-801-02 REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 3 SHUTTLE VALVE (R509WB)								Component ATA:26
PN:861585	MOS/MSC	07-Feb-91	H/T					
SN:1438	HRS	0		TSN 0				
WC#: 26.200	AFL	0						
PROC. REF: AMM 26-20-12-900-801PROC. REF: AMM 26-20-12-900-801								
26-20-12-900-801-03 REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 2 LH SHUTTLE VALVE (M509WB1)								Component ATA:26
PN:861585	MOS/MSC	07-Feb-91	H/T					
SN:1415	HRS	0		TSN 0				
WC#: 26.210	AFL	0						
PROC. REF: AMM 26-20-12-900-801PROC. REF: AMM 26-20-12-900-801								
26-20-12-900-801-04 REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 2 RH SHUTTLE VALVE (M509WB2)								Component ATA:26
PN:861585	MOS/MSC	07-Feb-91	H/T					
SN:1416	HRS	0		TSN 0				
WC#: 26.210	AFL	0						
PROC. REF: AMM 26-20-12-900-801PROC. REF: AMM 26-20-12-900-801								
26-20-12-960-801-01 DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 1 SHUTTLE VALVE (L509WB)								Service ATA:26
PN:861585	MOS/MSC	30-Jan-07	A/R					SCRAP
SN:4798	HRS	9294.2		TAC 0				
	AFL	4969						
PROC. REF: AMM 26-20-12-960-801PROC. REF: AMM 26-20-12-960-801								
26-20-12-960-801-02 DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 3 SHUTTLE VALVE (R509WB)								Service ATA:26
PN:861585	MOS/MSC	07-Feb-91	A/R					SCRAP
SN:1438	HRS	0		TAC 0				
	AFL	0						
PROC. REF: AMM 26-20-12-960-801PROC. REF: AMM 26-20-12-960-801								
26-20-12-960-801-03 DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 2 LH SHUTTLE VALVE (M509WB1)								Service ATA:26
PN:861585	MOS/MSC	07-Feb-91	A/R					SCRAP
SN:1415	HRS	0		TAC 0				
	AFL	0						
PROC. REF: AMM 26-20-12-960-801PROC. REF: AMM 26-20-12-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-12-960-801-04		DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 2 RH SHUTTLE VALVE (M509WB2)						Service ATA:26
PN:861585	MOS/MSC	07-Feb-91	A/R					SCRAP
SN:1416	HRS	0		TAC 0				
	AFL	0						
PROC. REF: AMM 26-20-12-960-801PROC. REF: AMM 26-20-12-960-801								
26-20-13-900-801-01		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)						Component ATA:26
PN:862710-00	MOS/MSC	13-May-24	H/T					
SN:LH/F9211	HRS	13723.5						
	AFL	7126						
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-900-801-02		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R3WB)						Component ATA:26
PN:M861375	MOS/MSC	17-Sep-25	H/T					
SN:UNKNOWN	HRS	13856.1		TSN 0				
	AFL	7271		TSN 0				
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-900-801-03		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)						Component ATA:26
PN:862700-00	MOS/MSC	05-Jan-24	H/T					
SN:F9211	HRS	13641						
	AFL	7052						
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-900-801-04		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT RH PERCUSSION CARTRIDGE (R4WB)						Component ATA:26
PN:M861385	MOS/MSC	17-Sep-25	H/T					
SN:UNKNOWN	HRS	13856.1		TSN 0				
	AFL	7271		TSN 0				
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-900-801-05		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L5WB)					Component	ATA:26
PN:M861385	MOS/MSC	17-Sep-25	H/T					
SN:UNKNOWN	HRS	13856.1		TSN 0				
	AFL	7271		TSN 0				
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-900-801-06		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)					Component	ATA:26
PN:861375	MOS/MSC	03-Mar-26	H/T					
SN:01570	HRS	13888.3						
	AFL	7308						
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-900-801-07		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT LH PERCUSSION CARTRIDGE (L6WB)					Component	ATA:26
PN:M861375	MOS/MSC	17-Sep-25	H/T					
SN:UNKNOWN	HRS	13856.1		TSN 0				
	AFL	7271		TSN 0				
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-900-801-08		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB)					Component	ATA:26
PN:M861385	MOS/MSC	17-Sep-25	H/T					
SN:UNKNOWN	HRS	13856.1		TSN 0				
	AFL	7271		TSN 0				
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-900-801-09		REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (27WB)					Component	ATA:26
PN:M861375	MOS/MSC	17-Sep-25	H/T					
SN:UNKNOWN	HRS	13856.1		TSN 0				
	AFL	7271		TSN 0				
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-900-801-10	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (9WB)							Component ATA:26
PN:M861385	MOS/MSC	17-Sep-25	H/T					
SN:UNKNOWN	HRS	13856.1		TSN 0				
	AFL	7271		TSN 0				
PROC. REF: AMM 26-20-13-900-801PROC. REF: AMM 26-20-13-900-801								
26-20-13-960-801-01	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)							Service ATA:26
PN:862710-00	MOS	26-Aug-21	60		26-Aug-26		124 d	SCRAP
SN:LH/F9211	HRS							
WC#: 26.080	AFL							
Installation Date: : 26-Aug-21								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-01M	DISCARD NO. 1 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (L3WB) CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:862710-00	MOS	30-Sep-17	120		30-Sep-27		524 d	LIFE LIMIT
SN:LH/F9211	HRS	13723.5						
WC#: 26.080	AFL	7126						
Manufacture Date:: 30-Sep-17								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-02	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R3WB)							Service ATA:26
PN:M861375	MOS	17-Sep-25	60		17-Sep-30		1607 d	SCRAP
SN:UNKNOWN	HRS	13856.1						
WC#: 26.110	AFL	7271						
Installation Date: : 17-Sep-25								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-02M	DISCARD NO. 3 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (R3WB) CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:M861375	MOS	17-Sep-25	84		17-Sep-32 (M)		2338 d	LIFE LIMIT
SN:UNKNOWN	HRS	13856.1						
WC#: 26.110	AFL	7271						
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-03		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)						Service ATA:26
PN:862700-00	MOS/MSC	05-Jan-24	O/C					
SN:F9211	HRS							
WC#: 26.080	AFL							
Installation Date: : 05-Jan-24								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-03M		DISCARD NO. 2 ENGINE SECOND SHOOT LH FIRE EXTINGUISHER PERCUSSION (L4WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:862700-00	MOS	30-Jun-19	120		30-Jun-29		1163 d	LIFE LIMIT
SN:F9211	HRS							
WC#: 26.080	AFL							
Manufacture Date:: 30-Jun-19								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-04		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT RH PERCUSSION CARTRIDGE (R4WB)						Service ATA:26
PN:M861385	MOS	17-Sep-25	60		17-Sep-30		1607 d	SCRAP
SN:UNKNOWN	HRS	13856.1						
WC#: 26.110	AFL	7271						
Installation Date: : 17-Sep-25								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-04M		DISCARD NO. 2 ENGINE SECOND SHOOT RH FIRE EXTINGUISHER PERCUSSION (R4WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:M861385	MOS	17-Sep-25	84		17-Sep-32 (M)		2338 d	LIFE LIMIT
SN:UNKNOWN	HRS	13856.1						
WC#: 26.110	AFL	7271						
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-05		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L5WB)						Service ATA:26
PN:M861385	MOS	17-Sep-25	60		17-Sep-30		1607 d	SCRAP
SN:UNKNOWN	HRS	13856.1						
WC#: 26.100	AFL	7271						
Installation Date: : 17-Sep-25								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-05M		DISCARD NO. 1 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (L5WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:M861385	MOS	17-Sep-25	84		17-Sep-32 (M)		2338 d	LIFE LIMIT
SN:UNKNOWN	HRS	13856.1						
WC#: 26.100	AFL	7271						
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-06		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)						Service ATA:26
PN:861375	MOS	03-Mar-26	60		03-Mar-31		1774 d	SCRAP
SN:01570	HRS							
WC#: 26.090	AFL							
Installation Date: : 03-Mar-26								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-06M		DISCARD NO. 3 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (R5WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:861375	MOS	03-Mar-26	84		28-May-28		765 d	LIFE LIMIT
SN:01570	HRS							
WC#: 26.090	AFL							
Manufacture Date:: 28-May-21								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-07		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT LH PERCUSSION CARTRIDGE (L6WB)						Service ATA:26
PN:M861375	MOS	17-Sep-25	60		17-Sep-30		1607 d	SCRAP
SN:UNKNOWN	HRS	13856.1						
WC#: 26.100	AFL	7271						
Installation Date: : 17-Sep-25								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-07M		DISCARD NO. 2 ENGINE FIRST SHOOT LH FIRE EXTINGUISHER PERCUSSION (L6WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:M861375	MOS	17-Sep-25	84		17-Sep-32 (M)		2338 d	LIFE LIMIT
SN:UNKNOWN	HRS	13856.1						
WC#: 26.100	AFL	7271						
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-08		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB)						Service ATA:26
PN:M861385	MOS	17-Sep-25	60		17-Sep-30		1607 d	SCRAP
SN:UNKNOWN	HRS	13856.1						
WC#: 26.090	AFL	7271						
Installation Date: : 17-Sep-25								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-08M		DISCARD NO. 2 ENGINE FIRST SHOOT RH FIRE EXTINGUISHER PERCUSSION (R6WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:M861385	MOS	17-Sep-25	84		17-Sep-32 (M)		2338 d	LIFE LIMIT
SN:UNKNOWN	HRS	13856.1						
WC#: 26.090	AFL	7271						
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-09		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (27WB)						Service ATA:26
PN:M861375	MOS	17-Sep-25	60		17-Sep-30		1607 d	SCRAP
SN:UNKNOWN	HRS	13856.1						
WC#: 26.120	AFL	7271						
Installation Date: : 17-Sep-25								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-09M		DISCARD APU FIRE EXTINGUISHER PERCUSSION (27WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:M861375	MOS	17-Sep-25	84		17-Sep-32 (M)		2338 d	LIFE LIMIT
SN:UNKNOWN	HRS	13856.1						
WC#: 26.120	AFL	7271						
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-13-960-801-10		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (9WB)						Service ATA:26
PN:M861385	MOS	17-Sep-25	60		17-Sep-30		1607 d	SCRAP
SN:UNKNOWN	HRS	13856.1						
WC#: 26.120	AFL	7271						
Installation Date: : 17-Sep-25								
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-10M		DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (9WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:M861385	MOS	17-Sep-25	84		17-Sep-32 (M)		2338 d	LIFE LIMIT
SN:UNKNOWN	HRS	13856.1						
WC#: 26.120	AFL	7271						
PROC. REF: AMM 26-20-13-960-801PROC. REF: AMM 26-20-13-960-801								
26-20-15-720-801-01		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service ATA:26
PN:898052	MOS	17-Feb-26	24 (+3%)		17-Feb-28	08-Mar-28	664 d (+20)	
SN:Y-170777	HRS	13885.3						
WC#: 26.130	AFL	7304						
WeightCheck Date : : 17-Feb-26								
PROC. REF: AMM 26-20-15-720-801PROC. REF: AMM 26-20-15-720-801								
26-20-15-720-801-02		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service ATA:26
PN:PN	MOS/MSC	05-Jul-22	N/A					
SN:NOT INSTALLED	HRS							
WC#: 26.140	AFL							
PROC. REF: AMM 26-20-15-720-801PROC. REF: AMM 26-20-15-720-801								
26-20-15-720-801-03		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service ATA:26
PN:898052	MOS	17-Feb-26	24 (+3%)		17-Feb-28	08-Mar-28	664 d (+20)	
SN:Y-76635	HRS	13885.3						
WC#: 26.150	AFL	7304						
WeightCheck Date : : 17-Feb-26								
PROC. REF: AMM 26-20-15-720-801PROC. REF: AMM 26-20-15-720-801								
26-20-15-790-801-01		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service ATA:26
PN:898052	MOS	31-Jan-24	144		31-Jan-36		3569 d	
SN:Y-170777	HRS							
WC#: 26.130	AFL							
HydroCheck Date : : 31-Jan-24								
PROC. REF: AMM 26-20-15-790-801PROC. REF: AMM 26-20-15-790-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-15-790-801-02		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service ATA:26
PN:PN	MOS/MSC	05-Jul-22	N/A					
SN:NOT INSTALLED	HRS							
WC#: 26.140	AFL							
PROC. REF: AMM 26-20-15-790-801PROC. REF: AMM 26-20-15-790-801								
26-20-15-790-801-03		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service ATA:26
PN:898052	MOS	31-Jan-24	144		31-Jan-36		3569 d	
SN:Y-76635	HRS							
WC#: 26.150	AFL							
HydroCheck Date: : 31-Jan-24								
PROC. REF: AMM 26-20-15-790-801PROC. REF: AMM 26-20-15-790-801								
261251		BAGGAGE COMPARTMENT SMOKE DETECTOR						Component ATA:26
PN:FR2220	MOS/MSC	28-Mar-97	O/C	TSN 0				
SN:127	HRS	2674		TSN 0				
WC#: 26.060	AFL			TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
261301		NO. 1 AND NO. 3 ENGINE MONITOR BOX						Component ATA:26
PN:6342-01	MOS/MSC	07-Feb-91	O/C					
SN:425	HRS	0		TSN 0				
WC#: 26.070	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
261311		NO. 2 ENGINE AND APU FIRE MONITOR BOX						Component ATA:26
PN:6342-01	MOS/MSC	07-Feb-91	O/C					
SN:455	HRS	0		TSN 0				
WC#: 26.070	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
262601		COCKPIT PORTABLE HALON FIRE EXTINGUISHER						Component ATA:26
PN:898052	MOS/MSC	09-Feb-24	O/C	TSO 0				
SN:Y-170777	HRS	13667.4		TSO 0				
WC#: 26.130	AFL	7071		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262651	FORWARD CABIN PORTABLE HALON FIRE EXTINGUISHER							Component ATA:26
PN:PN	MOS/MSC	05-Jul-22	O/C					
SN:NOT INSTALLED	HRS							
WC#: 26.140	AFL							
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
262701	AFT CABIN PORTABLE HALON FIRE EXTINGUISHER							Component ATA:26
PN:898052	MOS/MSC	28-Feb-24	O/C	TSO 0				
SN:Y-76635	HRS	13672.3		TSO 0				
WC#: 26.150	AFL	7075		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
ATA 27 - FLIGHT CONTROLS								
27-00-00-220-801-01A	INTEGRITY CHECK AND VISUAL INSPECTION FOR CORROSION AND EXTERNAL LEAKS ON FLIGHT CONTROL HYDRAULIC COMPONENTS (MANDATORY 5-40)							Service ATA:27
	MOS	05-Jun-13						MANDATORY 5-40
	HRS	12205.82	4000		16205.82		2309.5	
WC#: 27.010	AFL	6354						
PROC. REF: AMM 27-00-00-220-801PROC. REF: AMM 27-00-00-220-801								
27-00-00-640-801-01 ^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - LH AILERON SERVO-ACTUATOR (L521CC)							Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.065	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-801PROC. REF: AMM 27-00-00-640-801								PKG:32
27-00-00-640-801-02 ^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - RH AILERON SERVO-ACTUATOR (R521CC)							Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.065	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-801PROC. REF: AMM 27-00-00-640-801								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-640-801-03	^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - RUDDER SERVO-ACTUATOR (571CC)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.125	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-801PROC. REF: AMM 27-00-00-640-801								PKG:32
27-00-00-640-801-04	^S	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - ELEVATOR SERVO-ACTUATOR (522CW)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.200	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-801PROC. REF: AMM 27-00-00-640-801								PKG:32
27-00-00-640-803-01	^S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.020	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-803PROC. REF: AMM 27-00-00-640-803								PKG:32
27-00-00-640-804-01	^S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.015	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-804PROC. REF: AMM 27-00-00-640-804								PKG:32
27-00-00-640-806-01	^S	VISUAL INSPECTION AND GREASING OF YAW AND PITCH CONTROL SEALED BOXES - RUDDER						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.155	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-806PROC. REF: AMM 27-00-00-640-806								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-640-806-02	^S	VISUAL INSPECTION AND GREASING OF YAW AND PITCH CONTROL SEALED BOXES - ELEVATOR						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.252	AFL	6741	7500					
PROC. REF: AMM 27-00-00-640-806PROC. REF: AMM 27-00-00-640-806								PKG:32
27-00-00-710-801-01	^S	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 1						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-00-00-710-801PROC. REF: AMM 27-00-00-710-801								PKG:21
27-00-00-710-801-02	^S	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 2						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-00-00-710-801PROC. REF: AMM 27-00-00-710-801								PKG:21
27-00-00-710-802-01	^S	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL TRIM						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 27-00-00-710-802PROC. REF: AMM 27-00-00-710-802								PKG:31
27-00-00-710-802-02	^S	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL EMERGENCY TRIM						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 27-00-00-710-802PROC. REF: AMM 27-00-00-710-802								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-710-802-03	^S	OPERATIONAL TEST OF THE TRIM SYSTEMS - YAW TRIM						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.075	AFL	7052	3750					
PROC. REF: AMM 27-00-00-710-802PROC. REF: AMM 27-00-00-710-802								PKG:31
27-00-00-720-803-01	^S	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - LH ROLL AAFU (L522CC)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.095	AFL	6741	7500					
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								PKG:32
27-00-00-720-803-01A		FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - LH ROLL AAFU (L522CC) (MANDATORY 5-40)						Service ATA:27
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	10000		23275.5		9379.2	
WC#: 27.095	AFL	6741						
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								
27-00-00-720-803-02	^S	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - RH ROLL AAFU (R522CC)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.095	AFL	6741	7500					
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								PKG:32
27-00-00-720-803-02A		FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - RH ROLL AAFU (R522CC) (MANDATORY 5-40)						Service ATA:27
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	10000		23275.5		9379.2	
WC#: 27.095	AFL	6741						
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-720-803-03	^S	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - PITCH AAFU (523CW)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.230	AFL	6741	7500					
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								PKG:32
27-00-00-720-803-03A		FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - PITCH AAFU (523CW) (MANDATORY 5-40)						Service ATA:27
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	10000		23275.5		9379.2	
WC#: 27.230	AFL	6741						
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								
27-00-00-720-803-04	^S	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - YAW AAFU (572CC)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.165	AFL	6741	7500					
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								PKG:32
27-00-00-720-803-04A		FUNCTIONAL CHECK (AAFU CONNECTION AND VISUAL INSPECTION) (MANDATORY 5-40)						Service ATA:27
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	10000		23275.5		9379.2	
WC#: 27.165	AFL	6741						
PROC. REF: AMM 27-00-00-720-803PROC. REF: AMM 27-00-00-720-803								
27-00-00-720-807-01		DETAILED CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - AILERON						Service ATA:27
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-00-00-720-807PROC. REF: AMM 27-00-00-720-807								
27-00-00-720-807-02		DETAILED CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - RUDDER						Service ATA:27
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-00-00-720-807PROC. REF: AMM 27-00-00-720-807								
27-00-00-720-807-03	DETAILED CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - ELEVATOR							Service ATA:27
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-00-00-720-807PROC. REF: AMM 27-00-00-720-807								
27-00-00-790-804-01 ^S	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L521CC)							Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.065	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 27-00-00-790-804PROC. REF: AMM 27-00-00-790-804								
27-00-00-790-804-02 ^S	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R521CC)							Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.065	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 27-00-00-790-804PROC. REF: AMM 27-00-00-790-804								
27-00-00-790-804-03 ^S	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - RUDDER SERVO-ACTUATOR (571CC)							Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.125	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 27-00-00-790-804PROC. REF: AMM 27-00-00-790-804								
27-00-00-790-804-04 ^S	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - ELEVATOR SERVO-ACTUATOR (522CW)							Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.200	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 27-00-00-790-804PROC. REF: AMM 27-00-00-790-804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-900-806-01		REMOVAL / INSTALLATION OF THE AIRBRAKE / TAILPLANE / TRIM CONTROL BOX - AIRBRAKE/TAILPLANE/TRIM CONTROL BOX (2CF)					Component	ATA:27
PN:013015-14	MOS/MSC	07-Feb-91	O/C					
SN:1276	HRS	0		TSN 0				
WC#: 27.035	AFL	0						
PROC. REF: AMM 27-00-00-900-806PROC. REF: AMM 27-00-00-900-806								
27-12-01-900-801-01		REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L521CC)					Component	ATA:27
PN:103117-05	MOS/MSC	19-Dec-21	O/C					
SN:645	HRS	13275.5						
WC#: 27.065	AFL	6741						
PROC. REF: AMM 27-12-01-900-801PROC. REF: AMM 27-12-01-900-801								
27-12-01-900-801-02		REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R521CC)					Component	ATA:27
PN:103117-06	MOS/MSC	05-Jun-13	O/C	TSR 9				
SN:15	HRS	12205.82						
WC#: 27.065	AFL	6354						
PROC. REF: AMM 27-12-01-900-801PROC. REF: AMM 27-12-01-900-801								
27-13-01-640-806-01 ^S		LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA					Service	ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 27-13-01-640-806PROC. REF: AMM 27-13-01-640-806								PKG:31
27-13-01-640-808-01 ^S		GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA					Service	ATA:27
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 27.050	AFL	7304						
PROC. REF: AMM 27-13-01-640-808PROC. REF: AMM 27-13-01-640-808								PKG:16
27-13-01-900-802-01		REMOVAL / INSTALLATION OF THE CONTROL WHEEL - PILOT CONTROL WHEEL (10CR)					Component	ATA:27
PN:FGFB215250850	MOS/MSC	07-Feb-91	O/C					
SN:103	HRS	0		TSN 0				
WC#: 27.025	AFL	0						
PROC. REF: AMM 27-13-01-900-802PROC. REF: AMM 27-13-01-900-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-13-01-900-802-02	REMOVAL / INSTALLATION OF THE CONTROL WHEEL - COPILOT CONTROL WHEEL (20CR)							Component ATA:27
PN:FGFB215500850	MOS/MSC	07-Feb-91	O/C					
SN:106	HRS	0		TSN 0				
WC#: 27.030	AFL	0						
PROC. REF: AMM 27-13-01-900-802PROC. REF: AMM 27-13-01-900-802								
27-13-03-960-801-01 ^S	REPLACEMENT OF THE FR15 ROLL BELLCRANK BALL BEARINGS - LH FR15 ROLL BELLCRANK BALL BEARINGS							Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 27-13-03-960-801PROC. REF: AMM 27-13-03-960-801								
27-13-03-960-801-02 ^S	REPLACEMENT OF THE FR15 ROLL BELLCRANK BALL BEARINGS - RH FR15 ROLL BELLCRANK BALL BEARINGS							Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 27-13-03-960-801PROC. REF: AMM 27-13-03-960-801								
27-13-05-640-801-01 ^S	VISUAL INSPECTION AND GREASING OF ROLL CONTROL SEALED BOXES - LH ROLL PRESSURE-SEALED BOX (L14CC)							Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.097	AFL	6741	7500					
PROC. REF: AMM 27-13-05-640-801PROC. REF: AMM 27-13-05-640-801								
27-13-05-640-801-02 ^S	VISUAL INSPECTION AND GREASING OF ROLL CONTROL SEALED BOXES - RH ROLL PRESSURE-SEALED BOX (R14CC)							Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.097	AFL	6741	7500					
PROC. REF: AMM 27-13-05-640-801PROC. REF: AMM 27-13-05-640-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-14-01-350-801-01		RESTORATION OF THE ROLL TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL TRIM ACTUATOR (13CC)						Service ATA:27
PN:021057-32	MOS/MSC	03-Apr-03	O/C					
SN:7925	HRS	5826.4						
WC#: 27.080	AFL	2849						
PROC. REF: AMM 27-14-01-350-801PROC. REF: AMM 27-14-01-350-801								
27-14-01-900-801-01		REMOVAL / INSTALLATION OF THE ROLL TRIM ACTUATOR - ROLL TRIM ACTUATOR (13CC)						Component ATA:27
PN:021057-32	MOS/MSC	07-Feb-91	O/C					
SN:7925	HRS	0		TSN 0				
WC#: 27.080	AFL	0						
PROC. REF: AMM 27-14-01-900-801PROC. REF: AMM 27-14-01-900-801								
27-14-03-350-801-01		RESTORATION OF THE ROLL EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL EMERGENCY TRIM ACTUATOR (22CC)						Service ATA:27
PN:021127	MOS/MSC	12-Jun-09	O/C	Adj -65d				
SN:412	HRS	10850.2						
WC#: 27.070	AFL	5878						
PROC. REF: AMM 27-14-03-350-801PROC. REF: AMM 27-14-03-350-801								
27-14-03-900-801-01		REMOVAL / INSTALLATION OF THE EMERGENCY ROLL TRIM ACTUATOR - ROLL EMERGENCY TRIM ACTUATOR (22CC)						Component ATA:27
PN:021127	MOS/MSC	26-Jun-09	O/C					
SN:412	HRS	10850.2						
WC#: 27.070	AFL	5878						
PROC. REF: AMM 27-14-03-900-801PROC. REF: AMM 27-14-03-900-801								
27-14-05-720-801-01 ^S		FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.085	AFL	6741	7500					
PROC. REF: AMM 27-14-05-720-801, AMM 27-14-05-720-801PROC. REF: AMM 27-14-05-720-801, AMM 27-14-05-720-801								PKG:32
27-14-05-720-801-01A		FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS - ROLL TRIM RELAY BOX (12CC) (MANDATORY 5-40)						Service ATA:27
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	20000		33275.5		19379.2	
WC#: 27.085	AFL	6741						
PROC. REF: AMM 27-14-05-720-801, AMM 27-14-05-720-801PROC. REF: AMM 27-14-05-720-801, AMM 27-14-05-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-15-01-640-801-01	^S	PRESSURE GREASING OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS - ROLL ARTHUR VARIABLE BELLCRANK (33CW)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.060	AFL	6741	7500					
PROC. REF: AMM 27-15-01-640-801PROC. REF: AMM 27-15-01-640-801								PKG:32
27-15-01-720-801-01	^S	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (33CW)						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.060	AFL	7052	3750					
PROC. REF: AMM 27-15-01-720-801PROC. REF: AMM 27-15-01-720-801								PKG:31
27-15-01-900-801-01		REMOVAL / INSTALLATION OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (33CW)						Component ATA:27
PN:106043-28	MOS/MSC	29-Aug-08	O/C	TSR 0				
SN:2052	HRS	10680.1		TSR 0				
WC#: 27.060	AFL	5757		TSR 0				
PROC. REF: AMM 27-15-01-900-801PROC. REF: AMM 27-15-01-900-801								
27-15-03-960-801-01		REPLACEMENT OF THE SEALS ON THE SWIVEL COUPLING OF THE ROLL ARTHUR VARIABLE BELLCRANK						Service ATA:27
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 27-15-03-960-801PROC. REF: AMM 27-15-03-960-801								
27-15-05-350-801-01		RESTORATION OF THE ROLL MAIN AFU (FUNCTIONAL TEST / SERVICING) - ROLL MAIN AFU (523CC)						Service ATA:27
PN:105124	MOS/MSC	03-Apr-03	O/C					
SN:105	HRS	5826.4						
	AFL	2849						
PROC. REF: AMM 27-15-05-350-801PROC. REF: AMM 27-15-05-350-801								
27-15-05-900-801-01		REMOVAL / INSTALLATION OF THE ROLL MAIN AFU - ROLL MAIN AFU (523CC)						Component ATA:27
PN:105124	MOS/MSC	07-Feb-91	O/C					
SN:105	HRS	0		TSN 0				
WC#: 27.090	AFL	0						
PROC. REF: AMM 27-15-05-900-801PROC. REF: AMM 27-15-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-15-07-640-801-01	^S	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - LH ROLL AAFU (L522CC)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.095	AFL	6741	7500					
PKG:32								
PROC. REF: AMM 27-15-07-640-801PROC. REF: AMM 27-15-07-640-801								
27-15-07-640-801-02	^S	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - RH ROLL AAFU (R522CC)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.095	AFL	6741	7500					
PKG:32								
PROC. REF: AMM 27-15-07-640-801PROC. REF: AMM 27-15-07-640-801								
27-22-01-350-801-01		RESTORATION OF THE RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) - RUDDER SERVO-ACTUATOR (571CC)						Service ATA:27
PN:103103-18	MOS	03-Dec-10						
SN:1087	HRS	11147.5	4000		15147.5		1251.2	
WC#: 27.125	AFL	5962						
PROC. REF: AMM 27-22-01-350-801PROC. REF: AMM 27-22-01-350-801								
27-22-01-350-801-01A		RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-10)						Service ATA:27
PN:103103-18	MOS	03-Dec-10						MANDATORY 5-40
SN:1087	HRS	11147.5	4000		15147.5		1251.2	
WC#: 27.125	AFL	5962						
PROC. REF: AMM 27-22-01-350-801PROC. REF: AMM 27-22-01-350-801								
27-22-01-900-801-01		REMOVAL / INSTALLATION OF THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (571CC)						Component ATA:27
PN:103103-18	MOS/MSC	03-Dec-10	O/C	TSR 0				
SN:1087	HRS	11147.5		TSR 0				
WC#: 27.125	AFL	5962		TSR 0				
PROC. REF: AMM 27-22-01-900-801PROC. REF: AMM 27-22-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-23-01-640-806-01	^S	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.115	AFL	7052	3750					
PROC. REF: AMM 27-23-01-640-806PROC. REF: AMM 27-23-01-640-806								PKG:31
27-23-01-640-807-01	^S	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.110	AFL	7052	3750					
PROC. REF: AMM 27-23-01-640-807PROC. REF: AMM 27-23-01-640-807								PKG:31
27-23-01-640-808-01	^S	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						Service ATA:27
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 27.105	AFL	7304						
PROC. REF: AMM 27-23-01-640-808PROC. REF: AMM 27-23-01-640-808								PKG:16
27-24-01-350-801-01		RESTORATION OF THE YAW TRIM ACTUATOR (FUNCTIONAL TEST) - YAW TRIM ACTUATOR (3CC)						Service ATA:27
PN:021057-28	MOS/MSC	03-Apr-03	O/C					
SN:8147	HRS	5826.4						
WC#: 27.145	AFL	2849						
PROC. REF: AMM 27-24-01-350-801PROC. REF: AMM 27-24-01-350-801								
27-24-01-900-801-01		REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW TRIM ACTUATOR (3CC)						Component ATA:27
PN:021057-28	MOS/MSC	07-Feb-91	O/C					
SN:8147	HRS	0		TSN 0				
WC#: 27.145	AFL	0						
PROC. REF: AMM 27-24-01-900-801PROC. REF: AMM 27-24-01-900-801								
27-24-01-900-801-02		REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW MAIN AFU (573CC)						Component ATA:27
PN:105125	MOS/MSC	07-Feb-91	O/C					
SN:94	HRS	0		TSN 0				
WC#: 27.160	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-24-01-900-801PROC. REF: AMM 27-24-01-900-801								
27-24-05-720-802-01	S	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.150	AFL	6741	7500					
PKG:32								
PROC. REF: AMM 27-24-05-720-802, AMM 27-24-05-720-802PROC. REF: AMM 27-24-05-720-802, AMM 27-24-05-720-802								
27-24-05-720-802-01A		FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS - YAW TRIM RELAY BOX (2CC) (MANDATORY 5-40)						Service ATA:27
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	20000		33275.5		19379.2	
WC#: 27.150	AFL	6741						
PROC. REF: AMM 27-24-05-720-802, AMM 27-24-05-720-802PROC. REF: AMM 27-24-05-720-802, AMM 27-24-05-720-802								
27-25-05-350-801-01		RESTORATION OF THE YAW MAIN AFU (FUNCTIONAL TEST / SERVICING) - YAW MAIN AFU (573CC)						Service ATA:27
PN:105125	MOS/MSC	03-Apr-03	O/C					
SN:94	HRS	5826.4						
	AFL	2849						
PROC. REF: AMM 27-25-05-350-801PROC. REF: AMM 27-25-05-350-801								
27-25-07-350-801-01		RESTORATION OF THE YAW AUXILIARY AFU (FUNCTIONAL TEST / SERVICING) - YAW AAFU (572CC)						Service ATA:27
PN:105070-04	MOS/MSC	03-Apr-03	O/C					
SN:853	HRS	5826.4						
	AFL	2849						
PROC. REF: AMM 27-25-07-350-801PROC. REF: AMM 27-25-07-350-801								
27-25-07-900-801-01		REMOVAL / INSTALLATION OF THE YAW AUXILIARY AFU - YAW AAFU (572CC)						Component ATA:27
PN:105070-04	MOS/MSC	07-Feb-91	O/C					
SN:853	HRS	0		TSN 0				
WC#: 27.165	AFL	0						
PROC. REF: AMM 27-25-07-900-801PROC. REF: AMM 27-25-07-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-01-640-801-01	^S	GREASING OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (L8TB)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.025	AFL	6741	7500					
PROC. REF: AMM 27-31-01-640-801PROC. REF: AMM 27-31-01-640-801								PKG:32
27-31-01-640-801-02	^S	GREASING OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (R8TB)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.030	AFL	6741	7500					
PROC. REF: AMM 27-31-01-640-801PROC. REF: AMM 27-31-01-640-801								PKG:32
27-32-01-350-801-01		RESTORATION OF THE ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST) - ELEVATOR SERVO-ACTUATOR (522CW)						Service ATA:27
PN:103129	MOS	10-Aug-07						
SN:233	HRS	9902.6	10000 (+3%)		19902.6	20202.6	6006.3 (+300)	
	AFL	5277						
PROC. REF: AMM 27-32-01-350-801PROC. REF: AMM 27-32-01-350-801								
27-32-01-350-801-01A		RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-10)						Service ATA:27
PN:103129	MOS	07-Feb-91						MANDATORY 5-40
SN:233	HRS	0	14000		14000		103.7	
WC#: 27.200	AFL	0						
PROC. REF: AMM 27-32-01-350-801PROC. REF: AMM 27-32-01-350-801								
27-32-01-900-801-01		REMOVAL / INSTALLATION OF THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (522CW)						Component ATA:27
PN:103129	MOS/MSC	10-Aug-07	O/C					
SN:233	HRS	9902.6		TSR 0				
WC#: 27.200	AFL	5277						
PROC. REF: AMM 27-32-01-900-801PROC. REF: AMM 27-32-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-33-01-640-806-01	^S	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.185	AFL	7052	3750					
PROC. REF: AMM 27-33-01-640-806PROC. REF: AMM 27-33-01-640-806								PKG:31
27-33-01-640-807-01	^S	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						Service ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.180	AFL	7052	3750					
PROC. REF: AMM 27-33-01-640-807PROC. REF: AMM 27-33-01-640-807								PKG:31
27-33-01-640-808-01	^S	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHING OUTSIDE PRESSURIZED AREA						Service ATA:27
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 27.175	AFL	7304						
PROC. REF: AMM 27-33-01-640-808PROC. REF: AMM 27-33-01-640-808								PKG:16
27-35-00-720-801-01	^S	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.193	AFL	6741						
PROC. REF: AMM 27-35-00-720-801, AMM 27-35-00-720-801PROC. REF: AMM 27-35-00-720-801, AMM 27-35-00-720-801								PKG:22
27-35-01-640-801-01	^S	PRESSURE GREASING OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARINGS - PITCH ARTHUR VARIABLE BELLCRANK (43CW)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.195	AFL	6741	7500					
PROC. REF: AMM 27-35-01-640-801PROC. REF: AMM 27-35-01-640-801								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-35-01-900-801-01		REMOVAL / INSTALLATION OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (43CW)						Component ATA:27
PN:106126-01	MOS/MSC		O/C					
SN:29	HRS	3557						
WC#: 27.195	AFL							
PROC. REF: AMM 27-35-01-900-801PROC. REF: AMM 27-35-01-900-801								
27-35-05-350-801-01		RESTORATION OF THE PITCH MAIN AFU (FUNCTIONAL TEST / SERVICING) - PITCH MAIN AFU (524CW)						Service ATA:27
PN:105122-02	MOS/MSC	03-Apr-03	O/C					
SN:112	HRS	5826.4						
	AFL	2849						
PROC. REF: AMM 27-35-05-350-801PROC. REF: AMM 27-35-05-350-801								
27-35-05-900-801-01		REMOVAL / INSTALLATION OF THE PITCH MAIN AFU - PITCH MAIN AFU (524CW)						Component ATA:27
PN:105122-02	MOS/MSC	07-Feb-91	O/C					
SN:112	HRS	0		TSN 0				
WC#: 27.225	AFL	0						
PROC. REF: AMM 27-35-05-900-801PROC. REF: AMM 27-35-05-900-801								
27-35-07-350-801-01		RESTORATION OF THE PITCH AUXILIARY AFU (DISCARD OF BUSHINGS 1050450002) - PITCH AAFU (523CW)						Service ATA:27
PN:105045-13	MOS/MSC	03-Sep-10	O/C					MANDATORY 5-40
SN:3798	HRS	11012.17						
WC#: 27.230	AFL	5930						
PROC. REF: AMM 27-35-07-350-801PROC. REF: AMM 27-35-07-350-801								
27-35-07-350-801-01A		RESTORATION PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT (DISCARD OF BUSHING 105040002) (MANDATORY 5-40)						Service ATA:27
PN:105045-13	MOS/MSC	03-Sep-10	O/C					MANDATORY 5-40
SN:3798	HRS	11012.17						
	AFL	5930						
PROC. REF: AMM 27-35-07-350-801PROC. REF: AMM 27-35-07-350-801								
27-35-07-640-801-01 ^S		PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS - PITCH AAFU (523CW)						Service ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.230	AFL	6741	7500					
PROC. REF: AMM 27-35-07-640-801PROC. REF: AMM 27-35-07-640-801								

PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-35-07-900-801-01 REMOVAL / INSTALLATION OF THE PITCH AUXILIARY AFU - PITCH AAFU (523CW)								Component ATA:27
PN:105045-13	MOS/MSC	03-Sep-10	O/C	TSO 0				
SN:3798	HRS	11012.17		TSO 0				
WC#: 27.230	AFL	5930		TSO 0				
PROC. REF: AMM 27-35-07-900-801PROC. REF: AMM 27-35-07-900-801								
27-40-00-720-801-01 ^S FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM								Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.245	AFL	6741						
PROC. REF: AMM 27-40-00-720-801PROC. REF: AMM 27-40-00-720-801								
27-40-01-210-802-01 VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)								Service ATA:27
PN:021121-11	MOS	19-Dec-21	72 (+3%)	19-Dec-27	23-Feb-28	604 d (+66)		
SN:298	HRS	13275.5						
WC#: 27.255	AFL	6741	3750 (+3%)	10491	10603.5	3178 (+112.5)		
PROC. REF: AMM 27-40-01-210-802PROC. REF: AMM 27-40-01-210-802								
27-40-01-350-801-01 RESTORATION OF THE HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT) - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)								Service ATA:27
PN:021121-11	MOS/MSC	03-Apr-03	O/C					
SN:298	HRS	5826.4						
WC#: 27.255	AFL	2849						
PROC. REF: AMM 27-40-01-350-801PROC. REF: AMM 27-40-01-350-801								
27-40-01-640-802-01 ^S GREASING OF THE HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)								Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
WC#: 27.255	AFL	7304						
PROC. REF: AMM 27-40-01-640-802PROC. REF: AMM 27-40-01-640-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40-01-720-801-01	^S	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - NORMAL ELECTRIC MOTOR (93CFA)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.250	AFL	6741						
PROC. REF: AMM 27-40-01-720-801PROC. REF: AMM 27-40-01-720-801								PKG:21
27-40-01-720-801-02	^S	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - EMERGENCY ELECTRIC MOTOR (93CFB)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-40-01-720-801PROC. REF: AMM 27-40-01-720-801								PKG:21
27-40-01-900-801-01		REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)						Component ATA:27
PN:021121-11	MOS/MSC	26-Jun-09	O/C	TSO 74				
SN:298	HRS	10850.2		TSO 5024.2				
WC#: 27.255	AFL	5878		TSO 3029				
PROC. REF: AMM 27-40-01-900-801PROC. REF: AMM 27-40-01-900-801								
27-40-03-100-802-01		CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR NORMAL MOTOR - NORMAL ELECTRIC MOTOR (93CFA)						Service ATA:27
	MOS	13-Jan-23						
	HRS	13482.5	600 (+40)	Adj -1.15	14081.35	14121.35	185.1 (+40)	
WC#: 27.260	AFL	6909						
PROC. REF: AMM 27-40-03-100-802PROC. REF: AMM 27-40-03-100-802								
27-40-03-760-801-01		MEASUREMENT OF THE DROP-OUT CURRENT OF THE ELECTROMAGNETIC BRAKE OF HS ACTUATOR NORMAL MOTOR - NORMAL ELECTRIC MOTOR (93CFA)						Service ATA:27
	MOS/MSC	08-Aug-14	O/C					
	HRS	12881.35						
WC#: 27.260	AFL	6629						
PROC. REF: AMM 27-40-03-760-801PROC. REF: AMM 27-40-03-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40-03-900-801-01		REMOVAL / INSTALLATION OF THE NORMAL MOTOR OF THE HORIZONTAL STABILIZER ACTUATOR - NORMAL ELECTRIC MOTOR (93CFA)					Component	ATA:27
PN:1234	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.260	AFL	0						
PROC. REF: AMM 27-40-03-900-801PROC. REF: AMM 27-40-03-900-801								
27-40-05-900-801-01		REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER POSITION REPEATER BOX - HS POSITION REPEATER BOX (4CF)					Component	ATA:27
PN:016092-2	MOS/MSC	19-Feb-98	O/C	TSN 0				
SN:91	HRS			TSN 0				
WC#: 27.262	AFL			TSN 0				
PROC. REF: AMM 27-40-05-900-801PROC. REF: AMM 27-40-05-900-801								
27-40-15-710-801-01 ^S		OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY - AIRBRAKE/TAILPLANE/TRIM CONTROL BOX (2CF)					Service	ATA:27
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 27.270	AFL	6741	7500					
PROC. REF: AMM 27-40-15-710-801PROC. REF: AMM 27-40-15-710-801								
27-40-15-710-801-01A		OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY - AIRBRAKE/TAILPLANE/TRIM CONTROL BOX (2CF) (MANDATORY 5-40)					Service	ATA:27
	MOS	19-Dec-21					MANDATORY 5-40	
	HRS	13275.5	16000		29275.5		15379.2	
WC#: 27.270	AFL	6741						
PROC. REF: AMM 27-40-15-710-801PROC. REF: AMM 27-40-15-710-801								
27-40-17-720-801-01 ^S		FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX - HS RELAY BOX (91CF)					Service	ATA:27
	MOS	22-Nov-07						
	HRS	10138.1	4800 (+40)					
WC#: 27.265	AFL	5422						
PROC. REF: AMM 27-40-17-720-801PROC. REF: AMM 27-40-17-720-801								
27-40-17-720-801-01A		FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX - HS RELAY BOX (91CF) (MANDATORY 5-40)					Service	ATA:27
	MOS	25-Mar-10					MANDATORY 5-40	
	HRS	10865.5	5000	Adj -36.6	15828.9		1932.6	
WC#: 27.265	AFL	5891						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-40-17-720-801PROC. REF: AMM 27-40-17-720-801								
27-50-00-640-801-01	S	GREASING / LUBRICATION OF FLAP MECHANISMS						Service ATA:27
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 27.515	AFL	7304						
PROC. REF: AMM 27-50-00-640-801PROC. REF: AMM 27-50-00-640-801								
27-50-00-720-801-01	S	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.290	AFL	6741						
PROC. REF: AMM 27-50-00-720-801PROC. REF: AMM 27-50-00-720-801								
27-50-00-720-802-01	S	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.285	AFL	6741						
PROC. REF: AMM 27-50-00-720-802PROC. REF: AMM 27-50-00-720-802								
27-50-00-720-802-01A		FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)						Service ATA:27
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	1800		15075.5		1179.2	
WC#: 27.285	AFL	6741						
PROC. REF: AMM 27-50-00-720-802PROC. REF: AMM 27-50-00-720-802								
27-50-00-720-803-01	S	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-50-00-720-803PROC. REF: AMM 27-50-00-720-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-01-900-801-01	REMOVAL / INSTALLATION OF THE SLATS / FLAPS CONTROL BOX - SLATS/FLAPS CONTROL BOX (2CG)						Component	ATA:27
PN:013016-21	MOS/MSC	21-Jul-10	O/C					
SN:649	HRS	11009.58						
WC#: 27.040	AFL	5928						
PROC. REF: AMM 27-51-01-900-801PROC. REF: AMM 27-51-01-900-801								
27-52-01-900-801-01	REMOVAL / INSTALLATION OF THE FLAP POWER DRIVE UNIT - FLAP POWER DRIVE UNIT (3CG)						Component	ATA:27
PN:021138-05	MOS/MSC	07-Nov-03	O/C					
SN:174	HRS	5950						
WC#: 27.300	AFL	2938						
PROC. REF: AMM 27-52-01-900-801PROC. REF: AMM 27-52-01-900-801								
27-52-13-200-801-01	^S	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - LH WING					Service	ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 27.295	AFL	7052	3750					
PROC. REF: AMM 27-52-13-200-801PROC. REF: AMM 27-52-13-200-801								
27-52-13-200-801-02	^S	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - RH WING					Service	ATA:27
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 27-52-13-200-801PROC. REF: AMM 27-52-13-200-801								
27-53-01-220-801-01	^S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (L502CG)					Service	ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-220-801PROC. REF: AMM 27-53-01-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-220-801-02	^S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-220-801PROC. REF: AMM 27-53-01-220-801								PKG:5
27-53-01-220-801-03	^S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L500CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-220-801PROC. REF: AMM 27-53-01-220-801								PKG:5
27-53-01-220-801-04	^S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-220-801PROC. REF: AMM 27-53-01-220-801								PKG:5
27-53-01-220-801-05	^S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-220-801PROC. REF: AMM 27-53-01-220-801								PKG:5
27-53-01-220-801-06	^S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (R502CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-220-801PROC. REF: AMM 27-53-01-220-801								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-801-01		RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH OUTBOARD FLAP SCREW JACK (L502CG)						Service ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	O/C					
SN:1935	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-01A		RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY 5-40)						Service ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	O/C					MANDATORY 5-40
SN:1935	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-02		RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1705	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-02A		RESTORATION LH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					MANDATORY 5-40
SN:1705	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-03		RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP CENTER SCREW JACK (L500CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1923	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-03A		RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					MANDATORY 5-40
SN:1923	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-801-04		RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1947	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-04A		RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					MANDATORY 5-40
SN:1947	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-05		RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1932	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-05A		RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					MANDATORY 5-40
SN:1932	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-06		RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH OUTBOARD FLAP SCREW JACK (R502CG)						Service ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	O/C					
SN:1951	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								
27-53-01-350-801-06A		RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY 5-40)						Service ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	O/C					MANDATORY 5-40
SN:1951	HRS	0						
	AFL	0						
PROC. REF: AMM 27-53-01-350-801PROC. REF: AMM 27-53-01-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-802-01 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (L502CG)								Service ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	N/A					
SN:1935	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-01A UPGRADE LH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)								Service ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1935	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-02 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1705	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-02A UPGRADE LH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1705	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-03 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP CENTER SCREW JACK (L500CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1923	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-802-03A UPGRADE LH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1923	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-04 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP CENTER SCREW JACK (R500CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1947	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-04A UPGRADE RH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1947	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-05 UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1932	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-05A UPGRADE RH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1932	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-802-06		UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (R502CG)					Service	ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	N/A					
SN:1951	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-350-802-06A		UPGRADE RH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)					Service	ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1951	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-350-802PROC. REF: AMM 27-53-01-350-802								
27-53-01-640-802-01 ^S		GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)					Service	ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802								PKG:5
27-53-01-640-802-02 ^S		GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)					Service	ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802								PKG:5
27-53-01-640-802-03 ^S		GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)					Service	ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-640-802-04	^S	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802								PKG:5
27-53-01-640-802-05	^S	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802								PKG:5
27-53-01-640-802-06	^S	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802, AMM 27-53-01-640-802								PKG:5
27-53-01-720-803-01		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (L502CG)						Service ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	N/A					
SN:1935	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-01A		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (L502CG) (MANDATORY REF 5-40)						Service ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1935	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-720-803-02		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1705	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-02A		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L501CG) (MANDATORY REF 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1705	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-03		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP CENTER SCREW JACK (L500CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1923	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-03A		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP CENTER SCREW JACK (L500CG) (MANDATORY REF 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1923	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-04		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1947	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-720-803-04A		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP CENTER SCREW JACK (R500CG) (MANDATORY REF 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1947	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-05		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					
SN:1932	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-05A		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP LATERAL SCREW JACK (R501CG) (MANDATORY REF 5-40)						Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1932	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-06		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (R502CG)						Service ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	N/A					
SN:1951	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								
27-53-01-720-803-06A		CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (R502CG) (MANDATORY REF 5-40)						Service ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	N/A					MANDATORY 5-40
SN:1951	HRS	0						
	AFL	0						
	APH	0						
PROC. REF: AMM 27-53-01-720-803PROC. REF: AMM 27-53-01-720-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-720-804-01	^S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-53-01-720-804PROC. REF: AMM 27-53-01-720-804								PKG:21
27-53-01-720-804-02	^S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-53-01-720-804PROC. REF: AMM 27-53-01-720-804								PKG:21
27-53-01-720-804-03	^S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-53-01-720-804PROC. REF: AMM 27-53-01-720-804								PKG:21
27-53-01-720-804-04	^S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-53-01-720-804PROC. REF: AMM 27-53-01-720-804								PKG:21
27-53-01-720-804-05	^S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-53-01-720-804PROC. REF: AMM 27-53-01-720-804								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-720-804-06	^S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-53-01-720-804PROC. REF: AMM 27-53-01-720-804								PKG:21
27-53-01-900-803-01		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)						Component ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	O/C					
SN:1935	HRS	0		TSN 0				
	AFL	0						
PROC. REF: AMM 27-53-01-900-803PROC. REF: AMM 27-53-01-900-803								
27-53-01-900-803-02		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)						Component ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1705	HRS	0						
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01-900-803PROC. REF: AMM 27-53-01-900-803								
27-53-01-900-803-03		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)						Component ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1923	HRS	0						
WC#: 27.325	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01-900-803PROC. REF: AMM 27-53-01-900-803								
27-53-01-900-803-04		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						Component ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1947	HRS	0						
WC#: 27.325	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01-900-803PROC. REF: AMM 27-53-01-900-803								
27-53-01-900-803-05		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						Component ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1932	HRS	0						
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01-900-803PROC. REF: AMM 27-53-01-900-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-900-803-06 REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)								Component ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	O/C					
SN:1951	HRS	0		TSN 0				
	AFL	0						
PROC. REF: AMM 27-53-01-900-803PROC. REF: AMM 27-53-01-900-803								
27-53-01-960-801-01 DISCARD OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)								Service ATA:27
PN:021137-15	MOS/MSC	07-Feb-91	O/C					
SN:1935	HRS	0		TAC 0				
	AFL	0						
PROC. REF: AMM 27-53-01-960-801PROC. REF: AMM 27-53-01-960-801								
27-53-01-960-801-02 DISCARD OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1705	HRS	0						
WC#: 27.320	AFL	0		TAC 0				
PROC. REF: AMM 27-53-01-960-801PROC. REF: AMM 27-53-01-960-801								
27-53-01-960-801-03 DISCARD OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1923	HRS	0						
WC#: 27.325	AFL	0		TAC 0				
PROC. REF: AMM 27-53-01-960-801PROC. REF: AMM 27-53-01-960-801								
27-53-01-960-801-04 DISCARD OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1947	HRS	0						
WC#: 27.330	AFL	0		TAC 0				
PROC. REF: AMM 27-53-01-960-801PROC. REF: AMM 27-53-01-960-801								
27-53-01-960-801-05 DISCARD OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)								Service ATA:27
PN:021137-13	MOS/MSC	07-Feb-91	O/C					
SN:1932	HRS	0						
WC#: 27.335	AFL	0		TAC 0				
PROC. REF: AMM 27-53-01-960-801PROC. REF: AMM 27-53-01-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-960-801-06	DISCARD OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)							Service ATA:27
PN:021137-14	MOS/MSC	07-Feb-91	O/C					
SN:1951	HRS	0		TAC 0				
	AFL	0						
PROC. REF: AMM 27-53-01-960-801PROC. REF: AMM 27-53-01-960-801								
27-60-00-710-803-01 ^S	OPERATIONAL TEST OF THE AIRBRAKES IN NORMAL MODE AND AUTOMATIC RETRACTION MODES							Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.365	AFL	6741						
PKG:21								
PROC. REF: AMM 27-60-00-710-803PROC. REF: AMM 27-60-00-710-803								
27-61-01-720-801-01 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH OUTBOARD AIRBRAKE POSITION MICROSWITCH (L6CD)							Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PKG:22								
PROC. REF: AMM 27-61-01-720-801PROC. REF: AMM 27-61-01-720-801								
27-61-01-720-801-02 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH CENTER AIRBRAKE POSITION MICROSWITCH (L5CD)							Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PKG:22								
PROC. REF: AMM 27-61-01-720-801PROC. REF: AMM 27-61-01-720-801								
27-61-01-720-801-03 ^S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH INBOARD AIRBRAKE POSITION MICROSWITCH (L4CD)							Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PKG:22								
PROC. REF: AMM 27-61-01-720-801PROC. REF: AMM 27-61-01-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-61-01-720-801-04	S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH INBOARD AIRBRAKE POSITION MICROSWITCH (R4CD)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PROC. REF: AMM 27-61-01-720-801PROC. REF: AMM 27-61-01-720-801								PKG:22
27-61-01-720-801-05	S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH CENTER AIRBRAKE POSITION MICROSWITCH (R5CD)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PROC. REF: AMM 27-61-01-720-801PROC. REF: AMM 27-61-01-720-801								PKG:22
27-61-01-720-801-06	S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH OUTBOARD AIRBRAKE POSITION MICROSWITCH (R6CD)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PROC. REF: AMM 27-61-01-720-801PROC. REF: AMM 27-61-01-720-801								PKG:22
27-61-01-900-801-01	LH INBOARD AIRBRAKE POSITION MICROSWITCH MICROSWITCH							Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.390	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-61-01-900-801-02	LH CENTER AIRBRAKE POSITION MICROSWITCH							Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.390	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-61-01-900-801-03	LH OUTBOARD AIRBRAKE POSITION MICROSWITCH							Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.390	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-61-01-900-801-04	RH INBOARD AIRBRAKE POSITION MICROSWITCH							Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.395	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-61-01-900-801-05	RH CENTER AIRBRAKE POSITION MICROSWITCH							Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.395	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-61-01-900-801-06	RH OUTBOARD AIRBRAKE POSITION MICROSWITCH							Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.395	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-62-01-640-801-01 ^S	GREASING OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L502CD)							Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 27.360	AFL	7304						
PROC. REF: AMM 27-62-01-640-801PROC. REF: AMM 27-62-01-640-801								
27-62-01-640-801-02 ^S	GREASING OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L501CD)							Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 27-62-01-640-801PROC. REF: AMM 27-62-01-640-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-62-01-640-801-03	^S	GREASING OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L500CD)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 27-62-01-640-801PROC. REF: AMM 27-62-01-640-801								PKG:15
27-62-01-640-801-04	^S	GREASING OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R500CD)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 27-62-01-640-801PROC. REF: AMM 27-62-01-640-801								PKG:15
27-62-01-640-801-05	^S	GREASING OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R501CD)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 27-62-01-640-801PROC. REF: AMM 27-62-01-640-801								PKG:15
27-62-01-640-801-06	^S	GREASING OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R502CD)						Service ATA:27
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 27-62-01-640-801PROC. REF: AMM 27-62-01-640-801								PKG:15
27-62-01-900-801-01		REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L502CD)						Component ATA:27
PN:106091-04	MOS/MSC	07-Feb-91	O/C					
SN:2857	HRS	0		TSN 0				
WC#: 27.380	AFL	0						
PROC. REF: AMM 27-62-01-900-801PROC. REF: AMM 27-62-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-62-01-900-801-02 REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L501CD)								Component ATA:27
PN:106091-05	MOS/MSC	07-Feb-91	O/C					
SN:2867	HRS	0		TSN 0				
WC#: 27.380	AFL	0						
PROC. REF: AMM 27-62-01-900-801PROC. REF: AMM 27-62-01-900-801								
27-62-01-900-801-03 REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L500CD)								Component ATA:27
PN:106091-06	MOS/MSC	07-Feb-91	O/C					
SN:2871	HRS	0		TSN 0				
WC#: 27.380	AFL	0						
PROC. REF: AMM 27-62-01-900-801PROC. REF: AMM 27-62-01-900-801								
27-62-01-900-801-04 REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R500CD)								Component ATA:27
PN:106091-06	MOS/MSC	07-Feb-91	O/C					
SN:2863	HRS	0		TSN 0				
WC#: 27.385	AFL	0						
PROC. REF: AMM 27-62-01-900-801PROC. REF: AMM 27-62-01-900-801								
27-62-01-900-801-05 REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R501CD)								Component ATA:27
PN:106091-05	MOS/MSC	07-Feb-91	O/C					
SN:2869	HRS	0		TSN 0				
WC#: 27.385	AFL	0						
PROC. REF: AMM 27-62-01-900-801PROC. REF: AMM 27-62-01-900-801								
27-62-01-900-801-06 REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R502CD)								Component ATA:27
PN:106091-04	MOS/MSC	07-Feb-91	O/C					
SN:2856	HRS	0		TSN 0				
WC#: 27.385	AFL	0						
PROC. REF: AMM 27-62-01-900-801PROC. REF: AMM 27-62-01-900-801								
27-62-03-900-801-01 REMOVAL / INSTALLATION OF THE AIRBRAKE PRESSURE HOLDING VALVE ACCUMULATOR - AIRBRAKE PRESSURE-HOLDING VALVE (503CD)								Component ATA:27
PN:D25AB1702	MOS/MSC		O/C					
SN:225	HRS	4817						
WC#: 27.375	AFL							
PROC. REF: AMM 27-62-03-900-801PROC. REF: AMM 27-62-03-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-00-710-804-02	OPERATIONAL TEST OF THE SLATS IN NORMAL AND EMERGENCY MODES - EMERGENCY MODE							Service ATA:27
	MOS	25-Mar-22						
	HRS	13349.6	10000 (+40)	Adj -3349.6	20000	20040	6103.7 (+40)	
	AFL	6796						
PROC. REF: AMM 27-80-00-710-804PROC. REF: AMM 27-80-00-710-804								
27-80-00-710-807-02	^S	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH AND RH SOLENOIDS - LH SOLENOID (S1)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-80-00-710-807PROC. REF: AMM 27-80-00-710-807								
27-80-00-710-807-03	^S	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH AND RH SOLENOIDS - RH SOLENOID (S2)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 27-80-00-710-807PROC. REF: AMM 27-80-00-710-807								
27-80-00-720-801-02	^S	FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.490	AFL	6741						
PROC. REF: AMM 27-80-00-720-801PROC. REF: AMM 27-80-00-720-801								
27-80-01-900-801-01	OUTBOARD SLAT NORMAL SOLENOID SELECTOR/MANIFOLD VALVE							Component ATA:27
PN:108033-16	MOS/MSC	29-Mar-08	O/C	TSR 0				
SN:1628	HRS	10399.6		TSR 0				
WC#: 27.415	AFL	5565		TSR 0				
PROC. REF: AMM 27-80-01-900-801, AMM 27-80-01-900-801PROC. REF: AMM 27-80-01-900-801, AMM 27-80-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-05-900-801-01 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH INBOARD SLAT ACTUATOR (L500CM)								Component ATA:27
PN:106107-15	MOS/MSC	07-Feb-91	O/C					
SN:2684	HRS	0		TSN 0				
WC#: 27.430	AFL	0						
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								
27-80-05-900-801-02 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH INBOARD SLAT ACTUATOR (R500CM)								Component ATA:27
PN:106107-15	MOS/MSC	07-Mar-08	O/C	TSR 0				
SN:2331	HRS	10360.3		TSR 0				
WC#: 27.435	AFL	5544		TSR 0				
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								
27-80-05-900-801-03 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT INBOARD ACTUATOR (L501CM)								Component ATA:27
PN:106107-12	MOS/MSC	07-Feb-91	O/C					
SN:2706	HRS	0		TSN 0				
WC#: 27.430	AFL	0						
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								
27-80-05-900-801-04 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT INBOARD ACTUATOR (R501CM)								Component ATA:27
PN:106107-12	MOS/MSC	07-Feb-91	O/C					
SN:2691	HRS	0		TSN 0				
WC#: 27.435	AFL	0						
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								
27-80-05-900-801-05 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT EMERGENCY ACTUATOR (L502CM)								Component ATA:27
PN:106107-17	MOS/MSC	07-Feb-91	O/C					
SN:2702	HRS	0		TSN 0				
WC#: 27.440	AFL	0						
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								
27-80-05-900-801-06 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT EMERGENCY ACTUATOR (R502CM)								Component ATA:27
PN:106107-17	MOS/MSC	07-Feb-91	O/C					
SN:2686	HRS	0		TSN 0				
WC#: 27.440	AFL	0						
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-05-900-801-07 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT OUTBOARD ACTUATOR (L503CM)								Component ATA:27
PN:106107-13	MOS/MSC	07-Feb-91	O/C					
SN:2697	HRS	0		TSN 0				
WC#: 27.430	AFL	0						
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								
27-80-05-900-801-08 REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT OUTBOARD ACTUATOR (R503CM)								Component ATA:27
PN:106107-13	MOS/MSC	07-Feb-91	O/C					
SN:2695	HRS	0		TSN 0				
WC#: 27.435	AFL	0						
PROC. REF: AMM 27-80-05-900-801PROC. REF: AMM 27-80-05-900-801								
27-80-17-720-802-01 ^S FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (L2DX)								Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.465	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								
27-80-17-720-802-02 ^S FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH (L15CM)								Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.460	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								
27-80-17-720-802-03 ^S FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH (L3DX)								Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.470	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-17-720-802-04	^S	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (L16CM)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.475	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								PKG:22
27-80-17-720-802-05	^S	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (R2DX)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.465	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								PKG:22
27-80-17-720-802-06	^S	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH (R15CM)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.460	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								PKG:22
27-80-17-720-802-07	^S	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH (R3DX)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.470	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								PKG:22
27-80-17-720-802-08	^S	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (R16CM)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.475	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-17-720-802-09	^S	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - FLAP POSITION MICROSWITCH (7CM)						Service ATA:27
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 27.477	AFL	6741						
PROC. REF: AMM 27-80-17-720-802PROC. REF: AMM 27-80-17-720-802								
PKG:22								
27-80-17-900-801-01		LH INBOARD SLAT EXTENDED MICROSWITCH						Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.465	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-17-900-801-02		LH INBOARD SLAT RETRACTED MICROSWITCH						Component ATA:27
PN:402EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.460	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-17-900-801-03		LH OUTBOARD SLAT RETRACTED MICROSWITCH						Component ATA:27
PN:402EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.470	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-17-900-801-04		LH OUTBOARD SLAT EXTENDED MICROSWITCH						Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.475	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-17-900-801-05		RH INBOARD SLAT EXTENDED MICROSWITCH						Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.465	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-17-900-801-06		RH INBOARD SLAT RETRACTED MICROSWITCH						Component ATA:27
PN:402EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.460	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-17-900-801-07		RH OUTBOARD SLAT RETRACTED MICROSWITCH						Component ATA:27
PN:402EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.470	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-17-900-801-08		RH OUTBOARD SLAT EXTENDED MICROSWITCH						Component ATA:27
PN:602EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.475	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-17-900-803-01		FLAP POSITION MICROSWITCH						Component ATA:27
PN:402EN1-6	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.477	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
27-80-23-720-801-01		FUNCTIONAL TEST OF THE INBOARD SLAT VALVE BOX - INBOARD SLAT VALVE BOX (507CM)						Service ATA:27
PN:108117-06	MOS	09-May-23	144 (+3%)		09-May-35	18-Sep-35	3302 d (+132)	
SN:85	HRS	13532.8						
WC#: 27.425	AFL	6949						
PROC. REF: AMM 27-80-23-720-801PROC. REF: AMM 27-80-23-720-801								
27-80-23-720-802-01		FUNCTIONAL TEST OF THE OUTBOARD SLAT VALVE BOX - OUTBOARD SLAT VALVE BOX (517CM)						Service ATA:27
PN:108117-05	MOS	09-May-23	144 (+3%)		09-May-35	18-Sep-35	3302 d (+132)	
SN:187	HRS	13532.8						
WC#: 27.425	AFL	6949						
PROC. REF: AMM 27-80-23-720-802PROC. REF: AMM 27-80-23-720-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-23-900-801-01 REMOVAL / INSTALLATION OF THE INBOARD SLAT VALVE BOX - INBOARD SLAT VALVE BOX (507CM)								Component ATA:27
PN:108117-06	MOS/MSC	27-May-11	O/C		TSN 13			
SN:85	HRS	11414.25			TSN 494.92			
WC#: 27.425	AFL	6044			TSN 141			
PROC. REF: AMM 27-80-23-900-801PROC. REF: AMM 27-80-23-900-801								
270101 PILOT CONTROL COLUMN								Component ATA:27
PN:FGFB.215.001	MOS/MSC	07-Feb-91	O/C					
SN:98.1	HRS	0			TSN 0			
WC#: 27.025	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
270121 COPILOT CONTROL COLUMN								Component ATA:27
PN:FGFB.215.001	MOS/MSC	07-Feb-91	O/C					
SN:98.2	HRS	0			TSN 0			
WC#: 27.030	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
270221 TRIPLE TRIM INDICATOR								Component ATA:27
PN:4863-557-80-13	MOS/MSC	26-Dec-99	O/C		TSN 0			
SN:266	HRS				TSN 0			
WC#: 27.035	AFL				TSN 0			
PROC. REF: AMM 21-30-09-900-801PROC. REF: AMM 21-30-09-900-801								
271251 AILERON TRIM BOX								Component ATA:27
PN:F10A641812A1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 27.085	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
271351 LH AILERON NEUTRAL RETURN UNIT								Component ATA:27
PN:105045-06	MOS/MSC	07-Feb-91	O/C					
SN:3311	HRS	0			TSN 0			
WC#: 27.095	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271381	RH AILERON NEUTRAL RETURN UNIT							Component ATA:27
PN:105045-06	MOS/MSC	07-Feb-91	O/C					
SN:3310	HRS	0		TSN 0				
WC#: 27.095	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
271401	LH ROLL CONTROL SEALED BOX							Component ATA:27
PN:FGFB271111A1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.097	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
271421	RH ROLL CONTROL SEALED BOX							Component ATA:27
PN:FGFB271211A1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.097	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
271601	RUDDER PRESSURE SEALED BOX							Component ATA:27
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.155	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
271621	ELEVATOR PRESSURE SEALED BOX							Component ATA:27
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.252	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
272071	PILOT RUDDER BAR PEDAL ASSEMBLY							Component ATA:27
PN:0CV299-03	MOS/MSC	07-Feb-91	O/C					
SN:180	HRS	0		TSN 0				
WC#: 27.123	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272081	COPILOT RUDDER BAR PEDAL ASSEMBLY							Component ATA:27
PN:0CV299-04	MOS/MSC	07-Feb-91	O/C					
SN:217	HRS	0		TSN 0				
WC#: 27.123	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
272091	PILOT PEDALS ADJUSTMENT ROD BOX							Component ATA:27
PN:4505-1	MOS/MSC	07-Feb-91	O/C					
SN:294	HRS	0		TSN 0				
WC#: 27.124	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
272096	COPILOT PEDALS ADJUSTMENT ROD BOX							Component ATA:27
PN:4505-1	MOS/MSC	07-Feb-91	O/C					
SN:295	HRS	0		TSN 0				
WC#: 27.124	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
272163	YAW TRIM RELAY BOX							Component ATA:27
PN:FGFB600271010A2	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.150	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
273161	ARTHUR Q-UNIT PITCH SERVO VALVE							Component ATA:27
PN:108019-13	MOS/MSC	01-Dec-92	O/C	TSN 0				
SN:1559	HRS			TSN 0				
WC#: 27.215	AFL			TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
273171	PITCH ARTHUR BOX							Component ATA:27
PN:062175-03	MOS/MSC	03-Dec-04	O/C	TSN 0				
SN:104	HRS	7002.4		TSN 0				
WC#: 27.220	AFL	3654		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
274161	HORIZONTAL STABILIZER STANDBY ELECTRIC MOTOR							Component ATA:27
PN:993	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.260	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
274201	HORIZONTAL STABILIZER RELAY BOX							Component ATA:27
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.265	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
274251	HORIZONTAL STABILIZER STANDBY CONTROL BOX							Component ATA:27
PN:FGFB641810A2	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.270	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
275121	LH FLAP DUAL BEVEL GEAR							Component ATA:27
PN:021068-06	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.305	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
275141	RH FLAP DUAL BEVEL GEAR							Component ATA:27
PN:021068-07	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.305	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
275161	LH FLAP BEVEL GEAR							Component ATA:27
PN:021063-01	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.310	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275181	RH FLAP BEVEL GEAR							Component ATA:27
PN:021063-01	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.310	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
275351	LH FLAP POSITION TRANSMITTER							Component ATA:27
PN:1-4414-2	MOS/MSC	07-Feb-91	O/C					
SN:479	HRS	0		TSN 0				
WC#: 27.350	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
275361	RH FLAP POSITION TRANSMITTER							Component ATA:27
PN:2-4414-2	MOS/MSC	07-Feb-91	O/C					
SN:283	HRS	0		TSN 0				
WC#: 27.350	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
275371	FLAP ASYMMETRY DETECTOR							Component ATA:27
PN:J2201-2-10MEB	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.355	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
275401	CONFIGURATION PANEL							Component ATA:27
PN:205TS04Y01	MOS/MSC		O/C					
SN:427	HRS	1215						
WC#: 27.355	AFL							
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
276101	INBOARD/OUTBOARD AIRBRAKE SELECTOR VALVE							Component ATA:27
PN:65670-1	MOS/MSC	07-Feb-91	O/C					
SN:1260A	HRS	0		TSN 0				
WC#: 27.370	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276141	MIDDLE AIRBRAKE SELECTOR VALVE							Component ATA:27
PN:65670-1	MOS/MSC	07-Feb-91	O/C					
SN:1274A	HRS	0		TSN 0				
WC#: 27.370	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
276191	AIRBRAKE HOLD VALVE GAUGE							Component ATA:27
PN:18040100	MOS/MSC	31-Mar-14	O/C	TSN 0				
SN:031769	HRS	12625.42		TSN 0				
WC#: 27.375	AFL	6516		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
276401	LH OUTBOARD AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-202	MOS/MSC	07-Feb-91	O/C					
SN:B2978	HRS	0		TSN 0				
WC#: 27.402	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
276411	LH MIDDLE AIRBRAKE RESISTOR							Component ATA:27
PN:C24370-402	MOS/MSC	07-Feb-91	O/C					
SN:B3119	HRS	0		TSN 0				
WC#: 27.402	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
276421	LH INBOARD AIRBRAKE RESISTOR							Component ATA:27
PN:C24370-302	MOS/MSC	07-Feb-91	O/C					
SN:B3149	HRS	0		TSN 0				
WC#: 27.402	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
276431	RH INBOARD AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-302	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:B2830	HRS	10850.2		TSR 0				
WC#: 27.403	AFL	5878		TSR 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276441	RH MIDDLE AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-402	MOS/MSC	07-Feb-91	O/C					
SN:B3117	HRS	0		TSN 0				
WC#: 27.403	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
276451	RH OUTBOARD AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-202	MOS/MSC	07-Feb-91	O/C					
SN:B2962	HRS	0		TSN 0				
WC#: 27.403	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278101	OUTBOARD SLAT AUTOMATIC DISTRIBUTOR							Component ATA:27
PN:108103-04	MOS/MSC	07-Feb-91	O/C					
SN:576	HRS	0		TSN 0				
WC#: 27.415	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278121	OUTBOARD SLAT STANDBY ELECTRIC DISTRIBUTOR							Component ATA:27
PN:65670-1	MOS/MSC	07-Feb-91	O/C					
SN:1105A	HRS	0		TSN 0				
WC#: 27.420	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278131	INBOARD SLAT ELECTRIC DISTRIBUTOR							Component ATA:27
PN:65670-1	MOS/MSC	07-Feb-91	O/C					
SN:1254A	HRS	0		TSN 0				
WC#: 27.420	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278171	OUTBOARD SLAT VALVE BOX							Component ATA:27
PN:108117-05	MOS/MSC	27-May-11	O/C	TSN 0				
SN:187	HRS	11414.25		TSN 0				
WC#: 27.425	AFL	6044		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
278401	LH INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR							Component ATA:27
PN:C24346-102	MOS/MSC	07-Feb-91	O/C					
SN:B1319	HRS	0		TSN 0				
WC#: 27.445	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278411	RH INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR							Component ATA:27
PN:C24346-102	MOS/MSC	07-Feb-91	O/C					
SN:B1320	HRS	0		TSN 0				
WC#: 27.445	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278421	LH OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE							Component ATA:27
PN:C24370-102	MOS/MSC	07-Feb-91	O/C					
SN:B3175	HRS	0		TSN 0				
WC#: 27.450	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278431	RH OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE							Component ATA:27
PN:C24370-102	MOS/MSC	07-Feb-91	O/C					
SN:B3178	HRS	0		TSN 0				
WC#: 27.450	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278441	LH ACTUATOR STANDBY RESTRICTOR VALVE							Component ATA:27
PN:FGFB756380A1	MOS/MSC	07-Feb-91	O/C					
SN:MC015	HRS	0		TSN 0				
WC#: 27.455	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
278451	RH ACTUATOR STANDBY RESTRICTOR VALVE							Component ATA:27
PN:FGFB756380A1	MOS/MSC	07-Feb-91	O/C					
SN:MC016	HRS	0		TSN 0				
WC#: 27.455	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
278461	SLATS ACTUATOR RETRACTION RESTRICTOR VALVE							Component ATA:27
PN:C24346-302	MOS/MSC	07-Feb-91	O/C					
SN:B1210	HRS	0		TSN 0				
WC#: 27.455	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
ATA 28 - FUEL								
28-00-00-280-801-01	^S	FUEL CONTAMINATION DETECTION TEST						Service ATA:28
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800					
WC#: 28.560	AFL	7304						
PROC. REF: AMM 28-00-00-280-801PROC. REF: AMM 28-00-00-280-801								
28-00-00-290-801-01	^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH FEEDER TANK						Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
	AFL	7052						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								
28-00-00-290-801-02	^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH FEEDER TANK						Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
	AFL	7052						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								
28-00-00-290-801-03	^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE CTR FEEDER TANK						Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
	AFL	7052						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-00-00-290-801-04	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH CENTER-WING TANK							Service ATA:28
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								
28-00-00-290-801-05	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH CENTER-WING TANK							Service ATA:28
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								
28-00-00-290-801-06	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE REAR TANK							Service ATA:28
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								
28-00-00-290-801-07 ^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH WING TANK							Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
	AFL	7052						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								PKG:7
28-00-00-290-801-08 ^S	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH WING TANK							Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
	AFL	7052						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								PKG:7
28-00-00-290-801-09	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE FRONT TANK							Service ATA:28
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-290-801PROC. REF: AMM 28-00-00-290-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-00-00-910-804-01 MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS								Service ATA:28
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 28.570	AFL	0						
PROC. REF: AMM 28-00-00-910-804PROC. REF: AMM 28-00-00-910-804								
28-10-00-280-801-01 ^S SPECIAL DETAILED INSPECTION OF THE FUEL TANK FLAPPER VALVES								Service ATA:28
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 28.030	AFL	7052	3750					
PROC. REF: AMM 28-10-00-280-801PROC. REF: AMM 28-10-00-280-801								PKG:31
28-21-01-900-801-01 REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 1 (3QN1)								Component ATA:28
PN:P99C31-604	MOS/MSC	03-Jan-11	O/C	TSR 0				
SN:D31284	HRS	11228.25		TSR 0				
WC#: 28.370	AFL	5983		TSR 0				
PROC. REF: AMM 28-21-01-900-801PROC. REF: AMM 28-21-01-900-801								
28-21-01-900-801-02 REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 2 (3QN2)								Component ATA:28
PN:226650-51	MOS/MSC	10-Oct-02	O/C	TSO 0				
SN:664	HRS	5660.3		TSO 0				
WC#: 28.380	AFL	2733		TSO 0				
PROC. REF: AMM 28-21-01-900-801PROC. REF: AMM 28-21-01-900-801								
28-21-01-900-801-03 REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 3 (3QN3)								Component ATA:28
PN:226650-51	MOS/MSC	07-May-02	O/C	TSO 0				
SN:277	HRS	5264.5		TSO 0				
WC#: 28.370	AFL	2445		TSO 0				
PROC. REF: AMM 28-21-01-900-801PROC. REF: AMM 28-21-01-900-801								
28-21-01-900-801-04 REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - STAND-BY BOOSTER PUMP 2 (13QN)								Component ATA:28
PN:226650-51	MOS/MSC	16-Jan-00	O/C	TSN 0				
SN:616	HRS			TSN 0				
WC#: 28.380	AFL			TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-21-01-900-801PROC. REF: AMM 28-21-01-900-801								
28-21-05-900-801-01	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 1 MANIFOLD (32WB1)							Component ATA:28
PN:L88A31-662	MOS/MSC	22-Nov-07	O/C					
SN:20129	HRS	10138.1		TSR 0				
WC#: 28.280	AFL	5422						
PROC. REF: AMM 28-21-05-900-801PROC. REF: AMM 28-21-05-900-801								
28-21-05-900-801-02	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 2 MANIFOLD (32WB2)							Component ATA:28
PN:L88A31-663	MOS/MSC	22-Nov-07	O/C					
SN:20030	HRS	10138.1		TSR 0				
WC#: 28.290	AFL	5422						
PROC. REF: AMM 28-21-05-900-801PROC. REF: AMM 28-21-05-900-801								
28-21-05-900-801-03	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 3 MANIFOLD (32WB3)							Component ATA:28
PN:L88A31-664	MOS/MSC	22-Nov-07	O/C					
SN:20143	HRS	10138.1		TSR 0				
WC#: 28.300	AFL	5422						
PROC. REF: AMM 28-21-05-900-801PROC. REF: AMM 28-21-05-900-801								
28-21-11-710-801-01 ^S	OPERATIONAL TEST OF THE BP MANIFOLD CROSSFEED ELECTRICAL VALVES - BP 1 MANIFOLD CROSSFEED VALVE ELECTRICAL ACTUATOR (3221WB1)							Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
WC#: 28.350	AFL	7052						
								PKG:7
PROC. REF: AMM 28-21-11-710-801PROC. REF: AMM 28-21-11-710-801								
28-21-11-710-801-02 ^S	OPERATIONAL TEST OF THE BP MANIFOLD CROSSFEED ELECTRICAL VALVES - BP 3 MANIFOLD CROSSFEED VALVE ELECTRICAL ACTUATOR (3221WB3)							Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
WC#: 28.350	AFL	7052						
								PKG:7
PROC. REF: AMM 28-21-11-710-801PROC. REF: AMM 28-21-11-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-13-710-801-01	^S	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV (321WB1)						Service ATA:28
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.100	AFL	7052	3750					
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								PKG:31
28-21-13-710-801-01A		OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV (321WB1) (MANDATORY 5-40)						Service ATA:28
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641	11600		25241		11344.7	
WC#: 76.100	AFL	7052						
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								
28-21-13-710-801-02	^S	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV (321WB2)						Service ATA:28
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.110	AFL	7052	3750					
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								PKG:31
28-21-13-710-801-02A		OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV (321WB2) (MANDATORY 5-40)						Service ATA:28
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641	11600		25241		11344.7	
WC#: 76.110	AFL	7052						
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								
28-21-13-710-801-03	^S	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV (321WB3)						Service ATA:28
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.120	AFL	7052	3750					
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-13-710-801-03A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV (321WB3) (MANDATORY 5-40)							Service ATA:28
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641	11600		25241		11344.7	
WC#: 76.120	AFL	7052						
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								
28-21-13-710-801-04 ^S	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV CLOSING							Service ATA:28
	MOS	22-Dec-23	72					
	HRS	13641						
WC#: 76.100	AFL	7052	3750					
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								PKG:31
28-21-13-710-801-05 ^S	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV CLOSING							Service ATA:28
	MOS	22-Dec-23	72					
	HRS	13641						
WC#: 76.110	AFL	7052	3750					
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								PKG:31
28-21-13-710-801-06 ^S	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV CLOSING							Service ATA:28
	MOS	22-Dec-23	72					
	HRS	13641						
WC#: 76.120	AFL	7052	3750					
PROC. REF: AMM 28-21-13-710-801PROC. REF: AMM 28-21-13-710-801								PKG:31
28-21-14-720-801-01	FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 1 MANIFOLD (32WB1)							Service ATA:28
PN:L88A31-662	MOS	22-Nov-07						
SN:20129	HRS	10138.1	10000 (+3%)		20138.1	20438.1	6241.8 (+300)	
WC#: 28.280	AFL	5422						
PROC. REF: AMM 28-21-14-720-801PROC. REF: AMM 28-21-14-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-14-720-801-02		FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 2 MANIFOLD (32WB2)						Service ATA:28
PN:L88A31-663	MOS	22-Nov-07						
SN:20030	HRS	10138.1	10000 (+3%)		20138.1	20438.1	6241.8 (+300)	
WC#: 28.290	AFL	5422						
PROC. REF: AMM 28-21-14-720-801PROC. REF: AMM 28-21-14-720-801								
28-21-14-720-801-03		FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 3 MANIFOLD (32WB3)						Service ATA:28
PN:L88A31-664	MOS	22-Nov-07						
SN:20143	HRS	10138.1	10000 (+3%)		20138.1	20438.1	6241.8 (+300)	
WC#: 28.300	AFL	5422						
PROC. REF: AMM 28-21-14-720-801PROC. REF: AMM 28-21-14-720-801								
28-21-25-710-801-01 ^S		OPERATIONAL TEST OF THE CROSSFEED UNITS						Service ATA:28
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
WC#: 28.160	AFL	7052						
PKG:7								
PROC. REF: AMM 28-21-25-710-801PROC. REF: AMM 28-21-25-710-801								
28-21-25-900-801-01		REMOVAL / INSTALLATION OF THE LH AND RH CROSSFEED UNITS - LH CROSSFEED UNIT (L500QA)						Component ATA:28
PN:L88A31-665-1	MOS/MSC	07-Feb-91	O/C					
SN:20175	HRS	0		TSN 0				
WC#: 28.270	AFL	0						
PROC. REF: AMM 28-21-25-900-801PROC. REF: AMM 28-21-25-900-801								
28-21-25-900-801-02		REMOVAL / INSTALLATION OF THE LH AND RH CROSSFEED UNITS - RH CROSSFEED UNIT (R500QA)						Component ATA:28
PN:L88A31-666-1	MOS/MSC		O/C					
SN:20134	HRS	1173						
WC#: 28.270	AFL							
PROC. REF: AMM 28-21-25-900-801PROC. REF: AMM 28-21-25-900-801								
28-21-29-100-801-01 ^S		CLEANING OF THE CROSSFEED UNIT FILTERS AND BOOSTER PUMP 2 UNIT FILTER - LH CROSSFEED UNIT FILTER						Service ATA:28
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
WC#: 28.270	AFL	7304						
PKG:5								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-21-29-100-801PROC. REF: AMM 28-21-29-100-801								
28-21-29-100-801-02	^S	CLEANING OF THE CROSSFEED UNIT FILTERS AND BOOSTER PUMP 2 UNIT FILTER - RH CROSSFEED UNIT FILTER						Service ATA:28
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
WC#: 28.270	AFL	7304						
								PKG:5
PROC. REF: AMM 28-21-29-100-801PROC. REF: AMM 28-21-29-100-801								
28-21-29-100-801-03	^S	CLEANING OF THE CROSSFEED UNIT FILTERS AND BOOSTER PUMP 2 UNIT FILTER - BOOSTER PUMP 2 UNIT FILTER						Service ATA:28
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
WC#: 28.330	AFL	7304						
								PKG:5
PROC. REF: AMM 28-21-29-100-801PROC. REF: AMM 28-21-29-100-801								
28-22-00-610-801-01	^S	SERVICING OF THE TRANSFER SOLENOID VALVE STAND-BY MANUAL CONTROL						Service ATA:28
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 28.250	AFL	7304						
								PKG:16
PROC. REF: AMM 28-22-00-610-801PROC. REF: AMM 28-22-00-610-801								
28-22-01-710-801-01	^S	OPERATIONAL TEST OF THE XTK2 VALVE - XTK2 VALVE (34QA)						Service ATA:28
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 28.260	AFL	7304						
								PKG:16
PROC. REF: AMM 28-22-01-710-801PROC. REF: AMM 28-22-01-710-801								
28-22-01-900-801-01		REMOVAL / INSTALLATION OF THE TANK INTERCONNECTION VALVE - TANK INTERCONNECTION VALVE (28QA)						Component ATA:28
PN:L87B63-653	MOS/MSC	07-Feb-91	O/C					
SN:20068	HRS	0		TSN 0				
WC#: 28.150	AFL	0						
PROC. REF: AMM 28-22-01-900-801PROC. REF: AMM 28-22-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-30-00-680-802-06		DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY						Service ATA:28
	MOS/MSC	09-Feb-15	O/C					
	HRS	13109.23						
	AFL	6701						
PROC. REF: AMM 28-30-00-680-802PROC. REF: AMM 28-30-00-680-802								
28-30-00-680-803-01		DRAINING OF THE GRAVITY DEFUELING LINE						Service ATA:28
	MOS	03-Mar-26	2 (+5d)		03-May-26	08-May-26	9 d (+5)	
	HRS	13888.3						
WC#: 28.340	AFL	7308						
PROC. REF: AMM 28-30-00-680-803PROC. REF: AMM 28-30-00-680-803								
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS						Service ATA:28
	MOS	03-Mar-26	2 (+5d)		03-May-26	08-May-26	9 d (+5)	
	HRS	13888.3						
	AFL	7308						
PROC. REF: AMM 28-30-00-680-804PROC. REF: AMM 28-30-00-680-804								
28-30-11-900-801-01		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - FRONT TANK SUMP DRAIN VALVE (505QS)						Component ATA:28
PN:142G12-33	MOS/MSC	07-Feb-91	O/C					
SN:1292	HRS	0		TSN 0				
WC#: 28.060	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
28-30-11-900-801-02		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH CENTERWING TANK REAR SUMP DRAIN VALVE (507QS)						Component ATA:28
PN:142G12-33	MOS/MSC	07-Feb-91	O/C					
SN:1333	HRS	0		TSN 0				
WC#: 28.070	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
28-30-11-900-801-03		REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH WING INBOARD TANK SUMP DRAIN VALVE (508QS)						Component ATA:28
PN:142D12-11	MOS/MSC	05-Jun-13	O/C	TSN 0				
SN:HO1972	HRS	12205.82		TSN 0				
WC#: 28.060	AFL	6354		TSN 0				
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-30-11-900-801-04 REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH WING INBOARD TANK SUMP DRAIN VALVE (509QS)								Component ATA:28
PN:142D12-1	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:D71857	HRS	10850.2		TSN 0				
WC#: 28.060	AFL	5878		TSN 0				
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
28-30-11-900-801-05 REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - REAR TANK SUMP DRAIN VALVE (510QS)								Component ATA:28
PN:142G12-33	MOS/MSC	07-Feb-91	O/C					
SN:1290	HRS	0		TSN 0				
WC#: 28.080	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
28-30-11-900-801-06 REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH FEEDER TANK SUMP DRAIN VALVE (512QS)								Component ATA:28
PN:142G12-33	MOS/MSC	07-Feb-91	O/C					
SN:1336	HRS	0		TSN 0				
WC#: 28.080	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
28-30-11-900-801-07 REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - CENTER FEEDER TANK SUMP DRAIN VALVE (513QS)								Component ATA:28
PN:142G12-33	MOS/MSC	07-Feb-91	O/C					
SN:1309	HRS	0		TSN 0				
WC#: 28.080	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
28-30-11-900-801-08 REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH CENTERWING TANK FRONT SUMP DRAIN VALVE (514QS)								Component ATA:28
PN:142G12-33	MOS/MSC	07-Feb-91	O/C					
SN:1306	HRS	0		TSN 0				
WC#: 28.070	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
28-30-11-900-801-09 REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH FEEDER TANK SUMP DRAIN VALVE (515QS)								Component ATA:28
PN:142G12-33	MOS/MSC	07-Feb-91	O/C					
SN:1321	HRS	0		TSN 0				
WC#: 28.070	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-30-11-960-802-01		DISCARD OF THE FUEL DRAIN CAPS						Service ATA:28
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-30-11-960-802PROC. REF: AMM 28-30-11-960-802								
28-41-00-720-801-01 ^S		FUNCTIONAL TEST OF THE FUEL QUANTITY INDICATING SYSTEM						Service ATA:28
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 28.385	AFL	6741						
PROC. REF: AMM 28-41-00-720-801PROC. REF: AMM 28-41-00-720-801								
28-41-05-900-801-01		REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - LH WING CENTER TANK GAUGE (L6EJ)						Component ATA:28
PN:766-189-4	MOS/MSC	14-Nov-11	O/C	TSN 0				
SN:1011	HRS	11568.42		TSN 0				
WC#: 28.430	AFL	6104		TSN 0				
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-02		REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - RH WING CENTER TANK GAUGE (R6EJ)						Component ATA:28
PN:766-189-4	MOS/MSC	14-Nov-11	O/C	TSN 0				
SN:1012	HRS	11568.42		TSN 0				
WC#: 28.430	AFL	6104		TSN 0				
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-03		REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - LH FEEDER TANK GAUGE (L7EJ)						Component ATA:28
PN:766-190-2	MOS/MSC	14-Nov-11	O/C	TSN 0				
SN:889	HRS	11568.42		TSN 0				
WC#: 28.440	AFL	6104		TSN 0				
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-04		REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - CENTER FEEDER TANK GAUGE (25EJ)						Component ATA:28
PN:766-195-2	MOS/MSC	23-Feb-97	O/C					
SN:208	HRS	2618						
WC#: 28.460	AFL							
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-05-900-801-05 REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - RH FEEDER TANK GAUGE (R7EJ)								Component ATA:28
PN:766-190-2	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:862	HRS	10850.2		TSN 0				
WC#: 28.440	AFL	5878		TSN 0				
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-06 REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - FRONT TANK REAR GAUGE (23EJ)								Component ATA:28
PN:766-192-4	MOS/MSC	18-Oct-13	O/C					
SN:157	HRS	12430.13						
WC#: 28.450	AFL	6428						
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-07 REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - FRONT TANK FRONT GAUGE (24EJ)								Component ATA:28
PN:766-193-3	MOS/MSC	07-Feb-91	O/C					
SN:214	HRS	0		TSN 0				
WC#: 28.450	AFL	0						
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								
28-41-05-900-801-08 REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - REAR TANK GAUGE (26EJ)								Component ATA:28
PN:766-608-1	MOS/MSC	18-Jan-05	O/C					
SN:191	HRS	7174.8		TSR 0				
WC#: 28.460	AFL	3733						
PROC. REF: AMM 28-41-05-900-801PROC. REF: AMM 28-41-05-900-801								
28-41-09-900-801-01 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING INBOARD TANK GAUGE (L3EJ)								Component ATA:28
PN:792-366-1	MOS/MSC	07-Feb-91	O/C					
SN:771	HRS	0		TSN 0				
WC#: 28.400	AFL	0						
PROC. REF: AMM 28-41-09-900-801PROC. REF: AMM 28-41-09-900-801								
28-41-09-900-801-02 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING INBOARD TANK GAUGE (R3EJ)								Component ATA:28
PN:792-366-1	MOS/MSC	07-Feb-91	O/C					
SN:765	HRS	0		TSN 0				
WC#: 28.410	AFL	0						
PROC. REF: AMM 28-41-09-900-801PROC. REF: AMM 28-41-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-03 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING CENTER TANK GAUGE (L4EJ)								Component ATA:28
PN:792-367-2	MOS/MSC	07-Feb-91	O/C					
SN:836	HRS	0		TSN 0				
WC#: 28.400	AFL	0						
PROC. REF: AMM 28-41-09-900-801PROC. REF: AMM 28-41-09-900-801								
28-41-09-900-801-04 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING CENTER TANK GAUGE (R4EJ)								Component ATA:28
PN:792-367-2	MOS/MSC	07-Feb-91	O/C					
SN:816	HRS	0		TSN 0				
WC#: 28.410	AFL	0						
PROC. REF: AMM 28-41-09-900-801PROC. REF: AMM 28-41-09-900-801								
28-41-09-900-801-05 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING OUTBOARD TANK GAUGE (L5EJ)								Component ATA:28
PN:792-368-2	MOS/MSC	07-Feb-91	O/C					
SN:819	HRS	0		TSN 0				
WC#: 28.400	AFL	0						
PROC. REF: AMM 28-41-09-900-801PROC. REF: AMM 28-41-09-900-801								
28-41-09-900-801-06 REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING OUTBOARD TANK GAUGE (R5EJ)								Component ATA:28
PN:792-368-2	MOS/MSC	07-Feb-91	O/C					
SN:845	HRS	0		TSN 0				
WC#: 28.410	AFL	0						
PROC. REF: AMM 28-41-09-900-801PROC. REF: AMM 28-41-09-900-801								
28-41-13-900-801-04 REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - LH TANK GROUP FUEL QUANTITY INDICATOR (L8EJ)								Component ATA:28
PN:748-326-2	MOS/MSC	07-Feb-91	O/C					
SN:323	HRS	0		TSN 0				
WC#: 28.420	AFL	0						
PROC. REF: AMM 28-41-13-900-801PROC. REF: AMM 28-41-13-900-801								
28-41-13-900-801-05 REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - CENTER TANK GROUP FUEL QUANTITY INDICATOR (27EJ)								Component ATA:28
PN:748-469-1	MOS/MSC	07-Feb-91	O/C					
SN:209	HRS	0		TSN 0				
WC#: 28.420	AFL	0						
PROC. REF: AMM 28-41-13-900-801PROC. REF: AMM 28-41-13-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-13-900-801-06		REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - RH TANK GROUP FUEL QUANTITY INDICATOR (R8EJ)						Component ATA:28
PN:748-326-2	MOS/MSC	07-Feb-91	O/C					
SN:322	HRS	0		TSN 0				
WC#: 28.420	AFL	0						
PROC. REF: AMM 28-41-13-900-801PROC. REF: AMM 28-41-13-900-801								
28-41-17-900-801-01		REMOVAL / INSTALLATION OF THE FUEL GAUGE AMPLIFIERS - LH TANK GROUP GAUGES AMPLIFIER (L2EJ)						Component ATA:28
PN:736-327-1	MOS/MSC		O/C					
SN:456	HRS	2386		TSN 0				
WC#: 28.390	AFL							
PROC. REF: AMM 28-41-17-900-801PROC. REF: AMM 28-41-17-900-801								
28-41-17-900-801-02		REMOVAL / INSTALLATION OF THE FUEL GAUGE AMPLIFIERS - RH TANK GROUP GAUGES AMPLIFIER (R2EJ)						Component ATA:28
PN:736-327-1	MOS/MSC		O/C					
SN:307	HRS	546		TSN 0				
WC#: 28.390	AFL							
PROC. REF: AMM 28-41-17-900-801PROC. REF: AMM 28-41-17-900-801								
28-41-17-900-801-03		REMOVAL / INSTALLATION OF THE FUEL GAUGE AMPLIFIERS - CENTER TANK GROUP GAUGES AMPLIFIER (22EJ)						Component ATA:28
PN:736-328-2	MOS/MSC	04-Apr-05	O/C	TSR 0				
SN:298	HRS	7413.9		TSR 0				
WC#: 28.390	AFL	3876		TSR 0				
PROC. REF: AMM 28-41-17-900-801PROC. REF: AMM 28-41-17-900-801								
28-43-01-720-801-01		FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR - FUEL TEMPERATURE SENSOR (3ER)						Service ATA:28
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 28.490	AFL	0						
PROC. REF: AMM 28-43-01-720-801PROC. REF: AMM 28-43-01-720-801								
28-43-01-900-801-01		REMOVAL / INSTALLATION OF THE FUEL TEMPERATURE SENSOR - FUEL TEMPERATURE SENSOR (3ER)						Component ATA:28
PN:1122505	MOS/MSC	07-Feb-91	O/C					
SN:NOT INST.	HRS	0		TSN 0				
WC#: 28.490	AFL	0						
PROC. REF: AMM 28-43-01-900-801PROC. REF: AMM 28-43-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-50-05-700-801-01	INTEGRITY CHECK OF HIGH-LEVEL SENSORS							Service ATA:28
	MOS/MSC	03-Sep-10	O/C					
	HRS	11012						
WC#: 28.590	AFL	5930						
PROC. REF: AMM 28-50-05-700-801PROC. REF: AMM 28-50-05-700-801								
28-50-05-900-801-01	REMOVAL / INSTALLATION OF THE HIGH-LEVEL SENSORS - LH HIGH LEVEL SENSOR (L12QS)							Component ATA:28
PN:722105-3	MOS/MSC	27-May-11	O/C	TSN 0				
SN:1253	HRS	11414.25		TSN 0				
WC#: 28.470	AFL	6044		TSN 0				
PROC. REF: AMM 28-50-05-900-801PROC. REF: AMM 28-50-05-900-801								
28-50-05-900-801-02	REMOVAL / INSTALLATION OF THE HIGH-LEVEL SENSORS - RH HIGH LEVEL SENSOR (R12QS)							Component ATA:28
PN:722105-3	MOS/MSC	27-May-11	O/C	TSN 0				
SN:1239	HRS	11414.25		TSN 0				
WC#: 28.470	AFL	6044		TSN 0				
PROC. REF: AMM 28-50-05-900-801PROC. REF: AMM 28-50-05-900-801								
28-70-01-780-801-01 ^S	CHECK FOR CORRECT CALIBRATION OF THE PRESSURE GAUGE - PRESSURE GAUGE (506QD)							Service ATA:28
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 28.240	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 28-70-01-780-801PROC. REF: AMM 28-70-01-780-801								
28-70-05-900-801-01	REMOVAL / INSTALLATION OF THE PRESSURE REDUCING VALVE - PRESSURE REDUCING VALVE (500QD)							Component ATA:28
PN:B14DE2080	MOS/MSC	17-Dec-21	O/C					
SN:141	HRS	13275.5						
WC#: 28.170	AFL	6741						
PROC. REF: AMM 28-70-05-900-801PROC. REF: AMM 28-70-05-900-801								
28-70-09-350-801-01	RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - LH VALVE BOX (L507QD)							Service ATA:28
PN:B04BA1006	MOS	17-Dec-21						
SN:369	HRS	10865.5	5000 (+3%)		15865.5	16015.5	1969.2 (+150)	
	AFL	5891						
PROC. REF: AMM 28-70-09-350-801PROC. REF: AMM 28-70-09-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-70-09-350-801-02		RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - RH VALVE BOX (R507QD)						Service ATA:28
PN:B04BA1006	MOS	30-Jan-07						
SN:800	HRS	9294.2	5000 (+3%)		14294.2	14444.2	397.9 (+150)	
	AFL	4969						
PROC. REF: AMM 28-70-09-350-801PROC. REF: AMM 28-70-09-350-801								
28-70-09-900-801-01		REMOVAL / INSTALLATION OF THE VALVE BOXES - LH VALVE BOX (L507QD)						Component ATA:28
PN:B04BA1006	MOS/MSC	17-Dec-21	O/C	TSR 153				
SN:369	HRS	13275.5		TSR 2410				
WC#: 28.210	AFL	6741		TSR 850				
PROC. REF: AMM 28-70-09-900-801PROC. REF: AMM 28-70-09-900-801								
28-70-09-900-801-02		REMOVAL / INSTALLATION OF THE VALVE BOXES - RH VALVE BOX (R507QD)						Component ATA:28
PN:B04BA1006	MOS/MSC	17-Dec-21	O/C	TSR 157				
SN:800	HRS	13275.5		TSR 2509.8				
WC#: 28.210	AFL	6741		TSR 926				
PROC. REF: AMM 28-70-09-900-801PROC. REF: AMM 28-70-09-900-801								
28-70-13-350-801-01		RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L509QD)						Service ATA:28
PN:B06GA1052-1	MOS/MSC	EFF	O/C					
SN:5770	HRS	EFF						
	AFL	EFF						
PROC. REF: AMM 28-70-13-350-801PROC. REF: AMM 28-70-13-350-801								
28-70-13-350-801-02		RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R509QD)						Service ATA:28
PN:B06GA1051	MOS/MSC	EFF	O/C					
SN:2981	HRS	EFF						
	AFL	EFF						
PROC. REF: AMM 28-70-13-350-801PROC. REF: AMM 28-70-13-350-801								
28-70-13-720-802-01		FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L509QD)						Service ATA:28
PN:B06GA1052-1	MOS							
SN:5770	HRS	13275.5	5000		18275.5		4379.2	
	AFL	6741						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-70-13-720-802PROC. REF: AMM 28-70-13-720-802								
28-70-13-720-802-02	FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R509QD)							Service ATA:28
PN:B06GA1051	MOS	10-Aug-07						
SN:2981	HRS	9902.6	5000		14902.6		1006.3	
	AFL	5277						
PROC. REF: AMM 28-70-13-720-802PROC. REF: AMM 28-70-13-720-802								
28-70-13-900-801-01	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L509QD)							Component ATA:28
PN:B06GA1052-1	MOS/MSC	17-Dec-21	O/C					
SN:5770	HRS	13275.5						
WC#: 28.230	AFL	6741						
PROC. REF: AMM 28-70-13-900-801PROC. REF: AMM 28-70-13-900-801								
28-70-13-900-801-02	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R509QD)							Component ATA:28
PN:B06GA1051	MOS/MSC	10-Aug-07	O/C	TSN 0				
SN:2981	HRS	9902.6		TSN 0				
WC#: 28.230	AFL	5277		TSN 0				
PROC. REF: AMM 28-70-13-900-801PROC. REF: AMM 28-70-13-900-801								
28-70-17-130-801-01 ^S	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 1 PRESSURIZATION AIR FILTER (L502QD)							Service ATA:28
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 28.190	AFL	6741						
								PKG:21
PROC. REF: AMM 28-70-17-130-801PROC. REF: AMM 28-70-17-130-801								
28-70-17-130-801-02 ^S	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 2 PRESSURIZATION AIR FILTER (M502QD)							Service ATA:28
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 28.190	AFL	6741						
								PKG:21
PROC. REF: AMM 28-70-17-130-801PROC. REF: AMM 28-70-17-130-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-70-21-900-801-01 REMOVAL / INSTALLATION OF THE VENT VALVES - LH VENT VALVE (L5QS)								Component ATA:28
PN:B97F38-653	MOS/MSC	07-Feb-91	O/C					
SN:20035	HRS	0		TSN 0				
WC#: 28.130	AFL	0						
PROC. REF: AMM 28-70-21-900-801PROC. REF: AMM 28-70-21-900-801								
28-70-21-900-801-02 RH WING VENT VALVE								Component ATA:28
PN:B97F38-653	MOS/MSC	07-Feb-91	O/C					
SN:20036	HRS	0		TSN 0				
WC#: 28.130	AFL	0						
PROC. REF: AMM 28-70-21-900-801PROC. REF: AMM 28-70-21-900-801								
28-70-37-230-801-01 SPECIAL DETAILED INSPECTION OF FRAME 12 PRESSURIZATION LINE BASEPLATES								Service ATA:28
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 28.580	AFL	0						
PROC. REF: AMM 28-70-37-230-801PROC. REF: AMM 28-70-37-230-801								
281101 PRESSURE FUELING COUPLING								Component ATA:28
PN:K97-63-206	MOS/MSC	07-Feb-91	O/C					
SN:20377	HRS	0		TSN 0				
WC#: 28.040	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281211 FILLING BLOCK								Component ATA:28
PN:K99-31-007	MOS/MSC	07-Feb-91	O/C					
SN:20099	HRS	0		TSN 0				
WC#: 28.090	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281221 FRONT FUEL TANK FILLING ELECTRIC CHECK VALVE								Component ATA:28
PN:L96Z31-201	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281231	CENTER FUEL TANK FILLING ELECTRIC VALVE							Component ATA:28
PN:L96Z31-201	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281241	REAR FUEL TANK FILLING ELECTRIC VALVE							Component ATA:28
PN:L96Z31-201	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281251	FRONT FUEL TANK FILLING RESTRICTOR VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.110	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281261	CENTER FUEL TANK FILLING RESTRICTOR VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.110	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281271	REAR FUEL TANK FILLING RESTRICTOR VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.110	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281281	REAR FUEL TANK FILLING CHECK VALVE							Component ATA:28
PN:L85D38-001	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.120	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281311	LH WING FUELING ELECTRIC VALVE							Component ATA:28
PN:L94Z31-201	MOS/MSC	07-Feb-91	O/C					
SN:21026	HRS	0		TSN 0				
WC#: 28.140	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281321	RH WING FUELING ELECTRIC VALVE							Component ATA:28
PN:L94Z31-201	MOS/MSC	07-Feb-91	O/C					
SN:21027	HRS	0		TSN 0				
WC#: 28.140	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281331	FRONT/REAR FUEL TANK FUELING ELECTRIC VALVE							Component ATA:28
PN:L94Z31-201	MOS/MSC	07-Feb-91	O/C					
SN:21028	HRS	0		TSN 0				
WC#: 28.140	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
281351	LP3-1 ELECTRIC INTERCONNECTION VALVE							Component ATA:28
PN:L92B07-205	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.150	AFL	0						
PROC. REF: AMM 28-22-01-900-801PROC. REF: AMM 28-22-01-900-801								
282151	NO. 1 ENGINE PRESSURE BLEED CHECK VALVE							Component ATA:28
PN:L96Z19-003	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.180	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
282161	NO. 2 ENGINE PRESSURE BLEED CHECK VALVE							Component ATA:28
PN:L96Z19-003	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.180	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282201	NO. 1 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT							Component ATA:28
PN:P6742	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.190	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
282221	NO. 2 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT							Component ATA:28
PN:P6742	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.190	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
282451	FUEL PRESSURE GAGE							Component ATA:28
PN:MPMC50701-01	MOS/MSC	19-Jul-02	O/C	TSR 0				
SN:220	HRS	5476.9		TSR 0				
WC#: 28.240	AFL	2587		TSR 0				
PROC. REF: AMM 28-41-05-900-801, AMM 28-41-09-900-801PROC. REF: AMM 28-41-05-900-801, AMM 28-41-09-900-801								
282501	PARTIAL FUEL SELECTOR							Component ATA:28
PN:796-740	MOS/MSC	07-Feb-91	O/C					
SN:213	HRS	0		TSN 0				
WC#: 28.550	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
283121	XTK2 TRANSFER SOLENOID VALVE							Component ATA:28
PN:B97-38-662	MOS/MSC	06-Mar-05	O/C	TSO 0				
SN:20074	HRS	7323.9		TSO 0				
WC#: 28.260	AFL	3830		TSO 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
284251	NO. 2 ENGINE PUMPS BLOCK							Component ATA:28
PN:L88A31-206	MOS/MSC	07-Feb-91	O/C					
SN:20095	HRS	0		TSN 0				
WC#: 28.330	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284321	LOW PRESSURE 1-2 CROSSFEED ELECTRIC VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.350	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
284351	LOW PRESSURE 2-3 CROSSFEED ELECTRIC VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.350	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285401	LOW LEVEL THERMISTOR RELAY BOX							Component ATA:28
PN:722-087-2	MOS/MSC	07-Feb-91	O/C					
SN:378	HRS	0		TSN 0				
WC#: 28.480	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285421	1000 LBS LEVEL DETECTION BOX							Component ATA:28
PN:722-087-2	MOS/MSC	16-Jun-22	O/C					
SN:329	HRS	13419.3						
WC#: 28.480	AFL	6854						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285461	FUEL TEMPERATURE INDICATOR							Component ATA:28
PN:5318-201-80-10	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.490	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285471	REAR TANK LEVEL RELAY BOX							Component ATA:28
PN:722-233-1	MOS/MSC	24-Jan-08	O/C					
SN:205	HRS	10296.4						
WC#: 28.500	AFL	5492						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
285501	NO. 1 ENGINE LOW PRESSURE PRESSURE SWITCH							Component ATA:28
PN:8G1256-1	MOS/MSC	07-Feb-91	O/C					
SN:912	HRS	0		TSN 0				
WC#: 28.510	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285511	NO. 2 ENGINE LOW PRESSURE SWITCH							Component ATA:28
PN:8G1256-1	MOS/MSC	07-Feb-91	O/C					
SN:825	HRS	0		TSN 0				
WC#: 28.510	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285521	NO. 3 ENGINE LOW PRESSURE SWITCH							Component ATA:28
PN:8G1256-1	MOS/MSC	30-Mar-05	O/C					
SN:3098	HRS	7391.4		TSN 0				
WC#: 28.510	AFL	3865						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285531	HIGH LEVEL RELAY BOX							Component ATA:28
PN:722-087-2	MOS/MSC	20-Dec-04	O/C					
SN:0623	HRS	7062.9		TSN 0				
WC#: 28.520	AFL	3690						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
285701	FUELING PANEL							Component ATA:28
PN:19-54-6	MOS/MSC	07-Mar-08	O/C	TSR 0				
SN:136	HRS	10360.3		TSR 0				
WC#: 28.540	AFL	5544		TSR 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
ATA 29 - HYDRAULIC POWER								
29-10-00-720-801-01	^S	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 1						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					

PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-10-00-720-801PROC. REF: AMM 29-10-00-720-801								
29-10-00-720-801-02 ^S FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 2 Service ATA:29								
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-10-00-720-801PROC. REF: AMM 29-10-00-720-801								
29-11-01-350-801-01 RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 1 (L500ML) Service ATA:29								
PN:4204501	MOS	12-Oct-09		TAC 1				OVERHAUL
SN:ME23	HRS	10859.7	3240	TAC 0	14099.7		203.4	
WC#: 29.050	AFL	5883		TAC 0				
PROC. REF: AMM 29-11-01-350-801PROC. REF: AMM 29-11-01-350-801								
29-11-01-350-801-02 RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 2 (M500ML) Service ATA:29								
PN:4204501	MOS	27-May-11		TAC 0				OVERHAUL
SN:BD120	HRS	11414.25	3240	TAC 0	14654.25		758	
WC#: 29.050	AFL	6044		TAC 0				
PROC. REF: AMM 29-11-01-350-801PROC. REF: AMM 29-11-01-350-801								
29-11-01-350-801-03 RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 3 (R500ML) Service ATA:29								
PN:4204501	MOS	31-Mar-14						OVERHAUL
SN:BU659	HRS	12625.42	3240		15865.42		1969.1	
WC#: 29.050	AFL	6516						
PROC. REF: AMM 29-11-01-350-801PROC. REF: AMM 29-11-01-350-801								
29-11-01-900-801-01 REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 1 (L500ML) Component ATA:29								
PN:4204501	MOS/MSC	12-Oct-09	H/T	TSO 1				
SN:ME23	HRS	10859.7		TSO 0				
WC#: 29.050	AFL	5883		TSO 0				
PROC. REF: AMM 29-11-01-900-801PROC. REF: AMM 29-11-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-11-01-900-801-02		REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 2 (M500ML)					Component	ATA:29
PN:4204501	MOS/MSC	27-May-11	H/T	TSO 0				
SN:BD120	HRS	11414.25		TSO 0, Adj -37.55				
WC#: 29.050	AFL	6044		TSO 0				
PROC. REF: AMM 29-11-01-900-801PROC. REF: AMM 29-11-01-900-801								
29-11-01-900-801-03		REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 3 (R500ML)					Component	ATA:29
PN:4204501	MOS/MSC	31-Mar-14	H/T	TSO 0				
SN:BU659	HRS	12625.42		TSO 0				
WC#: 29.050	AFL	6516		TSO 0				
PROC. REF: AMM 29-11-01-900-801PROC. REF: AMM 29-11-01-900-801								
29-11-21-230-801-01		SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)					Service	ATA:29
PN:A24518-001	MOS/MSC	28-Nov-08	O/C					
SN:FM805	HRS	10765.7						
WC#: 29.070	AFL	5815						
PROC. REF: AMM 29-11-21-230-801PROC. REF: AMM 29-11-21-230-801								
29-11-21-230-801-02		SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)					Service	ATA:29
PN:A24518-001	MOS/MSC	28-Nov-08	O/C					
SN:FM645	HRS	10765.7						
WC#: 29.070	AFL	5815						
PROC. REF: AMM 29-11-21-230-801PROC. REF: AMM 29-11-21-230-801								
29-11-21-230-801-03		SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)					Service	ATA:29
PN:A24518001	MOS/MSC	28-Nov-08	O/C					
SN:FM843	HRS	10765.7						
WC#: 29.075	AFL	5815						
PROC. REF: AMM 29-11-21-230-801PROC. REF: AMM 29-11-21-230-801								
29-11-21-900-801-01		REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)					Component	ATA:29
PN:A24518-001	MOS/MSC	28-Nov-08	O/C	TSO 0				
SN:FM805	HRS	10765.7		TSO 0				
WC#: 29.070	AFL	5815		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-11-21-900-801PROC. REF: AMM 29-11-21-900-801								
29-11-21-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)						Component	ATA:29
PN:A24518-001	MOS/MSC	28-Nov-08	O/C					
SN:FM645	HRS	10765.7						
WC#: 29.070	AFL	5815						
PROC. REF: AMM 29-11-21-900-801PROC. REF: AMM 29-11-21-900-801								
29-11-21-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)						Component	ATA:29
PN:A24518001	MOS/MSC	07-Mar-08	O/C					
SN:FM843	HRS	10360.3						
WC#: 29.075	AFL	5544						
PROC. REF: AMM 29-11-21-900-801PROC. REF: AMM 29-11-21-900-801								
29-11-25-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (2DW1)						Component	ATA:29
PN:15H0089PH	MOS/MSC	17-Dec-21	O/C					
SN:13	HRS	13275.5						
WC#: 29.190	AFL	6741						
PROC. REF: AMM 29-11-25-900-801PROC. REF: AMM 29-11-25-900-801								
29-11-25-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (2DW2)						Component	ATA:29
PN:15H0089PH	MOS/MSC	03-Nov-06	O/C	TSN 0				
SN:0020	HRS	9207.9		TSN 0				
WC#: 29.190	AFL	4818		TSN 0				
PROC. REF: AMM 29-11-25-900-801PROC. REF: AMM 29-11-25-900-801								
29-11-25-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (2DW3)						Component	ATA:29
PN:15H0089PH	MOS/MSC	17-Dec-21	O/C					
SN:21	HRS	13275.5						
WC#: 29.190	AFL	6741						
PROC. REF: AMM 29-11-25-900-801PROC. REF: AMM 29-11-25-900-801								
29-11-25-960-801-01	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (2DW1)						Service	ATA:29
PN:15H0089PH	MOS/MSC		O/C					
SN:13	HRS							
WC#: 29.190	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-11-25-960-801PROC. REF: AMM 29-11-25-960-801								
29-11-25-960-801-02		DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (2DW2)						Service ATA:29
PN:15H0089PH	MOS/MSC	03-Nov-06	O/C	TAC 0				
SN:0020	HRS	9207.9		TAC 0				
WC#: 29.190	AFL	4818		TAC 0				
PROC. REF: AMM 29-11-25-960-801PROC. REF: AMM 29-11-25-960-801								
29-11-25-960-801-03		DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (2DW3)						Service ATA:29
PN:15H0089PH	MOS/MSC		O/C					
SN:21	HRS							
WC#: 29.190	AFL							
PROC. REF: AMM 29-11-25-960-801PROC. REF: AMM 29-11-25-960-801								
29-13-09-900-801-01		NO. 1 SYSTEM HYDRAULIC FILTER						Component ATA:29
PN:AD3258-10Y12	MOS/MSC	07-Feb-91	O/C					
SN:0104	HRS	0		TSN 0				
WC#: 29.110	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
29-13-09-900-801-02		NO. 2 SYSTEM HYDRAULIC FILTER						Component ATA:29
PN:AD3258-8Y54	MOS/MSC	07-Feb-91	O/C					
SN:0103	HRS	0		TSN 0				
WC#: 29.110	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
29-13-09-960-801-01 ^S		REPLACEMENT OF THE HYDRAULIC FILTERS - STANDBY PUMP FILTER (14ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								

PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-13-09-960-801-02	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 1 RETURN FILTER (L200ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31
29-13-09-960-801-03	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 2 RETURN FILTER (M200ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31
29-13-09-960-801-04	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 3 RETURN FILTER (R200ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31
29-13-09-960-801-05	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - SYSTEM 1 GENERAL RETURN FILTER (L300ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31
29-13-09-960-801-06	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - SYSTEM 2 GENERAL RETURN FILTER (R300ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-13-09-960-801-07	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 1 DELIVERY FILTER (L350ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31
29-13-09-960-801-08	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 2 DELIVERY FILTER (M350ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31
29-13-09-960-801-09	^S	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 3 DELIVERY FILTER (R350ML)						Service ATA:29
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 29-13-09-960-801PROC. REF: AMM 29-13-09-960-801								PKG:31
29-14-01-680-801-01		DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)						Service ATA:29
	MOS/MSC	25-Feb-11	O/C					
	HRS	11293.42						
WC#: 29.030	AFL	6006						
PROC. REF: AMM 29-14-01-680-801PROC. REF: AMM 29-14-01-680-801								
29-14-01-680-801-02		DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)						Service ATA:29
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
WC#: 29.030	AFL	5878						
PROC. REF: AMM 29-14-01-680-801PROC. REF: AMM 29-14-01-680-801								
29-14-01-900-801-01		REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)						Component ATA:29
PN:029029-06	MOS/MSC	25-Feb-11	O/C	TSR 0				
SN:38	HRS	11293.42		TSR 0				
WC#: 29.030	AFL	6006		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-14-01-900-801PROC. REF: AMM 29-14-01-900-801								
29-14-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)							Component ATA:29
PN:029029-05	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:256	HRS	10850.2		TSR 0				
WC#: 29.030	AFL	5878		TSR 0				
PROC. REF: AMM 29-14-01-900-801PROC. REF: AMM 29-14-01-900-801								
29-14-09-900-802-01	REMOVAL / INSTALLATION OF HYDRAULIC SYSTEM PRESSURE- HOLDING VALVES - SYSTEM 1 PRESSURE-HOLDING VALVE (L525ML)							Component ATA:29
PN:70073	MOS/MSC	07-Feb-91	O/C					
SN:192	HRS	0		TSN 0				
WC#: 29.090	AFL	0						
PROC. REF: AMM 29-14-09-900-802PROC. REF: AMM 29-14-09-900-802								
29-14-09-900-802-02	REMOVAL / INSTALLATION OF HYDRAULIC SYSTEM PRESSURE- HOLDING VALVES - SYSTEM 2 PRESSURE-HOLDING VALVE (R525ML)							Component ATA:29
PN:70073	MOS/MSC	07-Feb-91	O/C					
SN:193	HRS	0		TSN 0				
WC#: 29.090	AFL	0						
PROC. REF: AMM 29-14-09-900-802PROC. REF: AMM 29-14-09-900-802								
29-14-11-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 1 ACCUMULATOR (L515ML)							Component ATA:29
PN:60833-2	MOS/MSC	07-Feb-91	O/C					
SN:557	HRS	0		TSN 0				
WC#: 29.060	AFL	0						
PROC. REF: AMM 29-14-11-900-801PROC. REF: AMM 29-14-11-900-801								
29-14-11-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 2 ACCUMULATOR (R515ML)							Component ATA:29
PN:60833-2	MOS/MSC	07-Feb-91	O/C					
SN:558	HRS	0		TSN 0				
WC#: 29.060	AFL	0						
PROC. REF: AMM 29-14-11-900-801PROC. REF: AMM 29-14-11-900-801								
29-20-00-720-801-02	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - SYSTEM 2							Service ATA:29
	MOS	17-Sep-25						
	HRS	13856.1	5000 (+40)		18856.1	18896.1	4959.8 (+40)	
	AFL	7271						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-20-00-720-801PROC. REF: AMM 29-20-00-720-801								
29-20-01-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY ELECTRIC PUMP - STANDBY ELECTRIC PUMP (3ML)							Component ATA:29
PN:42032	MOS/MSC	10-Aug-07	O/C					
SN:0Z16	HRS	9902.6						
WC#: 29.240	AFL	5277						
PROC. REF: AMM 29-20-01-900-801PROC. REF: AMM 29-20-01-900-801								
29-20-03-220-801-01	CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (3ML)							Service ATA:29
PN:42032	MOS	10-Aug-07						
SN:0Z16	HRS	9902.6	5000 (+3%)		14902.6	15052.6	1006.3 (+150)	
WC#: 29.240	AFL	5277						
PROC. REF: AMM 29-20-03-220-801PROC. REF: AMM 29-20-03-220-801								
29-20-03-720-801-01	FUNCTIONAL TEST OF THE STANDBY ELECTRIC PUMP MOTOR - STANDBY ELECTRIC PUMP (3ML)							Service ATA:29
PN:42032	MOS/MSC	10-Aug-07	O/C					
SN:0Z16	HRS	9902.6						
WC#: 29.240	AFL	5277						
PROC. REF: AMM 29-20-03-720-801PROC. REF: AMM 29-20-03-720-801								
29-20-05-900-801-01	REMOVAL / INSTALLATION OF THE STANDBY PUMP SELECTOR VALVE - STANDBY PUMP SELECTOR VALVE (5ML)							Component ATA:29
PN:B94A13-205	MOS/MSC	07-Feb-91	O/C					
SN:20212	HRS	0		TSN 0				
WC#: 29.260	AFL	0						
PROC. REF: AMM 29-20-05-900-801PROC. REF: AMM 29-20-05-900-801								
29-20-07-900-801-01	REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (L4ML)							Component ATA:29
PN:15H0092PH	MOS/MSC	17-Dec-21	O/C					
SN:470	HRS	13275.5						
WC#: 29.200	AFL	6741						
PROC. REF: AMM 29-20-07-900-801PROC. REF: AMM 29-20-07-900-801								
29-20-07-900-801-02	REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (R4ML)							Component ATA:29
PN:15H0092PH	MOS/MSC	17-Dec-21	O/C					
SN:461	HRS	13275.5						
WC#: 29.200	AFL	6741						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-20-07-900-801PROC. REF: AMM 29-20-07-900-801								
29-20-07-960-801-01		DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (L4ML)						Service ATA:29
PN:15H0092PH	MOS/MSC		O/C					
SN:470	HRS							
WC#: 29.200	AFL							
PROC. REF: AMM 29-20-07-960-801PROC. REF: AMM 29-20-07-960-801								
29-20-07-960-801-02		DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (R4ML)						Service ATA:29
PN:15H0092PH	MOS/MSC		O/C					
SN:461	HRS							
WC#: 29.200	AFL							
PROC. REF: AMM 29-20-07-960-801PROC. REF: AMM 29-20-07-960-801								
291091		NO. 1 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR VALVE						Component ATA:29
PN:034001	MOS/MSC	16-Aug-97	O/C					
SN:201	HRS	2896						
WC#: 29.040	AFL							
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291141		NO. 2 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR VALVE						Component ATA:29
PN:034001	MOS/MSC	27-Jan-06	O/C	TSN 0				
SN:635	HRS	8376.7		TSN 0				
WC#: 29.040	AFL	4401		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291311		NO. 1 HYDRAULIC PUMP DISCHARGE FILTER						Component ATA:29
PN:AD3255-8Y60	MOS/MSC	07-Feb-91	O/C					
SN:0319	HRS	0		TSN 0				
WC#: 29.080	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291321		NO. 2 HYDRAULIC PUMP DISCHARGE FILTER						Component ATA:29
PN:AD3255-8Y60	MOS/MSC	07-Feb-91	O/C					
SN:0322	HRS	0		TSN 0				
WC#: 29.080	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291331	NO. 3 HYDRAULIC PUMP DISCHARGE FILTER							Component ATA:29
PN:AD3255-8Y60	MOS/MSC	07-Feb-91	O/C					
SN:0320	HRS	0		TSN 0				
WC#: 29.080	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291346	NO. 1 HYDRAULIC SYSTEM PRESSURE GAUGE							Component ATA:29
PN:18040100	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.095	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291356	NO. 2 HYDRAULIC SYSTEM PRESSURE GAUGE							Component ATA:29
PN:18040100	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.095	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291361	NO. 1 PUMP REGULATION RETURN FILTER							Component ATA:29
PN:ADB296-5Y3	MOS/MSC	07-Feb-91	O/C					
SN:0293	HRS	0		TSN 0				
WC#: 29.100	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291381	NO. 2 PUMP REGULATION RETURN FILTER							Component ATA:29
PN:ADB296-5Y3	MOS/MSC	07-Feb-91	O/C					
SN:0290	HRS	0		TSN 0				
WC#: 29.100	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291401	NO. 3 PUMP REGULATION RETURN FILTER							Component ATA:29
PN:ADB296-5Y3	MOS/MSC	07-Feb-91	O/C					
SN:0291	HRS	0		TSN 0				
WC#: 29.100	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291461	NO. 1 SUCTION SYSTEM HYDRAULIC GROUND CONNECTION							Component ATA:29
PN:B3005-S4-12D	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 29.120	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291471	NO. 2 SUCTION SYSTEM HYDRAULIC GROUND CONNECTION							Component ATA:29
PN:B3005-S4-12D	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 29.120	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291481	NO. 1 DISCHARGE SYSTEM HYDRAULIC GROUND CONNECTION							Component ATA:29
PN:TB3005-S4-8D	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.130	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291491	NO. 2 DISCHARGE SYSTEM HYDRAULIC GROUND CONNECTION							Component ATA:29
PN:TB3005-S4-8D	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.130	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291501	NO. 1 DISCHARGE PUMP QUICK DISCHARGE VALVE							Component ATA:29
PN:405-20403-13200	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.140	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291511	NO. 2 DISCHARGE PUMP QUICK DISCHARGE VALVE							Component ATA:29
PN:405-20403-13200	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.140	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291521	NO. 3 DISCHARGE PUMP QUICK DISCHARGE VALVE							Component ATA:29
PN:405-20403-13200	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.140	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291531	NO. 1 SUCTION PUMP QUICK DISCHARGE VALVE							Component ATA:29
PN:405-20402-13300	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.150	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291541	NO. 2 SUCTION PUMP QUICK DISCHARGE VALVE							Component ATA:29
PN:405-20402-13300	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.150	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291551	NO. 3 SUCTION PUMP QUICK DISCHARGE VALVE							Component ATA:29
PN:405-20402-13300	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.150	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291561	NO. 1 RETURN REGULATION PUMP CHECK VALVE							Component ATA:29
PN:A24515-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.160	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291571	NO. 2 AFT RETURN REGULATION PUMP CHECK VALVE							Component ATA:29
PN:A24515-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.160	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291581 NO. 3 RETURN REGULATION PUMP CHECK VALVE								Component ATA:29
PN:A24515-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.160	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291591 NO. 1 FILTER/PUMP PROTECTION CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	07-Feb-91	O/C					
SN:FM1625	HRS	0		TSN 0				
WC#: 29.170	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291601 NO. 2 PUMP PROTECTION CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	07-Feb-91	O/C					
SN:FM1624	HRS	0		TSN 0				
WC#: 29.180	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291611 NO. 2 FILTER PROTECTION CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	07-Feb-91	O/C					
SN:FM1630	HRS	0		TSN 0				
WC#: 29.170	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291621 NO. 3 PUMP PROTECTION CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	07-Feb-91	O/C					
SN:FM1637	HRS	0		TSN 0				
WC#: 29.180	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291631 NO. 2 SYSTEM EXTERIOR POWER SUPPLY CHECK VALVE								Component ATA:29
PN:A24517	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.185	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291701	NO. 1 LEVEL/PRESSURE DUAL INDICATOR							Component ATA:29
PN:5502-380-80-10	MOS/MSC	24-Aug-07	O/C		TSR 0			
SN:1038	HRS	9929.6			TSR 0			
WC#: 29.210	AFL	5297			TSR 0			
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291711	NO. 2 LEVEL/PRESSURE DUAL INDICATOR							Component ATA:29
PN:5502-380-80-10	MOS/MSC	07-Sep-07	O/C					
SN:922	HRS	9970.3			TSR 0			
WC#: 29.210	AFL	5326						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291721	NO. 1 SYSTEM PRESSURE TRANSMITTER							Component ATA:29
PN:8107-132-00-10	MOS/MSC	07-Feb-91	O/C					
SN:306	HRS	0			TSN 0			
WC#: 29.220	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291731	NO. 2 SYSTEM PRESSURE TRANSMITTER							Component ATA:29
PN:8107-132-00-10	MOS/MSC	07-Feb-91	O/C					
SN:265	HRS	0			TSN 0			
WC#: 29.220	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291751	NO. 1 SYSTEM HYDRAULIC QUANTITY GAUGE							Component ATA:29
PN:18040100	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 29.230	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
291761	NO. 2 SYSTEM HYDRAULIC QUANTITY GAUGE							Component ATA:29
PN:18040100	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 29.230	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 29 - HYDRAULIC POWER

PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1

292171	ELECTRIC PUMP DISCHARGE FILTER						Component	ATA:29
PN:AD3255-8Y63	MOS/MSC	07-Feb-91	O/C					
SN:0108	HRS	0		TSN 0				
WC#: 29.260	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

292201	NO. 1 SYSTEM ELECTRIC PUMP PROTECTION CHECK VALVE						Component	ATA:29
PN:A24516	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.270	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

292211	NO. 2 SYSTEM ELECTRIC PUMP PROTECTION CHECK VALVE						Component	ATA:29
PN:A24516	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.270	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

292301	HYDRAULIC CONTROL PANEL						Component	ATA:29
PN:380TS06Y02	MOS/MSC	24-Sep-94	O/C	TSN 0				
SN:135	HRS			TSN 0				
WC#: 29.280	AFL			TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

ATA 30 - ICE AND RAIN PROTECTION

30-00-00-960-801-01	^S	REPLACEMENT OF THE ANTI-ICING SYSTEM WIGGINS COUPLING SEALS					Service	ATA:30
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 30.040	AFL	6741	7500					
PROC. REF: AMM 30-00-00-960-801PROC. REF: AMM 30-00-00-960-801								

PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-00-350-801-01		RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH INBOARD SLAT TELESCOPIC DUCT (L501HJ)						Service ATA:30
PN:5035-600	MOS/MSC	12-Jun-09	O/C					
SN:252	HRS	10850.2						
WC#: 30.060	AFL	5878						
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-350-801-02		RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH INBOARD SLAT TELESCOPIC DUCT (R501HJ)						Service ATA:30
PN:5036-700	MOS/MSC	28-Nov-08	O/C	TAC 0				
SN:382	HRS	10765.7		TAC 0				
WC#: 30.060	AFL	5815		TAC 0				
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-350-801-03		RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH OUTBOARD SLAT TELESCOPIC DUCT (L502HJ)						Service ATA:30
PN:5035-600	MOS/MSC	12-Jun-09	O/C	TAC 0				
SN:740	HRS	10850.2		TAC 0				
WC#: 30.050	AFL	5878		TAC 0				
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-350-801-04		RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH OUTBOARD SLAT TELESCOPIC DUCT (R502HJ)						Service ATA:30
PN:5035-700	MOS/MSC	12-Jun-09	O/C	TAC 0				
SN:636R	HRS	10850.2		TAC 0				
WC#: 30.050	AFL	5878		TAC 0				
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-720-801-01		FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH INBOARD SLAT TELESCOPIC DUCT (L501HJ)						Service ATA:30
PN:5035-600	MOS	08-Aug-14						
SN:252	HRS	12881.35	1240 (+3%)		14121.35	14158.55	225.1 (+37.2)	
WC#: 30.060	AFL	6629	1000 (+3%)		7629	7659	316 (+30)	
PROC. REF: AMM 30-11-00-720-801PROC. REF: AMM 30-11-00-720-801								
30-11-00-720-801-02		FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH INBOARD SLAT TELESCOPIC DUCT (R501HJ)						Service ATA:30
PN:5036-700	MOS	08-Aug-14						
SN:382	HRS	12881.35	1240 (+3%)		14121.35	14158.55	225.1 (+37.2)	
WC#: 30.060	AFL	6629	1000 (+3%)		7629	7659	316 (+30)	
PROC. REF: AMM 30-11-00-720-801PROC. REF: AMM 30-11-00-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-00-720-801-03 FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD SLAT TELESCOPIC DUCT (L502HJ)								Service ATA:30
PN:5035-600	MOS	08-Aug-14						
SN:740	HRS	12881.35	1240 (+3%)		14121.35	14158.55	225.1 (+37.2)	
WC#: 30.050	AFL	6629	1000 (+3%)		7629	7659	316 (+30)	
PROC. REF: AMM 30-11-00-720-801PROC. REF: AMM 30-11-00-720-801								
30-11-00-720-801-04 FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD SLAT TELESCOPIC DUCT (R502HJ)								Service ATA:30
PN:5035-700	MOS	08-Aug-14						
SN:636R	HRS	12881.35	1240 (+3%)		14121.35	14158.55	225.1 (+37.2)	
WC#: 30.050	AFL	6629	1000 (+3%)		7629	7659	316 (+30)	
PROC. REF: AMM 30-11-00-720-801PROC. REF: AMM 30-11-00-720-801								
30-11-00-900-801-01 REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH INBOARD TELESCOPIC DUCT (L501HJ)								Component ATA:30
PN:5035-600	MOS/MSC	12-Jun-09	O/C					
SN:252	HRS	10850.2						
WC#: 30.060	AFL	5878						
PROC. REF: AMM 30-11-00-900-801PROC. REF: AMM 30-11-00-900-801								
30-11-00-900-801-02 REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH INBOARD TELESCOPIC DUCT (R501HJ)								Component ATA:30
PN:5036-700	MOS/MSC	28-Nov-08	O/C	TSO 0				
SN:382	HRS	10765.7		TSO 0				
WC#: 30.060	AFL	5815		TSO 0				
PROC. REF: AMM 30-11-00-900-801PROC. REF: AMM 30-11-00-900-801								
30-11-00-900-801-03 REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD TELESCOPIC DUCT (L502HJ)								Component ATA:30
PN:5035-600	MOS/MSC	12-Jun-09	O/C	TSO 0				
SN:740	HRS	10850.2		TSO 0				
WC#: 30.050	AFL	5878		TSO 0				
PROC. REF: AMM 30-11-00-900-801PROC. REF: AMM 30-11-00-900-801								
30-11-00-900-801-04 REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD TELESCOPIC DUCT (R502HJ)								Component ATA:30
PN:5035-700	MOS/MSC	12-Jun-09	O/C	TSO 0				
SN:636R	HRS	10850.2		TSO 0				
WC#: 30.050	AFL	5878		TSO 0				
PROC. REF: AMM 30-11-00-900-801PROC. REF: AMM 30-11-00-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-01-200-801-01	INSPECTION OF THE INBOARD SLAT TELESCOPIC DUCTS - LH INBOARD TELESCOPIC TUBE (L501HJ)							Service ATA:30
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
WC#: 30.060	AFL	5878						
PROC. REF: AMM 30-11-01-200-801PROC. REF: AMM 30-11-01-200-801								
30-11-01-200-801-02	INSPECTION OF THE INBOARD SLAT TELESCOPIC DUCTS - RH INBOARD TELESCOPIC TUBE (R501HJ)							Service ATA:30
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 30.060	AFL	0						
PROC. REF: AMM 30-11-01-200-801PROC. REF: AMM 30-11-01-200-801								
30-11-17-200-801-01 ^S	INSPECTION OF THE WING ANTI-ICING SYSTEM COUPLINGS LOCATED IN THE REAR COMPARTMENT							Service ATA:30
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 30.020	AFL	7304						
PROC. REF: AMM 30-11-17-200-801PKG:16								
30-11-17-200-803-01 ^S	INSPECTION OF THE WING ANTI-ICING SYSTEM GENERAL CONNECTOR COUPLINGS							Service ATA:30
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 30.150	AFL	7052	3750					
PROC. REF: AMM 30-11-17-200-803PKG:31								
30-12-01-900-801-01	REMOVAL / INSTALLATION OF THE WING ANTI-ICING VALVE - WING ANTI-ICING VALVE (3HJ)							Component ATA:30
PN:BYLB51035-1	MOS/MSC	09-Oct-97	O/C					
SN:320	HRS							
WC#: 30.070	AFL							
PROC. REF: AMM 30-12-01-900-801								
30-20-00-710-801-01 ^S	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 1							Service ATA:30
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PKG:21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-20-00-710-801PROC. REF: AMM 30-20-00-710-801								
30-20-00-710-801-02	^S	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 2						Service ATA:30
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 30.100	AFL	6741						
								PKG:21
PROC. REF: AMM 30-20-00-710-801PROC. REF: AMM 30-20-00-710-801								
30-20-00-710-801-03	^S	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 3						Service ATA:30
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
								PKG:21
PROC. REF: AMM 30-20-00-710-801PROC. REF: AMM 30-20-00-710-801								
30-20-01-700-801-01		FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L3HA)						Service ATA:30
PN:6911B030100	MOS	17-Dec-21						
SN:328	HRS	13275.5	5000 (+3%)		18275.5	18425.5	4379.2 (+150)	
WC#: 30.110	AFL	6741						
PROC. REF: AMM 30-20-01-700-801PROC. REF: AMM 30-20-01-700-801								
30-20-01-700-801-02		FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M3HA)						Service ATA:30
PN:6911B030100	MOS	30-Jan-07						
SN:571	HRS	9294.2	5000 (+3%)		14294.2	14444.2	397.9 (+150)	
WC#: 30.120	AFL	4969						
PROC. REF: AMM 30-20-01-700-801PROC. REF: AMM 30-20-01-700-801								
30-20-01-700-801-03		FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R3HA)						Service ATA:30
PN:6911B030100	MOS	30-Jan-07						
SN:333	HRS	9294.33	5000 (+3%)		14294.33	14444.33	398 (+150)	
WC#: 30.130	AFL	4969						
PROC. REF: AMM 30-20-01-700-801PROC. REF: AMM 30-20-01-700-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-30-00-710-801-01	^S	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM						Service ATA:30
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 30-30-00-710-801PROC. REF: AMM 30-30-00-710-801								PKG:21
30-41-00-200-801-01	^S	INSPECTION OF THE WINDSHIELD HEATING SYSTEM CONNECTORS						Service ATA:30
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 30-41-00-200-801PROC. REF: AMM 30-41-00-200-801								PKG:16
30-41-00-710-801-01	^S	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM						Service ATA:30
	MOS	22-Nov-07						
	HRS	10138.1	4800 (+40)					
WC#: 30.230	AFL	5422						
PROC. REF: AMM 30-41-00-710-801PROC. REF: AMM 30-41-00-710-801								PKG:23
30-43-05-900-801-01		REMOVAL / INSTALLATION OF THE WINDSHIELD WIPER MOTOR-ACTUATED ANGLE DRIVES - LH WINDSHIELD WIPER ARTICULATED ARM (L500MK)						Component ATA:30
PN:4218246	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.270	AFL	0						
PROC. REF: AMM 30-43-05-900-801PROC. REF: AMM 30-43-05-900-801								
30-43-05-900-801-02		REMOVAL / INSTALLATION OF THE WINDSHIELD WIPER MOTOR-ACTUATED ANGLE DRIVES - RH WINDSHIELD WIPER ARTICULATED ARM (R500MK)						Component ATA:30
PN:PN	MOS/MSC	23-Sep-09	O/C					
SN:UNKNOWN	HRS	10853.9						
WC#: 30.270	AFL	5880						
PROC. REF: AMM 30-43-05-900-801PROC. REF: AMM 30-43-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-43-09-220-801-01	CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - LH WINDSHIELD WIPER MOTOR (L5MK)							Service ATA:30
PN:4267568	MOS	07-Feb-91						
SN:12856	HRS	0	15000 (+3%)		15000	15450	1103.7 (+450)	
WC#: 30.260	AFL	0						
PROC. REF: AMM 30-43-09-220-801PROC. REF: AMM 30-43-09-220-801								
30-43-09-220-801-02	CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - RH WINDSHIELD WIPER MOTOR (R5MK)							Service ATA:30
PN:4267575	MOS	07-Feb-91						
SN:11206	HRS	0	15000 (+3%)		15000	15450	1103.7 (+450)	
WC#: 30.260	AFL	0						
PROC. REF: AMM 30-43-09-220-801PROC. REF: AMM 30-43-09-220-801								
30-90-00-710-801-01 ^S	OPERATIONAL TEST OF THE BRAKE HEATING SYSTEM							Service ATA:30
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 30.045	AFL	6741						
								PKG:21
PROC. REF: AMM 30-90-00-710-801PROC. REF: AMM 30-90-00-710-801								
301351	LH WING ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-2	MOS/MSC	03-Sep-97	O/C					
SN:1149	HRS	2923						
WC#: 30.080	AFL							
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
301381	RH WING ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-2	MOS/MSC	07-Sep-97	O/C					
SN:1150	HRS	2926						
WC#: 30.080	AFL							
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
301401	BLEED AIR HIGH PRESSURE MONITOR-							Component ATA:30
PN:EL126-00	MOS/MSC	26-Sep-97	O/C	TSN 0				
SN:237	HRS	2971		TSN 0				
WC#: 30.080	AFL			TSN 0				
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
302101	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE							Component ATA:30
PN:6911B030100	MOS/MSC	17-Dec-21	O/C					
SN:328	HRS	13275.5						
WC#: 30.110	AFL	6741						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302121	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE							Component ATA:30
PN:6911B030100	MOS/MSC	07-Feb-91	O/C					
SN:571	HRS	0		TSN 0				
WC#: 30.120	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302141	NO. 3 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE							Component ATA:30
PN:6911B030100	MOS/MSC	30-Jan-07	O/C					
SN:333	HRS	9294.33						
WC#: 30.130	AFL	4969						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302261	NO. 2 ENGINE DUCT ANTI-ICING VALVE							Component ATA:30
PN:BYLB51908	MOS/MSC	27-Sep-24	O/C					
SN:392	HRS	13765.3						
WC#: 30.160	AFL	7169						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302301	NO. 1 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-2	MOS/MSC	07-Feb-91	O/C					
SN:927	HRS	0		TSN 0				
WC#: 30.170	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302321	NO. 1 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1340-1	MOS/MSC	07-Feb-91	O/C					
SN:348	HRS	0		TSN 0				
WC#: 30.170	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
302341	NO. 2 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-2	MOS/MSC	07-Feb-91	O/C					
SN:1040	HRS	0		TSN 0				
WC#: 30.180	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302361	NO. 2 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-2	MOS/MSC	07-Feb-91	O/C					
SN:388	HRS	0		TSN 0				
WC#: 30.180	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302381	NO. 2 ENGINE DUCT ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-2	MOS/MSC	07-Feb-91	O/C					
SN:1037	HRS	0		TSN 0				
WC#: 30.190	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302401	NO. 3 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-2	MOS/MSC	07-Feb-91	O/C					
SN:924	HRS	0		TSN 0				
WC#: 30.200	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
302421	NO. 3 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1340-1	MOS/MSC	07-Feb-91	O/C					
SN:379	HRS	0		TSN 0				
WC#: 30.200	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
303101	LH PITOT/STATIC HEAT MONITORING BOX							Component ATA:30
PN:24-255	MOS/MSC	07-Feb-91	O/C					
SN:203	HRS	0		TSN 0				
WC#: 30.220	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
303131	RH PITOT/STATIC HEAT MONITORING BOX							Component ATA:30
PN:24-255	MOS/MSC	07-Feb-91	O/C					
SN:202	HRS	0		TSN 0				
WC#: 30.220	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
303161	STANDBY PITOT HEAT MONITORING BOX							Component ATA:30
PN:24-256	MOS/MSC	07-Feb-91	O/C					
SN:108	HRS	0		TSN 0				
WC#: 30.220	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
304101	PILOT WINDSHIELD HEATING REGULATOR							Component ATA:30
PN:AV30559060030-1	MOS/MSC	04-Aug-04	O/C					
SN:1215	HRS	6512.4		TSN 0				
WC#: 30.240	AFL	3456						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
304121	COPILOT WINDSHIELD HEATING REGULATOR							Component ATA:30
PN:HYZ50426-1	MOS/MSC	07-Feb-91	O/C					
SN:783D	HRS	0		TSN 0				
WC#: 30.240	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
304141	LH SIDE WINDOW HEATING REGULATOR							Component ATA:30
PN:HYZ50422	MOS/MSC	07-Feb-91	O/C					
SN:963D	HRS	0		TSN 0				
WC#: 30.250	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
304161	RH SIDE WINDOW HEATING REGULATOR							Component ATA:30
PN:HYZ50422	MOS/MSC	07-Feb-91	O/C					
SN:976D	HRS	0		TSN 0				
WC#: 30.250	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304301	PILOT WINDSHIELD WIPER MOTOR							Component ATA:30
PN:4267568	MOS/MSC	07-Feb-91	O/C					
SN:12856	HRS	0		TSN 0				
WC#: 30.260	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
304331	COPILOT WINDSHIELD WIPER MOTOR							Component ATA:30
PN:4267575	MOS/MSC	07-Feb-91	O/C					
SN:11206	HRS	0		TSN 0				
WC#: 30.260	AFL	0						
PROC. REF: AMM GENERIC 1PROC. REF: AMM GENERIC 1								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-21-05-960-801-01	REPLACEMENT OF THE PILOT CLOCK BATTERIES - LH PILOT CLOCK (L1DT) BATTERY							Service ATA:31
PN:811B	MOS	16-Apr-24	25		16-May-26		22 d	LIFE LIMIT
SN:25545	HRS	13715.9						
WC#: 31.080	AFL	7118						
PROC. REF: AMM 31-21-05-960-801PROC. REF: AMM 31-21-05-960-801								
31-21-05-960-801-02	REPLACEMENT OF THE PILOT CLOCK BATTERIES - RH PILOT CLOCK (R1DT) BATTERY							Service ATA:31
PN:811B	MOS	16-Apr-24	25		16-May-26		22 d	SCRAP
SN:26142	HRS	13715.9						
WC#: 31.080	AFL	7118						
PROC. REF: AMM 31-21-05-960-801PROC. REF: AMM 31-21-05-960-801								
31-31-00-710-802-01 ^S	OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) SYSTEM							Service ATA:31
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
WC#: 31.100	AFL	7052						
PROC. REF: AMM 31-31-00-710-802PROC. REF: AMM 31-31-00-710-802								
31-31-00-720-802-01	FUNCTIONAL TEST FLIGHT DATA (FDR) RECORDER 57-PARAMETERS							Service ATA:31
PN:17M800-261	MOS/MSC	09-Jun-25	O/C					
SN:03710	HRS	13844.3						
WC#: 31.100	AFL	7258						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
31-31-00-720-803-01 FUNCTIONAL TEST OF THE 32-PARAMETER FDR - FDR (14FZ)								Service ATA:31
	MOS/MSC	26-Jun-09	O/C					
	HRS	10850.33						
WC#: 31.100	AFL	5878						
PROC. REF: AMM 31-31-00-720-803PROC. REF: AMM 31-31-00-720-803								
31-31-00-970-801-01 DOWNLOAD OF THE FLIGHT DATA RECORDER (FDR) - FDR (14FZ)								Service ATA:31
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 31.100	AFL	0						
	APH	0						
PROC. REF: AMM 31-31-00-970-801PROC. REF: AMM 31-31-00-970-801								
31-31-09-710-801-01 OPERATIONAL TEST OF THE FDR/CVR ACCELERATION CONTACTS - CVR ACCELERATION CONTACT (5RK)								Service ATA:31
PN:400-10B	MOS	15-Dec-09	240 (+3%)		15-Dec-29	21-Jul-30	1331 d (+218)	
SN:6407	HRS	10860.17						
	AFL	5883						
PROC. REF: AMM 31-31-09-710-801PROC. REF: AMM 31-31-09-710-801								
31-31-09-710-801-02 OPERATIONAL TEST OF THE FDR/CVR ACCELERATION CONTACTS - FDR ACCELERATION CONTACT (15FZ) OR (23FZ)								Service ATA:31
PN:400-10B	MOS/MSC	15-Dec-09	N/A					
SN:6407	HRS	10860.17						
	AFL	5883						
PROC. REF: AMM 31-31-09-710-801PROC. REF: AMM 31-31-09-710-801								
31-31-09-900-801-01 REMOVAL / INSTALLATION OF THE FDR / CVR ACCELERATION CONTACTS - CVR ACCELERATION CONTACT (5RK)								Component ATA:31
PN:400-10B	MOS/MSC	15-Dec-09	O/C					
SN:6407	HRS	10860.17						
WC#: 31.110	AFL	5883						
PROC. REF: AMM 31-31-09-900-801PROC. REF: AMM 31-31-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-09-900-801-02 REMOVAL / INSTALLATION OF THE FDR / CVR ACCELERATION CONTACTS - FDR ACCELERATION CONTACT (15FZ) OR (23FZ)								Component ATA:31
PN:400-10B	MOS/MSC	15-Dec-09	O/C					
SN:6407	HRS	10860.17						
WC#: 31.110	AFL	5883						
PROC. REF: AMM 31-31-09-900-801PROC. REF: AMM 31-31-09-900-801								
31-31-31-900-801-01 REMOVAL / INSTALLATION OF THE FLIGHT DATA RECORDER (FDR) - FDR (14FZ)								Component ATA:31
PN:17M800-261	MOS/MSC	26-Jun-09	O/C					
SN:03710	HRS	10850.33						
WC#: 31.100	AFL	5878						
PROC. REF: AMM 31-31-31-900-801PROC. REF: AMM 31-31-31-900-801								
31-31-50-710-801-01 ^S OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) SYSTEM								Service ATA:31
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
WC#: 31.070	AFL	7052						
PROC. REF: AMM 31-31-50-710-801PKG:17 PROC. REF: AMM 31-31-50-710-801								
31-31-50-970-801-01 DOWNLOAD OF THE COCKPIT VOICE RECORDER (CVR) - CVR (2RK)								Service ATA:31
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 31-31-50-970-801PROC. REF: AMM 31-31-50-970-801								
31-31-51-900-801-01 REMOVAL / INSTALLATION OF THE COCKPIT VOICE RECORDER (CVR) - CVR (2RK)								Component ATA:31
PN:1603-02-12	MOS/MSC	30-Jan-07	O/C					
SN:228	HRS	9294.33						
WC#: 31.070	AFL	4969						
PROC. REF: AMM 31-31-51-900-801PROC. REF: AMM 31-31-51-900-801								
31-32-00-970-801-01 DOWNLOAD OF THE QUICK ACCESS RECORDER (QAR) - QAR (42FZ)								Service ATA:31
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:NOT INSTALLED	HRS	0						
WC#: 31.140	AFL	0						
PROC. REF: AMM 31-32-00-970-801, AMM 31-32-00-970-801PROC. REF: AMM 31-32-00-970-801, AMM 31-32-00-970-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER							Component ATA:31
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
WC#: 31.140	AFL	0		TSN 0				
PROC. REF: AMM 31-32-01-900-801, AMM 31-32-01-900-801PROC. REF: AMM 31-32-01-900-801, AMM 31-32-01-900-801								
31-32-05-350-801-01	RESTORATION OF THE QUICK ACCESS RECORDER (QAR BATTERY REPLACEMENT) - QAR (42FZ)							Service ATA:31
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 31-32-05-350-801PROC. REF: AMM 31-32-05-350-801								
31-32-05-960-801-01	REPLACEMENT OF THE QUICK ACCESS RECORDER (QAR) BATTERY - QAR (42FZ) BATTERY							Service ATA:31
PN:PN	MOS/MSC	07-Feb-91	N/A					
SN:NOT INSTALLED	HRS	0						
WC#: 31.140	AFL	0						
PROC. REF: AMM 31-32-05-960-801, AMM 31-32-05-960-801PROC. REF: AMM 31-32-05-960-801, AMM 31-32-05-960-801								
31-52-00-710-801-01 ^S	OPERATIONAL TEST OF THE WARNING PANEL DUAL POWER SUPPLY							Service ATA:31
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
WC#: 31.010	AFL	7052						
PROC. REF: AMM 31-52-00-710-801PROC. REF: AMM 31-52-00-710-801								PKG:7
31-54-00-720-803-01	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES - ALARM TEST							Service ATA:31
	MOS	13-Jan-23						
	HRS	13482.5	600 (+40)	Adj -1.15	14081.35	14121.35	185.1 (+40)	
WC#: 31.030	AFL	6909						
PROC. REF: AMM 31-54-00-720-803PROC. REF: AMM 31-54-00-720-803								
31-54-00-720-803-02 ^S	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES - TEST OF INDICATION LOGIC							Service ATA:31
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 31.030	AFL	6741						
PROC. REF: AMM 31-54-00-720-803PROC. REF: AMM 31-54-00-720-803								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-55-00-720-801-01 ^S FUNCTIONAL TEST OF THE LANDING SAFETIES Service ATA:31								
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 31.040	AFL	6741						
PKG:21								
PROC. REF: AMM 31-55-00-720-801PROC. REF: AMM 31-55-00-720-801								
310101 WARNING PANEL Component ATA:31								
PN:90300-4	MOS/MSC	07-Feb-91	O/C					
SN:210	HRS	0		TSN 0				
WC#: 31.010	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
312001 LH PILOT CLOCK (L1DT) Component ATA:31								
PN:811B	MOS/MSC	12-Jun-09	O/C					
SN:25545	HRS	10850.2						
WC#: 31.080	AFL	5878						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
312006 RH PILOT CLOCK (R1DT) Component ATA:31								
PN:811B	MOS/MSC	12-Jun-09	O/C					
SN:26142	HRS	10850.2						
WC#: 31.080	AFL	5878						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
313199 ^U FDAU - FLIGHT DATA ACQUISITION UNIT Component ATA:31								
PN:66502-000-4	MOS/MSC	06-May-13	O/C					
SN:198	HRS	12205.82						
	AFL	6354						
315101 AUDIO WARNING UNIT Component ATA:31								
PN:240ZS01Y05	MOS/MSC	02-May-03	O/C					
SN:180	HRS	5828.9						
WC#: 31.050	AFL	2857						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 31 - INDICATING/RECORDING SYSTEMS

PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2

315256	VOICE DATA RECORDER CONTROL							Component ATA:31
PN:1634-01	MOS/MSC	21-Sep-01	O/C	TSR 0				
SN:161	HRS	4967.8		TSR 0				
	AFL	2283		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

315261	VOICE DATA RECORDER REMOTE MICROPHONE							Component ATA:31
PN:PN	MOS/MSC	14-Mar-01	O/C					
SN:UNKNOWN	HRS	4661						
	AFL	2106						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

ATA 32 - LANDING GEAR

32-00-00-700-801-01	CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13GA)							Service ATA:32
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 32.130	AFL	6673						
PROC. REF: AMM 32-00-00-700-801PROC. REF: AMM 32-00-00-700-801								

32-00-00-700-801-02	CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA)							Service ATA:32
	MOS	07-Apr-25	18 (+1m)	Adj -12d	25-Sep-26	25-Oct-26	154 d (+30)	
	HRS	13828.9						
WC#: 32.050	AFL	7241						
PROC. REF: AMM 32-00-00-700-801PROC. REF: AMM 32-00-00-700-801								

32-00-00-700-801-03	CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA)							Service ATA:32
	MOS	07-Apr-25	18 (+1m)	Adj -12d	25-Sep-26	25-Oct-26	154 d (+30)	
	HRS	13828.9						
WC#: 32.050	AFL	7241						
PROC. REF: AMM 32-00-00-700-801PROC. REF: AMM 32-00-00-700-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-00-00-780-802-01	S	CHECK OF THE CHARGING PRESSURE OF THE MLG AND NLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-00-00-780-802PROC. REF: AMM 32-00-00-780-802								PKG:21
32-00-00-780-802-02	S	CHECK OF THE CHARGING PRESSURE OF THE MLG AND NLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-00-00-780-802PROC. REF: AMM 32-00-00-780-802								PKG:21
32-00-00-780-802-03	S	CHECK OF THE CHARGING PRESSURE OF THE MLG AND NLG SHOCK ABSORBERS - NLG SHOCK ABSORBER (3GF5)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-00-00-780-802PROC. REF: AMM 32-00-00-780-802								PKG:21
32-10-00-640-801-01		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND DOORS						Service ATA:32
	MOS	27-Mar-26	8 (+1m)	Adj -2d	25-Nov-26	25-Dec-26	215 d (+30)	
	HRS	13896.3						
WC#: 32.010	AFL	7313	400		7713		400	
PROC. REF: AMM 32-10-00-640-801PROC. REF: AMM 32-10-00-640-801								
32-10-00-640-801-02		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND DOORS						Service ATA:32
	MOS	27-Mar-26	8 (+1m)	Adj -2d	25-Nov-26	25-Dec-26	215 d (+30)	
	HRS	13896.3						
WC#: 32.010	AFL	7313	400		7713		400	
PROC. REF: AMM 32-10-00-640-801PROC. REF: AMM 32-10-00-640-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-350-801-01	RESTORATION OF THE MLG LEGS (OVERHAUL) - LH MLG LEG (L2GF)							Service ATA:32
PN:D22801100-11	MOS/MSC	03-Apr-03	O/C					
SN:U99	HRS	5826.4						
	AFL	2849						
PROC. REF: AMM 32-11-00-350-801PROC. REF: AMM 32-11-00-350-801								
32-11-00-350-801-02	RESTORATION OF THE MLG LEGS (OVERHAUL) - RH MLG LEG (R2GF)							Service ATA:32
PN:D22802100-11	MOS/MSC	03-Apr-03	O/C					
SN:U99	HRS	5826.4						
	AFL	2849						
PROC. REF: AMM 32-11-00-350-801PROC. REF: AMM 32-11-00-350-801								
32-11-00-900-801-01	REMOVAL / INSTALLATION OF THE MLG LEGS - LH MLG LEG (L2GF)							Component ATA:32
PN:D22801100-11	MOS/MSC	12-Jun-09	H/T	TSR 0				
SN:U99	HRS	10850.2		TSN 10850.2, TSR 0				
WC#: 32.020	AFL	5878		TSN 5878, TSR 0				
PROC. REF: AMM 32-11-00-900-801PROC. REF: AMM 32-11-00-900-801								
32-11-00-900-801-02	REMOVAL / INSTALLATION OF THE MLG LEGS - RH MLG LEG (R2GF)							Component ATA:32
PN:D22802100-11	MOS/MSC	12-Jun-09	H/T	TSR 6				
SN:U99	HRS	10850.2		TSN 10850.2, TSR 353.2				
WC#: 32.030	AFL	5878		TSN 5878, TSR 128				
PROC. REF: AMM 32-11-00-900-801PROC. REF: AMM 32-11-00-900-801								
32-11-00-960-801-01	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - LH MLG LEG (L2GF)							Service ATA:32
PN:D22801100-11	MOS	12-Jun-09						LIFE LIMIT
SN:U99	HRS	10850.2		TAC 10850.2				
WC#: 32.020	AFL	5878	20000	TAC 5878	20000		12687	
PROC. REF: AMM 32-11-00-960-801PROC. REF: AMM 32-11-00-960-801								
32-11-00-960-801-01A	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)							Service ATA:32
PN:D22801100-11	MOS	12-Jun-09						LIFE LIMIT
SN:U99	HRS	10850.2		TAC 10850.2				
	AFL	5878	20000	TAC 5878	20000		12687	
PROC. REF: AMM 32-11-00-960-801PROC. REF: AMM 32-11-00-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-960-801-02	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - RH MLG LEG (R2GF)							Service ATA:32
PN:D22802100-11	MOS	12-Jun-09						LIFE LIMIT
SN:U99	HRS	10850.2		TAC 10850.2				
WC#: 32.030	AFL	5878	20000	TAC 5878	20000		12687	
PROC. REF: AMM 32-11-00-960-801PROC. REF: AMM 32-11-00-960-801								
32-11-00-960-801-02A	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)							Service ATA:32
PN:D22802100-11	MOS	12-Jun-09						LIFE LIMIT
SN:U99	HRS	10850.2		TAC 10850.2				
	AFL	5878	20000	TAC 5878	20000		12687	
PROC. REF: AMM 32-11-00-960-801PROC. REF: AMM 32-11-00-960-801								
32-11-05-900-801-01	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER							Component ATA:32
PN:D22805100-7	MOS/MSC	14-Nov-11	O/C	TSO 95, TSR 0				
SN:U51	HRS	11568.42		TSR 0				
WC#: 32.020	AFL	6104		TSN 5964, TSO 1033, TSR 0				
PROC. REF: AMM 32-11-05-900-801PROC. REF: AMM 32-11-05-900-801								
32-11-05-900-801-02	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER							Component ATA:32
PN:D22805100-6	MOS/MSC	03-Apr-03	O/C	TSN 20, TSR 6				
SN:U103	HRS	5826.4		TSN 1183.9, TSR 353.2				
WC#: 32.030	AFL	2849		TSN 498, TSR 128				
PROC. REF: AMM 32-11-05-900-801PROC. REF: AMM 32-11-05-900-801								
32-11-21-900-801-01	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - LH MLG BRACE STRUT ACTUATOR (L12GA)							Component ATA:32
PN:D22791002	MOS/MSC	28-Nov-08	O/C	TSR 0				
SN:U104	HRS	10765.7		TSR 0				
WC#: 32.040	AFL	5815		TSR 0				
PROC. REF: AMM 32-11-21-900-801PROC. REF: AMM 32-11-21-900-801								
32-11-21-900-801-02	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - RH MLG BRACE STRUT ACTUATOR (R12GA)							Component ATA:32
PN:D22792002	MOS/MSC	07-Feb-91	O/C					
SN:U102	HRS	0		TSN 0				
WC#: 32.040	AFL	0						
PROC. REF: AMM 32-11-21-900-801PROC. REF: AMM 32-11-21-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-25-220-801-01	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)							Service ATA:32
	MOS	17-Aug-22	72 (+8m)		17-Aug-28	17-Apr-29	846 d (+243)	
	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 32-11-25-220-801PROC. REF: AMM 32-11-25-220-801								
32-11-25-220-801-02	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)							Service ATA:32
	MOS	17-Aug-22	72 (+8m)		17-Aug-28	17-Apr-29	846 d (+243)	
	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 32-11-25-220-801PROC. REF: AMM 32-11-25-220-801								
32-11-25-220-801-03	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)							Service ATA:32
	MOS	17-Aug-22	72 (+8m)		17-Aug-28	17-Apr-29	846 d (+243)	
	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 32-11-25-220-801PROC. REF: AMM 32-11-25-220-801								
32-11-25-220-801-04	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)							Service ATA:32
	MOS	17-Aug-22	72 (+8m)		17-Aug-28	17-Apr-29	846 d (+243)	
	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 32-11-25-220-801PROC. REF: AMM 32-11-25-220-801								
32-12-17-900-801-01	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA)							Component ATA:32
PN:C24244007-1	MOS/MSC	20-Oct-97	O/C					
SN:U62	HRS	3009						
WC#: 32.050	AFL	1460						
PROC. REF: AMM 32-12-17-900-801PROC. REF: AMM 32-12-17-900-801								
32-12-17-900-801-02	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA)							Component ATA:32
PN:C24245007-1	MOS/MSC	07-Feb-91	O/C					
SN:U526	HRS	0		TSN 0				
WC#: 32.050	AFL	0						
PROC. REF: AMM 32-12-17-900-801PROC. REF: AMM 32-12-17-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-12-25-900-801-01		REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - LH MLG MAIN DOOR ACTUATOR (L6GA)						Component ATA:32
PN:VN1031-2	MOS/MSC	07-Feb-91	O/C					
SN:205	HRS	0		TSN 0				
WC#: 32.080	AFL	0						
PROC. REF: AMM 32-12-25-900-801PROC. REF: AMM 32-12-25-900-801								
32-12-25-900-801-02		REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - RH MLG MAIN DOOR ACTUATOR (R6GA)						Component ATA:32
PN:VN1031-1	MOS/MSC		O/C					
SN:221	HRS	826						
WC#: 32.080	AFL	508						
PROC. REF: AMM 32-12-25-900-801PROC. REF: AMM 32-12-25-900-801								
32-12-29-900-801-01		REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - LH MLG MAIN DOOR UPLOCK BOX (L14GA)						Component ATA:32
PN:C24257002	MOS/MSC		O/C					
SN:U739	HRS	584						
WC#: 32.090	AFL	407						
PROC. REF: AMM 32-12-29-900-801PROC. REF: AMM 32-12-29-900-801								
32-12-29-900-801-02		REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - RH MLG MAIN DOOR UPLOCK BOX (R14GA)						Component ATA:32
PN:C2457002-2	MOS/MSC	19-Dec-21	O/C					
SN:H1889	HRS	13275.5						
WC#: 32.090	AFL	6741						
PROC. REF: AMM 32-12-29-900-801PROC. REF: AMM 32-12-29-900-801								
32-20-00-640-801-01		LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG LEG (3GF)						Service ATA:32
	MOS	27-Mar-26	8 (+1m)	Adj -2d	25-Nov-26	25-Dec-26	215 d (+30)	
	HRS	13896.3						
WC#: 32.100	AFL	7313	400		7713		400	
PROC. REF: AMM 32-20-00-640-801PROC. REF: AMM 32-20-00-640-801								
32-21-00-350-801-01		RESTORATION OF THE NLG LEG (OVERHAUL) - NLG LEG (3GF)						Service ATA:32
PN:D22811200-13	MOS/MSC	03-Apr-03	O/C	TAC 0				
SN:U99	HRS	5826.4		TAC 0				
	AFL	2849		TAC 0				
PROC. REF: AMM 32-21-00-350-801PROC. REF: AMM 32-21-00-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-00-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG - NLG LEG (3GF)							Component ATA:32
PN:D22811200-13	MOS/MSC	12-Jun-09	H/T	TSR 0				
SN:U99	HRS	10850.2		TSN 10850.2, TSR 0				
WC#: 32.110	AFL	5878		TSN 5878, TSR 0				
PROC. REF: AMM 32-21-00-900-801PROC. REF: AMM 32-21-00-900-801								
32-21-00-960-801-01	REPLACEMENT OF THE NLG LEG (DISCARD OF LIFE LIMITED PARTS) - NLG LEG (3GF)							Service ATA:32
PN:D22811200-13	MOS	12-Jun-09						LIFE LIMIT
SN:U99	HRS	10850.2		TAC 10850.2				
WC#: 32.110	AFL	5878	20000	TAC 5878	20000		12687	
PROC. REF: AMM 32-21-00-960-801PROC. REF: AMM 32-21-00-960-801								
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)							Service ATA:32
PN:D22811200-13	MOS	12-Jun-09						LIFE LIMIT
SN:U99	HRS	10850.2		TAC 10850.2				
	AFL	5878	20000	TAC 5878	20000		12687	
PROC. REF: AMM 32-21-00-960-801PROC. REF: AMM 32-21-00-960-801								
32-21-01-780-802-01	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER BY APPLYING A ROTATIONAL TORQUE - NLG SHOCK ABSORBER							Service ATA:32
	MOS/MSC	05-Jun-13	O/C					
	HRS	12205.82						
	AFL	6354						
PROC. REF: AMM 32-21-01-780-802PROC. REF: AMM 32-21-01-780-802								
32-21-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)							Component ATA:32
PN:D22813200-8	MOS/MSC	03-Apr-03	O/C	TSN 20, TSR 6				
SN:U102	HRS	5826.4		TSN 1183.9, TSR 353.2				
WC#: 32.110	AFL	2849		TSN 498, TSR 128				
PROC. REF: AMM 32-21-01-900-801PROC. REF: AMM 32-21-01-900-801								
32-21-09-220-801-01	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING							Service ATA:32
	MOS	17-Aug-22	72 (+8m)	17-Aug-28	17-Apr-29	846 d (+243)		
	HRS	13433.7						
WC#: 32.135	AFL	6872						
PROC. REF: AMM 32-21-09-220-801PROC. REF: AMM 32-21-09-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-09-220-801-02	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING							Service ATA:32
	MOS	17-Aug-22	72 (+8m)		17-Aug-28	17-Apr-29	846 d (+243)	
	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 32-21-09-220-801PROC. REF: AMM 32-21-09-220-801								
32-21-09-220-801-03	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING							Service ATA:32
	MOS	17-Aug-22	72 (+8m)		17-Aug-28	17-Apr-29	846 d (+243)	
	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 32-21-09-220-801PROC. REF: AMM 32-21-09-220-801								
32-21-09-220-801-04	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING							Service ATA:32
	MOS	17-Aug-22	72 (+8m)		17-Aug-28	17-Apr-29	846 d (+243)	
	HRS	13433.7						
	AFL	6872						
PROC. REF: AMM 32-21-09-220-801PROC. REF: AMM 32-21-09-220-801								
32-22-01-350-801-01	RESTORATION OF THE NLG DRAG BRACE YOKE ASSY (OVERHAUL) - NLG DRAG BRACE (11GA)							Service ATA:32
PN:D57635	MOS/MSC	03-Apr-03	O/C					
SN:436	HRS	5826.4						
WC#: 32.120	AFL	2849						
PROC. REF: AMM 32-22-01-350-801PROC. REF: AMM 32-22-01-350-801								
32-22-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG DRAG BRACE - NLG DRAG BRACE (11GA)							Component ATA:32
PN:D22796001-1	MOS/MSC	07-Feb-91	O/C					
SN:U102	HRS	0		TSN 0				
WC#: 32.120	AFL	0						
PROC. REF: AMM 32-22-01-900-801PROC. REF: AMM 32-22-01-900-801								
32-22-13-900-801-01	REMOVAL / INSTALLATION OF THE NLG ACTUATOR - NLG LEG ACTUATOR (500GA)							Component ATA:32
PN:D22795001	MOS/MSC	07-Feb-91	O/C					
SN:B6	HRS	0		TSN 0				
WC#: 32.130	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-22-13-900-801PROC. REF: AMM 32-22-13-900-801								
32-22-17-900-801-01	REMOVAL / INSTALLATION OF THE NLG UPLOCK BOX - NLG UPLOCK BOX (13GA)						Component	ATA:32
PN:C24245006-3	MOS/MSC	05-Jun-13	O/C	TSR 6				
SN:Y00003	HRS	12205.82		TSN 431				
WC#: 32.130	AFL	6354		TSN 197				
PROC. REF: AMM 32-22-17-900-801PROC. REF: AMM 32-22-17-900-801								
32-30-00-720-801-01	^S	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - NORMAL OPERATION						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 32.160	AFL	6741						
PKG:21								
PROC. REF: AMM 32-30-00-720-801PROC. REF: AMM 32-30-00-720-801								
32-30-00-720-801-02	^S	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - HYDRAULIC EMERGENCY OPERATION						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PKG:21								
PROC. REF: AMM 32-30-00-720-801PROC. REF: AMM 32-30-00-720-801								
32-30-00-720-801-03	^S	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - MECHANICAL EMERGENCY OPERATION						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PKG:21								
PROC. REF: AMM 32-30-00-720-801PROC. REF: AMM 32-30-00-720-801								
32-30-13-900-801-01	REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY SELECTOR VALVE - L/G NORMAL/EMERGENCY SELECTOR VALVE (3GA)						Component	ATA:32
PN:B94B09-202-1	MOS/MSC	07-Feb-91	O/C					
SN:20068	HRS	0		TSN 0				
WC#: 32.240	AFL	0						
PROC. REF: AMM 32-30-13-900-801PROC. REF: AMM 32-30-13-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-31-00-700-801-01	^S	CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 32.190	AFL	6741						
PROC. REF: AMM 32-31-00-700-801PROC. REF: AMM 32-31-00-700-801								PKG:21
32-32-00-640-801-01	^S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE NLG CONTROL						Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 32.180	AFL	7304						
PROC. REF: AMM 32-32-00-640-801PROC. REF: AMM 32-32-00-640-801								PKG:16
32-32-00-640-801-02	^S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE NLG CONTROL ACTUATION FORCE						Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 32-32-00-640-801PROC. REF: AMM 32-32-00-640-801								PKG:16
32-32-00-640-801-03	^S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE MLG CONTROLS						Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 32-32-00-640-801PROC. REF: AMM 32-32-00-640-801								PKG:16
32-32-00-640-801-04	^S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE MLG CONTROL ACTUATION FORCE						Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 32-32-00-640-801PROC. REF: AMM 32-32-00-640-801								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-00-700-801-01	CHECK AFTER LANDING GEAR EMERGENCY EXTENSION							Service ATA:32
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 32.830	AFL	0						
PROC. REF: AMM 32-32-00-700-801PROC. REF: AMM 32-32-00-700-801								
32-32-17-640-801-01	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - LUBRICATION OF THE L/G HYDRAULIC EMERGENCY EXTENSION CONTROL							Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 32.170	AFL	7304						
PROC. REF: AMM 32-32-17-640-801PROC. REF: AMM 32-32-17-640-801								
32-32-17-640-801-02	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - CHECK OF CONTROL ACTUATION LOADS							Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 32-32-17-640-801PROC. REF: AMM 32-32-17-640-801								
32-32-17-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE - L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE (504GA)							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-32-17-900-801PROC. REF: AMM 32-32-17-900-801								
32-40-00-780-801-01	CHECK OF BRAKING PRESSURES - NORMAL BRAKING SYSTEM							Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PROC. REF: AMM 32-40-00-780-801PROC. REF: AMM 32-40-00-780-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-00-780-801-02	^S	CHECK OF BRAKING PRESSURES - EMERGENCY BRAKING SYSTEM						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PROC. REF: AMM 32-40-00-780-801PROC. REF: AMM 32-40-00-780-801								PKG:22
32-41-00-710-802-01	^S	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - LH MLG OUTBOARD WHEEL						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-41-00-710-802PROC. REF: AMM 32-41-00-710-802								PKG:21
32-41-00-710-802-02	^S	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - LH MLG INBOARD WHEEL						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-41-00-710-802PROC. REF: AMM 32-41-00-710-802								PKG:21
32-41-00-710-802-03	^S	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - RH MLG OUTBOARD WHEEL						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-41-00-710-802PROC. REF: AMM 32-41-00-710-802								PKG:21
32-41-00-710-802-04	^S	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - RH MLG INBOARD WHEEL						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-41-00-710-802PROC. REF: AMM 32-41-00-710-802								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-07-610-801-01	S	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS - SERVICING						Service ATA:32
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 32.415	AFL	7052	3750					
PROC. REF: AMM 32-41-07-610-801PROC. REF: AMM 32-41-07-610-801								PKG:31
32-41-07-610-801-02	S	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS - MEASUREMENT OF SLIDING FORCES						Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 32.415	AFL	7304						
PROC. REF: AMM 32-41-07-610-801PROC. REF: AMM 32-41-07-610-801								PKG:16
32-41-37-960-801-01	S	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - LH MLG BRAKE FILTER (L580GC)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 32.590	AFL	6741						
PROC. REF: AMM 32-41-37-960-801PROC. REF: AMM 32-41-37-960-801								PKG:21
32-41-37-960-801-02	S	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - RH MLG BRAKE FILTER (R580GC)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 32.590	AFL	6741						
PROC. REF: AMM 32-41-37-960-801PROC. REF: AMM 32-41-37-960-801								PKG:21
32-41-37-960-801-03	S	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - UPSTREAM FILTER OF PARK BRAKE SELECTOR VALVE (900GC)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-41-37-960-801PROC. REF: AMM 32-41-37-960-801								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-37-960-801-04	S	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - DOWNSTREAM FILTER OF PARK BRAKE SELECTOR VALVE (901GC)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 32-41-37-960-801PROC. REF: AMM 32-41-37-960-801								PKG:21
32-41-45-900-801-01		REMOVAL / INSTALLATION OF THE ANTI-SKID CONTROL UNIT - ANTISKID CONTROL UNIT (2GC)						Component ATA:32
PN:C20188102-1	MOS/MSC	30-May-14	O/C					
SN:H0271	HRS	12736.3		TSN 4617				
WC#: 32.610	AFL	6551		TSN 2306				
PROC. REF: AMM 32-41-45-900-801PROC. REF: AMM 32-41-45-900-801								
32-41-49-900-802-01		REMOVAL / INSTALLATION OF THE NLG WHEEL TACHOMETER GENERATORS - LH NLG WHEEL TACHOMETER GENERATOR (L575GC)						Component ATA:32
PN:C20260000-1	MOS/MSC	17-Dec-21	O/C					
SN:684	HRS	13275.5						
WC#: 32.620	AFL	6741						
PROC. REF: AMM 32-41-49-900-802PROC. REF: AMM 32-41-49-900-802								
32-41-49-900-802-02		REMOVAL / INSTALLATION OF THE NLG WHEEL TACHOMETER GENERATORS - RH NLG WHEEL TACHOMETER GENERATOR (R575GC)						Component ATA:32
PN:C20260000-1	MOS/MSC	17-Dec-21	O/C					
SN:2032	HRS	13275.5						
WC#: 32.620	AFL	6741						
PROC. REF: AMM 32-41-49-900-802PROC. REF: AMM 32-41-49-900-802								
32-41-49-900-803-01		REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (L560GC)						Component ATA:32
PN:00-200-1021	MOS/MSC	27-Feb-04	O/C					
SN:2924	HRS	6192.4						
WC#: 32.630	AFL	3126						
PROC. REF: AMM 32-41-49-900-803PROC. REF: AMM 32-41-49-900-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-49-900-803-02	REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (L555GC)						Component	ATA:32
PN:C20260000-1	MOS/MSC	25-Mar-10	O/C	TSN 9				
SN:2015	HRS	10865.5		TSN 0				
WC#: 32.630	AFL	5891		TSN 0				
PROC. REF: AMM 32-41-49-900-803PROC. REF: AMM 32-41-49-900-803								
32-41-49-900-803-03	REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (R555GC)						Component	ATA:32
PN:C20260000-1	MOS/MSC	17-Dec-21	O/C					
SN:3359	HRS	13275.5						
WC#: 32.640	AFL	6741						
PROC. REF: AMM 32-41-49-900-803PROC. REF: AMM 32-41-49-900-803								
32-41-49-900-803-04	REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (R560GC)						Component	ATA:32
PN:00-200-1021	MOS/MSC	07-Apr-06	O/C	TSR 0				
SN:2610	HRS	8593.4		TSR 0				
WC#: 32.640	AFL	4545		TSR 0				
PROC. REF: AMM 32-41-49-900-803PROC. REF: AMM 32-41-49-900-803								
32-41-57-900-801-01	REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - LH MLG BRAKE SERVOVALVE (L5GC)						Component	ATA:32
PN:C20103300	MOS/MSC	30-May-14	O/C					
SN:00654	HRS	12736.3						
WC#: 32.550	AFL	6551						
PROC. REF: AMM 32-41-57-900-801PROC. REF: AMM 32-41-57-900-801								
32-41-57-900-801-02	REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - RH MLG BRAKE SERVOVALVE (R5GC)						Component	ATA:32
PN:C20103300	MOS/MSC	27-May-11	O/C	TSR 0				
SN:167	HRS	11414.25		TSR 0				
WC#: 32.550	AFL	6044		TSR 0				
PROC. REF: AMM 32-41-57-900-801PROC. REF: AMM 32-41-57-900-801								
32-42-00-610-801-01	SERVICING OF THE PARK BRAKE CONTROL - SERVICING OF THE PARK BRAKE CONTROL CABLE (511GC)						Service	ATA:32
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 32.420	AFL	6673						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-42-00-610-801PROC. REF: AMM 32-42-00-610-801								
32-42-00-720-801-01	^S	FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - PARK BRAKE SYSTEM						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
	AFL	6741						
PKG:22								
PROC. REF: AMM 32-42-00-720-801PROC. REF: AMM 32-42-00-720-801								
32-42-01-900-801-01		REMOVAL / INSTALLATION OF THE PARK BRAKE SELECTOR VALVE - PARK BRAKE SELECTOR VALVE (30GC)						Component ATA:32
PN:70012-1	MOS/MSC	07-Feb-91	O/C					
SN:108	HRS	0		TSN 0				
WC#: 32.680	AFL	0						
PROC. REF: AMM 32-42-01-900-801PROC. REF: AMM 32-42-01-900-801								
32-42-05-720-801-01		FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY - PARK BRAKE ACCUMULATOR (520GC)						Service ATA:32
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 32.690	AFL	6673						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32-42-05-780-801-01		CHECK OF THE PARK BRAKE ACCUMULATOR PRESSURE						Service ATA:32
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-42-05-780-801PROC. REF: AMM 32-42-05-780-801								
32-42-05-780-801-02	^S	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (520GC)						Service ATA:32
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3	1600 (+40)					
	AFL	7304						
PKG:6								
PROC. REF: AMM 32-42-05-780-801PROC. REF: AMM 32-42-05-780-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-42-05-900-801-01 REMOVAL / INSTALLATION OF THE PARK BRAKE SYSTEM ACCUMULATOR - PARK BRAKE ACCUMULATOR (520GC)								Component ATA:32
PN:60833-2	MOS/MSC	07-Feb-91	O/C					
SN:692	HRS	0		TSN 0				
WC#: 32.690	AFL	0						
PROC. REF: AMM 32-42-05-900-801PROC. REF: AMM 32-42-05-900-801								
32-42-17-900-801-01 REMOVAL/INSTALLATION OF PARK BRAKE PRESSURE SWITCH - PARK BRAKE PRESSURE SWITCH (13GW)								Component ATA:32
PN:90G198-1	MOS/MSC	07-Feb-91	O/C					
SN:267	HRS	0		TSN 0				
WC#: 32.700	AFL	0						
PROC. REF: AMM 32-42-17-900-801PROC. REF: AMM 32-42-17-900-801								
32-44-00-220-801-01 DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES								Service ATA:32
	MOS/MSC	09-Feb-15	O/C					
	HRS	13109.23						
	AFL	6701						
PROC. REF: AMM 32-44-00-220-801PROC. REF: AMM 32-44-00-220-801								
32-44-00-250-801-01 SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG OUTBOARD WHEEL (L540GC)								Service ATA:32
PN:C20180400	MOS							
SN:02624/02769	HRS							
WC#: 32.450	AFL	7118	400 (+3%)		7518	7530	205 (+12)	
PROC. REF: AMM 32-44-00-250-801PROC. REF: AMM 32-44-00-250-801								
32-44-00-250-801-02 SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG INBOARD WHEEL (L535GC)								Service ATA:32
PN:C20180400	MOS							
SN:02838/02716	HRS							
WC#: 32.460	AFL	7118	400 (+3%)		7518	7530	205 (+12)	
PROC. REF: AMM 32-44-00-250-801PROC. REF: AMM 32-44-00-250-801								
32-44-00-250-801-03 SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R535GC)								Service ATA:32
PN:C20180400	MOS	28-Jun-24						
SN:02703/01419/02041	HRS	13734.9						
WC#: 32.470	AFL	7139	400 (+3%)		7539	7551	226 (+12)	
PROC. REF: AMM 32-44-00-250-801PROC. REF: AMM 32-44-00-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-00-250-801-04	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R540GC)							Service ATA:32
PN:C20180400	MOS	28-Jun-24						
SN:01665/01136/0260	HRS	13734.9						
WC#: 32.480	AFL	7139	400 (+3%)		7539	7551	226 (+12)	
PROC. REF: AMM 32-44-00-250-801PROC. REF: AMM 32-44-00-250-801								
32-44-00-250-801-05	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L565GC)							Service ATA:32
PN:C20182100	MOS	28-Jun-24						
SN:01103/01085	HRS	13734.9						
WC#: 32.490	AFL	7139	500 (+3%)		7639	7654	326 (+15)	
PROC. REF: AMM 32-44-00-250-801PROC. REF: AMM 32-44-00-250-801								
32-44-00-250-801-06	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R565GC)							Service ATA:32
PN:C20182100	MOS	28-Jun-24						
SN:01228/01222	HRS	13734.9						
WC#: 32.500	AFL	7139	500 (+3%)		7639	7654	326 (+15)	
PROC. REF: AMM 32-44-00-250-801PROC. REF: AMM 32-44-00-250-801								
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES							Service ATA:32
	MOS	17-Feb-26	2 (+5d)		17-Apr-26	22-Apr-26	OVD	
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 32-44-00-780-801PROC. REF: AMM 32-44-00-780-801								
32-44-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEELS - LH NLG WHEEL (L565GC)							Component ATA:32
PN:C20182100	MOS/MSC	28-Jun-24	O/C	TSO 0				
SN:01103/01085	HRS	13734.9		TSO 0				
WC#: 32.490	AFL	7139		TSO 0				
PROC. REF: AMM 32-44-01-900-801PROC. REF: AMM 32-44-01-900-801								
32-44-01-900-801-02	REMOVAL / INSTALLATION OF THE NLG WHEELS - RH NLG WHEEL (R565GC)							Component ATA:32
PN:C20182100	MOS/MSC	28-Jun-24	O/C	TSO 0				
SN:01228/01222	HRS	13734.9		TSO 0				
WC#: 32.500	AFL	7139		TSO 0				
PROC. REF: AMM 32-44-01-900-801PROC. REF: AMM 32-44-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-05-900-801-01		REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - LH NLG TIRE (L570GC)						Component ATA:32
PN:M13301 IND 02	MOS/MSC	28-Jun-24	O/C	TSN 0				
SN:2137T181	HRS	13734.9		TSN 0				
WC#: 32.490	AFL	7139		TSN 0				
PROC. REF: AMM 32-44-05-900-801PROC. REF: AMM 32-44-05-900-801								
32-44-05-900-801-02		REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - RH NLG TIRE (R570GC)						Component ATA:32
PN:M13301 IND 02	MOS/MSC	28-Jun-24	O/C	TSN 0				
SN:2136T169	HRS	13734.9		TSN 0				
WC#: 32.500	AFL	7139		TSN 0				
PROC. REF: AMM 32-44-05-900-801PROC. REF: AMM 32-44-05-900-801								
32-44-09-900-801-01		REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG OUTBOARD WHEEL (L540GC)						Component ATA:32
PN:C20180400	MOS/MSC	16-Apr-24	O/C	TSO 0				
SN:02624/02769	HRS	13715.9		TSO 0				
WC#: 32.450	AFL	7118		TSO 0				
PROC. REF: AMM 32-44-09-900-801PROC. REF: AMM 32-44-09-900-801								
32-44-09-900-801-02		REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG INBOARD WHEEL (L535GC)						Component ATA:32
PN:C20180400	MOS/MSC	16-Apr-24	O/C	TSO 0				
SN:02838/02716	HRS	13715.9		TSO 0				
WC#: 32.460	AFL	7118		TSO 0				
PROC. REF: AMM 32-44-09-900-801PROC. REF: AMM 32-44-09-900-801								
32-44-09-900-801-03		REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG INBOARD WHEEL (R535GC)						Component ATA:32
PN:C20180400	MOS/MSC	28-Jun-24	O/C	TSO 0				
SN:02703/01419/02041	HRS	13734.9		TSO 0				
WC#: 32.470	AFL	7139		TSO 0				
PROC. REF: AMM 32-44-09-900-801PROC. REF: AMM 32-44-09-900-801								
32-44-09-900-801-04		REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG OUTBOARD WHEEL (R540GC)						Component ATA:32
PN:C20180400	MOS/MSC	28-Jun-24	O/C	TSO 0				
SN:01665/01136/0260	HRS	13734.9		TSO 0				
WC#: 32.480	AFL	7139		TSO 0				
PROC. REF: AMM 32-44-09-900-801PROC. REF: AMM 32-44-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-13-900-801-01 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG OUTBOARD TIRE (L550GC)							Component	ATA:32
PN:M06201IND04	MOS/MSC	16-Apr-24	O/C	TSN 0				
SN:2025T136	HRS	13715.9		TSN 0				
WC#: 32.450	AFL	7118		TSN 0				
PROC. REF: AMM 32-44-13-900-801PROC. REF: AMM 32-44-13-900-801								
32-44-13-900-801-02 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG INBOARD TIRE (L545GC)							Component	ATA:32
PN:M06201IND04	MOS/MSC	16-Apr-24	O/C	TSN 0				
SN:2021T164	HRS	13715.9		TSN 0				
WC#: 32.460	AFL	7118		TSN 0				
PROC. REF: AMM 32-44-13-900-801PROC. REF: AMM 32-44-13-900-801								
32-44-13-900-801-03 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG INBOARD TIRE (R545GC)							Component	ATA:32
PN:M06201 IND 04	MOS/MSC	28-Jun-24	O/C	TSN 0				
SN:2100T146	HRS	13734.9		TSN 0				
WC#: 32.470	AFL	7139		TSN 0				
PROC. REF: AMM 32-44-13-900-801PROC. REF: AMM 32-44-13-900-801								
32-44-13-900-801-04 REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG OUTBOARD TIRE (R550GC)							Component	ATA:32
PN:M06201 IND 04	MOS/MSC	28-Jun-24	O/C	TSN 0				
SN:3021T148	HRS	13734.9		TSN 0				
WC#: 32.480	AFL	7139		TSN 0				
PROC. REF: AMM 32-44-13-900-801PROC. REF: AMM 32-44-13-900-801								
32-44-17-350-801-01 RESTORATION OF THE BRAKES (OVERHAUL) - LH MLG OUTBOARD BRAKE (L530GC)							Service	ATA:32
PN:C20181100-8	MOS/MSC	08-Mar-13	A/R				OVERHAUL	
SN:1622	HRS	12150.15						
WC#: 32.510	AFL	6335						
PROC. REF: AMM 32-44-17-350-801PROC. REF: AMM 32-44-17-350-801								
32-44-17-350-801-02 RESTORATION OF THE BRAKES (OVERHAUL) - LH MLG INBOARD BRAKE (L525GC)							Service	ATA:32
PN:C20181100-8	MOS/MSC		A/R				OVERHAUL	
SN:01209	HRS							
WC#: 32.510	AFL							
PROC. REF: AMM 32-44-17-350-801PROC. REF: AMM 32-44-17-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-17-350-801-03	RESTORATION OF THE BRAKES (OVERHAUL) - RH MLG INBOARD BRAKE (R525GC)							Service ATA:32
PN:C20181100-8	MOS/MSC		A/R					OVERHAUL
SN:1211	HRS							
WC#: 32.520	AFL							
PROC. REF: AMM 32-44-17-350-801PROC. REF: AMM 32-44-17-350-801								
32-44-17-350-801-04	RESTORATION OF THE BRAKES (OVERHAUL) - RH MLG OUTBOARD BRAKE (R530GC)							Service ATA:32
PN:C20181100-8	MOS/MSC		A/R					OVERHAUL
SN:1634	HRS							
WC#: 32.520	AFL							
PROC. REF: AMM 32-44-17-350-801PROC. REF: AMM 32-44-17-350-801								
32-44-17-900-801-01	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG OUTBOARD BRAKE (L530GC)							Component ATA:32
PN:C20181100-8	MOS/MSC	08-Mar-13	A/R	TSO 5				OVERHAUL
SN:1622	HRS	12150.15		TSO 0				
WC#: 32.510	AFL	6335		TSN 2970, TSO 0				
PROC. REF: AMM 32-44-17-900-801PROC. REF: AMM 32-44-17-900-801								
32-44-17-900-801-02	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG INBOARD BRAKE (L525GC)							Component ATA:32
PN:C20181100-8	MOS/MSC	04-Nov-22	A/R					OVERHAUL
SN:01209	HRS	13441.5						
WC#: 32.510	AFL	6881						
PROC. REF: AMM 32-44-17-900-801PROC. REF: AMM 32-44-17-900-801								
32-44-17-900-801-03	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG INBOARD BRAKE (R525GC)							Component ATA:32
PN:C20181100-8	MOS/MSC	09-Mar-12	A/R					OVERHAUL
SN:1211	HRS	11749.08						
WC#: 32.520	AFL	6227						
PROC. REF: AMM 32-44-17-900-801PROC. REF: AMM 32-44-17-900-801								
32-44-17-900-801-04	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG OUTBOARD BRAKE (R530GC)							Component ATA:32
PN:C20181100-8	MOS/MSC	09-Mar-12	A/R					OVERHAUL
SN:1634	HRS	11749.08						
WC#: 32.520	AFL	6227						
PROC. REF: AMM 32-44-17-900-801PROC. REF: AMM 32-44-17-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-18-960-801-01	REPLACEMENT OF THE WHEEL BRAKE SEALS - LH MLG OUTBOARD BRAKE (L530GC) SEAL							Service ATA:32
PN:C20181100-8	MOS/MSC	08-Mar-13	C/C					
SN:1622	HRS	12150.15						
WC#: 32.510	AFL	6335						
PROC. REF: AMM 32-44-18-960-801PROC. REF: AMM 32-44-18-960-801								
32-44-18-960-801-02	REPLACEMENT OF THE WHEEL BRAKE SEALS - LH MLG INBOARD BRAKE (L525GC) SEAL							Service ATA:32
PN:C20181100-8	MOS/MSC		C/C					
SN:01209	HRS							
WC#: 32.510	AFL							
PROC. REF: AMM 32-44-18-960-801PROC. REF: AMM 32-44-18-960-801								
32-44-18-960-801-03	REPLACEMENT OF THE WHEEL BRAKE SEALS - RH MLG INBOARD BRAKE (R525GC) SEAL							Service ATA:32
PN:C20181100-8	MOS/MSC		C/C					
SN:1211	HRS							
WC#: 32.520	AFL							
PROC. REF: AMM 32-44-18-960-801PROC. REF: AMM 32-44-18-960-801								
32-44-18-960-801-04	REPLACEMENT OF THE WHEEL BRAKE SEALS - RH MLG OUTBOARD BRAKE (R530GC) SEAL							Service ATA:32
PN:C20181100-8	MOS/MSC		C/C					
SN:1634	HRS							
WC#: 32.520	AFL							
PROC. REF: AMM 32-44-18-960-801PROC. REF: AMM 32-44-18-960-801								
32-50-13-900-801-01	REMOVAL / INSTALLATION OF THE STEERING SERVOVALVE - STEERING SERVOVALVE (5GH)							Component ATA:32
PN:A25455004	MOS/MSC	31-Mar-14	O/C					
SN:01053	HRS	12625.42						
WC#: 32.770	AFL	6516						
PROC. REF: AMM 32-50-13-900-801PROC. REF: AMM 32-50-13-900-801								
32-50-17-960-801-01 ^S	REPLACEMENT OF THE STEERING SYSTEM FILTERING ELEMENT - STEERING SYSTEM FILTER (511GH)							Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 32.740	AFL	6741						
PROC. REF: AMM 32-50-17-960-801PROC. REF: AMM 32-50-17-960-801								

PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-50-25-900-801-01	REMOVAL / INSTALLATION OF THE STEERING CONTROL HANDWHEEL UNIT - STEERING CONTROL HANDWHEEL UNIT (2GH)							Component ATA:32
PN:287837-1	MOS/MSC		O/C					
SN:U697	HRS	4108						
WC#: 32.710	AFL							
PROC. REF: AMM 32-50-25-900-801PROC. REF: AMM 32-50-25-900-801								
32-61-45-760-801-01	^S	CHECK OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - LH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (L6GA1)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PKG:21								
PROC. REF: AMM 32-61-45-760-801PROC. REF: AMM 32-61-45-760-801								
32-61-45-760-801-02	^S	CHECK OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - RH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (R6GA1)						Service ATA:32
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PKG:21								
PROC. REF: AMM 32-61-45-760-801PROC. REF: AMM 32-61-45-760-801								
32-61-45-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - LH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (L6GA1)							Component ATA:32
PN:248022750	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.350	AFL	0						
PROC. REF: AMM 32-61-45-900-801PROC. REF: AMM 32-61-45-900-801								
32-61-45-900-801-02	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - RH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (R6GA1)							Component ATA:32
PN:248022750	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.350	AFL	0						
PROC. REF: AMM 32-61-45-900-801PROC. REF: AMM 32-61-45-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-49-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG LEG OUTBOARD PROXIMITY SWITCH (L2GF1)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-02	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG LEG INBOARD PROXIMITY SWITCH (L2GF2)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-03	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG LEG INBOARD PROXIMITY SWITCH (R2GF2)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-04	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG LEG OUTBOARD PROXIMITY SWITCH (R2GF1)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-05	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LEG LH PROXIMITY SWITCH (3GF1)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-49-900-801-06		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LEG RH PROXIMITY SWITCH (3GF2)					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-07		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LH DOOR PROXIMITY SWITCH (L3DG)					Component	ATA:32
PN:84738-702	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.390	AFL	0						
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-801-08		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG RH DOOR PROXIMITY SWITCH (R3DG)					Component	ATA:32
PN:84738-702	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.390	AFL	0						
PROC. REF: AMM 32-61-49-900-801PROC. REF: AMM 32-61-49-900-801								
32-61-49-900-802-01		REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - NLG DRAG BRACE LH PROXIMITY SWITCH (11GA1)					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-802PROC. REF: AMM 32-61-49-900-802								
32-61-49-900-802-02		REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - NLG DRAG BRACE RH PROXIMITY SWITCH (11GA2)					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-802PROC. REF: AMM 32-61-49-900-802								
32-61-49-900-802-03		REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - LH MLG BRACE ACTUATOR PROXIMITY SWITCH 1 (L12GA1)					Component	ATA:32
PN:84738702	MOS/MSC	07-Feb-91	O/C					
SN:2372	HRS	0		TSN 0				
WC#: 32.410	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-61-49-900-802PROC. REF: AMM 32-61-49-900-802								
32-61-49-900-802-04		REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - LH MLG BRACE ACTUATOR PROXIMITY SWITCH 2 (L12GA2)					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-802PROC. REF: AMM 32-61-49-900-802								
32-61-49-900-802-05		REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - RH MLG BRACE ACTUATOR PROXIMITY SWITCH 1 (R12GA1)					Component	ATA:32
PN:84738702	MOS/MSC	07-Feb-91	O/C					
SN:2372	HRS	0		TSN 0				
WC#: 32.410	AFL	0						
PROC. REF: AMM 32-61-49-900-802PROC. REF: AMM 32-61-49-900-802								
32-61-49-900-802-06		REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - RH MLG BRACE ACTUATOR PROXIMITY SWITCH 2 (R12GA2)					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-802PROC. REF: AMM 32-61-49-900-802								
32-61-49-900-803-01		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - NLG UPLOCK BOX PROXIMITY SWITCH 1 (13GA1)					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								
32-61-49-900-803-02		REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - NLG UPLOCK BOX PROXIMITY SWITCH 2 (13GA2)					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-49-900-803-03	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - LH MLG UPLOCK BOX PROXIMITY SWITCH (L7GA1)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								
32-61-49-900-803-04	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - RH MLG UPLOCK BOX PROXIMITY SWITCH (R7GA1)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								
32-61-49-900-803-05	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - LH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 1 (L14GA1)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								
32-61-49-900-803-06	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - LH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 2 (L14GA2)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								
32-61-49-900-803-07	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - RH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 1 (R14GA1)						Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-49-900-803-08	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - RH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 2 (R14GA2)							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-61-49-900-803PROC. REF: AMM 32-61-49-900-803								
321111	LH MAIN LANDING GEAR (MLG) STRUT ASSEMBLY							Component ATA:32
PN:D22801100-11	MOS/MSC	03-Apr-03	O/C	TSO 0				
SN:U99	HRS	5826.4		TSO 0				
WC#: 32.020	AFL	2849		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
321161	RH MAIN LANDING GEAR (MLG) STRUT ASSEMBLY							Component ATA:32
PN:D22801100-11	MOS/MSC	03-Apr-03	O/C	TSO 0				
SN:U99	HRS	5826.4		TSO 0				
WC#: 32.030	AFL	2849		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
321241	LH MAIN LANDING GEAR STRUT DOOR							Component ATA:32
PN:FGFB191	MOS/MSC	07-Feb-91	O/C					
SN:96	HRS	0		TSN 0				
WC#: 32.060	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
321251	RH MAIN LANDING GEAR STRUT DOOR							Component ATA:32
PN:FGFB192A2	MOS/MSC	23-Dec-03	O/C					
SN:340EXA	HRS	6042.5		TSN 0				
WC#: 32.060	AFL	3040						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
321261	LH MAIN LANDING GEAR DOOR							Component ATA:32
PN:FGFB293100	MOS/MSC	07-Feb-91	O/C					
SN:89BZ	HRS	0		TSN 0				
WC#: 32.070	AFL	0						
PROC. REF: AMM 52-80-05-900-801PROC. REF: AMM 52-80-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321271	RH MAIN LANDING GEAR DOOR							Component ATA:32
PN:FGFB293200	MOS/MSC	07-Feb-91	O/C					
SN:89BZ	HRS	0		TSN 0				
WC#: 32.070	AFL	0						
PROC. REF: AMM 52-80-05-900-801PROC. REF: AMM 52-80-05-900-801								
322111	NOSE LANDING GEAR (NLG) CYLINDER							Component ATA:32
PN:D22811200-13	MOS/MSC	03-Apr-03	O/C	TSO 0				
SN:U99	HRS	5826.4		TSO 0				
WC#: 32.110	AFL	2849		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
322155	NOSE LANDING GEAR TELESCOPIC TUBE YOKE ASSEMBLY							Component ATA:32
PN:D57635	MOS/MSC	03-Apr-03	H/T	TSO 0				
SN:436	HRS	5826.4		TSO 0				
WC#: 32.120	AFL	2849		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
322211	NOSE LANDING GEAR STRUT MAIN DOOR							Component ATA:32
PN:FGFB291300	MOS/MSC	07-Feb-91	O/C					
SN:92BZ	HRS	0		TSN 0				
WC#: 32.140	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
322221	NOSE LANDING GEAR STRUT SECONDARY DOOR							Component ATA:32
PN:FGFB291400	MOS/MSC	07-Feb-91	O/C					
SN:97AG	HRS	0		TSN 0				
WC#: 32.140	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
322231	LH NOSE LANDING GEAR DOOR							Component ATA:32
PN:FGFB291100	MOS/MSC	07-Feb-91	O/C					
SN:101BZ	HRS	0		TSN 0				
WC#: 32.150	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
322241		RH NOSE LANDING GEAR DOOR					Component	ATA:32
PN:FGFB291200	MOS/MSC	07-Feb-91	O/C					
SN:97BZ	HRS	0		TSN 0				
WC#: 32.150	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
322A01 ^U		ELECT NLG LOWER HARNESS					Component	ATA:32
PN:D23284000-2	MOS/MSC	18-Oct-13	O/C	TSR 2				
SN:B155	HRS	12430.13						
	AFL	6428						
323101		GEAR/DOOR CONTROL					Component	ATA:32
PN:BHC1031-2	MOS/MSC	07-Feb-91	O/C					
SN:108	HRS	0		TSN 0				
WC#: 32.200	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323121		GEAR EXTENSION CONTROL ELECTRIC VALVE					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.210	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323131		GEAR RETRACTION CONTROL ELECTRIC VALVE					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.210	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323141		DOOR OPENING CONTROL ELECTRIC VALVE					Component	ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.220	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323151	DOOR CLOSING CONTROL ELECTRIC VALVE							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.220	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323161	GEAR ELECTRO DISTRIBUTOR							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.230	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323181	DOOR ELECTRO DISTRIBUTOR							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.230	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323201	MAIN LANDING GEAR DOOR ACTUATOR RESTRICTOR VALVE							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.230	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323231	SHUTTLE VALVE PROTECTION CHECK VALVE							Component ATA:32
PN:C24816000	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.240	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323241	LH MAIN LANDING GEAR ACTUATOR EXTENSION RESTRICTOR VALVE							Component ATA:32
PN:A24508-5220	MOS/MSC	07-Feb-91	O/C					
SN:B12616	HRS	0		TSN 0				
WC#: 32.250	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323251	RH MAIN LANDING GEAR ACTUATOR EXTENSION RESTRICTOR VALVE							Component ATA:32
PN:A24508-5220	MOS/MSC	07-Feb-91	O/C					
SN:B12629	HRS	0		TSN 0				
WC#: 32.250	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323261	LH MAIN LANDING GEAR ACTUATOR RETRACTION RESTRICTOR VALVE							Component ATA:32
PN:A24510-5220	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.260	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323271	RH MAIN LANDING GEAR ACTUATOR RETRACTION RESTRICTOR VALVE							Component ATA:32
PN:A24510-5220	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.260	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323281	LH MAIN LANDING GEAR ACTUATOR DOOR OPENING RESTRICTOR VALVE							Component ATA:32
PN:A24506-5200	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.270	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323291	RH MAIN LANDING GEAR ACTUATOR DOOR OPENING RESTRICTOR VALVE							Component ATA:32
PN:A24506-5200	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.270	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323331	NOSE LANDING GEAR UNLOCKING RESTRICTOR VALVE							Component ATA:32
PN:A24508-5090	MOS/MSC	07-Feb-91	O/C					
SN:B15512	HRS	0		TSN 0				
WC#: 32.290	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323341	NOSE LANDING GEAR TELESCOPIC STRUT UNLOCKING RESTRICTOR VALVE							Component ATA:32
PN:A24508-5180	MOS/MSC	07-Feb-91	O/C					
SN:B12346	HRS	0		TSN 0				
WC#: 32.290	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323551	NOSE LANDING GEAR SWIVEL COUPLING							Component ATA:32
PN:C24266-1	MOS/MSC	09-Mar-12	O/C					
SN:H1288	HRS	11749.08						
WC#: 32.320	AFL	6227						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323721	LH MAIN LANDING GEAR WHEEL WELL PROXIMITY DETECTOR							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.380	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
323731	RH MAIN LANDING GEAR WHEEL WELL PROXIMITY DETECTOR							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.380	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324451	NORMAL/EMERGENCY BRAKE DISTRIBUTOR							Component ATA:32
PN:57530-21	MOS/MSC	17-Dec-21	O/C					
SN:206	HRS	13275.5						
WC#: 32.530	AFL	6741						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324461	NORMAL BRAKE ELECTRIC DISTRIBUTOR							Component ATA:32
PN:65660-1	MOS/MSC	07-Feb-91	O/C					
SN:221A	HRS	0		TSN 0				
WC#: 32.530	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324471	NORMAL BRAKE DISTRIBUTOR RETURN CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.540	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324501	LH SERVO-VALVE RETURN CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.560	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324511	RH SERVO-VALVE RETURN CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.560	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324521	LH BRAKE NORMAL RESTRICTOR VALVE							Component ATA:32
PN:C24758140	MOS/MSC	07-Feb-91	O/C					
SN:B233	HRS	0		TSN 0				
WC#: 32.570	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324531	RH BRAKE NORMAL RESTRICTOR VALVE							Component ATA:32
PN:C24758140	MOS/MSC	07-Feb-91	O/C					
SN:B232	HRS	0		TSN 0				
WC#: 32.570	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324541	LH BRAKE NORMAL PRESSURE SWITCH							Component ATA:32
PN:7G663-1	MOS/MSC	09-Jul-98	O/C	TSN 0				
SN:1110	HRS			TSN 0				
WC#: 32.580	AFL			TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324551	RH BRAKE NORMAL PRESSURE SWITCH							Component ATA:32
PN:7G1090	MOS/MSC	31-Mar-05	O/C					
SN:700	HRS	7394.8						
WC#: 32.580	AFL	3866						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324561	LH BRAKING SYSTEM FILTER							Component ATA:32
PN:ADB295-4	MOS/MSC	07-Feb-91	O/C					
SN:331	HRS	0		TSN 0				
WC#: 32.590	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324571	RH BRAKING SYSTEM FILTER							Component ATA:32
PN:ADB295-4	MOS/MSC	07-Feb-91	O/C					
SN:333	HRS	0		TSN 0				
WC#: 32.590	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324577	PARKING BRAKE SELECTOR VALVE UPSTREAM FILTER							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.595	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324578	PARKING BRAKE SELECTOR VALVE DOWNSTREAM FILTER							Component ATA:32
PN:PN	DAYS/MSC		O/C					
SN:UNKNOWN	HRS	0						
WC#: 32.595	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324581	LH BRAKING SYSTEM SWIVEL COUPLING							Component ATA:32
PN:A100-24660	MOS/MSC	09-Mar-12	O/C					
SN:B801	HRS	11749.08						
WC#: 32.600	AFL	6227						
PROC. REF: AMM 32-44-21-900-801PROC. REF: AMM 32-44-21-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324591	RH BRAKING SYSTEM SWIVEL COUPLING							Component ATA:32
PN:A101-24660	MOS/MSC	09-Mar-12	O/C					
SN:H1232	HRS	11749.08						
WC#: 32.600	AFL	6227						
PROC. REF: AMM 32-44-21-900-801PROC. REF: AMM 32-44-21-900-801								
324701	EMERGENCY BRAKE ELECTRIC DISTRIBUTOR							Component ATA:32
PN:65670-1	MOS/MSC	07-Feb-91	O/C					
SN:902A	HRS	0		TSN 0				
WC#: 32.650	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324711	EMERGENCY BRAKE DISTRIBUTOR RETURN CHECK VALVE							Component ATA:32
PN:A24515	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.650	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324721	LH MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH							Component ATA:32
PN:7G1108	MOS/MSC	28-May-11	O/C	TSN 0				
SN:549	HRS	11414.25		TSN 0				
WC#: 32.660	AFL	6044		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324731	RH MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH							Component ATA:32
PN:7G862	MOS/MSC	07-Feb-91	O/C					
SN:332	HRS	0		TSN 0				
WC#: 32.660	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324741	LH EMERGENCY/PARKING BRAKE SHUTTLE VALVE							Component ATA:32
PN:A24523	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.670	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324751	RH EMERGENCY/PARKING BRAKE SHUTTLE VALVE							Component ATA:32
PN:A24523	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.670	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324821	PARKING BRAKE ACCUMULATOR PRESSURE GAUGE							Component ATA:32
PN:18040100	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.690	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
324831	PARKING BRAKE ACCUMULATOR CHECK VALVE							Component ATA:32
PN:C24815000	MOS/MSC	07-Feb-91	O/C					
SN:FM59	HRS	0		TSN 0				
WC#: 32.700	AFL	0						
PROC. REF: AMM 32-42-05-900-801PROC. REF: AMM 32-42-05-900-801								
324841	PARKING BRAKE ACCUMULATOR OVERPRESSURE VALVE							Component ATA:32
PN:D25AB1310	MOS/MSC	07-Feb-91	O/C					
SN:107	HRS	0		TSN 0				
WC#: 32.700	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
325111	STEERING AMPLIFIER							Component ATA:32
PN:C24242010	MOS/MSC	07-Feb-91	O/C					
SN:U91	HRS	0		TSN 0				
WC#: 32.710	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
325121	NOSE LANDING GEAR STEERING ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.710	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
325171	STEERING ACCUMULATOR							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.730	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
325191	STEERING SYSTEM FILTERING ELEMENT							Component ATA:32
PN:ADB295-4	MOS/MSC	07-Feb-91	O/C					
SN:0236	HRS	0		TSN 0				
WC#: 32.740	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
325201	LH NOSE LANDING GEAR STEERING SWIVEL COUPLING							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.750	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
325211	RH NOSE LANDING GEAR STEERING SWIVEL COUPLING							Component ATA:32
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.750	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
325251	STEERING SLIDING DISTRIBUTOR VALVE							Component ATA:32
PN:C24166-1	MOS/MSC	28-Nov-08	O/C	TSR 0				
SN:U68	HRS	10765.7		TSR 0				
WC#: 32.760	AFL	5815		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
325271	STEERING SUPPLY ELECTRODISTRIBUTOR							Component ATA:32
PN:65670-1	MOS/MSC	07-Feb-91	O/C					
SN:579A	HRS	0		TSN 0				
WC#: 32.760	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-10-07-900-801-01		REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - PILOT DOME LIGHT (L7LH)						Component ATA:33
PN:35-43-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.020	AFL	0						
PROC. REF: AMM 33-10-07-900-801PROC. REF: AMM 33-10-07-900-801								
33-10-07-900-801-02		REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - COPILOT DOME LIGHT (R7LH)						Component ATA:33
PN:35-43-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.020	AFL	0						
PROC. REF: AMM 33-10-07-900-801PROC. REF: AMM 33-10-07-900-801								
33-10-17-900-801-01		REMOVAL / INSTALLATION OF THE CIRCUIT BREAKER PANEL SPOTLIGHTS - LH CIRCUIT BREAKER PANEL SPOTLIGHT (L5LC)						Component ATA:33
PN:4X650	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.030	AFL	0						
PROC. REF: AMM 33-10-17-900-801PROC. REF: AMM 33-10-17-900-801								
33-10-17-900-801-02		REMOVAL / INSTALLATION OF THE CIRCUIT BREAKER PANEL SPOTLIGHTS - RH CIRCUIT BREAKER PANEL SPOTLIGHT (R5LC)						Component ATA:33
PN:4X650	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.030	AFL	0						
PROC. REF: AMM 33-10-17-900-801PROC. REF: AMM 33-10-17-900-801								
33-20-00-200-801-01		INSPECTION OF "ALC" LIGHTING TUBES						Service ATA:33
	MOS	27-Mar-26	12 (+1m)	Adj -4d	23-Mar-27	23-Apr-27	333 d (+31)	
	HRS	13896.3	400 (+40)		14296.3	14336.3	400 (+40)	
WC#: 33.085	AFL	7313						
PROC. REF: AMM 33-20-00-200-801PROC. REF: AMM 33-20-00-200-801								
33-20-00-200-802-01		CHECK OF THE CONNECTION OF "SELA" LIGHTING TUBES						Service ATA:33
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 33.290	AFL	0						
PROC. REF: AMM 33-20-00-200-802PROC. REF: AMM 33-20-00-200-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-40-00-720-801-01 ^S FUNCTIONAL TEST OF THE EXTERIOR LIGHTS WITH LED TECHNOLOGY - TAXI LIGHT (4LR)								Service ATA:33
	MOS	07-Feb-91						
	HRS	0	1600 (+40)					
	AFL	0						
PROC. REF: AMM 33-40-00-720-801PROC. REF: AMM 33-40-00-720-801								PKG:21
33-40-01-900-801-01 REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - LH NAVIGATION LIGHT (L3LJ) OR (L3LJ) / (28L)								Component ATA:33
PN:A7512-24	MOS/MSC	04-Jun-08	O/C	TSN 0				
SN:UNKNOWN	HRS	10534.2		TSN 0				
WC#: 33.120	AFL	5657		TSN 0				
PROC. REF: AMM 33-40-01-900-801PROC. REF: AMM 33-40-01-900-801								
33-40-01-900-801-02 REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - RH NAVIGATION LIGHT (R3LJ) OR (R3LJ) / (29L)								Component ATA:33
PN:MS25309-7512	MOS/MSC	30-Aug-13	O/C	TSN 0				
SN:NSN	HRS	12348.5		TSN 0				
WC#: 33.120	AFL	6402		TSN 0				
PROC. REF: AMM 33-40-01-900-801PROC. REF: AMM 33-40-01-900-801								
33-40-09-900-802-01 REMOVAL / INSTALLATION OF UPPER ANTI-COLLISION LIGHT - UPPER ANTI-COLLISION LIGHT (4LX)								Component ATA:33
PN:01-0790044-09	MOS/MSC	09-Feb-15	O/C	TSN 0				
SN:07795	HRS	13109.23		TSN 0				
WC#: 33.190	AFL	6701		TSN 0				
PROC. REF: AMM 33-40-09-900-802PROC. REF: AMM 33-40-09-900-802								
33-40-37-900-801-01 REMOVAL / INSTALLATION OF THE LANDING LIGHTS - LH LANDING LIGHT (L3LM)								Component ATA:33
PN:Q4559X	MOS/MSC	24-Jan-08	O/C	TSN 0				
SN:UNKNOWN	HRS	10296.4		TSN 0				
WC#: 33.170	AFL	5492		TSN 0				
PROC. REF: AMM 33-40-37-900-801PROC. REF: AMM 33-40-37-900-801								
33-40-37-900-801-02 REMOVAL / INSTALLATION OF THE LANDING LIGHTS - RH LANDING LIGHT (R3LM)								Component ATA:33
PN:Q4559X	MOS/MSC	08-Nov-08	O/C	TSN 0				
SN:47841	HRS	5732.1		TSN 0				
WC#: 33.170	AFL	2776		TSN 0				
PROC. REF: AMM 33-40-37-900-801PROC. REF: AMM 33-40-37-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-40-41-900-801-01REMOVAL / INSTALLATION OF THE TAXI LIGHT - TAXI LIGHT (4LR)								Component ATA:33
PN:4626	MOS/MSC	28-May-08	O/C	TSN 0				
SN:UNKNOWN	HRS	10513.5		TSN 0				
WC#: 33.180	AFL	5645		TSN 0				
PROC. REF: AMM 33-40-41-900-801PROC. REF: AMM 33-40-41-900-801								
33-40-53-960-801-01REPLACEMENT OF THE WHITE REAR ANTI-COLLISION LIGHT POWER SUPPLY BOX - REAR WHITE ANTI-COLLISION LIGHT POWER SUPPLY BOX (7LX)								Component ATA:33
PN:39-44-31	MOS/MSC	20-Dec-08	O/C	TSN 0				
SN:1664	HRS	10780.5		TSN 0				
WC#: 33.210	AFL	5830		TSN 0				
PROC. REF: AMM 33-40-53-960-801PROC. REF: AMM 33-40-53-960-801								
33-50-00-710-804-01 ^S OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EMERGENCY LIGHTING SYSTEM								Service ATA:33
	MOS	07-Feb-91						
	HRS	0	4800 (+40)					
	AFL	0						
PROC. REF: AMM 33-50-00-710-804PROC. REF: AMM 33-50-00-710-804								PKG:23
33-50-05-350-801-01RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT)								Service ATA:33
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 33-50-05-350-801PROC. REF: AMM 33-50-05-350-801								
33-50-05-350-801-02RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT)								Service ATA:33
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 33-50-05-350-801PROC. REF: AMM 33-50-05-350-801								
33-50-05-960-801-01DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - LH FLASHLIGHT BATTERY (9610ME)								Service ATA:33
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 33-50-05-960-801PROC. REF: AMM 33-50-05-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-05-960-801-02	DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - RH FLASHLIGHT BATTERY (9620ME)							Service ATA:33
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 33-50-05-960-801PROC. REF: AMM 33-50-05-960-801								
33-50-33-610-801-01	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 1 (L3LW)							Service ATA:33
PN:D734-02-001	MOS/MSC	30-Oct-24	O/C					
SN:4115/02-2012	HRS	13773.3						
WC#: 33.240	AFL	7183						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-610-801-02	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 2 (R3LW)							Service ATA:33
PN:D734-02-001	MOS/MSC	31-Mar-14	O/C					
SN:1989/01-2003	HRS	12625.42						
WC#: 33.240	AFL	6516						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-610-801-03	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 3 (4LW)							Service ATA:33
PN:D734-02-001	MOS/MSC	31-Mar-14	O/C					
SN:2869/10-2006	HRS	12625.42						
WC#: 33.250	AFL	6516						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-610-801-04	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 4 (20LW) (OPTIONAL)							Service ATA:33
PN:PN	MOS/MSC	07-Feb-91	N/A					
SN:NOT INSTALLED	HRS	0						
WC#: 33.130	AFL	0						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 1 (L3LW)							Component ATA:33
PN:D734-02-001	MOS/MSC	30-Oct-24	O/C					
SN:4115/02-2012	HRS	13773.3						
WC#: 33.240	AFL	7183						
PROC. REF: AMM 33-50-33-900-801PROC. REF: AMM 33-50-33-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-33-900-801-02 REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 2 (R3LW)								Component ATA:33
PN:D734-02-001	MOS/MSC	31-Mar-14	O/C	TSR 19				
SN:1989/01-2003	HRS	12625.42		TSR 650				
WC#: 33.240	AFL	6516		TSR 217				
PROC. REF: AMM 33-50-33-900-801PROC. REF: AMM 33-50-33-900-801								
33-50-33-900-801-03 REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 3 (4LW)								Component ATA:33
PN:D734-02-001	MOS/MSC	31-Mar-14	O/C	TSN 19				
SN:2869/10-2006	HRS	12625.42		TSN 650				
WC#: 33.250	AFL	6516		TSN 217				
PROC. REF: AMM 33-50-33-900-801PROC. REF: AMM 33-50-33-900-801								
33-50-33-900-801-04 REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 4 (20LW) (OPTIONAL)								Component ATA:33
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:NOT INSTALLED	HRS	0						
WC#: 33.130	AFL	0						
PROC. REF: AMM 33-50-33-900-801PROC. REF: AMM 33-50-33-900-801								
33-50-37-900-801-01 REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 1 (L3LW) BATTERY PACK								Component ATA:33
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-50-37-900-801PROC. REF: AMM 33-50-37-900-801								
33-50-37-900-801-02 REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 2 (R3LW) BATTERY PACK								Component ATA:33
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-50-37-900-801PROC. REF: AMM 33-50-37-900-801								
33-50-37-900-801-03 REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 3 (4LW) BATTERY PACK								Component ATA:33
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-50-37-900-801PROC. REF: AMM 33-50-37-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-37-900-801-04 REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 4 (20LW) (OPTIONAL) BATTERY PACK								Component ATA:33
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-50-37-900-801PROC. REF: AMM 33-50-37-900-801								
33-50-37-960-802-01 DISCARD OF THE EPS BATTERY PACKS - EPS 1 (L3LW) BATTERY PACK								Service ATA:33
PN:PN	MOS/MSC	30-Oct-24	O/C					
SN:UNKNOWN	HRS	13773.3						
WC#: 33.240	AFL	7183						
PROC. REF: AMM 33-50-37-960-802PROC. REF: AMM 33-50-37-960-802								
33-50-37-960-802-02 DISCARD OF THE EPS BATTERY PACKS - EPS 2 (R3LW) BATTERY PACK								Service ATA:33
PN:PN	MOS/MSC	28-Aug-12	O/C					
SN:UNKNOWN	HRS	11975.42						
WC#: 33.240	AFL	6299						
PROC. REF: AMM 33-50-37-960-802PROC. REF: AMM 33-50-37-960-802								
33-50-37-960-802-03 DISCARD OF THE EPS BATTERY PACKS - EPS 3 (4LW) BATTERY PACK								Service ATA:33
PN:PN	MOS/MSC	28-Aug-12	O/C					
SN:UNKNOWN	HRS	11975.42						
WC#: 33.250	AFL	6299						
PROC. REF: AMM 33-50-37-960-802PROC. REF: AMM 33-50-37-960-802								
33-50-37-960-802-04 DISCARD OF THE EPS BATTERY PACKS - EPS 4 (20LW) (OPTIONAL) BATTERY PACK								Service ATA:33
PN:PN	MOS/MSC		N/A					
SN:UNKNOWN	HRS							
WC#: 33.130	AFL							
PROC. REF: AMM 33-50-37-960-802PROC. REF: AMM 33-50-37-960-802								
331101 PILOT LIGHTING BOX								Component ATA:33
PN:24-01	MOS/MSC	07-Feb-91	O/C					
SN:1554	HRS	0		TSN 0				
WC#: 33.010	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331111	COPILOT LIGHTING BOX							Component ATA:33
PN:24-01	MOS/MSC	07-Feb-91	O/C					
SN:1555	HRS	0		TSN 0				
WC#: 33.010	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
331161	PILOT READING LIGHT							Component ATA:33
PN:34150-13-305	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.040	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
331171	COPILOT READING LIGHT							Component ATA:33
PN:1309	MOS/MSC	19-Sep-03	O/C					
SN:UNKNOWN	HRS	5853.5		TSN 0				
WC#: 33.040	AFL	2871						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
331181	PILOT FLUORESCENT GLARESHIELD TUBE							Component ATA:33
PN:10-501BA	MOS/MSC	03-Apr-08	O/C	TSR 0				
SN:230	HRS	10415.6		TSR 0				
WC#: 33.050	AFL	5571		TSR 0				
PROC. REF: AMM 33-10-09-960-801PROC. REF: AMM 33-10-09-960-801								
331191	COPILOT FLUORESCENT GLARESHIELD TUBE							Component ATA:33
PN:10-501TD	MOS/MSC	30-Aug-13	O/C	TSN 0				
SN:661001	HRS	12348.5		TSN 0				
WC#: 33.050	AFL	6402		TSN 0				
PROC. REF: AMM 33-10-09-960-801PROC. REF: AMM 33-10-09-960-801								
331201	GLARESHIELD POWER SUPPLY BOX							Component ATA:33
PN:55-0520-4-3	MOS/MSC	07-Feb-91	O/C					
SN:128	HRS	0		TSN 0				
WC#: 33.060	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331211	PILOT LIGHTING INSTRUMENT TRANSFORMER							Component ATA:33
PN:24-54	MOS/MSC	07-Feb-91	O/C					
SN:907	HRS	0		TSN 0				
WC#: 33.070	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
331221	COPILOT LIGHTING INSTRUMENT TRANSFORMER							Component ATA:33
PN:24-54	MOS/MSC	07-Feb-91	O/C					
SN:917	HRS	0		TSN 0				
WC#: 33.070	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
331231	LIGHTING PEDESTAL TRANSFORMER							Component ATA:33
PN:24-57-1	MOS/MSC	07-Feb-91	O/C					
SN:22	HRS	0		TSN 0				
WC#: 33.080	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
331241	OVERHEAD PANEL LIGHTING TRANSFORMER							Component ATA:33
PN:24-014	MOS/MSC	07-Feb-91	O/C					
SN:237	HRS	0		TSN 0				
WC#: 33.080	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
331251	CENTER INSTRUMENT PANEL LIGHTING TRANSFORMER							Component ATA:33
PN:24-54	MOS/MSC	07-Feb-91	O/C					
SN:906	HRS	0		TSN 0				
WC#: 33.070	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
333101	LH REAR COMPARTMENT DOME LIGHT							Component ATA:33
PN:15-0254-3	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.090	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
333111	RH REAR COMPARTMENT DOME LIGHT							Component ATA:33
PN:15-0254-3	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.090	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
333121	BAGGAGE COMPARTMENT DOME LIGHT							Component ATA:33
PN:15-0254-3	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.100	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
333131	BAGGAGE COMPARTMENT SPOT LIGHT							Component ATA:33
PN:32-24	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.100	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
333141	NOSE CONE INSPECTION LIGHT							Component ATA:33
PN:B8550-1-1385	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.110	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334131	LH WING STROBE POWER SUPPLY							Component ATA:33
PN:39-42-4	MOS/MSC	24-Jan-08	O/C	TSO 0				
SN:1196	HRS	10296.4		TSO 0				
WC#: 33.140	AFL	5492		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334141	RH WING STROBE POWER SUPPLY							Component ATA:33
PN:39-42-1	MOS/MSC	01-Oct-04	O/C	TSR 0				
SN:0936	HRS	6887.2		TSR 0				
WC#: 33.150	AFL	3580		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334151	LH WING STROBE LIGHT							Component ATA:33
PN:39-28-21	MOS/MSC	28-Jun-05	O/C		TSR 0			
SN:2337	HRS	7719.3			TSR 0			
WC#: 33.140	AFL	4050			TSR 0			
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334161	RH WING STROBE LIGHT							Component ATA:33
PN:39-28-21	MOS/MSC	14-Mar-01	O/C					
SN:1703	HRS	4661						
WC#: 33.150	AFL	2106						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334171	LH ICE DETECTION SPOT LIGHT							Component ATA:33
PN:30-1361-9	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.160	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334181	RH ICE DETECTION SPOT LIGHT							Component ATA:33
PN:30-1361-10	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.160	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334231	TAXI LIGHT PROXIMITY DETECTOR							Component ATA:33
PN:84739702	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 33.180	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334251	VERTICAL STABILIZER ANTI-COLLISION POWER SUPPLY							Component ATA:33
PN:60-2667-3	MOS/MSC	07-Feb-91	O/C					
SN:2201	HRS	0			TSN 0			
WC#: 33.190	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334271	FUSELAGE ANTI-COLLISION POWER SUPPLY							Component ATA:33
PN:39-44-31	MOS/MSC		O/C					
SN:W196	HRS	1173						
WC#: 33.200	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
334281	FUSELAGE ANTI-COLLISION LIGHT							Component ATA:33
PN:39-59-2	MOS/MSC	31-Mar-14	O/C	TSN 0				
SN:1351	HRS	12625.42		TSN 0				
WC#: 33.200	AFL	6516		TSN 0				
PROC. REF: AMM 33-40-09-960-803PROC. REF: AMM 33-40-09-960-803								
334301	REAR STROBE LIGHT							Component ATA:33
PN:39-54-21R	MOS/MSC	01-Oct-04	O/C	TSR 0				
SN:323	HRS	6887.2		TSR 0				
WC#: 33.210	AFL	3580		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
335151	FORWARD PASSENGER DOOR LIGHT							Component ATA:33
PN:306-03	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.260	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
335161	AFT PASSENGER DOOR LIGHT							Component ATA:33
PN:306-03	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.260	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
335171	EMERGENCY EXIT EXTERIOR LIGHT							Component ATA:33
PN:69202-30100	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:18-08	HRS	10850.2		TSN 0				
WC#: 33.270	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
335181	RH WING EVACUATION LIGHT							Component ATA:33
PN:30-1358-17	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.270	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
ATA 34 - NAVIGATION								
34-01-00-720-801-01	^S	FUNCTIONAL TEST OF THE EFIS SYSTEM						Service ATA:34
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3	1600 (+40)					
	AFL	7304						
PROC. REF: AMM 34-01-00-720-801PROC. REF: AMM 34-01-00-720-801								
34-01-13-900-801-01	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EADI 1 (L12FV)							Component ATA:34
PN:7003110-901	MOS/MSC	27-May-11	O/C					
SN:90054765	HRS	11414.25						
WC#: 34.170	AFL	6044						
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-13-900-801-02	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EHSI 1 (L22FV)							Component ATA:34
PN:7003110-901	MOS/MSC	27-May-11	O/C					
SN:87082251	HRS	11414.25						
WC#: 34.170	AFL	6044						
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-13-900-801-03	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EADI 2 (R12FV)							Component ATA:34
PN:7003110-901	MOS/MSC	28-Aug-12	O/C	TSR 0				
SN:89023297	HRS	11975.42		TSR 0				
WC#: 34.180	AFL	6299		TSR 0				
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-13-900-801-04	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EHSI 2 (R22FV)							Component ATA:34
PN:7003110	MOS/MSC	10-Jul-08	O/C					
SN:89013203	HRS	10594.9						
WC#: 34.180	AFL	5693						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-13-900-801-05	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD (62FV)							Component ATA:34
PN:7003110-901	MOS/MSC	02-Jul-08	O/C					
SN:90014229	HRS	10575.6						
WC#: 34.190	AFL	5683						
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-25-710-801-01	^S	OPERATIONAL TEST OF THE EFIS FANS						Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 34.020	AFL	6741						
PKG:21								
PROC. REF: AMM 34-01-25-710-801PROC. REF: AMM 34-01-25-710-801								
34-10-00-720-801-01	^S	FUNCTIONAL TEST OF THE AIR DATA SYSTEM						Service ATA:34
	MOS	17-Feb-26	24 (+1m)					RVSM
	HRS	13885.3						
WC#: 34.045	AFL	7304						
PKG:16								
PROC. REF: AMM 34-10-00-720-801PROC. REF: AMM 34-10-00-720-801								
34-10-01-900-801-01	REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE TEMPERATURE PROBE (52FL)							Component ATA:34
PN:102AU1CK	MOS/MSC	31-Mar-14	O/C	TSN 0				
SN:B12962	HRS	12625.42		TSN 0				
WC#: 34.090	AFL	6516		TSN 0				
PROC. REF: AMM 34-10-01-900-801PROC. REF: AMM 34-10-01-900-801								
34-10-11-720-801-01	^S	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - LH AOA SENSOR (L11CM)						Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.480	AFL	6741						
PKG:21								
PROC. REF: AMM 34-10-11-720-801PROC. REF: AMM 34-10-11-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-10-11-720-801-02	^S	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - RH AOA SENSOR (R11CM)						Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 27.480	AFL	6741						
PROC. REF: AMM 34-10-11-720-801PROC. REF: AMM 34-10-11-720-801								PKG:21
34-10-11-900-801-01		REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - LH AOA SENSOR (L11CM)						Component ATA:34
PN:861CAU2	MOS/MSC	12-Jun-09	O/C					
SN:1684A	HRS	10850.2						
WC#: 27.480	AFL	5878						
PROC. REF: AMM 34-10-11-900-801PROC. REF: AMM 34-10-11-900-801								
34-10-11-900-801-02		REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - RH AOA SENSOR (R11CM)						Component ATA:34
PN:861CAU2	MOS/MSC	12-Jun-09	O/C					
SN:1056A	HRS	10850.2						
WC#: 27.480	AFL	5878						
PROC. REF: AMM 34-10-11-900-801PROC. REF: AMM 34-10-11-900-801								
34-11-00-680-802-01	^S	DRAINING OF THE STAND-BY PITOT / STATIC PRESSURE SYSTEM						Service ATA:34
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 34-11-00-680-802PROC. REF: AMM 34-11-00-680-802								PKG:16
34-11-00-790-801-01		LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT STATIC AIR PRESSURE SYSTEM						Service ATA:34
	MOS/MSC	03-Mar-21	O/C					
	HRS	13260.28						
	AFL	6735						
PROC. REF: AMM 34-11-00-790-801, FAR 91.411PROC. REF: AMM 34-11-00-790-801, FAR 91.411								
34-11-00-790-801-02		LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT TOTAL AIR PRESSURE SYSTEM						Service ATA:34
	MOS/MSC	03-Mar-21	O/C					
	HRS	13260.28						
	AFL	6735						
PROC. REF: AMM 34-11-00-790-801PROC. REF: AMM 34-11-00-790-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-790-801-03 LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT STATIC AIR PRESSURE SYSTEM Service ATA:34								
	MOS/MSC	03-Mar-21	O/C					
	HRS	13260.28						
	AFL	6735						
PROC. REF: AMM 34-11-00-790-801, FAR 91.411PROC. REF: AMM 34-11-00-790-801, FAR 91.411								
34-11-00-790-801-04 LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT TOTAL AIR PRESSURE SYSTEM Service ATA:34								
	MOS/MSC	31-Mar-14	O/C					
	HRS	12625.42						
	AFL	6516						
PROC. REF: AMM 34-11-00-790-801PROC. REF: AMM 34-11-00-790-801								
34-11-00-790-801-05 LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - STAND-BY STATIC AIR PRESSURE SYSTEMS Service ATA:34								
	MOS/MSC	31-Mar-14	O/C					
	HRS	12625.42						
	AFL	6516						
PROC. REF: AMM 34-11-00-790-801, FAR 91.411PROC. REF: AMM 34-11-00-790-801, FAR 91.411								
34-11-00-790-801-06 LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - STAND-BY TOTAL AIR PRESSURE SYSTEMS Service ATA:34								
	MOS/MSC	03-Mar-21	O/C					
	HRS	13260.28						
	AFL	6735						
PROC. REF: AMM 34-11-00-790-801PROC. REF: AMM 34-11-00-790-801								
34-11-01-200-801-01 CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - LH TOTAL PRESSURE PROBE (L4FL) Service ATA:34								
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
	AFL	6673						
PROC. REF: AMM 34-11-01-200-801PROC. REF: AMM 34-11-01-200-801								
34-11-01-200-801-02 CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - RH TOTAL PRESSURE PROBE (R4FL) Service ATA:34								
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
	AFL	6673						
PROC. REF: AMM 34-11-01-200-801PROC. REF: AMM 34-11-01-200-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-01-200-801-03	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - STAND-BY TOTAL PRESSURE PROBE (24FL)							Service ATA:34
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
	AFL	6673						
PROC. REF: AMM 34-11-01-200-801PROC. REF: AMM 34-11-01-200-801								
34-11-01-900-801-01	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - LH TOTAL PRESSURE PROBE (L4FL)							Component ATA:34
PN:50520	MOS/MSC	07-Feb-91	O/C					
SN:395	HRS	0		TSN 0				
WC#: 34.080	AFL	0						
PROC. REF: AMM 34-11-01-900-801PROC. REF: AMM 34-11-01-900-801								
34-11-01-900-801-02	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - RH TOTAL PRESSURE PROBE (R4FL)							Component ATA:34
PN:50520	MOS/MSC	07-Feb-91	O/C					
SN:396	HRS	0		TSN 0				
WC#: 34.080	AFL	0						
PROC. REF: AMM 34-11-01-900-801PROC. REF: AMM 34-11-01-900-801								
34-11-01-900-801-03	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - STAND-BY TOTAL PRESSURE PROBE (24FL)							Component ATA:34
PN:50520	MOS/MSC	07-Feb-91	O/C					
SN:305	HRS	0		TSN 0				
WC#: 34.080	AFL	0						
PROC. REF: AMM 34-11-01-900-801PROC. REF: AMM 34-11-01-900-801								
34-11-05-900-801-01	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (L13FL)							Component ATA:34
PN:49800-01	MOS/MSC	19-Dec-21	O/C					
SN:1994	HRS	13275.5						
WC#: 34.060	AFL	6741						
PROC. REF: AMM 34-11-05-900-801PROC. REF: AMM 34-11-05-900-801								
34-11-05-900-801-02	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (R13FL)							Component ATA:34
PN:49800-01	MOS/MSC	19-Dec-21	O/C					
SN:2410	HRS	13275.5						
WC#: 34.060	AFL	6741						
PROC. REF: AMM 34-11-05-900-801PROC. REF: AMM 34-11-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-05-900-802-01		REMOVAL / INSTALLATION OF THE STAND-BY STATIC PRESSURE PROBES - STAND-BY STATIC PRESSURE PROBE (L501FL)						Component ATA:34
PN:MY20210-10-1	MOS/MSC	06-Nov-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10860.17		TSN 0				
WC#: 34.070	AFL	5883		TSN 0				
PROC. REF: AMM 34-11-05-900-802PROC. REF: AMM 34-11-05-900-802								
34-11-05-900-802-02		REMOVAL / INSTALLATION OF THE STAND-BY STATIC PRESSURE PROBES - STAND-BY STATIC PRESSURE PROBE (R501FL)						Component ATA:34
PN:MY20210-10-1	MOS/MSC	06-Nov-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10860.17		TSN 0				
WC#: 34.070	AFL	5883		TSN 0				
PROC. REF: AMM 34-11-05-900-802PROC. REF: AMM 34-11-05-900-802								
34-14-01-700-881-01		TEST NO. 1 AIR DATA (ADC1) COMPUTER (FAR 91.411)						Service ATA:34
PN:7000700-647	MOS	28-Mar-25	24		28-Mar-27		338 d	MANDATORY
SN:92045266	HRS	13812						
	AFL	7225						
Calibration Date: : 28-Mar-25								
PROC. REF: AMM GENERIC 2, FAR 91.411PROC. REF: AMM GENERIC 2, FAR 91.411								
34-14-01-700-881-02		TEST NO. 2 AIR DATA (ADC 2) COMPUTER (FAR 91.411)						Service ATA:34
PN:7000700-647	MOS	28-Mar-25	24		28-Mar-27		338 d	MANDATORY
SN:86121905	HRS	13812						
	AFL	7225						
Calibration Date: : 28-Mar-25								
PROC. REF: AMM GENERIC 2, FAR 91.411PROC. REF: AMM GENERIC 2, FAR 91.411								
34-14-01-900-801-01		REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 1 (L2FX)						Component ATA:34
PN:7000700-647	MOS/MSC	28-Mar-25	O/C					
SN:92045266	HRS	13812						
	AFL	7225						
PROC. REF: AMM 34-14-01-900-801PROC. REF: AMM 34-14-01-900-801								
34-14-01-900-801-02		REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 2 (R2FX)						Component ATA:34
PN:7000700-647	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:86121905	HRS	10850.2		TSR 0				
	AFL	5878		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-14-01-900-801PROC. REF: AMM 34-14-01-900-801								
34-15-01-700-881-01	TEST PILOT ALTIMETER (FAR 91.411)							Service ATA:34
PN:4016341-904	MOS	28-Mar-25	24		28-Mar-27		338 d	MANDATORY
SN:89095693	HRS	13812						
WC#: 34.100	AFL	7225						
Calibration Date: : 28-Mar-25								
PROC. REF: AMM GENERIC 2, FAR 91.411PROC. REF: AMM GENERIC 2, FAR 91.411								
34-15-01-700-881-02	TEST COPILOT ALTIMETER (FAR 91.411)							Service ATA:34
PN:4016341-904	MOS	28-Mar-25	24		28-Mar-27		338 d	MANDATORY
SN:85103873	HRS	13812						
WC#: 34.100	AFL	7225						
Calibration Date: : 28-Mar-25								
PROC. REF: AMM GENERIC 2, FAR 91.411PROC. REF: AMM GENERIC 2, FAR 91.411								
34-15-02-700-881-01	TEST PILOT STAND-BY ALTIMETER (FAR 91.411)							Service ATA:34
PN:64141-530-1	MOS	28-Mar-25	24		28-Mar-27		338 d	MANDATORY
SN:3738	HRS	13812						
WC#: 34.110	AFL	7225						
Calibration Date: : 28-Mar-25								
PROC. REF: AMM GENERIC 2, FAR 91.411PROC. REF: AMM GENERIC 2, FAR 91.411								
34-16-00-720-801-01	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 1 (L2FX)							Service ATA:34
PN:7000700-647	MOS	28-Mar-25	24 (+3%)		28-Mar-27	19-Apr-27	338 d (+22)	RVSM
SN:92045266	HRS	13812						
	AFL	7225						
PROC. REF: AMM 34-16-00-720-801PROC. REF: AMM 34-16-00-720-801								
34-16-00-720-801-02	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 2 (R2FX)							Service ATA:34
PN:7000700-647	MOS	28-Mar-25	24 (+3%)		28-Mar-27	19-Apr-27	338 d (+22)	RVSM
SN:86121905	HRS	13812						
	AFL	7225						
PROC. REF: AMM 34-16-00-720-801PROC. REF: AMM 34-16-00-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-16-00-720-801-03	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY ALTIMETER (1FK)							Service ATA:34
PN:64141-530-1	MOS	28-Mar-25	24 (+3%)		28-Mar-27	19-Apr-27	338 d (+22)	RVSM
SN:3738	HRS	13812						
WC#: 34.110	AFL	7225						
PROC. REF: AMM 34-16-00-720-801PROC. REF: AMM 34-16-00-720-801								
34-16-00-720-801-04	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY MACH AIRSPEED INDICATOR (26FL)							Service ATA:34
PN:64032-229-1	MOS	24-Apr-25	24 (+3%)		24-Apr-27	15-May-27	365 d (+21)	RVSM
SN:1358	HRS	13836.2						
WC#: 34.140	AFL	7249						
PROC. REF: AMM 34-16-00-720-801PROC. REF: AMM 34-16-00-720-801								
34-21-00-700-801-01 ^S	CHECK OF THE ARINC 429 LINES TO THE INERTIAL REFERENCE SYSTEM (IRS)							Service ATA:34
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 34.150	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 34-21-00-700-801PROC. REF: AMM 34-21-00-700-801								
34-21-00-710-801-01 ^S	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 1 (L2FP)							Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 34.310	AFL	6741						
								PKG:21
PROC. REF: AMM 34-21-00-710-801PROC. REF: AMM 34-21-00-710-801								
34-21-00-710-801-02 ^S	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 2 (R2FP)							Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 34.310	AFL	6741						
								PKG:21
PROC. REF: AMM 34-21-00-710-801PROC. REF: AMM 34-21-00-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-21-00-710-801-03	^S	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 3 (22FP) (OPTION)						Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 34.312	AFL	6741						
PROC. REF: AMM 34-21-00-710-801PROC. REF: AMM 34-21-00-710-801								PKG:22
34-21-01-900-801-01		REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) - IRU 1 (L2FP)						Component ATA:34
PN:HG1075AE03	MOS/MSC	10-Apr-13	O/C	TSR 4				
SN:609	HRS							
WC#: 34.310	AFL							
PROC. REF: AMM 34-21-01-900-801PROC. REF: AMM 34-21-01-900-801								
34-21-01-900-801-02		REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) - IRU 2 (R2FP)						Component ATA:34
PN:HG1075AE04	MOS/MSC		O/C					
SN:2038	HRS	2133						
WC#: 34.310	AFL							
PROC. REF: AMM 34-21-01-900-801PROC. REF: AMM 34-21-01-900-801								
34-21-01-900-801-03		REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) - IRU 3 (22FP)						Component ATA:34
PN:HG1075AE03	MOS/MSC	03-May-06	O/C					
SN:870	HRS	8676						
WC#: 34.312	AFL	4586						
PROC. REF: AMM 34-21-01-900-801PROC. REF: AMM 34-21-01-900-801								
34-21-13-100-801-01	^S	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 1 (L2FP) FAN FILTER						Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 34.380	AFL	6741						
PROC. REF: AMM 34-21-13-100-801PROC. REF: AMM 34-21-13-100-801								PKG:22
34-21-13-100-801-02	^S	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 2 (R2FP) FAN FILTER						Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 34.380	AFL	6741						
								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-21-13-100-801PROC. REF: AMM 34-21-13-100-801								
34-21-13-100-801-03	^S	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 3 (22FP) FAN FILTER (OPTION)						Service ATA:34
	MOS	19-Dec-21						
	HRS	13275.5	3200 (+40)					
WC#: 34.385	AFL	6741						
PROC. REF: AMM 34-21-13-100-801PROC. REF: AMM 34-21-13-100-801								
34-23-00-900-801-01		REMOVAL / INSTALLATION OF THE STAND-BY HORIZON - STAND-BY HORIZON (6FG)						Component ATA:34
PN:H200AKM	MOS/MSC	07-May-02	O/C	TSR 0				
SN:5676	HRS	5264.5		TSR 0				
WC#: 34.250	AFL	2445		TSR 0				
PROC. REF: AMM 34-23-00-900-801PROC. REF: AMM 34-23-00-900-801								
34-25-00-820-801-01		COMPENSATION OF STAND-BY COMPASS - STAND-BY COMPASS (42FL)						Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-25-00-820-801PROC. REF: AMM 34-25-00-820-801								
34-41-01-900-801-01		REMOVAL / INSTALLATION OF THE WEATHER RADAR RECEIVER / TRANSMITTER / ANTENNA ASSEMBLY - RADAR ANTENNA (3SQ)						Component ATA:34
PN:7012640-922	MOS/MSC	03-Sep-10	O/C	TSR 0				
SN:90020517	HRS	11012.17		TSR 0				
	AFL	5930		TSR 0				
PROC. REF: AMM 34-41-01-900-801PROC. REF: AMM 34-41-01-900-801								
34-42-01-820-801-01		CALIBRATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 1 RECEIVER/TRANSMITTER (2SA) WITH CABLE						Service ATA:34
PN:7001840-932	MOS/MSC	20-Feb-13	O/C					
SN:88594	HRS							
WC#: 34.340	AFL							
Calibration Date: : 20-Feb-13								
PROC. REF: AMM 34-42-01-820-801PROC. REF: AMM 34-42-01-820-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-42-01-820-801-02	CALIBRATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 2 RECEIVER/TRANSMITTER (22SA) WITH CABLE							Service ATA:34
PN:7001840-922	MOS/MSC	31-Mar-14	O/C					
SN:91013772	HRS	12625.42						
WC#: 34.340	AFL	6516						
Calibration Date: : 31-Mar-14								
PROC. REF: AMM 34-42-01-820-801PROC. REF: AMM 34-42-01-820-801								
34-42-01-900-801-01	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 1 RECEIVER/TRANSMITTER (2SA)							Component ATA:34
PN:7001840-932	MOS/MSC	05-Jun-13	O/C	TSR 4				
SN:88594	HRS	12205.82						
WC#: 34.340	AFL	6354						
PROC. REF: AMM 34-42-01-900-801PROC. REF: AMM 34-42-01-900-801								
34-42-01-900-801-02	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 2 RECEIVER/TRANSMITTER (22SA)							Component ATA:34
PN:7001840-922	MOS/MSC	09-Mar-12	O/C	TSR 18				
SN:91013772	HRS	11749.08		TSR 736.92				
WC#: 34.340	AFL	6227		TSR 297				
PROC. REF: AMM 34-42-01-900-801PROC. REF: AMM 34-42-01-900-801								
34-42-09-900-801-01	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 TRANSMITTER ANTENNA (3SA)							Component ATA:34
PN:S67-2002-13	MOS/MSC		O/C					
SN:1450	HRS	4062						
WC#: 34.350	AFL							
PROC. REF: AMM 34-42-09-900-801PROC. REF: AMM 34-42-09-900-801								
34-42-09-900-801-02	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 RECEIVER ANTENNA (4SA)							Component ATA:34
PN:S67-2002-13	MOS/MSC	07-Feb-91	O/C					
SN:352	HRS	0		TSN 0				
WC#: 34.350	AFL	0						
PROC. REF: AMM 34-42-09-900-801PROC. REF: AMM 34-42-09-900-801								
34-42-09-900-801-03	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 2 TRANSMITTER ANTENNA (23SA)							Component ATA:34
PN:S67-2002-13	MOS/MSC	07-Feb-91	O/C					
SN:353	HRS	0		TSN 0				
WC#: 34.355	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-42-09-900-801PROC. REF: AMM 34-42-09-900-801								
34-42-09-900-801-04 REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 2 RECEIVER ANTENNA (24SA)								Component ATA:34
PN:S67-2002-13	MOS/MSC		O/C					
SN:444	HRS	2502		TSN 0				
WC#: 34.355	AFL							
PROC. REF: AMM 34-42-09-900-801PROC. REF: AMM 34-42-09-900-801								
34-51-00-710-801-01 OPERATIONAL TEST OF THE VOR NAVIGATION SYSTEM								Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-51-00-710-801PROC. REF: AMM 34-51-00-710-801								
34-51-01-820-801-01 CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 1 RECEIVER (L3RS)								Service ATA:34
PN:622-6137-201	MOS/MSC	31-Mar-14	O/C					
SN:3732	HRS	12625.42						
WC#: 34.430	AFL	6516						
Calibration Date: : 31-Mar-14								
PROC. REF: AMM 34-51-01-820-801PROC. REF: AMM 34-51-01-820-801								
34-51-01-820-801-02 CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 2 RECEIVER (R3RS)								Service ATA:34
PN:622-6137-201	MOS/MSC	31-Mar-14	O/C					
SN:14403	HRS	12625.42						
WC#: 34.430	AFL	6516						
Calibration Date: : 31-Mar-14								
PROC. REF: AMM 34-51-01-820-801PROC. REF: AMM 34-51-01-820-801								
34-51-05-900-801-01 REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - VOR/LOC ANTENNA (5RS) - LH								Component ATA:34
PN:DMN4-45-3	MOS/MSC	17-Dec-21	O/C					
SN:12626	HRS	13275.5						
WC#: 34.440	AFL	6741						
PROC. REF: AMM 34-51-05-900-801PROC. REF: AMM 34-51-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-51-05-900-801-02	REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - VOR/LOC ANTENNA (5RS) - RH							Component ATA:34
PN:DMN4-45-3	MOS/MSC	17-Dec-21	O/C					
SN:12903	HRS	13275.5						
WC#: 34.440	AFL	6741						
PROC. REF: AMM 34-51-05-900-801PROC. REF: AMM 34-51-05-900-801								
34-51-17-900-801-01	REMOVAL / INSTALLATION OF THE MARKER ANTENNA - MARKER ANTENNA (8RS) .							Component ATA:34
PN:S35-100-1	MOS/MSC	17-Dec-21	O/C					
SN:101-8082	HRS	13275.5						
WC#: 34.280	AFL	6741						
PROC. REF: AMM 34-51-17-900-801PROC. REF: AMM 34-51-17-900-801								
34-51-20-710-801-01	OPERATIONAL TEST OF THE INSTRUMENT LANDING SYSTEM (ILS)							Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-51-20-710-801PROC. REF: AMM 34-51-20-710-801								
34-51-40-710-801-01	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 1 SYSTEM							Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-51-40-710-801PROC. REF: AMM 34-51-40-710-801								
34-51-40-710-801-02	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 2 SYSTEM							Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-51-40-710-801PROC. REF: AMM 34-51-40-710-801								
34-52-00-710-801-01	OPERATIONAL TEST OF THE DISTANCE MEASURING EQUIPMENT (DME) SYSTEM							Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-52-00-710-801PROC. REF: AMM 34-52-00-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-52-05-900-801-01	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 1 ANTENNA (L4RV)							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Dec-21	O/C					
SN:136890	HRS	13275.5						
WC#: 34.460	AFL	6741						
PROC. REF: AMM 34-52-05-900-801PROC. REF: AMM 34-52-05-900-801								
34-52-05-900-801-02	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 2 ANTENNA (R4RV)							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Dec-21	O/C					
SN:136889	HRS	13275.5						
WC#: 34.460	AFL	6741						
PROC. REF: AMM 34-52-05-900-801PROC. REF: AMM 34-52-05-900-801								
34-53-00-710-801-01	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 1 SYSTEM							Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-53-00-710-801PROC. REF: AMM 34-53-00-710-801								
34-53-00-710-801-02	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 2 SYSTEM							Service ATA:34
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-53-00-710-801PROC. REF: AMM 34-53-00-710-801								
34-54-00-700-881-01	TEST NO. 1 ATC TRANSPONDER (FAR 91.413)							Service ATA:34
PN:622-9210-501	MOS	28-Mar-25	24		28-Mar-27		338 d	MANDATORY
SN:1YHB	HRS	13812						
WC#: 34.480	AFL	7225						
Calibration Date: : 28-Mar-25								
PROC. REF: AMM GENERIC 2, FAR 91.413PROC. REF: AMM GENERIC 2, FAR 91.413								
34-54-00-700-881-02	TEST NO. 2 ATC TRANSPONDER (FAR 91.413)							Service ATA:34
PN:622-9210-501	MOS	28-Mar-25	24		28-Mar-27		338 d	MANDATORY
SN:208XG	HRS	13812						
WC#: 34.490	AFL	7225						
Calibration Date: : 28-Mar-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM GENERIC 2, FAR 91.413PROC. REF: AMM GENERIC 2, FAR 91.413								
34-54-00-720-802-01FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM PERIODIC TESTS								Service ATA:34
PN:622-9210-501	MOS	28-Mar-25	24 (+3%)		28-Mar-27	19-Apr-27	338 d (+22)	
SN:1YHB	HRS	13812						
WC#: 34.480	AFL	7225						
PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802								
34-54-00-720-802-02FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM PERIODIC TESTS								Service ATA:34
PN:622-9210-501	MOS	28-Mar-25	24 (+3%)		28-Mar-27	19-Apr-27	338 d (+22)	
SN:208XG	HRS	13812						
WC#: 34.490	AFL	7225						
PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802								
34-54-05-900-801-01REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 1 LOWER ANTENNA (L5SH)								Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Dec-21	O/C					
SN:133850	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 34-54-05-900-801PROC. REF: AMM 34-54-05-900-801								
34-54-05-900-801-02REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 1 UPPER ANTENNA (L9SH)								Component ATA:34
PN:DMNI50-2-2	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:116460	HRS	10850.2		TSN 0				
WC#: 34.500	AFL	5878		TSN 0				
PROC. REF: AMM 34-54-05-900-801PROC. REF: AMM 34-54-05-900-801								
34-54-05-900-801-03REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 2 LOWER ANTENNA (R5SH)								Component ATA:34
PN:DMNI50-2-2	MOS/MSC	17-Dec-21	O/C					
SN:133853	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 34-54-05-900-801PROC. REF: AMM 34-54-05-900-801								
34-54-05-900-801-04REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 2 UPPER ANTENNA (R9SH)								Component ATA:34
PN:DMNI50-2-2	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:116449	HRS	10850.2		TSN 0				
WC#: 34.500	AFL	5878		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-54-05-900-801PROC. REF: AMM 34-54-05-900-801								
34-58-01-710-881-01	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)							Service ATA:34
	DAYS	27-Mar-26	30		26-Apr-26		2 d	MANDATORY
	HRS	13896.3						
WC#: 34.445	AFL	7313						
PROC. REF: AMM GENERIC 2, FAR 91.171PROC. REF: AMM GENERIC 2, FAR 91.171								
34-61-00-710-801-01	OPERATIONAL TEST OF THE FLIGHT MANAGEMENT SYSTEM (FMS) - PILOT FMS							Service ATA:34
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 34.240	AFL	6673						
PROC. REF: AMM 34-61-00-710-801PROC. REF: AMM 34-61-00-710-801								
34-61-00-710-801-02	OPERATIONAL TEST OF THE FLIGHT MANAGEMENT SYSTEM (FMS) - COPILOT FMS							Service ATA:34
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 34.240	AFL	6673						
PROC. REF: AMM 34-61-00-710-801PROC. REF: AMM 34-61-00-710-801								
34-61-01-900-803-01	REMOVAL / INSTALLATION OF THE DATA MANAGEMENT UNIT (DMU) - DMU COMPUTER (22RJ)							Component ATA:34
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-01-900-803PROC. REF: AMM 34-61-01-900-803								
34-61-07-900-801-01	REMOVAL / INSTALLATION OF THE FMS CDU - CDU 1 (L12RJ)							Component ATA:34
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-07-900-801PROC. REF: AMM 34-61-07-900-801								
34-61-07-900-801-02	REMOVAL / INSTALLATION OF THE FMS CDU - CDU 2 (R12RJ)							Component ATA:34
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-61-07-900-801PROC. REF: AMM 34-61-07-900-801								
3400A1 ^U	EGPWS							Component ATA:34
PN:965-0976-040-212-212	MOS/MSC	28-Oct-04	O/C	TSN 0				
SN:20730	HRS			TSN 0				
	AFL			TSN 0				
341021	ANGLE OF ATTACK METER COMPUTER							Component ATA:34
PN:910000-543	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.520	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341026	ANGLE OF ATTACK METER PROBE							Component ATA:34
PN:SLZ9164	MOS/MSC	07-Feb-91	O/C					
SN:A131749G	HRS	0		TSN 0				
WC#: 34.530	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341031	ANGLE OF ATTACK METER INDICATOR							Component ATA:34
PN:SLZ7725	MOS/MSC	07-Feb-91	O/C					
SN:FB1009C	HRS	0		TSN 0				
WC#: 34.550	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341036	ANGLE OF ATTACK METER CONTROL							Component ATA:34
PN:911001	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.550	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341301	PILOT ALTIMETER							Component ATA:34
PN:4016341-904	MOS/MSC	22-Jul-94	O/C	TSN 0				
SN:89095693	HRS			TSN 0				
WC#: 34.100	AFL			TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341321	COPILOT ALTIMETER							Component ATA:34
PN:4016341-904	MOS/MSC	25-Nov-10	O/C	TSR 0				
SN:85103873	HRS	11145.33		TSR 0				
WC#: 34.100	AFL	5961		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341341	PILOT STAND-BY ALTIMETER							Component ATA:34
PN:64141-530-1	MOS/MSC	28-Mar-25	O/C					
SN:3738	HRS	13812						
WC#: 34.110	AFL	7225						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341401	PILOT VERTICAL SPEED INDICATOR							Component ATA:34
PN:622-9728-324	MOS/MSC	17-Nov-05	O/C					
SN:2467	HRS	8205.2						
WC#: 34.120	AFL	4306						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341421	COPILOT VERTICAL SPEED INDICATOR							Component ATA:34
PN:622-9728-324	MOS/MSC	27-May-11	O/C	TSR 0				
SN:1D7TJ	HRS	11414.25		TSR 0				
WC#: 34.120	AFL	6044		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341441	PILOT MACH-AIRSPEED INDICATOR							Component ATA:34
PN:4018366-902	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.130	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341461	COPILOT MACH-AIRSPEED INDICATOR							Component ATA:34
PN:4018366-902	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.130	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
341481	STAND-BY MACH-AIRSPEED INDICATOR							Component ATA:34
PN:64032-229-1	MOS/MSC	15-Sep-08	O/C	TSR 0				
SN:1358	HRS	10699.1		TSR 0				
WC#: 34.140	AFL	5771		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342101	PILOT DDRMI INDICATOR							Component ATA:34
PN:63540-250-2	MOS/MSC	31-Oct-93	O/C	TSN 0				
SN:1470	HRS			TSN 0				
WC#: 34.160	AFL			TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342121	COPILOT DDRMI INDICATOR							Component ATA:34
PN:63540-250-2	MOS/MSC		O/C					
SN:W880	HRS							
WC#: 34.160	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342301	PILOT PROCESSOR DISPLAY UNIT							Component ATA:34
PN:7007356-906	MOS/MSC	17-Dec-21	O/C					
SN:9006357	HRS	13275.5						
WC#: 34.200	AFL	6741						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342321	COPILOT PROCESSOR DISPLAY UNIT							Component ATA:34
PN:7007356-905	MOS/MSC	05-Jun-13	O/C					
SN:86080145	HRS	12205.82						
WC#: 34.200	AFL	6354						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342341	PILOT CONTROL DISPLAY PANEL							Component ATA:34
PN:7007277-901	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:86110148	HRS	10850.2		TSR 0				
WC#: 34.210	AFL	5878		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342361	COPILOT CONTROL DISPLAY PANEL							Component ATA:34
PN:7007277-901	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:89120320	HRS	10850.2		TSN 10850.2, TSR 0				
WC#: 34.210	AFL	5878		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342381	PILOT SWITCH REVERSION PANEL							Component ATA:34
PN:7007280-901	MOS/MSC	02-Jul-08	O/C					
SN:89110314	HRS	10575.6						
WC#: 34.220	AFL	5683						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342391	COPILOT SWITCH REVERSION PANEL							Component ATA:34
PN:7007280-901	MOS/MSC	02-Jul-08	O/C					
SN:89126316	HRS	10575.6						
WC#: 34.220	AFL	5683						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342451	REMOTE CONTROL DISPLAY PANEL							Component ATA:34
PN:AI-RC1-170450	MOS/MSC	26-Jun-09	O/C					
SN:010100028	HRS	10850.33						
WC#: 34.245	AFL	5878						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342541	STAND-BY COMPASS							Component ATA:34
PN:KCA0105W	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:AZ1060607	HRS	10850.2		TSN 0				
WC#: 34.270	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342601	EFIS 1 BLOWER							Component ATA:34
PN:030002	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.275	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342611	EFIS 2 BLOWER							Component ATA:34
PN:030002	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.275	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
342751	EFIS CONTROL							Component ATA:34
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.590	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
343101	GLIDE NO. 1/ NO. 2 ANTENNA							Component ATA:34
PN:DMN25-2	MOS/MSC	07-Feb-91	O/C					
SN:2672	HRS	0		TSN 0				
WC#: 34.280	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344051	MULTIFUNCTION DISPLAY PROCESSOR UNIT							Component ATA:34
PN:7009289-805	MOS/MSC	23-Dec-04	O/C	TSR 0				
SN:90100225	HRS	7075.5		TSR 0				
WC#: 34.285	AFL	3700		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344061	MULTIFUNCTION DISPLAY CONTROL							Component ATA:34
PN:7007062-803	MOS/MSC		O/C					
SN:90010696	HRS							
WC#: 34.285	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
344141	PILOT RADAR CONTROL							Component ATA:34
PN:7006921-301	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.300	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344151	COPILOT RADAR CONTROL							Component ATA:34
PN:7006921-301	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.300	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344156	MLS ANTENNA							Component ATA:34
PN:810001-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.410	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344241	INTERTIAL SYSTEM DISPLAY UNIT							Component ATA:34
PN:CG1230AC10	MOS/MSC	27-Jan-06	O/C					
SN:019	HRS	8376.7						
WC#: 34.315	AFL	4401						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344261	NO. 1 MODE SELECTOR UNIT							Component ATA:34
PN:CG1042AB03	MOS/MSC	22-Nov-07	O/C					
SN:455	HRS	10138.1						
WC#: 34.320	AFL	5422						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344281	NO. 2 MODE SELECTOR UNIT							Component ATA:34
PN:CG1042AB03	MOS/MSC	04-May-07	O/C					
SN:946	HRS	9577.2						
WC#: 34.320	AFL	5083						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
344301	NO. 3 MODE SELECTOR UNIT							Component ATA:34
PN:CG1042AB03	MOS/MSC		O/C					
SN:850	HRS	3817						
WC#: 34.320	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344441	NO. 1 IRU BLOWER							Component ATA:34
PN:10089782-105	MOS/MSC	28-May-11	O/C		TSN 0			
SN:9851	HRS	11414.25			TSN 0			
WC#: 34.380	AFL	6044			TSN 0			
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344461	NO. 2 IRU BLOWER							Component ATA:34
PN:10089782-105	MOS/MSC	07-Feb-91	O/C					
SN:PH9016	HRS	0			TSN 0			
WC#: 34.380	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
344481	NO. 3 IRU BLOWER							Component ATA:34
PN:10089782-105	MOS/MSC	07-Feb-91	O/C					
SN:TA5305	HRS	0			TSN 0			
WC#: 34.385	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345101	NO. 1 ADF CONTROL							Component ATA:34
PN:622-6522-005	MOS/MSC	31-Mar-14	O/C		TSO 0			
SN:8612	HRS	12625.42			TSO 0			
WC#: 34.390	AFL	6516			TSO 0			
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345111	NO. 2 ADF CONTROL							Component ATA:34
PN:622-6522-005	MOS/MSC	26-Nov-14	O/C					
SN:7899	HRS	13029.05						
WC#: 34.390	AFL	6673						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345121	NO. 1 ADF RECEIVER							Component ATA:34
PN:622-2873-001	MOS/MSC	07-Feb-91	O/C					
SN:757	HRS	0		TSN 0				
WC#: 34.400	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345131	NO. 2 ADF RECEIVER							Component ATA:34
PN:622-2873-001	MOS/MSC	07-Feb-91	O/C					
SN:730	HRS	0		TSN 0				
WC#: 34.400	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345141	NO. 1 ADF LOOP ANTENNA							Component ATA:34
PN:622-2363-001	MOS/MSC	07-Feb-91	O/C					
SN:24617	HRS	0		TSN 0				
WC#: 34.410	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345151	NO. 2 ADF LOOP ANTENNA							Component ATA:34
PN:622-2363-001	MOS/MSC	07-Feb-91	O/C					
SN:24619	HRS	0		TSN 0				
WC#: 34.410	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345201	NO. 1 VOR/DME CONTROL							Component ATA:34
PN:622-6521-013	MOS/MSC	12-Jun-09	O/C	TSR 0				
SN:9250	HRS	10850.2		TSR 0				
WC#: 34.420	AFL	5878		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345211	NO. 2 VOR/DME CONTROL							Component ATA:34
PN:622-6521-013	MOS/MSC	31-Mar-14	O/C	TSO 0				
SN:13543	HRS	12625.42		TSO 0				
WC#: 34.420	AFL	6516		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345221	NO. 1 VOR/ILS/MARKER RECEIVER							Component ATA:34
PN:622-6137-201	MOS/MSC	07-Sep-07	O/C					
SN:3732	HRS	9970.3						
WC#: 34.430	AFL	5326						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345231	NO. 2 VOR/ILS/MARKER RECEIVER							Component ATA:34
PN:622-6137-201	MOS/MSC	07-Sep-07	O/C					
SN:14403	HRS	9970.3						
WC#: 34.430	AFL	5326						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345301	NO. 1 DME TRANSCEIVER							Component ATA:34
PN:622-6263-003	MOS/MSC	11-Feb-12	O/C					
SN:8052	HRS	11716.5						
WC#: 34.450	AFL	6216						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345311	NO. 2 DME TRANSCEIVER							Component ATA:34
PN:622-6263-003	MOS/MSC	16-Jan-09	O/C	TSO 0				
SN:263	HRS	10823		TSO 0				
WC#: 34.450	AFL	5854		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345401	NO. 1 ATC CONTROL							Component ATA:34
PN:622-6523-001	MOS/MSC	07-Feb-91	O/C					
SN:2715	HRS	0		TSN 0				
WC#: 34.470	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345411	NO. 2 ATC CONTROL							Component ATA:34
PN:622-6523-001	MOS/MSC		O/C					
SN:8123	HRS	3250						
WC#: 34.470	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345421	NO. 1 ATC TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	28-Mar-25	O/C					
SN:1YHB	HRS	13812						
WC#: 34.480	AFL	7225						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345431	NO. 2 ATC TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	28-Mar-25	O/C					
SN:208XG	HRS	13812						
WC#: 34.490	AFL	7225						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345461	NO. 1 ADF ADAPTER							Component ATA:34
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.600	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345471	NO. 2 ADF ADAPTER							Component ATA:34
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.600	AFL	0		TSN 0				
	APH	0		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345501	VLF/OMEGA RECEIVER/ PROCESSOR UNIT							Component ATA:34
PN:87272054V06	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.510	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345511	VLF/OMEGA ANTENNA							Component ATA:34
PN:87232276V00	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.510	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
345A30 ^U	TCAS PROCESSOR							Component ATA:34
PN:622-8971-122	MOS/MSC	30-Aug-13	O/C					
SN:3589	HRS	12348.5						
	AFL	6402						
346101 ^U	PILOT FMS CONTROL DISPLAY							Component ATA:34
PN:7004403-901	MOS/MSC	27-May-11	O/C	TSR 0				
SN:90100587	HRS	11414.25		TSR 0				
WC#: 34.230	AFL	6044		TSR 0				
346121 ^U	COPILOT FMS CONTROL DISPLAY							Component ATA:34
PN:7004403-901	MOS/MSC	25-Mar-10	O/C					
SN:87090260	HRS	10865.5						
WC#: 34.230	AFL	5891						
346141	PILOT FMS COMPUTER							Component ATA:34
PN:7018879-03014	MOS/MSC	15-Oct-05	O/C	TSR 0				
SN:04084130	HRS	8071.7		TSR 0				
WC#: 34.240	AFL	4261		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
346161	COPILOT FMS COMPUTER							Component ATA:34
PN:7018879-03014	MOS/MSC	15-Oct-05	O/C	TSR 0				
SN:0012625	HRS	8071.7		TSR 0				
WC#: 34.240	AFL	4261		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
346181	FMS DATA LOADER							Component ATA:34
PN:G7226-01	MOS/MSC	04-May-07	O/C	TSN 0				
SN:924	HRS	9577.2		TSN 0				
WC#: 34.230	AFL	5083		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 34 - NAVIGATION

346211	NO. 1 FMS CONFIGURATION MODULE						Component	ATA:34
PN:7014940-903	MOS/MSC	14-Mar-01	O/C					
SN:00104510	HRS	4661						
	AFL	2106						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

346221	NO. 2 FMS CONFIGURATION MODULE						Component	ATA:34
PN:7014940-903	MOS/MSC	14-Mar-01	O/C					
SN:00104513	HRS	4661						
	AFL	2106						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

346A11 ^U	DATA AFIS MANAGEMENT UNIT						Component	ATA:34
PN:400-045500-0005	MOS/MSC	14-Mar-01	O/C					
SN:2743	HRS	4661		TSN 0				
	AFL	2106		TSN 0				

346A15 ^U	CONFIG AFIS MODULE						Component	ATA:34
PN:31990-1	MOS/MSC	14-Mar-01	O/C					
SN:9782	HRS	4661		TSN 0				
	AFL	2106		TSN 0				

ATA 35 - OXYGEN

35-10-05-350-801-01	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - LH PILOT OXYGEN MASK (L502WH)						Service	ATA:35
PN:MC10-12-151	MOS	25-Mar-22	72	25-Mar-28		701 d	OVERHAUL	
SN:SE21706	HRS	13349.6						
WC#: 35.060	AFL	6796						
PROC. REF: AMM 35-10-05-350-801PROC. REF: AMM 35-10-05-350-801								

35-10-05-350-801-02	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - RH PILOT OXYGEN MASK (R502WH)						Service	ATA:35
PN:MC10-12-152	MOS	25-Mar-22	72	25-Mar-28		701 d	OVERHAUL	
SN:B000484	HRS	13349.6						
WC#: 35.060	AFL	6796						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-10-05-350-801PROC. REF: AMM 35-10-05-350-801								
35-10-05-350-801-03	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - THIRD CREW MEMBER OXYGEN MASK (524WH)							Service ATA:35
PN:MC1012-100	MOS/MSC	06-Apr-22	O/C					
SN:18141	HRS	13355.8						
	AFL	6803						
PROC. REF: AMM 35-10-05-350-801PROC. REF: AMM 35-10-05-350-801								
35-10-05-710-801-01	^S	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)						Service ATA:35
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
								PKG:15
PROC. REF: AMM 35-10-05-710-801PROC. REF: AMM 35-10-05-710-801								
35-10-05-710-801-02	^S	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)						Service ATA:35
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
								PKG:15
PROC. REF: AMM 35-10-05-710-801PROC. REF: AMM 35-10-05-710-801								
35-10-05-710-801-03	^S	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)						Service ATA:35
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
								PKG:15
PROC. REF: AMM 35-10-05-710-801PROC. REF: AMM 35-10-05-710-801								
35-10-05-900-801-01	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)							Component ATA:35
PN:MC10-12-151	MOS/MSC	25-Mar-22	H/T					
SN:SE21706	HRS	13349.6						
WC#: 35.060	AFL	6796						
PROC. REF: AMM 35-10-05-900-801PROC. REF: AMM 35-10-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-10-05-900-801-02	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)							Component ATA:35
PN:MC10-12-152	MOS/MSC	25-Mar-22	H/T					
SN:B000484	HRS	13349.6						
WC#: 35.060	AFL	6796						
PROC. REF: AMM 35-10-05-900-801PROC. REF: AMM 35-10-05-900-801								
35-10-05-900-801-03	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)							Component ATA:35
PN:MC1012-100	MOS/MSC	06-Apr-22	O/C					
SN:18141	HRS	13355.8						
WC#: 35.160	AFL	6803						
PROC. REF: AMM 35-10-05-900-801PROC. REF: AMM 35-10-05-900-801								
35-20-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS							Service ATA:35
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 35.250	AFL	7304						
PROC. REF: AMM 35-20-00-210-801PKG:16								
35-20-00-720-801-01 ^S	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM							Service ATA:35
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 35.090	AFL	6741						
PROC. REF: AMM 35-20-00-720-801PKG:21								
35-20-01-350-801-01	RESTORATION OF THE PASSENGER OXYGEN CONTROLLER (OVERHAUL) - PASSENGER OXYGEN CONTROLLER (1WH)							Service ATA:35
PN:RCA74-03	MOS/MSC	26-Nov-14	O/C					
SN:1312	HRS	13029.05						
WC#: 35.110	AFL	6673						
PROC. REF: AMM 35-20-01-350-801								
35-20-01-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER OXYGEN CONTROLLER - PASSENGER OXYGEN CONTROLLER (1WH)							Component ATA:35
PN:RCA74-03	MOS/MSC	26-Nov-14	H/T	TSO 5				
SN:1312	HRS	13029.05						
WC#: 35.110	AFL	6673						
PROC. REF: AMM 35-20-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-05-210-801-01	S	INSPECTION OF THE RILSAN TUBE ASSEMBLY						Service ATA:35
	MOS	19-Dec-21					SMM	
	HRS	13275.5	1600 (+40)					
	AFL	6741						
PROC. REF: AMM 35-21-05-210-801PROC. REF: AMM 35-21-05-210-801								
35-30-01-960-801-01		DISCARD OF THE SMOKE HOOD - SMOKE HOOD (508WH)						Service ATA:35
PN:DP3113(A)	MOS/MSC	30-Jan-07	O/C					
SN:E0302239	HRS	9294.33						
WC#: 35.230	AFL	4969						
PROC. REF: AMM 35-30-01-960-801PROC. REF: AMM 35-30-01-960-801								
35-30-05-210-801-01		GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						Service ATA:35
PN:894-20330	MOS	24-Apr-25	12 (+3%)	24-Apr-26	04-May-26	0 d (+10)		
SN:587006	HRS	13836.2						
WC#: 35.240	AFL	7249						
PROC. REF: AMM 35-30-05-210-801PROC. REF: AMM 35-30-05-210-801								
35-30-05-350-801-01		RESTORATION OF THE PORTABLE OXYGEN BOTTLE (OVERHAUL) - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						Service ATA:35
PN:894-20330	MOS	30-Mar-22	60 (+3%)	30-Mar-27	24-May-27	340 d (+55)	OVERHAUL	
SN:587006	HRS							
WC#: 35.050	AFL							
HydroCheck Date: : 30-Mar-22								
PROC. REF: AMM 35-30-05-350-801PROC. REF: AMM 35-30-05-350-801								
35-30-05-960-801-01		DISCARD OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						Service ATA:35
PN:894-20330	MOS/MSC		O/C					
SN:587006	HRS							
	AFL							
PROC. REF: AMM 35-30-05-960-801PROC. REF: AMM 35-30-05-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-30-09-100-801-01	CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)							Service ATA:35
PN:894-20330	MOS	27-Mar-26	12 (+3%)	Adj -4d	23-Mar-27	03-Apr-27	333 d (+11)	
SN:587006	HRS	13896.3						
WC#: 35.050	AFL	7313						
PROC. REF: AMM 35-30-09-100-801PROC. REF: AMM 35-30-09-100-801								
35-40-01-720-801-01	FUNCTIONAL TEST OF THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY - OXYGEN CYLINDER (500WH)							Service ATA:35
PN:176220	MOS	30-Mar-22	60		30-Mar-27		340 d	
SN:654414601	HRS							
	AFL							
Test Date: : 30-Mar-22								
PROC. REF: AMM 35-40-01-720-801PROC. REF: AMM 35-40-01-720-801								
35-40-01-790-801-01	HYDROSTATIC TEST OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)							Service ATA:35
PN:176220	MOS/MSC		O/C					
SN:654414601	HRS							
WC#: 35.010	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
35-40-01-900-801-01	REMOVAL / INSTALLATION OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)							Component ATA:35
PN:176220	MOS/MSC	06-Apr-22	H/T					
SN:654414601	HRS	13355.8						
WC#: 35.010	AFL	6803						
PROC. REF: AMM 35-40-01-900-801PROC. REF: AMM 35-40-01-900-801								
35-40-01-960-801-01	DISCARD OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)							Service ATA:35
PN:176220	MOS	30-Nov-14	180		30-Nov-29		1316 d	LIFE LIMIT
SN:654414601	HRS							
WC#: 35.010	AFL							
Manufacture Date:: 30-Nov-14								
PROC. REF: AMM 35-40-01-960-801PROC. REF: AMM 35-40-01-960-801								
35-40-05-720-801-01	FUNCTIONAL TEST OF THE OXYGEN CYLINDER PRESSURE REDUCING VALVE							Service ATA:35
PN:172200-3	MOS/MSC	06-Apr-22	O/C					
SN:0457	HRS	13355.8						
WC#: 35.010	AFL	6803						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
350121 OXYGEN PRESSURE REDUCER VALVE								Component ATA:35
PN:172200-3	MOS/MSC	05-Jun-13	O/C					
SN:0457	HRS	12205.82						
WC#: 35.010	AFL	6354						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
350141 HP OXYGEN PRESSURE BOTTLE GAGE								Component ATA:35
PN:CMT150	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.030	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
350161 OXYGEN FILLER VALVE								Component ATA:35
PN:DKR131	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.040	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
350201 PORTABLE OXYGEN BOTTLE								Component ATA:35
PN:894-20330	MOS/MSC	06-Apr-22	O/C					
SN:587006	HRS	13355.8						
WC#: 35.050	AFL	6803						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
351121 PILOT OXYGEN MASK HOSE								Component ATA:35
PN:DTF44A435	MOS/MSC	01-Oct-89	O/C					
SN:UNKNOWN	HRS			TSN 0				
WC#: 35.070	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
351131 PILOT OXYGEN CONNECTOR								Component ATA:35
PN:DPB179	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.080	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
351171COPILOT OXYGEN MASK HOSE								Component ATA:35
PN:DTF55A350	MOS/MSC	01-Nov-89	O/C					
SN:UNKNOWN	HRS			TSN 0				
WC#: 35.070	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
351181COPILOT OXYGEN CONNECTOR								Component ATA:35
PN:DPB179	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.080	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
352111NO. 1 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.120	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352121NO. 2 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.120	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352131NO. 3 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.120	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352141NO. 4 PASSENGER OXYGEN MASK								Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.130	AFL	5878		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352151	NO. 5 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.130	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352161	NO. 6 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.130	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352171	NO. 7 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.140	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352181	NO. 8 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.140	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352191	NO. 9 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.140	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352201	NO. 10 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.150	AFL	5878		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352211	NO. 11 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.150	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352221	NO. 12 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.150	AFL	5878		TSN 0				
PROC. REF: AMM 35-20-09-900-801PROC. REF: AMM 35-20-09-900-801								
352261	NO. 1 FIRST AID MASK							Component ATA:35
PN:MW3718	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.170	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
352271	NO. 2 FIRST AID MASK							Component ATA:35
PN:MW3718	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.170	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
352281	NO. 1 LAVATORY OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.180	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
352291	NO. 2 LAVATORY OXYGEN MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 35.180	AFL	5878		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
352A01 ^U	NO. 3 LAVATORY OXYGEN (FORWARD) MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.33						
	AFL	5878						
352A02 ^U	NO. 4 LAVATORY OXYGEN (FORWARD) MASK							Component ATA:35
PN:289-601-235	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.33						
	AFL	5878						
352A21 ^U	OXYGEN PASSENGER #13 MASK							Component ATA:35
PN:289-601-235	MOS/MSC	26-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.33						
	AFL	5878						
352A22 ^U	OXYGEN PASSENGER #14 MASK							Component ATA:35
PN:289-601-235	MOS/MSC	26-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.33						
	AFL	5878						
352A23 ^U	OXYGEN PASSENGER #15 MASK							Component ATA:35
PN:289-601-235	MOS/MSC	26-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.33						
	AFL	5878						
353101	PROTECTIVE BREATHING EQUIPMENT HOOD							Component ATA:35
PN:DP3113(A)	MOS/MSC	30-Jan-07	H/T					
SN:E0302239	HRS	9294.33						
WC#: 35.230	AFL	4969						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
353A01 ^U	NO. 2 PROTECTIVE BREATHING EQUIPMENT HOOD							Component ATA:35
PN:802300-11	MOS/MSC	25-Mar-10	A/R	TSN 25				LIFE LIMIT
SN:UNKNOWN	HRS	10865.5		TSN 0				
	AFL	5891		TSN 0				
ATA 36 - PNEUMATIC								
36-10-29-280-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 HP BLEED AIR PIPE							Service ATA:36
	MOS/MSC	08-Feb-05	O/C					
	HRS	7233.5						
WC#: 36.010	AFL	3778						
PROC. REF: AMM 36-10-29-280-801PROC. REF: AMM 36-10-29-280-801								
36-10-33-350-801-01	RESTORATION OF THE BLEED AIR ARTICULATED PIPES (OVERHAUL) - ENGINE 1 ARTICULATED PIPE (L510HU)							Service ATA:36
PN:B45CB1120	MOS/MSC	30-Jan-07	E/C	TAC 0				OVERHAUL
SN:T595	HRS	9294.2	5000 (+150)	TAC 0	14294.2	14444.2	397.9 (+150)	
WC#: 36.040	AFL	4969		TAC 0				
PROC. REF: AMM 36-10-33-350-801PROC. REF: AMM 36-10-33-350-801								
36-10-33-350-801-02	RESTORATION OF THE BLEED AIR ARTICULATED PIPES (OVERHAUL) - ENGINE 3 ARTICULATED PIPE (R510HU)							Service ATA:36
PN:B45CB1120	MOS/MSC	30-Jan-07	E/C	TAC 0				OVERHAUL
SN:O1513	HRS	9294.2	5000 (+150)	TAC 0	14294.2	14444.2	397.9 (+150)	
WC#: 36.040	AFL	4969		TAC 0				
PROC. REF: AMM 36-10-33-350-801PROC. REF: AMM 36-10-33-350-801								
36-10-33-900-801-01	REMOVAL / INSTALLATION OF THE BLEED AIR ARTICULATED PIPES - ENGINE 1 ARTICULATED PIPE (L510HU)							Component ATA:36
PN:B45CB1120	MOS/MSC	30-Jan-07	H/T	TSN 0				
SN:T595	HRS	9294.2		TSN 0				
WC#: 36.040	AFL	4969		TSN 0				
PROC. REF: AMM 36-10-33-900-801PROC. REF: AMM 36-10-33-900-801								
36-10-33-900-801-02	REMOVAL / INSTALLATION OF THE BLEED AIR ARTICULATED PIPES - ENGINE 3 ARTICULATED PIPE (R510HU)							Component ATA:36
PN:B45CB1120	MOS/MSC	30-Jan-07	H/T	TSN 0				
SN:O1513	HRS	9294.2		TSN 0				
WC#: 36.040	AFL	4969		TSN 0				
PROC. REF: AMM 36-10-33-900-801PROC. REF: AMM 36-10-33-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-21-17-900-801-01	REMOVAL / INSTALLATION OF THE OVERHEATING DETECTION BOX							Component ATA:36
PN:EL124-01	MOS/MSC	27-Jun-95	O/C					
SN:251	HRS							
WC#: 36.120	AFL							
PROC. REF: AMM 36-21-17-900-801PROC. REF: AMM 36-21-17-900-801								
361101	NO. 1 ENGINE LOW PRESSURE BLEED CHECK VALVE							Component ATA:36
PN:CYLB51161-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.020	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361111	NO. 2 ENGINE LOW PRESSURE BLEED CHECK VALVE							Component ATA:36
PN:CYLB51161-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.020	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361121	NO. 3 ENGINE LOW PRESSURE BLEED CHECK VALVE							Component ATA:36
PN:CYLB51161-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.020	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361191	NO. 1 ENGINE LOW PRESSURE INTERCOMMUNICATION CHECK VALVE							Component ATA:36
PN:CYLB51161-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.050	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361201	NO. 3 ENGINE LOW PRESSURE INTERCOMMUNICATION CHECK VALVE							Component ATA:36
PN:CYLB51161-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.050	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361211	NO. 2 ENGINE HIGH PRESSURE CHECK VALVE							Component ATA:36
PN:CYLB50713-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.060	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361221	APU BLEED AIR CHECK VALVE							Component ATA:36
PN:CYLB50713-1	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.070	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361241	NO. 2 ENGINE PRESSURE REGULATING (PRV2) VALVE							Component ATA:36
PN:3215632-3	MOS/MSC	16-Jan-09	O/C	TSO 0				
SN:133	HRS	10823		TSO 0				
WC#: 36.080	AFL	5854		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361251	NO. 3 ENGINE PRESSURE REGULATING (PRV3) VALVE							Component ATA:36
PN:3214730-3	MOS/MSC	09-Nov-97	O/C					
SN:487	HRS	3043						
WC#: 36.080	AFL	1476						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361261	NO. 2 ENGINE PRV2 3 WAYS ELECTRIC VALVE							Component ATA:36
PN:L92A07-501	MOS/MSC	07-Feb-91	O/C					
SN:20215	HRS	0		TSN 0				
WC#: 36.090	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361271	NO. 3 PRV2 3 WAYS ELECTRIC VALVE							Component ATA:36
PN:L92A07-501	MOS/MSC	04-Dec-97	O/C					
SN:20315	HRS	3119						
WC#: 36.090	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361281	NO. 1 HIGH PRESSURE AIR BLEED VALVE							Component ATA:36
PN:B48CB1042	MOS/MSC	17-Apr-14	O/C	TSN 0				
SN:T00638	HRS	12671.82		TSN 0				
WC#: 36.100	AFL	6527		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
361291	BLEED AIR ISOLATION ELECTRIC VALVE							Component ATA:36
PN:B48CA1121	MOS/MSC	06-Dec-02	O/C	TSN 0				
SN:T648	HRS	5755.4		TSN 0				
WC#: 36.110	AFL	2794		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
362101	AIR BLEED INDICATING CONTROL							Component ATA:36
PN:EL125-02	MOS/MSC	13-Jul-08	O/C	TSN 0				
SN:207	HRS			TSN 0				
WC#: 36.120	AFL			TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
362151	NO. 1 ENGINE THERMOCOUPLE SENSOR							Component ATA:36
PN:RP161-00	MOS/MSC	23-Apr-98	O/C	TSN 0				
SN:280	HRS			TSN 0				
WC#: 36.130	AFL			TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
362161	NO. 2 ENGINE THERMOCOUPLE SENSOR							Component ATA:36
PN:RP161-00	MOS/MSC	05-Jul-06	O/C					
SN:2917	HRS	8844						
WC#: 36.130	AFL	4709						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
362171	NO. 3 ENGINE THERMOCOUPLE SENSOR							Component ATA:36
PN:RP161-00	MOS/MSC	07-Feb-91	O/C					
SN:298	HRS	0		TSN 0				
WC#: 36.130	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362181	NO. 1 ENGINE THERMOCOUPLE SENSOR							Component ATA:36
PN:RP129-00	MOS/MSC	07-Feb-91	O/C					
SN:808	HRS	0		TSN 0				
WC#: 36.140	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
362191	NO. 2 THERMOCOUPLE SENSOR							Component ATA:36
PN:RP482-00	MOS/MSC	29-Aug-08	O/C	TSN 0				
SN:DAAA00947	HRS	10680.1		TSN 0				
WC#: 36.140	AFL	5757		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
362201	NO. 3 ENGINE THERMOCOUPLE SENSOR							Component ATA:36
PN:RP129-00	MOS/MSC	07-Feb-91	O/C					
SN:802	HRS	0		TSN 0				
WC#: 36.140	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
ATA 38 - WATER/WASTE								
38-00-00-610-801-01	^S	SERVICING OF THE WATER SYSTEM						Service ATA:38
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 38.080	AFL	7304						
PROC. REF: AMM 38-00-00-610-801, AMM 38-00-00-610-801PROC. REF: AMM 38-00-00-610-801, AMM 38-00-00-610-801								
38-10-00-210-801-01	^S	DETAILED INSPECTION OF WATER SYSTEM COMPONENTS						Service ATA:38
	MOS	22-Dec-23	72 (+2m)				SMM	
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 38-10-00-210-801PROC. REF: AMM 38-10-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
38-10-00-670-801-01	STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION							Service ATA:38
	MOS	27-Mar-26	6 (+1m)	Adj -8d	19-Sep-26	19-Oct-26	148 d (+30)	
	HRS	13896.3						
WC#: 38.010	AFL	7313						
PROC. REF: AMM 38-10-00-670-801PROC. REF: AMM 38-10-00-670-801								
38-13-01-960-801-01	REPLACEMENT OF THE MAIN FILTER CARTRIDGE							Service ATA:38
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 38.020	AFL	6673						
PROC. REF: AMM 38-13-01-960-801PROC. REF: AMM 38-13-01-960-801								
38-13-09-710-801-01	OPERATIONAL TEST OF THE WATER HEATING MONITORING SYSTEM							Service ATA:38
	MOS/MSC	28-Nov-08	O/C					
	HRS	10765.7						
WC#: 38.070	AFL	5815						
PROC. REF: AMM 38-13-09-710-801PROC. REF: AMM 38-13-09-710-801								
38-13-09-900-802-01	REMOVAL / INSTALLATION OF THE FORWARD WATER HEATER - FWD WATER HEATER (63HR)							Component ATA:38
PN:116393-213	MOS/MSC	30-Jan-07	O/C					
SN:1591	HRS	9294.33						
	AFL	4969						
PROC. REF: AMM 38-13-09-900-802PROC. REF: AMM 38-13-09-900-802								
38-15-09-960-801-01	REPLACEMENT OF THE UV LAMP - UV LAMP (9870MT)							Service ATA:38
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 38-15-09-960-801PROC. REF: AMM 38-15-09-960-801								
38-15-17-100-801-01	CLEANING OF THE UV STERILIZER QUARTZ SLEEVE - QUARTZ SLEEVE (9890MT)							Service ATA:38
	MOS/MSC		N/A					SMM
	HRS							
	AFL							
PROC. REF: AMM 38-15-17-100-801PROC. REF: AMM 38-15-17-100-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
38-30-00-100-801-01	CLEANING OF THE WATER TRAP FILTER IN WASH HANDBASIN DRAINAGE SYSTEM							Service ATA:38
	MOS/MSC	28-Nov-08	O/C					
	HRS	10765.7						
WC#: 38.060	AFL	5815						
PROC. REF: AMM 38-30-00-100-801PROC. REF: AMM 38-30-00-100-801								
38-31-13-960-801-01	REPLACEMENT OF THE GALLEY WATER FILTER							Service ATA:38
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 38-31-13-960-801, AMM 38-31-13-960-801PROC. REF: AMM 38-31-13-960-801, AMM 38-31-13-960-801								
38-31-17-200-801-01	INSPECTION OF THE DRAIN BOX - DRAIN BOX (905MD)							Service ATA:38
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 38.090	AFL	0						
PROC. REF: AMM 38-31-17-200-801PROC. REF: AMM 38-31-17-200-801								
38-34-17-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE FORWARD TOILET DRAIN CONTROL - FORWARD TOILET DRAIN CONTROL (525MD)							Service ATA:38
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 38-34-17-210-801PROC. REF: AMM 38-34-17-210-801								PKG:17
38-34-21-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE AFT TOILET DRAIN CONTROL - AFT TOILET DRAIN CONTROL (516MD)							Service ATA:38
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 38-34-21-210-801PROC. REF: AMM 38-34-21-210-801								PKG:17
381151	POTABLE WATER PRESSURE REGULATOR							Component ATA:38
PN:G9227B	MOS/MSC	03-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	9207.9		TSN 0				
WC#: 38.030	AFL	4818		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
381171	POTABLE WATER TWO WAYS VALVE							Component ATA:38
PN:879B14-13	MOS/MSC	07-Feb-91	O/C					
SN:200	HRS	0		TSN 0				
WC#: 38.040	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
381199 U	POTABLE WATER TREATMENT UNIT - UV STERILIZER							Component ATA:38
PN:9-11021-01	MOS/MSC	26-Nov-14	O/C	TSO 11				
SN:1-1007	HRS	13029.05		TSO 0				
	AFL	6673		TSO 0				
381201	POTABLE WATER FILLING PLUG							Component ATA:38
PN:AR88-03-00-02	MOS/MSC	26-Jun-09	O/C					
SN:UNKNOWN	HRS	10850.33						
WC#: 38.040	AFL	5878						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
ATA 49 - AIRBORNE AUXILIARY POWER								
49-10-01-900-803-01	APU - REMOVAL / INSTALLATION OF THE APU ECU - APU ECU (12HT)							Component ATA:49
PN:3882730-9	MOS/MSC	27-Oct-00	O/C	TSO 0				
SN:A301C	HRS	2431		TSO 0				
WC#: 49.030	APUS							
PROC. REF: AMM 49-10-01-900-803, AMM 49-10-01-900-803, AMM 49-10-01-900-803PROC. REF: AMM 49-10-01-900-803, AMM 49-10-01-900-803, AMM 49-10-01-900-803								
491010	APU - TURBINE ROTOR							Component ATA:49
PN:3615880-1	MOS	27-Nov-00						LIFE LIMIT
SN:000134508150	HRS	2431	10000	TSN 0	12431		5673.7	
	APUS							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
491020	APU - COMPRESSOR ROTOR							Component ATA:49
PN:3822101-1	MOS	13-Jun-88						LIFE LIMIT
SN:1-03501-1022	HRS	0	100000	TSN 0, TSO 0	100000		93242.7	
	APUS							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
491025	APU - VISUAL CHECK COMPRESSOR ROTOR							Service ATA:49
PN:3822101-1	MOS	20-Aug-03						
SN:1-03501-1022	HRS	3329	4500		7829		1071.7	
	APUS							
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
493020	APU - REMOVE AND REPLACE FUEL CONTROL FUEL FILTER ELEMENT							Service ATA:49
PN:3882730-9	MOS	31-Mar-14						
SN:A301C	HRS	6156	1000		7156		398.7	
	APUS	0						
PROC. REF: MM 49-30-52PROC. REF: MM 49-30-52								
493030	APU - ORIFICE FITTING							Component ATA:49
PN:3606721-1	MOS/MSC	13-Jun-88	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
	APUS							
PROC. REF: MM 49-30-56PROC. REF: MM 49-30-56								
493040	APU - FUEL SHUTOFF VALVE							Component ATA:49
PN:692545-17	MOS/MSC	26-Apr-01	O/C					
SN:UNKNOWN	HRS	2478		TSN 0				
	APUS							
PROC. REF: MM 49-30-54PROC. REF: MM 49-30-54								
493050	APU - CHECK FUEL NOZZLE FLOW RATE							Service ATA:49
	MOS	20-Aug-03						
	HRS	3329	4500		7829		1071.7	
	APUS							
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
493060	APU - CONTROLLER							Component ATA:49
PN:2118306-3	MOS/MSC	26-Apr-01	O/C					
SN:82-1272	HRS	2478		TSN 0				
	APUS							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
PROC. REF: MM 49-60-46PROC. REF: MM 49-60-46								
493070	APU - LOAD CONTROL VALVE							Component ATA:49
PN:109812-3-1	MOS/MSC	25-Oct-03	O/C	TSR 0				
SN:396	HRS			TSR 0				
	APUS							
PROC. REF: MM 49-50-33PROC. REF: MM 49-50-33								
494010	APU - IGNITION UNIT							Component ATA:49
PN:3888000-2	MOS/MSC	26-Apr-01	O/C					
SN:00021807373	HRS	2478		TSN 0				
	APUS							
PROC. REF: MM 49-40-32PROC. REF: MM 49-40-32								
494020	APU - IGNITOR PLUG							Component ATA:49
PN:3888002-2	MOS/MSC	08-Mar-13	O/C	TSN 4				
SN:NSN	HRS	5940		TSN 0				
	APUS	0		TSN 0				
PROC. REF: MM 49-40-33PROC. REF: MM 49-40-33								
494030	APU - INSPECT/CLEAN IGNITOR PLUG							Service ATA:49
PN:3888002-2	MOS	01-May-25						
SN:NSN	HRS	6710.7	750		7460.7		703.4	
	APUS							
PROC. REF: MM 49-40-33PROC. REF: MM 49-40-33								
496101	APU T5 INDICATOR							Component ATA:49
PN:2396-507-00-10	MOS/MSC	17-Feb-92	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
	APH	0	0					
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
496201	APU TACHOMETER							Component ATA:49
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 49.155	AFL	0		TSN 0				
	APH	0	0	TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
497010	APU - MOTION PICK UP TRANSDUCER							Component ATA:49
PN:3876104-1	MOS/MSC	29-Mar-01	O/C	TSN 0				
SN:001936019275	HRS			TSN 0				
	APUS							
PROC. REF: MM 49-60-43PROC. REF: MM 49-60-43								
497020	APU - IMMERSION THERMOCOUPLE							Component ATA:49
PN:3876003-3	MOS/MSC	29-Mar-01	O/C	TSN 0				
SN:002021901104	HRS			TSN 0				
	APUS							
PROC. REF: MM 49-60-45PROC. REF: MM 49-60-45								
497030	APU - HOURMETER							Component ATA:49
PN:3888126-1	MOS/MSC	26-Apr-01	O/C					
SN:UNKNOWN	HRS	2478		TSN 0				
	APUS							
PROC. REF: MM 49-70-41PROC. REF: MM 49-70-41								
499010	APU - ROTARY OIL PUMP							Component ATA:49
PN:3880225-2	MOS/MSC	13-Jun-88	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
	APUS							
PROC. REF: MM 49-90-51PROC. REF: MM 49-90-51								
499020	APU - REMOVE AND INSPECT MAGNETIC DRAIN PLUG							Service ATA:49
	MOS	30-Jan-25	17		30-Jun-26		67 d	
	HRS	6677.9	750		7427.9		670.6	
	APUS							
PROC. REF: MM 49-90-46PROC. REF: MM 49-90-46								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
499030	APU - DRAIN AND REFILL OIL							Service ATA:49
	MOS	30-Jan-25	17		30-Jun-26		67 d	
	HRS	6677.9	750		7427.9		670.6	
	APUS							
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
499040	APU - REMOVE AND REPLACE OIL FILTER ELEMENT							Service ATA:49
	MOS	30-Jan-25	17		30-Jun-26		67 d	
	HRS	6677.9	750		7427.9		670.6	
	APUS							
PROC. REF: MM 49-90-47PROC. REF: MM 49-90-47								
499050	APU - PRESSURE REGULATING VALVE							Component ATA:49
PN:3880021-13	MOS/MSC	26-Apr-01	O/C					
SN:UNKNOWN	HRS	2478		TSN 0				
	APUS							
PROC. REF: MM 49-90-52PROC. REF: MM 49-90-52								
499060	APU - HIGH OIL TEMPERATURE SWITCH							Component ATA:49
PN:3888030-1	MOS/MSC	26-Apr-01	O/C					
SN:990922705618	HRS	2478		TSN 0				
	APUS							
PROC. REF: MM 49-60-46PROC. REF: MM 49-60-46								
499070	APU - LOW OIL PRESSURE SWITCH							Component ATA:49
PN:3876001-6	MOS/MSC	26-Apr-01	O/C					
SN:1954	HRS	2478		TSN 0				
	APUS							
PROC. REF: MM 49-60-43PROC. REF: MM 49-60-43								
499110	APU - SOAP CHECK OIL							Service ATA:49
	MOS/MSC	12-Jun-09	O/C					
	HRS	5333						
	APUS							
PROC. REF: SIL SIL APU-49PROC. REF: SIL SIL APU-49								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
49APU1	APU							Component ATA:49
PN:3800188-2	MOS/MSC	11-Mar-06	E/C					
SN:P-125	HRS	9207.9		TSN 3938				
	AFL	4818						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 51 - STD PRACTICES AND STRUCT-GENRL								
51-00-00-200-801-01	^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 12 M OR 800 FH INSPECTION						Service ATA:51
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
PROC. REF: AMM 51-00-00-200-801PROC. REF: AMM 51-00-00-200-801								PKG:5
51-00-00-200-802-01	^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 24 M OR 1600 FH INSPECTION						Service ATA:51
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3	1600 (+40)					
	AFL	7304						
PROC. REF: AMM 51-00-00-200-802PROC. REF: AMM 51-00-00-200-802								PKG:6
51-00-00-200-803-01	^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 1C INSPECTION						Service ATA:51
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 51-00-00-200-803PROC. REF: AMM 51-00-00-200-803								PKG:31
51-00-00-200-804-01	^S	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 2C INSPECTION						Service ATA:51
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
	AFL	6741	7500					
PROC. REF: AMM 51-00-00-200-804PROC. REF: AMM 51-00-00-200-804								PKG:32
51-30-00-220-802-01		DETAILED INSPECTION OF THE INTERNAL COMPOSITE MATERIAL COMPONENTS						Service ATA:51
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
WC#: 51.040	AFL	5878						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-00-00-200-802-01	S	INSPECTION / CHECK OF THE MAIN ENTRANCE, BAGGAGE COMPARTMENT AND REAR COMPARTMENT DOOR FRAME SEALS - MAIN ENTRANCE DOOR FRAME SEAL					Service	ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.100	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 52-00-00-200-802PROC. REF: AMM 52-00-00-200-802								
52-00-00-200-802-02	S	INSPECTION / CHECK OF THE MAIN ENTRANCE, BAGGAGE COMPARTMENT AND REAR COMPARTMENT DOOR FRAME SEALS - BAGGAGE COMPARTMENT DOOR FRAME SEAL					Service	ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 52-00-00-200-802PROC. REF: AMM 52-00-00-200-802								
52-00-00-200-802-03	S	INSPECTION / CHECK OF THE MAIN ENTRANCE, BAGGAGE COMPARTMENT AND REAR COMPARTMENT DOOR FRAME SEALS - REAR COMPARTMENT DOOR FRAME SEAL					Service	ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 52-00-00-200-802PROC. REF: AMM 52-00-00-200-802								
52-00-00-640-801-01	S	LUBRICATION OF SERVICE DOORS					Service	ATA:52
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 52.010	AFL	7304						
								PKG:15
PROC. REF: AMM 52-00-00-640-801PROC. REF: AMM 52-00-00-640-801								
52-10-00-220-801-01	S	DETAILED INSPECTION OF THE PASSENGER DOOR COUNTERBALANCING SYSTEM					Service	ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 52.040	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 52-10-00-220-801, AMM 52-10-00-220-801PROC. REF: AMM 52-10-00-220-801, AMM 52-10-00-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-00-610-801-01	^S	SERVICING OF THE PASSENGER DOOR						Service ATA:52
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
WC#: 52.030	AFL	7052						
PROC. REF: AMM 52-10-00-610-801PROC. REF: AMM 52-10-00-610-801								PKG:17
52-10-00-610-802-01	^S	SERVICING OF THE PASSENGER DOOR SAFETY CATCH						Service ATA:52
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 52-10-00-610-802PROC. REF: AMM 52-10-00-610-802								PKG:17
52-10-00-640-801-01	^S	LUBRICATION OF THE ROLLERS OF THE PASSENGER DOOR LOWER MECHANISM						Service ATA:52
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 52.120	AFL	6741	7500					
PROC. REF: AMM 52-10-00-640-801PROC. REF: AMM 52-10-00-640-801								PKG:32
52-10-00-720-801-01	^S	FUNCTIONAL TEST OF THE PASSENGER DOOR						Service ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 52.020	AFL	7052	3750					
PROC. REF: AMM 52-10-00-720-801PROC. REF: AMM 52-10-00-720-801								PKG:31
52-10-01-900-801-01		REMOVAL / INSTALLATION OF THE PASSENGER DOOR						Component ATA:52
PN:FGFB295-A5	MOS/MSC		O/C					
SN:B27-142	HRS	740						
WC#: 52.030	AFL							
PROC. REF: AMM 52-10-01-900-801PROC. REF: AMM 52-10-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-03-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (902MC)						Component	ATA:52
PN:222900M02	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0						
WC#: 52.045	AFL	0						
PROC. REF: AMM 52-10-03-900-801PROC. REF: AMM 52-10-03-900-801								
52-10-03-960-801-01	DISCARD OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (902MC)						Service	ATA:52
PN:222900M02	MOS/MSC	07-Feb-91	N/A					
SN:UNKNOWN	HRS	0						
WC#: 52.045	AFL	0						
PROC. REF: AMM 52-10-03-960-801PROC. REF: AMM 52-10-03-960-801								
52-10-11-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR COUNTERBALANCING LEAF-SPRING ACTUATOR - PASSENGER DOOR COUNTERBALANCING ACTUATOR (500MA)						Component	ATA:52
PN:AE40142Z007	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:2319347	HRS	10850.2		TSN 0				
WC#: 52.040	AFL	5878		TSN 0				
PROC. REF: AMM 52-10-11-900-801PROC. REF: AMM 52-10-11-900-801								
52-10-11-960-801-01	DISCARD OF THE PASSENGER DOOR COUNTERBALANCING LEAF-SPRING ACTUATOR - PASSENGER DOOR COUNTERBALANCING ACTUATOR (500MA)						Service	ATA:52
PN:AE40142Z007	MOS/MSC	12-Jun-09	O/C	TAC 0				
SN:2319347	HRS	10850.2		TAC 0				
WC#: 52.040	AFL	5878		TAC 0				
PROC. REF: AMM 52-10-11-960-801PROC. REF: AMM 52-10-11-960-801								
52-20-00-610-801-01 ^S	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN						Service	ATA:52
	MOS	17-Feb-26	24					
	HRS	13885.3						
WC#: 52.050	AFL	7304						
PROC. REF: AMM 52-20-00-610-801PROC. REF: AMM 52-20-00-610-801								

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-00-610-801-01A	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40)							Service ATA:52
	MOS	11-Dec-25	24		11-Dec-27		596 d	MANDATORY 5-40
	HRS	13869.7						
WC#: 52.050	AFL	7285						
PROC. REF: AMM 52-20-00-610-801PROC. REF: AMM 52-20-00-610-801								
52-20-00-610-801-02 ^S	SERVICING OF THE EMERGENCY EXIT DOOR							Service ATA:52
	MOS	17-Feb-26	24 (+1d)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 52-20-00-610-801PROC. REF: AMM 52-20-00-610-801								PKG:16
52-20-00-710-801-01 ^S	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE							Service ATA:52
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 52.050	AFL	6741						
PROC. REF: AMM 52-20-00-710-801PROC. REF: AMM 52-20-00-710-801								PKG:21
52-20-01-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY EXIT DOOR							Component ATA:52
PN:FGFB296001	MOS/MSC	07-Feb-91	O/C					
SN:96HP	HRS	0		TSN 0				
WC#: 52.050	AFL	0						
PROC. REF: AMM 52-20-01-900-801PROC. REF: AMM 52-20-01-900-801								
52-30-00-270-801-01	ULTRASONIC TEST OF THE BAGGAGE COMPARTMENT DOOR OUTER SKIN							Service ATA:52
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 52.060	AFL	0						
PROC. REF: AMM 52-30-00-270-801PROC. REF: AMM 52-30-00-270-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30-00-610-801-01	S	SERVICING OF THE BAGGAGE COMPARTMENT DOOR						Service ATA:52
	MOS	22-Dec-23	36					
	HRS	13641						
WC#: 52.060	AFL	7052						
PROC. REF: AMM 52-30-00-610-801PROC. REF: AMM 52-30-00-610-801								PKG:17
52-30-00-710-801-01	S	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM - TEST OF DOOR MECHANISM						Service ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 52.060	AFL	7052	3750					
PROC. REF: AMM 52-30-00-710-801PROC. REF: AMM 52-30-00-710-801								PKG:31
52-30-00-710-801-02	S	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM - TEST OF DOOR SLIDING BOLTS						Service ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 52.060	AFL	7052	3750					
PROC. REF: AMM 52-30-00-710-801PROC. REF: AMM 52-30-00-710-801								PKG:31
52-30-00-710-801-02A		CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM - TEST OF DOOR SLIDING BOLTS (MANDATORY 5-40)						Service ATA:52
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641	8000		21641		7744.7	
WC#: 52.060	AFL	7052						
PROC. REF: AMM 52-30-00-710-801PROC. REF: AMM 52-30-00-710-801								
52-30-01-900-801-01		REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR						Component ATA:52
PN:FGFB299	MOS/MSC	07-Feb-91	O/C					
SN:95BZ	HRS	0		TSN 0				
WC#: 52.060	AFL	0						
PROC. REF: AMM 52-30-01-900-801PROC. REF: AMM 52-30-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30-19-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR REDUCING GEAR MOTOR ASSEMBLY - BAGGAGE COMPARTMENT DOOR REDUCING GEAR MOTOR (3MC)							Component ATA:52
PN:4220-5	MOS/MSC	08-Mar-13	O/C	TSR 1				
SN:403	HRS	12150.15		TSR 0				
WC#: 52.060	AFL	6335		TSR 0				
PROC. REF: AMM 52-30-19-900-801PROC. REF: AMM 52-30-19-900-801								
52-40-00-210-801-01	^S	GENERAL VISUAL INSPECTION OF THE ACCESS PANELS AND DOORS						Service ATA:52
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 52.090	AFL	7304						
PROC. REF: AMM 52-40-00-210-801PROC. REF: AMM 52-40-00-210-801								
52-41-07-610-801-01	^S	SERVICING OF THE NLG WELL CEILING DOOR						Service ATA:52
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 52.110	AFL	7304						
PROC. REF: AMM 52-41-07-610-801PROC. REF: AMM 52-41-07-610-801								
52-50-00-710-801-01	^S	INSPECTION / TEST OF THE BLOWOUT DOORS / PANELS						Service ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 52-50-00-710-801PROC. REF: AMM 52-50-00-710-801								
52-53-00-610-801-01	^S	SERVICING OF THE CABIN / BAGGAGE COMPARTMENT DOOR						Service ATA:52
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
WC#: 52.100	AFL	7052						
PROC. REF: AMM 52-53-00-610-801PROC. REF: AMM 52-53-00-610-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-54-00-210-801-01	^S	GENERAL VISUAL INSPECTION OF CABIN DOORS, DIVIDERS AND BULKHEADS						Service ATA:52
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 52-54-00-210-801PROC. REF: AMM 52-54-00-210-801								PKG:31
52-54-05-210-801-02	^S	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR - INSPECTION OF MOUNTING LOCATIONS, LAMINATE AND MECHANISM						Service ATA:52
	MOS	22-Dec-23	72 (+2m)					SMM
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 52-54-05-210-801PROC. REF: AMM 52-54-05-210-801								PKG:31
52-54-05-210-802-01	^S	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER - INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER						Service ATA:52
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3	1600 (+40)					
	AFL	7304						
PROC. REF: AMM 52-54-05-210-802PROC. REF: AMM 52-54-05-210-802								PKG:6
52-55-00-610-801-01	^S	SERVICING OF THE S-DUCT DOOR						Service ATA:52
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 52.080	AFL	7304						
PROC. REF: AMM 52-55-00-610-801PROC. REF: AMM 52-55-00-610-801								PKG:16
52-60-09-610-801-01	^S	SERVICING OF THE REAR COMPARTMENT DOOR						Service ATA:52
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
WC#: 52.070	AFL	7052						
PROC. REF: AMM 52-60-09-610-801PROC. REF: AMM 52-60-09-610-801								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
523A11 ^U	BAGGAGE DOOR CABLE							Component ATA:52
PN:4220-250	MOS/MSC	14-Mar-01	O/C					
SN:991123023	HRS	4661		TSN 0				
	AFL	2061		TSN 0				
524101	REAR COMPARTMENT DOOR							Component ATA:52
PN:FGFB297	MOS/MSC	07-Feb-91	O/C					
SN:90HP	HRS	0		TSN 0				
WC#: 52.070	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
525301	S-DUCT DOOR							Component ATA:52
PN:FGFB241025500	MOS/MSC	07-Feb-91	O/C					
SN:98BZ	HRS	0		TSN 0				
WC#: 52.080	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
ATA 53 - FUSELAGE								
53-00-00-200-803-01	INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 - GENERAL VISUAL INSPECTION							Service ATA:53
	MOS	12-Jun-09						
	HRS	10850.2						
WC#: 53.140	AFL	5878	T:11250	TAC 5878	11250		3937	
PROC. REF: AMM 53-00-00-200-803PROC. REF: AMM 53-00-00-200-803								
53-00-00-200-803-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 (MANDATORY 5-40)							Service ATA:53
	MOS	12-Jun-09						MANDATORY 5-40
	HRS	10850.2						
WC#: 53.140	AFL	5878	T:11250	TAC 5878	11250		3937	
PROC. REF: AMM 53-00-00-200-803PROC. REF: AMM 53-00-00-200-803								
53-00-00-200-803-02	INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 - DETAILED INSPECTION IN SPECIFIC AREAS							Service ATA:53
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-00-00-200-803PROC. REF: AMM 53-00-00-200-803								
53-00-00-200-803-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 (MANDATORY 5-40)							Service ATA:53
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 53-00-00-200-803PROC. REF: AMM 53-00-00-200-803								
53-00-00-200-810-01	INSPECTIONS SPECIFIC TO A/C 1							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 53.305	AFL	0						
PROC. REF: AMM 53-00-00-200-810PROC. REF: AMM 53-00-00-200-810								
53-00-00-200-811-01	SPECIFIC INSPECTION OF THE REPAIRED AREAS (S/N 155)							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 53.300	AFL	0						
PROC. REF: AMM 53-00-00-200-811PROC. REF: AMM 53-00-00-200-811								
53-00-00-200-812-01	SPECIFIC INSPECTION OF THE REPAIRED AREAS (S/N 67)							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 53.0502	AFL	0						
	APH	0						
PROC. REF: AMM 53-00-00-200-812PROC. REF: AMM 53-00-00-200-812								
53-00-00-210-801-01 ^S	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION							Service ATA:53
	MOS	17-Feb-26	24 (+1m)					RVSM
	HRS	13885.3						
WC#: 53.010	AFL	7304						
PROC. REF: AMM 53-00-00-210-801PROC. REF: AMM 53-00-00-210-801								

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION (CPCP)							Service ATA:53
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-00-00-210-801PROC. REF: AMM 53-00-00-210-801								
53-00-00-220-801-01 S	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION							Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 53-00-00-220-801PROC. REF: AMM 53-00-00-220-801								
53-00-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION (CPCP)							Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-00-00-220-801PROC. REF: AMM 53-00-00-220-801								
53-00-00-220-810-01	SPECIFIC DETAILED INSPECTION OF THE REPAIRED AREAS (S/N 67)							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 53.0501	AFL	0						
	APH	0						
PROC. REF: AMM 53-00-00-220-810PROC. REF: AMM 53-00-00-220-810								
53-00-00-220-811-01	SPECIFIC DETAILED INSPECTION OF THE REPAIRED AREAS (S/N 155)							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 53.300	AFL	0						
PROC. REF: AMM 53-00-00-220-811PROC. REF: AMM 53-00-00-220-811								
53-00-00-220-812-01	DETAILED INSPECTION OF THE RIVETS AT FRAMES 05 AND 07 (S/N 2)							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 53.315	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-00-00-220-812PROC. REF: AMM 53-00-00-220-812								
53-00-00-370-801-01	APPLICATION OF CORROSION INHIBITOR COMPOUND IN FUSELAGE AREAS							Service ATA:53
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-00-00-370-801PROC. REF: AMM 53-00-00-370-801								
53-10-00-200-808-01 ^S	INSPECTION OF THE NLG BAY							Service ATA:53
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 53.095	AFL	7304						
PKG:15								
PROC. REF: AMM 53-10-00-200-808PROC. REF: AMM 53-10-00-200-808								
53-10-00-200-808-01C	INSPECTION OF THE NLG BAY (CPCP)							Service ATA:53
	MOS	11-Dec-25	12 (+1m)		11-Dec-26	11-Jan-27	231 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-10-00-200-808PROC. REF: AMM 53-10-00-200-808								
53-10-00-200-810-01	INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 - GENERAL VISUAL INSPECTION							Service ATA:53
	MOS	12-Jun-09						
	HRS	10850.2						
WC#: 53.120	AFL	5878	3750		9628		2315	
PROC. REF: AMM 53-10-00-200-810PROC. REF: AMM 53-10-00-200-810								
53-10-00-200-810-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)							Service ATA:53
	MOS	12-Jun-09						MANDATORY 5-40
	HRS	10850.2						
WC#: 53.120	AFL	5878	3750		9628		2315	
PROC. REF: AMM 53-10-00-200-810PROC. REF: AMM 53-10-00-200-810								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-200-810-02	INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 - DETAILED INSPECTION IN SPECIFIC AREAS							Service ATA:53
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 53-10-00-200-810PROC. REF: AMM 53-10-00-200-810								
53-10-00-200-810-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)							Service ATA:53
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 53-10-00-200-810PROC. REF: AMM 53-10-00-200-810								
53-10-00-210-802-01	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT							Service ATA:53
	MOS	17-Feb-26	24 (+1m)		17-Feb-28	17-Mar-28	664 d (+29)	
	HRS	13885.3	4000		17885.3		3989	
WC#: 53.0301	AFL	7304						
								PKG:16
PROC. REF: AMM 53-10-00-210-802PROC. REF: AMM 53-10-00-210-802								
53-10-00-220-801-01 ^S	DETAILED INSPECTION OF THE STATIC PRESSURE PROBES AND OF THE FUSELAGE SKIN IN THE PROBE AREAS							Service ATA:53
	MOS	17-Feb-26	24 (+1m)					RVSM
	HRS	13885.3						
WC#: 53.260	AFL	7304						
								PKG:16
PROC. REF: AMM 53-10-00-220-801PROC. REF: AMM 53-10-00-220-801								
53-10-00-220-802-01 ^S	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT							Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.0302	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 53-10-00-220-802PROC. REF: AMM 53-10-00-220-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)							Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-10-00-220-802PROC. REF: AMM 53-10-00-220-802								
53-10-01-250-801-01	EDDY CURRENT INSPECTION OF THE FRAME 0 STIFFENER TIP							Service ATA:53
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 53.170	AFL	6741	3750 (+3%)		10491	10603.5	3178 (+112.5)	
PROC. REF: AMM 53-10-01-250-801PROC. REF: AMM 53-10-01-250-801								
53-10-03-220-801-03 ^S	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS - DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS.							Service ATA:53
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
	AFL	6741	7500					
PROC. REF: AMM 53-10-03-220-801PKG:32 PROC. REF: AMM 53-10-03-220-801								
53-10-03-220-801-03C	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS - DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)							Service ATA:53
	MOS	19-Dec-21	144 (+2m)		19-Dec-33	19-Feb-34	2796 d (+62)	CPCP
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 53-10-03-220-801PROC. REF: AMM 53-10-03-220-801								
53-10-03-250-801-01	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR FRAME EDGING							Service ATA:53
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 53.130	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-10-03-250-801PROC. REF: AMM 53-10-03-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-03-250-801-01A	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR FRAME EDGING (MANDATORY 5-40)							Service ATA:53
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5						
WC#: 53.130	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-10-03-250-801PROC. REF: AMM 53-10-03-250-801								
53-10-33-220-802-01	INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS							Service ATA:53
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 53.230	AFL	0						
PROC. REF: AMM 53-10-33-220-802PROC. REF: AMM 53-10-33-220-802								
53-10-33-220-802-01C	INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS (CPCP)							Service ATA:53
	MOS/MSC	07-Feb-91	O/C					CPCP
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-10-33-220-802PROC. REF: AMM 53-10-33-220-802								
53-10-39-220-801-01 ^S	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES							Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.220	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 53-10-39-220-801PROC. REF: AMM 53-10-39-220-801								
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-10-39-220-801PROC. REF: AMM 53-10-39-220-801								
53-10-39-220-802-01	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES							Service ATA:53
	MOS	19-Dec-21	144 (+2m)		19-Dec-33	19-Feb-34	2796 d (+62)	
	HRS	13275.5						
WC#: 53.240	AFL	6741	5030		11771		4458	
								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-10-39-220-802PROC. REF: AMM 53-10-39-220-802								
53-10-39-220-802-01A	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (MANDATORY 5-40)							Service ATA:53
	MOS	07-Feb-91						FD
	HRS	0						
	AFL	0	5030		7978 (M)		665	
	APH	0						
PROC. REF: AMM 53-10-39-220-802PROC. REF: AMM 53-10-39-220-802								
53-10-39-220-802-01C	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							Service ATA:53
	MOS	19-Dec-21	144 (+2m)		19-Dec-33	19-Feb-34	2796 d (+62)	CPCP
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 53-10-39-220-802PROC. REF: AMM 53-10-39-220-802								
53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR							Service ATA:53
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 53.200	AFL	0						
PROC. REF: AMM 53-10-41-220-801PROC. REF: AMM 53-10-41-220-801								
53-10-41-220-801-01A	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR (MANDATORY 5-40)							Service ATA:53
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 53.200	AFL	0						
PROC. REF: AMM 53-10-41-220-801PROC. REF: AMM 53-10-41-220-801								
53-10-43-220-801-01	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NLG WELL LH WALL							Service ATA:53
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 53.097	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-10-43-220-801PROC. REF: AMM 53-10-43-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-43-220-801-01A	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NOSE LANDING GEAR (NLG) WELL LH WALL (MANDATORY 5-40)							Service ATA:53
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5						
WC#: 53.097	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-10-43-220-801PROC. REF: AMM 53-10-43-220-801								
53-11-00-210-801-01	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA							Service ATA:53
	MOS/MSC	05-Jun-13	O/C					
	HRS	12205.82						
WC#: 53.0201	AFL	6354						
PROC. REF: AMM 53-11-00-210-801PROC. REF: AMM 53-11-00-210-801								
53-11-00-210-801-02 ^S	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA							Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 53-11-00-210-801PROC. REF: AMM 53-11-00-210-801								PKG:16
53-11-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)							Service ATA:53
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-11-00-210-801PROC. REF: AMM 53-11-00-210-801								
53-11-00-760-801-01 ^S	CHECK OF THE NOSE CONE ELECTRICAL BONDING							Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 53.250	AFL	7304						
PROC. REF: AMM 53-11-00-760-801PROC. REF: AMM 53-11-00-760-801								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-11-21-960-801-01	REPLACEMENT OF THE NOSE CONE SEAL							Service ATA:53
	MOS	22-Dec-23						
	HRS	13641						
WC#: 53.270	AFL	7052	7500		14552		7239	
PROC. REF: AMM 53-11-21-960-801PROC. REF: AMM 53-11-21-960-801								
PKG:31								
53-30-00-210-802-01 ^S	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN							Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 53.0401	AFL	7304						
PROC. REF: AMM 53-30-00-210-802PROC. REF: AMM 53-30-00-210-802								
PKG:16								
53-30-00-220-801-01 ^S	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR							Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.0402	AFL	7052	3750					
PROC. REF: AMM 53-30-00-220-801PROC. REF: AMM 53-30-00-220-801								
PKG:31								
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR (CPCP)							Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-30-00-220-801PROC. REF: AMM 53-30-00-220-801								
53-30-00-220-807-01 ^S	DETAILED INSPECTION OF THE PASSENGER CABIN ABOVE THE FLOOR							Service ATA:53
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 53.0402	AFL	6741	7500					
PROC. REF: AMM 53-30-00-220-807PROC. REF: AMM 53-30-00-220-807								
PKG:32								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-250-801-01	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES							Service ATA:53
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 53.160	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-30-00-250-801PROC. REF: AMM 53-30-00-250-801								
53-30-00-250-801-01A	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES (MANDATORY 5-40)							Service ATA:53
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5						
WC#: 53.160	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-30-00-250-801PROC. REF: AMM 53-30-00-250-801								
53-30-00-250-802-01	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS							Service ATA:53
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 53.150	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-30-00-250-802PROC. REF: AMM 53-30-00-250-802								
53-30-00-250-802-01A	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS (MANDATORY 5-40)							Service ATA:53
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5						
WC#: 53.150	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-30-00-250-802PROC. REF: AMM 53-30-00-250-802								
53-30-03-960-801-01	REPLACEMENT OF THE ALUMINUM LIGHTNING DIVERTER STRIPS ON REAR TANK							Service ATA:53
	MOS/MSC	07-Feb-91	A/R					
	HRS	0						
WC#: 53.290	AFL	0						
PROC. REF: AMM 53-30-03-960-801PROC. REF: AMM 53-30-03-960-801								
53-40-00-200-804-01 ^S	INSPECTION OF THE MLG BAYS - LH MLG BAY							Service ATA:53
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 53.090	AFL	7304						
PROC. REF: AMM 53-40-00-200-804PROC. REF: AMM 53-40-00-200-804								

PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-200-804-01C	INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)							Service ATA:53
	MOS	11-Dec-25	12 (+1m)		11-Dec-26	11-Jan-27	231 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-40-00-200-804PROC. REF: AMM 53-40-00-200-804								
53-40-00-200-804-02 ^S	INSPECTION OF THE MLG BAYS - RH MLG BAY							Service ATA:53
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 53.090	AFL	7304						
PROC. REF: AMM 53-40-00-200-804PROC. REF: AMM 53-40-00-200-804								
53-40-00-200-804-02C	INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)							Service ATA:53
	MOS	11-Dec-25	12 (+1m)		11-Dec-26	11-Jan-27	231 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-40-00-200-804PROC. REF: AMM 53-40-00-200-804								
53-40-00-200-810-01	INSPECTION OF THE CENTER WING LOWER PANEL FROM FR15 TO FR19							Service ATA:53
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
PROC. REF: AMM 53-40-00-200-810PROC. REF: AMM 53-40-00-200-810								
53-40-00-200-810-01A	INSPECTION OF THE CENTER WING LOWER PANEL FROM FR15 TO FR19 (MANDATORY 5-40)							Service ATA:53
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
PROC. REF: AMM 53-40-00-200-810PROC. REF: AMM 53-40-00-200-810								
53-40-00-210-802-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS							Service ATA:53
	MOS	17-Feb-26	24 (+1m)		17-Feb-28	17-Mar-28	664 d (+29)	
	HRS	13885.3	4000		17885.3		3989	
WC#: 53.0601	AFL	7304						

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-40-00-210-802PROC. REF: AMM 53-40-00-210-802								
53-40-00-220-801-01	^S	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS						Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.0602	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 53-40-00-220-801PROC. REF: AMM 53-40-00-220-801								
53-40-00-220-801-01C		DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)						Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-40-00-220-801PROC. REF: AMM 53-40-00-220-801								
53-40-00-220-802-01	^S	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS						Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.050	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 53-40-00-220-802PROC. REF: AMM 53-40-00-220-802								
53-40-00-220-802-01C		DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)						Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-40-00-220-802PROC. REF: AMM 53-40-00-220-802								
53-40-00-270-801-01	^S	ULTRASONIC INSPECTION FOR CORROSION AROUND THE FASTENERS OF THE FRONT CENTER PANEL AHEAD OF FRAME 10						Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.280	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 53-40-00-270-801PROC. REF: AMM 53-40-00-270-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-270-801-01C	ULTRASONIC-INSPECTION FOR CORROSION AROUND THE FASTENERS OF THE FRONT CENTER PANEL AHEAD OF FRAME 10 (CPCP)							Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-40-00-270-801PROC. REF: AMM 53-40-00-270-801								
53-40-06-220-801-01	DETAILED INSPECTION OF THE CORROSION ON CENTERWING REAR SPAR							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
WC#: 53.310	AFL	0						
PROC. REF: AMM 53-40-06-220-801PROC. REF: AMM 53-40-06-220-801								
53-40-07-280-802-01	SPECIFIC DETAILED INSPECTION (SDI) OF THE REPAIRED AREA ON CENTERWING LOWER PANEL							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-40-07-280-802PROC. REF: AMM 53-40-07-280-802								
53-40-07-280-803-01A	SPECIAL DETAILED INSPECTION OF THE REPAIRED AREAS ON CENTERWING LOWER PANEL							Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-40-07-280-802PROC. REF: AMM 53-40-07-280-802								
53-41-00-220-801-01 ^S	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING							Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								PKG:16
53-41-00-220-801-01C	DETAILED INSPECTION OF THE UPPER LH WING ROOT BOLT RECESSES (CPCP)							Service ATA:53
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-00-220-801-02	^S	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING						Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								PKG:16
53-41-00-220-801-02C		DETAILED INSPECTION OF THE UPPER RH WING ROOT BOLT RECESSES (CPCP)						Service ATA:53
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								
53-41-00-220-802-01	^S	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING						Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.110	AFL	7052	3750					
PROC. REF: AMM 53-41-00-220-802PROC. REF: AMM 53-41-00-220-802								PKG:31
53-41-00-220-802-01A		DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING (MANDATORY 5-40)						Service ATA:53
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641						
WC#: 53.110	AFL	7052	7500		14552		7239	
PROC. REF: AMM 53-41-00-220-802PROC. REF: AMM 53-41-00-220-802								
53-41-00-220-802-02	^S	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING						Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 53-41-00-220-802PROC. REF: AMM 53-41-00-220-802								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-00-220-802-02A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING (MANDATORY 5-40)							Service ATA:53
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641						
	AFL	7052	7500		14552		7239	
PROC. REF: AMM 53-41-00-220-802PROC. REF: AMM 53-41-00-220-802								
53-41-00-620-802-01	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH WING ROOT UPPER BOLT RECESSES							Service ATA:53
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
WC#: 57.240	AFL	5878						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-41-00-620-802-02	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH WING ROOT UPPER BOLT RECESSES							Service ATA:53
	MOS/MSC	12-Jun-09	O/C					
	HRS	10850.2						
WC#: 57.250	AFL	5878						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53-41-01-640-801-01 ^S	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - LH LINK ROD							Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.030	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 53-41-01-640-801PROC. REF: AMM 53-41-01-640-801								
53-41-01-640-801-02 ^S	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - RH LINK ROD							Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.030	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 53-41-01-640-801PROC. REF: AMM 53-41-01-640-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-50-00-210-804-02	^S	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT						Service ATA:53
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 53.080	AFL	7304						
PROC. REF: AMM 53-50-00-210-804PROC. REF: AMM 53-50-00-210-804								PKG:15
53-50-00-210-804-02C		GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)						Service ATA:53
	MOS	11-Dec-25	12 (+1m)		11-Dec-26	11-Jan-27	231 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-50-00-210-804PROC. REF: AMM 53-50-00-210-804								
53-50-00-210-806-01	^S	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT						Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 53.0701	AFL	7304						
PROC. REF: AMM 53-50-00-210-806PROC. REF: AMM 53-50-00-210-806								PKG:16
53-50-00-210-806-01C		GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)						Service ATA:53
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-50-00-210-806PROC. REF: AMM 53-50-00-210-806								
53-50-00-210-807-01		GENERAL VISUAL INSPECTION APU OF THE APU AREA						Service ATA:53
	MOS/MSC	26-Nov-14	O/C					
	HRS	13029.05						
WC#: 49.005	AFL	6673						
PROC. REF: AMM 53-50-00-210-807PROC. REF: AMM 53-50-00-210-807								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-50-00-210-807-02	^S	GENERAL VISUAL INSPECTION OF THE APU AREA						Service ATA:53
	MOS	17-Feb-26	12					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 53-50-00-210-807PROC. REF: AMM 53-50-00-210-807								PKG:15
53-50-00-220-803-01	^S	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT						Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 53.0702	AFL	7052	3750					
PROC. REF: AMM 53-50-00-220-803PROC. REF: AMM 53-50-00-220-803								PKG:31
53-50-00-220-803-01A		DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT						Service ATA:53
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641						
	AFL	7052	3750		10802		3489	
PROC. REF: AMM 53-50-00-220-803PROC. REF: AMM 53-50-00-220-803								
53-50-00-220-803-01C		DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)						Service ATA:53
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 53-50-00-220-803PROC. REF: AMM 53-50-00-220-803								
53-50-00-220-805-01		DETAILED INSPECTION OF THE REAR COMPARTMENT						Service ATA:53
	MOS/MSC	05-Jun-13	O/C					
	HRS	12205.82						
WC#: 53.082	AFL	6354						
PROC. REF: AMM 53-50-00-220-805PROC. REF: AMM 53-50-00-220-805								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-50-00-220-805-02	^S	DETAILED INSPECTION OF THE REAR COMPARTMENT						Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 53-50-00-220-805PROC. REF: AMM 53-50-00-220-805								PKG:16
53-50-00-220-805-02C		DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)						Service ATA:53
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 53-50-00-220-805PROC. REF: AMM 53-50-00-220-805								
53-50-00-220-807-01		DETAILED INSPECTION OF THE FRAME 30 UPPER PART						Service ATA:53
	MOS	06-Apr-22						
	HRS	13355.8						
	AFL	6803	3750		10553		3240	
PROC. REF: AMM 53-50-00-220-807PROC. REF: AMM 53-50-00-220-807								
53-50-00-220-807-01A		DETAILED INSPECTION OF THE FRAME 30 UPPER PART						Service ATA:53
	MOS	06-Apr-22						MANDATORY 5-40
	HRS	13355.8						
	AFL	6803	3750		10553		3240	
PROC. REF: AMM 53-50-00-220-807PROC. REF: AMM 53-50-00-220-807								
53-50-30-250-802-01		EDDY-CURRENT INSPECTION OF THE REAR EDGE OF BEAMS AT FRAME 30						Service ATA:53
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 53.180	AFL	6741	3750		10491		3178	
PROC. REF: AMM 53-50-30-250-802PROC. REF: AMM 53-50-30-250-802								
53-60-00-760-801-01	^S	CHECK OF THE FUSELAGE VENTRAL FAIRING ELECTRICAL BONDING - FUSELAGE CENTER LOWER FAIRING (150A)						Service ATA:53
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641						
WC#: 53.255	AFL	7052						

PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-60-00-760-801PROC. REF: AMM 53-60-00-760-801								
53-80-00-200-801-01	S	CHECK OF THE CONDENSATION AND STREAM WATER DRAINS						Service ATA:53
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 51.020	AFL	7304						
PKG:16								
PROC. REF: AMM 53-80-00-200-801PROC. REF: AMM 53-80-00-200-801								
53-80-01-710-801-01		OPERATIONAL TEST OF THE WATER DETECTION SYSTEM - "AFT WATER LEAK" PCB (53MD)						Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-80-01-710-801PROC. REF: AMM 53-80-01-710-801								
53-80-01-710-801-02		OPERATIONAL TEST OF THE WATER DETECTION SYSTEM - "AFT WATER LEAK" SENSOR (55MD)						Service ATA:53
	MOS/MSC	07-Feb-91	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-80-01-710-801PROC. REF: AMM 53-80-01-710-801								
53-80-01-900-801-01		REMOVAL / INSTALLATION OF THE WATER DETECTION SENSOR - "AFT WATER LEAK" SENSOR (55MD)						Component ATA:53
PN:PN	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-80-01-900-801PROC. REF: AMM 53-80-01-900-801								
53-80-09-710-801-01	S	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS						Service ATA:53
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 51.050	AFL	7052	3750					
PKG:31								
PROC. REF: AMM 53-80-09-710-801PROC. REF: AMM 53-80-09-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
534A01 ^U	LANDING LIGHT LEFT LENS							Component ATA:53
PN:SPSF900-10-4-0	MOS/MSC	14-Mar-01	O/C					
SN:351	HRS	4661						
	AFL	2106						
534A02 ^U	LANDING LIGHT RIGHT LENS							Component ATA:53
PN:SPSF900-9-4-0	MOS/MSC	14-Mar-01	O/C					
SN:46	HRS	4661						
	AFL	2106						
ATA 54 - NACELLES/PYLONS								
54-00-00-210-810-01 ^S	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ)							Service ATA:54
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	300 (+100)					
WC#: 54.0101	AFL	7304						
PROC. REF: AMM 54-00-00-210-810PROC. REF: AMM 54-00-00-210-810								PKG:42
54-00-00-210-810-01C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ) (CPCP)							Service ATA:54
	MOS	17-Feb-26	12 (+1m)	17-Feb-27	17-Mar-27	299 d (+28)	CPCP	
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 54-00-00-210-810PROC. REF: AMM 54-00-00-210-810								
54-00-00-210-810-02 ^S	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ)							Service ATA:54
	MOS	17-Sep-25	12 (+1m)					
	HRS	13856.1	300 (+100)					
WC#: 54.0101	AFL	7271						
PROC. REF: AMM 54-00-00-210-810PROC. REF: AMM 54-00-00-210-810								PKG:62
54-00-00-210-810-02C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ) (CPCP)							Service ATA:54
	MOS	17-Sep-25	12 (+1m)	17-Sep-26	17-Oct-26	146 d (+30)	CPCP	
	HRS	13856.1						
	AFL	7271						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
PROC. REF: AMM 54-00-00-210-810PROC. REF: AMM 54-00-00-210-810								
54-00-00-210-811-01	^S	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE						Service ATA:54
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	300 (+100)					
WC#: 54.0201	AFL	7304						
								PKG:52
PROC. REF: AMM 54-00-00-210-811PROC. REF: AMM 54-00-00-210-811								
54-00-00-220-801-01	^S	DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ)						Service ATA:54
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 54.0102	AFL	6741	7500					
								PKG:32
PROC. REF: AMM 54-00-00-220-801PROC. REF: AMM 54-00-00-220-801								
54-00-00-220-801-01C		DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ) (CPCP)						Service ATA:54
	MOS	19-Dec-21	144 (+2m)	19-Dec-33	19-Feb-34	2796 d (+62)	CPCP	
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 54-00-00-220-801PROC. REF: AMM 54-00-00-220-801								
54-00-00-220-801-02	^S	DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ)						Service ATA:54
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 54.0102	AFL	6741	7500					
								PKG:32
PROC. REF: AMM 54-00-00-220-801PROC. REF: AMM 54-00-00-220-801								
54-00-00-220-801-02C		DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ) (CPCP)						Service ATA:54
	MOS	19-Dec-21	144 (+2m)	19-Dec-33	19-Feb-34	2796 d (+62)	CPCP	
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 54-00-00-220-801PROC. REF: AMM 54-00-00-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-11-00-610-801-01	^S	SERVICING OF THE ENGINE COWLINGS - ENGINE 1 COWLINGS						Service ATA:54
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 54.060	AFL	7304						
PROC. REF: AMM 54-11-00-610-801PROC. REF: AMM 54-11-00-610-801								PKG:16
54-11-00-610-801-02	^S	SERVICING OF THE ENGINE COWLINGS - ENGINE 2 COWLINGS						Service ATA:54
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 54.060	AFL	7304						
PROC. REF: AMM 54-11-00-610-801PROC. REF: AMM 54-11-00-610-801								PKG:16
54-11-00-610-801-03	^S	SERVICING OF THE ENGINE COWLINGS - ENGINE 3 COWLINGS						Service ATA:54
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 54.060	AFL	7304						
PROC. REF: AMM 54-11-00-610-801PROC. REF: AMM 54-11-00-610-801								PKG:16
54-11-00-760-801-01	^S	CHECK OF THE ENGINE COWLING ELECTRICAL BONDING						Service ATA:54
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 54.125	AFL	7304						
PROC. REF: AMM 54-11-00-760-801PROC. REF: AMM 54-11-00-760-801								PKG:16
54-13-05-210-801-01	^S	GENERAL VISUAL INSPECTION OF THE ENGINE 2 AFTERBODY						Service ATA:54
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
WC#: 78.015	AFL	7304						
PROC. REF: AMM 54-13-05-210-801PROC. REF: AMM 54-13-05-210-801								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-13-05-220-801-01	DETAILED INSPECTION OF THE NO. 2 ENGINE AFTERBODY							Service ATA:54
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 54-13-05-220-801PROC. REF: AMM 54-13-05-220-801								
54-13-05-220-801-02 ^S	DETAILED INSPECTION OF THE ENGINE 2 AFTERBODY							Service ATA:54
	MOS	22-Dec-23	72					
	HRS	13641						
	AFL	7052	3750					
PROC. REF: AMM 54-13-05-220-801PROC. REF: AMM 54-13-05-220-801								
54-14-01-280-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLE FAN INNER DUCTS - ENGINE 1 (L4EZ)							Service ATA:54
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 54.120	AFL	0						
PROC. REF: AMM 54-14-01-280-801PROC. REF: AMM 54-14-01-280-801								
54-14-01-280-801-02	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLE FAN INNER DUCTS - ENGINE 3 (R4EZ)							Service ATA:54
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 54.120	AFL	0						
PROC. REF: AMM 54-14-01-280-801PROC. REF: AMM 54-14-01-280-801								
ATA 55 - STABILIZERS								
55-00-00-210-801-01	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT							Service ATA:55
	MOS	17-Feb-26	24 (+1m)		17-Feb-28	17-Mar-28	664 d (+29)	
	HRS	13885.3	4000		17885.3		3989	
WC#: 55.0101	AFL	7304						
PROC. REF: AMM 55-00-00-210-801PROC. REF: AMM 55-00-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)							Service ATA:55
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 55-00-00-210-801PROC. REF: AMM 55-00-00-210-801								
55-00-00-220-801-01 ^S	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT							Service ATA:55
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 55.0102	AFL	7052	3750					
PROC. REF: AMM 55-00-00-220-801PROC. REF: AMM 55-00-00-220-801								
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)							Service ATA:55
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 55-00-00-220-801PROC. REF: AMM 55-00-00-220-801								
55-00-00-370-801-01	APPLICATION OF CORROSION INHIBITOR COMPOUND IN STABILIZER AREAS							Service ATA:55
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 55-00-00-370-801PROC. REF: AMM 55-00-00-370-801								
55-00-00-760-801-01 ^S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RUDDER							Service ATA:55
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 55.110	AFL	7304						
PROC. REF: AMM 55-00-00-760-801PROC. REF: AMM 55-00-00-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-00-00-760-801-02	^S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - LH ELEVATOR						Service ATA:55
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 55-00-00-760-801PROC. REF: AMM 55-00-00-760-801								PKG:16
55-00-00-760-801-03	^S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RH ELEVATOR						Service ATA:55
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 55-00-00-760-801PROC. REF: AMM 55-00-00-760-801								PKG:16
55-10-00-220-801-01	^S	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE						Service ATA:55
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
	AFL	6741	7500					
PROC. REF: AMM 55-10-00-220-801PROC. REF: AMM 55-10-00-220-801								PKG:32
55-10-00-220-801-01C		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE (CPCP)						Service ATA:55
	MOS	19-Dec-21	144 (+2m)	19-Dec-33	19-Feb-34	2796 d (+62)	CPCP	
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 55-10-00-220-801PROC. REF: AMM 55-10-00-220-801								
55-10-00-220-802-01	^S	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS						Service ATA:55
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
	AFL	6741	7500					
PROC. REF: AMM 55-10-00-220-802PROC. REF: AMM 55-10-00-220-802								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-00-220-802-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS (CPCP)							Service ATA:55
	MOS	19-Dec-21	144 (+2m)		19-Dec-33	19-Feb-34	2796 d (+62)	CPCP
	HRS	13275.5						
	AFL	6741						
PROC. REF: AMM 55-10-00-220-802PROC. REF: AMM 55-10-00-220-802								
55-10-00-270-801-01 ^S	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS							Service ATA:55
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 55.030	AFL	7052	3750					
PROC. REF: AMM 55-10-00-270-801PROC. REF: AMM 55-10-00-270-801								
55-10-00-270-801-01A	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS (MANDATORY 5-40)							Service ATA:55
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641						
WC#: 55.030	AFL	7052	3750		10802		3489	
PROC. REF: AMM 55-10-00-270-801PROC. REF: AMM 55-10-00-270-801								
55-10-00-640-802-01 ^S	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK AND ACTUATOR UPPER HINGE - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)							Service ATA:55
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 27.237	AFL	7304						
PROC. REF: AMM 55-10-00-640-802PROC. REF: AMM 55-10-00-640-802								
55-10-01-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER							Component ATA:55
PN:FGFB330	MOS/MSC	07-Feb-91	O/C					
SN:93304	HRS	0		TSN 0				
WC#: 55.065	AFL	0						
PROC. REF: AMM 55-10-01-900-801PROC. REF: AMM 55-10-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-03-640-801-01	S	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM						Service ATA:55
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 55-10-03-640-801PROC. REF: AMM 55-10-03-640-801								PKG:16
55-10-31-220-801-01	S	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS						Service ATA:55
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 55.090	AFL	7052	3750					
PROC. REF: AMM 55-10-31-220-801PROC. REF: AMM 55-10-31-220-801								PKG:31
55-10-31-220-801-01A		DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)						Service ATA:55
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641						
WC#: 55.090	AFL	7052	3750		10802		3489	
PROC. REF: AMM 55-10-31-220-801PROC. REF: AMM 55-10-31-220-801								
55-10-33-640-801-01		LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS						Service ATA:55
	MOS	13-Jan-25	36 (+1m)	Adj -25d	19-Dec-27	19-Jan-28	604 d (+31)	
	HRS	13790.5	600 (+40)		14390.5	14430.5	494.2 (+40)	
WC#: 27.235	AFL	7204						
PROC. REF: AMM 55-10-33-640-801PROC. REF: AMM 55-10-33-640-801								
55-10-39-220-801-01		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE						Service ATA:55
	MOS	07-Feb-91						
	HRS	0						
WC#: 55.040	AFL	0	T:11250		11250		3937	
PROC. REF: AMM 55-10-39-220-801PROC. REF: AMM 55-10-39-220-801								
55-10-39-220-801-01A		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS (MANDATORY 5-40)						Service ATA:55
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
WC#: 55.040	AFL	0	T:11250		11250		3937	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
PROC. REF: AMM 55-10-39-220-801PROC. REF: AMM 55-10-39-220-801								
55-10-39-220-801-02	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE							Service ATA:55
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 55-10-39-220-801PROC. REF: AMM 55-10-39-220-801								
55-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ELEVATORS - LH ELEVATOR							Component ATA:55
PN:PN	MOS/MSC	26-Jun-09	O/C	TSR 0				
SN:UNKNOWN	HRS	10850.2		TSR 0				
WC#: 55.070	AFL	5878		TSR 0				
PROC. REF: AMM 55-20-01-900-801PROC. REF: AMM 55-20-01-900-801								
55-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ELEVATORS - RH ELEVATOR							Component ATA:55
PN:PN	MOS/MSC	26-Jun-09	O/C	TSR 0				
SN:UNKNOWN	HRS	10850.2		TSR 0				
WC#: 55.070	AFL	5878		TSR 0				
PROC. REF: AMM 55-20-01-900-801PROC. REF: AMM 55-20-01-900-801								
55-20-03-640-801-01 ^S	LUBRICATION OF THE ELEVATOR BEARINGS - LH ELEVATOR							Service ATA:55
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 55.070	AFL	6741	7500					
PROC. REF: AMM 55-20-03-640-801PROC. REF: AMM 55-20-03-640-801								PKG:32
55-20-03-640-801-02 ^S	LUBRICATION OF THE ELEVATOR BEARINGS - RH ELEVATOR							Service ATA:55
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 55.070	AFL	6741	7500					
PROC. REF: AMM 55-20-03-640-801PROC. REF: AMM 55-20-03-640-801								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-03-640-802-01	^S	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES						Service ATA:55
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 27.170	AFL	7304						
PROC. REF: AMM 55-20-03-640-802PROC. REF: AMM 55-20-03-640-802								PKG:15
55-20-05-640-801-01	^S	LUBRICATION OF THE ELEVATOR CONTROL BEARINGS AND U-JOINTS						Service ATA:55
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
WC#: 27.240	AFL	7304						
PROC. REF: AMM 55-20-05-640-801PROC. REF: AMM 55-20-05-640-801								PKG:5
55-30-00-270-801-01	^S	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS						Service ATA:55
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 55.050	AFL	7052	3750					
PROC. REF: AMM 55-30-00-270-801PROC. REF: AMM 55-30-00-270-801								PKG:31
55-30-00-270-801-01A		ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS (MANDATORY 5-40)						Service ATA:55
	MOS	22-Dec-23						MANDATORY 5-40
	HRS	13641						
WC#: 55.050	AFL	7052	3750		10802		3489	
PROC. REF: AMM 55-30-00-270-801PROC. REF: AMM 55-30-00-270-801								
55-30-01-900-801-01		REMOVAL / INSTALLATION OF THE VERTICAL STABILIZER						Component ATA:55
PN:FGFB310	MOS/MSC	07-Feb-91	O/C					
SN:1696	HRS	0		TSN 0				
WC#: 55.075	AFL	0						
PROC. REF: AMM 55-30-01-900-801PROC. REF: AMM 55-30-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-01-900-801-01	REMOVAL / INSTALLATION OF THE RUDDER							Component ATA:55
PN:FGFB321-1	MOS/MSC	26-Jun-09	O/C					
SN:16RA36	HRS	10850.33						
WC#: 55.080	AFL	5878						
PROC. REF: AMM 55-40-01-900-801PROC. REF: AMM 55-40-01-900-801								
55-40-05-640-801-01	LUBRICATION OF THE RUDDER BEARINGS							Service ATA:55
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 55.080	AFL	6741	7500					
PROC. REF: AMM 55-40-05-640-801PKG:32								
55-40-05-640-802-01	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES							Service ATA:55
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
WC#: 27.100	AFL	7304						
PROC. REF: AMM 55-40-05-640-802PKG:15								
551101	LH SPRING LOADED RIB							Component ATA:55
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 55.060	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
551121	RH SPRING LOADED RIB							Component ATA:55
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 55.060	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
ATA 56 - WINDOWS								
56-10-01-900-801-01	REMOVAL / INSTALLATION OF THE WINDSHIELDS - PILOT WINDSHIELD (L4HH)							Component ATA:56
PN:SPSF900-2-8-3	MOS/MSC	02-Dec-05	O/C	TSN 0				
SN:2379	HRS	8252.8		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
WC#: 56.010	AFL	4328		TSN 0				
PROC. REF: AMM 56-10-01-900-801PROC. REF: AMM 56-10-01-900-801								
56-10-01-900-801-02	REMOVAL / INSTALLATION OF THE WINDSHIELDS - COPILOT WINDSHIELD (R4HH)							Component ATA:56
PN:SPSF900-3-5-2	MOS/MSC	07-Feb-91	O/C					
SN:294	HRS	0		TSN 0				
WC#: 56.010	AFL	0						
PROC. REF: AMM 56-10-01-900-801PROC. REF: AMM 56-10-01-900-801								
56-10-01-900-801-03	REMOVAL / INSTALLATION OF THE WINDSHIELDS - FRONT WINDSHIELD (5HH)							Component ATA:56
PN:SPSF2M1-3-2	MOS/MSC	17-Dec-21	O/C					
SN:871	HRS	13275.5						
WC#: 56.010	AFL	6741						
PROC. REF: AMM 56-10-01-900-801PROC. REF: AMM 56-10-01-900-801								
56-10-07-900-801-01	REMOVAL / INSTALLATION OF THE RH LATERAL WINDOW - RH LATERAL WINDOW (R35HH)							Component ATA:56
PN:SPSF900-5-8-2	MOS/MSC	07-Mar-08	O/C	TSN 0				
SN:1863	HRS	10360.3		TSN 0				
WC#: 56.035	AFL	5544		TSN 0				
PROC. REF: AMM 56-10-07-900-801PROC. REF: AMM 56-10-07-900-801								
56-10-09-640-801-01 ^S	LUBRICATION OF THE OPENING WINDOW MECHANISM - LH SLIDING WINDOW (L35HH)							Service ATA:56
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 56.020	AFL	7304						
PROC. REF: AMM 56-10-09-640-801PROC. REF: AMM 56-10-09-640-801								
56-10-09-900-801-01	REMOVAL / INSTALLATION OF THE OPENING WINDOW - LH SLIDING WINDOW (L35HH)							Component ATA:56
PN:SPSF900-4-6-2	MOS/MSC	17-Dec-21	O/C					
SN:3004	HRS	13275.5						
WC#: 56.020	AFL	6741						
PROC. REF: AMM 56-10-09-900-801PROC. REF: AMM 56-10-09-900-801								

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-11-900-801-01	REMOVAL / INSTALLATION OF THE REAR WINDOWS - LH REAR WINDOW (L44HH)							Component ATA:56
PN:SPSF900-6-8-2	MOS/MSC	17-Apr-02	O/C	TSR 0				
SN:2713	HRS	5229.4		TSR 0				
WC#: 56.030	AFL	2413		TSR 0				
PROC. REF: AMM 56-10-11-900-801PROC. REF: AMM 56-10-11-900-801								
56-10-11-900-801-02	REMOVAL / INSTALLATION OF THE REAR WINDOWS - RH REAR WINDOW (R44HH)							Component ATA:56
PN:SPSF900-7-8-2	MOS/MSC	01-Jan-00	O/C	TSN 0				
SN:2340	HRS			TSN 0				
WC#: 56.030	AFL			TSN 0				
PROC. REF: AMM 56-10-11-900-801PROC. REF: AMM 56-10-11-900-801								
56-20-05-900-801-01	NO. 1 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20032	HRS	10853.9		TSN 0				
WC#: 56.040	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 1 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20045	HRS	10853.9		TSN 0				
WC#: 56.080	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 10 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20043	HRS	10853.9		TSN 0				
WC#: 56.070	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 10 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:19808	HRS	10850.2		TSN 0				
WC#: 56.110	AFL	5878		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01	NO. 11 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20042	HRS	10853.9		TSN 0				
WC#: 56.070	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 11 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:19802	HRS	10850.2		TSN 0				
WC#: 56.110	AFL	5878		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 12 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20044	HRS	10853.9		TSN 0				
WC#: 56.070	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 12 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:19810	HRS	10850.2		TSN 0				
WC#: 56.110	AFL	5878		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 2 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20031	HRS	10853.9		TSN 0				
WC#: 56.040	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 2 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20036	HRS	10853.9		TSN 0				
WC#: 56.080	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01	NO. 3 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20030	HRS	10853.9		TSN 0				
WC#: 56.040	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 3 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20034	HRS	10853.9		TSN 0				
WC#: 56.080	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 4 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20029	HRS	10853.9		TSN 0				
WC#: 56.050	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 4 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:19789	HRS	10850.2		TSN 0				
WC#: 56.090	AFL	5878		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 5 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20028	HRS	10853.9		TSN 0				
WC#: 56.050	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 5 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:19807	HRS	10850.2		TSN 0				
WC#: 56.090	AFL	5878		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01	NO. 6 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20027	HRS	10853.9		TSN 0				
WC#: 56.050	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 6 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:19791	HRS	10850.2		TSN 0				
WC#: 56.090	AFL	5878		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 7 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20038	HRS	10853.9		TSN 0				
WC#: 56.060	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 7 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20037	HRS	10853.9		TSN 0				
WC#: 56.100	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 8 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20040	HRS	10853.9		TSN 0				
WC#: 56.060	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 8 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20033	HRS	10853.9		TSN 0				
WC#: 56.100	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01	NO. 9 LEFT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20041	HRS	10853.9		TSN 0				
WC#: 56.060	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 9 RIGHT CABIN WINDOW							Component ATA:56
PN:SPSF2M8-3-0	MOS/MSC	23-Sep-09	O/C	TSN 0				
SN:20035	HRS	10853.9		TSN 0				
WC#: 56.100	AFL	5880		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
ATA 57 - WINGS								
57-00-00-210-801-01	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING							Service ATA:57
	MOS	17-Feb-26	24 (+1m)		17-Feb-28	17-Mar-28	664 d (+29)	
	HRS	13885.3	4000		17885.3		3989	
WC#: 57.0101	AFL	7304						
PKG:16								
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING (CPCP)							Service ATA:57
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-02	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING							Service ATA:57
	MOS	17-Feb-26	24 (+1m)		17-Feb-28	17-Mar-28	664 d (+29)	
	HRS	13885.3	4000		17885.3		3989	
WC#: 57.0101	AFL	7304						
PKG:16								
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING (CPCP)							Service ATA:57
	MOS	11-Dec-25	24 (+1m)		11-Dec-27	11-Jan-28	596 d (+31)	CPCP
	HRS	13869.7						
	AFL	7285						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-03 ^S	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING ANTI-ICING SYSTEM							Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-03A	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING ANTI-ICING SYSTEM (MANDATORY 5-40)							Service ATA:57
	MOS	17-Feb-26	26		17-Apr-28		724 d	
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-04 ^S	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING ANTI-ICING SYSTEM							Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-04A	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING ANTI-ICING SYSTEM (MANDATORY 5-40)							Service ATA:57
	MOS	17-Feb-26	26		17-Apr-28		724 d	
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-220-802-01	^S	DETAILED INSPECTION OF THE WINGS - LH WING						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.0102	AFL	7052	3750					
PROC. REF: AMM 57-00-00-220-802PROC. REF: AMM 57-00-00-220-802								PKG:31
57-00-00-220-802-01C		DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)						Service ATA:57
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 57-00-00-220-802PROC. REF: AMM 57-00-00-220-802								
57-00-00-220-802-02	^S	DETAILED INSPECTION OF THE WINGS - RH WING						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.0102	AFL	7052	3750					
PROC. REF: AMM 57-00-00-220-802PROC. REF: AMM 57-00-00-220-802								PKG:31
57-00-00-220-802-02C		DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)						Service ATA:57
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 57-00-00-220-802PROC. REF: AMM 57-00-00-220-802								
57-00-00-370-801-01		APPLICATION OF CORROSION INHIBITOR COMPOUND IN WING AREAS - RESTORATION OF CIC AT LH/RH WING LEADING EDGE BOX STRUCTURE						Service ATA:57
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 57-00-00-370-801PROC. REF: AMM 57-00-00-370-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-760-801-01	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AILERON						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.265	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16
57-00-00-760-801-02	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AILERON						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.265	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16
57-00-00-760-801-03	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH FLAPS						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.270	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16
57-00-00-760-801-04	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH FLAPS						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.270	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16
57-00-00-760-801-05	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH SLATS						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.280	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-760-801-06	^S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH SLATS						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.280	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16
57-00-00-760-801-07	^S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AIRBRAKES						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.275	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16
57-00-00-760-801-08	^S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AIRBRAKES						Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 57.275	AFL	7304						
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								PKG:16
57-00-01-900-800-01		LH WING						Component ATA:57
PN:FGFB101	MOS/MSC	19-Dec-21	O/C					
SN:95306	HRS	13275.5		TSN 13275.5				
WC#: 57.145	AFL	6741						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
57-00-01-900-800-02		RH WING						Component ATA:57
PN:FGFB101	MOS/MSC	19-Dec-21	O/C					
SN:95306	HRS	13275.5		TSN 13275.5				
WC#: 57.145	AFL	6741						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-290-801-01	^S	BORESCOPE INSPECTION OF THE WING TANKS						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.130	AFL	7052	3750					
PROC. REF: AMM 57-10-00-290-801PROC. REF: AMM 57-10-00-290-801								PKG:31
57-10-00-290-801-01C		BORESCOPE INSPECTION OF THE WING TANKS (CPCP)						Service ATA:57
	MOS	22-Dec-23	72 (+2m)		22-Dec-29	22-Feb-30	1338 d (+62)	CPCP
	HRS	13641						
	AFL	7052						
PROC. REF: AMM 57-10-00-290-801PROC. REF: AMM 57-10-00-290-801								
57-10-01-210-801-01		GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - LH WING						Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-01-210-801PROC. REF: AMM 57-10-01-210-801								
57-10-01-210-801-01A		GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - LH WING (MANDATORY 5-40)						Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-01-210-801PROC. REF: AMM 57-10-01-210-801								
57-10-01-210-801-02		GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - RH WING						Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-01-210-801PROC. REF: AMM 57-10-01-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-01-210-801-02A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-01-210-801PROC. REF: AMM 57-10-01-210-801								
57-10-14-220-801-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-14-220-801PROC. REF: AMM 57-10-14-220-801								
57-10-14-220-801-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-14-220-801PROC. REF: AMM 57-10-14-220-801								
57-10-14-220-801-02	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-220-801PROC. REF: AMM 57-10-14-220-801								
57-10-14-220-801-02A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-220-801PROC. REF: AMM 57-10-14-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-14-220-802-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-14-220-802PROC. REF: AMM 57-10-14-220-802								
57-10-14-220-802-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-14-220-802PROC. REF: AMM 57-10-14-220-802								
57-10-14-220-802-02	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-220-802PROC. REF: AMM 57-10-14-220-802								
57-10-14-220-802-02A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-220-802PROC. REF: AMM 57-10-14-220-802								
57-10-14-250-801-01	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-250-801PROC. REF: AMM 57-10-14-250-801								
57-10-14-250-801-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57-10-14-250-801PROC. REF: AMM 57-10-14-250-801								
57-10-14-250-801-02	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-250-801PROC. REF: AMM 57-10-14-250-801								
57-10-14-250-801-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-250-801PROC. REF: AMM 57-10-14-250-801								
57-10-14-250-802-01	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-250-802PROC. REF: AMM 57-10-14-250-802								
57-10-14-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-250-802PROC. REF: AMM 57-10-14-250-802								
57-10-14-250-802-02	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-250-802PROC. REF: AMM 57-10-14-250-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-14-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-14-250-802PROC. REF: AMM 57-10-14-250-802								
57-10-15-220-801-01	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-15-220-801PROC. REF: AMM 57-10-15-220-801								
57-10-15-220-801-01A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-15-220-801PROC. REF: AMM 57-10-15-220-801								
57-10-15-220-801-02	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-220-801PROC. REF: AMM 57-10-15-220-801								
57-10-15-220-801-02A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-220-801PROC. REF: AMM 57-10-15-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-15-220-802-01	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-15-220-802PROC. REF: AMM 57-10-15-220-802								
57-10-15-220-802-01A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250		3937	
	APH	0						
PROC. REF: AMM 57-10-15-220-802PROC. REF: AMM 57-10-15-220-802								
57-10-15-220-802-02	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-220-802PROC. REF: AMM 57-10-15-220-802								
57-10-15-220-802-02A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-220-802PROC. REF: AMM 57-10-15-220-802								
57-10-15-250-801-01	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS							
WC#: 57.120	AFL	0	T:11250		11250		3937	
PROC. REF: AMM 57-10-15-250-801PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-801-01A	SPECIAL DETAILED INSPECTION OF RIB 8 REAR WING SPAR SPLICE PLATE - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
WC#: 57.120	AFL	0	T:11250		11250		3937	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57-10-15-250-801PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-801-02	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-801PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-801-02A	SPECIAL DETAILED INSPECTION OF RIB 8 REAR WING SPAR SPLICE PLATE - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-801PROC. REF: AMM 57-10-15-250-801								
57-10-15-250-802-01	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-802PROC. REF: AMM 57-10-15-250-802								
57-10-15-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-802PROC. REF: AMM 57-10-15-250-802								
57-10-15-250-802-02	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-802PROC. REF: AMM 57-10-15-250-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-15-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-802PROC. REF: AMM 57-10-15-250-802								
57-10-15-250-803-01	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-803PROC. REF: AMM 57-10-15-250-803								
57-10-15-250-803-01A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-803PROC. REF: AMM 57-10-15-250-803								
57-10-15-250-803-02	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING							Service ATA:57
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-803PROC. REF: AMM 57-10-15-250-803								
57-10-15-250-803-02A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:11250		11250 (M)		3937	
PROC. REF: AMM 57-10-15-250-803PROC. REF: AMM 57-10-15-250-803								
57-41-13-640-801-01 ^S	LUBRICATION OF THE SLAT MECHANISMS							Service ATA:57
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 27.405	AFL	7304						
PROC. REF: AMM 57-41-13-640-801PROC. REF: AMM 57-41-13-640-801								

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-45-01-900-801-01		REMOVAL / INSTALLATION OF THE INBOARD SLATS - LH INBOARD SLAT						Component ATA:57
PN:FGFB133A7	MOS/MSC	23-Dec-03	O/C	TSR 0				
SN:176/443RA	HRS	6042.5		TSR 0				
WC#: 57.160	AFL	3040		TSR 0				
PROC. REF: AMM 57-45-01-900-801PROC. REF: AMM 57-45-01-900-801								
57-45-01-900-801-02		REMOVAL / INSTALLATION OF THE INBOARD SLATS - RH INBOARD SLAT						Component ATA:57
PN:FGFB133	MOS/MSC	07-Feb-91	O/C					
SN:101324	HRS	0		TSN 0				
WC#: 57.170	AFL	0						
PROC. REF: AMM 57-45-01-900-801PROC. REF: AMM 57-45-01-900-801								
57-45-13-900-801-01		REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - LH OUTBOARD SLAT						Component ATA:57
PN:FGFB134	MOS/MSC	13-Oct-92	O/C	TSN 0				
SN:118-319	HRS			TSN 0				
WC#: 57.160	AFL			TSN 0				
PROC. REF: AMM 57-45-13-900-801PROC. REF: AMM 57-45-13-900-801								
57-45-13-900-801-02		REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - RH OUTBOARD SLAT						Component ATA:57
PN:FGFB134	MOS/MSC	07-Feb-91	O/C					
SN:100321	HRS	0		TSN 0				
WC#: 57.170	AFL	0						
PROC. REF: AMM 57-45-13-900-801PROC. REF: AMM 57-45-13-900-801								
57-45-25-250-801-01		EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 5 AND 10						Service ATA:57
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 57.300	AFL	6741	7500		14241		6928	
PROC. REF: AMM 57-45-25-250-801PROC. REF: AMM 57-45-25-250-801								
57-45-25-250-801-02		EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 1 AND 4						Service ATA:57
	MOS	19-Dec-21						
	HRS	13275.5						
	AFL	6741	T:11250		17991		10678	
PROC. REF: AMM 57-45-25-250-801PROC. REF: AMM 57-45-25-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-55-00-700-801-01	^S	CHECK OF THE FLAP LATERAL CLEARANCE - LH WING						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.285	AFL	7052	3750					
PROC. REF: AMM 57-55-00-700-801PROC. REF: AMM 57-55-00-700-801								PKG:31
57-55-00-700-801-02	^S	CHECK OF THE FLAP LATERAL CLEARANCE - RH WING						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.290	AFL	7052	3750					
PROC. REF: AMM 57-55-00-700-801PROC. REF: AMM 57-55-00-700-801								PKG:31
57-55-01-900-801-01		REMOVAL / INSTALLATION OF THE INBOARD FLAPS - LH INBOARD FLAP						Component ATA:57
PN:FGFB161A5	MOS/MSC	19-Dec-21	O/C					
SN:LE320	HRS	13275.5						
WC#: 57.180	AFL	6741						
PROC. REF: AMM 57-55-01-900-801PROC. REF: AMM 57-55-01-900-801								
57-55-01-900-801-02		REMOVAL / INSTALLATION OF THE INBOARD FLAPS - RH INBOARD FLAP						Component ATA:57
PN:FGFB162A5	MOS/MSC	19-Dec-21	O/C					
SN:LE320	HRS	13275.5						
WC#: 57.180	AFL	6741						
PROC. REF: AMM 57-55-01-900-801PROC. REF: AMM 57-55-01-900-801								
57-55-05-900-801-01		REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - LH OUTBOARD FLAP						Component ATA:57
PN:FGFB163A3	MOS/MSC	19-Dec-21	O/C					
SN:LE486	HRS	13275.5						
WC#: 57.190	AFL	6741						
PROC. REF: AMM 57-55-05-900-801PROC. REF: AMM 57-55-05-900-801								
57-55-05-900-801-02		REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - RH OUTBOARD FLAP						Component ATA:57
PN:FGFB164A3	MOS/MSC	19-Dec-21	O/C					
SN:LE602	HRS	13275.5						
WC#: 57.190	AFL	6741						
PROC. REF: AMM 57-55-05-900-801PROC. REF: AMM 57-55-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-55-07-220-801-01	^S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - LH WING						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.150	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 57-55-07-220-801PROC. REF: AMM 57-55-07-220-801								
57-55-07-220-801-02	^S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - RH WING						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.150	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 57-55-07-220-801PROC. REF: AMM 57-55-07-220-801								
57-55-11-210-801-01	^S	GENERAL VISUAL INSPECTION OF THE FOREFLAP BRACKETS						Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.210	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 57-55-11-210-801PROC. REF: AMM 57-55-11-210-801								
57-55-13-640-801-01	^S	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - LH WING						Service ATA:57
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
								PKG:5
PROC. REF: AMM 57-55-13-640-801PROC. REF: AMM 57-55-13-640-801								
57-55-13-640-801-02	^S	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - RH WING						Service ATA:57
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3	800 (+40)					
	AFL	7304						
								PKG:5
PROC. REF: AMM 57-55-13-640-801PROC. REF: AMM 57-55-13-640-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-55-21-250-801-01	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5							Service ATA:57
	MOS	19-Dec-21						
	HRS	13275.5						
WC#: 57.200	AFL	6741	3750		10491		3178	
PROC. REF: AMM 57-55-21-250-801PROC. REF: AMM 57-55-21-250-801								
57-55-21-250-801-01A	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5 (MANDATORY 5-40)							Service ATA:57
	MOS	19-Dec-21						FD
	HRS	13275.5						
	AFL	6741	4770		11511		4198	
PROC. REF: AMM 57-55-21-250-801PROC. REF: AMM 57-55-21-250-801								
57-60-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERONS - LH AILERON							Component ATA:57
PN:F50B153	MOS/MSC	14-Mar-01	O/C					
SN:138309	HRS	4661		TSN 4661				
WC#: 57.140	AFL	2106		TSN 2106				
PROC. REF: AMM 57-60-01-900-801PROC. REF: AMM 57-60-01-900-801								
57-60-01-900-801-02	REMOVAL / INSTALLATION OF THE AILERONS - RH AILERON							Component ATA:57
PN:F50B153	MOS/MSC	14-Mar-01	O/C					
SN:138309	HRS	4661		TSN 4661				
WC#: 57.140	AFL	2106		TSN 2106				
PROC. REF: AMM 57-60-01-900-801PROC. REF: AMM 57-60-01-900-801								
57-60-05-640-801-01 ^S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - LH AILERON BEARINGS							Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.140	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 57-60-05-640-801PROC. REF: AMM 57-60-05-640-801								
57-60-05-640-801-02 ^S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - RH AILERON BEARINGS							Service ATA:57
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 57.140	AFL	7052	3750					
								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57-60-05-640-801PROC. REF: AMM 57-60-05-640-801								
57-60-05-640-802-01	^S	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - LH AILERON						Service ATA:57
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
								PKG:15
PROC. REF: AMM 57-60-05-640-802PROC. REF: AMM 57-60-05-640-802								
57-60-05-640-802-02	^S	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - RH AILERON						Service ATA:57
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
								PKG:15
PROC. REF: AMM 57-60-05-640-802PROC. REF: AMM 57-60-05-640-802								
57-70-01-900-801-01		REMOVAL / INSTALLATION OF THE AIRBRAKES - LH OUTBOARD AIRBRAKE						Component ATA:57
PN:FGFB165	MOS/MSC	07-Feb-91	O/C					
SN:120311	HRS	0		TSN 0				
WC#: 57.220	AFL	0						
PROC. REF: AMM 57-70-01-900-801PROC. REF: AMM 57-70-01-900-801								
57-70-01-900-801-02		REMOVAL / INSTALLATION OF THE AIRBRAKES - LH MIDDLE AIRBRAKE						Component ATA:57
PN:FGFB169	MOS/MSC	07-Feb-91	O/C					
SN:120611	HRS	0		TSN 0				
WC#: 57.220	AFL	0						
PROC. REF: AMM 57-70-01-900-801PROC. REF: AMM 57-70-01-900-801								
57-70-01-900-801-03		REMOVAL / INSTALLATION OF THE AIRBRAKES - LH INBOARD AIRBRAKE						Component ATA:57
PN:FGFB167	MOS/MSC	07-Feb-91	O/C					
SN:120303	HRS	0		TSN 0				
WC#: 57.220	AFL	0						
PROC. REF: AMM 57-70-01-900-801PROC. REF: AMM 57-70-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-70-01-900-801-04 REMOVAL / INSTALLATION OF THE AIRBRAKES - RH INBOARD AIRBRAKE								Component ATA:57
PN:FGFB167	MOS/MSC	07-Feb-91	O/C					
SN:120303	HRS	0		TSN 0				
WC#: 57.230	AFL	0						
PROC. REF: AMM 57-70-01-900-801PROC. REF: AMM 57-70-01-900-801								
57-70-01-900-801-05 REMOVAL / INSTALLATION OF THE AIRBRAKES - RH MIDDLE AIRBRAKE								Component ATA:57
PN:FGFB169	MOS/MSC	07-Feb-91	O/C					
SN:120611	HRS	0		TSN 0				
WC#: 57.230	AFL	0						
PROC. REF: AMM 57-70-01-900-801PROC. REF: AMM 57-70-01-900-801								
57-70-01-900-801-06 REMOVAL / INSTALLATION OF THE AIRBRAKES - RH OUTBOARD AIRBRAKE								Component ATA:57
PN:FGFB165	MOS/MSC	07-Feb-91	O/C					
SN:120311	HRS	0		TSN 0				
WC#: 57.230	AFL	0						
PROC. REF: AMM 57-70-01-900-801PROC. REF: AMM 57-70-01-900-801								
57-70-03-640-801-01 ^S LUBRICATION OF THE AIRBRAKE HINGES								Service ATA:57
	MOS	17-Feb-26	12 (+1m)					
	HRS	13885.3						
	AFL	7304						
PROC. REF: AMM 57-70-03-640-801PROC. REF: AMM 57-70-03-640-801								PKG:15
570201 LH WING/FUSELAGE CONNECTING ROD								Component ATA:57
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.030	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
570221 RH WING/FUSELAGE CONNECTING ROD								Component ATA:57
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.030	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-910-802-01	ENGINE INSPECTION RUN-UP - ENGINE 1 (L4EZ)							Service ATA:71
	MOS/MSC	13-Apr-12	O/C					
	HRS	11770.08						
WC#: 71.050	AFL	6239						
PROC. REF: AMM 71-00-00-910-802PROC. REF: AMM 71-00-00-910-802								
71-00-00-910-802-02	ENGINE INSPECTION RUN-UP - ENGINE 2 (M4EZ)							Service ATA:71
	MOS/MSC	13-Apr-12	O/C					
	HRS	11770.08						
WC#: 71.050	AFL	6239						
PROC. REF: AMM 71-00-00-910-802PROC. REF: AMM 71-00-00-910-802								
71-00-00-910-802-03	ENGINE INSPECTION RUN-UP - ENGINE 3 (R4EZ)							Service ATA:71
	MOS/MSC	13-Apr-12	O/C					
	HRS	11770.08						
WC#: 71.050	AFL	6239						
PROC. REF: AMM 71-00-00-910-802PROC. REF: AMM 71-00-00-910-802								
71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 1 FRONT MOUNT							Service ATA:71
	MOS	07-Feb-91						
	HRS	0						
WC#: 54.030	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-02-250-801PROC. REF: AMM 71-20-02-250-801								
71-20-02-250-801-01A	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 1 ENGINE FRONT MOUNT (MANDATORY 5-40)							Service ATA:71 MANDATORY 5-40
	MOS	07-Feb-91						
	HRS	0						
	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-02-250-801PROC. REF: AMM 71-20-02-250-801								
71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 3 FRONT MOUNT							Service ATA:71
	MOS	07-Feb-91						
	HRS	0						
WC#: 54.030	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-02-250-801PROC. REF: AMM 71-20-02-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-02-250-801-02A	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 3 ENGINE FRONT MOUNT (MANDATORY 5-40)							Service ATA:71
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-02-250-801PROC. REF: AMM 71-20-02-250-801								
71-20-02-250-802-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 FRONT MOUNT SHACKLES - ENGINE 1 FRONT MOUNT SHACKLE							Service ATA:71
	MOS	07-Feb-91						
	HRS	0						
WC#: 54.050	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-02-250-802PROC. REF: AMM 71-20-02-250-802								
71-20-02-250-802-02	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 FRONT MOUNT SHACKLES - ENGINE 3 FRONT MOUNT SHACKLE							Service ATA:71
	MOS	07-Feb-91						
	HRS	0						
WC#: 54.050	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-02-250-802PROC. REF: AMM 71-20-02-250-802								
71-20-07-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT							Service ATA:71
	MOS	07-Feb-91						
	HRS	0						
WC#: 54.040	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-07-250-801PROC. REF: AMM 71-20-07-250-801								
71-20-07-250-801-01A	SPECIAL DETAILED INSPECTION NO. 1 ENGINE REAR MOUNT (MANDATORY 5-40)							Service ATA:71
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-07-250-801PROC. REF: AMM 71-20-07-250-801								
71-20-07-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT							Service ATA:71
	MOS	07-Feb-91						
	HRS	0						
WC#: 54.040	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-07-250-801PROC. REF: AMM 71-20-07-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-07-250-801-02A	SPECIAL DETAILED INSPECTION NO. 3 ENGINE REAR MOUNT (MANDATORY 5-40)							Service ATA:71
	MOS	07-Feb-91						MANDATORY 5-40
	HRS	0						
	AFL	0	T:10000		10000		2687	
PROC. REF: AMM 71-20-07-250-801PROC. REF: AMM 71-20-07-250-801								
71-20-17-230-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 LH FRONT VIBRATION ISOLATOR (M900EZ1)							Service ATA:71
PN:LM833SA13	MOS	12-Jun-09						
SN:UNKNOWN	HRS	10850.2	5000		15850.2		1953.9	
WC#: 71.070	AFL	5878						
PROC. REF: AMM 71-20-17-230-801PROC. REF: AMM 71-20-17-230-801								
71-20-17-230-801-02	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 RH FRONT VIBRATION ISOLATOR (M900EZ2)							Service ATA:71
PN:LM833SA13	MOS	12-Jun-09						
SN:UNKNOWN	HRS	10850.2	5000		15850.2		1953.9	
WC#: 71.070	AFL	5878						
PROC. REF: AMM 71-20-17-230-801PROC. REF: AMM 71-20-17-230-801								
712001	NO. 1 ENGINE FRONT UPPER SHOCK MOUNT							Component ATA:71
PN:3071070-4	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.075	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
712002	NO. 1 ENGINE FRONT LOWER SHOCK MOUNT							Component ATA:71
PN:3071070-4	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.075	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
712003	NO. 2 ENGINE LH FRONT SHOCK MOUNT							Component ATA:71
PN:LM833SA13	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 71.070	AFL	5878		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712004	NO. 2 ENGINE RH FRONT SHOCK MOUNT							Component ATA:71
PN:LM833SA13	MOS/MSC	12-Jun-09	O/C	TSN 0				
SN:UNKNOWN	HRS	10850.2		TSN 0				
WC#: 71.070	AFL	5878						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
712005	NO. 3 ENGINE FRONT UPPER SHOCK MOUNT							Component ATA:71
PN:3071070-4	MOS/MSC	14-Nov-11	O/C					
SN:04P10994	HRS							
WC#: 71.080	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
712006	NO. 3 ENGINE FRONT LOWER SHOCK MOUNT							Component ATA:71
PN:3071070-4	MOS/MSC	14-Nov-11	O/C					
SN:M-255	HRS							
WC#: 71.080	AFL							
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
712251	NO. 2 ENGINE HOIST							Component ATA:71
PN:4219-1	MOS/MSC	07-Feb-91	O/C					
SN:200	HRS	0		TSN 0				
WC#: 71.040	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS							Service ATA:71
	MOS	11-Jan-21						
	HRS	10373.1	800 (+50)					
WC#: 71.030	ENC	7792						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
714010 ^S	NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS							Service ATA:71
	MOS	12-May-25						
	HRS	8612.02	300 (+100)					
	ENC	7370						
								PKG:2
714010 ^S	NO. 3 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS							Service ATA:71
	MOS	20-Jan-15						
	HRS	11672.88	850					
WC#: 71.030	ENC	5594						
								PKG:4
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
715010 ^S	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS							Service ATA:71
	MOS	11-Jan-21						
	HRS	10373.1	800 (+50)					
WC#: 71.040	ENC	7792						
								PKG:4
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
715010 ^S	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS							Service ATA:71
	MOS	12-May-25						
	HRS	8612.02	300 (+100)					
	ENC	7370						
								PKG:2
715010 ^S	NO. 3 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS							Service ATA:71
	MOS	20-Jan-15						
	HRS	11672.88	850					
WC#: 71.040	ENC	5594						
								PKG:4
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:3075370-2	MOS/MSC	04-Oct-21	E/C					
SN:P-98117C	HRS	13272.28		TSN 10373.1				
	AFL	6738						
PROC. REF: SIL F731-88, AMM 71-00-01-900-801PROC. REF: SIL F731-88, AMM 71-00-01-900-801								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:3075370-2	MOS/MSC	04-Oct-21	E/C					
SN:P-98124	HRS	13272.28		TSN 8048.1				
	AFL	6738						
PROC. REF: SIL F731-88, AMM 71-00-05-900-801PROC. REF: SIL F731-88, AMM 71-00-05-900-801								
71EN3	NO. 3 ENGINE							Component ATA:71
PN:3075330-3	MOS/MSC	20-Oct-21	E/C					
SN:P-97343C	HRS	13272.28		TSN 11835.7				
	AFL	6738						
PROC. REF: SIL F731-88, AMM 71-00-01-900-801PROC. REF: SIL F731-88, AMM 71-00-01-900-801								
ATA 72 - ENGINE								
710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:72
	MOS	16-Apr-19						
	HRS	8019.8	2500 (+100)		(10519.8) 15743.98	10619.8	1847.7 (+100)	
	ENC	6841						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
710130 ^S	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES							Service ATA:72
	MOS	12-May-25						
	HRS	8612.02	300 (+100)					
	ENC	7370						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00.10	NO. 1 ENGINE - HOT START							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.11	NO. 1 ENGINE - SURGE BLEED VALVE OPERATION CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.12	NO. 1 ENGINE - SURGE BLEED VALVE AND SOLENOID CONTROLLER CHECKS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.13 INSP	NO. 1 ENGINE - ROUTINE PERIODIC INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.13 ITT	NO. 1 ENGINE - INTERSTAGE TURBINE TEMPERATURE (ITT) CIRCUITRY CHECKS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.14 BINDING	NO. 1 ENGINE - ENGINE INTERNAL BINDING CHECKS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00.14 STALL	NO. 1 ENGINE - COMPRESSOR STALL							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.15 MEDRA	NO. 1 ENGINE - ENGINE PERFORMANCE EVALUATION RUN USING MANUAL ENGINE DATA REDUCTION AND ANALYSIS (MEDRA)							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.16 COMBUSTION	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE PERIODIC INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.16 P3	NO. 1 ENGINE - COMPRESSOR DISCHARGE PRESSURE (P3) LIMITER VALVE FUNCTIONAL TEST							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.19	NO. 1 ENGINE - COMBUSTION CHAMBER LINER BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.2	NO. 1 ENGINE - NO N2 INDICATION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00.23	NO. 1 ENGINE - HOT SECTION INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.5	NO. 1 ENGINE - NO OR LOW FUEL FLOW							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.6B	NO. 1 ENGINE - N1 TRANSDUCER CIRCUIT CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.6C	NO. 1 ENGINE - N2 TRANSDUCER CIRCUIT CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.6D	NO. 1 ENGINE - INLET TEMPERATURE (T2) SENSOR CIRCUIT CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.6H	NO. 1 ENGINE - SURGE CONTROL VALVE SOLENOID CIRCUIT CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00.7	NO. 1 ENGINE - FUEL LEAKAGE CHECKS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.8	NO. 1 ENGINE - NO N1 INDICATION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-00-00.9	NO. 1 ENGINE - HUNG START (NO OR SLOW ACCELERATION)							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-20-01.4A	NO. 1 ENGINE - REPAIR OF DAMAGED ABRADABLE MATERIAL							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-20-01PROC. REF: LMM 72-20-01								
72-30-04.2	NO. 1 ENGINE - LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
72-30-04.4	NO. 1 ENGINE - REPAIR OF LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-40-01.1	NO. 1 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER							Component ATA:72
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-40-01PROC. REF: LMM 72-40-01								
72-40-01.2	NO. 1 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER TEST							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-40-01PROC. REF: LMM 72-40-01								
72-40-02.1	NO. 1 ENGINE - COMBUSTION CHAMBER LINER							Component ATA:72
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-40-02PROC. REF: LMM 72-40-02								
72-40-02.2	NO. 1 ENGINE - COMBUSTION CHAMBER LINER INSPECTION/CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-40-02PROC. REF: LMM 72-40-02								
72-40-03.1	NO. 1 ENGINE - OUTER TRANSITION LINER							Component ATA:72
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-40-03PROC. REF: LMM 72-40-03								
72-40-03.2	NO. 1 ENGINE - OUTER TRANSITION LINER INSPECTION/CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-40-03PROC. REF: LMM 72-40-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720000	NO. 1 ENGINE - SPECIAL INSPECTION - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720001	NO. 1 ENGINE - SPECIAL INSPECTION - ACCIDENT OR INCIDENT INSPECTION REQUIREMENTS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720002	NO. 1 ENGINE - SPECIAL INSPECTION - LIGHTNING STRIKE INSPECTION REQUIREMENTS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720003	NO. 1 ENGINE - SPECIAL INSPECTION - OVERTEMPERATURE INSPECTION REQUIREMENTS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720004	NO. 1 ENGINE - SPECIAL INSPECTION - FOREIGN OBJECT DAMAGE (FOD) AND/OR BIRD STRIKE INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720005	NO. 1 ENGINE - SPECIAL INSPECTION - OIL AND FILTER ANALYSIS							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720006	NO. 1 ENGINE - SPECIAL INSPECTION - OVERSPEED INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720007	NO. 1 ENGINE - SPECIAL INSPECTION - HP IMPELLER BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720008	NO. 1 ENGINE - SPECIAL INSPECTION - [POST SB TFE731-72-3469] [PRE SB TFE731-72-3597 AND PRE SB TFE731-72-3613] SPECIAL INSPECTIONREQUIREMENTS ASSOCIATED WITH A NO. 3 CARBON SEAL FAILURE, PART NO. 3074032-1							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720008	NO. 2 ENGINE - SPECIAL INSPECTION - [POST SB TFE731-72-3469] [PRE SB TFE731-72-3597 AND PRE SB TFE731-72-3613] SPECIAL INSPECTIONREQUIREMENTS ASSOCIATED WITH A NO. 3 CARBON SEAL FAILURE, PART NO. 3074032-1							Service ATA:72
	MOS/MSC	22-Feb-90	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720008	NO. 3 ENGINE - SPECIAL INSPECTION - [POST SB TFE731-72-3469] [PRE SB TFE731-72-3597 AND PRE SB TFE731-72-3613] SPECIAL INSPECTIONREQUIREMENTS ASSOCIATED WITH A NO. 3 CARBON SEAL FAILURE, PART NO. 3074032-1							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720009	NO. 1 ENGINE - SPECIAL INSPECTION - SPECIAL INSPECTION REQUIREMENTS ASSOCIATED WITH A NO. 4 AND NO. 5 BEARING/CARBON SEAL FAILURE							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720009	NO. 2 ENGINE - SPECIAL INSPECTION - SPECIAL INSPECTION REQUIREMENTS ASSOCIATED WITH A NO. 4 AND NO. 5 BEARING/CARBON SEAL FAILURE							Service ATA:72
	MOS/MSC	22-Feb-90	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720009	NO. 3 ENGINE - SPECIAL INSPECTION - SPECIAL INSPECTION REQUIREMENTS ASSOCIATED WITH A NO. 4 AND NO. 5 BEARING/CARBON SEAL FAILURE							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720010	NO. 1 ENGINE - SPECIAL INSPECTION - SPECIAL INSPECTION REQUIREMENTS ASSOCIATED WITH A NO. 6 BEARING OIL SUPPLY TUBE FAILURE							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720010	NO. 2 ENGINE - SPECIAL INSPECTION - SPECIAL INSPECTION REQUIREMENTS ASSOCIATED WITH A NO. 6 BEARING OIL SUPPLY TUBE FAILURE							Service ATA:72
	MOS/MSC	22-Feb-90	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720010	NO. 3 ENGINE - SPECIAL INSPECTION - SPECIAL INSPECTION REQUIREMENTS ASSOCIATED WITH A NO. 6 BEARING OIL SUPPLY TUBE FAILURE							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720011	NO. 1 ENGINE - SPECIAL INSPECTION - HP IMPELLER BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720011	NO. 2 ENGINE - SPECIAL INSPECTION - HP IMPELLER BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC	22-Feb-90	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720011	NO. 3 ENGINE - SPECIAL INSPECTION - HP IMPELLER BORESCOPE INSPECTION							Service ATA:72
	MOS/MSC		A/R					
	HRS							
	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:72
	MOS	11-Jan-21						
	HRS	10373.1	2500 (+100)		(12873.1) 15772.28	12973.1	1876 (+100)	
WC#: 71.010	ENC	7792						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:72
	MOS	20-Jan-15						
	HRS	11672.88	2500 (+100)		(14172.88) 15609.47	14272.88	1713.2 (+100)	
WC#: 71.010	ENC	5594						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
720130 ^S	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES							Service ATA:72
	MOS	11-Jan-21						
	HRS	10373.1	800 (+50)					
WC#: 71.020	ENC	7792						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:4
720130 ^S	NO. 3 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES							Service ATA:72
	MOS	20-Jan-15						
	HRS	11672.88	850					
WC#: 71.020	ENC	5594						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:4
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC	29-Nov-78	O/C					
	HRS	0						
WC#: 72.001	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
721001	NO. 3 ENGINE - PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC	15-Jan-15	O/C					
	HRS	11672.88						
WC#: 72.001	ENC	5594						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK							Service ATA:72
	MOS/MSC	29-Nov-78	O/C					
	HRS	0						
WC#: 72.001	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
721002	NO. 3 ENGINE - PERFORM ENGINE PRESERVATION CHECK							Service ATA:72
	MOS/MSC		O/C					
	HRS							
WC#: 72.001	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC	29-Nov-78	O/C					
	HRS	0						
WC#: 72.001	ENC	0						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
721003	NO. 3 ENGINE - DE-PRESERVATION OF ENGINE							Service ATA:72
	MOS/MSC		O/C					
	HRS							
WC#: 72.001	ENC							
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	11-Jan-21						
	HRS	10373.1	5000 (+200)		(15373.1) 18272.28	15573.1	4376 (+200)	
WC#: 72.010	ENC	7792						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	16-Apr-19						
	HRS	8019.8	5000 (+200)		(13019.8) 18243.98	13219.8	4347.7 (+200)	
	ENC	6841						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723110	NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	20-Jan-15						
	HRS	11672.88	5000 (+200)		(16672.88) 18109.47	16872.88	4213.2 (+200)	
WC#: 72.010	ENC	5594						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
724110	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE							Component ATA:72
PN:3072443-5	MOS/MSC	29-Nov-78	O/C					
SN:9-22151-3722	HRS	0		TSN 0				
WC#: 72.020	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724110	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE							Component ATA:72
PN:3072443-5	MOS/MSC	16-Apr-19	O/C	TSO 0				
SN:4-22151-2668	HRS	8019.8		TSO 0				
	ENC	6841		TSO 0				
724110	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE							Component ATA:72
PN:3072443-5	MOS/MSC	30-Dec-00	O/C					
SN:8-22151-2382	HRS	4559		TSN 5568				
WC#: 72.020	ENC	1962		TSN 4751				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724120	NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE							Service ATA:72
PN:3072443-5	MOS	11-Jan-21						
SN:9-22151-3722	HRS	10373.1	2500 (+100)		(12873.1) 15772.28	12973.1	1876 (+100)	
	ENC	7792						
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04								
724120	NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE							Service ATA:72
PN:3072443-5	MOS	16-Apr-19						
SN:4-22151-2668	HRS	8019.8	2500 (+100)		(10519.8) 15743.98	10619.8	1847.7 (+100)	
	ENC	6841						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04								
724120	NO. 3 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE							Service ATA:72
PN:3072443-5	MOS	20-Jan-15						
SN:8-22151-2382	HRS	11672.88	2500 (+100)		(14172.88) 15609.47	14272.88	1713.2 (+100)	
	ENC	5594						
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04								
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3074747	MOS	29-Nov-78						LIFE LIMIT
SN:8-23315-1045	HRS	0		TSN 0				
WC#: 72.040	ENC	0	10000	TSN 0	(10000) 8944		1631	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725010 ^U	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:70080025-1	MOS	16-Apr-19		TSN 0				LIFE LIMIT
SN:15-156103-01018	HRS	8019.8		TSN 0				
	ENC	6841	10000	TSN 0	(16841) 16720		9407	
725010	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:70080020-1	MOS	20-Jan-15						LIFE LIMIT
SN:13-156103-00275	HRS	11672.88		TSN 0				
WC#: 72.040	ENC	5594	10000	TSN 0	(15594) 16701		9388	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075425-1	MOS	06-Jul-99						LIFE LIMIT
SN:1-03229-409	HRS	5508.7		TSN 4189				
WC#: 72.050	ENC	3713	10000	TSN 2881	(10832) 9776		2463	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725020 ^U	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075425	MOS	06-Oct-95						LIFE LIMIT
SN:5-03229-103	HRS	2150.7		TSN 0				
	ENC	1854	10000	TSN 0	(11854) 11733		4420	
725020	NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075425-1	MOS	07-May-08						LIFE LIMIT
SN:000322900866	HRS	9387.6		TSN 4827.8				
WC#: 72.050	ENC	4723	10000	TSN 2761	(11962) 13069		5756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075437-3	MOS	06-Jul-99						LIFE LIMIT
SN:0-12172-1266	HRS	5508.7		TSN 4191				
WC#: 72.060	ENC	3713	10000	TSN 2867	(10846) 9790		2477	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725030 ^U	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3074757-1	MOS	06-Oct-95						LIFE LIMIT
SN:5-12172-279	HRS	2150.7		TSN 0				
	ENC	1854	10000	TSN 0	(11854) 11733		4420	
725030	NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075436-1	MOS	07-May-08						LIFE LIMIT
SN:981217201332	HRS	9388		TSN 4829				
WC#: 72.060	ENC	4723	10000	TSN 2761	(11962) 13069		5756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC							Component ATA:72
PN:3075227	MOS	29-Nov-78						LIFE LIMIT
SN:7-12172-248	HRS	0		TSN 0				
WC#: 72.070	ENC	0	10000	TSN 0	(10000) 8944		1631	
PROC. REF: LMM 72-50-06PROC. REF: LMM 72-50-06								
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC							Component ATA:72
PN:3074786-5	MOS	06-Oct-95						LIFE LIMIT
SN:2-12172-374	HRS	2150.7		TSN 1414				
	ENC	1854	10000	TSN 1029	(10825) 10704		3391	
PROC. REF: LMM 72-50-06PROC. REF: LMM 72-50-06								
725040	NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC							Component ATA:72
PN:3075227	MOS	07-May-08		TSN 36				LIFE LIMIT
SN:8-12172-464	HRS	9388		TSN 2565.9				
WC#: 72.070	ENC	4723	10000	TSN 1380	(13343) 14450		7137	
PROC. REF: LMM 72-50-06PROC. REF: LMM 72-50-06								
725050	NO. 1 ENGINE - FAN DISC							Component ATA:72
PN:3074621	MOS	29-Nov-78						LIFE LIMIT
SN:7-12172-459	HRS	0		TSN 0				
WC#: 72.080	ENC	0	10000	TSN 0	(10000) 8944		1631	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - FAN DISC							Component ATA:72
PN:3074622-4	MOS	13-Feb-79						LIFE LIMIT
SN:7-12172-455	HRS	0		TSN 0				
	ENC	0	10000	TSN 0	(10000) 9879		2566	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 3 ENGINE - FAN DISC							Component ATA:72
PN:3074621-4	MOS	23-May-08						LIFE LIMIT
SN:6-12172-1845	HRS	9387.6		TSN 6868.9				
WC#: 72.080	ENC	4723	10000	TSN 4160	(10563) 11670		4357	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072395	MOS	29-Nov-78						LIFE LIMIT
SN:8-12112-348	HRS	0		TSN 0				
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 8944		1631	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725060 ^U	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3070440-9	MOS	13-Feb-79						LIFE LIMIT
SN:8-12112-364	HRS	0		TSN 0				
	ENC	0	10000	TSN 0	(10000) 9879		2566	
725060	NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072395-2	MOS	30-Dec-00						LIFE LIMIT
SN:000316003003	HRS	4559		TSN 0				
WC#: 72.090	ENC	1962	10000	TSN 0	(11962) 13069		5756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072396	MOS	29-Nov-78						LIFE LIMIT
SN:6-12112-1130	HRS	0		TSN 0				
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 8944		1631	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725070 ^U	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072416-4	MOS	13-Feb-79						LIFE LIMIT
SN:6-12112-1048	HRS	0		TSN 0				
	ENC	0	10000	TSN 0	(10000) 9879		2566	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725070	NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072396-3	MOS	30-Dec-00						LIFE LIMIT
SN:830322901209	HRS	4559		TSN 0				
WC#: 72.100	ENC	1962	10000	TSN 0	(11962) 13069		5756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072397	MOS	29-Nov-78						LIFE LIMIT
SN:8-03229-594	HRS	0		TSN 0				
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 8944		1631	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725080 ^U	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072417-4	MOS	13-Feb-79						LIFE LIMIT
SN:8-03229-456	HRS	0		TSN 0				
	ENC	0	10000	TSN 0	(10000) 9879		2566	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725080	NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072397-3	MOS	30-Dec-00						LIFE LIMIT
SN:000316002662	HRS	4559		TSN 0				
WC#: 72.110	ENC	1962	10000	TSN 0	(11962) 13069		5756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072398	MOS	06-Jul-99						LIFE LIMIT
SN:0-03501-7166	HRS	5508.7		TSN 4189				
WC#: 72.120	ENC	3713	20000	TSN 2881	(20832) 19776		12463	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725090 ^U	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3074997-3	MOS	06-Oct-95						LIFE LIMIT
SN:5-03501-1558	HRS	2150.7		TSN 0				
	ENC	1854	10000	TSN 0	(11854) 11733		4420	
725090	NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3075326-3	MOS	30-Dec-00						LIFE LIMIT
SN:001365107801	HRS	4559		TSN 0				
WC#: 72.120	ENC	1962	20000	TSN 0	(21962) 23069		15756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725091	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component ATA:72
PN:3074744-1	MOS/MSC	29-Nov-78	O/C					
SN:7P-23292	HRS	0		TSN 0				
WC#: 72.130	ENC	0		TSN 0				
PROC. REF: LMM 72-30-10PROC. REF: LMM 72-30-10								
725091	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component ATA:72
PN:3074744-1	MOS/MSC	13-Feb-79	O/C					
SN:9P8303	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-30-10PROC. REF: LMM 72-30-10								
725091	NO. 3 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component ATA:72
PN:3074744-1	MOS/MSC	13-Dec-89	O/C					
SN:9P-15250	HRS	0		TSN 0				
WC#: 72.130	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: LMM 72-30-10PROC. REF: LMM 72-30-10								
725110	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER							Component ATA:72
PN:3073398-3	MOS	06-Jul-99						LIFE LIMIT
SN:995332200508	HRS	5508.7		TSN 0				
WC#: 72.140	ENC	3713	10000	TSN 0	(13713) 12657		5344	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725110	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER							Component ATA:72
PN:3073398-1	MOS	16-Apr-19		TSR 0				LIFE LIMIT
SN:6-12172-728	HRS	8019.8		TSN 8019.8, TSR 0				
	ENC	6841	10000	TSN 6841, TSR 0	(10000) 9879		2566	
725110	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER							Component ATA:72
PN:3075765-1	MOS	30-Dec-00						LIFE LIMIT
SN:005332200290	HRS	4559		TSN 0				
WC#: 72.140	ENC	1962	10000	TSN 0	(11962) 13069		5756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725120	NO. 1 ENGINE - ROTATING AIR SEAL							Component ATA:72
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.260	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725120 ^U	NO. 2 ENGINE - ROTATING AIR SEAL							Component ATA:72
PN:PN	MOS/MSC	22-Feb-90	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
	(AFL)	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725130	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT							Component ATA:72
PN:3072545-1	MOS	29-Nov-78						LIFE LIMIT
SN:9P-9526	HRS	0		TSN 0				
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 10944		3631	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725130	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT							Component ATA:72
PN:3072545-1	MOS	13-Feb-79						LIFE LIMIT
SN:9P14776	HRS	0		TSN 0				
	ENC	0	12000	TSN 0	(12000) 11879		4566	
725130	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT							Component ATA:72
PN:3072545-1	MOS	13-Dec-89						LIFE LIMIT
SN:9P-25436	HRS	0		TSN 0				
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 13107		5794	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725140	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE							Component ATA:72
PN:3071839-1	MOS	25-Jan-08		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	7994.5		TSN 0				
WC#: 72.160	ENC	6466	30000	TSN 0	(36466) 35410		28097	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725140	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE							Component ATA:72
PN:3075205-1	MOS	13-Feb-79						LIFE LIMIT
SN:7-18040-2720	HRS	0		TSN 0				
	ENC	0	30000	TSN 0	(30000) 29879		22566	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725140	NO. 3 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE							Component ATA:72
PN:3077065-1	MOS	30-Dec-00						LIFE LIMIT
SN:6-18040-5123	HRS	4559.8		TSN 0				
WC#: 72.160	ENC	1962	30000	TSN 0, TSO 0	(31962) 33069		25756	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725150	NO. 1 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3074641-2	MOS/MSC	29-Nov-78	O/C					
SN:9P-10126	HRS	0		TSN 0				
WC#: 72.170	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725150	NO. 2 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3074641-2	MOS/MSC	13-Feb-79	O/C					
SN:9P15632	HRS	0		TSN 0				
	ENC	0		TSN 0				
725150	NO. 3 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3074641-3	MOS/MSC	30-Dec-00	O/C	TSO 0				
SN:OP-13937	HRS	4559.8		TSO 0				
WC#: 72.170	ENC	1962		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3075292-4	MOS/MSC	25-Jan-08	O/C					
SN:5P9807	HRS	7994.5						
WC#: 72.180	ENC	6466						
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05								
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3077063-2	MOS/MSC	16-Apr-19	O/C	TSO 0				
SN:9P-5171	HRS	8019.8		TSO 0				
	ENC	6841		TSO 0				
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725160	NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3075292-4	MOS/MSC	07-May-08	O/C					
SN:99P13746	HRS	9387.6						
WC#: 72.180	ENC	4723						
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05								
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3075406-8	MOS/MSC	25-Jan-08	O/C					
SN:06P35876	HRS	7994.5						
WC#: 72.190	ENC	6466						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725180 ^U	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3075225	MOS/MSC	06-Oct-95	O/C					
SN:4P-17634	HRS	2150.7		TSN 0				
	ENC	1854		TSN 0				
725180	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3075715-4	MOS/MSC	07-May-08	O/C	TSN 36				
SN:05P06716	HRS	9388		TSN 2565.9				
WC#: 72.190	ENC	4723		TSN 1380				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3074741	MOS/MSC	06-Jul-99	O/C					
SN:5P-10436	HRS	5508.7		TSN 2112				
WC#: 72.200	ENC	3713		TSN 1446				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3074741	MOS/MSC	06-Oct-95	O/C					
SN:9-23151-144	HRS	2150.7						
	ENC	1854						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725190	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3073765-9	MOS/MSC	23-May-05	O/C		TSN 0			
SN:05P02649	HRS	6822.1			TSN 0			
WC#: 72.200	ENC	3343			TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3074052-1	MOS/MSC	06-Jul-99	O/C					
SN:5P-12906	HRS	5508.7			TSN 2112			
WC#: 72.210	ENC	3713			TSN 1446			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3074052-1	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	ENC							
725191	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3074052-2	MOS/MSC	23-May-05	O/C		TSN 0			
SN:05P06709	HRS	6822.1			TSN 0			
WC#: 72.210	ENC	3343			TSN 0			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725230	NO. 1 ENGINE - FAN SPINNER							Component ATA:72
PN:3074623-3	MOS/MSC	29-Nov-78	O/C					
SN:7-01734-185	HRS	0			TSN 0			
WC#: 72.220	ENC	0			TSN 0			
PROC. REF: LMM 72-70-01PROC. REF: LMM 72-70-01								
725230	NO. 2 ENGINE - FAN SPINNER							Component ATA:72
PN:3074623	MOS/MSC	06-Oct-95	O/C					
SN:7-01734-199	HRS	2150.7			TSN 0			
	ENC	1854			TSN 0			
PROC. REF: LMM 72-70-01PROC. REF: LMM 72-70-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725230	NO. 3 ENGINE - FAN SPINNER							Component ATA:72
PN:3074623-3	MOS/MSC	16-Nov-01	O/C	TSN 0				
SN:012428000109	HRS	4832		TSN 0				
WC#: 72.220	ENC	2127		TSN 0				
PROC. REF: LMM 72-70-01PROC. REF: LMM 72-70-01								
726110	NO. 1 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-17	MOS/MSC	29-Nov-78	O/C					
SN:P-5156	HRS	0		TSN 0				
WC#: 72.230	ENC	0		TSN 0				
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726110	NO. 2 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-17	MOS/MSC	13-Feb-79	O/C					
SN:P5234	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726110	NO. 3 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-31	MOS/MSC	23-May-05	O/C					
SN:P5324	HRS	6822.1						
WC#: 72.230	ENC	3343						
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-17	MOS	11-Jan-21						
SN:P-5156	HRS	10373.1	5000 (+200)		(15373.1) 18272.28	15573.1	4376 (+200)	
WC#: 72.240	ENC	7792						
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-17	MOS	22-May-05						
SN:P5234	HRS	5603.8	5000 (+200)		(10603.8) 15827.98	10803.8	1931.7 (+200)	
	ENC	4818						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726120	NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-31	MOS	20-Jan-15						
SN:P5324	HRS	11672.88	5000 (+200)		(16672.88) 18109.47	16872.88	4213.2 (+200)	
WC#: 72.240	ENC	5594						
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726130	NO. 1 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-4	MOS/MSC	29-Nov-78	O/C					
SN:P-6399	HRS	0		TSN 0				
WC#: 72.250	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726130	NO. 2 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-4	MOS/MSC	13-Feb-79	O/C					
SN:P6468	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726130	NO. 3 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-12	MOS/MSC	23-May-05	O/C					
SN:P-6564	HRS	6822.1						
WC#: 72.250	ENC	3343						
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726140	NO. 1 ENGINE - INSPECT TRANSFER GEARBOX							Service ATA:72
PN:3070093-4	MOS/MSC	06-Jul-99	O/C					
SN:P-6399	HRS	5508.7						
WC#: 72.250	ENC	3713						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726140	NO. 2 ENGINE - INSPECT TRANSFER GEARBOX							Service ATA:72
PN:3070093-4	MOS/MSC	06-Oct-95	O/C					
SN:P6468	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
726140	NO. 3 ENGINE - INSPECT TRANSFER GEARBOX							Service ATA:72
	MOS/MSC	23-May-05	O/C					
	HRS	6822.1						
WC#: 72.250	ENC	3343						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	11-Jan-21						
	HRS	10373.1	5000 (+200)		(15373.1) 18272.28	15573.1	4376 (+200)	
WC#: 72.270	ENC	7792						
PROC. REF: LMM 72-70-06PROC. REF: LMM 72-70-06								
727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	22-May-05						
	HRS	5603.8	5000 (+200)		(10603.8) 15827.98	10803.8	1931.7 (+200)	
	ENC	4818						
PROC. REF: LMM 72-70-06PROC. REF: LMM 72-70-06								
727110	NO. 3 ENGINE - INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	20-Jan-15						
	HRS	11672.88	5000 (+200)		(16672.88) 18109.47	16872.88	4213.2 (+200)	
WC#: 72.270	ENC	5594						
PROC. REF: LMM 72-70-06PROC. REF: LMM 72-70-06								
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-01.1	NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY							Component ATA:73
PN:PN	MOS/MSC	29-Nov-78	A/R	TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-10-01PROC. REF: LMM 73-10-01								
73-10-01.2	NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY INSPECTION/CHECK							Service ATA:73
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 73-10-01PROC. REF: LMM 73-10-01								
73-10-04.2	NO. 1 ENGINE - FUEL HEATER AND CHECK VALVE INSPECTION/CHECK							Service ATA:73
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
73-10-2.1	NO. 1 ENGINE - FUEL AND P3 SENSING LINES INSTALLATION							Service ATA:73
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 73-10-02PROC. REF: LMM 73-10-02								
73-10-3.1	NO. 1 ENGINE - SERVICE TUBES CLAMP AND TUBES							Component ATA:73
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-10-03PROC. REF: LMM 73-10-03								
73-10-3.2	NO. 1 ENGINE - SERVICE TUBES CLAMP AND TUBES INSPECTION/CHECK							Service ATA:73
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 73-10-03PROC. REF: LMM 73-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-20-01-710-802-01	^S	OPERATIONAL TEST OF THE ENGINE 1 COMPUTER STAND-BY POWER SUPPLY						Service ATA:73
	MOS	19-Dec-21						
	HRS	13275.5	1600 (+40)					
WC#: 73.075	AFL	6741						
PROC. REF: AMM 73-20-01-710-802PROC. REF: AMM 73-20-01-710-802								PKG:21
73-20-01-710-802-01A OPERATIONAL TEST OF THE NO. 1 ENGINE COMPUTER STAND-BY POWER SUPPLY (MANDATORY 5-40) Service ATA:73								
	MOS	19-Dec-21						MANDATORY 5-40
	HRS	13275.5	1640		14915.5		1019.2	
WC#: 73.075	AFL	6741						
PROC. REF: AMM 73-20-01-710-802PROC. REF: AMM 73-20-01-710-802								
73-20-01.2 NO. 1 ENGINE - FUEL SYSTEMS INSPECTION/CHECK Service ATA:73								
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
73-21-01.1 NO. 1 ENGINE - FUEL CONTROL COMPONENTS Component ATA:73								
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-21-01PROC. REF: LMM 73-21-01								
73-21-01.2 NO. 1 ENGINE - FUEL CONTROL COMPONENTS INSPECTION/CHECK Service ATA:73								
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 73-21-01PROC. REF: LMM 73-21-01								
73-30-12-900-801-04 REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FLOWMETER 1/TOTAL FUEL USED INDICATOR (2EH1) Component ATA:73								
PN:9-464-30	MOS/MSC	31-Mar-14	O/C					
SN:1353	HRS	12625.42						
WC#: 73.080	AFL	6516						
PROC. REF: AMM 73-30-12-900-801PROC. REF: AMM 73-30-12-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-30-12-900-801-05		REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FLOWMETER 2/TOTAL FUEL USED INDICATOR (2EH2)						Component ATA:73
PN:9-464-30	MOS/MSC	09-Feb-15	O/C					
SN:E4713	HRS	13109.23						
WC#: 73.080	AFL	6701						
PROC. REF: AMM 73-30-12-900-801PROC. REF: AMM 73-30-12-900-801								
73-30-12-900-801-06		REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FLOWMETER 3/TOTAL FUEL USED INDICATOR (2EH3)						Component ATA:73
PN:9-464-30	MOS/MSC	23-Sep-09	O/C	TSR 0				
SN:E4715	HRS	10853.9		TSO 10762.9, TSR 0				
WC#: 73.080	AFL	5880		TSR 0				
PROC. REF: AMM 73-30-12-900-801PROC. REF: AMM 73-30-12-900-801								
731110		NO. 1 ENGINE - FUEL PUMP						Component ATA:73
PN:3070850-57	MOS/MSC	13-Dec-13	O/C	TSR 2				
SN:MX539548	HRS	9972.5		TSR 0				
WC#: 73.010	ENC	7440		TSR 0				
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
731110		NO. 2 ENGINE - FUEL PUMP						Component ATA:73
PN:3070850-57	MOS/MSC	13-Feb-79	O/C					
SN:MX490370	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
731110		NO. 3 ENGINE - FUEL PUMP						Component ATA:73
PN:3070850-57	MOS/MSC	23-May-05	O/C	TSO 0				
SN:MX490364	HRS	6822.1		TSO 0				
WC#: 73.010	ENC	3343		TSO 0				
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
731120 ^S		NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT						Service ATA:73
	MOS	17-Sep-25						
	HRS	10956.92	300 (+100)					
WC#: 73.010	ENC	8327						
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02								

PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731120 ^S	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	17-Sep-25						
	HRS	8631.92	600 (+50)					
	ENC	7392						
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02								PKG:2
731120 ^S	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	17-Sep-25						
	HRS	12419.52	400					
WC#: 73.010	ENC	6164						
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02								PKG:2
731130	NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:394396-2-1	MOS/MSC	29-Nov-78	O/C					
SN:7339	HRS	0		TSN 0				
WC#: 73.030	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731130	NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:394396-2-1	MOS/MSC	13-Feb-79	O/C					
SN:2464	HRS	0		TSN 0				
	ENC	0		TSN 0				
731130	NO. 3 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:394396-2-1	MOS/MSC	30-Mar-07	O/C	TSO 0				
SN:P3650	HRS	8579.6		TSO 0				
WC#: 73.030	ENC	4304		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731140	NO. 1 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-5	MOS/MSC	29-Nov-78	O/C					
SN:126-4659C	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731140	NO. 2 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-5	MOS/MSC	06-Oct-95	O/C					
SN:58-4915	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
731140	NO. 3 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-3	MOS/MSC	15-Dec-89	O/C					
SN:18-4783	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
731150 ^S	NO. 1 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)							Service ATA:73
	MOS	11-Jan-21						
	HRS	10373.1	800 (+50)					
WC#: 73.050	ENC	7792						
PROC. REF: LMM 79-20-06PROC. REF: LMM 79-20-06								PKG:4
731150 ^S	NO. 2 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)							Service ATA:73
	MOS	12-May-25						
	HRS	8612.02	300 (+100)					
	ENC	7370						
PROC. REF: LMM 79-20-06PROC. REF: LMM 79-20-06								PKG:2
731150	NO. 3 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)							Service ATA:73
	MOS/MSC	20-Jan-15	O/C					
	HRS	11672.88						
WC#: 73.050	ENC	5594						
PROC. REF: LMM 79-20-06PROC. REF: LMM 79-20-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731160	NO. 1 ENGINE - FUEL HEATER CHECK VALVE							Component ATA:73
PN:3073932-4	MOS/MSC	29-Nov-78	O/C					
SN:9-20404-366	HRS	0		TSN 0				
WC#: 73.060	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
731160	NO. 2 ENGINE - FUEL HEATER CHECK VALVE							Component ATA:73
PN:3073932-4	MOS/MSC	06-Oct-95	O/C					
SN:9-20404-317	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
731160	NO. 3 ENGINE - FUEL HEATER CHECK VALVE							Component ATA:73
PN:3073932-4	MOS/MSC	07-May-08	O/C	TSR 89				
SN:9-20404-527	HRS	9388		TSR 4828.2				
WC#: 73.060	ENC	4723		TSR 2761				
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
732101	NO. 1 ENGINE FUEL COMPUTER							Component ATA:73
PN:2118002-60	MOS/MSC	31-Mar-14	O/C					
SN:48-1059	HRS	12625.42						
WC#: 73.070	AFL	6516						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
732102	NO. 2 ENGINE FUEL COMPUTER							Component ATA:73
PN:2118002-60	MOS/MSC	31-Mar-14	O/C					
SN:105-AC0068	HRS	12625.42						
WC#: 73.070	AFL	6516						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
732103	NO. 3 ENGINE FUEL COMPUTER							Component ATA:73
PN:2118002-60	MOS/MSC	23-May-05	O/C					
SN:108-1318	HRS	8178.27						
WC#: 73.070	AFL	4422						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732110	NO. 1 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-19	MOS/MSC	29-Nov-78	O/C					
SN:A9793C	HRS	0		TSN 0				
WC#: 73.070	ENC	0		TSN 0				
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
732110	NO. 2 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-26	MOS/MSC	30-Jun-03	O/C					
SN:A10150C	HRS	4800.4						
	ENC	4003						
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
732110	NO. 3 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-35	MOS/MSC	30-Mar-07	O/C	TSR 0				
SN:12794	HRS	8579.6		TSR 0				
WC#: 73.070	ENC	4304		TSR 0				
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:3070685-6	MOS/MSC	29-Nov-78	O/C					
SN:A9574	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:3070685-6	MOS/MSC	17-Sep-03	O/C	TSO 0				
SN:A5500	HRS	4920.4		TSO 0				
	ENC	4117		TSO 0				
732120	NO. 3 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:3070685-6	MOS/MSC	15-Dec-89	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732130 ^U	NO. 2 ENGINE - INSPECT FUEL NOZZLE SHROUDS							Service ATA:73
	MOS/MSC	16-Apr-19	O/C					
	HRS	8019.8						
	ENC	6841						
732160	NO. 1 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-231-14	MOS/MSC	29-Nov-78	O/C					
SN:5458	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732160	NO. 2 ENGINE - FUEL FLOW TRANSMITTER							Component ATA:73
PN:8TJ64GDZ3	MOS/MSC	01-Nov-08	O/C	TSR 0				
SN:C.0860.A	HRS	6640.3		TSR 0				
	ENC	5792		TSR 0				
733151	NO. 1 ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-231-14	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:3029	HRS	0		TSN 0				
WC#: 73.090	AFL	0		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
733152	NO. 2 ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-231-14	MOS/MSC	06-Mar-05	O/C	TSN 0				
SN:H7419	HRS	7323.9		TSN 0				
WC#: 73.090	AFL	3830		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
733153	NO. 3 ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:9-231-14	MOS/MSC	07-Feb-91	O/C					
SN:3131	HRS	0		TSN 0				
WC#: 73.090	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-00-01.2	NO. 1 ENGINE - IGNITION UNIT AND IGNITER PLUG INSPECTION/CHECK							Service ATA:74
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
741110	NO. 1 ENGINE - IGNITION UNIT							Component ATA:74
PN:3073914	MOS/MSC	29-Nov-78	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.010	ENC	0		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
741110	NO. 2 ENGINE - IGNITION UNIT							Component ATA:74
PN:3073914-4	MOS/MSC	18-Jul-12	O/C	TSO 0				
SN:90331244	HRS	7329.5		TSO 0				
	ENC	6339		TSO 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
741110	NO. 3 ENGINE - IGNITION UNIT							Component ATA:74
PN:3073914-4	MOS/MSC	03-Apr-06	O/C	TSO 0				
SN:92504789	HRS	7752.7		TSO 0				
WC#: 74.010	ENC	3891		TSO 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
741120 ^S	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service ATA:74
	MOS	11-Jan-21						
	HRS	10373.1	1000 (+400)					
WC#: 74.010	ENC	7792						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:0
741120 ^S	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service ATA:74
	MOS	16-Apr-19						
	HRS	8019.8	1200 (+200)					
	ENC	6841						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741120 ^S	NO. 3 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service ATA:74
	MOS	20-Jan-15						
	HRS	11672.88	1400					
WC#: 74.010	ENC	5594						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:0
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:CH31815-2	MOS/MSC	11-Jan-13	O/C	TSN 0				
SN:NSN	HRS	9621		TSN 0				
WC#: 74.030	ENC	7354		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	16-Apr-19	O/C	TSN 0				
SN:NA	HRS	8019.8		TSN 0				
	ENC	6841		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742110	NO. 3 ENGINE - 6 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	07-May-08	O/C	TSN 0				
SN:UNKNOWN	HRS	9387.6		TSN 0				
WC#: 74.030	ENC	4723		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742120 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	11-Jan-21						
	HRS	10373.1	1600 (+50)					
WC#: 74.030	ENC	7792						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742120 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	16-Apr-19						
	HRS	8019.8	1200 (+450)					
	ENC	6841						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:3
742120 ^S	NO. 3 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	20-Jan-15						
	HRS	11672.88	1650					
WC#: 74.030	ENC	5594						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:5
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:CH31815-2	MOS/MSC	11-Jan-13	O/C	TSN 0				
SN:NSN	HRS	9621		TSN 0				
WC#: 74.050	ENC	7354		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742130	NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	16-Apr-19	O/C	TSN 0				
SN:NA	HRS	8019.8		TSN 0				
	ENC	6841		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742130	NO. 3 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	07-May-08	O/C	TSN 0				
SN:UNKNOWN	HRS	9387.6		TSN 0				
WC#: 74.050	ENC	4723		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	11-Jan-21						
	HRS	10373.1	1600 (+50)					
WC#: 74.050	ENC	7792						
								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	16-Apr-19						
	HRS	8019.8	1200 (+450)					
	ENC	6841						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:3
742140 ^S	NO. 3 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service ATA:74
	MOS	20-Jan-15						
	HRS	11672.88	1650					
WC#: 74.050	ENC	5594						
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								PKG:5
ATA 75 - AIR								
75-10-05.1	NO. 1 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT							Component ATA:75
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 75-10-05PROC. REF: LMM 75-10-05								
75-10-05.2	NO. 1 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT INSPECTION/CHECK							Service ATA:75
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 75-10-05PROC. REF: LMM 75-10-05								
75-40-01.2	NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR INSPECTION/CHECK							Service ATA:75
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 75-40-01PROC. REF: LMM 75-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
750130	NO. 1 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component ATA:75
PN:3070816-4	MOS/MSC	22-May-07	O/C					
SN:4288	HRS	7686.9						
WC#: 75.010	ENC	6290						
PROC. REF: LMM 75-40-01PROC. REF: LMM 75-40-01								
750130	NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component ATA:75
PN:3070816-4	MOS/MSC	01-Feb-90	O/C					
SN:UNKNOWN	HRS			TSN 0				
	ENC							
PROC. REF: LMM 75-40-01PROC. REF: LMM 75-40-01								
750130	NO. 3 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component ATA:75
PN:3070816-12	MOS/MSC	28-Aug-12	O/C	TSN 0				
SN:1216901765117	HRS	10619.25		TSN 0				
WC#: 75.010	ENC	5220		TSN 0				
PROC. REF: LMM 75-40-01PROC. REF: LMM 75-40-01								
751010	NO. 1 ENGINE - ANTI-ICE VALVE							Component ATA:75
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 75.020	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 76 - ENGINE CONTROLS								
76-10-00-220-801-01	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 1							Service ATA:76
	MOS/MSC	08-Aug-14	O/C					
	HRS	12881.35						
WC#: 76.030	AFL	6629						
PROC. REF: AMM 76-10-00-220-801PROC. REF: AMM 76-10-00-220-801								
76-10-00-220-801-02	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 2							Service ATA:76
	MOS/MSC	08-Aug-14	O/C					
	HRS	12881.35						
WC#: 76.030	AFL	6629						
PROC. REF: AMM 76-10-00-220-801PROC. REF: AMM 76-10-00-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-10-00-220-801-03	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 3							Service ATA:76
	MOS/MSC	08-Aug-14	O/C					
	HRS	12881.35						
WC#: 76.030	AFL	6629						
PROC. REF: AMM 76-10-00-220-801PROC. REF: AMM 76-10-00-220-801								
76-10-00-220-802-01	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 1							Service ATA:76
	MOS/MSC	14-Mar-01	O/C					
	HRS	4661						
WC#: 76.060	AFL	2106						
PROC. REF: AMM 76-10-00-220-802PROC. REF: AMM 76-10-00-220-802								
76-10-00-220-802-02	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 2							Service ATA:76
	MOS/MSC	26-Jul-05	O/C					
	HRS	7797.2						
WC#: 76.060	AFL	4094						
PROC. REF: AMM 76-10-00-220-802PROC. REF: AMM 76-10-00-220-802								
76-10-00-220-802-03	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 3							Service ATA:76
	MOS/MSC	14-Nov-11	O/C					
	HRS	11568.42						
WC#: 76.060	AFL	6104						
PROC. REF: AMM 76-10-00-220-802PROC. REF: AMM 76-10-00-220-802								
76-10-01-900-801-01	REMOVAL / INSTALLATION OF THE THROTTLE CONTROL UNIT - THROTTLE CONTROL UNIT (500EC)							Component ATA:76
PN:FGFB771100A4	MOS/MSC	07-Feb-91	O/C					
SN:96	HRS	0		TSN 0				
WC#: 76.070	AFL	0						
PROC. REF: AMM 76-10-01-900-801PROC. REF: AMM 76-10-01-900-801								
76-10-02.1	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS							Component ATA:76
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 76-10-02PROC. REF: LMM 76-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-10-02.2	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS INSPECTION/CHECK							Service ATA:76
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 76-10-02PROC. REF: LMM 76-10-02								
76-10-03.1	NO. 1 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS							Component ATA:76
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 76-10-03PROC. REF: LMM 76-10-03								
76-10-03.2	NO. 1 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS INSPECTION/CHECK							Service ATA:76
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 76-10-03PROC. REF: LMM 76-10-03								
76-10-21-640-802-01 ^S	LUBRICATION OF THE TELEFLEX CONTROL CABLE BALL-JOINTS - LUBRICATION OF TELEFLEX CABLE BALL-JOINTS (ENGINE 1)							Service ATA:76
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.050	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 76-10-21-640-802PROC. REF: AMM 76-10-21-640-802								
76-10-21-640-802-02 ^S	LUBRICATION OF THE TELEFLEX CONTROL CABLE BALL-JOINTS - LUBRICATION OF TELEFLEX CABLE BALL-JOINTS (ENGINE 2)							Service ATA:76
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.050	AFL	7052	3750					
								PKG:31
PROC. REF: AMM 76-10-21-640-802PROC. REF: AMM 76-10-21-640-802								
76-10-21-640-802-03 ^S	LUBRICATION OF THE TELEFLEX CONTROL CABLE BALL-JOINTS - LUBRICATION OF TELEFLEX CABLE BALL-JOINTS (ENGINE 3)							Service ATA:76
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.050	AFL	7052	3750					
								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
PROC. REF: AMM 76-10-21-640-802PROC. REF: AMM 76-10-21-640-802								
76-10-21-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - LH ENGINE TELEFLEX CONTROL CABLE (L502EC)						Component	ATA:76
PN:4234476	MOS/MSC	07-Feb-91	O/C					
SN:3072	HRS	0		TSN 0				
WC#: 76.090	AFL	0						
PROC. REF: AMM 76-10-21-900-801PROC. REF: AMM 76-10-21-900-801								
76-10-21-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - RH ENGINE TELEFLEX CONTROL CABLE (R502EC)						Component	ATA:76
PN:4234499	MOS/MSC	07-Feb-91	O/C					
SN:3077	HRS	0		TSN 0				
WC#: 76.090	AFL	0						
PROC. REF: AMM 76-10-21-900-801PROC. REF: AMM 76-10-21-900-801								
76-10-21-900-802-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 2 TELEFLEX CONTROL CABLE - CENTER ENGINE TELEFLEX CONTROL CABLE (M502EC)						Component	ATA:76
PN:4234483	MOS/MSC	19-Dec-21	O/C					
SN:1749	HRS	13275.5						
WC#: 76.095	AFL	6741						
PROC. REF: AMM 76-10-21-900-802PROC. REF: AMM 76-10-21-900-802								
76-10-25-640-801-01 ^S	GREASING OF THE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS - ENGINE 1						Service	ATA:76
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 76.040	AFL	6741	7500					
								PKG:32
PROC. REF: AMM 76-10-25-640-801PROC. REF: AMM 76-10-25-640-801								
76-10-25-640-801-02 ^S	GREASING OF THE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS - ENGINE 2						Service	ATA:76
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 76.040	AFL	6741	7500					
								PKG:32
PROC. REF: AMM 76-10-25-640-801PROC. REF: AMM 76-10-25-640-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-10-25-640-801-03	^S	GREASING OF THE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS - ENGINE 3						Service ATA:76
	MOS	19-Dec-21	144 (+2m)					
	HRS	13275.5						
WC#: 76.040	AFL	6741	7500					
PROC. REF: AMM 76-10-25-640-801PROC. REF: AMM 76-10-25-640-801								PKG:32
76-10-33-820-801-01	^S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 1 CONTROL CABLE (L501EC)						Service ATA:76
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.065	AFL	7052	3750					
PROC. REF: AMM 76-10-33-820-801PROC. REF: AMM 76-10-33-820-801								PKG:31
76-10-33-820-801-02	^S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 2 CONTROL CABLE (M501EC)						Service ATA:76
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.065	AFL	7052	3750					
PROC. REF: AMM 76-10-33-820-801PROC. REF: AMM 76-10-33-820-801								PKG:31
76-10-33-820-801-03	^S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 3 CONTROL CABLE (R501EC)						Service ATA:76
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 76.065	AFL	7052	3750					
PROC. REF: AMM 76-10-33-820-801PROC. REF: AMM 76-10-33-820-801								PKG:31
76-10-33-900-801-01		REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE CONTROL CABLES - ENGINE 1 THROTTLE CONTROL CABLE						Component ATA:76
PN:FGFB771000040	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.080	AFL	0						
PROC. REF: AMM 76-10-33-900-801PROC. REF: AMM 76-10-33-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-10-33-900-801-02 REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE CONTROL CABLES - ENGINE 2 THROTTLE CONTROL CABLE								Component ATA:76
PN:FGFB771000050	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.080	AFL	0						
PROC. REF: AMM 76-10-33-900-801PROC. REF: AMM 76-10-33-900-801								
76-10-33-900-801-03 REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE CONTROL CABLES - ENGINE 3 THROTTLE CONTROL CABLE								Component ATA:76
PN:FGFB771000060	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.080	AFL	0						
PROC. REF: AMM 76-10-33-900-801PROC. REF: AMM 76-10-33-900-801								
760110 ^U NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL								Component ATA:76
PN:2119010-9000	MOS/MSC	17-Dec-21	O/C					
SN:65-BW0534	HRS	10376.32						
WC#: 76.010	ENC	7797						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
760110 ^U NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL								Component ATA:76
PN:2119010-9000	MOS/MSC	17-Dec-21	O/C					
SN:95-BW0535	HRS	8051.32						
	ENC	6862						
760120 ^S NO. 1 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL								Service ATA:76
	MOS	01-Mar-24						
	HRS	10773.12	300 (+100)					
WC#: 76.020	ENC	8131						
PROC. REF: LMM 72-00-00, LMM 76-10-03PROC. REF: LMM 72-00-00, LMM 76-10-03								PKG:2
760120 ^S NO. 2 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL								Service ATA:76
	MOS	12-May-25						
	HRS	8612.02	300 (+100)					
	ENC	7370						
PROC. REF: LMM 72-00-00, LMM 76-10-03PROC. REF: LMM 72-00-00, LMM 76-10-03								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
760120 ^S	NO. 3 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL							Service ATA:76
	MOS	02-Oct-23						
	HRS	12155.92	400					
WC#: 76.020	ENC	5896						
PROC. REF: LMM 72-00-00, LMM 76-10-03PROC. REF: LMM 72-00-00, LMM 76-10-03								PKG:2
760130	NO. 1 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS/MSC	06-May-25	O/C					
	HRS	10937.02						
WC#: 76.050	ENC	8305						
PROC. REF: LMM 76-10-03, MSC CAMP EHM ADENDUMPROC. REF: LMM 76-10-03, MSC CAMP EHM ADENDUM								
760130	NO. 2 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS/MSC	12-May-25	O/C					
	HRS	8612.02						
	ENC	7370						
PROC. REF: LMM 76-10-03, MSC CAMP EHM ADENDUMPROC. REF: LMM 76-10-03, MSC CAMP EHM ADENDUM								
760130	NO. 3 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS/MSC	12-May-25	O/C					
	HRS	12399.62						
WC#: 76.050	ENC	6142						
PROC. REF: LMM 76-10-03, MSC CAMP EHM ADENDUMPROC. REF: LMM 76-10-03, MSC CAMP EHM ADENDUM								
761310	NO. 1 ENGINE - SURGE BLEED VALVE							Component ATA:76
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.030	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
761310	NO. 2 ENGINE - SURGE BLEED VALVE							Component ATA:76
PN:978812-5-1	MOS/MSC	16-Apr-19	O/C	TSO 0				
SN:P-2680	HRS	8019.8		TSO 0				
	ENC	6841		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
761310	NO. 3 ENGINE - SURGE BLEED VALVE							Component ATA:76
PN:978812-5-1	MOS/MSC	07-May-08	O/C	TSN 89				
SN:5991	HRS	9388		TSN 4828.2				
WC#: 76.030	ENC	4723		TSN 2761				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE							Component ATA:76
PN:109696-4-1	MOS/MSC	29-Nov-78	O/C					
SN:6081	HRS	0		TSN 0				
WC#: 76.040	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE							Component ATA:76
PN:109696-4-1	MOS/MSC	06-Oct-95	O/C					
SN:6324	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
761320	NO. 3 ENGINE - SOLENOID CONTROLLER VALVE							Component ATA:76
PN:109696-4-1	MOS/MSC	15-Dec-89	O/C					
SN:6513	HRS	0		TSN 0				
WC#: 76.040	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
762111	NO. 1 ENGINE FUEL SHUTOFF VALVE							Component ATA:76
PN:L88A31-662	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.100	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
762112	NO. 2 ENGINE FUEL SHUTOFF VALVE							Component ATA:76
PN:L88A31-663	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.110	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
762113	NO. 3 ENGINE FUEL SHUTOFF VALVE							Component ATA:76
PN:L88A31-664	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.120	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
ATA 77 - ENGINE INDICATING								
77-10-03.2	NO. 1 ENGINE - N1 TRANSDUCER AND N1 COMPENSATOR INSPECTION/CHECK							Service ATA:77
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 77-10-03PROC. REF: LMM 77-10-03								
77-10-05-900-801-07	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 "N1" INDICATOR (2EU1)							Component ATA:77
PN:5428-706-80-10	MOS/MSC	07-Feb-91	O/C					
SN:115	HRS	0		TSN 0				
WC#: 77.020	AFL	0						
PROC. REF: AMM 77-10-05-900-801PROC. REF: AMM 77-10-05-900-801								
77-10-05-900-801-08	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 "N1" INDICATOR (2EU2)							Component ATA:77
PN:5428-706-80-10	MOS/MSC	21-Jul-10	O/C	TSO 0				
SN:439	HRS	11009.58		TSO 0				
WC#: 77.020	AFL	5928		TSO 0				
PROC. REF: AMM 77-10-05-900-801PROC. REF: AMM 77-10-05-900-801								
77-10-05-900-801-09	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 "N1" INDICATOR (2EU3)							Component ATA:77
PN:5428-706-80-10	MOS/MSC	09-Feb-15	O/C					
SN:789	HRS	13109.23		TSN 10521				
WC#: 77.020	AFL	6701		TSN 4065				
PROC. REF: AMM 77-10-05-900-801PROC. REF: AMM 77-10-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-10-05-900-801-10	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 "N2" INDICATOR (3EU1)							Component ATA:77
PN:5423-708-80-10	MOS/MSC	07-Feb-91	O/C					
SN:203	HRS	0		TSN 0				
WC#: 77.040	AFL	0						
PROC. REF: AMM 77-10-05-900-801PROC. REF: AMM 77-10-05-900-801								
77-10-05-900-801-11	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 "N2" INDICATOR (3EU2)							Component ATA:77
PN:5423-701-80-10	MOS/MSC	07-Feb-91	O/C					
SN:252	HRS	0		TSN 0				
WC#: 77.040	AFL	0						
PROC. REF: AMM 77-10-05-900-801PROC. REF: AMM 77-10-05-900-801								
77-10-05-900-801-12	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 "N2" INDICATOR (3EU3)							Component ATA:77
PN:5423-713-80-10	MOS/MSC	03-Mar-06	O/C	TSR 0				
SN:296A	HRS	8482.3		TSR 0				
WC#: 77.040	AFL	4476		TSR 0				
PROC. REF: AMM 77-10-05-900-801PROC. REF: AMM 77-10-05-900-801								
77-10-05.2	NO. 1 ENGINE - N2 TRANSDUCER INSPECTION/CHECK							Service ATA:77
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 77-10-05PROC. REF: LMM 77-10-05								
77-20-01.2	NO. 1 ENGINE - THERMOCOUPLE HARNESS INSPECTION/CHECK							Service ATA:77
	MOS/MSC	29-Nov-78	A/R					
	HRS	0						
	ENC	0						
PROC. REF: LMM 77-20-01PROC. REF: LMM 77-20-01								
77-20-17-900-801-04	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 1 ITT INDICATOR (2EC1)							Component ATA:77
PN:5428-555-80-10	MOS/MSC	07-Feb-91	O/C					
SN:108	HRS	0		TSN 0				
WC#: 77.050	AFL	0						
PROC. REF: AMM 77-20-17-900-801PROC. REF: AMM 77-20-17-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-17-900-801-05 REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 2 ITT INDICATOR (2EC2)								Component ATA:77
PN:5428-559-08-80-10	MOS/MSC	17-Dec-21	O/C					
SN:123A	HRS	13275.5						
WC#: 77.050	AFL	6741						
PROC. REF: AMM 77-20-17-900-801PROC. REF: AMM 77-20-17-900-801								
77-20-17-900-801-06 REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 3 ITT INDICATOR (2EC3)								Component ATA:77
PN:5428-559-80-10	MOS/MSC	09-Feb-15	O/C					
SN:299	HRS	13109.23						
WC#: 77.050	AFL	6701						
PROC. REF: AMM 77-20-17-900-801PROC. REF: AMM 77-20-17-900-801								
771110 NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER								Component ATA:77
PN:3075388-2	MOS/MSC	06-Jul-99	O/C					
SN:981936000865	HRS	5508.7			TSN 0			
WC#: 77.010	ENC	3713			TSN 0			
PROC. REF: LMM 77-10-03PROC. REF: LMM 77-10-03								
771110 NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER								Component ATA:77
PN:3075388-1	MOS/MSC	01-Feb-90	O/C					
SN:UNKNOWN	HRS				TSN 0			
	ENC							
PROC. REF: LMM 77-10-03PROC. REF: LMM 77-10-03								
771110 NO. 3 ENGINE - LOW PRESSURE (N1) TRANSDUCER								Component ATA:77
PN:3073827-3	MOS/MSC	07-May-08	O/C					
SN:UNKNOWN	HRS	9388			TSN 9388			
WC#: 77.010	ENC	4723			TSN 4723			
PROC. REF: LMM 77-10-03PROC. REF: LMM 77-10-03								
771120 NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								Component ATA:77
PN:3070722-10	MOS/MSC	15-Mar-15	O/C		TSN 0			
SN:68001	HRS	10096.1			TSN 0			
WC#: 77.020	ENC	7632			TSN 0			
PROC. REF: LMM 77-10-05PROC. REF: LMM 77-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771120	NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component ATA:77
PN:3070722-3(L)	MOS/MSC	06-Jul-94	O/C					
SN:6778	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: LMM 77-10-05PROC. REF: LMM 77-10-05								
771120	NO. 3 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component ATA:77
PN:3070722-3	MOS/MSC	15-Dec-89	O/C					
SN:4990	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
PROC. REF: LMM 77-10-05PROC. REF: LMM 77-10-05								
772110	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:3073605-1	MOS/MSC	25-Jan-08	O/C					
SN:082021900342	HRS	7994.5						
WC#: 77.030	ENC	6466						
PROC. REF: LMM 77-20-01PROC. REF: LMM 77-20-01								
772110	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:3073605-1	MOS/MSC	16-Apr-19	O/C	TSN 0				
SN:1715027700182	HRS	8019.8		TSN 0				
	ENC	6841		TSN 0				
PROC. REF: LMM 77-20-01PROC. REF: LMM 77-20-01								
772110	NO. 3 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:3073605-1	MOS/MSC	07-May-08	O/C	TSN 0				
SN:08-20219-01778	HRS	9387.6		TSN 0				
WC#: 77.030	ENC	4723		TSN 0				
PROC. REF: LMM 77-20-01PROC. REF: LMM 77-20-01								
ATA 78 - EXHAUST								
78-30-00-210-801-01	^S	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER						Service ATA:78
	MOS	22-Dec-23	36 (+1m)					
	HRS	13641	2400 (+40)					
WC#: 78.010	AFL	7052						

PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: AMM 78-30-00-210-801PROC. REF: AMM 78-30-00-210-801								
78-30-00-720-801-01	^S	FUNCTIONAL TEST OF THE THRUST REVERSER SYSTEM WITH ENGINE SHUT DOWN						Service ATA:78
	MOS	22-Dec-23	72 (+2m)					
	HRS	13641						
WC#: 78.020	AFL	7052	3750					
PROC. REF: AMM 78-30-00-720-801PROC. REF: AMM 78-30-00-720-801								
78-30-00-910-807-01		INHIBITION OF THE THRUST REVERSER						Service ATA:78
	MOS/MSC	07-Feb-91	O/C					
	HRS	0						
WC#: 78.170	AFL	0						
PROC. REF: AMM 78-30-00-910-807PROC. REF: AMM 78-30-00-910-807								
78-31-00-640-802-01		GREASING OF THE THRUST REVERSER DOOR HINGE PINS						Service ATA:78
	MOS	17-Feb-26	12 (+1m)		17-Feb-27	17-Mar-27	299 d (+28)	
	HRS	13885.3	400 (+40)		14285.3	14325.3	389 (+40)	
WC#: 78.145	AFL	7304						
PROC. REF: AMM 78-31-00-640-802PROC. REF: AMM 78-31-00-640-802								
78-31-00-640-804-01	^S	GREASING OF THE THRUST REVERSER CONTROL AND UNLOCKING LINKAGE						Service ATA:78
	MOS	17-Feb-26	24 (+1m)					
	HRS	13885.3						
WC#: 78.100	AFL	7304						
PROC. REF: AMM 78-31-00-640-804PROC. REF: AMM 78-31-00-640-804								
78-31-05-900-801-01		REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR UPPER LATCH						Component ATA:78
PN:A861TS4RF900	MOS/MSC	07-Feb-91	O/C					
SN:872	HRS	0		TSN 0				
WC#: 78.140	AFL	0						
PROC. REF: AMM 78-31-05-900-801PROC. REF: AMM 78-31-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-31-05-900-802-01 REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR LOWER LATCH								Component ATA:78
PN:A861TS4RF50	MOS/MSC	07-Feb-91	O/C					
SN:818	HRS	0		TSN 0				
WC#: 78.140	AFL	0						
PROC. REF: AMM 78-31-05-900-802PROC. REF: AMM 78-31-05-900-802								
78-31-15-960-801-01 REPLACEMENT OF THE BALL-JOINT END-FITTING OF THE THRUST REVERSER DOOR ACTUATOR - TR ACTUATOR (202KR)								Service ATA:78
PN:106124-01	MOS/MSC	03-Dec-04	O/C					
SN:57	HRS	7002.4						
WC#: 78.100	AFL	3654						
PROC. REF: AMM 78-31-15-960-801PROC. REF: AMM 78-31-15-960-801								
78-32-09-900-801-01 REMOVAL / INSTALLATION OF THE THRUST REVERSER HYDRAULIC ACCUMULATOR - TR ACCUMULATOR (190KR)								Component ATA:78
PN:60909-1	MOS/MSC	07-Feb-91	O/C					
SN:7909	HRS	0		TSN 0				
WC#: 78.050	AFL	0						
PROC. REF: AMM 78-32-09-900-801PROC. REF: AMM 78-32-09-900-801								
783101 THRUST REVERSER SYSTEM PRESSURE GAGE								Component ATA:78
PN:18040100	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.030	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783106 THRUST REVERSER SYSTEM CHARGING VALVE								Component ATA:78
PN:MS26889-2	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.040	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783221 THRUST REVERSER ELECTRODISTRIBUTION CONTROL								Component ATA:78
PN:108131-02	MOS/MSC	03-Dec-04	O/C	TSR 0				
SN:84	HRS	7002.4		TSR 0				
WC#: 78.060	AFL	3654		TSR 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783301	THRUST REVERSER SYSTEM CHECK SUPPLY VALVE							Component ATA:78
PN:A24515	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.070	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783311	THRUST REVERSER SYSTEM CHECK RETURN VALVE							Component ATA:78
PN:C24816000	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.070	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783321	THRUST REVERSER RETRACTION JACK ISOLATION VALVE							Component ATA:78
PN:AE99113E	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.080	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783331	THRUST REVERSER EXTENSION JACK ISOLATION VALVE							Component ATA:78
PN:AE99113E	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.080	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783341	THRUST REVERSER JACK LOCKING ISOLATION VALVE							Component ATA:78
PN:AE99113G	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.090	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783401	THRUST REVERSER HYDRAULIC CONTROL ACTUATOR							Component ATA:78
PN:106124-01	MOS/MSC	03-Dec-04	O/C					
SN:57	HRS	7002.4		TSR 0				
WC#: 78.100	AFL	3654						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783411	THRUST REVERSER SYNCHRONIZING BELLCRANK							Component ATA:78
PN:F900HD3200240A5	MOS/MSC	14-Mar-01	O/C					
SN:UNKNOWN	HRS	4661						
WC#: 78.110	AFL	2106						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783421	THRUST REVERSER LEFT CONTROL DOOR ADJUSTMENT ROD							Component ATA:78
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.120	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783431	THRUST REVERSER RIGHT CONTROL DOOR ADJUSTMENT ROD							Component ATA:78
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.120	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783441	THRUST REVERSER UPPER CATCH UNLOCK JACK							Component ATA:78
PN:106125-01	MOS/MSC	09-Feb-15	O/C					
SN:229	HRS	13109.23						
WC#: 78.130	AFL	6701						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783451	THRUST REVERSER LOWER CATCH UNLOCK JACK							Component ATA:78
PN:106125-01	MOS/MSC	07-Feb-91	O/C					
SN:209	HRS	0		TSN 0				
WC#: 78.130	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783501	LH THRUST REVERSER DOOR INDICATING MICROSWITCH							Component ATA:78
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.150	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783506	RH THRUST REVERSER DOOR INDICATING MICROSWITCH							Component ATA:78
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.150	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
783511	THRUST REVERSER SYNCHRONIZING BELLCRANK MICROSWITCH							Component ATA:78
PN:PN	MOS/MSC	07-Feb-91	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.160	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
ATA 79 - OIL								
79-30-17-900-801-04	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 1 OIL PRESSURE/TEMPERATURE INDICATOR (2EM1)							Component ATA:79
PN:64857-418-1	MOS/MSC	24-Nov-07	O/C					
SN:308	HRS	10139						
WC#: 79.100	AFL	5423						
PROC. REF: AMM 79-30-17-900-801PROC. REF: AMM 79-30-17-900-801								
79-30-17-900-801-05	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 2 OIL PRESSURE/TEMPERATURE INDICATOR (2EM2)							Component ATA:79
PN:64857-418-1	MOS/MSC	02-Jul-08	O/C	TSR 0				
SN:334	HRS	10575.6		TSR 0				
WC#: 79.100	AFL	5683		TSR 0				
PROC. REF: AMM 79-30-17-900-801PROC. REF: AMM 79-30-17-900-801								
79-30-17-900-801-06	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 3 OIL PRESSURE/TEMPERATURE INDICATOR (2EM3)							Component ATA:79
PN:64857-418-1	MOS/MSC	24-Nov-07	O/C					
SN:527	HRS	10139						
WC#: 79.100	AFL	5423						
PROC. REF: AMM 79-30-17-900-801PROC. REF: AMM 79-30-17-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790110	NO. 1 ENGINE - ANALYZE OIL AND FILTER							Service ATA:79
	MOS	06-May-25						
	HRS	10937.02	150 (+100)		(11087.02) 13986.2	11187.02	89.9 (+100)	
WC#: 79.010	ENC	8305						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
790110	NO. 2 ENGINE - ANALYZE OIL AND FILTER							Service ATA:79
	MOS	12-May-25						
	HRS	8612.02	150 (+100)		(8762.02) 13986.2	8862.02	89.9 (+100)	
	ENC	7370						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
790111 ^S	NO. 3 ENGINE - ANALYZE OIL AND FILTER							Service ATA:79
	MOS	12-May-25						
	HRS	12399.62	150 (+100)					
WC#: 79.010	ENC	6142						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:1
790120	NO. 1 ENGINE - CHANGE OIL							Service ATA:79
	MOS	11-Jan-21						
	HRS	10373.1	1500 (+50)		(11873.1) 14772.28	11923.1	876 (+50)	
WC#: 79.020	ENC	7792						
PROC. REF: AMM 79-00-00, LMM 72-00-00PROC. REF: AMM 79-00-00, LMM 72-00-00								
790120	NO. 2 ENGINE - CHANGE OIL							Service ATA:79
	MOS	16-Apr-19						
	HRS	8019.8	1200 (+100)		(9219.8) 14443.98	9319.8	547.7 (+100)	
	ENC	6841						
PROC. REF: AMM 79-00-00, LMM 72-00-00PROC. REF: AMM 79-00-00, LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790120	NO. 3 ENGINE - CHANGE OIL							Service ATA:79
	MOS	20-Jan-15						
	HRS	11672.88	1200 (+100)		(12872.88) 14309.47	12972.88	413.2 (+100)	
WC#: 79.020	ENC	5594						
PROC. REF: AMM 79-00-00, LMM 72-00-00PROC. REF: AMM 79-00-00, LMM 72-00-00								
790130 ^S	NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR							Service ATA:79
	MOS	06-May-25						
	HRS	10937.02	150 (+100)					
WC#: 79.030	ENC	8305						
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03								PKG:1
790130 ^S	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR							Service ATA:79
	MOS	12-May-25						
	HRS	8612.02	150 (+100)					
	ENC	7370						
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03								PKG:1
790130 ^S	NO. 3 ENGINE - INSPECT OIL CHIP DETECTOR							Service ATA:79
	MOS	12-May-25						
	HRS	12399.62	150 (+100)					
WC#: 79.030	ENC	6142						
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03								PKG:1
792110	NO. 1 ENGINE - OIL PUMP							Component ATA:79
PN:3071949-12	MOS/MSC	17-Oct-12	O/C	TSR 4				
SN:1131C	HRS	9555.4		TSR 0				
WC#: 79.040	ENC	7315		TSR 0				
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792110	NO. 2 ENGINE - OIL PUMP							Component ATA:79
PN:3071949-12	MOS/MSC	18-Oct-12	O/C	TSR 1				
SN:804	HRS	7377.4		TSR 0				
	ENC	6366		TSR 0				
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03								
792110	NO. 3 ENGINE - OIL PUMP							Component ATA:79
PN:3071949-12	MOS/MSC	06-Nov-09	O/C	TSR 0				
SN:991405700165	HRS	9693.77		TSR 0				
WC#: 79.040	ENC	4922		TSR 0				
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03								
792120	NO. 1 ENGINE - BY-PASS INDICATOR VALVE							Component ATA:79
PN:3002780-3	MOS/MSC	29-Nov-78	O/C					
SN:847	HRS	0		TSN 0				
WC#: 79.050	ENC	0		TSN 0				
PROC. REF: LMM 79-30-01PROC. REF: LMM 79-30-01								
792120	NO. 2 ENGINE - BY-PASS INDICATOR VALVE							Component ATA:79
PN:3002780-4	MOS/MSC	06-Oct-95	O/C					
SN:856	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 79-30-01PROC. REF: LMM 79-30-01								
792120	NO. 3 ENGINE - BY-PASS INDICATOR VALVE							Component ATA:79
PN:3002780-4	MOS/MSC	07-May-08	O/C					
SN:000913900567	HRS	9388						
WC#: 79.050	ENC	4723						
PROC. REF: LMM 79-30-01PROC. REF: LMM 79-30-01								
792130	NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:3075253-3	MOS/MSC	06-Nov-20	O/C	TSN 0				
SN:19P31888	HRS	10345.3		TSN 0				
WC#: 79.060	ENC	7794		TSN 0				
PROC. REF: LMM 79-20-02PROC. REF: LMM 79-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:3075323-2	MOS/MSC	06-Oct-95	O/C					
SN:1-0814500658	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 79-20-02PROC. REF: LMM 79-20-02								
792130	NO. 3 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:3075323-3	MOS/MSC	04-Feb-11	O/C	TSO 0				
SN:1132	HRS	10091.17		TSO 0				
WC#: 79.060	ENC	5045		TSO 0				
PROC. REF: LMM 79-20-02PROC. REF: LMM 79-20-02								
792140	NO. 1 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:158600-7	MOS/MSC	29-Nov-78	O/C					
SN:83-251	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792140	NO. 2 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:158600-7	MOS/MSC	06-Oct-95	O/C					
SN:19-9423	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792140	NO. 3 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:158600-7	MOS/MSC	15-Dec-89	O/C					
SN:38-9198	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:159900-3	MOS/MSC	29-Nov-78	O/C					
SN:122-187	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:159900-3	MOS/MSC	06-Oct-95	O/C					
SN:18-6700	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792150	NO. 3 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:159900-3	MOS/MSC	15-Dec-89	O/C					
SN:49-7067	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	29-Nov-78	O/C					
SN:95-664	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	06-Oct-95	O/C					
SN:108-6907	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792160	NO. 3 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	15-Dec-89	O/C					
SN:10-7090	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792170	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR							Component ATA:79
PN:158610-8	MOS/MSC	29-Nov-78	O/C					
SN:17-1206	HRS	0		TSN 0				
WC#: 79.100	ENC	0		TSN 0				
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792170	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR							Component ATA:79
PN:158610-8	MOS/MSC	06-Oct-95	O/C					
SN:38-6931	HRS	2150.7						
	ENC	1854						
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07								
792170	NO. 3 ENGINE - OIL TEMPERATURE REGULATOR							Component ATA:79
PN:158610-8	MOS/MSC	15-Dec-89	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.100	ENC	0		TSN 0				
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07								
793083	NO. 1 ENGINE LOW OIL PRESSURE SWITCH							Component ATA:79
PN:8G1126-2	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:683	HRS	0		TSN 0				
WC#: 79.075	AFL	0		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793084	NO. 2 ENGINE LOW OIL PRESSURE SWITCH							Component ATA:79
PN:8G1126-2	MOS/MSC	06-May-13	O/C	TSN 0				
SN:2217	HRS	11118.98		TSN 0				
WC#: 79.075	AFL	5842		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793085	NO. 3 ENGINE LOW OIL PRESSURE SWITCH							Component ATA:79
PN:8G1126-2	MOS/MSC	16-May-95	O/C	TSN 0				
SN:920	HRS			TSN 0				
WC#: 79.075	AFL			TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793101	NO. 1 ENGINE OIL PRESSURE TRANSMITTER							Component ATA:79
PN:64251-417-2	MOS/MSC	31-Mar-14	O/C					
SN:2897	HRS	12625.42						
WC#: 79.080	AFL	6516						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793102	NO. 2 ENGINE OIL PRESSURE TRANSMITTER							Component ATA:79
PN:64251-417-2	MOS/MSC	04-Jul-08	O/C	TSN 0				
SN:7795	HRS	10578.5		TSN 0				
WC#: 79.080	AFL	5685		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793103	NO. 3 ENGINE OIL PRESSURE TRANSMITTER							Component ATA:79
PN:64251-417-2	MOS/MSC	17-Apr-14	O/C					
SN:7910	HRS	12671.82						
WC#: 79.080	AFL	6527						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793110	NO. 1 ENGINE - OIL PRESSURE TRANSMITTER							Component ATA:79
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
793110 ^U	NO. 2 ENGINE - OIL PRESSURE TRANSMITTER							Component ATA:79
PN:PN	MOS/MSC	22-Feb-90	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
	(AFL)	0		TSN 0				
793119	NO. 1 ENGINE OIL TEMPERATURE PROBE							Component ATA:79
PN:56B17	MOS/MSC	16-Jul-00	O/C	TSN 0				
SN:12875	HRS			TSN 0				
WC#: 79.090	AFL			TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793120	NO. 2 ENGINE OIL TEMPERATURE PROBE							Component ATA:79
PN:56B17	MOS/MSC	07-Feb-91	O/C	TSN 0				
SN:96620	HRS	0		TSN 0				
WC#: 79.090	AFL	0		TSN 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793121	NO. 3 ENGINE OIL TEMPERATURE PROBE							Component ATA:79
PN:56B17	MOS/MSC	07-Feb-91	O/C					
SN:96620	HRS	0		TSN 0				
WC#: 79.090	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793155	ENGINE OIL LEVEL INDICATOR							Component ATA:79
PN:267-968-004	MOS/MSC	07-Feb-91	O/C					
SN:147	HRS	0		TSN 0				
WC#: 79.110	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793161	ENGINE OIL LEVEL AMPLIFIER							Component ATA:79
PN:360-967-004	MOS/MSC	07-Feb-91	O/C					
SN:258	HRS	0		TSN 0				
WC#: 79.120	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793167	NO. 1 ENGINE OIL LEVEL GAGE							Component ATA:79
PN:029-907-004	MOS/MSC	22-Oct-03	O/C	TSO 0				
SN:274	HRS	6281.9		TSO 0				
WC#: 79.130	AFL	2902		TSO 0				
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793168	NO. 2 ENGINE OIL LEVEL GAGE							Component ATA:79
PN:029-907-004	MOS/MSC	07-Feb-91	O/C					
SN:460	HRS	0		TSN 0				
WC#: 79.130	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								
793169	NO. 3 ENGINE OIL LEVEL GAGE							Component ATA:79
PN:029-907-004	MOS/MSC	07-Feb-91	O/C					
SN:463	HRS	0		TSN 0				
WC#: 79.130	AFL	0						
PROC. REF: AMM GENERIC 2PROC. REF: AMM GENERIC 2								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: FALCON 900B Serial: 091 RegNo: N900KU HRS: 13896.3 AFL: 7313 As Of: 27-Mar-2026

24-Apr-2026 08:54 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793320	NO. 1 ENGINE - FUEL/OIL COOLER							Component ATA:79
PN:PN	MOS/MSC	29-Nov-78	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07								
793320 ^U	NO. 2 ENGINE - FUEL/OIL COOLER							Component ATA:79
PN:PN	MOS/MSC	22-Feb-90	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
	(AFL)	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task