



CAMP SYSTEMS INTERNATIONAL INC.
8201 E. 34TH STREET N
BUILDING 1100, SUITE 1101
WICHITA, KS 67226
USA

BOUND PRINTED MATTER

WIDE OPEN ADVENTURES
ATTN: STEVE MINGHENELLI
1264 OLD WHITE HORSE PK
WATERFORD, NJ 08089
USA

Ship Method:

Ship Count	Zone
1	USA

525 - CITATION JET S/N: 525-0139 Reg: N36RG



525 - CITATION JET S/N: 525-0139 Reg: N36RG

OWNER: WIDE OPEN ADVENTURES
ADDRESS: 1264 OLD WHITE HORSE PK
WATERFORD NJ 08089
PHONE: 609-313-4135
FAX: 856-767-2773

OPERATOR: WIDE OPEN ADVENTURES
ADDRESS: 1264 OLD WHITE HORSE PK
WATERFORD NJ 08089
PHONE: 609-313-4135
FAX: 856-767-2773

ANALYST: FIRAS MANDOUR
EMAIL: FMANDOUR@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
316-462-2442 (FAX)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 1	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 2	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
AIR COND	1573.1		31-Oct-2024	.05	0.17	15.28		92	3



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
E062-221212 E1	LIGHT MAINTENANCE MANUAL - FJ44-1A - REVISION 66 - DEC 12/2022			MTH			-			
E062-221212 E2	LIGHT MAINTENANCE MANUAL - FJ44-1A - REVISION 66 - DEC 12/2022			MTH			-			
E062-230330 E1	REVIEW REVIEW FJ44-1A LMM REV 67			MTH			-			
E062-230330 E2	REVIEW REVIEW FJ44-1A LMM REV 67			MTH			-			
5-12-01 0512001B	INSPECTION DOCUMENT 01 N81			MTH HRS LDG	02-Jul-2024 2931.7 2459		300		3231.7	229.8
5-12-02 0512002	INSPECTION DOCUMENT 02 N81			MTH HRS LDG	04-Jul-2024 2931.7 2459		12		31-Jul-2025	3 m 0 d
B262201 COCKPIT 0512016	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER N81			C352TS E-92812238 MTH HRS LDG	04-Jul-2024 2931.7 2459		12		31-Jul-2025	3 m 0 d
Weight Check Date: 04-Jul-2024										
5-12-04	INSPECTION DOCUMENT 04 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) CHA			MTH HRS LDG	07-Apr-2022 2642.8 2253		36			
A323101 0512004 : GEAR	RESTORATION (HYDROSTATIC TEST) EMERGENCY GEAR BOTTLE CHA			40005320-2 7471 MTH	07-Apr-2022		36		30-Apr-2025	0 d
Hydro Check Date: 07-Apr-2022										
5-12-05	INSPECTION DOCUMENT 05 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH HRS LDG	19-Mar-2021 2641.8 2252		60			
B262002 LEFT 0512005 : L	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE KTTN			30400031-1 36687B1 MTH	25-Feb-2021		60		28-Feb-2026	10 m 0 d
Hydro Check Date: 25-Feb-2021										
B262002 RIGHT 0512005 : R	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE KTTN			30400031-1 36686B1 MTH	25-Feb-2021		60		28-Feb-2026	10 m 0 d
Hydro Check Date: 25-Feb-2021										
5-12-06	INSPECTION DOCUMENT 06 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) KTTN			MTH HRS LDG	01-May-2014 2543.4 2156		72			
A262201 COCKPIT 0512006	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER N81			C352TS E-92812238 MTH HRS LDG	31-Jan-2025 2974.9 2490		72		28-Feb-2031	70 m 0 d
Test Date: 01-Feb-2025										
5-12-07	INSPECTION DOCUMENT 07 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) TTN			MTH HRS LDG	19-Jul-2011 2409.8 2057		144			
B262202 COCKPIT 0512007	RESTORATION (HYDROSTATIC TEST) PORTABLE FIRE EXTINGUISHER KTTN			C352TS E-92812238 MTH	24-Oct-2018		144		31-Oct-2030	66 m 0 d
Hydro Check Date: 24-Oct-2018										
5-12-08 0512008	INSPECTION DOCUMENT 08 N81			MTH HRS LDG	04-Jul-2024 2931.7 2459		24 300		31-Jul-2026 3231.7	15 m 0 d 229.8

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-09	INSPECTION DOCUMENT 09 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	N81			MTH 30-Jan-2025 HRS 2974.9 LDG 2490		12 600			
A243301 0512009	LEAD ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) NOTE: THE INSPECTION SCHEDULE MAY BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED, BASED ON OPERATIONS. TASK 24-33-00-720	N81		RG380E/44L 70020633	MTH 30-Jan-2025 HRS 2974.9 LDG 2490		12 600		31-Jan-2026 3574.9	9 m 0 d 573
5-12-10 0512010	INSPECTION DOCUMENT 10	N81			MTH 10-Jul-2024 HRS 2931.7 LDG 2459		36 1200		31-Jul-2027 4131.7	27 m 0 d 1129.8
5-12-11 0512011	INSPECTION DOCUMENT 11	N81			MTH 10-Jul-2024 HRS 2931.7 LDG 2459		36 1200		31-Jul-2027 4131.7	27 m 0 d 1129.8
5-12-12 0512012	INSPECTION DOCUMENT 12 (14 CFR 91.207)	N81			MTH 04-Jul-2024 HRS 2931.7 LDG 2459		12		31-Jul-2025	3 m 0 d
5-12-13	INSPECTION DOCUMENT 13 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK			MTH 10-Jan-2025 HRS LDG		24			
B341011 LEFT 0512013 : L Calibration Date: 10-Jan-2025	LEFT PITOT-STATIC SYSTEMS FUNCTIONAL CHECK (AIRPLANES -0003, -0360 AND ON AND AIRPLANES -0001 THRU -0359 INCORPORATING SB525-34-41)	UNK			MTH 10-Jan-2025		24		31-Jan-2027	21 m 0 d
B341011 RIGHT 0512013 : R Calibration Date: 10-Jan-2025	RIGHT PITOT-STATIC SYSTEMS FUNCTIONAL CHECK (AIRPLANES -0003, -0360 AND ON AND AIRPLANES -0001 THRU -0359 INCORPORATING SB525-34-41)	UNK			MTH 10-Jan-2025		24		31-Jan-2027	21 m 0 d
B345401 NO. 1 0512013 : 1 Calibration Date: 10-Jan-2025	NO. 1 TRANSPONDER SYSTEM 14 CFR PART 91.413 CALIBRATION CHECK (EXCEPT PHILIPPINE REGISTERED AIRPLANES)	UNK		011-03303-01 3EH040458	MTH 10-Jan-2025		24		31-Jan-2027	21 m 0 d
B345401 NO. 2 0512013 : 2 Calibration Date: 10-Jan-2025	NO. 2 TRANSPONDER SYSTEM 14 CFR PART 91.413 CALIBRATION CHECK (EXCEPT PHILIPPINE REGISTERED AIRPLANES)	UNK		011-03301-01 7KU000327	MTH 10-Jan-2025		24		31-Jan-2027	21 m 0 d
5-12-14	INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 31-May-1996 HRS 0 LDG 0		T/C			
A324103 LEFT 0512014 : L	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI)	*CF		3-1527-1 0431	MTH		T/C			
A324103 NOSE 0512014 : NOSE	SPECIAL DETAIL INSPECT LANDING GEAR WHEEL ASSY (NDI)	*CF		3-1418 2168	MTH 31-May-1996		T/C			
A324103 RIGHT 0512014 : R	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI)	*CF		3-1527-1 0432	MTH		T/C			
5-12-18 0512018	INSPECTION DOCUMENT 18	N81			MTH 04-Jul-2024 HRS 2931.7 LDG 2459		N/A			
5-12-21 0512021	INSPECTION DOCUMENT 21	KLNS			MTH 04-May-2023 HRS 2764 LDG 2343		24 600		31-May-2025 3364	1 m 0 d 362.1
5-12-29	INSPECTION DOCUMENT 29				MTH 31-May-1996 HRS 0		7200		7200	4198.1

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-33 0512033	INSPECTION DOCUMENT 33	N81	MTH HRS LDG	04-Jul-2024 2931.7 2459		12 300		31-Jul-2025 3231.7	3 m 0 d 229.8
5-12-34 0512034	INSPECTION DOCUMENT 34 (NOT CURRENTLY USED)	MIV	MTH ACH	21-Sep-2005 961		N/R			
5-12-35 0512035	INSPECTION DOCUMENT 35 (NOT CURRENTLY USED)	*CF	MTH	31-May-1996		N/R			
5-12-36	INSPECTION DOCUMENT 36	N81	MTH HRS LDG	30-Jan-2025 2974.9 2490		6		31-Jul-2025	3 m 0 d
5-12-MA 05120MA	INSPECTION DOCUMENT MA	N81	MTH HRS LDG	10-Jul-2024 2931.7 2459		300		3231.7	229.8
5-12-MC 05120MC	INSPECTION DOCUMENT MC	MQS	MTH HRS LDG	02-Aug-2012 2468.4 2102		1200		3668.4	666.5
5-12-MD 05120MD	INSPECTION DOCUMENT MD	*CF	MTH LDG	31-May-1996 0		5000		5000	2495
5-12-MF 05120MF	INSPECTION DOCUMENT MF	*CF	MTH HRS	31-May-1996 0		6000		6000	2998.1
5-12-MG 05120MG	INSPECTION DOCUMENT MG	*CF	MTH HRS	31-May-1996 0		6000		6000	2998.1
5-12-MH 05120MH	INSPECTION DOCUMENT MH	*CF	MTH HRS	31-May-1996 0		6000		6000	2998.1
5-12-MI 05120MI	INSPECTION DOCUMENT MI	*CF	MTH HRS	31-May-1996 0		7200		7200	4198.1
5-12-MJ 05120MJ	INSPECTION DOCUMENT MJ	*CF	MTH HRS	31-May-1996 0		7200		7200	4198.1
5-12-MK 05120MK	INSPECTION DOCUMENT MK	*CF	MTH HRS	31-May-1996 0		7900		7900	4898.1
5-12-ML 05120ML	INSPECTION DOCUMENT ML	*CF	MTH HRS	31-May-1996 0		9600		9600	6598.1
5-12-MO 05120MO	INSPECTION DOCUMENT MO	*CF	MTH HRS	31-May-1996 0		15200		15200	12198.1
5-12-MQ	INSPECTION DOCUMENT MQ		MTH HRS			14000		14000	10998.1
A551004 045503	HORIZONTAL STABILIZER FRONT UPPER SPAR CAP AT SS4.78	*CF	INSPECTION TASK 55-10-00-250 MTH HRS	31-May-1996 0		14000		14000	10998.1
5-12-MR	INSPECTION DOCUMENT MR		MTH HRS			13200		13200	10198.1
A570006 045701	LOWER MAIN SPAR SPLICE AT WS 93.00 (EDDY CURRENT)	*CF	SPECIAL DETAILED INSPECTION TASK 57-00-00-250 MTH HRS	31-May-1996 0		13200		13200	10198.1
5-12-MS	INSPECTION DOCUMENT MS		MTH HRS			15000		15000	11998.1
A570007 045702	LOWER REAR SPAR SPLICE AT WS 93.00 (EDDY CURRENT)	*CF	SPECIAL DETAILED INSPECTION TASK 57-00-00-251 MTH HRS	31-May-1996 0		15000		15000	11998.1
5-12-MT	INSPECTION DOCUMENT MT		MTH HRS			19200		19200	16198.1
A570008 045703	MAIN SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) (EDDY CURRENT)	*CF	SPECIAL DETAILED INSPECTION TASK 57-00-00-252 MTH HRS	31-May-1996 0		19200		19200	16198.1
5-12-MU	INSPECTION DOCUMENT MU		MTH HRS			19200		19200	16198.1

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains
A570009 045704	REAR SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-253	*CF		MTH 31-May-1996 HRS 0			19200		19200	16198.1
5-12-MV	INSPECTION DOCUMENT MV			MTH HRS			22800		22800	19798.1
A570010 045705	MAIN SPAR OUTBOARD LOWER CAP (WS 120.0 TO WS 152.00) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-254	*CF		MTH 31-May-1996 HRS 0			22800		22800	19798.1
05-50-00-870-803-01 E1	POLISH FAN ROTOR			MTH 31-May-1996			A/R			
05-50-00-870-803-01 E2	POLISH FAN ROTOR			MTH 31-May-1996			A/R			
052001 E1	FJ44 CHECK 1	KSWF		MTH 19-Oct-2023 HRS 2837.6 LDG 2402			300		3137.6	135.7
052001 E2	FJ44 CHECK 1	KSWF		MTH 19-Oct-2023 HRS 2837.6 LDG 2402			300		3137.6	135.7
052002 E1	FJ44 CHECK 2	KSWF		MTH 19-Oct-2023 HRS 2837.6 LDG 2402			600		3437.6	435.7
052002 E2	FJ44 CHECK 2	KSWF		MTH 19-Oct-2023 HRS 2837.6 LDG 2402			600		3437.6	435.7
052003 E1	FJ44 CHECK 3			MTH 17-Oct-2002 HRS 1485 LDG 1310			-			
052003 E2	FJ44 CHECK 3			MTH 17-Oct-2002 HRS 1485 LDG 1310			-			
052004 E1	FJ44 CHECK 4	DAL		MTH 31-May-1996 HRS 0	-15		5000		4985	1983.1
052004 E2	FJ44 CHECK 4	DAL		MTH 31-May-1996 HRS 0	-15		5000		4985	1983.1
052005 E1	FJ44 CHECK 5			MTH 31-May-1996 HRS 0	-15		8500		8485	5483.1
052005 E2	FJ44 CHECK 5			MTH 31-May-1996 HRS 0	-15		8500		8485	5483.1
052006 E1	FJ44 CHECK 6			MTH 31-May-1996 HRS 0	-15		10000		9985	6983.1
052006 E2	FJ44 CHECK 6			MTH 31-May-1996 HRS 0	-15		10000		9985	6983.1
052007 E1	FJ44 CHECK 7			MTH 31-May-1996 HRS 0	-15		13500		13485	10483.1
052007 E2	FJ44 CHECK 7			MTH 31-May-1996 HRS 0	-15		13500		13485	10483.1
052008 E1	FJ44 CHECK 8			MTH 31-May-1996 HRS 0	-15		15000		14985	11983.1
052008 E2	FJ44 CHECK 8			MTH 31-May-1996 HRS 0	-15		15000		14985	11983.1
052009 E1	FJ44 CHECK 9			MTH 31-May-1996 HRS 0	-15		18500		18485	15483.1
052009 E2	FJ44 CHECK 9			MTH 31-May-1996 HRS 0	-15		18500		18485	15483.1
052010 E1	FJ44 CHECK 10			MTH 31-May-1996 HRS 0	-15		20000		19985	16983.1

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
052010 E2	FJ44 CHECK 10			MTH	31-May-1996					
				HRS	0	-15	20000		19985	16983.1
052011 E1	FJ44 CHECK 11			MTH	31-May-1996		23500		23500	20498.1
				HRS	0					
052011 E2	FJ44 CHECK 11			MTH	31-May-1996		23500		23500	20498.1
				HRS	0					
052012 E1	FJ44 CHECK 12			MTH	31-May-1996		25000		25000	21998.1
				HRS	0					
052012 E2	FJ44 CHECK 12			MTH	31-May-1996		25000		25000	21998.1
				HRS	0					
052013 E1	FJ44 CHECK 13			MTH	31-May-1996		28500		28500	25498.1
				HRS	0					
052013 E2	FJ44 CHECK 13			MTH	31-May-1996		28500		28500	25498.1
				HRS	0					
052014 E1	FJ44 CHECK 14			MTH	31-May-1996		30000		30000	26998.1
				HRS	0					
052014 E2	FJ44 CHECK 14			MTH	31-May-1996		30000		30000	26998.1
				HRS	0					
12-22-01-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH			DAYS	17-Apr-2022		A/R			
				HRS	2660.3					
12-22-01-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH UNK			DAYS	15-May-2022		A/R			
				HRS	2675					
12-22-01-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH UNK			DAYS	27-Jun-2022		A/R			
				HRS	2688.2					
262002A LEFT NO. 1 262002 : L1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KSWF			AE13083-5 A158	MTH	19-Oct-2023	96		31-Oct-2031	78 m 0 d
					HRS	2837.6				
					LDG	2402				
262002C LEFT NO. 2 262002 : L2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KSWF			AE13083-5 A154	MTH	19-Oct-2023	96		31-Oct-2031	78 m 0 d
					HRS	2837.6				
					LDG	2402				
262002E RIGHT NO. 1 262002 : R1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KSWF			AE13083-5 A156	MTH	19-Oct-2023	96		31-Oct-2031	78 m 0 d
					HRS	2837.6				
					LDG	2402				
262002G RIGHT NO. 2 262002 : R2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KSWF			AE13083-5 A155	MTH	19-Oct-2023	96		31-Oct-2031	78 m 0 d
					HRS	2837.6				
					LDG	2402				
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH	03-Aug-2022	A/R			
					HRS	2693.7				
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH	31-May-1996	A/R			
341057 LEFT 0512013B : L-ADC Calibration Date: 10-Jan-2025	CALIBRATION TEST ADC/ALT UNIT (FAR 91.411) UNK			AM250 03091144B	MTH	10-Jan-2025	A/R			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
341058 RIGHT <i>0512013B : R-ADC</i> Calibration Date: 10-Jan-2025	CALIBRATION TEST ADC/ALT UNIT (FAR 91.411)	UNK		AM250 03091177B	MTH 10-Jan-2025		A/R			
341106 STANDBY <i>0512013 : STDBY</i> Calibration Date: 10-Jan-2025	CALIBRATION TEST ENCODING ALTIMETER (FAR 91.411)			44929-935 1099	MTH 10-Jan-2025		A/R			
350004 Hydro Check Date: 02-Mar-2021	HYDROSTATIC TEST OXYGEN BOTTLE (DOT SP-10945)	KTTN		176274-50 ALT279-19239/0501	MTH 02-Mar-2021		60		31-Mar-2026	11 m 0 d
710010 E1	COMPRESSOR CLEANING				MTH 31-May-1996		A/R			
710010 E2	COMPRESSOR CLEANING				MTH 31-May-1996		A/R			
731025 E1	FUEL FILTER REPLACEMENT KSWF				MTH 19-Oct-2023 HRS 2837.6 LDG 2402		1200		4037.6	1035.7
731025 E2	FUEL FILTER REPLACEMENT KSWF				MTH 19-Oct-2023 HRS 2837.6 LDG 2402		1200		4037.6	1035.7



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
 Aircraft Model: **525 - CITATION JET**
 Aircraft Serial: **525-0139**
 Unit: **0139** Reg No: **N36RG**
 Airworthiness: **31-May-1996**
 Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	B/A FLOW CONTROL VALVE 9912420-3	*CF		1H124-8 1AM2	MTH 31-May-1996		O/C			
211003	HEAT PRESSURE EXCHANGER *CF			10840A 242	MTH 31-May-1996		O/C			
211004	RAM AIR MODULATING VALVE OBI			27241287-15 3AP22E	MTH 27-Feb-2009 HRS 2235		O/C	0		
211005	EMERGENCY PRESS SHUTOFF VALVE CHA			9912422-1 0348	MTH 07-Apr-2022 HRS 2642.8 LDG 2253		O/C			
212001	UNDERFLOOR INLET AIR BLOWER *CF			0113-12 184	MTH 31-May-1996		O/C			
212003	TEMP PRESS COMPRESSION SWITCH *CF			1173T42-3 1888	MTH 31-May-1996		O/C			
212011 AFT	TEMP UNDERFLOOR SENSOR 9912085-3	*CF		27221274 3AM78	MTH 31-May-1996		O/C			
212202	OVERHEAD AIR VALVE SOLENOID *CF			D113204 SN-UNKNOWN	MTH 31-May-1996		O/C			
212203	ACTUATOR *CF			D-68070-A-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
212302	BLOWER - WINDSHIELD AIR MOTOR *CF			7003-200 169	MTH 31-May-1996		O/C			
212401	AVIONICS COOLING BLOWER KA33	*CF		071-04037-0001 SN-UNKNOWN	MTH 31-May-1996		O/C			
212403	AVIONICS COOLING BLOWER *CF			19A827 SN-UNKNOWN	MTH 31-May-1996		O/C			
212404 NOSE	AVIONICS COOLING FAN *CF			032105 SN-UNKNOWN	MTH 31-May-1996		O/C			
213001	PRESS MASTER OUTFLOW VALVE 9912409-2	*CF		52771-101 251	MTH 31-May-1996		O/C			
213002	PRESS SECONDARY OUTFLOW VALVE 9912409-3	*CF		52772-101 239	MTH 31-May-1996		O/C			
213003	PRESSURIZATION CONTROLLER 9912409-5	*CF		52770-111 275	MTH 31-May-1996		O/C			
213005	DIFFERENTIAL PRESS INDICATOR *CF			C668511-0105 1095	MTH 31-May-1996		O/C			
213008	PRESS MANUAL CONTROL SWITCH 9912409-4	*CF		52773-001 262	MTH 31-May-1996		O/C			
215001	FORWARD EVAPORATOR *CF			1134820-1 123	MTH 31-May-1996		O/C			
215002	AFT EVAPORATOR 9912459-10	KMQS		1134820-14 262	MTH 06-Jul-2010 HRS 2354.3 LDG 2021 ACH 1242		O/C	0		
215003 AFT	EVAPORATOR MOTOR *CF			1250210-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
215003 FORWARD	EVAPORATOR MOTOR *CF			1250210-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
215004	AIR CONDITIONER COMPRESSOR *CF			1134162 371	MTH 31-May-1996		O/C			
215005	AIR CONDITIONER CONDENSER *CF			1134180-1 125	MTH 31-May-1996		O/C			
215006	COMPRESSOR DRIVE MOTOR N81			1134104-1 3676	MTH 31-Oct-2024 HRS 2951.4 LDG 2473		O/C	0 0 0		
215007	RECEIVER DRYER ASSEMBLY *CF			1134140-3 SN-UNKNOWN	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215008	BINARY SWITCH	*CF		1250232-4 2358	MTH 31-May-1996		O/C			
215009	A/C FLIGHT HOUR METER	*CF		1250703 SN-UNKNOWN	MTH 31-May-1996		O/C			
215011	AIR CONDITIONER DRIVE BELT R134A	N81		232L100 2980SS	MTH 16-Jun-2022 HRS 2671 LDG 2257		O/C	0 0		
215012	COMPRESSOR DRIVE MOTOR BRUSHES N81			1251171 SN-UNKNOWN	MTH 31-Oct-2024 HRS 2951.4 LDG 2473 ACH 1573.1			0 0 0 0	2073.1	500
215013 AFT	EXPANSION VALVE	*CF		1250218 SN-UNKNOWN	MTH 31-May-1996		O/C			
215013 FORWARD	EXPANSION VALVE	*CF		1250218 SN-UNKNOWN	MTH 31-May-1996		O/C			
216002	TEMPERATURE CONTROLLER	*CF		27231272-25 1AM5	MTH 31-May-1996		O/C			
216003	TEMP CNTL SYS SENSOR 9912085-3	*CF		27221274 11AL228	MTH 31-May-1996		O/C			
221002	AUTOPILOT COMPUTER CONTROL PC-400	*CF		7003897-907 96010918	MTH 31-May-1996		O/C			
221003 AILERON	SERVO SM-200	*CF		4006719-906 95118139	MTH 31-May-1996		O/C			
221004 RUDDER	SERVO SM-200	*CF		4006719-906 95118262	MTH 31-May-1996		O/C			
221005 ELEVATOR	SERVO SM-200	*CF		4006719-914 95098000	MTH 31-May-1996		O/C			
231005	MINATURE CONTROL KFS-594	ICT		071-01274-0002 3458	MTH 23-May-1996		O/C			
232001 NO. 1	COMM RADIO SYSTEM CONTROL			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
232001 NO. 2	COMM RADIO SYSTEM CONTROL			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
232008 BOTTOM	ANTENNA - COMM 1	MKE		17-50-01 1271	MTH 09-Dec-1998 HRS 577		O/C	0		
232008 TOP	ANTENNA - COMM 2	*CF		18-50-01 204	MTH 31-May-1996		O/C			
235001 LEFT	AUDIO AMPLIFIER S3100-62	KTTN		5635-1-1 399	MTH 19-Mar-2021 HRS 2641.8 LDG 2252		O/C			
235001 RIGHT	AUDIO AMPLIFIER S3100-62	KTTN		5635-1-1 400	MTH 19-Mar-2021 HRS 2641.8 LDG 2252		O/C	0 0 0		
235001	XM SATELIITE RADIO ANTENNA			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
235002	XM SAT WEATHER DATA RECEIVER			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
242001 NO. 1	SECOND AC POWER INVERTER S3100-39	*CF		PC251-123E 8172	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
242001 NO. 2	SECOND AC POWER INVERTER S3100-39	KTTN		PC251-123E 9082	MTH 20-Apr-2017 HRS 2593.7 LDG 2204 ACH 1380.4		O/C	0 0		
243001	BATTERY TEMP INDICATOR KOWD			S3597-9 40007578	MTH 10-Jun-2020 HRS 2639.2 LDG 2243		O/C	0 0 0		
243002 LEFT	GENERATOR CONTROL UNIT SHV			51525-001F 95077	MTH 24-Sep-2002 HRS 1478		O/C	68		
243002 RIGHT	GENERATOR CONTROL UNIT KTTN			51525-001F P3702	MTH 17-Jun-2013 HRS 2512.4 LDG 2132		O/C			
243003	MAIN BATTERY	N81		RG380E/44L 70020633	MTH 30-Jan-2025 HRS 2974.9 LDG 2490		O/C	0 0 0		
243004	BATTERY TEMPERATURE MONITOR- KOB1			1529-1 2631	MTH 28-Feb-2020 HRS 2634.8 LDG 2237		O/C			
243005	OVERVOLTAGE MONITOR- *CF			1645-1 1285	MTH 31-May-1996		O/C			
243006 LEFT	AMMETER	*CF		C662501-0105 1088	MTH 31-May-1996		O/C			
243006 RIGHT	AMMETER	*CF		C662501-0105 1090	MTH 31-May-1996		O/C			
243008	BATTERY DISCONNECT RELAY *CF			A931F CL59515	MTH 31-May-1996		O/C			
243011	VOLTMETER	*CF		C662502-0101 1106	MTH 31-May-1996		O/C			
245001 LEFT	START PCB ASSY	*CF		6318324-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
245001 RIGHT	START PCB ASSY	*CF		6318324-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
245002 LEFT	ASSEMBLY-FUEL CONTROL PCB *CF			6318321-3 SN-UNKNOWN	MTH 31-May-1996		O/C			
245002 RIGHT	ASSEMBLY-FUEL CONTROL PCB *CF			6318321-3 SN-UNKNOWN	MTH 31-May-1996		O/C			
245003 LEFT	ASSEMBLY-IGNITOR PCB *CF			6318322-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
245003 RIGHT	ASSEMBLY-IGNITOR PCB *CF			6318322-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
245004 LEFT	ANTI ICE PCB ASSY	*CF		6318323-3 SN-UNKNOWN	MTH 31-May-1996		O/C			
245004 RIGHT	ANTI ICE PCB ASSY	*CF		6318323-3 SN-UNKNOWN	MTH 31-May-1996		O/C			
245005	ATTENUATOR PCB ASSY *CF			6318355-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
245006	ENVIRONMENTAL PCB ASSY *CF			6318356-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
245007	MISCELLANEOUS PCB ASSY *CF			6318357-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
245008	TRIM CONTROL PCB ASSY DAL			6518351-10 0628	MTH 06-Apr-2004 HRS 1687		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
245009	DIMMING PCB ASSY	*CF		6518353-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
245010	GEAR LOGIC PCB ASSY	*CF		6518354-3 SN-UNKNOWN	MTH 31-May-1996		O/C			
245011	FUEL FLOW XMITTER PCB ASSY 9912417-2	*CF		85-230-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
256001	ELT TRANSMITTER ME406-406MHZ	TTN		453-6603 197-07938	MTH 19-Jul-2011 HRS 2409.8 LDG 2057		O/C	0 0 0		
256004	ELT ANTENNA	TTN		110-338 339901	MTH 19-Jul-2011 HRS 2409.8 LDG 2057		O/C	0 0 0		
256005	ELT BEACON BATTERY PACK KSWF			452-6499 1004472-040	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		60	0 0 0	28-Feb-2030	58 m 0 d
256006 CO-PILOT	LIFE VEST	KTTN		P01074-101 20110680278	MTH 19-Mar-2021 HRS 2641.8 LDG 2252		60	0	30-Nov-2025	7 m 0 d
256006 NO. 1	LIFE VEST	KTTN		P01074-101 20110680586	MTH 19-Mar-2021 HRS 2641.8 LDG 2252		60	0	31-Mar-2026	11 m 0 d
256006 NO. 2	LIFE VEST	KSWF		P01074-101 23060722988	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		60	0 0 0	20-Jun-2028	37 m 20 d
256006 NO. 3	LIFE VEST	KSWF		P01074-101 23060722989	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		60	0 0 0	20-Jun-2028	37 m 20 d
256006 NO. 4	LIFE VEST	KSWF		P01074-101 23060722993	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		60	2 0 0	31-Aug-2028	40 m 0 d
256006 NO. 5	LIFE VEST	KSWF		P01074-101 23060722998	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		60	2 0 0	31-Aug-2028	40 m 0 d
256006 PILOT	LIFE VEST XF-35	KTTN		PO1074-101 20110680672	MTH 19-Mar-2021 HRS 2641.8 LDG 2252		60	0	30-Nov-2025	7 m 0 d
256011	LIFE RAFT	KTTN		R0101A103 TR04123	MTH 30-Oct-2015 HRS 2561.6 LDG 2176		O/C	0 0 0		
261002 LEFT	FIRE DETECT SENSOR 9912416-1	*CF		30012121004/4559 201771	MTH 31-May-1996		O/C			
261002 RIGHT	FIRE DETECT SENSOR 9912416-1	*CF		30012121004/4559 201810	MTH 31-May-1996		O/C			
262001 LEFT	FIRE EXTINGUISHER BOTTLE 9912048-4	MIV		30400031-1 36687B1	MTH 15-Feb-2006 HRS 1875		O/C	117		
262001 RIGHT	FIRE EXTINGUISHER BOTTLE 9912048-4	MIV		30400031-1 36686B1	MTH 15-Feb-2006 HRS 1875		O/C	117		
262002 LEFT NO. 1	FIRE EXTINGUISHER CARTRIDGE KSWF			AE13083-5 A158	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		120	0 0 0	30-Jul-2032	87 m -1 d
Manufacture Date: 01-Jul-2022										
262002 LEFT NO. 2	FIRE EXTINGUISHER CARTRIDGE KSWF			AE13083-5 A154	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		120	0 0 0	30-Jul-2032	87 m -1 d
Manufacture Date: 01-Jul-2022										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
 Aircraft Model: **525 - CITATION JET**
 Aircraft Serial: **525-0139**
 Unit: **0139** Reg No: **N36RG**
 Airworthiness: **31-May-1996**
 Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
262002 RIGHT NO. 1	FIRE EXTINGUISHER CARTRIDGE KSWF			AE13083-5 A156	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		120	0 0 0	30-Jul-2032	87 m -1 d
Manufacture Date: 01-Jul-2022										
262002 RIGHT NO. 2	FIRE EXTINGUISHER CARTRIDGE KSWF			AE13083-5 A155	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		120	0 0 0	30-Jul-2032	87 m -1 d
Manufacture Date: 01-Jul-2022										
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER KTTN			C352TS E-92812238	MTH 21-Jan-2019 HRS 2620.8 LDG 2225		O/C	0 0 0		
273001 LEFT	SHAKER CONTROL *CF			201 1413	MTH 31-May-1996		O/C			
273002	ELEVATOR ELECTRIC TRIM SERVO *CF			44430-3548 T275	MTH 31-May-1996		O/C			
273003	SERVO MOUNT ASSY *CF			44575-3415 SN-UNKNOWN	MTH 31-May-1996		O/C			
273004 LEFT	ELEVATOR TRIM ACTUATOR *CF			6361215-1 SN-UNKNOWN	MTH 31-May-1996		O/C			
273004 RIGHT	ELEVATOR TRIM ACTUATOR *CF			6361215-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
273005	RUDDER TRIM TAB ACTUATOR MKE			6361215-21 SN-UNKNOWN	MTH 24-Jun-2000 HRS 864		O/C	0		
275001	SHUTOFF VALVE *CF			4083 151	MTH 31-May-1996		O/C			
275002 LEFT	FLAP HYD ACTUATOR 9912365-4 *CF			1542000-3 292	MTH 31-May-1996		O/C			
275002 RIGHT	FLAP HYD ACTUATOR 9912365-4 *CF			1542000-3 293	MTH 31-May-1996		O/C			
276001 LEFT	SPEEDBRAKE ACTUATOR 9912375-3 *CF			1542100-3 333	MTH 31-May-1996		O/C			
276001 RIGHT	SPEEDBRAKE ACTUATOR 9912375-3 *CF			1542100-3 310	MTH 31-May-1996		O/C			
281001 LEFT	FUEL SURGE VALVE 9912016-1 *CF			35C10C 478	MTH 31-May-1996		O/C			
281001 RIGHT	FUEL SURGE VALVE 9912016-1 *CF			35C10C 483	MTH 31-May-1996		O/C			
282001 LEFT	ELECTRIC FUEL PUMP 9912017-4 *CF			1C7-13 10AL53	MTH 31-May-1996		O/C			
282001 RIGHT	ELECTRIC FUEL PUMP 9912017-4 *CF			1C7-13 11AL57	MTH 31-May-1996		O/C			
282002 LEFT	FUEL TRANSFER PUMP 9912190-3 *CF			RG45880 B385	MTH 31-May-1996		O/C			
282002 RIGHT	FUEL TRANSFER PUMP 9912190-3 *CF			RG45880 B386	MTH 31-May-1996		O/C			
282004 LEFT	FUEL MOTOR ACTUATED VALVE 9912014-3 *CF			EM9014-3 300	MTH 31-May-1996		O/C			
282004 RIGHT	FUEL MOTOR ACTUATED VALVE 9912014-3 *CF			EM9014-3 303	MTH 31-May-1996		O/C			
282005 LEFT	FUEL TRANSFER EJECTOR 9912190-2 *CF			RG45310 B6401	MTH 31-May-1996		O/C			
282005 RIGHT	FUEL TRANSFER EJECTOR 9912190-2 *CF			RG45310 B6403	MTH 31-May-1996		O/C			
282006	TRANSFER VALVE 9914103-6 *CF			ZSV57 50629181	MTH 31-May-1996		O/C			
284001 LEFT	#5 FUEL TRANSMITTER 9912412-5 *CF			10307T01Y00 432	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284001 RIGHT	#5 FUEL TRANSMITTER 9912412-5	*CF		10307T01Y00 436	MTH 31-May-1996		O/C			
284002 LEFT	FUEL QUANTITY TRANSMITTER 9912412-6	*CF		10309T01Y00 356	MTH 31-May-1996		O/C			
284002 RIGHT	FUEL QUANTITY TRANSMITTER 9912412-6	*CF		10309T01Y00 330	MTH 31-May-1996		O/C			
284003	FUEL QUANTITY SIGNAL CONDITIONER 9912412-7	*CF		10310B01Y02 260	MTH 31-May-1996		O/C			
284004 LEFT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 439	MTH 31-May-1996		O/C			
284004 RIGHT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 442	MTH 31-May-1996		O/C			
284005 LEFT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 391	MTH 31-May-1996		O/C			
284005 RIGHT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 390	MTH 31-May-1996		O/C			
284006 LEFT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 457	MTH 31-May-1996		O/C			
284006 RIGHT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 466	MTH 31-May-1996		O/C			
284007 LEFT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 419	MTH 31-May-1996		O/C			
284007 RIGHT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 429	MTH 31-May-1996		O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH 9912412-1	*CF		GIF5400-40 SN-UNKNOWN	MTH 31-May-1996		O/C			
284008 RIGHT	FUEL LOW LEVEL SWITCH 9912412-1	*CF		GIF5400-40 SN-UNKNOWN	MTH 31-May-1996		O/C			
284009	FUEL QUANTITY/FUEL FLOW INDICATOR 9912399-6	*CF		10274N02M00 317	MTH 31-May-1996		O/C			
291002 LEFT	HYDRAULIC PUMP ASSY 9912392-3	MKE		MC14549-5 903	MTH 19-Nov-1998 HRS 563		O/C	0		
291002 RIGHT	HYDRAULIC PUMP ASSY 9912392-1	*CF		MC14549-4 425B	MTH 31-May-1996		O/C			
291003	HYDRAULIC CHECK VALVE 9912392-1	*CF		CV02-193 SN-UNKNOWN	MTH 31-May-1996		O/C			
291005	HYDRAULIC RESERVOIR ASSEMBLY 9912392-1	*CF		6317001-46 SN-UNKNOWN	MTH 31-May-1996		O/C			
291007	PRESSURE SWITCH 9912373-2	*CF		GPP1250-36 942079	MTH 31-May-1996		O/C			
291008	HYDRAULIC MANIFOLD ASSEMBLY 9912423-24	*CF		8184-8 171	MTH 31-May-1996		O/C			
291009	HYDRAULIC RELIEF VALVE 9912423-24	*CF		1785-1 146	MTH 31-May-1996		O/C			
291010 LEFT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-3	*CF		AV24B1388-1 P69595	MTH 31-May-1996		O/C			
291010 RIGHT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-3	*CF		AV24B1388-1 P73837	MTH 31-May-1996		O/C			
291011 LEFT	FLOW SWITCH/CHECK FLOW VALVE 9912393-2	*CF		MC19232-2 355	MTH 31-May-1996		O/C			
291011 RIGHT	FLOW SWITCH/CHECK HYD VALVE 9912393-2	*CF		MC19232-2 350	MTH 31-May-1996		O/C			
291011	SYSTEM RELIEF VALVE 9912423-46	KTTN		2576-2 626A	MTH 03-May-2013 HRS 2508.6 LDG 2127		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
291012	SPEED BRAKE DUMP VALVE SOLENOID 9912423-7	*CF		4082-2 1628	MTH 31-May-1996		O/C			
291013	LOADING VALVE SOLENOID 9912423-39	DAL		4134-4 339	MTH 10-May-2002 HRS 1367		O/C	0		
291014	GEAR VALVE SOLENOID 9912423-35	KTTN		4051-3 300	MTH 10-Oct-2014 HRS 2545.9 LDG 2166		O/C	2 0 0		
291015	GEAR PORTION CHECK VALVE 9912423-13	*CF		9504 161	MTH 31-May-1996		O/C			
291016	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 134	MTH 31-May-1996		O/C			
291016	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 533	MTH 31-May-1996		O/C			
291017	SPEED BRAKE PORTION VALVE 9912423-15	*CF		2577 166	MTH 31-May-1996		O/C			
291018	PNEUMATIC DUMP VALVE 9912423-17	*CF		9503-1 172	MTH 31-May-1996		O/C			
291019	ATTENUATOR VALVE SOLENOID 9912423-19	*CF		4107-1 155	MTH 31-May-1996		O/C			
291019	ATTENUATOR VALVE SOLENOID 9912423-20	*CF		4107-2 165	MTH 31-May-1996		O/C			
291020	SPEEDBRAKE VALVE SOLENOID 9912423-6	*CF		4052-1 50	MTH 31-May-1996		O/C			
291021	FLAP VALVE SOLENOID 9912423-8	*CF		4052-2 168	MTH 31-May-1996		O/C			
291022	ELECTRO/HYDRAULIC SERVO VALVE *CF			37-509 SN-UNKNOWN	MTH 31-May-1996		O/C			
301001	SHUTOFF ISOLATION VALVE 9912403-1	*CF		2602-15 6143	MTH 31-May-1996		O/C			
301002	PNEUMATIC DEICE SWITCH LEFT	*CF		1106P55-1 286	MTH 31-May-1996		O/C			
301002	PNEUMATIC DEICE SWITCH RIGHT	*CF		1106P55-1 316	MTH 31-May-1996		O/C			
301003	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 12AL108	MTH 31-May-1996		O/C			
301003	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 3AM22	MTH 31-May-1996		O/C			
301004	TEMPERATURE DEICE SWITCH LEFT	*CF		1173T42-4 276	MTH 31-May-1996		O/C			
301004	TEMPERATURE DEICE SWITCH RIGHT	*CF		1173T42-4 278	MTH 31-May-1996		O/C			
301010	HORIZONTAL STABILIZER BOOT LEFT	DAL		25S4D5244-01 MQ36990	MTH 09-Feb-2001 HRS 923		O/C	0		
301010	HORIZONTAL STABILIZER BOOT RIGHT	SWF		29S4D5244-12 MYGLZP0	MTH 14-May-2008 HRS 2155		O/C	0		
301011	DEICE TAIL TIMER 9912440-1	*CF		937-1-1 255	MTH 31-May-1996		O/C			
302001	SOLENOID VALVE 9912402-10	*CF		1H127-5 1AM05	MTH 31-May-1996		O/C			
302001	SOLENOID VALVE 9912402-10	*CF		1H127-5 1AM1	MTH 31-May-1996		O/C			
302003	INLET MONITOR SWITCH LEFT	*CF		21548-2-19-6 SN-UNKNOWN	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
302003 RIGHT	INLET MONITOR SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 31-May-1996		O/C			
303002 LEFT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 31-May-1996		O/C			
303002 RIGHT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 31-May-1996		O/C			
304001	B/A TEMP MONITOR- *CF			1169-1 2334	MTH 31-May-1996		O/C			
304002	HEAT EXCHANGER 9912041-3 *CF			10653A 846	MTH 31-May-1996		O/C			
304003	WINDSHIELD S/O VALVE 9912402-9 *CF			1H127-4 12AL116	MTH 31-May-1996		O/C			
304004 LEFT	PITOT STATIC CURRENT SENSOR *CF			76250-1 2767	MTH 31-May-1996		O/C			
304004 RIGHT	PITOT STATIC CURRENT SENSOR *CF			76250-1 2838	MTH 31-May-1996		O/C			
304006	TEMP BLEED AIR CONTROLLER 9912085-5 GSO			27231272-20 12AJ125	MTH 22-Feb-2000 HRS 801		O/C	152		
304007	TEMP CONTROL BLEED AIR VALVE 9912085-1 *CF			27241287 9AL93	MTH 31-May-1996		O/C			
304009 LEFT	SOLENOID DEICE VALVE *CF			3D2353-06 N13442	MTH 31-May-1996		O/C			
304009 RIGHT	SOLENOID DEICE VALVE *CF			3D2353-06 N13439	MTH 31-May-1996		O/C			
304010	ALCOHOL PUMP ASSEMBLY *CF			476411 SN-UNKNOWN	MTH 31-May-1996		O/C			
304011	TEMPERATURE SENSOR 9912085-3 *CF			27221274 1AM30	MTH 31-May-1996		O/C			
304012 LEFT	WINDSHIELD BLEED AIR VALVE *CF			1403-20 524	MTH 31-May-1996		O/C			
304012 RIGHT	WINDSHIELD BLEED AIR VALVE *CF			1403-20 523	MTH 31-May-1996		O/C			
304013	PRESSURE WINDSHIELD SWITCH *CF			1115P25 2616A	MTH 31-May-1996		O/C			
304014 AFT	TEMPERATURE EVAPORATOR SENSOR 9912085-3 *CF			27221274 1AM30	MTH 31-May-1996		O/C			
312001 LEFT	DIGITAL CLOCK *CF			M877A5V 6910	MTH 31-May-1996		O/C			
313001	FLIGHT HOUR METER 85071 MIV			C664503-0104 SN-UNKNOWN	MTH 16-Aug-2006 HRS 1948		O/C	0		
315001	CABIN ALTITUDE PRESSURE SWITCH 9910095-6 *CF			GB300NA161 9534863	MTH 31-May-1996		O/C			
315002	MASTER WARN ANNUNCIATOR ASSY DAL			9912438-9 438000285	MTH 09-Apr-2004 HRS 1687		O/C	0		
321001 LEFT MAIN LANDING GEAR	AND ATTACHING HARDWARE ASSEMBLY *CF			6341003-5 10	MTH 31-May-1996		O/C			
321001 NOSE LANDING GEAR	STRUT AND ATTACHING HARDWARE ASSEMBLY *CF			6342000-21 SN-UNKNOWN	MTH 31-May-1996 LDG 0		22500	0	22500	19995
321001 RIGHT MAIN LANDING GEAR	AND ATTACHING HARDWARE ASSEMBLY *CF			6341003-6 10	MTH 31-May-1996		O/C			
321002 : R										
321003 LEFT MAIN GEAR	TRUNNION ASSEMBLY *CF			6341007-3 SN-UNKNOWN	MTH 31-May-1996 LDG 0		12480	0	12480	9975

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
321004 RIGHT MAIN GEAR	TRUNNION ASSEMBLY *CF			6341007-4 SN-UNKNOWN	MTH 31-May-1996 LDG 0		12480	0	12480	9975
321005 LEFT	TRAILING LINK AND AXLE ASSEMBLY *CF			6341002-7 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
321006 RIGHT	TRAILING LINK AND AXLE ASSEMBLY *CF			6341002-8 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
321007	SHIMMY DAMPER ASSEMBLY MKE			6343001-5 695	MTH 11-Sep-1997 HRS 319 LDG 315		O/C	0		
321008 LEFT	OLEO ASSEMBLY *CF			6341130-2 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
321008 RIGHT	OLEO ASSEMBLY *CF			6341130-2 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
321009 321004	FORK AND PISTON ASSEMBLY *CF			6342000-3 SN-UNKNOWN	MTH 31-May-1996 LDG 0		12500	0	12500	9995
323000 NOSE LANDING GEAR 323001	ACTUATOR ASSEMBLY 9912370-3 *CF			1541900-3 153	MTH 31-May-1996 LDG 0		22500	0	22500	19995
323001 LEFT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912397-4 *CF			1541800-5 317	MTH 31-May-1996 LDG 0		12000	0	12000	9495
323002 RIGHT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912397-4 MKE			1541800-5 304	MTH 07-Aug-1997 HRS 294 LDG 288		12000	267	12021	9516
323003	NG UPLOCK ACTUATOR *CF			6327504-5 150	MTH 31-May-1996		O/C			
323005 LEFT	MLG UPLOCK ACTUATOR *CF			6327504-4 303	MTH 31-May-1996		O/C			
323005 RIGHT	MLG UPLOCK ACTUATOR *CF			6327504-4 307	MTH 31-May-1996		O/C			
323006	HYD SHUTTLE VALVE *CF			95784 449	MTH 31-May-1996		O/C			
324001 LEFT	MAIN LANDING GEAR WHEEL 9912398-2 RDG			3-1527-1 0431	MTH 21-Dec-2023 HRS 2875 LDG 2427		O/C	0		
324001 RIGHT	MAIN LANDING GEAR WHEEL 9912398-2 KTTN			3-1527-1 0432	MTH 21-Jan-2019 HRS 2620.8 LDG 2225		O/C			
324002 NOSE	LANDING GEAR WHEEL ASSY 9914069-2			3-1418 2168	MTH 14-Sep-2007 HRS 2082 LDG 1813		O/C	0		
324005 LEFT	MLG TIRE RDG			277K08-1 13532261	MTH 21-Dec-2023 HRS 2875 LDG 2427		O/C	0 0		
324005 RIGHT	MLG TIRE RDG			277K08-1 23470283	MTH 21-Dec-2023 HRS 2875 LDG 2427		O/C	0 0		
324007 NOSE	LANDING GEAR TIRE TTN			030-611-0 1026500135	MTH 19-Jul-2011 HRS 2409.8 LDG 2057		O/C	0 0 0		
324008 LEFT 324007 : L	SHUTTLE VALVE			195-191-1 SN-UNKNOWN	MTH 05-Sep-1996 HRS 100		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324008 RIGHT	SHUTTLE VALVE 9912374-4			195-191-1 SN-UNKNOWN	MTH 05-Sep-1996 HRS 100		O/C	0		
324016 LEFT MAIN LANDING GEAR	BRAKE ASSY 9912398-8	RDG		2-1559-3 2104	MTH 15-Jan-2024 HRS 2881 LDG 2431		O/C	2 0 0		
324016 RIGHT MAIN LANDING GEAR	BRAKE ASSY 9912398-8	RDG		2-1559-3 1312	MTH 15-Jan-2024 HRS 2881 LDG 2431		O/C	3 0 0		
324101	POWER BRAKE AND ANTISKID VALVE 9912374-4	*CF		38-747 243	MTH 31-May-1996		O/C			
324102 LEFT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 3509	MTH 31-May-1996		O/C			
324102 RIGHT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 3327	MTH 31-May-1996		O/C			
324103	BRAKE CONTROL BOX 9912305-6	*CF		42-707-1 1005	MTH 31-May-1996		O/C			
324104 LEFT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 374	MTH 31-May-1996		O/C			
324104 RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 353	MTH 31-May-1996		O/C			
324104A LEFT	BRAKE CYLINDER ASSEMBLY 9912366-2	*CF		95805-1 360	MTH 31-May-1996		O/C			
324104A RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-2	*CF		95805-1 395	MTH 31-May-1996		O/C			
324105	PARKING BRAKE VALVE 9912388-1	*CF		95853 270A	MTH 31-May-1996		O/C			
324106	HYDRAULIC PUMP MOTOR 9912388-1	*CF		MP50B1 506	MTH 31-May-1996		O/C			
324107	ANTISKID ACCUMULATOR 9912373-1	*CF		57C57663 145	MTH 31-May-1996		O/C			
324108	HYDRAULIC PRESSURE SWITCH 9912373-1	*CF		GPP1250-29 9545155	MTH 31-May-1996		O/C			
324109	BRAKE PRESSURE PUMP ASSY 9912364-1	*CF		636652 SN-UNKNOWN	MTH 31-May-1996		O/C			
324110	EMERGENCY BRAKE VALVE ASSY 9912387-1	MKE		878208-01 321	MTH 21-Jan-1999 HRS 600		O/C	0		
324111 LEFT	MLG UP & LOCK SWITCH 9912387-1	MKE		65-430087 SN-UNKNOWN	MTH 12-Nov-1998 HRS 560 LDG 538		O/C	0		
324111 RIGHT	MLG UP & LOCK SWITCH 9912387-1	*CF		65-430087 SN-UNKNOWN	MTH 31-May-1996		O/C			
324111	NLG UP & LOCK SWITCH 9912387-1	*CF		65-430087 SN-UNKNOWN	MTH 31-May-1996		O/C			
324112	PRESSURE ANTISKID SWITCH 9912374-6	*CF		38-747502 178	MTH 31-May-1996		O/C			
325001	NOSE LANDING GEAR ASSEMBLY 9912374-6	*CF		6342000-22 8	MTH 31-May-1996		O/C			
325002	NOSE STEERING BUNGEE ASSEMBLY 9912374-6	*CF		5565624-19 SN-UNKNOWN	MTH 31-May-1996		O/C			
326001 LEFT	M/G DOWN&LOCK SWITCH 9912374-6	*CF		1EN118-6 SN-UNKNOWN	MTH 31-May-1996		O/C			
326001 RIGHT	M/G DOWN&LOCK SWITCH 9912374-6	*CF		1EN118-6 SN-UNKNOWN	MTH 31-May-1996		O/C			
326002	N/G DOWN&LOCK SWITCH 9912374-6	*CF		1EN118-6 SN-UNKNOWN	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
 Aircraft Model: **525 - CITATION JET**
 Aircraft Serial: **525-0139**
 Unit: **0139** Reg No: **N36RG**
 Airworthiness: **31-May-1996**
 Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
326006	EMERGENCY GEAR BOTTLE 9912368-2	KTTN		40005320-2 7471	MTH 19-Jun-2017 HRS 2595.3 LDG 2206 ACH 1380.4		288	1 0 0	30-Apr-2035	120 m o d
Manufacture Date: 30-Apr-2011										
326007	EMERGENCY GEAR GAUGE *CF			18225901 59902A	MTH 31-May-1996		O/C			
330001 CENTER	PANEL LIGHTS DIMMER *CF			273-1 3891	MTH 31-May-1996		O/C			
330001 LEFT	PANEL LIGHTS DIMMER *CF			273-1 3792	MTH 31-May-1996		O/C			
330001 RIGHT	PANEL LIGHTS DIMMER *CF			273-1 3800	MTH 31-May-1996		O/C			
330002	ELECTRICAL PANEL INVERTER *CF			EM2044-1 2113A	MTH 31-May-1996		O/C			
332001 L1	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
332002 L2	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
332003 L3	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
332004 L4	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
332005 R1	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
332006 R2	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
332007 R3	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
332008 R4	INDIRECT LIGHTING INVERTER S2800-217 *CF			6900113-2 SN-UNKNOWN	MTH 31-May-1996		O/C			
334001	GROUND RECOGNITION LIGHT *CF			90033-13 1559968	MTH 31-May-1996		O/C			
334003 LEFT	ANTI COLLISION POWER SUPPLY *CF			04-1502-1408 8111	MTH 31-May-1996		O/C			
334003 RIGHT	ANTI COLLISION POWER SUPPLY *CF			04-1502-1408 8113	MTH 31-May-1996		O/C			
334004 LEFT	HOUSING ASSY-LANDING LIGHT LAMP *CF			50033011-1 264	MTH 31-May-1996		O/C			
334004 RIGHT	HOUSING ASSY-LANDING LIGHT LAMP *CF			50033011-1 285	MTH 31-May-1996		O/C			
334005 LEFT	ANTI COLLISION LIGHT ASSY *CF			03-1302-0003 9884	MTH 31-May-1996		O/C			
334005 RIGHT	ANTI COLLISION LIGHT ASSY *CF			03-1302-0004 9331	MTH 31-May-1996		O/C			
340551	FLIGHT STREAM 510 --			011-03595-00 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
341001 LEFT	AIRSPEED INDICATOR			9912446-4 SN-UNKNOWN	MTH 22-Nov-2022		O/C			
341001 RIGHT	AIRSPEED INDICATOR			9912446-4 SN-UNKNOWN	MTH 22-Nov-2022		O/C			
341001	AOA COMPUTER *CF			C12406-2 247	MTH 31-May-1996		O/C			
341008	AOA INDICATOR *CF			C12405-1 244	MTH 31-May-1996		O/C			
341009	AOA SENSOR *CF			C12417-2 241	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
 Aircraft Model: **525 - CITATION JET**
 Aircraft Serial: **525-0139**
 Unit: **0139** Reg No: **N36RG**
 Airworthiness: **31-May-1996**
 Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
341010 AFT	RADIO ALTIMETER ANTENNA *CF			S67-2002 9774	MTH 31-May-1996		O/C			
341010 FORWARD	RADIO ALTIMETER ANTENNA *CF			S67-2002 9773	MTH 31-May-1996		O/C			
341019 STANDBY	ENCODING ALTIMETER UNK			44929-935 1099	MTH 22-Nov-2022		O/C			
341020 LEFT	ADC/ALT UNIT			AM250 03091144B	MTH 02-Dec-2022 HRS 2720.6		O/C			
341020 RIGHT	ADC/ALT UNIT			AM250 03091177B	MTH 02-Dec-2022 HRS 2720.6		O/C			
341020	REMOTE COURSE CONTROLLER RI-553 *CF			7016954-901 95100379	MTH 31-May-1996		O/C			
341029	MARKER BEACON INDICATOR KR-21 *CF			066-01021-0002 10946	MTH 31-May-1996		O/C			
341030	OAT INDICATOR *CF			C307FCL 2524	MTH 31-May-1996		O/C			
342001	MAGNETIC COMPASS C2400-L4V2W-5B CHA			C660501-0301 SN-UNKNOWN	MTH 07-Apr-2022 HRS 2642.8 LDG 2253		O/C	0 0 0		
342002	AIR DATA SENSOR AZ-429 *CF			7017970-901 95120266	MTH 31-May-1996		O/C			
342004 RIGHT	ATTITUDE DIRECTOR INDICATOR AD500A *CF			7000836-927 96012623	MTH 31-May-1996		O/C			
342006	SLAVING ACCESSORY KA-51B *CF			071-01242-0007 22810	MTH 31-May-1996		O/C			
342021 LEFT	VERTICAL SPEED INDICATOR *CF			C661006-0101 347370	MTH 31-May-1996		O/C			
342021 RIGHT	VERTICAL SPEED INDICATOR *CF			C661006-0101 347364	MTH 31-May-1996		O/C			
342042 LEFT	FLIGHT DIRECTOR MODE SELECTOR MS-560 MKE			7018341-905 94110324	MTH 11-Oct-1996 HRS 148		O/C	0		
342043 LEFT	VERTICAL GYRO VG-14A *CF			7000622-901 95117867	MTH 31-May-1996		O/C			
342043 RIGHT	VERTICAL GYRO VG-14A *CF			7000622-901 95057747	MTH 31-May-1996		O/C			
342044 LEFT	FLIGHT GUIDANCE COMPUTER IC-500 *CF			7017000-52105 95050497	MTH 31-May-1996		O/C			
342045	ACCELEROMETER AG-222 *CF			7000992 7267	MTH 31-May-1996		O/C			
342046	HORIZONTAL SITUATION INDICATOR KI525A *CF			066-03046-0011 43461	MTH 31-May-1996		O/C			
342048	YAW RATE GYRO RG-204 *CF			7007453-903 95113995	MTH 31-May-1996		O/C			
342049 LEFT	DIRECTIONAL GYRO C-14D *CF			4020577-3 96015898	MTH 31-May-1996		O/C			
342049 RIGHT	DIRECTIONAL GYRO KG102A MIV			060-00015-0001 35635	MTH 22-Jun-2006 HRS 1922		O/C	0		
342050 RIGHT	FLUX DETECTOR KMT-112 *CF			071-01052-0000 48929	MTH 31-May-1996		O/C			
342050	FLUX DETECTOR FX-220 *CF			2594484 95111489	MTH 31-May-1996		O/C			
342052	DUAL REMOTE COMPENSATOR CS-412 *CF			2593379-001 95121692	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
 Aircraft Model: **525 - CITATION JET**
 Aircraft Serial: **525-0139**
 Unit: **0139** Reg No: **N36RG**
 Airworthiness: **31-May-1996**
 Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342063	STANDBY JET GYRO AI-804	*CF		501-1197-09 5635	MTH 31-May-1996		O/C			
342064	STANDBY GYRO POWER SUPPLY KTTN			501-1682-01 1006	MTH 07-Oct-2014 HRS 2545.9 LDG 2166		O/C			
342066 LEFT BOTTOM	EHSI INDICATOR ED-600	MKE		7003430-901 94083459	MTH 27-Jan-1998 HRS 387		O/C	1681		
342066 LEFT TOP	EADI INDICATOR ED-600	SHV		7003430-901 87010816	MTH 18-Dec-2002 HRS 1562		O/C	3881		
342067	MFD DISPLAY			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
342068	CONTROL DISPLAY DC-550	*CF		7016986-701 95120633	MTH 31-May-1996		O/C			
344001	ANTENNA GLIDESLOPE COUPLER *CF			82-70-01 663	MTH 31-May-1996		O/C			
344002	WEATHER RADAR INDICATOR IN-182A	*CF		066-03084-0033 22707	MTH 31-May-1996		O/C			
344004	ARRAY RADAR ANTENNA AA-2012V	*CF		071-01549-0200 K729	MTH 31-May-1996		O/C			
344005	RADAR TRANSCEIVER ART-2000	ICT		071-01519-0101 X3710	MTH 22-Apr-2003 HRS 1629		O/C	153		
344007	FMS CONFIGURATION MODULE *CF			071-00097-0100 2272	MTH 31-May-1996		O/C			
344021	RADIO MAGNETIC INDICATOR KNI-582	ICT		066-03060-0003 X8836	MTH 24-May-1999 HRS 644		O/C	0		
344022	RADIO ALTIMETER RECEIVER/TRANSMITTER KRA-405	*CF		066-01048-0002 6611	MTH 31-May-1996		O/C			
344023 NO. 1	DUAL NAVIGATION CONVERTER KN-40	*CF		066-01130-0701 10708	MTH 31-May-1996		O/C			
344024	RADIO ALTIMETER INDICATOR KNI-415	SWF		066-3031-02 6025	MTH 14-May-2008 HRS 2155		O/C	0		
345000 #2	DIPLEXER --			CI 507 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
345000	DIPLEXER			CI 507 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
345001 AFT	DME #2 ANTENNA	*CF		56-80-01 7359	MTH 31-May-1996		O/C			
345001 FORWARD	DME #1 ANTENNA	*CF		56-80-01 7341	MTH 31-May-1996		O/C			
345002 NO. 1	DME RECEIVER/TRANSMITTER KN-63	*CF		066-01070-0001 12617	MTH 31-May-1996		O/C			
345002 NO. 2	DME RECEIVER/TRANSMITTER KN-63	*CF		066-01070-0001 12650	MTH 31-May-1996		O/C			
345003 LEFT	DME INDICATOR KDI-574	*CF		066-01069-0014 72083	MTH 31-May-1996		O/C			
345003 RIGHT	DME INDICATOR KDI-574	MCO		066-01069-0014 72572	MTH 05-May-2005 HRS 1769		O/C	0		
345004 NO. 1	TRANSPONDER ANTENNA KA-60	*CF		071-01174-0000 SN-UNKNOWN	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345004 NO. 2	TRANSPONDER ANTENNA KA-60	*CF		071-01174-0000 SN-UNKNOWN	MTH 31-May-1996		O/C			
345005	MARKER BEACON ANTENNA *CF			31-10-01 2453	MTH 31-May-1996		O/C			
345006	GLIDESLOPE ANTENNA *CF			44-70-01 A4468	MTH 31-May-1996		O/C			
345011 NO. 1	ADF RECEIVER			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
345012 NO. 1	ADF ANTENNA KA-44B	*CF		071-01234-0000 60313	MTH 31-May-1996		O/C			
345020 BOTTOM	VHF NAV 2 RECEIVER			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
345020 TOP	VHF NAV 1 RECEIVER			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
345021 LEFT	NAVIGATION INDICATOR KI-204	*CF		066-03034-0022 51039	MTH 31-May-1996		O/C			
345022 LEFT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 1807	MTH 31-May-1996		O/C			
345022 RIGHT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 1804	MTH 31-May-1996		O/C			
345034 NO. 1	TRANSPONDER			011-03303-01 3EH040458	MTH 02-Dec-2022 HRS 2720.6		O/C			
345034 NO. 2	TRANSPONDER			011-03301-01 7KU000327	MTH 02-Dec-2022 HRS 2720.6		O/C			
345039 RIGHT	GPS 2 ANTENNA GA-35			013-00235-00 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
345039	GPS 1 ANTENNA GA-35			013-00235-00 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
345040	NAV DATA BASE GPS KLN-90	*CF		071-01523-0302 28322	MTH 31-May-1996		O/C			
345055	JETTECH GPS CONVERTER			1201-4000-01 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
345061 NO. 1	GTN-750 GARMIN			011-04634-30 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
345061 NO. 2	GTN-750 GARMIN			011-04634-30 SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
346001 NO. 1	GPS RECEIVER			PN NOT INSTALLED	MTH 02-Dec-2022 HRS 2720.6		O/C			
346005	STORMSCOPE DISPLAY WX-1000	KTTN		78-8060-5900-9 JSD06900303	MTH 01-Feb-2018 HRS 2605 LDG 2215		O/C			
346006 NO. 2	TRAFIC ADVISORY COMPUTER TRC497-SKYWATCH	KTTN		805-10800-001 SKY07700044	MTH 21-Jan-2019 HRS 2620.8 LDG 2225		O/C			
346006	STORMSCOPE PROCESSOR WX-1000	SHV		78-8051-9160-4 JXPO39O4273	MTH 18-Oct-2002 HRS 1485		O/C	805		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
346007 NO. 2	SKYWATCH ANTENNA NY-164			805-10890-001 SKA04102657	MTH 10-May-2001 HRS 1018		O/C	0		
346007	STORMSCOPE ANTENNA WX-1000E	FCM		78-8051-9200-8 JSA02903030	MTH 31-Jul-1999 HRS 680		O/C	0		
346009 LEFT	AIR DATA COMPUTER F/ADC 200		1	962820-3A SN-UNKNOWN	MTH 02-Dec-2022 HRS 2720.6		O/C			
350006	OXYGEN BOTTLE DOT-E 8162	KMQS		176274-50 ALT279-19239/0501	MTH 06-Jul-2010 HRS 2354.3 LDG 2021		180		31-Mar-2025	-1 m 0 d
Over Due										
Manufacture Date: 31-Mar-2010										
350007	OXYGEN PRESSURE GAGE MD-97	*CF		C668512-0101 871	MTH 31-May-1996		O/C			
351002 COPILOT	COPILOT CREW OXYGEN MASK RESTORATION 9914067-41	KTTN		MC10-16-101 53667	MTH 17-Mar-2020 HRS 2634.8 LDG 2237		72	0	31-Mar-2026	11 m 0 d
351002 PILOT	PILOT CREW OXYGEN MASK RESTORATION 9914067-41	UNK		MC10-16-101 101329	MTH 02-Dec-2022 HRS 2720.6		72	5 0	31-Jul-2028	39 m 0 d
351004 LEFT	ALTITUDE PRESSURE SWITCH 9912057-5	*CF		P24031 SN-UNKNOWN	MTH 31-May-1996		O/C			
351008	OXYGEN 3 POSITION VALVE 9912057-21	*CF		110081-06 309	MTH 31-May-1996		O/C			
361001 LEFT	TEMPERATURE SENSOR *CF			27431501-05 1AM10	MTH 31-May-1996		O/C			
361001 RIGHT	TEMPERATURE SENSOR *CF			27431501-05 1AM7	MTH 31-May-1996		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY 8161-5	KTTN		9914402-6 S4883T0266	MTH 01-Nov-2019 HRS 2626 LDG 2229		3200	0	5826	2824.1
361002 RIGHT	B/A PRECOOLER ASSEMBLY 8161-5	KTTN		9914402-6 S4883-T-1132	MTH 01-Feb-2018 HRS 2605 LDG 2215		3200	0 0	5805	2803.1
361004 LEFT	PNEUMATIC SHUTOFF VALVE ASSY 9912421-1	*CF		4713-2 308	MTH 31-May-1996		O/C			
361004 RIGHT	PNEUMATIC SHUTOFF VALVE ASSY 9912421-1	*CF		4713-2 306	MTH 31-May-1996		O/C			
361006	PRESSURE BLEED AIR REGULATOR 9912043-4	*CF		1H75-16 9AK37	MTH 31-May-1996		O/C			
361007 LEFT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 1045	MTH 31-May-1996		O/C			
361007 RIGHT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 1053	MTH 31-May-1996		O/C			
361007	DOOR SEAL CONTROL VALVE *CF			MJV3 SN-UNKNOWN	MTH 31-May-1996		O/C			
361008 LEFT	PRECOOLER DOOR VALVE *CF			5060-00-01 358	MTH 31-May-1996		O/C			
361008 RIGHT	PRECOOLER DOOR VALVE *CF			5060-00-01 356	MTH 31-May-1996		O/C			
361009 LEFT	CHECK VALVE *CF			1989-00-1 254	MTH 31-May-1996		O/C			
361009 RIGHT	CHECK VALVE *CF			1989-00-1 296	MTH 31-May-1996		O/C			
361010 LEFT	CHECK VALVE *CF			1553-00-18 1084	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361010 RIGHT	CHECK VALVE *CF			1553-00-18 809	MTH 31-May-1996		O/C			
361011 LEFT	PRECOOLER ACTUATOR *CF			6312213-1 10AL60	MTH 31-May-1996		O/C			
361012 RIGHT	PRECOOLER ACTUATOR *CF			6312213-2 12AL64	MTH 31-May-1996		O/C			
521000	CABIN ENTRY DOOR			PN SN-UNKNOWN	MTH 31-May-1996		O/C	0		
522001	DOOR INFLATABLE SEAL KTTN			9912075-4 NSN	MTH 21-Jan-2019 HRS 2620.8 LDG 2225		O/C	0 0 0		
522002	SECONDARY SEAL KTTN			5511230-92 NSN	MTH 21-Jan-2019 HRS 2620.8 LDG 2225		O/C	0 0 0		
522003	ESCAPE HATCH SEAL *CF			R441236 SN-UNKNOWN	MTH 31-May-1996		O/C			
522004	PRESSURE SWITCH *CF			P18M-30 SN-UNKNOWN	MTH 31-May-1996		O/C			
522005	EMERGENCY ESCAPE HATCH			PN SN-UNKNOWN	MTH 31-May-1996		H/T H/T	0		
531000 LEFT	TRUNNION SUPPORT FITTING *CF			5513056-5 SN-UNKNOWN	MTH 31-May-1996 LDG 0		22500	0	22500	19995
531000 RIGHT	TRUNNION SUPPORT FITTING *CF			5513056-6 SN-UNKNOWN	MTH 31-May-1996 LDG 0		22500	0	22500	19995
531001	ACTUATOR SUPPORT FITTING *CF			6511105-1 SN-UNKNOWN	MTH 31-May-1996 LDG 0		22500	0	22500	19995
531201	RADOME ASSEMBLY *CF			6313101-47 SN-UNKNOWN	MTH 31-May-1996		O/C			
541001 LEFT ENGINE	INLET *CF			6352100-56 SN-UNKNOWN	MTH 31-May-1996		O/C			
541001 RIGHT ENGINE	INLET *CF			6352100-56 SN-UNKNOWN	MTH 31-May-1996		O/C			
561001 LEFT	WINDSHIELD ASSY, (LH) 9912064-15 *CF			E149000-101 3587	MTH 31-May-1996		O/C			
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912064-16 *CF			E149000-102 3714	MTH 31-May-1996		O/C			
561002 L1	CABIN DOOR WINDOW *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561002 L2	CABIN WINDOW *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561002 L3	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561002 L4	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561002 R1	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561002 R2	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561002 R3	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561002 R4	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 31-May-1996		O/C			
561003 PILOT	SIDE WINDOW *CF			6311065-15 SN-UNKNOWN	MTH 31-May-1996		O/C			
561004 COPILOT	SIDE WINDOW *CF			6311065-16 SN-UNKNOWN	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
571000 LEFT AFT	TRUNNION ATTACH FITTING *CF			6322070-1 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
571000 RIGHT AFT	TRUNNION ATTACH FITTING *CF			6322070-2 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
571001 LEFT FORWARD	TRUNNION ATTACH FITTING *CF			6322060-1 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
571001 RIGHT FORWARD	TRUNNION ATTACH FITTING *CF			6322060-2 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
571002 LEFT	SIDE BRACE FITTING *CF			6322080-1 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
571002 RIGHT	SIDE BRACE FITTING *CF			6322080-2 SN-UNKNOWN	MTH 31-May-1996 LDG 0		28300	0	28300	25795
712001 LEFT ENGINE AFT	ISOLATOR MOUNT 9912410-2	DAL		LM601SA4 SN-UNKNOWN	MTH 31-May-1996 HRS 6		CSI CSI CSI	6	4985	1983.1
712001 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912410-3	DAL		LM601SA5 SN-UNKNOWN	MTH 31-May-1996 HRS 6		CSI CSI CSI	6	4985	1983.1
712001 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912410-3	DAL		LM601SA5 SN-UNKNOWN	MTH 31-May-1996 HRS 6		CSI CSI CSI	6	4985	1983.1
712001 RIGHT ENGINE AFT	ISOLATOR MOUNT 9912410-2	DAL		LM601SA4 SN-UNKNOWN	MTH 31-May-1996 HRS 6		CSI CSI CSI	6	4985	1983.1
712001 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912410-3	DAL		LM601SA5 SN-UNKNOWN	MTH 31-May-1996 HRS 6		CSI CSI CSI	6	4985	1983.1
712001 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912410-3	DAL		LM601SA5 SN-UNKNOWN	MTH 31-May-1996 HRS 6		CSI CSI CSI	6	4985	1983.1
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	DAL		45700-104 1287	MTH 17-Oct-2002 HRS 1485		E/C	1485		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	DAL		45700-104 1288	MTH 17-Oct-2002 HRS 1485		E/C	1485		
720007 E1	1ST LP TURBINE NOZZLE DAL			57375 GDT10A	MTH 17-Oct-2002 HRS 1485		O/C	1485		
720007 E2	1ST LP TURBINE NOZZLE DAL			60780 GD533A	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723001 E1	FAN ROTOR DAL			50333 AU00361	MTH 17-Oct-2002 HRS 1485 LDG 1310		16500	1310	16500	13995
723001 E2	FAN ROTOR DAL			50333 AU00358	MTH 17-Oct-2002 HRS 1485 LDG 1310		16500	1310	16500	13995
723010 E1	HP COMPRESSOR ROTOR 250 DAL			50967 LC383	MTH 17-Oct-2002 HRS 1485 LDG 1310		5000	1310	5000	2495
723010 E2	HP COMPRESSOR ROTOR 250 DAL			50967 LC586	MTH 17-Oct-2002 HRS 1485 LDG 1310		5000	1310	5000	2495
723015 E1	IP COMPRESSOR ROTOR DAL			66032 HW13831	MTH 17-Oct-2002 HRS 1485 LDG 1310		10000	0	11310	8805

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
 Aircraft Model: **525 - CITATION JET**
 Aircraft Serial: **525-0139**
 Unit: **0139** Reg No: **N36RG**
 Airworthiness: **31-May-1996**
 Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
723015 E2	IP COMPRESSOR ROTOR DAL			66032 HW13704	MTH 17-Oct-2002 HRS 1485 LDG 1310		10000	0	11310	8805
723022 E1	DIFFUSER CASE ASSEMBLY 290 DAL			54861 AU00250	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723022 E2	DIFFUSER CASE ASSEMBLY 290 DAL			54861 AU00275	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723061 E1	HIGH PRESSURE SHAFT 200 DAL			55667 GG461	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723061 E2	HIGH PRESSURE SHAFT 200 DAL			55667 GG491	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723092 E1	COMPLETE LP SHAFT ASSEMBLY 40 DAL			50865 RRL1384	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723092 E2	COMPLETE LP SHAFT ASSEMBLY 40 DAL			50865 RRL1381	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723149 E1	HP COMPRESSOR COVER ASSY DAL			50778 AU00755	MTH 17-Oct-2002 HRS 1485		O/C	1485		
723149 E2	HP COMPRESSOR COVER ASSY DAL			50778 AU00332	MTH 17-Oct-2002 HRS 1485		O/C	1485		
724035 E1	HP TURBINE ROTOR ASSEMBLY DAL			65442 RRL0308	MTH 17-Oct-2002 HRS 1485		O/C	1485		
724035 E2	HP TURBINE ROTOR ASSEMBLY DAL			65442 RRL0284	MTH 17-Oct-2002 HRS 1485		O/C	1485		
724040 E1	REAR FUEL SLINGER SEAL ASSEMBLY 280 DAL			55608 AU01308	MTH 17-Oct-2002 HRS 1485		O/C	1485		
724040 E2	REAR FUEL SLINGER SEAL ASSEMBLY 280 DAL			55608 AU01332	MTH 17-Oct-2002 HRS 1485		O/C	1485		
725010 E1	HP TURBINE DISK DAL			59809 RRL7EYVM	MTH 17-Oct-2002 HRS 1485 LDG 1310		3600 3600	1485 1310	3600 3600	598.1 1095
725010 E2	HP TURBINE DISK DAL			59809 RRL7EXWZ	MTH 17-Oct-2002 HRS 1485 LDG 1310		3600 3600	1485 1310	3600 3600	598.1 1095
725020 E1	1ST LP TURBINE DISK 411 DAL			50255 RRL7EXCM	MTH 17-Oct-2002 HRS 1485 LDG 1310		14700	1310	14700	12195
725020 E2	1ST LP TURBINE DISK 411 DAL			50255 RRL7EYGE	MTH 17-Oct-2002 HRS 1485 LDG 1310		14700	1310	14700	12195
725030 E1	2ND LP TURBINE DISK 551 DAL			50792 RRL7EXDE	MTH 17-Oct-2002 HRS 1485 LDG 1310		13500	1310	13500	10995
725030 E2	2ND LP TURBINE DISK 551 DAL			50792 RRL7EXVF	MTH 17-Oct-2002 HRS 1485 LDG 1310		13500	1310	13500	10995
726011 E1	ACCESSORY DRIVE GEARBOX ASSEMBLY DAL			56400 WL01430	MTH 17-Oct-2002 HRS 1485		O/C	1485		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
726011 E2	ACCESSORY DRIVE GEARBOX ASSEMBLY	DAL		56400 WL01411	MTH 17-Oct-2002 HRS 1485		O/C	1485		
730001 LEFT ENGINE	FUEL PRESSURE SWITCH 9912033-2	*CF		1103P0448 2523	MTH 31-May-1996		O/C			
730001 RIGHT ENGINE	FUEL PRESSURE SWITCH 9912033-2	*CF		1103P0448 2516	MTH 31-May-1996		O/C			
732002	SYNCHRONIZER CONTROLLER MKE			213693 2251846	MTH 19-Nov-1998 HRS 563		O/C	0		
732003	ENGINE SYNCHRONIZER ACTUATOR *CF			5485-066 11481169	MTH 31-May-1996		O/C			
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	*CF		1573-4 343	MTH 31-May-1996		O/C			
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	*CF		1573-4 339	MTH 31-May-1996		O/C			
730002 E1	FUEL NOZZLE ASSEMBLY KSWF			C50817 CBCC0000214	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		O/C			
730002 E2	FUEL NOZZLE ASSEMBLY 115	KSWF		50817 BCC-00005896	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		O/C			
731001 E1	FUEL PUMP	DAL	K	716700-5 YYK0943	MTH 17-Oct-2002 HRS 1485		6000	621	6864	3862.1
731001 E2	FUEL PUMP 640	DAL		54904 YYK0260	MTH 17-Oct-2002 HRS 1485		6000	1466	6019	3017.1
732090 E1	START NOZZLE CONTROL VALVE 625	DAL		50803 RF11437812	MTH 17-Oct-2002 HRS 1485		6000	1485	6000	2998.1
732090 E2	START NOZZLE CONTROL VALVE 625	DAL		50803 RF11452835	MTH 17-Oct-2002 HRS 1485		6000	1485	6000	2998.1
732301 E1	ELEC FUEL FILTER INDICATOR 650	DAL		56015 GE0459	MTH 17-Oct-2002 HRS 1485		O/C	1485		
732301 E2	ELEC FUEL FILTER INDICATOR DAL			57847 GE0084	MTH 17-Oct-2002 HRS 1485		O/C	1191		
732401 E1	FUEL CONTROL (HMU) UNIT 630	DAL		55629 RF11430755	MTH 17-Oct-2002 HRS 1485		6000	621	6864	3862.1
732401 E2	FUEL CONTROL (HMU) UNIT 630	DAL		55629 RF11430754	MTH 17-Oct-2002 HRS 1485		6000	1485	6000	2998.1
741010 E1 INBOARD	IGNITION EXCITER DAL			50846 HF435	MTH 17-Oct-2002 HRS 1485		O/C	1337		
741010 E2 INBOARD	IGNITION EXCITER DAL			50846 CK0E084	MTH 17-Oct-2002 HRS 1485		O/C	1485		
741020 E1 OUTBOARD	IGNITION EXCITER DAL			50846 CK0929	MTH 17-Oct-2002 HRS 1485		O/C	1485		
741020 E2 OUTBOARD	IGNITION EXCITER DAL			50846 CK0E084	MTH 17-Oct-2002 HRS 1485		O/C	1485		
742001 E1	SHORT IGNITOR LEAD KSWF			50852 N/A	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		O/C	0 0 0		

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No		C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
742001 E2	SHORT IGNITOR LEAD	DAL		50852 SN-UNKNOWN	MTH HRS	17-Oct-2002 1485		O/C			1485
742002 E1	LONG IGNITOR LEAD	KSWF		50853 N/A	MTH HRS LDG	19-Oct-2023 2837.6 2402		O/C	0 0 0		
742002 E2	LONG IGNITOR LEAD	DAL		50853 SN-UNKNOWN	MTH HRS	17-Oct-2002 1485		O/C			1485
742201 E1 INBOARD	IGNITOR	KSWF		68032 1801987	MTH HRS LDG	19-Oct-2023 2837.6 2402		O/C			
742201 E1 OUTBOARD	IGNITOR	KSWF		68032 1800262	MTH HRS LDG	19-Oct-2023 2837.6 2402		O/C			
742201 E2 INBOARD	IGNITOR	KSWF		CH-31956 2300475	MTH HRS LDG	19-Oct-2023 2837.6 2402		O/C			
742201 E2 OUTBOARD	IGNITOR	KSWF		CH-31956 1041624	MTH HRS LDG	19-Oct-2023 2837.6 2402		O/C			
771003 STANDBY	N1 INDICATOR	CHA		9912399-7 278A	MTH HRS LDG	07-Apr-2022 2642.8 2253		O/C	0 0		
771005 E1	N1 DUAL MAGNETIC SPEED SENSOR 740	DAL		50867 YYV114	MTH HRS	17-Oct-2002 1485		O/C			1485
771005 E2	N1 DUAL MAGNETIC SPEED SENSOR 740	UNK		50867 YYV102	MTH HRS	16-Dec-2022 2725.2		O/C			
771015 E1	N2 DUAL MAGNETIC SPEED SENSOR 750	DAL		50866 YYV044	MTH HRS	17-Oct-2002 1485		O/C			1485
771015 E2	N2 DUAL MAGNETIC SPEED SENSOR 750	DAL		50866 YYV057	MTH HRS	17-Oct-2002 1485		O/C			1485
772001 E1 NO. 1	ITT PROBE 680	DAL		55631-S 833	MTH HRS	17-Oct-2002 1485		O/C			1485
772001 E1 NO. 2	ITT PROBE	DAL		55633-L 598	MTH HRS	17-Oct-2002 1485		O/C			1485
772001 E1 NO. 3	ITT PROBE 682	DAL		55633-L 597	MTH HRS	17-Oct-2002 1485		O/C			1485
772001 E1 NO. 4	ITT PROBE 710	DAL		55631-S 834	MTH HRS	17-Oct-2002 1485		O/C			1485
772001 E1 NO. 5	ITT PROBE 711	DAL		55631-S 835	MTH HRS	17-Oct-2002 1485		O/C			1485
772001 E1 NO. 6	ITT PROBE 712	DAL		55633-L 600	MTH HRS	17-Oct-2002 1485		O/C			1485

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
772001 E2 NO. 1	ITT PROBE 680	DAL		55631-S 862	MTH 17-Oct-2002 HRS 1485		O/C	1485		
772001 E2 NO. 2	ITT PROBE 681	DAL		55631-S 863	MTH 17-Oct-2002 HRS 1485		O/C	1485		
772001 E2 NO. 3	ITT PROBE 682	DAL		55633-L 612	MTH 17-Oct-2002 HRS 1485		O/C	1485		
772001 E2 NO. 4	ITT PROBE	DAL		65697 YYF000083	MTH 17-Oct-2002 HRS 1485		O/C	0		
772001 E2 NO. 5	ITT PROBE 711	DAL		55633-L 614	MTH 17-Oct-2002 HRS 1485		O/C	1485		
772001 E2 NO. 6	ITT PROBE 712	DAL		55631-S SN-UNKNOWN	MTH 17-Oct-2002 HRS 1485		O/C	1485		
781001 LEFT	EXHAUST NOZZLE *CF			6352350-20 SN-UNKNOWN	MTH 31-May-1996		O/C			
781001 RIGHT	EXHAUST NOZZLE *CF			6352350-20 SN-UNKNOWN	MTH 31-May-1996		O/C			
783001 LEFT	T/A SWITCH *CF			602EN602-6 SN-UNKNOWN	MTH 31-May-1996		O/C			
783001 RIGHT	T/A SWITCH MKE			602EN602-6 321	MTH 21-Jan-1999 HRS 600		O/C	0		
783002 LEFT	T/A PADDLE ASSY *CF			6354051-79 SN-UNKNOWN	MTH 31-May-1996		O/C			
783002 RIGHT	T/A PADDLE ASSY OBI			6354051-79-1 N/A	MTH 22-Nov-2011 HRS 2427.1 LDG 2071		O/C	0 0 0		
783003 LEFT	ATTENUATOR ACTUATOR *CF			6317105-10 SN-UNKNOWN	MTH 31-May-1996		O/C			
783003 RIGHT	ATTENUATOR ACTUATOR *CF			6317105-10 SN-UNKNOWN	MTH 31-May-1996		O/C			
783005 LEFT	THRUST ATTENUATOR BELLCRANK *CF			6354051-59 SN-UNKNOWN	MTH 31-May-1996		O/C			
783005 RIGHT	THRUST ATTENUATOR BELLCRANK *CF			6354051-60 SN-UNKNOWN	MTH 31-May-1996		O/C			
793001	OIL TEMPERATURE/PRESSURE N2 SENSOR 9912399-5 ICT			10273N03M00 287	MTH 10-Jan-1997 HRS 205		O/C	0		
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 68080	MTH 31-May-1996		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 68031	MTH 31-May-1996		O/C			
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1 *CF			123479 50934	MTH 31-May-1996		O/C			
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1 MKE			123479 41045	MTH 04-May-1999 HRS 640		O/C	0		
793006 LEFT ENGINE	OIL PRESSURE SWITCH 9912178-4 SHV			S1103P89-3 1076	MTH 16-Oct-2001 HRS 1169		O/C	0		
793006 RIGHT ENGINE	OIL PRESSURE SWITCH 9912178-4 *CF			S1103P89-3 337	MTH 31-May-1996		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
792201 E1	LUBE OIL COOLER 670	DAL		56157 PP-175	MTH 17-Oct-2002 HRS 1485		O/C	1485		
792201 E2	LUBE OIL COOLER 670	DAL		56157 000179	MTH 17-Oct-2002 HRS 1485		O/C	1485		
792401 E1	LUBE AND SCAVENGE PUMP 660	DAL		54886 WL01180	MTH 17-Oct-2002 HRS 1485		6000	1485	6000	2998.1
792401 E2	LUBE AND SCAVENGE PUMP 660	DAL		54886 WL01187	MTH 17-Oct-2002 HRS 1485		6000	1485	6000	2998.1
801101 LEFT ENGINE	STARTER/GENERATOR 9912125-2	N81		300SGL129Q 1900XL2	MTH 04-Jul-2024 HRS 2931.7 LDG 2459		1000	0	3931.7	929.8
801101 RIGHT ENGINE	STARTER/GENERATOR 9912125-2	N81		300SGL129Q 5571XL2	MTH 04-Jul-2024 HRS 2931.7 LDG 2459		1000	0	3931.7	929.8



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL 525-99-02 R05	CESCOM PRICES (THIS SL CANCELS SL525-99-02 R4 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 525-99-05	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 525-99-06	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525-03-01 R01	SUPPLEMENTAL TYPE CERTIFICATE (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	MOC :									
SL 525-99-10	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 525-05-03 R01 05SL-03 : 525R1	NEW 525 TASK BASED INSPECTION PROGRAM			MANDATORY	MTH 13-Mar-2007 HRS 2012		A/R			Complete
	MOC : COMPLIED WITH									
SL 525-05-05	PRECOOLER LIFE LIMIT			INFORMATIONAL	MTH 01-Feb-2018 HRS 2605 LDG 2215		-			Complete
	KTTN									
	MOC : COMPLIED WITH - ACCOMPLISHED SB525-36-04 ON RIGHT PRECOOLER ONLY. LEFT PRECOOLER REPLACED ON 08AUG12 2471.3 HRS, 2105 CYC.									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01) MOC :	INFORMATIONAL			-			
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01) MOC :	INFORMATIONAL			-			
PSID WI-05-1000 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
PSID WI-05-1000 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
PSID WI-05-1000 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
PSID WI-05-1000 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
PSID WI-05-1000 R06 E1	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
PSID WI-05-1000 R06 E2	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
PSID WI-05-1003 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS MOC :				-			
PSID WI-05-1003 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS MOC :				-			
PSID WI-05-1003 E1	TIME LIMITS/MAINTENANCE CHECKS - FORMS MOC :				-			
PSID WI-05-1003 E2	TIME LIMITS/MAINTENANCE CHECKS - FORMS MOC :				-			
SL WI-05-1009-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL MOC :	CANCELLED			-			
SL WI-05-1009-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL MOC :	CANCELLED			-			
SL WI-05-1009 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL MOC :				-			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl Part Serial No	Part Number	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-05-1009 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1021-CN E1	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL	CANCELLED						-
	MOC :							
SL WI-05-1021-CN E2	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL	CANCELLED						-
	MOC :							
SL WI-05-1021 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1021 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1092-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL	CANCELLED						-
	MOC :							
SL WI-05-1092-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL	CANCELLED						-
	MOC :							
SL WI-05-1092 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1092 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1149 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							
SL WI-05-1149 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL							-
	MOC :							

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-05-1173-CN E1	CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1173-CN E2	CANCELLED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1194-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1194-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1198 R01 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1198 R01 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1198 E1	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1198 E2	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SB 525-11-09 11SB-09	FUEL PLACARD RELOCATION			OPTIONAL	MTH		-			
MOC :										
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS						-			
MOC :										
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS						-			
MOC :										
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS						-			
MOC :										
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS				MTH		-			
MOC :										
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL						-			
MOC :										
SL CIL-20-01 R03-CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL						-			
MOC :										
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL						-			
MOC :										
SL 525-20-01 R18	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL						A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-20-05 20SL-05	ELECTRICAL CONNECTOR REPLACEMENT	DAL		RECOMMENDED	MTH 10-May-2002 HRS 1367		-			Complete
MOC : COMPLIED WITH										
SL 525-20-06	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
MOC :										
SB 525-21-08 R01 21SB-08 : 525R1	FLOOD COOLING DUCT MODIFICATION	MKE		RECOMMENDED	MTH 06-Mar-1997 HRS 222		A/R			Complete
MOC : COMPLIED WITH										
SB 525-21-11 21SB-11	COCKPIT SIDE DUCT MODIFICATION	MKE		RECOMMENDED	MTH 06-Mar-1997 HRS 222		-			Complete
MOC : COMPLIED WITH										
SB 525-21-12 21SB-12	PRESSURIZATION DUMP WIRING MODIFICATION AND SWITCH GUARD INSTALLATION	MKE		RECOMMENDED	MTH 07-Aug-1997 HRS 294		-			Complete
MOC : COMPLIED WITH										
SB 525-21-13 R01 21SB-13 : 525R1	EVAPORATOR WATER COLLECTION & DRAINAGE			OPTIONAL	MTH		-			
MOC :										
SB 525-21-15 21SB-15	BINARY PRESSURE SWITCH REPLACE	DAL		RECOMMENDED	MTH 10-May-2002 HRS 1367		-			Complete
MOC : COMPLIED WITH										
SB 525-21-17 R02	FORWARD EVAPORATOR RELAY INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 525-21-17 R03	FORWARD EVAPORATOR REPLAY INSTALLATION			OPTIONAL			-			
MOC :										
SB 525-21-17 21SB-17	FORWARD EVAPORATOR RELAY INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 525-21-19 21SB-19	TEMPERATURE SENSOR RELOCATION			OPTIONAL	MTH		A/R			
MOC :										
SB 525-21-20 R01	AIR CONDITIONING - BAROMETRIC PRESSURE SWITCH INSTALLATION			OPTIONAL			-			
MOC :										
SB 525-21-20	BAROMETRIC PRESSURE SWITCH INSTALLATION			OPTIONAL			-			
MOC :										
ASL 525-21-01 21SLA01	AIR CONDITIONER GROUND CABLE INSPECTION	SHV		MANDATORY	MTH 11-Oct-2001 HRS 1161		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
MOC :										
SB 525-22-01 22SB-01	AILERON SERVO MOUNT AND ATTACHMENT MODIFICATION	*CF		RECOMMENDED	MTH 31-May-1996		A/R			Complete
MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-23-06 23SB-06	AVTECH AUDIO CONTROL PANEL MODIFICATION	MKE		MANDATORY	MTH 11-Oct-1996 HRS 148		A/R			Complete
MOC : COMPLIED WITH										
SB 525-23-08 23SB-08	ALLIEDSIGNAL 8.33 KHZ COMMUNICATION RADIO INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 525-23-12 23SB-12	HONEYWELL KY-196A/KY-196B DUAL VHF COMMUNICATION SYSTEM UPGRADE	MIV		RECOMMENDED	MTH 30-Sep-2006 HRS 1962		-			N/A
MOC : NOT APPLICABLE										
SB 525-23-13 23SB-13	GARMIN RADIO REPLACEMENT			OPTIONAL	MTH		-			
MOC :										
SL 525-23-05 23SL-05	TRANSMITTAL OF ALLIED SIGNAL BENDIX/KING SERVICE BULLETIN KY196A-9 - KY196A VHF COMM TRANSCEIVER	MKE		RECOMMENDED	MTH 25-Jan-2000 HRS 785		-			Complete
MOC : COMPLIED WITH										
SL 525-23-06 23SL-06	TRANSMITTAL OF ALLIED SIGNAL BENDIX/KING SERVICE BULLETIN KY196B-2 - KY196B VHF COMM TRANSCEIVER	MKE		RECOMMENDED	MTH 25-Jan-2000 HRS 785		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 525-23-11	COMMUNICATIONS - ATG 5000 SOFTWARE UPGRADE			OPTIONAL			-			
MOC :										
SL 525-23-12	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8			OPTIONAL			-			
MOC :										
SLA 525-23-03 23SLA-03	AVTECH AUDIO CONTROL PANEL OPERATIONAL CHECK	MKE		RECOMMENDED	MTH 11-Oct-1996 HRS 148		A/R			Complete
MOC : COMPLIED WITH										
SB 525-24-02 24SB-02	ELECTRICAL GROUND STUD INSTALLATION/INSPECTION	MKE		RECOMMENDED	MTH 07-Aug-1997 HRS 294		-			Complete
MOC : COMPLIED WITH										
SB 525-24-07 24SB-07	44 AMP HOUR BATTERY INSTALLATION	MKE		OPTIONAL	MTH 17-Jun-1997 HRS 271		A/R			Complete
MOC : COMPLIED WITH										
SB 525-24-14 R01 24SB-14 : 525R1	GCU START MODIFICATION	MKE		MANDATORY	MTH 10-May-1998 HRS 411		A/R			Complete
MOC : COMPLIED WITH										
SB 525-24-15 24SB-15	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT	MKE		RECOMMENDED	MTH 08-Dec-1999 HRS 758		-			Complete
MOC : COMPLIED WITH										
SB 525-24-17 24SB-17	EXTERNAL POWER REVERSE POLARITY PROTECTION	MKE		OPTIONAL	MTH 19-Nov-1998 HRS 563		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains
SB 525-24-19 R01 24SB-19 : 525R1	CONCORDE LEAD ACID BATTERY INSTALLATION	SHV		OPTIONAL	MTH 13-Feb-2001 HRS 923		A/R			Complete
MOC : COMPLIED WITH										
SB 525-24-19 R02 24SB-19 : 525R2	CONCORDE LEAD ACID BATTERY INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 525-24-22 24SB-22	TAILCONE ELECTRICAL GROUND STUD IMPROVEMENT	MIV		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 525-24-23 24SB-23	AFT CABIN WIRE BUNDLE PROTECTION	DAL		RECOMMENDED	MTH 25-Mar-2004 HRS 1687		-			Complete
MOC : COMPLIED WITH										
SB 525-24-25 24SB-25	NICKEL-CADMIUM BATTERY INSTALLATION			OPTIONAL	MTH		-			
MOC :										
COM MC 525-007 R01	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES			INFORMATIONAL	MTH		-			
MOC :										
COM MC 525-007	GENERATOR CONTROL UNIT TROUBLESHOOTING GUIDELINES						-			
MOC :										
SL 525-24-02 24SL-02	ENGINE INDICATOR VOLTAGE REGULATOR INSPECTION/REPLACEMENT	MKE		RECOMMENDED	MTH 11-Sep-1997 HRS 319		-			Complete
MOC : COMPLIED WITH										
SL 525-24-03 R01 24SL-03 : 525R1	IGNITER CONTROL PRINTED/CIRCUIT BOARD INSPECTION	SHV		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 525-24-10	ELECTRICAL POWER - BATTERY TEMPERATURE INDICATOR GAGE BLANKING PLATE INSTALLATION			OPTIONAL			-			
MOC :										
SB 525-25-18 R01 25SB-18 : 525R1	COAT HANGER INSTALLATION	MKE		RECOMMENDED	MTH 19-Nov-1998 HRS 563		-			Complete
MOC : COMPLIED WITH										
SB 525-25-22 R01 25SB-22 : 525R1	GLARESHIELD LEATHER STRAP INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 525-25-23 R01	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 525-25-23 25SB-23	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 525-25-25 25SB-25	TOILET TRAY AND PAD INSTALLATION			SUPERSEDED	MTH		A/R			
MOC : - SERVICE BULLETIN CANCELLED 08-22-2007.										
SB 525-25-26 25SB-26	PASSENGER SEAT GEAR AND BACKREST LATCH PIN REPLACEMENT			OPTIONAL	MTH		-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-25-34	EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK OPTIONAL						-			
MOC :										
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION OPTIONAL						-			
MOC :										
SL 525-25-02 25SL-02	TRANSMITTAL OF EASTERN AERO MARINE SERVICE BULLETIN SBV-25-2, EQUIPMENT/FURNISHINGS-LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT OF CO2 INFLATOR-MANDATORY	MKE		MANDATORY	MTH 06-Mar-1997 HRS 222		A/R			Complete
MOC : COMPLIED WITH										
SL 525-25-03 25SL-03	LEFT HAND TOILET SEAT BELT INSPECTION/INSTALLATION	MKE		RECOMMENDED	MTH 08-Dec-1999 HRS 758		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 525-25-05 25SL-05	INSPECTION OF THE BACKREST LATCH PLATES	OBI		MANDATORY	MTH 05-Nov-2009 HRS 2291		A/R			Complete
MOC : COMPLIED WITH										
SB 525-26-01 26SB-01	FIRE BOTTLE IDENTIFICATION SLEEVE INSTALLATION	MCO		MANDATORY	MTH 05-May-2005 HRS 1769		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH		-			
MOC :										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH		-			
MOC :										
COM MC 525-009	HYDRAULIC FIREWALL SHUTOFF VALVES			INFORMATIONAL			-			
MOC :										
SB 525-27-05 27SB-05	HYDRAULIC SYSTEM LOADING IMPROVEMENT	*CF		OPTIONAL	MTH		-			
MOC :										
SB 525-27-06 27SB-06	TRIM ACTUATOR GREASE FITTING INSTALLATION	MKE		OPTIONAL	MTH 24-Jun-2000 HRS 864		-			Complete
MOC : COMPLIED WITH										
SB 525-27-07 27SB-07	FLAP HYDRAULIC SYSTEM RESTRICTOR REPLACEMENT/INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 525-27-08 27SB-08	CONTROL LOCK SLIDE TUBE INSPECTION/MODIFICATION	MKE		RECOMMENDED	MTH 27-Jan-1998 HRS 387		-			Complete
MOC : COMPLIED WITH										
SB 525-27-11 R02 27SB-11 : 525R2	STEEP APPROACH CERTIFICATION-SPEED BRAKE SWITCH ADJUSTMENT			OPTIONAL	MTH		-			
MOC :										
SB 525-27-15 R01 27SB-15 : 525R1	FLAP OVERRIDE SWITCH INSTALLATION	MIV		RECOMMENDED	MTH 30-Sep-2006 HRS 1962		-			N/A
MOC : NOT APPLICABLE										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-27-17 27SB-17	ELECTRIC ELEVATOR TRIM PRINTED CIRCUIT BOARD REPLACEMENT	DAL		MANDATORY	MTH 20-Jan-2004 HRS 1682		A/R			Complete
	MOC : COMPLIED WITH									
SB 525-27-18 27SB-18	ELEVATOR TRIM POINTER IMPROVEMENT		OPTIONAL		MTH		-			
	MOC :									
SB 525-27-19 R02	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION	KTTN		MANDATORY	MTH 07-Oct-2014 HRS 2545.9 LDG 2166		A/R			Complete
	MOC : COMPLIED WITH - PERFORMED BY NY CITATION SERVICE CENTER TECH ON SITE KTTN. SEE MTR # 2346790 REFERENCING CESSNA W.O. # 331192.									
SB 525-27-20 27SB-20	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT		OPTIONAL		MTH		A/R			
	MOC :									
SB 525-27-26 R01	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION		RECOMMENDED	MTH			-			
	MOC :									
SB 525-27-28	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION		RECOMMENDED	MTH			-			
	MOC :									
ASL 525-27-02 27SLA02	ELECTRIC ELEVATOR TRIM RUNAWAY PROCEDURE	SHV		MANDATORY	MTH 30-Oct-2003 HRS 1680		A/R			Complete
	MOC : COMPLIED WITH									
SL 525-27-01 27SL-01	ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION	DAL		RECOMMENDED	MTH 01-Oct-2002 HRS 1485		-			Complete
	MOC : COMPLIED WITH									
SL 525-27-04 R01 27SL-04 : 525R1	FLAP PUSHROD SAFETY WIRE INSPECTION		RECOMMENDED				A/R			
	MOC :									
SL 525-27-09	FLIGHT CONTROLS - SPEED BRAKE ACTUATOR SCREW REPLACEMENT		OPTIONAL				-			
	MOC :									
SB 525-28-10 28SB-10	FUEL CROSSFEED TO FUEL TRANSFER MODIFICATION		OPTIONAL		MTH		-			
	MOC :									
SB 525-28-11 R01 28SB-11 : 525R1	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	MIV		MANDATORY	MTH 30-Sep-2006 HRS 1962		A/R			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE									
SB 525-28-12 28SB-12	WING FUEL BOOST PUMP WIRE IMPROVEMENT	MCO		MANDATORY	MTH 23-Jul-2004 HRS 1729		A/R			Complete
	MOC : COMPLIED WITH									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS		INFORMATIONAL				-			
	MOC :									
SB 525-29-09 29SB-09	HYDRAULIC LINE IMPROVEMENT	DAL		MANDATORY	MTH 09-Feb-2001 HRS 923		-			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains
SB 525-29-10 29SB-10	SOLENOID LOADING VALVE REPLACEMENT	DAL		RECOMMENDED	MTH 10-May-2002 HRS 1367		-			Complete
MOC : COMPLIED WITH										
SB 525-29-11 R02 29SB-11 : 525R2	HYDRAULIC RELIEF VALVE INSPECTION			CANCELLED	MTH HRS		36 1200			
SERVICE BULLETIN CANCELLED.										
MOC :										
SB 525-29-14 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	KTTN		MANDATORY	MTH 03-May-2013 HRS 2508.6 LDG 2127		A/R			Complete
MOC : COMPLIED WITH										
SB 525-29-15	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 525-30-06 30SB-06	WING ANTI-ICE OVER TEMPERATURE SWITCH WIRING IMPROVEMENT	MKE		RECOMMENDED	MTH 30-Sep-1999 HRS 719		-			Complete
MOC : COMPLIED WITH										
SB 525-30-07 R02 30SB-07 : 525R2	WING ANTI-ICE OVERTEMPERATURE SWITCH RELOCATION			OPTIONAL	MTH		A/R			
MOC :										
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
MOC :										
SL 525-30-02 R01 30SL-02 : 525R1	LEFT AND RIGHT WINDSHIELD ANTI-ICE CONTROL ASSEMBLY INSPECTION	MKE		RECOMMENDED	MTH 19-Nov-1998 HRS 563		A/R			Complete
MOC : COMPLIED WITH										
SL 525-30-02 30SL-02	LEFT AND RIGHT WINDSHIELD ANTI-ICE CNTROL ASSEMBLY INSPECTION	MKE		RECOMMENDED	MTH 27-Jan-1998 HRS 387		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
MOC :										
SL 525-31-02 31SL-02	ANNUNCIATOR PANEL REPLACEMENT			OPTIONAL	MTH		-			
MOC :										
SB 525-32-06 R01 32SB-06 : 525R1	GRAVEL RUNWAY OPTION MOD			OPTIONAL	MTH		-			
MOC :										
SB 525-32-08 R01 32SB-08 : 525R1	MAIN LANDING GEAR TRUNNION BEARING REPLACEMENT	MKE		MANDATORY	MTH 11-Oct-1996 HRS 148		A/R			Complete
MOC : COMPLIED WITH										
SB 525-32-11 32SB-11	MAIN LANDING GEAR ACTUATOR HYDRAULIC FITTING REPLACEMENT	MKE		RECOMMENDED	MTH 06-Mar-1997 HRS 222		-			Complete
MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-32-12 32SB-12	BRAKE RESERVOIR PLUMBING IMPROVEMENT	MKE		RECOMMENDED	MTH 06-Mar-1997 HRS 222		-			Complete
MOC : COMPLIED WITH										
SB 525-32-13 32SB-13	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT	MKE		RECOMMENDED	MTH 07-Aug-1997 HRS 294		A/R			Complete
MOC : COMPLIED WITH										
SB 525-32-14 32SB-14	MAIN LANDING GEAR TRUNNION PIN REPLACEMENT	ICT		RECOMMENDED	MTH 24-May-1999 HRS 644		-			Complete
MOC : COMPLIED WITH										
SB 525-32-15 32SB-15	LANDING GEAR ANTISKID DIODE REMOVAL	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		-			Complete
MOC : COMPLIED WITH										
SB 525-32-17 R01 32SB-17 : 525R1	BRAKE LINE REPLACEMENT	DAL		RECOMMENDED	MTH 10-May-2002 HRS 1367		-			Complete
MOC : COMPLIED WITH										
SB 525-32-17 32SB-17	LANDING GEAR BRAKE LINE REPLACEMENT	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		A/R			Complete
MOC : COMPLIED WITH										
SB 525-32-18 32SB-18	BREAK MOTOR COUPLING REPLACEMENT	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		-			Complete
MOC : COMPLIED WITH										
SB 525-32-19 R02 32SB-19 : 525R2	LANDING GEAR ON GROUND OPERATION & MODIFICATION	SHV		RECOMMENDED	MTH		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 525-32-20 R01 32SB-20 : 525R1	BRAKE LINE REPLACEMENT & RELOCATION	DAL		RECOMMENDED	MTH 10-May-2002 HRS 1367		-			Complete
MOC : COMPLIED WITH										
SB 525-32-22 R01 32SB-22 : 525R1	EMERGENCY GEAR RELEASE BRACKET CLEARANCE IMPROVEMENT	SHV		RECOMMENDED	HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 525-32-25 32SB-25	BEARING REPLACEMENT	MIV		MANDATORY	MTH 22-Apr-2006 HRS 1900		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE										
ASL 525-32-21 32SLA21	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1559-32-4, MAIN LANDING GEAR - BRAKE ASSEMBLY - P/N 2-1559-1 AND 2-1559-2 - CESSNA CITATION AIRCRAFT - INTRODUCTION OF A NEW BRAKE ASSEMBLY P/N 2-1559-3	KMQS		MANDATORY	MTH 23-Mar-2010 HRS 2329.9 LDG 2007		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	N81		RECOMMENDED	MTH 04-Jul-2024 HRS 2931.7 LDG 2459		-			Complete
	MOC : COMPLIED WITH - C/W CIL-32-03, NO DEFECTS FOUND									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION						-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION						-			
	MOC :									
SL 525-32-10 32SL-10	TRANSMITTAL OF BF GOODRICH SERVICE LETTER SL1728, LANDING GEAR-NOSE WHEEL BALANCE WEIGHT FASTENER PLACEMENT	MKE		RECOMMENDED	MTH 06-Mar-1997 HRS 222		-			Complete
	MOC : COMPLIED WITH									
SL 525-32-12 32SL-12	MAIN LANDING GEAR TRAILING LINK/SPACER GAP INSPECTION	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		-			Complete
	MOC : COMPLIED WITH									
SL 525-32-14 32SL-14	NOSE GEAR STEERING BUNGEE INSPECTION	MKE		RECOMMENDED	MTH 19-Nov-1998 HRS 563		-			Complete
	MOC : COMPLIED WITH									
SL 525-32-15 32SL-15	NOSE LANDING GEAR TIRE INSPECTION	SHV		MANDATORY	MTH 15-Mar-2002 HRS 1319 LDG 1174		A/R			Complete
	MOC : COMPLIED WITH									
SL 525-32-17 R01 32SL-17 : 525R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
	MOC :									
SL 525-32-19 32SL-19	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	ILG		RECOMMENDED	MTH HRS		150			
	OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
	MOC :									
SL 525-32-20 32SL-20	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION			RECOMMENDED			A/R			
	MOC :									
SL 525-32-23 R02 32SL-23	EMERGENCY GEAR RELEASE INSPECTION	TTN		MANDATORY	MTH 10-Sep-2012 HRS 2473.2 LDG 2107		-			Complete
	MOC : COMPLIED WITH									
SL 525-32-23 32SL-23	EMERGENCY GEAR RELEASE INSPECTION			MANDATORY	MTH		A/R			
	MUST BE ACCOMPLISHED IN CONJUNCTION WITH INSPECTION DOCUMENT 10.									
	MOC :									
SL 525-32-27	LANDING GEAR - MAIN LANDING GEAR REPAIR			INFORMATIONAL			-			
	MOC :									
SLA 525-32-11 R01 32SLA-11 : 525R1	MAIN LANDING GEAR TRUNNION PIN INSPECTION	MKE		MANDATORY	MTH 11-Oct-1996 HRS 148		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SLA 525-32-11 32SLA-11	MAIN LANDING GEAR TRUNNION PIN INSPECTION	MKE		MANDATORY	MTH 18-Sep-1996 HRS 120		A/R			Complete
	MOC : COMPLIED WITH									
SB 525-33-06 R01 33SB-06 : 525R2	EMERGENCY LIGHTING BATTERY PACK UPGRADE			OPTIONAL	MTH		-			
	MOC :									
SB 525-33-07 33SB-07	CHART LIGHT MODIFICATION			OPTIONAL	MTH		-			
	MOC :									
SB 525-33-10	LIGHTS - WING TIP LED LIGHT MODIFICATION			OPTIONAL			-			
	MOC :									
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
	MOC :									
SB 525-34-27 34SB-27	GNS-XLS FAULT DETECTION AND EXCLUSION (FDE) SOFTWARE UPGRADE	MKE		RECOMMENDED	MTH 27-Jan-1998 HRS 387		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE									
SB 525-34-28 34SB-28	GNS-XLS 5 VOLT LIGHTING WIRING MODIFICATION	MKE		RECOMMENDED	MTH 17-Jun-1997 HRS 271		-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE									
SB 525-34-29 34SB-29	NAV-RG204 RATE GYRO RUDDER KICK	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		-			Complete
	MOC : COMPLIED WITH									
SB 525-34-30 34SB-30	ART-2000-6 RADAR MODIFICATION	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		A/R			Complete
	MOC : COMPLIED WITH									
SB 525-34-31 34SB-31	GNSXLS SOFTWARE MOD 3 UPGRD	MKE		RECOMMENDED	MTH 19-Nov-1998 HRS 563		-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SB 525-34-32 R01 34SB-32 : 525R1	AVIONICS MASTER SWITCH REPLACEMENT	MKE		RECOMMENDED	MTH 19-Nov-1998 HRS 563		A/R			Complete
	MOC : COMPLIED WITH									
SB 525-34-33 34SB-33	KLN-90B SOFTWARE MOD 21/10 MOD	MKE		MANDATORY	MTH 30-Sep-1999 HRS 719		A/R			Complete
	MOC : COMPLIED WITH									
SB 525-34-34 34SB-34	KLN-900 SOFTWARE MODIFICATION	MKE		RECOMMENDED	MTH 08-Dec-1999 HRS 758		-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SB 525-34-35 34SB-35	BRNAV INCORPORATION			OPTIONAL	MTH		-			
	MOC :									
SB 525-34-36 34SB-36	UNS-1K W/604.0 SOFTWARE UPGRADE	SHV		RECOMMENDED	MTH 03-Dec-2001 HRS 1213		-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-34-38 R01 34SB-38 : 525R1	SHADIN ADC-200 FUEL/AIR DATA COMPUTER	SHV		RECOMMENDED	MTH 03-Dec-2001 HRS 1213		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SB 525-34-38 34SB-38	SHADIN ADC-200 FUEL/AIR DATA COMPUTER	MKE		RECOMMENDED	MTH 08-Dec-1999 HRS 758		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 525-34-39 34SB-39	GNS-XLS SOFTWARE MOD 4 UPGRADE	MKE		RECOMMENDED	MTH 30-Sep-1999 HRS 719		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 525-34-41 R02 34SB-41 : 525R2	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION	MCO		OPTIONAL	MTH 05-May-2005 HRS 1769		-			Complete
MOC : COMPLIED WITH										
SB 525-34-46 34SB-46	UNIVERSAL AVIONICS FLAT PANEL CONTROL DISPLAY UNIT UPGRADE TO MOD 8	SHV		MANDATORY	MTH 18-Dec-2002 HRS 1562		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SB 525-34-61 34SB-61	MST-67A TRANSPONDER INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 525-34-62 R01 34SB-62 : 525R1	GARMIN RADIO INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 525-34-84 R03	NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES			OPTIONAL			-			
MOC :										
ASL 525-34-13 34SLA13	FLAT PANEL CONTROL DISPLAY UNIT INVERTER CIRCUITRY INTEGRITY TEST	SHU		MANDATORY	MTH 03-Dec-2001 HRS 1213		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 525-34-08 34SL-08	TRANSMITTAL OF BFGOODRICH ALERT SERVICE BULLETIN 78A	FCM		MANDATORY	MTH 01-Feb-1999 HRS 601		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SL 525-34-09 34SL-09	TRANSMITTAL OF BF GOODRICH ALERT SERVICE BULLETIN #79	MKE		MANDATORY	MTH 30-Sep-1999 HRS 719		A/R			Complete
MOC : COMPLIED WITH										
SL 525-34-10 34SL-10	GNS-XLS FMS MOD 7 SFTWRE UPGR	SHV		RECOMMENDED	MTH 18-Dec-2002 HRS 1562		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SL 525-34-14 R01 34SL-14 : 525R1	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN IN 182A-16 RADAR INDICATOR	MIV		RECOMMENDED	MTH		150			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SLA 525-34-04 34SLA04	KLN89B,KLN90B & KLN900 GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS	MKE		MANDATORY	MTH 07-Aug-1997 HRS 294		-			Complete
MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KOBI		MANDATORY	MTH 10-Jun-2016 DAYS 2574.5 HRS 2183 LDG 1367.2 ACH		-			N/A
MOC : NOT APPLICABLE - N/A BY INSTALLED P/N										
SL 525-35-02 35SL-02	PORTABLE OXYGEN CYLINDER MASK INSPECTION/REPLACEMENT	SHV		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL 525-35-05	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL 525-35-06 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 525-35-06 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KTTN		MANDATORY	MTH 03-May-2013 HRS 2508.6 LDG 2127		-			N/A
MOC : NOT APPLICABLE - C/W SL525-35-06 CAPTAIN AND CO-PILOTS MASK ARE NOT AFFECTED DUE TO PART# AND SERIAL#.CAPTAIN PN: MC-15-109 , SN: 119233CO-PILOTS PN: MC10-16-101 , SN: 98430										
SB 525-36-04 R01 36SB-04 : 525R1	PRECOOLER IMPROVEMENT	KTTN		DISCRETIONARY	MTH 01-Feb-2018 HRS 2605 LDG 2215		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525-36-04 ON RIGHT PRECOOLER ONLY. LEFT PRECOOLER REPLACED ON 08AUG12 2471.3 HRS, 2105 CYC.										
SB 525-36-04 R02	PRECOOLER IMPROVEMENT	KTTN		DISCRETIONARY	MTH 01-Feb-2018 HRS 2605 LDG 2215		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525-36-04 ON RIGHT PRECOOLER ONLY. LEFT PRECOOLER REPLACED ON 08AUG12 2471.3 HRS, 2105 CYC.										
SB 525-36-04 R03	PNEUMATIC - PRECOOLER IMPROVEMENT	KTTN		DISCRETIONARY	MTH 01-Feb-2018 HRS 2605 LDG 2215		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525-36-04 ON RIGHT PRECOOLER ONLY. LEFT PRECOOLER REPLACED ON 08AUG12 2471.3 HRS, 2105 CYC.										
COM MC 525-008	LIFE LIMITED PRECOOLERS						-			
MOC :										
SL 525-36-01 R01 LEFT 36SL-01 : L	PRECOOLER INSPECTION MODEL 525	MIV		RECOMMENDED	MTH 26-Nov-2007 HRS 2114		-			Complete
MOC : COMPLIED WITH										
SL 525-36-01 R01 RIGHT 36SL-01 : R	PRECOOLER INSPECTION	MIV		RECOMMENDED	MTH 26-Nov-2007 HRS 2114		-			Complete
MOC : COMPLIED WITH										
SB 525-52-05 R01 52SB-05 : 525R1	DOOR SEAL VALVE REPLACEMENT			OPTIONAL	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-52-07 52SB-07	TAILCONE BAGGAGE DOOR UPPER DOOR LATCH DRAIN OPTIONAL			MTH			-			
MOC :										
SB 525-52-08 R01 52SB-08 : 525R1	IMPROVEMENT FOR THE CABIN ENTRY STEPS OPTIONAL			MTH			A/R			
MOC :										
SB 525-52-09 R01	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION OPTIONAL						A/R			
MOC :										
ASL 525-52-01 52SLA01	EMERGENCY DOOR INSPECTION SWF			MANDATORY	MTH 14-May-2008 HRS 2155		A/R			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.										
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION KTTN			MANDATORY	MTH 30-Sep-2013 HRS 2526.8 LDG 2142		-			Complete
MOC : COMPLIED WITH - INSPECTED AND LUBED EMERGENCY EXIT PER INSTRUCTIONS OUTLINED IN CIL-52-01. NO DEFECTS NOTED.										
SL CIL-52-02	DOORS - EMERGENCY EXIT DOOR INSPECTION INFORMATIONAL						-			
MOC :										
SL CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION KTTN			MANDATORY	MTH 19-Mar-2021 HRS 2641.8 LDG 2252		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH EMERGENCY ESCAPE HATCH INSPECTION, NO DEFECTS NOTED I.A.W. CIL-52-03 SERVICE LETTER.										
SB 525-53-06	AFT ENGINE BEAM RIVET INSPECTION/INSTALLATION TTN			RECOMMENDED	MTH 19-Jul-2011 HRS 2409.8 LDG 2057		-			Complete
MOC : COMPLIED WITH										
SB 525-53-07 R02 53SB-07 : 525R2	AFT BAGGAGE SECTION SKI OPTION INSTALLATION OPTIONAL			MTH			-			
MOC :										
SB 525-53-10 R01 53SB-10 : 525R1	TAILCONE AIR CONDITIONING INLET INSTALLATION MKE			RECOMMENDED	MTH 19-Nov-1998 HRS 563		A/R			Complete
MOC : COMPLIED WITH										
SB 525-53-10 R02 53SB-10 : 525R2	TAILCONE AIR CONDITIONING INLET INSTALLATION SHV			RECOMMENDED	MTH		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 525-53-10 53SB-10	TAILCONE AIR CONDITIONING INLET INSTALLATION MKE			RECOMMENDED	MTH 10-May-1998 HRS 411		A/R			Complete
MOC : COMPLIED WITH										
SB 525-53-13 53SB-13	RADOME LIGHTING DIVERTER STRIP ELECTRICAL RESISTANCE INSPECTION MKE			MANDATORY	MTH 17-Jun-1997 HRS 271		-			Complete
MOC : COMPLIED WITH										
SB 525-53-15 R01 53SB-15 : 525R1	TAILCONE STRINGER RIVET INSTALLATION ICT			RECOMMENDED	MTH 24-May-1999 HRS 644		-			Complete
MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-53-16 53SB-16	AFT FAIRING DOUBLER MODIFICATION	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		-			Complete
MOC : COMPLIED WITH										
SB 525-53-17 R01 53SB-17 : 525R1	NOSE WHEEL STEER BRACKET REPLACEMENT	SHV		MANDATORY	MTH 01-Nov-2001 HRS 1183		A/R			Complete
MOC : COMPLIED WITH										
SB 525-53-17 53SB-17	NOSE WHEEL STEERING BRACKET REPLACEMENT	MKE		MANDATORY	MTH 08-Dec-1999 HRS 758		A/R			Complete
MOC : COMPLIED WITH										
SB 525-53-18 R01 53SB-18 : 525R1	RIVET INSPECTION/INSTALLATION	DAL		RECOMMENDED	MTH 10-May-2002 HRS 1367		-			Complete
MOC : COMPLIED WITH										
SB 525-53-20 53SB-20	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S)	SWF		MANDATORY	MTH 01-Jun-2007 HRS 2037		A/R			Complete
MOC : COMPLIED WITH										
ASL 525-53-03 53SLA03	RELIEF TUBE CORROSION	MIV		MANDATORY	MTH 30-Nov-2006 HRS 1979		A/R			Complete
MOC : COMPLIED WITH										
ASL 525-53-04 R01 53SLA04 : 525R1	RELIEF TUBE CORROSION INSPECTION	SWF		MANDATORY	MTH 01-Jun-2007 HRS 2037		A/R			Complete
MOC : COMPLIED WITH										
ASL 525-53-04 R06 53SLA04 : 525R6	RELIEF TUBE CORROSION INSPECTION	MIV		MANDATORY	MTH 18-Jul-2008 HRS 2169		A/R			Complete
MOC : COMPLIED WITH										
SL 525-53-05 53SL-05	INTERCOSTAL DRAINAGE PATH INSPECTION	KTTN		RECOMMENDED	MTH 07-Oct-2014 HRS 2545.9 LDG 2166		-			Complete
MOC : COMPLIED WITH - INSPECTED AND FOUND NO RIVET INSTALLED AND DRAIN OPEN. NO FURTHER ACTION AT THIS TIME PER SL INSTRUCTIONS.										
SL 525-53-06	UPPER TAILCONE SKIN INSPECTION	OBI		MANDATORY	MTH 22-Oct-2011 HRS 2421.1 LDG 2068		A/R			Complete
MOC : COMPLIED WITH - PCW BY JET ESAT AVIATION										
SL 525-53-07	ACCESS PANEL DRAIN HOLE INSTALLATION	RDG		RECOMMENDED	MTH 21-Dec-2023 HRS 2875 LDG 2427		-			Complete
MOC : COMPLIED WITH - **** ITEM # 13367-5 PERFORM SERVICE LETTER SL525-53-07 ****DISCREPANCY: PERFORM SERVICE LETTER SL525-53-07 ACTION: PERFORMED SERVICE LETTER SL525-53-07, CONFIRMED PRESENCE OF DRAIN HOLES IN DRY BAY PANEL 192B. NO FURTHER ACTION NEEDED.										
SB 525-54-03 R01 54SB-03 : 525R1	ENGINE INLET ASSEMBLY DOUBLER/GUSSETT INSTALLATION	MKE		RECOMMENDED	MTH 11-Oct-1996 HRS 148		A/R			Complete
MOC : COMPLIED WITH										
SB 525-54-04 R02	NACELLES/PYLONS - FIREWALL BOX REPAIR			RECOMMENDED			A/R			
MOC :										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-54-04	FIREWALL BOX REPAIR			RECOMMENDED	MTH 19-Mar-2021 HRS 2641.8 LDG 2252		-			Complete
MOC : COMPLIED WITH - C/W L/H PYLON FIREWALL MODIFICATION IAW SB525-54-04 ACCOMPLISHMENT INSTRUCTIONS AND ENGINEERING DWG 6391049. ENGINE REMOVAL AND INSTALLATION PERFORMED IAW CE525 M.M. CHAPTER 71-01-00. ENGINE RUN AND LEAK CHECK GOOD										
SB 525-54-05	NACELLES/PYLONS - MID FIREWALL FASTENER INSPECTION	OBI		MANDATORY	MTH 22-Oct-2011 HRS 2421.1 LDG 2068		A/R			Complete
MOC : COMPLIED WITH										
SB 525-56-02 56SB-02	COCKPIT SIDE WINDOW INSPECTION			MANDATORY	MTH 31-May-1996		A/R			Complete
MOC : COMPLIED WITH										
SB 525-57-05 57SB-05	MAIN LANDING GEAR WHEEL WELL MODIFICATION			RECOMMENDED	MTH 31-May-1996		A/R			Complete
MOC : COMPLIED WITH										
SB 525-57-08 57SB-08	POLISHED LEADING EDGE WING TIP			OPTIONAL	MTH		-			
MOC :										
SB 525-57-09 R01 57SB-09 : 525R1	LEADING EDGE TUBE REPLACEMENT			OPTIONAL	MTH		-			
MOC :										
SB 525-57-10 R01 57SB-10 : 525R1	SKID PLATE CAP ADDITION			RECOMMENDED	MTH 30-Sep-1999 HRS 719		-			Complete
MOC : COMPLIED WITH										
SB 525-57-10 57SB-10	SKID PLATE CAP ADDITION			RECOMMENDED	MTH 30-Sep-1999 HRS 719		-			Complete
MOC : COMPLIED WITH										
SB 525-57-13 57SB-13	LOWER WING SKIN PANEL MODIFICATION			RECOMMENDED	MTH 10-May-2002 HRS 1367		-			Complete
MOC : COMPLIED WITH										
SL 525-57-02 57SL-02	ACCESS DOOR DRAINAGE IMPROVEMENT			RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL WI-70-1008-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-70-1008-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-70-1008 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-70-1008 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-70-1010-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-70-1010-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-70-1010 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-70-1010 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-70-1011-CN E1	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED						
	MOC :									
SL WI-70-1011-CN E2	CANCELLED - STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED						
	MOC :									
SL WI-70-1011 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-70-1011 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SB FJ44-71-006-CN E1	CANCELLED - ENGINE - COMPRESSOR SECTION INSPECTION (CSI) - NOTIFICATION			CANCELLED						
	MOC :									
SB FJ44-71-006-CN E2	CANCELLED - ENGINE - COMPRESSOR SECTION INSPECTION (CSI) - NOTIFICATION			CANCELLED						
	MOC :									
SL 44-71-153 E1	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING									
	MOC :									
SL 44-71-153 E2	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING									
	MOC :									
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED						
	MOC :									
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED						
	MOC :									
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL									
	MOC :									
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL									
	MOC :									
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED						
	MOC :									
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL			CANCELLED						
	MOC :									
SL WI-71-1606 E1	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-71-1606 E2	POWER PLANT - IDLE SPEED AND LEAK CHECK RUN - REVISION TO LINE MAINTENANCE MANUAL									
	MOC :									
SB 525-72-01 72SB-01	ENGINE BOLT GREEN DYE INSPECTION/REPLACEMENT			MTH 06-Mar-1997 MKE RECOMMENDED HRS 222			A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-72-06 72SL-06	TRANSMITTAL OF WILLIAMS ROLLS SERVICE LETTER SL44-72-72 GEARBOX CARBON SEALS-MAINTENANCE REQUIREMENTS	MKE		MANDATORY	MTH 19-Nov-1998 HRS 563		-			Complete
MOC : COMPLIED WITH										
SL 525-72-07 72SL-07	TRANSMITTAL OF WILLIAMS ROLLS SB FJ44-A72-38, ENGINE - HP TURBINE DISK - REVISE APPROVED SERVICE LIFE	MIV		INFORMATIONAL	MTH 11-Aug-2005 HRS 1795		-			Complete
MOC : COMPLIED WITH										
SL 525-72-09 72SL-09	TRANSMITTAL OF WILLIAMS ROLLS SERVICE BULLETIN FJ44-72-052, ENGINE-IP COMPRESSOR ROTOR-REPLACE	SHV		MANDATORY	MTH 11-Nov-2002 HRS 1509		-			Complete
MOC : COMPLIED WITH										
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-72-014 R01-CN E1	COMPLETED - FCW - ENGINE - FRONT INNER BYPASS DUCT FAIRING - INSPECTION AND REPLACEMENT			RECOMMENDED			-			
MOC :										
SB FJ44-72-014 R01-CN E2	COMPLETED - FCW - ENGINE - FRONT INNER BYPASS DUCT FAIRING - INSPECTION AND REPLACEMENT			RECOMMENDED			-			
MOC :										
SB FJ44-72-022 R01 E1	REPAIR RIGHT-HAND SERVICE ADAPTER INSERT OF FRONT BYPASS DUCT			RECOMMENDED			-			
MOC :										
SB FJ44-72-022 R01 E2	REPAIR RIGHT-HAND SERVICE ADAPTER INSERT OF FRONT BYPASS DUCT			RECOMMENDED			-			
MOC :										
SB FJ44-72-022 R02-CN E1	CANCELED - ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT HAND SERVICE ADAPTER INSERT			CANCELLED			-			
MOC :										
SB FJ44-72-022 R02-CN E2	CANCELED - ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT HAND SERVICE ADAPTER INSERT			CANCELLED			-			
MOC :										
SB FJ44-72-022 R02 E1	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT			RECOMMENDED			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-022 R02 E2	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT			RECOMMENDED			-			
MOC :										
SB FJ44-72-027-CNFCW E1	ENGINE - GEARBOX ASSY - INSPECT OF BREATHER PORT MAGNETIC CARBON SEAL & REWORK OF BREATHER TUBE			RECOMMENDED			-			
MOC :										
SB FJ44-72-027-CNFCW E2	ENGINE - GEARBOX ASSY - INSPECT OF BREATHER PORT MAGNETIC CARBON SEAL & REWORK OF BREATHER TUBE			RECOMMENDED			-			
MOC :										
SB FJ44-72-029 R03 E1	1ST LP TURBINE NOZZLE ASSEMBLY-ADD OIL SCAVENGE SLOT			RECOMMENDED			-			
MOC :										
SB FJ44-72-034 R06 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE CARBON SEAL MAGNET KEEPERS			MANDATORY	HRS		DUE DUE		4985	1983.1
MOC :										
SB FJ44-72-034 R06 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE CARBON SEAL MAGNET KEEPERS			MANDATORY	HRS		DUE DUE		4985	1983.1
MOC :										
SB FJ44-72-035 R03 E1	NO. 1 CARBON SEAL AND NO.1 CARBON SEAL RUNNER - REPLACE			RECOMMENDED	HRS		DUE DUE		4985	1983.1
MOC :										
SB FJ44-72-035 R03 E2	NO. 1 CARBON SEAL AND NO.1 CARBON SEAL RUNNER - REPLACE			RECOMMENDED	HRS		DUE DUE		4985	1983.1
MOC :										
SB FJ44-72-039 R03 E1	ENGINE HP COMPRESSOR ROTOR REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-72-039 R03 E2	ENGINE HP COMPRESSOR ROTOR REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R04)			RECOMMENDED			-			
MOC :										
SB FJ44-72-039 R04 E1	HP COMPRESSOR ROTOR - REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-72-039 R04 E2	HP COMPRESSOR ROTOR - REWORK BACKWALL (SUPERSEDED BY FJ44-72-039 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-72-039 R05 E1	HP COMPRESSOR ROTOR - REWORK BACKWALL			RECOMMENDED	MTH HRS		DUE DUE DUE		4985	1983.1
MOC :										
SB FJ44-72-039 R05 E2	HP COMPRESSOR ROTOR - REWORK BACKWALL			RECOMMENDED	MTH HRS		DUE DUE DUE		4985	1983.1
MOC :										
SB FJ44-72-041 R04 E1	ENGINE & HP TURBINE & REPLACEMENT OF BLADES AND BLADE RETAINERS / RE-IDENTIFICATION OF HP TURBINE DISKS AND ROTOR ASSEMBLIES			RECOMMENDED			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-041 R04 E2	ENGINE 6 HP TURBINE 6 REPLACEMENT OF BLADES AND BLADE RETAINERS / RE-IDENTIFICATION OF HP TURBINE DISKS AND ROTOR ASSEMBLIES RECOMMENDED				-			
	MOC :							
SB FJ44-72-051 R03 E1	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04) RECOMMENDED				-			
	MOC :							
SB FJ44-72-051 R03 E2	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04) RECOMMENDED				-			
	MOC :							
SB FJ44-72-051 R04 E1	REWORK NAMEPLATE RECOMMENDED				-			
	MOC :							
SB FJ44-72-051 R04 E2	REWORK NAMEPLATE RECOMMENDED				-			
	MOC :							
SB FJ44-72-051 R05 E1	NAMEPLATE - REWORK RECOMMENDED	MTH HRS			MPI MPI MPI		4985	1983.1
	MOC :							
SB FJ44-72-051 R05 E2	NAMEPLATE - REWORK RECOMMENDED	MTH HRS			MPI MPI MPI		4985	1983.1
	MOC :							
SB FJ44-72-054 R04 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05) RECOMMENDED				-			
	MOC :							
SB FJ44-72-054 R04 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05) RECOMMENDED				-			
	MOC :							
SB FJ44-72-054 R05 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06) RECOMMENDED				-			
	MOC :							
SB FJ44-72-054 R05 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06) RECOMMENDED				-			
	MOC :							
SB FJ44-72-054 R06 E1	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER RECOMMENDED				-			
	MOC :							
SB FJ44-72-054 R06 E2	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER RECOMMENDED				-			
	MOC :							
SB FJ44-72-054 R07 E1	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER RECOMMENDED				-			
	MOC :							
SB FJ44-72-054 R07 E2	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER RECOMMENDED				-			
	MOC :							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-076 R01 E1	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 R01 E2	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 R02 E1	IP COMPRESSOR STATOR - REWORK			OPTIONAL	MTH HRS		CSI CSI CSI		4985	1983.1
	MOC :									
SB FJ44-72-076 R02 E2	IP COMPRESSOR STATOR - REWORK			OPTIONAL	MTH HRS		CSI CSI CSI		4985	1983.1
	MOC :									
SB FJ44-72-076 E1	REWORK - ENGINE- COMPRESSOR STATOR (SUPERSEDED BY FJ44-72-076 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 E2	REWORK - ENGINE- COMPRESSOR STATOR (SUPERSEDED BY FJ44-72-076 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-72-079 R02 E1	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
	MOC :									
SB FJ44-72-079 R02 E2	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
	MOC :									
SB FJ44-72-083 R04 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R05)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R04 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R05)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R05 E1	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R05 E2	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R06 E1	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL	MTH HRS		DUE DUE DUE		4985	1983.1
	MOC :									
SB FJ44-72-083 R06 E2	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL	MTH HRS		DUE DUE DUE		4985	1983.1
	MOC :									
SB FJ44-72-087 R04 E1	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R05)			OPTIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-087 R04 E2	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R05) OPTIONAL						-			
	MOC :									
SB FJ44-72-087 R05 E1	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1011 R01) OPTIONAL MTH						-			
	MOC :									
SB FJ44-72-087 R05 E2	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1011 R01) OPTIONAL MTH						-			
	MOC :									
SB FJ44-72-099 R01 E1	ENGINE - 6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R02) RECOMMENDED						-			
	MOC :									
SB FJ44-72-099 R01 E2	ENGINE - 6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R02) RECOMMENDED						-			
	MOC :									
SB FJ44-72-099 R02 E1	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R03) RECOMMENDED						-			
	MOC :									
SB FJ44-72-099 R02 E2	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R03) RECOMMENDED						-			
	MOC :									
SB FJ44-72-099 R03 E1	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R04) RECOMMENDED						-			
	MOC :									
SB FJ44-72-099 R03 E2	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R04) RECOMMENDED						-			
	MOC :									
SB FJ44-72-099 R04 E1	6 BOLT SPINNER - REPLACE RECOMMENDED MTH						-			
	MOC :									
SB FJ44-72-099 R04 E2	6 BOLT SPINNER - REPLACE RECOMMENDED MTH						-			
	MOC :									
SB FJ44-72-108 R01-CN E1	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) CANCELLED						-			
	MOC :									
SB FJ44-72-108 R01-CN E2	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE) CANCELLED						-			
	MOC :									
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01) RECOMMENDED						-			
	MOC :									
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01) RECOMMENDED						-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		DUE DUE		4985	1983.1
	MOC :									
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		DUE DUE		4985	1983.1
	MOC :									
SB FJ44-72-111 R01 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-111 R01 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-111 R02 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION			RECOMMENDED	HRS		-		4985	1983.1
	MOC :									
SB FJ44-72-111 R02 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION			RECOMMENDED	HRS		-		4985	1983.1
	MOC :									
SB FJ44-72-111 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-111 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-112 E1	CANCELLED - ENGINE - ROUTINE PERIODIC INSPECTION - TIME EXTENSION			CANCELLED			-			
	MOC :									
SB FJ44-72-112 E2	CANCELLED - ENGINE - ROUTINE PERIODIC INSPECTION - TIME EXTENSION			CANCELLED			-			
	MOC :									
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-129 R01-CN E1	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									
SB FJ44-72-129 R01-CN E2	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02) RECOMMENDED				-			
MOC :								
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02) RECOMMENDED				-			
MOC :								
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION RECOMMENDED	MTH HRS			DUE DUE DUE		4985	1983.1
MOC :								
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION RECOMMENDED	MTH HRS			DUE DUE DUE		4985	1983.1
MOC :								
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01) RECOMMENDED				-			
MOC :								
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01) RECOMMENDED				-			
MOC :								
SB FJ44-72-144 E1	DIFFUSER CASE ASSEMBLY - REPLACE / REWORK RECOMMENDED	MTH HRS			DUE DUE DUE		4985	1983.1
MOC :								
SB FJ44-72-144 E2	DIFFUSER CASE ASSEMBLY - REPLACE / REWORK RECOMMENDED	MTH HRS			DUE DUE DUE		4985	1983.1
MOC :								
SB FJ44-72-145 R03 E1	GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY MTH				-			
MOC :								
SB FJ44-72-145 R03 E2	GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY MTH				-			
MOC :								
SB FJ44-72-147 R01 E1	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED				-			
MOC :								
SB FJ44-72-147 R01 E2	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED				-			
MOC :								
SB FJ44-72-147 R02 E1	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED	MTH HRS			MPI MPI MPI		4985	1983.1
MOC :								
SB FJ44-72-147 R02 E2	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED	MTH HRS			MPI MPI MPI		4985	1983.1
MOC :								
SB FJ44-72-147 E1	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED				-			
MOC :								
SB FJ44-72-147 E2	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED				-			
MOC :								

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-149 R01 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-149 R01 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-149 R02 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED MTH			-			
	MOC :									
SB FJ44-72-149 R02 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED MTH			-			
	MOC :									
SB FJ44-72-149 R03 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED HRS			MPI MPI		4985	1983.1
	MOC :									
SB FJ44-72-149 R03 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED HRS			MPI MPI		4985	1983.1
	MOC :									
SB FJ44-72-149 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-149 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-16-CN E1	CANCELLED-REAR BYPASS DUCT AND TAILPIPE-APPLY			CANCELLED			-			
	MOC :									
SB FJ44-72-16-CN E2	CANCELLED-REAR BYPASS DUCT AND TAILPIPE-APPLY			CANCELLED			-			
	MOC :									
SL 44-72-325 R06 E1	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R06 E2	ENGINE - 1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R07 E1	1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
SL 44-72-325 R07 E2	1ST LP TURBINE DISK - INSPECTION						-			
	MOC :									
PSID WI-05-1000 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
PSID WI-05-1000 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task # City Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
PSID WI-05-1000 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION MOC :	INFORMATIONAL			-			
PSID WI-72-1022 R01 E1	OPERATING IN AREAS OF SMOKE MOC :				-			
PSID WI-72-1022 R01 E2	OPERATING IN AREAS OF SMOKE MOC :				-			
PSID WI-72-1026 E1	FAN CASE - RUB INDICATIONS MOC :				-			
PSID WI-72-1026 E2	FAN CASE - RUB INDICATIONS MOC :				-			
SB WI-72-1011 R01 E1	BLEED VALVE ASSEMBLY - UPGRADE MOC :	OPTIONAL			-			
SB WI-72-1011 R01 E2	BLEED VALVE ASSEMBLY - UPGRADE MOC :	OPTIONAL			-			
SB WI-72-1011 E1	BLEED VALVE ASSEMBLY - UPGRADE MOC :	OPTIONAL			-			
SB WI-72-1011 E2	BLEED VALVE ASSEMBLY - UPGRADE MOC :	OPTIONAL			-			
SB WI-72-1037 R01 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :	RECOMMENDED			-			
SB WI-72-1037 R01 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :	RECOMMENDED			-			
SB WI-72-1037 R02 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :	RECOMMENDED	MTH		-			
SB WI-72-1037 R02 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :	RECOMMENDED	MTH		-			
SB WI-72-1037 R03 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :				-			
SB WI-72-1037 R03 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :				-			
SB WI-72-1037 R04 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :				-			
SB WI-72-1037 R04 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :				-			
SB WI-72-1037 R05 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE MOC :	RECOMMENDED	MTH		CSI CSI			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-72-1037 E2	R05 ACCESSORY DRIVE TOWERSHAFT - REPLACE			RECOMMENDED	MTH		CSI CSI			
MOC :										
SB WI-72-1041 E1	R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-72-1041 E2	R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-72-1041 E1	R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED	MTH		-			
MOC :										
SB WI-72-1041 E2	R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED	MTH		-			
MOC :										
SB WI-72-1041 E1	R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE						-			
MOC :										
SB WI-72-1041 E2	R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE						-			
MOC :										
SB WI-72-1041 E1	R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			MPI			
MOC :										
SB WI-72-1041 E2	R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			MPI			
MOC :										
SB WI-72-1041 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-72-1041 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-72-1044 E1	R01 BALANCE PISTON - REPLACE						-			
MOC :										
SB WI-72-1044 E2	R01 BALANCE PISTON - REPLACE						-			
MOC :										
SB WI-72-1044 E1	R02 BALANCE PISTON - REPLACE						-			
MOC :										
SB WI-72-1044 E2	R02 BALANCE PISTON - REPLACE						-			
MOC :										
SB WI-72-1044 E1	R03 BALANCE PISTON - REPLACE			RECOMMENDED			CSI			
MOC :										
SB WI-72-1044 E2	R03 BALANCE PISTON - REPLACE			RECOMMENDED			CSI			
MOC :										
SB WI-72-1044 E1	ENGINE - BALANCE PISTON - REPLACE			RECOMMENDED	MTH		-			
MOC :										
SB WI-72-1044 E2	ENGINE - BALANCE PISTON - REPLACE			RECOMMENDED	MTH		-			
MOC :										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-72-1068 R01 6 BOLT SPINNER - REPLACE E1				RECOMMENDED	MTH HRS		RPI 400 RPI		3297.38	295.48
MOC :										
SB WI-72-1068 R01 6 BOLT SPINNER - REPLACE E2				RECOMMENDED	MTH HRS		RPI 400 RPI		3297.38	295.48
MOC :										
SB WI-72-1068 E1	6 BOLT SPINNER - REPLACE			RECOMMENDED	MTH		-			
MOC :										
SB WI-72-1068 E2	6 BOLT SPINNER - REPLACE			RECOMMENDED	MTH		-			
MOC :										
SL WI-72-1080 E1	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL						-			
MOC :										
SL WI-72-1080 E2	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL						-			
MOC :										
SL WI-72-1128 E1	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-72-1128 E2	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-72-1132-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
MOC :										
SL WI-72-1132-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
MOC :										
SL WI-72-1132 E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-72-1132 E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-72-1140 E1	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
MOC :										
SL WI-72-1140 E2	INDUCTION HEATING - REVISION TO ENGINE MANUAL						-			
MOC :										
SL WI-72-1262-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
MOC :										
SL WI-72-1262-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL CANCELLED						-			
MOC :										
SL WI-72-1262 E1	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-72-1262 E2	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-72-1332-CN E1	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS			CANCELLED			-			
MOC :										
SL WI-72-1332-CN E2	CANCELED - FAN ROTOR - INSPECTION/CHECK - REVISION TO LINE MAINTENANCE MANUALS			CANCELLED			-			
MOC :										
ASL 525-73-06 RT ENG 73ASL06 : E2**R	TRANSMITTAL OF WILLIAMS-ROLLS ALERT SERVICE BULLETIN FJ44-A73-12 ENGINE FUEL CONTROL UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY - REPLACE	MKE		RECOMMENDED	MTH 25-Jan-2000 HRS 785		A/R			Complete
MOC : COMPLIED WITH										
ASL 525-73-06L 73ASL06 : E1**L	TRANSMITTAL OF WILLIAMS-ROLLS ALERT SERVICE BULLETIN FJ44-A73-12 ENGINE FUEL CONTROL UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY - REPLACE	MKE		RECOMMENDED	MTH 25-Jan-2000 HRS 785		-			Complete
MOC : COMPLIED WITH										
SB FJ44-73-062 R01 E1	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE	KSWF		RECOMMENDED	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB FJ44-73-062 R01 FUEL FLOW TO OIL COOLER TUBE ASSEMBLY REPLACEMENT PER ACCOMPLISHMENT INSTRUCTIONS.										
SB FJ44-73-062 R01 E2	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE	KSWF		RECOMMENDED	MTH 19-Oct-2023 HRS 2837.6 LDG 2402		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB FJ44-73-062 R01 FUEL FLOW TO OIL COOLER TUBE ASSEMBLY REPLACEMENT PER ACCOMPLISHMENT INSTRUCTIONS.										
SB FJ44-73-062 E1	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-73-062 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-73-062 E2	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-73-062 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-73-9-CN E1	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)						-			
MOC :										
SB FJ44-73-9-CN E2	ENGINE FUEL AND CONTROL - FUEL CONTROL UNIT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)						-			
MOC :										
SB WI-73-1000 R01 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		-		4985	1983.1
MOC :										
SB WI-73-1000 R01 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		-		4985	1983.1
MOC :										
SB WI-73-1000 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-73-1000 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-74-1001 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	KSWF		MANDATORY	MTH 19-Oct-2023 HRS 2837.6 LDG 2364		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB WI-74-1001 IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT PER ACCOMPLISHMENT INSTRUCTIONS.										
SB WI-74-1001 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	KSWF		MANDATORY	MTH 19-Oct-2023 HRS 2837.6 LDG 2364		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB WI-74-1001 IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT PER ACCOMPLISHMENT INSTRUCTIONS.										
SB WI-75-1002 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1				RECOMMENDED			-			
MOC :										
SB WI-75-1002 R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2				RECOMMENDED			-			
MOC :										
SB WI-75-1002 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E1				RECOMMENDED	MTH			CSI		
MOC :										
SB WI-75-1002 R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE E2				RECOMMENDED	MTH			CSI		
MOC :										
SB WI-75-1002 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1002 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB 525-76-03 R01 76SB-03 : 525R1	ENGINE SYNCHRONIZER CONTROLLER REPLACEMENT			MTH 19-Nov-1998 HRS 563			A/R			Complete
MOC : COMPLIED WITH										
SB 525-76-04 R01 76SB-04 : 525R1	FORWARD THROTTLE CABLE REPLACEMENT			OPTIONAL	MTH		-			
MOC :										
SB 525-76-05 R01 76SB-05 : 525R1	ENGINE POWER CONTROL CABLE REPLACEMENT			OPTIONAL	MTH		-			
MOC :										
SB 525-76-06 76SB-06	SAFE FLIGHT N1 COMPUTER INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL									
	MOC :									
SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL									
	MOC :									
SB FJ44-77-008 R03 E1	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS RECOMMENDED									
	MOC :									
SB FJ44-77-008 R03 E2	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS RECOMMENDED									
	MOC :									
SB 525-78-04 R01 78SB-04 : 525R1	EXHAUST NOZZLE WELD INSPECTION/REPAIR				MTH 07-Aug-1997		-			Complete
	MKE			RECOMMENDED	HRS 294					
	MOC : COMPLIED WITH									
SB 525-78-05 R01 78SB-05 : 525R1	THRUST ATTENUATOR PADDLE BELLCRANK IMPROVEMENT				MTH 24-May-1999		-			Complete
	ICT			RECOMMENDED	HRS 644					
	MOC : COMPLIED WITH									
SB 525-79-01 79SB-01	OIL PRESSURE TRANSMITTER				MTH 19-Nov-1998		-			Complete
	MKE			RECOMMENDED	HRS 563					
	MOC : COMPLIED WITH - NOT APPLICABLE									
SL 525-79-02 79SL-02	TRANSMITTAL OF WILLIAMS/ROLLS SERVICE LETTER SL44-79-5, INCORPORATION OF 3-MICRON OIL FILTER (56066)									
				INFORMATIONAL	MTH		-			
	MOC :									
SB FJ44-79-011 R01 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)									
				MANDATORY			-			
	MOC :									
SB FJ44-79-011 R01 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)									
				MANDATORY			-			
	MOC :									
SB FJ44-79-011 R02 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03)									
				MANDATORY			-			
	MOC :									
SB FJ44-79-011 R02 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03)									
				MANDATORY			-			
	MOC :									
SB FJ44-79-011 R03 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)									
				MANDATORY			-			
	MOC :									
SB FJ44-79-011 R03 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)									
				MANDATORY			-			
	MOC :									
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE									
				MANDATORY			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R05 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
MOC :										
SB FJ44-79-011 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
MOC :										
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB 525-80-02 R02 80SB-02 : 525R2	AIRCRAFT PARTS CORPORATION (APC) PART NUMBER 9912125-2 STARTER GENERATOR INSPECTION/REPLACEMENT	MKE		RECOMMENDED	MTH 10-May-1998 HRS 411		A/R			Complete
MOC : COMPLIED WITH										
SB 525-80-02 80SB-02	AIRCRAFT PARTS CORPORATION (APC) PART NUMBER 9912125-2 STARTER GENERATOR INSPECTION/REPLACEMENT	MKE		RECOMMENDED	MTH 27-Jan-1998 HRS 387		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1998-25-02 34AD-02	APPLIANCE AD - BFGOODRICH SKYWATCH FCM			SKY497 MANDATORY	MTH 01-Feb-1999 HRS 601		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
FAA 2013-08-05 PARA (G)	INSPECTION AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM A/C COMPRESSOR HOUR METER	KTTN		MANDATORY	DAYS 03-May-2013 HRS 2508.6 LDG 2127		-			Complete
MOC : COMPLIED WITH - COMPRESSOR DRIVE MOTOR WAS REPLACED AT FREON HRS 1242 NEXT INSPECTION DUE IN 500 HRS AT 1742.										
FAA 2013-08-05 PARA (H)	REPLACE AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES	KTTN		MANDATORY	MTH 03-May-2013 HRS 2508.6 LDG 2127 ACH 1311.7		500		1811.7	Complete 238.6
MOC : COMPLIED WITH										
FAA 2013-08-05 PARA (I)	DEACTIVATION AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM OF THE AIR CONDITIONING			MANDATORY			A/R			
MOC :										
FAA 2013-08-05 PARA (J)	RETURN AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM OF REPLACED PARTS AND REPORTING REQUIREMENT			MANDATORY	DAYS		30			
MOC :										
FAA 2013-08-05	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM	KTTN		MANDATORY	MTH 03-May-2013 HRS 2508.6 LDG 2127		-			Complete
MOC : COMPLIED WITH - COMPRESSOR MOTOR WAS REPLACED AT FREON HRS 1242 AND DOES NOT NEED TO BE CHECKED UNTIL 500HRS AT 1742.										
FAA 1998-25-10 25AD-01	APPLIANCE AD - AIRCRAFT BELTS INC FCM			MANDATORY	MTH 01-Feb-1999 HRS 601		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS			MANDATORY			-			
MOC :										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT			MANDATORY	MTH		-			
MOC :										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KTTN			MTH 01-Feb-2018 HRS 2605 LDG 2215		-			N/A
MOC : NOT APPLICABLE										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KTTN		MANDATORY	MTH 01-Feb-2018 HRS 2605 LDG 2215		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KTTN		MANDATORY	MTH 01-Feb-2018 HRS 2605 LDG 2215		-			N/A
MOC : NOT APPLICABLE - AMERI-KING CORP ELT NOT INSTALLED ON THIS AIRCRAFT I/A/W AD 2017-16-01										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	CHA		MANDATORY	MTH 07-Apr-2022 HRS 2642.8 LDG 2253		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	CHA		MANDATORY	MTH 07-Apr-2022 HRS 2642.8 LDG 2253		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	CHA		MANDATORY	MTH 07-Apr-2022 HRS 2642.8 LDG 2253		-			N/A
MOC : NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	CHA		MANDATORY	MTH 07-Apr-2022 HRS 2642.8 LDG 2253		-			N/A
MOC : NOT APPLICABLE - AD NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED IN AIRCRAFT .										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		6		07-Sep-2025	4 m 7 d
MOC :										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		12		07-Mar-2026	10 m 7 d
MOC :										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
MOC :										
FAA 2005-17-11 26AD-01	PREVENT INCORRECT INSTALLATION OF WIRES	MIV		MANDATORY	MTH 30-Aug-2005 HRS 1801		A/R			Complete
MOC : COMPLIED WITH										

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2003-21-07 27AD-01	ELECTRIC PITCH TRIM FAILURE CAUSING RUN AWAY PITCH TRIM CONDITION, LARGE PITCH MISTRIM AND EXCESSIVE CONTROL FORCES (SUPERSEDED BY FAA AD 2004-14-20)	DAL		SUPERSEDED	MTH 06-Apr-2004 HRS 1687		N/A			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.										
FAA 2004-14-20 27AD-02	CORRECT SINGLE POINT FAILURE IN THE ELECTRIC PITCH TRIM SYSTEM	MIV		MANDATORY	MTH 31-Jul-2006 HRS 1945		A/R			Complete
MOC : COMPLIED WITH										
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06)			MANDATORY			-			
MOC :										
FAA 2024-15-09	GUST LOCK/DAMPER SYSTEM - INSTALL PLACARDS ON THE LEFT-HAND INBOARD EDGE OF THE TAMARACK ACTIVE CAMBER SURFACE (TACS) AND REVISING THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE			MANDATORY	MTH		-			
MOC :										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	CHA		MANDATORY	MTH 07-Apr-2022 HRS 2642.8 LDG 2253		-			N/A
MOC : NOT APPLICABLE - N/A TO AIRCRAFT CATEGORY.										
FAA 1997-01-02 32AD-01	MLG SELF LUBE BEARING FOR S/N 525-0001 THROUGH 525-0153	MKE		MANDATORY	MTH 17-Jun-1997 HRS 271		A/R			Complete
MOC : COMPLIED WITH										
FAA 1997-05-03 34AD-01	APPLIANCE AD - ALLIEDSIGNAL GNS-XLS & GNS-XL	MKE		SUPERSEDED	MTH 17-Jun-1997 HRS 271		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
FAA 2001-23-17 34AD-04	APPLIANCE AD - GARMIN GNS 430	SHV		MANDATORY	MTH 11-May-2002 HRS 1367		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2002-20-09 31AD-01	APPLIANCE AD - COLLINS AFD-3010 AFD UNITS	DAL		MANDATORY	MTH 06-Apr-2004 HRS 1687		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2003-13-08 34AD-05	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS	DAL		MANDATORY	MTH 06-Apr-2004 HRS 1687		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2004-08-15 34AD-06	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS	MCO		MANDATORY	MTH 23-Jul-2004 HRS 1729		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2006-16-18 34AD-12	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)	MIV		MANDATORY	MTH 24-Oct-2006 HRS 1968		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	KTTN		MANDATORY	MTH 30-Oct-2015 HRS 2561.6 LDG 2176		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A, (ACSS) EQUIPMENT NOT INSTALLED.										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
MOC :										
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY			-			
MOC :										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	KTTN		MANDATORY	MTH 30-Oct-2015 HRS 2561.6 LDG 2176		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A. AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 1999-08-21 35AD-01	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM	ICT		MANDATORY	MTH 24-May-1999 HRS 644		A/R			Complete
MOC : COMPLIED WITH										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES			MANDATORY	MTH 05-Jul-2022		-			Complete
MOC : COMPLIED WITH										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KOBI		MANDATORY	MTH 10-Jun-2016 DAYS 2574.5 HRS 2183 LDG 1367.2 ACH		-			N/A
MOC : NOT APPLICABLE - N/A BY INSTALLED P/N										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KOBI		MANDATORY	MTH 10-Jun-2016 DAYS 2574.5 HRS 2183 LDG 1367.2 ACH		-			N/A
MOC : NOT APPLICABLE - N/A BY INSTALLED P/N										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KOBI		MANDATORY	MTH 10-Jun-2016 DAYS 2574.5 HRS 2183 LDG 1367.2 ACH		-			N/A
MOC : NOT APPLICABLE - N/A BY INSTALLED P/N										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KOBI		MANDATORY	MTH 10-Jun-2016 DAYS 2574.5 HRS 2183 LDG 1367.2 ACH		-			N/A
MOC : NOT APPLICABLE - N/A BY INSTALLED P/N										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KOBI		MANDATORY	MTH 10-Jun-2016 HRS 2574.5 LDG 2183		-			N/A
MOC : NOT APPLICABLE - N/A BY INSTALLED P/N										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KOBI		MANDATORY	MTH 10-Jun-2016 HRS 2574.5 LDG 2183		-			N/A
MOC : NOT APPLICABLE - N/A BY INSTALLED P/N										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KTTN		MANDATORY	MTH 07-Nov-2016 HRS 2589 LDG 2197 ACH 1380.4		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2016-11-20 VERIFIED EQUIPMENT IS NOT INSTALLED. TERMINATING ACTION										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KOWD		MANDATORY	MTH 18-Oct-2017 HRS 2595.3 LDG 2206		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KOWD		MANDATORY	MTH 18-Oct-2017 HRS 2595.3 LDG 2206 ACH 1380.4		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KOWD		MANDATORY	MTH 18-Oct-2017 HRS 2595.3 LDG 2206		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KOWD		MANDATORY	MTH 18-Oct-2017 HRS 2595.3 LDG 2206		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KOWD		MANDATORY	MTH 18-Oct-2017 HRS 2595.3 LDG 2206		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KOWD		MANDATORY	MTH 18-Oct-2017 HRS 2595.3 LDG 2206 ACH 1380.4		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES									
		KOWD		MANDATORY	MTH 18-Oct-2017 HRS 2595.3 LDG 2206		-			N/A
	MOC : NOT APPLICABLE									
FAA 2008-03-10 53AD-01	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE									
		MIV		MANDATORY	MTH 18-Jul-2008 HRS 2169		-			Complete
	MOC : COMPLIED WITH									
FAA 1999-07-04 E1	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)				MTH 12-May-1999 HRS 644 LDG 616		A/R			Complete
	MOC : COMPLIED WITH									
FAA 1999-07-04 E2	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)				MTH 12-May-1999 HRS 644 LDG 616		A/R			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	3001.9	2505	13-Mar-2025	.37
ENG 1	3001.9	2505	13-Mar-2025	.37
ENG 2	3001.9	2505	13-Mar-2025	.37
AIR COND	1573.1		31-Oct-2024	.05

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
25FO-01 525/D 25FO-01 : 525/D	REFRESH CTR-LH FWD DELUXE(EXCH) FACTORY OPTION	*CF		128D FO	MTH 31-May-1996		-			
25FO-05 525/B 25FO-05 : 525/B	LOCATOR BEACON ARTEX FACTORY OPTION	*CF		175B FO	MTH 31-May-1996		-			
25FO-06 525 25FO-06 : 525	STANDARD SEATING FACTORY OPTION	*CF		109 FO	MTH 31-May-1996		-			
25FO-08 525 25FO-08 : 525	NAVIGATION CHART CASE, LH FACTORY OPTION	*CF		103 FO	MTH 31-May-1996		-			
25FO-10 525/Y 25FO-10 : 525/Y	DIVIDER, RH AFT W/MIRROR(EXCH) FACTORY OPTION	*CF		120Y FO	MTH 31-May-1996		-			
25FO-13 525/F 25FO-13 : 525/F	CURTAIN, AFT REMOVABLE(EXCH) FACTORY OPTION	*CF		121F FO	MTH 31-May-1996		-			
25FO-20 525/E 25FO-20 : 525/E	RH SIDELEDGE, CABIN W/LEATHER INLAY AND TABLE FACTORY OPTION	*CF		122E FO	MTH 31-May-1996		-			
25FO-33 525/J 25FO-33 : 525/J	RH EXECUTIVE TABLE W/LEATHER LEAF FACTORY OPTION	*CF		123J FO	MTH 31-May-1996		-			
25FO-37 525/Q 25FO-37 : 525/Q	OVERBOARD DRAIN, LH FWD RELIEF TUBE FACTORY OPTION	*CF		131Q FO	MTH 31-May-1996		-			
28FO-01 525 28FO-01 : 525	LOCKING FUEL CAPS (EXCHANGE) FACTORY OPTION	*CF		36 FO	MTH 31-May-1996		-			
34FO-03 525/R 34FO-03 : 525/R	RADIO ALTIMETER FACTORY OPTION	*CF		672R FO	MTH 31-May-1996		-			
34FO-04 525 34FO-04 : 525	DME 2-HONEYWELL FACTORY OPTION	*CF		682 FO	MTH 31-May-1996		-			
35FO-01 525/F 35FO-01 : 525/F	OXY-50 CU FT BOTTLE (EXCH) FACTORY OPTION	*CF		66F FO	MTH 31-May-1996		-			
73FO-01 525 73FO-01 : 525	ENGINE SYNCHRONIZER FACTORY OPTION	*CF		76 FO	MTH 31-May-1996		-			



CESCOM 20 - Projected Maintenance Due

Owner: **WIDE OPEN ADVENTURES**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0139**

Unit: **0139** Reg No: **N36RG**

Airworthiness: **31-May-1996**

Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 1	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 2	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
AIR COND	1573.1		31-Oct-2024	.05	0.17	15.28		92	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Overdue Maintenance Tasks

Item Code	Description			Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
350006	OXYGEN BOTTLE	KMQS		176274-50	MTH	06-Jul-2010	180		31-Mar-2025	-1 m 0 d
	DOT-E 8162			ALT279-19239/0501	HRS	2354.3				
					LDG	2021				

Over Due

Date Flag

Label: 31-

Mar-2010

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains	
A323101	RESTORATION (HYDROSTATIC TEST) EMERGENCY GEAR BOTTLE							
0512004 : GEAR	CHA	40005320-2 MTH	07-Apr-2022		36		30-Apr-2025	0 d
		7471						
Date Flag Label: 07-Apr-2022								
5-12-21	INSPECTION DOCUMENT 21	MTH	04-May-2023		24		31-May-2025	1 m 0 d
0512021	KLNS	HRS	2764		600		3364	362.1
		LDG	2343					
5-12-02	INSPECTION DOCUMENT 02	MTH	04-Jul-2024		12		31-Jul-2025	3 m 0 d
0512002	N81	HRS	2931.7					
		LDG	2459					
5-12-12	INSPECTION DOCUMENT 12 (14 CFR 91.207)	MTH	04-Jul-2024		12		31-Jul-2025	3 m 0 d
0512012	N81	HRS	2931.7					
		LDG	2459					
5-12-33	INSPECTION DOCUMENT 33	MTH	04-Jul-2024		12		31-Jul-2025	3 m 0 d
0512033	N81	HRS	2931.7		300		3231.7	229.8
		LDG	2459					
5-12-36	INSPECTION DOCUMENT 36	MTH	30-Jan-2025		6		31-Jul-2025	3 m 0 d
	N81	HRS	2974.9					
		LDG	2490					
B262201	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER							
COCKPIT	N81	C352TS MTH	04-Jul-2024		12		31-Jul-2025	3 m 0 d
0512016		E-92812238 HRS	2931.7					
		LDG	2459					

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City	Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB WI-72-1068 R01 6 BOLT SPINNER - REPLACE E1		RECOMMENDED	MTH HRS MSC		400 HRS RPI		3297.38	295.48
SB WI-72-1068 R01 6 BOLT SPINNER - REPLACE E2		RECOMMENDED	MTH HRS MSC		400 HRS RPI		3297.38	295.48
SB FJ44-72-034 R06 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE CARBON SEAL MAGNET KEEPERS		HRS MSC		DUE		4985	1983.1
SB FJ44-72-034 R06 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE CARBON SEAL MAGNET KEEPERS	MANDATORY	HRS MSC		DUE		4985	1983.1
SB FJ44-72-035 R03 E1	NO. 1 CARBON SEAL AND NO.1 CARBON SEAL RUNNER - REPLACE		HRS MSC		DUE		4985	1983.1
SB FJ44-72-035 R03 E2	NO. 1 CARBON SEAL AND NO.1 CARBON SEAL RUNNER - REPLACE	RECOMMENDED	HRS MSC		DUE		4985	1983.1

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **WIDE OPEN ADVENTURES**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0139**

Unit: **0139** Reg No: **N36RG**

Airworthiness: **31-May-1996**

Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 1	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 2	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
AIR COND	1573.1		31-Oct-2024	.05	0.17	15.28		92	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB FJ44-72-039 R05 E1	HP COMPRESSOR ROTOR - REWORK BACKWALL RECOMMENDED	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-039 R05 E2	HP COMPRESSOR ROTOR - REWORK BACKWALL RECOMMENDED	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-051 R05 E1	NAMEPLATE - REWORK RECOMMENDED	MTH HRS MSC			MPI		4985	1983.1
SB FJ44-72-051 R05 E2	NAMEPLATE - REWORK RECOMMENDED	MTH HRS MSC			MPI		4985	1983.1
SB FJ44-72-076 R02 E1	IP COMPRESSOR STATOR - REWORK OPTIONAL	MTH HRS MSC			CSI		4985	1983.1
SB FJ44-72-076 R02 E2	IP COMPRESSOR STATOR - REWORK OPTIONAL	MTH HRS MSC			CSI		4985	1983.1
SB FJ44-72-083 R06 E1	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION OPTIONAL	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-083 R06 E2	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION OPTIONAL	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE RECOMMENDED	HRS MSC			DUE		4985	1983.1
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE RECOMMENDED	HRS MSC			DUE		4985	1983.1
SB FJ44-72-111 R02 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION RECOMMENDED	HRS MSC			-		4985	1983.1
SB FJ44-72-111 R02 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION RECOMMENDED	HRS MSC			-		4985	1983.1
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION RECOMMENDED	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION RECOMMENDED	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-144 E1	DIFFUSER CASE ASSEMBLY - REPLACE / REWORK RECOMMENDED	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-144 E2	DIFFUSER CASE ASSEMBLY - REPLACE / REWORK RECOMMENDED	MTH HRS MSC			DUE		4985	1983.1
SB FJ44-72-147 R02 E1	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED	MTH HRS MSC			MPI		4985	1983.1
SB FJ44-72-147 R02 E2	DIFFUSER CASE ASSEMBLY - INSPECTION RECOMMENDED	MTH HRS MSC			MPI		4985	1983.1
SB FJ44-72-149 R03 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE RECOMMENDED	HRS MSC			MPI		4985	1983.1

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **WIDE OPEN ADVENTURES**
Aircraft Model: **525 - CITATION JET**
Aircraft Serial: **525-0139**
Unit: **0139** Reg No: **N36RG**
Airworthiness: **31-May-1996**
Print Date: **30-Apr-2025 1:57AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 1	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
ENG 2	3001.9	2505	13-Mar-2025	.37	0.4	36.68	19	92	3
AIR COND	1573.1		31-Oct-2024	.05	0.17	15.28		92	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB FJ44-72-149 R03	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE									
E2				RECOMMENDED	HRS				4985	1983.1
					MSC		MPI			
SB WI-73-1000 R01	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
E1				RECOMMENDED	MTH				4985	1983.1
					HRS					
					MSC		-			
SB WI-73-1000 R01	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
E2				RECOMMENDED	MTH				4985	1983.1
					HRS					
					MSC		-			
SB 525-27-26 R01	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION									
				RECOMMENDED	MTH					
					MSC		-			
SB 525-27-28	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION									
				RECOMMENDED	MTH					
					MSC		-			
SB FJ44-79-011 R05	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE				MSC					
E1							-			
SB FJ44-79-011 R05	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE				MSC					
E2							-			
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING									
					MTH					
				MANDATORY	MSC		-			

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE									
				MANDATORY	MTH		6 MTH		07-Sep-2025	4 m 7 d
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE									
				MANDATORY	MTH		12 MTH		07-Mar-2026	10 m 7 d
FAA 2013-08-05 PARA (H)	REPLACE AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES									
		KTNN			MTH	03-May-2013				
				MANDATORY	HRS	2508.6				
					LDG	2127				
					ACH	1311.7	500		1811.7	238.6



CESCOM 30 - Maintenance Transaction

Print Date: 30-Apr-2025

Owner: WIDE OPEN ADVENTURES
Aircraft Model: 525 - CITATION JET
Aircraft Serial: 525-0139
Unit: 0139 Reg No: N36RG
Transaction Dates: 30-Mar-2025 to 29-Apr-2025

							----- Install -----			----- Removal -----		
Item Code	Item	Mfg		Mfg Part Number		Date	P-Time	P-TSO	P-TBO	Rmvl Date	Schd Date	
Position	Act Cst	Manhr	Code	Operator	Alt Part Nbr/Model	P-Time	P-Time	P-TSO	P-TBO	P-Time	Rmvl Rsn	
					Part Serial	S-Time	S-Time	S-TSO	S-TBO	S-Time	Action	
***** Maintenance Accomplished *****												