OWNER:	MACARTHUR JET CHARTER PTY. LTD.	OPERATOR:	MACARTHUR JET CHARTER PTY. LTD.	OPERATOR:	FALCON 50 PTY LTD
ADDRESS:	115 ELLIS LANE ELLIS LANE NSW 2570	ADDRESS:	P.O. BOX 689 CAMDEN NSW	ADDRESS:	P.O. BOX 689 CAMDEN NSW 2570
OFFICE:		OFFICE:		OFFICE:	
FAX:		FAX:		FAX:	

ANALYST:	KIRAN BAALI	- (DIRECT)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL:	KIRAN.BAALI@CAMPSYSTEMS.COM	+1-631-588-3200 (MAIN)	
		WWW.CAMPSYSTEMS.COM	

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT

SERIAL/REGNO: 252/VH-FJQ MODEL: FALCON 50 MANUFACTURER: DASSAULT AVIATION S.A.

CERTIFICATION DATE: 11-JUL-1995

LAST ACTUALS:

6792.3	A/C HRS	as of 20-SEP-2026
4010	AFL	as of 20-SEP-2026
3009.1	APH	as of 20-SEP-2026

APU

SERIAL/PART: P-355/3800016-3-1 MODEL: GTCP36-100(A) MANUFACTURER: HONEYWELL

INSTALLED ON: 01-FEB-1996

3	APU HRS	0 A/C HRS
0	APUS	

LAST ACTUALS:

3009.1	APU HRS	as of 20-SEP-2026
1883	APUS	as of 05-FEB-2019

ENGINE NO. 1

SERIAL/PART: P-76905/3072800-5 MODEL: TFE731-3-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 18-JUN-2019

5597.2	ENG. HRS	5790.5 A/C HRS
3400	ENC	

LAST ACTUALS:

6599	ENG. HRS	as of 20-SEP-2026
3903	ENC	as of 20-SEP-2026

ENGINE NO. 2

SERIAL/PART: P-76904/3072800-5 MODEL: TFE731-3-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 18-JUN-2019

5594.6	ENG. HRS	5790.5 A/C HRS
3396	ENC	

LAST ACTUALS:

6596.4	ENG. HRS	as of 20-SEP-2026
3899	ENC	as of 20-SEP-2026

ENGINE NO. 3

SERIAL/PART: P-76903/3072800-5 MODEL: TFE731-3-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 18-JUN-2019

5556.2	ENG. HRS	5790.5 A/C HRS
3380	ENC	

LAST ACTUALS:

6558	ENG. HRS	as of 20-SEP-2026
3883	ENC	as of 20-SEP-2026

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA								
1 U	12/24/36 MONTH INSPECTIONS							SETS ATA:
	MOS		12					
	HRS							
	AFL							
ATA 00 - INFORMATION								
3645-170701	REVIEW DASSAULT AVIATION FALCON 50 AND 50EX MPD CHAPTER 5 REVISION 6, DATED JULY 2017 - SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	25-Jul-17	-					
	HRS	5184.5						
	AFL	3264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
3645-170809	REVIEW DASSAULT AVIATION FALCON 50 MPD CHAPTER 5-40 REVISION 24, DATED JULY 2017 - SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	17-Aug-17	-					REQUIREMENT CHANGE FORMS
	HRS	5196.5						
	AFL	3278						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057110	NO. 1 ENGINE - 150/250 HOUR INSPECTION							Package ATA:05
	MOS	24-Feb-26						
	HRS	6543.8	150 (+100)		(6693.8) 6887.1	6793.8	94.8 (+100)	
	ENC	3864						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057110	NO. 2 ENGINE - 150/250 HOUR INSPECTION							Package ATA:05
	MOS	24-Feb-26						
	HRS	6541.2	150 (+100)		(6691.2) 6887.1	6791.2	94.8 (+100)	
	ENC	3860						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057110	NO. 3 ENGINE - 150/250 HOUR INSPECTION							Package ATA:05
	MOS	24-Feb-26						
	HRS	6502.8	150 (+100)		(6652.8) 6887.1	6752.8	94.8 (+100)	
	ENC	3844						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057120	NO. 1 ENGINE - 300/400 HOUR INSPECTION							Package ATA:05
	MOS	29-May-24						
	HRS	6379.4	400		(6779.4) 6972.7		180.4	
	ENC	3752						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057120	NO. 2 ENGINE - 300/400 HOUR INSPECTION							Package ATA:05
	MOS	29-May-24						
	HRS	6376.8	400		(6776.8) 6972.7		180.4	
	ENC	3748						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057120	NO. 3 ENGINE - 300/400 HOUR INSPECTION							Package ATA:05
	MOS	29-May-24						
	HRS	6338.4	400		(6738.4) 6972.7		180.4	
	ENC	3732						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057130	NO. 1 ENGINE - 600/800 HOUR INSPECTION							Package ATA:05
	MOS	30-May-23						
	HRS	6221.1	600 (+200)	Adj -23.9	(6797.2) 6990.5	6997.2	198.2 (+200)	
	ENC	3693						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057130	NO. 2 ENGINE - 600/800 HOUR INSPECTION							Package ATA:05
	MOS	30-May-23						
	HRS	6218.5	600 (+200)	Adj -23.9	(6794.6) 6990.5	6994.6	198.2 (+200)	
	ENC	3689						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057130	NO. 3 ENGINE - 600/800 HOUR INSPECTION							Package ATA:05
	MOS	30-May-23						
	HRS	6180.1	600 (+200)	Adj -23.9	(6756.2) 6990.5	6956.2	198.2 (+200)	
	ENC	3673						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057140	NO. 1 ENGINE - 1000/1500 HOUR INSPECTION							Package ATA:05
	MOS	17-Apr-19						
	HRS	5597.2	1200 (+300)		(6797.2) 6990.5	7097.2	198.2 (+300)	
	ENC	3400						
								PKG:1
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057140	NO. 2 ENGINE - 1000/1500 HOUR INSPECTION							Package ATA:05
	MOS	19-Apr-19						
	HRS	5594.6	1200 (+300)		(6794.6) 6990.5	7094.6	198.2 (+300)	
	ENC	3396						
								PKG:1
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057140	NO. 3 ENGINE - 1000/1500 HOUR INSPECTION							Package ATA:05
	MOS	26-Apr-19						
	HRS	5556.2	1200 (+300)		(6756.2) 6990.5	7056.2	198.2 (+300)	
	ENC	3380						
								PKG:1
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-16	24 M INSPECTION							Package ATA:05
	MOS	02-Oct-24	24 (+1m)	Adj -52d	11-Aug-26	11-Sep-26	OVD	
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-21	1B INSPECTION							Package ATA:05
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)		7442.6	7472.6	650.3 (+30)	
	AFL	3569						
								PKG:21
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-22	2B INSPECTION							Package ATA:05
	MOS	11-Aug-20						
	HRS	5942.6	3000 (+30)		8942.6	8972.6	2150.3 (+30)	
	AFL	3569						
								PKG:22
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-23	3B INSPECTION							Package ATA:05
	MOS	23-Oct-13						
	HRS	4569.5	4500 (+30)	Adj -108.5	8961	8991	2168.7 (+30)	
	AFL	2879						
								PKG:23
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-24	4B INSPECTION							Package ATA:05
	MOS	11-Aug-20						
	HRS	5942.6	6000 (+30)		11942.6	11972.6	5150.3 (+30)	
	AFL	3569						
								PKG:24
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-31	1C INSPECTION							Package ATA:05
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-32	2C INSPECTION							Package ATA:05
	MOS	11-Aug-20	144 (+2m)		11-Aug-32	11-Oct-32	2133 d (+61)	
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-33	3C INSPECTION							Package ATA:05
	MOS/MSC	08-May-14	N/A					
	HRS	4694.25						
	AFL	2957						
								PKG:33
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-34	4C INSPECTION							Package ATA:05
	MOS/MSC	11-Aug-20	N/A					
	HRS	5942.6						
	AFL	3569						
								PKG:34
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-08-00-200-800-15	12 M INSPECTION							Package ATA:05
	MOS	24-Oct-25	12 (+1m)	Adj -22d	02-Oct-26	02-Nov-26	TOL (+24 d)	
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-17	36 M INSPECTION							Package ATA:05
	MOS	08-Dec-23	36 (+1m)		08-Dec-26	08-Jan-27	60 d (+31)	
	HRS	6529.1						
	AFL	3833						
								PKG:208
PROC. REF: MPD 05-10-00PROC. REF: MPD 05-10-00								
05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 24.310	AFL	0						
PROC. REF: AMM 05-50-00-100-801PROC. REF: AMM 05-50-00-100-801								
05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 32.160	AFL	0						
PROC. REF: AMM 05-50-00-200-801PROC. REF: AMM 05-50-00-200-801								
05-50-00-200-802-01	CHECK AFTER HAILSTORM							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 51.070	AFL	0						
PROC. REF: AMM 05-50-00-200-802PROC. REF: AMM 05-50-00-200-802								
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 51.080	AFL	0						
PROC. REF: AMM 05-50-00-200-803PROC. REF: AMM 05-50-00-200-803								
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 32.205	AFL	0						
PROC. REF: AMM 05-50-00-200-804PROC. REF: AMM 05-50-00-200-804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 51.060	AFL	0						
PROC. REF: AMM 05-50-00-200-805	PROC. REF: AMM 05-50-00-200-805							
05-50-00-200-806-01	CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-806	PROC. REF: AMM 05-50-00-200-806							
05-50-00-200-809-01	INSPECTION AFTER SLAT OPERATION IN OVERSPEED CONDITION							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-809	PROC. REF: AMM 05-50-00-200-809							
05-50-00-200-810-01	INSPECTION AFTER FLAP OPERATION IN OVERSPEED CONDITION							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-810	PROC. REF: AMM 05-50-00-200-810							
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-812	PROC. REF: AMM 05-50-00-200-812							
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 32.260	AFL	0						
PROC. REF: AMM 05-50-00-200-813	PROC. REF: AMM 05-50-00-200-813							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-200-817-01	CHECK AFTER COLLISION WITH FOREIGN OBJECT							Service ATA:05
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-817	PROC. REF: AMM 05-50-00-200-817							
05-50-00-200-822-01	OPERATION TO BE PERFORMED AFTER VMO/MMO EXCEEDANCE							Service ATA:05
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-822	PROC. REF: AMM 05-50-00-200-822							
05-50-00-200-823-01	CHECK OF THE SLATS AFTER OVERHEATING - LH WING							Service ATA:05
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-823	PROC. REF: AMM 05-50-00-200-823							
05-50-00-200-823-02	CHECK OF THE SLATS AFTER OVERHEATING - RH WING							Service ATA:05
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-200-823	PROC. REF: AMM 05-50-00-200-823							
05-50-00-620-801-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-620-801	PROC. REF: AMM 05-50-00-620-801							
05-50-00-620-803-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 05.020	AFL	0						
PROC. REF: AMM 05-50-00-620-803	PROC. REF: AMM 05-50-00-620-803							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-620-804-01	PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 51.100	AFL	0						
PROC. REF: AMM 05-50-00-620-804	PROC. REF: AMM 05-50-00-620-804							
05-50-00-700-803-01	CHECK AFTER FIRE EXTINGUISHER PERCUSSION							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 20.020	AFL	0						
PROC. REF: SL 20-350, AMM 05-50-00-700-803	PROC. REF: SL 20-350, AMM 05-50-00-700-803							
05-50-00-700-807-01	CHECK AFTER LANDING ON A DRY AND DIRTY RUNWAY							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 32.205	AFL	0						
PROC. REF: AMM 05-50-00-700-807	PROC. REF: AMM 05-50-00-700-807							
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 32.160	AFL	0						
PROC. REF: AMM 05-50-00-700-808	PROC. REF: AMM 05-50-00-700-808							
05-50-00-700-810-01	CHECK AFTER SAND CONDITION - CHECKS AFTER EACH FLIGHT THROUGH SAND							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-810	PROC. REF: AMM 05-50-00-700-810							
05-50-00-700-810-02	CHECK AFTER SAND CONDITION - FURTHER INSPECTIONS IN CASE OF SAND DEPOSITS AFTER FLIGHT THROUGH SAND							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-810	PROC. REF: AMM 05-50-00-700-810							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-700-810-03	CHECK AFTER SAND CONDITION - PERIODIC INSPECTIONS AND CHECKS AFTER FLIGHTS THROUGH SAND							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-810	PROC. REF: AMM 05-50-00-700-810							
05-50-00-700-810-04	CHECK AFTER SAND CONDITION - INSPECTIONS AND CHECKS AFTER A SANDSTORM (AIRCRAFT PARKED)							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-810	PROC. REF: AMM 05-50-00-700-810							
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-818	PROC. REF: AMM 05-50-00-700-818							
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-822	PROC. REF: AMM 05-50-00-700-822							
05-50-00-700-822-02	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - FURTHER CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-822	PROC. REF: AMM 05-50-00-700-822							
05-50-00-700-822-03	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS AFTER EXCEPTIONAL FLIGHT THROUGH A HIGH VOLCANIC ASH CONCENTRATION AREA							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
PROC. REF: AMM 05-50-00-700-822PROC. REF: AMM 05-50-00-700-822								
05-50-00-700-822-04	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-822PROC. REF: AMM 05-50-00-700-822								
05-50-00-700-822-05	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A HEAVY VOLCANIC ASH FALLOUT AREA							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-700-822PROC. REF: AMM 05-50-00-700-822								
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-50-00-730-802PROC. REF: AMM 05-50-00-730-802								
05-50-00-860-801-01	CHECK AND PREPARATION FOR FLIGHT WITH ONE ENGINE INOPERATIVE							Service ATA:05
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 71.090	AFL	0						
PROC. REF: AMM 05-50-00-860-801, AMM 05-50-00-860-801PROC. REF: AMM 05-50-00-860-801, AMM 05-50-00-860-801								
05-50-00-910-801-01	AIRCRAFT CHECK FLIGHT							Service ATA:05
	MOS	11-Aug-20	72 (+3%)		11-Aug-26 (M)	15-Oct-26	TOL (+6 d)	
	HRS	5942.6						
WC#: 51.020	AFL	3569						
PROC. REF: AMM 05-50-00-910-801PROC. REF: AMM 05-50-00-910-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-60-00-200-801-01	BASIC INSPECTION							Service ATA:05
	MOS	25-Jul-25	12 (+1m)	Adj -8d	17-Jul-26	17-Aug-26	OVD	
	HRS	6676.3	300 (+30)		6976.3	7006.3	184 (+30)	
WC#: 05.010	AFL	3928						
PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801								
05-60-00-200-801-03	BASIC INSPECTION - GROUND SERVICING CHECKS							Service ATA:05
	MOS	25-Jul-25	12 (+1m)	Adj -8d	17-Jul-26	17-Aug-26	OVD	
	HRS	6676.3	300 (+30)		6976.3	7006.3	184 (+30)	
WC#: 05.010	AFL	3928						
PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801PROC. REF: MPD 05-10-00, AMM 05-60-00-200-801								
05A101 U	CASA MAINTENANCE RELEASE INSPECTION							Service ATA:05
	MOS	24-Oct-25	13		24-Nov-26		46 d	CASA
	HRS	6700.5	330		7030.5		238.2	
	AFL	3940						
05A102 U	REVIEW CASA SYSTEM OF MAINTENANCE							Service ATA:05
	MOS/MSC	08-Jul-21	O/C	Adj 18				CASA
	HRS	6074						
	AFL	3636						
05A103 U	REVIEW CASA MINIMUM EQUIPMENT LIST							Service ATA:05
	MOS/MSC	08-Jul-21	O/C	Adj 18				CASA
	HRS	6074						
	AFL	3636						
ATA 08 - LEVELING AND WEIGHING								
08-10-00-910-801-01	WEIGHING THE AIRCRAFT - WEIGHING THE AIRCRAFT ON WHEELS							Service ATA:08
	MOS	08-Dec-23	36		08-Dec-26		60 d	
	HRS	6529.1						
	AFL	3833						
PROC. REF: AMM 08-10-00-910-801PROC. REF: AMM 08-10-00-910-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 09 - TOWING AND TAXING								
09-10-00-910-810-01	DEBOGGING THE AIRCRAFT							Service ATA:09
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 09-10-00-910-810	PROC. REF: AMM 09-10-00-910-810							
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS							Service ATA:10
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00-200-801	PROC. REF: AMM 10-10-00-200-801							
10-10-00-550-801-09 U	PERFORM STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PRE-STROAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 8 WEEKS							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
10-10-00-550-801-10	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - NON-FLYING AND NON-STORED PERIOD							Service ATA:10
	MOS/MSC	11-Jul-95	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							
10-10-00-550-801-11	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 2 MONTHS							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							
10-10-00-550-801-12	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - ADDITIONAL OPERATIONS FOR STORAGE FROM 2 TO 12 MONTHS							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-10-00-550-801-13	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A PERIOD OF 12 TO 18 MONTHS							Service ATA:10
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							
10-10-00-550-801-14	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY MONTH							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							
10-10-00-550-801-15	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 2 MONTHS							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							
10-10-00-550-801-16	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 6 MONTHS							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							
10-10-00-550-801-17	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AT THE END OF THE 2 MONTHS OR LESS							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							
10-10-00-550-801-18	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AFTER MORE THAN 2 MONTHS							Service ATA:10
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 20.010	AFL	0						
PROC. REF: AMM 10-10-00-550-801	PROC. REF: AMM 10-10-00-550-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 10 - PARKING, MOORING, STORE AND RET TO SERV								
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL							Service ATA:10
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 10.010	AFL	0						
PROC. REF: AMM 10-20-00-910-802	PROC. REF: AMM 10-20-00-910-802							
ATA 20 - STANDARD PRACTICES - AIRFRAME								
20-30-00-330-801-01	TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT							Service ATA:20
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 51.090	AFL	0						
PROC. REF: AMM 20-30-00-330-801	PROC. REF: AMM 20-30-00-330-801							
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR							Service ATA:20
	MOS/MSC	09-Apr-25	A/R					
	HRS	6648.6						
WC#: 20.060	AFL	3909						
PROC. REF: SL 20-318, AMM 20-31-00-140-801	PROC. REF: SL 20-318, AMM 20-31-00-140-801							
20-31-00-910-801-01	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - DE-ICING TREATMENT							Service ATA:20
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 20.050	AFL	0						
PROC. REF: SL 20-625, AMM 20-31-00-910-801	PROC. REF: SL 20-625, AMM 20-31-00-910-801							
20-33-00-300-804-01	TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS							Service ATA:20
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 20-33-00-300-804	PROC. REF: AMM 20-33-00-300-804							
20-60-00-370-813-01	APPLICATION OF THE PAINT SCHEME ON COMPOSITE COMPONENTS							Service ATA:20
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 20.040	AFL	0						
PROC. REF: SL 20-615, AMM 20-60-00-370-813	PROC. REF: SL 20-615, AMM 20-60-00-370-813							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 20 - STANDARD PRACTICES - AIRFRAME								
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (L2GF)							Service ATA:20
PN:C23791-1012	MOS/MSC	11-Aug-20	O/C					
SN:U63	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 20-60-00-370-816	PROC. REF: AMM 20-60-00-370-816							
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (R2GF)							Service ATA:20
PN:C23792-1012	MOS/MSC	11-Aug-20	O/C					
SN:U239	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 20-60-00-370-816	PROC. REF: AMM 20-60-00-370-816							
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (L2GF5)							Service ATA:20
PN:C23795-1004	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 20-60-00-370-816	PROC. REF: AMM 20-60-00-370-816							
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (R2GF5)							Service ATA:20
PN:C23796-1004	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 20-60-00-370-816	PROC. REF: AMM 20-60-00-370-816							
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (3GF)							Service ATA:20
PN:C23787-1010	MOS/MSC	11-Aug-20	O/C					
SN:U263	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 20-60-00-370-816	PROC. REF: AMM 20-60-00-370-816							
203559	STORAGE AND STORAGE REMOVAL WHEN AIRCRAFT DOES NOT FLY FOR MORE THAN 65 DAYS							Service ATA:20
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
WC#: 20.030	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-20-01-350-801-01	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - LH FLOW LIMITER (L518H)							Service ATA:21
PN:2725F030100	MOS	23-Oct-13						OVERHAUL
SN:01045	HRS	4569.5	4500 (+3%)		9069.5	9204.5	2277.2 (+135)	
WC#: 21.070	AFL	2879						
PROC. REF: AMM 21-20-01-350-801	PROC. REF: AMM 21-20-01-350-801							
21-20-01-350-801-02	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - RH FLOW LIMITER (R518H)							Service ATA:21
PN:272SF030100	MOS	23-Oct-13						OVERHAUL
SN:300	HRS	4569.5	4500 (+3%)		9069.5	9204.5	2277.2 (+135)	
WC#: 21.070	AFL	2879						
PROC. REF: AMM 21-20-01-350-801	PROC. REF: AMM 21-20-01-350-801							
21-30-00-790-801-01	GROUND CHECK OF CABIN SEALING							Service ATA:21
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 21-30-00-790-801	PROC. REF: AMM 21-30-00-790-801							
21-30-00-790-802-01	IN-FLIGHT CHECK OF CABIN SEALING							Service ATA:21
	MOS	15-Jul-96						
	HRS	0						
	AFL	0	T:7000		7000		2990	
PROC. REF: AMM 21-30-00-790-802	PROC. REF: AMM 21-30-00-790-802							
21-30-00-790-802-01A	CHECK (IN-FLIGHT) OF CABIN SEALING (MANDATORY 5-40)							Service ATA:21
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
	AFL	0	T:7000		7000		2990	
PROC. REF: AMM 21-30-00-790-802	PROC. REF: AMM 21-30-00-790-802							
21-30-01-900-801-01	REMOVAL / INSTALLATION OF THE AUTOMATIC PRESSURIZATION CONTROLLER - PRESSURIZATION CONTROLLER (73H)							Component ATA:21
PN:22201N031000	MOS/MSC	24-Apr-06	O/C	TSR 4				
SN:1048	HRS	2490.6						
WC#: 21.140	AFL	1725						
PROC. REF: AMM 21-30-01-900-801	PROC. REF: AMM 21-30-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-30-09-720-801-01	FUNCTIONAL TEST OF THE ALTITUDE ALERT OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (37F)							Service ATA:21
PN:3311AJ68	MOS/MSC	08-Mar-12	N/A					
SN:UNKNOWN	HRS	3996.83						
WC#: 21.200	AFL	2577						
PROC. REF: AMM 21-30-09-720-801	PROC. REF: AMM 21-30-09-720-801							
21-30-09-900-801-01	REMOVAL / INSTALLATION OF THE TRIPLE INDICATOR							Component ATA:21
PN:3311AJ68	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.200	AFL	0						
PROC. REF: AMM 21-30-09-900-801	PROC. REF: AMM 21-30-09-900-801							
21-30-17-820-801-01	CALIBRATION OF THE ALTIMETRIC SWITCH - ALTIMETRIC SWITCH (150H)							Service ATA:21
PN:4224ZR21	MOS	08-Mar-12						
SN:873	HRS	3996.83	4000		7996.83		1204.5	
WC#: 21.210	AFL	2577						
PROC. REF: AMM 21-30-17-820-801	PROC. REF: AMM 21-30-17-820-801							
21-30-17-900-801-01	REMOVAL / INSTALLATION OF THE ALTIMETRIC SWITCH - ALTIMETRIC SWITCH (150H)							Component ATA:21
PN:4224ZR21	MOS/MSC	08-Mar-12	O/C	TSR 0				
SN:873	HRS	3996.83		TSR 0				
WC#: 21.210	AFL	2577		TSR 0				
PROC. REF: AMM 21-30-17-900-801	PROC. REF: AMM 21-30-17-900-801							
21-31-09-350-801-01	RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS) - NOSE CONE FAN (83H)							Service ATA:21
PN:AE0402A00	MOS/MSC		N/A					
SN:00346	HRS							
WC#: 21.100	AFL							
PROC. REF: AMM 21-31-09-350-801	PROC. REF: AMM 21-31-09-350-801							
21-31-09-900-801-01	REMOVAL / INSTALLATION OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (83H)							Component ATA:21
PN:AE0402A00	MOS/MSC	13-Dec-19	O/C	TSN 0				
SN:00346	HRS			TSN 0				
WC#: 21.100	AFL			TSN 0				
PROC. REF: AMM 21-31-09-900-801	PROC. REF: AMM 21-31-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-13-720-801-01 S	FUNCTIONAL TEST OF THE NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR - PNEUMATIC ACTUATOR							Service ATA:21
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 21.090	AFL	3569						
								PKG:31
PROC. REF: AMM 21-31-13-720-801	PROC. REF: AMM 21-31-13-720-801							
21-31-13-720-801-02 S	FUNCTIONAL TEST OF THE NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR - NOSE CONE PRESSURE-RELIEF VALVE							Service ATA:21
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 21-31-13-720-801	PROC. REF: AMM 21-31-13-720-801							
21-31-25-220-801-01	CHECK / REPLACEMENT OF THE NOSE CONE VENTILATION FAN BRUSHES - NOSE CONE FAN (83H)							Service ATA:21
PN:AE0402A00	MOS/MSC		N/A					
SN:00346	HRS							
WC#: 21.100	AFL							
PROC. REF: AMM 21-31-25-220-801	PROC. REF: AMM 21-31-25-220-801							
21-32-00-710-801-01 S	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM							Service ATA:21
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 21.120	AFL	3569						
								PKG:21
PROC. REF: AMM 21-32-00-710-801	PROC. REF: AMM 21-32-00-710-801							
21-32-00-710-801-01A	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM (MANDATORY 5-40)							Service ATA:21
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6	1550		7492.6		700.3	
WC#: 21.120	AFL	3569						
PROC. REF: AMM 21-32-00-710-801	PROC. REF: AMM 21-32-00-710-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-00-790-801-01 S	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (16F1)							Service ATA:21
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 21-32-00-790-801	PROC. REF: AMM 21-32-00-790-801							
21-32-00-790-801-02 S	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (16F2)							Service ATA:21
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 21-32-00-790-801	PROC. REF: AMM 21-32-00-790-801							
21-32-06-200-801-01	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF ELECTROPNEUMATIC VALVE (L74H)							Service ATA:21
PN:2095D01042	MOS	11-Aug-20						
SN:674	HRS	5942.6	1640 (+3%)		7582.6	7631.8	790.3 (+49.2)	
WC#: 21.160	AFL	3569						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							
21-32-06-200-801-02	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF PNEUMATIC VALVE (R74H)							Service ATA:21
PN:2096E010200	MOS	08-Sep-22						
SN:560	HRS	6221.1	1640 (+3%)		7861.1	7910.3	1068.8 (+49.2)	
WC#: 21.170	AFL	3722						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							
21-32-06-200-801-03	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF ELECTROPNEUMATIC VALVE (L74H)							Service ATA:21
PN:2095D01042	MOS	11-Aug-20						
SN:674	HRS	5942.6	1640		7582.6		790.3	
WC#: 21.160	AFL	3569						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-06-200-801-03A	CHECK ELECTROPNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)							Service ATA:21
PN:2095D01042	MOS	11-Aug-20						MANDATORY 5-40
SN:674	HRS	5942.6	1640		7582.6		790.3	
WC#: 21.320	AFL	3569						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							
21-32-06-200-801-04	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF PNEUMATIC VALVE (R74H)							Service ATA:21
PN:2096E010200	MOS	08-Sep-22						
SN:560	HRS	6221.1	1640		7861.1		1068.8	
WC#: 21.170	AFL	3722						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							
21-32-06-200-801-04A	CHECK PNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)							Service ATA:21
PN:2096E010200	MOS	08-Sep-22						MANDATORY 5-40
SN:560	HRS	6221.1	1640		7861.1		1068.8	
WC#: 21.315	AFL	3722						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							
21-32-06-200-801-05	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (975HP) AND (976HP)							Service ATA:21
	MOS	11-Aug-20						
	HRS	5942.6	7500		13442.6		6650.3	
WC#: 21.170	AFL	3569						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							
21-32-06-200-801-05A	INSPECTION/CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY 5-40)							Service ATA:21
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6	7500		13442.6		6650.3	
WC#: 21.170	AFL	3569						
PROC. REF: AMM 21-32-06-200-801	PROC. REF: AMM 21-32-06-200-801							
21-32-06-720-801-01	FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - ELECTROPNEUMATIC VALVE (L74H)							Service ATA:21
PN:2095D01042	MOS	23-Oct-13						
SN:674	HRS	4569.5	4500 (+3%)		9069.5	9204.5	2277.2 (+135)	
	AFL	2879						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-32-06-720-801	PROC. REF: AMM 21-32-06-720-801							
21-32-06-720-801-01A	FUNCTIONAL TEST ELECTROPNEUMATIC REGULATING VALVE (MANDATORY 5-40)							Service ATA:21
PN:2095D01042	MOS	23-Oct-13						MANDATORY 5-40
SN:674	HRS	4569.5	5000		9569.5		2777.2	
WC#: 21.160	AFL	2879						
PROC. REF: AMM 21-32-06-720-801	PROC. REF: AMM 21-32-06-720-801							
21-32-06-720-801-02	FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - PNEUMATIC VALVE (R74H)							Service ATA:21
PN:2096E010200	MOS	08-Sep-22						
SN:560	HRS	6221.1	4500 (+3%)		10721.1	10856.1	3928.8 (+135)	
	AFL	3722						
PROC. REF: AMM 21-32-06-720-801	PROC. REF: AMM 21-32-06-720-801							
21-32-06-720-801-02A	FUNCTIONAL TEST PNEUMATIC REGULATING VALVE (ALTITUDE LIMIT) (MANDATORY 5-40)							Service ATA:21
PN:2096E010200	MOS	08-Sep-22						MANDATORY 5-40
SN:560	HRS	6221.1	5000		11221.1		4428.8	
WC#: 21.170	AFL	3722						
PROC. REF: AMM 21-32-06-720-801	PROC. REF: AMM 21-32-06-720-801							
21-32-06-720-802-01 S	FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - ELECTROPNEUMATIC VALVE (L74H)							Service ATA:21
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 21-32-06-720-802	PROC. REF: AMM 21-32-06-720-802							
21-32-06-720-802-02 S	FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - PNEUMATIC VALVE (R74H)							Service ATA:21
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 21-32-06-720-802	PROC. REF: AMM 21-32-06-720-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-06-900-801-01	REMOVAL / INSTALLATION OF THE ELECTROPNEUMATIC VALVE - ELECTROPNEUMATIC VALVE (L74H)							Component ATA:21
PN:2095D01042	MOS/MSC	23-Oct-13	O/C					
SN:674	HRS	4569.5						
WC#: 21.160	AFL	2879						
PROC. REF: AMM 21-32-06-900-801	PROC. REF: AMM 21-32-06-900-801							
21-32-06-900-802-01	REMOVAL / INSTALLATION OF THE PNEUMATIC VALVE - PNEUMATIC VALVE (R74H)							Component ATA:21
PN:2096E010200	MOS/MSC	08-Sep-22	O/C	TSR 104				
SN:560	HRS	6221.1		TSR 1526.9				
WC#: 21.170	AFL	3722		TSR 765				
PROC. REF: AMM 21-32-06-900-802	PROC. REF: AMM 21-32-06-900-802							
21-32-17-720-801-01 S	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - LH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (L536H)							Service ATA:21
	MOS	11-Aug-20						
	HRS	5942.6	3000 (+30)					
WC#: 21.190	AFL	3569						
								PKG:22
PROC. REF: AMM 21-32-17-720-801	PROC. REF: AMM 21-32-17-720-801							
21-32-17-720-801-01A	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - LH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (L536H) (MANDATORY 5-40)							Service ATA:21
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6	3700		9642.6		2850.3	
WC#: 21.190	AFL	3569						
PROC. REF: AMM 21-32-17-720-801	PROC. REF: AMM 21-32-17-720-801							
21-32-17-720-801-02 S	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - RH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (R536H)							Service ATA:21
	MOS	11-Aug-20						
	HRS	5942.6	3000 (+30)					
WC#: 21.190	AFL	3569						
								PKG:22
PROC. REF: AMM 21-32-17-720-801	PROC. REF: AMM 21-32-17-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-17-720-801-02A		FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - RH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (R536H) (MANDATORY 5-40)						Service ATA:21
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6	3700		9642.6		2850.3	
WC#: 21.190	AFL	3569						
PROC. REF: AMM 21-32-17-720-801	PROC. REF: AMM 21-32-17-720-801							
21-32-33-710-801-01		OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION AND SUPPLY VALVES - BAGGAGE COMPARTMENT ISOLATION VALVE (153H)						Service ATA:21
PN:B97-26-553	MOS	08-Sep-22						
SN:20141	HRS	6221.1	600 (+30)		6821.1	6851.1	28.8 (+30)	
WC#: 21.050	AFL	3722						
PROC. REF: AMM 21-32-33-710-801	PROC. REF: AMM 21-32-33-710-801							
21-32-33-710-801-01A		OPERATIONAL TEST BAGGAGE COMPARTMENT ISOLATION VALVE (MANDATORY 5-40)						Service ATA:21
PN:B97-26-553	MOS	08-Sep-22						MANDATORY 5-40
SN:20141	HRS	6221.1	650		6871.1		78.8	
WC#: 21.050	AFL	3722						
PROC. REF: AMM 21-32-33-710-801	PROC. REF: AMM 21-32-33-710-801							
21-32-33-710-801-02		OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION AND SUPPLY VALVES - BAGGAGE COMPARTMENT HOT AIR SUPPLY VALVE (154H)						Service ATA:21
PN:B97-26-551	MOS	08-Sep-22						
SN:20288	HRS	6221.1	600 (+30)		6821.1	6851.1	28.8 (+30)	
WC#: 21.050	AFL	3722						
PROC. REF: AMM 21-32-33-710-801	PROC. REF: AMM 21-32-33-710-801							
21-32-33-710-801-02A		OPERATIONAL TEST BAGGAGE COMPARTMENT SUPPLY VALVE (MANDATORY 5-40)						Service ATA:21
PN:B97-26-551	MOS	08-Sep-22						MANDATORY 5-40
SN:20288	HRS	6221.1	650		6871.1		78.8	
WC#: 21.050	AFL	3722						
PROC. REF: AMM 21-32-33-710-801	PROC. REF: AMM 21-32-33-710-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-32-38-710-801-01	OPERATIONAL TEST OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - UPPER NEGATIVE PRESSURE RELIEF VALVE (977HP)							Service ATA:21
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 21.180	AFL	0						
PROC. REF: AMM 21-32-38-710-801	PROC. REF: AMM 21-32-38-710-801							
21-32-38-710-801-02	OPERATIONAL TEST OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - LOWER NEGATIVE PRESSURE RELIEF VALVE (978HP)							Service ATA:21
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 21.180	AFL	0						
PROC. REF: AMM 21-32-38-710-801	PROC. REF: AMM 21-32-38-710-801							
21-32-38-820-801-01	CALIBRATION OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - UPPER NEGATIVE PRESSURE RELIEF VALVE (977HP)							Service ATA:21
PN:CYLB50416	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
WC#: 21.180	AFL	0						
PROC. REF: AMM 21-32-38-820-801	PROC. REF: AMM 21-32-38-820-801							
21-32-38-820-801-02	CALIBRATION OF THE CABIN NEGATIVE PRESSURE RELIEF VALVES - LOWER NEGATIVE PRESSURE RELIEF VALVE (978HP)							Service ATA:21
PN:CYLB50416	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
WC#: 21.180	AFL	0						
PROC. REF: AMM 21-32-38-820-801	PROC. REF: AMM 21-32-38-820-801							
21-32-41-200-801-01 S	INSPECTION OF THE NICOTINE FILTER CARTRIDGE - NICOTINE FILTER (534H)							Service ATA:21
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 21.150	AFL	3569						
								PKG:21
PROC. REF: AMM 21-32-41-200-801	PROC. REF: AMM 21-32-41-200-801							
21-51-29-720-801-01 S	FUNCTIONAL TEST OF THE LOWER COOLING UNIT AIR INTAKE DOOR							Service ATA:21
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 21.250	AFL	3569						
								PKG:31
PROC. REF: AMM 21-51-29-720-801	PROC. REF: AMM 21-51-29-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-51-30-640-801-01 S	LUBRICATION OF THE LOWER COOLING UNIT AIR INTAKE DOOR CONTROL CABLE							Service ATA:21
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 21.260	AFL	3875						
								PKG:16
PROC. REF: AMM 21-51-30-640-801PROC. REF: AMM 21-51-30-640-801								
21-52-01-350-801-01	RESTORATION OF THE COOLING UNITS (OVERHAUL) - UPPER COOLING UNIT (R519H)							Service ATA:21
PN:3500C01	MOS	08-Mar-12						OVERHAUL
SN:326	HRS	3996.83	4000		7996.83		1204.5	
WC#: 21.230	AFL	2577						
PROC. REF: AMM 21-52-01-350-801PROC. REF: AMM 21-52-01-350-801								
21-52-01-350-801-02	RESTORATION OF THE COOLING UNITS (OVERHAUL) - LOWER COOLING UNIT (L519H)							Service ATA:21
PN:3500C01	MOS	08-Mar-12						OVERHAUL
SN:397	HRS	3996.83	4000		7996.83		1204.5	
WC#: 21.240	AFL	2577						
PROC. REF: AMM 21-52-01-350-801PROC. REF: AMM 21-52-01-350-801								
21-52-01-900-801-01	REMOVAL / INSTALLATION OF THE UPPER AND LOWER COOLING UNITS - LOWER COOLING UNIT (L519H)							Component ATA:21
PN:3500C01	MOS/MSC	08-Mar-12	H/T	TSR 0				
SN:397	HRS	3996.83		TSR 0				
WC#: 21.240	AFL	2577		TSR 0				
PROC. REF: AMM 21-52-01-900-801PROC. REF: AMM 21-52-01-900-801								
21-52-01-900-801-02	REMOVAL / INSTALLATION OF THE UPPER AND LOWER COOLING UNITS - UPPER COOLING UNIT (R519H)							Component ATA:21
PN:3500C01	MOS/MSC	08-Mar-12	H/T	TSR 0				
SN:326	HRS	3996.83		TSR 0				
WC#: 21.230	AFL	2577		TSR 0				
PROC. REF: AMM 21-52-01-900-801PROC. REF: AMM 21-52-01-900-801								
21-52-05-350-801-01	RESTORATION OF THE TURBOCOOLER (OVERHAUL) - UPPER TURBOCOOLER (R544H)							Service ATA:21
PN:3176C01	MOS	08-Mar-12						OVERHAUL
SN:246	HRS	3996.83	4000 (+3%)		7996.83	8116.83	1204.5 (+120)	
WC#: 21.230	AFL	2577						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-52-05-350-801	PROC. REF: AMM 21-52-05-350-801							
21-52-05-350-801-02	RESTORATION OF THE TURBOCOOLER (OVERHAUL) - LOWER TURBOCOOLER (L544H)							Service ATA:21
PN:3176C01	MOS	08-Mar-12						OVERHAUL
SN:310	HRS	3996.83	4000 (+3%)		7996.83	8116.83	1204.5 (+120)	
WC#: 21.240	AFL	2577						
PROC. REF: AMM 21-52-05-350-801	PROC. REF: AMM 21-52-05-350-801							
21-52-05-610-801-01	TURBOCOOLER OIL SERVICING - LOWER TURBOCOOLER (L544H)							Service ATA:21
	MOS	08-Dec-23						
	HRS	6529.1	600 (+30)		7129.1	7159.1	336.8 (+30)	
WC#: 21.240	AFL	3833						
PROC. REF: AMM 21-52-05-610-801	PROC. REF: AMM 21-52-05-610-801							
21-52-05-610-801-02	TURBOCOOLER OIL SERVICING - UPPER TURBOCOOLER (R544H)							Service ATA:21
	MOS	08-Dec-23						
	HRS	6529.1	600 (+30)		7129.1	7159.1	336.8 (+30)	
WC#: 21.230	AFL	3833						
PROC. REF: AMM 21-52-05-610-801	PROC. REF: AMM 21-52-05-610-801							
21-52-05-700-801-01	TURBOCOOLER OIL LEVEL CHECK - LOWER TURBOCOOLER (L544H)							Service ATA:21
	MOS	24-Oct-25						
	HRS	6700.5	200 (+10%)		6900.5	6920.5	108.2 (+20)	
	AFL	3940						
PROC. REF: AMM 21-52-05-700-801	PROC. REF: AMM 21-52-05-700-801							
21-52-05-700-801-02	TURBOCOOLER OIL LEVEL CHECK - UPPER TURBOCOOLER (R544H)							Service ATA:21
	MOS	24-Oct-25						
	HRS	6700.5	200 (+10%)		6900.5	6920.5	108.2 (+20)	
	AFL	3940						
PROC. REF: AMM 21-52-05-700-801	PROC. REF: AMM 21-52-05-700-801							
21-52-05-900-801-01	REMOVAL / INSTALLATION OF THE TURBOCOOLER - LOWER TURBOCOOLER (L544H)							Component ATA:21
PN:3176C01	MOS/MSC	08-Mar-12	H/T	TSR 0				
SN:310	HRS	3996.83		TSR 0				
WC#: 21.240	AFL	2577		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-52-05-900-801PROC. REF: AMM 21-52-05-900-801								
21-52-05-900-801-02	REMOVAL / INSTALLATION OF THE TURBOCOOLER - UPPER TURBOCOOLER (R544H)							Component ATA:21
PN:3176C01	MOS/MSC	08-Mar-12	H/T	TSR 0				
SN:246	HRS	3996.83		TSR 0				
WC#: 21.230	AFL	2577		TSR 0				
PROC. REF: AMM 21-52-05-900-801PROC. REF: AMM 21-52-05-900-801								
21-64-05-900-801-01	REMOVAL / INSTALLATION OF THE CABIN DUAL TEMPERATURE REGULATING VALVE - COCKPIT DUAL TEMPERATURE REGULATING VALVE (4H)							Component ATA:21
PN:BYLB50418-12	MOS/MSC	11-Jul-95	O/C					
SN:597	HRS	0		TSN 0				
WC#: 21.280	AFL	0						
PROC. REF: AMM 21-64-05-900-801PROC. REF: AMM 21-64-05-900-801								
21-64-05-900-801-02	REMOVAL / INSTALLATION OF THE CABIN DUAL TEMPERATURE REGULATING VALVE - CABIN DUAL TEMPERATURE REGULATING VALVE (164H)							Component ATA:21
PN:BYLB50418-12	MOS/MSC	01-Sep-05	O/C	TSN 1				
SN:813	HRS	2384.8		TSN 0				
WC#: 21.280	AFL	1653		TSN 0				
PROC. REF: AMM 21-64-05-900-801PROC. REF: AMM 21-64-05-900-801								
212101	CABIN AIR CONDITIONING VALVE							Component ATA:21
PN:BYLB50423-1	MOS/MSC	11-Jul-95	O/C					
SN:920	HRS	0		TSN 0				
WC#: 21.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212121	COCKPIT AIR CONDITIONING VALVE							Component ATA:21
PN:BYLB50423-1	MOS/MSC	11-Jul-95	O/C					
SN:923	HRS	0		TSN 0				
WC#: 21.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212141	LH COLD AIR NON RETURN VALVE							Component ATA:21
PN:CYLB50417	MOS/MSC	11-Jul-95	O/C					
SN:563	HRS	0		TSN 0				
WC#: 21.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212146	RH COLD AIR NON RETURN VALVE							Component ATA:21
PN:CYLB50417	MOS/MSC	11-Jul-95	O/C					
SN:564	HRS	0		TSN 0				
WC#: 21.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212151	LH AIR CONDITIONING NON RETURN VALVE							Component ATA:21
PN:CYLB50416	MOS/MSC	11-Jul-95	O/C					
SN:577	HRS	0		TSN 0				
WC#: 21.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212156	RH AIR CONDITIONING NON RETURN VALVE							Component ATA:21
PN:CYLB50416	MOS/MSC	11-Jul-95	O/C					
SN:624	HRS	0		TSN 0				
WC#: 21.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212161	BAGGAGE COMPARTMENT ISOLATION VALVE							Component ATA:21
PN:B97-26-553	MOS/MSC	11-Jul-95	O/C					
SN:20141	HRS	0		TSN 0				
WC#: 21.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212171	BAGGAGE COMPARTMENT SUPPLY VALVE							Component ATA:21
PN:B97-26-551	MOS/MSC	11-Jul-95	O/C					
SN:20288	HRS	0		TSN 0				
WC#: 21.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212181	PILOT AERATOR							Component ATA:21
PN:2368	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212186	COPILOT AERATOR							Component ATA:21
PN:2368	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212201	LH HOT AIR NON RETURN VALVE							Component ATA:21
PN:CYLB50414	MOS/MSC	11-Jul-95	O/C					
SN:1778	HRS	0		TSN 0				
WC#: 21.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212206	RH HOT AIR NON RETURN VALVE							Component ATA:21
PN:CYLB50414	MOS/MSC	11-Jul-95	O/C					
SN:1781	HRS	0		TSN 0				
WC#: 21.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212211	NOSE CONE SHUT OFF VALVE							Component ATA:21
PN:B97M19-201	MOS/MSC	11-Jul-95	O/C					
SN:20167	HRS	0		TSN 0				
WC#: 21.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212241	NOSE CONE PRESSURE RELIEF VALVE							Component ATA:21
PN:P85-533	MOS/MSC	11-Jul-95	O/C					
SN:01128135	HRS	0		TSN 0				
WC#: 21.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212251	LH ELECTRICAL RACK BLOWER							Component ATA:21
PN:125XS01-62-001D	MOS/MSC	11-Jul-95	O/C					
SN:252G	HRS	0		TSN 0				
WC#: 21.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212261	RH ELECTRICAL RACK BLOWER							Component ATA:21
PN:125XS01-62-001D	MOS/MSC	11-Jul-95	O/C					
SN:252D	HRS	0		TSN 0				
WC#: 21.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212271	FRONT TOILET BLOWER							Component ATA:21
PN:125XS01-62-001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213091	NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR							Component ATA:21
PN:7021-000	MOS/MSC	11-Jul-95	O/C					
SN:489	HRS	0		TSN 0				
WC#: 21.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213106	STAND-BY REGULATOR							Component ATA:21
PN:912K101	MOS/MSC	08-May-14	O/C					
SN:129	HRS	4694.5						
WC#: 21.140	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213131	NICOTINE FILTER							Component ATA:21
PN:234A01-01	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213141	UPPER NEGATIVE PRESSURE RELIEF VALVE							Component ATA:21
PN:CYLB50416	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213156	LOWER NEGATIVE PRESSURE RELIEF VALVE							Component ATA:21
PN:CYLB50416	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 21.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213171	LH BAGGAGE COMPARTMENT POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE							Component ATA:21
PN:2832C01	MOS/MSC	11-Jul-95	O/C					
SN:556	HRS	0		TSN 0				
WC#: 21.190	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213191	RH BAGGAGE COMPARTMENT POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE							Component ATA:21
PN:2832C01	MOS/MSC	11-Jul-95	O/C					
SN:557	HRS	0		TSN 0				
WC#: 21.190	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213226	JET PUMP							Component ATA:21
PN:F50B722001	MOS/MSC	11-Jul-95	O/C					
SN:312	HRS	0		TSN 0				
WC#: 21.220	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215113	RH AIR CONDITIONING FLOW LIMITER							Component ATA:21
PN:272SF030100	MOS/MSC	23-Oct-13	H/T	TSO 0				
SN:300	HRS	4569.5		TSO 0				
WC#: 21.070	AFL	2879		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215133	LH AIR CONDITIONING FLOW LIMITER							Component ATA:21
PN:2725F030100	MOS/MSC	23-Oct-13	H/T	TSO 0				
SN:01045	HRS	4569.5		TSO 0				
WC#: 21.070	AFL	2879		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216101	CABIN TEMPERATURE THERMOSTAT							Component ATA:21
PN:150T325	MOS/MSC	11-Jul-95	O/C					
SN:415	HRS	0		TSN 0				
WC#: 21.270	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216106	COCKPIT TEMPERATURE THERMOSTAT							Component ATA:21
PN:150T346	MOS/MSC	11-Jul-95	O/C					
SN:747	HRS	0		TSN 0				
WC#: 21.270	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216126	CABIN TEMPERATURE AMPLIFIER PROBE							Component ATA:21
PN:HYLZ50514-012	MOS/MSC	24-Nov-15	O/C					
SN:447E	HRS	4950.18						
WC#: 21.290	AFL	3093						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216136	COCKPIT TEMPERATURE AMPLIFIER PROBE							Component ATA:21
PN:HYLZ50514-013	MOS/MSC	22-Jun-18	O/C	TSR 13				
SN:100D	HRS	5357.3		TSR 0				
WC#: 21.290	AFL	3346		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216146	CABIN DUCT TEMPERATURE PROBE							Component ATA:21
PN:AYLF50425	MOS/MSC	11-Jul-95	O/C					
SN:1327	HRS	0		TSN 0				
WC#: 21.300	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216151		COCKPIT DUCT TEMPERATURE PROBE						Component ATA:21
PN:AYLF50425	MOS/MSC	11-Jul-95	O/C					
SN:1296	HRS	0		TSN 0				
WC#: 21.300	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216156		AIR CONDITIONING CONTROL BOX						Component ATA:21
PN:5897-651-8	MOS/MSC	08-Jun-16	O/C					
SN:312	HRS	5064.3						
WC#: 21.310	AFL	3203						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 22 - AUTO FLIGHT								
22-10-00-700-801-01 S		CHECK OF THE AP / FD SYSTEM DISENGAGEMENT PROTECTIONS						Service ATA:22
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 22.100	AFL	3569						PKG:21
PROC. REF: AMM 22-10-00-700-801PROC. REF: AMM 22-10-00-700-801								
22-10-00-710-801-01 S		OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)						Service ATA:22
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
WC#: 22.090	AFL	3875						PKG:16
PROC. REF: AMM 22-10-00-710-801, AMM 22-10-00-710-801, AMM 22-10-00-710-801, AMM 22-10-00-710-801PROC. REF: AMM 22-10-00-710-801, AMM 22-10-00-710-801, AMM 22-10-00-710-801, AMM 22-10-00-710-801								
22-10-05-720-801-01 S		FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (210CA)						Service ATA:22
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						PKG:32
PROC. REF: AMM 22-10-05-720-801, AMM 22-10-05-720-801, AMM 22-10-05-720-801PROC. REF: AMM 22-10-05-720-801, AMM 22-10-05-720-801, AMM 22-10-05-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-10-05-720-801-02 S	FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (211CA)							Service ATA:22
PN:622-4404-002	MOS	11-Aug-20	144 (+2m)					
SN:592	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 22-10-05-720-801, AMM 22-10-05-720-801, AMM 22-10-05-720-801PROC. REF: AMM 22-10-05-720-801, AMM 22-10-05-720-801, AMM 22-10-05-720-801								
22-10-05-900-801-01	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (210CA)							Component ATA:22
PN:622-4404-002	MOS/MSC	18-Jun-15	O/C					
SN:593	HRS	4886						
WC#: 22.050	AFL	3054						
PROC. REF: AMM 22-10-05-900-801PROC. REF: AMM 22-10-05-900-801								
22-10-05-900-801-02	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (211CA)							Component ATA:22
PN:622-4404-002	MOS/MSC	18-Jun-15	O/C					
SN:592	HRS	4886						
WC#: 22.060	AFL	3054						
PROC. REF: AMM 22-10-05-900-801PROC. REF: AMM 22-10-05-900-801								
22-10-05-900-801-03	RUDDER AUTOPILOT SERVOMOTOR							Component ATA:22
PN:622-8171-008	MOS/MSC	17-Jul-96	O/C					
SN:5582	HRS	150		TSN 0				
WC#: 22.070	AFL	62						
PROC. REF: AMM 22-10-05-900-801PROC. REF: AMM 22-10-05-900-801								
22-10-07-700-801-01 S	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - AILERON							Service ATA:22
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
WC#: 22.170	AFL	3875						
								PKG:16
PROC. REF: AMM 22-10-07-700-801, AMM 22-10-07-700-801PROC. REF: AMM 22-10-07-700-801, AMM 22-10-07-700-801								
22-10-07-700-801-02 S	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - ELEVATOR							Service ATA:22
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
WC#: 22.170	AFL	3875						
								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
PROC. REF: AMM 22-10-07-700-801, AMM 22-10-07-700-801PROC. REF: AMM 22-10-07-700-801, AMM 22-10-07-700-801								
22-10-07-700-801-03 S	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - RUDDER							Service ATA:22
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
WC#: 22.170	AFL	3875						
								PKG:16
PROC. REF: AMM 22-10-07-700-801PROC. REF: AMM 22-10-07-700-801								
22-10-13-700-801-01	CHECK / ADJUSTMENT OF THE AUTOPILOT SERVOMOTOR CAPSTAN SLIP TORQUE - AILERON SERVOMOTOR CAPSTAN (502CA)							Service ATA:22
PN:622-5028-001	MOS	15-Jul-96						
SN:449	HRS	0	14000 (+3%)		14000	14420	7207.7 (+420)	
WC#: 22.110	AFL	0						
PROC. REF: AMM 22-10-13-700-801PROC. REF: AMM 22-10-13-700-801								
22-10-13-700-801-02	CHECK / ADJUSTMENT OF THE AUTOPILOT SERVOMOTOR CAPSTAN SLIP TORQUE - ELEVATOR SERVOMOTOR CAPSTAN (503CA)							Service ATA:22
PN:622-5028-001	MOS	18-Jun-15						
SN:13XTL	HRS	4886	14000 (+3%)		18886	19306	12093.7 (+420)	
WC#: 22.120	AFL	3054						
PROC. REF: AMM 22-10-13-700-801PROC. REF: AMM 22-10-13-700-801								
22-10-13-720-801-01	RESTORATION OF THE AUTOPILOT SERVOMOTOR CAPSTAN (FUNCTIONAL TEST) - AILERON SERVOMOTOR CAPSTAN (502CA)							Service ATA:22
PN:622-5028-001	MOS/MSC	15-Jul-96	N/A					
SN:449	HRS	0						
WC#: 22.110	AFL	0						
PROC. REF: AMM 22-10-13-720-801PROC. REF: AMM 22-10-13-720-801								
22-10-13-720-801-02	RESTORATION OF THE AUTOPILOT SERVOMOTOR CAPSTAN (FUNCTIONAL TEST) - ELEVATOR SERVOMOTOR CAPSTAN (503CA)							Service ATA:22
PN:622-5028-001	MOS/MSC		N/A					
SN:13XTL	HRS							
WC#: 22.120	AFL							
PROC. REF: AMM 22-10-13-720-801PROC. REF: AMM 22-10-13-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-10-13-720-801-03	RESTORATION OF THE AUTOPILOT SERVOMOTOR CAPSTAN (FUNCTIONAL TEST) - RUDDER SERVOMOTOR CAPSTAN (504CA)							Service ATA:22
PN:792-6785-001	MOS	15-Jul-96						
SN:UNKNOWN	HRS	0	10000 (+3%)		10000	10300	3207.7 (+300)	
WC#: 22.130	AFL	0						
PROC. REF: AMM 22-10-13-720-801	PROC. REF: AMM 22-10-13-720-801							
22-10-13-900-801-01	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTOR CAPSTANS - AILERON SERVOMOTOR CAPSTAN (502CA)							Component ATA:22
PN:622-5028-001	MOS/MSC	17-Jul-96	O/C					
SN:449	HRS	150		TSN 0				
WC#: 22.110	AFL	62						
PROC. REF: AMM 22-10-13-900-801	PROC. REF: AMM 22-10-13-900-801							
22-10-13-900-801-02	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTOR CAPSTANS - ELEVATOR SERVOMOTOR CAPSTAN (503CA)							Component ATA:22
PN:622-5028-001	MOS/MSC	18-Jun-15	O/C	TSO 0				
SN:13XTL	HRS	4886		TSO 0				
WC#: 22.120	AFL	3054		TSO 0				
PROC. REF: AMM 22-10-13-900-801	PROC. REF: AMM 22-10-13-900-801							
22-10-13-900-801-03	REMOVAL / INSTALLATION OF THE AUTOPILOT SERVOMOTOR CAPSTANS - RUDDER SERVOMOTOR CAPSTAN (504CA)							Component ATA:22
PN:792-6785-001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.130	AFL	0						
PROC. REF: AMM 22-10-13-900-801	PROC. REF: AMM 22-10-13-900-801							
22-13-01-350-801-01	RESTORATION OF THE YAW DAMPER ACTUATOR (OVERHAUL) - YAW DAMPER LINEAR ACTUATOR (220CA) OR (2CJ)							Service ATA:22
PN:622-8171-008	MOS	30-Jan-12						OVERHAUL
SN:5548	HRS	3968.8	5000 (+3%)		8968.8	9118.8	2176.5 (+150)	
WC#: 22.160	AFL	2560						
PROC. REF: AMM 22-13-01-350-801	PROC. REF: AMM 22-13-01-350-801							
22-13-01-350-801-01A	RESTORATION OF THE YAW DAMPER ACTUATOR (OVERHAUL) (MANDATORY 5-40)							Service ATA:22
PN:622-8171-008	MOS/MSC	30-Jan-12	O/C					
SN:5548	HRS	3968.8						
	AFL	2560						
PROC. REF: AMM 22-13-01-350-801	PROC. REF: AMM 22-13-01-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-15-00-720-801-01	FUNCTIONAL TEST OF MACH TRIM							Service ATA:22
	MOS/MSC	05-Jan-17	O/C					
	HRS	5149.6						
	AFL	3244						
PROC. REF: AMM 22-15-00-720-801, AMM 22-15-00-720-801PROC. REF: AMM 22-15-00-720-801, AMM 22-15-00-720-801								
221001	AUTOPILOT CONTROL PANEL							Component ATA:22
PN:622-3109-011	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221003	AUTOPILOT MODE SELECTOR							Component ATA:22
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221011	PILOT AUTOPILOT COMPUTER							Component ATA:22
PN:822-1148-116	MOS/MSC	25-Nov-09	O/C					
SN:2074	HRS							
WC#: 22.020	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221015	COPILOT AUTOPILOT COMPUTER							Component ATA:22
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221021	AUTOPILOT AMPLIFIER							Component ATA:22
PN:822-0385-002	MOS/MSC	27-Nov-09	O/C	TSO 0				
SN:1YGYK	HRS	3438.1		TSO 0				
WC#: 22.030	AFL	2257		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221056	YAW DAMPER ACTUATOR							Component ATA:22
PN:622-8171-008	MOS/MSC	11-Jul-95	H/T					
SN:5548	HRS	0		TSN 0				
WC#: 22.160	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221061	AUTOPILOT YAW COMPUTER							Component ATA:22
PN:622-3167-045	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221101	PILOT AUTOPILOT PITCH SERVO CABLE							Component ATA:22
PN:59304	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221106	PILOT AUTOPILOT ROLL SERVO CABLE							Component ATA:22
PN:59309	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
221111	PILOT AUTOPILOT YAW SERVO CABLE							Component ATA:22
PN:59303	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 22.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
222001	MACH TRIM UNIT							Component ATA:22
PN:051162-03	MOS/MSC	11-Jul-95	O/C					
SN:391	HRS	0		TSN 0				
WC#: 22.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-11-05-900-801-01	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 1 ANTENNA (13RC) OR (L210RC)							Component ATA:23
PN:822-0730-314	MOS/MSC	23-Jul-99	O/C					
SN:187	HRS	1045						
WC#: 23.020	AFL	706						
PROC. REF: AMM 23-11-05-900-801	PROC. REF: AMM 23-11-05-900-801							
23-11-05-900-801-02	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 2 ANTENNA (23RC) OR (R215RC)							Component ATA:23
PN:S85-8280-10	MOS/MSC	08-May-14	O/C	TSN 3				
SN:310-25581	HRS	4694.25		TSN 0				
WC#: 23.030	AFL	2957		TSN 0				
PROC. REF: AMM 23-11-05-900-801	PROC. REF: AMM 23-11-05-900-801							
23-11-05-900-801-03	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 3 ANTENNA (93RC) OR (305RC)							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.150	AFL	0		TSN 0				
PROC. REF: AMM 23-11-05-900-801	PROC. REF: AMM 23-11-05-900-801							
23-11-21-900-801-01	REMOVAL / INSTALLATION OF THE VHF TRANSCEIVER - VHF 1 TRANSCEIVER (L220RC)							Component ATA:23
PN:822-1115-001	MOS/MSC	30-Jul-09	O/C	TSO 0				
SN:5406	HRS	3354.3		TSO 0				
WC#: 23.040	AFL	2212		TSO 0				
PROC. REF: AMM 23-11-21-900-801	PROC. REF: AMM 23-11-21-900-801							
23-11-21-900-801-02	REMOVAL / INSTALLATION OF THE VHF TRANSCEIVER - VHF 2 TRANSCEIVER (R220RC)							Component ATA:23
PN:822-1115-001	MOS/MSC	08-Jun-16	O/C					
SN:2468	HRS	5064.3						
WC#: 23.040	AFL	3203						
PROC. REF: AMM 23-11-21-900-801	PROC. REF: AMM 23-11-21-900-801							
23-11-21-900-801-03	REMOVAL / INSTALLATION OF THE VHF TRANSCEIVER - VHF 3 TRANSCEIVER (320RC)							Component ATA:23
PN:622-1334-001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.090	AFL	0						
PROC. REF: AMM 23-11-21-900-801	PROC. REF: AMM 23-11-21-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-12-13-900-801-01	REMOVAL / INSTALLATION OF THE HF ANTENNA - HF ANTENNA (5RE)							Component ATA:23
PN:F50B312001A3	MOS/MSC	11-Jul-95	O/C					
SN:BZ40	HRS	0		TSN 0				
WC#: 23.010	AFL	0						
PROC. REF: AMM 23-12-13-900-801	PROC. REF: AMM 23-12-13-900-801							
23-60-00-760-801-01 S	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS							Service ATA:23
	MOS	11-Aug-20						
	HRS	5942.6	1500					
WC#: 23.060	AFL	3569						
								PKG:21
PROC. REF: AMM 23-60-00-760-801	PROC. REF: AMM 23-60-00-760-801							
23-81-01-900-801-01	REMOVAL / INSTALLATION OF THE RADIO TUNING UNITS (RTU) - RTU 1 (L230RC)							Component ATA:23
PN:822-0730-334	MOS/MSC	08-Dec-23	O/C	TSO 0				
SN:1090	HRS	6529.1		TSO 0				
WC#: 23.050	AFL	3833		TSO 0				
PROC. REF: AMM 23-81-01-900-801	PROC. REF: AMM 23-81-01-900-801							
23-81-01-900-801-02	REMOVAL / INSTALLATION OF THE RADIO TUNING UNITS (RTU) - RTU 2 (R230RC)							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.050	AFL	0		TSN 0				
PROC. REF: AMM 23-81-01-900-801	PROC. REF: AMM 23-81-01-900-801							
231801 U	NO. 1 EMERGENCY COMMUNICATIONS POWER SUPPLY							Component ATA:23
PN:501-1712-02	MOS/MSC	17-Apr-26	O/C	TSR 39				
SN:80271	HRS	6746.8		TSR 396.6				
	AFL	3979		TSR 201				
231802 U	VOLTAGE CHECK NO. 1 EMERGENCY COMMUNICATIONS POWER SUPPLY							Service ATA:23
PN:501-1712-02	MOS	17-Apr-26	6		17-Oct-26		8 d	
SN:80271	HRS	6746.8						
	AFL	3979						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231803 U	CAPACITY TEST NO. 1 EMERGENCY COMMUNICATIONS POWER SUPPLY							Service ATA:23
PN:501-1712-02	MOS	24-Oct-25	12		24-Oct-26		15 d	
SN:80271	HRS	6700.5						
	AFL	3940						
232011	NO. 1 VHF CONTROL							Component ATA:23
PN:G7023-05A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232031	NO. 2 VHF CONTROL							Component ATA:23
PN:822-0730-314	MOS/MSC	08-Feb-05	O/C	TSN 0				
SN:259	HRS	2243		TSN 0				
WC#: 23.050	AFL	1565		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232066	NO. 3 VHF CONTROL							Component ATA:23
PN:516-1025-603	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232071	HF TRANSCEIVER							Component ATA:23
PN:064-1015-01	MOS/MSC	17-Jul-96	O/C					
SN:29242	HRS	150		TSN 0				
WC#: 23.070	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232076	NO. 2 HF TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232081	HF AMPLIFIER COUPLER							Component ATA:23
PN:064-1017-02	MOS/MSC	22-Jun-18	O/C	TSO 4				
SN:X15391	HRS	5357.3		TSO 0				
WC#: 23.070	AFL	3346		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232083	NO. 2 HF AMPLIFIER/ COUPLER							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232086	NO. 1 HF CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232088	NO. 2 HF CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.110	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232111	UHF ANTENNA							Component ATA:23
PN:DMC7-8	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232121	UHF TRANSCEIVER							Component ATA:23
PN:9595-102-03301	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.120	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232131	UHF CONTROL							Component ATA:23
PN:9595-102-00214	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232141	UHF DISPLAY							Component ATA:23
PN:2-39388-A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232801 U	HF CONTROL							Component ATA:23
PN:064-1016-03	MOS/MSC	17-Jul-96	O/C					
SN:9043	HRS	150						
	AFL	62						
232803 U	SELECT PANEL,AUDIO #1							Component ATA:23
PN:B1045-F357-HRS7	MOS/MSC	24-Jul-08	O/C	TSR 0				
SN:9507158	HRS	3036.1		TSR 0				
	AFL	2036		TSR 0				
232805 U	HF NO.2 CONTROL							Component ATA:23
PN:064-1016-03	MOS/MSC	17-Jul-96	O/C					
SN:9359	HRS	150						
	AFL	62						
232807 U	SELECT PANEL,AUDIO NO.2							Component ATA:23
PN:B1045F357HRS7	MOS/MSC	17-Jul-96	O/C					
SN:9507158	HRS	150						
	AFL	62						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232809 U	HF NO.2 TRANSCEIVER							Component ATA:23
PN:064-1015-01	MOS/MSC	17-Jul-96	O/C					
SN:29086	HRS	150						
	AFL	62						
232813 U	AMPLIFIER/COUPLER,HF NO.2							Component ATA:23
PN:064-1017-02	MOS/MSC	17-Jul-96	O/C					
SN:13567	HRS	150						
	AFL	62						
232817 U	SELCAL DECODER							Component ATA:23
PN:1200008-003	MOS/MSC	17-Jul-96	O/C					
SN:135	HRS	150						
	AFL	62						
232849 U	BRIDGING HF #1 AMP							Component ATA:23
PN:071-0019-00	MOS/MSC	17-Jul-96	O/C					
SN:2778	HRS	150						
	AFL	62						
232854 U	BRIDGING HF #2 AMP							Component ATA:23
PN:071-0019-00	MOS/MSC	17-Jul-96	O/C					
SN:2752	HRS	150						
	AFL	62						
233001	PUBLIC ADDRESS (TEAM) AMPLIFIER							Component ATA:23
PN:M1050L358-02	MOS/MSC	23-Jul-99	O/C					
SN:9707231	HRS	1045						
WC#: 23.080	AFL	706						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233006	PILOT AUDIO CONTROL							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.130	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233011	COPILOT AUDIO CONTROL							Component ATA:23
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.160	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233801 U	VIDEO MONITOR-							Component ATA:23
PN:990-4143-002	MOS/MSC	17-Jul-96	O/C					
SN:9508205	HRS	150						
	AFL	62						
233B11 U	PA (BAKER) AMPLIFIER							Component ATA:23
PN:M1052A	MOS/MSC	17-Jul-96	O/C					
SN:9409152	HRS	150						
WC#: 23.160	AFL	62						
235213 U	COMPACT DISC PLAYER,CABIN							Component ATA:23
PN:ECD415	MOS/MSC	17-Jul-96	O/C					
SN:A1800131	HRS	150						
	AFL	62						
235706 U	HNDST,RADIOTELEPHONE CKPT							Component ATA:23
PN:724866-808PD	MOS/MSC	17-Jul-96	O/C					
SN:MX21985	HRS	150						
	AFL	62						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
235711 U	HNDST,RADIOTELEPHONE CAB1							Component ATA:23
PN:724866-807PD	MOS/MSC	17-Jul-96	O/C					
SN:MX21982	HRS	150						
	AFL	62						
235713 U	DATA BUSS RPTR,RT CAB 1							Component ATA:23
PN:724864-801	MOS/MSC	17-Jul-96	O/C					
SN:MSK1049	HRS	150						
	AFL	62						
235716 U	HNDST,RADIOTELEPHONE CAB2							Component ATA:23
PN:724866-805PD	MOS/MSC	17-Jul-96	O/C					
SN:MX22212	HRS	150						
	AFL	62						
235718 U	DATA BUSS RPTR,RT CAB 2							Component ATA:23
PN:724864-801	MOS/MSC	17-Jul-96	O/C					
SN:MSK1046	HRS	150						
	AFL	62						
235746 U	RADIOTELEPHONE DUPLEXER							Component ATA:23
PN:620317-1	MOS/MSC	17-Jul-96	O/C					
SN:LF058	HRS	150						
	AFL	62						
235801 U	FLITEFONE TRANSCEIVER							Component ATA:23
PN:724855-801	MOS/MSC	24-Jul-08	O/C	TSR 2				
SN:MSA0391	HRS	3036.1		TSR 0				
	AFL	2036		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
235811 U	FLITEFONE ANTENNA							Component ATA:23
PN:902131-2	MOS/MSC	17-Jul-96	O/C					
SN:0182	HRS	150						
	AFL	62						
236801 U	FAX MACHINE							Component ATA:23
PN:PF-2	MOS/MSC	17-Jul-96	O/C					
SN:R8200001702	HRS	150						
	AFL	62						
ATA 24 - ELECTRICAL POWER								
24-20-00-720-802-01	FUNCTIONAL TEST OF THE AC GENERATION SYSTEM							Service ATA:24
	MOS/MSC	23-Oct-13	N/A					
	HRS	4513.2						
WC#: 24.040	AFL	2854						
PROC. REF: AMM 24-20-00-720-802	PROC. REF: AMM 24-20-00-720-802							
24-20-01-900-802-01	REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - PILOT INVERTER (2X1)							Component ATA:24
PN:PC17A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.030	AFL	0						
PROC. REF: AMM 24-20-01-900-802	PROC. REF: AMM 24-20-01-900-802							
24-20-01-900-802-02	REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - COPILOT INVERTER (2X2)							Component ATA:24
PN:PC17A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.030	AFL	0						
PROC. REF: AMM 24-20-01-900-802	PROC. REF: AMM 24-20-01-900-802							
24-20-01-900-802-03	REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - ST-BY INVERTER (2X3)							Component ATA:24
PN:PC17A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.030	AFL	0						
PROC. REF: AMM 24-20-01-900-802	PROC. REF: AMM 24-20-01-900-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-20-01-900-802-04		REMOVAL / INSTALLATION OF THE PILOT, COPILOT, EMERGENCY AND INS INVERTERS - INS INVERTER (48X)						Component ATA:24
PN:AL-0581	MOS/MSC	23-Oct-12	O/C	TSR 0				
SN:7729	HRS	4193.5		TSR 0				
WC#: 34.880	AFL	2686		TSR 0				
PROC. REF: AMM 24-20-01-900-802	PROC. REF: AMM 24-20-01-900-802							
24-30-00-710-801-01 S		OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 1						Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 24.230	AFL	3569						
								PKG:21
PROC. REF: AMM 24-30-00-710-801	PROC. REF: AMM 24-30-00-710-801							
24-30-00-710-801-02 S		OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 2						Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 24.230	AFL	3569						
								PKG:21
PROC. REF: AMM 24-30-00-710-801	PROC. REF: AMM 24-30-00-710-801							
24-30-00-710-801-03 S		OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 3						Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 24.230	AFL	3569						
								PKG:21
PROC. REF: AMM 24-30-00-710-801	PROC. REF: AMM 24-30-00-710-801							
24-30-00-710-801-04 S		OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - APU						Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 24.300	AFL	3569						
								PKG:21
PROC. REF: AMM 24-30-00-710-801	PROC. REF: AMM 24-30-00-710-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-09-900-801-01	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 1 (17P1)							Component ATA:24
PN:D22-010-1	MOS/MSC	11-Jul-95	O/C					
SN:80277-02	HRS	0		TSN 0				
WC#: 24.070	AFL	0						
PROC. REF: AMM 24-31-09-900-801	PROC. REF: AMM 24-31-09-900-801							
24-31-09-900-801-02	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 2 (17P2)							Component ATA:24
PN:D22-010-1	MOS/MSC	21-Feb-05	O/C	TSR 15				
SN:1409	HRS	2247.6		TSR 0				
WC#: 24.070	AFL	1570		TSR 0				
PROC. REF: AMM 24-31-09-900-801	PROC. REF: AMM 24-31-09-900-801							
24-31-09-900-801-03	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 3 (17P3)							Component ATA:24
PN:D22-010-1	MOS/MSC	24-Nov-04	O/C	TSN 112				
SN:80444-04	HRS	2182.7						
WC#: 24.070	AFL	1514						
PROC. REF: AMM 24-31-09-900-801	PROC. REF: AMM 24-31-09-900-801							
24-31-09-900-801-04	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - APU GCU (107P)							Component ATA:24
PN:D22-100	MOS/MSC	05-Apr-23	O/C	TSR 0				
SN:1685	HRS	6370.4		TSR 0				
WC#: 24.300	AFL	3783		TSR 0				
PROC. REF: AMM 24-31-09-900-801	PROC. REF: AMM 24-31-09-900-801							
24-31-13-350-801-01	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 1 STARTER-GENERATOR (3P1)							Service ATA:24
PN:8060-360	MOS	11-Aug-20						OVERHAUL
SN:1009	HRS	5942.6	1200 (+3%)		7142.6	7178.6	350.3 (+36)	
WC#: 24.080	AFL	3569						
PROC. REF: AMM 24-31-13-350-801	PROC. REF: AMM 24-31-13-350-801							
24-31-13-350-801-02	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 2 STARTER-GENERATOR (3P2)							Service ATA:24
PN:8060-360	MOS	08-Sep-22						OVERHAUL
SN:258	HRS	6221.1	1200 (+3%)		7421.1	7457.1	628.8 (+36)	
WC#: 24.090	AFL	3722						
PROC. REF: AMM 24-31-13-350-801	PROC. REF: AMM 24-31-13-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-13-350-801-03	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 3 STARTER-GENERATOR (3P3)							Service ATA:24
PN:8060-360	MOS	11-Aug-20						OVERHAUL
SN:1406	HRS	5942.6	1200 (+3%)		7142.6	7178.6	350.3 (+36)	
WC#: 24.085	AFL	3569						
PROC. REF: AMM 24-31-13-350-801	PROC. REF: AMM 24-31-13-350-801							
24-31-13-350-801-04	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - APU STARTER-GENERATOR (103P) OR (21PA)							Service ATA:24
PN:8060-360	MOS	05-Apr-23						OVERHAUL
SN:1048	HRS							
WC#: 24.210	AFL							
	APH	2905.4	1200 (+3%)		4105.4	4141.4	1096.3 (+36)	
PROC. REF: AMM 24-31-13-350-801	PROC. REF: AMM 24-31-13-350-801							
24-31-13-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE STARTER-GENERATORS - ENGINE 1 STARTER-GENERATOR (3P1)							Component ATA:24
PN:8060-360	MOS/MSC	11-Aug-20	H/T	TSO 16				
SN:1009	HRS	5942.6		TSO 0				
WC#: 24.080	AFL	3569		TSO 0				
PROC. REF: AMM 24-31-13-900-801	PROC. REF: AMM 24-31-13-900-801							
24-31-13-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE STARTER-GENERATORS - ENGINE 2 STARTER-GENERATOR (3P2)							Component ATA:24
PN:8060-360	MOS/MSC	08-Sep-22	H/T	TSO 0				
SN:258	HRS	6221.1		TSO 0				
WC#: 24.090	AFL	3722		TSO 0				
PROC. REF: AMM 24-31-13-900-801	PROC. REF: AMM 24-31-13-900-801							
24-31-13-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE STARTER-GENERATORS - ENGINE 3 STARTER-GENERATOR (3P3)							Component ATA:24
PN:8060-360	MOS/MSC	11-Aug-20	H/T	TSO 70				
SN:1406	HRS	5942.6		TSO 0				
WC#: 24.085	AFL	3569		TSO 0				
PROC. REF: AMM 24-31-13-900-801	PROC. REF: AMM 24-31-13-900-801							
24-31-17-220-803-01	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (3P1)							Service ATA:24
PN:8060-360	MOS	09-Apr-25						
SN:1009	HRS	6648.6	150 (+3%)		6798.6	6803.1	6.3 (+4.5)	
	AFL	3909						
PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803	PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-17-220-803-02		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (3P2)						Service ATA:24
PN:8060-360	MOS	08-Sep-22						
SN:258	HRS	6221.1	T:600 (+60)		6821.1	6881.1	28.8 (+60)	
	AFL	3722						
PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803								
24-31-17-220-803-03		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (3P3)						Service ATA:24
PN:8060-360	MOS	09-Apr-25						
SN:1406	HRS	6648.6	150 (+3%)		6798.6	6803.1	6.3 (+4.5)	
	AFL	3909						
PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803PROC. REF: AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803, AMM 24-31-17-220-803								
24-32-00-710-803-01	S	OPERATIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P1)						Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 24-32-00-710-803PROC. REF: AMM 24-32-00-710-803								
24-32-00-710-803-02	S	OPERATIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P2)						Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 24-32-00-710-803PROC. REF: AMM 24-32-00-710-803								
24-32-00-720-801-01		FUNCTIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P1)						Service ATA:24
	MOS/MSC	08-May-14	O/C					
	HRS	4694.25						
	AFL	2957						
PROC. REF: AMM 24-32-00-720-801PROC. REF: AMM 24-32-00-720-801								
24-32-00-720-801-02		FUNCTIONAL TEST OF THE BATTERY BUS DIODES - DIODE (59P2)						Service ATA:24
	MOS/MSC	08-May-14	O/C					
	HRS	4694.25						
	AFL	2957						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
PROC. REF: AMM 24-32-00-720-801	PROC. REF: AMM 24-32-00-720-801							
24-32-01-350-801-01	RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 1 (2P1)							Service ATA:24
PN:276CH10	MOS	14-May-25	33 (+3%)		14-Feb-28	13-Mar-28	493 d (+28)	OVERHAUL
SN:201802260	HRS	6657	1700 (+3%)		8357	8408	1564.7 (+51)	
WC#: 24.100	AFL	3912						
PROC. REF: AMM 24-32-01-350-801	PROC. REF: AMM 24-32-01-350-801							
24-32-01-350-801-02	RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 2 (2P2)							Service ATA:24
PN:276CH10	MOS	02-May-25	33 (+3%)		02-Feb-28	01-Mar-28	481 d (+28)	OVERHAUL
SN:202104463	HRS	6648.6	1700 (+3%)		8348.6	8399.6	1556.3 (+51)	
WC#: 24.190	AFL	3909						
PROC. REF: AMM 24-32-01-350-801	PROC. REF: AMM 24-32-01-350-801							
24-32-01-700-801-01	REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 1 (2P1)							Service ATA:24
PN:276CH10	MOS	14-May-25	16 (+1m)		14-Sep-26	14-Oct-26	TOL (+5 d)	
SN:201802260	HRS	6657	850 (+85)		7507	7592	714.7 (+85)	
WC#: 24.100	AFL	3912						
PROC. REF: AMM 24-32-01-700-801	PROC. REF: AMM 24-32-01-700-801							
24-32-01-700-801-02	REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 2 (2P2)							Service ATA:24
PN:276CH10	MOS	02-May-25	16 (+1m)		02-Sep-26	02-Oct-26	OVD	
SN:202104463	HRS	6648.6	850 (+85)		7498.6	7583.6	706.3 (+85)	
WC#: 24.190	AFL	3909						
PROC. REF: AMM 24-32-01-700-801	PROC. REF: AMM 24-32-01-700-801							
24-32-01-900-801-01	REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 1 (2P1)							Component ATA:24
PN:276CH10	MOS/MSC	14-May-25	O/C	TSO 3				
SN:201802260	HRS	6657		TSO 0				
WC#: 24.100	AFL	3912		TSO 0				
PROC. REF: AMM 24-32-01-900-801	PROC. REF: AMM 24-32-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-01-900-801-02	REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 2 (2P2)							Component ATA:24
PN:276CH10	MOS/MSC	02-May-25	O/C	TSR 2				
SN:202104463	HRS	6648.6		TSR 0				
WC#: 24.190	AFL	3909		TSR 0				
PROC. REF: AMM 24-32-01-900-801	PROC. REF: AMM 24-32-01-900-801							
24-32-05-710-801-01	OPERATIONAL TEST OF THE BATTERY FAN - BATTERY FAN (55P)							Service ATA:24
PN:018804-000(2376-4)	MOS/MSC	14-Jul-12	C/C					
SN:090520011F51A	HRS	4125.5						
WC#: 24.170	AFL	2653						
PROC. REF: AMM 24-32-05-710-801	PROC. REF: AMM 24-32-05-710-801							
24-32-09-610-801-01	SERVICING STAND-BY HORIZON POWER SUPPLY (NICKEL-CADMIUM BATTERY ONLY)							Service ATA:24
PN:804747	MOS	24-Oct-25	12 (+1m)		24-Oct-26	24-Nov-26	15 d (+31)	
SN:3011	HRS	6700.5						
	AFL	3940						
PROC. REF: AMM 24-32-09-610-801, AMM 24-32-09-610-801	PROC. REF: AMM 24-32-09-610-801, AMM 24-32-09-610-801							
24-32-09-610-801-02	SERVICING NO. 1 IRS EMERGENCY POWER SUPPLY (NICKEL-CADMIUM BATTERY ONLY)							Service ATA:24
PN:804747	MOS	24-Oct-25	12 (+3%)		24-Oct-26	04-Nov-26	15 d (+11)	
SN:3251	HRS	6700.5						
WC#: 34.890	AFL	3940						
PROC. REF: AMM 24-32-09-610-801, AMM 24-32-09-610-801, AMM 24-32-09-610-801, AMM 24-32-09-610-801	PROC. REF: AMM 24-32-09-610-801, AMM 24-32-09-610-801, AMM 24-32-09-610-801, AMM 24-32-09-610-801							
24-32-09-610-801-03	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)							Service ATA:24
PN:804747	MOS	24-Oct-25	12 (+1m)		24-Oct-26	24-Nov-26	15 d (+31)	
SN:3219	HRS	6700.5						
	AFL	3940						
PROC. REF: AMM 24-32-09-610-801	PROC. REF: AMM 24-32-09-610-801							
24-32-09-610-801-04	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)							Service ATA:24
PN:PN-UNKNOWN	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 24-32-09-610-801	PROC. REF: AMM 24-32-09-610-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-610-801-05	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - AUXILIARY BATTERY (710PE)							Service ATA:24
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 23.100	AFL	0						
PROC. REF: AMM 24-32-09-610-801	PROC. REF: AMM 24-32-09-610-801							
24-32-09-610-801-06	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (85RC)							Service ATA:24
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 24-32-09-610-801	PROC. REF: AMM 24-32-09-610-801							
24-32-09-610-801-07	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 1 STAND-BY BATTERY (17RC)							Service ATA:24
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 24-32-09-610-801	PROC. REF: AMM 24-32-09-610-801							
24-32-09-610-802-01	SERVICING OF "J.E.T." LEAD / ACID STAND-BY BATTERIES - VOLTAGE TEST OF THE BATTERY							Service ATA:24
PN:804747	MOS/MSC		N/A					
SN:3011	HRS							
	AFL							
PROC. REF: AMM 24-32-09-610-802	PROC. REF: AMM 24-32-09-610-802							
24-32-09-610-802-02	SERVICING OF "J.E.T." LEAD / ACID STAND-BY BATTERIES - CAPACITY TEST OF THE BATTERY							Service ATA:24
PN:804747	MOS/MSC		N/A					
SN:3011	HRS							
	AFL							
PROC. REF: AMM 24-32-09-610-802	PROC. REF: AMM 24-32-09-610-802							
24-32-09-710-802-01	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (5F)							Service ATA:24
PN:804747	MOS/MSC		N/A					
SN:3011	HRS							
	AFL							
PROC. REF: AMM 24-32-09-710-802	PROC. REF: AMM 24-32-09-710-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-710-802-04	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)							Service ATA:24
PN:PN-UNKNOWN	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
WC#: 34.950	AFL	0						
PROC. REF: AMM 24-32-09-710-802	PROC. REF: AMM 24-32-09-710-802							
24-32-09-710-802-05	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - AUXILIARY BATTERY (710PE)							Service ATA:24
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 24-32-09-710-802	PROC. REF: AMM 24-32-09-710-802							
24-32-09-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (5F)							Component ATA:24
PN:804747	MOS/MSC	24-Oct-25	O/C	TSN 37				
SN:3011	HRS	6700.5		TSN 479.4				
WC#: 34.380	AFL	3940		TSN 218				
PROC. REF: AMM 24-32-09-900-801	PROC. REF: AMM 24-32-09-900-801							
24-32-09-900-801-02	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 1 STAND-BY BATTERY (195NP)							Component ATA:24
PN:804747	MOS/MSC	24-Oct-25	O/C	TSN 31				
SN:3251	HRS	6700.5		TSN 350.3				
WC#: 34.950	AFL	3940		TSN 162				
PROC. REF: AMM 24-32-09-900-801	PROC. REF: AMM 24-32-09-900-801							
24-32-09-900-801-03	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 2 STAND-BY BATTERY (295NP)							Component ATA:24
PN:804747	MOS/MSC	24-Oct-25	O/C	TSN 36				
SN:3219	HRS	6700.5		TSN 363.2				
WC#: 34.950	AFL	3940		TSN 169				
PROC. REF: AMM 24-32-09-900-801	PROC. REF: AMM 24-32-09-900-801							
24-32-09-900-801-04	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 3 STAND-BY BATTERY (95NP)							Component ATA:24
PN:PN-UNKNOWN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.950	AFL	0						
PROC. REF: AMM 24-32-09-900-801	PROC. REF: AMM 24-32-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-32-09-900-801-05	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - AUXILIARY BATTERY (710PE)							Component ATA:24
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-32-09-900-801	PROC. REF: AMM 24-32-09-900-801							
24-32-09-900-801-06	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (85RC)							Component ATA:24
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 23.100	AFL	0		TSN 0				
PROC. REF: AMM 24-32-09-900-801	PROC. REF: AMM 24-32-09-900-801							
24-32-09-900-801-07	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - VHF 1 STAND-BY BATTERY (17RC)							Component ATA:24
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-32-09-900-801	PROC. REF: AMM 24-32-09-900-801							
24-32-09-960-802-01	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - STAND-BY HORIZON BATTERY (5F)							Service ATA:24
PN:804747	MOS/MSC		N/A					
SN:3011	HRS							
	AFL							
PROC. REF: AMM 24-32-09-960-802	PROC. REF: AMM 24-32-09-960-802							
24-32-09-960-802-04	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 3 STAND-BY BATTERY (95NP)							Service ATA:24
PN:PN-UNKNOWN	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
WC#: 34.950	AFL	0						
PROC. REF: AMM 24-32-09-960-802	PROC. REF: AMM 24-32-09-960-802							
24-32-09-960-802-05	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - AUXILIARY BATTERY (710PE)							Service ATA:24
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 24-32-09-960-802	PROC. REF: AMM 24-32-09-960-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-33-01-900-801-01	REMOVAL / INSTALLATION OF THE APU STARTER-GENERATOR - APU STARTER-GENERATOR (103P) OR (21PA)							Component ATA:24
PN:8060-360	MOS/MSC	05-Apr-23	H/T	TSO 0				
SN:1048	HRS			TSO 0				
WC#: 24.210	AFL			TSO 0				
	APH	2905.4	0	TSN 10399, TSO 0				
PROC. REF: AMM 24-33-01-900-801	PROC. REF: AMM 24-33-01-900-801							
24-33-05-220-803-01	CHECK OF THE APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (103P) OR (21PA)							Service ATA:24
PN:8060-360	MOS	05-Apr-23						
SN:1048	HRS							
	AFL							
	APH	2905.4	150 (+3%)		3055.4	3059.9	46.3 (+4.5)	
PROC. REF: AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803	PROC. REF: AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803, AMM 24-33-05-220-803							
24-40-00-720-801-01 S	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB - GPU OVERVOLTAGE PROTECTION PCB (42P)							Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 24.250	AFL	3569						
								PKG:21
PROC. REF: AMM 24-40-00-720-801	PROC. REF: AMM 24-40-00-720-801							
24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE CHARGING FUNCTION							Service ATA:24
	MOS/MSC	23-Oct-13	N/A					
	HRS	4513.2						
	AFL	2854						
PROC. REF: AMM 24-41-00-720-801	PROC. REF: AMM 24-41-00-720-801							
24-41-00-720-801-02	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES							Service ATA:24
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 24-41-00-720-801	PROC. REF: AMM 24-41-00-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-63-13-710-801-01 S	OPERATIONAL TEST OF THE DOME LIGHT PCB - DOME LIGHT PCB (415J)							Service ATA:24
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 24.270	AFL	3569						
								PKG:21
PROC. REF: AMM 24-63-13-710-801	PROC. REF: AMM 24-63-13-710-801							
240011	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI915	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 39.020	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
240016	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI852A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 39.020	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
240021	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI853B	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 39.020	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
240026	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI854A	MOS/MSC	24-May-10	O/C	TSN 0				
SN:320	HRS	3546.83		TSN 0				
WC#: 39.030	AFL	2326		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
240031	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI855B	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 39.030	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
240036	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI857	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 39.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
240041	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI857	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 39.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
240046	PRINTED CIRCUIT BOARD							Component ATA:24
PN:CI955B	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 39.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242101	ALTERNATING CURRENT VOLTMETER							Component ATA:24
PN:2396-213-0	MOS/MSC	11-Jul-95	O/C					
SN:622	HRS	0		TSN 0				
WC#: 24.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242111	NO. 1 FREQUENCY MONITOR PRINTED CARD							Component ATA:24
PN:C1-818A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242116	NO. 2 FREQUENCY MONITOR PRINTED CARD							Component ATA:24
PN:C1-818A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243191	NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE							Component ATA:24
PN:P600-14B	MOS/MSC	13-Dec-06	O/C					
SN:12599	HRS	2522		TSN 2522				
WC#: 24.100	AFL	1744		TSN 1744				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243196	NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE							Component ATA:24
PN:P600-14B	MOS/MSC	02-Oct-24	O/C	TSR 1				
SN:08707	HRS	6601.6		TSR 0				
WC#: 24.190	AFL	3875		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243211	NO. 1 BATTERY CONNECTOR							Component ATA:24
PN:410	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243213	NO. 1 BATTERY REVERSE CURRENT RELAY							Component ATA:24
PN:317GC01Y1AB	MOS/MSC	11-Jul-95	O/C					
SN:810	HRS	0		TSN 0				
WC#: 24.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243216	NO. 2 BATTERY CONNECTOR							Component ATA:24
PN:410	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243219	NO. 2 BATTERY REVERSE CURRENT RELAY							Component ATA:24
PN:317GC01Y1AB	MOS/MSC	11-Jul-95	O/C					
SN:811	HRS	0		TSN 0				
WC#: 24.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243221	BATTERY FAN							Component ATA:24
PN:018804-000(2376-4)	MOS/MSC	14-Jul-12	O/C					
SN:090520011F51A	HRS	4125.5						
WC#: 24.170	AFL	2653						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243236	NO. 1 GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:3510M0	MOS/MSC	11-Jul-95	O/C					
SN:3583	HRS	0		TSN 0				
WC#: 24.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243238	NO. 1 STARTER/ RELAY							Component ATA:24
PN:2540M	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.160	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243241	NO. 2 GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:3510M0	MOS/MSC	11-Jul-95	O/C					
SN:3585	HRS	0		TSN 0				
WC#: 24.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243243	NO. 2 STARTER/ RELAY							Component ATA:24
PN:2540M	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.160	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243246	NO. 3 GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:3510M0	MOS/MSC	11-Jul-95	O/C					
SN:3584	HRS	0		TSN 0				
WC#: 24.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243248	NO. 3 STARTER/ RELAY							Component ATA:24
PN:2540M	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.160	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243249	APU GENERATOR REVERSE CURRENT RELAY							Component ATA:24
PN:3510M0	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.280	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243250	APU STARTER RELAY							Component ATA:24
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.290	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243251	LH POWER SUPPLY DC VOLTMETER							Component ATA:24
PN:2396-118-0	MOS/MSC	11-Jul-95	O/C					
SN:1404	HRS	0		TSN 0				
WC#: 24.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243261	RH POWER SUPPLY DC VOLTMETER							Component ATA:24
PN:2396-118-0	MOS/MSC	11-Jul-95	O/C					
SN:1401	HRS	0		TSN 0				
WC#: 24.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243271	LH POWER SUPPLY DC AMMETER							Component ATA:24
PN:2396-323-0	MOS/MSC	11-Jul-95	O/C					
SN:1072	HRS	0		TSN 0				
WC#: 24.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243281	RH POWER SUPPLY DC AMMETER							Component ATA:24
PN:2396-323-0	MOS/MSC	11-Jul-95	O/C					
SN:1075	HRS	0		TSN 0				
WC#: 24.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243291	BATTERY TEMPERATURE INDICATOR							Component ATA:24
PN:BTI600-3A	MOS/MSC	17-Jul-96	O/C					
SN:3456	HRS	150						
WC#: 24.200	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
244401	GROUND POWER RECEPTACLE							Component ATA:24
PN:280B	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 25 - EQUIPMENT/FURNISHINGS								
25-00-01-200-801-01	INSPECTION OF THE ONBOARD KIT							Service ATA:25
	MOS/MSC	25-May-17	O/C					
	HRS	5157.3						
WC#: 25.220	AFL	3249						
PROC. REF: AMM 25-00-01-200-801PROC. REF: AMM 25-00-01-200-801								
25-11-01-900-801-01	REMOVAL / INSTALLATION OF THE PILOT SEATS - LH PILOT SEAT (L2MG)							Component ATA:25
PN:394-14	MOS/MSC	05-Apr-19	O/C					
SN:304	HRS	5705.9		TSN 5705.9				
WC#: 25.010	AFL	3477						
PROC. REF: AMM 25-11-01-900-801PROC. REF: AMM 25-11-01-900-801								
25-11-01-900-801-02	REMOVAL / INSTALLATION OF THE PILOT SEATS - RH PILOT SEAT (R2MG)							Component ATA:25
PN:394-24	MOS/MSC	05-Apr-19	O/C					
SN:304	HRS	5705.9		TSN 5705.9				
WC#: 25.010	AFL	3477						
PROC. REF: AMM 25-11-01-900-801PROC. REF: AMM 25-11-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-05-200-801-01A	VISUAL INSPECTION OF BUCKLE SPRING OF ANJOU AERONAUTIQUE SAFETY BELTS AND RESTRAINT SYSTEM (TYPE 343 AMD 343-1)							Service ATA:25
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 25-11-05-200-801	PROC. REF: AMM 25-11-05-200-801							
25-11-05-220-801-01 S	DETAILED INSPECTION OF THE PILOT SEAT SAFETY BELT ASSEMBLY - LH PILOT SEAT (L2MG)							Service ATA:25
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 25-11-05-220-801	PROC. REF: AMM 25-11-05-220-801							
25-11-05-220-801-02 S	DETAILED INSPECTION OF THE PILOT SEAT SAFETY BELT ASSEMBLY - RH PILOT SEAT (R2MG)							Service ATA:25
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 25-11-05-220-801	PROC. REF: AMM 25-11-05-220-801							
25-11-13-640-801-01 S	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - LH PILOT SEAT (L2MG)							Service ATA:25
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 25.010	AFL	3569						
								PKG:21
PROC. REF: AMM 25-11-13-640-801	PROC. REF: AMM 25-11-13-640-801							
25-11-13-640-801-02 S	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - RH PILOT SEAT (R2MG)							Service ATA:25
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 25.010	AFL	3569						
								PKG:21
PROC. REF: AMM 25-11-13-640-801	PROC. REF: AMM 25-11-13-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-19-960-801-01 S	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - LH PILOT SEAT (L2MG)							Service ATA:25
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 25-11-19-960-801	PROC. REF: AMM 25-11-19-960-801							
25-11-19-960-801-02 S	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - RH PILOT SEAT (R2MG)							Service ATA:25
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 25-11-19-960-801	PROC. REF: AMM 25-11-19-960-801							
25-40-25-100-801-01	CLEANING OF THE TRASH CANS							Service ATA:25
	MOS	02-Oct-24						
	HRS	6601.6	1000		7601.6		809.3	
WC#: 25.060	AFL	3875						
PROC. REF: AMM 25-40-25-100-801	PROC. REF: AMM 25-40-25-100-801							
25-60-00-200-801-02 S	INSPECTION OF THE SAFETY EQUIPMENT - SAFETY EQUIPMENT							Service ATA:25
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 25.200	AFL	3875						
								PKG:16
PROC. REF: AMM 25-60-00-200-801	PROC. REF: AMM 25-60-00-200-801							
25-60-00-200-801-03	INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT							Service ATA:25
	MOS	24-Oct-25	12		24-Oct-26		15 d	
	HRS	6700.5						
	AFL	3940						
PROC. REF: AMM 25-60-00-200-801	PROC. REF: AMM 25-60-00-200-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)							Service ATA:25
	MOS	24-Oct-25	12		24-Oct-26		15 d	MANDATORY
	HRS	6700.5						
	AFL	3940						
PROC. REF: GENERIC NO REF, FAR 91.207PROC. REF: GENERIC NO REF, FAR 91.207								
25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT 96/97							Service ATA:25
	MOS/MSC	08-May-14	O/C					
	HRS	4694.25						
WC#: 25.210	AFL	2957						
PROC. REF: AMM 25-61-00-710-801PROC. REF: AMM 25-61-00-710-801								
25-61-01-900-803-01	REMOVAL / INSTALLATION OF THE ELT AND REPLACEMENT OF THE ELT BATTERY PACKS (ELT 90 / 91 OR ELT 96 / 97) - ELT (32RB)							Component ATA:25
PN:453-5000	MOS/MSC	30-Apr-24	O/C	TSR 32				
SN:06791	HRS	6553		TSR 478.2				
WC#: 25.210	AFL	3851		TSR 215				
PROC. REF: AMM 25-61-01-900-803PROC. REF: AMM 25-61-01-900-803								
25-61-13-960-801-01	DISCARD OF THE ELT BATTERY PACKS - ELT (32RB) OR ELT (61RC)							Service ATA:25
PN:453-5000	MOS/MSC	30-Apr-24	DUE		31-Jul-29 (M)		1026 d	LIFE LIMIT
SN:06791	HRS	6553						
	AFL	3851						
PROC. REF: AMM 25-61-13-960-801PROC. REF: AMM 25-61-13-960-801								
25-62-00-900-801-01	REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (10FZ1)							Component ATA:25
PN:DK120/90	MOS/MSC	11-Aug-20	O/C	TSN 0				
SN:AT145745	HRS	5942.6		TSN 0				
	AFL	3569		TSN 0				
PROC. REF: AMM 25-62-00-900-801PROC. REF: AMM 25-62-00-900-801								
25-62-00-900-801-02	REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (130FZ1)							Component ATA:25
PN:DK120/90	MOS/MSC	08-Sep-22	O/C	TSN 0				
SN:AT174057	HRS	6221.1		TSN 0				
	AFL	3722		TSN 0				
PROC. REF: AMM 25-62-00-900-801PROC. REF: AMM 25-62-00-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-01-720-801-01	FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (10FZ1)							Service ATA:25
PN:DK120/90	MOS	02-Oct-24	25		02-Nov-26		24 d	
SN:AT145745	HRS	6601.6						
WC#: 31.100	AFL	3875						
PROC. REF: AMM 25-62-01-720-801	PROC. REF: AMM 25-62-01-720-801							
25-62-01-720-801-02	FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (130FZ1)							Service ATA:25
	MOS	02-Oct-24	25		02-Nov-26		24 d	
	HRS	6601.6						
WC#: 31.110	AFL	3875						
PROC. REF: AMM 25-62-01-720-801	PROC. REF: AMM 25-62-01-720-801							
25-62-05-960-801-01	RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - CVR UNDERWATER LOCATOR BEACON (10FZ1)							Service ATA:25
PN:DK120/90	MOS/MSC	02-Oct-24	DUE	TAC 4	30-Apr-27 (M)		203 d	LIFE LIMIT
SN:AT145745	HRS	6601.6						
WC#: 31.100	AFL	3875						
PROC. REF: AMM 25-62-05-960-801	PROC. REF: AMM 25-62-05-960-801							
25-62-05-960-801-02	RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - FDR UNDERWATER LOCATOR BEACON (130FZ1)							Service ATA:25
	MOS/MSC	08-Sep-22	DUE		31-Jan-29 (M)		845 d	LIFE LIMIT
	HRS	6221.1						
WC#: 31.110	AFL	3722						
PROC. REF: AMM 25-62-05-960-801	PROC. REF: AMM 25-62-05-960-801							
25-62-11-050-001 U	EMERGENCY LOCATOR TRANSMITTER (ELT 406) -							Component ATA:25
PN:453-5000	MOS/MSC	30-Apr-24	O/C	TSR 32				STC ICA
SN:06791	HRS	6553		TSR 478.2				
	AFL	3851		TSR 215				
25-62-11-220-001 U	INSPECTION EMERGENCY LOCATOR TRANSMITTER (ELT 406) - COAX CABLES AND WIRING CONNECTIONS							Service ATA:25
PN:453-5000	MOS	24-Oct-25	12		24-Oct-26		15 d	ICA
SN:06791	HRS	6700.5	100		6800.5		8.2	
	AFL	3940						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-350-802-01	RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - LH PILOT LIFE VEST (L10ME)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:17010530024	HRS	5157.3						
WC#: 25.190	AFL	3249						
PROC. REF: AMM 25-64-17-350-802	PROC. REF: AMM 25-64-17-350-802							
25-64-17-350-802-02	RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - RH PILOT LIFE VEST (R10ME)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:170105530023	HRS	5157.3						
WC#: 25.190	AFL	3249						
PROC. REF: AMM 25-64-17-350-802	PROC. REF: AMM 25-64-17-350-802							
25-64-17-350-802-03	RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - THIRD CREW MEMBER LIFE VEST (M10ME)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:17010530022	HRS	5157.3						
	AFL	3249						
PROC. REF: AMM 25-64-17-350-802	PROC. REF: AMM 25-64-17-350-802							
25-64-17-350-803-01	RESTORATION NO. 1 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:17010530015	HRS	5157.3						
WC#: 25.100	AFL	3249						
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
25-64-17-350-803-01	RESTORATION NO. 2 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:17010530019	HRS	5157.3						
WC#: 25.110	AFL	3249						
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
25-64-17-350-803-01	RESTORATION NO. 3 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:17010530020	HRS	5157.3						
WC#: 25.120	AFL	3249						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
25-64-17-350-803-01	RESTORATION NO. 4 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:17010530021	HRS	5157.3						
WC#: 25.130	AFL	3249						
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
25-64-17-350-803-01	RESTORATION NO. 5 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:17010530025	HRS	5157.3						
WC#: 25.140	AFL	3249						
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
25-64-17-350-803-01	RESTORATION NO. 6 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:16111520015	HRS	5157.3						
WC#: 25.150	AFL	3249						
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
25-64-17-350-803-01	RESTORATION NO. 7 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:170105530016	HRS	5157.3						
WC#: 25.160	AFL	3249						
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
25-64-17-350-803-01	RESTORATION NO. 8 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:P01074-209WC	MOS	25-May-17	120		25-May-27		228 d	OVERHAUL
SN:14080540004	HRS	5157.3						
WC#: 25.170	AFL	3249						
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-64-17-350-803-01	RESTORATION NO. 9 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)							Service ATA:25
PN:63600-505	MOS	26-Oct-19	120		26-Oct-29		1113 d	OVERHAUL
SN:L4858944	HRS							
WC#: 25.180	AFL							
PROC. REF: AMM 25-64-17-350-803	PROC. REF: AMM 25-64-17-350-803							
251121	PILOT SEAT BELT							Component ATA:25
PN:1101167-09	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.020	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
251126	COPILOT SEAT BELT							Component ATA:25
PN:1101167-09	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.020	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
251130	PILOT SHOULDER HARNESS							Component ATA:25
PN:2825A3X03	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
251135	COPILOT SHOULDER HARNESS							Component ATA:25
PN:2825A3X03	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 25.030	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
251141	PILOT HEATING CARPET							Component ATA:25
PN:592046	MOS/MSC	11-Jul-95	O/C					
SN:333	HRS	0		TSN 0				
WC#: 25.050	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
251146	COPILOT HEATING CARPET							Component ATA:25
PN:592045	MOS/MSC	11-Jul-95	O/C					
SN:328	HRS	0		TSN 0				
WC#: 25.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
251151	THIRD CREW MEMBER HEATING CARPET							Component ATA:25
PN:592044	MOS/MSC	11-Jul-95	O/C					
SN:339	HRS	0						
WC#: 25.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
255801 U	MINI COMPUTER							Component ATA:25
PN:149500-005	MOS/MSC	17-Jul-96	O/C					
SN:6437HFJ50466	HRS	150						
	AFL	62						
255806 U	MINI COMPUTER PRINTER							Component ATA:25
PN:180SI	MOS/MSC	17-Jul-96	O/C					
SN:PAA31YP411	HRS	150						
	AFL	62						
256001	NO. 1 LIFE RAFT							Component ATA:25
PN:RAF1212-301	MOS/MSC	02-May-25	O/C	TSO 1				
SN:1621JGA	HRS	6648.6		TSO 0				
WC#: 25.070	AFL	3909		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256006	INSPECT/CHECK NO. 1 LIFE RAFT							Service ATA:25
PN:RAF1212-301	MOS	02-May-25	36		08-Apr-28		547 d	
SN:1621JGA	HRS	6648.6						
WC#: 25.070	AFL	3909						
		Service Date: : 08-Apr-25						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256031	NO. 1 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:17010530015	HRS	5157.3		TSN 0				
WC#: 25.100	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256041	NO. 2 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:17010530019	HRS	5157.3		TSN 0				
WC#: 25.110	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256051	NO. 3 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:17010530020	HRS	5157.3		TSN 0				
WC#: 25.120	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256061	NO. 4 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:17010530021	HRS	5157.3		TSN 0				
WC#: 25.130	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256071	NO. 5 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:17010530025	HRS	5157.3		TSN 0				
WC#: 25.140	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256081	NO. 6 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:16111520015	HRS	5157.3		TSN 0				
WC#: 25.150	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256091	NO. 7 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:170105530016	HRS	5157.3		TSN 0				
WC#: 25.160	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256101	NO. 8 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C					
SN:14080540004	HRS	5157.3						
WC#: 25.170	AFL	3249						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256111	NO. 9 PASSENGER LIFE VEST							Component ATA:25
PN:63600-505	MOS/MSC	05-Jan-22	O/C	TSN 26				
SN:L4858944	HRS	6119.7		TSN 0				
WC#: 25.180	AFL	3679		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256121	PILOT LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:17010530024	HRS	5157.3		TSN 0				
WC#: 25.190	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256131	COPILOT LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	O/C	TSN 0				
SN:170105530023	HRS	5157.3		TSN 0				
WC#: 25.190	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256141	REMOVAL / INSTALLATION OF THE THIRD CREW MEMBER LIFE VEST							Component ATA:25
PN:P01074-209WC	MOS/MSC	25-May-17	H/T	TSN 0				
SN:17010530022	HRS	5157.3		TSN 0				
	AFL	3249		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256150 U	EMERGENCY LOCATOR TRANSMITTER ANTENNA							Component ATA:25
PN:110-337	MOS/MSC	08-May-14	O/C					
SN:4011723	HRS	4694.25						
	AFL	2957						
256153 U	REMOTE ELT CONTROL							Component ATA:25
PN:DMU231-2	MOS/MSC	17-Jul-96	O/C					
SN:0811B	HRS	150						
	AFL	62						
256838 U	INFANT LIFE VEST							Component ATA:25
PN:P0640-101W	MOS/MSC	16-Mar-22	O/C	TSN 3				
SN:21120050005	HRS	6124.5		TSN 0				
	AFL	3681		TSN 0				
256839 U	INFANT LIFE VEST INSPECT							Service ATA:25
PN:P0640-101W	MOS	01-Dec-21	60		01-Dec-26		53 d	
SN:21120050005	HRS							
	AFL							
258901 U	PILOT BREATHING DEVICE							Component ATA:25
PN:802300-14	MOS/MSC	02-Dec-24	O/C	TSN 4				
SN:E24081058	HRS	6622.1		TSN 0				
	AFL	3889		TSN 0				
258903 U	CO-PILOT BREATHING DEVICE							Component ATA:25
PN:802300-14	MOS/MSC	02-Dec-24	O/C	TSN 3				
SN:E24090475	HRS	6622.1		TSN 0				
	AFL	3889		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
258905 U	RECONFIGURE INTERIOR TO MEDIVAC IAW AUTO AVIA EO 217/572/EI1 REV IR							Service ATA:25
	MOS/MSC	30-Mar-22	O/C					
	HRS	6136.5						
	AFL	3685						
258907 U	RECONFIGURE INTERIOR TO EXECUTIVE IAW AUTO AVIA EO 217/572/EI1 REV IR							Service ATA:25
	MOS/MSC		O/C					
	HRS							
	AFL							
258910 U	DISCARD PILOT BREATHING DEVICE							Service ATA:25
PN:802300-14	MOS	02-Dec-24	120		01-Aug-34		2853 d	
SN:E24081058	HRS	6622.1						
	AFL	3889						
			Manufacture Date:: 01-Aug-24					
258930 U	DISCARD CO-PILOT BREATHING DEVICE							Service ATA:25
PN:802300-14	MOS	02-Dec-24	120		01-Sep-34		2884 d	
SN:E24090475	HRS	6622.1						
	AFL	3889						
			Manufacture Date:: 01-Sep-24					
25A047 U	REPLACE ALL HIGH AND LOW PRESSURE GAS HOSES INCLUDING HIGH-PRESSURE BRAD.							Service ATA:25
	MOS/MSC	13-Feb-23	O/C					
	HRS	6337.3						
	AFL	3771						
25A070 U	MEDIVAC STRETCHER OUTBOARD BOTTLE							Component ATA:25
PN:DOT-3AL2216	MOS/MSC	18-Feb-20	O/C	TSN 58				
SN:AB0192918	HRS	5868.3						
	AFL	3550						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25A071 U	MEDIVAC STRETCHER INBOARD BOTTLE							Component ATA:25
PN:DOT3AL2216	MOS/MSC	22-Jun-18	O/C	TSN 19, TSO 0				
SN:MM189541	HRS	5357.3		TSO 0				
	AFL	3346		TSO 0				
25A072 U	ANNUAL INSPECTION OF MEDIVAC EQUIPMENT IAW FAA STC STO2863CH							Service ATA:25
	MOS/MSC	08-Dec-23	O/C					ICA
	HRS	6529.1						
	AFL	3833						
25A073 U	SEMI-ANNUAL INSPECTION OF MEDIVAC EQUIPMENT IAW FAA STC STO2863CH							Service ATA:25
	MOS/MSC	30-Mar-22	A/R					ICA
	HRS	6136.5						
	AFL	3685						
25A074 U	CHECK ALL UNDER FLOOR WIRING AT NEXT PHASE INSPECTION AND REPAIR/REPLACE AS NECESSARY FOR SAFE OPERATION OF AIRCRAFT.							Service ATA:25
	MOS/MSC	08-Dec-23	O/C					ICA
	HRS	6529.1						
	AFL	3833						
25A075 U	HYDROSTATIC TEST MEDIVAC STRETCHER OUTBOARD BOTTLE							Service ATA:25
PN:DOT-3AL2216	MOS/MSC	17-Feb-20	O/C					ICA
SN:AB0192918	HRS							
	AFL							
25A076 U	HYDROSTATIC TEST MEDIVAC STRETCHER INBOARD BOTTLE							Service ATA:25
PN:DOT3AL2216	MOS/MSC	22-Jun-23	O/C					ICA
SN:MM189541	HRS	6443.6						
	AFL	3807						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25A174 U	REPLACE ALL HIGH AND LOW PRESSURE GAS HOSES INCLUDING HIGH-PRESSURE BRAD.							Service ATA:25
	MOS/MSC		-					
	HRS							
	AFL							
25XX02 U	LIFE RAFT PORTABLE ELT							Component ATA:25
PN:2881-64	MOS/MSC	06-Mar-18	O/C					
SN:10686	HRS							
	AFL							
25XX22 U	REPLACE BATTERY LIFE RAFT PORTABLE ELT							Service ATA:25
	MOS/MSC	04-Apr-25	DUE		30-Apr-30 (M)		1299 d	
	HRS	6648.6						
	AFL	3909						
			Expiry Date: : 30-Apr-30					
ATA 26 - FIRE PROTECTION								
26-10-00-720-801-01	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2W)							Service ATA:26
PN:30016190040013	MOS/MSC	18-Jun-19	E/C					
SN:17769	HRS	5790.5	5600		11390.5		4598.2	
WC#: 26.010	AFL	3507						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-01A	FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR (MANDATORY 5-40)							Service ATA:26
PN:30016190040013	MOS	18-Jun-19						MANDATORY 5-40
SN:17769	HRS	5790.5	5600		11390.5		4598.2	
WC#: 26.010	AFL	3507						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-02	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2W)							Service ATA:26
PN:30016190040013	MOS/MSC	18-Jun-19	E/C					
SN:17772	HRS	5790.5	5600		11390.5		4598.2	
WC#: 26.015	AFL	3507						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-10-00-720-801-02A	FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR (MANDATORY 5-40)							Service ATA:26
PN:30016190040013	MOS	18-Jun-19						MANDATORY 5-40
SN:17772	HRS	5790.5	5600		11390.5		4598.2	
WC#: 26.015	AFL	3507						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-03	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2W)							Service ATA:26
PN:30016190040013	MOS/MSC	18-Jun-19	E/C					
SN:17735	HRS	5790.5	5600		11390.5		4598.2	
WC#: 26.010	AFL	3507						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-03A	FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR (MANDATORY 5-40)							Service ATA:26
PN:30016190040013	MOS	18-Jun-19						MANDATORY 5-40
SN:17735	HRS	5790.5	5600		11390.5		4598.2	
WC#: 26.010	AFL	3507						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-04	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - APU FIRE DETECTOR (72W)							Service ATA:26
PN:30011690040012	MOS	10-Feb-02						
SN:UNKNOWN	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-04A	FUNCTIONAL TEST APU FIRE DETECTOR (MANDATORY 5-40)							Service ATA:26
PN:30011690040012	MOS	10-Feb-02						MANDATORY 5-40
SN:UNKNOWN	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-05	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - REAR COMPARTMENT FIRE DETECTOR (22W)							Service ATA:26
PN:300119800270-3	MOS	10-Feb-02						
SN:74318	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-05A	FUNCTIONAL TEST REAR COMPARTMENT FIRE DETECTOR (MANDATORY 5-40)							Service ATA:26
PN:300119800270-3	MOS	10-Feb-02						MANDATORY 5-40
SN:74318	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-06	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (29W1)							Service ATA:26
PN:30015160027012	MOS	10-Feb-02						
SN:74318	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-06A	FUNCTIONAL TEST LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (MANDATORY 5-40)							Service ATA:26
PN:30015160027012	MOS	10-Feb-02						MANDATORY 5-40
SN:74318	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-07	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (29W2)							Service ATA:26
PN:30015160027012	MOS	10-Feb-02						
SN:74300	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-00-720-801-07A	FUNCTIONAL TEST RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (MANDATORY 5-40)							Service ATA:26
PN:30015160027012	MOS	10-Feb-02						MANDATORY 5-40
SN:74300	HRS	1532	5600		7132		339.7	
WC#: 26.050	AFL	1065						
PROC. REF: AMM 26-10-00-720-801	PROC. REF: AMM 26-10-00-720-801							
26-10-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2W)							Component ATA:26
PN:30016190040013	MOS/MSC	11-Jul-95	O/C					
SN:17769	HRS	0		TSN 0				
WC#: 26.010	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801								
26-10-01-900-801-02		REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2W)						Component ATA:26
PN:30016190040013	MOS/MSC	11-Jul-95	O/C					
SN:17772	HRS	0		TSN 0				
WC#: 26.015	AFL	0						
PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801								
26-10-01-900-801-03		REMOVAL / INSTALLATION OF THE ENGINE PNEUMATIC FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2W)						Component ATA:26
PN:30016190040013	MOS/MSC	11-Jul-95	O/C					
SN:17735	HRS	0		TSN 0				
WC#: 26.010	AFL	0						
PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801PROC. REF: AMM 26-10-01-900-801, AMM 26-10-01-900-801								
26-10-21-900-801-01		REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT SMOKE DETECTOR AND LAMP / LED REPLACEMENT - SMOKE DETECTOR (27W)						Component ATA:26
PN:FR2210-2	MOS/MSC	21-Jan-98	O/C	TSN 0				
SN:544	HRS	650		TSN 0				
WC#: 26.030	AFL	427		TSN 0				
PROC. REF: AMM 26-10-21-900-801PROC. REF: AMM 26-10-21-900-801								
26-20-01-760-801-01 S		CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 1" SELECTOR SWITCH (POSITION "1")						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-02 S		CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 1" SELECTOR SWITCH (POSITION "2")						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-01-760-801-03	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 2" SELECTOR SWITCH (POSITION "1")						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-04	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 2" SELECTOR SWITCH (POSITION "2")						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-05	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 3" SELECTOR SWITCH (POSITION "1")						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-06	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 3" SELECTOR SWITCH (POSITION "2")						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-07	S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE APU" SELECTOR SWITCH						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.170	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-01-760-801-08 S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE BAG COMP" SELECTOR SWITCH							Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.220	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-01-760-801-09 S	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE AFT COMP" SELECTOR SWITCH							Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.190	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-01-760-801PROC. REF: AMM 26-20-01-760-801								
26-20-09-220-801-01	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)							Service ATA:26
PN:860640	MOS	24-Oct-25	12		18-Sep-26		OVD	
SN:50550	HRS	6700.5						
WC#: 26.060	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								
26-20-09-220-801-02	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)							Service ATA:26
PN:860640	MOS	24-Oct-25	12		18-Sep-26		OVD	
SN:20698	HRS	6700.5						
WC#: 26.070	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								
26-20-09-220-801-03	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)							Service ATA:26
PN:863470-01	MOS	17-Apr-26	18		12-Oct-27		368 d	
SN:UE001684	HRS	6746.8						
WC#: 26.080	AFL	3979						
			WeightCheck Date : : 12-Apr-26					
PROC. REF: AMM 26-20-09-220-801PROC. REF: AMM 26-20-09-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-09-220-801-04	WEIGHING OF THE FIRE EXTINGUISHERS - APU FIRE EXTINGUISHER (73W)							Service ATA:26
PN:30111102	MOS	24-Oct-25	12		18-Sep-26		OVD	
SN:09928A1	HRS	6700.5						
WC#: 26.090	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-09-220-801	PROC. REF: AMM 26-20-09-220-801							
26-20-09-220-801-05	WEIGHING OF THE FIRE EXTINGUISHERS - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)							Service ATA:26
PN:30702102-1	MOS	24-Oct-25	12		18-Sep-26		OVD	
SN:06029D2	HRS	6700.5						
WC#: 26.210	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-09-220-801	PROC. REF: AMM 26-20-09-220-801							
26-20-09-220-801-06	WEIGHING OF THE FIRE EXTINGUISHERS - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)							Service ATA:26
PN:30702102-1	MOS	24-Oct-25	12		18-Sep-26		OVD	
SN:20299D2	HRS	6700.5						
WC#: 26.180	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-09-220-801	PROC. REF: AMM 26-20-09-220-801							
26-20-09-350-801-01	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)							Service ATA:26
PN:860640	MOS	24-Oct-25	60	TAC 10	31-Dec-28		814 d	
SN:50550	HRS	6700.5						
	AFL	3940						
			Restoration Date:: 31-Oct-24					
PROC. REF: AMM 26-20-09-350-801	PROC. REF: AMM 26-20-09-350-801							
26-20-09-350-801-02	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)							Service ATA:26
PN:860640	MOS	24-Oct-25	60		05-Feb-30		1215 d	
SN:20698	HRS	6700.5						
	AFL	3940						
			Restoration Date:: 05-Feb-25					
PROC. REF: AMM 26-20-09-350-801	PROC. REF: AMM 26-20-09-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-09-350-801-03	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)							Service ATA:26
PN:863470-01	MOS	01-Apr-19	120		01-Apr-29		905 d	
SN:UE001684	HRS							
	AFL							
			Restoration Date:: 01-Apr-19					
PROC. REF: AMM 26-20-09-350-801	PROC. REF: AMM 26-20-09-350-801							
26-20-09-350-801-04	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - APU FIRE EXTINGUISHER (73W)							Service ATA:26
PN:30111102	MOS	24-Oct-25	60		08-Mar-29		881 d	MANDATORY
SN:09928A1	HRS	6700.5						
WC#: 26.090	AFL	3940						
			HydroCheck Date: : 08-Mar-24					
PROC. REF: AMM 26-20-09-350-801	PROC. REF: AMM 26-20-09-350-801							
26-20-09-350-801-05	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)							Service ATA:26
PN:30702102-1	MOS	24-Oct-25	60		24-Apr-29		928 d	MANDATORY
SN:06029D2	HRS	6700.5						
WC#: 26.210	AFL	3940						
			HydroCheck Date: : 24-Apr-24					
PROC. REF: AMM 26-20-09-350-801	PROC. REF: AMM 26-20-09-350-801							
26-20-09-350-801-06	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)							Service ATA:26
PN:30702102-1	MOS	24-Oct-25	60		24-Apr-29		928 d	MANDATORY
SN:20299D2	HRS	6700.5						
WC#: 26.180	AFL	3940						
			HydroCheck Date: : 24-Apr-24					
PROC. REF: AMM 26-20-09-350-801	PROC. REF: AMM 26-20-09-350-801							
26-20-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)							Component ATA:26
PN:860640	MOS/MSC	24-Oct-25	O/C					
SN:50550	HRS	6700.5						
WC#: 26.060	AFL	3940						
PROC. REF: AMM 26-20-09-900-801	PROC. REF: AMM 26-20-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)							Component ATA:26
PN:860640	MOS/MSC	24-Oct-25	O/C	TSO 3				
SN:20698	HRS	6700.5		TSO 24.2				
WC#: 26.070	AFL	3940		TSO 12				
PROC. REF: AMM 26-20-09-900-801	PROC. REF: AMM 26-20-09-900-801							
26-20-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)							Component ATA:26
PN:863470-01	MOS/MSC	17-Apr-26	O/C	TSN 193, TSO 84				
SN:UE001684	HRS	6746.8		TSO 956.3				
WC#: 26.080	AFL	3979		TSO 472				
PROC. REF: AMM 26-20-09-900-801	PROC. REF: AMM 26-20-09-900-801							
26-20-09-900-802-01	REMOVAL / INSTALLATION OF THE APU FIRE EXTINGUISHER - APU FIRE EXTINGUISHER (73W)							Component ATA:26
PN:30111102	MOS/MSC	24-Oct-25	O/C	TSO 19				
SN:09928A1	HRS	6700.5		TSO 156.1				
WC#: 26.090	AFL	3940		TSO 95				
PROC. REF: AMM 26-20-09-900-802	PROC. REF: AMM 26-20-09-900-802							
26-20-09-900-803-01	REMOVAL / INSTALLATION OF THE REAR / BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)							Component ATA:26
PN:30702102-1	MOS/MSC	24-Oct-25	O/C	TSO 18				
SN:20299D2	HRS	6700.5		TSO 147.5				
WC#: 26.180	AFL	3940		TSO 89				
PROC. REF: AMM 26-20-09-900-803	PROC. REF: AMM 26-20-09-900-803							
26-20-09-900-804-01	REMOVAL / INSTALLATION OF THE REAR COMPARTMENT FIRE EXTINGUISHER - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)							Component ATA:26
PN:30702102-1	MOS/MSC	24-Oct-25	O/C	TSO 18				
SN:06029D2	HRS	6700.5		TSO 147.5				
WC#: 26.210	AFL	3940		TSO 89				
PROC. REF: AMM 26-20-09-900-804	PROC. REF: AMM 26-20-09-900-804							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-11-700-801-01	S	CHECKING EXTINGUISHING LINES FOR CLOGGING - APU FIRE EXTINGUISHER (73W)						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.160	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-11-700-801	PROC. REF: AMM 26-20-11-700-801							
26-20-11-700-801-02	S	CHECKING EXTINGUISHING LINES FOR CLOGGING - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.100	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-11-700-801	PROC. REF: AMM 26-20-11-700-801							
26-20-11-700-801-03	S	CHECKING EXTINGUISHING LINES FOR CLOGGING - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.110	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-11-700-801	PROC. REF: AMM 26-20-11-700-801							
26-20-11-700-801-04	S	CHECKING EXTINGUISHING LINES FOR CLOGGING - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.120	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-11-700-801	PROC. REF: AMM 26-20-11-700-801							
26-20-11-700-801-05	S	CHECKING EXTINGUISHING LINES FOR CLOGGING - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)						Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.200	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-11-700-801	PROC. REF: AMM 26-20-11-700-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-11-700-801-06 S	CHECKING EXTINGUISHING LINES FOR CLOGGING - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)							Service ATA:26
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 26.230	AFL	3569						
								PKG:31
PROC. REF: AMM 26-20-11-700-801	PROC. REF: AMM 26-20-11-700-801							
26-20-13-760-801-01	INSULATION TEST OF THE ENGINE 1/2 FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (14W1)							Service ATA:26
PN:860640	MOS/MSC	24-Oct-25	O/C					
SN:50550	HRS	6700.5						
WC#: 26.060	AFL	3940						
PROC. REF: AMM 26-20-13-760-801	PROC. REF: AMM 26-20-13-760-801							
26-20-13-760-802-01	INSULATION TEST OF THE ENGINE 2/3 FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (14W2)							Service ATA:26
PN:860640	MOS/MSC	24-Oct-25	O/C					
SN:20698	HRS	6700.5						
WC#: 26.070	AFL	3940						
PROC. REF: AMM 26-20-13-760-802	PROC. REF: AMM 26-20-13-760-802							
26-20-13-760-803-01	INSULATION TEST OF THE ENGINE 3/1 FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (14W3)							Service ATA:26
PN:863470-01	MOS/MSC	18-Jun-19	O/C					
SN:UE001684	HRS	5790.5						
WC#: 26.080	AFL	3507						
PROC. REF: AMM 26-20-13-760-803	PROC. REF: AMM 26-20-13-760-803							
26-20-13-760-804-01	INSULATION TEST OF THE APU FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - APU FIRE EXTINGUISHER (73W)							Service ATA:26
PN:30111102	MOS/MSC	24-Oct-25	O/C					
SN:09928A1	HRS	6700.5						
WC#: 26.090	AFL	3940						
PROC. REF: AMM 26-20-13-760-804	PROC. REF: AMM 26-20-13-760-804							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-760-805-01	INSULATION TEST OF THE REAR / BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHER (23W2)							Service ATA:26
PN:30702102-1	MOS/MSC	24-Oct-25	O/C					
SN:20299D2	HRS	6700.5						
WC#: 26.180	AFL	3940						
PROC. REF: AMM 26-20-13-760-805	PROC. REF: AMM 26-20-13-760-805							
26-20-13-760-806-01	INSULATION TEST OF THE REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM - REAR COMPARTMENT FIRE EXTINGUISHER (23W1)							Service ATA:26
PN:30702102-1	MOS/MSC	24-Oct-25	O/C					
SN:06029D2	HRS	6700.5						
WC#: 26.210	AFL	3940						
PROC. REF: AMM 26-20-13-760-806	PROC. REF: AMM 26-20-13-760-806							
26-20-13-900-802-01	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L14W)							Component ATA:26
PN:861385	MOS/MSC	04-Apr-24	H/T	TSN 4				
SN:NO SN	HRS	6550		TSN 0				
	AFL	3849		TSN 0				
PROC. REF: AMM 26-20-13-900-802	PROC. REF: AMM 26-20-13-900-802							
26-20-13-900-802-02	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT PERCUSSION CARTRIDGE (M14W)							Component ATA:26
PN:861375	MOS/MSC	04-Apr-24	H/T	TSN 6				
SN:NO SN	HRS	6550		TSN 0				
	AFL	3849		TSN 0				
PROC. REF: AMM 26-20-13-900-802	PROC. REF: AMM 26-20-13-900-802							
26-20-13-900-802-03	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R14W)							Component ATA:26
PN:PN	MOS/MSC	16-Mar-22	H/T	TSN 5				
SN:UNKNOWN	HRS	6124.5						
	AFL	3681						
PROC. REF: AMM 26-20-13-900-802	PROC. REF: AMM 26-20-13-900-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-900-802-04	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L15W)							Component ATA:26
PN:862710-00	MOS/MSC	13-Dec-17	H/T	TSN 8				
SN:UNKNOWN	HRS	5213.5						
	AFL	3293						
PROC. REF: AMM 26-20-13-900-802	PROC. REF: AMM 26-20-13-900-802							
26-20-13-900-802-05	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE (M15W)							Component ATA:26
PN:861375	MOS/MSC	04-Apr-24	H/T	TSN 6				
SN:NO SN	HRS	6550		TSN 0				
	AFL	3849		TSN 0				
PROC. REF: AMM 26-20-13-900-802	PROC. REF: AMM 26-20-13-900-802							
26-20-13-900-802-06	REMOVAL / INSTALLATION OF THE ENGINE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R15W)							Component ATA:26
PN:861385	MOS/MSC	04-Apr-24	H/T	TSN 4				
SN:NO SN	HRS	6550		TSN 0				
	AFL	3849		TSN 0				
PROC. REF: AMM 26-20-13-900-802	PROC. REF: AMM 26-20-13-900-802							
26-20-13-900-805-01	REMOVAL / INSTALLATION OF THE APU FIRE EXTINGUISHER PERCUSSION CARTRIDGE - APU PERCUSSION CARTRIDGE (28W)							Component ATA:26
PN:M13083-5	MOS/MSC	24-Oct-25	H/T	TSN 3				
SN:52292	HRS	6700.5		TSN 0				
	AFL	3940		TSN 0				
PROC. REF: AMM 26-20-13-900-805	PROC. REF: AMM 26-20-13-900-805							
26-20-13-900-806-01	REMOVAL / INSTALLATION OF THE RH REAR COMPARTMENT AND BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGES - RH REAR COMPARTMENT PERCUSSION CARTRIDGE (24W)							Component ATA:26
PN:13083-5	MOS/MSC	24-Oct-25	H/T	TSN 3				
SN:52293	HRS	6700.5		TSN 0				
	AFL	3940		TSN 0				
PROC. REF: AMM 26-20-13-900-806	PROC. REF: AMM 26-20-13-900-806							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-900-806-02	REMOVAL / INSTALLATION OF THE RH REAR COMPARTMENT AND BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (23W)							Component ATA:26
PN:13083-5	MOS/MSC	24-Oct-25	H/T	TSN 3				
SN:52291	HRS	6700.5		TSN 0				
	AFL	3940		TSN 0				
PROC. REF: AMM 26-20-13-900-806	PROC. REF: AMM 26-20-13-900-806							
26-20-13-900-807-01	REMOVAL / INSTALLATION OF THE LH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION CARTRIDGE - LH REAR COMPARTMENT PERCUSSION CARTRIDGE (25W)							Component ATA:26
PN:13083-5	MOS/MSC	24-Oct-25	H/T	TSN 3				
SN:52295	HRS	6700.5		TSN 0				
	AFL	3940		TSN 0				
PROC. REF: AMM 26-20-13-900-807	PROC. REF: AMM 26-20-13-900-807							
26-20-13-960-801-01	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L14W)							Service ATA:26
PN:861385	MOS	04-Apr-24	60		04-Apr-29	908 d		SCRAP
SN:NO SN	HRS	6550						
WC#: 26.060	AFL	3849						
			Installation Date: : 04-Apr-24					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-01M	DISCARD ENGINE 1 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (L14W) CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:861385	MOS	23-Nov-23	84		23-Nov-30	1506 d		LIFE LIMIT
SN:NO SN	HRS							
WC#: 26.060	AFL							
			Manufacture Date:: 23-Nov-23					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-02	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT PERCUSSION CARTRIDGE (M14W)							Service ATA:26
PN:861375	MOS	04-Apr-24	60		04-Apr-29	908 d		SCRAP
SN:NO SN	HRS	6550						
WC#: 26.070	AFL	3849						
			Installation Date: : 04-Apr-24					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-02M	DISCARD ENGINE 2 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (M14W) CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:861375	MOS	07-Sep-23	84		07-Sep-30		1429 d	LIFE LIMIT
SN:NO SN	HRS							
WC#: 26.070	AFL							
			Manufacture Date:: 07-Sep-23					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-03	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R14W)							Service ATA:26
PN:PN	MOS/MSC	16-Mar-22	O/C					
SN:UNKNOWN	HRS							
WC#: 26.080	AFL							
			Installation Date: : 16-Mar-22					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-03M	DISCARD ENGINE 3 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (R14W) CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:PN	MOS	01-Oct-21	120		01-Oct-31		1818 d	LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 26.080	AFL							
			Manufacture Date:: 01-Oct-21					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-04	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L15W)							Service ATA:26
PN:862710-00	MOS/MSC	13-Dec-17	O/C					
SN:UNKNOWN	HRS							
WC#: 26.080	AFL							
			Installation Date: : 13-Dec-17					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-04M	DISCARD ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (L15W) CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:862710-00	MOS	01-Apr-17	120		01-Apr-27		174 d	LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 26.080	AFL							
			Manufacture Date:: 01-Apr-17					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-05	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE (M15W)						Service	ATA:26
PN:861375	MOS	04-Apr-24	60		04-Apr-29		908 d	SCRAP
SN:NO SN	HRS	6550						
WC#: 26.060	AFL	3849						
			Installation Date: : 04-Apr-24					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-05M	DISCARD ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (M15W) CARTRIDGE (LIFE LIMIT)						Service	ATA:26
PN:861375	MOS	07-Sep-23	84		07-Sep-30		1429 d	LIFE LIMIT
SN:NO SN	HRS							
WC#: 26.060	AFL							
			Manufacture Date:: 07-Sep-23					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-06	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R15W)						Service	ATA:26
PN:861385	MOS	04-Apr-24	60		04-Apr-29		908 d	SCRAP
SN:NO SN	HRS	6550						
WC#: 26.070	AFL	3849						
			Installation Date: : 04-Apr-24					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-06M	DISCARD ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (R15W) CARTRIDGE (LIFE LIMIT)						Service	ATA:26
PN:861385	MOS	23-Nov-23	84		23-Nov-30		1506 d	LIFE LIMIT
SN:NO SN	HRS							
WC#: 26.070	AFL							
			Manufacture Date:: 23-Nov-23					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-07	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (23W)						Service	ATA:26
PN:13083-5	MOS	24-Oct-25	72		18-Sep-31		1805 d	SCRAP
SN:52291	HRS	6700.5						
WC#: 26.180	AFL	3940						
			Installation Date: : 18-Sep-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-07M	DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (23W) CARTRIDGE (LIFE LIMIT)						Service	ATA:26
PN:13083-5	MOS	24-Oct-25	108		29-Jul-34		2850 d	LIFE LIMIT
SN:52291	HRS	6700.5						
WC#: 26.180	AFL	3940						
			Manufacture Date:: 29-Jul-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-08	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - RH REAR COMPARTMENT PERCUSSION CARTRIDGE (24W)						Service	ATA:26
PN:13083-5	MOS	24-Oct-25	72		18-Aug-31		1774 d	SCRAP
SN:52293	HRS	6700.5						
WC#: 26.180	AFL	3940						
			Installation Date: : 18-Aug-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-08M	DISCARD RH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (24W) CARTRIDGE (LIFE LIMIT)						Service	ATA:26
PN:13083-5	MOS	24-Oct-25	108		29-Jul-34		2850 d	LIFE LIMIT
SN:52293	HRS	6700.5						
WC#: 26.180	AFL	3940						
			Manufacture Date:: 29-Jul-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-09	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - LH REAR COMPARTMENT PERCUSSION CARTRIDGE (25W)						Service	ATA:26
PN:13083-5	MOS	24-Oct-25	72		24-Oct-31		1841 d	SCRAP
SN:52295	HRS	6700.5						
WC#: 26.210	AFL	3940						
			Installation Date: : 24-Oct-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-09M	DISCARD LH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (25W) CARTRIDGE (LIFE LIMIT)						Service	ATA:26
PN:13083-5	MOS	24-Oct-25	108		29-Jul-34		2850 d	LIFE LIMIT
SN:52295	HRS	6700.5						
WC#: 26.210	AFL	3940						
			Manufacture Date:: 29-Jul-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-13-960-801-10	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (28W)							Service ATA:26
PN:M13083-5	MOS	24-Oct-25	72		24-Oct-31		1841 d	SCRAP
SN:52292	HRS	6700.5						
WC#: 26.090	AFL	3940						
			Installation Date: : 24-Oct-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-13-960-801-10M	DISCARD APU FIRE EXTINGUISHER PERCUSSION (28W) CARTRIDGE (LIFE LIMIT)							Service ATA:26
PN:M13083-5	MOS	24-Oct-25	108		29-Jul-34		2850 d	LIFE LIMIT
SN:52292	HRS	6700.5						
WC#: 26.090	AFL	3940						
			Manufacture Date:: 29-Jul-25					
PROC. REF: AMM 26-20-13-960-801	PROC. REF: AMM 26-20-13-960-801							
26-20-15-350-802-02	RESTORATION OF THE PORTABLE EXTINGUISHERS (OVERHAUL) - CABIN PORTABLE FIRE EXTINGUISHER (501WB)							Service ATA:26
PN:898052	MOS/MSC	30-Oct-15	O/C					
SN:A93827965	HRS	4941.5						
	AFL	3091						
PROC. REF: AMM 26-20-15-350-802	PROC. REF: AMM 26-20-15-350-802							
26-20-15-350-802-03	RESTORATION OF THE PORTABLE EXTINGUISHERS (OVERHAUL) - SECOND CABIN PORTABLE FIRE EXTINGUISHER (502WB)							Service ATA:26
PN:898052	MOS/MSC	25-May-17	O/C					
SN:W-860107	HRS	5157.3						
	AFL	3249						
PROC. REF: AMM 26-20-15-350-802	PROC. REF: AMM 26-20-15-350-802							
26-20-15-720-801-01	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)							Service ATA:26
PN:898052	MOS	24-Oct-25	24		18-Sep-27		344 d	
SN:A93827964	HRS	6700.5						
	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801	PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-15-720-801-02	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN PORTABLE FIRE EXTINGUISHER (501WB)							Service ATA:26
PN:898052	MOS	24-Oct-25	24		18-Sep-27		344 d	
SN:A93827965	HRS	6700.5						
	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801								
26-20-15-720-801-03	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - SECOND CABIN PORTABLE FIRE EXTINGUISHER (502WB)							Service ATA:26
PN:898052	MOS	24-Oct-25	24		18-Sep-27		344 d	
SN:W-860107	HRS	6700.5						
	AFL	3940						
			WeightCheck Date : : 18-Sep-25					
PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801PROC. REF: AMM 26-20-15-720-801, AMM 26-20-15-720-801								
26-20-15-790-801-01	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)							Service ATA:26
PN:898052	MOS	02-Apr-15	144 (+3%)		02-Apr-27	11-Aug-27	175 d (+131)	
SN:A93827964	HRS							
	AFL							
			HydroCheck Date: : 02-Apr-15					
PROC. REF: AMM 26-20-15-790-801PROC. REF: AMM 26-20-15-790-801								
26-20-15-790-801-02	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN PORTABLE FIRE EXTINGUISHER (501WB)							Service ATA:26
PN:898052	MOS	02-Apr-15	144 (+3%)		02-Apr-27	11-Aug-27	175 d (+131)	
SN:A93827965	HRS							
	AFL							
			HydroCheck Date: : 02-Apr-15					
PROC. REF: AMM 26-20-15-790-801PROC. REF: AMM 26-20-15-790-801								
26-20-15-790-801-03	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - SECOND CABIN PORTABLE FIRE EXTINGUISHER (502WB)							Service ATA:26
PN:898052	MOS	25-May-17	144 (+3%)		25-May-29	04-Oct-29	959 d (+132)	
SN:W-860107	HRS							
	AFL							
			HydroCheck Date: : 25-May-17					
PROC. REF: AMM 26-20-15-790-801PROC. REF: AMM 26-20-15-790-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-20-15-900-801-01	COCKPIT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:898052	MOS/MSC	30-Oct-15	O/C	TSN 6				
SN:A93827964	HRS	4941.5		TSN 0				
	AFL	3091		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
26-20-15-900-801-02	NO. 1 CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:898052	MOS/MSC	30-Oct-15	O/C	TSN 6				
SN:A93827965	HRS	4941.5		TSN 0				
	AFL	3091		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
26-20-15-900-801-03	NO. 2 CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:898052	MOS/MSC	25-May-17	O/C	TSN 149, TSO 0				
SN:W-860107	HRS	5157.3		TSO 0				
	AFL	3249		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
261155	LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR							Component ATA:26
PN:30015160027012	MOS/MSC	11-Jul-95	O/C					
SN:74318	HRS	0		TSN 0				
WC#: 26.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
261160	RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR							Component ATA:26
PN:30015160027012	MOS/MSC	11-Jul-95	O/C					
SN:74300	HRS	0		TSN 0				
WC#: 26.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
261165	APU FIRE DETECTOR							Component ATA:26
PN:30011690040012	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261170	REAR COMPARTMENT FIRE DETECTOR							Component ATA:26
PN:300119800270-3	MOS/MSC	11-Jul-95	O/C					
SN:74318	HRS	0		TSN 0				
WC#: 26.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
261801	FIRE DETECTION PANEL							Component ATA:26
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.270	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262186	NO. 1 ENGINE DUAL CHECK VALVE							Component ATA:26
PN:860655	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.260	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262196	NO. 2 ENGINE DUAL CHECK VALVE							Component ATA:26
PN:860655	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.260	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262206	NO. 3 ENGINE DUAL CHECK VALVE							Component ATA:26
PN:860655	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 26.260	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 27 - FLIGHT CONTROLS								
27-00-00-640-803-01 S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA - ROLL							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.050	AFL	3569						

PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-00-00-640-803 PROC. REF: AMM 27-00-00-640-803								
27-00-00-640-803-02 S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA - YAW							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.050	AFL	3569						
								PKG:32
PROC. REF: AMM 27-00-00-640-803 PROC. REF: AMM 27-00-00-640-803								
27-00-00-640-803-03 S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA - PITCH							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.050	AFL	3569						
								PKG:32
PROC. REF: AMM 27-00-00-640-803 PROC. REF: AMM 27-00-00-640-803								
27-00-00-640-804-01 S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA - ROLL							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.040	AFL	3569						
								PKG:32
PROC. REF: AMM 27-00-00-640-804 PROC. REF: AMM 27-00-00-640-804								
27-00-00-640-804-02 S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA - YAW							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.040	AFL	3569						
								PKG:32
PROC. REF: AMM 27-00-00-640-804 PROC. REF: AMM 27-00-00-640-804								
27-00-00-640-804-03 S	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA - PITCH							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.040	AFL	3569						
								PKG:32
PROC. REF: AMM 27-00-00-640-804 PROC. REF: AMM 27-00-00-640-804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-640-806-01 S	VISUAL INSPECTION AND GREASING OF YAW AND PITCH CONTROL SEALED BOXES							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 27-00-00-640-806	PROC. REF: AMM 27-00-00-640-806							
27-00-00-710-801-01 S	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 1							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-00-00-710-801	PROC. REF: AMM 27-00-00-710-801							
27-00-00-710-801-02 S	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 2							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-00-00-710-801	PROC. REF: AMM 27-00-00-710-801							
27-00-00-710-802-01 S	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.200	AFL	3569						
								PKG:31
PROC. REF: AMM 27-00-00-710-802	PROC. REF: AMM 27-00-00-710-802							
27-00-00-710-802-02 S	OPERATIONAL TEST OF THE TRIM SYSTEMS - YAW							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.200	AFL	3569						
								PKG:31
PROC. REF: AMM 27-00-00-710-802	PROC. REF: AMM 27-00-00-710-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-00-00-720-803-01 S	FUNCTIONAL TEST OF ROLL AND PITCH AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - LH ROLL AAFU (L960CC)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-00-00-720-803	PROC. REF: AMM 27-00-00-720-803							
27-00-00-720-803-02 S	FUNCTIONAL TEST OF ROLL AND PITCH AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - RH ROLL AAFU (R960CC)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-00-00-720-803	PROC. REF: AMM 27-00-00-720-803							
27-00-00-720-803-03 S	FUNCTIONAL TEST OF ROLL AND PITCH AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - PITCH AAFU (924CW)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.190	AFL	3569						
								PKG:31
PROC. REF: AMM 27-00-00-720-803	PROC. REF: AMM 27-00-00-720-803							
27-00-00-720-806-01	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - ROLL							Service ATA:27
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-00-00-720-806	PROC. REF: AMM 27-00-00-720-806							
27-00-00-720-806-02	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - YAW							Service ATA:27
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 27.600	AFL	0						
PROC. REF: AMM 27-00-00-720-806	PROC. REF: AMM 27-00-00-720-806							
27-00-00-720-806-03	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - PITCH							Service ATA:27
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 27.600	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-00-00-720-806	PROC. REF: AMM 27-00-00-720-806							
27-12-01-640-801-01 S	PRESSURE GREASING OF THE AILERON SERVO-ACTUATOR BEARINGS - LH AILERON SERVO-ACTUATOR (L950CC)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.070	AFL	3569						
								PKG:32
PROC. REF: AMM 27-12-01-640-801	PROC. REF: AMM 27-12-01-640-801							
27-12-01-640-801-02 S	PRESSURE GREASING OF THE AILERON SERVO-ACTUATOR BEARINGS - RH AILERON SERVO-ACTUATOR (R950CC)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.070	AFL	3569						
								PKG:32
PROC. REF: AMM 27-12-01-640-801	PROC. REF: AMM 27-12-01-640-801							
27-12-01-790-802-01 S	CHECK FOR INTERNAL LEAKS ON THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L950CC)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.070	AFL	3569						
								PKG:31
PROC. REF: AMM 27-12-01-790-802	PROC. REF: AMM 27-12-01-790-802							
27-12-01-790-802-02 S	CHECK FOR INTERNAL LEAKS ON THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R950CC)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.070	AFL	3569						
								PKG:31
PROC. REF: AMM 27-12-01-790-802	PROC. REF: AMM 27-12-01-790-802							
27-12-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L950CC)							Component ATA:27
PN:103117-01	MOS/MSC	11-Jul-95	O/C					
SN:863	HRS	0		TSN 0				
WC#: 27.070	AFL	0						
PROC. REF: AMM 27-12-01-900-801	PROC. REF: AMM 27-12-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-12-01-900-801-02		REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R950CC)						Component ATA:27
PN:103117-02	MOS/MSC	11-Jul-95	O/C					
SN:859	HRS	0		TSN 0				
WC#: 27.070	AFL	0						
PROC. REF: AMM 27-12-01-900-801	PROC. REF: AMM 27-12-01-900-801							
27-13-01-640-806-01 S		LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.170	AFL	3569						
								PKG:31
PROC. REF: AMM 27-13-01-640-806	PROC. REF: AMM 27-13-01-640-806							
27-13-01-640-808-01 S		GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						Service ATA:27
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 27-13-01-640-808	PROC. REF: AMM 27-13-01-640-808							
27-13-05-640-801-01 S		VISUAL INSPECTION AND GREASING OF ROLL CONTROL SEALED BOXES						Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 27-13-05-640-801	PROC. REF: AMM 27-13-05-640-801							
27-13-07-350-801-01		RESTORATION OF "AMEDEE" VARIABLE BELLCRANK (FUNCTIONAL TEST AND SERVICING) - VARIABLE BELLCRANK (AMEDEE) (930CC)						Service ATA:27
PN:028008-28	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	
SN:2545	HRS	5942.6						
WC#: 27.150	AFL	3569						
PROC. REF: AMM 27-13-07-350-801	PROC. REF: AMM 27-13-07-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-14-01-350-801-01		RESTORATION OF THE ROLL TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL TRIM ACTUATOR (112C)						Service ATA:27
PN:021057-26	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	
SN:8326	HRS	5942.6						
WC#: 27.100	AFL	3569						
PROC. REF: AMM 27-14-01-350-801	PROC. REF: AMM 27-14-01-350-801							
27-14-03-350-801-01		RESTORATION OF THE ROLL EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL EMERGENCY TRIM ACTUATOR (103C)						Service ATA:27
PN:021127	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	
SN:422	HRS	5942.6						
WC#: 27.140	AFL	3569						
PROC. REF: AMM 27-14-03-350-801	PROC. REF: AMM 27-14-03-350-801							
27-14-03-720-802-01	S	FUNCTIONAL TEST OF THE ROLL EMERGENCY TRIM ACTUATOR - ROLL EMERGENCY TRIM ACTUATOR (103C)						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.140	AFL	3569						
								PKG:21
PROC. REF: AMM 27-14-03-720-802	PROC. REF: AMM 27-14-03-720-802							
27-14-05-720-801-01	S	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS						Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.110	AFL	3569						
								PKG:32
PROC. REF: AMM 27-14-05-720-801	PROC. REF: AMM 27-14-05-720-801							
27-15-00-720-801-01	S	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK MONITORING SYSTEM						Service ATA:27
	MOS	08-Sep-22						
	HRS	6221.1	3000 (+30)					
WC#: 27.080	AFL	3722						
								PKG:22
PROC. REF: AMM 27-15-00-720-801, AMM 27-15-00-720-801	PROC. REF: AMM 27-15-00-720-801, AMM 27-15-00-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-15-01-640-801-01 S	PRESSURE GREASING OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS - ROLL ARTHUR VARIABLE BELLCRANK (43C)							Service ATA:27
	MOS	08-Sep-22	144 (+2m)					
	HRS	6221.1						
WC#: 27.080	AFL	3722						
								PKG:32
PROC. REF: AMM 27-15-01-640-801 PROC. REF: AMM 27-15-01-640-801								
27-15-01-720-801-01 S	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (43C)							Service ATA:27
	MOS	08-Sep-22	72 (+2m)					
	HRS	6221.1						
WC#: 27.080	AFL	3722						
								PKG:31
PROC. REF: AMM 27-15-01-720-801 PROC. REF: AMM 27-15-01-720-801								
27-15-01-900-801-01	REMOVAL / INSTALLATION OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (43C)							Component ATA:27
PN:106043-20	MOS/MSC	08-Sep-22	O/C	TSR 2				
SN:1825	HRS	6221.1		TSR 0				
WC#: 27.080	AFL	3722		TSR 0				
PROC. REF: AMM 27-15-01-900-801 PROC. REF: AMM 27-15-01-900-801								
27-15-05-350-801-01	RESTORATION OF THE ROLL MAIN AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - ROLL MAIN AFU (940CC)							Service ATA:27
PN:105044-07	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	
SN:1088	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 27-15-05-350-801 PROC. REF: AMM 27-15-05-350-801								
27-15-07-640-801-01 S	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - LH ROLL AAFU (L960CC)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.130	AFL	3569						
								PKG:32
PROC. REF: AMM 27-15-07-640-801 PROC. REF: AMM 27-15-07-640-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-15-07-640-801-02 S	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - RH ROLL AAFU (R960CC)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.130	AFL	3569						
								PKG:32
PROC. REF: AMM 27-15-07-640-801	PROC. REF: AMM 27-15-07-640-801							
27-22-01-350-801-01	RESTORATION OF THE RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST OF VALVES AND CHECK OF DAMPER) - RUDDER SERVO-ACTUATOR (571CC)							Service ATA:27
PN:103103-13	MOS/MSC	15-Jul-96	N/A					
SN:953	HRS	0						
	AFL	0						
PROC. REF: AMM 27-22-01-350-801	PROC. REF: AMM 27-22-01-350-801							
27-22-01-350-802-01	RESTORATION OF THE RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) - RUDDER SERVO-ACTUATOR (571CC)							Service ATA:27
PN:103103-13	MOS	09-Apr-04						
SN:953	HRS	2009.8	10000		12009.8		5217.5	
	AFL	1422						
PROC. REF: AMM 27-22-01-350-802	PROC. REF: AMM 27-22-01-350-802							
27-22-01-350-802-01A	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY 5-40)							Service ATA:27
PN:103103-13	MOS	09-Apr-04						MANDATORY 5-40
SN:953	HRS	2009.8	10000		12009.8		5217.5	
WC#: 27.220	AFL	1422						
PROC. REF: AMM 27-22-01-350-802	PROC. REF: AMM 27-22-01-350-802							
27-22-01-640-801-01 S	PRESSURE GREASING OF THE RUDDER SERVO-ACTUATOR BEARINGS - RUDDER SERVO-ACTUATOR (571CC)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.220	AFL	3569						
								PKG:32
PROC. REF: AMM 27-22-01-640-801	PROC. REF: AMM 27-22-01-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-22-01-790-802-01 S	CHECK FOR INTERNAL LEAKS ON THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (571CC)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.220	AFL	3569						
								PKG:31
PROC. REF: AMM 27-22-01-790-802 PROC. REF: AMM 27-22-01-790-802								
27-22-01-900-801-01	REMOVAL / INSTALLATION OF THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (571CC)							Component ATA:27
PN:103103-13	MOS/MSC	09-Apr-04	O/C	TSR 1				
SN:953	HRS	2009.8		TSN 2009.8				
WC#: 27.220	AFL	1422		TSN 1422				
PROC. REF: AMM 27-22-01-900-801 PROC. REF: AMM 27-22-01-900-801								
27-23-01-640-806-01 S	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.300	AFL	3569						
								PKG:31
PROC. REF: AMM 27-23-01-640-806 PROC. REF: AMM 27-23-01-640-806								
27-23-01-640-807-01 S	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-23-01-640-807 PROC. REF: AMM 27-23-01-640-807								
27-23-01-640-808-01 S	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA							Service ATA:27
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 27.290	AFL	3875						
								PKG:16
PROC. REF: AMM 27-23-01-640-808 PROC. REF: AMM 27-23-01-640-808								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-24-01-350-801-01		RESTORATION OF THE YAW TRIM ACTUATOR (FUNCTIONAL TEST) - YAW TRIM ACTUATOR (92C)						Service ATA:27
PN:021057-28	MOS	08-May-14	144 (+5m)		08-May-26	08-Oct-26	OVD	
SN:8289	HRS	4694.25						
WC#: 27.250	AFL	2957						
PROC. REF: AMM 27-24-01-350-801	PROC. REF: AMM 27-24-01-350-801							
27-24-05-720-802-01 S		FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS - YAW TRIM SAFETY RELAY (93C)						Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 27-24-05-720-802	PROC. REF: AMM 27-24-05-720-802							
27-24-05-720-802-02 S		FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS - YAW TRIM SAFETY RELAY (94C)						Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 27-24-05-720-802	PROC. REF: AMM 27-24-05-720-802							
27-25-05-350-801-01		RESTORATION OF THE YAW MAIN AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - YAW MAIN AFU (573CC)						Service ATA:27
PN:105043-07	MOS	08-May-14	144 (+5m)		08-May-26	08-Oct-26	OVD	
SN:1166	HRS	4694.25						
	AFL	2957						
PROC. REF: AMM 27-25-05-350-801	PROC. REF: AMM 27-25-05-350-801							
27-25-07-350-801-01		RESTORATION OF THE YAW AUXILIARY AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - YAW AAFU (572CC)						Service ATA:27
PN:105070-04	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	
SN:939	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 27-25-07-350-801	PROC. REF: AMM 27-25-07-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-01-640-801-01 S	GREASING OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (L8TB)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.060	AFL	3569						
								PKG:32
PROC. REF: AMM 27-31-01-640-801	PROC. REF: AMM 27-31-01-640-801							
27-31-01-640-801-02 S	GREASING OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (R8TB)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.060	AFL	3569						
								PKG:32
PROC. REF: AMM 27-31-01-640-801	PROC. REF: AMM 27-31-01-640-801							
27-31-01-900-801-01	REMOVAL / INSTALLATION OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (L8TB)							Component ATA:27
PN:MY20215-25850-1	MOS/MSC	11-Jul-95	O/C					
SN:332	HRS	0		TSN 0				
WC#: 27.060	AFL	0						
PROC. REF: AMM 27-31-01-900-801	PROC. REF: AMM 27-31-01-900-801							
27-31-01-900-801-02	REMOVAL / INSTALLATION OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (R8TB)							Component ATA:27
PN:MY20215-50850-1	MOS/MSC	11-Jul-95	O/C					
SN:327	HRS	0		TSN 0				
WC#: 27.060	AFL	0						
PROC. REF: AMM 27-31-01-900-801	PROC. REF: AMM 27-31-01-900-801							
27-32-01-350-801-01	RESTORATION OF THE ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST) - ELEVATOR SERVO-ACTUATOR (925CW)							Service ATA:27
PN:103062-36	MOS	24-Jul-08						
SN:2335	HRS	3036.1	10000		13036.1		6243.8	
WC#: 27.320	AFL	2036						
PROC. REF: AMM 27-32-01-350-801	PROC. REF: AMM 27-32-01-350-801							
27-32-01-350-801-01A	RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST)(MANDATORY 5-40)							Service ATA:27
PN:103062-36	MOS	24-Jul-08						MANDATORY 5-40
SN:2335	HRS	3036.1	10000		13036.1		6243.8	
	AFL	2036						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-32-01-350-801	PROC. REF: AMM 27-32-01-350-801							
27-32-01-640-801-01 S	PRESSURE GREASING OF THE ELEVATOR SERVO-ACTUATOR BEARINGS - ELEVATOR SERVO-ACTUATOR (925CW)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.320	AFL	3569						
								PKG:32
PROC. REF: AMM 27-32-01-640-801	PROC. REF: AMM 27-32-01-640-801							
27-32-01-790-802-01 S	CHECK FOR INTERNAL LEAKS ON THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (925CW)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.320	AFL	3569						
								PKG:31
PROC. REF: AMM 27-32-01-790-802	PROC. REF: AMM 27-32-01-790-802							
27-32-01-900-801-01	REMOVAL / INSTALLATION OF THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (925CW)							Component ATA:27
PN:103062-36	MOS/MSC	24-Jul-08	O/C	TSR 4				
SN:2335	HRS	3036.1		TSR 0				
WC#: 27.320	AFL	2036		TSR 0				
PROC. REF: AMM 27-32-01-900-801	PROC. REF: AMM 27-32-01-900-801							
27-32-03-350-801-01	RESTORATION OF THE GUST DAMPING VALVE (FUNCTIONAL TEST) - GUST DAMPING VALVE (31F)							Service ATA:27
PN:104086-13	MOS	15-Jul-96						
SN:3833	HRS	0	10000		10000		3207.7	
	AFL	0						
PROC. REF: AMM 27-32-03-350-801	PROC. REF: AMM 27-32-03-350-801							
27-32-03-350-801-01A	RESTORATION PITCH GUST VALVE (FUNCTIONAL TEST) (MANDATORY 5-40)							Service ATA:27
PN:104086-13	MOS	15-Jul-96						MANDATORY 5-40
SN:3833	HRS	0	10000		10000		3207.7	
WC#: 27.960	AFL	0						
PROC. REF: AMM 27-32-03-350-801	PROC. REF: AMM 27-32-03-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-33-01-640-806-01 S	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.400	AFL	3569						
								PKG:31
PROC. REF: AMM 27-33-01-640-806	PROC. REF: AMM 27-33-01-640-806							
27-33-01-640-807-01 S	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-33-01-640-807	PROC. REF: AMM 27-33-01-640-807							
27-35-00-720-801-01 S	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	3000 (+30)					
WC#: 27.360	AFL	3569						
								PKG:22
PROC. REF: AMM 27-35-00-720-801, AMM 27-35-00-720-801	PROC. REF: AMM 27-35-00-720-801, AMM 27-35-00-720-801							
27-35-01-640-801-01 S	PRESSURE GREASING OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARINGS - PITCH ARTHUR VARIABLE BELLCRANK (42C)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.360	AFL	3569						
								PKG:32
PROC. REF: AMM 27-35-01-640-801	PROC. REF: AMM 27-35-01-640-801							
27-35-01-720-801-01 S	FUNCTIONAL TEST OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (42C)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.360	AFL	3569						
								PKG:31
PROC. REF: AMM 27-35-01-720-801	PROC. REF: AMM 27-35-01-720-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-35-01-900-801-01	REMOVAL / INSTALLATION OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (42C)							Component ATA:27
PN:106043-19	MOS/MSC	23-Oct-12	O/C	TSR 0				
SN:1809	HRS	4193.5		TSR 0				
WC#: 27.360	AFL	2686		TSR 0				
PROC. REF: AMM 27-35-01-900-801	PROC. REF: AMM 27-35-01-900-801							
27-35-05-350-801-01	RESTORATION OF THE PITCH MAIN AFU (INSPECTION, SERVICING AND FUNCTIONAL TEST) - PITCH MAIN AFU (524C)							Service ATA:27
PN:105034-07	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	
SN:1123	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 27-35-05-350-801	PROC. REF: AMM 27-35-05-350-801							
27-35-05-900-801-01	REMOVAL / INSTALLATION OF THE PITCH MAIN AFU - PITCH MAIN AFU (524C)							Component ATA:27
PN:105034-07	MOS/MSC	11-Aug-20	O/C	TSO 0, TSR 145				
SN:1123	HRS	5942.6		TSO 0, TSR 2906.5				
WC#: 27.340	AFL	3569		TSO 0, TSR 1533				
PROC. REF: AMM 27-35-05-900-801	PROC. REF: AMM 27-35-05-900-801							
27-35-07-640-801-01 S	PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS - PITCH AAFU (924CW)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 27.350	AFL	3569						
								PKG:32
PROC. REF: AMM 27-35-07-640-801	PROC. REF: AMM 27-35-07-640-801							
27-40-00-720-801-01 S	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.460	AFL	3569						
								PKG:21
PROC. REF: AMM 27-40-00-720-801	PROC. REF: AMM 27-40-00-720-801							
27-40-01-210-802-01	VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)							Service ATA:27
PN:021121-11	MOS	02-Oct-24	72 (+3%)		02-Oct-30	06-Dec-30	1454 d (+65)	
SN:422	HRS	6601.6						
WC#: 27.420	AFL	3875	3750		7625		3615	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-40-01-210-802 PROC. REF: AMM 27-40-01-210-802								
27-40-01-350-801-01		RESTORATION OF THE HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT) - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)						Service ATA:27
PN:021121-11	MOS	18-Jun-19	144 (+3%)	TAC 3	18-Mar-31	27-Jul-31	1621 d (+131)	
SN:422	HRS	5790.5		TAC 0				
WC#: 27.420	AFL	3507	7500 (+3%)	TAC 0	11007	11232	6997 (+225)	
PROC. REF: AMM 27-40-01-350-801 PROC. REF: AMM 27-40-01-350-801								
27-40-01-640-802-01 S		GREASING OF THE HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 27.450	AFL	3940						
								PKG:207
PROC. REF: AMM 27-40-01-640-802 PROC. REF: AMM 27-40-01-640-802								
27-40-01-720-801-01 S		MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - NORMAL ELECTRIC MOTOR (954CA)						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.470	AFL	3569						
								PKG:21
PROC. REF: AMM 27-40-01-720-801 PROC. REF: AMM 27-40-01-720-801								
27-40-01-720-801-02 S		MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - EMERGENCY ELECTRIC MOTOR (954CB)						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.470	AFL	3569						
								PKG:21
PROC. REF: AMM 27-40-01-720-801 PROC. REF: AMM 27-40-01-720-801								
27-40-01-900-801-01		REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (54C)						Component ATA:27
PN:021121-11	MOS/MSC	18-Jun-19	O/C	TSR 3				
SN:422	HRS	5790.5		TSR 0				
WC#: 27.420	AFL	3507		TSR 0				
PROC. REF: AMM 27-40-01-900-801 PROC. REF: AMM 27-40-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40-03-100-801-01	CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR MOTORS - NORMAL ELECTRIC MOTOR (954CA)							Service ATA:27
	MOS/MSC	22-Jun-18	N/A					
	HRS	5357.3						
WC#: 27.500	AFL	3346						
PROC. REF: AMM 27-40-03-100-801	PROC. REF: AMM 27-40-03-100-801							
27-40-03-760-801-01	MEASUREMENT OF THE DROP-OUT CURRENT OF THE ELECTROMAGNETIC BRAKE OF HS ACTUATOR NORMAL MOTOR - NORMAL ELECTRIC MOTOR (954CA)							Service ATA:27
	MOS/MSC	18-Jun-19	N/A					
	HRS	5790.5						
WC#: 27.500	AFL	3507						
PROC. REF: AMM 27-40-03-760-801	PROC. REF: AMM 27-40-03-760-801							
27-40-03-900-801-01	REMOVAL / INSTALLATION OF THE NORMAL MOTOR OF THE HORIZONTAL STABILIZER ACTUATOR - NORMAL ELECTRIC MOTOR (954CA)							Component ATA:27
PN:021121270003	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.500	AFL	0		TSN 0				
PROC. REF: AMM 27-40-03-900-801	PROC. REF: AMM 27-40-03-900-801							
27-40-15-710-801-01 S	OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY - HS EMERGENCY TRIM CONTROL RELAY (953C)							Service ATA:27
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 27-40-15-710-801	PROC. REF: AMM 27-40-15-710-801							
27-40-17-720-801-01 S	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX - HS RELAY BOX (80C)							Service ATA:27
	MOS	23-Oct-13						
	HRS	4569.5	4500 (+30)					
WC#: 27.490	AFL	2879						
								PKG:23
PROC. REF: AMM 27-40-17-720-801, AMM 27-40-17-720-801	PROC. REF: AMM 27-40-17-720-801, AMM 27-40-17-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-40-17-720-801-01A		FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX (MANDATORY 5-40)						Service ATA:27
	MOS	23-Oct-13						MANDATORY 5-40
	HRS	4569.5	5000		9569.5		2777.2	
WC#: 27.490	AFL	2879						
PROC. REF: AMM 27-40-17-720-801, AMM 27-40-17-720-801PROC. REF: AMM 27-40-17-720-801, AMM 27-40-17-720-801								
27-50-00-640-801-01	S	GREASING / LUBRICATION OF FLAP MECHANISMS						Service ATA:27
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 27.071	AFL	3875						
								PKG:16
PROC. REF: AMM 27-50-00-640-801PROC. REF: AMM 27-50-00-640-801								
27-50-00-720-801-01	S	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.620	AFL	3569						
								PKG:21
PROC. REF: AMM 27-50-00-720-801PROC. REF: AMM 27-50-00-720-801								
27-50-00-720-802-01	S	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.630	AFL	3569						
								PKG:21
PROC. REF: AMM 27-50-00-720-802PROC. REF: AMM 27-50-00-720-802								
27-50-00-720-804-01	S	MEASUREMENT OF OVERALL LINKAGE PLAY OF FLAP LINKAGE - LH WING						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.640	AFL	3569						
								PKG:21
PROC. REF: AMM 27-50-00-720-804PROC. REF: AMM 27-50-00-720-804								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-50-00-720-804-02 S	MEASUREMENT OF OVERALL LINKAGE PLAY OF FLAP LINKAGE - RH WING							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.640	AFL	3569						
								PKG:21
PROC. REF: AMM 27-50-00-720-804	PROC. REF: AMM 27-50-00-720-804							
27-52-01-900-801-01	REMOVAL / INSTALLATION OF THE FLAP POWER DRIVE UNIT - FLAP POWER DRIVE UNIT (3C)							Component ATA:27
PN:021138-06	MOS/MSC	08-Jun-16	O/C					
SN:229	HRS	5064.3						
WC#: 27.530	AFL	3203						
PROC. REF: AMM 27-52-01-900-801	PROC. REF: AMM 27-52-01-900-801							
27-52-13-200-801-01 S	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - LH WING							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.650	AFL	3569						
								PKG:31
PROC. REF: AMM 27-52-13-200-801	PROC. REF: AMM 27-52-13-200-801							
27-52-13-200-801-02 S	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - RH WING							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 27.650	AFL	3569						
								PKG:31
PROC. REF: AMM 27-52-13-200-801	PROC. REF: AMM 27-52-13-200-801							
27-53-01-220-801-01 S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (L502C)							Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-220-801	PROC. REF: AMM 27-53-01-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-220-801-02	S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L501C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-220-801	PROC. REF: AMM 27-53-01-220-801							
27-53-01-220-801-03	S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L500C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-220-801	PROC. REF: AMM 27-53-01-220-801							
27-53-01-220-801-04	S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R500C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-220-801	PROC. REF: AMM 27-53-01-220-801							
27-53-01-220-801-05	S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R501C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-220-801	PROC. REF: AMM 27-53-01-220-801							
27-53-01-220-801-06	S	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (R502C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-220-801	PROC. REF: AMM 27-53-01-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-350-801-01	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH OUTBOARD FLAP SCREW JACK (L502C)							Service ATA:27
PN:021137-21	MOS/MSC	15-Jul-96	O/C					
SN:2605	HRS	0		TAC 0				
WC#: 27.560	AFL	0						
PROC. REF: AMM 27-53-01-350-801	PROC. REF: AMM 27-53-01-350-801							
27-53-01-350-801-02	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP LATERAL SCREW JACK (L501C)							Service ATA:27
PN:021137-19	MOS/MSC	15-Jul-96	O/C					
SN:2601	HRS	0		TAC 0				
WC#: 27.540	AFL	0						
PROC. REF: AMM 27-53-01-350-801	PROC. REF: AMM 27-53-01-350-801							
27-53-01-350-801-03	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP CENTER SCREW JACK (L500C)							Service ATA:27
PN:021137-19	MOS/MSC	15-Jul-96	O/C					
SN:2600	HRS	0		TAC 0				
WC#: 27.540	AFL	0						
PROC. REF: AMM 27-53-01-350-801	PROC. REF: AMM 27-53-01-350-801							
27-53-01-350-801-04	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP CENTER SCREW JACK (R500C)							Service ATA:27
PN:021137-19	MOS/MSC	08-May-14	O/C					
SN:966	HRS	4694.25						
WC#: 27.550	AFL	2957						
PROC. REF: AMM 27-53-01-350-801	PROC. REF: AMM 27-53-01-350-801							
27-53-01-350-801-05	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP LATERAL SCREW JACK (R501C)							Service ATA:27
PN:021137-19	MOS/MSC	08-May-14	O/C					
SN:448	HRS	4694.25						
WC#: 27.550	AFL	2957						
PROC. REF: AMM 27-53-01-350-801	PROC. REF: AMM 27-53-01-350-801							
27-53-01-350-801-06	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH OUTBOARD FLAP SCREW JACK (R502C)							Service ATA:27
PN:021137-20	MOS/MSC	15-Jul-96	O/C					
SN:2604	HRS	0		TAC 0				
WC#: 27.560	AFL	0						
PROC. REF: AMM 27-53-01-350-801	PROC. REF: AMM 27-53-01-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-640-802-01	S	GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802								
27-53-01-640-802-02	S	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802								
27-53-01-640-802-03	S	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802								
27-53-01-640-802-04	S	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802								
27-53-01-640-802-05	S	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C)						Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-640-802PROC. REF: AMM 27-53-01-640-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-640-802-06 S	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C)							Service ATA:27
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 27-53-01-640-802	PROC. REF: AMM 27-53-01-640-802							
27-53-01-720-804-01 S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.560	AFL	3569						
								PKG:21
PROC. REF: AMM 27-53-01-720-804	PROC. REF: AMM 27-53-01-720-804							
27-53-01-720-804-02 S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.540	AFL	3569						
								PKG:21
PROC. REF: AMM 27-53-01-720-804	PROC. REF: AMM 27-53-01-720-804							
27-53-01-720-804-03 S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.540	AFL	3569						
								PKG:21
PROC. REF: AMM 27-53-01-720-804	PROC. REF: AMM 27-53-01-720-804							
27-53-01-720-804-04 S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.550	AFL	3569						
								PKG:21
PROC. REF: AMM 27-53-01-720-804	PROC. REF: AMM 27-53-01-720-804							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-720-804-05 S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.550	AFL	3569						
								PKG:21
PROC. REF: AMM 27-53-01-720-804	PROC. REF: AMM 27-53-01-720-804							
27-53-01-720-804-06 S	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.560	AFL	3569						
								PKG:21
PROC. REF: AMM 27-53-01-720-804	PROC. REF: AMM 27-53-01-720-804							
27-53-01-900-803-01	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C)							Component ATA:27
PN:021137-21	MOS/MSC	11-Jul-95	O/C					
SN:2605	HRS	0		TSN 0				
WC#: 27.560	AFL	0						
PROC. REF: AMM 27-53-01-900-803	PROC. REF: AMM 27-53-01-900-803							
27-53-01-900-803-02	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C)							Component ATA:27
PN:021137-19	MOS/MSC	11-Jul-95	O/C					
SN:2601	HRS	0		TSN 0				
WC#: 27.540	AFL	0						
PROC. REF: AMM 27-53-01-900-803	PROC. REF: AMM 27-53-01-900-803							
27-53-01-900-803-03	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C)							Component ATA:27
PN:021137-19	MOS/MSC	11-Jul-95	O/C					
SN:2600	HRS	0		TSN 0				
WC#: 27.540	AFL	0						
PROC. REF: AMM 27-53-01-900-803	PROC. REF: AMM 27-53-01-900-803							
27-53-01-900-803-04	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C)							Component ATA:27
PN:021137-19	MOS/MSC	08-May-14	O/C	TSR 7				
SN:966	HRS	4694.25		TSR 0				
WC#: 27.550	AFL	2957		TSR 0				
PROC. REF: AMM 27-53-01-900-803	PROC. REF: AMM 27-53-01-900-803							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-53-01-900-803-05		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C)						Component ATA:27
PN:021137-19	MOS/MSC	08-May-14	O/C	TSR 7				
SN:448	HRS	4694.25		TSR 0				
WC#: 27.550	AFL	2957		TSR 0				
PROC. REF: AMM 27-53-01-900-803	PROC. REF: AMM 27-53-01-900-803							
27-53-01-900-803-06		REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C)						Component ATA:27
PN:021137-20	MOS/MSC	11-Jul-95	O/C					
SN:2604	HRS	0		TSN 0				
WC#: 27.560	AFL	0						
PROC. REF: AMM 27-53-01-900-803	PROC. REF: AMM 27-53-01-900-803							
27-60-00-720-802-01 S		FUNCTIONAL TEST OF THE AIRBRAKE SYSTEM						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 27.760	AFL	3569						
								PKG:21
PROC. REF: AMM 27-60-00-720-802	PROC. REF: AMM 27-60-00-720-802							
27-60-00-720-802-01A		FUNCTIONAL TEST OF THE AIRBRAKE SYSTEM (MANDATORY 5-40)						Service ATA:27
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6	10000		15942.6		9150.3	
WC#: 27.760	AFL	3569						
PROC. REF: AMM 27-60-00-720-802	PROC. REF: AMM 27-60-00-720-802							
27-61-01-720-801-01 S		FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C1)						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-61-01-720-801	PROC. REF: AMM 27-61-01-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-61-01-720-801-02 S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH CENTER AIRBRAKE POSITION MICROSWITCH (24C1)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-61-01-720-801 PROC. REF: AMM 27-61-01-720-801								
27-61-01-720-801-03 S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH INBOARD AIRBRAKE POSITION MICROSWITCH (23C1)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-61-01-720-801 PROC. REF: AMM 27-61-01-720-801								
27-61-01-720-801-04 S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH INBOARD AIRBRAKE POSITION MICROSWITCH (23C2)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-61-01-720-801 PROC. REF: AMM 27-61-01-720-801								
27-61-01-720-801-05 S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH CENTER AIRBRAKE POSITION MICROSWITCH (24C2)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-61-01-720-801 PROC. REF: AMM 27-61-01-720-801								
27-61-01-720-801-06 S	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH OUTBOARD AIRBRAKE POSITION MICROSWITCH (25C2)							Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-61-01-720-801 PROC. REF: AMM 27-61-01-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-62-01-640-801-01	GREASING OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L30C)							Service ATA:27
	MOS/MSC	08-May-14	O/C					
	HRS	4694.5						
	AFL	2957						
PROC. REF: AMM 27-62-01-640-801	PROC. REF: AMM 27-62-01-640-801							
27-62-01-640-801-02	GREASING OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L29C)							Service ATA:27
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 27-62-01-640-801	PROC. REF: AMM 27-62-01-640-801							
27-62-01-640-801-03	GREASING OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L28C)							Service ATA:27
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 27-62-01-640-801	PROC. REF: AMM 27-62-01-640-801							
27-62-01-640-801-04	GREASING OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R28C)							Service ATA:27
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 27-62-01-640-801	PROC. REF: AMM 27-62-01-640-801							
27-62-01-640-801-05	GREASING OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R29C)							Service ATA:27
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 27-62-01-640-801	PROC. REF: AMM 27-62-01-640-801							
27-62-01-640-801-06	GREASING OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R30C)							Service ATA:27
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 27-62-01-640-801	PROC. REF: AMM 27-62-01-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-62-01-900-801-01	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L30C)							Component ATA:27
PN:106091-07	MOS/MSC	11-Aug-20	O/C	TSR 39				
SN:3881	HRS	5942.6		TSR 0				
WC#: 27.670	AFL	3569		TSR 0				
PROC. REF: AMM 27-62-01-900-801	PROC. REF: AMM 27-62-01-900-801							
27-62-01-900-801-02	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L29C)							Component ATA:27
PN:106091-08	MOS/MSC	11-Jul-95	O/C					
SN:3511	HRS	0		TSN 0				
WC#: 27.670	AFL	0						
PROC. REF: AMM 27-62-01-900-801	PROC. REF: AMM 27-62-01-900-801							
27-62-01-900-801-03	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L28C)							Component ATA:27
PN:106091-09	MOS/MSC	11-Jul-95	O/C					
SN:3515	HRS	0		TSN 0				
WC#: 27.670	AFL	0						
PROC. REF: AMM 27-62-01-900-801	PROC. REF: AMM 27-62-01-900-801							
27-62-01-900-801-04	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R28C)							Component ATA:27
PN:106091-09	MOS/MSC	11-Jul-95	O/C					
SN:3516	HRS	0		TSN 0				
WC#: 27.680	AFL	0						
PROC. REF: AMM 27-62-01-900-801	PROC. REF: AMM 27-62-01-900-801							
27-62-01-900-801-05	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R29C)							Component ATA:27
PN:106091-08	MOS/MSC	11-Jul-95	O/C					
SN:3512	HRS	0		TSN 0				
WC#: 27.680	AFL	0						
PROC. REF: AMM 27-62-01-900-801	PROC. REF: AMM 27-62-01-900-801							
27-62-01-900-801-06	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R30C)							Component ATA:27
PN:106091-07	MOS/MSC	11-Aug-20	O/C	TSR 11				
SN:5449	HRS	5942.6		TSR 0				
WC#: 27.680	AFL	3569		TSR 0				
PROC. REF: AMM 27-62-01-900-801	PROC. REF: AMM 27-62-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-00-710-806-01		OPERATIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF-ATTACK SENSOR CONTACTS						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1000 (+30)		6942.6	6972.6	150.3 (+30)	
WC#: 27.950	AFL	3569						
PROC. REF: AMM 27-80-00-710-806	PROC. REF: AMM 27-80-00-710-806							
27-80-00-720-801-01	S	FUNCTIONAL TEST OF THE SLATS - NORMAL MODE						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-80-00-720-801	PROC. REF: AMM 27-80-00-720-801							
27-80-00-720-801-02	S	FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-80-00-720-801	PROC. REF: AMM 27-80-00-720-801							
27-80-00-720-801-03	S	FUNCTIONAL TEST OF THE SLATS - EMERGENCY MODE						Service ATA:27
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 27-80-00-720-801	PROC. REF: AMM 27-80-00-720-801							
27-80-01-350-802-01		RESTORATION OF THE SLAT SUPPLY DISTRIBUTOR (FUNCTIONAL TEST) - SLAT SUPPLY DISTRIBUTOR (508D)						Service ATA:27
PN:108103-05	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	
SN:706	HRS	5942.6						
WC#: 27.810	AFL	3569						
PROC. REF: AMM 27-80-01-350-802	PROC. REF: AMM 27-80-01-350-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-05-900-801-01	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH INBOARD SLAT ACTUATOR (L500D)							Component ATA:27
PN:106132-05	MOS/MSC	26-Sep-19	O/C					
SN:174	HRS	5844.8						
WC#: 27.820	AFL	3531						
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							
27-80-05-900-801-02	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH INBOARD SLAT ACTUATOR (R500D)							Component ATA:27
PN:106132-05	MOS/MSC	11-Jul-95	O/C					
SN:530	HRS	0		TSN 0				
WC#: 27.830	AFL	0						
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							
27-80-05-900-801-03	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT INBOARD ACTUATOR (L501D)							Component ATA:27
PN:106132-06	MOS/MSC	08-May-14	O/C	TSR 1				
SN:459	HRS	4694.25		TSN 4694.25, TSR 0				
WC#: 27.820	AFL	2957		TSR 0				
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							
27-80-05-900-801-04	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT INBOARD ACTUATOR (R501D)							Component ATA:27
PN:106132-06	MOS/MSC	08-May-14	O/C	TSR 1				
SN:458	HRS	4694.25		TSN 4694.25, TSR 0				
WC#: 27.830	AFL	2957		TSR 0				
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							
27-80-05-900-801-05	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT EMERGENCY ACTUATOR (L502D)							Component ATA:27
PN:106132-07	MOS/MSC	11-Jul-95	O/C					
SN:511	HRS	0		TSN 0				
WC#: 27.840	AFL	0						
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							
27-80-05-900-801-06	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT EMERGENCY ACTUATOR (R502D)							Component ATA:27
PN:106132-07	MOS/MSC	11-Jul-95	O/C					
SN:512	HRS	0		TSN 0				
WC#: 27.840	AFL	0						
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-05-900-801-07	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT OUTBOARD ACTUATOR (L503D)							Component ATA:27
PN:106132-08	MOS/MSC	11-Jul-95	O/C					
SN:491	HRS	0		TSN 0				
WC#: 27.820	AFL	0						
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							
27-80-05-900-801-08	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT OUTBOARD ACTUATOR (R503D)							Component ATA:27
PN:106132-08	MOS/MSC	23-Jul-99	O/C					
SN:630	HRS	1045						
WC#: 27.830	AFL	706						
PROC. REF: AMM 27-80-05-900-801	PROC. REF: AMM 27-80-05-900-801							
27-80-17-720-801-01 S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH (53D)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							
27-80-17-720-801-02 S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH (54D)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							
27-80-17-720-801-03 S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH (55D)							Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-17-720-801-04	S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH (56D)						Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							
27-80-17-720-801-05	S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (57D)						Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							
27-80-17-720-801-06	S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (58D)						Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							
27-80-17-720-801-07	S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (59D)						Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							
27-80-17-720-801-08	S	FUNCTIONAL TEST OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (60D)						Service ATA:27
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 27-80-17-720-801	PROC. REF: AMM 27-80-17-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-80-31-640-801-01 S	SERVICING OF THE SLAT CONTROL CABLE - SLAT CONTROL CABLE (509D)							Service ATA:27
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 27.920	AFL	3875						
								PKG:16
PROC. REF: AMM 27-80-31-640-801	PROC. REF: AMM 27-80-31-640-801							
270021	AILERON CONTROL PRESSURE SEAL BOX							Component ATA:27
PN:F50B271100	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.020	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
270041	RUDDER/ELEVATOR CONTROL PRESSURE SEAL BOX							Component ATA:27
PN:F50B270100	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.025	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
271160	ELEVATOR/AILERON ARTHUR Q-UNIT MONITORING-PRINTED CIRCUIT							Component ATA:27
PN:CI816B	MOS/MSC	18-Aug-06	O/C	TSN 0				
SN:176	HRS	2515.8		TSN 0				
WC#: 27.090	AFL	1741		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
271161	(NORMAL) NORMAL AILERON TRIM ACTUATOR							Component ATA:27
PN:021057-26	MOS/MSC	11-Aug-20	O/C					
SN:8326	HRS	5942.6						
WC#: 27.100	AFL	3569						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
271171	AILERON ARTIFICIAL FEEL UNIT							Component ATA:27
PN:105044-07	MOS/MSC	11-Aug-20	O/C	TSO 0, TSR 145				
SN:1088	HRS	5942.6		TSO 0, TSR 2906.5				
WC#: 27.120	AFL	3569		TSO 0, TSR 1533				
PROC. REF: AMM 27-15-05-900-801	PROC. REF: AMM 27-15-05-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271181	LH AILERON NEUTRAL RETURN UNIT							Component ATA:27
PN:105045-06	MOS/MSC	11-Jul-95	O/C					
SN:3619	HRS	0		TSN 0				
WC#: 27.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
271191	RH AILERON NEUTRAL RETURN UNIT							Component ATA:27
PN:105045-06	MOS/MSC	11-Jul-95	O/C					
SN:3618	HRS	0		TSN 0				
WC#: 27.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
271201	AILERON EMERGENCY ACTUATOR							Component ATA:27
PN:021127	MOS/MSC	11-Aug-20	O/C	TSO 0				
SN:422	HRS	5942.6		TSO 0				
WC#: 27.140	AFL	3569		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
271211	VARIABLE RATIO (AMEDEE) BELLCRANK							Component ATA:27
PN:028008-28	MOS/MSC	11-Aug-20	O/C	TSR 145				
SN:2545	HRS	5942.6		TSR 2906.5				
WC#: 27.150	AFL	3569		TSR 1533				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
272121	RUDDER ARTIFICIAL FEEL UNIT							Component ATA:27
PN:105043-07	MOS/MSC	08-May-14	O/C	TSR 20				
SN:1166	HRS	4694.25		TSR 0				
WC#: 27.230	AFL	2957		TSR 0				
PROC. REF: AMM 27-24-01-900-801PROC. REF: AMM 27-24-01-900-801								
272131	RUDDER AUXILIARY ARTIFICIAL FEEL UNIT							Component ATA:27
PN:105070-04	MOS/MSC	11-Aug-20	O/C	TSO 0, TSR 145				
SN:939	HRS	5942.6		TSO 0, TSR 2906.5				
WC#: 27.240	AFL	3569		TSO 0, TSR 1533				
PROC. REF: AMM 27-25-07-900-801PROC. REF: AMM 27-25-07-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272141	RUDDER TRIM ACTUATOR							Component ATA:27
PN:021057-28	MOS/MSC	08-May-14	O/C	TSR 1				
SN:8289	HRS	4694.25		TSN 4694.25, TSR 0				
WC#: 27.250	AFL	2957		TSN 2957, TSR 0				
PROC. REF: AMM 27-24-01-900-801	PROC. REF: AMM 27-24-01-900-801							
272161	AILERON-RUDDER-ELEVATOR TRIM TRIPLE INDICATOR							Component ATA:27
PN:4863-52-8	MOS/MSC	11-Jul-95	O/C					
SN:393	HRS	0		TSN 0				
WC#: 27.270	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
273126	HORIZONTAL STABILIZER POSITION PICK-OFF TRANSMITTER							Component ATA:27
PN:016082-04	MOS/MSC	23-Jul-99	O/C					
SN:51	HRS	1045						
WC#: 27.330	AFL	706						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
273141	ELEVATOR NEUTRAL RETURN UNIT							Component ATA:27
PN:105045	MOS/MSC	11-Jul-95	O/C					
SN:3625	HRS	0		TSN 0				
WC#: 27.350	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
274171	HORIZONTAL STABILIZER AIRBRAKES-TRIM CONTROL BOX							Component ATA:27
PN:013015-14	MOS/MSC	11-Jul-95	O/C					
SN:1381	HRS	0		TSN 0				
WC#: 27.520	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
274186	HORIZONTAL STABILIZER ACTUATOR EMERGENCY ELECTRIC MOTOR							Component ATA:27
PN:0210972800	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.510	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275136	LH DOUBLE ANGLE GEARBOX							Component ATA:27
PN:021068-06	MOS/MSC	11-Jul-95	O/C					
SN:1906	HRS	0		TSN 0				
WC#: 27.570	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275141	RH DOUBLE ANGLE GEARBOX							Component ATA:27
PN:021068-07	MOS/MSC	11-Jul-95	O/C					
SN:1929	HRS	0		TSN 0				
WC#: 27.570	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275146	LH FLAP SINGLE GEARBOX							Component ATA:27
PN:021063-01	MOS/MSC	11-Jul-95	O/C					
SN:1907	HRS	0		TSN 0				
WC#: 27.580	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275151	RH FLAP SINGLE GEARBOX							Component ATA:27
PN:021063-01	MOS/MSC	11-Jul-95	O/C					
SN:1098	HRS	0		TSN 0				
WC#: 27.580	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275156	FLAP FLAP POSITION INDICATOR							Component ATA:27
PN:4203-30-8	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.590	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275161	LH FLAP POSITION TRANSMITTER							Component ATA:27
PN:1-4414-2	MOS/MSC	11-Jul-95	O/C					
SN:586	HRS	0		TSN 0				
WC#: 27.590	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275166	RH FLAP POSITION TRANSMITTER							Component ATA:27
PN:2-4415-2	MOS/MSC	11-Jul-95	O/C					
SN:293	HRS	0		TSN 0				
WC#: 27.590	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276131	INBOARD/OUTBOARD AIRBRAKE ELECTRO- DISTRIBUTOR							Component ATA:27
PN:65670-1	MOS/MSC	11-Jul-95	O/C					
SN:1770	HRS	0		TSN 0				
WC#: 27.690	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276136	MIDDLE AIRBRAKE ELECTRO- DISTRIBUTOR							Component ATA:27
PN:65670-1	MOS/MSC	11-Jul-95	O/C					
SN:1787	HRS	0		TSN 0				
WC#: 27.690	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276141	LH AIRBRAKE CHECK VALVE							Component ATA:27
PN:C24539000	MOS/MSC	11-Jul-95	O/C					
SN:U48	HRS	0		TSN 0				
WC#: 27.700	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276146	RH AIRBRAKE CHECK VALVE							Component ATA:27
PN:A24524	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.700	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276151	MIDDLE AIRBRAKE CIRCUIT PRESSURE RELIEF VALVE							Component ATA:27
PN:A24519001	MOS/MSC	11-Jul-95	O/C					
SN:FM1075	HRS	0		TSN 0				
WC#: 27.710	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276156	INBOARD/OUTBOARD AIRBRAKE CIRCUIT PRESSURE RELIEF VALVE							Component ATA:27
PN:A24519	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.710	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276161	CENTER AIRBRAKE ACTUATOR SUPPLY CHECK VALVE							Component ATA:27
PN:C24541000	MOS/MSC	11-Jul-95	O/C					
SN:U73	HRS	0		TSN 0				
WC#: 27.720	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276166	INBOARD/OUTBOARD AIRBRAKE ACTUATOR CIRCUIT NONRETURN VALVE							Component ATA:27
PN:A24515	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.720	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276171	LH INBOARD AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-202	MOS/MSC	11-Jul-95	O/C					
SN:B3821	HRS	0		TSN 0				
WC#: 27.730	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276176	RH INBOARD AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-202	MOS/MSC	11-Jul-95	O/C					
SN:B3829	HRS	0		TSN 0				
WC#: 27.740	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276181	LH MIDDLE AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-302	MOS/MSC	11-Jul-95	O/C					
SN:B3815	HRS	0		TSN 0				
WC#: 27.730	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276186	RH MIDDLE AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-302	MOS/MSC	11-Jul-95	O/C					
SN:B3841	HRS	0		TSN 0				
WC#: 27.740	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276191	LH OUTBOARD AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-402	MOS/MSC	11-Jul-95	O/C					
SN:3807	HRS	0		TSN 0				
WC#: 27.730	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
276196	RH OUTBOARD AIRBRAKE RESTRICTOR							Component ATA:27
PN:C24370-402	MOS/MSC	11-Jul-95	O/C					
SN:3808	HRS	0		TSN 0				
WC#: 27.740	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278111	LH INTERMEDIATE BEARING							Component ATA:27
PN:021063-01	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.780	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278116	RH INTERMEDIATE BEARING							Component ATA:27
PN:021063-01	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.780	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278121	FLAP/SLAT FLAP/SLAT CONTROL BOX							Component ATA:27
PN:7016	MOS/MSC	11-Jul-95	O/C					
SN:379	HRS	0		TSN 0				
WC#: 27.790	AFL	0						
PROC. REF: AMM 27-51-01-900-801PROC. REF: AMM 27-51-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
278126	SLAT CONTROL DISTRIBUTOR							Component ATA:27
PN:108092-03	MOS/MSC	11-Jul-95	O/C					
SN:536	HRS	0		TSN 0				
WC#: 27.800	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278131	SLAT SUPPLY DISTRIBUTOR							Component ATA:27
PN:108103-05	MOS/MSC	11-Aug-20	O/C	TSO 0				
SN:706	HRS	5942.6		TSO 0				
WC#: 27.810	AFL	3569		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278136	SLAT STAND-BY DISTRIBUTOR							Component ATA:27
PN:65670-1	MOS/MSC	11-Jul-95	O/C					
SN:1758	HRS	0		TSN 0				
WC#: 27.800	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278181	LH SLATS EMERGENCY CIRCUIT ADJUSTABLE DIAPHRAGM							Component ATA:27
PN:JETX0504650AC	MOS/MSC	11-Jul-95	O/C					
SN:MA77	HRS	0		TSN 0				
WC#: 27.850	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278186	RH SLATS EMERGENCY CIRCUIT ADJUSTABLE DIAPHRAGM							Component ATA:27
PN:JETX0504650AC	MOS/MSC	11-Jul-95	O/C					
SN:MA78	HRS	0		TSN 0				
WC#: 27.850	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278191	SLAT SUPPLY CIRCUIT CHECK VALVE							Component ATA:27
PN:A24515	MOS/MSC	11-Jul-95	O/C					
SN:FM2085	HRS	0		TSN 0				
WC#: 27.860	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
278196	OUTBOARD SLAT RETRACTION FLOW RESTRICTOR							Component ATA:27
PN:C24346-302	MOS/MSC	11-Jul-95	O/C					
SN:B1634	HRS	0		TSN 0				
WC#: 27.870	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278201	LH INBOARD SLAT RETRACTION RESTRICTOR							Component ATA:27
PN:C24346-102	MOS/MSC	11-Jul-95	O/C					
SN:B1645	HRS	0		TSN 0				
WC#: 27.880	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278206	RH INBOARD SLAT RETRACTION RESTRICTOR							Component ATA:27
PN:C24346-102	MOS/MSC	11-Jul-95	O/C					
SN:B1648	HRS	0		TSN 0				
WC#: 27.880	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278211	LH NORMAL SLAT CIRCUIT ADJUSTABLE RESTRICTOR							Component ATA:27
PN:C24370-102	MOS/MSC	11-Jul-95	O/C					
SN:B3849	HRS	0		TSN 0				
WC#: 27.890	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278216	RH NORMAL SLAT CIRCUIT ADJUSTABLE RESTRICTOR							Component ATA:27
PN:C24370-102	MOS/MSC	11-Jul-95	O/C					
SN:B3846	HRS	0		TSN 0				
WC#: 27.890	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278235	LEADING EDGE SELECTOR VALVE CONTROL CABLE							Component ATA:27
PN:F50B773001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.920	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
278286	PITCH GUST VALVE							Component ATA:27
PN:104086-13	MOS/MSC	11-Jul-95	O/C					
SN:3833	HRS	0		TSN 0				
WC#: 27.960	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
278311	SLAT AIRSPEED SWITCH							Component ATA:27
PN:4219F010301	MOS/MSC	11-Jul-95	O/C					
SN:1709	HRS	0		TSN 0				
WC#: 27.900	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 28 - FUEL								
28-00-00-280-801-01	FUEL CONTAMINATION DETECTION TEST							Service ATA:28
	MOS	17-Apr-26	6		17-Oct-26		8 d	
	HRS	6746.8						
WC#: 28.820	AFL	3979						
								PKG:207
PROC. REF: AMM 28-00-00-280-801PROC. REF: AMM 28-00-00-280-801								
28-00-00-290-801-01 U	BORESCOPE INSPECTION LEFT FEEDER TANK							Service ATA:28
	MOS	24-Oct-25	12		24-Oct-26		15 d	
	HRS	6700.5	500		7200.5		408.2	
	AFL	3940						
28-00-00-290-801-02 U	BORESCOPE INSPECTION CENTER FEEDER TANK							Service ATA:28
	MOS	24-Oct-25	12		24-Oct-26		15 d	
	HRS	6700.5	500		7200.5		408.2	
	AFL	3940						
28-00-00-290-801-03 U	BORESCOPE INSPECTION RIGHT FEEDER TANK							Service ATA:28
	MOS	24-Oct-25	12		24-Oct-26		15 d	
	HRS	6700.5	500		7200.5		408.2	
	AFL	3940						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-00-00-910-803-01	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD							Service ATA:28
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-910-803	PROC. REF: AMM 28-00-00-910-803							
28-00-00-910-803-02	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - GRAVITY POURING METHOD							Service ATA:28
	MOS	24-Oct-25	6 (+2m)		24-Apr-26	24-Jun-26	OVD	
	HRS	6700.5						
	AFL	3940						
PROC. REF: AMM 28-00-00-910-803	PROC. REF: AMM 28-00-00-910-803							
28-00-00-910-803-03	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - FUEL INJECTION METHOD							Service ATA:28
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-910-803	PROC. REF: AMM 28-00-00-910-803							
28-00-00-910-803-04	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - GRAVITY POURING METHOD							Service ATA:28
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-910-803	PROC. REF: AMM 28-00-00-910-803							
28-00-00-910-803-06	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING / REPLACEMENT OF FILTERS							Service ATA:28
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00-910-803	PROC. REF: AMM 28-00-00-910-803							
28-00-00-910-804-01	MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS							Service ATA:28
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-00-00-910-804	PROC. REF: AMM 28-00-00-910-804							
28-00-00-960-802-01	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK SOL./TRANSF. VALVE HOSE (L903QD)							Service ATA:28
PN:71029-380A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77371	HRS	4193.5						
WC#: 28.470	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-02	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK SOL./TRANSF. VALVE HOSE (M903QD)							Service ATA:28
PN:71029-420A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77559	HRS	4193.5						
WC#: 28.475	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-03	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK SOL./TRANSF. VALVE HOSE (R903QD)							Service ATA:28
PN:71029-380A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77415	HRS	4193.5						
WC#: 28.470	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-04	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK REG. VALVE SUPPLY HOSE (L904QD)							Service ATA:28
PN:71029-1020A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:76692	HRS	4193.5						
WC#: 28.480	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-05	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG. VALVE SUPPLY HOSE (M904QD)							Service ATA:28
PN:71029-450A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77585	HRS	4193.5						
WC#: 28.485	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-00-00-960-802-06	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK REG. VALVE SUPPLY HOSE (R904QD)							Service ATA:28
PN:71029-1020A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:76693	HRS	4193.5						
WC#: 28.480	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-07	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG./TRANSF. VALVE SUPPLY HOSE (M905QD)							Service ATA:28
PN:71029-560A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77531	HRS	4193.5						
WC#: 28.490	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-08	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (L906QD)							Service ATA:28
PN:71028-610A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77170	HRS	4193.5						
WC#: 28.500	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-09	DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (R906QD)							Service ATA:28
PN:71028-610A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77166	HRS	4193.5						
WC#: 28.500	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-10	DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (L907QD)							Service ATA:28
PN:71028-1290A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77618	HRS	4193.5						
WC#: 28.510	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-11	DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (M907QD)							Service ATA:28
PN:71028-2460A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:76522	HRS	4193.5						
WC#: 28.515	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-00-00-960-802-12		DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (R907QD)						Service ATA:28
PN:71028-1290A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77619	HRS	4193.5						
WC#: 28.510	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-13		DISCARD OF FEEDER TANK FUEL HOSES - LH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (L908QD)						Service ATA:28
PN:71030-496A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77459	HRS	4193.5						
WC#: 28.520	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-14		DISCARD OF FEEDER TANK FUEL HOSES - CENTER FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (M908QD)						Service ATA:28
PN:71030-676A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77003	HRS	4193.5						
WC#: 28.525	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-00-00-960-802-15		DISCARD OF FEEDER TANK FUEL HOSES - RH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (R908QD)						Service ATA:28
PN:71030-496A	MOS	23-Oct-12	144 (+20%/-20%)		23-Oct-24	17-Mar-27	TOL (+159 d)	LIFE LIMIT
SN:77460	HRS	4193.5						
WC#: 28.520	AFL	2686						
PROC. REF: AMM 28-00-00-960-802	PROC. REF: AMM 28-00-00-960-802							
28-20-00-710-802-01 S		OPERATIONAL TEST OF THE TRANSFER VALVES AND ISOLATION VALVES - TRANSFER MANIFOLD TRANSFER VALVES (17Q1) AND (17Q2)						Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 28-20-00-710-802	PROC. REF: AMM 28-20-00-710-802							
28-20-00-710-802-02 S		OPERATIONAL TEST OF THE TRANSFER VALVES AND ISOLATION VALVES - TRANSFER VALVE (13Q1) AND (13Q2)						Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-20-00-710-802 PROC. REF: AMM 28-20-00-710-802								
28-20-00-710-802-03 S	OPERATIONAL TEST OF THE TRANSFER VALVES AND ISOLATION VALVES - ISOLATION VALVES (L17QD) , (M17QD) AND (R17QD)							Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 28-20-00-710-802 PROC. REF: AMM 28-20-00-710-802								
28-20-00-900-801-01	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK SOL./TRANSF. VALVE HOSE (L903QD)							Component ATA:28
PN:71029-380A	MOS/MSC	23-Oct-12	H/T	TSN 6				
SN:77371	HRS	4193.5		TSN 0				
WC#: 28.470	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801 PROC. REF: AMM 28-20-00-900-801								
28-20-00-900-801-02	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK SOL./TRANSF. VALVE HOSE (M903QD)							Component ATA:28
PN:71029-420A	MOS/MSC	23-Oct-12	H/T	TSN 4				
SN:77559	HRS	4193.5		TSN 0				
WC#: 28.475	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801 PROC. REF: AMM 28-20-00-900-801								
28-20-00-900-801-03	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK SOL./TRANSF. VALVE HOSE (R903QD)							Component ATA:28
PN:71029-380A	MOS/MSC	23-Oct-12	H/T	TSN 6				
SN:77415	HRS	4193.5		TSN 0				
WC#: 28.470	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801 PROC. REF: AMM 28-20-00-900-801								
28-20-00-900-801-04	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK REG. VALVE SUPPLY HOSE (L904QD)							Component ATA:28
PN:71029-1020A	MOS/MSC	23-Oct-12	H/T	TSN 13				
SN:76692	HRS	4193.5		TSN 0				
WC#: 28.480	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801 PROC. REF: AMM 28-20-00-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-20-00-900-801-05	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG. VALVE SUPPLY HOSE (M904QD)							Component ATA:28
PN:71029-450A	MOS/MSC	23-Oct-12	H/T	TSN 4				
SN:77585	HRS	4193.5		TSN 0				
WC#: 28.485	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-06	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK REG. VALVE SUPPLY HOSE (R904QD)							Component ATA:28
PN:71029-1020A	MOS/MSC	23-Oct-12	H/T	TSN 13				
SN:76693	HRS	4193.5		TSN 0				
WC#: 28.480	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-07	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK REG./TRANSF. VALVE SUPPLY HOSE (M905QD)							Component ATA:28
PN:71029-560A	MOS/MSC	23-Oct-12	H/T	TSN 4				
SN:77531	HRS	4193.5		TSN 0				
WC#: 28.490	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-08	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (L906QD)							Component ATA:28
PN:71028-610A	MOS/MSC	23-Oct-12	H/T	TSN 8				
SN:77170	HRS	4193.5		TSN 0				
WC#: 28.500	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-09	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/SOL. VALVE HOSE (R906QD)							Component ATA:28
PN:71028-610A	MOS/MSC	23-Oct-12	H/T	TSN 8				
SN:77166	HRS	4193.5		TSN 0				
WC#: 28.500	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-10	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (L907QD)							Component ATA:28
PN:71028-1290A	MOS/MSC	23-Oct-12	H/T	TSN 4				
SN:77618	HRS	4193.5		TSN 0				
WC#: 28.510	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-20-00-900-801-11	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (M907QD)							Component ATA:28
PN:71028-2460A	MOS/MSC	23-Oct-12	H/T	TSN 4				
SN:76522	HRS	4193.5		TSN 0				
WC#: 28.515	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-12	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE (R907QD)							Component ATA:28
PN:71028-1290A	MOS/MSC	23-Oct-12	H/T	TSN 4				
SN:77619	HRS	4193.5		TSN 0				
WC#: 28.510	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-13	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - LH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (L908QD)							Component ATA:28
PN:71030-496A	MOS/MSC	23-Oct-12	H/T	TSN 5				
SN:77459	HRS	4193.5		TSN 0				
WC#: 28.520	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-14	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - CENTER FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (M908QD)							Component ATA:28
PN:71030-676A	MOS/MSC	23-Oct-12	H/T	TSN 11				
SN:77003	HRS	4193.5		TSN 0				
WC#: 28.525	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-20-00-900-801-15	REMOVAL / INSTALLATION OF THE FEEDER TANK FUEL HOSES - RH FEEDER TANK CK VALVE/HIGH LEVEL VALVE RETURN HOSE (R908QD)							Component ATA:28
PN:71030-496A	MOS/MSC	23-Oct-12	H/T	TSN 5				
SN:77460	HRS	4193.5		TSN 0				
WC#: 28.520	AFL	2686		TSN 0				
PROC. REF: AMM 28-20-00-900-801	PROC. REF: AMM 28-20-00-900-801							
28-21-01-350-801-01	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF MOTOR BRUSHES) - BOOSTER PUMP 1 (3Q1)							Service ATA:28
PN:226075-51	MOS	21-Sep-18						
SN:B56153	HRS	5469.5	1800 (+3%)		7269.5	7323.5	477.2 (+54)	
WC#: 28.600	AFL	3390						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-21-01-350-801	PROC. REF: AMM 28-21-01-350-801							
28-21-01-350-801-02	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF MOTOR BRUSHES) - BOOSTER PUMP 2 (3Q2)							Service ATA:28
PN:226075-51	MOS	15-Mar-19						
SN:10341	HRS	5704.5	1800 (+3%)		7504.5	7558.5	712.2 (+54)	
WC#: 28.610	AFL	3476						
PROC. REF: AMM 28-21-01-350-801	PROC. REF: AMM 28-21-01-350-801							
28-21-01-350-801-03	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF MOTOR BRUSHES) - BOOSTER PUMP 3 (3Q3)							Service ATA:28
PN:226075-51	MOS	15-Aug-23						
SN:10180	HRS	6522.2	1800 (+3%)		8322.2	8376.2	1529.9 (+54)	
WC#: 28.620	AFL	3830						
PROC. REF: AMM 28-21-01-350-801	PROC. REF: AMM 28-21-01-350-801							
28-21-01-350-802-01	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF BEARINGS) - BOOSTER PUMP 1 (3Q1)							Service ATA:28
PN:226075-51	MOS/MSC	21-Sep-18	O/C					
SN:B56153	HRS	5469.5						
WC#: 28.600	AFL	3390						
PROC. REF: AMM 28-21-01-350-802	PROC. REF: AMM 28-21-01-350-802							
28-21-01-350-802-02	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF BEARINGS) - BOOSTER PUMP 2 (3Q2)							Service ATA:28
PN:226075-51	MOS/MSC	02-Oct-24	O/C					
SN:10341	HRS	6601.6						
WC#: 28.610	AFL	3875						
PROC. REF: AMM 28-21-01-350-802	PROC. REF: AMM 28-21-01-350-802							
28-21-01-350-802-03	RESTORATION OF THE BOOSTER PUMPS (REPLACEMENT OF BEARINGS) - BOOSTER PUMP 3 (3Q3)							Service ATA:28
PN:226075-51	MOS/MSC	15-Aug-23	O/C					
SN:10180	HRS	6522.2						
WC#: 28.620	AFL	3830						
PROC. REF: AMM 28-21-01-350-802	PROC. REF: AMM 28-21-01-350-802							
28-21-01-900-801-01	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 1 (3Q1)							Component ATA:28
PN:226075-51	MOS/MSC	21-Sep-18	O/C	TSN 77				
SN:B56153	HRS	5469.5		TSN 0				
WC#: 28.600	AFL	3390		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-21-01-900-801PROC. REF: AMM 28-21-01-900-801								
28-21-01-900-801-02	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 2 (3Q2)							Component ATA:28
PN:226075-51	MOS/MSC	02-Oct-24	O/C	TSR 9				
SN:10341	HRS	6601.6		TSR 0				
WC#: 28.610	AFL	3875		TSR 0				
PROC. REF: AMM 28-21-01-900-801PROC. REF: AMM 28-21-01-900-801								
28-21-01-900-801-03	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 3 (3Q3)							Component ATA:28
PN:226075-51	MOS/MSC	15-Aug-23	O/C	TSR 1				
SN:10180	HRS	6522.2		TSR 0				
WC#: 28.620	AFL	3830		TSR 0				
PROC. REF: AMM 28-21-01-900-801PROC. REF: AMM 28-21-01-900-801								
28-21-05-200-802-01	CHECK OF LOW PRESSURE CROSSFEED DRAINING AND SHUT-OFF VALVE SEALS OF THE BP MANIFOLD - BP 1 MANIFOLD (L14QD)							Service ATA:28
PN:L88A19-208	MOS	15-Jul-96						
SN:20603	HRS	0	10000 (+3%)		10000	10300	3207.7 (+300)	
WC#: 28.550	AFL	0						
PROC. REF: AMM 28-21-05-200-802PROC. REF: AMM 28-21-05-200-802								
28-21-05-200-802-02	CHECK OF LOW PRESSURE CROSSFEED DRAINING AND SHUT-OFF VALVE SEALS OF THE BP MANIFOLD - BP 3 MANIFOLD (R14QD)							Service ATA:28
PN:L88A19-209	MOS	15-Jul-96						
SN:20582	HRS	0	10000 (+3%)		10000	10300	3207.7 (+300)	
WC#: 28.550	AFL	0						
PROC. REF: AMM 28-21-05-200-802PROC. REF: AMM 28-21-05-200-802								
28-21-05-900-801-01	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 1 MANIFOLD (L14QD)							Component ATA:28
PN:L88A19-208	MOS/MSC	11-Jul-95	O/C					
SN:20603	HRS	0		TSN 0				
WC#: 28.550	AFL	0						
PROC. REF: AMM 28-21-05-900-801PROC. REF: AMM 28-21-05-900-801								
28-21-05-900-801-02	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 2 MANIFOLD (M14QD)							Component ATA:28
PN:L88A25-203	MOS/MSC	11-Jul-95	O/C					
SN:20282	HRS	0		TSN 0				
WC#: 28.560	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-21-05-900-801 PROC. REF: AMM 28-21-05-900-801								
28-21-05-900-801-03		REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 3 MANIFOLD (R14QD)						Component ATA:28
PN:L88A19-209	MOS/MSC	11-Jul-95	O/C					
SN:20582	HRS	0		TSN 0				
WC#: 28.550	AFL	0						
PROC. REF: AMM 28-21-05-900-801 PROC. REF: AMM 28-21-05-900-801								
28-21-07-100-801-01 S		CLEANING OF THE JET PUMP FILTERS - LH JET PUMP FILTER (L40QD)						Service ATA:28
	MOS	08-Apr-21	72 (+2m)					
	HRS	6073.9						
WC#: 28.150	AFL	3634						
								PKG:31
PROC. REF: AMM 28-21-07-100-801 PROC. REF: AMM 28-21-07-100-801								
28-21-07-100-801-02 S		CLEANING OF THE JET PUMP FILTERS - RH JET PUMP FILTER (R40QD)						Service ATA:28
	MOS	08-Apr-21	72 (+2m)					
	HRS	6073.9						
	AFL	3634						
								PKG:31
PROC. REF: AMM 28-21-07-100-801 PROC. REF: AMM 28-21-07-100-801								
28-21-13-790-801-01		LEAK TEST OF THE FUEL SHUT-OFF VALVES - ENGINE 1 SHUT-OFF VALVE INTEGRATED IN BP 1 MANIFOLD (L14QD)						Service ATA:28
PN:PN	MOS/MSC	18-Jun-19	E/C					
SN:UNKNOWN	HRS	5790.5	1530		7320.5		528.2	
WC#: 28.570	AFL	3507						
PROC. REF: AMM 28-21-13-790-801 PROC. REF: AMM 28-21-13-790-801								
28-21-13-790-801-01A		LEAK TEST LH FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)						Service ATA:28
PN:PN	MOS	18-Jun-19						MANDATORY 5-40
SN:UNKNOWN	HRS	5790.5	1530		7320.5		528.2	
WC#: 28.570	AFL	3507						
PROC. REF: AMM 28-21-13-790-801 PROC. REF: AMM 28-21-13-790-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-13-790-801-02	LEAK TEST OF THE FUEL SHUT-OFF VALVES - ENGINE 2 SHUT-OFF VALVE INTEGRATED IN BP 2 MANIFOLD (M14QD)							Service ATA:28
PN:PN	MOS/MSC	18-Jun-19	E/C					
SN:UNKNOWN	HRS	5790.5	1530		7320.5		528.2	
WC#: 28.580	AFL	3507						
PROC. REF: AMM 28-21-13-790-801	PROC. REF: AMM 28-21-13-790-801							
28-21-13-790-801-02A	LEAK TEST MIDDLE FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)							Service ATA:28
PN:PN	MOS	18-Jun-19						MANDATORY 5-40
SN:UNKNOWN	HRS	5790.5	1530		7320.5		528.2	
WC#: 28.580	AFL	3507						
PROC. REF: AMM 28-21-13-790-801	PROC. REF: AMM 28-21-13-790-801							
28-21-13-790-801-03	LEAK TEST OF THE FUEL SHUT-OFF VALVES - ENGINE 3 SHUT-OFF VALVE INTEGRATED IN BP 3 MANIFOLD (R14QD)							Service ATA:28
PN:PN	MOS/MSC	18-Jun-19	E/C					
SN:UNKNOWN	HRS	5790.5	1530		7320.5		528.2	
WC#: 28.590	AFL	3507						
PROC. REF: AMM 28-21-13-790-801	PROC. REF: AMM 28-21-13-790-801							
28-21-13-790-801-03A	LEAK TEST RH FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)							Service ATA:28
PN:PN	MOS	18-Jun-19						MANDATORY 5-40
SN:UNKNOWN	HRS	5790.5	1530		7320.5		528.2	
WC#: 28.590	AFL	3507						
PROC. REF: AMM 28-21-13-790-801	PROC. REF: AMM 28-21-13-790-801							
28-21-14-720-801-01	FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 1 MANIFOLD (L14QD)							Service ATA:28
PN:L88A19-208	MOS	15-Jul-96						
SN:20603	HRS	0	10000 (+3%)		10000	10300	3207.7 (+300)	
WC#: 28.550	AFL	0						
PROC. REF: AMM 28-21-14-720-801	PROC. REF: AMM 28-21-14-720-801							
28-21-14-720-801-02	FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 3 MANIFOLD (R14QD)							Service ATA:28
PN:L88A19-209	MOS	15-Jul-96						
SN:20582	HRS	0	10000 (+3%)		10000	10300	3207.7 (+300)	
WC#: 28.550	AFL	0						
PROC. REF: AMM 28-21-14-720-801	PROC. REF: AMM 28-21-14-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-16-610-801-01		SERVICING OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - SERVICING OF THE CONTROL CABLES AND CHECKING OF THE SHUT-OFF VALVES OPENING/CLOSING						Service ATA:28
	MOS	24-Oct-25	12 (+1m)	Adj -22d	02-Oct-26	02-Nov-26	TOL (+24 d)	
	HRS	6700.5	1000 (+30)		7700.5	7730.5	908.2 (+30)	
	AFL	3940						
								PKG:207
PROC. REF: AMM 28-21-16-610-801	PROC. REF: AMM 28-21-16-610-801							
28-21-16-610-801-01A		SERVICING OF THE FUEL SHUT-OFF VALVE CONTROL CABLES AND CHECKING OF THE SHUT-OFF VALVES OPENING/CLOSING (MANDATORY 5-40)						Service ATA:28
	MOS	24-Oct-25	13		24-Nov-26	46 d		MANDATORY 5-40
	HRS	6700.5	1000		7700.5	908.2		
	AFL	3940						
PROC. REF: AMM 28-21-16-610-801	PROC. REF: AMM 28-21-16-610-801							
28-21-16-610-801-02 S		SERVICING OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - MEASUREMENT OF CONTROL CABLE SLIDING FORCES						Service ATA:28
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 28-21-16-610-801	PROC. REF: AMM 28-21-16-610-801							
28-21-16-900-801-01		REMOVAL / INSTALLATION OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - LH SHUT-OFF VALVE FLEXIBLE CONTROL CABLE (L15QD)						Component ATA:28
PN:F50B795001110A3	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.650	AFL	0						
PROC. REF: AMM 28-21-16-900-801	PROC. REF: AMM 28-21-16-900-801							
28-21-16-900-801-02		REMOVAL / INSTALLATION OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - CENTER SHUT-OFF VALVE FLEXIBLE CONTROL CABLE (M15QD)						Component ATA:28
PN:F50B795001110A3	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.660	AFL	0						
PROC. REF: AMM 28-21-16-900-801	PROC. REF: AMM 28-21-16-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-16-900-801-03	REMOVAL / INSTALLATION OF THE FUEL SHUT-OFF VALVES CONTROL CABLES - RH SHUT-OFF VALVE FLEXIBLE CONTROL CABLE (R15QD)							Component ATA:28
PN:F50B795001110A3	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.670	AFL	0						
PROC. REF: AMM 28-21-16-900-801	PROC. REF: AMM 28-21-16-900-801							
28-21-33-900-801-01	NO. 1 ENGINE FUEL SUPPLY HOSE							Component ATA:28
PN:665106EE2001	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:01-07	HRS	2709.8		TSN 0				
WC#: 28.530	AFL	1854		TSN 0				
PROC. REF: AMM 28-21-33-900-801, AMM 28-21-33-900-802	PROC. REF: AMM 28-21-33-900-801, AMM 28-21-33-900-802							
28-21-33-900-801-01	NO. 2 ENGINE FUEL SUPPLY HOSE							Component ATA:28
PN:665054EE2004	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:12-06	HRS	2709.8		TSN 0				
WC#: 28.535	AFL	1854		TSN 0				
PROC. REF: AMM 28-21-33-900-801, AMM 28-21-33-900-802	PROC. REF: AMM 28-21-33-900-801, AMM 28-21-33-900-802							
28-21-33-900-801-01	NO. 3 ENGINE FUEL SUPPLY HOSE							Component ATA:28
PN:665106EE2001	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:01-07	HRS	2709.8		TSN 0				
WC#: 28.530	AFL	1854		TSN 0				
PROC. REF: AMM 28-21-33-900-801, AMM 28-21-33-900-802	PROC. REF: AMM 28-21-33-900-801, AMM 28-21-33-900-802							
28-21-33-900-803-01	REMOVAL / INSTALLATION OF THE APU FUEL SUPPLY HOSE - APU FUEL SUPPLY HOSE (902QD)							Component ATA:28
PN:156F005-6D0125	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 28.540	AFL	1854		TSN 0				
PROC. REF: AMM 28-21-33-900-803	PROC. REF: AMM 28-21-33-900-803							
28-21-33-960-801-01	DISCARD OF THE FUEL SUPPLY HOSES - APU FUEL SUPPLY HOSE (902QD)							Service ATA:28
PN:156F005-6D0125	MOS/MSC	17-Jul-07	O/C	TAC 0				
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 28.540	AFL	1854		TAC 0				
PROC. REF: AMM 28-21-33-960-801	PROC. REF: AMM 28-21-33-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-33-960-801-02	DISCARD OF THE FUEL SUPPLY HOSES - ENGINE 1 FUEL SUPPLY HOSE (L901QD)							Service ATA:28
PN:665106EE2001	MOS/MSC	17-Jul-07	O/C	TAC 0				
SN:01-07	HRS	2709.8		TAC 0				
WC#: 28.530	AFL	1854		TAC 0				
PROC. REF: AMM 28-21-33-960-801	PROC. REF: AMM 28-21-33-960-801							
28-21-33-960-801-03	DISCARD OF THE FUEL SUPPLY HOSES - ENGINE 2 FUEL SUPPLY HOSE (M901QD)							Service ATA:28
PN:665054EE2004	MOS/MSC	17-Jul-07	O/C	TAC 0				
SN:12-06	HRS	2709.8		TAC 0				
WC#: 28.535	AFL	1854		TAC 0				
PROC. REF: AMM 28-21-33-960-801	PROC. REF: AMM 28-21-33-960-801							
28-21-33-960-801-04	DISCARD OF THE FUEL SUPPLY HOSES - ENGINE 3 FUEL SUPPLY HOSE (R901QD)							Service ATA:28
PN:665106EE2001	MOS/MSC	17-Jul-07	O/C	TAC 0				
SN:01-07	HRS	2709.8		TAC 0				
WC#: 28.530	AFL	1854		TAC 0				
PROC. REF: AMM 28-21-33-960-801	PROC. REF: AMM 28-21-33-960-801							
28-21-41-900-801-01	REMOVAL / INSTALLATION OF THE LP INTERCONNECTION VALVE ACTUATOR - BP 1 MANIFOLD TRANSFER VALVE ACTUATOR (13Q1)							Component ATA:28
PN:D97C00-205	MOS/MSC	01-Nov-04	O/C	TSN 0				
SN:20151	HRS	2155.2		TSN 0				
WC#: 28.310	AFL	1499						
PROC. REF: AMM 28-21-41-900-801	PROC. REF: AMM 28-21-41-900-801							
28-21-41-900-801-02	REMOVAL / INSTALLATION OF THE LP INTERCONNECTION VALVE ACTUATOR - BP 3 MANIFOLD TRANSFER VALVE ACTUATOR (13Q2)							Component ATA:28
PN:D97C00-215	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.310	AFL	0						
PROC. REF: AMM 28-21-41-900-801	PROC. REF: AMM 28-21-41-900-801							
28-22-05-350-801-01	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) - LH TRANSFER PUMP (23Q1)							Service ATA:28
PN:206311-50	MOS/MSC		N/A					
SN:A32711	HRS							
WC#: 28.270	AFL							
PROC. REF: AMM 28-22-05-350-801	PROC. REF: AMM 28-22-05-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-22-05-350-801-02	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) - CENTER TRANSFER PUMP (23Q2)							Service ATA:28
PN:206311-50	MOS/MSC		N/A					
SN:A84549	HRS							
WC#: 28.280	AFL							
PROC. REF: AMM 28-22-05-350-801	PROC. REF: AMM 28-22-05-350-801							
28-22-05-350-801-03	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) - RH TRANSFER PUMP (23Q3)							Service ATA:28
PN:206311-50	MOS/MSC		N/A					
SN:A32710	HRS							
WC#: 28.290	AFL							
PROC. REF: AMM 28-22-05-350-801	PROC. REF: AMM 28-22-05-350-801							
28-22-05-350-802-01	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF BEARINGS) - LH TRANSFER PUMP (23Q1)							Service ATA:28
PN:206311-50	MOS/MSC		N/A					
SN:A32711	HRS							
WC#: 28.270	AFL							
PROC. REF: AMM 28-22-05-350-802	PROC. REF: AMM 28-22-05-350-802							
28-22-05-350-802-02	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF BEARINGS) - CENTER TRANSFER PUMP (23Q2)							Service ATA:28
PN:206311-50	MOS/MSC		N/A					
SN:A84549	HRS							
WC#: 28.280	AFL							
PROC. REF: AMM 28-22-05-350-802	PROC. REF: AMM 28-22-05-350-802							
28-22-05-350-802-03	RESTORATION OF THE TRANSFER PUMP (REPLACEMENT OF BEARINGS) - RH TRANSFER PUMP (23Q3)							Service ATA:28
PN:206311-50	MOS/MSC		N/A					
SN:A32710	HRS							
WC#: 28.290	AFL							
PROC. REF: AMM 28-22-05-350-802	PROC. REF: AMM 28-22-05-350-802							
28-22-05-900-801-01	REMOVAL / INSTALLATION OF THE TRANSFER PUMPS - LH TRANSFER PUMP (23Q1)							Component ATA:28
PN:206311-50	MOS/MSC	14-Jun-17	O/C	TSN 192, TSR 1				
SN:A32711	HRS	5158.2		TSN 2078, TSR 0				
WC#: 28.270	AFL	3250		TSR 0				
PROC. REF: AMM 28-22-05-900-801	PROC. REF: AMM 28-22-05-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-22-05-900-801-02	REMOVAL / INSTALLATION OF THE TRANSFER PUMPS - CENTER TRANSFER PUMP (23Q2)							Component ATA:28
PN:206311-50	MOS/MSC	14-Jun-17	O/C	TSN 177, TSR 1				
SN:A84549	HRS	5158.2		TSN 3847, TSR 0				
WC#: 28.280	AFL	3250		TSR 0				
PROC. REF: AMM 28-22-05-900-801	PROC. REF: AMM 28-22-05-900-801							
28-22-05-900-801-03	REMOVAL / INSTALLATION OF THE TRANSFER PUMPS - RH TRANSFER PUMP (23Q3)							Component ATA:28
PN:206311-50	MOS/MSC	14-Jun-17	O/C	TSN 192, TSR 1				
SN:A32710	HRS	5158.2		TSN 2078, TSR 0				
WC#: 28.290	AFL	3250		TSR 0				
PROC. REF: AMM 28-22-05-900-801	PROC. REF: AMM 28-22-05-900-801							
28-22-13-220-801-01 S	INSPECTION FOR CORROSION OF THE TRANSFER VALVE BASES AND LINES FITTED WITH DRAINAGE SLEEVES							Service ATA:28
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 28.330	AFL	3569						
								PKG:31
PROC. REF: AMM 28-22-13-220-801	PROC. REF: AMM 28-22-13-220-801							
28-22-15-350-801-01	RESTORATION OF THE TRANSFER VALVES (OVERHAUL) - LH TRANSFER VALVE (L615QS)							Service ATA:28
PN:2504-3	MOS	08-Sep-22	108 (+3%)		08-Sep-31	15-Dec-31	1795 d (+98)	OVERHAUL
SN:1878	HRS	6221.1	4800 (+3%)		11021.1	11165.1	4228.8 (+144)	
WC#: 28.240	AFL	3722						
PROC. REF: AMM 28-22-15-350-801	PROC. REF: AMM 28-22-15-350-801							
28-22-15-350-801-02	RESTORATION OF THE TRANSFER VALVES (OVERHAUL) - CENTER TRANSFER VALVE (M615QS)							Service ATA:28
PN:2504-3	MOS	08-Sep-22	108 (+3%)		08-Sep-31	15-Dec-31	1795 d (+98)	OVERHAUL
SN:1531	HRS	6221.1	4800 (+3%)		11021.1	11165.1	4228.8 (+144)	
WC#: 28.240	AFL	3722						
PROC. REF: AMM 28-22-15-350-801	PROC. REF: AMM 28-22-15-350-801							
28-22-15-350-801-03	RESTORATION OF THE TRANSFER VALVES (OVERHAUL) - RH TRANSFER VALVE (R615QS)							Service ATA:28
PN:2504-3	MOS	08-Sep-22	108 (+3%)		08-Sep-31	15-Dec-31	1795 d (+98)	OVERHAUL
SN:2309	HRS	6221.1	4800 (+3%)		11021.1	11165.1	4228.8 (+144)	
WC#: 28.240	AFL	3722						
PROC. REF: AMM 28-22-15-350-801	PROC. REF: AMM 28-22-15-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-22-15-900-801-01	REMOVAL / INSTALLATION OF THE TRANSFER VALVES - LH TRANSFER VALVE (L615QS)							Component ATA:28
PN:2504-3	MOS/MSC	08-Sep-22	H/T	TSO 4				
SN:1878	HRS	6221.1		TSO 0				
WC#: 28.240	AFL	3722		TSO 0				
PROC. REF: AMM 28-22-15-900-801	PROC. REF: AMM 28-22-15-900-801							
28-22-15-900-801-02	REMOVAL / INSTALLATION OF THE TRANSFER VALVES - CENTER TRANSFER VALVE (M615QS)							Component ATA:28
PN:2504-3	MOS/MSC	08-Sep-22	H/T	TSO 7				
SN:1531	HRS	6221.1		TSO 0				
WC#: 28.240	AFL	3722		TSO 0				
PROC. REF: AMM 28-22-15-900-801	PROC. REF: AMM 28-22-15-900-801							
28-22-15-900-801-03	REMOVAL / INSTALLATION OF THE TRANSFER VALVES - RH TRANSFER VALVE (R615QS)							Component ATA:28
PN:2504-3	MOS/MSC	08-Sep-22	H/T	TSO 14				
SN:2309	HRS	6221.1		TSO 0				
WC#: 28.240	AFL	3722		TSO 0				
PROC. REF: AMM 28-22-15-900-801	PROC. REF: AMM 28-22-15-900-801							
28-22-17-900-801-01	REMOVAL / INSTALLATION OF THE CENTER FEEDER TANK LOW LEVEL FLOAT VALVE							Component ATA:28
PN:C21KL0014	MOS/MSC	11-Jul-95	O/C					
SN:2007	HRS	0		TSN 0				
WC#: 28.355	AFL	0						
PROC. REF: AMM 28-22-17-900-801	PROC. REF: AMM 28-22-17-900-801							
28-22-21-900-801-01	REMOVAL / INSTALLATION OF THE ISOLATION VALVES - LH ISOLATION VALVE (L17QD)							Component ATA:28
PN:B97M31-201	MOS/MSC	11-Jul-95	O/C					
SN:20396	HRS	0		TSN 0				
WC#: 28.160	AFL	0						
PROC. REF: AMM 28-22-21-900-801	PROC. REF: AMM 28-22-21-900-801							
28-22-21-900-801-02	REMOVAL / INSTALLATION OF THE ISOLATION VALVES - CENTER ISOLATION VALVE (M17QD)							Component ATA:28
PN:B97M31-201	MOS/MSC	11-Jul-95	O/C					
SN:20404	HRS	0		TSN 0				
WC#: 28.160	AFL	0						
PROC. REF: AMM 28-22-21-900-801	PROC. REF: AMM 28-22-21-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-22-21-900-801-03	REMOVAL / INSTALLATION OF THE ISOLATION VALVES - RH ISOLATION VALVE (R17QD)							Component ATA:28
PN:B97M31-201	MOS/MSC	11-Jul-95	O/C					
SN:20406	HRS	0		TSN 0				
WC#: 28.160	AFL	0						
PROC. REF: AMM 28-22-21-900-801	PROC. REF: AMM 28-22-21-900-801							
28-22-29-900-801-01	REMOVAL / INSTALLATION OF THE TRANSFER INTERCONNECTION VALVE ACTUATOR							Component ATA:28
PN:D97C00-215	MOS/MSC	11-Aug-20	O/C					
SN:20327	HRS	5942.6						
WC#: 28.320	AFL	3569						
PROC. REF: AMM 28-22-29-900-801	PROC. REF: AMM 28-22-29-900-801							
28-22-29-900-801-02	RIGHT TRANSFER INTERCONNECTION VALVE ACTUATOR							Component ATA:28
PN:D97C00-202	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.320	AFL	0						
PROC. REF: AMM 28-22-29-900-801	PROC. REF: AMM 28-22-29-900-801							
28-30-00-680-802-01	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE LH TANK GROUP							Service ATA:28
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-30-00-680-802	PROC. REF: AMM 28-30-00-680-802							
28-30-00-680-802-02	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE CENTER TANK GROUP							Service ATA:28
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-30-00-680-802	PROC. REF: AMM 28-30-00-680-802							
28-30-00-680-802-03	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE RH TANK GROUP							Service ATA:28
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-30-00-680-802	PROC. REF: AMM 28-30-00-680-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-30-00-680-802-05	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY							Service ATA:28
	MOS	13-Aug-26	2 (+5d)		13-Oct-26	18-Oct-26	4 d (+5)	
	HRS	6770						
	AFL	4000						
PROC. REF: AMM 28-30-00-680-802	PROC. REF: AMM 28-30-00-680-802							
28-30-00-680-802-06	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - FUEL SAMPLING							Service ATA:28
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-30-00-680-802	PROC. REF: AMM 28-30-00-680-802							
28-30-00-680-804-01	DRAINING WATER FROM THE FUEL TANKS							Service ATA:28
	MOS	13-Aug-26	2 (+5d)		13-Oct-26	18-Oct-26	4 d (+5)	
	HRS	6770						
	AFL	4000						
PROC. REF: AMM 28-30-00-680-804	PROC. REF: AMM 28-30-00-680-804							
28-30-11-960-802-01	DISCARD OF THE FUEL DRAIN CAPS							Service ATA:28
	MOS/MSC	11-Jul-95	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-30-11-960-802	PROC. REF: AMM 28-30-11-960-802							
28-41-00-720-802-01 S	FUNCTIONAL TEST OF THE FEEDER TANK LOW LEVEL INDICATING SYSTEM							Service ATA:28
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 28.810	AFL	3940						
								PKG:207
PROC. REF: AMM 28-41-00-720-802	PROC. REF: AMM 28-41-00-720-802							
28-41-09-900-801-01	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING INBOARD TANK GAUGE (44E1)							Component ATA:28
PN:792-366-1	MOS/MSC	11-Jul-95	O/C					
SN:948	HRS	0		TSN 0				
WC#: 28.710	AFL	0						
PROC. REF: AMM 28-41-09-900-801	PROC. REF: AMM 28-41-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-09-900-801-02	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING INBOARD TANK GAUGE (44E2)							Component ATA:28
PN:792-366-1	MOS/MSC	11-Jul-95	O/C					
SN:869	HRS	0		TSN 0				
WC#: 28.720	AFL	0						
PROC. REF: AMM 28-41-09-900-801	PROC. REF: AMM 28-41-09-900-801							
28-41-09-900-801-03	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING CENTER TANK GAUGE (45E1)							Component ATA:28
PN:792-367-2	MOS/MSC	11-Jul-95	O/C					
SN:1014	HRS	0		TSN 0				
WC#: 28.710	AFL	0						
PROC. REF: AMM 28-41-09-900-801	PROC. REF: AMM 28-41-09-900-801							
28-41-09-900-801-04	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING CENTER TANK GAUGE (45E2)							Component ATA:28
PN:792-367-2	MOS/MSC	11-Jul-95	O/C					
SN:1017	HRS	0		TSN 0				
WC#: 28.720	AFL	0						
PROC. REF: AMM 28-41-09-900-801	PROC. REF: AMM 28-41-09-900-801							
28-41-09-900-801-05	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING OUTBOARD TANK GAUGE (46E1)							Component ATA:28
PN:792-368-2	MOS/MSC	11-Jul-95	O/C					
SN:1023	HRS	0		TSN 0				
WC#: 28.710	AFL	0						
PROC. REF: AMM 28-41-09-900-801	PROC. REF: AMM 28-41-09-900-801							
28-41-09-900-801-06	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING OUTBOARD TANK GAUGE (46E2)							Component ATA:28
PN:792-368-2	MOS/MSC	11-Jul-95	O/C					
SN:1024	HRS	0		TSN 0				
WC#: 28.720	AFL	0						
PROC. REF: AMM 28-41-09-900-801	PROC. REF: AMM 28-41-09-900-801							
28-41-13-900-801-01	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - LH TANK GROUP FUEL QUANTITY INDICATOR (43E1)							Component ATA:28
PN:716686	MOS/MSC	11-Jul-95	O/C					
SN:731	HRS	0		TSN 0				
WC#: 28.750	AFL	0						
PROC. REF: AMM 28-41-13-900-801	PROC. REF: AMM 28-41-13-900-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-13-900-801-02	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - CENTER TANK GROUP FUEL QUANTITY INDICATOR (63E)							Component ATA:28
PN:716687	MOS/MSC	11-Jul-95	O/C					
SN:732	HRS	0		TSN 0				
WC#: 28.750	AFL	0						
PROC. REF: AMM 28-41-13-900-801	PROC. REF: AMM 28-41-13-900-801							
28-41-13-900-801-03	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - RH TANK GROUP FUEL QUANTITY INDICATOR (43E2)							Component ATA:28
PN:716686	MOS/MSC	11-Jul-95	O/C					
SN:483	HRS	0		TSN 0				
WC#: 28.750	AFL	0						
PROC. REF: AMM 28-41-13-900-801	PROC. REF: AMM 28-41-13-900-801							
28-43-01-720-801-01	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR - FUEL TEMPERATURE PROBE (51E)							Service ATA:28
	MOS/MSC	08-May-14	N/A					
	HRS	4694.5						
WC#: 28.840	AFL	2957						
PROC. REF: AMM 28-43-01-720-801	PROC. REF: AMM 28-43-01-720-801							
28-43-05-900-801-01	REMOVAL/INSTALLATION OF FUEL TEMPERATURE INDICATOR - FUEL TEMPERATURE INDICATOR (52E)							Component ATA:28
PN:162LC617	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 28.800	AFL	0						
PROC. REF: AMM 28-43-05-900-801	PROC. REF: AMM 28-43-05-900-801							
28-50-00-700-801-02 S	INTEGRITY AND LEAK CHECK OF REFUELING CONNECTOR SEALING VALVE AND LEAK CHECK OF ISOLATION CHECK VALVES - TIGHTNESS CHECK OF REFUELING SYSTEM/TRANSFER SYSTEM ISOLATION CHECK VALVES							Service ATA:28
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 28.465	AFL	3569						
								PKG:32
PROC. REF: AMM 28-50-00-700-801	PROC. REF: AMM 28-50-00-700-801							
28-50-27-900-801-01	REMOVAL / INSTALLATION OF THE FUEL TEST VALVE PROXIMITY SENSOR - TEST VALVE PROXIMITY SWITCH (67Q)							Component ATA:28
PN:8-240-02	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.790	AFL	0						
PROC. REF: AMM 28-50-27-900-801	PROC. REF: AMM 28-50-27-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-70-00-720-801-01 S	FUNCTIONAL TEST OF THE PRESSURIZATION SYSTEM							Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	6000 (+30)					
WC#: 28.450	AFL	3569						
								PKG:24
PROC. REF: AMM 28-70-00-720-801 PROC. REF: AMM 28-70-00-720-801								
28-70-09-350-801-01	RESTORATION OF THE VALVE BOXES (OVERHAUL) - LH VALVE BOX (L200QP)							Service ATA:28
PN:2415-1010	MOS	08-Sep-22	72 (+3%)		08-Sep-28	12-Nov-28	700 d (+65)	OVERHAUL
SN:1446	HRS	6221.1	1600 (+3%)		7821.1	7869.1	1028.8 (+48)	
WC#: 28.440	AFL	3722						
PROC. REF: AMM 28-70-09-350-801 PROC. REF: AMM 28-70-09-350-801								
28-70-09-350-801-02	RESTORATION OF THE VALVE BOXES (OVERHAUL) - RH VALVE BOX (R200QP)							Service ATA:28
PN:2415-1010	MOS	08-Sep-22	72 (+3%)		08-Sep-28	12-Nov-28	700 d (+65)	OVERHAUL
SN:1450	HRS	6221.1	1600 (+3%)		7821.1	7869.1	1028.8 (+48)	
WC#: 28.440	AFL	3722						
PROC. REF: AMM 28-70-09-350-801 PROC. REF: AMM 28-70-09-350-801								
28-70-13-350-801-01	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L100QP)							Service ATA:28
PN:B06GA1052-1	MOS/MSC	08-Jun-16	O/C					
SN:6092	HRS	5064.3						
	AFL	3203						
PROC. REF: AMM 28-70-13-350-801 PROC. REF: AMM 28-70-13-350-801								
28-70-13-350-801-02	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R100QP)							Service ATA:28
PN:B06GA1052-1	MOS/MSC	25-May-17	O/C					
SN:6279	HRS	5157.3						
	AFL	3249						
PROC. REF: AMM 28-70-13-350-801 PROC. REF: AMM 28-70-13-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-70-13-720-802-01		FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L100QP)						Service ATA:28
PN:B06GA1052-1	MOS	08-Jun-16						
SN:6092	HRS	5064.3	5000 (+3%)		10064.3	10214.3	3272 (+150)	
	AFL	3203						
PROC. REF: AMM 28-70-13-720-802	PROC. REF: AMM 28-70-13-720-802							
28-70-13-720-802-02		FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R100QP)						Service ATA:28
PN:B06GA1052-1	MOS	25-May-17						
SN:6279	HRS	5157.3	5000 (+3%)		10157.3	10307.3	3365 (+150)	
	AFL	3249						
PROC. REF: AMM 28-70-13-720-802	PROC. REF: AMM 28-70-13-720-802							
28-70-13-900-801-01		REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L100QP)						Component ATA:28
PN:B06GA1052-1	MOS/MSC	08-Jun-16	O/C	TSO 0				
SN:6092	HRS	5064.3		TSO 0				
WC#: 28.420	AFL	3203		TSO 0				
PROC. REF: AMM 28-70-13-900-801	PROC. REF: AMM 28-70-13-900-801							
28-70-13-900-801-02		REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R100QP)						Component ATA:28
PN:B06GA1052-1	MOS/MSC	25-May-17	O/C	TSN 0				
SN:6279	HRS	5157.3		TSN 0				
WC#: 28.420	AFL	3249		TSN 0				
PROC. REF: AMM 28-70-13-900-801	PROC. REF: AMM 28-70-13-900-801							
28-70-17-130-801-01 S		CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 1 PRESSURIZATION AIR FILTER (L206QP)						Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 28.680	AFL	3569						PKG:21
PROC. REF: AMM 28-70-17-130-801	PROC. REF: AMM 28-70-17-130-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-70-17-130-801-02 S	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 2 PRESSURIZATION AIR FILTER (R206QP)							Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 28.680	AFL	3569						
								PKG:21
PROC. REF: AMM 28-70-17-130-801	PROC. REF: AMM 28-70-17-130-801							
28-70-41-710-801-01 S	OPERATIONAL TEST OF THE FEEDER TANK PRESSURE RELIEF VALVES - LH FEEDER TANK PRESSURE RELIEF VALVE (L300QP)							Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 28.410	AFL	3569						
								PKG:21
PROC. REF: AMM 28-70-41-710-801	PROC. REF: AMM 28-70-41-710-801							
28-70-41-710-801-02 S	OPERATIONAL TEST OF THE FEEDER TANK PRESSURE RELIEF VALVES - RH FEEDER TANK PRESSURE RELIEF VALVE (R300QP)							Service ATA:28
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 28.410	AFL	3569						
								PKG:21
PROC. REF: AMM 28-70-41-710-801	PROC. REF: AMM 28-70-41-710-801							
28-70-41-900-801-01	REMOVAL / INSTALLATION OF THE FEEDER TANK PRESSURE-RELIEF VALVES - LH FEEDER TANK PRESSURE RELIEF VALVE (L300QP)							Component ATA:28
PN:1551-1000	MOS/MSC	11-Jul-95	O/C					
SN:2180	HRS	0		TSN 0				
WC#: 28.410	AFL	0						
PROC. REF: AMM 28-70-41-900-801	PROC. REF: AMM 28-70-41-900-801							
28-70-41-900-801-02	REMOVAL / INSTALLATION OF THE FEEDER TANK PRESSURE-RELIEF VALVES - RH FEEDER TANK PRESSURE RELIEF VALVE (R300QP)							Component ATA:28
PN:1551-1000	MOS/MSC	11-Jul-95	O/C					
SN:2181	HRS	0		TSN 0				
WC#: 28.410	AFL	0						
PROC. REF: AMM 28-70-41-900-801	PROC. REF: AMM 28-70-41-900-801							
280111	LH WING DRAIN VALVE							Component ATA:28
PN:142D12-11	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:D20783	HRS	3036.1		TSN 0				
WC#: 28.020	AFL	2036		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280116	RH WING DRAIN VALVE							Component ATA:28
PN:142D12-1	MOS/MSC	13-Dec-19	O/C					
SN:M16474	HRS	5862.3						
WC#: 28.020	AFL	3541						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280121	FORWARD CENTER WING DRAIN VALVE							Component ATA:28
PN:142G12-42	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:D08503	HRS	3036.1		TSN 0				
WC#: 28.030	AFL	2036		TSN 0				
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280126	MIDDLE CENTER WING DRAIN VALVE							Component ATA:28
PN:142G12-42	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:D08504	HRS	3036.1		TSN 0				
WC#: 28.030	AFL	2036		TSN 0				
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280131	REAR CENTER WING DRAIN VALVE							Component ATA:28
PN:142G12-42	MOS/MSC	24-Jul-08	O/C					
SN:1725	HRS	3036.1						
WC#: 28.030	AFL	2036						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280136	LH FEEDER TANK DRAIN VALVE							Component ATA:28
PN:142G12-43	MOS/MSC	11-Jul-95	O/C					
SN:1736	HRS	0		TSN 0				
WC#: 28.040	AFL	0						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280141	CENTER FEEDER TANK DRAIN VALVE							Component ATA:28
PN:142G12-43	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:D08505	HRS	3036.1		TSN 0				
WC#: 28.040	AFL	2036		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280146	RH FEEDER TANK DRAIN VALVE							Component ATA:28
PN:142G12-42	MOS/MSC	24-Jul-08	O/C					
SN:1733	HRS	3036.1						
WC#: 28.040	AFL	2036						
PROC. REF: AMM 28-30-11-900-801PROC. REF: AMM 28-30-11-900-801								
280156	LH DOOR FEEDER TANK DRAIN VALVE							Component ATA:28
PN:142G12-43	MOS/MSC	24-Jul-08	O/C					
SN:1730	HRS	3036.1						
WC#: 28.045	AFL	2036						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
280161	RH DOOR FEEDER TANK DRAIN VALVE							Component ATA:28
PN:142G12-43	MOS/MSC	24-Jul-08	O/C					
SN:1736	HRS	3036.1						
WC#: 28.045	AFL	2036						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281101	LH FILLER PLUG							Component ATA:28
PN:431-1251	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281103	CENTER TRANSFER PUMP PRIMING CHECK VALVE							Component ATA:28
PN:L85Z13-201	MOS/MSC	11-Jul-95	O/C					
SN:20997	HRS	0		TSN 0				
WC#: 28.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281106	RH FILLER PLUG							Component ATA:28
PN:431-1251	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.060	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281108	RH TEST SYSTEM CHECK VALVE							Component ATA:28
PN:L85Z13-201	MOS/MSC	11-Jul-95	O/C					
SN:21017	HRS	0		TSN 0				
WC#: 28.120	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281111	LH STRAINER							Component ATA:28
PN:431-51-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281113	NO. 1 SYSTEM CENTER FEEDER TANK TEST CHECK VALVE							Component ATA:28
PN:L85Z13-201	MOS/MSC	11-Jul-95	O/C					
SN:21045	HRS	0		TSN 0				
WC#: 28.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281116	RIGHT STRAINER							Component ATA:28
PN:431-51-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281118	NO. 2 SYSTEM CENTER FEEDER TANK TEST CHECK VALVE							Component ATA:28
PN:L85Z13-201	MOS/MSC	11-Jul-95	O/C					
SN:21054	HRS	0		TSN 0				
WC#: 28.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281121	LH JET PUMP BOOSTER SYSTEM CHECK VALVE							Component ATA:28
PN:L96Z19-203	MOS/MSC	11-Jul-95	O/C					
SN:20535	HRS	0		TSN 0				
WC#: 28.140	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281126	RH JET PUMP BOOSTER SYSTEM CHECK VALVE							Component ATA:28
PN:L96Z19-203	MOS/MSC	11-Jul-95	O/C					
SN:20538	HRS	0		TSN 0				
WC#: 28.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281131	LH TRANSFER JET PUMP FILTER							Component ATA:28
PN:CH8066093732N00	MOS/MSC	20-Feb-15	O/C	TSN 0				
SN:M762350-022	HRS	4843.4		TSN 0				
WC#: 28.150	AFL	3022		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281141	RH TRANSFER JET PUMP FILTER							Component ATA:28
PN:CH8066093732N00	MOS/MSC	20-Feb-15	O/C	TSN 0				
SN:M811780-015	HRS	4843.4		TSN 0				
WC#: 28.150	AFL	3022		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281166	PRESSURE REFUELING UNIT							Component ATA:28
PN:K97-63-206	MOS/MSC	11-Jul-95	O/C					
SN:20425	HRS	0		TSN 0				
WC#: 28.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281176	NO. 1 FILLER VALVE							Component ATA:28
PN:L94Z31-201	MOS/MSC	08-May-14	O/C	TSN 8				
SN:H13765	HRS	4694.25		TSN 0				
WC#: 28.070	AFL	2957		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281181	NO. 2 FILLER VALVE							Component ATA:28
PN:L94Z31-201	MOS/MSC	08-May-14	O/C	TSN 8				
SN:H13766	HRS	4694.25						
WC#: 28.070	AFL	2957		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281186	NO. 3 FILLER VALVE							Component ATA:28
PN:L94Z31-201	MOS/MSC	08-May-14	O/C	TSN 7				
SN:H13767	HRS	4694.25		TSN 0				
WC#: 28.070	AFL	2957		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281191	LH TRANSFER PUMP CHECK VALVE							Component ATA:28
PN:L96Z31-201	MOS/MSC	11-Jul-95	O/C					
SN:21546	HRS	0		TSN 0				
WC#: 28.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281196	MIDDLE TRANSFER PUMP CHECK VALVE							Component ATA:28
PN:L96Z31-201	MOS/MSC	11-Jul-95	O/C					
SN:21572	HRS	0		TSN 0				
WC#: 28.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281201	RH TRANSFER PUMP CHECK VALVE							Component ATA:28
PN:L96Z31-201	MOS/MSC	11-Jul-95	O/C					
SN:21573	HRS	0		TSN 0				
WC#: 28.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281206	FILLING CIRCUIT TRANSFER CHECK VALVE							Component ATA:28
PN:L96Z31-201	MOS/MSC	11-Jul-95	O/C					
SN:21583	HRS	0		TSN 0				
WC#: 28.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281211	FILLER BLOCK							Component ATA:28
PN:K99Z31-001	MOS/MSC	11-Jul-95	O/C					
SN:20264	HRS	0		TSN 0				
WC#: 28.090	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281216	FEEDER TANK AIR VENT VALVE							Component ATA:28
PN:B97J38-251	MOS/MSC	09-Mar-05	O/C	TSR 13				
SN:20203	HRS	2259.5		TSR 0				
WC#: 28.190	AFL	1579		TSR 0				
PROC. REF: AMM 28-70-21-900-801PROC. REF: AMM 28-70-21-900-801								
281221	LH CENTER SECTION AIR VENT DRAINING BALL VALVE							Component ATA:28
PN:L87D06-001	MOS/MSC	11-Jul-95	O/C					
SN:20548	HRS	0		TSN 0				
WC#: 28.200	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281226	RH CENTER SECTION AIR VENT DRAINING BALL VALVE							Component ATA:28
PN:L87D06-001	MOS/MSC	11-Jul-95	O/C					
SN:20551	HRS	0		TSN 0				
WC#: 28.200	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281231	LH WING AIR VENT VALVE							Component ATA:28
PN:B97L38-251	MOS/MSC	26-Oct-05	O/C	TSN 1				
SN:20143	HRS	2405.2		TSN 0				
WC#: 28.190	AFL	1669		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281236	RH WING AIR VENT VALVE							Component ATA:28
PN:B97L38-252	MOS/MSC	11-Jul-95	O/C					
SN:20143	HRS	0		TSN 0				
WC#: 28.190	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281241	LH WING FUELLING FLOAT SWITCH							Component ATA:28
PN:005-906-001	MOS/MSC	11-Jul-95	O/C					
SN:1530	HRS	0		TSN 0				
WC#: 28.210	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281246	RH WING FUELLING FLOAT SWITCH							Component ATA:28
PN:005-906-001	MOS/MSC	11-Jul-95	O/C					
SN:1529	HRS	0		TSN 0				
WC#: 28.220	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281251	LH CENTER SECTION OVERFULL FLOAT SWITCH							Component ATA:28
PN:005-906-001	MOS/MSC	11-Jul-95	O/C					
SN:1486	HRS	0		TSN 0				
WC#: 28.210	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281256	RH CENTER SECTION OVERFULL FLOAT SWITCH							Component ATA:28
PN:005-906-001	MOS/MSC	11-Jul-95	O/C					
SN:1528	HRS	0		TSN 0				
WC#: 28.220	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281261	FEEDER TANK OVERFULL FLOAT SWITCH							Component ATA:28
PN:005-906-001	MOS/MSC	11-Jul-95	O/C					
SN:1525	HRS	0		TSN 0				
WC#: 28.230	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281266	LH CENTER SECTION FUELLING FLOAT SWITCH							Component ATA:28
PN:005-909-001	MOS/MSC	11-Jul-95	O/C					
SN:1314	HRS	0		TSN 0				
WC#: 28.210	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281271	RH CENTER SECTION FUELLING FLOAT SWITCH							Component ATA:28
PN:005-909-001	MOS/MSC	11-Jul-95	O/C					
SN:1316	HRS	0		TSN 0				
WC#: 28.220	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281273	LATERAL TANK LOADING PRINTED CARD							Component ATA:28
PN:CI822A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.250	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281275	CENTER TANK LOADING PRINTED CARD							Component ATA:28
PN:CI845A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.250	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281276	TRANSFER UNIT							Component ATA:28
PN:L88A31-207	MOS/MSC	11-Jul-95	O/C					
SN:20279	HRS	0		TSN 0				
WC#: 28.260	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281353	TRANSFER MANIFOLD REFUELING VALVE							Component ATA:28
PN:3073591-2	MOS/MSC	22-Oct-12	O/C	TSO 0				
SN:9-235C	HRS	4172.6		TSO 0				
WC#: 28.300	AFL	2685		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281391	LH TANK LEVEL SOLENOID VALVE							Component ATA:28
PN:C41BP0043	MOS/MSC	11-Jul-95	O/C					
SN:1049	HRS	0		TSN 0				
WC#: 28.340	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281396	MIDDLE TANK LEVEL SOLENOID VALVE							Component ATA:28
PN:C41BP0042	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.340	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281401	RH TANK LEVEL SOLENOID VALVE							Component ATA:28
PN:C41BP0042	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.340	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281406	LH TANK HIGH LEVEL FLOAT VALVE							Component ATA:28
PN:C21KL0014	MOS/MSC	11-Jul-95	O/C					
SN:1992	HRS	0		TSN 0				
WC#: 28.350	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281411	LH TANK LOW LEVEL FLOAT VALVE							Component ATA:28
PN:C21KL0014	MOS/MSC	11-Jul-95	O/C					
SN:2004	HRS	0		TSN 0				
WC#: 28.360	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281416	MIDDLE TANK HIGH LEVEL FLOAT VALVE							Component ATA:28
PN:C21KL0014	MOS/MSC	11-Jul-95	O/C					
SN:2006	HRS	0		TSN 0				
WC#: 28.350	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281426	RH TANK HIGH LEVEL FLOAT VALVE							Component ATA:28
PN:C21KL0014	MOS/MSC	11-Jul-95	O/C					
SN:2049	HRS	0		TSN 0				
WC#: 28.350	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281431	RH TANK LOW LEVEL FLOAT VALVE							Component ATA:28
PN:C21KL0014	MOS/MSC	11-Jul-95	O/C					
SN:2051	HRS	0		TSN 0				
WC#: 28.360	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281436	LH FEEDER TANK TRANSFER JET-PUMP							Component ATA:28
PN:C17AS0051	MOS/MSC	11-Jul-95	O/C					
SN:115	HRS	0		TSN 0				
WC#: 28.370	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281441	RH FEEDER TANK TRANSFER JET-PUMP							Component ATA:28
PN:C17AS0061	MOS/MSC	11-Jul-95	O/C					
SN:263	HRS	0		TSN 0				
WC#: 28.370	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281466	WING TANK PRESSURIZATION REAR NON RETURN VALVE							Component ATA:28
PN:L96Z19-003	MOS/MSC	11-Jul-95	O/C					
SN:21858	HRS	0		TSN 0				
WC#: 28.380	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281471	FEEDER TANK PRESSURIZATION FORWARD NON RETURN VALVE							Component ATA:28
PN:L96Z19-003	MOS/MSC	11-Jul-95	O/C					
SN:21859	HRS	0		TSN 0				
WC#: 28.380	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281476	WING TANK REAR PRESSURE REDUCER VALVE							Component ATA:28
PN:B14DE2041	MOS/MSC	11-Jul-95	O/C					
SN:463	HRS	0		TSN 0				
WC#: 28.390	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281481	FEEDER TANK FORWARD PRESSURE REDUCER VALVE							Component ATA:28
PN:B14DE2031	MOS/MSC	11-Jul-95	O/C					
SN:470	HRS	0		TSN 0				
WC#: 28.390	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281486	TANK PRESSURIZATION AUTOMATIC DRAIN							Component ATA:28
PN:P177-526	MOS/MSC	18-Oct-04	O/C	TSN 0				
SN:N/A	HRS	2150.2		TSN 0				
WC#: 28.400	AFL	1495						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281491	WING TANK PRESSURIZATION AUTOMATIC DRAIN							Component ATA:28
PN:P177-526	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.400	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281526	LH FEEDER TANK VACUUM PRESSURE RELIEF VALVE							Component ATA:28
PN:B42LA1040	MOS/MSC	11-Jul-95	O/C					
SN:627	HRS	0		TSN 0				
WC#: 28.430	AFL	0						
PROC. REF: AMM 28-70-41-900-801PROC. REF: AMM 28-70-41-900-801								
281531	RH FEEDER TANK VACUUM PRESSURE RELIEF VALVE							Component ATA:28
PN:B42LA1040	MOS/MSC	11-Jul-95	O/C					
SN:628	HRS	0		TSN 0				
WC#: 28.430	AFL	0						
PROC. REF: AMM 28-70-41-900-801PROC. REF: AMM 28-70-41-900-801								
281536	LH VALVE BOX							Component ATA:28
PN:2415-1010	MOS/MSC	08-Sep-22	H/T	TSO 4				
SN:1446	HRS	6221.1		TSO 0				
WC#: 28.440	AFL	3722		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281541	RH VALVE BOX							Component ATA:28
PN:2415-1010	MOS/MSC	08-Sep-22	H/T	TSO 6				
SN:1450	HRS	6221.1		TSO 0				
WC#: 28.440	AFL	3722		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282011	LH FUEL FIRE SHUT-OFF VALVE							Component ATA:28
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.570	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282031	MIDDLE FUEL FIRE SHUT-OFF VALVE							Component ATA:28
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.580	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282051	RH FUEL FIRE SHUT-OFF VALVE							Component ATA:28
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.590	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282191	LH LOW PRESSURE PUMP BELL HOUSING							Component ATA:28
PN:2061J	MOS/MSC	11-Jul-95	O/C					
SN:890	HRS	0		TSN 0				
WC#: 28.630	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282201	CENTRAL LOW PRESSURE PUMP BELL HOUSING							Component ATA:28
PN:2061J	MOS/MSC	11-Jul-95	O/C					
SN:891	HRS	0		TSN 0				
WC#: 28.630	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282211	RH LOW PRESSURE PUMP BELL HOUSING							Component ATA:28
PN:2061J	MOS/MSC	11-Jul-95	O/C					
SN:831	HRS	0		TSN 0				
WC#: 28.630	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282221	NO. 1 FIRE SHUT-OFF HANDLE							Component ATA:28
PN:4161174	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.640	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282226	NO. 2 FIRE SHUT-OFF HANDLE							Component ATA:28
PN:4161181	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.640	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282231	NO. 3 FIRE SHUT-OFF HANDLE							Component ATA:28
PN:4161197	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.640	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282311	NO. 1 ENGINE PRESSURIZATION AIR FILTER							Component ATA:28
PN:018500AA000NF0A	MOS/MSC	11-Jul-95	O/C					
SN:941070006	HRS	0		TSN 0				
WC#: 28.680	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282321	NO. 2 ENGINE PRESSURIZATION AIR FILTER							Component ATA:28
PN:018500AA000NF0A	MOS/MSC	11-Jul-95	O/C					
SN:941070009	HRS	0		TSN 0				
WC#: 28.680	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284101	LH LOW TRANSFER PRESSURE SWITCH							Component ATA:28
PN:1G344-1	MOS/MSC	28-Oct-05	O/C	TSN 6, TSO 0				
SN:25Q2.888/25Q3	HRS	2405.2		TSO 0				
WC#: 28.690	AFL	1669		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284106	CENTER LOW TRANSFER PRESSURE SWITCH							Component ATA:28
PN:1G344-1	MOS/MSC	16-Mar-22	O/C	TSN 106				
SN:1730	HRS	6124.5		TSN 0				
WC#: 28.690	AFL	3681		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284111	RH LOW TRANSFER PRESSURE SWITCH							Component ATA:28
PN:1G344-1	MOS/MSC	11-Jul-95	O/C					
SN:483	HRS	0		TSN 0				
WC#: 28.690	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284116	LH LOW PRESSURE SWITCH							Component ATA:28
PN:8G1256-1	MOS/MSC	11-Jul-95	O/C					
SN:1515	HRS	0		TSN 0				
WC#: 28.700	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284121	CENTER LOW PRESSURE SWITCH							Component ATA:28
PN:8G1256-1	MOS/MSC	11-Jul-95	O/C					
SN:1477	HRS	0		TSN 0				
WC#: 28.700	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284126	RH LOW PRESSURE SWITCH							Component ATA:28
PN:8G1256-1	MOS/MSC	11-Jul-95	O/C					
SN:1476	HRS	0		TSN 0				
WC#: 28.700	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284161	CENTER WING FORWARD QUANTITY GAUGE							Component ATA:28
PN:792-370-1	MOS/MSC	11-Jul-95	O/C					
SN:396	HRS	0		TSN 0				
WC#: 28.730	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284166	CENTER WING REAR QUANTITY GAUGE							Component ATA:28
PN:792-371-1	MOS/MSC	11-Jul-95	O/C					
SN:220	HRS	0		TSN 0				
WC#: 28.730	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284171	CENTER FEEDER TANK QUANTITY GAUGE							Component ATA:28
PN:792-795-2	MOS/MSC	02-Oct-96	O/C	TSO 0				
SN:446	HRS	294		TSO 0				
WC#: 28.740	AFL	158		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284176	LH FEEDER TANK QUANTITY GAUGE							Component ATA:28
PN:792-794-2	MOS/MSC	11-Jul-95	O/C					
SN:707	HRS	0		TSN 0				
WC#: 28.740	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284178	RH FEEDER TANK QUANTITY GAUGE							Component ATA:28
PN:792794-3	MOS/MSC	18-Jun-19	O/C					
SN:921	HRS	5790.5						
WC#: 28.740	AFL	3507						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284196	LH QUANTITY INDICATOR SYSTEM AMPLIFIER							Component ATA:28
PN:706-719-1	MOS/MSC	11-Jul-95	O/C					
SN:737	HRS	0		TSN 0				
WC#: 28.760	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284201	CENTER QUANTITY INDICATOR SYSTEM AMPLIFIER							Component ATA:28
PN:706-720-1	MOS/MSC	17-Jul-96	O/C					
SN:397	HRS	150		TSO 0				
WC#: 28.760	AFL	62						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284206	RH QUANTITY INDICATOR SYSTEM AMPLIFIER							Component ATA:28
PN:706-719-1	MOS/MSC	17-Jul-96	O/C					
SN:543	HRS	150						
WC#: 28.760	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284211	FUEL TANK LOW LEVEL PRINTED CIRCUIT CARD							Component ATA:28
PN:CI815A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.770	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284221	FUEL TEST VALVE							Component ATA:28
PN:B97M13-201	MOS/MSC	11-Jul-95	O/C					
SN:20003	HRS	0		TSN 0				
WC#: 28.780	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284231	FUEL TEMPERATURE PROBE							Component ATA:28
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 28.850	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 29 - HYDRAULIC POWER								
29-00-00-610-802-01	REPLACEMENT OF THE HYDRAULIC FLUID AFTER FAILURE OF A HYDRAULIC POWER SYSTEM COMPONENT							Service ATA:29
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
WC#: 29.380	AFL	0						
PROC. REF: AMM 29-00-00-610-802PROC. REF: AMM 29-00-00-610-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-10-00-720-801-01 S	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 1							Service ATA:29
	MOS	11-Aug-20						
	HRS	5942.6	6000 (+30)					
	AFL	3569						
								PKG:24
PROC. REF: AMM 29-10-00-720-801	PROC. REF: AMM 29-10-00-720-801							
29-10-00-720-801-02 S	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 2							Service ATA:29
	MOS	11-Aug-20						
	HRS	5942.6	6000 (+30)					
	AFL	3569						
								PKG:24
PROC. REF: AMM 29-10-00-720-801	PROC. REF: AMM 29-10-00-720-801							
29-11-01-350-801-01	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 1 (L500ML)							Service ATA:29
PN:PVB-022-2	MOS	23-Oct-12						OVERHAUL
SN:MX-538566H	HRS	4193.5	4000 (+3%)		8193.5	8313.5	1401.2 (+120)	
WC#: 29.030	AFL	2686						
PROC. REF: AMM 29-11-01-350-801	PROC. REF: AMM 29-11-01-350-801							
29-11-01-350-801-02	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 2 (M500ML)							Service ATA:29
PN:PVB-022-2	MOS	23-Oct-12						OVERHAUL
SN:MX-540547G	HRS	4193.5	4000 (+3%)		8193.5	8313.5	1401.2 (+120)	
WC#: 29.040	AFL	2686						
PROC. REF: AMM 29-11-01-350-801	PROC. REF: AMM 29-11-01-350-801							
29-11-01-350-801-03	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 3 (R500ML)							Service ATA:29
PN:PVB-022-2	MOS	08-Mar-12						OVERHAUL
SN:MX3750820H	HRS	3996.83	4000 (+3%)		7996.83	8116.83	1204.5 (+120)	
WC#: 29.050	AFL	2577						
PROC. REF: AMM 29-11-01-350-801	PROC. REF: AMM 29-11-01-350-801							
29-11-01-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 1 (L500ML)							Component ATA:29
PN:PVB-022-2	MOS/MSC	23-Oct-12	H/T	TSO 0				
SN:MX-538566H	HRS	4193.5		TSO 0				
WC#: 29.030	AFL	2686		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801								
29-11-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 2 (M500ML)							Component ATA:29
PN:PVB-022-2	MOS/MSC	23-Oct-12	H/T	TSO 0				
SN:MX-540547G	HRS	4193.5		TSO 0				
WC#: 29.040	AFL	2686		TSO 0				
PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801								
29-11-01-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 3 (R500ML)							Component ATA:29
PN:PVB-022-2	MOS/MSC	08-Mar-12	H/T	TSR 0				
SN:MX3750820H	HRS	3996.83		TSR 0				
WC#: 29.050	AFL	2577		TSR 0				
PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801PROC. REF: AMM 29-11-01-900-801, AMM 29-11-01-900-801								
29-11-21-230-801-01	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)							Service ATA:29
PN:A24518001A	MOS/MSC	15-Jul-96	O/C					
SN:FM1654	HRS	0						
WC#: 29.250	AFL	0						
PROC. REF: AMM 29-11-21-230-801PROC. REF: AMM 29-11-21-230-801								
29-11-21-230-801-02	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)							Service ATA:29
PN:A24518001	MOS/MSC		O/C					
SN:FM02093	HRS							
WC#: 29.250	AFL							
PROC. REF: AMM 29-11-21-230-801PROC. REF: AMM 29-11-21-230-801								
29-11-21-230-801-03	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)							Service ATA:29
PN:A24518001A	MOS/MSC	15-Jul-96	O/C					
SN:FM1649	HRS	0						
WC#: 29.260	AFL	0						
PROC. REF: AMM 29-11-21-230-801PROC. REF: AMM 29-11-21-230-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-11-21-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)							Component ATA:29
PN:A24518001A	MOS/MSC	11-Jul-95	O/C					
SN:FM1654	HRS	0		TSN 0				
WC#: 29.250	AFL	0						
PROC. REF: AMM 29-11-21-900-801	PROC. REF: AMM 29-11-21-900-801							
29-11-21-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)							Component ATA:29
PN:A24518001	MOS/MSC	11-Aug-20	O/C	TSR 36				
SN:FM02093	HRS	5942.6		TSR 0				
WC#: 29.250	AFL	3569		TSR 0				
PROC. REF: AMM 29-11-21-900-801	PROC. REF: AMM 29-11-21-900-801							
29-11-21-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)							Component ATA:29
PN:A24518001A	MOS/MSC	11-Jul-95	O/C					
SN:FM1649	HRS	0		TSN 0				
WC#: 29.260	AFL	0						
PROC. REF: AMM 29-11-21-900-801	PROC. REF: AMM 29-11-21-900-801							
29-11-25-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (11D1)							Component ATA:29
PN:90G229	MOS/MSC	21-Sep-07	O/C	TSN 0				
SN:1962	HRS	2778.9		TSN 0				
WC#: 29.360	AFL	1892		TSN 0				
PROC. REF: AMM 29-11-25-900-801	PROC. REF: AMM 29-11-25-900-801							
29-11-25-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (11D2)							Component ATA:29
PN:90G229	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:1029	HRS	0		TSN 0				
WC#: 29.360	AFL	0		TSN 0				
PROC. REF: AMM 29-11-25-900-801	PROC. REF: AMM 29-11-25-900-801							
29-11-25-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (11D3)							Component ATA:29
PN:90G229	MOS/MSC	26-Aug-10	O/C	TSN 0				
SN:2754	HRS	3575.7		TSN 0				
WC#: 29.360	AFL	2341		TSN 0				
PROC. REF: AMM 29-11-25-900-801	PROC. REF: AMM 29-11-25-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-11-25-900-801-04	NO. 1 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH							Component ATA:29
PN:90G196-2	MOS/MSC	11-Jul-95	O/C					
SN:1652	HRS	0		TSN 0				
WC#: 29.320	AFL	0						
PROC. REF: AMM 29-11-25-900-801	PROC. REF: AMM 29-11-25-900-801							
29-11-25-900-801-05	NO. 2 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH							Component ATA:29
PN:90G196-2	MOS/MSC	26-Aug-10	O/C	TSN 0				
SN:2928	HRS	3575.7		TSN 0				
WC#: 29.320	AFL	2341		TSN 0				
PROC. REF: AMM 29-11-25-900-801	PROC. REF: AMM 29-11-25-900-801							
29-11-25-960-801-01	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (11D1)							Service ATA:29
PN:90G229	MOS/MSC		O/C					
SN:1962	HRS							
WC#: 29.360	AFL							
PROC. REF: AMM 29-11-25-960-801	PROC. REF: AMM 29-11-25-960-801							
29-11-25-960-801-02	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (11D2)							Service ATA:29
PN:90G229	MOS/MSC	15-Jul-96	O/C					
SN:1029	HRS	0		TAC 0				
WC#: 29.360	AFL	0						
PROC. REF: AMM 29-11-25-960-801	PROC. REF: AMM 29-11-25-960-801							
29-11-25-960-801-03	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (11D3)							Service ATA:29
PN:90G229	MOS/MSC		O/C					
SN:2754	HRS							
WC#: 29.360	AFL							
PROC. REF: AMM 29-11-25-960-801	PROC. REF: AMM 29-11-25-960-801							
29-13-09-100-801-01	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 1 RETURN FILTER (L200ML)							Service ATA:29
PN:285695	MOS	08-Sep-22						
SN:U2122	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.070	AFL	3722						
PROC. REF: AMM 29-13-09-100-801	PROC. REF: AMM 29-13-09-100-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-13-09-100-801-02	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 2 RETURN FILTER (M200ML)							Service ATA:29
PN:285695	MOS	08-Sep-22						
SN:U2123	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.070	AFL	3722						
PROC. REF: AMM 29-13-09-100-801	PROC. REF: AMM 29-13-09-100-801							
29-13-09-100-801-03	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 3 RETURN FILTER (R200ML)							Service ATA:29
PN:285695	MOS	08-Sep-22						
SN:U2121	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.080	AFL	3722						
PROC. REF: AMM 29-13-09-100-801	PROC. REF: AMM 29-13-09-100-801							
29-13-09-100-801-04	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 1 DELIVERY FILTER (L350ML)							Service ATA:29
PN:C24636000	MOS	08-Sep-22						
SN:U175	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.140	AFL	3722						
PROC. REF: AMM 29-13-09-100-801	PROC. REF: AMM 29-13-09-100-801							
29-13-09-100-801-05	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 2 DELIVERY FILTER (M350ML)							Service ATA:29
PN:C24636000	MOS	08-Sep-22						
SN:U177	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.150	AFL	3722						
PROC. REF: AMM 29-13-09-100-801	PROC. REF: AMM 29-13-09-100-801							
29-13-09-100-801-06	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 3 DELIVERY FILTER (R350ML)							Service ATA:29
PN:C24636000	MOS	08-Sep-22						
SN:U176	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.160	AFL	3722						
PROC. REF: AMM 29-13-09-100-801	PROC. REF: AMM 29-13-09-100-801							
29-13-09-100-801-07	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - STANDBY PUMP FILTER (14ML)							Service ATA:29
PN:C24561000	MOS	26-Nov-25						
SN:U188	HRS	6712.3	1200 (+30)		7912.3	7942.3	1120 (+30)	
WC#: 29.330	AFL	3950						
PROC. REF: AMM 29-13-09-100-801	PROC. REF: AMM 29-13-09-100-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-14-01-220-801-01	DETAILED INSPECTION OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)							Service ATA:29
PN:C24304002	MOS/MSC	08-Jun-16	O/C					
SN:U107	HRS	5064.3						
WC#: 29.060	AFL	3203						
PROC. REF: AMM 29-14-01-220-801	PROC. REF: AMM 29-14-01-220-801							
29-14-01-220-801-02	DETAILED INSPECTION OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)							Service ATA:29
PN:C24304002	MOS/MSC	08-Jun-16	O/C					
SN:U106	HRS	5064.3						
WC#: 29.060	AFL	3203						
PROC. REF: AMM 29-14-01-220-801	PROC. REF: AMM 29-14-01-220-801							
29-14-01-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)							Component ATA:29
PN:C24304002	MOS/MSC	11-Jul-95	O/C					
SN:U107	HRS	0		TSN 0				
WC#: 29.060	AFL	0						
PROC. REF: AMM 29-14-01-900-801	PROC. REF: AMM 29-14-01-900-801							
29-14-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)							Component ATA:29
PN:C24304002	MOS/MSC	11-Jul-95	O/C					
SN:U106	HRS	0		TSN 0				
WC#: 29.060	AFL	0						
PROC. REF: AMM 29-14-01-900-801	PROC. REF: AMM 29-14-01-900-801							
29-14-11-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 1 ACCUMULATOR (L515ML)							Component ATA:29
PN:60833-2	MOS/MSC	11-Jul-95	O/C					
SN:766	HRS	0		TSN 0				
WC#: 29.190	AFL	0						
PROC. REF: AMM 29-14-11-900-801	PROC. REF: AMM 29-14-11-900-801							
29-14-11-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 2 ACCUMULATOR (R515ML)							Component ATA:29
PN:60833-2	MOS/MSC	11-Jul-95	O/C					
SN:856	HRS	0		TSN 0				
WC#: 29.190	AFL	0						
PROC. REF: AMM 29-14-11-900-801	PROC. REF: AMM 29-14-11-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-14-33-960-801-01		REPLACEMENT OF THE HYDRAULIC RESERVOIR FILTERING ELEMENTS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)						Service ATA:29
PN:C24304002	MOS	08-Sep-22						
SN:U107	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.060	AFL	3722						
PROC. REF: AMM 29-14-33-960-801	PROC. REF: AMM 29-14-33-960-801							
29-14-33-960-801-02		REPLACEMENT OF THE HYDRAULIC RESERVOIR FILTERING ELEMENTS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)						Service ATA:29
PN:C24304002	MOS	08-Sep-22						
SN:U106	HRS	6221.1	1200 (+30)		7421.1	7451.1	628.8 (+30)	
WC#: 29.060	AFL	3722						
PROC. REF: AMM 29-14-33-960-801	PROC. REF: AMM 29-14-33-960-801							
29-14-33-960-802-01		REPLACEMENT OF THE CHLORINE RETAINING ELEMENT - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)						Service ATA:29
	MOS/MSC	08-May-14	N/A					
	HRS	4694.5						
WC#: 29.010	AFL	2957						
PROC. REF: AMM 29-14-33-960-802	PROC. REF: AMM 29-14-33-960-802							
29-14-33-960-802-02		REPLACEMENT OF THE CHLORINE RETAINING ELEMENT - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)						Service ATA:29
	MOS/MSC	08-May-14	N/A					
	HRS	4694.5						
WC#: 29.010	AFL	2957						
PROC. REF: AMM 29-14-33-960-802	PROC. REF: AMM 29-14-33-960-802							
29-15-00-720-801-01 S		FUNCTIONAL TEST OF THE HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - HYDRAULIC SYSTEM 1						Service ATA:29
	MOS	11-Aug-20						
	HRS	5942.6	6000 (+30)					
WC#: 29.060	AFL	3569						
								PKG:24
PROC. REF: AMM 29-15-00-720-801	PROC. REF: AMM 29-15-00-720-801							
29-15-00-720-801-02 S		FUNCTIONAL TEST OF THE HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - HYDRAULIC SYSTEM 2						Service ATA:29
	MOS	11-Aug-20						
	HRS	5942.6	6000 (+30)					
WC#: 29.060	AFL	3569						
								PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
PROC. REF: AMM 29-15-00-720-801	PROC. REF: AMM 29-15-00-720-801							
29-15-05-100-801-01	CLEANING OF THE HYDRAULIC RESERVOIR PRESSURE REDUCER FILTERS - HYDRAULIC RESERVOIR PRESSURE REDUCER (10ML)							Service ATA:29
PN:2407ZR4EQ10	MOS	02-Oct-24	48		02-Oct-28		724 d	
SN:1879	HRS	6601.6						
WC#: 29.090	AFL	3875						
PROC. REF: AMM 29-15-05-100-801	PROC. REF: AMM 29-15-05-100-801							
29-15-05-350-801-01	RESTORATION OF THE HYDRAULIC RESERVOIR PRESSURE REDUCER (FUNCTIONAL TEST AND DIAPHRAGM REPLACEMENT) - HYDRAULIC RESERVOIR PRESSURE REDUCER (10ML)							Service ATA:29
PN:2407ZR4EQ10	MOS	11-Aug-20	72		11-Aug-26		OVD	
SN:1879	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 29-15-05-350-801	PROC. REF: AMM 29-15-05-350-801							
29-15-05-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIR PRESSURE REDUCER - HYDRAULIC RESERVOIR PRESSURE REDUCER (10ML)							Component ATA:29
PN:2407ZR4EQ10	MOS/MSC	11-Aug-20	O/C	TSO 16				
SN:1879	HRS	5942.6		TSO 0				
WC#: 29.090	AFL	3569		TSO 0				
PROC. REF: AMM 29-15-05-900-801	PROC. REF: AMM 29-15-05-900-801							
29-20-00-720-801-01	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - TEST ON HYDRAULIC SYSTEM 2							Service ATA:29
	MOS	08-May-14						
	HRS	4694.5	4800 (+30)		9494.5	9524.5	2702.2 (+30)	
WC#: 29.300	AFL	2957						
PROC. REF: AMM 29-20-00-720-801	PROC. REF: AMM 29-20-00-720-801							
29-20-01-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY ELECTRIC PUMP - STANDBY ELECTRIC PUMP (15M)							Component ATA:29
PN:EP1600-12	MOS/MSC	08-May-14	O/C					
SN:388	HRS	4694.5						
WC#: 29.300	AFL	2957						
PROC. REF: AMM 29-20-01-900-801	PROC. REF: AMM 29-20-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-20-03-220-801-01	CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (15M)							Service ATA:29
PN:1153-1	MOS	08-May-14						
SN:UNKNOWN	HRS	4694.25	4800 (+3%)		9494.25	9638.25	2702 (+144)	
WC#: 29.300	AFL	2957						
PROC. REF: AMM 29-20-03-220-801	PROC. REF: AMM 29-20-03-220-801							
29-20-05-900-801-01	REMOVAL / INSTALLATION OF THE STANDBY PUMP SELECTOR VALVE - STANDBY PUMP SELECTOR VALVE (17D)							Component ATA:29
PN:B94A13-205	MOS/MSC	17-Jul-96	O/C					
SN:20277	HRS	150						
WC#: 29.310	AFL	62						
PROC. REF: AMM 29-20-05-900-801	PROC. REF: AMM 29-20-05-900-801							
29-20-07-960-801-01	DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (16M1)							Service ATA:29
PN:90G196-2	MOS/MSC	15-Jul-96	O/C					
SN:1652	HRS	0		TAC 0				
WC#: 29.320	AFL	0						
PROC. REF: AMM 29-20-07-960-801	PROC. REF: AMM 29-20-07-960-801							
29-20-07-960-801-02	DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (16M2)							Service ATA:29
PN:90G196-2	MOS/MSC		O/C					
SN:2928	HRS							
WC#: 29.320	AFL							
PROC. REF: AMM 29-20-07-960-801	PROC. REF: AMM 29-20-07-960-801							
291161	HYDRAULIC PRESSURIZATION VALVE ASSEMBLY							Component ATA:29
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
291166	NO. 1 CIRCUIT NO.1 RETURN REGULATION FILTER							Component ATA:29
PN:285695	MOS/MSC	08-May-14	O/C					
SN:U2122	HRS	4694.25						
WC#: 29.070	AFL	2957						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291176	NO. 1 CIRCUIT NO.2 RETURN REGULATION FILTER							Component ATA:29
PN:285695	MOS/MSC	08-May-14	O/C					
SN:U2123	HRS	4694.25						
WC#: 29.070	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291186	NO. 2 CIRCUIT NO.3 RETURN REGULATION FILTER							Component ATA:29
PN:285695	MOS/MSC	08-May-14	O/C					
SN:U2121	HRS	4694.25						
WC#: 29.080	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291226	NO. 1 PUMP RETURN CHECK VALVE							Component ATA:29
PN:A24515-1	MOS/MSC	11-Jul-95	O/C					
SN:FM1073	HRS	0		TSN 0				
WC#: 29.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291231	NO. 2 PUMP RETURN CHECK VALVE							Component ATA:29
PN:A24515-1	MOS/MSC	11-Jul-95	O/C					
SN:FM1071	HRS	0		TSN 0				
WC#: 29.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291236	NO. 3 PUMP RETURN CHECK VALVE							Component ATA:29
PN:A24515-1	MOS/MSC	11-Jul-95	O/C					
SN:FM1156	HRS	0		TSN 0				
WC#: 29.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291241	NO. 1 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING							Component ATA:29
PN:405-20402-13300	MOS/MSC	23-Oct-12	O/C	TSO 0				
SN:667	HRS	4193.5		TSO 0				
WC#: 29.110	AFL	2686		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291246	NO. 2 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING							Component ATA:29
PN:405-20402-13300	MOS/MSC	11-Jul-95	O/C					
SN:1202	HRS	0		TSN 0				
WC#: 29.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291251	NO. 3 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING							Component ATA:29
PN:405-20402-13300	MOS/MSC	11-Jul-95	O/C					
SN:1203	HRS	0		TSN 0				
WC#: 29.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291256	NO. 1 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING							Component ATA:29
PN:405-20403-13200	MOS/MSC	23-Oct-12	O/C	TSO 0				
SN:729	HRS	4193.5		TSO 0				
WC#: 29.120	AFL	2686		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291261	NO. 2 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING							Component ATA:29
PN:405-20403-13200	MOS/MSC	11-Jul-95	O/C					
SN:1272	HRS	0		TSN 0				
WC#: 29.120	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291266	NO. 3 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING							Component ATA:29
PN:405-20403-13200	MOS/MSC	11-Jul-95	O/C					
SN:1273	HRS	0		TSN 0				
WC#: 29.120	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291271	NO. 1 PUMP DISCHARGE QUICK DISCONNECT VALVE							Component ATA:29
PN:AE99113H	MOS/MSC	11-Jul-95	O/C					
SN:NONE	HRS	0		TSN 0				
WC#: 29.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291276	NO. 2 PUMP DISCHARGE QUICK DISCONNECT VALVE							Component ATA:29
PN:AE99113H	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291281	NO. 3 PUMP DISCHARGE QUICK DISCONNECT VALVE							Component ATA:29
PN:AE99113H	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291286	NO. 1 HP HYDRAULIC FILTER							Component ATA:29
PN:C24636000	MOS/MSC	08-May-14	O/C					
SN:U175	HRS	4694.25						
WC#: 29.140	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291296	NO. 2 HP HYDRAULIC FILTER							Component ATA:29
PN:C24636000	MOS/MSC	08-May-14	O/C					
SN:U177	HRS	4694.25						
WC#: 29.150	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291306	NO. 3 HP HYDRAULIC FILTER							Component ATA:29
PN:C24636000	MOS/MSC	08-May-14	O/C					
SN:U176	HRS	4694.25						
WC#: 29.160	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291316	NO. 1 HYDRAULIC SYSTEM LEFT GROUND RETURN CONNECTION							Component ATA:29
PN:B3005S4-12D	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291321	NO. 2 HYDRAULIC SYSTEM RIGHT GROUND RETURN CONNECTION							Component ATA:29
PN:B3005S4-12D	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291326	NO. 1 HYDRAULIC SYSTEM LEFT GROUND PRESSURE CONNECTION							Component ATA:29
PN:TB3005S4-8D	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291331	NO. 2 HYDRAULIC SYSTEM RIGHT GROUND PRESSURE CONNECTION							Component ATA:29
PN:TB3005S4-8D	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291356	NO. 1 PRESSURE INDICATOR							Component ATA:29
PN:18040100	MOS/MSC	11-Jul-95	O/C					
SN:33719C	HRS	0		TSN 0				
WC#: 29.200	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291366	NO. 2 PRESSURE INDICATOR							Component ATA:29
PN:18040100	MOS/MSC	11-Jul-95	O/C					
SN:32749C	HRS	0		TSN 0				
WC#: 29.200	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291376	NO. 1 HYDRAULIC SYSTEM ACCUMULATOR FILLER VALVE							Component ATA:29
PN:MS28889-2	MOS/MSC	11-Jul-95	O/C					
SN:NONE	HRS	0		TSN 0				
WC#: 29.210	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291381	NO. 2 HYDRAULIC SYSTEM ACCUMULATOR FILLER VALVE							Component ATA:29
PN:MS28889-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.210	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291386	PARKING BRAKE ACCUMULATOR FILLER VALVE							Component ATA:29
PN:MS28889-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.220	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291391	THRUST REVERSER ACCUMULATOR FILLER VALVE							Component ATA:29
PN:MS28889-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.220	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291396	NO. 1 PUMP SUCTION CHECK VALVE							Component ATA:29
PN:A24517	MOS/MSC	11-Jul-95	O/C					
SN:FM4372	HRS	0		TSN 0				
WC#: 29.230	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291401	NO. 2 PUMP SUCTION CHECK VALVE							Component ATA:29
PN:A24517	MOS/MSC	11-Jul-95	O/C					
SN:FM4377	HRS	0		TSN 0				
WC#: 29.230	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291406	NO. 3 PUMP SUCTION CHECK VALVE							Component ATA:29
PN:A24517	MOS/MSC	11-Jul-95	O/C					
SN:FM4373	HRS	0		TSN 0				
WC#: 29.230	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291411	NO. 1 SYSTEM SUCTION CHECK VALVE GROUND CONNECTION							Component ATA:29
PN:A24517	MOS/MSC	11-Jul-95	O/C					
SN:FM4386	HRS	0		TSN 0				
WC#: 29.240	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291416	NO. 2 SYSTEM SUCTION CHECK VALVE GROUND CONNECTION							Component ATA:29
PN:A24517	MOS/MSC	11-Jul-95	O/C					
SN:FM4388	HRS	0		TSN 0				
WC#: 29.240	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291436	NO. 1 SYSTEM ELECTRO PUMP DISTRIBUTOR CHECK VALVE							Component ATA:29
PN:A24516	MOS/MSC	11-Jul-95	O/C					
SN:FM3190	HRS	0		TSN 0				
WC#: 29.270	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291441	NO. 2 SYSTEM ELECTRO PUMP DISTRIBUTOR CHECK VALVE							Component ATA:29
PN:A24516	MOS/MSC	11-Jul-95	O/C					
SN:FM3197	HRS	0		TSN 0				
WC#: 29.270	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291446	HYDRAULIC PRESSURIZATION CHECK VALVE							Component ATA:29
PN:2504CD01	MOS/MSC	11-Jul-95	O/C					
SN:652	HRS	0		TSN 0				
WC#: 29.280	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
292121	HYDRAULIC ELECTRO- PUMP-MOTOR							Component ATA:29
PN:1153-1	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.300	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
292156	AUXILIARY HYDRAULIC SYSTEM FILTER							Component ATA:29
PN:C24561000	MOS/MSC	08-May-14	O/C					
SN:U188	HRS	4694.25		TSN 4694.25				
WC#: 29.330	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
293101	NO. 1 CIRCUIT PRESSURE TRANSMITTER							Component ATA:29
PN:8107-134-00-12	MOS/MSC	14-Sep-21	O/C					
SN:216	HRS	6074.8						
WC#: 29.340	AFL	3636						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
293106	NO. 2 CIRCUIT PRESSURE TRANSMITTER							Component ATA:29
PN:8107-134-00-12	MOS/MSC	11-Jul-95	O/C					
SN:307	HRS	0		TSN 0				
WC#: 29.340	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
293111	NO. 1 CIRCUIT DUAL INDICATOR PRESSURE LEVEL							Component ATA:29
PN:5502-382-80-12	MOS/MSC	20-Dec-06	O/C	TSR 0				
SN:973	HRS	2522.08		TSR 0				
WC#: 29.350	AFL	1744		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
293116	NO. 2 CIRCUIT DUAL INDICATOR PRESSURE LEVEL							Component ATA:29
PN:5502-382-80-12	MOS/MSC	20-Dec-06	O/C	TSR 0				
SN:964	HRS	2522.08		TSR 0				
WC#: 29.350	AFL	1744		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
293141	NO. 1 HYDRAULIC RESERVOIR PRESSURIZATION LOW PRESSURE SWITCH							Component ATA:29
PN:8A1206-1	MOS/MSC	11-Jul-95	O/C					
SN:290	HRS	0		TSN 0				
WC#: 29.370	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293146	NO. 2 HYDRAULIC RESERVOIR PRESSURIZATION LOW PRESSURE SWITCH							Component ATA:29
PN:8A1206-1	MOS/MSC	11-Jul-95	O/C					
SN:287	HRS	0		TSN 0				
WC#: 29.370	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 30 - ICE AND RAIN PROTECTION								
30-11-00-350-801-01	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH INBOARD SLAT TELESCOPIC DUCT (L537H1)							Service ATA:30
PN:5040-000	MOS/MSC		O/C					
SN:579	HRS							
WC#: 30.030	AFL							
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-350-801-02	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH INBOARD SLAT TELESCOPIC DUCT (R537H1)							Service ATA:30
PN:5041-200	MOS/MSC		O/C					
SN:334	HRS							
WC#: 30.030	AFL							
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-350-801-03	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH OUTBOARD SLAT TELESCOPIC DUCT (L537H2)							Service ATA:30
PN:5041-300	MOS/MSC	15-Jul-96	O/C					
SN:347	HRS	0		TAC 0				
WC#: 30.020	AFL	0						
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-350-801-04	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH OUTBOARD SLAT TELESCOPIC DUCT (R537H2)							Service ATA:30
PN:5040-300	MOS/MSC	02-Oct-24	O/C					
SN:468	HRS	6601.6						
WC#: 30.020	AFL	3875						
PROC. REF: AMM 30-11-00-350-801PROC. REF: AMM 30-11-00-350-801								
30-11-00-720-801-01	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH INBOARD SLAT TELESCOPIC DUCT (L537H1)							Service ATA:30
PN:5040-000	MOS	02-Oct-24						
SN:579	HRS	6601.6	T:2500 (+3%)		9101.6	9176.6	2309.3 (+75)	
WC#: 30.030	AFL	3875	T:2000 (+3%)		5875	5935	1865 (+60)	
PROC. REF: AMM 30-11-00-720-801PROC. REF: AMM 30-11-00-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-00-720-801-02	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH INBOARD SLAT TELESCOPIC DUCT (R537H1)							Service ATA:30
PN:5041-200	MOS	02-Oct-24						
SN:334	HRS	6601.6	T:2500 (+3%)		9101.6	9176.6	2309.3 (+75)	
WC#: 30.030	AFL	3875	T:2000 (+3%)		5875	5935	1865 (+60)	
PROC. REF: AMM 30-11-00-720-801	PROC. REF: AMM 30-11-00-720-801							
30-11-00-720-801-03	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD SLAT TELESCOPIC DUCT (L537H2)							Service ATA:30
PN:5041-300	MOS	02-Oct-24						
SN:347	HRS	6601.6	T:2500 (+3%)		9101.6	9176.6	2309.3 (+75)	
WC#: 30.020	AFL	3875	T:2000 (+3%)		5875	5935	1865 (+60)	
PROC. REF: AMM 30-11-00-720-801	PROC. REF: AMM 30-11-00-720-801							
30-11-00-720-801-04	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD SLAT TELESCOPIC DUCT (R537H2)							Service ATA:30
PN:5040-300	MOS	02-Oct-24						
SN:468	HRS	6601.6	T:2500 (+3%)		9101.6	9176.6	2309.3 (+75)	
WC#: 30.020	AFL	3875	T:2000 (+3%)		5875	5935	1865 (+60)	
PROC. REF: AMM 30-11-00-720-801	PROC. REF: AMM 30-11-00-720-801							
30-11-00-900-801-01	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH INBOARD TELESCOPIC DUCT (L537H1)							Component ATA:30
PN:5040-000	MOS/MSC	02-Oct-24	O/C					
SN:579	HRS	6601.6						
WC#: 30.020	AFL	3875						
PROC. REF: AMM 30-11-00-900-801	PROC. REF: AMM 30-11-00-900-801							
30-11-00-900-801-02	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH INBOARD TELESCOPIC DUCT (R537H1)							Component ATA:30
PN:5041-200	MOS/MSC	02-Oct-24	O/C					
SN:334	HRS	6601.6						
WC#: 30.030	AFL	3875						
PROC. REF: AMM 30-11-00-900-801	PROC. REF: AMM 30-11-00-900-801							
30-11-00-900-801-03	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD TELESCOPIC DUCT (L537H2)							Component ATA:30
PN:5041-300	MOS/MSC	02-Oct-24	O/C					
SN:347	HRS	6601.6						
WC#: 30.030	AFL	3875						
PROC. REF: AMM 30-11-00-900-801	PROC. REF: AMM 30-11-00-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-11-00-900-801-04	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD TELESCOPIC DUCT (R537H2)							Component ATA:30
PN:5040-300	MOS/MSC	02-Oct-24	O/C	TSO 0				
SN:468	HRS	6601.6		TSO 0				
WC#: 30.020	AFL	3875		TSO 0				
PROC. REF: AMM 30-11-00-900-801	PROC. REF: AMM 30-11-00-900-801							
30-12-01-720-801-01	FUNCTIONAL TEST OF THE WING ANTI-ICING VALVES - WING ANTI-ICING VALVE (113H)							Service ATA:30
PN:1263-00-12	MOS	08-Mar-12						
SN:0615	HRS	3996.83	4000		7996.83		1204.5	
WC#: 30.010	AFL	2577						
PROC. REF: AMM 30-12-01-720-801	PROC. REF: AMM 30-12-01-720-801							
30-12-01-720-801-02	FUNCTIONAL TEST OF THE WING ANTI-ICING VALVES - WING STAND-BY ANTI-ICING VALVE (97H)							Service ATA:30
PN:1263-00-12	MOS	08-Dec-23						
SN:0528AB	HRS	6529.1	4000		10529.1		3736.8	
WC#: 30.010	AFL	3833						
PROC. REF: AMM 30-12-01-720-801	PROC. REF: AMM 30-12-01-720-801							
30-12-13-900-801-01	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PRESSURE SWITCHES - LH WING PRESSURE SWITCH (115H1)							Component ATA:30
PN:8G1199-4	MOS/MSC	27-Aug-98	O/C	TSO 0				
SN:486	HRS	801.7		TSO 0				
WC#: 30.040	AFL	528		TSO 0				
PROC. REF: AMM 30-12-13-900-801	PROC. REF: AMM 30-12-13-900-801							
30-12-13-900-801-02	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PRESSURE SWITCHES - RH WING PRESSURE SWITCH (115H2)							Component ATA:30
PN:8G1199-4	MOS/MSC	27-Aug-98	O/C	TSO 0				
SN:445	HRS	801.7		TSO 0				
WC#: 30.040	AFL	528		TSO 0				
PROC. REF: AMM 30-12-13-900-801	PROC. REF: AMM 30-12-13-900-801							
30-20-01-700-801-01	FUNCTIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L103H)							Service ATA:30
PN:1780-00-1	MOS	08-Mar-12						
SN:934	HRS	3996.83	4000		7996.83		1204.5	
WC#: 30.070	AFL	2577						
PROC. REF: AMM 30-20-01-700-801	PROC. REF: AMM 30-20-01-700-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-20-01-700-801-02	FUNCTIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M103H)							Service ATA:30
PN:1780-00-1	MOS	23-Oct-12						
SN:1126	HRS	4193.5	4000		8193.5		1401.2	
WC#: 30.060	AFL	2686						
PROC. REF: AMM 30-20-01-700-801	PROC. REF: AMM 30-20-01-700-801							
30-20-01-700-801-03	FUNCTIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R103H)							Service ATA:30
PN:1780-00-1	MOS	08-Mar-12						
SN:930	HRS	3996.83	4000		7996.83		1204.5	
WC#: 30.070	AFL	2577						
PROC. REF: AMM 30-20-01-700-801	PROC. REF: AMM 30-20-01-700-801							
30-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L103H)							Component ATA:30
PN:1780-00-1	MOS/MSC	11-Jul-95	O/C					
SN:934	HRS	0		TSN 0				
WC#: 30.070	AFL	0						
PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801	PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801							
30-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M103H)							Component ATA:30
PN:1780-00-1	MOS/MSC	23-Oct-12	O/C	TSO 0				
SN:1126	HRS	4193.5		TSO 0				
WC#: 30.060	AFL	2686		TSO 0				
PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801	PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801							
30-20-01-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R103H)							Component ATA:30
PN:1780-00-1	MOS/MSC	11-Jul-95	O/C					
SN:930	HRS	0		TSN 0				
WC#: 30.070	AFL	0						
PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801	PROC. REF: AMM 30-20-01-900-801, AMM 30-20-01-900-801							
30-20-09-900-801-01	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-4	MOS/MSC	17-Jul-96	O/C	TSN 0				
SN:164	HRS	149.5		TSN 0				
WC#: 30.080	AFL	62		TSN 0				
PROC. REF: AMM 30-20-09-900-801, AMM 30-20-09-900-801	PROC. REF: AMM 30-20-09-900-801, AMM 30-20-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-20-09-900-801-02	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH							Component ATA:30
PN:8G1199-4	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:202	HRS	0		TSN 0				
WC#: 30.090	AFL	0		TSN 0				
PROC. REF: AMM 30-20-09-900-801, AMM 30-20-09-900-801PROC. REF: AMM 30-20-09-900-801, AMM 30-20-09-900-801								
30-20-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING PRESSURE INDICATING SWITCHES - ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH (R107H)							Component ATA:30
PN:8G1199-4	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:199	HRS	0		TSN 0				
WC#: 30.080	AFL	0		TSN 0				
PROC. REF: AMM 30-20-09-900-801PROC. REF: AMM 30-20-09-900-801								
30-20-09-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING PRESSURE INDICATING SWITCHES - S-DUCT ANTI-ICING PRESSURE SWITCH (109H)							Component ATA:30
PN:8G1199-5	MOS/MSC	10-Nov-21	O/C	TSN 0				
SN:5240	HRS	6083.4		TSN 0				
WC#: 30.090	AFL	3653		TSN 0				
PROC. REF: AMM 30-20-09-900-801PROC. REF: AMM 30-20-09-900-801								
30-30-00-710-801-01 S	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM							Service ATA:30
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 30.300	AFL	3569						
								PKG:21
PROC. REF: AMM 30-30-00-710-801PROC. REF: AMM 30-30-00-710-801								
30-41-00-200-801-01	INSPECTION OF THE WINDSHIELD HEATING SYSTEM CONNECTORS							Service ATA:30
	MOS	02-Oct-24	24 (+1m)		02-Oct-26	02-Nov-26	TOL (+24 d)	
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 30-41-00-200-801PROC. REF: AMM 30-41-00-200-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-41-00-710-801-01	S	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM						Service ATA:30
	MOS	11-Aug-20						
	HRS	5942.6	6000 (+30)					
	AFL	3569						
								PKG:24
PROC. REF: AMM 30-41-00-710-801	PROC. REF: AMM 30-41-00-710-801							
30-42-00-200-801-01		INSPECTION OF THE DESICCANT OF COCKPIT AFT SIDE WINDOW DEMISTING - LH REAR WINDOW (146H1)						Service ATA:30
	MOS/MSC	02-Dec-14	O/C					
	HRS	4828.1						
WC#: 30.190	AFL	3016						
PROC. REF: AMM 30-42-00-200-801	PROC. REF: AMM 30-42-00-200-801							
30-42-00-200-801-02		INSPECTION OF THE DESICCANT OF COCKPIT AFT SIDE WINDOW DEMISTING - RH REAR WINDOW (146H2)						Service ATA:30
	MOS/MSC	02-Dec-14	O/C					
	HRS	4828.1						
WC#: 30.190	AFL	3016						
PROC. REF: AMM 30-42-00-200-801	PROC. REF: AMM 30-42-00-200-801							
30-43-09-220-801-01		CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - LH WINDSHIELD WIPER MOTOR (3M1)						Service ATA:30
PN:XW23827G1	MOS	15-Jul-96						
SN:00071	HRS	0	10000		10000		3207.7	
	AFL	0						
PROC. REF: AMM 30-43-09-220-801	PROC. REF: AMM 30-43-09-220-801							
30-43-09-220-801-02		CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - RH WINDSHIELD WIPER MOTOR (3M2)						Service ATA:30
PN:XW23827G1	MOS	15-Jul-96						
SN:00072	HRS	0	10000		10000		3207.7	
	AFL	0						
PROC. REF: AMM 30-43-09-220-801	PROC. REF: AMM 30-43-09-220-801							
30-60-01-720-801-01		FUNCTIONAL TEST OF THE S-DUCT ANTI-ICING VALVE - S-DUCT ANTI-ICING VALVE (104H)						Service ATA:30
PN:3137-100	MOS	23-Oct-12						
SN:298	HRS	4193.5	4000		8193.5		1401.2	
WC#: 30.060	AFL	2686						
PROC. REF: AMM 30-60-01-720-801	PROC. REF: AMM 30-60-01-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301050	AIRFOIL ANTI-ICING VALVE							Component ATA:30
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.210	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
301091	AIRFRAME NORMAL ANTI-ICING VALVE							Component ATA:30
PN:1263-00-12	MOS/MSC	11-Jul-95	O/C					
SN:0615	HRS	0		TSN 0				
WC#: 30.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
301101	AIRFRAME EMERGENCY ANTI-ICING VALVE							Component ATA:30
PN:1263-00-12	MOS/MSC	08-Dec-23	O/C	TSR 0				
SN:0528AB	HRS	6529.1		TSR 0				
WC#: 30.010	AFL	3833		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
302111	S-DUCT ANTI-ICING VALVE							Component ATA:30
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.220	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
302116	TC-T'C DUAL TEMPERATURE PROBE (38H1)							Component ATA:30
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
302126	TV-T'V DUAL TEMPERATURE PROBE (38H3)							Component ATA:30
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.240	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
302131	NO. 2 ENGINE S-DUCT ANTI-ICING VALVE							Component ATA:30
PN:3137-100	MOS/MSC	23-Oct-12	O/C					
SN:298	HRS	4193.5						
WC#: 30.060	AFL	2686						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
303001	LH PITOT HEAT INDICATOR PRINTED CIRCUIT BOARD							Component ATA:30
PN:24-250	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
303106	RH PITOT HEAT INDICATOR PRINTED CIRCUIT BOARD							Component ATA:30
PN:24-250	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304101	PILOT WINDSHIELD WIPER MOTOR							Component ATA:30
PN:XW23827G1	MOS/MSC	11-Jul-95	O/C					
SN:00071	HRS	0		TSN 0				
WC#: 30.110	AFL	0						
PROC. REF: AMM 56-10-01-900-801PROC. REF: AMM 56-10-01-900-801								
304111	COPILOT WINDSHIELD WIPER MOTOR							Component ATA:30
PN:XW23827G1	MOS/MSC	11-Jul-95	O/C					
SN:00072	HRS	0		TSN 0				
WC#: 30.110	AFL	0						
PROC. REF: AMM 56-10-01-900-801PROC. REF: AMM 56-10-01-900-801								
304121	PILOT WINDSHIELD WIPER CONVERTER							Component ATA:30
PN:XW203453421082L	MOS/MSC	11-Jul-95	O/C					
SN:00021	HRS	0		TSN 0				
WC#: 30.120	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304126	COPILOT WINDSHIELD WIPER CONVERTER							Component ATA:30
PN:XW203453421082R	MOS/MSC	11-Jul-95	O/C					
SN:00026	HRS	0		TSN 0				
WC#: 30.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304131	PILOT WINDSHIELD FLEXIBLE DRIVE							Component ATA:30
PN:4172396	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.120	AFL	0						
PROC. REF: AMM 56-10-01-900-801PROC. REF: AMM 56-10-01-900-801								
304136	COPILOT WINDSHIELD FLEXIBLE DRIVE							Component ATA:30
PN:4172396	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.130	AFL	0						
PROC. REF: AMM 56-10-01-900-801PROC. REF: AMM 56-10-01-900-801								
304141	PILOT WINDSHIELD WIPER ARM							Component ATA:30
PN:4011316	MOS/MSC	11-Jul-95	O/C					
SN:NONE	HRS	0		TSN 0				
WC#: 30.120	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304146	COPILOT WINDSHIELD WIPER ARM							Component ATA:30
PN:4011323	MOS/MSC	11-Jul-95	O/C					
SN:NONE	HRS	0		TSN 0				
WC#: 30.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304156	PILOT FRONT WINDSHIELD HEATER REGULATOR							Component ATA:30
PN:HYLZ50426-1	MOS/MSC	11-Jul-95	O/C					
SN:931D	HRS	0		TSN 0				
WC#: 30.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304161	COPILOT FRONT WINDSHIELD HEATER REGULATOR							Component ATA:30
PN:HYLZ50426-1	MOS/MSC	11-Jul-95	O/C					
SN:932D	HRS	0		TSN 0				
WC#: 30.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304166	PILOT SIDE WINDSHIELD HEATER REGULATOR							Component ATA:30
PN:HYLZ50422	MOS/MSC	11-Jul-95	O/C					
SN:1192D	HRS	0		TSN 0				
WC#: 30.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304171	COPILOT SIDE WINDSHIELD HEATER REGULATOR							Component ATA:30
PN:HYLZ50422	MOS/MSC	11-Jul-95	O/C					
SN:1193D	HRS	0		TSN 0				
WC#: 30.150	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304181	LH WIPER PARKING POSITION RESISTOR							Component ATA:30
PN:24-450	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304186	WINDSHIELD DE-MIST BLOWER							Component ATA:30
PN:125XS01-62-001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304191	DE-MIST CIRCUIT THERMAL FUSE							Component ATA:30
PN:4257A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.170	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304196	DE-MIST CIRCUIT RESISTOR							Component ATA:30
PN:505-0087	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304201	DE-MIST CIRCUIT THERMOSTAT							Component ATA:30
PN:M1-140-120-182	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304209	DE-MIST CIRCUIT SPEED SELECTOR							Component ATA:30
PN:319-100-01	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.180	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304211	LH DESSICANT BOTTLE							Component ATA:30
PN:210-90-17-68601	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.190	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304221	RH DESSICANT BOTTLE							Component ATA:30
PN:210-90-17-68601	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.190	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
304241	OUTSIDE AIR TEMPERATURE PROBE							Component ATA:30
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.200	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-21-05-960-801-01	REPLACEMENT OF THE PILOT CLOCK BATTERIES - LH PILOT CLOCK (93D) BATTERY							Service ATA:31
PN:811-BATT-1	MOS	02-Oct-24	25		02-Nov-26		24 d	SCRAP
SN:NSN	HRS	6601.6						
WC#: 31.010	AFL	3875						
PROC. REF: AMM 31-21-05-960-801	PROC. REF: AMM 31-21-05-960-801							
31-21-05-960-801-02	REPLACEMENT OF THE PILOT CLOCK BATTERIES - RH PILOT CLOCK (103D) BATTERY							Service ATA:31
PN:811-BATT-1	MOS	02-Oct-24	25		02-Nov-26		24 d	SCRAP
SN:NSN	HRS	6601.6						
WC#: 31.010	AFL	3875						
PROC. REF: AMM 31-21-05-960-801	PROC. REF: AMM 31-21-05-960-801							
31-31-00-710-802-01 S	OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) SYSTEM							Service ATA:31
	MOS	08-Dec-23	36 (+1m)					
	HRS	6529.1						
WC#: 31.090	AFL	3833						
								PKG:208
PROC. REF: AMM 31-31-00-710-802	PROC. REF: AMM 31-31-00-710-802							
31-31-00-720-803-01	FUNCTIONAL TEST OF THE 32-PARAMETER FDR - FDR (2FZ)							Service ATA:31
PN:S703-1000-00	MOS/MSC		N/A					
SN:000265602	HRS							
WC#: 31.090	AFL							
PROC. REF: AMM 31-31-00-720-803	PROC. REF: AMM 31-31-00-720-803							
31-31-00-970-801-01	DOWNLOAD OF THE FLIGHT DATA RECORDER (FDR) - FDR (130FZ) OR (701FZ)							Service ATA:31
PN:S703-1000-00	MOS	24-Oct-25	12		24-Oct-26		15 d	
SN:000265602	HRS	6700.5						
WC#: 31.190	AFL	3940						
PROC. REF: AMM 31-31-00-970-801	PROC. REF: AMM 31-31-00-970-801							
31-31-09-710-801-01	OPERATIONAL TEST DIGITAL FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT							Service ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C					NOT INSTALLED
SN:UNKNOWN	HRS	0						
WC#: 31.130	AFL	0						
PROC. REF: AMM 31-31-09-710-801	PROC. REF: AMM 31-31-09-710-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-09-710-801-01	OPERATIONAL TEST OF THE FDR/CVR ACCELERATION CONTACTS - ACCELERATION CONTACT (4RK)							Service ATA:31
PN:400-10B	MOS	13-Dec-11	240 (+3%)		13-Dec-31	19-Jul-32	1891 d (+219)	
SN:UNKNOWN	HRS	3892						
WC#: 31.120	AFL							
PROC. REF: AMM 31-31-09-710-801	PROC. REF: AMM 31-31-09-710-801							
31-31-09-900-801-01	DIGITAL FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT							Component ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.130	AFL	0		TSN 0				
PROC. REF: AMM 31-31-09-900-801	PROC. REF: AMM 31-31-09-900-801							
31-31-09-900-801-01	REMOVAL / INSTALLATION OF THE FDR/CVR ACCELERATION CONTACTS - ACCELERATION CONTACT (4RK)							Component ATA:31
PN:400-10B	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.120	AFL	0		TSN 0				
PROC. REF: AMM 31-31-09-900-801	PROC. REF: AMM 31-31-09-900-801							
31-31-50-710-801-01 S	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) SYSTEM - CVR (10FZ)							Service ATA:31
	MOS	08-Dec-23	36 (+1m)					
	HRS	6529.1						
WC#: 31.080	AFL	3833						
								PKG:208
PROC. REF: AMM 31-31-50-710-801	PROC. REF: AMM 31-31-50-710-801							
31-31-50-970-801-01	DOWNLOAD OF THE COCKPIT VOICE RECORDER (CVR) - CVR (2RK)							Service ATA:31
PN:S703-1000-00	MOS/MSC	15-Jul-96	O/C					
SN:000265602	HRS	0						
	AFL	0						
PROC. REF: AMM 31-31-50-970-801	PROC. REF: AMM 31-31-50-970-801							
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER							Component ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.140	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-32-05-960-801-01	REPLACEMENT QUICK ACCESS (QAR) RECORDER BATTERY							Service ATA:31
PN:PN	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
WC#: 31.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
31-52-00-710-801-01	OPERATIONAL TEST OF THE WARNING PANEL DUAL POWER SUPPLY - WARNING PANEL (32W)							Service ATA:31
	MOS	25-May-17						
	HRS	5157.3	2400 (+30)		7557.3	7587.3	765 (+30)	
	AFL	3249						
PROC. REF: AMM 31-52-00-710-801PROC. REF: AMM 31-52-00-710-801								
31-54-00-720-802-01 S	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST - ALARM TEST							Service ATA:31
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 31.040	AFL	3569						
								PKG:21
PROC. REF: AMM 31-54-00-720-802PROC. REF: AMM 31-54-00-720-802								
31-54-00-720-802-02 S	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST - TEST OF INDICATION LOGIC							Service ATA:31
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 31-54-00-720-802PROC. REF: AMM 31-54-00-720-802								
31-55-00-720-801-01 S	FUNCTIONAL TEST OF THE LANDING SAFETIES							Service ATA:31
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 31.050	AFL	3569						
								PKG:21
PROC. REF: AMM 31-55-00-720-801PROC. REF: AMM 31-55-00-720-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-60-51-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 1 (10EA)							Component ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.170	AFL	0		TSN 0				
PROC. REF: AMM 31-60-51-900-801	PROC. REF: AMM 31-60-51-900-801							
31-60-51-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 2 (20EA)							Component ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.170	AFL	0		TSN 0				
PROC. REF: AMM 31-60-51-900-801	PROC. REF: AMM 31-60-51-900-801							
31-60-51-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) - EIED 3 (30EA)							Component ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.170	AFL	0		TSN 0				
PROC. REF: AMM 31-60-51-900-801	PROC. REF: AMM 31-60-51-900-801							
310001	WARNING PANEL							Component ATA:31
PN:FE950-1	MOS/MSC	24-Jul-08	O/C					
SN:0157	HRS	3036.1						
WC#: 39.010	AFL	2036						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
310006	ELECTRONIC PANEL							Component ATA:31
PN:203TS04Y01	MOS/MSC	11-Jul-95	O/C					
SN:621	HRS	0		TSN 0				
WC#: 39.010	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
310009	HYDRAULIC PANEL							Component ATA:31
PN:694TS03Y01SE	MOS/MSC	11-Jul-95	O/C					
SN:366	HRS	0		TSN 0				
WC#: 39.010	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
312001	PILOT CLOCK BATTERY							Component ATA:31
PN:811-BATT-1	MOS/MSC	02-Oct-24	H/T	TSN 0				
SN:NSN	HRS	6601.6		TSN 0				
WC#: 31.010	AFL	3875		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
312006	COPILOT CLOCK BATTERY							Component ATA:31
PN:811-BATT-1	MOS/MSC	02-Oct-24	H/T	TSN 0				
SN:NSN	HRS	6601.6		TSN 0				
WC#: 31.010	AFL	3875		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
312011	GROUND PROXIMITY WARNING SYSTEM COMPUTER							Component ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.150	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
312016	GROUND PROXIMITY WARNING SYSTEM INVERTER							Component ATA:31
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.160	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
312801 U	PILOT CLOCK							Component ATA:31
PN:811BFTR24HR	MOS/MSC	20-Dec-06	O/C	TSN 0				
SN:37975	HRS	2522.08		TSN 0				
	AFL	1744		TSN 0				
312803 U	COPILOT CLOCK							Component ATA:31
PN:81BFTR24HR	MOS/MSC	20-Dec-06	O/C	TSN 0				
SN:37970	HRS	2522.08		TSN 0				
	AFL	1744		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
313146 U	CVR MICROPHONE							Component ATA:31
PN:93A055-60	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:000394899	HRS	3036.1		TSN 0				
	AFL	2036		TSN 0				
314001 U	GPWS COMPUTER							Component ATA:31
PN:965-0676-011	MOS/MSC	17-Jul-96	O/C					
SN:2647	HRS	150						
	AFL	62						
315101	AUDIO WARNING UNIT							Component ATA:31
PN:164ZS01Y01	MOS/MSC	11-Jul-95	O/C					
SN:513	HRS	0		TSN 0				
WC#: 31.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
315111	TAKE OFF WARNING PRINTED CARD							Component ATA:31
PN:CI820A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 31.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316001	COCKPIT VOICE RECORDER							Component ATA:31
PN:S703-1000-00	MOS/MSC	25-May-17	O/C	TSN 157				
SN:000265602	HRS	5157.3		TSN 3147.5				
WC#: 31.080	AFL	3249		TSN 1827				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316008	COCKPIT VOICE RECORDER CONTROL							Component ATA:31
PN:93-A152-20	MOS/MSC	17-Jul-96	O/C					
SN:76203	HRS	150						
WC#: 31.070	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316021		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON						Component ATA:31
PN:DK120/90	MOS/MSC	04-Apr-24	O/C	TSN 51				
SN:AT145745	HRS	6550		TSN 607.4				
WC#: 31.100	AFL	3849		TSN 280				
PROC. REF: AMM 25-62-00-900-801	PROC. REF: AMM 25-62-00-900-801							
316051		FLIGHT DATA RECORDER						Component ATA:31
PN:S703-1000-00	MOS/MSC	11-Aug-20	O/C					
SN:000265602	HRS	5942.6						
WC#: 31.090	AFL	3569						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
316071		FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON						Component ATA:31
PN:DK120	MOS/MSC	31-Aug-16	O/C	TSO 0				
SN:SC77319	HRS	5106.6		TSO 0				
WC#: 31.110	AFL	3227		TSO 0				
PROC. REF: AMM 25-62-00-900-801	PROC. REF: AMM 25-62-00-900-801							
ATA 32 - LANDING GEAR								
32-00-00-700-801-01 S		CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13G)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.940	AFL	3569						
								PKG:21
PROC. REF: AMM 32-00-00-700-801	PROC. REF: AMM 32-00-00-700-801							
32-00-00-700-801-02 S		CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (7G1)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500					
WC#: 32.940	AFL	3569						
								PKG:21
PROC. REF: AMM 32-00-00-700-801	PROC. REF: AMM 32-00-00-700-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-00-00-700-801-03 S	CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (7G2)							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500					
WC#: 32.940	AFL	3569						
								PKG:21
PROC. REF: AMM 32-00-00-700-801 PROC. REF: AMM 32-00-00-700-801								
32-10-00-640-801-01	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND MLG DOORS							Service ATA:32
	MOS	17-Apr-26	6 (+1m)		17-Oct-26	17-Nov-26	8 d (+31)	
	HRS	6746.8						
	AFL	3979	400		4379		369	
PROC. REF: AMM 32-10-00-640-801 PROC. REF: AMM 32-10-00-640-801								
32-10-00-640-801-02	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND MLG DOORS							Service ATA:32
	MOS	17-Apr-26	6 (+1m)		17-Oct-26	17-Nov-26	8 d (+31)	
	HRS	6746.8						
	AFL	3979	400		4379		369	
PROC. REF: AMM 32-10-00-640-801 PROC. REF: AMM 32-10-00-640-801								
32-11-00-220-801-01	DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF)							Service ATA:32
PN:C23791-1012	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
SN:U63	HRS	5942.6						
WC#: 32.930	AFL	3569						
PROC. REF: AMM 32-11-00-220-801 PROC. REF: AMM 32-11-00-220-801								
32-11-00-220-801-01C	DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF) (CPCP)							Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	CPCP
	HRS	5942.6						
WC#: 32.015	AFL	3569						
PROC. REF: AMM 32-11-00-220-801 PROC. REF: AMM 32-11-00-220-801								
32-11-00-220-801-02	DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF)							Service ATA:32
PN:C23792-1012	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
SN:U239	HRS	5942.6						
WC#: 32.930	AFL	3569						
PROC. REF: AMM 32-11-00-220-801 PROC. REF: AMM 32-11-00-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-220-801-02C	DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF) (CPCP)						Service	ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	CPCP
	HRS	5942.6						
WC#: 32.015	AFL	3569						
PROC. REF: AMM 32-11-00-220-801	PROC. REF: AMM 32-11-00-220-801							
32-11-00-350-801-01	RESTORATION OF THE MLG LEGS (OVERHAUL) - LH MLG LEG (L2GF)						Service	ATA:32
PN:C23791-1012	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	OVERHAUL
SN:U63	HRS	5942.6						
	AFL	3569	6000		9569		5559	
PROC. REF: AMM 32-11-00-350-801	PROC. REF: AMM 32-11-00-350-801							
32-11-00-350-801-02	RESTORATION OF THE MLG LEGS (OVERHAUL) - RH MLG LEG (R2GF)						Service	ATA:32
PN:C23792-1012	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	OVERHAUL
SN:U239	HRS	5942.6						
	AFL	3569	6000		9569		5559	
PROC. REF: AMM 32-11-00-350-801	PROC. REF: AMM 32-11-00-350-801							
32-11-00-700-801-01	CHECK OF THE MLG LEG GRAVITY OSCILLATIONS - LH MLG LEG (L2GF)						Service	ATA:32
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 32.130	AFL	0						
PROC. REF: AMM 32-11-00-700-801	PROC. REF: AMM 32-11-00-700-801							
32-11-00-700-801-02	CHECK OF THE MLG LEG GRAVITY OSCILLATIONS - RH MLG LEG (R2GF)						Service	ATA:32
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 32.130	AFL	0						
PROC. REF: AMM 32-11-00-700-801	PROC. REF: AMM 32-11-00-700-801							
32-11-00-900-801-01	REMOVAL / INSTALLATION OF THE MLG LEGS - LH MLG LEG (L2GF)						Component	ATA:32
PN:C23791-1012	MOS/MSC	11-Aug-20	H/T	TSO 0				
SN:U63	HRS	5942.6		TSO 0				
WC#: 32.010	AFL	3569		TSO 0				
PROC. REF: AMM 32-11-00-900-801	PROC. REF: AMM 32-11-00-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-00-900-801-02	REMOVAL / INSTALLATION OF THE MLG LEGS - RH MLG LEG (R2GF)							Component ATA:32
PN:C23792-1012	MOS/MSC	11-Aug-20	H/T	TSO 0				
SN:U239	HRS	5942.6		TSO 0				
WC#: 32.010	AFL	3569		TSO 0				
PROC. REF: AMM 32-11-00-900-801	PROC. REF: AMM 32-11-00-900-801							
32-11-00-960-801-01	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - LH MLG LEG (L2GF)							Service ATA:32
PN:C23791-1012	MOS	11-Aug-20						LIFE LIMIT
SN:U63	HRS							
WC#: 32.010	AFL	3569	20000	TAC 3569	20000		15990	
PROC. REF: AMM 32-11-00-960-801	PROC. REF: AMM 32-11-00-960-801							
32-11-00-960-801-01A	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)							Service ATA:32
PN:C23791-1012	MOS	11-Aug-20						MANDATORY 5-40
SN:U63	HRS							
	AFL	3569	20000	TAC 3569	20000		15990	
PROC. REF: AMM 32-11-00-960-801	PROC. REF: AMM 32-11-00-960-801							
32-11-00-960-801-02	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - RH MLG LEG (R2GF)							Service ATA:32
PN:C23792-1012	MOS	11-Aug-20						LIFE LIMIT
SN:U239	HRS	5942.6						
WC#: 32.010	AFL	3569	20000	TAC 1533	22036		18026	
PROC. REF: AMM 32-11-00-960-801	PROC. REF: AMM 32-11-00-960-801							
32-11-00-960-801-02A	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)							Service ATA:32
PN:C23792-1012	MOS	11-Aug-20						MANDATORY 5-40
SN:U239	HRS	5942.6						
	AFL	3569	20000	TAC 1533	22036		18026	
PROC. REF: AMM 32-11-00-960-801	PROC. REF: AMM 32-11-00-960-801							
32-11-03-960-801-01	DISCARD OF THE MLG PINTLE PIN - LH MLG PINTLE PIN (L2GF7)							Service ATA:32
PN:D52554-1	MOS	15-Jul-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.060	AFL	0	18670		18670		14660	
PROC. REF: AMM 32-11-03-960-801	PROC. REF: AMM 32-11-03-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-03-960-801-01A	DISCARD LH REAR MAIN LANDING GEAR (MLG) PINTLE PIN (MANDATORY 5-40)							Service ATA:32
PN:D52554-1	MOS	15-Jul-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	AFL	0	18670		18670		14660	
PROC. REF: AMM 32-11-03-960-801	PROC. REF: AMM 32-11-03-960-801							
32-11-03-960-801-02	DISCARD OF THE MLG PINTLE PIN - RH MLG PINTLE PIN (R2GF7)							Service ATA:32
PN:D52554-1	MOS	15-Jul-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.060	AFL	0	18670		18670		14660	
PROC. REF: AMM 32-11-03-960-801	PROC. REF: AMM 32-11-03-960-801							
32-11-03-960-801-02A	DISCARD RH REAR MAIN LANDING GEAR (MLG) PINTLE PIN (MANDATORY 5-40)							Service ATA:32
PN:D52554-1	MOS	15-Jul-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	AFL	0	18670		18670		14660	
PROC. REF: AMM 32-11-03-960-801	PROC. REF: AMM 32-11-03-960-801							
32-11-05-350-801-01	RESTORATION OF THE MLG SHOCK ABSORBER (DISCARD OF END-FITTING) - LH MLG SHOCK ABSORBER (L2GF5)							Service ATA:32
PN:D50493	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-05-350-801	PROC. REF: AMM 32-11-05-350-801							
32-11-05-350-801-01A	RESTORATION LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) (MANDATORY 5-40)							Service ATA:32
PN:D50493	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
WC#: 32.020	AFL	0						
PROC. REF: AMM 32-11-05-350-801	PROC. REF: AMM 32-11-05-350-801							
32-11-05-350-801-02	RESTORATION OF THE MLG SHOCK ABSORBER (DISCARD OF END-FITTING) - RH MLG SHOCK ABSORBER (R2GF5)							Service ATA:32
PN:D50493	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-05-350-801	PROC. REF: AMM 32-11-05-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-05-350-801-02A	RESTORATION RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) (MANDATORY 5-40)							Service ATA:32
PN:D50493	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
WC#: 32.030	AFL	0						
PROC. REF: AMM 32-11-05-350-801	PROC. REF: AMM 32-11-05-350-801							
32-11-05-780-801-01 S	CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.020	AFL	3569						
								PKG:21
PROC. REF: AMM 32-11-05-780-801	PROC. REF: AMM 32-11-05-780-801							
32-11-05-780-801-02 S	CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.030	AFL	3569						
								PKG:21
PROC. REF: AMM 32-11-05-780-801	PROC. REF: AMM 32-11-05-780-801							
32-11-05-900-801-01	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)							Component ATA:32
PN:C23795-1004	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 10				
SN:UNKNOWN	HRS	0						
WC#: 32.020	AFL	0		TSN 0				
PROC. REF: AMM 32-11-05-900-801	PROC. REF: AMM 32-11-05-900-801							
32-11-05-900-801-02	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)							Component ATA:32
PN:C23796-1004	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 10				
SN:UNKNOWN	HRS	0						
WC#: 32.030	AFL	0		TSN 0				
PROC. REF: AMM 32-11-05-900-801	PROC. REF: AMM 32-11-05-900-801							
32-11-21-350-801-01	RESTORATION OF THE MLG BRACE ACTUATOR (DISCARD OF DASH-POT FITTING) - LH MLG BRACE STRUT ACTUATOR (12G1)							Service ATA:32
PN:D52369	MOS	15-Jul-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.040	AFL	0	20000		20000		15990	
PROC. REF: AMM 32-11-21-350-801	PROC. REF: AMM 32-11-21-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-21-350-801-01A	RESTORATION LH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)(MANDATORY 5-40)							Service ATA:32
PN:D52369	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-21-350-801	PROC. REF: AMM 32-11-21-350-801							
32-11-21-350-801-02	RESTORATION OF THE MLG BRACE ACTUATOR (DISCARD OF DASH-POT FITTING) - RH MLG BRACE STRUT ACTUATOR (12G2)							Service ATA:32
PN:D52369	MOS	15-Jul-96						LIFE LIMIT
SN:UNKNOWN	HRS	0						
WC#: 32.050	AFL	0	20000		20000		15990	
PROC. REF: AMM 32-11-21-350-801	PROC. REF: AMM 32-11-21-350-801							
32-11-21-350-801-02A	RESTORATION RH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)(MANDATORY 5-40)							Service ATA:32
PN:D52369	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-21-350-801	PROC. REF: AMM 32-11-21-350-801							
32-11-21-900-801-01	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - LH MLG BRACE STRUT ACTUATOR (12G1)							Component ATA:32
PN:C23925-1104	MOS/MSC	08-Mar-12	O/C	TSO 0				
SN:B5	HRS	3996		TSO 0				
WC#: 32.040	AFL	2577		TSO 0				
PROC. REF: AMM 32-11-21-900-801	PROC. REF: AMM 32-11-21-900-801							
32-11-21-900-801-02	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - RH MLG BRACE STRUT ACTUATOR (12G2)							Component ATA:32
PN:C23926-1103	MOS/MSC	11-Jul-95	O/C					
SN:B65	HRS	0		TSN 0				
WC#: 32.050	AFL	0						
PROC. REF: AMM 32-11-21-900-801	PROC. REF: AMM 32-11-21-900-801							
32-11-25-220-801-01	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)							Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-11-25-220-801	PROC. REF: AMM 32-11-25-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-25-220-801-02	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)							Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-11-25-220-801	PROC. REF: AMM 32-11-25-220-801							
32-11-25-220-801-03	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)							Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-11-25-220-801	PROC. REF: AMM 32-11-25-220-801							
32-11-25-220-801-04	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)							Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-11-25-220-801	PROC. REF: AMM 32-11-25-220-801							
32-11-25-900-801-01	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG FRONT BALL-JOINT BEARING (L90GA)							Component ATA:32
PN:BRS50RTGSP6	MOS/MSC	08-May-14	O/C					
SN:UNKNOWN	HRS	4694.25		TSN 4694.25				
WC#: 32.120	AFL	2957						
PROC. REF: AMM 32-11-25-900-801	PROC. REF: AMM 32-11-25-900-801							
32-11-25-900-801-02	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG REAR BALL-JOINT BEARING (L100GA)							Component ATA:32
PN:BRS55TAGSP2	MOS/MSC	08-May-14	O/C					
SN:UNKNOWN	HRS	4694.25		TSN 4694.25				
WC#: 32.060	AFL	2957						
PROC. REF: AMM 32-11-25-900-801	PROC. REF: AMM 32-11-25-900-801							
32-11-25-900-801-03	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG FRONT BALL-JOINT BEARING (R90GA)							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	11-Aug-20	O/C	TSN 0				
SN:UNKNOWN	HRS	5942.6		TSN 0				
WC#: 32.120	AFL	3569		TSN 0				
PROC. REF: AMM 32-11-25-900-801	PROC. REF: AMM 32-11-25-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-25-900-801-04	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG REAR BALL-JOINT BEARING (R100GA)							Component ATA:32
PN:BRS55TAGSP2	MOS/MSC	08-May-14	O/C					
SN:UNKNOWN	HRS	4694.25		TSN 4694.25				
WC#: 32.070	AFL	2957						
PROC. REF: AMM 32-11-25-900-801	PROC. REF: AMM 32-11-25-900-801							
32-12-17-900-801-01	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - LH MLG UPLOCK BOX (7G1)							Component ATA:32
PN:C24244-0-1	MOS/MSC	11-Jul-95	O/C					
SN:U429	HRS	0		TSN 0				
WC#: 32.310	AFL	0						
PROC. REF: AMM 32-12-17-900-801	PROC. REF: AMM 32-12-17-900-801							
32-12-17-900-801-02	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - RH MLG UPLOCK BOX (7G2)							Component ATA:32
PN:C24245-0-1	MOS/MSC	11-Jul-95	O/C					
SN:U807	HRS	0		TSN 0				
WC#: 32.310	AFL	0						
PROC. REF: AMM 32-12-17-900-801	PROC. REF: AMM 32-12-17-900-801							
32-12-25-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - LH MLG MAIN DOOR ACTUATOR (6G1)							Component ATA:32
PN:C23735-1101	MOS/MSC	11-Jul-95	O/C					
SN:B41	HRS	0		TSN 0				
WC#: 32.090	AFL	0						
PROC. REF: AMM 32-12-25-900-801	PROC. REF: AMM 32-12-25-900-801							
32-12-25-900-801-02	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - RH MLG MAIN DOOR ACTUATOR (6G2)							Component ATA:32
PN:C23736-1101	MOS/MSC	11-Jul-95	O/C					
SN:B34	HRS	0		TSN 0				
WC#: 32.090	AFL	0						
PROC. REF: AMM 32-12-25-900-801	PROC. REF: AMM 32-12-25-900-801							
32-12-29-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - LH MLG MAIN DOOR UPLOCK BOX (14G1)							Component ATA:32
PN:C24257-1-4	MOS/MSC	14-Feb-11	O/C	TSR 8				
SN:U198	HRS	3653.6						
WC#: 32.320	AFL	2403						
PROC. REF: AMM 32-12-29-900-801	PROC. REF: AMM 32-12-29-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-12-29-900-801-02	REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - RH MLG MAIN DOOR UPLOCK BOX (14G2)							Component ATA:32
PN:C24257-1-3	MOS/MSC	11-Jul-95	O/C					
SN:U928	HRS	0		TSN 0				
WC#: 32.320	AFL	0						
PROC. REF: AMM 32-12-29-900-801	PROC. REF: AMM 32-12-29-900-801							
32-20-00-640-801-01	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG AND NLG DOORS							Service ATA:32
	MOS	17-Apr-26	6 (+1m)		17-Oct-26	17-Nov-26	8 d (+31)	
	HRS	6746.8						
WC#: 32.290	AFL	3979	400		4379		369	
PROC. REF: AMM 32-20-00-640-801	PROC. REF: AMM 32-20-00-640-801							
32-20-00-640-801-02	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG SLIDING ROD LOWER BEARING							Service ATA:32
	MOS/MSC	11-Aug-20	N/A					
	HRS	5942.6						
WC#: 32.300	AFL	3569						
PROC. REF: AMM 32-20-00-640-801	PROC. REF: AMM 32-20-00-640-801							
32-21-00-220-801-01	DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF)							Service ATA:32
PN:C23787-1010	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
SN:U263	HRS	5942.6						
WC#: 32.920	AFL	3569						
PROC. REF: AMM 32-21-00-220-801	PROC. REF: AMM 32-21-00-220-801							
32-21-00-220-801-01C	DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF) (CPCP)							Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	CPCP
	HRS	5942.6						
WC#: 32.025	AFL	3569						
PROC. REF: AMM 32-21-00-220-801	PROC. REF: AMM 32-21-00-220-801							
32-21-00-350-801-01	RESTORATION OF THE NLG LEG (OVERHAUL) - NLG LEG (3GF)							Service ATA:32
PN:C23787-1010	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	OVERHAUL
SN:U263	HRS	5942.6						
	AFL	3569	6000		9569		5559	
PROC. REF: AMM 32-21-00-350-801	PROC. REF: AMM 32-21-00-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-00-700-801-01	CHECK OF THE NLG LEG GRAVITY OSCILLATIONS - NLG LEG (3GF)							Service ATA:32
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 32.270	AFL	0						
PROC. REF: AMM 32-21-00-700-801	PROC. REF: AMM 32-21-00-700-801							
32-21-00-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG - NLG LEG (3GF)							Component ATA:32
PN:C23787-1010	MOS/MSC	11-Aug-20	H/T	TSO 0				
SN:U263	HRS	5942.6		TSO 0				
WC#: 32.180	AFL	3569		TSO 0				
PROC. REF: AMM 32-21-00-900-801	PROC. REF: AMM 32-21-00-900-801							
32-21-00-960-801-01	REPLACEMENT OF THE NLG LEG (DISCARD OF LIFE LIMITED PARTS) - NLG LEG (3GF)							Service ATA:32
PN:C23787-1010	MOS	11-Aug-20						LIFE LIMIT
SN:U263	HRS	5942.6						
WC#: 32.180	AFL	3569	20000	TAC 1533	22036		18026	
PROC. REF: AMM 32-21-00-960-801	PROC. REF: AMM 32-21-00-960-801							
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)							Service ATA:32
PN:C23787-1010	MOS	11-Aug-20						MANDATORY 5-40
SN:U263	HRS	5942.6						
	AFL	3569	20000	TAC 1533	22036		18026	
PROC. REF: AMM 32-21-00-960-801	PROC. REF: AMM 32-21-00-960-801							
32-21-01-610-801-01	SERVICING OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)							Service ATA:32
PN:C23789-1002	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS	3036.1						
	AFL	2036						
PROC. REF: AMM 32-21-01-610-801	PROC. REF: AMM 32-21-01-610-801							
32-21-01-610-802-01	CHARGING OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)							Service ATA:32
PN:C23789-1002	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS	3036.1						
	AFL	2036						
PROC. REF: AMM 32-21-01-610-802	PROC. REF: AMM 32-21-01-610-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-01-780-801-01	S	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.190	AFL	3569						
								PKG:21
PROC. REF: AMM 32-21-01-780-801	PROC. REF: AMM 32-21-01-780-801							
32-21-01-900-801-01		REMOVAL / INSTALLATION OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)						Component ATA:32
PN:C23789-1002	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 10				
SN:UNKNOWN	HRS	0						
WC#: 32.190	AFL	0		TSN 0				
PROC. REF: AMM 32-21-01-900-801	PROC. REF: AMM 32-21-01-900-801							
32-21-09-220-801-01		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING						Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-21-09-220-801	PROC. REF: AMM 32-21-09-220-801							
32-21-09-220-801-02		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING						Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-21-09-220-801	PROC. REF: AMM 32-21-09-220-801							
32-21-09-220-801-03		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING						Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-21-09-220-801	PROC. REF: AMM 32-21-09-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-09-220-801-04	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING							Service ATA:32
	MOS	11-Aug-20	72 (+8m)		11-Aug-26	11-Apr-27	TOL (+184 d)	
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-21-09-220-801	PROC. REF: AMM 32-21-09-220-801							
32-21-09-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG DRAG BRACE BALL-JOINT BEARING							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	11-Aug-20	O/C					
SN:UNKNOWN	HRS	5942.6						
WC#: 32.250	AFL	3569						
PROC. REF: AMM 32-21-09-900-801	PROC. REF: AMM 32-21-09-900-801							
32-21-09-900-801-02	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG DRAG BRACE BALL-JOINT BEARING							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	11-Aug-20	O/C					
SN:UNKNOWN	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 32-21-09-900-801	PROC. REF: AMM 32-21-09-900-801							
32-21-09-900-801-03	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG LEG BALL-JOINT BEARING							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	11-Aug-20	O/C	TSN 0				
SN:UNKNOWN	HRS	5942.6		TSN 0				
WC#: 32.240	AFL	3569		TSN 0				
PROC. REF: AMM 32-21-09-900-801	PROC. REF: AMM 32-21-09-900-801							
32-21-09-900-801-04	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG LEG BALL-JOINT BEARING							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	11-Aug-20	O/C					
SN:UNKNOWN	HRS	5942.6						
WC#: 32.240	AFL	3569						
PROC. REF: AMM 32-21-09-900-801	PROC. REF: AMM 32-21-09-900-801							
32-22-01-350-801-01	RESTORATION OF THE NLG DRAG BRACE YOKE ASSY (OVERHAUL) - NLG DRAG BRACE (11G)							Service ATA:32
PN:GA58346	MOS	11-Aug-20	144 (+5m)		11-Aug-32	11-Jan-33	2133 d (+153)	OVERHAUL
SN:319	HRS	5942.6						
WC#: 32.210	AFL	3569	6000		9569		5559	
PROC. REF: AMM 32-22-01-350-801	PROC. REF: AMM 32-22-01-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-22-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG DRAG BRACE - NLG DRAG BRACE (11G)							Component ATA:32
PN:C23811-11	MOS/MSC	11-Aug-20	O/C	TSO 145				
SN:B39	HRS	5942.6		TSO 2906.5				
WC#: 32.210	AFL	3569		TSO 1533				
PROC. REF: AMM 32-22-01-900-801	PROC. REF: AMM 32-22-01-900-801							
32-22-13-900-801-01	REMOVAL / INSTALLATION OF THE NLG ACTUATOR - NLG LEG ACTUATOR (500GA)							Component ATA:32
PN:C23810-10-1	MOS/MSC	11-Jul-95	O/C					
SN:B50	HRS	0		TSN 0				
WC#: 32.200	AFL	0						
PROC. REF: AMM 32-22-13-900-801	PROC. REF: AMM 32-22-13-900-801							
32-22-17-900-801-01	REMOVAL / INSTALLATION OF THE NLG UPLOCK BOX - NLG UPLOCK BOX (13G)							Component ATA:32
PN:C24245-4-1	MOS/MSC	11-Jul-95	O/C					
SN:U798	HRS	0		TSN 0				
WC#: 32.310	AFL	0						
PROC. REF: AMM 32-22-17-900-801	PROC. REF: AMM 32-22-17-900-801							
32-30-00-720-801-01 S	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - NORMAL OPERATION							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 32-30-00-720-801	PROC. REF: AMM 32-30-00-720-801							
32-30-00-720-801-02 S	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - HYDRAULIC EMERGENCY OPERATION							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 32-30-00-720-801	PROC. REF: AMM 32-30-00-720-801							
32-30-00-720-801-03 S	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - MECHANICAL EMERGENCY OPERATION							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-30-00-720-801	PROC. REF: AMM 32-30-00-720-801							
32-30-13-900-801-01		REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY SELECTOR VALVE - L/G NORMAL/EMERGENCY SELECTOR VALVE (3G)						Component ATA:32
PN:B94B09-202-1	MOS/MSC	11-Jul-95	O/C					
SN:20239	HRS	0		TSN 0				
WC#: 32.370	AFL	0						
PROC. REF: AMM 32-30-13-900-801	PROC. REF: AMM 32-30-13-900-801							
32-31-00-700-801-01	S	CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.450	AFL	3569						
								PKG:21
PROC. REF: AMM 32-31-00-700-801	PROC. REF: AMM 32-31-00-700-801							
32-31-01-900-801-01		REMOVAL / INSTALLATION OF THE LANDING GEAR CONTROL LEVER - L/G CONTROL LEVER (2G)						Component ATA:32
PN:12-337-37	MOS/MSC	11-Jul-95	O/C					
SN:510	HRS	0		TSN 0				
WC#: 32.360	AFL	0						
PROC. REF: AMM 32-31-01-900-801	PROC. REF: AMM 32-31-01-900-801							
32-31-13-790-801-01	S	INTERNAL LEAK CHECK OF THE LANDING GEAR SOLENOID SELECTOR VALVE - L/G SOLENOID SELECTOR VALVE (9G)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.910	AFL	3569						
								PKG:21
PROC. REF: AMM 32-31-13-790-801	PROC. REF: AMM 32-31-13-790-801							
32-32-00-640-801-01	S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE NLG CONTROL						Service ATA:32
PN:PN	MOS	02-Oct-24	24 (+1m)					
SN:UNKNOWN	HRS	6601.6						
WC#: 32.430	AFL	3875						
								PKG:16
PROC. REF: AMM 32-32-00-640-801	PROC. REF: AMM 32-32-00-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-00-640-801-02 S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE NLG CONTROL ACTUATION FORCE							Service ATA:32
PN:PN	MOS	02-Oct-24	24 (+1m)					
SN:UNKNOWN	HRS	6601.6						
WC#: 32.430	AFL	3875						
								PKG:16
PROC. REF: AMM 32-32-00-640-801	PROC. REF: AMM 32-32-00-640-801							
32-32-00-640-801-03 S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE MLG CONTROLS							Service ATA:32
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 32.420	AFL	3875						
								PKG:16
PROC. REF: AMM 32-32-00-640-801	PROC. REF: AMM 32-32-00-640-801							
32-32-00-640-801-04 S	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE MLG CONTROL ACTUATION FORCE							Service ATA:32
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 32.420	AFL	3875						
								PKG:16
PROC. REF: AMM 32-32-00-640-801	PROC. REF: AMM 32-32-00-640-801							
32-32-00-700-801-01	CHECK AFTER LANDING GEAR EMERGENCY EXTENSION							Service ATA:32
	MOS/MSC	15-Jul-96	A/R					
	HRS	0						
WC#: 32.160	AFL	0						
PROC. REF: AMM 32-32-00-700-801	PROC. REF: AMM 32-32-00-700-801							
32-32-05-900-801-01	REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - LH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (L515GA)							Component ATA:32
PN:F50B796001110A4	MOS/MSC	24-May-10	O/C	TSN 0				
SN:2907	HRS	3546.83		TSN 0				
WC#: 32.420	AFL	2326		TSN 0				
PROC. REF: AMM 32-32-05-900-801	PROC. REF: AMM 32-32-05-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-32-05-900-801-02		REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - RH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (R515GA)						Component ATA:32
PN:F50B796001110	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.420	AFL	0						
PROC. REF: AMM 32-32-05-900-801	PROC. REF: AMM 32-32-05-900-801							
32-32-17-640-801-01 S		SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - LUBRICATION OF THE L/G HYDRAULIC EMERGENCY EXTENTION CONTROL						Service ATA:32
PN:F50B793001110A3	MOS	02-Oct-24	24 (+1m)					
SN:UNKNOWN	HRS	6601.6						
WC#: 32.350	AFL	3875						
								PKG:16
PROC. REF: AMM 32-32-17-640-801	PROC. REF: AMM 32-32-17-640-801							
32-32-17-640-801-02 S		SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - CHECK OF CONTROL ACTUATION LOADS						Service ATA:32
PN:F50B793001110A3	MOS	02-Oct-24	24 (+1m)					
SN:UNKNOWN	HRS	6601.6						
WC#: 32.350	AFL	3875						
								PKG:16
PROC. REF: AMM 32-32-17-640-801	PROC. REF: AMM 32-32-17-640-801							
32-32-17-900-801-01		REMOVAL / INSTALLATION OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE - L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE (504GA)						Component ATA:32
PN:F50B793001110A3	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.350	AFL	0						
PROC. REF: AMM 32-32-17-900-801	PROC. REF: AMM 32-32-17-900-801							
32-40-00-780-801-01 S		CHECK OF BRAKING PRESSURES - NORMAL BRAKING SYSTEM						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	3000 (+30)					
WC#: 32.710	AFL	3569						
								PKG:22
PROC. REF: AMM 32-40-00-780-801	PROC. REF: AMM 32-40-00-780-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-40-00-780-801-02	S	CHECK OF BRAKING PRESSURES - EMERGENCY BRAKING SYSTEM						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	3000 (+30)					
WC#: 32.710	AFL	3569						
								PKG:22
PROC. REF: AMM 32-40-00-780-801	PROC. REF: AMM 32-40-00-780-801							
32-41-00-720-802-01	S	FUNCTIONAL TEST OF THE ANTI-SKID SYSTEM						Service ATA:32
	MOS	23-Oct-13						
	HRS	4569.5	1500 (+30)					
WC#: 32.730	AFL	2879						
								PKG:21
PROC. REF: AMM 32-41-00-720-802	PROC. REF: AMM 32-41-00-720-802							
32-41-23-900-801-01		REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY BRAKE SELECTOR VALVE - NORMAL/EMERGENCY BRAKE SELECTOR VALVE (501GC)						Component ATA:32
PN:65670-1	MOS/MSC	11-Jul-95	O/C					
SN:1780	HRS	0		TSN 0				
WC#: 32.490	AFL	0						
PROC. REF: AMM 32-41-23-900-801	PROC. REF: AMM 32-41-23-900-801							
32-41-37-960-801-01	S	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - LH MLG BRAKE FILTER (L580GC)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.670	AFL	3569						
								PKG:21
PROC. REF: AMM 32-41-37-960-801	PROC. REF: AMM 32-41-37-960-801							
32-41-37-960-801-02	S	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - RH MLG BRAKE FILTER (R580GC)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.670	AFL	3569						
								PKG:21
PROC. REF: AMM 32-41-37-960-801	PROC. REF: AMM 32-41-37-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-45-900-801-01	REMOVAL / INSTALLATION OF THE ANTI-SKID CONTROL UNIT - ANTI-SKID CONTROL UNIT (52G)							Component ATA:32
PN:6002614-3	MOS/MSC	24-Jan-10	O/C	TSR 0				
SN:DEC01-0577	HRS			TSR 0				
WC#: 32.620	AFL			TSR 0				
PROC. REF: AMM 32-41-45-900-801	PROC. REF: AMM 32-41-45-900-801							
32-41-49-900-801-01	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (53G)							Component ATA:32
PN:9542653-1	MOS/MSC	11-Jul-95	O/C					
SN:AUG93-2997	HRS	0		TSN 0				
WC#: 32.630	AFL	0						
PROC. REF: AMM 32-41-49-900-801	PROC. REF: AMM 32-41-49-900-801							
32-41-49-900-801-02	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (55G)							Component ATA:32
PN:9542653-1	MOS/MSC	17-Jul-96	O/C					
SN:APR95-3007	HRS	150						
WC#: 32.630	AFL	62						
PROC. REF: AMM 32-41-49-900-801	PROC. REF: AMM 32-41-49-900-801							
32-41-49-900-801-03	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (56G)							Component ATA:32
PN:9542653-1	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:AUG93-2996	HRS	0		TSN 0				
WC#: 32.640	AFL	0		TSN 0				
PROC. REF: AMM 32-41-49-900-801	PROC. REF: AMM 32-41-49-900-801							
32-41-49-900-801-04	REMOVAL / INSTALLATION OF THE TACHOMETER GENERATORS - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (54G)							Component ATA:32
PN:9542653-1	MOS/MSC	17-Jul-96	O/C					
SN:SEP76-651	HRS	150		TSO 0				
WC#: 32.640	AFL	62						
PROC. REF: AMM 32-41-49-900-801	PROC. REF: AMM 32-41-49-900-801							
32-41-57-350-801-01	RESTORATION OF THE BRAKE SERVOVALVES (OVERHAUL) - LH MLG BRAKE SERVOVALVE (57G1)							Service ATA:32
PN:9542732-2	MOS	16-Mar-22	300 (+3%)		16-Mar-47	16-Dec-47	7463 d (+275)	OVERHAUL
SN:MAR82-1893D	HRS	6124.5						
WC#: 32.600	AFL	3681						
PROC. REF: AMM 32-41-57-350-801	PROC. REF: AMM 32-41-57-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-57-350-801-02		RESTORATION OF THE BRAKE SERVOVALVES (OVERHAUL) - RH MLG BRAKE SERVOVALVE (57G2)						Service ATA:32
PN:9542732-2	MOS	16-Mar-22	300 (+3%)		16-Mar-47	16-Dec-47	7463 d (+275)	OVERHAUL
SN:DEC99-2443D	HRS	6124.5						
WC#: 32.600	AFL	3681						
PROC. REF: AMM 32-41-57-350-801	PROC. REF: AMM 32-41-57-350-801							
32-41-57-900-801-01		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - LH MLG BRAKE SERVOVALVE (57G1)						Component ATA:32
PN:9542732-2	MOS/MSC	16-Mar-22	H/T	TSO 4				
SN:MAR82-1893D	HRS	6124.5		TSO 0				
WC#: 32.600	AFL	3681		TSO 0				
PROC. REF: AMM 32-41-57-900-801	PROC. REF: AMM 32-41-57-900-801							
32-41-57-900-801-02		REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - RH MLG BRAKE SERVOVALVE (57G2)						Component ATA:32
PN:9542732-2	MOS/MSC	16-Mar-22	H/T	TSR 47				
SN:DEC99-2443D	HRS	6124.5		TSR 0				
WC#: 32.600	AFL	3681		TSR 0				
PROC. REF: AMM 32-41-57-900-801	PROC. REF: AMM 32-41-57-900-801							
32-41-57-960-801-01 S		REPLACEMENT OF THE FILTER AND SEAL OF THE BRAKE SERVOVALVES - LH MLG BRAKE SERVOVALVE (57G1)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.600	AFL	3569						
								PKG:21
PROC. REF: AMM 32-41-57-960-801	PROC. REF: AMM 32-41-57-960-801							
32-41-57-960-801-02 S		REPLACEMENT OF THE FILTER AND SEAL OF THE BRAKE SERVOVALVES - RH MLG BRAKE SERVOVALVE (57G2)						Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.600	AFL	3569						
								PKG:21
PROC. REF: AMM 32-41-57-960-801	PROC. REF: AMM 32-41-57-960-801							
32-42-00-610-801-01		SERVICING OF THE PARK BRAKE CONTROL						Service ATA:32
PN:F50B794001A1	MOS/MSC	25-May-17	O/C					
SN:UNKNOWN	HRS	5157.3						
WC#: 32.590	AFL	3249						
PROC. REF: AMM 32-42-00-610-801	PROC. REF: AMM 32-42-00-610-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-42-00-720-801-01 S	FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - PARK BRAKE SYSTEM							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	3000					
	AFL	3569						
								PKG:22
PROC. REF: AMM 32-42-00-720-801PROC. REF: AMM 32-42-00-720-801								
32-42-01-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SELECTOR VALVE - PARK BRAKE SELECTOR VALVE (30GC)							Component ATA:32
PN:A24522-1	MOS/MSC	31-Dec-08	O/C	TSO 0				
SN:FM98	HRS	3204		TSO 0				
WC#: 32.480	AFL	2119		TSO 0				
PROC. REF: AMM 32-42-01-900-801PROC. REF: AMM 32-42-01-900-801								
32-42-05-720-801-01	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY - PARK BRAKE ACCUMULATOR (520GC)							Service ATA:32
	MOS/MSC	11-Aug-20	O/C					
	HRS	5942.6						
WC#: 32.720	AFL	3569						
PROC. REF: AMM 32-42-00-720-801PROC. REF: AMM 32-42-00-720-801								
32-42-05-780-801-02 S	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (520GC)							Service ATA:32
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6	2000					
	AFL	3875						
								PKG:16
PROC. REF: AMM 32-42-05-780-801PROC. REF: AMM 32-42-05-780-801								
32-42-05-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SYSTEM ACCUMULATOR - PARK BRAKE ACCUMULATOR (520GC)							Component ATA:32
PN:60833-2	MOS/MSC	11-Jul-95	O/C					
SN:TRS974	HRS	0		TSN 0				
WC#: 32.530	AFL	0						
PROC. REF: AMM 32-42-05-900-801PROC. REF: AMM 32-42-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-42-13-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE FLEXIBLE CONTROL - PARK BRAKE CONTROL CABLE (511GC)							Component ATA:32
PN:F50B794001A1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.590	AFL	0						
PROC. REF: AMM 32-42-13-900-801	PROC. REF: AMM 32-42-13-900-801							
32-42-17-900-801-01	REMOVAL/INSTALLATION OF PARK BRAKE PRESSURE SWITCH - PARK BRAKE PRESSURE SWITCH (82G)							Component ATA:32
PN:90G198-1	MOS/MSC	11-Jul-95	O/C					
SN:377	HRS	0		TSN 0				
WC#: 32.540	AFL	0						
PROC. REF: AMM 32-42-17-900-801	PROC. REF: AMM 32-42-17-900-801							
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES							Service ATA:32
	MOS/MSC	11-Jun-21	O/C	Adj -3d				
	HRS							
WC#: 32.260	AFL	3636						
PROC. REF: AMM 32-44-00-220-801	PROC. REF: AMM 32-44-00-220-801							
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES							Service ATA:32
	MOS	13-Aug-26	2 (+5d)		13-Oct-26	18-Oct-26	4 d (+5)	
	HRS	6770						
	AFL	4000						
PROC. REF: AMM 32-44-00-780-801	PROC. REF: AMM 32-44-00-780-801							
32-44-01-280-801-01	SPECIAL DETAILED INSPECTION OF THE NLG WHEELS - LH NLG WHEEL (L565GC)							Service ATA:32
PN:9550309	MOS	02-Oct-24						
SN:MAR69-34	HRS	6601.6						
WC#: 32.560	AFL	3875	500 (+3%)		4375	4390	365 (+15)	
PROC. REF: AMM 32-44-01-280-801	PROC. REF: AMM 32-44-01-280-801							
32-44-01-280-801-02	SPECIAL DETAILED INSPECTION OF THE NLG WHEELS - RH NLG WHEEL (R565GC)							Service ATA:32
PN:9543426	MOS	02-Oct-24						
SN:NOV90-3151	HRS	6601.6						
WC#: 32.565	AFL	3875	500 (+3%)		4375	4390	365 (+15)	
PROC. REF: AMM 32-44-01-280-801	PROC. REF: AMM 32-44-01-280-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEELS - LH NLG WHEEL (L565GC)							Component ATA:32
PN:9550309	MOS/MSC	02-Oct-24	O/C					
SN:MAR69-34	HRS	6601.6						
WC#: 32.560	AFL	3875						
PROC. REF: AMM 32-44-01-900-801	PROC. REF: AMM 32-44-01-900-801							
32-44-01-900-801-02	REMOVAL / INSTALLATION OF THE NLG WHEELS - RH NLG WHEEL (R565GC)							Component ATA:32
PN:9543426	MOS/MSC	02-Oct-24	O/C					
SN:NOV90-3151	HRS	6601.6						
WC#: 32.565	AFL	3875						
PROC. REF: AMM 32-44-01-900-801	PROC. REF: AMM 32-44-01-900-801							
32-44-05-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - LH NLG TIRE (L570GC)							Component ATA:32
PN:M08301IND03	MOS/MSC	02-Oct-24	O/C	TSN 0				
SN:8009S234	HRS	6601.6		TSN 0				
WC#: 32.560	AFL	3875		TSN 0				
PROC. REF: AMM 32-44-05-900-801	PROC. REF: AMM 32-44-05-900-801							
32-44-05-900-801-02	REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - RH NLG TIRE (R570GC)							Component ATA:32
PN:M08301IND03	MOS/MSC	02-Oct-24	O/C					
SN:5284S150	HRS	6601.6						
WC#: 32.565	AFL	3875						
PROC. REF: AMM 32-44-05-900-801	PROC. REF: AMM 32-44-05-900-801							
32-44-09-280-801-01	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - LH MLG OUTBOARD WHEEL (L540GC)							Service ATA:32
PN:5003279-3	MOS	05-Jun-25						
SN:JUN93-1713	HRS	6665.4						
	AFL	3918	400 (+3%)	TAC 161	4157	4169	147 (+12)	
PROC. REF: AMM 32-44-09-280-801	PROC. REF: AMM 32-44-09-280-801							
32-44-09-280-801-02	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - LH MLG INBOARD WHEEL (L535GC)							Service ATA:32
PN:5003279-3	MOS	18-Dec-25						
SN:JAN88-1307	HRS	6719.3						
	AFL	3957	400 (+3%)	TAC 137	4220	4232	210 (+12)	
PROC. REF: AMM 32-44-09-280-801	PROC. REF: AMM 32-44-09-280-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-09-280-801-03	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - RH MLG INBOARD WHEEL (R535GC)							Service ATA:32
PN:5003279-3	MOS	03-Jan-25						
SN:SEP93-1723	HRS	6627.5						
	AFL	3893	400 (+3%)	TAC 107	4186	4198	176 (+12)	
PROC. REF: AMM 32-44-09-280-801	PROC. REF: AMM 32-44-09-280-801							
32-44-09-280-801-04	SPECIAL DETAILED INSPECTION OF THE MLG WHEELS - RH MLG OUTBOARD WHEEL (R540GC)							Service ATA:32
PN:5003279-3	MOS	29-May-24						
SN:OCT93-1726	HRS	6572.7						
	AFL	3859	400 (+3%)		4259	4271	249 (+12)	
PROC. REF: AMM 32-44-09-280-801	PROC. REF: AMM 32-44-09-280-801							
32-44-09-900-801-01	REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG OUTBOARD WHEEL (L540GC)							Component ATA:32
PN:5003279-3	MOS/MSC	05-Jun-25	O/C	TSR 0				
SN:JUN93-1713	HRS	6665.4		TSR 0				
WC#: 32.570	AFL	3918		TSO 161, TSR 0				
PROC. REF: AMM 32-44-09-900-801	PROC. REF: AMM 32-44-09-900-801							
32-44-09-900-801-02	REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG INBOARD WHEEL (L535GC)							Component ATA:32
PN:5003279-3	MOS/MSC	18-Dec-25	O/C	TSR 16				
SN:JAN88-1307	HRS	6719.3		TSR 0				
WC#: 32.575	AFL	3957		TSO 137, TSR 0				
PROC. REF: AMM 32-44-09-900-801	PROC. REF: AMM 32-44-09-900-801							
32-44-09-900-801-03	REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG INBOARD WHEEL (R535GC)							Component ATA:32
PN:5003279-3	MOS/MSC	03-Jan-25	O/C					
SN:SEP93-1723	HRS	6627.5						
WC#: 32.580	AFL	3893		TSO 107				
PROC. REF: AMM 32-44-09-900-801	PROC. REF: AMM 32-44-09-900-801							
32-44-09-900-801-04	REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG OUTBOARD WHEEL (R540GC)							Component ATA:32
PN:5003279-3	MOS/MSC	29-May-24	O/C	TSO 0				
SN:OCT93-1726	HRS	6572.7		TSO 0				
WC#: 32.585	AFL	3859		TSO 0				
PROC. REF: AMM 32-44-09-900-801	PROC. REF: AMM 32-44-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-13-900-801-01	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG OUTBOARD TIRE (L550GC)							Component ATA:32
PN:M15101-01	MOS/MSC	05-Jun-25	O/C	TSN 0				
SN:9091J107	HRS	6665.4		TSN 0				
WC#: 32.570	AFL	3918		TSN 0				
PROC. REF: AMM 32-44-13-900-801	PROC. REF: AMM 32-44-13-900-801							
32-44-13-900-801-02	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG INBOARD TIRE (L545GC)							Component ATA:32
PN:M15101-01	MOS/MSC	18-Dec-25	O/C	TSN 0				
SN:4071K108	HRS	6719.3		TSN 0				
WC#: 32.575	AFL	3957		TSN 0				
PROC. REF: AMM 32-44-13-900-801	PROC. REF: AMM 32-44-13-900-801							
32-44-13-900-801-03	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG INBOARD TIRE (R545GC)							Component ATA:32
PN:M15101-01	MOS/MSC	03-Jan-25	O/C	TSN 0				
SN:9091J106	HRS	6627.5		TSN 0				
WC#: 32.580	AFL	3893		TSN 0				
PROC. REF: AMM 32-44-13-900-801	PROC. REF: AMM 32-44-13-900-801							
32-44-13-900-801-04	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG OUTBOARD TIRE (R550GC)							Component ATA:32
PN:M15101-01	MOS/MSC	29-May-24	O/C	TSN 0				
SN:9095J106	HRS	6572.7		TSN 0				
WC#: 32.585	AFL	3859		TSN 0				
PROC. REF: AMM 32-44-13-900-801	PROC. REF: AMM 32-44-13-900-801							
32-44-17-900-801-01	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG OUTBOARD BRAKE (L530GC)							Component ATA:32
PN:5003280-5	MOS/MSC	16-Mar-22	O/C	TSO 3				
SN:FEB80-133	HRS	6124.5		TSO 0				
WC#: 32.460	AFL	3681		TSO 0				
PROC. REF: AMM 32-44-17-900-801	PROC. REF: AMM 32-44-17-900-801							
32-44-17-900-801-02	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG INBOARD BRAKE (L525GC)							Component ATA:32
PN:5003280-5	MOS/MSC	16-Mar-22	O/C	TSN 241, TSO 0				
SN:JUN00-1747	HRS	6124.5		TSO 0				
WC#: 32.460	AFL	3681		TSO 0				
PROC. REF: AMM 32-44-17-900-801	PROC. REF: AMM 32-44-17-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-44-17-900-801-03	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG INBOARD BRAKE (R525GC)							Component ATA:32
PN:5003280-5	MOS/MSC	16-Mar-22	O/C	TSO 5				
SN:NOV76-925	HRS	6124.5		TSO 0				
WC#: 32.470	AFL	3681		TSO 0				
PROC. REF: AMM 32-44-17-900-801	PROC. REF: AMM 32-44-17-900-801							
32-44-17-900-801-04	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG OUTBOARD BRAKE (R530GC)							Component ATA:32
PN:5003280-5	MOS/MSC	16-Mar-22	O/C	TSN 241, TSO 0				
SN:JUN00-1746	HRS	6124.5		TSO 0				
WC#: 32.470	AFL	3681		TSO 0				
PROC. REF: AMM 32-44-17-900-801	PROC. REF: AMM 32-44-17-900-801							
32-50-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEEL STEERING REPEATER BOX - STEERING REPEATER BOX (66G)							Component ATA:32
PN:C24166-1	MOS/MSC	11-Jul-95	O/C					
SN:U487	HRS	0		TSN 0				
WC#: 32.740	AFL	0						
PROC. REF: AMM 32-50-01-900-801	PROC. REF: AMM 32-50-01-900-801							
32-50-05-900-801-01	REMOVAL / INSTALLATION OF THE STEERING HYDRAULIC UNIT - STEERING HYDRAULIC UNIT (67G)							Component ATA:32
PN:C24248-1	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:U434	HRS	0		TSN 0				
WC#: 32.780	AFL	0		TSN 0				
PROC. REF: AMM 32-50-05-900-801	PROC. REF: AMM 32-50-05-900-801							
32-50-13-900-801-01	REMOVAL / INSTALLATION OF THE STEERING SERVOVALVE - STEERING SERVOVALVE (65G)							Component ATA:32
PN:C24248-1	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.790	AFL	0		TSN 0				
PROC. REF: AMM 32-50-13-900-801	PROC. REF: AMM 32-50-13-900-801							
32-50-17-960-801-01 S	REPLACEMENT OF THE STEERING SYSTEM FILTERING ELEMENT - STEERING SYSTEM FILTER (511GH)							Service ATA:32
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 32.760	AFL	3569						
								PKG:21
PROC. REF: AMM 32-50-17-960-801	PROC. REF: AMM 32-50-17-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-37-900-801-01	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG PROXIMITY SWITCH UNIT (41G)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.850	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-02	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG PROXIMITY SWITCH UNIT (42G)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.850	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-03	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG BRACE STRUT ACTUATOR (12G1)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.860	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-04	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG BRACE STRUT ACTUATOR (12G2)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.860	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-05	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG UPLOCK BOX (7G1)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.870	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-06	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG UPLOCK BOX (7G2)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.870	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-37-900-801-07	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG MAIN DOOR UPLOCK BOX (14G1)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.880	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-08	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG MAIN DOOR UPLOCK BOX (14G2)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.890	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-09	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - LH MLG MAIN DOOR ACTUATOR (6G1)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.880	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-37-900-801-10	REMOVAL / INSTALLATION OF THE MLG AND MLG DOOR PROXIMITY SWITCHES - RH MLG MAIN DOOR ACTUATOR (6G2)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.890	AFL	0						
PROC. REF: AMM 32-61-37-900-801	PROC. REF: AMM 32-61-37-900-801							
32-61-41-900-801-01	REMOVAL / INSTALLATION OF THE NLG PROXIMITY SWITCHES - NLG UPLOCK BOX (13G)							Component ATA:32
PN:D22073-3	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.820	AFL	0						
PROC. REF: AMM 32-61-41-900-801	PROC. REF: AMM 32-61-41-900-801							
32-61-41-900-801-02	REMOVAL / INSTALLATION OF THE NLG PROXIMITY SWITCHES - NLG PROXIMITY SWITCH UNIT (44G)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.820	AFL	0						
PROC. REF: AMM 32-61-41-900-801	PROC. REF: AMM 32-61-41-900-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-41-900-801-03	REMOVAL / INSTALLATION OF THE NLG PROXIMITY SWITCHES - NLG DRAG BRACE (11G)							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.830	AFL	0						
PROC. REF: AMM 32-61-41-900-801	PROC. REF: AMM 32-61-41-900-801							
321102	LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING							Component ATA:32
PN:D50493	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 7				
SN:UNKNOWN	HRS	0						
WC#: 32.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
321104	LH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE							Component ATA:32
PN:D52369	MOS/MSC	11-Jul-95	H/T					
SN:UNKNOWN	HRS	0						
WC#: 32.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
321107	RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING							Component ATA:32
PN:D50493	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 7				
SN:UNKNOWN	HRS	0						
WC#: 32.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
321109	RH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE							Component ATA:32
PN:D52369	MOS/MSC	11-Jul-95	H/T					
SN:UNKNOWN	HRS	0						
WC#: 32.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
321117	LH REAR MAIN LANDING GEAR (MLG) PINTLE PIN							Component ATA:32
PN:D52554-1	MOS/MSC	11-Jul-95	H/T					
SN:UNKNOWN	HRS	0						
WC#: 32.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321118	RH REAR MAIN LANDING GEAR (MLG) PINTLE PIN							Component ATA:32
PN:D52554-1	MOS/MSC	11-Jul-95	H/T					
SN:UNKNOWN	HRS	0						
WC#: 32.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321119	LH MAIN LANDING GEAR (MLG) BARREL							Component ATA:32
PN:C23793-10	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 10				
SN:UNKNOWN	HRS	0						
WC#: 32.020	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321120	RH MAIN LANDING GEAR (MLG) BARREL							Component ATA:32
PN:C23794-10	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 10				
SN:UNKNOWN	HRS	0						
WC#: 32.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321121	LH MAIN LANDING GEAR (MLG) BRAKE RESTRICTOR VALVE							Component ATA:32
PN:A24506-5200	MOS/MSC	11-Jul-95	O/C					
SN:U262	HRS	0		TSN 0				
WC#: 32.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321126	RH MAIN LANDING GEAR (MLG) BRAKE RESTRICTOR VALVE							Component ATA:32
PN:A24506-5200	MOS/MSC	11-Jul-95	O/C					
SN:U263	HRS	0		TSN 0				
WC#: 32.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321141	LH MAIN LANDING GEAR (MLG) (ACTUATOR SIDE) SHAFT							Component ATA:32
PN:C23929-0-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
321146	RH MAIN LANDING GEAR (MLG) (ACTUATOR SIDE) SHAFT							Component ATA:32
PN:C23929-0-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.100	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321151	LH MAIN LANDING GEAR (MLG) (STRUCTURE SIDE) SHAFT							Component ATA:32
PN:C23321	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321156	RH MAIN LANDING GEAR (MLG) (STRUCTURE SIDE) SHAFT							Component ATA:32
PN:C23321	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.110	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322104	NOSE LANDING GEAR BARREL							Component ATA:32
PN:C23788-10	MOS/MSC	11-Jul-95	O/C	TSN 0, Adj 10				
SN:UNKNOWN	HRS	0						
WC#: 32.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322112	NOSE LANDING GEAR TELESCOPIC STRUT YOKE ASSEMBLY							Component ATA:32
PN:GA58346	MOS/MSC	11-Aug-20	H/T	TSO 0, TSR 145				
SN:319	HRS	5942.6		TSO 0, TSR 2906.5				
WC#: 32.210	AFL	3569		TSO 0, TSR 1533				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322131	NOSE LANDING GEAR RETRACTION STRUT RIGHT BALL-JOINT BEARING							Component ATA:32
PN:BRS35TAGSP5	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.250	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
322136	NOSE LANDING GEAR RETRACTION STRUT (STRUCTURE SIDE) SHAFT							Component ATA:32
PN:C23807	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.220	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322141	NOSE LANDING GEAR SWIVEL COUPLING							Component ATA:32
PN:C24266-1	MOS/MSC	31-Jul-06	O/C					
SN:H0751	HRS	2512.6						
WC#: 32.230	AFL	1737						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323106	NOSE LANDING GEAR "UP" RESTRICTOR VALVE							Component ATA:32
PN:A24508-5150	MOS/MSC	11-Jul-95	O/C					
SN:U1320	HRS	0		TSN 0				
WC#: 32.340	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323111	NOSE LANDING GEAR RESTRICTOR VALVE							Component ATA:32
PN:A5060-24508	MOS/MSC	11-Jul-95	O/C					
SN:U1333	HRS	0		TSN 0				
WC#: 32.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323121	LANDING GEAR CIRCUIT SHUTTLE VALVE							Component ATA:32
PN:A25493-1	MOS/MSC	11-Jul-95	O/C					
SN:669	HRS	0		TSN 0				
WC#: 32.360	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323126	LANDING GEAR DOORS CIRCUIT SHUTTLE VALVE							Component ATA:32
PN:A25493-1	MOS/MSC	11-Jul-95	O/C					
SN:688	HRS	0		TSN 0				
WC#: 32.360	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323146	LANDING GEAR SOLENOID DIRECTIONAL VALVE							Component ATA:32
PN:A24520-1	MOS/MSC	11-Jul-95	O/C					
SN:FM321	HRS	0		TSN 0				
WC#: 32.380	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323151	LANDING GEAR DOORS SOLENOID DIRECTIONAL VALVE							Component ATA:32
PN:A24521-102	MOS/MSC	11-Jul-95	O/C					
SN:FM1052	HRS	0		TSN 0				
WC#: 32.380	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323158	LH MAIN LANDING GEAR (MLG) DOOR MANUAL UNLOCKING CONTROL PIN							Component ATA:32
PN:F50B793600180	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 32.330	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323163	RH MAIN LANDING GEAR (MLG) DOOR MANUAL UNLOCKING CONTROL PIN							Component ATA:32
PN:F50B793600180	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 32.330	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323166	LH MAIN LANDING GEAR (MLG) DOOR RESTRICTOR VALVE							Component ATA:32
PN:A5150-24506	MOS/MSC	11-Jul-95	O/C					
SN:U264	HRS	0		TSN 0				
WC#: 32.390	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323171	RH MAIN LANDING GEAR (MLG) DOOR RESTRICTOR VALVE							Component ATA:32
PN:A5150-24506	MOS/MSC	11-Jul-95	O/C					
SN:U265	HRS	0		TSN 0				
WC#: 32.400	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323176	LH MAIN LANDING GEAR (MLG) DOWN RESTRICTOR VALVE							Component ATA:32
PN:A24508-5180	MOS/MSC	11-Jul-95	O/C					
SN:U1282	HRS	0		TSN 0				
WC#: 32.390	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323181	RH MAIN LANDING GEAR (MLG) DOWN RESTRICTOR VALVE							Component ATA:32
PN:A24508-5180	MOS/MSC	11-Jul-95	O/C					
SN:U1283	HRS	0		TSN 0				
WC#: 32.400	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323186	LH MAIN LANDING GEAR (MLG) UP RESTRICTOR VALVE							Component ATA:32
PN:A24510-5220	MOS/MSC	11-Jul-95	O/C					
SN:U120	HRS	0		TSN 0				
WC#: 32.390	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323191	RH MAIN LANDING GEAR (MLG) UP RESTRICTOR VALVE							Component ATA:32
PN:A24510-5220	MOS/MSC	11-Jul-95	O/C					
SN:U121	HRS	0		TSN 0				
WC#: 32.400	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323196	MAIN LANDING GEAR SUPPLY CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	11-Jul-95	O/C					
SN:FM3196	HRS	0		TSN 0				
WC#: 32.410	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323201	MAIN LANDING GEAR RETURN CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	11-Jul-95	O/C					
SN:FM3199	HRS	0		TSN 0				
WC#: 32.410	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323206	GEAR DOOR ELECTRO DISTRIBUTOR CIRCUIT RESTRICTOR VALVE							Component ATA:32
PN:A5040-24510	MOS/MSC	11-Jul-95	O/C					
SN:U130	HRS	0		TSN 0				
WC#: 32.410	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323221	NOSE LANDING GEAR/DOOR MANUAL/EMERGENCY CONTROL CABLE							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.430	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324141	NORMAL/EMERGENCY BRAKE DISTRIBUTOR							Component ATA:32
PN:57530-2	MOS/MSC	11-Jul-95	O/C					
SN:294	HRS	0		TSN 0				
WC#: 32.480	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324151	NORMAL/BRAKE DISTRIBUTOR VALVE							Component ATA:32
PN:65660	MOS/MSC	11-Jul-95	O/C					
SN:368	HRS	0		TSN 0				
WC#: 32.490	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324161	LH BRAKE CIRCUIT SHUTTLE VALVE							Component ATA:32
PN:CN100	MOS/MSC	11-Jul-95	O/C					
SN:397	HRS	0		TSN 0				
WC#: 32.500	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324166	RH BRAKE CIRCUIT SHUTTLE VALVE							Component ATA:32
PN:CN100	MOS/MSC	11-Jul-95	O/C					
SN:401	HRS	0		TSN 0				
WC#: 32.500	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324171	CENTER PARKING BRAKE CIRCUIT OVERPRESSURE VALVE							Component ATA:32
PN:A24519001	MOS/MSC	11-Jul-95	O/C					
SN:FM1115	HRS	0		TSN 0				
WC#: 32.520	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324176	PARKING BRAKE ACCUMULATOR SUPPLY CHECK VALVE							Component ATA:32
PN:A24515	MOS/MSC	11-Jul-95	O/C					
SN:FM2150	HRS	0		TSN 0				
WC#: 32.520	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324181	EMERGENCY BRAKE DISTRIBUTOR CHECK VALVE							Component ATA:32
PN:A24515	MOS/MSC	11-Jul-95	O/C					
SN:FM2168	HRS	0		TSN 0				
WC#: 32.510	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324186	LH BRAKE CIRCUIT SWIVEL CONNECTOR							Component ATA:32
PN:A100-24660	MOS/MSC	11-Jul-95	O/C					
SN:U190	HRS	0		TSN 0				
WC#: 32.515	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324191	RH BRAKE CIRCUIT SWIVEL CONNECTOR							Component ATA:32
PN:A101-24660	MOS/MSC	11-Jul-95	O/C					
SN:U268	HRS	0		TSN 0				
WC#: 32.515	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324201	PARKING BRAKE ACCUMULATOR GAUGE							Component ATA:32
PN:18040100	MOS/MSC	11-Jul-95	O/C					
SN:32747C	HRS	0		TSN 0				
WC#: 32.530	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324211	PARKING BRAKE ACCUMULATOR FILLER VALVE							Component ATA:32
PN:MS28889-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.530	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324216	LH PARKING BRAKE PRESSURE SWITCH							Component ATA:32
PN:7G663-1	MOS/MSC	11-Jul-95	O/C					
SN:1349	HRS	0		TSN 0				
WC#: 32.540	AFL	0						
PROC. REF: AMM 32-42-17-900-801PROC. REF: AMM 32-42-17-900-801								
324221	RH PARKING BRAKE PRESSURE SWITCH							Component ATA:32
PN:7G1090	MOS/MSC	11-Aug-20	O/C	TSN 0				
SN:1037	HRS	5942.6		TSN 0				
WC#: 32.540	AFL	3569		TSN 0				
PROC. REF: AMM 32-42-17-900-801PROC. REF: AMM 32-42-17-900-801								
324231	NORMAL BRAKING DISTRIBUTOR RETURN CIRCUIT CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	11-Jul-95	O/C					
SN:FM3198	HRS	0		TSN 0				
WC#: 32.510	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324236	PARKING BRAKE CONTROL HANDLE							Component ATA:32
PN:4183907	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.550	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324341	NO. 1 DRIVING CAP							Component ATA:32
PN:6002597	MOS/MSC	11-Jul-95	O/C					
SN:NONE	HRS	0		TSN 0				
WC#: 32.650	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324346	NO. 2 DRIVING CAP							Component ATA:32
PN:6002597	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.650	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324351	NO. 3 DRIVING CAP							Component ATA:32
PN:6002597	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.660	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324356	NO. 4 DRIVING CAP							Component ATA:32
PN:6002597	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.660	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324361	LH ANTI-SKID PRESSURE SWITCH							Component ATA:32
PN:7G1089	MOS/MSC	20-Dec-06	O/C	TSN 0				
SN:714	HRS	2522.08		TSN 0				
WC#: 32.610	AFL	1744		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324366	RH ANTI-SKID PRESSURE SWITCH							Component ATA:32
PN:7G612-1	MOS/MSC	11-Jul-95	O/C					
SN:1152	HRS	0		TSN 0				
WC#: 32.610	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324371	LH BRAKE CIRCUIT FILTER							Component ATA:32
PN:285697	MOS/MSC	11-Jul-95	O/C					
SN:U2112	HRS	0		TSN 0				
WC#: 32.670	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324381	RH BRAKE CIRCUIT FILTER							Component ATA:32
PN:285697	MOS/MSC	11-Jul-95	O/C					
SN:U2113	HRS	0		TSN 0				
WC#: 32.670	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324391	LH BRAKE SERVO VALVE RETURN CIRCUIT CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	11-Jul-95	O/C					
SN:FM3150	HRS	0		TSN 0				
WC#: 32.680	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324396	RH BRAKE SERVO VALVE RETURN CIRCUIT CHECK VALVE							Component ATA:32
PN:A24516	MOS/MSC	11-Jul-95	O/C					
SN:FM3117	HRS	0		TSN 0				
WC#: 32.680	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324401	LH BRAKE SERVO VALVE SUPPLY CIRCUIT CHECK VALVE							Component ATA:32
PN:A5140-24508	MOS/MSC	11-Jul-95	O/C					
SN:U1337	HRS	0		TSN 0				
WC#: 32.690	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324406	RH BRAKE SERVO VALVE SUPPLY CIRCUIT CHECK VALVE							Component ATA:32
PN:A5140-24508	MOS/MSC	11-Jul-95	O/C					
SN:U1338	HRS	0		TSN 0				
WC#: 32.690	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
325106	STEERING DIRECTIONAL VALVE							Component ATA:32
PN:65670-1	MOS/MSC	11-Jul-95	O/C					
SN:1782	HRS	0		TSN 0				
WC#: 32.750	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
325111	STEERING CONTROL UNIT							Component ATA:32
PN:287837-1	MOS/MSC	25-Nov-98	O/C	TSO 0				
SN:U778	HRS	859		TSO 0				
WC#: 32.750	AFL	565		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
325116	STEERING FILTER							Component ATA:32
PN:CG8104013356N00	MOS/MSC	24-Jul-08	O/C	TSO 0				
SN:UNKNOWN	HRS	3036.1		TSO 0				
WC#: 32.760	AFL	2036		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
325126	STEERING AMPLIFIER							Component ATA:32
PN:C24242	MOS/MSC	11-Jul-95	O/C					
SN:U286	HRS	0		TSN 0				
WC#: 32.770	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326006	L/G CONTROL PRINTED CIRCUIT BOARD							Component ATA:32
PN:CI823A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.800	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326011	NA-BLANK PRINTED CIRCUIT							Component ATA:32
PN:CI846A	MOS/MSC	08-Jun-16	O/C	TSN 0				
SN:418	HRS	5064.3		TSN 0				
WC#: 32.800	AFL	3203		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326026	LH MAIN LANDING GEAR (MLG) LEG DUAL PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.840	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
326031	RH MAIN LANDING GEAR (MLG) LEG DUAL PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.840	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326076	NOSE GEAR LEG DUAL PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.830	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326101	LANDING GEAR UP IAS INDICATOR SWITCH							Component ATA:32
PN:4219G010201	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.810	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 33 - LIGHTS								
33-20-00-200-802-01	CHECK OF THE CONNECTION OF "SELA" LIGHTING TUBES							Service ATA:33
	MOS/MSC	25-May-17	N/A					
	HRS	5157.3						
WC#: 33.240	AFL	3249						
PROC. REF: AMM 33-20-00-200-802PROC. REF: AMM 33-20-00-200-802								
33-40-01-900-801-01	REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - LH WING TIP NAVIGATION LIGHT LAMPS							Component ATA:33
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-01-900-801PROC. REF: AMM 33-40-01-900-801								
33-40-01-900-801-02	REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - RH WING TIP NAVIGATION LIGHT LAMPS							Component ATA:33
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-01-900-801PROC. REF: AMM 33-40-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-40-09-900-802-01	REMOVAL / INSTALLATION OF UPPER ANTI-COLLISION LIGHT - UPPER ANTI-COLLISION LIGHT (17L)							Component ATA:33
PN:30-1136-9	MOS/MSC	11-Jul-95	O/C					
SN:3009	HRS	0		TSN 0				
WC#: 33.140	AFL	0						
PROC. REF: AMM 33-40-09-900-802	PROC. REF: AMM 33-40-09-900-802							
33-40-33-900-802-01	LH UPPER LOGO LIGHT							Component ATA:33
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-33-900-801	PROC. REF: AMM 33-40-33-900-801							
33-40-33-900-802-02	RH UPPER LOGO LIGHT							Component ATA:33
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-33-900-801	PROC. REF: AMM 33-40-33-900-801							
33-40-33-900-802-03	LH LOWER LOGO LIGHT							Component ATA:33
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-33-900-801	PROC. REF: AMM 33-40-33-900-801							
33-40-33-900-802-04	RH LOWER LOGO LIGHT							Component ATA:33
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-33-900-801	PROC. REF: AMM 33-40-33-900-801							
33-40-33-960-801-01	REPLACEMENT OF THE LOGO LIGHT BULB - LH UPPER LOGO LIGHT (294L1) BULB							Service ATA:33
PN:PN	MOS/MSC	08-Dec-23	O/C					
SN:UNKNOWN	HRS	6529.1						
	AFL	3833						
PROC. REF: AMM 33-40-33-960-801	PROC. REF: AMM 33-40-33-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-40-33-960-801-02	REPLACEMENT OF THE LOGO LIGHT BULB - RH UPPER LOGO LIGHT (294L2) BULB							Service ATA:33
PN:PN	MOS/MSC	15-Jul-96	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 33-40-33-960-801	PROC. REF: AMM 33-40-33-960-801							
33-40-37-900-801-01	REMOVAL / INSTALLATION OF THE LANDING LIGHTS - LH LANDING LIGHT (3L1)							Component ATA:33
PN:4160818	MOS/MSC	11-Jul-95	O/C					
SN:63160	HRS	0		TSN 0				
WC#: 33.150	AFL	0						
PROC. REF: AMM 33-40-37-900-801	PROC. REF: AMM 33-40-37-900-801							
33-40-37-900-801-02	REMOVAL / INSTALLATION OF THE LANDING LIGHTS - RH LANDING LIGHT (3L2)							Component ATA:33
PN:4160818	MOS/MSC	11-Jul-95	O/C					
SN:63844	HRS	0		TSN 0				
WC#: 33.150	AFL	0						
PROC. REF: AMM 33-40-37-900-801	PROC. REF: AMM 33-40-37-900-801							
33-40-41-900-801-01	REMOVAL / INSTALLATION OF THE TAXI LIGHT - TAXI LIGHT (9L)							Component ATA:33
PN:4060622	MOS/MSC	11-Jul-95	O/C					
SN:66873	HRS	0		TSN 0				
WC#: 33.160	AFL	0						
PROC. REF: AMM 33-40-41-900-801	PROC. REF: AMM 33-40-41-900-801							
33-40-41-900-802-01	REMOVAL / INSTALLATION OF THE TAXI LIGHT CIRCUIT PROXIMITY SENSOR - PROXIMITY SWITCH (20L)							Component ATA:33
PN:8-240-02	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.170	AFL	0						
PROC. REF: AMM 33-40-41-900-802	PROC. REF: AMM 33-40-41-900-802							
33-50-00-710-804-01 S	OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM							Service ATA:33
	MOS	11-Jul-95						
	HRS	0	4500					
	AFL	0						
								PKG:23
PROC. REF: AMM 33-50-00-710-804	PROC. REF: AMM 33-50-00-710-804							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-00-720-801-01	FUNCTIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EPS 1 (113L)							Service ATA:33
PN:D734-02-001	MOS/MSC		O/C					
SN:2226/09-2004	HRS							
WC#: 33.100	AFL							
33-50-00-720-801-02	FUNCTIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EPS 2 (114L1)							Service ATA:33
PN:D734-02-001	MOS/MSC		O/C					
SN:2750/06-2006	HRS							
WC#: 33.110	AFL							
PROC. REF: AMM 33-50-00-720-801PROC. REF: AMM 33-50-00-720-801								
33-50-00-720-801-03	FUNCTIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EPS 3 (114L2)							Service ATA:33
PN:D734-02-001	MOS/MSC		O/C					
SN:3662480	HRS							
WC#: 33.120	AFL							
PROC. REF: AMM 33-50-00-720-801PROC. REF: AMM 33-50-00-720-801								
33-50-33-610-801-01	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 1 (113L)							Service ATA:33
PN:D734-02-001	MOS/MSC	24-Oct-25	O/C					
SN:2226/09-2004	HRS	6700.5						
WC#: 33.100	AFL	3940						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-610-801-02	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 2 (114L1)							Service ATA:33
PN:D734-02-001	MOS/MSC	29-Oct-25	O/C					
SN:2750/06-2006	HRS	6702.6						
WC#: 33.110	AFL	3942						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								
33-50-33-610-801-03	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 3 (114L2)							Service ATA:33
PN:D734-02-001	MOS/MSC	24-Oct-25	O/C					
SN:3662480	HRS	6700.5						
WC#: 33.120	AFL	3940						
PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801PROC. REF: AMM 33-50-33-610-801, AMM 33-50-33-610-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-50-33-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 1 (113L)							Component ATA:33
PN:D734-02-001	MOS/MSC	24-Oct-25	O/C	TSR 0				
SN:2226/09-2004	HRS	6700.5		TSR 0				
WC#: 33.100	AFL	3940		TSR 0				
PROC. REF: AMM 33-50-33-900-801	PROC. REF: AMM 33-50-33-900-801							
33-50-33-900-801-02	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 2 (114L1)							Component ATA:33
PN:D734-02-001	MOS/MSC	26-Oct-25	O/C	TSR 0				
SN:2750/06-2006	HRS	6700.5		TSR 0				
WC#: 33.110	AFL	3940		TSR 0				
PROC. REF: AMM 33-50-33-900-801	PROC. REF: AMM 33-50-33-900-801							
33-50-33-900-801-03	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 3 (114L2)							Component ATA:33
PN:D734-02-001	MOS/MSC	26-Oct-25	O/C	TSR 0				
SN:3662480	HRS	6700.5		TSR 0				
WC#: 33.120	AFL	3940		TSR 0				
PROC. REF: AMM 33-50-33-900-801	PROC. REF: AMM 33-50-33-900-801							
33-50-37-960-802-01	DISCARD OF THE EPS BATTERY PACKS - EPS 1 (113L) BATTERY PACK							Service ATA:33
PN:D734-02-001	MOS	24-Oct-25	24		24-Oct-27		380 d	LIFE LIMIT
SN:2226/09-2004	HRS	6700.5						
WC#: 33.100	AFL	3940						
PROC. REF: AMM 33-50-37-960-802	PROC. REF: AMM 33-50-37-960-802							
33-50-37-960-802-02	DISCARD OF THE EPS BATTERY PACKS - EPS 2 (114L1) BATTERY PACK							Service ATA:33
PN:D734-02-001	MOS	24-Oct-25	24		24-Oct-27		380 d	LIFE LIMIT
SN:2750/06-2006	HRS	6700.5						
WC#: 33.110	AFL	3940						
PROC. REF: AMM 33-50-37-960-802	PROC. REF: AMM 33-50-37-960-802							
33-50-37-960-802-03	DISCARD OF THE EPS BATTERY PACKS - EPS 3 (114L2) BATTERY PACK							Service ATA:33
PN:D734-02-001	MOS	24-Oct-25	24		24-Oct-27		380 d	LIFE LIMIT
SN:3662480	HRS	6700.5						
WC#: 33.120	AFL	3940						
PROC. REF: AMM 33-50-37-960-802	PROC. REF: AMM 33-50-37-960-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331101	FLIGHT COMPARTMENT LEFT READING LIGHT							Component ATA:33
PN:10-0027-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331106	FLIGHT COMPARTMENT RIGHT READING LIGHT							Component ATA:33
PN:10-0027-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331111	LH SPOT LIGHT							Component ATA:33
PN:4X650	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331113	LOWER LIGHT ASSEMBLY							Component ATA:33
PN:10-50B	MOS/MSC	11-Jul-95	O/C					
SN:321	HRS	0		TSN 0				
WC#: 33.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331116	RH SPOT LIGHT							Component ATA:33
PN:4X650	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331118	UPPER LIGHT ASSEMBLY							Component ATA:33
PN:10-50T	MOS/MSC	11-Jul-95	O/C					
SN:344	HRS	0		TSN 0				
WC#: 33.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331121	GLARE SHIELD LIGHTING POWER SUPPLY							Component ATA:33
PN:17-3019-1	MOS/MSC	11-Jul-95	O/C					
SN:1192	HRS	0		TSN 0				
WC#: 33.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331126	PILOT LIGHTING UNIT POWER SUPPLY							Component ATA:33
PN:24-54	MOS/MSC	30-Jan-19	O/C					
SN:1111	HRS	5672.1						
WC#: 33.040	AFL	3468						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331131	COPILOT LIGHTING UNIT POWER SUPPLY							Component ATA:33
PN:24-54	MOS/MSC	24-Nov-15	O/C					
SN:362	HRS	4950.18						
WC#: 33.040	AFL	3093						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331136	LH CONSOLE UNIT POWER SUPPLY							Component ATA:33
PN:24-54	MOS/MSC	11-Jul-95	O/C					
SN:1160	HRS	0		TSN 0				
WC#: 33.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331141	RH CONSOLE UNIT POWER SUPPLY							Component ATA:33
PN:24-54	MOS/MSC	11-Jul-95	O/C					
SN:1161	HRS	0		TSN 0				
WC#: 33.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331146	OVERHEAD PANEL POWER SUPPLY							Component ATA:33
PN:24-014	MOS/MSC	11-Jul-95	O/C					
SN:310	HRS	0		TSN 0				
WC#: 33.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331151	LH SEGMENTS UNIT POWER SUPPLY							Component ATA:33
PN:24-52-4	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331156	RH SEGMENTS UNIT POWER SUPPLY							Component ATA:33
PN:24-52-4	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
332101	LH EMERGENCY EXIT LIGHT							Component ATA:33
PN:30-1358-17	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
332106	RH EMERGENCY EXIT LIGHT							Component ATA:33
PN:30-1358-17	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
334106	LOWER ANTI-COLLISION LIGHT							Component ATA:33
PN:30-1136-9	MOS/MSC	24-Apr-15	O/C					
SN:2434	HRS	4844						
WC#: 33.140	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
334116	UPPER ANTI-COLLISION LIGHTS UNIT POWER SUPPLY							Component ATA:33
PN:60-2667-3	MOS/MSC	04-Aug-09	O/C	TSN 0				
SN:3609	HRS	3346.8		TSN 0				
WC#: 33.070	AFL	2210		TSN 0				
PROC. REF: AMM 33-40-65-960-801PROC. REF: AMM 33-40-65-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334121	LOWER ANTI-COLLISION LIGHTS UNIT POWER SUPPLY							Component ATA:33
PN:60-2667-3	MOS/MSC	24-Apr-15	O/C					
SN:1646	HRS	4844						
WC#: 33.070	AFL							
PROC. REF: AMM 33-40-65-960-801	PROC. REF: AMM 33-40-65-960-801							
334146	LH WING STROBE LIGHT							Component ATA:33
PN:39-28-21	MOS/MSC	22-Dec-06	O/C	TSN 0				
SN:2627	HRS	2523.08		TSN 0				
WC#: 33.180	AFL	1745		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
334151	RIGHT WING STROBE LIGHT							Component ATA:33
PN:39-28-21	MOS/MSC	11-Jul-95	O/C					
SN:723	HRS	0		TSN 0				
WC#: 33.180	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
334156	LH WING STROBE UNIT POWER SUPPLY							Component ATA:33
PN:39-42-1	MOS/MSC	11-Jul-95	O/C					
SN:749	HRS	0		TSN 0				
WC#: 33.190	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
334161	RH WING STROBE UNIT POWER SUPPLY							Component ATA:33
PN:39-42-4	MOS/MSC	24-Jan-24	O/C	TSN 0				
SN:1150	HRS	6535.8		TSN 0				
WC#: 33.190	AFL	3839		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
334171	TAIL NAVIGATION LIGHT							Component ATA:33
PN:6480651	MOS/MSC	05-Jan-17	O/C	TSN 0				
SN:327	HRS	5149.6		TSN 0				
WC#: 33.200	AFL	3244		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334851 U	PULSELITE CONTROL							Component ATA:33
PN:2400-25-4-4	MOS/MSC	17-Jul-96	O/C					
SN:K00972	HRS	150						
	AFL	62						
335121	LH EVACUATION LIGHT							Component ATA:33
PN:30-0424-9	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
335126	RH EVACUATION LIGHT							Component ATA:33
PN:30-0424-9	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 33.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 34 - NAVIGATION								
34-01-00-720-801-01 S	FUNCTIONAL TEST OF THE EFIS SYSTEM							Service ATA:34
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 34.640	AFL	3875						
								PKG:16
PROC. REF: AMM 34-01-00-720-801, AMM 34-01-00-720-801, AMM 34-01-00-720-801PROC. REF: AMM 34-01-00-720-801, AMM 34-01-00-720-801, AMM 34-01-00-720-801								
34-01-13-900-801-01	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - PFD 1 (L360NH)							Component ATA:34
PN:622-9978-114	MOS/MSC	02-Oct-24	O/C	TSO 9				
SN:49TRM	HRS	6601.6		TSO 0				
WC#: 34.230	AFL	3875		TSO 0				
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-13-900-801-02	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - PFD 2 (R360NH)							Component ATA:34
PN:622-9978-114	MOS/MSC	20-Sep-24	O/C	TSO 0				
SN:1758	HRS			TSO 0				
WC#: 34.230	AFL			TSO 0				
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-01-13-900-801-03		REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD 1 (L361NH)						Component ATA:34
PN:622-9978-114	MOS/MSC	09-Aug-19	O/C	TSO 4				
SN:1758	HRS	5809.2		TSO 0				
WC#: 34.240	AFL	3520		TSO 0				
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-13-900-801-04		REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD 2 (R361NH)						Component ATA:34
PN:PN	MOS/MSC	08-Sep-22	O/C					
SN:1458	HRS	6221.1						
WC#: 34.240	AFL	3722						
PROC. REF: AMM 34-01-13-900-801PROC. REF: AMM 34-01-13-900-801								
34-01-25-710-801-07 S		OPERATIONAL TEST OF THE EFIS FANS - EFIS FANS						Service ATA:34
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 34.630	AFL	3569						PKG:21
PROC. REF: AMM 34-01-25-710-801, AMM 34-01-25-710-801, AMM 34-01-25-710-801PROC. REF: AMM 34-01-25-710-801, AMM 34-01-25-710-801, AMM 34-01-25-710-801								
34-10-00-700-881-01		TEST PILOT AIR DATA (ADC) COMPUTER (FAR 91.411)						Service ATA:34
PN:822-1036-466	MOS	07-Oct-24	24		02-Oct-26	OVD		MANDATORY
SN:3295	HRS	6606.8						
WC#: 34.510	AFL	3879						
		Test Date: : 02-Oct-24						
PROC. REF: GENERIC NO REF, FAR 91.411PROC. REF: GENERIC NO REF, FAR 91.411								
34-10-00-700-881-02		TEST COPILOT AIR DATA (ADC) COMPUTER (FAR 91.411)						Service ATA:34
PN:822-1036-466	MOS	07-Oct-24	24		02-Oct-26	OVD		MANDATORY
SN:2772	HRS	6606.8						
WC#: 34.520	AFL	3879						
		Test Date: : 02-Oct-24						
PROC. REF: GENERIC NO REF, FAR 91.411PROC. REF: GENERIC NO REF, FAR 91.411								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-10-00-700-881-03		TEST STAND BY ALTIMETER (FAR 91.411)						Service ATA:34
PN:64141-530-1	MOS	07-Oct-24	24		02-Oct-26		OVD	MANDATORY
SN:4488	HRS	6606.8						
WC#: 34.530	AFL	3879						
			Test Date: : 02-Oct-24					
PROC. REF: GENERIC NO REF, FAR 91.411PROC. REF: GENERIC NO REF, FAR 91.411								
34-10-00-720-801-01 S		FUNCTIONAL TEST OF THE AIR DATA SYSTEM						Service ATA:34
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
WC#: 34.105	AFL	3875						
								PKG:16
PROC. REF: AMM 34-10-00-720-801, AMM 34-10-00-720-801PROC. REF: AMM 34-10-00-720-801, AMM 34-10-00-720-801								
34-10-00-720-802-01		FUNCTIONAL TEST PILOT AIR DATA (ADC) COMPUTER						Service ATA:34
PN:822-1036-466	MOS	07-Oct-24	24 (+3%)		07-Oct-26	29-Oct-26	TOL (+20 d)	
SN:3295	HRS	6606.8						
WC#: 34.510	AFL	3879						
PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802								
34-10-00-720-802-02		FUNCTIONAL TEST COPILOT AIR DATA (ADC) COMPUTER						Service ATA:34
PN:822-1036-466	MOS	07-Oct-24	24 (+3%)		07-Oct-26	29-Oct-26	TOL (+20 d)	
SN:2772	HRS	6606.8						
WC#: 34.520	AFL	3879						
PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802								
34-10-00-720-802-03		FUNCTIONAL TEST STAND BY ALTIMETER						Service ATA:34
PN:64141-530-1	MOS	07-Oct-24	24 (+3%)		07-Oct-26	29-Oct-26	TOL (+20 d)	
SN:4488	HRS	6606.8						
WC#: 34.530	AFL	3879						
PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802								
34-10-00-720-802-04		FUNCTIONAL TEST STANDBY MACH-AIRSPEED INDICATOR						Service ATA:34
PN:64032-229-1	MOS	02-Oct-24	24 (+3%)		02-Oct-26	24-Oct-26	TOL (+15 d)	
SN:1310	HRS	6601.6						
WC#: 34.535	AFL	3875						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition

ATA 34 - NAVIGATION

PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802

34-10-00-720-802-05		FUNCTIONAL TEST STANDBY AIR DATA UNIT						Service ATA:34
PN:PN	MOS/MSC	11-Jul-95	N/A					
SN:UNKNOWN	HRS	0						
WC#: 34.560	AFL	0						

PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802PROC. REF: AMM 34-10-00-720-802, AMM 34-10-00-720-802

34-10-01-700-881-01		TEST STANDBY AIR DATA UNIT (FAR 91.411)						Service ATA:34
PN:PN	MOS/MSC		N/A					
SN:UNKNOWN	HRS							
WC#: 34.560	AFL							

PROC. REF: GENERIC NO REF, FAR 91.413PROC. REF: GENERIC NO REF, FAR 91.413

34-10-01-900-801-01		REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE AIR TEMPERATURE PROBE (185F)						Component ATA:34
PN:102AU1CK	MOS/MSC	20-Dec-06	O/C	TSR 0				
SN:A6568	HRS	2522.08		TSR 0				
WC#: 34.100	AFL	1744		TSR 0				

PROC. REF: AMM 34-10-01-900-801PROC. REF: AMM 34-10-01-900-801

34-10-11-720-801-01	S	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - LH AOA SENSOR (52F1)						Service ATA:34
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						

PKG:31

PROC. REF: AMM 34-10-11-720-801PROC. REF: AMM 34-10-11-720-801

34-10-11-720-801-02	S	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - RH AOA SENSOR (52F2)						Service ATA:34
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						

PKG:31

PROC. REF: AMM 34-10-11-720-801PROC. REF: AMM 34-10-11-720-801

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-10-11-900-801-01		REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - LH AOA SENSOR (52F1)						Component ATA:34
PN:2551A11P	MOS/MSC	08-May-14	O/C					
SN:1035	HRS	4694.5						
WC#: 30.200	AFL	2957						
PROC. REF: AMM 34-10-11-900-801	PROC. REF: AMM 34-10-11-900-801							
34-10-11-900-801-02		REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - RH AOA SENSOR (52F2)						Component ATA:34
PN:2551A12P	MOS/MSC	08-May-14	O/C					
SN:1034	HRS	4694.5						
WC#: 30.200	AFL	2957						
PROC. REF: AMM 34-10-11-900-801	PROC. REF: AMM 34-10-11-900-801							
34-11-00-680-801-01 S		DRAINING OF THE TOTAL / STATIC PRESSURE SYSTEM						Service ATA:34
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 34.110	AFL	3875						
								PKG:16
PROC. REF: AMM 34-11-00-680-801	PROC. REF: AMM 34-11-00-680-801							
34-11-00-790-801-01		LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT STATIC AIR PRESSURE SYSTEM						Service ATA:34
	MOS/MSC	18-Jun-19	O/C					
	HRS	5790.5						
WC#: 34.120	AFL	3507						
PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801	PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801							
34-11-00-790-801-02		LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT TOTAL AIR PRESSURE SYSTEM						Service ATA:34
	MOS/MSC	24-Apr-06	O/C					
	HRS	2490.6						
	AFL	1725						
PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801	PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801							
34-11-00-790-801-03		LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT STATIC AIR PRESSURE SYSTEM						Service ATA:34
	MOS/MSC	18-Jun-19	O/C					
	HRS	5790.5						
	AFL	3507						
PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801	PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-00-790-801-04	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT TOTAL AIR PRESSURE SYSTEM							Service ATA:34
	MOS/MSC	05-Jan-16	O/C					
	HRS	5149.6						
	AFL	3244						
PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801								
34-11-00-790-801-05	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - STAND-BY STATIC AIR PRESSURE SYSTEM							Service ATA:34
	MOS/MSC	18-Jun-19	O/C					
	HRS	5790.5						
	AFL	3507						
PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801PROC. REF: AMM 34-11-00-790-801, AMM 34-11-00-790-801								
34-11-01-200-801-01	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - LH TOTAL PRESSURE PROBE (14F1)							Service ATA:34
	MOS	11-Aug-25	12 (+1m)	Adj -25d	17-Jul-26	17-Aug-26	OVD	
	HRS	6680.7	300 (+30)		6980.7	7010.7	188.4 (+30)	
	AFL	3931						
PROC. REF: AMM 34-11-01-200-801PROC. REF: AMM 34-11-01-200-801								
34-11-01-200-801-02	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - RH TOTAL PRESSURE PROBE (14F2)							Service ATA:34
	MOS	11-Aug-25	12 (+1m)	Adj -25d	17-Jul-26	17-Aug-26	OVD	
	HRS	6680.7	300 (+30)		6980.7	7010.7	188.4 (+30)	
	AFL	3931						
PROC. REF: AMM 34-11-01-200-801PROC. REF: AMM 34-11-01-200-801								
34-11-01-900-801-01	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - LH TOTAL PRESSURE PROBE (14F1)							Component ATA:34
PN:50520	MOS/MSC	11-Jul-95	O/C					
SN:1265	HRS	0		TSN 0				
WC#: 34.080	AFL	0						
PROC. REF: AMM 34-11-01-900-801PROC. REF: AMM 34-11-01-900-801								
34-11-01-900-801-02	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - RH TOTAL PRESSURE PROBE (14F2)							Component ATA:34
PN:50520	MOS/MSC	11-Jul-95	O/C					
SN:1281	HRS	0		TSN 0				
WC#: 34.080	AFL	0						
PROC. REF: AMM 34-11-01-900-801PROC. REF: AMM 34-11-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-05-900-801-01	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (16F1)							Component ATA:34
PN:44320	MOS/MSC	08-May-14	O/C	TSN 226				
SN:662	HRS	4694.5		TSN 4694.5				
WC#: 34.090	AFL	2957		TSN 2957				
PROC. REF: AMM 34-11-05-900-801	PROC. REF: AMM 34-11-05-900-801							
34-11-05-900-801-02	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (16F2)							Component ATA:34
PN:44320	MOS/MSC	11-Aug-20	O/C					
SN:1765	HRS	5942.6						
WC#: 34.090	AFL	3569						
PROC. REF: AMM 34-11-05-900-801	PROC. REF: AMM 34-11-05-900-801							
34-11-07-900-801-01	PILOT RATE OF CLIMB INDICATOR HOSE							Component ATA:34
PN:07035L0500	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:UNKNOWN	HRS	3036.1		TSN 0				
WC#: 34.150	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
34-11-07-900-801-02	COPILOT RATE OF CLIMB INDICATOR HOSE							Component ATA:34
PN:07035L0390	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:UNKNOWN	HRS	3036.1		TSN 0				
WC#: 34.150	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
34-11-07-900-801-03	LH PILOT AIRSPEED MACHMETER INDICATOR HOSE							Component ATA:34
PN:07034L0390	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:UNKNOWN	HRS	3036.1		TSN 0				
WC#: 34.160	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
34-11-07-900-801-04	LH COPILOT AIRSPEED MACHMETER INDICATOR HOSE							Component ATA:34
PN:07035L0400	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:UNKNOWN	HRS	3036.1		TSN 0				
WC#: 34.170	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-900-801-05	RH PILOT AIRSPEED MACHMETER INDICATOR HOSE							Component ATA:34
PN:07035L0460	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:UNKNOWN	HRS	3036.1		TSN 0				
WC#: 34.160	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-06	RH COPILOT AIRSPEED MACHMETER INDICATOR HOSE							Component ATA:34
PN:07034L0485	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:UNKNOWN	HRS	3036.1		TSN 0				
WC#: 34.170	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-07	EMERGENCY ALTIMETER HOSE							Component ATA:34
PN:07035L0340	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:UNKNOWN	HRS	3036.1		TSN 0				
WC#: 34.180	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-08	COPILOT ALTIMETER HOSE							Component ATA:34
PN:07035L0425	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS	3036.1						
WC#: 34.180	AFL	2036						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-09	CABIN TRIPLE INDICATOR HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.190	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-10	NOSE CONE ACTUATOR HOSE							Component ATA:34
PN:07034L0315	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:DF-03-2003	HRS	2709.8		TSN 0				
WC#: 34.190	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-900-801-11	PILOT PITOT HOSE							Component ATA:34
PN:07202L0305	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.200	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-12	COPILOT PITOT HOSE							Component ATA:34
PN:07202L0305	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.200	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-13	PILOT LOWER STATIC HOSE							Component ATA:34
PN:07035L0330	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.210	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-14	COPILOT LOWER STATIC HOSE							Component ATA:34
PN:07035L0330	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.220	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-15	PILOT UPPER STATIC HOSE							Component ATA:34
PN:07035L0330	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.210	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-16	COPILOT UPPER STATIC HOSE							Component ATA:34
PN:07035L0330	MOS/MSC	05-Jan-17	H/T	TSN 114				
SN:UNKNOWN	HRS	5149.6		TSN 2439.8				
WC#: 34.220	AFL	3244		TSN 1390				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-900-801-17	PILOT SOLENOID VALVE LOWER HOSE							Component ATA:34
PN:07035L0390	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:12-06	HRS	2709.8		TSN 0				
WC#: 34.230	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-18	COPILOT SOLENOID VALVE FRONT HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.240	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-19	PILOT SOLENOID VALVE CENTER HOSE							Component ATA:34
PN:07035L0300	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:708800-06	HRS	2709.8		TSN 0				
WC#: 34.235	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-20	COPILOT SOLENOID VALVE CENTER HOSE							Component ATA:34
PN:07034L0225	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.245	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-21	PILOT SOLENOID VALVE UPPER HOSE							Component ATA:34
PN:07035L0460	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:DF-03-2004	HRS	2709.8		TSN 0				
WC#: 34.230	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-22	COPILOT SOLENOID VALVE REAR HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.240	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-900-801-23	AIR DATA COMPUTER PITOT HOSE							Component ATA:34
PN:07034L0280	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:0306	HRS	2709.8		TSN 0				
WC#: 34.250	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-24	COPILOT AIR DATA COMPUTER PITOT HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.270	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-25	RH MANIFOLD BLOCK/COP. S/V HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.260	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-26	AIR DATA COMPUTER STATIC HOSE							Component ATA:34
PN:PN-UNKNOWN	MOS/MSC	18-Jun-19	H/T					
SN:UNKNOWN	HRS	5790.5						
WC#: 34.250	AFL	3507						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-27	COPILOT AIR DATA COMPUTER STATIC HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.270	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-28	L/G IAS SWITCH PITOT HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.280	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-900-801-29	AILERON ARTHUR PITOT HOSE							Component ATA:34
PN:19644L0350	MOS/MSC	08-Dec-23	H/T	TSN 0				
SN:NA	HRS	6529.1		TSN 0				
WC#: 34.290	AFL	3833		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-30	L/G IAS SWITCH STATIC HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.280	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-31	AILERON ARTHUR STATIC HOSE							Component ATA:34
PN:6780060015	MOS/MSC	08-Dec-23	H/T	TSN 0				
SN:NA	HRS	6529.1		TSN 0				
WC#: 34.290	AFL	3833		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-32	SLATS IAS SWITCH PITOT HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.300	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-33	ELEVATOR ARTHUR PITOT HOSE							Component ATA:34
PN:07034L0310	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:DF-01-2001	HRS	2709.8		TSN 0				
WC#: 34.310	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-34	SLATS IAS SWITCH STATIC HOSE							Component ATA:34
PN:PN	MOS/MSC	17-Jul-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	2709.8		TSN 0				
WC#: 34.300	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-900-801-35	ELEVATOR ARTHUR STATIC HOSE							Component ATA:34
PN:07035L0340	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:10-06	HRS	2709.8		TSN 0				
WC#: 34.310	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-36	PRESSURE TRANSMITTER HOSE							Component ATA:34
PN:07035L0245	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:10-06	HRS	2709.8		TSN 0				
WC#: 34.320	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-37	NO. 1 ENGINE FUEL COMPUTER PT2 HOSE							Component ATA:34
PN:07034L0385	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.330	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-38	NO. 2 ENGINE FUEL COMPUTER PT2 HOSE							Component ATA:34
PN:07034L0310	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.335	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-900-801-39	NO. 3 ENGINE FUEL COMPUTER PT2 HOSE							Component ATA:34
PN:07034L0385	MOS/MSC	17-Jul-07	H/T	TSN 0				
SN:UNKNOWN	HRS	2709.8		TSN 0				
WC#: 34.330	AFL	1854		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-11-07-960-801-01	DISCARD OF THE ELASTOMER HOSES INSTALLED ON TOTAL AND STATIC PRESSURE LINES							Service ATA:34
PN:07035L0500	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.150	AFL							
		Manufacture Date:: 24-Jul-08						
PROC. REF: AMM 34-11-07-960-801PROC. REF: AMM 34-11-07-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-960-801-02	DISCARD COPILOT RATE OF CLIMB INDICATOR HOSE							Service ATA:34
PN:07035L0390	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.150	AFL							
			Manufacture Date:: 24-Jul-08					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-03	DISCARD LH PILOT AIRSPEED MACHMETER INDICATOR HOSE							Service ATA:34
PN:07034L0390	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.160	AFL							
			Manufacture Date:: 24-Jul-08					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-04	DISCARD LH COPILOT AIRSPEED MACHMETER INDICATOR HOSE							Service ATA:34
PN:07035L0400	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.170	AFL							
			Manufacture Date:: 24-Jul-08					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-05	DISCARD RH PILOT AIRSPEED MACHMETER INDICATOR HOSE							Service ATA:34
PN:07035L0460	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.160	AFL							
			Manufacture Date:: 24-Jul-08					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-06	DISCARD RH COPILOT AIRSPEED MACHMETER INDICATOR HOSE							Service ATA:34
PN:07034L0485	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.170	AFL							
			Manufacture Date:: 24-Jul-08					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-960-801-07	DISCARD EMERGENCY ALTIMETER HOSE							Service ATA:34
PN:07035L0340	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.180	AFL							
			Manufacture Date:: 24-Jul-08					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-08	DISCARD COPILOT ALTIMETER HOSE							Service ATA:34
PN:07035L0425	MOS/MSC	24-Jul-08	O/C					
SN:UNKNOWN	HRS							
WC#: 34.180	AFL							
			Manufacture Date:: 24-Jul-08					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-09	DISCARD CABIN TRIPLE INDICATOR HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.190	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-10	DISCARD NOSE CONE ACTUATOR HOSE							Service ATA:34
PN:07034L0315	MOS/MSC	17-Jul-07	O/C					
SN:DF-03-2003	HRS	2709.8		TAC 0				
WC#: 34.190	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-11	DISCARD PILOT PITOT HOSE							Service ATA:34
PN:07202L0305	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.200	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-960-801-12	DISCARD COPILOT PITOT HOSE							Service ATA:34
PN:07202L0305	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.200	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-13	DISCARD PILOT LOWER STATIC HOSE							Service ATA:34
PN:07035L0330	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.210	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-14	DISCARD COPILOT LOWER STATIC HOSE							Service ATA:34
PN:07035L0330	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.220	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-15	DISCARD PILOT UPPER STATIC HOSE							Service ATA:34
PN:07035L0330	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.210	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-16	DISCARD COPILOT UPPER STATIC HOSE							Service ATA:34
PN:07035L0330	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.220	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-17	DISCARD PILOT SOLENOID VALVE LOWER HOSE							Service ATA:34
PN:07035L0390	MOS/MSC	17-Jul-07	O/C					
SN:12-06	HRS	2709.8		TAC 0				
WC#: 34.230	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-960-801-18	DISCARD COPILOT SOLENOID VALVE FRONT HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.240	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-19	DISCARD PILOT SOLENOID VALVE CENTER HOSE							Service ATA:34
PN:07035L0300	MOS/MSC	17-Jul-07	O/C					
SN:708800-06	HRS	2709.8		TAC 0				
WC#: 34.235	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-20	DISCARD COPILOT SOLENOID VALVE CENTER HOSE							Service ATA:34
PN:07034L0225	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.245	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-21	DISCARD PILOT SOLENOID VALVE UPPER HOSE							Service ATA:34
PN:07035L0460	MOS/MSC	17-Jul-07	O/C					
SN:DF-03-2004	HRS	2709.8		TAC 0				
WC#: 34.230	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-22	DISCARD COPILOT SOLENOID VALVE REAR HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.240	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-23	DISCARD AIR DATA COMPUTER PITOT HOSE							Service ATA:34
PN:07034L0280	MOS/MSC	17-Jul-07	O/C					
SN:0306	HRS	2709.8		TAC 0				
WC#: 34.250	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-960-801-24	DISCARD COPILOT AIR DATA COMPUTER PITOT HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.270	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-25	DISCARD RH MANIFOLD BLOCK/COP. S/V HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.260	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-26	DISCARD AIR DATA COMPUTER STATIC HOSE							Service ATA:34
PN:PN-UNKNOWN	MOS	18-Jun-19	144		18-Jun-31		1713 d	LIFE LIMIT
SN:UNKNOWN	HRS	5790.5						
WC#: 34.250	AFL	3507						
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-27	DISCARD COPILOT AIR DATA COMPUTER STATIC HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C					
	HRS	2709.8		TAC 0				
WC#: 34.270	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-28	DISCARD L/G IAS SWITCH PITOT HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.260	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-960-801-29	DISCARD AILERON ARTHUR PITOT HOSE							Service ATA:34
PN:19644L0350	MOS	08-Dec-23	144		08-Dec-35		3347 d	LIFE LIMIT
SN:NA	HRS	6529.1						
WC#: 34.270	AFL	3833						
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-30	DISCARD L/G IAS SWITCH STATIC HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.280	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-31	DISCARD AILERON ARTHUR STATIC HOSE							Service ATA:34
PN:6780060015	MOS	08-Dec-23	144		08-Dec-35		3347 d	LIFE LIMIT
SN:NA	HRS	6529.1						
WC#: 34.290	AFL	3833						
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-32	DISCARD SLATS IAS SWITCH PITOT HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.300	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-33	DISCARD ELEVATOR ARTHUR PITOT HOSE							Service ATA:34
PN:07034L0310	MOS/MSC	17-Jul-07	O/C					
SN:DF-01-2001	HRS	2709.8		TAC 0				
WC#: 34.310	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-11-07-960-801-34	DISCARD SLATS IAS SWITCH STATIC HOSE							Service ATA:34
	MOS/MSC	17-Jul-07	O/C	TAC 0				
	HRS	2709.8		TAC 0				
WC#: 34.300	AFL	1854		TAC 0				
			Manufacture Date:: 17-Jul-07					
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-35	DISCARD ELEVATOR ARTHUR STATIC HOSE							Service ATA:34
PN:07035L0340	MOS/MSC	17-Jul-07	O/C					
SN:10-06	HRS	2709.8		TAC 0				
WC#: 34.310	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-36	DISCARD PRESSURE TRANSMITTER HOSE							Service ATA:34
PN:07035L0245	MOS/MSC	17-Jul-07	O/C					
SN:10-06	HRS	2709.8		TAC 0				
WC#: 34.320	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-37	DISCARD NO. 1 ENGINE FUEL COMPUTER PT2 HOSE							Service ATA:34
PN:07034L0385	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.330	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-38	DISCARD NO. 2 ENGINE FUEL COMPUTER PT2 HOSE							Service ATA:34
PN:07034L0310	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.335	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							
34-11-07-960-801-39	DISCARD NO. 3 ENGINE FUEL COMPUTER PT2 HOSE							Service ATA:34
PN:07034L0385	MOS/MSC	17-Jul-07	O/C					
SN:UNKNOWN	HRS	2709.8		TAC 0				
WC#: 34.330	AFL	1854		TAC 0				
PROC. REF: AMM 34-11-07-960-801	PROC. REF: AMM 34-11-07-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-14-01-710-802-01	OPERATIONAL TEST PILOT AIR DATA (ADC) COMPUTER							Service ATA:34
PN:822-1036-466	MOS/MSC	07-Oct-24	O/C					
SN:3295	HRS	6606.8						
WC#: 34.510	AFL	3879						
PROC. REF: AMM 34-14-01-710-802, AMM 34-14-01-710-802PROC. REF: AMM 34-14-01-710-802, AMM 34-14-01-710-802								
34-14-01-710-803-01	OPERATIONAL TEST COPILOT AIR DATA (ADC) COMPUTER							Service ATA:34
PN:822-1036-466	MOS/MSC	07-Oct-24	O/C					
SN:2772	HRS	6606.8						
WC#: 34.520	AFL	3879						
PROC. REF: AMM 34-14-01-710-803, AMM 34-14-01-710-803PROC. REF: AMM 34-14-01-710-803, AMM 34-14-01-710-803								
34-14-01-900-801-01	REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 1 (1FX) OR (10FX) OR (L320FE)							Component ATA:34
PN:822-1036-466	MOS/MSC	08-Sep-22	O/C					
SN:3295	HRS	6221.1		TSO 0				
WC#: 34.510	AFL	3722		TSO 0				
PROC. REF: AMM 34-14-01-900-801PROC. REF: AMM 34-14-01-900-801								
34-14-01-900-801-02	REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 2 (81FX) OR (20FX) OR (R320FE)							Component ATA:34
PN:822-1036-466	MOS/MSC	08-Sep-22	O/C	TSO 68				
SN:2772	HRS	6221.1		TSO 1071.5				
WC#: 34.520	AFL	3722		TSO 478				
PROC. REF: AMM 34-14-01-900-801PROC. REF: AMM 34-14-01-900-801								
34-15-00-720-801-01	FUNCTIONAL TEST OF THE ALTITUDE ALERTER SYSTEM - ALTITUDE ALERTER SYSTEM							Service ATA:34
	MOS/MSC	11-Jul-95	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 34-15-00-720-801PROC. REF: AMM 34-15-00-720-801								
34-16-09-900-801-01	STAND BY ALTIMETER							Component ATA:34
PN:64141-530-1	MOS/MSC	02-Dec-14	O/C	TSR 0				
SN:4488	HRS	4828.1		TSR 0				
WC#: 34.530	AFL	3016		TSR 0				
PROC. REF: AMM 34-16-09-900-801, AMM 34-16-09-900-801PROC. REF: AMM 34-16-09-900-801, AMM 34-16-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-21-01-900-801-01	NO. 1 INERTIAL REFERENCE (IRU 1) UNIT							Component ATA:34
PN:HG2001AB02	MOS/MSC	17-Jul-96	O/C					
SN:95120619	HRS	150		TSN 0				
WC#: 34.900	AFL	62						
PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801								
34-21-01-900-801-02	NO. 2 INERTIAL REFERENCE (IRU2) UNIT							Component ATA:34
PN:HG2001AB02	MOS/MSC	17-Jul-96	O/C					
SN:UNKNOWN	HRS	150		TSN 0				
WC#: 34.900	AFL	62						
PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801								
34-21-01-900-801-03	NO. 3 INERTIAL REFERENCE (IRU 3) UNIT							Component ATA:34
PN:HG1075AB02	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.900	AFL	0						
PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801PROC. REF: AMM 34-21-01-900-801, AMM 34-21-01-900-801								
34-21-13-100-801-01 S	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 1 FAN FILTER							Service ATA:34
	MOS	11-Aug-20						
	HRS	5942.6	3000					
WC#: 34.975	AFL	3569						
								PKG:22
PROC. REF: AMM 34-21-13-100-801PROC. REF: AMM 34-21-13-100-801								
34-21-13-100-801-02 S	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 2 FAN FILTER							Service ATA:34
	MOS	11-Aug-20						
	HRS	5942.6	3000					
WC#: 34.975	AFL	3569						
								PKG:22
PROC. REF: AMM 34-21-13-100-801PROC. REF: AMM 34-21-13-100-801								
34-21-13-100-801-03 S	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 3 FAN FILTER							Service ATA:34
	MOS	11-Aug-20						
	HRS	5942.6	3000					
WC#: 34.975	AFL	3569						
								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-21-13-100-801PROC. REF: AMM 34-21-13-100-801								
34-22-00-710-801-01	OPERATIONAL TEST OF THE ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS)							Service ATA:34
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 34.980	AFL	0						
PROC. REF: AMM 34-22-00-710-801, AMM 34-22-00-710-801PROC. REF: AMM 34-22-00-710-801, AMM 34-22-00-710-801								
34-26-01-710-801-01	OPERATIONAL TEST OF THE HEADING REFERENCE SYSTEM FLUX VALVES - HDG 1 FLUX VALVE (11FF)							Service ATA:34
PN:622-8154-001	MOS/MSC	15-Jul-96	O/C					
SN:602	HRS	0						
WC#: 34.390	AFL	0						
PROC. REF: AMM 34-26-01-710-801PROC. REF: AMM 34-26-01-710-801								
34-26-01-710-801-02	OPERATIONAL TEST OF THE HEADING REFERENCE SYSTEM FLUX VALVES - HDG 2 FLUX VALVE (21FF)							Service ATA:34
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 34.390	AFL	0						
PROC. REF: AMM 34-26-01-710-801PROC. REF: AMM 34-26-01-710-801								
34-26-05-900-801-01	REMOVAL / INSTALLATION OF THE DIRECTIONAL GYROS - DIRECTIONAL GYRO 1 (12FF)							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.350	AFL	0		TSN 0				
PROC. REF: AMM 34-26-05-900-801PROC. REF: AMM 34-26-05-900-801								
34-26-05-900-801-02	REMOVAL / INSTALLATION OF THE DIRECTIONAL GYROS - DIRECTIONAL GYRO 2 (22FF)							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.350	AFL	0		TSN 0				
PROC. REF: AMM 34-26-05-900-801PROC. REF: AMM 34-26-05-900-801								
34-27-01-900-801-01	REMOVAL / INSTALLATION OF THE VERTICAL GYROS - VERTICAL GYRO 1 (13FV)							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.460	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-27-01-900-801PROC. REF: AMM 34-27-01-900-801								
34-27-01-900-801-02	REMOVAL / INSTALLATION OF THE VERTICAL GYROS - VERTICAL GYRO 2 (23FV)							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.460	AFL	0		TSN 0				
PROC. REF: AMM 34-27-01-900-801PROC. REF: AMM 34-27-01-900-801								
34-41-01-900-801-01	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.380	AFL	0		TSN 0				
PROC. REF: AMM 34-41-01-900-801, AMM 34-41-01-900-801PROC. REF: AMM 34-41-01-900-801, AMM 34-41-01-900-801								
34-41-05-900-801-01	REMOVAL / INSTALLATION OF THE WEATHER RADAR ANTENNA - WEATHER RADAR ANTENNA (3SQ)							Component ATA:34
PN:622-8441-003	MOS/MSC	03-Sep-15	O/C	TSO 6				
SN:1732	HRS	4916.3		TSO 0				
WC#: 34.750	AFL	3077		TSO 0				
PROC. REF: AMM 34-41-05-900-801PROC. REF: AMM 34-41-05-900-801								
34-42-00-710-801-01	OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 1 SYSTEM							Service ATA:34
	MOS/MSC	08-May-14	N/A					
	HRS	4694.5						
	AFL	2957						
PROC. REF: AMM 34-42-00-710-801, AMM 34-42-00-710-801PROC. REF: AMM 34-42-00-710-801, AMM 34-42-00-710-801								
34-42-00-710-801-02	OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 2 SYSTEM							Service ATA:34
	MOS/MSC	23-Oct-13	N/A					
	HRS	4569.5						
	AFL	2879						
PROC. REF: AMM 34-42-00-710-801, AMM 34-42-00-710-801PROC. REF: AMM 34-42-00-710-801, AMM 34-42-00-710-801								
34-42-01-900-801-01	NO. 1 RADIO ALTIMETER RECEIVER/TRANSMITTER							Component ATA:34
PN:622-2855-011	MOS/MSC	08-May-14	O/C					
SN:10114	HRS	4694.25						
WC#: 34.010	AFL	2957						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801								
34-42-01-900-801-02	NO. 2 RADIO ALTIMETER RECEIVER/TRANSMITTER							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.015	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801								
34-44-01-900-801-01	REMOVAL / INSTALLATION OF THE TCAS TRANSCEIVER - TCAS TRANSCEIVER (350NP)							Component ATA:34
PN:622-1293-033	MOS/MSC	31-Aug-23	O/C	TSR 0				
SN:145875	HRS	6528		TSR 0				
WC#: 34.400	AFL	3832		TSR 0				
PROC. REF: AMM 34-44-01-900-801PROC. REF: AMM 34-44-01-900-801								
34-44-05-900-801-01	REMOVAL / INSTALLATION OF THE TCAS ANTENNAS - LOWER TCAS ANTENNA (356NP)							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-44-05-900-801PROC. REF: AMM 34-44-05-900-801								
34-44-05-900-801-02	REMOVAL / INSTALLATION OF THE TCAS ANTENNAS - UPPER TCAS ANTENNA (354NP)							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-44-05-900-801PROC. REF: AMM 34-44-05-900-801								
34-51-01-820-801-01	CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 1 RECEIVER (L210NR) / (12RS)							Service ATA:34
PN:622-7194-201	MOS	24-Oct-25	25 (+3%)		24-Nov-27	16-Dec-27	411 d (+22)	
SN:5227	HRS	6700.5						
WC#: 34.700	AFL	3940						
PROC. REF: AMM 34-51-01-820-801PROC. REF: AMM 34-51-01-820-801								
34-51-01-820-801-02	CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 2 RECEIVER (R210NR) / (22RS)							Service ATA:34
PN:622-7194-201	MOS	24-Oct-25	25 (+3%)		24-Nov-27	16-Dec-27	411 d (+22)	
SN:18MTN	HRS	6700.5						
WC#: 34.700	AFL	3940						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-51-01-820-801PROC. REF: AMM 34-51-01-820-801								
34-51-05-900-801-01	REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - LH VOR/LOC ANTENNA (L230NR)							Component ATA:34
PN:DMN4-15-3D	MOS/MSC	11-Jul-95	O/C					
SN:24913	HRS	0		TSN 0				
WC#: 34.720	AFL	0						
PROC. REF: AMM 34-51-05-900-801PROC. REF: AMM 34-51-05-900-801								
34-51-05-900-801-02	REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - RH VOR/LOC ANTENNA (R230NR)							Component ATA:34
PN:DMN4-15-3D	MOS/MSC	11-Jul-95	O/C					
SN:24930	HRS	0		TSN 0				
WC#: 34.720	AFL	0						
PROC. REF: AMM 34-51-05-900-801PROC. REF: AMM 34-51-05-900-801								
34-52-05-900-801-01	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 1 ANTENNA (13RV) OR (L330NR)							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	08-May-14	O/C	TSN 3				
SN:135086	HRS	4694.25		TSN 0				
	AFL	2957		TSN 0				
PROC. REF: AMM 34-52-05-900-801PROC. REF: AMM 34-52-05-900-801								
34-52-05-900-801-02	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 2 ANTENNA (23RV) OR (R330NR)							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	08-May-14	O/C	TSN 3				
SN:135085	HRS	4694.25		TSN 0				
	AFL	2957		TSN 0				
PROC. REF: AMM 34-52-05-900-801PROC. REF: AMM 34-52-05-900-801								
34-54-00-700-881-01	TEST NO. 1 ATC TRANSPONDER (FAR 91.413)							Service ATA:34
PN:622-9210-501	MOS	07-Oct-24	24		22-Aug-26	OVD		MANDATORY
SN:5459	HRS	6606.8						
WC#: 34.820	AFL	3879						
		Test Date: : 22-Aug-24						
PROC. REF: GENERIC NO REF, FAR 91.413PROC. REF: GENERIC NO REF, FAR 91.413								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-54-00-700-881-02	TEST NO. 2 ATC TRANSPONDER (FAR 91.413)							Service ATA:34
PN:622-9210-501	MOS	07-Oct-24	24		22-Aug-26		OVD	MANDATORY
SN:4HWTN	HRS	6606.8						
WC#: 34.820	AFL	3879						
			Test Date: : 22-Aug-24					
PROC. REF: GENERIC NO REF, FAR 91.413PROC. REF: GENERIC NO REF, FAR 91.413								
34-54-00-720-802-01	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM PERIODIC TESTS							Service ATA:34
PN:622-9210-501	MOS	07-Oct-24	24 (+3%)		07-Oct-26	29-Oct-26	TOL (+20 d)	
SN:5459	HRS	6606.8						
WC#: 34.820	AFL	3879						
PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802								
34-54-00-720-802-02	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM PERIODIC TESTS							Service ATA:34
PN:622-9210-501	MOS	07-Oct-24	24 (+3%)		07-Oct-26	29-Oct-26	TOL (+20 d)	
SN:4HWTN	HRS	6606.8						
WC#: 34.820	AFL	3879						
PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802PROC. REF: AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802, AMM 34-54-00-720-802								
34-58-01-710-881-01	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)							Service ATA:34
	MOS/MSC		A/R					
	HRS	0						
WC#: 34.725	AFL	0						
PROC. REF: GENERIC NO REF, FAR 91.171PROC. REF: GENERIC NO REF, FAR 91.171								
34-61-01-900-801-01	REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 1 (L110NG)							Component ATA:34
PN:3017-41-221	MOS/MSC	11-Aug-25	O/C					
SN:162	HRS	6680.7		TSR 32.1				
WC#: 34.960	AFL	3931		TSR 22				
PROC. REF: AMM 34-61-01-900-801PROC. REF: AMM 34-61-01-900-801								
34-61-01-900-801-02	REMOVAL / INSTALLATION OF THE FMS COMPUTER (COLLINS) - FMC 2 (R110NG)							Component ATA:34
PN:3017-41-221	MOS/MSC	22-Oct-25	O/C	TSR 0				
SN:1037	HRS	6700.5		TSR 0				
WC#: 34.960	AFL	3940		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-61-01-900-801PROC. REF: AMM 34-61-01-900-801								
34-61-05-900-802-01	REMOVAL / INSTALLATION OF THE DATA MANAGEMENT UNIT (DMU)							Component ATA:34
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 34-61-01-900-803, GENERIC NO REFPROC. REF: AMM 34-61-01-900-803, GENERIC NO REF								
34-61-05-900-803-01	REMOVAL / INSTALLATION OF THE DATA MANAGEMENT UNIT (DMU) INTERNAL BATTERY							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34-66-01-900-801-01	REMOVAL / INSTALLATION OF THE INERTIAL NAVIGATION UNITS (INU) - INU 1 (1FP)							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.860	AFL	0		TSN 0				
PROC. REF: AMM 34-66-01-900-801PROC. REF: AMM 34-66-01-900-801								
340001 U	CALIBRATE STAND-BY COMPASS							Service ATA:34
PN:KCA0105W	MOS	02-Oct-24	24		02-Oct-26		OVD	
SN:AF461	HRS	6601.6						
	AFL	3875						
341008	NO.1 ANALOGIC/DIGITAL CONVERTER							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.990	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341009	NO.2 ANALOGIC/DIGITAL CONVERTER							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.020	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341011	NO. 1 RADIO ALTIMETER INDICATOR							Component ATA:34
PN:622-2937-008	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.020	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341014	NO. 2 RADIO ALTIMETER INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.951	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341015	NO.1 RADIO ALTIMETER RECEIVER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.030	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801								
341016	NO.2 RADIO ALTIMETER RECEIVER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.030	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801								
341017	NO.1 RADIO ALTIMETER TRANSMITTER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.040	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801PROC. REF: AMM 34-42-01-900-801, AMM 34-42-01-900-801								
341018	NO.2 RADIO ALTIMETER TRANSMITTER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.040	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-42-09-900-801PROC. REF: AMM 34-42-09-900-801								
341021	RADIO ALTIMETER ANTENNA							Component ATA:34
PN:622-6793-001	MOS/MSC	17-Jul-96	O/C					
SN:2267	HRS	150		TSN 0				
WC#: 34.020	AFL	62						
PROC. REF: AMM 34-42-09-900-801PROC. REF: AMM 34-42-09-900-801								
341029 U	RADIO ALT NO.2 ANTENNA							Component ATA:34
PN:622-6793-001	MOS/MSC	17-Jul-96	O/C					
SN:2268	HRS	150						
	AFL	62						
341033	STANDBY AIR DATA UNIT							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.560	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341041	STANDBY MACH-AIRSPEED INDICATOR							Component ATA:34
PN:64032-229-1	MOS/MSC	08-May-14	O/C					
SN:1310	HRS	4694.25						
WC#: 34.535	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341101	PILOT AIRSPEED/MACH INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.030	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341111	COPILOT AIRSPEED/MACH INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.030	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341121	PILOT ALTIMETER							Component ATA:34
PN:622-3975-005	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341126	COPILOT ALTIMETER							Component ATA:34
PN:622-3975-005	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341131	PILOT RATE OF CLIMB INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341141	COPILOT RATE OF CLIMB INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341151	TOTAL TEMPERATURE INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.070	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341191	STATIC PRESSURE SELECTOR VALVE							Component ATA:34
PN:919ZEQ4	MOS/MSC	11-Jul-95	O/C					
SN:1131	HRS	0		TSN 0				
WC#: 34.130	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341193	DUAL CUT-OFF VALVE							Component ATA:34
PN:914A01	MOS/MSC	11-Jul-95	O/C					
SN:725	HRS	0		TSN 0				
WC#: 34.140	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341196	ALTITUDE ALERTER							Component ATA:34
PN:622-2923-005	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341236	PILOT AIR DATA COMPUTER REFERENCE PANEL							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341241	COPILOT AIR DATA COMPUTER REFERENCE PANEL							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341351	REMOVAL/INSTALLATION OF STATIC PRESSURE PROBES							Service ATA:34
	MOS/MSC	11-Jul-95	A/R					
	HRS	0						
WC#: 34.945	AFL	0						
PROC. REF: AMM 34-11-05-900-801PROC. REF: AMM 34-11-05-900-801								
341836 U	REFERENCE ADC PILOT PANEL							Component ATA:34
PN:822-0326-002	MOS/MSC	17-Jul-96	O/C					
SN:460	HRS	150						
	AFL	62						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341838 U	REFERENCE ADC CPLT PANEL							Component ATA:34
PN:822-0326-002	MOS/MSC	17-Jul-96	O/C					
SN:516	HRS	150						
	AFL	62						
342001	STAND-BY COMPASS							Component ATA:34
PN:KCA0105W	MOS/MSC	11-Jul-95	O/C					
SN:AF461	HRS	0		TSN 0				
WC#: 34.340	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342037	STAND-BY HORIZON							Component ATA:34
PN:501-1197-25	MOS/MSC	27-Feb-13	O/C	TSO 0				
SN:5801	HRS	4319.3		TSO 0				
WC#: 34.370	AFL	2752		TSO 0				
PROC. REF: AMM 34-23-00-900-801, AMM 34-23-00-900-801PROC. REF: AMM 34-23-00-900-801, AMM 34-23-00-900-801								
342041	NO. 1 HEADING REFERENCE SYSTEM (HDG 1) FLUX VALVE							Component ATA:34
PN:622-8154-001	MOS/MSC	17-Jul-96	O/C					
SN:602	HRS	150						
WC#: 34.390	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342051	NO. 2 HEADING REFERENCE SYSTEM (HDG 2) FLUX VALVE							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.390	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342061	LH COMPASS COUPLER							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.360	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342066	RH COMPASS COUPLER							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.360	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342071	PILOT FLIGHT DIRECTOR MODE SELECTOR							Component ATA:34
PN:622-2313-053	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.400	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342072	REPLACEMENT MAINTENANCE DIAGNOSTIC COMPUTER (MDC) MODULE BATTERY							Service ATA:34
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 34.946	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342081	COPILOT FLIGHT DIRECTOR MODE SELECTOR							Component ATA:34
PN:622-2313-053	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.400	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342091	PILOT RMI INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.420	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342101	COPILOT RMI INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.420	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342111	PILOT FLIGHT DIRECTOR INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342121	COPILOT FLIGHT DIRECTOR INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342131	PILOT COMPASS HEADING CONTROL BOX							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342141	COPILOT COMPASS HEADING CONTROL BOX							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.450	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342151	PILOT FLIGHT DIRECTOR COMPUTER							Component ATA:34
PN:622-5224-001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.410	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342161	COPILOT FLIGHT DIRECTOR COMPUTER							Component ATA:34
PN:622-5224-001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.410	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342191	PILOT ACCELEROMETER							Component ATA:34
PN:229-0324-010	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.470	AFL	0						
PROC. REF: AMM 31-31-38-900-801	PROC. REF: AMM 31-31-38-900-801							
342197	COPILOT ACCELEROMETER							Component ATA:34
PN:229-0324-010	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.470	AFL	0						
PROC. REF: AMM 31-31-38-900-801	PROC. REF: AMM 31-31-38-900-801							
342226	COURSE SELECTOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.500	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
342231	RATE OF TURN GYRO							Component ATA:34
PN:622-0181-001	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.480	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
342260	REPLACEMENT PILOT AIR DATA (ADC) COMPUTER BATTERY							Service ATA:34
PN:822-1036-466	MOS/MSC	08-Sep-22	O/C					
SN:3295	HRS	6221.1		TAC 0				
WC#: 34.948	AFL	3722		TAC 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
342266	PILOT HORIZONTAL SITUATION (HSI) INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342276	COPILOT HORIZONTAL SITUATION (HSI) INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342296	REPLACEMENT COPILOT AIR DATA (ADC) COMPUTER BATTERY							Service ATA:34
PN:822-1036-466	MOS/MSC	04-Jan-17	O/C					
SN:2772	HRS	5149.6						
WC#: 34.948	AFL	3244						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342331	PILOT DISPLAY (DCP) CONTROL							Component ATA:34
PN:822-0321-002	MOS/MSC	17-Jul-96	O/C					
SN:513	HRS	150		TSN 0				
WC#: 34.570	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342371	COPILOT DISPLAY CONTROL (DCP) PANEL							Component ATA:34
PN:822-0321-002	MOS/MSC	17-Jul-96	O/C					
SN:514	HRS	150		TSN 0				
WC#: 34.570	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342401	COURSE HEADING PANEL							Component ATA:34
PN:622-6404-002	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.620	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342411	WEATHER RADAR CONTROL (WXP) PANEL							Component ATA:34
PN:622-6092-012	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.600	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342451	PILOT REVERSION SWITCH (RSP) PANEL							Component ATA:34
PN:822-0273-002	MOS/MSC	15-Dec-03	O/C	TSO 12				
SN:483	HRS	1956.8		TSO 0				
WC#: 34.580	AFL	1377		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342461	COPILOT REVERSION SWITCH (RSP) PANEL							Component ATA:34
PN:622-6383-002	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.580	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342501	PILOT F/D INDIC./SITUATION INDIC. (EADI/EHSI) BLOWER							Component ATA:34
PN:030002	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.670	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342506	COPILOT F/D INDIC./SITUATION INDIC. (EADI/EHSI) BLOWER							Component ATA:34
PN:030002	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.670	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342511	MULTIFUNCTION CATHODE RAY TUBE DISPLAY (MFB) BLOWER							Component ATA:34
PN:030002	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.690	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342516	PILOT DISPLAY PROCESSOR UNIT (DPU) BLOWER							Component ATA:34
PN:026955	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.680	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342521	COPILOT DISPLAY PROCESSOR UNIT (DPU) BLOWER							Component ATA:34
PN:026955	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.680	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342526	MULTIFUNCTION DISPLAY PROCESSOR UNIT (MPU) BLOWER							Component ATA:34
PN:026949	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 34.690	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342601	LONGITUDINAL ACCELEROMETER							Component ATA:34
PN:229-0324-020	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.490	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342830 U	COMPENSATOR RIGHT VALVE							Component ATA:34
PN:622-6189-002	MOS/MSC	17-Jul-96	O/C					
SN:2143	HRS	150						
	AFL	62						
342860 U	SAT COMM ANTENNA							Component ATA:34
PN:S67-1575-165	MOS/MSC	08-May-14	O/C	TSN 3				
SN:449-6626	HRS	4694.25		TSN 0				
	AFL	2957		TSN 0				
342901	LH CONFIGURATION (CSU) MODULE							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342902	RH CONFIGURATION (CSU) MODULE							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342905	INTERGRATED AVIONICS SYSTEM PROCESSOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.180	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342911	LH UPPER INPUT/OUTPUT CONCENTRATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342912	LH LOWER INPUT/OUTPUT CONCENTRATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342913	RH UPPER INPUT/OUTPUT CONCENTRATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342914	RH LOWER INPUT/OUTPUT CONCENTRATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
342921	EFIS INPUT/OUTPUT CONCENTRATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.210	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342935	SECONDARY FLIGHT DISPLAY							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.570	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342945	PILOT REVERSIONARY CONTROL							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342946	COPILOT REVERSIONARY CONTROL							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342947	PILOT DISPLAY CONTROL							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342948	COPILOT DISPLAY CONTROL							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.260	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
343001	NO. 1 VOR/ILS/MKR RECEIVER							Component ATA:34
PN:622-7194-201	MOS/MSC	24-Oct-25	O/C	TSO 0				
SN:5227	HRS	6700.5		TSO 0				
WC#: 34.700	AFL	3940		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
343011	NO. 2 VOR/ILS/MKR RECEIVER							Component ATA:34
PN:622-7194-201	MOS/MSC	24-Oct-25	O/C	TSO 0				
SN:18MTN	HRS	6700.5		TSO 0				
WC#: 34.700	AFL	3940		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
343021	VOR/ILS/MKR1/DME1/VHF1 CONTROL							Component ATA:34
PN:G6286	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.710	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
343023	VOR/ILS/MKR2/DME2/ATC1/ATC2 CONTROL							Component ATA:34
PN:G-4876A	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.710	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
343041	MARKER ANTENNA							Component ATA:34
PN:DMN27-1A	MOS/MSC	08-May-14	O/C					
SN:3111	HRS	4694.25						
WC#: 34.730	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
343051	GLIDESLOPE ANTENNA							Component ATA:34
PN:DMN25-2	MOS/MSC	11-Jul-95	O/C					
SN:3465	HRS	0		TSN 0				
WC#: 34.730	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
344001	RADAR TRANSCEIVER							Component ATA:34
PN:622-8441-003	MOS/MSC	16-Feb-11	O/C	TSN 187				
SN:1545	HRS	2655.4		TSN 2655.4				
WC#: 34.740	AFL	2404		TSN 2404				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344003	WEATHER RADAR CONTROL							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.390	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344011	RADAR INDICATOR							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.760	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344086	NO.1 ATC UPPER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344087	NO.2 ATC UPPER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.430	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344088	NO.1 ATC LOWER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
344089	NO.2 ATC LOWER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.440	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345001	NO. 1 VLF/OMEGA RECEIVER/ COMPUTER							Component ATA:34
PN:10050-3-2AD	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.770	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345011	NO. 2 VLF/OMEGA RECEIVER/ COMPUTER							Component ATA:34
PN:10050-3-2AD	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.780	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345021	NO. 1 OMEGA CONTROL AND DISPLAY UNIT							Component ATA:34
PN:10600-6	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.770	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345031	NO. 2 OMEGA CONTROL AND DISPLAY UNIT							Component ATA:34
PN:10600-6	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.780	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345041	NO. 1 VLF/OMEGA ANTENNA							Component ATA:34
PN:11455-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.790	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345051	NO. 2 VLF/OMEGA ANTENNA							Component ATA:34
PN:11455-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.790	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345061	NO. 1 OMEGA OPTIONAL EQUIPMENT UNIT							Component ATA:34
PN:10600-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.770	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345071	NO. 2 OMEGA OPTIONAL EQUIPMENT UNIT							Component ATA:34
PN:10600-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.780	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345086	NO. 1 ADF RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	17-Jul-96	O/C					
SN:3472	HRS	150		TSN 0				
WC#: 34.800	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345096	NO. 2 ADF RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	17-Jul-96	O/C					
SN:3477	HRS	150		TSN 0				
WC#: 34.800	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345106	ADF1/ADF2 CONTROL UNIT							Component ATA:34
PN:G6095	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.810	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345126	NO. 1 ADF ANTENNA							Component ATA:34
PN:622-7383-001	MOS/MSC	17-Jul-96	O/C					
SN:2324	HRS	150		TSN 0				
WC#: 34.810	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345136	NO. 2 ADF ANTENNA							Component ATA:34
PN:622-7383-001	MOS/MSC	17-Jul-96	O/C					
SN:2035	HRS	150		TSN 0				
WC#: 34.810	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345181	NO. 1 ATC TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	08-Sep-22	O/C					
SN:5459	HRS	6221.1		TSR 0				
WC#: 34.820	AFL	3722		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345196	NO. 1 ATC ANTENNA							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	08-May-14	O/C					
SN:60510	HRS	4694.2						
WC#: 34.830	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345206	NO. 2 ATC TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	25-May-17	O/C					
SN:4HWTN	HRS	5157.3						
WC#: 34.820	AFL	3249						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345221	NO. 2 ATC ANTENNA							Component ATA:34
PN:DMNI50-2-2	MOS/MSC	08-May-14	O/C					
SN:60511	HRS	4694.2						
WC#: 34.830	AFL	2957						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345231	NO. 1 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	02-Dec-14	O/C	TSO 0				
SN:4793	HRS	4828.1		TSO 0				
WC#: 34.840	AFL	3016		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345241	NO. 2 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	17-Jul-96	O/C					
SN:2315	HRS	150		TSN 0				
WC#: 34.840	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346006	MODE SELECTOR (MSU) UNIT							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.870	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346008 U	MODE INS #2 SELECTOR UNIT							Component ATA:34
PN:CG1042AB03	MOS/MSC	17-Jul-96	O/C					
SN:96011847	HRS	150						
	AFL	62						
346011	CONTROL DISPLAY (CDU) UNIT							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.870	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346016	INS BATTERY							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.890	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346026	INS BLOWER							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.880	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346036	INS CARD READER							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.880	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346045	DATA TRANSFER UNIT							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.510	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346050	NAV DATA INTERFACE							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.650	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346053	NAV DATA MEMORY MODULE							Component ATA:34
PN:22150-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.650	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346064 U	CABIN DISPLAY CONTROL							Component ATA:34
PN:911010-2	MOS/MSC	17-Jul-96	O/C					
SN:670	HRS	150						
	AFL	62						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346066 U	AIRSHOW INTERFACE UNIT							Component ATA:34
PN:920050	MOS/MSC	24-Jul-08	O/C	TSR 0				
SN:509	HRS	3036.1		TSR 0				
	AFL	2036		TSR 0				
346106	NO. 1 IRS MODE SELECTOR (MSU 1) UNIT							Component ATA:34
PN:CG1042AB03	MOS/MSC	17-Jul-96	O/C					
SN:94071591	HRS	150		TSN 0				
WC#: 34.910	AFL	62						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346116	NO. 2 IRS MODE SELECTOR (MSU 2) UNIT							Component ATA:34
PN:CG1042AB03	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.910	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346126	NO. 3 IRS MODE SELECTOR (MSU 3) UNIT							Component ATA:34
PN:CG1042AB03	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.910	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346131	IRS CONTROL DISPLAY (ISDU) PANEL							Component ATA:34
PN:CG1230AC10	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.920	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346151	NO. 1 IRS BLOWER							Component ATA:34
PN:10089782-103	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.930	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346156	NO. 1 IRS BLOWER FILTER							Component ATA:34
PN:10090306-101	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.940	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346166	NO. 2 IRS BLOWER							Component ATA:34
PN:10089782-103	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.930	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346171	NO. 2 IRS BLOWER FILTER							Component ATA:34
PN:10090306-101	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.940	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346181	NO. 3 IRS BLOWER							Component ATA:34
PN:10089782-103	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.930	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346186	NO. 3 IRS BLOWER FILTER							Component ATA:34
PN:10090306-101	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.940	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346241	NO.1 GLOBAL POSISTIONING SENSING ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.530	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346246	NO.2 GLOBAL POSISTIONING SENSING ANTENNA							Component ATA:34
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.530	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346303	REPLACEMENT FMC 1 (FLIGHT MANAGEMENT COMPUTER) BATTERY							Service ATA:34
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 34.949	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346306	NO. 1 FMS CONTROL DISPLAY UNIT							Component ATA:34
PN:3017-41-221	MOS/MSC	13-Apr-22	O/C	TSR 0				
SN:162	HRS	6152.5		TSR 0				
WC#: 34.970	AFL	3694		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346313	REPLACEMENT FMC 2 (FLIGHT MANAGEMENT COMPUTER) BATTERY							Service ATA:34
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 34.949	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346316	NO. 2 FMS CONTROL DISPLAY UNIT							Component ATA:34
PN:3017-41-221	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:149	HRS	3036.1		TSN 0				
WC#: 34.970	AFL	2036		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346806 U	CONFIG FMS #1 MODULE							Component ATA:34
PN:30171	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:148	HRS	3036.1		TSN 0				
	AFL	2036		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346811 U	CONFIG FMS #2 MODULE							Component ATA:34
PN:30171	MOS/MSC	24-Jul-08	O/C	TSN 0				
SN:149	HRS	3036.1		TSN 0				
	AFL	2036		TSN 0				
346863 U	AFIS DATA MANAGEMENT UNIT							Component ATA:34
PN:400-45500-003	MOS/MSC	20-May-04	O/C	TSN 106, TSR 0				
SN:1176	HRS	2042.4		TSN 2042.4, TSR 0				
	AFL	1436		TSN 1436, TSR 0				
346869 U	CONFIGURATION AFIS MODULE							Component ATA:34
PN:31990-1	MOS/MSC	17-Jul-96	O/C					
SN:4399	HRS	150						
	AFL	62						
347824 U	SATCOM TRANSCEIVER							Component ATA:34
PN:153-017311-01	MOS/MSC	17-Jul-96	O/C					
SN:451	HRS	150						
	AFL	62						
347826 U	GNSX DTU CONTROL							Component ATA:34
PN:15655-0101	MOS/MSC	17-Jul-96	O/C					
SN:886	HRS	150						
	AFL	62						
347830 U	HPA/LNA AMPLIFIER							Component ATA:34
PN:153-017310-01	MOS/MSC	17-Jul-96	O/C					
SN:440	HRS	150						
	AFL	62						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
347832 U	GPS #1 ANTENNA							Component ATA:34
PN:10708	MOS/MSC	08-May-14	O/C					
SN:5264	HRS	4694.25						
	AFL	2957						
347836 U	GPS #2 ANTENNA							Component ATA:34
PN:10708	MOS/MSC	08-May-14	O/C					
SN:5265	HRS	4694.25						
	AFL	2957						
347873 U	TCAS #1 ANTENNA							Component ATA:34
PN:622-8973-001	MOS/MSC	08-May-14	O/C	TSO 11				
SN:1X77H	HRS	4694.25		TSO 0				
	AFL	2957		TSO 0				
347875 U	TCAS #2 ANTENNA							Component ATA:34
PN:622-8973-001	MOS/MSC	31-Aug-16	O/C	TSN 0				
SN:47YDF7	HRS	5106.6		TSN 0				
	AFL	3227		TSN 0				
347881 U	TCAS TRANSCEIVER							Component ATA:34
PN:822-1293-033	MOS/MSC	25-May-17	O/C					
SN:151667	HRS	5157.3						
	AFL	3249						
347889 U	RADIO ALTIMETER ADAPTER							Component ATA:34
PN:622-7209-002	MOS/MSC	17-Jul-96	O/C					
SN:928	HRS	150						
	AFL	62						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
347A01 U	ACQUISITION DATA UNIT							Component ATA:34
PN:822-1075-001	MOS/MSC	26-Mar-97	O/C					
SN:186	HRS	399		TSN 0				
	AFL	260						
ATA 35 - OXYGEN								
35-10-05-350-801-01	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - LH PILOT OXYGEN MASK (L502WH)							Service ATA:35
PN:MA10-12-00	MOS	23-Jan-24	72 (+3%)		23-Jan-30	27-Mar-30	1202 d (+63)	OVERHAUL
SN:77581	HRS	6535.8						
WC#: 35.080	AFL	3839						
PROC. REF: AMM 35-10-05-350-801	PROC. REF: AMM 35-10-05-350-801							
35-10-05-350-801-02	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - RH PILOT OXYGEN MASK (R502WH)							Service ATA:35
PN:MA10-12-00	MOS	19-Nov-21	72 (+3%)		19-Nov-27	23-Jan-28	406 d (+65)	OVERHAUL
SN:43005	HRS							
WC#: 35.080	AFL							
PROC. REF: AMM 35-10-05-350-801	PROC. REF: AMM 35-10-05-350-801							
35-10-05-350-801-03	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - THIRD CREW MEMBER OXYGEN MASK (524WH)							Service ATA:35
PN:289-601-228	MOS/MSC	30-Jan-12	O/C					
SN:UNKNOWN	HRS	3968.8						
WC#: 35.180	AFL	2560						
PROC. REF: AMM 35-10-05-350-801	PROC. REF: AMM 35-10-05-350-801							
35-10-05-710-801-01 S	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)							Service ATA:35
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 35.080	AFL	3940						
								PKG:207
PROC. REF: AMM 35-10-05-710-801	PROC. REF: AMM 35-10-05-710-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-10-05-710-801-02	S	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)						Service ATA:35
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 35.080	AFL	3940						
								PKG:207
PROC. REF: AMM 35-10-05-710-801	PROC. REF: AMM 35-10-05-710-801							
35-10-05-710-801-03	S	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)						Service ATA:35
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 35.180	AFL	3940						
								PKG:207
PROC. REF: AMM 35-10-05-710-801	PROC. REF: AMM 35-10-05-710-801							
35-10-05-900-801-01		REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)						Component ATA:35
PN:MA10-12-00	MOS/MSC	23-Jan-24	H/T	TSO 0				
SN:77581	HRS	6535.8		TSO 0				
WC#: 35.080	AFL	3839		TSO 0				
PROC. REF: AMM 35-10-05-900-801	PROC. REF: AMM 35-10-05-900-801							
35-10-05-900-801-02		REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)						Component ATA:35
PN:MA10-12-00	MOS/MSC	05-Jan-22	H/T	TSO 2				
SN:43005	HRS	6119.7		TSO 0				
WC#: 35.080	AFL	3679		TSO 0				
PROC. REF: AMM 35-10-05-900-801	PROC. REF: AMM 35-10-05-900-801							
35-10-05-900-801-03		REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)						Component ATA:35
PN:289-601-228	MOS/MSC	17-Jul-96	O/C					
SN:UNKNOWN	HRS	150						
WC#: 35.180	AFL	62						
PROC. REF: AMM 35-10-05-900-801	PROC. REF: AMM 35-10-05-900-801							
35-20-00-210-801-01	S	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS - PASSENGER OXYGEN MASK (9510WJ)						Service ATA:35
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 35.205	AFL	3875						
								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-20-00-210-801	PROC. REF: AMM 35-20-00-210-801							
35-20-00-720-801-01 S	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM							Service ATA:35
	MOS	08-Aug-25						
	HRS	6680.7	1500 (+30)					
WC#: 35.010	AFL	3931						
								PKG:21
PROC. REF: AMM 35-20-00-720-801	PROC. REF: AMM 35-20-00-720-801							
35-20-01-350-801-01	RESTORATION OF THE PASSENGER OXYGEN CONTROLLER (OVERHAUL) - PASSENGER OXYGEN CONTROLLER (1WH)							Service ATA:35
PN:RCA70	MOS	08-Aug-25	72 (+3%)		08-Aug-31	12-Oct-31	1764 d (+65)	OVERHAUL
SN:980	HRS	6680.7						
WC#: 35.100	AFL	3931						
PROC. REF: AMM 35-20-01-350-801	PROC. REF: AMM 35-20-01-350-801							
35-20-01-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER OXYGEN CONTROLLER							Component ATA:35
PN:RCA70	MOS/MSC	08-Aug-25	H/T	TSO 0				
SN:980	HRS	6680.7		TSO 0				
WC#: 35.100	AFL	3931		TSO 0				
PROC. REF: AMM 35-20-01-900-801	PROC. REF: AMM 35-20-01-900-801							
35-20-09-900-801-01	NO. 1 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-228	MOS/MSC	25-May-17	O/C	TSN 0				
SN:UNKNOWN	HRS	5157.3		TSN 0				
WC#: 35.110	AFL	3249		TSN 0				
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 10 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.140	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-20-09-900-801-01	NO. 11 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.140	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 12 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.140	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 2 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.110	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 3 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.110	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 4 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.120	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 5 PASSENGER OXYGEN MASK							Component ATA:35
PN:289-601-228	MOS/MSC	25-May-17	O/C	TSN 0				
SN:UNKNOWN	HRS	5157.3		TSN 0				
WC#: 35.120	AFL	3249		TSN 0				
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-20-09-900-801-01	NO. 6 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.120	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 7 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.130	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 8 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.130	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	NO. 9 PASSENGER OXYGEN MASK							Component ATA:35
PN:MW3514	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.130	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	THERAPEUTIC OXYGEN MASK							Component ATA:35
PN:MW3511	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.150	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							
35-20-09-900-801-01	TOILET OXYGEN MASK							Component ATA:35
PN:MW3511	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.150	AFL	0						
PROC. REF: AMM 35-20-09-900-801	PROC. REF: AMM 35-20-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-30-01-960-801-01	DISCARD OF THE SMOKE HOOD - SMOKE HOOD (508WH)							Service ATA:35
	MOS/MSC		O/C					
	HRS							
WC#: 35.190	AFL							
PROC. REF: AMM 35-30-01-960-801	PROC. REF: AMM 35-30-01-960-801							
35-30-05-210-801-01	GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)							Service ATA:35
PN:894-20330	MOS	24-Oct-25	12 (+3%)		24-Oct-26	04-Nov-26	15 d (+11)	
SN:144188	HRS	6700.5						
WC#: 35.170	AFL	3940						
PROC. REF: AMM 35-30-05-210-801	PROC. REF: AMM 35-30-05-210-801							
35-30-05-350-801-01	RESTORATION OF THE PORTABLE OXYGEN BOTTLE (OVERHAUL) - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)							Service ATA:35
PN:894-20330	MOS	30-Apr-24	60 (+3%)		30-Apr-29	24-Jun-29	934 d (+55)	OVERHAUL
SN:144188	HRS	6553						
	AFL	3851						
			HydroCheck Date: : 30-Apr-24					
PROC. REF: AMM 35-30-05-350-801	PROC. REF: AMM 35-30-05-350-801							
35-30-05-960-801-01	DISCARD OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)							Service ATA:35
PN:894-20330	MOS	30-Apr-24	300		30-Apr-49		8239 d	LIFE LIMIT
SN:144188	HRS	6553						
WC#: 35.030	AFL	3851						
PROC. REF: AMM 35-30-05-960-801	PROC. REF: AMM 35-30-05-960-801							
35-30-09-100-801-01	CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)							Service ATA:35
PN:894-20330	MOS	24-Oct-25	12 (+3%)		24-Oct-26	04-Nov-26	15 d (+11)	
SN:144188	HRS	6700.5						
WC#: 35.030	AFL	3940						
PROC. REF: AMM 35-30-09-100-801	PROC. REF: AMM 35-30-09-100-801							
35-40-01-790-801-01	HYDROSTATIC TEST OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)							Service ATA:35
PN:GST2151	MOS	29-Jun-26	36		29-Jun-29		994 d	MANDATORY
SN:N549786	HRS	6756.3						
WC#: 35.020	AFL	3988						
			HydroCheck Date: : 29-Jun-26					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-40-01-790-801PROC. REF: AMM 35-40-01-790-801								
35-40-01-900-801-01	REMOVAL / INSTALLATION OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)							Component ATA:35
PN:GST2151	MOS/MSC	29-Jun-26	H/T	TSO 0				
SN:N549786	HRS	6756.3		TSO 0				
WC#: 35.020	AFL	3988		TSO 0				
PROC. REF: AMM 35-40-01-900-801PROC. REF: AMM 35-40-01-900-801								
35-40-01-960-801-01	DISCARD OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)							Service ATA:35
PN:GST2151	MOS	02-Oct-24	288		31-Oct-40		5136 d	LIFE LIMIT
SN:N549786	HRS	6601.6						
WC#: 35.020	AFL	3875						
			Manufacture Date:: 31-Oct-16					
PROC. REF: AMM 35-40-01-960-801PROC. REF: AMM 35-40-01-960-801								
35-40-05-350-801-01	RESTORATION OF THE OXYGEN CYLINDER PRESSURE REDUCING VALVE (OVERHAUL) - OXYGEN CYLINDER PRESSURE REDUCING VALVE (50WY)							Service ATA:35
PN:RDN1000	MOS	08-Sep-22	72 (+3%)		08-Sep-28	12-Nov-28	700 d (+65)	OVERHAUL
SN:393	HRS	6221.1						
WC#: 35.060	AFL	3722						
PROC. REF: AMM 35-40-05-350-801PROC. REF: AMM 35-40-05-350-801								
350116	FILLER VALVE							Component ATA:35
PN:DKR130	MOS/MSC	24-May-10	O/C	TSN 11				
SN:UNKNOWN	HRS	3546.83		TSN 0				
WC#: 35.050	AFL	2326		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
350121	OXYGEN PRESSURE REDUCING VALVE							Component ATA:35
PN:RDN1000	MOS/MSC	08-Sep-22	H/T	TSO 5				
SN:393	HRS	6221.1		TSO 0				
WC#: 35.060	AFL	3722		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350131	OXYGEN BOTTLE HP INDICATOR							Component ATA:35
PN:LM40AMD	MOS/MSC	11-Jul-95	O/C					
SN:NONE	HRS	0		TSN 0				
WC#: 35.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
350141	COPILOT OXYGEN HP INDICATOR							Component ATA:35
PN:CMT10-1	MOS/MSC	11-Jul-95	O/C					
SN:1453	HRS	0		TSN 0				
WC#: 35.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
351111	PILOT OXYGEN CONNECTOR							Component ATA:35
PN:DPB179	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
351131	COPILOT OXYGEN CONNECTOR							Component ATA:35
PN:DPB179	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.090	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353111	PORTABLE OXYGEN BOTTLE							Component ATA:35
PN:894-20330	MOS/MSC	30-Apr-24	H/T	TSN 353, TSO 0				
SN:144188	HRS	6553		TSO 0				
WC#: 35.030	AFL	3851		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353121	SMOKE HOOD							Component ATA:35
PN:PN	MOS/MSC	11-Jul-95	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 35.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-10-00-790-801-01 S	LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT APU							Service ATA:36
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 36-10-00-790-801	PROC. REF: AMM 36-10-00-790-801							
36-10-00-790-801-02 S	LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT ENGINE 1							Service ATA:36
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 36-10-00-790-801	PROC. REF: AMM 36-10-00-790-801							
36-10-00-790-801-03 S	LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT ENGINE 2							Service ATA:36
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 36-10-00-790-801	PROC. REF: AMM 36-10-00-790-801							
36-10-00-790-801-04 S	LEAK CHECK OF THE BLEED AIR SYSTEM - CHECK FOR LEAKS AT ENGINE 3							Service ATA:36
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
	AFL	3569						
								PKG:21
PROC. REF: AMM 36-10-00-790-801	PROC. REF: AMM 36-10-00-790-801							
36-10-02-720-801-01	FUNCTIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 1 HP BLEED AIR VALVE (23H1)							Service ATA:36
PN:1780-00-1	MOS	08-Mar-12						
SN:931	HRS	3996.5	4000		7996.5		1204.2	
WC#: 36.030	AFL	2577						
PROC. REF: AMM 36-10-02-720-801	PROC. REF: AMM 36-10-02-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-10-02-720-801-02	FUNCTIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 2 HP BLEED AIR VALVE (23H2)							Service ATA:36
PN:1780-00-1	MOS	08-Mar-12						
SN:932	HRS	3996.5	4000		7996.5		1204.2	
WC#: 36.040	AFL	2577						
PROC. REF: AMM 36-10-02-720-801	PROC. REF: AMM 36-10-02-720-801							
36-10-02-720-801-03	FUNCTIONAL TEST OF THE ENGINE HP BLEED AIR VALVES - ENGINE 3 HP BLEED AIR VALVE (23H3)							Service ATA:36
PN:1780-00-1	MOS	08-Mar-12						
SN:933	HRS	3996.5	4000		7996.5		1204.2	
WC#: 36.050	AFL	2577						
PROC. REF: AMM 36-10-02-720-801	PROC. REF: AMM 36-10-02-720-801							
36-10-02-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE HP BLEED AIR VALVES - ENGINE 1 HP BLEED AIR VALVE (23H1)							Component ATA:36
PN:1780-00-1	MOS/MSC	08-Mar-12	O/C					
SN:931	HRS	3996.5						
WC#: 36.030	AFL	2577						
PROC. REF: AMM 36-10-02-900-801	PROC. REF: AMM 36-10-02-900-801							
36-10-02-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE HP BLEED AIR VALVES - ENGINE 2 HP BLEED AIR VALVE (23H2)							Component ATA:36
PN:1780-00-1	MOS/MSC	08-Mar-12	O/C					
SN:932	HRS	3996.5						
WC#: 36.040	AFL	2577						
PROC. REF: AMM 36-10-02-900-801	PROC. REF: AMM 36-10-02-900-801							
36-10-02-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE HP BLEED AIR VALVES - ENGINE 3 HP BLEED AIR VALVE (23H3)							Component ATA:36
PN:1780-00-1	MOS/MSC	08-Mar-12	O/C					
SN:933	HRS	3996.5						
WC#: 36.050	AFL	2577						
PROC. REF: AMM 36-10-02-900-801	PROC. REF: AMM 36-10-02-900-801							
36-10-03-720-801-01	FUNCTIONAL TEST OF THE ENGINE 2 HP PRESSURE REGULATING VALVE - ENGINE 2 HP PRESSURE REGULATING VALVE (29H)							Service ATA:36
PN:3213902-2	MOS	26-Nov-08						
SN:P-134	HRS	3176.2	4000		7176.2		383.9	
WC#: 36.060	AFL	2104						
PROC. REF: AMM 36-10-03-720-801	PROC. REF: AMM 36-10-03-720-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-10-03-900-803-01	REMOVAL / INSTALLATION OF THE ENGINE 2 HP PRESSURE REGULATING VALVE							Component ATA:36
PN:3213902-2	MOS/MSC	26-Nov-08	O/C	TSO 0				
SN:P-134	HRS	3176.2		TSO 0				
WC#: 36.060	AFL	2104		TSO 0				
PROC. REF: AMM 36-10-03-900-803	PROC. REF: AMM 36-10-03-900-803							
36-10-05-200-801-01	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 1 LP BLEED AIR CHECK VALVE (L515H)							Service ATA:36
	MOS/MSC	24-Jul-08	N/A					
	HRS	3036.1						
WC#: 36.080	AFL	2036						
PROC. REF: AMM 36-10-05-200-801	PROC. REF: AMM 36-10-05-200-801							
36-10-05-200-801-02	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 2 LP BLEED AIR CHECK VALVE (M515H)							Service ATA:36
	MOS/MSC	24-Jul-08	N/A					
	HRS	3036.1						
WC#: 36.090	AFL	2036						
PROC. REF: AMM 36-10-05-200-801	PROC. REF: AMM 36-10-05-200-801							
36-10-05-200-801-03	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 3 LP BLEED AIR CHECK VALVE (R515H)							Service ATA:36
	MOS/MSC	24-Jul-08	N/A					
	HRS	3036.1						
WC#: 36.100	AFL	2036						
PROC. REF: AMM 36-10-05-200-801	PROC. REF: AMM 36-10-05-200-801							
36-10-05-200-801-04	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 1 HP/LP BLEED AIR CHECK VALVE (L516H)							Service ATA:36
	MOS/MSC	24-Jul-08	N/A					
	HRS	3036.1						
WC#: 36.080	AFL	2036						
PROC. REF: AMM 36-10-05-200-801	PROC. REF: AMM 36-10-05-200-801							
36-10-05-200-801-05	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 2 HP/LP BLEED AIR CHECK VALVE (M516H)							Service ATA:36
	MOS/MSC	24-Jul-08	N/A					
	HRS	3036.1						
WC#: 36.090	AFL	2036						
PROC. REF: AMM 36-10-05-200-801	PROC. REF: AMM 36-10-05-200-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-10-05-200-801-06	INSPECTION OF THE BLEED AIR CHECK VALVES - ENGINE 3 HP/LP BLEED AIR CHECK VALVE (R516H)							Service ATA:36
	MOS/MSC	24-Jul-08	N/A					
	HRS	3036.1						
WC#: 36.100	AFL	2036						
PROC. REF: AMM 36-10-05-200-801	PROC. REF: AMM 36-10-05-200-801							
36-10-05-200-801-07	INSPECTION OF THE BLEED AIR CHECK VALVES - APU BLEED AIR CHECK VALVE (599H)							Service ATA:36
	MOS/MSC	24-Jul-08	N/A					
	HRS	3036.1						
WC#: 36.140	AFL	2036						
PROC. REF: AMM 36-10-05-200-801	PROC. REF: AMM 36-10-05-200-801							
36-10-05-900-801-01	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 1 LP BLEED AIR CHECK VALVE (L515H)							Component ATA:36
PN:CYLB50419-1H	MOS/MSC	11-Jul-95	O/C					
SN:1663	HRS	0		TSN 0				
WC#: 36.080	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801	PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801							
36-10-05-900-801-02	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 2 LP BLEED AIR CHECK VALVE (M515H)							Component ATA:36
PN:CYLB50419-1H	MOS/MSC	11-Jul-95	O/C					
SN:1666	HRS	0		TSN 0				
WC#: 36.090	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801	PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801							
36-10-05-900-801-03	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 3 LP BLEED AIR CHECK VALVE (R515H)							Component ATA:36
PN:CYLB50419-1H	MOS/MSC	11-Jul-95	O/C					
SN:1536	HRS	0		TSN 0				
WC#: 36.100	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801	PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801							
36-10-05-900-801-04	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 1 HP/LP BLEED AIR CHECK VALVE (L516H)							Component ATA:36
PN:CYLB50419-1H	MOS/MSC	11-Jul-95	O/C					
SN:1538	HRS	0		TSN 0				
WC#: 36.080	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801	PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-10-05-900-801-05	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 2 HP/LP BLEED AIR CHECK VALVE (M516H)							Component ATA:36
PN:CYLB50419-1H	MOS/MSC	11-Jul-95	O/C					
SN:1664	HRS	0		TSN 0				
WC#: 36.090	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801								
36-10-05-900-801-06	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - ENGINE 3 HP/LP BLEED AIR CHECK VALVE (R516H)							Component ATA:36
PN:CYLB50419-1H	MOS/MSC	11-Jul-95	O/C					
SN:1667	HRS	0		TSN 0				
WC#: 36.100	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801								
36-10-05-900-801-07	CABIN HP BLEED AIR CHECK VALVE							Component ATA:36
PN:CYLB50414	MOS/MSC	11-Jul-95	O/C					
SN:1753	HRS	0		TSN 0				
WC#: 36.110	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801								
36-10-05-900-801-08	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - COCKPIT HP BLEED AIR CHECK VALVE (546H)							Component ATA:36
PN:CYLB50414	MOS/MSC	11-Jul-95	O/C					
SN:1777	HRS	0		TSN 0				
WC#: 36.110	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801								
36-10-05-900-801-09	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - CABIN LP BLEED AIR CHECK VALVE (547H)							Component ATA:36
PN:CYLB50414	MOS/MSC	11-Jul-95	O/C					
SN:1783	HRS	0		TSN 0				
WC#: 36.120	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801								
36-10-05-900-801-10	REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - COCKPIT LP BLEED AIR CHECK VALVE (548H)							Component ATA:36
PN:CYLB50414	MOS/MSC	11-Jul-95	O/C					
SN:1784	HRS	0		TSN 0				
WC#: 36.120	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-10-05-900-801-11		REMOVAL / INSTALLATION OF THE BLEED AIR CHECK VALVES - APU BLEED AIR CHECK VALVE (599H)						Component ATA:36
PN:CYLB50419-1H	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.140	AFL	0						
PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801PROC. REF: AMM 36-10-05-900-801, AMM 36-10-05-900-801								
36-10-21-710-801-01 S		OPERATIONAL TEST OF THE BLEED AIR ISOLATION VALVE - BLEED AIR ISOLATION VALVE (43H)						Service ATA:36
	MOS	23-Oct-13						
	HRS	4569.5	4500 (+30)					
WC#: 36.070	AFL	2879						
								PKG:23
PROC. REF: AMM 36-10-21-710-801PROC. REF: AMM 36-10-21-710-801								
36-10-33-350-801-01		RESTORATION OF THE BLEED AIR ARTICULATED PIPES (LEAK TEST AND DISCARD OF PISTON RING) - ENGINE 1 ARTICULATED PIPE (L510HU)						Service ATA:36
PN:B45CB1042	MOS	23-Oct-12						
SN:00930	HRS	4193.5	4000		8193.5		1401.2	
	AFL	2686						
PROC. REF: AMM 36-10-33-350-801PROC. REF: AMM 36-10-33-350-801								
36-10-33-350-801-02		RESTORATION OF THE BLEED AIR ARTICULATED PIPES (LEAK TEST AND DISCARD OF PISTON RING) - ENGINE 2 ARTICULATED PIPE (M510HU)						Service ATA:36
PN:B45CB1042	MOS	23-Oct-12						
SN:T812	HRS	4193.5	4000		8193.5		1401.2	
	AFL	2686						
PROC. REF: AMM 36-10-33-350-801PROC. REF: AMM 36-10-33-350-801								
36-10-33-350-801-03		RESTORATION OF THE BLEED AIR ARTICULATED PIPES (LEAK TEST AND DISCARD OF PISTON RING) - ENGINE 3 ARTICULATED PIPE (R510HU)						Service ATA:36
PN:B45CB1042	MOS	23-Oct-12						
SN:158	HRS	4193.5	4000		8193.5		1401.2	
	AFL	2686						
PROC. REF: AMM 36-10-33-350-801PROC. REF: AMM 36-10-33-350-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361101	NO. 1 ENGINE EXPANSION PIPE							Component ATA:36
PN:B45CB1042	MOS/MSC	23-Oct-12	O/C	TSO 0				
SN:00930	HRS	4193.5		TSO 0				
WC#: 36.010	AFL	2686		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361106	NO. 2 ENGINE EXPANSION PIPE							Component ATA:36
PN:B45CB1042	MOS/MSC	23-Oct-12	O/C	TSO 0				
SN:T812	HRS	4193.5		TSO 0				
WC#: 36.020	AFL	2686		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361111	NO. 3 ENGINE EXPANSION PIPE							Component ATA:36
PN:B45CB1042	MOS/MSC	23-Oct-12	O/C	TSO 0				
SN:158	HRS	4193.5		TSO 0				
WC#: 36.010	AFL	2686		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361201	BLEED AIR SHUTOFF VALVE							Component ATA:36
PN:BYLB50423-1	MOS/MSC	11-Jul-95	O/C					
SN:919	HRS	0		TSN 0				
WC#: 36.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361206	NO. 1 ENGINE BLEED VENTURI CHECK VALVE							Component ATA:36
PN:AR88-020-003	MOS/MSC	11-Jul-95	O/C					
SN:546	HRS	0		TSN 0				
WC#: 36.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361211	NO. 2 ENGINE BLEED VENTURI CHECK VALVE							Component ATA:36
PN:AR88-020-003	MOS/MSC	11-Jul-95	O/C					
SN:574	HRS	0		TSN 0				
WC#: 36.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361251	APU BLEED VENTURI CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.130	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362101	NO. 1 ENGINE BLEED AIR THERMOSTAT							Component ATA:36
PN:150T321-1	MOS/MSC	20-Dec-06	O/C	TSN 0				
SN:1945	HRS	2522.08		TSN 0				
WC#: 36.160	AFL	1744		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362106	NO. 1 ENGINE BLEED AIR (THERMOSTAT 25H1) TEMPERATURE PROBE							Component ATA:36
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.190	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362111	NO. 2 ENGINE BLEED AIR THERMOSTAT							Component ATA:36
PN:150T321-1	MOS/MSC	20-Dec-06	O/C	TSN 0				
SN:1946	HRS	2522.08		TSN 0				
WC#: 36.160	AFL	1744		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362116	NO. 2 ENGINE BLEED AIR (THERMOSTAT 25H2) TEMPERATURE PROBE							Component ATA:36
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.200	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362121	NO. 3 ENGINE BLEED AIR THERMOSTAT							Component ATA:36
PN:150T321-1	MOS/MSC	20-Dec-06	O/C	TSN 0				
SN:1946	HRS	2522.1		TSN 0				
WC#: 36.160	AFL	1744		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362126	NO. 3 ENGINE BLEED AIR (THERMOSTAT 25H3) TEMPERATURE PROBE							Component ATA:36
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.210	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362131	CABIN AIR CONDITIONING THERMOSTAT							Component ATA:36
PN:150T321-1	MOS/MSC	27-Aug-98	O/C	TSN 0				
SN:1643	HRS	801.7		TSN 0				
WC#: 36.170	AFL	528		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362136	BLEED AIR SYSTEM COMPUTER							Component ATA:36
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.220	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362141	COCKPIT AIR CONDITIONING THERMOSTAT							Component ATA:36
PN:150T321-1	MOS/MSC	27-Aug-98	O/C	TSN 0				
SN:1644	HRS	801.7		TSN 0				
WC#: 36.170	AFL	528		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362144	NO.1 AND NO.3 ENGINE PRESSURE TRANSDUCER							Component ATA:36
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.170	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362146	NO. 2 ENGINE PRESSURE TRANSDUCER							Component ATA:36
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 36.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362151	AIR BLEED INDICATOR PRINTED CIRCUIT							Component ATA:36
PN:CI999-1	MOS/MSC	31-Jul-06	O/C	TSN 0				
SN:645	HRS	2512.6		TSN 0				
WC#: 36.180	AFL	1737		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362156	AIR BLEED INDICATOR PRINTED CIRCUIT							Component ATA:36
PN:CI999-1	MOS/MSC	31-Jul-06	O/C	TSN 0				
SN:734	HRS	2512.6		TSN 0				
WC#: 36.180	AFL	1737		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 38 - WATER/WASTE								
38-00-00-610-801-01 S	SERVICING OF THE WATER SYSTEM							Service ATA:38
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 38.030	AFL	3875						
								PKG:16
PROC. REF: AMM 38-00-00-610-801PROC. REF: AMM 38-00-00-610-801								
38-10-00-670-801-01	STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION							Service ATA:38
	MOS	17-Apr-26	6 (+1m)		17-Oct-26	17-Nov-26	8 d (+31)	
	HRS	6746.8						
WC#: 38.020	AFL	3979						
PROC. REF: AMM 38-10-00-670-801PROC. REF: AMM 38-10-00-670-801								
38-34-00-600-801-01	DRAINING AND FILLING OF THE TOILETS							Service ATA:38
	MOS/MSC	08-Mar-23	O/C					
	HRS	6350.2						
	AFL	3778						
PROC. REF: AMM 38-34-00-600-801PROC. REF: AMM 38-34-00-600-801								
381814 U	CLEAN WATER SYSTEM-ANNUALLY							Service ATA:38
	MOS	24-Oct-25	12		24-Oct-26		15 d	
	HRS	6700.5						
	AFL	3940						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
381820 U	TEST BELLY DRAIN							Service ATA:38
	MOS	17-Apr-26	6		17-Oct-26		8 d	
	HRS	6746.8	300		7046.8		254.5	
	AFL	3979						
PROC. REF: MSC BELLY DRAIN SYSTEMPROC. REF: MSC BELLY DRAIN SYSTEM								
381824 U S	INSPECT/CHECK WATER SYSTEM COMPONENTS							Service ATA:38
	MOS	11-Aug-20	72					
	HRS	5942.6						
	AFL	3569						
								PKG:31
ATA 45 - CENTRAL MAINT SYSTEM								
45-10-02-900-801-01	REMOVAL / INSTALLATION OF THE MAINTENANCE DIAGNOSTIC COMPUTER (MDC) MODULE - MDC (355NH)							Component ATA:45
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.220	AFL	0		TSN 0				
PROC. REF: AMM 45-10-02-900-801PROC. REF: AMM 45-10-02-900-801								
ATA 49 - AIRBORNE AUXILIARY POWER								
49-50-01-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE APU AIR INLET DOOR ACTUATOR - AIR INTAKE DOOR ACTUATOR (333H)							Component ATA:49
PN:4175115	MOS/MSC	24-Mar-09	O/C	TSO 0				
SN:11137	HRS	3257.3		TSO 0				
WC#: 49.123	AFL	2159		TSO 0				
PROC. REF: AMM 49-50-01-900-801PROC. REF: AMM 49-50-01-900-801								
49-60-00-710-801-01 S	OPERATIONAL TEST OF THE APU FUEL SHUT-OFF ELECTRIC VALVE AND FIRE DETECTION CIRCUIT - APU SHUT-OFF VALVE (189H)							Service ATA:49
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 49.110	AFL	3569						
								PKG:21
PROC. REF: AMM 49-60-00-710-801PROC. REF: AMM 49-60-00-710-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
490010	APU - OPERATIONAL CHECK							Service ATA:49
	MOS/MSC	01-Feb-96	C/C					
	HRS	3		TAC 3				
	APUS	0						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
490113 U	APU DOOR MOTOR							Component ATA:49
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 49.225	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
490213	APU DOOR MOTOR							Component ATA:49
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 49.306	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
491010	APU - TURBINE ROTOR							Component ATA:49
PN:3615880-1	MOS/MSC	24-Dec-08	O/C					LIFE LIMIT
SN:3-01345-3143	HRS	1654		TSN 1654				
	APUS							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
491020	APU - COMPRESSOR ROTOR							Component ATA:49
PN:3822101-1	MOS/MSC	24-Dec-08	O/C					LIFE LIMIT
SN:7-03501-3308	HRS	1654		TSN 1654				
	APUS							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
491030	APU - HOT SECTION INSPECTION							Service ATA:49
	MOS	24-Dec-08						
	HRS	1654.8	2100 (+45)		3754.8	3799.8	745.7 (+45)	
	APUS							
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
491080	APU - COMBUSTOR UNIT							Component ATA:49
PN:3830077-9	MOS/MSC	23-Oct-12	O/C	TSN 0				
SN:NSN	HRS	1997		TSN 0				
	APUS			TSN 0				
PROC. REF: MM 49-20-04	PROC. REF: MM 49-20-04							
491110	APU - INSPECT COMBUSTOR UNIT							Service ATA:49
PN:3830077-9	MOS	24-Feb-26						
SN:NSN	HRS	2999.6	300 (+10%)	Adj -3.7	3295.9	3325.9	286.8 (+30)	
	APUS	1883						
PROC. REF: MM 49-20-04	PROC. REF: MM 49-20-04							
491120	APU - VISUAL CHECK COMPRESSOR ROTOR							Service ATA:49
PN:3822101-1	MOS	23-Apr-14						
SN:7-03501-3308	HRS	2173.3	2100 (+45)		4273.3	4318.3	1264.2 (+45)	
	APUS							
PROC. REF: MM 49-20-00, MM 49-20-00	PROC. REF: MM 49-20-00, MM 49-20-00							
492001	APU - PRESERVATION OF APU							Service ATA:49
	MOS/MSC	24-Jul-20	O/C					
	HRS							
	APUS							
PROC. REF: MM 49-20-00	PROC. REF: MM 49-20-00							
493010	APU - FUEL CONTROL							Component ATA:49
PN:3882600-8	MOS/MSC	24-Dec-08	O/C					
SN:A804C	HRS	1654.5						
	APUS							
PROC. REF: MM 49-30-49	PROC. REF: MM 49-30-49							
493020	APU - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service ATA:49
	MOS	24-Feb-26						
	HRS	2999.6	300 (+10%)	Adj -3.7	3295.9	3325.9	286.8 (+30)	
	APUS	1883						
PROC. REF: MM 49-30-49	PROC. REF: MM 49-30-49							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493040	APU - FUEL SHUTOFF VALVE							Component ATA:49
PN:692545-1	MOS/MSC	27-Nov-18	O/C					
SN:NSN	HRS	2630.1						
	APUS							
PROC. REF: MM 49-30-54	PROC. REF: MM 49-30-54							
493041	APU FUEL SHUT-OFF SOLENOID VALVE							Component ATA:49
PN:65690	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 49.110	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
493060	APU - CONTROLLER							Component ATA:49
PN:2117406-6	MOS/MSC	22-Jan-09	O/C	TSR 0				
SN:123-A0516	HRS	1654.5		TSR 0				
	APUS			TSR 0				
PROC. REF: MM 49-60-42	PROC. REF: MM 49-60-42							
493070	APU - AIR LOAD CONTROL VALVE							Component ATA:49
PN:109776-3-2	MOS/MSC	05-Apr-23	O/C	TSO 0				
SN:P-222C	HRS	2908.9		TSO 0				
	APUS			TSO 0				
PROC. REF: MM 49-50-31	PROC. REF: MM 49-50-31							
493110	APU - FUEL NOZZLE							Component ATA:49
PN:3830061-5	MOS/MSC	23-Oct-12	O/C	TSO 0				
SN:1PN05738	HRS	1997		TSO 0				
	APUS			TSO 0				
PROC. REF: MM 49-30-51	PROC. REF: MM 49-30-51							
493120	APU - CLEAN FUEL NOZZLE							Service ATA:49
PN:3830061-5	MOS	24-Feb-26						
SN:1PN05738	HRS	2999.6	300 (+10%)	Adj -3.7	3295.9	3325.9	286.8 (+30)	
	APUS	1883						
PROC. REF: MM 49-30-51	PROC. REF: MM 49-30-51							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493130	APU - COMBUSTOR DRAIN/ORIFICE FITTING VALVE							Component ATA:49
PN:968214-1	MOS/MSC	08-Feb-08	O/C	TSN 0				
SN:NSN	HRS			TSN 0				
	APUS			TSN 0				
PROC. REF: MM 49-30-24	PROC. REF: MM 49-30-24							
493140	APU - CLEAN/INSPECT COMBUSTOR DRAIN/ORIFICE FITTING VALVE							Service ATA:49
PN:968214-1	MOS	24-Feb-26						
SN:NSN	HRS	2999.6	300 (+10%)	Adj -3.7	3295.9	3325.9	286.8 (+30)	
	APUS	1883						
PROC. REF: MM 49-30-24	PROC. REF: MM 49-30-24							
494010	APU - IGNITION UNIT							Component ATA:49
PN:3888000-2	MOS/MSC	24-Dec-08	O/C					
SN:97208720	HRS	1654.5						
	APUS							
PROC. REF: MM 49-40-32	PROC. REF: MM 49-40-32							
494020	APU - IGNITER PLUG							Component ATA:49
PN:PN-UNKNOWN	MOS/MSC	18-Jun-19	O/C	TSN 0				
SN:NSN	HRS	2695.9		TSN 0				
	APUS			TSN 0				
PROC. REF: MM 49-40-33	PROC. REF: MM 49-40-33							
494030	APU - CLEAN/INSPECT IGNITER PLUG							Service ATA:49
PN:PN-UNKNOWN	MOS	24-Feb-26						
SN:NSN	HRS	2999.6	300 (+10%)	Adj -3.7	3295.9	3325.9	286.8 (+30)	
	APUS	1883						
PROC. REF: MM 49-40-33	PROC. REF: MM 49-40-33							
495006 U	APU SURGE (SHUTOFF) VALVE							Component ATA:49
PN:978668-3-1	MOS/MSC	24-Dec-08	O/C					
SN:3254	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
497010	APU - MOTION PICK UP TRANSDUCER							Component ATA:49
PN:3876000-1G	MOS/MSC	24-Dec-08	O/C					
SN:4-05104-105	HRS	1654.5						
	APUS							
PROC. REF: MM 49-60-43	PROC. REF: MM 49-60-43							
497020	APU - THERMOCOUPLE							Component ATA:49
PN:3876003-1	MOS/MSC	24-Dec-08	O/C					
SN:072021900192	HRS	1654.5						
	APUS							
PROC. REF: MM 49-60-45	PROC. REF: MM 49-60-45							
497030	APU - HOURMETER							Component ATA:49
PN:3888016-1	MOS/MSC	24-Dec-08	O/C					
SN:NSN	HRS	1654.5						
	APUS							
PROC. REF: MM 49-70-40	PROC. REF: MM 49-70-40							
499030	APU - DRAIN AND REFILL OIL							Service ATA:49
	MOS/MSC	23-Apr-14	O/C					
	HRS	2173.3						
	APUS							
PROC. REF: MM 49-20-00	PROC. REF: MM 49-20-00							
499040	APU - REMOVE/INSPECT/REPLACE OIL FILTER ELEMENT							Service ATA:49
	MOS	18-Jun-19						
	HRS	2695.9	500 (+20%/-20%)		3195.9	3295.9	186.8 (+100)	
	APUS							
PROC. REF: MM 49-90-14, SIL SIL-49, SIL SIL-49	PROC. REF: MM 49-90-14, SIL SIL-49, SIL SIL-49							
499070	APU - LOW PRESSURE SWITCH							Component ATA:49
PN:3876001-8	MOS/MSC	24-Dec-08	O/C	TSN 0				
SN:09816	HRS	1654.5		TSN 0				
	APUS			TSN 0				
PROC. REF: MM 49-60-44	PROC. REF: MM 49-60-44							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
499110	APU - SOAP CHECK OIL							Service ATA:49
	MOS	16-Mar-22						
	HRS	2820.8	500 (+20%/-20%)		3320.8	3420.8	311.7 (+100)	
	APUS							
PROC. REF: GENERIC NO REF, SIL SIL-49, SIL SIL-49PROC. REF: GENERIC NO REF, SIL SIL-49, SIL SIL-49								
49APU1	APU							Component ATA:49
PN:3800016-3-1	MOS/MSC		E/C					
SN:P-355	HRS							
	AFL							
PROC. REF: AMM 49-10-01-900-802PROC. REF: AMM 49-10-01-900-802								
ATA 51 - STD PRACTICES AND STRUCT-GENRL								
51-00-00-210-801-01	GENERAL VISUAL INSPECTION OF THE CONTROL SURFACES AND EXPOSED AREAS OF THE AIRCRAFT SKIN							Service ATA:51
	MOS/MSC	25-May-17	O/C					
	HRS	5157.3						
WC#: 51.010	AFL	3249						
PROC. REF: AMM 51-00-00-210-801PROC. REF: AMM 51-00-00-210-801								
ATA 52 - DOORS								
52-00-00-640-802-01 S	LUBRICATION OF THE VISIBLE DOOR HINGES							Service ATA:52
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 52.010	AFL	3940						
								PKG:207
PROC. REF: AMM 52-00-00-640-802PROC. REF: AMM 52-00-00-640-802								
52-10-00-200-803-01 S	INSPECTION CHECK AND SERVICING OF THE PASSENGER DOOR - PASSENGER DOOR (900MA)							Service ATA:52
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 52-10-00-200-803PROC. REF: AMM 52-10-00-200-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-00-610-801-01	SERVICING OF THE PASSENGER DOOR - CHECK OF STRUCTURE AND LATCHES							Service ATA:52
	MOS	02-Oct-24	24		02-Oct-26		OVD	
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-01A	SERVICING OF THE PASSENGER DOOR - CHECK OF STRUCTURE AND LATCHES (MANDATORY 5-40)							Service ATA:52
	MOS	02-Oct-24	24		02-Oct-26		OVD	ALI
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-02	SERVICING OF THE PASSENGER DOOR - CHECK OF OPENING AND CLOSING MECHANISM							Service ATA:52
	MOS	02-Oct-24	24	Adj -52d	11-Aug-26		OVD	
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-02A	SERVICING OF THE PASSENGER DOOR - CHECK OF OPENING AND CLOSING MECHANISM (MANDATORY 5-40)							Service ATA:52
	MOS	02-Oct-24	24		02-Oct-26		OVD	ALI
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-03	SERVICING OF THE PASSENGER DOOR - GREASING / LUBRICATION							Service ATA:52
	MOS	02-Oct-24	24	Adj -52d	11-Aug-26		OVD	
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-03A	SERVICING OF THE PASSENGER DOOR - GREASING / LUBRICATION (MANDATORY 5-40)							Service ATA:52
	MOS	02-Oct-24	24		02-Oct-26		OVD	ALI
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-00-610-801-04	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR COUNTERBALANCING SYSTEM							Service ATA:52
	MOS	02-Oct-24	24	Adj -52d	11-Aug-26		OVD	
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-04A	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR COUNTERBALANCING SYSTEM (MANDATORY 5-40)							Service ATA:52
	MOS	02-Oct-24	24		02-Oct-26		OVD	ALI
	HRS	6601.6	800		7401.6		609.3	
	AFL	3875						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-05	SERVICING OF THE PASSENGER DOOR - CHECK OF DOOR LOCKED INDICATION							Service ATA:52
	MOS	17-Apr-26	6 (+1m)		17-Oct-26	17-Nov-26	8 d (+31)	
	HRS	6746.8	800		7546.8		754.5	
WC#: 52.020	AFL	3979						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-00-610-801-05A	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR LOCKED INDICATION (MANDATORY 5-40)							Service ATA:52
	MOS	17-Apr-26	24		17-Apr-28		556 d	ALI
	HRS	6746.8	800		7546.8		754.5	
	AFL	3979						
PROC. REF: AMM 52-10-00-610-801	PROC. REF: AMM 52-10-00-610-801							
52-10-01-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR							Component ATA:52
PN:F50B295A2	MOS/MSC	11-Jul-95	O/C					
SN:S0255	HRS	0		TSN 0				
WC#: 52.020	AFL	0						
PROC. REF: AMM 52-10-01-900-801	PROC. REF: AMM 52-10-01-900-801							
52-10-03-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (902MC)							Component ATA:52
PN:107-15-0	MOS/MSC	23-Jul-99	O/C					
SN:1010	HRS	1045						
WC#: 52.030	AFL	706						
PROC. REF: AMM 52-10-03-900-801	PROC. REF: AMM 52-10-03-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-07-220-801-01		DETAILED INSPECTION OF THE PASSENGER DOOR LOCKING HOOKS						Service ATA:52
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.160	AFL	0	T:11435		11435		7425	
PROC. REF: AMM 52-10-07-220-801	PROC. REF: AMM 52-10-07-220-801							
52-10-07-220-801-01A		DETAILED INSPECTION OF THE PASSENGER DOOR LOCKING HOOKS (MANDATORY 5-40)						Service ATA:52
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.290	AFL	0	T:11435		11435		7425	
PROC. REF: AMM 52-10-07-220-801	PROC. REF: AMM 52-10-07-220-801							
52-20-00-610-801-01 S		SERVICING OF THE EMERGENCY EXIT DOOR - SERVICING OF THE LH EMERGENCY EXIT DOOR						Service ATA:52
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 52.040	AFL	3875						
								PKG:16
PROC. REF: AMM 52-20-00-610-801	PROC. REF: AMM 52-20-00-610-801							
52-20-00-610-801-02 S		SERVICING OF THE EMERGENCY EXIT DOOR - SERVICING OF THE RH EMERGENCY EXIT DOOR						Service ATA:52
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 52.040	AFL	3875						
								PKG:16
PROC. REF: AMM 52-20-00-610-801	PROC. REF: AMM 52-20-00-610-801							
52-20-00-610-801-03 S		SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE LH EMERGENCY EXIT DOOR						Service ATA:52
	MOS	02-Oct-24	24					
	HRS	6601.6						
WC#: 52.040	AFL	3875						
								PKG:16
PROC. REF: AMM 52-20-00-610-801	PROC. REF: AMM 52-20-00-610-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-00-610-801-03A	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE LH EMERGENCY EXIT DOOR (MANDATORY 5-40)							Service ATA:52
	MOS	02-Oct-24	24		02-Oct-26		OVD	MANDATORY 5-40
	HRS	6601.6						
WC#: 52.040	AFL	3875						
PROC. REF: AMM 52-20-00-610-801	PROC. REF: AMM 52-20-00-610-801							
52-20-00-610-801-04 S	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE RH EMERGENCY EXIT DOOR							Service ATA:52
	MOS	02-Oct-24	24					
	HRS	6601.6						
WC#: 52.040	AFL	3875						
								PKG:16
PROC. REF: AMM 52-20-00-610-801	PROC. REF: AMM 52-20-00-610-801							
52-20-00-610-801-04A	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE RH EMERGENCY EXIT DOOR (MANDATORY 5-40)							Service ATA:52
	MOS	02-Oct-24	24		02-Oct-26		OVD	MANDATORY 5-40
	HRS	6601.6						
WC#: 52.040	AFL	3875						
PROC. REF: AMM 52-20-00-610-801	PROC. REF: AMM 52-20-00-610-801							
52-20-00-710-801-03 S	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE - UNLOCKING TEST FROM OUTSIDE OF LH EXIT							Service ATA:52
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 52.040	AFL	3569						
								PKG:21
PROC. REF: AMM 52-20-00-710-801	PROC. REF: AMM 52-20-00-710-801							
52-20-00-710-801-04 S	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE - UNLOCKING TEST FROM OUTSIDE OF RH EXIT							Service ATA:52
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 52.040	AFL	3569						
								PKG:21
PROC. REF: AMM 52-20-00-710-801	PROC. REF: AMM 52-20-00-710-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-01-960-801-01	DISCARD OF THE EMERGENCY EXIT DOORS - LH EMERGENCY EXIT DOOR (900MB1)							Service ATA:52
PN:F50B296001A2	MOS	15-Jul-96						LIFE LIMIT
SN:518DX053	HRS	0		TAC 0				
WC#: 52.040	AFL	0	26718		26718		22708	
PROC. REF: AMM 52-20-01-960-801	PROC. REF: AMM 52-20-01-960-801							
52-20-01-960-801-01A	DISCARD LH EMERGENCY EXIT (MANDATORY 5-40)							Service ATA:52
PN:F50B296001A2	MOS	15-Jul-96						MANDATORY 5-40
SN:518DX053	HRS	0						
	AFL	0	26718		26718		22708	
PROC. REF: AMM 52-20-01-960-801	PROC. REF: AMM 52-20-01-960-801							
52-20-01-960-801-02	DISCARD OF THE EMERGENCY EXIT DOORS - RH EMERGENCY EXIT DOOR (900MB2)							Service ATA:52
PN:F50B296001A2	MOS	15-Jul-96						LIFE LIMIT
SN:519DX054	HRS	0		TAC 0				
WC#: 52.040	AFL	0	26718		26718		22708	
PROC. REF: AMM 52-20-01-960-801	PROC. REF: AMM 52-20-01-960-801							
52-20-01-960-801-02A	DISCARD RH EMERGENCY EXIT (MANDATORY 5-40)							Service ATA:52
PN:F50B296001A2	MOS	15-Jul-96						MANDATORY 5-40
SN:519DX054	HRS	0						
	AFL	0	26718		26718		22708	
PROC. REF: AMM 52-20-01-960-801	PROC. REF: AMM 52-20-01-960-801							
52-20-17-640-801-01	LUBRICATION OF THE EMERGENCY EXIT DOOR MECHANISM							Service ATA:52
	MOS/MSC	30-Apr-07	O/C					
	HRS	2667.67						
WC#: 52.040	AFL	1830						
PROC. REF: AMM 52-20-17-640-801	PROC. REF: AMM 52-20-17-640-801							
52-20-17-640-801-02	LUBRICATION OF THE EMERGENCY EXIT DOOR MECHANISM							Service ATA:52
	MOS/MSC	17-Jul-07	O/C					
	HRS	2709.8						
WC#: 52.040	AFL	1854						
PROC. REF: AMM 52-20-17-640-801	PROC. REF: AMM 52-20-17-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-30-00-200-801-01A	VISUAL INSPECTION BAGGAGE COMPARTMENT DOOR (MANDATORY 5-40)							Service ATA:52
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.370	AFL	0	T:26299		26299		22289	
PROC. REF: AMM 52-30-00-200-801	PROC. REF: AMM 52-30-00-200-801							
52-30-00-200-802-01	INSPECTION OF THE BAGGAGE COMPARTMENT DOOR FORWARD SIDE FOLD							Service ATA:52
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.150	AFL	0	T:7000 (+34)		7000	7034	2990 (+34)	
PROC. REF: AMM 52-30-00-200-802	PROC. REF: AMM 52-30-00-200-802							
52-30-00-200-802-01A	INSPECTION OF THE BAGGAGE COMPARTMENT DOOR FORWARD SIDE FOLD (MANDATORY 5-40)							Service ATA:52
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.285	AFL	0						
PROC. REF: AMM 52-30-00-200-802	PROC. REF: AMM 52-30-00-200-802							
52-30-00-610-801-01 S	SERVICING OF THE BAGGAGE COMPARTMENT DOOR							Service ATA:52
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 52-30-00-610-801	PROC. REF: AMM 52-30-00-610-801							
52-30-01-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR							Component ATA:52
PN:F50B299B1	MOS/MSC	11-Jul-95	O/C					
SN:254	HRS	0		TSN 0				
WC#: 52.050	AFL	0						
PROC. REF: AMM 52-30-01-900-801	PROC. REF: AMM 52-30-01-900-801							
52-40-00-210-801-01 S	GENERAL VISUAL INSPECTION OF THE SERVICE DOORS							Service ATA:52
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 52.070	AFL	3875						
								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
PROC. REF: AMM 52-40-00-210-801	PROC. REF: AMM 52-40-00-210-801							
52-50-00-710-801-01 S	INSPECTION / TEST OF THE BLOWOUT DOORS / PANELS							Service ATA:52
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 52-50-00-710-801	PROC. REF: AMM 52-50-00-710-801							
52-60-09-610-801-03 S	SERVICING OF THE REAR COMPARTMENT DOOR							Service ATA:52
	MOS	08-Dec-23	36 (+1m)					
	HRS	6529.1						
	AFL	3833						
								PKG:208
PROC. REF: AMM 52-60-09-610-801	PROC. REF: AMM 52-60-09-610-801							
52-60-09-900-801-01	REMOVAL / INSTALLATION OF THE REAR COMPARTMENT DOOR							Component ATA:52
PN:F50B297A4	MOS/MSC	11-Jul-95	O/C					
SN:263	HRS	0		TSN 0				
WC#: 52.060	AFL	0						
PROC. REF: AMM 52-60-09-900-801	PROC. REF: AMM 52-60-09-900-801							
52-70-11-710-801-01 S	OPERATIONAL TEST OF THE S-DUCT DOOR POSITION INDICATING MICROSWITCH							Service ATA:52
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 52.080	AFL	3875						
								PKG:16
PROC. REF: AMM 52-70-11-710-801	PROC. REF: AMM 52-70-11-710-801							
52-70-11-710-801-01A	OPERATIONAL TEST OF THE S-DUCT DOOR POSITION INDICATING MICROSWITCH (MANDATORY 5-40)							Service ATA:52
	MOS	02-Oct-24						MANDATORY 5-40
	HRS	6601.6	10000		16601.6		9809.3	
WC#: 52.080	AFL	3875						
PROC. REF: AMM 52-70-11-710-801	PROC. REF: AMM 52-70-11-710-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
522101	LH EMERGENCY EXIT							Component ATA:52
PN:F50B296001A2	MOS/MSC	11-Jul-95	H/T					
SN:518DX053	HRS	0		TSN 0				
WC#: 52.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
522121	RH EMERGENCY EXIT							Component ATA:52
PN:F50B296001A2	MOS/MSC	11-Aug-20	H/T					
SN:519DX054	HRS	5942.6		TSN 5942.6				
WC#: 52.040	AFL	3569		TSN 3569				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 53 - FUSELAGE								
53-00-00-200-801-01 S	INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 53.025	AFL	3875						PKG:16
PROC. REF: AMM 53-00-00-200-801PROC. REF: AMM 53-00-00-200-801								
53-00-00-200-801-01C	INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.035	AFL	3875						
PROC. REF: AMM 53-00-00-200-801PROC. REF: AMM 53-00-00-200-801								
53-00-00-200-802-01A	VISUAL INSPECTION OF THE SKIN PANELS - FRAME 7 TO FRAME 31 (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.310	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-00-00-200-802PROC. REF: AMM 53-00-00-200-802								
53-00-00-220-801-01	DETAILED INSPECTION OF THE FUSELAGE FRAMES IN PRESSURIZED AREA							Service ATA:53
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.250	AFL	0	10000		10000		5990	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-00-00-220-801	PROC. REF: AMM 53-00-00-220-801							
53-00-00-250-801-01	EDDY-CURRENT INSPECTION FOR CORROSION AT INTERFACES BETWEEN SPOT-WELDED SKIN PANELS AND STRINGERS BETWEEN FRAMES 0 AND 19							Service ATA:53
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.350	AFL	0						
PROC. REF: AMM 53-00-00-250-801	PROC. REF: AMM 53-00-00-250-801							
53-00-00-250-801-01C	EDDY-CURRENT INSPECTION FOR CORROSION AT INTERFACES BETWEEN SPOT-WELDED SKIN PANELS AND STRINGERS BETWEEN FRAMES 0 AND 19 (CPCP)							Service ATA:53
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.045	AFL	0						
PROC. REF: AMM 53-00-00-250-801	PROC. REF: AMM 53-00-00-250-801							
53-00-00-250-802-01A	NON DESTRUCTIVE TEST OF THE FUSELAGE FRAMEWORK AROUND THE WINDOWS IN T2 AND T3 SECTIONS (LONGITUDINAL CRACKS) (MANDATORY 5-40)							Service ATA:53
	MOS							MANDATORY 5-40
	HRS							
WC#: 53.330	AFL		T:31250		31250		27240	
PROC. REF: AMM 53-00-00-250-802	PROC. REF: AMM 53-00-00-250-802							
53-04-01-220-801-01A	VISUAL INSPECTION FLOOR OMEGAS AT FRAMES 18-19 (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.145	AFL	0	T:27500		27500		23490	
PROC. REF: AMM 53-04-01-220-801	PROC. REF: AMM 53-04-01-220-801							
53-04-05-250-801-01A	EDDY CURRENT INSPECTION OF FLOOR PANEL STIFFENERS BETWEEN FRAMES 31 AND 35 (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.195	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-04-05-250-801	PROC. REF: AMM 53-04-05-250-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-200-808-01 S	INSPECTION OF THE NLG BAY							Service ATA:53
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 32.2801	AFL	3940						
								PKG:207
PROC. REF: AMM 53-10-00-200-808	PROC. REF: AMM 53-10-00-200-808							
53-10-00-200-808-01C	INSPECTION OF THE NLG BAY (CPCP)							Service ATA:53
	MOS	24-Oct-25	12 (+1m)	Adj -22d	02-Oct-26	02-Nov-26	TOL (+24 d)	CPCP
	HRS	6700.5						
	AFL	3940						
PROC. REF: AMM 53-10-00-200-808	PROC. REF: AMM 53-10-00-200-808							
53-10-00-210-802-01 S	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 53.0401	AFL	3875						
								PKG:16
PROC. REF: AMM 53-10-00-210-802	PROC. REF: AMM 53-10-00-210-802							
53-10-00-220-801-01 S	DETAILED INSPECTION OF THE STATIC PRESSURE PROBE AND OF THE FUSELAGE SKIN IN PROBE AREA							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					RVSM
	HRS	6601.6						
WC#: 53.030	AFL	3875						
								PKG:16
PROC. REF: AMM 53-10-00-220-801	PROC. REF: AMM 53-10-00-220-801							
53-10-00-220-802-01 S	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 53.0402	AFL	3569						
								PKG:31
PROC. REF: AMM 53-10-00-220-802	PROC. REF: AMM 53-10-00-220-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.055	AFL	3569						
PROC. REF: AMM 53-10-00-220-802	PROC. REF: AMM 53-10-00-220-802							
53-10-00-220-803-01 S	DETAILED INSPECTION OF THE NLG BAY							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 32.2802	AFL	3875						
								PKG:16
PROC. REF: AMM 53-10-00-220-803	PROC. REF: AMM 53-10-00-220-803							
53-10-00-220-803-01C	DETAILED INSPECTION OF THE NLG BAY (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.065	AFL	3875						
PROC. REF: AMM 53-10-00-220-803	PROC. REF: AMM 53-10-00-220-803							
53-10-03-250-802-01A	EDDY CURRENT INSPECTION OF THE PASSENGER DOOR FRAME CORNERS (MANDATORY 5-40)							Service ATA:53
	MOS							MANDATORY 5-40
	HRS							
WC#: 53.320	AFL		T:31250		31250		27240	
PROC. REF: AMM 53-10-03-250-802	PROC. REF: AMM 53-10-03-250-802							
53-10-05-250-801-01A	EDDY CURRENT INSPECTION OF FRAME 12 AROUND PAX DOOR TELESCOPIC ROD FITTING (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.215	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-10-05-250-801	PROC. REF: AMM 53-10-05-250-801							
53-10-31-220-801-01A	DETAILED INSPECTION OF COCKPIT UPPER SKIN JUNCTION WITH WINDSHIELD AND WINDOW FRAMES (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.152	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-10-31-220-801	PROC. REF: AMM 53-10-31-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-39-220-801-01 S	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES							Service ATA:53
PN:PN	MOS	11-Aug-20	72 (+2m)					
SN:UNKNOWN	HRS	5942.6						
WC#: 53.210	AFL	3569						
								PKG:31
PROC. REF: AMM 53-10-39-220-801	PROC. REF: AMM 53-10-39-220-801							
53-10-39-220-801-01A	INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (MANDATORY 5-40)							Service ATA:53
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6						
WC#: 53.210	AFL	3569	3750		7319		3309	
PROC. REF: AMM 53-10-39-220-801	PROC. REF: AMM 53-10-39-220-801							
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.075	AFL	3569						
PROC. REF: AMM 53-10-39-220-801	PROC. REF: AMM 53-10-39-220-801							
53-10-39-220-803-01	DETAILED INSPECTION OF THE SCREWS ATTACHING THE WINDSHIELD FRAMES TO FRAME 0							Service ATA:53
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.090	AFL	0	T:10525		10525		6515	
PROC. REF: AMM 53-10-39-220-803	PROC. REF: AMM 53-10-39-220-803							
53-10-39-220-803-01A	DETAILED INSPECTION OF THE ATTACHING SCREW OF COCKPIT WINDSHIELD FRAMES TO FRAME 0 (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.235	AFL	0	T:10525		10525		6515	
PROC. REF: AMM 53-10-39-220-803	PROC. REF: AMM 53-10-39-220-803							
53-10-39-220-804-01	DETAILED INSPECTION OF THE FRAME OF THE LH AND RH REAR COCKPIT WINDOWS - LH SIDE REAR WINDOW							Service ATA:53
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 53.140	AFL	0						
PROC. REF: AMM 53-10-39-220-804	PROC. REF: AMM 53-10-39-220-804							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-39-220-804-01A	DETAILED INSPECTION OF THE FRAME OF THE LH SIDE REAR COCKPIT WINDOWS (MANDATORY 5-40)							Service ATA:53
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.265	AFL	0						
PROC. REF: AMM 53-10-39-220-804	PROC. REF: AMM 53-10-39-220-804							
53-10-39-220-804-02	DETAILED INSPECTION OF THE FRAME OF THE LH AND RH REAR COCKPIT WINDOWS - RH SIDE REAR WINDOW							Service ATA:53
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.140	AFL	0	T:12000		12000		7990	
PROC. REF: AMM 53-10-39-220-804	PROC. REF: AMM 53-10-39-220-804							
53-10-39-220-804-02A	INSPECTION RIGHT REAR WINDOW FRAME (MADATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.275	AFL	0	T:12000		12000		7990	
PROC. REF: AMM 53-10-39-220-804	PROC. REF: AMM 53-10-39-220-804							
53-10-39-220-805-01	DETAILED INSPECTION OF THE FRAME OF THE RH COCKPIT LATERAL WINDOW							Service ATA:53
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.110	AFL	0						
PROC. REF: AMM 53-10-39-220-805	PROC. REF: AMM 53-10-39-220-805							
53-10-39-220-805-01A	DETAILED INSPECTION OF THE FRAME OF THE RH COCKPIT LATERAL WINDOW (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.110	AFL	0	T:10050		10050		6040	
PROC. REF: AMM 53-10-39-220-805	PROC. REF: AMM 53-10-39-220-805							
53-10-39-250-801-01 S	EDDY CURRENT INSPECTION OF THE LOWER RECESSES OF THE COCKPIT WINDSHIELD / WINDOW FRAMES							Service ATA:53
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 53.420	AFL	3569						
								PKG:32
PROC. REF: AMM 53-10-39-250-801	PROC. REF: AMM 53-10-39-250-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-39-250-801-01C	EDDY CURRENT INSPECTION OF THE LOWER RECESSES OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							Service ATA:53
	MOS	11-Aug-20	144 (+2m)		11-Aug-32	11-Oct-32	2133 d (+61)	CPCP
	HRS	5942.6						
WC#: 53.095	AFL	3569						
PROC. REF: AMM 53-10-39-250-801	PROC. REF: AMM 53-10-39-250-801							
53-10-39-250-802-01A	EDDY CURRENT INSPECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.300	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-10-39-250-802	PROC. REF: AMM 53-10-39-250-802							
53-10-39-270-801-01 S	ULTRASONIC CHECK OF THE LOWER PART OF THE FRAMES OF THE COCKPIT WINDSHIELDS AND WINDOWS							Service ATA:53
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 53.420	AFL	3569						
								PKG:32
PROC. REF: AMM 53-10-39-270-801	PROC. REF: AMM 53-10-39-270-801							
53-10-39-270-801-01C	ULTRASONIC CHECK OF THE LOWER PART OF THE FRAMES OF THE COCKPIT WINDSHIELDS AND WINDOWS (CPCP)							Service ATA:53
	MOS	11-Aug-20	144 (+2m)		11-Aug-32	11-Oct-32	2133 d (+61)	CPCP
	HRS	5942.6						
WC#: 53.115	AFL	3569						
PROC. REF: AMM 53-10-39-270-801	PROC. REF: AMM 53-10-39-270-801							
53-10-39-270-802-01 S	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:31
PROC. REF: AMM 53-10-39-270-802	PROC. REF: AMM 53-10-39-270-802							
53-10-39-270-802-01A	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS (MANDATORY 5-40)							Service ATA:53
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6						
WC#: 53.270	AFL	3569	3750		7319		3309	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-10-39-270-802	PROC. REF: AMM 53-10-39-270-802							
53-10-39-270-802-01C	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.120	AFL	3569						
PROC. REF: AMM 53-10-39-270-802	PROC. REF: AMM 53-10-39-270-802							
53-10-39-290-801-01C	ENDOSCOPE INSPECTION OF THE LOWER RECESSES OF COCKPIT WINDSHIELD/WINDOW FRAMES (CPCP)							Service ATA:53
	MOS/MSC	08-May-14	O/C					CPCP
	HRS	4694.5						
WC#: 53.125	AFL	2957						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR							Service ATA:53
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.228	AFL	0	T:10000		10000		5990	
PROC. REF: AMM 53-10-41-220-801	PROC. REF: AMM 53-10-41-220-801							
53-10-41-220-801-01A	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.228	AFL	0	T:10000		10000		5990	
PROC. REF: AMM 53-10-41-220-801	PROC. REF: AMM 53-10-41-220-801							
53-10-45-250-801-01A	EDDY CURRENT INSPECTION OF THE NLG BAY SKIN PANEL AND DOOR FRAME AT FRAME 7 (MANDATORY 5-40)							Service ATA:53
	MOS							MANDATORY 5-40
	HRS							
WC#: 53.340	AFL		T:31250		31250		27240	
PROC. REF: AMM 53-10-45-250-801	PROC. REF: AMM 53-10-45-250-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-11-00-210-801-02 S	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 53.0301	AFL	3875						
								PKG:16
PROC. REF: AMM 53-11-00-210-801 PROC. REF: AMM 53-11-00-210-801								
53-11-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.130	AFL	3875						
PROC. REF: AMM 53-11-00-210-801 PROC. REF: AMM 53-11-00-210-801								
53-11-00-220-801-01 S	DETAILED INSPECTION OF THE NOSE CONE AREA							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 53.0302	AFL	3569						
								PKG:31
PROC. REF: AMM 53-11-00-220-801 PROC. REF: AMM 53-11-00-220-801								
53-11-00-220-801-01C	DETAILED INSPECTION OF THE NOSE CONE AREA (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.135	AFL	3569						
PROC. REF: AMM 53-11-00-220-801 PROC. REF: AMM 53-11-00-220-801								
53-11-00-760-801-01	CHECK OF THE NOSE CONE ELECTRICAL BONDING							Service ATA:53
	MOS/MSC	08-May-14	N/A					
	HRS	4694.25						
WC#: 53.380	AFL	2957						
PROC. REF: AMM 53-11-00-760-801 PROC. REF: AMM 53-11-00-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-210-802-01 S	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 53.0501	AFL	3875						
								PKG:16
PROC. REF: AMM 53-30-00-210-802 PROC. REF: AMM 53-30-00-210-802								
53-30-00-220-801-01 S	DETAILED INSPECTION OF THE PASSENGER CABIN							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 53.0502	AFL	3569						
								PKG:31
PROC. REF: AMM 53-30-00-220-801 PROC. REF: AMM 53-30-00-220-801								
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.230	AFL	3569						
PROC. REF: AMM 53-30-00-220-801 PROC. REF: AMM 53-30-00-220-801								
53-30-00-220-802-01	INSPECTION OF THE CENTER FLOOR ANGLE PIECE, RH SIDE BETWEEN FRAME 19 AND FRAME 26							Service ATA:53
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.170	AFL	0						
PROC. REF: AMM 53-30-00-220-802 PROC. REF: AMM 53-30-00-220-802								
53-30-00-220-802-01A	INSPECTION OF THE CENTER FLOOR ANGLE PIECE, RH SIDE BETWEEN FRAME 19 AND FRAME 26 (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.302	AFL	0	T:16192		16192		12182	
PROC. REF: AMM 53-30-00-220-802 PROC. REF: AMM 53-30-00-220-802								
53-30-00-220-803-01	DETAILED INSPECTION OF THE FLOOR PICK-UP ANGLE AT FRAME 27 AND OF THE FLOOR PANEL BETWEEN FRAME 26 AND FRAME 29							Service ATA:53
	MOS	15-Jul-96						
	HRS	0						
WC#: 53.305	AFL	0	T:10000		10000		5990	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-30-00-220-803	PROC. REF: AMM 53-30-00-220-803							
53-30-00-220-803-01A	DETAILED INSPECTION OF THE FLOOR PICKUP ANGLE AT FRAME 27 AND OF THE FLOOR PANEL BETWEEN FRAME 26 AND FRAME 29 (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.360	AFL	0	T:10000		10000		5990	
PROC. REF: AMM 53-30-00-220-803	PROC. REF: AMM 53-30-00-220-803							
53-30-00-220-805-01A	DETAILED INSPECTION OF FUSELAGE SKIN IN SPLICE AREA AT STRINGER 13 BETWEEN FRAME 13 AND 18 (MANDATORY 5-40)							Service ATA:53
	MOS	11-Jul-95						MANDATORY 5-40
	HRS	0						
	AFL	0	T:30000		30000		25990	
PROC. REF: AMM 53-30-00-220-805	PROC. REF: AMM 53-30-00-220-805							
53-30-00-250-801-01A	EDDY CURRENT INSPECTION OF THE PASSENGER CABIN SKIN PANEL AROUND EMERGENCY EXIT DOOR ROUNDED ANGLES (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.175	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-30-00-250-801	PROC. REF: AMM 53-30-00-250-801							
53-30-00-250-803-01A	EDDY CURRENT INSPECTION OF THE FINGER PLATE OF CIRCUMFERENTIAL SPLICE AT FRAMES 19 AND 26 (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.180	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-30-00-250-803	PROC. REF: AMM 53-30-00-250-803							
53-30-01-220-801-01 S	DETAILED INSPECTION OF THE FEEDER TANKS							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 53.010	AFL	3569						
								PKG:31
PROC. REF: AMM 53-30-01-220-801	PROC. REF: AMM 53-30-01-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-01-220-801-01A	DETAILED INSPECTION OF THE FEEDER TANKS (MANDATORY 5-40)							Service ATA:53
	MOS	11-Aug-20	74		11-Oct-26		2 d	MANDATORY 5-40
	HRS	5942.6						
WC#: 53.225	AFL	3569						
PROC. REF: AMM 53-30-01-220-801	PROC. REF: AMM 53-30-01-220-801							
53-30-01-220-801-01C	DETAILED INSPECTION OF THE FEEDER TANKS (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.240	AFL	3569						
PROC. REF: AMM 53-30-01-220-801	PROC. REF: AMM 53-30-01-220-801							
53-30-01-790-801-01 S	LEAK TEST OF THE FEEDER TANK							Service ATA:53
	MOS	11-Aug-20						
	HRS	5942.6	1500 (+30)					
WC#: 53.260	AFL	3569						
								PKG:21
PROC. REF: AMM 53-30-01-790-801	PROC. REF: AMM 53-30-01-790-801							
53-30-01-790-801-01A	LEAK TEST OF THE FEEDER TANK (MANDATORY 5-40)							Service ATA:53
	MOS/MSC	11-Aug-20	N/A					
	HRS	5942.6						
WC#: 53.280	AFL	3569						
PROC. REF: AMM 53-30-01-790-801	PROC. REF: AMM 53-30-01-790-801							
53-30-03-960-801-01	REPLACEMENT OF THE ALUMINUM LIGHTNING DIVERTER STRIPS ON REAR TANK							Service ATA:53
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 53.430	AFL	0						
PROC. REF: AMM 53-30-03-960-801	PROC. REF: AMM 53-30-03-960-801							
53-40-00-200-804-01 S	INSPECTION OF THE MLG BAYS - LH MLG BAY							Service ATA:53
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 32.1401	AFL	3940						
								PKG:207

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-40-00-200-804	PROC. REF: AMM 53-40-00-200-804							
53-40-00-200-804-01C	INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)							Service ATA:53
	MOS	24-Oct-25	12 (+1m)	Adj -22d	02-Oct-26	02-Nov-26	TOL (+24 d)	CPCP
	HRS	6700.5						
WC#: 53.245	AFL	3940						
PROC. REF: AMM 53-40-00-200-804	PROC. REF: AMM 53-40-00-200-804							
53-40-00-200-804-02 S	INSPECTION OF THE MLG BAYS - RH MLG BAY							Service ATA:53
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 32.1401	AFL	3940						
								PKG:207
PROC. REF: AMM 53-40-00-200-804	PROC. REF: AMM 53-40-00-200-804							
53-40-00-200-804-02C	INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)							Service ATA:53
	MOS	24-Oct-25	12 (+1m)	Adj -22d	02-Oct-26	02-Nov-26	TOL (+24 d)	CPCP
	HRS	6700.5						
WC#: 53.245	AFL	3940						
PROC. REF: AMM 53-40-00-200-804	PROC. REF: AMM 53-40-00-200-804							
53-40-00-210-803-02 S	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 53.0601	AFL	3875						
								PKG:16
PROC. REF: AMM 53-40-00-210-803	PROC. REF: AMM 53-40-00-210-803							
53-40-00-210-803-02C	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.255	AFL	3875						
PROC. REF: AMM 53-40-00-210-803	PROC. REF: AMM 53-40-00-210-803							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-220-802-01 S	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 53.450	AFL	3569						
								PKG:31
PROC. REF: AMM 53-40-00-220-802 PROC. REF: AMM 53-40-00-220-802								
53-40-00-220-802-01A	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (MANDATORY 5-40)							Service ATA:53
	MOS	11-Aug-20	74		11-Oct-26		2 d	MANDATORY 5-40
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 53-40-00-220-802 PROC. REF: AMM 53-40-00-220-802								
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 53-40-00-220-802 PROC. REF: AMM 53-40-00-220-802								
53-40-00-220-803-01 S	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 53.0602	AFL	3569						
								PKG:31
PROC. REF: AMM 53-40-00-220-803 PROC. REF: AMM 53-40-00-220-803								
53-40-00-220-803-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.295	AFL	3569						
PROC. REF: AMM 53-40-00-220-803 PROC. REF: AMM 53-40-00-220-803								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-40-00-220-804-01 S	DETAILED INSPECTION OF THE MLG BAYS - LH MLG BAY							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 32.1402	AFL	3875						
								PKG:16
PROC. REF: AMM 53-40-00-220-804	PROC. REF: AMM 53-40-00-220-804							
53-40-00-220-804-01C	DETAILED INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.315	AFL	3875						
PROC. REF: AMM 53-40-00-220-804	PROC. REF: AMM 53-40-00-220-804							
53-40-00-220-804-02 S	DETAILED INSPECTION OF THE MLG BAYS - RH MLG BAY							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 32.1402	AFL	3875						
								PKG:16
PROC. REF: AMM 53-40-00-220-804	PROC. REF: AMM 53-40-00-220-804							
53-40-00-220-804-02C	DETAILED INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.315	AFL	3875						
PROC. REF: AMM 53-40-00-220-804	PROC. REF: AMM 53-40-00-220-804							
53-40-07-220-801-01	DETAILED INSPECTION OF THE CENTERWING TANK LOWER PANELS							Service ATA:53
	MOS/MSC	11-Jul-95	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-40-07-220-801	PROC. REF: AMM 53-40-07-220-801							
53-40-07-220-801-01A	DETAILED INSPECTION OF THE CENTERWING TANK LOWER PANELS (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.165	AFL	0	T:20000		20000		15990	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 53-40-07-220-801	PROC. REF: AMM 53-40-07-220-801							
53-40-07-250-801-01A	EDDY CURRENT INSPECTION OF CENTERWING TANK LOWER PANEL SPLICE (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.172	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-40-07-250-801	PROC. REF: AMM 53-40-07-250-801							
53-40-07-280-801-01	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS							Service ATA:53
	MOS	15-Jul-96	T:360 (+2m)		15-Jul-26	15-Sep-26	OVD	
	HRS	0						
WC#: 53.400	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-40-07-280-801	PROC. REF: AMM 53-40-07-280-801							
53-40-07-280-801-01A	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.155	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-40-07-280-801	PROC. REF: AMM 53-40-07-280-801							
53-40-07-280-801-01C	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS (CPCP)							Service ATA:53
	MOS	15-Jul-96	T:360 (+2m)		15-Jul-26	15-Sep-26	OVD	CPCP
	HRS	0						
WC#: 53.325	AFL	0						
PROC. REF: AMM 53-40-07-280-801	PROC. REF: AMM 53-40-07-280-801							
53-40-07-960-801-01A	DISCARD CENTRAL WING SECTION OF THE CENTERWING TANK LOWER PANELS (MANDATORY 5-40)							Service ATA:53
	MOS/MSC	15-Jul-96	O/C					LIFE LIMIT
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-40-07-960-801	PROC. REF: AMM 53-40-07-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-00-220-801-01 S	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								
53-41-00-220-801-01C	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.335	AFL	3875						
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								
53-41-00-220-801-02 S	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								
53-41-00-220-801-02C	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.335	AFL	3875						
PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801PROC. REF: AMM 53-41-00-220-801, AMM 53-41-00-220-801								
53-41-00-620-802-01 S	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING UPPER BOLT RECESSES							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.170	AFL	3569						
								PKG:31
PROC. REF: AMM 53-41-00-620-802PROC. REF: AMM 53-41-00-620-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-00-620-802-01C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING UPPER BOLT RECESSES (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.345	AFL	3569						
PROC. REF: AMM 53-41-00-620-802	PROC. REF: AMM 53-41-00-620-802							
53-41-00-620-802-02 S	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING UPPER BOLT RECESSES							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.180	AFL	3569						
								PKG:31
PROC. REF: AMM 53-41-00-620-802	PROC. REF: AMM 53-41-00-620-802							
53-41-00-620-802-02C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING UPPER BOLT RECESSES (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.345	AFL	3569						
PROC. REF: AMM 53-41-00-620-802	PROC. REF: AMM 53-41-00-620-802							
53-41-00-620-802-03 S	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING LOWER BOLT RECESSES							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.170	AFL	3569						
								PKG:31
PROC. REF: AMM 53-41-00-620-802	PROC. REF: AMM 53-41-00-620-802							
53-41-00-620-802-03C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - LH WING LOWER BOLT RECESSES (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 53-41-00-620-802	PROC. REF: AMM 53-41-00-620-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-00-620-802-04 S	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING LOWER BOLT RECESSES							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.180	AFL	3569						
								PKG:31
PROC. REF: AMM 53-41-00-620-802	PROC. REF: AMM 53-41-00-620-802							
53-41-00-620-802-04C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - RH WING LOWER BOLT RECESSES (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 53-41-00-620-802	PROC. REF: AMM 53-41-00-620-802							
53-41-01-640-801-01 S	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - LH LINK ROD							Service ATA:53
PN:PN	MOS	11-Aug-20	72 (+2m)					
SN:UNKNOWN	HRS	5942.6						
WC#: 57.040	AFL	3569						
								PKG:31
PROC. REF: AMM 53-41-01-640-801	PROC. REF: AMM 53-41-01-640-801							
53-41-01-640-801-02 S	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - RH LINK ROD							Service ATA:53
PN:PN	MOS	11-Aug-20	72 (+2m)					
SN:UNKNOWN	HRS	5942.6						
WC#: 57.040	AFL	3569						
								PKG:31
PROC. REF: AMM 53-41-01-640-801	PROC. REF: AMM 53-41-01-640-801							
53-41-01-900-801-01	REMOVAL / INSTALLATION OF THE WING TO FUSELAGE CONNECTING ROD AT FRAME 29							Component ATA:53
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.040	AFL	0						
PROC. REF: AMM 53-41-01-900-801	PROC. REF: AMM 53-41-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-41-01-900-801-02	RH WING TO FUSELAGE CONNECTING AT FRAME 29 ROD							Component ATA:53
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.040	AFL	0						
PROC. REF: AMM 53-41-01-900-801	PROC. REF: AMM 53-41-01-900-801							
53-50-00-210-804-02 S	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT							Service ATA:53
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 53.0801	AFL	3940						
								PKG:207
PROC. REF: AMM 53-50-00-210-804	PROC. REF: AMM 53-50-00-210-804							
53-50-00-210-804-02C	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)							Service ATA:53
	MOS	24-Oct-25	12 (+1m)	Adj -22d	02-Oct-26	02-Nov-26	TOL (+24 d)	CPCP
	HRS	6700.5						
WC#: 53.350	AFL	3940						
PROC. REF: AMM 53-50-00-210-804	PROC. REF: AMM 53-50-00-210-804							
53-50-00-210-806-02 S	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 53.0701	AFL	3875						
								PKG:16
PROC. REF: AMM 53-50-00-210-806	PROC. REF: AMM 53-50-00-210-806							
53-50-00-210-806-02C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.355	AFL	3875						
PROC. REF: AMM 53-50-00-210-806	PROC. REF: AMM 53-50-00-210-806							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-50-00-210-807-02 S	GENERAL VISUAL INSPECTION OF THE APU AREA							Service ATA:53
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 49.124	AFL	3940						
								PKG:207
PROC. REF: AMM 53-50-00-210-807	PROC. REF: AMM 53-50-00-210-807							
53-50-00-220-803-02 S	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT							Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 53.0702	AFL	3569						
								PKG:31
PROC. REF: AMM 53-50-00-220-803	PROC. REF: AMM 53-50-00-220-803							
53-50-00-220-803-02C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							Service ATA:53
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 53.375	AFL	3569						
PROC. REF: AMM 53-50-00-220-803	PROC. REF: AMM 53-50-00-220-803							
53-50-00-220-805-01 S	DETAILED INSPECTION OF THE REAR COMPARTMENT							Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 53.0802	AFL	3875						
								PKG:16
PROC. REF: AMM 53-50-00-220-805	PROC. REF: AMM 53-50-00-220-805							
53-50-00-220-805-01C	DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)							Service ATA:53
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 53.385	AFL	3875						
PROC. REF: AMM 53-50-00-220-805	PROC. REF: AMM 53-50-00-220-805							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-50-34-220-801-01A	DETAILED INSPECTION OF THE FRAME 34 UPPER AND LOWER SECTIONS (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.142	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-50-34-220-801	PROC. REF: AMM 53-50-34-220-801							
53-50-35-220-801-01	DETAILED INSPECTION OF THE FRAME 35 LOWER SECTION							Service ATA:53
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.100	AFL	0		TAC 0				
PROC. REF: AMM 53-50-35-220-801	PROC. REF: AMM 53-50-35-220-801							
53-50-35-220-802-01A	DETAILED INSPECTION OF THE FRAME 35 UPPER AND LOWER SECTIONS (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-50-35-220-802	PROC. REF: AMM 53-50-35-220-802							
53-50-35-250-801-01A	EDDY CURRENT INSPECTION OF THE FRAME 35 VERTICAL BEAMS (MANDATORY 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.185	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-50-35-250-801	PROC. REF: AMM 53-50-35-250-801							
53-50-40-220-802-01	DETAILED INSPECTION OF THE STUB-FUSELAGE ASSEMBLY SCREWS AT FRAMES 41 AND 42							Service ATA:53
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
WC#: 53.220	AFL	0						
PROC. REF: AMM 53-50-40-220-802	PROC. REF: AMM 53-50-40-220-802							
53-50-44-220-801-01A	DETAILED INSPECTION OF THE FIN STUB FRONT SPAR (MANDATORY REF 5-40)							Service ATA:53
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.205	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 53-50-44-220-801	PROC. REF: AMM 53-50-44-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-80-00-200-801-01	S	CHECK OF THE CONDENSATION AND STREAM WATER DRAINS						Service ATA:53
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 51.040	AFL	3875						
								PKG:16
PROC. REF: AMM 53-80-00-200-801	PROC. REF: AMM 53-80-00-200-801							
53-80-09-710-801-01	S	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS						Service ATA:53
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 51.050	AFL	3569						
								PKG:31
PROC. REF: AMM 53-80-09-710-801	PROC. REF: AMM 53-80-09-710-801							
530321		FLIGHT COMPARTMENT REMOVABLE WINDOW FAIRING						Component ATA:53
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 53.210	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
ATA 54 - NACELLES/PYLONS								
54-00-00-210-810-03		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1						Service ATA:54
	MOS	24-Oct-25	19		24-May-27	227 d		
	HRS	6700.5	800		7500.5	708.2		
WC#: 54.0101	AFL	3940						
PROC. REF: AMM 54-00-00-210-810	PROC. REF: AMM 54-00-00-210-810							
54-00-00-210-810-03C		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (CPCP)						Service ATA:54
	MOS	24-Oct-25	19		24-May-27	227 d	CPCP	
	HRS	6700.5	800		7500.5	708.2		
WC#: 54.085	AFL	3940						
PROC. REF: AMM 54-00-00-210-810	PROC. REF: AMM 54-00-00-210-810							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-00-00-210-810-04	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3							Service ATA:54
	MOS	24-Oct-25	19		24-May-27		227 d	
	HRS	6700.5	800		7500.5		708.2	
WC#: 54.0101	AFL	3940						
PROC. REF: AMM 54-00-00-210-810	PROC. REF: AMM 54-00-00-210-810							
54-00-00-210-810-04C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (CPCP)							Service ATA:54
	MOS	24-Oct-25	19		24-May-27		227 d	CPCP
	HRS	6700.5	800		7500.5		708.2	
WC#: 54.055	AFL	3940						
PROC. REF: AMM 54-00-00-210-810	PROC. REF: AMM 54-00-00-210-810							
54-00-00-210-811-02	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE							Service ATA:54
	MOS	03-Jul-25	19		03-Feb-27		117 d	
	HRS	6670.5	800		7470.5		678.2	
WC#: 54.0201	AFL	3922						
PROC. REF: AMM 54-00-00-210-811	PROC. REF: AMM 54-00-00-210-811							
54-00-00-210-811-02C	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE (CPCP)							Service ATA:54
	MOS	03-Jul-25	19		03-Feb-27		117 d	CPCP
	HRS	6670.5	800		7470.5		678.2	
WC#: 54.065	AFL	3922						
PROC. REF: AMM 54-00-00-210-811	PROC. REF: AMM 54-00-00-210-811							
54-00-00-220-802-01 S	DETAILED INSPECTION OF THE ENGINE 2 NACELLE							Service ATA:54
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 54.0202	AFL	3569						
								PKG:32
PROC. REF: AMM 54-00-00-220-802	PROC. REF: AMM 54-00-00-220-802							
54-00-00-220-802-01C	DETAILED INSPECTION OF THE ENGINE 2 NACELLE (CPCP)							Service ATA:54
	MOS	11-Aug-20	144 (+2m)		11-Aug-32	11-Oct-32	2133 d (+61)	CPCP
	HRS	5942.6						
WC#: 54.095	AFL	3569						
PROC. REF: AMM 54-00-00-220-802	PROC. REF: AMM 54-00-00-220-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-11-00-610-801-01 S	SERVICING OF THE ENGINE COWLINGS - ENGINE 1 COWLINGS							Service ATA:54
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 54.030	AFL	3875						
								PKG:16
PROC. REF: AMM 54-11-00-610-801PROC. REF: AMM 54-11-00-610-801								
54-11-00-610-801-02 S	SERVICING OF THE ENGINE COWLINGS - ENGINE 2 COWLINGS							Service ATA:54
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 54.030	AFL	3875						
								PKG:16
PROC. REF: AMM 54-11-00-610-801PROC. REF: AMM 54-11-00-610-801								
54-11-00-610-801-03 S	SERVICING OF THE ENGINE COWLINGS - ENGINE 3 COWLINGS							Service ATA:54
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 54.030	AFL	3875						
								PKG:16
PROC. REF: AMM 54-11-00-610-801PROC. REF: AMM 54-11-00-610-801								
54-14-00-210-801-01	GENERAL VISUAL INSPECTION OF THE ENGINE CORE COWL ASSEMBLIES - ENGINE 1							Service ATA:54
	MOS	17-Jul-23						
	HRS	6504	300		6804		11.7	
	AFL	3825						
PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801								
54-14-00-210-801-02	GENERAL VISUAL INSPECTION OF THE ENGINE CORE COWL ASSEMBLIES - ENGINE 2							Service ATA:54
	MOS	17-Jul-23						
	HRS	6504	300		6804		11.7	
	AFL	3825						
PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-14-00-210-801-03	GENERAL VISUAL INSPECTION OF THE ENGINE CORE COWL ASSEMBLIES - ENGINE 3							Service ATA:54
	MOS	17-Jul-23						
	HRS	6504	300		6804		11.7	
	AFL	3825						
PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801PROC. REF: AMM 54-14-00-210-801, AMM 54-14-00-210-801								
54-42-17-200-801-01	CHECK FOR NON-LOOSENING OF SCREWS OF S-DUCT SECTIONS 2 AND 3 COUPLING FLANGES							Service ATA:54
	MOS	08-Sep-22						
	HRS	6221.1	600 (+30)		6821.1	6851.1	28.8 (+30)	
WC#: 54.070	AFL	3722						
PROC. REF: AMM 54-42-17-200-801PROC. REF: AMM 54-42-17-200-801								
54-50-00-220-802-01A	DETAILED INSPECTION OF PYLON UPPER FLANGE RIBS AT FRAME 32 (MANDATORY 5-40)							Service ATA:54
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 53.222	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 54-50-00-220-802PROC. REF: AMM 54-50-00-220-802								
540171	NO. 1 ENGINE REAR ATTACH FITTING							Component ATA:54
PN:F50B581106400	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 54.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
540173	NO. 1 ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT							Component ATA:54
PN:3073361-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 54.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
540176	NO. 1 ENGINE MAIN ATTACH FITTING							Component ATA:54
PN:F10A5B10555	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 54.040	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
540181	NO. 2 ENGINE REAR ATTACH FITTING							Component ATA:54
PN:F50B25520	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 54.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
540186	NO. 2 ENGINE REAR ATTACH LINK							Component ATA:54
PN:F50B255520110	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 54.050	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
540191	NO. 3 ENGINE REAR ATTACH FITTING							Component ATA:54
PN:F50B581106400	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 54.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
540193	NO. 3 ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT							Component ATA:54
PN:3073361-1	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 54.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
540196	NO. 3 ENGINE MAIN ATTACH FITTING							Component ATA:54
PN:F10A5B10555	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0						
WC#: 54.060	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 55 - STABILIZERS								
55-00-00-210-801-01 S	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT							Service ATA:55
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 55.0101	AFL	3875						

PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
PROC. REF: AMM 55-00-00-210-801 PROC. REF: AMM 55-00-00-210-801								
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)						Service	ATA:55
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 55.025	AFL	3875						
PROC. REF: AMM 55-00-00-210-801 PROC. REF: AMM 55-00-00-210-801								
55-00-00-220-801-01 S	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT						Service	ATA:55
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 55.0102	AFL	3569						
								PKG:31
PROC. REF: AMM 55-00-00-220-801 PROC. REF: AMM 55-00-00-220-801								
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)						Service	ATA:55
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 55.035	AFL	3569						
PROC. REF: AMM 55-00-00-220-801 PROC. REF: AMM 55-00-00-220-801								
55-00-00-270-801-01 S	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES						Service	ATA:55
	MOS	16-Mar-22	72 (+2m)					
	HRS	6124.5						
WC#: 55.070	AFL	3681						
								PKG:31
PROC. REF: AMM 55-00-00-270-801 PROC. REF: AMM 55-00-00-270-801								
55-00-00-270-801-01A	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES (MANDATORY 5-40)						Service	ATA:55
	MOS	16-Mar-22					MANDATORY 5-40	
	HRS	6124.5						
	AFL	3681	3750		7431		3421	
PROC. REF: AMM 55-00-00-270-801 PROC. REF: AMM 55-00-00-270-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-00-00-270-801-01C		ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES (CPCP)						Service ATA:55
	MOS	16-Mar-22	72 (+2m)		16-Mar-28	16-May-28	524 d (+61)	CPCP
	HRS	6124.5						
WC#: 55.060	AFL	3681						
PROC. REF: AMM 55-00-00-270-801	PROC. REF: AMM 55-00-00-270-801							
55-00-00-760-801-01	S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RUDDER						Service ATA:55
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 55.080	AFL	3875						
								PKG:16
PROC. REF: AMM 55-00-00-760-801	PROC. REF: AMM 55-00-00-760-801							
55-00-00-760-801-02	S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - LH ELEVATOR						Service ATA:55
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 55.080	AFL	3875						
								PKG:16
PROC. REF: AMM 55-00-00-760-801	PROC. REF: AMM 55-00-00-760-801							
55-00-00-760-801-03	S	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RH ELEVATOR						Service ATA:55
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 55.080	AFL	3875						
								PKG:16
PROC. REF: AMM 55-00-00-760-801	PROC. REF: AMM 55-00-00-760-801							
55-10-00-220-801-01	S	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE						Service ATA:55
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 55-10-00-220-801	PROC. REF: AMM 55-10-00-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-00-220-801-01C		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE (CPCP)						Service ATA:55
	MOS	11-Aug-20	144 (+2m)		11-Aug-32	11-Oct-32	2133 d (+61)	CPCP
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 55-10-00-220-801	PROC. REF: AMM 55-10-00-220-801							
55-10-00-220-802-01 S		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS						Service ATA:55
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
	AFL	3569						
								PKG:32
PROC. REF: AMM 55-10-00-220-802	PROC. REF: AMM 55-10-00-220-802							
55-10-00-220-802-01C		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS (CPCP)						Service ATA:55
	MOS	11-Aug-20	144 (+2m)		11-Aug-32	11-Oct-32	2133 d (+61)	CPCP
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 55-10-00-220-802	PROC. REF: AMM 55-10-00-220-802							
55-10-00-220-803-01A		DETAILED INSPECTION OF HORIZONTAL STABILIZER UPPER PANELS BETWEEN ROOT AND RIB2 (MANDATORY 5-40)						Service ATA:55
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 55.045	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 55-10-00-220-803	PROC. REF: AMM 55-10-00-220-803							
55-10-00-640-803-01 S		GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK, ACTUATOR UPPER HINGE, AND ELEVATOR U-JOINTS - LINKAGE U-JOINTS AND ELEVATOR BEARINGS						Service ATA:55
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 27.380	AFL	3875						
								PKG:16
PROC. REF: AMM 55-10-00-640-803	PROC. REF: AMM 55-10-00-640-803							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-00-640-803-02 S	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK, ACTUATOR UPPER HINGE, AND ELEVATOR U-JOINTS - HORIZONTAL STABILIZER FRONT HINGE POINTS							Service ATA:55
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 27.440	AFL	3875						
								PKG:16
PROC. REF: AMM 55-10-00-640-803	PROC. REF: AMM 55-10-00-640-803							
55-10-03-640-801-01 S	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM							Service ATA:55
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 27.440	AFL	3875						
								PKG:16
PROC. REF: AMM 55-10-03-640-801	PROC. REF: AMM 55-10-03-640-801							
55-10-31-220-801-01	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS							Service ATA:55
	MOS	11-Aug-20						
	HRS	5942.6						
WC#: 55.040	AFL	3569	3750		7319		3309	
								PKG:31
PROC. REF: AMM 55-10-31-220-801	PROC. REF: AMM 55-10-31-220-801							
55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)							Service ATA:55
	MOS	11-Aug-20						MANDATORY 5-40
	HRS	5942.6						
WC#: 55.040	AFL	3569	3750		7319		3309	
PROC. REF: AMM 55-10-31-220-801	PROC. REF: AMM 55-10-31-220-801							
55-10-33-640-801-01	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS							Service ATA:55
	MOS	24-Oct-25	12 (+1m)	Adj -46d	08-Sep-26	08-Oct-26	OVD	
	HRS	6700.5	600 (+30)		7300.5	7330.5	508.2 (+30)	
WC#: 27.430	AFL	3940						
PROC. REF: AMM 55-10-33-640-801	PROC. REF: AMM 55-10-33-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-39-220-801-01A	DETAILED INSPECTION OF HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS (MANDATORY 5-40)							Service ATA:55
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 55.065	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 55-10-39-220-801	PROC. REF: AMM 55-10-39-220-801							
55-20-00-220-801-01A	DETAILED INSPECTION OF THE ELEVATORS SKIN AND HINGE FITTINGS (MANDATORY 5-40)							Service ATA:55
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 55.050	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 55-20-00-220-801	PROC. REF: AMM 55-20-00-220-801							
55-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ELEVATORS - LH ELEVATOR							Component ATA:55
PN:FGFB341A1	MOS/MSC	11-Jul-95	O/C					
SN:404	HRS	0		TSN 0				
WC#: 55.020	AFL	0						
PROC. REF: AMM 55-20-01-900-801	PROC. REF: AMM 55-20-01-900-801							
55-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ELEVATORS - RH ELEVATOR							Component ATA:55
PN:FGFB342A1	MOS/MSC	11-Jul-95	O/C					
SN:404	HRS	0		TSN 0				
WC#: 55.020	AFL	0						
PROC. REF: AMM 55-20-01-900-801	PROC. REF: AMM 55-20-01-900-801							
55-20-03-640-801-01 S	LUBRICATION OF THE ELEVATOR BEARINGS - LH ELEVATOR							Service ATA:55
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 55.020	AFL	3569						
								PKG:32
PROC. REF: AMM 55-20-03-640-801	PROC. REF: AMM 55-20-03-640-801							
55-20-03-640-801-02 S	LUBRICATION OF THE ELEVATOR BEARINGS - RH ELEVATOR							Service ATA:55
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 55.020	AFL	3569						
								PKG:32

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
PROC. REF: AMM 55-20-03-640-801	PROC. REF: AMM 55-20-03-640-801							
55-20-03-640-802-01 S	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES							Service ATA:55
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 27.370	AFL	3940						
								PKG:207
PROC. REF: AMM 55-20-03-640-802	PROC. REF: AMM 55-20-03-640-802							
55-40-00-220-801-01A	DETAILED INSPECTION OF THE RUDDER SKIN AND HINGE FITTINGS (MANDATORY 5-40)							Service ATA:55
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 55.055	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 55-40-00-220-801	PROC. REF: AMM 55-40-00-220-801							
55-40-01-900-801-01	REMOVAL / INSTALLATION OF THE RUDDER							Component ATA:55
PN:F50B321	MOS/MSC	11-Jul-95	O/C					
SN:BZ50	HRS	0		TSN 0				
WC#: 55.030	AFL	0						
PROC. REF: AMM 55-40-01-900-801	PROC. REF: AMM 55-40-01-900-801							
55-40-05-640-801-01 S	LUBRICATION OF THE RUDDER BEARINGS							Service ATA:55
	MOS	11-Aug-20	144 (+2m)					
	HRS	5942.6						
WC#: 55.030	AFL	3569						
								PKG:32
PROC. REF: AMM 55-40-05-640-801	PROC. REF: AMM 55-40-05-640-801							
55-40-05-640-802-01 S	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES							Service ATA:55
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 27.280	AFL	3940						
								PKG:207
PROC. REF: AMM 55-40-05-640-802	PROC. REF: AMM 55-40-05-640-802							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-00-00-910-801-01	ACCEPTANCE CRITERIA FOR DAMAGE TO WINDSHIELDS, WINDOWS AND TRANSPARENT FAIRINGS							Service ATA:56
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 56-00-00-910-801	PROC. REF: AMM 56-00-00-910-801							
56-10-01-900-801-01	REMOVAL / INSTALLATION OF THE WINDSHIELDS - PILOT WINDSHIELD (126H1)							Component ATA:56
PN:MY20267-10-8	MOS/MSC	11-Jul-95	O/C					
SN:2675	HRS	0		TSN 0				
WC#: 56.010	AFL	0						
PROC. REF: AMM 56-10-01-900-801	PROC. REF: AMM 56-10-01-900-801							
56-10-01-900-801-02	REMOVAL / INSTALLATION OF THE WINDSHIELDS - COPILOT WINDSHIELD (126H2)							Component ATA:56
PN:MY20268-10-8	MOS/MSC	11-Jul-95	O/C					
SN:2808	HRS	0		TSN 0				
WC#: 56.010	AFL	0						
PROC. REF: AMM 56-10-01-900-801	PROC. REF: AMM 56-10-01-900-801							
56-10-01-900-801-03	REMOVAL / INSTALLATION OF THE WINDSHIELDS - FRONT WINDSHIELD (127H)							Component ATA:56
PN:MY20261-10-8	MOS/MSC	11-Jul-95	O/C					
SN:2811	HRS	0		TSN 0				
WC#: 56.010	AFL	0						
PROC. REF: AMM 56-10-01-900-801	PROC. REF: AMM 56-10-01-900-801							
56-10-07-900-801-01	REMOVAL / INSTALLATION OF THE RH LATERAL WINDOW - RH LATERAL WINDOW (145H2)							Component ATA:56
PN:MY20263-10-6	MOS/MSC	17-Jul-96	O/C					
SN:4718	HRS	150						
WC#: 56.020	AFL	62						
PROC. REF: AMM 56-10-07-900-801, AMM 56-10-07-900-801	PROC. REF: AMM 56-10-07-900-801, AMM 56-10-07-900-801							
56-10-09-640-801-01 S	LUBRICATION OF THE OPENING WINDOW MECHANISM - LH SLIDING WINDOW (145H1)							Service ATA:56
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 56.040	AFL	3875						
								PKG:16
PROC. REF: AMM 56-10-09-640-801	PROC. REF: AMM 56-10-09-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-09-900-801-01	REMOVAL / INSTALLATION OF THE OPENING WINDOW							Component ATA:56
PN:MY20264-10-5	MOS/MSC	23-Jul-99	O/C					
SN:4977	HRS	1045						
WC#: 56.040	AFL	706						
PROC. REF: AMM 56-10-09-900-801PROC. REF: AMM 56-10-09-900-801								
56-10-11-900-801-01	REMOVAL / INSTALLATION OF THE REAR WINDOWS - LH REAR WINDOW (146H1)							Component ATA:56
PN:F50B265001001B5	MOS/MSC	30-Aug-11	O/C	TSN 0				
SN:1471	HRS	3831.35		TSN 0				
WC#: 56.030	AFL	2491		TSN 0				
PROC. REF: AMM 56-10-11-900-801, AMM 56-10-11-900-801PROC. REF: AMM 56-10-11-900-801, AMM 56-10-11-900-801								
56-10-11-900-801-02	REMOVAL / INSTALLATION OF THE REAR WINDOWS - RH REAR WINDOW (146H2)							Component ATA:56
PN:F50B266001001B3	MOS/MSC	23-Jul-99	O/C	TSN 0				
SN:952	HRS	1045		TSN 0				
WC#: 56.030	AFL	706		TSN 0				
PROC. REF: AMM 56-10-11-900-801, AMM 56-10-11-900-801PROC. REF: AMM 56-10-11-900-801, AMM 56-10-11-900-801								
56-20-05-900-801-01	NO. 1 LEFT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:6530	HRS	0		TSN 0				
WC#: 56.060	AFL	0		TSN 0				
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 1 RIGHT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6521	HRS	0		TSN 0				
WC#: 56.060	AFL	0						
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								
56-20-05-900-801-01	NO. 2 LEFT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6516	HRS	0		TSN 0				
WC#: 56.070	AFL	0						
PROC. REF: AMM 56-20-05-900-801PROC. REF: AMM 56-20-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01	NO. 2 RIGHT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6522	HRS	0		TSN 0				
WC#: 56.070	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 3 LEFT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6527	HRS	0		TSN 0				
WC#: 56.080	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 3 RIGHT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6523	HRS	0		TSN 0				
WC#: 56.080	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 4 LEFT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6518	HRS	0		TSN 0				
WC#: 56.090	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 4 RIGHT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6526	HRS	0		TSN 0				
WC#: 56.090	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 5 LEFT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6519	HRS	0		TSN 0				
WC#: 56.100	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-05-900-801-01	NO. 5 RIGHT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6525	HRS	0		TSN 0				
WC#: 56.100	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 6 LEFT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6515	HRS	0		TSN 0				
WC#: 56.110	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 6 RIGHT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6524	HRS	0		TSN 0				
WC#: 56.110	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 7 LEFT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6520	HRS	0		TSN 0				
WC#: 56.120	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
56-20-05-900-801-01	NO. 7 RIGHT PASSENGER CABIN WINDOW							Component ATA:56
PN:F50B228100A4	MOS/MSC	11-Jul-95	O/C					
SN:6517	HRS	0		TSN 0				
WC#: 56.120	AFL	0						
PROC. REF: AMM 56-20-05-900-801	PROC. REF: AMM 56-20-05-900-801							
561136	LH DEFOGGING VALVE							Component ATA:56
PN:L95-001	MOS/MSC	11-Jul-95	O/C					
SN:22012	HRS	0		TSN 0				
WC#: 56.050	AFL	0						
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
561141	RH DEFOGGING VALVE							Component ATA:56
PN:L95-001	MOS/MSC	11-Jul-95	O/C					
SN:22225	HRS	0		TSN 0				
WC#: 56.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 57 - WINGS								
57-00-00-210-801-03 S	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING							Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.0101	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-03C	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING (CPCP)							Service ATA:57
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 57.035	AFL	3875						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-04 S	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING							Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.0101	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								
57-00-00-210-801-04C	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING (CPCP)							Service ATA:57
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	CPCP
	HRS	6601.6						
WC#: 57.035	AFL	3875						
PROC. REF: AMM 57-00-00-210-801PROC. REF: AMM 57-00-00-210-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-220-802-01 S	DETAILED INSPECTION OF THE WINGS - LH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.0102	AFL	3569						
								PKG:31
PROC. REF: AMM 57-00-00-220-802 PROC. REF: AMM 57-00-00-220-802								
57-00-00-220-802-01C	DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)							Service ATA:57
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 57.045	AFL	3569						
PROC. REF: AMM 57-00-00-220-802 PROC. REF: AMM 57-00-00-220-802								
57-00-00-220-802-02 S	DETAILED INSPECTION OF THE WINGS - RH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.0102	AFL	3569						
								PKG:31
PROC. REF: AMM 57-00-00-220-802 PROC. REF: AMM 57-00-00-220-802								
57-00-00-220-802-02C	DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)							Service ATA:57
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 57.045	AFL	3569						
PROC. REF: AMM 57-00-00-220-802 PROC. REF: AMM 57-00-00-220-802								
57-00-00-760-801-01 S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AILERON							Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.240	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801 PROC. REF: AMM 57-00-00-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-760-801-02	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AILERON						Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.240	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								
57-00-00-760-801-03	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH FLAPS						Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.250	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								
57-00-00-760-801-04	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH FLAPS						Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.250	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								
57-00-00-760-801-05	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH SLATS						Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.260	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								
57-00-00-760-801-06	S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH SLATS						Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.260	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801PROC. REF: AMM 57-00-00-760-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-00-00-760-801-07 S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AIRBRAKES							Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.270	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801	PROC. REF: AMM 57-00-00-760-801							
57-00-00-760-801-08 S	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AIRBRAKES							Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 57.270	AFL	3875						
								PKG:16
PROC. REF: AMM 57-00-00-760-801	PROC. REF: AMM 57-00-00-760-801							
57-00-01-900-801-01	REMOVAL / INSTALLATION OF THE WINGS - LH WING							Component ATA:57
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01-900-801	PROC. REF: AMM 57-00-01-900-801							
57-00-01-900-801-02	REMOVAL / INSTALLATION OF THE WINGS - RH WING							Component ATA:57
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01-900-801	PROC. REF: AMM 57-00-01-900-801							
57-10-00-220-801-01	DETAILED INSPECTION OF THE MLG WHEEL WELL GAP SEALING BRUSHES - LH MLG BAY							Service ATA:57
	MOS/MSC	05-Jun-17	O/C	Adj -35d				
	HRS	5157.3						
WC#: 57.150	AFL	3249						
PROC. REF: AMM 57-10-00-220-801	PROC. REF: AMM 57-10-00-220-801							
57-10-00-220-801-02	DETAILED INSPECTION OF THE MLG WHEEL WELL GAP SEALING BRUSHES - RH MLG BAY							Service ATA:57
	MOS/MSC	05-Jun-17	O/C	Adj -35d				
	HRS	5157.3						
WC#: 57.150	AFL	3249						
PROC. REF: AMM 57-10-00-220-801	PROC. REF: AMM 57-10-00-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-00-290-801-01 S	BORESCOPE INSPECTION OF THE WING TANKS							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.030	AFL	3569						
								PKG:31
PROC. REF: AMM 57-10-00-290-801	PROC. REF: AMM 57-10-00-290-801							
57-10-00-290-801-01A	BORESCOPE INSPECTION OF THE WING TANKS (MANDATORY 5-40)							Service ATA:57
	MOS	11-Aug-20	74		11-Oct-26		2 d	MANDATORY 5-40
	HRS	5942.6						
	AFL	3569						
PROC. REF: AMM 57-10-00-290-801	PROC. REF: AMM 57-10-00-290-801							
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)							Service ATA:57
	MOS	11-Aug-20	72 (+2m)		11-Aug-26	11-Oct-26	TOL (+2 d)	CPCP
	HRS	5942.6						
WC#: 57.057	AFL	3569						
PROC. REF: AMM 57-10-00-290-801	PROC. REF: AMM 57-10-00-290-801							
57-10-01-220-801-01A	DETAILED INSPECTION OF LOWER WING PANELS (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.172	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-01-220-801	PROC. REF: AMM 57-10-01-220-801							
57-10-01-270-801-01	ULTRASONIC INSPECTION OF THE WING LOWER SURFACE PANEL STIFFENERS BETWEEN RIBS 13 AND 17							Service ATA:57
	MOS	15-Jul-96						
	HRS	0						
WC#: 57.290	AFL	0	T:14200		14200		10190	
PROC. REF: AMM 57-10-01-270-801	PROC. REF: AMM 57-10-01-270-801							
57-10-01-270-801-01A	ULTRASONIC INSPECTION OF THE WING LOWER SURFACE PANEL STIFFENERS BETWEEN RIBS 13 AND 17 (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.295	AFL	0	T:14200		14200		10190	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: AMM 57-10-01-270-801	PROC. REF: AMM 57-10-01-270-801							
57-10-01-280-801-01	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS							Service ATA:57
	MOS	15-Jul-96	T:360 (+2m)		15-Jul-26	15-Sep-26	OVD	
	HRS	0						
WC#: 57.280	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-01-280-801	PROC. REF: AMM 57-10-01-280-801							
57-10-01-280-801-01A	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.165	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-01-280-801	PROC. REF: AMM 57-10-01-280-801							
57-10-01-280-801-01C	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS (CPCP)							Service ATA:57
	MOS	15-Jul-96	T:360 (+2m)		15-Jul-26	15-Sep-26	OVD	CPCP
	HRS	0						
WC#: 57.065	AFL	0						
PROC. REF: AMM 57-10-01-280-801	PROC. REF: AMM 57-10-01-280-801							
57-10-14-200-801-01A	INSPECTION OF WING FRONT SPAR FROM ROOT TO RIB 8 AND FROM RIB 9 TO RIB 17 (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.175	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-14-200-801	PROC. REF: AMM 57-10-14-200-801							
57-10-14-200-802-01A	INSPECTION OF WING FRONT SPAR FROM RIB 8 TO RIB 9 (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.182	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-14-200-802	PROC. REF: AMM 57-10-14-200-802							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-14-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR SPLICE AREA AT RIB7 - LH WING (MANDATORY 5-40)							Service ATA:57
	MOS	11-Jul-95						MANDATORY 5-40
	HRS	0						
	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-14-250-802	PROC. REF: AMM 57-10-14-250-802							
57-10-14-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR SPLICE AREA AT RIB7 - RH WING (MANDATORY 5-40)							Service ATA:57
	MOS	11-Jul-95						MANDATORY 5-40
	HRS	0						
	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-14-250-802	PROC. REF: AMM 57-10-14-250-802							
57-10-15-200-801-01A	INSPECTION OF WING REAR SPAR 1 FROM ROOT TO RIB 3 (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.192	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-15-200-801	PROC. REF: AMM 57-10-15-200-801							
57-10-15-200-802-01A	INSPECTION OF WING REAR SPAR 2 FROM RIB 3 TO RIB 17 (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.185	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-15-200-802	PROC. REF: AMM 57-10-15-200-802							
57-10-15-250-801-01A	EDDY CURRENT INSPECTION OF WING REAR SPAR RIB 8 SPLICE (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.195	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-10-15-250-801	PROC. REF: AMM 57-10-15-250-801							
57-41-13-640-801-01 S	LUBRICATION OF THE SLAT ROLLERS							Service ATA:57
	MOS	02-Oct-24	24 (+1m)					
	HRS	6601.6						
WC#: 27.910	AFL	3875						
								PKG:16
PROC. REF: AMM 57-41-13-640-801	PROC. REF: AMM 57-41-13-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-45-01-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD SLATS - LH INBOARD SLAT							Component ATA:57
PN:F50B133B2	MOS/MSC	11-Jul-95	O/C					
SN:318RA	HRS	0		TSN 0				
WC#: 57.110	AFL	0						
PROC. REF: AMM 57-45-01-900-801	PROC. REF: AMM 57-45-01-900-801							
57-45-01-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD SLATS - RH INBOARD SLAT							Component ATA:57
PN:F50B143B2	MOS/MSC	11-Jul-95	O/C					
SN:426RA	HRS	0		TSN 0				
WC#: 57.110	AFL	0						
PROC. REF: AMM 57-45-01-900-801	PROC. REF: AMM 57-45-01-900-801							
57-45-13-900-801-01	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - LH OUTBOARD SLAT							Component ATA:57
PN:F50B134B2	MOS/MSC	11-Jul-95	O/C					
SN:435RA	HRS	0		TSN 0				
WC#: 57.120	AFL	0						
PROC. REF: AMM 57-45-13-900-801	PROC. REF: AMM 57-45-13-900-801							
57-45-13-900-801-02	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - RH OUTBOARD SLAT							Component ATA:57
PN:F50B144B2	MOS/MSC	11-Jul-95	O/C					
SN:434RA	HRS	0		TSN 0				
WC#: 57.120	AFL	0						
PROC. REF: AMM 57-45-13-900-801	PROC. REF: AMM 57-45-13-900-801							
57-45-25-250-801-01A	EDDY CURRENT INSPECTION OF SLAT TRACKS (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.225	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-45-25-250-801	PROC. REF: AMM 57-45-25-250-801							
57-55-00-700-801-01 S	CHECK OF THE FLAP LATERAL CLEARANCE - LH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.235	AFL	3569						
								PKG:31
PROC. REF: AMM 57-55-00-700-801	PROC. REF: AMM 57-55-00-700-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-55-00-700-801-02 S	CHECK OF THE FLAP LATERAL CLEARANCE - RH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.235	AFL	3569						
								PKG:31
PROC. REF: AMM 57-55-00-700-801	PROC. REF: AMM 57-55-00-700-801							
57-55-01-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD FLAPS - LH INBOARD FLAP							Component ATA:57
PN:F50B161B8	MOS/MSC	11-Jul-95	O/C					
SN:408LE253	HRS	0		TSN 0				
WC#: 57.070	AFL	0						
PROC. REF: AMM 57-55-01-900-801	PROC. REF: AMM 57-55-01-900-801							
57-55-01-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD FLAPS - RH INBOARD FLAP							Component ATA:57
PN:F50B162B8	MOS/MSC	11-Jul-95	O/C					
SN:410LE253	HRS	0		TSN 0				
WC#: 57.070	AFL	0						
PROC. REF: AMM 57-55-01-900-801	PROC. REF: AMM 57-55-01-900-801							
57-55-05-900-801-01	REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - LH OUTBOARD FLAP							Component ATA:57
PN:F50B163B8	MOS/MSC	11-Jul-95	O/C					
SN:409LE253	HRS	0		TSN 0				
WC#: 57.080	AFL	0						
PROC. REF: AMM 57-55-05-900-801	PROC. REF: AMM 57-55-05-900-801							
57-55-05-900-801-02	REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - RH OUTBOARD FLAP							Component ATA:57
PN:F50B164B8	MOS/MSC	11-Jul-95	O/C					
SN:410LE253	HRS	0		TSN 0				
WC#: 57.080	AFL	0						
PROC. REF: AMM 57-55-05-900-801	PROC. REF: AMM 57-55-05-900-801							
57-55-07-220-801-01 S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - LH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.130	AFL	3569						
								PKG:31
PROC. REF: AMM 57-55-07-220-801	PROC. REF: AMM 57-55-07-220-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-55-07-220-801-02 S	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - RH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.130	AFL	3569						
								PKG:31
PROC. REF: AMM 57-55-07-220-801	PROC. REF: AMM 57-55-07-220-801							
57-55-07-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD / OUTBOARD FLAP JUNCTION FAIRINGS - LH FLAP JUNCTION FAIRING							Component ATA:57
PN:PN	MOS/MSC	10-Feb-02	O/C					
SN:UNKNOWN	HRS	1532						
WC#: 57.130	AFL	1065						
PROC. REF: AMM 57-55-07-900-801	PROC. REF: AMM 57-55-07-900-801							
57-55-11-210-801-01 S	GENERAL VISUAL INSPECTION OF THE FORE FLAP BRACKETS - LH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.140	AFL	3569						
								PKG:31
PROC. REF: AMM 57-55-11-210-801	PROC. REF: AMM 57-55-11-210-801							
57-55-11-210-801-02 S	GENERAL VISUAL INSPECTION OF THE FORE FLAP BRACKETS - RH WING							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.140	AFL	3569						
								PKG:31
PROC. REF: AMM 57-55-11-210-801	PROC. REF: AMM 57-55-11-210-801							
57-55-13-640-801-01	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - LH WING							Service ATA:57
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	
	HRS	6601.6	800 (+30)		7401.6	7431.6	609.3 (+30)	
	AFL	3875						
PROC. REF: AMM 57-55-13-640-801	PROC. REF: AMM 57-55-13-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-55-13-640-801-02	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - RH WING							Service ATA:57
	MOS	02-Oct-24	24 (+1m)	Adj -24d	08-Sep-26	08-Oct-26	OVD	
	HRS	6601.6	800 (+30)		7401.6	7431.6	609.3 (+30)	
	AFL	3875						
PROC. REF: AMM 57-55-13-640-801	PROC. REF: AMM 57-55-13-640-801							
57-55-21-250-801-01	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5							Service ATA:57
	MOS	15-Jul-96						
	HRS	0						
WC#: 57.310	AFL	0	T:7900		7900		3890	
PROC. REF: AMM 57-55-21-250-801	PROC. REF: AMM 57-55-21-250-801							
57-55-21-250-801-01A	EDDY CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5 (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
	AFL	0	T:7900		7900		3890	
PROC. REF: AMM 57-55-21-250-801	PROC. REF: AMM 57-55-21-250-801							
57-60-00-220-801-01A	DETAILED INSPECTION OF THE AILERON SKIN AND HINGE FITTINGS (MANDATORY 5-40)							Service ATA:57
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 57.210	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 57-60-00-220-801	PROC. REF: AMM 57-60-00-220-801							
57-60-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERONS - LH AILERON							Component ATA:57
PN:F50B153A1	MOS/MSC	11-Jul-95	O/C					
SN:233SE402	HRS	0		TSN 0				
WC#: 57.020	AFL	0						
PROC. REF: AMM 57-60-01-900-801	PROC. REF: AMM 57-60-01-900-801							
57-60-01-900-801-02	REMOVAL / INSTALLATION OF THE AILERONS - RH AILERON							Component ATA:57
PN:F50B154A1	MOS/MSC	11-Jul-95	O/C					
SN:238SE404	HRS	0		TSN 0				
WC#: 57.020	AFL	0						
PROC. REF: AMM 57-60-01-900-801	PROC. REF: AMM 57-60-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-05-640-801-01 S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - LH AILERON BEARINGS							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.020	AFL	3569						
								PKG:31
PROC. REF: AMM 57-60-05-640-801	PROC. REF: AMM 57-60-05-640-801							
57-60-05-640-801-02 S	PRESSURE LUBRICATION OF THE AILERON BEARINGS - RH AILERON BEARINGS							Service ATA:57
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 57.020	AFL	3569						
								PKG:31
PROC. REF: AMM 57-60-05-640-801	PROC. REF: AMM 57-60-05-640-801							
57-60-05-640-802-01 S	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - LH AILERON							Service ATA:57
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 57-60-05-640-802	PROC. REF: AMM 57-60-05-640-802							
57-60-05-640-802-02 S	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - RH AILERON							Service ATA:57
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 57-60-05-640-802	PROC. REF: AMM 57-60-05-640-802							
57-60-09-270-801-01	ULTRASONIC INSPECTION OF THE COMPOSITE MATERIAL AILERONS - LH AILERON F50B153A1							Service ATA:57
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 57.020	AFL	0						
PROC. REF: AMM 57-60-09-270-801	PROC. REF: AMM 57-60-09-270-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-09-270-801-02	ULTRASONIC INSPECTION OF THE COMPOSITE MATERIAL AILERONS - RH AILERON F50B154A1							Service ATA:57
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 57.020	AFL	0						
PROC. REF: AMM 57-60-09-270-801	PROC. REF: AMM 57-60-09-270-801							
57-70-01-900-801-01	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH OUTBOARD AIRBRAKE							Component ATA:57
PN:FGFB165	MOS/MSC	11-Jul-95	O/C					
SN:414LE223	HRS	0		TSN 0				
WC#: 57.090	AFL	0						
PROC. REF: AMM 57-70-01-900-801	PROC. REF: AMM 57-70-01-900-801							
57-70-01-900-801-02	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH MIDDLE AIRBRAKE							Component ATA:57
PN:FGFB169	MOS/MSC	11-Jul-95	O/C					
SN:815LE223	HRS	0		TSN 0				
WC#: 57.090	AFL	0						
PROC. REF: AMM 57-70-01-900-801	PROC. REF: AMM 57-70-01-900-801							
57-70-01-900-801-03	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH INBOARD AIRBRAKE							Component ATA:57
PN:FGFB167	MOS/MSC	11-Jul-95	O/C					
SN:406LE223	HRS	0		TSN 0				
WC#: 57.090	AFL	0						
PROC. REF: AMM 57-70-01-900-801	PROC. REF: AMM 57-70-01-900-801							
57-70-01-900-801-04	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH INBOARD AIRBRAKE							Component ATA:57
PN:FGFB168	MOS/MSC	11-Jul-95	O/C					
SN:409LE223	HRS	0		TSN 0				
WC#: 57.100	AFL	0						
PROC. REF: AMM 57-70-01-900-801	PROC. REF: AMM 57-70-01-900-801							
57-70-01-900-801-05	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH MIDDLE AIRBRAKE							Component ATA:57
PN:FGFB169	MOS/MSC	11-Jul-95	O/C					
SN:816LE223	HRS	0		TSN 0				
WC#: 57.100	AFL	0						
PROC. REF: AMM 57-70-01-900-801	PROC. REF: AMM 57-70-01-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-70-01-900-801-06	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH OUTBOARD AIRBRAKE							Component ATA:57
PN:FGFB166	MOS/MSC	11-Jul-95	O/C					
SN:407LE223	HRS	0		TSN 0				
WC#: 57.100	AFL	0						
PROC. REF: AMM 57-70-01-900-801	PROC. REF: AMM 57-70-01-900-801							
57-70-03-640-801-01 S	LUBRICATION OF THE AIRBRAKE HINGES							Service ATA:57
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
	AFL	3940						
								PKG:207
PROC. REF: AMM 57-70-03-640-801	PROC. REF: AMM 57-70-03-640-801							
57-70-03-960-801-01	DISCARD OF OUTBOARD AIRBRAKE CENTER HINGE - LH OUTBOARD AIRBRAKE CENTER HINGE (L901CD)							Service ATA:57
PN:F50B165003001	MOS	15-Jul-96		TAC 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TAC 0				
WC#: 57.230	AFL	0	20000		20000		15990	
PROC. REF: AMM 57-70-03-960-801	PROC. REF: AMM 57-70-03-960-801							
57-70-03-960-801-01A	DISCARD LH OUTBOARD AIRBRAKE CENTRAL HINGE (MANDATORY 5-40)							Service ATA:57
PN:F50B165003001	MOS	15-Jul-96						MANDATORY 5-40
SN:UNKNOWN	HRS	0						
	AFL	0	20000		20000		15990	
PROC. REF: AMM 57-70-03-960-801	PROC. REF: AMM 57-70-03-960-801							
57-70-03-960-801-02	DISCARD OF OUTBOARD AIRBRAKE CENTER HINGE - RH OUTBOARD AIRBRAKE CENTER HINGE (R901CD)							Service ATA:57
PN:F50B165003001	MOS	15-Jul-96		TAC 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TAC 0				
WC#: 57.230	AFL	0	20000		20000		15990	
PROC. REF: AMM 57-70-03-960-801	PROC. REF: AMM 57-70-03-960-801							
57-70-03-960-801-02A	DISCARD RH OUTBOARD AIRBRAKE CENTRAL HINGE (MANDATORY 5-40)							Service ATA:57
PN:F50B165003001	MOS	15-Jul-96						MANDATORY 5-40
SN:UNKNOWN	HRS	0						
	AFL	0	20000		20000		15990	
PROC. REF: AMM 57-70-03-960-801	PROC. REF: AMM 57-70-03-960-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570701	CENTRAL WING SECTION							Component ATA:57
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.300	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
575151	LINKING FAIRING-INBOARD FLAP-LEFT OUTBOARD FLAP ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	10-Feb-02	O/C					
SN:UNKNOWN	HRS	1532						
WC#: 57.130	AFL	1065						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
575181	LH OUTBOARD AIRBRAKE CENTRAL HINGE							Component ATA:57
PN:F50B165003001	MOS/MSC	11-Jul-95	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
575186	RH OUTBOARD AIRBRAKE CENTRAL HINGE							Component ATA:57
PN:F50B165003001	MOS/MSC	11-Jul-95	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 57.230	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 71 - POWER PLANT								
71-00-00-910-802-01	ENGINE INSPECTION RUN-UP - ENGINE 1 (L4EZ)							Service ATA:71
	MOS/MSC	16-Mar-22	C/C					
	HRS	6124.5						
WC#: 71.010	AFL	3681						
PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802								
71-00-00-910-802-02	ENGINE INSPECTION RUN-UP - ENGINE 2 (M4EZ)							Service ATA:71
	MOS/MSC	16-Mar-22	C/C					
	HRS	6124.5						
WC#: 71.020	AFL	3681						
PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-910-802-03	ENGINE INSPECTION RUN-UP - ENGINE 3 (R4EZ)							Service ATA:71
	MOS/MSC	16-Mar-22	C/C					
	HRS	6124.5						
WC#: 71.030	AFL	3681						
PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802PROC. REF: AMM 71-00-00-910-802, AMM 71-00-00-910-802								
71-20-01-220-801-01A	DETAILED INSPECTION OF ENGINE 1 AND 3 FRONT AND REAR MOUNTS (MANDATORY 5-40)							Service ATA:71
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 54.075	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 71-20-01-220-801PROC. REF: AMM 71-20-01-220-801								
71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 1 FRONT MOUNT							Service ATA:71
	MOS	15-Jul-96						
	HRS	0						
	AFL	0	T:11250		11250		7240	
PROC. REF: AMM 71-20-02-250-801PROC. REF: AMM 71-20-02-250-801								
71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 3 FRONT MOUNT							Service ATA:71
	MOS	15-Jul-96						
	HRS	0						
	AFL	0	T:11250		11250		7240	
PROC. REF: AMM 71-20-02-250-801PROC. REF: AMM 71-20-02-250-801								
71-20-02-250-801-03	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 1 FAIL SAFE ATTACHMENTS							Service ATA:71
	MOS	15-Jul-96						
	HRS	0						
	AFL	0	T:11250		11250		7240	
PROC. REF: AMM 71-20-02-250-801PROC. REF: AMM 71-20-02-250-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-02-250-801-04	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS AND FAIL SAFE ATTACHMENTS - ENGINE 3 FAIL SAFE ATTACHMENTS							Service ATA:71
	MOS	15-Jul-96						
	HRS	0						
	AFL	0	T:11250		11250		7240	
PROC. REF: AMM 71-20-02-250-801	PROC. REF: AMM 71-20-02-250-801							
71-20-05-350-801-01	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 1 FRONT MOUNT UPPER VIBRATION ISOLATOR (L901EZ1)							Service ATA:71
PN:3071070-2	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-05-350-801	PROC. REF: AMM 71-20-05-350-801							
71-20-05-350-801-02	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 1 FRONT MOUNT LOWER VIBRATION ISOLATOR (L901EZ2)							Service ATA:71
PN:3071070-2	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-05-350-801	PROC. REF: AMM 71-20-05-350-801							
71-20-05-350-801-03	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 3 FRONT MOUNT UPPER VIBRATION ISOLATOR (R901EZ1)							Service ATA:71
PN:3071070-2	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-05-350-801	PROC. REF: AMM 71-20-05-350-801							
71-20-05-350-801-04	RESTORATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 3 FRONT MOUNT LOWER VIBRATION ISOLATOR (R901EZ2)							Service ATA:71
PN:3071070-2	MOS/MSC	15-Jul-96	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-05-350-801	PROC. REF: AMM 71-20-05-350-801							

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 1 FRONT MOUNT UPPER VIBRATION ISOLATOR (L901EZ1)							Component ATA:71
PN:3071070-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.050	AFL	0						
PROC. REF: AMM 71-20-05-900-801	PROC. REF: AMM 71-20-05-900-801							
71-20-05-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 1 FRONT MOUNT LOWER VIBRATION ISOLATOR (L901EZ2)							Component ATA:71
PN:3071070-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.050	AFL	0						
PROC. REF: AMM 71-20-05-900-801	PROC. REF: AMM 71-20-05-900-801							
71-20-05-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 3 FRONT MOUNT UPPER VIBRATION ISOLATOR (R901EZ1)							Component ATA:71
PN:3071070-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.055	AFL	0						
PROC. REF: AMM 71-20-05-900-801	PROC. REF: AMM 71-20-05-900-801							
71-20-05-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 FRONT MOUNT VIBRATION ISOLATORS - ENGINE 3 FRONT MOUNT LOWER VIBRATION ISOLATOR (R901EZ2)							Component ATA:71
PN:3071070-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.055	AFL	0						
PROC. REF: AMM 71-20-05-900-801	PROC. REF: AMM 71-20-05-900-801							
71-20-07-250-801-01	SPECIAL DETAILED INSPECTION (NDT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT (L910EZ)							Service ATA:71
	MOS	15-Jul-96						
	HRS	0						
WC#: 54.100	AFL	0	T:11250		11250		7240	
PROC. REF: AMM 71-20-07-250-801	PROC. REF: AMM 71-20-07-250-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-07-250-801-02	SPECIAL DETAILED INSPECTION (NDT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT (R910EZ)							Service ATA:71
	MOS	15-Jul-96						
	HRS	0						
WC#: 54.100	AFL	0	T:11250		11250		7240	
PROC. REF: AMM 71-20-07-250-801	PROC. REF: AMM 71-20-07-250-801							
71-20-07-960-801-01	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 1							Service ATA:71
PN:3073361-1	MOS/MSC	23-Oct-12	O/C					
SN:UNKNOWN	HRS	4193.5						
WC#: 54.040	AFL	2686						
PROC. REF: AMM 71-20-07-960-801	PROC. REF: AMM 71-20-07-960-801							
71-20-07-960-801-01A	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 1 (MANDATORY 5-40)							Service ATA:71
PN:3073361-1	MOS/MSC	23-Oct-12	O/C					
SN:UNKNOWN	HRS	4193.5						
	AFL	2686						
PROC. REF: AMM 71-20-07-960-801	PROC. REF: AMM 71-20-07-960-801							
71-20-07-960-801-02	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 3							Service ATA:71
PN:3073361-1	MOS/MSC	23-Oct-12	O/C					
SN:UNKNOWN	HRS	4193.5						
WC#: 54.060	AFL	2686						
PROC. REF: AMM 71-20-07-960-801	PROC. REF: AMM 71-20-07-960-801							
71-20-07-960-801-02A	DISCARD OF THE ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT - ENGINE 3 (MANDATORY 5-40)							Service ATA:71
PN:3073361-1	MOS/MSC	23-Oct-12	O/C					
SN:UNKNOWN	HRS	4193.5						
	AFL	2686						
PROC. REF: AMM 71-20-07-960-801	PROC. REF: AMM 71-20-07-960-801							
71-20-09-350-801-01	RESTORATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 1 REAR MOUNT VIBRATION ISOLATOR (L911EZ)							Service ATA:71
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-09-350-801	PROC. REF: AMM 71-20-09-350-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-09-350-801-02	RESTORATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS (OVERHAUL) - ENGINE 3 REAR MOUNT VIBRATION ISOLATOR (R911EZ)							Service ATA:71
	MOS/MSC	15-Jul-96	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-09-350-801	PROC. REF: AMM 71-20-09-350-801							
71-20-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS - ENGINE 1 REAR MOUNT VIBRATION ISOLATOR (L911EZ)							Component ATA:71
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.070	AFL	0		TSN 0				
PROC. REF: AMM 71-20-09-900-801	PROC. REF: AMM 71-20-09-900-801							
71-20-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 REAR MOUNT VIBRATION ISOLATORS - ENGINE 3 REAR MOUNT VIBRATION ISOLATOR (R911EZ)							Component ATA:71
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 71.080	AFL	0		TSN 0				
PROC. REF: AMM 71-20-09-900-801	PROC. REF: AMM 71-20-09-900-801							
71-20-11-220-801-01A	DETAILED INSPECTION OF ENGINE 2 HOISTING PLATE AND MOUNTS (MANDATORY 5-40)							Service ATA:71
	MOS	15-Jul-96						MANDATORY 5-40
	HRS	0						
WC#: 54.082	AFL	0	T:20000		20000		15990	
PROC. REF: AMM 71-20-11-220-801	PROC. REF: AMM 71-20-11-220-801							
71-20-11-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 MOUNT COMPONENTS - ENGINE 2 LH FRONT MOUNT							Component ATA:71
PN:LM833SA13	MOS/MSC	14-Feb-11	O/C	TSN 0				
SN:UNKNOWN	HRS	3653.6		TSN 0				
WC#: 71.045	AFL	2403		TSN 0				
PROC. REF: AMM 71-20-11-900-801	PROC. REF: AMM 71-20-11-900-801							
71-20-11-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 2 MOUNT COMPONENTS - ENGINE 2 RH FRONT MOUNT							Component ATA:71
PN:LM833-SA13	MOS/MSC	14-Feb-11	O/C	TSN 0				
SN:UNKNOWN	HRS	3653.6		TSN 0				
WC#: 71.046	AFL	2403		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71-20-11-900-801PROC. REF: AMM 71-20-11-900-801								
71-20-11-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE 2 MOUNT COMPONENTS - ENGINE 2 AFT MOUNT							Component ATA:71
PN:LM833-SA9	MOS/MSC	14-Feb-11	O/C	TSN 0				
SN:UNKNOWN	HRS	3653.6		TSN 0				
WC#: 71.047	AFL	2403		TSN 0				
PROC. REF: AMM 71-20-11-900-801PROC. REF: AMM 71-20-11-900-801								
71-20-17-230-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 LH FRONT VIBRATION ISOLATOR (M900EZ1)							Service ATA:71
PN:LM833SA13	MOS	23-Oct-12						
SN:UNKNOWN	HRS	4193.5	5000 (+150)		9193.5	9343.5	2401.2 (+150)	
	AFL	2686						
PROC. REF: AMM 71-20-17-230-801, AMM 71-20-17-230-801PROC. REF: AMM 71-20-17-230-801, AMM 71-20-17-230-801								
71-20-17-230-801-02	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 RH FRONT VIBRATION ISOLATOR (M900EZ2)							Service ATA:71
PN:LM833-SA13	MOS	23-Oct-12						
SN:UNKNOWN	HRS	4193.5	5000 (+150)		9193.5	9343.5	2401.2 (+150)	
	AFL	2686						
PROC. REF: AMM 71-20-17-230-801, AMM 71-20-17-230-801PROC. REF: AMM 71-20-17-230-801, AMM 71-20-17-230-801								
71-20-21-230-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 REAR VIBRATION ISOLATOR / REPLACEMENT OF RUBBER CORES - ENGINE 2 REAR VIBRATION ISOLATOR (M910EZ)							Service ATA:71
PN:LM833-SA9	MOS	23-Oct-12						
SN:UNKNOWN	HRS	4193.5	5000 (+150)		9193.5	9343.5	2401.2 (+150)	
	AFL	2686						
PROC. REF: AMM 71-20-21-230-801PROC. REF: AMM 71-20-21-230-801								
71-20-21-960-801-01	DISCARD OF THE ENGINE 2 REAR MOUNT VIBRATION ISOLATOR - ENGINE 2 REAR VIBRATION ISOLATOR (M910EZ)							Service ATA:71
PN:LM833-SA9	MOS/MSC	14-Feb-11	O/C					
SN:UNKNOWN	HRS	3653.6						
WC#: 71.065	AFL	2403						
PROC. REF: AMM 71-20-21-960-801PROC. REF: AMM 71-20-21-960-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-23-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 HOISTING PLATE - ENGINE 2 HOISTING PLATE							Component ATA:71
PN:4210-3	MOS/MSC	11-Jul-95	O/C					
SN:369	HRS	0		TSN 0				
WC#: 71.060	AFL	0						
PROC. REF: AMM 71-20-23-900-801	PROC. REF: AMM 71-20-23-900-801							
710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:71
	MOS	17-Apr-19						
	HRS	5597.2	1400 (+100)	Adj -70.8	(6926.4) 7119.7	7026.4	327.4 (+100)	
WC#: 71.010	ENC	3400						
PROC. REF: LMM 72-00-00	PROC. REF: LMM 72-00-00							
710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:71
	MOS	19-Apr-19						
	HRS	5594.6	1400 (+100)	Adj -70.4	(6924.2) 7120.1	7024.2	327.8 (+100)	
WC#: 71.010	ENC	3396						
PROC. REF: LMM 72-00-00	PROC. REF: LMM 72-00-00							
710120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service ATA:71
	MOS	26-Apr-19						
	HRS	5556.2	1400 (+100)	Adj -70.8	(6885.4) 7119.7	6985.4	327.4 (+100)	
WC#: 71.010	ENC	3380						
PROC. REF: LMM 72-00-00	PROC. REF: LMM 72-00-00							
710130 S	NO. 1 ENGINE - FAN ROTOR ASSEMBLY BLADES - INSPECT FOR FOREIGN OBJECT DAMAGE							Service ATA:71
	MOS	29-May-24						
	HRS	6379.4	300 (+100)					
WC#: 71.020	ENC	3752						PKG:0
PROC. REF: LMM 72-00-00	PROC. REF: LMM 72-00-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710130 S	NO. 2 ENGINE - FAN ROTOR ASSEMBLY BLADES - INSPECT FOR FOREIGN OBJECT DAMAGE							Service ATA:71
	MOS	29-May-24						
	HRS	6376.8	300 (+100)					
WC#: 71.020	ENC	3748						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
710130 S	NO. 3 ENGINE - FAN ROTOR ASSEMBLY BLADES - INSPECT FOR FOREIGN OBJECT DAMAGE							Service ATA:71
	MOS	29-May-24						
	HRS	6338.4	300 (+100)					
WC#: 71.020	ENC	3732						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
710336	FLIGHT CHECK ENGINE							Service ATA:71
	MOS/MSC	15-Jul-96	E/C					
	HRS	0						
WC#: 71.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
714010 S	NO. 1 ENGINE - ELECTRICAL WIRING AND CONNECTIONS - CHECK FOR SECURITY AND DAMAGE							Service ATA:71
	MOS	30-May-23						
	HRS	6221.1	600 (+200)					
WC#: 71.040	ENC	3693						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
714010 S	NO. 2 ENGINE - ELECTRICAL WIRING AND CONNECTIONS - CHECK FOR SECURITY AND DAMAGE							Service ATA:71
	MOS	30-May-23						
	HRS	6218.5	600 (+200)					
WC#: 71.040	ENC	3689						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
714010 S	NO. 3 ENGINE - ELECTRICAL WIRING AND CONNECTIONS - CHECK FOR SECURITY AND DAMAGE							Service ATA:71
	MOS	30-May-23						
	HRS	6180.1	600 (+200)					
WC#: 71.040	ENC	3673						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
715010 S	NO. 1 ENGINE - PLUMBING LINES AND CONNECTIONS - CHECK FOR SECURITY, LEAKS, CRACKS, CUTS, OR RUBBING							Service ATA:71
	MOS	30-May-23						
	HRS	6221.1	600 (+200)					
WC#: 71.050	ENC	3693						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
715010 S	NO. 2 ENGINE - PLUMBING LINES AND CONNECTIONS - CHECK FOR SECURITY, LEAKS, CRACKS, CUTS, OR RUBBING							Service ATA:71
	MOS	30-May-23						
	HRS	6218.5	600 (+200)					
WC#: 71.050	ENC	3689						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
715010 S	NO. 3 ENGINE - PLUMBING LINES AND CONNECTIONS - CHECK FOR SECURITY, LEAKS, CRACKS, CUTS, OR RUBBING							Service ATA:71
	MOS	30-May-23						
	HRS	6180.1	600 (+200)					
WC#: 71.050	ENC	3673						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:3072800-5	MOS/MSC	18-Jun-19	E/C					
SN:P-76905	HRS	5790.5		TSN 5597.2				
	AFL	3507						
PROC. REF: SIL F731-88, AMM 71-00-01-900-801, AMM 71-00-01-900-801PROC. REF: SIL F731-88, AMM 71-00-01-900-801, AMM 71-00-01-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:3072800-5	MOS/MSC	18-Jun-19	E/C					
SN:P-76904	HRS	5790.5		TSN 5594.6				
	AFL	3507						
PROC. REF: SIL F731-88, AMM 71-00-05-900-801, AMM 71-00-05-900-801, AMM 71-00-05-900-801PROC. REF: SIL F731-88, AMM 71-00-05-900-801, AMM 71-00-05-900-801, AMM 71-00-05-900-801								
71EN3	NO. 3 ENGINE							Component ATA:71
PN:3072800-5	MOS/MSC	18-Jun-19	E/C					
SN:P-76903	HRS	5790.5		TSN 5556.2				
	AFL	3507						
PROC. REF: SIL F731-88, AMM 71-00-01-900-801, AMM 71-00-01-900-801PROC. REF: SIL F731-88, AMM 71-00-01-900-801, AMM 71-00-01-900-801								
ATA 72 - ENGINE								
723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	22-Oct-12						
	HRS	4126.4	4200 (+200)		(8326.4) 8519.7	8526.4	1727.4 (+200)	
WC#: 72.010	ENC	2630						
PROC. REF: GENERIC NO REF, LMM 72-00-00PROC. REF: GENERIC NO REF, LMM 72-00-00								
723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	15-Oct-12						
	HRS	4124.2	4200 (+200)		(8324.2) 8520.1	8524.2	1727.8 (+200)	
WC#: 72.010	ENC	2626						
PROC. REF: GENERIC NO REF, LMM 72-00-00PROC. REF: GENERIC NO REF, LMM 72-00-00								
723110	NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service ATA:72
	MOS	16-Oct-12						
	HRS	4085.4	4200 (+200)		(8285.4) 8519.7	8485.4	1727.4 (+200)	
WC#: 72.010	ENC	2610						
PROC. REF: GENERIC NO REF, LMM 72-00-00PROC. REF: GENERIC NO REF, LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724110	NO. 1 ENGINE - COMBUSTION PLENUM CASE							Component ATA:72
PN:3072443-4	MOS/MSC	30-Nov-93	O/C					
SN:3P8548	HRS	0		TSN 0				
WC#: 72.020	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724110	NO. 2 ENGINE - COMBUSTION PLENUM CASE							Component ATA:72
PN:3072443-4	MOS/MSC	29-Nov-93	O/C					
SN:3P12863	HRS	0		TSN 0				
WC#: 72.020	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724110	NO. 3 ENGINE - COMBUSTION PLENUM CASE							Component ATA:72
PN:3072443-4	MOS/MSC	16-Oct-12	O/C					
SN:3P11689	HRS	4085.4						
WC#: 72.020	ENC	2610						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724120	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE							Service ATA:72
	MOS	17-Apr-19						
	HRS	5597.2	1400 (+100)		(6997.2) 7190.5	7097.2	398.2 (+100)	
WC#: 72.030	ENC	3400						
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04								
724120	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE							Service ATA:72
	MOS	19-Apr-19						
	HRS	5594.6	1400 (+100)		(6994.6) 7190.5	7094.6	398.2 (+100)	
WC#: 72.030	ENC	3396						
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724120	NO. 3 ENGINE - INSPECT COMBUSTION PLENUM CASE							Service ATA:72
	MOS	26-Apr-19						
	HRS	5556.2	1400 (+100)		(6956.2) 7190.5	7056.2	398.2 (+100)	
WC#: 72.030	ENC	3380						
PROC. REF: LMM 72-40-04PROC. REF: LMM 72-40-04								
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075830-1	MOS	22-Oct-12						LIFE LIMIT
SN:060322905323	HRS	4126.4		TSN 1415.3				
WC#: 72.040	ENC	2630	3000	TSN 807	(4823) 4930		920	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075830-1	MOS	15-Oct-12						LIFE LIMIT
SN:050322902350	HRS	4124.2		TSN 1773.7				
WC#: 72.040	ENC	2626	3000	TSN 1014	(4612) 4723		713	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								
725010	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3075830-1	MOS	07-Sep-07						LIFE LIMIT
SN:060322905343	HRS	2711.1		TSN 0				
WC#: 72.040	ENC	1823	3000	TSN 0	(4823) 4950		940	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3072542-5	MOS	22-Oct-12		TSN 0				LIFE LIMIT
SN:12-182449-05843	HRS	4126.4		TSN 0				
WC#: 72.050	ENC	2630	3000	TSN 0	(5630) 5737		1727	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3072542-5	MOS	15-Oct-12						LIFE LIMIT
SN:1018244901438	HRS	4124.2		TSN 353.8				
WC#: 72.050	ENC	2626	3000	TSN 189	(5437) 5548		1538	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								
725020	NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3072542-5	MOS	16-Oct-12		TSN 0				LIFE LIMIT
SN:12-182449-05854	HRS	4085.4		TSN 0				
WC#: 72.050	ENC	2610	3000	TSN 0	(5610) 5737		1727	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3072821-5	MOS	22-Oct-12						LIFE LIMIT
SN:3-12172-142	HRS	4126.4		TSN 4126.4				
WC#: 72.060	ENC	2630	6000	TSN 2630	(6000) 6107		2097	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3072821-5	MOS	29-Nov-93						LIFE LIMIT
SN:3-12172-110	HRS	0		TSN 0				
WC#: 72.060	ENC	0	6000	TSN 0	(6000) 6111		2101	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								
725030	NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component ATA:72
PN:3072821-5	MOS	29-Nov-93						LIFE LIMIT
SN:3-12172-109	HRS	0		TSN 0				
WC#: 72.060	ENC	0	6000	TSN 0	(6000) 6127		2117	
PROC. REF: LMM 72-50-04PROC. REF: LMM 72-50-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC							Component ATA:72
PN:3072316-2	MOS	22-Oct-12						LIFE LIMIT
SN:2-03229-132	HRS	4126.4		TSN 4126.4				
WC#: 72.070	ENC	2630	7000	TSN 2630	(7000) 7107		3097	
PROC. REF: LMM 72-50-06	PROC. REF: LMM 72-50-06							
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC							Component ATA:72
PN:3072316-2	MOS	29-Nov-93						LIFE LIMIT
SN:2-03229-206	HRS	0		TSN 0				
WC#: 72.070	ENC	0	7000	TSN 0	(7000) 7111		3101	
PROC. REF: LMM 72-50-06	PROC. REF: LMM 72-50-06							
725040	NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC							Component ATA:72
PN:3072316-2	MOS	29-Nov-93						LIFE LIMIT
SN:2-03229-128	HRS	0		TSN 0				
WC#: 72.070	ENC	0	7000	TSN 0	(7000) 7127		3117	
PROC. REF: LMM 72-50-06	PROC. REF: LMM 72-50-06							
725050	NO. 1 ENGINE - FAN ROTOR DISC							Component ATA:72
PN:3073570-3	MOS	22-Oct-12		TSR 0				LIFE LIMIT
SN:3-03229-131	HRS	4126.4		TSN 4126.4, TSR 0				
WC#: 72.090	ENC	2630	10000	TSN 2630, TSR 0	(10000) 10107		6097	
PROC. REF: LMM 72-70-03	PROC. REF: LMM 72-70-03							
725050	NO. 2 ENGINE - FAN ROTOR DISC							Component ATA:72
PN:3073563-2	MOS	29-Nov-93						LIFE LIMIT
SN:3-03229-149	HRS	0		TSN 0				
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 10111		6101	
PROC. REF: LMM 72-70-03	PROC. REF: LMM 72-70-03							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725050	NO. 3 ENGINE - FAN ROTOR DISC							Component ATA:72
PN:3073563-2	MOS	29-Nov-93						LIFE LIMIT
SN:3-03229-517	HRS	0		TSN 0				
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 10127		6117	
PROC. REF: LMM 72-70-03PROC. REF: LMM 72-70-03								
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072395-2	MOS	22-Oct-12						LIFE LIMIT
SN:2-03501-2900	HRS	4126.4		TSN 4126.4				
WC#: 72.100	ENC	2630	10000	TSN 2630	(10000) 10107		6097	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072395-2	MOS	29-Nov-93						LIFE LIMIT
SN:2-03501-2944	HRS	0		TSN 0				
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 10111		6101	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725060	NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072395-2	MOS	29-Nov-93						LIFE LIMIT
SN:2-03501-2924	HRS	0		TSN 0				
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 10127		6117	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072396-3	MOS	22-Oct-12						LIFE LIMIT
SN:3-03160-271	HRS	4126.4		TSN 4126.4				
WC#: 72.110	ENC	2630	10000	TSN 2630	(10000) 10107		6097	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072396-3	MOS	29-Nov-93						LIFE LIMIT
SN:3-03160-275	HRS	0		TSN 0				
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 10111		6101	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725070	NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072396-3	MOS	29-Nov-93						LIFE LIMIT
SN:3-03160-281	HRS	0		TSN 0				
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 10127		6117	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072397-3	MOS	22-Oct-12						LIFE LIMIT
SN:2-12172-0688	HRS	4126.4		TSN 4126.4				
WC#: 72.120	ENC	2630	10000	TSN 2630	(10000) 10107		6097	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072397-3	MOS	29-Nov-93						LIFE LIMIT
SN:2-12172-0667	HRS	0		TSN 0				
WC#: 72.120	ENC	0	10000	TSN 0	(10000) 10111		6101	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725080	NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072397-3	MOS	29-Nov-93						LIFE LIMIT
SN:2-12172-0670	HRS	0		TSN 0				
WC#: 72.120	ENC	0	10000	TSN 0	(10000) 10127		6117	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072398-2	MOS	22-Oct-12						LIFE LIMIT
SN:1-03160-860	HRS	4126.4		TSN 4126.4				
WC#: 72.130	ENC	2630	10000	TSN 2630	(10000) 10107		6097	
PROC. REF: LMM 72-30-04	PROC. REF: LMM 72-30-04							
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:3072398-2	MOS	29-Nov-93						LIFE LIMIT
SN:1-03160-874	HRS	0		TSN 0				
WC#: 72.130	ENC	0	10000	TSN 0	(10000) 10111		6101	
PROC. REF: LMM 72-30-04	PROC. REF: LMM 72-30-04							
725090	NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component ATA:72
PN:302398-2	MOS	29-Nov-93						LIFE LIMIT
SN:1-03160-899	HRS	0		TSN 0				
WC#: 72.130	ENC	0	10000	TSN 0	(10000) 10127		6117	
PROC. REF: LMM 72-30-04	PROC. REF: LMM 72-30-04							
725091	NO. 1 ENGINE - LOW PRESSURE TIE ROD							Component ATA:72
PN:3073049-1	MOS/MSC	22-Oct-12	O/C					
SN:3P14255	HRS	4126.4		TSN 4126.4				
WC#: 72.140	ENC	2630		TSN 2630				
PROC. REF: LMM 72-30-10	PROC. REF: LMM 72-30-10							
725091	NO. 2 ENGINE - LOW PRESSURE TIE ROD							Component ATA:72
PN:3073049-1	MOS/MSC	29-Nov-93	O/C					
SN:3P14265	HRS	0		TSN 0				
WC#: 72.140	ENC	0		TSN 0				
PROC. REF: LMM 72-30-10	PROC. REF: LMM 72-30-10							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725091	NO. 3 ENGINE - LOW PRESSURE TIE ROD							Component ATA:72
PN:3073049-1	MOS/MSC	16-Oct-12	O/C					
SN:2P-12220	HRS	4085.4		TSN 16527.6				
WC#: 72.140	ENC	2610		TSN 12979				
PROC. REF: LMM 72-30-10PROC. REF: LMM 72-30-10								
725110	NO. 1 ENGINE - HIGH PRESSURE IMPELLER							Component ATA:72
PN:3073398-2	MOS	22-Oct-12						LIFE LIMIT
SN:3-12172-199	HRS	4126.4		TSN 4126.4				
WC#: 72.150	ENC	2630	10000	TSN 2630	(10000) 10107		6097	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725110	NO. 2 ENGINE - HIGH PRESSURE IMPELLER							Component ATA:72
PN:3073398-2	MOS	29-Nov-93						LIFE LIMIT
SN:2-12172-806	HRS	0		TSN 0				
WC#: 72.150	ENC	0	10000	TSN 0	(10000) 10111		6101	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725110	NO. 3 ENGINE - HIGH PRESSURE IMPELLER							Component ATA:72
PN:3073398-2	MOS	29-Nov-93						LIFE LIMIT
SN:2-12172-805	HRS	0		TSN 0				
WC#: 72.150	ENC	0	10000	TSN 0	(10000) 10127		6117	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725120	NO. 1 ENGINE - ROTATING SEAL							Component ATA:72
PN:3072729-1	MOS/MSC	22-Oct-12	O/C					
SN:3P11264	HRS	4126.4		TSN 4126.4				
WC#: 72.160	ENC	2630		TSN 2630				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725120	NO. 2 ENGINE - ROTATING SEAL							Component ATA:72
PN:3072729-1	MOS/MSC	29-Nov-93	O/C					
SN:3P11255	HRS	0		TSN 0				
WC#: 72.160	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725120	NO. 3 ENGINE - ROTATING SEAL							Component ATA:72
PN:3072729-1	MOS/MSC	29-Nov-93	O/C					
SN:3P11261	HRS	0		TSN 0				
WC#: 72.160	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725130	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT							Component ATA:72
PN:3072545-1	MOS	22-Oct-12						LIFE LIMIT
SN:3P14894	HRS	4126.4		TSN 4126.4				
WC#: 72.170	ENC	2630	12000	TSN 2630	(12000) 12107		8097	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725130	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT							Component ATA:72
PN:3072545-1	MOS	29-Nov-93						LIFE LIMIT
SN:3P14897	HRS	0		TSN 0				
WC#: 72.170	ENC	0	12000	TSN 0	(12000) 12111		8101	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725130	NO. 3 ENGINE - HIGH PRESSURE SHOULDERED SHAFT							Component ATA:72
PN:3072545-1	MOS	29-Nov-93						LIFE LIMIT
SN:3P14895	HRS	0		TSN 0				
WC#: 72.170	ENC	0	12000	TSN 0	(12000) 12127		8117	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725140	NO. 1 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE							Component ATA:72
PN:3072411-1	MOS	22-Oct-12						LIFE LIMIT
SN:3-03160-528	HRS	4126.4		TSN 4126.4				
WC#: 72.180	ENC	2630	10000	TSN 2630	(10000) 10107		6097	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725140	NO. 2 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE							Component ATA:72
PN:3072411-1	MOS	29-Nov-93						LIFE LIMIT
SN:3-03160-1080	HRS	0		TSN 0				
WC#: 72.180	ENC	0	10000	TSN 0	(10000) 10111		6101	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725140	NO. 3 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE							Component ATA:72
PN:3072411-1	MOS	29-Nov-93						LIFE LIMIT
SN:3-03160-521	HRS	0		TSN 0				
WC#: 72.180	ENC	0	10000	TSN 0	(10000) 10127		6117	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725150	NO. 1 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3071955-3	MOS/MSC	22-Oct-12	O/C					
SN:3P13140	HRS	4126.4		TSN 4126.4				
WC#: 72.190	ENC	2630		TSN 2630				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725150	NO. 2 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3071955-5	MOS/MSC	29-Nov-93	O/C					
SN:3P13137	HRS	0		TSN 0				
WC#: 72.190	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725150	NO. 3 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3071955-5	MOS/MSC	29-Nov-93	O/C					
SN:3P13132	HRS	0		TSN 0				
WC#: 72.190	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3072318-5	MOS/MSC	22-Oct-12	O/C	TSO 0				
SN:2P-31175	HRS	4126.4		TSO 0				
WC#: 72.200	ENC	2630		TSO 0				
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05								
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3072318-3	MOS/MSC	29-Nov-93	O/C					
SN:2P8097	HRS	0		TSN 0				
WC#: 72.200	ENC	0		TSN 0				
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05								
725160	NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3072318-3	MOS/MSC	29-Nov-93	O/C					
SN:3P14226	HRS	0		TSN 0				
WC#: 72.200	ENC	0		TSN 0				
PROC. REF: LMM 72-50-05PROC. REF: LMM 72-50-05								
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3072319-11	MOS/MSC	30-Nov-93	O/C					
SN:2-01345-1818	HRS	0		TSN 0				
WC#: 72.220	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725180	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3072319-11	MOS/MSC	29-Nov-93	O/C					
SN:3-01345-206	HRS	0		TSN 0				
WC#: 72.220	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725180	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component ATA:72
PN:3077123-1	MOS/MSC	16-Oct-12	O/C	TSN 0				
SN:11-3300-03448	HRS	4085.4		TSN 0				
WC#: 72.220	ENC	2610		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3073765-3	MOS/MSC	30-Nov-93	O/C					
SN:3-03405-3181	HRS	0		TSN 0				
WC#: 72.230	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3073765-3	MOS/MSC	29-Nov-93	O/C					
SN:3-03405-3162	HRS	0		TSN 0				
WC#: 72.230	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725190	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component ATA:72
PN:3073765-3	MOS/MSC	29-Nov-93	O/C					
SN:3-03405-3141	HRS	0		TSN 0				
WC#: 72.230	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3073764-3	MOS/MSC	30-Nov-93	O/C					
SN:3-06671-3071	HRS	0		TSN 0				
WC#: 72.240	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3073764-3	MOS/MSC	29-Nov-93	O/C					
SN:3-06671-3080	HRS	0		TSN 0				
WC#: 72.240	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725191	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component ATA:72
PN:3073764-3	MOS/MSC	29-Nov-93	O/C					
SN:3-06671-3072	HRS	0		TSN 0				
WC#: 72.240	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726110	NO. 1 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-11	MOS/MSC	30-Nov-93	O/C					
SN:P6521	HRS	0		TSN 0				
WC#: 72.250	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726110	NO. 2 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-11	MOS/MSC	29-Nov-93	O/C					
SN:P6520	HRS	0		TSN 0				
WC#: 72.250	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726110	NO. 3 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3070003-11	MOS/MSC	29-Nov-93	O/C					
SN:P6519	HRS	0		TSN 0				
WC#: 72.250	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-11	MOS	22-Oct-12						
SN:P6521	HRS	4126.4	4200 (+200)		(8326.4) 8519.7	8526.4	1727.4 (+200)	
WC#: 72.260	ENC	2630						
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-11	MOS	15-Oct-12						
SN:P6520	HRS	4124.2	4200 (+200)		(8324.2) 8520.1	8524.2	1727.8 (+200)	
WC#: 72.260	ENC	2626						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726120	NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX							Service ATA:72
PN:3070003-11	MOS	16-Oct-12						
SN:P6519	HRS	4085.4	4200 (+200)		(8285.4) 8519.7	8485.4	1727.4 (+200)	
WC#: 72.260	ENC	2610						
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
726130	NO. 1 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-12	MOS/MSC	16-Jul-99	O/C					
SN:P-7676	HRS	1093.9						
WC#: 72.270	ENC	689						
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726130	NO. 2 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-4	MOS/MSC	29-Nov-93	O/C					
SN:P7675	HRS	0		TSN 0				
WC#: 72.270	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726130	NO. 3 ENGINE - TRANSFER GEARBOX							Component ATA:72
PN:3070093-4	MOS/MSC	29-Nov-93	O/C					
SN:P7674	HRS	0		TSN 0				
WC#: 72.270	ENC	0		TSN 0				
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								
726310	NO. 1 ENGINE - ACCESSORY DRIVE SPLINES - CHECK STARTER/GENERATOR AND ALTERNATOR DRIVE SPLINES FOR WEAR							Service ATA:72
	MOS	17-Apr-19						PART OF MPI
	HRS	5597.2	1400 (+100)	Adj -70.8	(6926.4) 7119.7	7026.4	327.4 (+100)	
WC#: 72.280	ENC	3400						
PROC. REF: LMM 72-60-01PROC. REF: LMM 72-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726310	NO. 2 ENGINE - ACCESSORY DRIVE SPLINES - CHECK STARTER/GENERATOR AND ALTERNATOR DRIVE SPLINES FOR WEAR							Service ATA:72
	MOS	19-Apr-19						PART OF MPI
	HRS	5594.6	1400 (+100)	Adj -70.4	(6924.2) 7120.1	7024.2	327.8 (+100)	
WC#: 72.280	ENC	3396						
PROC. REF: LMM 72-60-01	PROC. REF: LMM 72-60-01							
726310	NO. 3 ENGINE - ACCESSORY DRIVE SPLINES - CHECK STARTER/GENERATOR AND ALTERNATOR DRIVE SPLINES FOR WEAR							Service ATA:72
	MOS	26-Apr-19						PART OF MPI
	HRS	5556.2	1400 (+100)	Adj -70.8	(6885.4) 7119.7	6985.4	327.4 (+100)	
WC#: 72.280	ENC	3380						
PROC. REF: LMM 72-60-01	PROC. REF: LMM 72-60-01							
727110	NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	22-Oct-12						
	HRS	4126.4	4200 (+200)		(8326.4) 8519.7	8526.4	1727.4 (+200)	
WC#: 72.300	ENC	2630						
PROC. REF: LMM 72-70-06	PROC. REF: LMM 72-70-06							
727110	NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	15-Oct-12						
	HRS	4124.2	4200 (+200)		(8324.2) 8520.1	8524.2	1727.8 (+200)	
WC#: 72.300	ENC	2626						
PROC. REF: LMM 72-70-06	PROC. REF: LMM 72-70-06							
727110	NO. 3 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY							Service ATA:72
	MOS	16-Oct-12						
	HRS	4085.4	4200 (+200)		(8285.4) 8519.7	8485.4	1727.4 (+200)	
WC#: 72.300	ENC	2610						
PROC. REF: LMM 72-70-06	PROC. REF: LMM 72-70-06							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-20-01-900-801-01	NO. 1 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 1) COMPUTER							Component ATA:73
PN:2119020-1	MOS/MSC	14-Jun-17	O/C	TSN 199				
SN:50-AK0250	HRS	5158.2		TSN 3830.2				
WC#: 73.070	AFL	3250		TSN 2351				
PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801								
73-20-01-900-801-02	NO. 2 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 2) COMPUTER							Component ATA:73
PN:2119020-1	MOS/MSC	14-Jun-17	O/C	TSN 199				
SN:50-AK0206	HRS	5158.2		TSN 3830.2				
WC#: 73.070	AFL	3250		TSN 2351				
PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801								
73-20-01-900-801-03	NO. 3 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 3) COMPUTER							Component ATA:73
PN:2119020-1	MOS/MSC	08-Nov-00	O/C	TSN 0				
SN:50-AK0201	HRS	1328		TSN 0				
WC#: 73.070	AFL	899		TSN 0				
PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801PROC. REF: AMM 73-20-01-900-801, AMM 73-20-01-900-801								
73-30-09-900-801-01	REMOVAL / INSTALLATION OF THE FUEL FLOWMETERS - ENGINE 1 FUEL FLOWMETER (L103E)							Component ATA:73
PN:9-127-27	MOS/MSC	11-Jul-95	O/C					
SN:6344	HRS	0		TSN 0				
WC#: 73.090	AFL	0						
PROC. REF: AMM 73-30-09-900-801PROC. REF: AMM 73-30-09-900-801								
73-30-09-900-801-02	REMOVAL / INSTALLATION OF THE FUEL FLOWMETERS - ENGINE 2 FUEL FLOWMETER (M103E)							Component ATA:73
PN:9-127-27	MOS/MSC	11-Jul-95	O/C					
SN:6570	HRS	0		TSN 0				
WC#: 73.090	AFL	0						
PROC. REF: AMM 73-30-09-900-801PROC. REF: AMM 73-30-09-900-801								
73-30-09-900-801-03	REMOVAL / INSTALLATION OF THE FUEL FLOWMETERS - ENGINE 3 FUEL FLOWMETER (R103E)							Component ATA:73
PN:9-127-27	MOS/MSC	11-Jul-95	O/C					
SN:6774	HRS	0		TSN 0				
WC#: 73.090	AFL	0						
PROC. REF: AMM 73-30-09-900-801PROC. REF: AMM 73-30-09-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-30-12-900-801-01	REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FUEL FLOW 1 INDICATOR METER (102E1)							Component ATA:73
PN:9-328-01	MOS/MSC	17-Nov-20	O/C					
SN:A3104	HRS	5998						
WC#: 73.080	AFL	3603						
PROC. REF: AMM 73-30-12-900-801	PROC. REF: AMM 73-30-12-900-801							
73-30-12-900-801-02	REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FUEL FLOW 2 INDICATOR METER (102E2)							Component ATA:73
PN:9-328-01	MOS/MSC	24-Jul-08	O/C	TSR 1				
SN:626	HRS	3036.1		TSR 0				
WC#: 73.080	AFL	2036		TSR 0				
PROC. REF: AMM 73-30-12-900-801	PROC. REF: AMM 73-30-12-900-801							
73-30-12-900-801-03	REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FUEL FLOW 3 INDICATOR METER (102E3)							Component ATA:73
PN:9-328-01	MOS/MSC	26-Mar-97	O/C					
SN:611	HRS	399		TSO 0				
WC#: 73.080	AFL	260		TSO 0				
PROC. REF: AMM 73-30-12-900-801	PROC. REF: AMM 73-30-12-900-801							
731110	NO. 1 ENGINE - ENGINE FUEL PUMP							Component ATA:73
PN:3070850-28	MOS/MSC	30-Nov-93	O/C					
SN:MX548439	HRS	0		TSN 0				
WC#: 73.010	ENC	0		TSN 0				
PROC. REF: LMM 73-21-02	PROC. REF: LMM 73-21-02							
731110	NO. 2 ENGINE - ENGINE FUEL PUMP							Component ATA:73
PN:3070850-28	MOS/MSC	03-Oct-05	O/C					
SN:MX347093	HRS	2350.5						
WC#: 73.010	ENC	1612						
PROC. REF: LMM 73-21-02	PROC. REF: LMM 73-21-02							
731110	NO. 3 ENGINE - ENGINE FUEL PUMP							Component ATA:73
PN:3070850-28	MOS/MSC	27-Feb-11	O/C	TSN 0				
SN:MX458859	HRS	3540.3		TSN 0				
WC#: 73.010	ENC	2326		TSN 0				
PROC. REF: LMM 73-21-02	PROC. REF: LMM 73-21-02							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731120	NO. 1 ENGINE - FUEL FILTER ELEMENT - REMOVE AND REPLACE							Service ATA:73
	MOS	18-Dec-25						
	HRS	6526	600 (+50)		(7126) 7319.3	7176	527 (+50)	
WC#: 73.020	ENC	3850						
PROC. REF: LMM 73-21-02	PROC. REF: LMM 73-21-02							
731120	NO. 2 ENGINE - FUEL FILTER ELEMENT - REMOVE AND REPLACE							Service ATA:73
	MOS	04-Jun-26						
	HRS	6560.4	600 (+50)		(7160.4) 7356.3	7210.4	564 (+50)	
WC#: 73.020	ENC	3877						
PROC. REF: LMM 73-21-02	PROC. REF: LMM 73-21-02							
731120	NO. 3 ENGINE - FUEL FILTER ELEMENT - REMOVE AND REPLACE							Service ATA:73
	MOS	03-Jan-25						
	HRS	6393.2	600 (+50)		(6993.2) 7227.5	7043.2	435.2 (+50)	
WC#: 73.020	ENC	3766						
PROC. REF: LMM 73-21-02	PROC. REF: LMM 73-21-02							
731130	NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:394396-2-1	MOS/MSC	30-Nov-93	O/C					
SN:8886	HRS	0		TSN 0				
WC#: 73.030	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							
731130	NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:394396-2-1	MOS/MSC	29-Nov-93	O/C					
SN:8868	HRS	0		TSN 0				
WC#: 73.030	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF	PROC. REF: GENERIC NO REF							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731130	NO. 3 ENGINE - FLOW DIVIDER/DRAIN VALVE							Component ATA:73
PN:394396-2-1	MOS/MSC	29-Nov-93	O/C					
SN:8878	HRS	0		TSN 0				
WC#: 73.030	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731140	NO. 1 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-5	MOS/MSC	30-Nov-93	O/C					
SN:73-6340	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
731140	NO. 2 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-5	MOS/MSC	29-Nov-93	O/C					
SN:73-6351	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
731140	NO. 3 ENGINE - FUEL HEATER							Component ATA:73
PN:158670-5	MOS/MSC	29-Nov-93	O/C					
SN:73-6332	HRS	0		TSN 0				
WC#: 73.040	ENC	0		TSN 0				
PROC. REF: LMM 73-10-04PROC. REF: LMM 73-10-04								
731150	NO. 1 ENGINE - FUEL/OIL COOLER							Component ATA:73
PN:158610-8	MOS/MSC	30-Nov-93	O/C					
SN:108-8671	HRS	0		TSN 0				
WC#: 73.050	ENC	0		TSN 0				
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07								
731150	NO. 2 ENGINE - FUEL/OIL COOLER							Component ATA:73
PN:158610-8	MOS/MSC	29-Nov-93	O/C					
SN:103-8672	HRS	0		TSN 0				
WC#: 73.050	ENC	0		TSN 0				
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07								

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731150	NO. 3 ENGINE - FUEL/OIL COOLER							Component ATA:73
PN:158610-8	MOS/MSC	29-Nov-93	O/C					
SN:103-8668	HRS	0		TSN 0				
WC#: 73.050	ENC	0		TSN 0				
PROC. REF: LMM 79-20-07PROC. REF: LMM 79-20-07								
732110	NO. 1 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-22	MOS/MSC	20-Dec-00	O/C	TSN 85				
SN:A8992C	HRS	1328		TSN 1328				
WC#: 73.060	ENC	822		TSN 822				
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
732110	NO. 2 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-22	MOS/MSC	08-Apr-04	O/C	TSR 0				
SN:A7385C	HRS			TSR 0				
WC#: 73.060	ENC			TSR 0				
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
732110	NO. 3 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-22	MOS/MSC	08-May-14	O/C					
SN:A8586C	HRS	4544.45						
WC#: 73.060	ENC	2860						
PROC. REF: LMM 73-20-01PROC. REF: LMM 73-20-01								
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:3070685-6	MOS/MSC	30-Nov-93	O/C					
SN:A10896	HRS	0		TSN 0				
WC#: 73.070	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:3070685-6	MOS/MSC	29-Nov-93	O/C					
SN:A10899	HRS	0		TSN 0				
WC#: 73.070	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732120	NO. 3 ENGINE - PRESSURE LIMITER VALVE							Component ATA:73
PN:3070685-6	MOS/MSC	29-Nov-93	O/C					
SN:A10897	HRS	0		TSN 0				
WC#: 73.070	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732130	NO. 1 ENGINE - SURGE BLEED VALVE							Component ATA:73
PN:978812-5-1	MOS/MSC	30-Nov-93	O/C					
SN:8220	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
732130	NO. 2 ENGINE - SURGE BLEED VALVE							Component ATA:73
PN:978812-5-1	MOS/MSC	29-Nov-93	O/C					
SN:8184	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
732130	NO. 3 ENGINE - SURGE BLEED VALVE							Component ATA:73
PN:978812-5-1	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 73.080	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
732140	NO. 1 ENGINE - SOLENOID CONTROL VALVE							Component ATA:73
PN:109696-4-1	MOS/MSC	30-Nov-93	O/C					
SN:7116	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								
732140	NO. 2 ENGINE - SOLENOID CONTROL VALVE							Component ATA:73
PN:109696-4-1	MOS/MSC	29-Nov-93	O/C					
SN:7724	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01PROC. REF: LMM 76-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732140	NO. 3 ENGINE - SOLENOID CONTROL VALVE							Component ATA:73
PN:109696-4-1	MOS/MSC	29-Nov-93	O/C					
SN:7723	HRS	0		TSN 0				
WC#: 73.090	ENC	0		TSN 0				
PROC. REF: LMM 76-10-01	PROC. REF: LMM 76-10-01							
ATA 74 - IGNITION								
741110	NO. 1 ENGINE - IGNITION UNIT							Component ATA:74
PN:3070378-1	MOS/MSC	30-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.010	ENC	0		TSN 0				
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							
741110	NO. 2 ENGINE - IGNITION UNIT							Component ATA:74
PN:3070378-1	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.010	ENC	0		TSN 0				
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							
741110	NO. 3 ENGINE - IGNITION UNIT							Component ATA:74
PN:3070378-1	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 74.010	ENC	0		TSN 0				
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							
741120 S	NO. 1 ENGINE - IGNITION SYSTEM - PERFORM IGNITION SYSTEM TEST							Service ATA:74
	MOS	17-Apr-19						
	HRS	5597.2	1200 (+300)					
WC#: 74.020	ENC	3400						PKG:1
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741120 S	NO. 2 ENGINE - IGNITION SYSTEM - PERFORM IGNITION SYSTEM TEST							Service ATA:74
	MOS	19-Apr-19						
	HRS	5594.6	1200 (+300)					
WC#: 74.020	ENC	3396						
								PKG:1
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							
741120 S	NO. 3 ENGINE - IGNITION SYSTEM - PERFORM IGNITION SYSTEM TEST							Service ATA:74
	MOS	26-Apr-19						
	HRS	5556.2	1200 (+300)					
WC#: 74.020	ENC	3380						
								PKG:1
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITER PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	17-Apr-19	O/C	TSN 0				
SN:NSN	HRS	5597.2		TSN 0				
WC#: 74.030	ENC	3400		TSN 0				
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITER PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	19-Apr-19	O/C	TSN 0				
SN:NSN	HRS	5594.6		TSN 0				
WC#: 74.030	ENC	3396		TSN 0				
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							
742110	NO. 3 ENGINE - 6 O'CLOCK IGNITER PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	23-Apr-19	O/C	TSN 0				
SN:NSN	HRS	5556.2		TSN 0				
WC#: 74.030	ENC	3380		TSN 0				
PROC. REF: LMM 74-00-01	PROC. REF: LMM 74-00-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742120 S	NO. 1 ENGINE - 6 O'CLOCK IGNITER PLUGS AND IGNITER LEAD TERMINALS - REMOVE IGNITER PLUGS AND VISUALLY INSPECT IGNITER PLUGS AND IGNITER LEAD TERMINALS							Service ATA:74
	MOS	17-Apr-19						
	HRS	5597.2	1200 (+300)					
WC#: 74.040	ENC	3400						
								PKG:1
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742120 S	NO. 2 ENGINE - 6 O'CLOCK IGNITER PLUGS AND IGNITER LEAD TERMINALS - REMOVE IGNITER PLUGS AND VISUALLY INSPECT IGNITER PLUGS AND IGNITER LEAD TERMINALS							Service ATA:74
	MOS	19-Apr-19						
	HRS	5594.6	1200 (+300)					
WC#: 74.040	ENC	3396						
								PKG:1
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742120 S	NO. 3 ENGINE - 6 O'CLOCK IGNITER PLUGS AND IGNITER LEAD TERMINALS - REMOVE IGNITER PLUGS AND VISUALLY INSPECT IGNITER PLUGS AND IGNITER LEAD TERMINALS							Service ATA:74
	MOS	26-Apr-19						
	HRS	5556.2	1200 (+300)					
WC#: 74.040	ENC	3380						
								PKG:1
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	17-Apr-19	O/C	TSN 0				
SN:NSN	HRS	5597.2		TSN 0				
WC#: 74.050	ENC	3400		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742130	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	19-Apr-19	O/C	TSN 0				
SN:NSN	HRS	5594.6		TSN 0				
WC#: 74.050	ENC	3396		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742130	NO. 3 ENGINE - 7 O'CLOCK IGNITER PLUG							Component ATA:74
PN:3074541-4	MOS/MSC	23-Apr-19	O/C	TSN 0				
SN:NSN	HRS	5556.2		TSN 0				
WC#: 74.050	ENC	3380		TSN 0				
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742140 S	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUGS AND IGNITER LEAD TERMINALS - REMOVE IGNITER PLUGS AND VISUALLY INSPECT IGNITER PLUGS AND IGNITER LEAD TERMINALS							Service ATA:74
	MOS	17-Apr-19						
	HRS	5597.2	1200 (+300)					
WC#: 74.060	ENC	3400						
								PKG:1
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742140 S	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUGS AND IGNITER LEAD TERMINALS - REMOVE IGNITER PLUGS AND VISUALLY INSPECT IGNITER PLUGS AND IGNITER LEAD TERMINALS							Service ATA:74
	MOS	19-Apr-19						
	HRS	5594.6	1200 (+300)					
WC#: 74.060	ENC	3396						
								PKG:1
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
742140 S	NO. 3 ENGINE - 7 O'CLOCK IGNITER PLUGS AND IGNITER LEAD TERMINALS - REMOVE IGNITER PLUGS AND VISUALLY INSPECT IGNITER PLUGS AND IGNITER LEAD TERMINALS							Service ATA:74
	MOS	26-Apr-19						
	HRS	5556.2	1200 (+300)					
WC#: 74.060	ENC	3380						
								PKG:1
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
ATA 76 - ENGINE CONTROLS								
76-10-00-220-801-01	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 1							Service ATA:76
PN:7-43497-1	MOS/MSC	18-Jun-19	O/C					
SN:299	HRS	5790.5						
WC#: 76.020	AFL	3507						
PROC. REF: AMM 76-10-00-220-801PROC. REF: AMM 76-10-00-220-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-10-00-220-801-02	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 2							Service ATA:76
PN:7-43497-2	MOS/MSC	18-Jun-19	O/C					
SN:282	HRS	5790.5						
WC#: 76.030	AFL	3507						
PROC. REF: AMM 76-10-00-220-801	PROC. REF: AMM 76-10-00-220-801							
76-10-00-220-801-03	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 3							Service ATA:76
PN:7-43497-3	MOS/MSC	18-Jun-19	O/C					
SN:273	HRS	5790.5						
WC#: 76.020	AFL	3507						
PROC. REF: AMM 76-10-00-220-801	PROC. REF: AMM 76-10-00-220-801							
76-10-00-220-802-01	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 1							Service ATA:76
PN:7-43497-1	MOS/MSC	18-Jun-19	O/C					
SN:299	HRS	5790.5						
WC#: 76.020	AFL	3507						
PROC. REF: AMM 76-10-00-220-802	PROC. REF: AMM 76-10-00-220-802							
76-10-00-220-802-02	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 2							Service ATA:76
PN:7-43497-2	MOS/MSC	18-Jun-19	O/C					
SN:282	HRS	5790.5						
WC#: 76.030	AFL	3507						
PROC. REF: AMM 76-10-00-220-802	PROC. REF: AMM 76-10-00-220-802							
76-10-00-220-802-03	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 3							Service ATA:76
PN:7-43497-3	MOS/MSC	18-Jun-19	O/C					
SN:273	HRS	5790.5						
WC#: 76.020	AFL	3507						
PROC. REF: AMM 76-10-00-220-802	PROC. REF: AMM 76-10-00-220-802							
76-10-21-640-801-01	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - LH ENGINE TELEFLEX CONTROL CABLE (L502EC)							Service ATA:76
PN:7-43497-1	MOS/MSC	11-Aug-20	74 / E/C		11-Oct-26		2 d	
SN:299	HRS	5942.6						
WC#: 76.020	AFL	3569						
PROC. REF: AMM 76-10-21-640-801	PROC. REF: AMM 76-10-21-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
76-10-21-640-801-02	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - CENTER ENGINE TELEFLEX CONTROL CABLE (M502EC)							Service ATA:76
PN:7-43497-2	MOS/MSC	11-Aug-20	74 / E/C		11-Oct-26		2 d	
SN:282	HRS	5942.6						
WC#: 76.030	AFL	3569						
PROC. REF: AMM 76-10-21-640-801	PROC. REF: AMM 76-10-21-640-801							
76-10-21-640-801-03	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - RH ENGINE TELEFLEX CONTROL CABLE (R502EC)							Service ATA:76
PN:7-43497-3	MOS/MSC	11-Aug-20	74 / E/C		11-Oct-26		2 d	
SN:273	HRS	5942.6						
WC#: 76.020	AFL	3569						
PROC. REF: AMM 76-10-21-640-801	PROC. REF: AMM 76-10-21-640-801							
76-10-21-640-801-04	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - ENGINE 1 CONTROL UNIT							Service ATA:76
PN:7-43497-1	MOS/MSC	11-Aug-20	74 / E/C		11-Oct-26		2 d	
SN:299	HRS	5942.6						
WC#: 76.020	AFL	3569						
PROC. REF: AMM 76-10-21-640-801	PROC. REF: AMM 76-10-21-640-801							
76-10-21-640-801-05	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - ENGINE 2 CONTROL UNIT							Service ATA:76
PN:7-43497-2	MOS/MSC	11-Aug-20	74 / E/C		11-Oct-26		2 d	
SN:282	HRS	5942.6						
WC#: 76.030	AFL	3569						
PROC. REF: AMM 76-10-21-640-801	PROC. REF: AMM 76-10-21-640-801							
76-10-21-640-801-06	LUBRICATION OF THE TELEFLEX CONTROL CABLE AND TELEFLEX CONTROL UNIT - ENGINE 3 CONTROL UNIT							Service ATA:76
PN:7-43497-3	MOS/MSC	11-Aug-20	74 / E/C		11-Oct-26		2 d	
SN:273	HRS	5942.6						
WC#: 76.020	AFL	3569						
PROC. REF: AMM 76-10-21-640-801	PROC. REF: AMM 76-10-21-640-801							
76-10-21-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - LH ENGINE TELEFLEX CONTROL CABLE (L502EC)							Component ATA:76
PN:7-43497-1	MOS/MSC	11-Jul-95	O/C					
SN:299	HRS	0		TSN 0				
WC#: 76.020	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
PROC. REF: AMM 76-10-21-900-801 PROC. REF: AMM 76-10-21-900-801								
76-10-21-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - RH ENGINE TELEFLEX CONTROL CABLE (R502EC)							Component ATA:76
PN:7-43497-3	MOS/MSC	11-Jul-95	O/C					
SN:273	HRS	0		TSN 0				
WC#: 76.020	AFL	0						
PROC. REF: AMM 76-10-21-900-801 PROC. REF: AMM 76-10-21-900-801								
76-10-21-900-802-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 2 TELEFLEX CONTROL CABLE - CENTER ENGINE TELEFLEX CONTROL CABLE (M502EC)							Component ATA:76
PN:7-43497-2	MOS/MSC	11-Jul-95	O/C					
SN:282	HRS	0		TSN 0				
WC#: 76.030	AFL	0						
PROC. REF: AMM 76-10-21-900-802 PROC. REF: AMM 76-10-21-900-802								
76-10-33-820-801-01 S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 1 CONTROL CABLE (L501EC)							Service ATA:76
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 76.020	AFL	3569						
								PKG:31
PROC. REF: AMM 76-10-33-820-801 PROC. REF: AMM 76-10-33-820-801								
76-10-33-820-801-02 S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 2 CONTROL CABLE (M501EC)							Service ATA:76
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 76.030	AFL	3569						
								PKG:31
PROC. REF: AMM 76-10-33-820-801 PROC. REF: AMM 76-10-33-820-801								
76-10-33-820-801-03 S	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 3 CONTROL CABLE (R501EC)							Service ATA:76
	MOS	11-Aug-20	72 (+2m)					
	HRS	5942.6						
WC#: 76.020	AFL	3569						
								PKG:31
PROC. REF: AMM 76-10-33-820-801 PROC. REF: AMM 76-10-33-820-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
760130	NO. 1 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS	13-Aug-26						
	HRS	6576.7						
WC#: 76.010	ENC	3893	40 (+10)	Adj -3	(3930) 4037	3940	27 (+10)	
PROC. REF: LMM 72-00-00, MSC CAMP EHM ADENDUMPROC. REF: LMM 72-00-00, MSC CAMP EHM ADENDUM								
760130	NO. 2 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS	13-Aug-26						
	HRS	6574.1						
WC#: 76.010	ENC	3889	40 (+10)	Adj -3	(3926) 4037	3936	27 (+10)	
PROC. REF: LMM 72-00-00, MSC CAMP EHM ADENDUMPROC. REF: LMM 72-00-00, MSC CAMP EHM ADENDUM								
760130	NO. 3 ENGINE - DOWNLOAD ECTM							Service ATA:76
	MOS	13-Aug-26						
	HRS	6535.7						
WC#: 76.010	ENC	3873	40 (+10)	Adj -3	(3910) 4037	3920	27 (+10)	
PROC. REF: LMM 72-00-00, MSC CAMP EHM ADENDUMPROC. REF: LMM 72-00-00, MSC CAMP EHM ADENDUM								
761101	THROTTLE CONTROL UNIT							Component ATA:76
PN:F50B771100A-3	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 76.010	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 77 - ENGINE INDICATING								
77-10-05-900-801-01	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 N1 INDICATOR (12E1)							Component ATA:77
PN:224-902-002	MOS/MSC	09-Apr-04	O/C	TSR 0				
SN:1264A	HRS	2009.8		TSR 0				
WC#: 77.020	AFL	1422		TSR 0				
PROC. REF: AMM 77-10-05-900-801PROC. REF: AMM 77-10-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-10-05-900-801-02	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 N1 INDICATOR (12E2)							Component ATA:77
PN:224-902-002	MOS/MSC	17-Aug-06	O/C	TSR 0				
SN:1103A	HRS	2515.8		TSR 0				
WC#: 77.020	AFL	1741		TSR 0				
PROC. REF: AMM 77-10-05-900-801	PROC. REF: AMM 77-10-05-900-801							
77-10-05-900-801-03	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 N1 INDICATOR (12E3)							Component ATA:77
PN:224-902-002	MOS/MSC	09-Apr-04	O/C	TSR 0				
SN:1072A	HRS	2009.8		TSR 0				
WC#: 77.020	AFL	1422		TSR 0				
PROC. REF: AMM 77-10-05-900-801	PROC. REF: AMM 77-10-05-900-801							
77-10-05-900-801-04	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 N2 INDICATOR (22E1)							Component ATA:77
PN:218-901-002	MOS/MSC	20-Dec-06	O/C	TSR 0				
SN:143	HRS	2522.08		TSR 0				
WC#: 77.040	AFL	1744		TSR 0				
PROC. REF: AMM 77-10-05-900-801	PROC. REF: AMM 77-10-05-900-801							
77-10-05-900-801-05	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 N2 INDICATOR (22E2)							Component ATA:77
PN:218-901-002	MOS/MSC	22-Jun-18	O/C	TSO 22				
SN:1279	HRS	5357.3		TSO 0				
WC#: 77.040	AFL	3346		TSO 0				
PROC. REF: AMM 77-10-05-900-801	PROC. REF: AMM 77-10-05-900-801							
77-10-05-900-801-06	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 N2 INDICATOR (22E3)							Component ATA:77
PN:218-901-002	MOS/MSC	16-Dec-04	O/C					
SN:1507	HRS	2194.9						
WC#: 77.040	AFL	1522						
PROC. REF: AMM 77-10-05-900-801	PROC. REF: AMM 77-10-05-900-801							
77-20-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE PT2 - TT2 SENSOR - ENGINE 1 PT2-TT2 SENSOR (L77E)							Component ATA:77
PN:3070816-4	MOS/MSC	07-Sep-18	O/C					
SN:1616901766021	HRS	5460.8						
WC#: 75.010	AFL							
PROC. REF: AMM 77-20-09-900-801	PROC. REF: AMM 77-20-09-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE PT2 - TT2 SENSOR - ENGINE 2 PT2-TT2 SENSOR (M77E)							Component ATA:77
PN:3070816-4	MOS/MSC	13-Aug-07	O/C					
SN:071789318713	HRS	2740.4		TSN 0				
WC#: 75.010	AFL	1868		TSN 0				
PROC. REF: AMM 77-20-09-900-801	PROC. REF: AMM 77-20-09-900-801							
77-20-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE PT2 - TT2 SENSOR - ENGINE 3 PT2-TT2 SENSOR (R77E)							Component ATA:77
PN:PN	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 75.010	AFL	0						
PROC. REF: AMM 77-20-09-900-801	PROC. REF: AMM 77-20-09-900-801							
77-20-17-900-801-01	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 1 ITT INDICATOR (32E1)							Component ATA:77
PN:224-901-002	MOS/MSC	24-Jul-08	O/C	TSR 0				
SN:1403	HRS	3036.1		TSR 0				
WC#: 77.050	AFL	2036		TSR 0				
PROC. REF: AMM 77-20-17-900-801	PROC. REF: AMM 77-20-17-900-801							
77-20-17-900-801-02	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 2 ITT INDICATOR (32E2)							Component ATA:77
PN:224-901-002	MOS/MSC	14-Apr-22	O/C	TSO 17				
SN:1292	HRS	6152.5		TSO 0				
WC#: 77.050	AFL	3694		TSO 0				
PROC. REF: AMM 77-20-17-900-801	PROC. REF: AMM 77-20-17-900-801							
77-20-17-900-801-03	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 3 ITT INDICATOR (32E3)							Component ATA:77
PN:224-901-002	MOS/MSC	22-Jun-18	O/C					
SN:175	HRS	5357.3						
WC#: 77.050	AFL	3346						
PROC. REF: AMM 77-20-17-900-801	PROC. REF: AMM 77-20-17-900-801							
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component ATA:77
PN:3073827-1	MOS/MSC	30-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.010	ENC	0		TSN 0				
PROC. REF: LMM 77-10-03	PROC. REF: LMM 77-10-03							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771110	NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component ATA:77
PN:3071928-4	MOS/MSC	22-Sep-11	O/C	TSN 0				
SN:NSN	HRS	3770.4		TSN 0				
WC#: 77.010	ENC	2437		TSN 0				
PROC. REF: LMM 77-10-03	PROC. REF: LMM 77-10-03							
771110	NO. 3 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component ATA:77
PN:3073827-4	MOS/MSC	26-Jan-04	O/C	TSN 0				
SN:34507	HRS	1927.8		TSN 0				
WC#: 77.010	ENC	1346		TSN 0				
PROC. REF: LMM 77-10-03	PROC. REF: LMM 77-10-03							
771120	NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component ATA:77
PN:3070722-3	MOS/MSC	30-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
PROC. REF: LMM 77-10-05	PROC. REF: LMM 77-10-05							
771120	NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component ATA:77
PN:3070722-3	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
PROC. REF: LMM 77-10-05	PROC. REF: LMM 77-10-05							
771120	NO. 3 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							Component ATA:77
PN:3070722-3	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
PROC. REF: LMM 77-10-05	PROC. REF: LMM 77-10-05							
772110	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:3071849-3	MOS/MSC	30-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.030	ENC	0		TSN 0				
PROC. REF: LMM 77-20-01	PROC. REF: LMM 77-20-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772110	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:3073595-1	MOS/MSC	19-Apr-19	O/C					
SN:6-20219-252	HRS	5594.6						
WC#: 77.030	ENC	3396						
PROC. REF: LMM 77-20-01	PROC. REF: LMM 77-20-01							
772110	NO. 3 ENGINE - ITT THERMOCOUPLE HARNESS							Component ATA:77
PN:3071849-3	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.030	ENC	0		TSN 0				
PROC. REF: LMM 77-20-01	PROC. REF: LMM 77-20-01							
ATA 78 - EXHAUST								
78-30-00-910-809-01	INHIBITION / ACTIVATION OF THE THRUST REVERSER FOR FLIGHT							Service ATA:78
	MOS/MSC	11-Jul-95	O/C					
	HRS	0						
WC#: 78.120	AFL	0						
PROC. REF: AMM 78-30-00-910-809	PROC. REF: AMM 78-30-00-910-809							
78-31-00-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THRUST REVERSER DOOR HINGE FITTINGS - LH THRUST-REVERSER DOOR (456DL)							Service ATA:78
	MOS/MSC	08-May-14	O/C					
	HRS	4694.5						
WC#: 78.100	AFL	2957						
PROC. REF: AMM 78-31-00-250-801	PROC. REF: AMM 78-31-00-250-801							
78-31-00-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THRUST REVERSER DOOR HINGE FITTINGS - RH THRUST-REVERSER DOOR (456DR)							Service ATA:78
	MOS/MSC	15-Jul-96	O/C					
	HRS	0						
WC#: 78.100	AFL	0						
PROC. REF: AMM 78-31-00-250-801	PROC. REF: AMM 78-31-00-250-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-31-00-250-802-01 S	SPECIAL DETAILED INSPECTION (FLUORESCENT PENETRANT) OF THE THRUST REVERSER DOOR HINGE FITTINGS - LH THRUST-REVERSER DOOR (456DL)							Service ATA:78
	MOS	02-Oct-24	24					
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 78-31-00-250-802	PROC. REF: AMM 78-31-00-250-802							
78-31-00-250-802-01A	SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE LH THRUST REVERSER DOOR HINGE FITTINGS (MANDATORY 5-40)							Service ATA:78
	MOS	02-Oct-24						MANDATORY 5-40
	HRS	6601.6						
	AFL	3875	1155		5030		1020	
PROC. REF: AMM 78-31-00-250-802	PROC. REF: AMM 78-31-00-250-802							
78-31-00-250-802-02 S	SPECIAL DETAILED INSPECTION (FLUORESCENT PENETRANT) OF THE THRUST REVERSER DOOR HINGE FITTINGS - RH THRUST-REVERSER DOOR (456DR)							Service ATA:78
	MOS	02-Oct-24	24					
	HRS	6601.6						
	AFL	3875						
								PKG:16
PROC. REF: AMM 78-31-00-250-802	PROC. REF: AMM 78-31-00-250-802							
78-31-00-250-802-02A	SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE RH THRUST REVERSER DOOR HINGE FITTINGS (MANDATORY 5-40)							Service ATA:78
	MOS	02-Oct-24						MANDATORY 5-40
	HRS	6601.6						
	AFL	3875	1155		5030		1020	
PROC. REF: AMM 78-31-00-250-802	PROC. REF: AMM 78-31-00-250-802							
78-31-00-640-801-01 S	GREASING OF THE THRUST REVERSER ASSEMBLY							Service ATA:78
	MOS	24-Oct-25	12 (+1m)					
	HRS	6700.5						
WC#: 78.020	AFL	3940						
								PKG:207
PROC. REF: AMM 78-31-00-640-801	PROC. REF: AMM 78-31-00-640-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-31-01-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THRUST REVERSER DOORS - LH THRUST-REVERSER DOOR (456DL)							Component ATA:78
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-01-900-801, AMM 78-31-01-900-801PROC. REF: AMM 78-31-01-900-801, AMM 78-31-01-900-801								
78-31-01-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THRUST REVERSER DOORS - RH THRUST-REVERSER DOOR (456DR)							Component ATA:78
PN:PN	MOS/MSC	11-Jul-95	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-01-900-801, AMM 78-31-01-900-801PROC. REF: AMM 78-31-01-900-801, AMM 78-31-01-900-801								
78-31-13-900-801-01	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR ACTUATORS - TR ACTUATOR (202KR)							Component ATA:78
PN:F10A5SCH203-4	MOS/MSC	11-Jul-95	O/C					
SN:2341	HRS	0		TSN 0				
WC#: 78.080	AFL	0						
PROC. REF: AMM 78-31-13-900-801PROC. REF: AMM 78-31-13-900-801								
783101	THRUST REVERSER SOLENOID VALVE							Component ATA:78
PN:A24521-102	MOS/MSC	11-Jul-95	O/C					
SN:FM1046	HRS	0		TSN 0				
WC#: 78.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783106	THRUST REVERSER ACCUMULATOR							Component ATA:78
PN:60909-1	MOS/MSC	03-Jun-02	O/C	TSR 6				
SN:3026C	HRS	1607		TSR 1.3				
WC#: 78.010	AFL	1116		TSR 2				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783121	THRUST REVERSER PRESSURE INDICATOR							Component ATA:78
PN:18040100	MOS/MSC	11-Jul-95	O/C					
SN:32748C	HRS	0		TSN 0				
WC#: 78.040	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783126	THRUST REVERSER FILLER VALVE							Component ATA:78
PN:MS28889-2	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.050	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783131	LH THRUST REVERSER DISCHARGE VALVE							Component ATA:78
PN:3300-4	MOS/MSC	11-Jul-95	O/C					
SN:NONE	HRS	0		TSN 0				
WC#: 78.060	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783136	RH THRUST REVERSER DISCHARGE VALVE							Component ATA:78
PN:AE99113G	MOS/MSC	14-Feb-11	O/C	TSN 0				
SN:UNKNOWN	HRS	3653.6		TSN 0				
WC#: 78.060	AFL	2403		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783141	LH THRUST REVERSER CHECK VALVE							Component ATA:78
PN:A24515	MOS/MSC	11-Jul-95	O/C					
SN:FM2156	HRS	0		TSN 0				
WC#: 78.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783146	RH THRUST REVERSER CHECK VALVE							Component ATA:78
PN:A24515	MOS/MSC	11-Jul-95	O/C					
SN:FM2161	HRS	0		TSN 0				
WC#: 78.070	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783151	THRUST REVERSER LATCHING SOLENOID							Component ATA:78
PN:A861TS4RF50	MOS/MSC	11-Jul-95	O/C					
SN:932	HRS	0		TSN 0				
WC#: 78.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783156	THRUST REVERSER LOCKING SOLENOID							Component ATA:78
PN:A861TS4RF50	MOS/MSC	11-Jul-95	O/C					
SN:964	HRS	0		TSN 0				
WC#: 78.030	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783166	THRUST REVERSER JUNCTION ACTUATOR							Component ATA:78
PN:JEFX0500250AA	MOS/MSC	11-Jul-95	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.080	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783201	THRUST REVERSER LOCKING SOLENOID							Component ATA:78
PN:F10A-5-SCAV200-1	MOS/MSC	02-Aug-96	O/C					
SN:1479	HRS	185		TSO 0				
WC#: 78.030	AFL	77		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 79 - OIL								
79-30-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE TRANSDUCER - ENGINE 1 OIL PRESSURE TRANSMITTER (L4E)							Component ATA:79
PN:418-28044	MOS/MSC	11-Jul-95	O/C					
SN:9343164	HRS	0		TSN 0				
WC#: 79.090	AFL	0						
PROC. REF: AMM 79-30-05-900-801PROC. REF: AMM 79-30-05-900-801								
79-30-05-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE TRANSDUCER - ENGINE 2 OIL PRESSURE TRANSMITTER (M4E)							Component ATA:79
PN:418-28044	MOS/MSC	06-Aug-02	O/C	TSN 0				
SN:9901-0050	HRS	1638		TSN 0				
WC#: 79.090	AFL	1142		TSN 0				
PROC. REF: AMM 79-30-05-900-801PROC. REF: AMM 79-30-05-900-801								
79-30-05-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE TRANSDUCER - ENGINE 3 OIL PRESSURE TRANSMITTER (R4E)							Component ATA:79
PN:418-28044	MOS/MSC	11-Jul-95	O/C					
SN:9019089	HRS	0		TSN 0				
WC#: 79.090	AFL	0						
PROC. REF: AMM 79-30-05-900-801PROC. REF: AMM 79-30-05-900-801								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE SWITCH - ENGINE 1 OIL PRESSURE SWITCH (L6E)							Component ATA:79
PN:8G1126-2	MOS/MSC	11-Jul-95	O/C					
SN:1173	HRS	0		TSN 0				
WC#: 79.040	AFL	0						
PROC. REF: AMM 79-30-09-900-801	PROC. REF: AMM 79-30-09-900-801							
79-30-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE SWITCH - ENGINE 2 OIL PRESSURE SWITCH (M6E)							Component ATA:79
PN:8G1126-2	MOS/MSC	11-Jul-95	O/C					
SN:1483	HRS	0		TSN 0				
WC#: 79.040	AFL	0						
PROC. REF: AMM 79-30-09-900-801	PROC. REF: AMM 79-30-09-900-801							
79-30-09-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE OIL PRESSURE SWITCH - ENGINE 3 OIL PRESSURE SWITCH (R6E)							Component ATA:79
PN:8G1126-2	MOS/MSC	11-Jul-95	O/C					
SN:1489	HRS	0		TSN 0				
WC#: 79.040	AFL	0						
PROC. REF: AMM 79-30-09-900-801	PROC. REF: AMM 79-30-09-900-801							
79-30-13-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE OIL TEMPERATURE SENSOR - ENGINE 1 TEMPERATURE SENSOR (L3E)							Component ATA:79
PN:56B17	MOS/MSC	11-Jul-95	O/C					
SN:G62796	HRS	0		TSN 0				
WC#: 79.120	AFL	0						
PROC. REF: AMM 79-30-13-900-801	PROC. REF: AMM 79-30-13-900-801							
79-30-13-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE OIL TEMPERATURE SENSOR - ENGINE 2 TEMPERATURE SENSOR (M3E)							Component ATA:79
PN:56B17	MOS/MSC	11-Jul-95	O/C					
SN:50007	HRS	0		TSN 0				
WC#: 79.120	AFL	0						
PROC. REF: AMM 79-30-13-900-801	PROC. REF: AMM 79-30-13-900-801							
79-30-13-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE OIL TEMPERATURE SENSOR - ENGINE 3 TEMPERATURE SENSOR (R3E)							Component ATA:79
PN:56B17	MOS/MSC	11-Jul-95	O/C					
SN:46666	HRS	0		TSN 0				
WC#: 79.120	AFL	0						
PROC. REF: AMM 79-30-13-900-801	PROC. REF: AMM 79-30-13-900-801							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-17-900-801-01	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 1 OIL PRESSURE/TEMPERATURE INDICATOR (2E1)							Component ATA:79
PN:5427-395-8	MOS/MSC	02-Feb-00	O/C	TSR 0				
SN:353	HRS	1171.8		TSR 0				
WC#: 79.130	AFL	790		TSR 0				
PROC. REF: AMM 79-30-17-900-801	PROC. REF: AMM 79-30-17-900-801							
79-30-17-900-801-02	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 2 OIL PRESSURE/TEMPERATURE INDICATOR (2E2)							Component ATA:79
PN:5427-395-8	MOS/MSC	24-Sep-96	O/C					
SN:UNKNOWN	HRS	279						
WC#: 79.130	AFL	153						
PROC. REF: AMM 79-30-17-900-801	PROC. REF: AMM 79-30-17-900-801							
79-30-17-900-801-03	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 3 OIL PRESSURE/TEMPERATURE INDICATOR (2E3)							Component ATA:79
PN:5427-395-8	MOS/MSC	27-Aug-98	O/C	TSR 0				
SN:283	HRS	801.7		TSR 0				
WC#: 79.130	AFL	528		TSR 0				
PROC. REF: AMM 79-30-17-900-801	PROC. REF: AMM 79-30-17-900-801							
790110 S	NO. 1 ENGINE - OIL AND FILTER ANALYSIS							Service ATA:79
	MOS	24-Feb-26						
	HRS	6543.8	150 (+100)					
WC#: 79.010	ENC	3864						
								PKG:0
PROC. REF: LMM 72-00-00	PROC. REF: LMM 72-00-00							
790110 S	NO. 2 ENGINE - OIL AND FILTER ANALYSIS							Service ATA:79
	MOS	24-Feb-26						
	HRS	6541.2	150 (+100)					
WC#: 79.010	ENC	3860						
								PKG:0
PROC. REF: LMM 72-00-00	PROC. REF: LMM 72-00-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790110 S	NO. 3 ENGINE - OIL AND FILTER ANALYSIS							Service ATA:79
	MOS	24-Feb-26						
	HRS	6502.8	150 (+100)					
WC#: 79.010	ENC	3844						
								PKG:0
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
790120 S	NO. 1 ENGINE - CHANGE OIL							Service ATA:79
	MOS	17-Apr-19						
	HRS	5597.2	1200 (+100)					
WC#: 79.020	ENC	3400						
								PKG:1
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
790120 S	NO. 2 ENGINE - CHANGE OIL							Service ATA:79
	MOS	19-Apr-19						
	HRS	5594.6	1200 (+100)					
WC#: 79.020	ENC	3396						
								PKG:1
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
790120 S	NO. 3 ENGINE - CHANGE OIL							Service ATA:79
	MOS	26-Apr-19						
	HRS	5556.2	1200 (+100)		(6756.2) 6990.5 (M)	6856.2	198.2 (+100)	
WC#: 79.020	ENC	3380						
								PKG:1
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
790130 S	NO. 1 ENGINE - CHIP DETECTOR - INSPECT FOR CONTAMINATION							Service ATA:79
	MOS	24-Feb-26						
	HRS	6543.8	150 (+100)					
WC#: 79.030	ENC	3864						
								PKG:0
PROC. REF: LMM 79-20-03PROC. REF: LMM 79-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790130 S	NO. 2 ENGINE - CHIP DETECTOR - INSPECT FOR CONTAMINATION							Service ATA:79
	MOS	24-Feb-26						
	HRS	6541.2	150 (+100)					
WC#: 79.030	ENC	3860						
								PKG:0
PROC. REF: LMM 79-20-03	PROC. REF: LMM 79-20-03							
790130 S	NO. 3 ENGINE - CHIP DETECTOR - INSPECT FOR CONTAMINATION							Service ATA:79
	MOS	24-Feb-26						
	HRS	6502.8	150 (+100)					
WC#: 79.030	ENC	3844						
								PKG:0
PROC. REF: LMM 79-20-03	PROC. REF: LMM 79-20-03							
792110	NO. 1 ENGINE - OIL PUMP							Component ATA:79
PN:3071949-11	MOS/MSC	08-May-14	O/C					
SN:98-14057-0153	HRS	4585.8						
WC#: 79.040	ENC	2880						
PROC. REF: LMM 79-20-03	PROC. REF: LMM 79-20-03							
792110	NO. 2 ENGINE - OIL PUMP							Component ATA:79
PN:3071949-12	MOS/MSC	22-May-10	O/C	TSR 0				
SN:98-14057-0159	HRS	3485.92		TSR 0				
WC#: 79.040	ENC	2279		TSR 0				
PROC. REF: LMM 79-20-03	PROC. REF: LMM 79-20-03							
792110	NO. 3 ENGINE - OIL PUMP							Component ATA:79
PN:3071949-12	MOS/MSC	16-Oct-12	O/C	TSR 0				
SN:95-14057-3100	HRS	4085.4		TSR 0				
WC#: 79.040	ENC	2610		TSR 0				
PROC. REF: LMM 79-20-03	PROC. REF: LMM 79-20-03							
792120	NO. 1 ENGINE - OIL FILTER BY-PASS INDICATOR							Component ATA:79
PN:3070246-4	MOS/MSC	30-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.050	ENC	0		TSN 0				
PROC. REF: LMM 79-30-01	PROC. REF: LMM 79-30-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792120	NO. 2 ENGINE - OIL FILTER BY-PASS INDICATOR							Component ATA:79
PN:3070246-4	MOS/MSC	22-Aug-19	O/C					
SN:UNKNOWN	HRS	5643.6		TSN 5643.6				
WC#: 79.050	ENC	3417		TSN 3417				
PROC. REF: LMM 79-30-01	PROC. REF: LMM 79-30-01							
792120	NO. 3 ENGINE - OIL FILTER BY-PASS INDICATOR							Component ATA:79
PN:3070246-4	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.050	ENC	0		TSN 0				
PROC. REF: LMM 79-30-01	PROC. REF: LMM 79-30-01							
792130	NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:3075323-3	MOS/MSC	15-Aug-23	O/C	TSN 0				
SN:41568	HRS	6328.9		TSN 0				
WC#: 79.060	ENC	3723		TSN 0				
PROC. REF: LMM 79-20-02	PROC. REF: LMM 79-20-02							
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:3071564-9	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.060	ENC	0		TSN 0				
PROC. REF: LMM 79-20-02	PROC. REF: LMM 79-20-02							
792130	NO. 3 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component ATA:79
PN:3071564-5	MOS/MSC	29-Nov-93	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 79.060	ENC	0		TSN 0				
PROC. REF: LMM 79-20-02	PROC. REF: LMM 79-20-02							
792140	NO. 1 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:158600-7	MOS/MSC	30-Nov-93	O/C					
SN:73-10854	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09	PROC. REF: LMM 79-20-09							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792140	NO. 2 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:158600-7	MOS/MSC	29-Nov-93	O/C					
SN:103-10870	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792140	NO. 3 ENGINE - UPPER OIL COOLER							Component ATA:79
PN:158600-7	MOS/MSC	29-Nov-93	O/C					
SN:73-10850	HRS	0		TSN 0				
WC#: 79.070	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:159900-3	MOS/MSC	30-Nov-93	O/C					
SN:13-8316	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	29-Nov-93	O/C					
SN:53-8345	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792150	NO. 3 ENGINE - LOWER LEFT OIL COOLER							Component ATA:79
PN:159900-3	MOS/MSC	29-Nov-93	O/C					
SN:53-8352	HRS	0		TSN 0				
WC#: 79.080	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	30-Nov-93	O/C					
SN:73-8196	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	29-Nov-93	O/C					
SN:73-8215	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792160	NO. 3 ENGINE - LOWER RIGHT OIL COOLER							Component ATA:79
PN:159910-3	MOS/MSC	29-Nov-93	O/C					
SN:73-8208	HRS	0		TSN 0				
WC#: 79.090	ENC	0		TSN 0				
PROC. REF: LMM 79-20-09PROC. REF: LMM 79-20-09								
792170	NO. 1 ENGINE - OIL TEMPERATURE VALVE							Component ATA:79
PN:158465-3	MOS/MSC	30-Nov-93	O/C					
SN:103-7308	HRS	0		TSN 0				
WC#: 79.100	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792170	NO. 2 ENGINE - OIL TEMPERATURE VALVE							Component ATA:79
PN:158465-3	MOS/MSC	29-Nov-93	O/C					
SN:103-7309	HRS	0		TSN 0				
WC#: 79.100	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792170	NO. 3 ENGINE - OIL TEMPERATURE VALVE							Component ATA:79
PN:158465-3	MOS/MSC	29-Nov-93	O/C					
SN:103-7311	HRS	0		TSN 0				
WC#: 79.100	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

© CAMP SYSTEMS