

<b>OWNER:</b> BENTLEY DOWNERS GROVE LUXURY MOTORS	<b>OPERATOR:</b> BENTLEY DOWNERS GROVE LUXURY MOTORS	<b>OPERATOR:</b> MIDAMERICA JET WORKS, LLC
<b>ADDRESS:</b> C/O MIDAMERICA JET WORKS LLC SUGAR GROVE IL 60554	<b>ADDRESS:</b> C/O MIDAMERICA JET WORKS LLC SUGAR GROVE IL 60554	<b>ADDRESS:</b> 43W 450 U.S. ROUTE 30 SUGAR GROVE IL 60554
<b>PHONE:</b> 630.466.9297	<b>PHONE:</b> 630.466.9297	<b>PHONE:</b> 630-466-9297
<b>FAX:</b> 630.466.9546	<b>FAX:</b> 630.466.9546	<b>FAX:</b> 630-466-9546
<b>ANALYST:</b> SAMPSON OKAINE	877-411-CAMP (2267) (OFFICE)	800-787-9749 (EFAX-CARDS)
<b>EMAIL:</b> SOKAINE@CAMPSYSTEMS.COM	631-588-3200 (OFFICE)	631-980-4222 (FAX)
	WWW.CAMPSYSTEMS.COM	

<b>AIRCRAFT</b>	PROJECTED : 3 MOS. to 23-OCT-2007 <b>SERIAL/REGNO:</b> 082/N582EJ	<b>MODEL:</b> FALCON 50	<b>MANUFACTURER:</b> DASSAULT AVIATION
-----------------	--	-------------------------	--

DATES	LAST ACTUALS		PROJECTED
CERTIFICATION DATE: 14-DEC-1981	5739.2 A/C HRS	as of 23-JUL-2007	5939
	3805 AFL	as of 23-JUL-2007	4005
	4240 APH	as of 11-JUN-2007	4330

<b>APU</b>	<b>SERIAL/PART:</b> 861812/160981-200	<b>MODEL:</b> T-62T-40C3A/3A1	<b>MANUFACTURER:</b> HAMILTON SUNDSTRAND
------------	---------------------------------------	-------------------------------	--

INSTALLED ON 03-JUN-2001	LAST ACTUALS		PROJECTED
2670 APU HRS	4240 APU HRS	as of 11-JUN-2007	4330
5111 APUS	7255 APUS	as of 10-APR-2007	7375

<b>ENGINE NO. 1</b>	<b>SERIAL/PART:</b> P76385/TFE731-3-1C	<b>MODEL:</b> TFE731-3	<b>MANUFACTURER:</b> HONEYWELL
---------------------	--	------------------------	--------------------------------

INSTALLED ON 16-JAN-2004	LAST ACTUALS		PROJECTED	
4624.4 ENG. HRS	4727.7 A/C HRS	5634.7 ENG. HRS	as of 23-JUL-2007	5835
3218 ENC		3733 ENC	as of 10-APR-2007	3933

<b>ENGINE NO. 2</b>	<b>SERIAL/PART:</b> P76254/TFE731-3-1C	<b>MODEL:</b> TFE731-3	<b>MANUFACTURER:</b> HONEYWELL
---------------------	--	------------------------	--------------------------------

INSTALLED ON 16-JAN-2004	LAST ACTUALS		PROJECTED	
4506.7 ENG. HRS	4727.7 A/C HRS	5518.2 ENG. HRS	as of 23-JUL-2007	5718
3138 ENC		3653 ENC	as of 10-APR-2007	3853

<b>ENGINE NO. 3</b>	<b>SERIAL/PART:</b> P76384/TFE731-3-1C	<b>MODEL:</b> TFE731-3	<b>MANUFACTURER:</b> HONEYWELL
---------------------	--	------------------------	--------------------------------

INSTALLED ON 03-JUN-2001	LAST ACTUALS		PROJECTED	
3119 ENG. HRS	3497 A/C HRS	5360 ENG. HRS	as of 23-JUL-2007	5560
2267 ENC		3545 ENC	as of 10-APR-2007	3745



## NEW REQUIREMENT ITEMS Operator Review And Action Required

Aircraft Model : FALCON 50  
Serial #: 082 Reg. #: N582EJ

*These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.*

TASK NO	TASK DESCRIPTION	EFFECTIVE DATE	UNIT	INTERVAL	BASE TIME		NEXT DUE	DISPOSITION
					Current	Change To		
274181	<b>NDT INSPECT HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY)</b>							
		DUE EVERY	MOS	144	14-DEC-1981 (Cert)	_____	14-DEC-1993	
			HRS/MS			0 (Cert)	_____	
	REF: GENERIC NO REF	DUE EVERY	AFL	7500	0 (Cert)	_____	7500	
NEW REQUIREMENT ADDED. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

AUTHORIZED BY \_\_\_\_\_ CERT.# \_\_\_\_\_ DATE \_\_\_\_\_

?-Insufficient Information      (s) Suppressed Requirement      \*-Estimated Due (New Requirement)      (EBT)-Estimated Base Time

24-JUL-2007

© CAMP SYSTEMS



# AIRFRAME Maintenance Due (CALENDAR)

Aircraft Model - FALCON 50  
Serial #: 082 Reg. #: N582EJ

Projected To: 3 MOS. to 23-OCT-2007

TASK NO	WORK CARD WORK ORDER	TASK DESCRIPTION PART #/PKG SERIAL#	UNIT	INTERVAL			COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
				TS	NTS	SRTSI		ADJ	WARR		
R	274181	NDT INSPECT HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY)									
	27.420	021121-09 96 REF: GENERIC NO REF	DUE EVERY MOS HRS/MSC AFL	144			14-DEC-1981 0 0	14-DEC-1993 7500		New Reqmt	
NEW REQUIREMENT ADDED. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.											
R	321107	RIGHT MAIN LANDING GEAR SHOCK ABSORBER END-FITTING									
	32.030	D50493 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	144	0 0 6000		17-FEB-1993 765 491	OVERHAUL 17-FEB-2005 6491		L2 OVD 2686	
H	R	243179	CHECK NO. 2 BATTERY								F7
		24.190	2376-4 083527 REF: AMM 24-071	MOS HRS/MSC AFL	6 250		29-NOV-2004 4906.80 3334	29-MAY-2005 5156.80		OVD OVD	
R	ASB A472	HYDRAULIC POWER - MAIN HYDRAULIC POWER - HYDRAULIC HOSE/AIR TUBE INTERFERENCE ALERT SERVICE BULLETIN									
		REF: BULLETINS	DAYS HRS/MSC AFL	31				RECOMMENDED 26-SEP-2005		OVD	
H	R	243164	CHECK NO. 1 BATTERY								F7
		24.100	2376-4 084183 REF: AMM 24-071	MOS HRS/MSC AFL	6 250		31-MAR-2005 4911.10 3339	30-SEP-2005 5161.10		OVD OVD	
H	R +	243167	CHECK NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE								F7
		24.100	P600-14A 19316 REF: AMM 24-071	MOS HRS/MSC AFL	6 250		31-MAR-2005 4911.10 3339	30-SEP-2005 5161.10		OVD OVD	
H	R +	243182	CHECK NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE								F7
		24.190	2376-4 092267 REF: AMM 24-071	MOS HRS/MSC AFL	6 250		31-MAR-2005 4911.10 3339	30-SEP-2005 5161.10		OVD OVD	
R	341013	CALIBRATE STAND-BY AIRSPEED INDICATOR CHANGE									
		8059-2BFJ 6655 REF:	MOS HRS/MSC AFL	24			10-DEC-2003	CALIBRATE 10-DEC-2005		OVD	

( )-No. of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time  
\*-Estimated Due (New Requirement) (EFF)-Effective C/W H - Task also due in hours due list

Projected To: 3 MOS. to 23-OCT-2007

TASK NO	TASK DESCRIPTION	PART #/PKG SERIAL#	UNIT	INTERVAL	TSNTSOTSR	TSI	ADJ	WARR	COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
										NEXT DUE	(ENH) AFH (xEXT)		
WORK CARD WORK ORDER													
R + 243173	CHECK NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE RESISTANCE												F7
24.100	P600-14A 19316 REF: AMM 24-071		MOS HRS/MSC AFL	12					31-MAR-2005 4911.10 3339		31-MAR-2006	OVD	
R + 243189	CHECK NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE RESISTANCE												F7
24.190	2376-4 092267 REF: AMM 24-071		MOS HRS/MSC AFL	12					31-MAR-2005 4911.10 3339		31-MAR-2006	OVD	
R 243170	OVERHAUL NO. 1 BATTERY												F7
24.100	2376-4 084183 REF: AMM 24-071		MOS HRS/MSC AFL	12					12-MAY-2005 4927.30 3346		OVERHAUL 12-MAY-2006	OVD	
R 243185	OVERHAUL NO. 2 BATTERY												F7
24.190	2376-4 083527 REF: AMM 24-071		MOS HRS/MSC AFL	12					12-MAY-2005 4927.30 3346		OVERHAUL 12-MAY-2006	OVD	
R 262326	REPLACE BAGGAGE COMPARTMENT LEFT FIRE EXTINGUISHER CARTRIDGE (SERVICE LIMIT)												F6
26.210	REF: See Workcard		MOS HRS/MSC AFL	48					02-AUG-2002		SCRAP 02-AUG-2006	OVD	
R SB 0434	EXHAUST - THRUST REVERSER - INSPECTION OF THRUST REVERSER DOOR HINGE FITTINGS SERVICE BULLETIN												F7
	REF: BULLETINS		MOS HRS/MSC AFL	24							RECOMMENDED 08-SEP-2006	OVD	
R 324306	LEFT ANTI-SKID SERVO VALVE												L1
32.600	9542732-2 JAN81-1729 REF: GENERIC NO REF		MOS HRS/MSC AFL	300	0				14-DEC-1981 0 0		OVERHAUL 14-DEC-2006	OVD	
R 291163	REPLACE HYDRAULIC RESERVOIR AIR PRESSURE REDUCING VALVE DIAPHRAGM												F7
29.090	2407ZR4EQ10 2452 REF: GENERIC NO REF		MOS HRS/MSC AFL	72					24-JAN-2001 3255 2299		24-JAN-2007	OVD	
R + 291164	FUNCTIONAL TEST HYDRAULIC RESERVOIR AIR PRESSURE REDUCING VALVE												F7
29.090	2407ZR4EQ10 2452 REF: GENERIC NO REF		MOS HRS/MSC AFL	72					24-JAN-2001 3255 2299		24-JAN-2007	OVD	

( )-No.of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time  
 \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Projected To: 3 MOS. to 23-OCT-2007

TASK NO	WORK CARD WORK ORDER	TASK DESCRIPTION PART #/PKG SERIAL#	UNIT	INTERVAL			COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH (xEXT)	TIME REMAINING OVD = Overdue	AREA PRICE LABOR
				TS	NTS	TSRTSI				
R	351126 35.080	COPILOT OXYGEN MASK MA1012-00 3175 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	0 0 0		24-JAN-2001 3255 2299	OVERHAUL 24-JAN-2007	F3 OVD	
R	301121 30.020	LEAK TEST LEFT OUTBOARD SLAT TELESCOPIC COUPLING AND SWIVELING TORQUE MEASUREMENT 5040-000 552 REF: See Workcard	MOS HRS/MSC AFL	12			22-MAR-2006 5273.40 3520	22-MAR-2007	W1 OVD	
R +	341125 34.040	TEST PILOT ALTIMETER (FAR 91.411) 4016341-904 87044556 REF: FAR 91.411	MOS HRS/MSC AFL	24			06-MAY-2005	MANDATORY 06-MAY-2007	F3 OVD	
R +	341130 34.040	TEST COPILOT ALTIMETER (FAR 91.411) 4016341-904 88085136 REF: FAR 91.411	MOS HRS/MSC AFL	24			06-MAY-2005	MANDATORY 06-MAY-2007	F3 OVD	
R +	342254 34.510	TEST PILOT AIR DATA COMPUTER (FAR 91.411) 7000700-622 98118223 REF: FAR 91.411	MOS HRS/MSC AFL	24			06-MAY-2005	MANDATORY 06-MAY-2007	F2 OVD	
R +	342259 34.530	TEST STAND BY ALTIMETER (FAR 91.411) 570-31400-003 213 REF: FAR 91.411	MOS HRS/MSC AFL	24			06-MAY-2005	MANDATORY 06-MAY-2007	F3 OVD	
R +	342293 34.520	TEST COPILOT AIR DATA COMPUTER (FAR 91.411) 7000700-622 99068426 REF: FAR 91.411	MOS HRS/MSC AFL	24			06-MAY-2005	MANDATORY 06-MAY-2007	F2 OVD	
R +	345191 34.820	TEST NO. 1 ATC TRANSPONDER (FAR 91.413) 622-9210-004 7579 REF: FAR 91.413	MOS HRS/MSC AFL	24			06-MAY-2005	MANDATORY 06-MAY-2007	F4 OVD	
R +	345216 34.820	TEST NO. 2 ATC TRANSPONDER (FAR 91.413) 622-9210-004 7578 REF: FAR 91.413	MOS HRS/MSC AFL	24			06-MAY-2005	MANDATORY 06-MAY-2007	F4 OVD	

( )-No. of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time  
 \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Projected To: 3 MOS. to 23-OCT-2007

	TASK NO	TASK DESCRIPTION PART #/PKG SERIAL#	UNIT	INTERVAL	TSNTSOTSR	TSI	ADJ	WARR	COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
										NEXT DUE ( ENH )	AFH (xEXT)		
R	345331	FUNCTIONAL TEST NO. 1 ATC TRANSPONDER 622-9210-004 7579 REF: See Workcard	MOS HRS/MSC AFL	24					06-MAY-2005	06-MAY-2007		OVD	
	34.820												
R	345332	FUNCTIONAL TEST NO. 2 ATC TRANSPONDER 622-9210-004 7578 REF: See Workcard	MOS HRS/MSC AFL	24					06-MAY-2005	06-MAY-2007		OVD	
	34.820												
R	256146	REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY ELT10 A-20705 REF: AMM 25-110	MOS HRS/MSC AFL	DUE					09-SEP-2005 5046.60 3411	SCRAP 31-MAY-2007 M		F4 OVD	
H	R + 342040	VOLTAGE TEST STANDBY HORIZON (POWER SUPPLY 23F) BATTERY 501-1075-06 1330 REF: See Workcard	MOS HRS/MSC AFL	3 100					10-APR-2007 5665.40 3746	10-JUL-2007 5765.40		F2 OVD 26.20	
	34.380												
R	335103	SERVICE LEFT EMERGENCY LIGHTING (114L1) UNIT 60-2502-1 295 REF: See Workcard	MOS HRS/MSC AFL	12					11-JUL-2006 5352.40 3560	11-JUL-2007		OVD	
	33.100												
R	335113	SERVICE RIGHT EMERGENCY LIGHTING (114L2) UNIT 60-2502-1 297 REF: See Workcard	MOS HRS/MSC AFL	12					11-JUL-2006 5352.40 3560	11-JUL-2007		OVD	
	33.110												
R	335133	SERVICE FRONT EMERGENCY LIGHTING (113L) UNIT 60-2502-1 465 REF: See Workcard	MOS HRS/MSC AFL	12					11-JUL-2006 5352.40 3560	11-JUL-2007		OVD	
	33.120												
R +	052501	BASIC CHECK (MONTHLY INSPECTION)  REF: See Workcard	DAYS HRS/MSC AFL	31					11-JUN-2007 5701.10 3766	12-JUL-2007		OVD	
	05.010												
R	052506	BASIC CHECK (DAILY SERVICING)  REF: AMM 05-050	DAYS HRS/MSC AFL	31					11-JUN-2007 5701.10 3766	12-JUL-2007		OVD	
	05.010												

( )-No. of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time  
 \*-Estimated Due (New Requirement) (EFF)-Effective C/W H - Task also due in hours due list

Projected To: 3 MOS. to 23-OCT-2007

TASK NO	TASK DESCRIPTION	PART #/PKG SERIAL#	UNIT	INTERVAL	TSNTSOTSR	TSI	ADJ	WARR	COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
										NEXT DUE	( ENH ) AFH (xEXT)		
WORK CARD WORK ORDER													
R + 262126	HYDROSTATIC CHECK REAR FIRE (14W2) EXTINGUISHER												
26.070	860640 52418ABC REF: GENERIC NO REF	MOS HRS/MSC AFL	60						03-AUG-2002	MANDATORY 03-AUG-2007		F7 0.3	
R 262129	OVERHAUL REAR FIRE (14W2) EXTINGUISHER												
26.070	860640 52418ABC REF: GENERIC NO REF	MOS HRS/MSC AFL	60						03-AUG-2002	03-AUG-2007		F7 0.3	
R + 262146	HYDROSTATIC CHECK FRONT FIRE (14W3) EXTINGUISHER												
26.080	860640 19354ABC REF: GENERIC NO REF	MOS HRS/MSC AFL	60						03-AUG-2002	MANDATORY 03-AUG-2007		F7 0.3	
R 262149	OVERHAUL FRONT FIRE (14W3) EXTINGUISHER												
26.080	860640 19354ABC REF: GENERIC NO REF	MOS HRS/MSC AFL	60						03-AUG-2002	03-AUG-2007		F7 0.3	
262807	WEIGHT CHECK LEFT FWD CABIN HALON EXTINGUISHER												
	A1600 A570991 REF:	MOS HRS/MSC AFL	6						06-MAR-2007	06-SEP-2007		F4 1.4	
256006	INSPECT/CHECK NO. 1 LIFE RAFT												
25.070	R010A105 TX03022 REF: GENERIC NO REF	MOS HRS/MSC AFL	24						18-SEP-2005	18-SEP-2007		F4 1.8	
256016	INSPECT/CHECK NO. 2 LIFE RAFT												
25.080	R0101A105 TX04024 REF: GENERIC NO REF	MOS HRS/MSC AFL	24						19-SEP-2005	19-SEP-2007		F4 1.83	
256026	INSPECT/CHECK NO. 3 LIFE RAFT												
25.090	R0101A105 TX04026 REF: GENERIC NO REF	MOS HRS/MSC AFL	24						19-SEP-2005	19-SEP-2007		F4 1.83	
+ 050100	A INSPECTION												
	REF: GENERIC NO REF	MOS HRS/MSC AFL	6 300				-15		10-APR-2007 5665.40 3746	25-SEP-2007 5965.40		2.03 226.20	

(-)-No. of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time  
 \*-Estimated Due (New Requirement) (EFF)-Effective C/W

### AIRFRAME Maintenance Due (CALENDAR)

Projected To: 3 MOS. to 23-OCT-2007

TASK NO WORK CARD WORK ORDER	TASK DESCRIPTION PART #/PKG SERIAL#	UNIT	INTERVAL TSNTSOTSR	TSI	ADJ	WARR	COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
								( ENH )	AFH (xEXT)		
+ 050200	2A INSPECTION	MOS HRS/MSC AFL	12 600		-69.30		25-SEP-2006 5434.70 3611	<b>25-SEP-2007</b> 5965.40		2.03 226.20	
	REF: GENERIC NO REF										
+ 050250	A+ INSPECTION	MOS HRS/MSC AFL	6		-15		10-APR-2007 5665.40 3746	<b>25-SEP-2007</b>		2.03	
	REF: GENERIC NO REF										
+ 050300	2A+ INSPECTION	MOS HRS/MSC AFL	12				25-SEP-2006 5434.70 3611	<b>25-SEP-2007</b>		2.03	
	REF: GENERIC NO REF										
+ 332111	FUNCTIONAL TEST LEFT EMERGENCY LIGHTING (114L1) UNIT	MOS HRS/MSC AFL	12				25-SEP-2006 5434.70 3611	<b>25-SEP-2007</b>		2.03	F4
33.100	REF: See Workcard										
332121	FUNCTIONAL TEST RIGHT EMERGENCY LIGHTING (114L2) UNIT	MOS HRS/MSC AFL	12				25-SEP-2006 5434.70 3611	<b>25-SEP-2007</b>		2.03	
33.110	REF: AMM 33-501										
332131	FUNCTIONAL TEST FRONT EMERGENCY LIGHTING (113L) UNIT	MOS HRS/MSC AFL	12				25-SEP-2006 5434.70 3611	<b>25-SEP-2007</b>		2.03	
33.120	REF: AMM 33-501										
AD 2007-01-12	IDENTIFICATION OF OUTBOARD SLATS	MOS HRS/MSC AFL	7 330				(EFF)	<b>MANDATORY</b> 06-OCT-2007 5956.35		2.4 217.15	
	REF: AD										
262802	WEIGHT CHECK COCKPIT HALON EXTINGUISHER	MOS HRS/MSC AFL	6				10-APR-2007 5665.40 3746	<b>10-OCT-2007</b>		2.53	F3
	A352 V-663444 REF:										
+ 262818	WEIGHT CHECK RIGH FWD CABIN HALON EXTINGUISHER	MOS HRS/MSC AFL	6				10-APR-2007 5665.40 3746	<b>10-OCT-2007</b>		2.53	F4
	HAL-035-AVH 000-572C REF:										

( )-No. of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time  
 \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Projected To: 3 MOS. to 23-OCT-2007

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION		TIME REMAINING	AREA PRICE
					TSNTSOTSR	TSI		
WORK CARD	PART #/PKG							
WORK ORDER	SERIAL#							
+ 342292	OPERATIONAL TEST COPILOT AIR DATA COMPUTER							F2
34.520	7000700-622 99068426 REF: See Workcard	MOS HRS/MSC AFL	6 300	10-APR-2007 5665.40 3746		10-OCT-2007 5965.40	2.53 226.20	
+ 490010	APU - ACCOMPLISH 6 MONTH/125 HOUR/250 CYCLE INSPECTION							
49.010	REF: MSC SB-T-62T-49-77	MOS HRS/MSC APUS	6 125 250	10-APR-2007 4216 7255		10-OCT-2007 4341 7505	2.53 101 250	
+ 490020	APU - ACCOMPLISH 6 MONTH/250 HOUR/500 CYCLE INSPECTION							
49.015	REF: MSC SB-T-62T-49-77	MOS HRS/MSC APUS	6 250 500	10-APR-2007 4216 7255		10-OCT-2007 4466 7755	2.53 226 500	
+ 499110	APU - SOAP CHECK OIL							
49.110	REF: GENERIC NO REF	MOS HRS/MSC APUS	6 250 500	10-APR-2007 4216 7255		10-OCT-2007 4466 7755	2.53 226 500	

( )-No.of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time

\*-Estimated Due (New Requirement) (EFF)-Effective C/W



# AIRFRAME Maintenance Due (HOURS)

Aircraft Model - FALCON 50  
 Serial #: 082 Reg. #: N582EJ

TASK NO	WORK CARD	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION		TIME REMAINING	AREA PRICE
						TS	TSOTSRTSI		
	WORK ORDER	PART #/PKG SERIAL#						OVD = Overdue	LABOR
C R	243179	CHECK NO. 2 BATTERY 2376-4 083527 REF: AMM 24-071	MOS HRS/MSC AFL	6 250	29-NOV-2004 4906.80 3334			29-MAY-2005 5156.80	F7 OVD OVD
C R	243164	CHECK NO. 1 BATTERY 2376-4 084183 REF: AMM 24-071	MOS HRS/MSC AFL	6 250	31-MAR-2005 4911.10 3339			30-SEP-2005 5161.10	F7 OVD OVD
C R +	243167	CHECK NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE P600-14A 19316 REF: AMM 24-071	MOS HRS/MSC AFL	6 250	31-MAR-2005 4911.10 3339			30-SEP-2005 5161.10	F7 OVD OVD
C R +	243182	CHECK NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE 2376-4 092267 REF: AMM 24-071	MOS HRS/MSC AFL	6 250	31-MAR-2005 4911.10 3339			30-SEP-2005 5161.10	F7 OVD OVD
R	281311	REPLACE NO. 2 TRANSFER PUMP MOTOR BRUSHES 2060A01 1854 REF: GENERIC NO REF	MOS HRS/MSC AFL	2000	20-APR-2001 3473 2450		5473		F5 OVD
R	281321	REPLACE NO. 2 TRANSFER PUMP BEARINGS 2060A01 1854 REF: GENERIC NO REF	MOS HRS/MSC AFL	2000	20-APR-2001 3473 2450		5473		F5 OVD
R +	281517	FLOW RATE/FALL TEST LEFT WING VACUUM PRESSURE RELIEF VALVE B06GA1050 91 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800	28-APR-1993 765 491		5565		W1 OVD
R +	281518	SEALING TEST LEFT WING VACUUM PRESSURE RELIEF VALVE B06GA1050 91 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800	28-APR-1993 765 491		5565		W1 OVD

( )-No. of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time  
 \*-Estimated Due (New Requirement) (EFF)-Effective C/W C - Task also due in calendar due list

TASK NO	TASK DESCRIPTION	PART #/PKG SERIAL#	UNIT	INTERVAL	TSNTSOTSRTSI	ADJ	WARR	COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
									NEXT DUE ( ENH )	AFH (xEXT)		
R + 281522	FLOW RATE/FALL TEST RIGHT WING VACUUM PRESSURE RELIEF VALVE	B06GA1050	MOS					28-APR-1993				W2
28.420	632 REF: GENERIC NO REF		HRS/MSC AFL	4800				765 491		5565	OVD	
R + 281523	SEALING TEST RIGHT WING VACUUM PRESSURE RELIEF VALVE	B06GA1050	MOS					28-APR-1993				W2
28.420	632 REF: GENERIC NO REF		HRS/MSC AFL	4800				765 491		5565	OVD	
R 281336	REPLACE NO. 3 TRANSFER PUMP MOTOR BRUSHES	2060A01	MOS					28-AUG-2001				F5
28.290	1050 REF: GENERIC NO REF		HRS/MSC AFL	2000				3698 2642		5698	OVD	
R 281346	REPLACE NO. 3 TRANSFER PUMP BEARINGS	2060A01	MOS					28-AUG-2001				F5
28.290	1050 REF: GENERIC NO REF		HRS/MSC AFL	2000				3698 2642		5698	OVD	
R + 057120	NO. 1 ENGINE - 300/400 HOUR ENGINE INSPECTION		MOS					26-OCT-2006				
	REF:		HRS/MSC ENC	300				5360.20		(5660.20) 5764.70	25.50	
R + 057120	NO. 2 ENGINE - 300/400 HOUR ENGINE INSPECTION		MOS					26-OCT-2006				
	REF:		HRS/MSC ENC	300				5243.70		(5543.70) 5764.70	25.50	
R + 057120	NO. 3 ENGINE - 300/400 HOUR ENGINE INSPECTION		MOS					26-OCT-2006				
	REF:		HRS/MSC ENC	300				5085.50		(5385.50) 5764.70	25.50	
C R + 342040	VOLTAGE TEST STANDBY HORIZON (POWER SUPPLY 23F) BATTERY	501-1075-06	MOS					10-APR-2007				F2
34.380	1330 REF: See Workcard		HRS/MSC AFL	100				5665.40 3746		10-JUL-2007 5765.40	OVD 26.20	
+ 243106	CHECK NO. 1 STARTER GENERATOR BRUSHES	8060-320-1	MOS					11-JUL-2006				E1
24.080	1435 REF: See Workcard		HRS/MSC AFL	450				5352.40 3560		5802.40	63.20	

( )-No.of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time

\*-Estimated Due (New Requirement) (EFF)-Effective C/W C - Task also due in calendar due list

TASK NO WORK CARD WORK ORDER	TASK DESCRIPTION PART #/PKG SERIAL#	UNIT	INTERVAL	TSNTSOTSRTSI	ADJ	WARR	COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
								NEXT DUE ( ENH )	AFH (xEXT)		
+ 243121 24.090	CHECK NO. 2 STARTER/GENERATOR BRUSHES 8060-320-1 1821 REF: See Workcard	MOS HRS/MSC AFL	450				11-JUL-2006 5352.40 3560		<b>5802.40</b>	63.20	E2
213116 21.170	CLEAN PNEUMATIC REGULATION (EMERGENCY) VALVE SEAT 2096E010500 222 REF: AMM 21-160	MOS HRS/MSC AFL	1200				12-SEP-2003 4603.10 3171		<b>5803.10</b>	63.90	F4
243101 24.080	NO. 1 STARTER GENERATOR 8060-320-1 1435 REF: See Workcard	MOS HRS/MSC AFL	900	0 0 0			29-NOV-2004 4906.80 3334		<b>OVERHAUL</b> <b>5806.80</b>	67.60	E1
243116 24.090	NO. 2 STARTER/GENERATOR 8060-320-1 1821 REF: See Workcard	MOS HRS/MSC AFL	900	0 0 0			29-NOV-2004 4906.80 3334		<b>OVERHAUL</b> <b>5806.80</b>	67.60	E2
+ 057110	NO. 2 ENGINE - 150/200 HOUR ENGINE INSPECTION  REF:	MOS HRS/MSC ENC	150				10-APR-2007 5444.40 3653		<b>(5594.40)</b> <b>5815.40</b>	76.20	
+ 057110	NO. 1 ENGINE - 150/200 HOUR ENGINE INSPECTION  REF:	MOS HRS/MSC ENC	150				10-APR-2007 5561.10 3733		<b>(5711.10)</b> <b>5815.60</b>	76.40	
+ 057110	NO. 3 ENGINE - 150/200 HOUR ENGINE INSPECTION  REF:	MOS HRS/MSC ENC	150				10-APR-2007 5286.40 3545		<b>(5436.40)</b> <b>5815.60</b>	76.40	
+ 731120 73.020	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT  REF: EMM 73-21-02	MOS HRS/MSC ENC	600				28-MAR-2006 5052.40		<b>(5652.40)</b> <b>5873.40</b>	134.20	
+ 731120 73.020	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT  REF: EMM 73-21-02	MOS HRS/MSC ENC	600				28-MAR-2006 4894.40		<b>(5494.40)</b> <b>5873.60</b>	134.40	

( )-No.of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time

\*-Estimated Due (New Requirement) (EFF)-Effective C/W

TASK NO WORK CARD WORK ORDER	TASK DESCRIPTION PART #/PKG SERIAL#	UNIT	INTERVAL TSNTSOTSRTSI	ADJ	WARR	COMPLIANCE	DISPOSITION		TIME REMAINING OVD = Overdue	AREA PRICE LABOR
							NEXT DUE ( ENH )	AFH (xEXT)		
+ 057130	NO. 1 ENGINE - 600/800 HOUR INSPECTION	MOS HRS/MSC ENC	600			28-MAR-2006 5169.90 3621	(5769.90) 5874.40		135.20	
057140	NO. 1 ENGINE - 1000/1500 HOUR INSPECTION	MOS HRS/MSC ENC	1200	-54.50		26-DEC-2003 4624.40 3218	(5769.90) 5874.40		135.20	
+ 731120 73.020	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT REF: EMM 73-21-02	MOS HRS/MSC ENC	600			28-MAR-2006 5170.10	(5770.10) 5874.60		135.40	
+ 057130	NO. 2 ENGINE - 600/800 HOUR INSPECTION	MOS HRS/MSC ENC	600			28-MAR-2006 5053.60 3541	(5653.60) 5874.60		135.40	
057140	NO. 2 ENGINE - 1000/1500 HOUR INSPECTION	MOS HRS/MSC ENC	1200	-53.10		18-DEC-2003 4506.70 3138	(5653.60) 5874.60		135.40	
+ 057130	NO. 3 ENGINE - 600/800 HOUR INSPECTION	MOS HRS/MSC ENC	600			28-MAR-2006 4895.40 3437	(5495.40) 5874.60		135.40	
+ 243136 24.085	CHECK NO. 3 STARTER/GENERATOR BRUSHES 8060-320-1 2041 REF: See Workcard	MOS HRS/MSC AFL	450			25-SEP-2006 5434.70 3611	5884.70		145.50	E3

( )-No.of times task due in projected period (xEXT)-Extension incorporated in the next due (s) Suppressed Requirement +-FAA manual flag is set (EBT)-Estimated Base Time

\*-Estimated Due (New Requirement) (EFF)-Effective C/W

<b>OWNER:</b> BENTLEY DOWNERS GROVE LUXURY MOTORS	<b>OPERATOR:</b> BENTLEY DOWNERS GROVE LUXURY MOTORS	<b>OPERATOR:</b> MIDAMERICA JET WORKS, LLC
<b>ADDRESS:</b> C/O MIDAMERICA JET WORKS LLC SUGAR GROVE IL 60554	<b>ADDRESS:</b> C/O MIDAMERICA JET WORKS LLC SUGAR GROVE IL 60554	<b>ADDRESS:</b> 43W 450 U.S. ROUTE 30 SUGAR GROVE IL 60554
<b>PHONE:</b> 630.466.9297	<b>PHONE:</b> 630.466.9297	<b>PHONE:</b> 630-466-9297
<b>FAX:</b> 630.466.9546	<b>FAX:</b> 630.466.9546	<b>FAX:</b> 630-466-9546

**ANALYST:** SAMPSON OKAINE      877-411-CAMP (2267) (OFFICE)      800-787-9749 (EFAX-CARDS)      PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.  
**EMAIL:** SOKAINE@CAMPSYSTEMS.COM      631-588-3200 (OFFICE)      631-980-4222 (FAX)

**AIRCRAFT SERIAL/REGNO:** 082/N582EJ      **MODEL:** FALCON 50      **MANUFACTURER:** DASSAULT AVIATION

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 14-DEC-1981	5739.2 A/C HRS as of 23-JUL-2007	A/C HRS as of ___/___/___
	3805 AFL as of 23-JUL-2007	AFL as of ___/___/___
	4240 APH as of 11-JUN-2007	APH as of ___/___/___

**APU SERIAL/PART:** 861812/160981-200      **MODEL:** T-62T-40C3A/3A1      **MANUFACTURER:** HAMILTON SUNDSTRAND

INSTALLED ON 03-JUN-2001	LAST ACTUALS	CURRENT ACTUAL
2670 APU HRS	4240 APU HRS as of 11-JUN-2007	APU HRS as of ___/___/___
5111 APUS	7255 APUS as of 10-APR-2007	APUS as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** P76385/TFE731-3-1C      **MODEL:** TFE731-3      **MANUFACTURER:** HONEYWELL

INSTALLED ON 16-JAN-2004	LAST ACTUALS	CURRENT ACTUAL
4624.4 ENG. HRS      4727.7 A/C HRS	5634.7 ENG. HRS as of 23-JUL-2007	ENG. HRS as of ___/___/___
3218 ENC	3733 ENC as of 10-APR-2007	ENC as of ___/___/___

**ENGINE NO. 2 SERIAL/PART:** P76254/TFE731-3-1C      **MODEL:** TFE731-3      **MANUFACTURER:** HONEYWELL

INSTALLED ON 16-JAN-2004	LAST ACTUALS	CURRENT ACTUAL
4506.7 ENG. HRS      4727.7 A/C HRS	5518.2 ENG. HRS as of 23-JUL-2007	ENG. HRS as of ___/___/___
3138 ENC	3653 ENC as of 10-APR-2007	ENC as of ___/___/___

**ENGINE NO. 3 SERIAL/PART:** P76384/TFE731-3-1C      **MODEL:** TFE731-3      **MANUFACTURER:** HONEYWELL

INSTALLED ON 03-JUN-2001	LAST ACTUALS	CURRENT ACTUAL
3119 ENG. HRS      3497 A/C HRS	5360 ENG. HRS as of 23-JUL-2007	ENG. HRS as of ___/___/___
2267 ENC	3545 ENC as of 10-APR-2007	ENC as of ___/___/___

# Status Due Tasks Report

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

## Work Packages

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE						DISPOSITION	Time Remaining / Total Time	AREA PRICE
				TSN	TSO	TSR	TSI	ADJ	Warr Exp			
WORKCARD	PKG #											
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>												
+ 050100	A INSPECTION PKG 1 in PKG 2,22,9	MOS	6					-15		10-APR-2007	25-SEP-2007	2 / 3.47
	REF: GENERIC NO REF	HRS/MSC	300							5665.4	5965.4	226.20 / 73.80
		AFL								3746		
+ 050200	2A INSPECTION PKG 2 in PKG 22,9	MOS	12							25-SEP-2006	25-SEP-2007	2 / 9.97
	REF: GENERIC NO REF	HRS/MSC	600					-69.3		5434.7	5965.4	226.20 / 304.50
		AFL								3611		
050220	4A INSPECTION PKG 22 in PKG 9	MOS	24							25-SEP-2006	25-SEP-2008	14 / 9.97
	REF: GENERIC NO REF	HRS/MSC	1200							5434.7	6634.7	895.50 / 304.50
		AFL								3611		
+ 050250	A+ INSPECTION PKG 12 in PKG 3,4,9	MOS	6					-15		10-APR-2007	25-SEP-2007	2 / 3.47
	REF: GENERIC NO REF	HRS/MSC								5665.4		
		AFL								3746		
+ 050300	2A+ INSPECTION PKG 3 in PKG 4,9	MOS	12							25-SEP-2006	25-SEP-2007	2 / 9.97
	REF: GENERIC NO REF	HRS/MSC								5434.7		
		AFL								3611		
+ 050400	4A+ INSPECTION PKG 4 in PKG 9	MOS	24							25-SEP-2006	25-SEP-2008	14 / 9.97
	REF: GENERIC NO REF	HRS/MSC								5434.7		
		AFL								3611		
+ 050500	B INSPECTION PKG 5	MOS								31-MAR-2005		
	REF: GENERIC NO REF	HRS/MSC	1500							4911.1	6411.1	671.90 / 828.10
		AFL								3339		
+ 050600	2B INSPECTION CHECK-LIST PKG 6	MOS								03-JUN-2001		
	REF: GENERIC NO REF	HRS/MSC	3000					-85.9		3497	6411.1	671.90 / 2242.20
		AFL								2468		
+ 050700	3B INSPECTION CHECK-LIST PKG 7	MOS								31-MAR-2005		
	REF: GENERIC NO REF	HRS/MSC	4500							4911.1	9411.1	3671.90 / 828.10
		AFL								3339		
+ 050800	4B INSPECTION CHECK-LIST PKG 8	MOS								28-APR-1993		
	REF: GENERIC NO REF	HRS/MSC	6000					-353.9		765	6411.1	671.90 / 4974.20
		AFL								491		
+ 050900	C INSPECTION PKG 9	MOS	72							29-NOV-2004	29-NOV-2010	40 / 31.83
	REF: GENERIC NO REF	HRS/MSC								4906.8		
		AFL								3334		

# Status Due Tasks Report

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

## Work Packages

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE						DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS	
				TSN	TSO	TSR	TSI	ADJ	Warr Exp				NEXT DUE (ENH) AFH
+ 051000	2C INSPECTION CHECK-LIST PKG 10	MOS HRS/MSC AFL	144							29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
	REF: GENERIC NO REF												
<b>ENGINE NO. 1 Model : TFE731-3 Serial # P76385 Part # TFE731-3-1C</b>													
+ 057110	NO. 1 ENGINE - 150/200 HOUR ENGINE INSPECTION PKG 1 in PKG 2,3,4	MOS HRS/MSC ENC	150							10-APR-2007 5561.1 3733	(5711.1) 5815.6	76.40 / 73.60	
+ 057120	NO. 1 ENGINE - 300/400 HOUR ENGINE INSPECTION PKG 2 in PKG 3,4	MOS HRS/MSC ENC	300							26-OCT-2006 5360.2	(5660.2) 5764.7	25.50 / 274.50	
+ 057130	NO. 1 ENGINE - 600/800 HOUR INSPECTION PKG 3 in PKG 4	MOS HRS/MSC ENC	600							28-MAR-2006 5169.9 3621	(5769.9) 5874.4	135.20 / 464.80	
057140	NO. 1 ENGINE - 1000/1500 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	1200					-54.5		26-DEC-2003 4624.4 3218	(5769.9) 5874.4	135.20 / 1010.30	
<b>ENGINE NO. 2 Model : TFE731-3 Serial # P76254 Part # TFE731-3-1C</b>													
+ 057110	NO. 2 ENGINE - 150/200 HOUR ENGINE INSPECTION PKG 1 in PKG 2,3,4	MOS HRS/MSC ENC	150							10-APR-2007 5444.4 3653	(5594.4) 5815.4	76.20 / 73.80	
+ 057120	NO. 2 ENGINE - 300/400 HOUR ENGINE INSPECTION PKG 2 in PKG 3,4	MOS HRS/MSC ENC	300							26-OCT-2006 5243.7	(5543.7) 5764.7	25.50 / 274.50	
+ 057130	NO. 2 ENGINE - 600/800 HOUR INSPECTION PKG 3 in PKG 4	MOS HRS/MSC ENC	600							28-MAR-2006 5053.6 3541	(5653.6) 5874.6	135.40 / 464.60	
057140	NO. 2 ENGINE - 1000/1500 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	1200					-53.1		18-DEC-2003 4506.7 3138	(5653.6) 5874.6	135.40 / 1011.50	
<b>ENGINE NO. 3 Model : TFE731-3 Serial # P76384 Part # TFE731-3-1C</b>													
+ 057110	NO. 3 ENGINE - 150/200 HOUR ENGINE INSPECTION PKG 1 in PKG 2,3,4	MOS HRS/MSC ENC	150							10-APR-2007 5286.4 3545	(5436.4) 5815.6	76.40 / 73.60	
+ 057120	NO. 3 ENGINE - 300/400 HOUR ENGINE INSPECTION PKG 2 in PKG 3,4	MOS HRS/MSC ENC	300							26-OCT-2006 5085.5	(5385.5) 5764.7	25.50 / 274.50	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

**Status Due Tasks Report**

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

**Work Packages**

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL								COMPLIANCE	DISPOSITION		Time Remaining / Total Time	AREA PRICE		
				TSN	TSO	TSR	TSI	ADJ	Warr Exp	( ENH )		AFH	LABOR		HRS		
+ 057130	NO. 3 ENGINE - 600/800 HOUR INSPECTION PKG 3 in PKG 4	MOS									28-MAR-2006						
	REF:	ENC	600								4895.4	(5495.4)	5874.6	135.40 / 464.60			
											3437						
057140	NO. 3 ENGINE - 1000/1500 HOUR INSPECTION PKG 4	MOS									28-JUL-2004						
	REF:	ENC	1200								4505.3	(5705.3)	6084.5	345.30 / 854.70			
											3112						

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>													
+ 052501	BASIC CHECK (MONTHLY INSPECTION)	DAYS	31							11-JUN-2007	12-JUL-2007	OVD / 43	
05.010	REF: See Workcard	HRS/MSC								5701.1			
		AFL								3766			
052506	BASIC CHECK (DAILY SERVICING)	DAYS	31							11-JUN-2007	12-JUL-2007	OVD / 43	
05.010	REF: AMM 05-050	HRS/MSC								5701.1			
		AFL								3766			
<b>CHAPTER 21 AIR CONDITIONING</b>													
+ 212167	VALVE:OPERATIONAL TEST BAGGAGE COMPARTMENT ISOLATION VALVE (MANDATORY REF 5-40-00)										MANDATORY 5-40		F4
21.050	REF: See Workcard	MOS								25-SEP-2006			
		HRS/MSC	650							5434.7	6084.7	345.50 / 304.50	
		AFL								3611			
+ 212179	VALVE:OPERATIONAL TEST BAGGAGE COMPARTMENT SUPPLY VALVE (MANDATORY REF 5-40-00)										MANDATORY 5-40		F5
21.050	REF: See Workcard	MOS								25-SEP-2006			
		HRS/MSC	650							5434.7	6084.7	345.50 / 304.50	
		AFL								3611			
+ 212226	BLOWER:INSPECT/CHECK NOSE CONE BLOWER BRUSHES												F2
21.100	REF: AMM 21-040	MOS								28-AUG-2001			
		HRS/MSC	3600							3698	7298	1558.80 / 2041.20	
		AFL								2642			
212231	BLOWER:REPLACE NOSE CONE BLOWER BEARINGS												F2
21.100	REF: GENERIC NO REF	MOS								21-AUG-2001			
		HRS/MSC	3600							3698	7298	1558.80 / 2041.20	
		AFL								2642			
+ 213113	VALVE:TEST PNEUMATIC REGULATION (EMERGENCY) VALVE (VACUUM FUNCTION)												F4
21.170	REF: GENERIC NO REF	MOS								12-SEP-2003			
		HRS/MSC	4500							4603.1	9103.1	3363.90 / 1136.10	
		AFL								3171			
213115	VALVE:CHECK PNEUMATIC REGULATION (EMERGENCY) VALVE OVERPRESSURE TIGHTNESS												
21.170	REF: AMM 21-160	MOS								12-SEP-2003			
		HRS/MSC	1500							4603.1	6103.1	363.90 / 1136.10	
		AFL								3171			
213116	VALVE:CLEAN PNEUMATIC REGULATION (EMERGENCY) VALVE SEAT												F4
21.170	REF: AMM 21-160	MOS								12-SEP-2003			
		HRS/MSC	1200							4603.1	5803.1	63.90 / 1136.10	
		AFL								3171			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp	( ENH ) AFH			
+ 213117	VALVE:TEST PNEUMATIC REGULATION (EMERGENCY) VALVE (OVERPRESSURE FUNCTION)	MOS		12-SEP-2003			F4
21.170		HRS/MSC 4500		4603.1	9103.1	3363.90 / 1136.10	
	REF: GENERIC NO REF	AFL		3171			
+ 213118	VALVE:FUNCTIONAL TEST PNEUMATIC REGULATION (EMERGENCY) VALVE (ALTITUDE LIMIT)	MOS		12-SEP-2003			F4
21.170		HRS/MSC 4500		4603.1	9103.1	3363.90 / 1136.10	
	REF: GENERIC NO REF	AFL		3171			
+ 213119	VALVE:FUNCTIONAL TEST PNEUMATIC REGULATION (EMERGENCY) VALVE (ALTITUDE LIMIT) (MANDATORY REF 5-40-00)	MOS		12-SEP-2003	<b>MANDATORY 5-40</b>		F4
21.170		HRS/MSC 5000		4603.1	9603.1	3863.90 / 1136.10	
	REF: GENERIC NO REF	AFL		3171			
+ 213123	VALVE:TEST ELECTRO-PNEUMATIC REGULATION (MAIN) VALVE (VACUUM FUNCTION)	MOS		09-JAN-2002			F4
21.160		HRS/MSC 4500		3992	8492	2752.80 / 1747.20	
	REF: GENERIC NO REF	AFL		2862			
213125	VALVE:CHECK ELECTRO-PNEUMATIC REGULATION (MAIN) VALVE OVERPRESSURE TIGHTNESS	MOS		29-NOV-2004			
21.160		HRS/MSC 1500		4906.8	6406.8	667.60 / 832.40	
	REF: AMM 21-160	AFL		3334			
213126	VALVE:CLEAN ELECTRO-PNEUMATIC REGULATION (MAIN) VALVE SEAT	MOS		29-NOV-2004			F4
21.160		HRS/MSC 1200		4906.8	6106.8	367.60 / 832.40	
	REF: AMM 21-160	AFL		3334			
+ 213127	VALVE:TEST ELECTRO-PNEUMATIC REGULATION (MAIN) VALVE (OVERPRESSURE FUNCTION)	MOS		29-NOV-2004			F4
21.160		HRS/MSC 4500		4906.8	9406.8	3667.60 / 832.40	
	REF: GENERIC NO REF	AFL		3334			
+ 213128	VALVE:FUNCTIONAL TEST ELECTRO-PNEUMATIC REGULATION (MAIN) VALVE (ALTITUDE LIMIT)	MOS		29-NOV-2004			F4
21.160		HRS/MSC 4500		4906.8	9406.8	3667.60 / 832.40	
	REF: GENERIC NO REF	AFL		3334			
+ 213129	VALVE:FUNCTIONAL TEST ELECTRO-PNEUMATIC REGULATION (MAIN) VALVE (ALTITUDE LIMIT) (MANDATORY REF 5-40-00)	MOS		29-NOV-2004	<b>MANDATORY 5-40</b>		F4
21.160		HRS/MSC 5000		4906.8	9906.8	4167.60 / 832.40	
	REF: GENERIC NO REF	AFL		3334			
+ 213187	VALVE:FUNCTIONAL TEST LEFT OVERPRESSURE/VACUUM VALVE (MANDATORY REF 5-40-00)	MOS		26-AUG-1999	<b>MANDATORY 5-40</b>		F6
21.190		HRS/MSC 3700		2311	6011	271.80 / 3428.20	
	REF: AMM 21-180	AFL		1616			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 213207	VALVE:FUNCTIONAL TEST RIGHT OVERPRESSURE/VACUUM VALVE (MANDATORY REF 5-40-00)										MANDATORY 5-40		F6
21.190	REF: AMM 21-180	MOS HRS/MSC AFL	3700							26-AUG-1999 2311 1616	6011	271.80 / 3428.20	
+ 213221	SWITCH:CALIBRATION CHECK ALTITUDE PRESSURE SWITCH												F3
21.210	REF: GENERIC NO REF	MOS HRS/MSC AFL	4000							09-JAN-2002 3992 2862	7992	2252.80 / 1747.20	
+ 213232	CHECK FLIGHT OR GROUND CABIN SEALING (MANDATORY REF 5-40-00)										MANDATORY 5-40		F3
21.130	REF: See Workcard	MOS HRS/MSC AFL	7000							14-DEC-1981 0 0	7000	3195 / 3805	
215101	COOLING UNIT:UPPER AIR COOLING UNIT										OVERHAUL		F7
21.230	3500C01 279 REF: AMM 21-190	MOS HRS/MSC AFL	4000		0					03-JUN-2001 3497 2468	7497	1757.80 / 2242.20	
215103	TURBINE:UPPER COOLING TURBINE										OVERHAUL		F7
21.230	3176C01 148 REF: See Workcard	MOS HRS/MSC AFL	4000		0					25-FEB-2000 2610 1837	6610	870.80 / 3129.20	
215113	FLOW LIMITER:CABIN AIR CONDITIONING FLOW LIMITER										OVERHAUL		F7
21.070	2725F030100 231 REF: GENERIC NO REF	MOS HRS/MSC AFL	4500		0					31-JUL-2002 4191.1 2986	8691.1	2951.90 / 1548.10	
215121	COOLING UNIT:LOWER AIR COOLING UNIT										OVERHAUL		F7
21.240	3500C01 188 REF: AMM 21-190	MOS HRS/MSC AFL	4000		0					03-JUN-2001 3497.4 2468	7497.4	1758.20 / 2241.80	
215123	TURBINE:LOWER COOLING TURBINE										OVERHAUL		F7
21.240	3176C01 188 REF: See Workcard	MOS HRS/MSC AFL	4000		0					03-JUN-2001 3497.4 2468	7497.4	1758.20 / 2241.80	
215133	FLOW LIMITER:COCKPIT AIR CONDITIONING FLOW LIMITER										OVERHAUL		F7
21.070	2725F030100 716 REF: GENERIC NO REF	MOS HRS/MSC AFL	4500		0					31-JUL-2002 4191.1 2986	8691.1	2951.90 / 1548.10	

**CHAPTER 22 AUTO FLIGHT**

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #										NEXT DUE ( ENH ) AFH		
+ 221032	CAPSTAN:CHECK AUTOPILOT ROLL SERVO MOUNT CAPSTAN SLIP CLUTCH												F5
22.110		MOS								14-DEC-1981			
		HRS/MSC	14000							0	14000	8260.80 / 5739.20	
	REF: AMM 22-110	AFL								0			
+ 221042	CAPSTAN:CHECK AUTOPILOT PITCH SERVO MOUNT CAPSTAN SLIP CLUTCH												F7
22.120		MOS								14-DEC-1981			
		HRS/MSC	14000							0	14000	8260.80 / 5739.20	
	REF: AMM 22-110	AFL								0			
<b>CHAPTER 24 ELECTRICAL POWER</b>													
243101	STARTER GENERATOR:NO. 1 STARTER GENERATOR										OVERHAUL		E1
24.080	8060-320-1	MOS								29-NOV-2004			
	1435	HRS/MSC	900							4906.8	5806.8	67.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 243106	STARTER GENERATOR:CHECK NO. 1 STARTER GENERATOR BRUSHES												E1
24.080		MOS								11-JUL-2006			
		HRS/MSC	450							5352.4	5802.4	63.20 / 386.80	
	REF: See Workcard	AFL								3560			
243116	STARTER/GENERATOR:NO. 2 STARTER/GENERATOR										OVERHAUL		E2
24.090	8060-320-1	MOS								29-NOV-2004			
	1821	HRS/MSC	900							4906.8	5806.8	67.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 243121	STARTER/GENERATOR:CHECK NO. 2 STARTER/GENERATOR BRUSHES												E2
24.090		MOS								11-JUL-2006			
		HRS/MSC	450							5352.4	5802.4	63.20 / 386.80	
	REF: See Workcard	AFL								3560			
243131	STARTER/GENERATOR:NO. 3 STARTER/GENERATOR										OVERHAUL		E3
24.085	8060-320-1	MOS								25-SEP-2006			
	2041	HRS/MSC	900							5434.7	6334.7	595.50 / 304.50	
	REF: See Workcard	AFL								3611			
+ 243136	STARTER/GENERATOR:CHECK NO. 3 STARTER/GENERATOR BRUSHES												E3
24.085		MOS								25-SEP-2006			
		HRS/MSC	450							5434.7	5884.7	145.50 / 304.50	
	REF: See Workcard	AFL								3611			
243164	BATTERY:CHECK NO. 1 BATTERY												F7
24.100		MOS	6							31-MAR-2005	30-SEP-2005	OVD / 27.77	
		HRS/MSC	250							4911.1	5161.1	OVD / 828.10	
	REF: AMM 24-071	AFL								3339			
+ 243167	PROBE:CHECK NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE												F7
24.100		MOS	6							31-MAR-2005	30-SEP-2005	OVD / 27.77	
		HRS/MSC	250							4911.1	5161.1	OVD / 828.10	
	REF: AMM 24-071	AFL								3339			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE						DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ	Warr Exp			
WORKCARD	PART#/PKG SERIAL #											
243170	BATTERY:OVERHAUL NO. 1 BATTERY	MOS	12						12-MAY-2005	OVERHAUL		F7
24.100		HRS/MSC							4927.3	12-MAY-2006	OVD / 26.4	
	REF: AMM 24-071	AFL							3346			
+ 243173	PROBE:CHECK NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE RESISTANCE	MOS	12						31-MAR-2005	31-MAR-2006	OVD / 27.77	F7
24.100		HRS/MSC							4911.1			
	REF: AMM 24-071	AFL							3339			
243179	BATTERY:CHECK NO. 2 BATTERY	MOS	6						29-NOV-2004	29-MAY-2005	OVD / 31.83	F7
24.190		HRS/MSC	250						4906.8	5156.8	OVD / 832.40	
	REF: AMM 24-071	AFL							3334			
+ 243182	PROBE:CHECK NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE	MOS	6						31-MAR-2005	30-SEP-2005	OVD / 27.77	F7
24.190		HRS/MSC	250						4911.1	5161.1	OVD / 828.10	
	REF: AMM 24-071	AFL							3339			
243185	BATTERY:OVERHAUL NO. 2 BATTERY	MOS	12						12-MAY-2005	OVERHAUL		F7
24.190		HRS/MSC							4927.3	12-MAY-2006	OVD / 26.4	
	REF: AMM 24-071	AFL							3346			
+ 243189	PROBE:CHECK NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE RESISTANCE	MOS	12						31-MAR-2005	31-MAR-2006	OVD / 27.77	F7
24.190		HRS/MSC							4911.1			
	REF: AMM 24-071	AFL							3339			
243301	STARTER GENERATOR:APU STARTER GENERATOR	MOS							12-SEP-2003	OVERHAUL		F7
24.210	8060-300	HRS/MSC				0			4603.1			
	1367	AFL				0			3171			
	REF: AMM 24-120	APH	900			0			3480	4380	140 / 760	
+ 243306	STARTER GENERATOR:CHECK APU STARTER GENERATOR BRUSHES	MOS							10-APR-2007			F7
24.210		HRS/MSC							5665.4			
	REF: See Workcard	AFL							3746			
		APH	300						4216	4516	276 / 24	
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>												
256006	LIFE RAFT:INSPECT/CHECK NO. 1 LIFE RAFT	MOS	24						18-SEP-2005	18-SEP-2007	2 / 22.2	F4
25.070		HRS/MSC										
	REF: GENERIC NO REF	AFL										

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
256016	LIFE RAFT:INSPECT/CHECK NO. 2	LIFE RAFT											F4
25.080		MOS	24							19-SEP-2005	19-SEP-2007	2 / 22.17	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256026	LIFE RAFT:INSPECT/CHECK NO. 3	LIFE RAFT											F4
25.090		MOS	24							19-SEP-2005	19-SEP-2007	2 / 22.17	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256036	LIFE JACKET:INSPECT/CHECK NO. 1	PASSENGER LIFE JACKET											F4
25.100		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256046	LIFE JACKET:INSPECT/CHECK NO. 2	PASSENGER LIFE JACKET											F4
25.110		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256056	LIFE JACKET:INSPECT/CHECK NO. 3	PASSENGER LIFE JACKET											F4
25.120		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256066	LIFE JACKET:INSPECT/CHECK NO. 4	PASSENGER LIFE JACKET											F4
25.130		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256076	LIFE JACKET:INSPECT/CHECK NO. 5	PASSENGER LIFE JACKET											F4
25.140		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256086	LIFE JACKET:INSPECT/CHECK NO. 6	PASSENGER LIFE JACKET											F4
25.150		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256096	LIFE JACKET:INSPECT/CHECK NO. 7	PASSENGER LIFE JACKET											F4
25.160		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											
256106	LIFE JACKET:INSPECT/CHECK NO. 8	PASSENGER LIFE JACKET											F4
25.170		MOS	60							31-OCT-2003	31-OCT-2008	15 / 44.77	
	REF: GENERIC NO REF	HRS/MSC											
		AFL											

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE (ENH) AFH		
256116	LIFE JACKET:INSPECT/CHECK NO. 9 PASSENGER LIFE JACKET	MOS	60	31-OCT-2003	31-OCT-2008	15 / 44.77	F4
25.180	REF: GENERIC NO REF	HRS/MSC AFL					
256126	LIFE JACKET:INSPECT/CHECK PILOT LIFE JACKET	MOS	60	30-OCT-2003	30-OCT-2008	15 / 44.8	F3
25.190	REF: GENERIC NO REF	HRS/MSC AFL					
256136	LIFE JACKET:INSPECT/CHECK COPILOT LIFE JACKET	MOS	60	31-OCT-2003	31-OCT-2008	15 / 44.77	F3
25.190	REF: GENERIC NO REF	HRS/MSC AFL					
256146	TRANSMITTER:REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY	MOS		09-SEP-2005	<b>SCRAP</b>		F4
25.210	REF: AMM 25-110	HRS/MSC DUE AFL		5046.6 3411	31-MAY-2007 M	OVD / 22.5	
<b>CHAPTER 26 FIRE PROTECTION</b>							
+ 261141	FIRE DETECTOR:FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR	MOS		29-NOV-2004			E1
26.010	REF: AMM 26-380	HRS/MSC 5600 AFL		4906.8 3334	10506.8	4767.60 / 832.40	
+ 261142	FIRE DETECTOR:FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR (MANDATORY REF 5-40-00)	MOS		29-NOV-2004	<b>MANDATORY 5-40</b>		E1
26.010	REF: AMM 26-380	HRS/MSC 5600 AFL		4906.8 3334	10506.8	4767.60 / 832.40	
+ 261146	FIRE DETECTOR:FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR	MOS		29-NOV-2004			E2
26.015	REF: AMM 26-380	HRS/MSC 5600 AFL		4906.8 3334	10506.8	4767.60 / 832.40	
+ 261147	FIRE DETECTOR:FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR (MANDATORY REF 5-40-00)	MOS		29-NOV-2004	<b>MANDATORY 5-40</b>		E2
26.015	REF: AMM 26-380	HRS/MSC 5600 AFL		4906.8 3334	10506.8	4767.60 / 832.40	
+ 261151	FIRE DETECTOR:FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR	MOS		03-JUN-2001			E3
26.010	REF: AMM 26-380	HRS/MSC 5600 AFL		3497 2468	9097	3357.80 / 2242.20	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 261152	FIRE DETECTOR:FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		E3
26.010		MOS								03-JUN-2001			
	REF: AMM 26-380	HRS/MSC 5600								3497	<b>9097</b>	3357.80 / 2242.20	
		AFL								2468			
+ 261156	FIRE DETECTOR:FUNCTIONAL TEST LEFT MAIN GEAR WHEEL WELL FIRE DETECTOR												L1
26.050		MOS								31-MAR-2005			
	REF: AMM 26-380	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			
+ 261157	FIRE DETECTOR:FUNCTIONAL TEST LEFT MAIN GEAR WHEEL WELL FIRE DETECTOR (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		L1
26.050		MOS								31-MAR-2005			
	REF: GENERIC NO REF	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			
+ 261161	FIRE DETECTOR:FUNCTIONAL TEST RIGHT MAIN GEAR WHEEL WELL FIRE DETECTOR												F7, L2
26.050		MOS								31-MAR-2005			
	REF: AMM 26-380	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			
+ 261162	FIRE DETECTOR:FUNCTIONAL TEST RIGHT MAIN GEAR WHEEL WELL FIRE DETECTOR (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		F7, L2
26.050		MOS								31-MAR-2005			
	REF: GENERIC NO REF	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			
+ 261163	FIRE DETECTOR:FUNCTIONAL TEST REAR COMPARTMENT FIRE DETECTOR												F7
26.050		MOS								31-MAR-2005			
	REF: AMM 26-380	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			
+ 261164	FIRE DETECTOR:FUNCTIONAL TEST REAR COMPARTMENT FIRE DETECTOR (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		F7
26.050		MOS								31-MAR-2005			
	REF: AMM 26-380	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			
+ 261166	FIRE DETECTOR:FUNCTIONAL TEST APU FIRE DETECTOR												F7
26.050		MOS								31-MAR-2005			
	REF: AMM 26-380	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			
+ 261167	FIRE DETECTOR:FUNCTIONAL TEST APU FIRE DETECTOR (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		F7
26.050		MOS								31-MAR-2005			
	REF: AMM 26-380	HRS/MSC 5600								4911.1	<b>10511.1</b>	4771.90 / 828.10	
		AFL								3339			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE (ENH) AFH		
+ 262106	EXTINGUISHER:HYDROSTATIC CHECK MIDDLE FIRE (14W1) EXTINGUISHER	MOS	60	29-NOV-2005	<b>MANDATORY</b> 29-NOV-2010	40 / 19.83	F7
26.060	REF: GENERIC NO REF	HRS/MSC AFL					
262109	EXTINGUISHER:OVERHAUL MIDDLE FIRE (14W1) EXTINGUISHER	MOS	60	29-NOV-2005	<b>29-NOV-2010</b>	40 / 19.83	F7
26.060	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262111	EXTINGUISHER:WEIGHT CHECK MIDDLE FIRE (14W1) EXTINGUISHER	MOS	12	06-MAR-2007	<b>06-MAR-2008</b>	7 / 4.6	F7
26.060	REF: AMM 26-204	HRS/MSC AFL					
262116	REPLACE MIDDLE FIRE (14W1) EXTINGUISHER RED HEAD CARTRIDGE (SERVICE LIFE)	MOS	60	07-JAN-2003	<b>SCRAP</b> 07-JAN-2008	5 / 54.57	F7
26.060	REF: AMM 26-205	HRS/MSC AFL		4295.5 3040			
262117	REPLACE MIDDLE FIRE (14W1) EXTINGUISHER GREEN HEAD CARTRIDGE (SERVICE LIFE)	MOS	60	09-DEC-2005	<b>SCRAP</b> 09-DEC-2010	41 / 19.5	F7
26.060	REF: AMM 26-205	HRS/MSC AFL					
262119	REPLACE MIDDLE FIRE (14W1) EXTINGUISHER RED HEAD CARTRIDGE (LIFE LIMIT)	MOS	84	25-MAR-2002	<b>LIFE LIMIT</b> 25-MAR-2009	20 / 63.97	F7
26.060	REF: GENERIC NO REF	HRS/MSC AFL					
262120	REPLACE MIDDLE FIRE (14W1) EXTINGUISHER GREEN HEAD CARTRIDGE (LIFE LIMIT)	MOS	84	01-SEP-2005	<b>LIFE LIMIT</b> 01-SEP-2012	61 / 22.77	F7
26.060	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262126	EXTINGUISHER:HYDROSTATIC CHECK REAR FIRE (14W2) EXTINGUISHER	MOS	60	03-AUG-2002	<b>MANDATORY</b> 03-AUG-2007	0 / 59.7	F7
26.070	REF: GENERIC NO REF	HRS/MSC AFL					
262129	EXTINGUISHER:OVERHAUL REAR FIRE (14W2) EXTINGUISHER	MOS	60	03-AUG-2002	<b>03-AUG-2007</b>	0 / 59.7	F7
26.070	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262131	EXTINGUISHER:WEIGHT CHECK REAR FIRE (14W2) EXTINGUISHER	MOS	12	06-MAR-2007	<b>06-MAR-2008</b>	7 / 4.6	F7
26.070	REF: AMM 26-204	HRS/MSC AFL					

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
262136	REPLACE REAR FIRE (14W2) EXTINGUISHER RED CARTRIDGE (SERVICE LIFE)	MOS	60	07-JAN-2003	SCRAP	5 / 54.57	F7
26.070	REF: AMM 26-205	HRS/MSC		4295.5	07-JAN-2008		
		AFL		3040			
262137	REPLACE REAR FIRE (14W2) EXTINGUISHER GREEN CARTRIDGE (SERVICE LIFE)	MOS	60	07-JAN-2003	SCRAP	5 / 54.57	F7
26.070	REF: AMM 26-205	HRS/MSC		4295.5	07-JAN-2008		
		AFL		3040			
262139	REPLACE REAR FIRE (14W2) EXTINGUISHER RED CARTRIDGE (LIFE LIMIT)	MOS	84	25-MAR-2002	LIFE LIMIT	20 / 63.97	F7
26.070	REF: GENERIC NO REF	HRS/MSC			25-MAR-2009		
		AFL					
262140	REPLACE REAR FIRE (14W2) EXTINGUISHER GREEN CARTRIDGE (LIFE LIMIT)	MOS	84	25-MAR-2002	LIFE LIMIT	20 / 63.97	F7
26.070	REF: GENERIC NO REF	HRS/MSC			25-MAR-2009		
		AFL					
+ 262146	EXTINGUISHER:HYDROSTATIC CHECK FRONT FIRE (14W3) EXTINGUISHER	MOS	60	03-AUG-2002	MANDATORY	0 / 59.7	F7
26.080	REF: GENERIC NO REF	HRS/MSC			03-AUG-2007		
		AFL					
262149	EXTINGUISHER:OVERHAUL FRONT FIRE (14W3) EXTINGUISHER	MOS	60	03-AUG-2002	MANDATORY	0 / 59.7	F7
26.080	REF: GENERIC NO REF	HRS/MSC			03-AUG-2007		
		AFL					
+ 262151	EXTINGUISHER:WEIGHT CHECK FRONT FIRE (14W3) EXTINGUISHER	MOS	12	06-MAR-2007	MANDATORY	7 / 4.6	F7
26.080	REF: AMM 26-204	HRS/MSC			06-MAR-2008		
		AFL					
262156	REPLACE FRONT FIRE (14W3) EXTINGUISHER RED CARTRIDGE (SERVICE LIFE)	MOS	60	07-JAN-2003	SCRAP	5 / 54.57	F7
26.080	REF: AMM 26-205	HRS/MSC		4295.5	07-JAN-2008		
		AFL		3040			
262157	REPLACE FRONT FIRE (14W3) EXTINGUISHER GREEN CARTRIDGE (SERVICE LIFE)	MOS	60	07-JAN-2003	SCRAP	5 / 54.57	F7
26.080	REF: AMM 26-205	HRS/MSC		4295.5	07-JAN-2008		
		AFL		3040			
262159	REPLACE FRONT FIRE (14W3) EXTINGUISHER RED CARTRIDGE (LIFE LIMIT)	MOS	84	25-MAR-2002	LIFE LIMIT	20 / 63.97	F7
26.080	REF: GENERIC NO REF	HRS/MSC			25-MAR-2009		
		AFL					

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
262160	REPLACE FRONT FIRE (14W3) EXTINGUISHER GREEN CARTRIDGE(LIFE LIMIT)	MOS	84	25-MAR-2002	LIFE LIMIT 25-MAR-2009	20 / 63.97	F7
26.080	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262171	EXTINGUISHER:HYDROSTATIC TEST APU FIRE EXTINGUISHER	MOS	60	15-JAN-2003	MANDATORY 15-JAN-2008	6 / 54.3	F7
26.090	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262176	EXTINGUISHER:WEIGHT CHECK APU FIRE EXTINGUISHER	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F7
26.090	REF: See Workcard	HRS/MSC AFL					
262181	REPLACE APU FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	MOS	48	29-NOV-2004 4906.8 3334	SCRAP 29-NOV-2008	16 / 31.83	F7
26.090	REF: AMM 26-230	HRS/MSC AFL					
262184	REPLACE APU FIRE EXTINGUISHER CARTRIDGE (LIFE LIMIT)	MOS	72	31-MAR-2004	LIFE LIMIT 31-MAR-2010	32 / 39.77	F7
26.090	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262185	EXTINGUISHER:INSULATION TEST APU FIRE EXTINGUISHER SQUIB	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F7
26.090	REF: AMM 26-200	HRS/MSC C/C AFL					
+ 262216	EXTINGUISHER:INSULATION TEST MIDDLE FIRE (14W1) EXTINGUISHER SQUIB	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F7
26.060	REF: AMM 26-020	HRS/MSC C/C AFL					
+ 262217	EXTINGUISHER:INSULATION TEST REAR FIRE (14W2) EXTINGUISHER SQUIB	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F7
26.070	REF: AMM 26-080	HRS/MSC C/C AFL					
+ 262218	EXTINGUISHER:INSULATION TEST FRONT FIRE (14W3) EXTINGUISHER SQUIB	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F7
26.080	REF: AMM 26-140	HRS/MSC C/C AFL					
+ 262266	EXTINGUISHER:HYDROSTATIC CHECK BAGGAGE COMPARTMENT RIGHT FIRE EXTINGUISHER	MOS	60	15-JAN-2003	MANDATORY 15-JAN-2008	6 / 54.3	F6
26.180	REF: GENERIC NO REF	HRS/MSC AFL					

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
+ 262271	EXTINGUISHER:WEIGHT CHECK BAGGAGE COMPARTMENT RIGHT FIRE EXTINGUISHER	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F6
26.180	REF: See Workcard	HRS/MSC AFL					
262276	REPLACE BAGGAGE COMPARTMENT RIGHT FIRE EXTINGUISHER NO. 1 CARTRIDGE (SERVICE LIFE)	MOS	48	18-JUL-2006	SCRAP 18-JUL-2010	36 / 12.2	F6
26.180	REF: AMM 26-300	HRS/MSC AFL		5369.7 3562			
262281	REPLACE BAGGAGE COMPARTMENT RIGHT FIRE EXTINGUISHER NO. 2 CARTRIDGE (SERVICE LIFE)	MOS	48	04-NOV-2003	SCRAP 04-NOV-2007	3 / 44.67	F6
26.180	REF: AMM 26-300	HRS/MSC AFL					
262286	REPLACE BAGGAGE COMPARTMENT RIGHT FIRE EXTINGUISHER NO. 1 CARTRIDGE (LIFE LIMIT)	MOS	72	01-FEB-2005	LIFE LIMIT 01-FEB-2011	42 / 29.77	F6
26.180	REF: GENERIC NO REF	HRS/MSC AFL					
262291	REPLACE BAGGAGE COMPARTMENT RIGHT FIRE EXTINGUISHER NO. 2 CARTRIDGE (LIFE LIMIT)	MOS	72	01-SEP-2003	LIFE LIMIT 01-SEP-2009	25 / 46.77	F6
26.180	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262296	EXTINGUISHER:INSULATION TEST BAGGAGE COMPARTMENT RIGHT FIRE EXTINGUISHER SQUIBS	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F6
26.180	REF: AMM 26-270	HRS/MSC AFL	C/C				
+ 262316	EXTINGUISHER:HYDROSTATIC CHECK BAGGAGE COMPARTMENT LEFT FIRE EXTINGUISHER	MOS	60	15-JAN-2003	MANDATORY 15-JAN-2008	6 / 54.3	F6
26.210	REF: GENERIC NO REF	HRS/MSC AFL					
+ 262321	EXTINGUISHER:WEIGHT CHECK BAGGAGE COMPARTMENT LEFT FIRE EXTINGUISHER	MOS	12	06-MAR-2007	06-MAR-2008	7 / 4.6	F6
26.210	REF: AMM 26-350	HRS/MSC AFL					
262326	REPLACE BAGGAGE COMPARTMENT LEFT FIRE EXTINGUISHER CARTRIDGE (SERVICE LIMIT)	MOS	48	02-AUG-2002	SCRAP 02-AUG-2006	OVD / 59.73	F6
26.210	REF: See Workcard	HRS/MSC AFL					
262331	REPLACE BAGGAGE COMPARTMENT LEFT FIRE EXTINGUISHER CARTRIDGE (LIFE LIMIT)	MOS	72	01-MAY-2002	LIFE LIMIT 01-MAY-2008	9 / 62.77	F6
26.210	REF: GENERIC NO REF	HRS/MSC AFL					

Model : FALCON 50  
Owner : BENTLEY DOWNERS GROVE LUXURY  
Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 262336	EXTINGUISHER:INSULATION TEST	BAGGAGE	COMPARTMENT LEFT FIRE EXTINGUISHER										F6
26.210		MOS	12							06-MAR-2007	06-MAR-2008	7 / 4.6	
	REF: AMM 26-330	HRS/MSC	C/C										
		AFL											
262802	EXTINGUISHER:WEIGHT CHECK	COCKPIT HALON	EXTINGUISHER										F3
		MOS	6							10-APR-2007	10-OCT-2007	3 / 3.47	
	REF:	HRS/MSC								5665.4			
		AFL								3746			
262803	EXTINGUISHER:HYDROSTATIC TEST	COCKPIT HALON	EXTINGUISHER								MANDATORY		F3
		MOS	72							29-NOV-2004	29-NOV-2010	40 / 31.83	
	REF:	HRS/MSC								4906.8			
		AFL								3334			
262807	EXTINGUISHER:WEIGHT CHECK	LEFT FWD CABIN HALON	EXTINGUISHER										F4
		MOS	6							06-MAR-2007	06-SEP-2007	1 / 4.6	
	REF:	HRS/MSC											
		AFL											
262808	EXTINGUISHER:HYDROSTATIC TEST	LEFT FWD CABIN HALON	EXTINGUISHER								MANDATORY		F4
		MOS	72							30-DEC-2005	30-DEC-2011	53 / 18.8	
	REF:	HRS/MSC											
		AFL											
+ 262818	EXTINGUISHER:WEIGHT CHECK	RIGH FWD CABIN HALON	EXTINGUISHER										F4
		MOS	6							10-APR-2007	10-OCT-2007	3 / 3.47	
	REF:	HRS/MSC								5665.4			
		AFL								3746			
262819	EXTINGUISHER:HYDROSTATIC TEST	RIGH FWD CABIN HALON	EXTINGUISHER								MANDATORY		F4
		MOS	72							23-JAN-2003	23-JAN-2009	18 / 54.03	
	REF:	HRS/MSC											
		AFL											
<b>CHAPTER 27 FLIGHT CONTROLS</b>													
+ 271166	ACTUATOR:FUNCTIONAL CHECK (NORMAL)	AILERON TRIM	ACTUATOR										F3
27.100		MOS	144							29-NOV-2004	29-NOV-2016	112 / 31.83	
	REF: GENERIC NO REF	HRS/MSC								4906.8			
		AFL								3334			
+ 271176	FEEL UNIT:CHECK/GREASE	AILERON ARTIFICIAL FEEL UNIT	INTERNAL										F4
27.120		MOS	144							29-NOV-2004	29-NOV-2016	112 / 31.83	
	REF: AMM 27-320	HRS/MSC								4906.8			
		AFL								3334			
+ 271178	FEEL UNIT:BENCH CHECK	AILERON ARTIFICIAL FEEL UNIT											F4
27.120		MOS	144							29-NOV-2004	29-NOV-2016	112 / 31.83	
	REF: GENERIC NO REF	HRS/MSC								4906.8			
		AFL								3334			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp	(ENH) AFH			
+ 271206	ACTUATOR:FUNCTIONAL CHECK AILERON EMERGENCY ACTUATOR	MOS	144	29-NOV-2004	29-NOV-2016	112 / 31.83	W1
27.140	REF: GENERIC NO REF	HRS/MSC		4906.8			
		AFL		3334			
+ 271216	BELLCRANK:FUNCTIONAL CHECK VARIABLE RATIO (AMEDEE) BELLCRANK /GREASING/LUBRICATION	MOS	144	29-NOV-2004	29-NOV-2016	112 / 31.83	F4
27.150	REF: GENERIC NO REF	HRS/MSC		4906.8			
		AFL		3334			
+ 272109	SERVO UNIT:FUNCTIONAL TEST RUDDER SERVO UNIT (TIGHTNESS) CHECK VALVES AND GUST DAMPING VALVES (MANDATORY REF 5-40-00)	MOS	10000	14-DEC-1981	MANDATORY 5-40		F3
27.220	REF: GENERIC NO REF	HRS/MSC		0	10000	4260.80 / 5739.20	
		AFL		0			
+ 272123	FEEL UNIT:BENCH CHECK RUDDER ARTIFICIAL FEEL UNIT	MOS	144	11-NOV-2004	11-NOV-2016	112 / 32.43	F7
27.230	REF: GENERIC NO REF	HRS/MSC		4906.8			
		AFL		3334			
+ 272126	FEEL UNIT:CHECK RUDDER ARTIFICIAL FEEL UNIT INTERNAL LUBRICATION	MOS	144	11-NOV-2004	11-NOV-2016	112 / 32.43	F7
27.230	REF: See Workcard	HRS/MSC		4906.8			
		AFL		3334			
+ 272134	FEEL UNIT:BENCH CHECK RUDDER AUXILIARY ARTIFICIAL FEEL UNIT	MOS	144	29-NOV-2004	29-NOV-2016	112 / 31.83	T1
27.240	REF: GENERIC NO REF	HRS/MSC		4906.8			
		AFL		3334			
+ 272136	FEEL UNIT:CHECK RUDDER AUXILIARY ARTIFICIAL FEEL UNIT /INTERNAL LUBRICATION	MOS	144	29-NOV-2004	29-NOV-2016	112 / 31.83	F7
27.240	REF: See Workcard	HRS/MSC		4906.8			
		AFL		3334			
+ 272151	ACTUATOR:FUNCTIONAL TEST RUDDER TRIM ACTUATOR	MOS	144	29-NOV-2004	29-NOV-2016	112 / 31.83	F7
27.250	REF: GENERIC NO REF	HRS/MSC		4906.8			
		AFL		3334			
+ 273114	SERVO UNIT:FUNCTIONAL TEST ELEVATOR SERVO UNIT (TIGHTNESS) ELEVATOR SERVO CHECK VALVES (MANDATORY REF 5-40-00)	MOS	10000	14-DEC-1981	MANDATORY 5-40		F3
27.320	REF: GENERIC NO REF	HRS/MSC		0	10000	4260.80 / 5739.20	
		AFL		0			
+ 273136	FEEL UNIT:CHECK/INTERNAL LUBRICATION ELEVATOR ARTIFICIAL FEEL UNIT	MOS	144	29-NOV-2004	29-NOV-2016	112 / 31.83	F7
27.340	REF: See Workcard	HRS/MSC		4906.8			
		AFL		3334			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 273143	FEEL UNIT:BENCH TEST ELEVATOR	ARTIFICIAL	FEEL UNIT										F7
27.340		MOS	144							29-NOV-2004	29-NOV-2016	112 / 31.83	
	REF: GENERIC NO REF	HRS/MSC								4906.8			
		AFL								3334			
+ 274127	FUNCTIONAL TEST (MANDATORY REF 5-40-00)										MANDATORY 5-40		F3
27.460		MOS								31-MAR-2005			
	REF: See Workcard	HRS/MSC	5000							4911.1	9911.1	4171.90 / 828.10	
		AFL								3339			
+ 274157	FUNCTIONAL TEST HORIZONTAL STABILIZER RELAY BOX (MANDATORY REF 5-40-00)										MANDATORY 5-40		F3
27.490		MOS								31-MAR-2005			
	REF: See Workcard	HRS/MSC	5000							4911.1	9911.1	4171.90 / 828.10	
		AFL								3339			
274176	ACTUATOR:VISUAL CHECK HORIZONTAL STABILIZER ACTUATOR												
27.420		MOS	72							25-SEP-2006	25-SEP-2012	62 / 9.97	
	REF: See Workcard	HRS/MSC								5434.7			
		AFL	3750							3611	7361	3556 / 194	
274181	ACTUATOR:NDT INSPECT HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY)												
27.420		MOS	144							14-DEC-1981	14-DEC-1993	OVD / 307.33	
	REF: GENERIC NO REF	HRS/MSC								0			
	NEW REQUIREMENT ADDED. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.	AFL	7500							0	7500	3695 / 3805	
+ 276212	FUNCTIONAL TEST NORMAL AND STAND-BY CIRCUITS OF AIRBRAKES (MANDATORY REF 5-40-00)										MANDATORY 5-40		F3
27.760		MOS								31-MAR-2005			
	REF: See Workcard	HRS/MSC	10000							4911.1	14911.1	9171.90 / 828.10	
		AFL								3339			
+ 278134	VALVE:FUNCTIONAL CHECK SLAT SUPPLY SELECTOR VALVE												F5
27.810		MOS	144							29-NOV-2004	29-NOV-2016	112 / 31.83	
	REF: GENERIC NO REF	HRS/MSC								4906.8			
		AFL								3334			
+ 278291	VALVE:FUNCTIONAL TEST PITCH GUST VALVE (MANDATORY REF 5-40-00)										MANDATORY 5-40		F3
27.960		MOS								14-DEC-1981			
	REF: GENERIC NO REF	HRS/MSC	10000							0	10000	4260.80 / 5739.20	
		AFL								0			
<b>CHAPTER 28 FUEL</b>													
281286	PUMP:REPLACE NO. 1 TRANSFER PUMP MOTOR BRUSHES												F5
28.270		MOS								23-JAN-2002			
	REF: GENERIC NO REF	HRS/MSC	2000							4015	6015	275.80 / 1724.20	
		AFL								2877			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL						COMPLIANCE	DISPOSITION	Time	AREA
WORKCARD	PART#/PKG SERIAL #			TSN	TSO	TSR	TSI	ADJ	Warr Exp	NEXT DUE ( ENH ) AFH	Remaining / Total Time	PRICE LABOR HRS
281296	PUMP:REPLACE NO. 1 TRANSFER PUMP BEARINGS	MOS								23-JAN-2002		F5
28.270		HRS/MSC	2000							4015	275.80 / 1724.20	
	REF: GENERIC NO REF	AFL								2877		
281311	PUMP:REPLACE NO. 2 TRANSFER PUMP MOTOR BRUSHES	MOS								20-APR-2001		F5
28.280		HRS/MSC	2000							3473	OVD / 2266.20	
	REF: GENERIC NO REF	AFL								2450		
281321	PUMP:REPLACE NO. 2 TRANSFER PUMP BEARINGS	MOS								20-APR-2001		F5
28.280		HRS/MSC	2000							3473	OVD / 2266.20	
	REF: GENERIC NO REF	AFL								2450		
281336	PUMP:REPLACE NO. 3 TRANSFER PUMP MOTOR BRUSHES	MOS								28-AUG-2001		F5
28.290		HRS/MSC	2000							3698	OVD / 2041.20	
	REF: GENERIC NO REF	AFL								2642		
281346	PUMP:REPLACE NO. 3 TRANSFER PUMP BEARINGS	MOS								28-AUG-2001		F5
28.290		HRS/MSC	2000							3698	OVD / 2041.20	
	REF: GENERIC NO REF	AFL								2642		
281361	VALVE:LEFT FEEDER TANK TRANSFER VALVE	MOS	108							23-JAN-2002		F5
28.240	2504-3	HRS/MSC	4800		0					4015	42 / 66.03	
	1450	AFL			0					8815	3075.80 / 1724.20	
	REF: See Workcard	AFL			0					2877		
281371	VALVE:CENTER FEEDER TANK TRANSFER VALVE	MOS	108							23-JAN-2002		F5
28.240	2504-3	HRS/MSC	4800		0					4015	42 / 66.03	
	1131	AFL			0					8815	3075.80 / 1724.20	
	REF: See Workcard	AFL			0					2877		
281381	VALVE:RIGHT FEEDER TANK TRANSFER VALVE	MOS	108							23-JAN-2002		F5
28.240	2504-3	HRS/MSC	4800		0					4015	42 / 66.03	
	748	AFL			0					8815	3075.80 / 1724.20	
	REF: AMM 28-070	AFL			0					2877		
+ 281517	VALVE:FLOW RATE/FALL TEST LEFT WING VACUUM PRESSURE RELIEF VALVE	MOS								28-APR-1993		W1
28.420		HRS/MSC	4800							765	OVD / 4974.20	
	REF: GENERIC NO REF	AFL								491		
+ 281518	VALVE:SEALING TEST LEFT WING VACUUM PRESSURE RELIEF VALVE	MOS								28-APR-1993		W1
28.420		HRS/MSC	4800							765	OVD / 4974.20	
	REF: GENERIC NO REF	AFL								491		

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp	( ENH ) AFH			
+ 281522	VALVE:FLOW RATE/FALL TEST RIGHT WING VACUUM PRESSURE RELIEF VALVE	MOS		28-APR-1993			W2
28.420		HRS/MSC	4800	765	5565	OVD / 4974.20	
	REF: GENERIC NO REF	AFL		491			
+ 281523	VALVE:SEALING TEST RIGHT WING VACUUM PRESSURE RELIEF VALVE	MOS		28-APR-1993			W2
28.420		HRS/MSC	4800	765	5565	OVD / 4974.20	
	REF: GENERIC NO REF	AFL		491			
+ 281537	VALVE BOX:CALIBRATION CHECK LEFT VALVE BOX	MOS		09-JAN-2002			F5
28.440		HRS/MSC	4000	3992	7992	2252.80 / 1747.20	
	REF: GENERIC NO REF	AFL		2862			
281538	VALVE BOX:CLEAN LEFT VALVE BOX FILTER	MOS		09-JAN-2002			F5
28.440		HRS/MSC	4000	3992	7992	2252.80 / 1747.20	
	REF: GENERIC NO REF	AFL		2862			
+ 281543	VALVE BOX:CALIBRATION CHECK RIGHT VALVE BOX	MOS		09-JAN-2002			F5
28.440		HRS/MSC	4000	3992	7992	2252.80 / 1747.20	
	REF: GENERIC NO REF	AFL		2862			
281544	VALVE BOX:CLEAN RIGHT VALVE BOX FILTER	MOS		09-JAN-2002			F5
28.440		HRS/MSC	4000	3992	7992	2252.80 / 1747.20	
	REF: GENERIC NO REF	AFL		2862			
281601	HOSE:LEFT FEEDER TANK SOLENOID/TRANSFER VALVE HOSE	MOS	144	29-NOV-2004	SCRAP		F5
28.470	71029-380A	HRS/MSC	0	4906.8	29-NOV-2016	112 / 31.83	
	685000	AFL	0	3334			
	REF: GENERIC NO REF						
281606	HOSE:CENTER FEEDER TANK SOLENOID/TRANSFER VALVE HOSE	MOS	144	29-NOV-2004	SCRAP		F5
28.475	71029-420A	HRS/MSC	0	4906.8	29-NOV-2016	112 / 31.83	
	66458	AFL	0	3334			
	REF: GENERIC NO REF						
281611	HOSE:RIGHT FEEDER TANK SOLENOID/TRANSFER VALVE HOSE	MOS	144	29-NOV-2004	SCRAP		F5
28.470	71029-380A	HRS/MSC	0	4906.8	29-NOV-2016	112 / 31.83	
	68501	AFL	0	3334			
	REF: GENERIC NO REF						
281616	HOSE:LEFT FEEDER TANK REGULATION VALVE SUPPLY HOSE	MOS	144	29-NOV-2004	SCRAP		F5
28.480	71029-1020A	HRS/MSC	0	4906.8	29-NOV-2016	112 / 31.83	
	69291	AFL	0	3334			
	REF: GENERIC NO REF						

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp	( ENH ) AFH			
281621	HOSE:CENTER FEEDER TANK REGULATION/TRANSFER VALVE SPLY HOSE				SCRAP		F5
28.490	71029-560A 68643 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
281626	HOSE:CENTER FEEDER TANK REGULATION VALVE SUPPLY HOSE				SCRAP		F5
28.485	71029-450A 68405 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
281631	HOSE:RIGHT FEEDER TANK REGULATION VALVE SUPPLY HOSE				SCRAP		F5
28.480	71029-1020A 69290 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
281636	HOSE:LEFT FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE				SCRAP		F5
28.500	71028-610A 68723 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
281641	HOSE:RIGHT FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE				SCRAP		F5
28.500	71028-610A 68724 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
281646	HOSE:LEFT FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE				SCRAP		F5
28.510	71028-1290A 70264 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
281651	HOSE:CENTER FEEDER TANK LEVEL/VALVE SUPPLY HOSE				SCRAP		F5
28.515	71028-2460A 67516 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
281656	HOSE:RIGHT FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE				SCRAP		F5
28.510	71028-1290A 70263 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 0 0	29-NOV-2004 4906.8 3334	29-NOV-2016	112 / 31.83	
+ 282001	MANIFOLD:CHECK LEFT FEEDER TANK MANIFOLD LEFT LOW PRESSURE INTERCONNECTION VALVE FITTINGS						F5
28.550	MOS HRS/MSC REF: GENERIC NO REF		10000	14-DEC-1981 0 0	10000	4260.80 / 5739.20	
+ 282006	MANIFOLD:CHECK RIGHT FEEDER TANK MANIFOLD RIGHT LOW PRESSURE INTERCONNECTION VALVE FITTINGS						F5
28.550	MOS HRS/MSC REF: GENERIC NO REF		10000	14-DEC-1981 0 0	10000	4260.80 / 5739.20	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 282016	VALVE:SEALING TEST LEFT FUEL FIRE SHUT-OFF VALVE	MOS								29-NOV-2004			F5
28.570		HRS/MSC	1530/E/C							4906.8	6436.8	697.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 282017	VALVE:SEALING TEST LEFT FUEL FIRE SHUT-OFF VALVE (MANDATORY REF 5-40-00)	MOS								29-NOV-2004	MANDATORY 5-40		F5
28.570		HRS/MSC	1530							4906.8	6436.8	697.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 282036	VALVE:SEALING TEST MIDDLE FUEL FIRE SHUT-OFF VALVE	MOS								29-NOV-2004			F5
28.580		HRS/MSC	1530/E/C							4906.8	6436.8	697.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 282037	VALVE:SEALING TEST MIDDLE FUEL FIRE SHUT-OFF VALVE (MANDATORY REF 5-40-00)	MOS								29-NOV-2004	MANDATORY 5-40		F5
28.580		HRS/MSC	1530							4906.8	6436.8	697.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 282056	VALVE:SEALING TEST RIGHT FUEL FIRE SHUT-OFF VALVE	MOS								29-NOV-2004			F5
28.590		HRS/MSC	1530/E/C							4906.8	6436.8	697.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 282057	VALVE:SEALING TEST RIGHT FUEL FIRE SHUT-OFF VALVE (MANDATORY REF 5-40-00)	MOS								29-NOV-2004	MANDATORY 5-40		F5
28.590		HRS/MSC	1530							4906.8	6436.8	697.60 / 832.40	
	REF: See Workcard	AFL								3334			
+ 282102	MANIFOLD:CHECK LEFT FEEDER TANK MANIFOLD LEFT THERMAL EXPANSION VALVE FOR SEIZING	MOS								14-DEC-1981			F5
28.550		HRS/MSC	10000							0	10000	4260.80 / 5739.20	
	REF: GENERIC NO REF	AFL								0			
+ 282107	MANIFOLD:CHECK RIGHT FEEDER TANK MANIFOLD RIGHT THERMAL EXPANSION VALVE FOR SEIZING	MOS								14-DEC-1981			F5
28.550		HRS/MSC	10000							0	10000	4260.80 / 5739.20	
	REF: GENERIC NO REF	AFL								0			
282242	CABLE:SERVICE NO. 1 SHUT-OFF VALVE CABLE (MANDATORY REF 5-40-00)	MOS								10-APR-2007	MANDATORY 5-40		F3
28.650		HRS/MSC	330							5665.4	5995.4	256.20 / 73.80	
	REF: See Workcard	AFL								3746			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
282267	CABLE:SERVICE NO. 2 SHUT-OFF VALVE CABLE (MANDATORY REF 5-40-00)										MANDATORY 5-40		F3
28.660	REF: See Workcard	MOS HRS/MSC AFL	330							10-APR-2007 5665.4 3746	5995.4	256.20 / 73.80	
282292	CABLE:SERVICE NO. 3 SHUT-OFF VALVE CABLE (MANDATORY REF 5-40-00)										MANDATORY 5-40		F3
28.670	REF: See Workcard	MOS HRS/MSC AFL	330							10-APR-2007 5665.4 3746	5995.4	256.20 / 73.80	
282601	HOSE:LEFT FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE										SCRAP 29-NOV-2016	112 / 31.83	F5
28.520	71030-496A 68054 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	0						29-NOV-2004 4906.8 3334			
282606	HOSE:CENTER FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE										SCRAP 29-NOV-2016	112 / 31.83	F5
28.525	71030-676A 69061 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	0						29-NOV-2004 4906.8 3334			
282611	HOSE:RIGHT FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE										SCRAP 29-NOV-2016	112 / 31.83	F5
28.520	71030-496A 68053 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	0						29-NOV-2004 4906.8 3334			
282706	HOSE:NO. 1 ENGINE FUEL SUPPLY HOSE										SCRAP 29-NOV-2016	112 / 31.83	E1
28.530	665106EE2001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	144	0						29-NOV-2004 4906.8 3334			
282708	HOSE:NO. 2 ENGINE FUEL SUPPLY HOSE										SCRAP 29-NOV-2016	112 / 31.83	E2
28.535	665054EE2004 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	144	0						29-NOV-2004 4906.8 3334			
282711	HOSE:NO. 3 ENGINE FUEL SUPPLY HOSE										SCRAP 29-NOV-2016	112 / 31.83	E3
28.530	66510EE2001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	144	0						29-NOV-2004 4906.8 3334			
<b>CHAPTER 29 HYDRAULIC POWER</b>													
291101	PUMP:NO. 1 HYDRAULIC PUMP										OVERHAUL		E1
29.030	PVB022-2 MX381335H REF: See Workcard	MOS HRS/MSC AFL	4000		0					30-OCT-2001 3846 2751	7846	2106.80 / 1893.20	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE						DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ	Warr Exp			
WORKCARD	PART#/PKG SERIAL #								( ENH ) AFH			
291111	PUMP:NO. 2 HYDRAULIC PUMP								OVERHAUL		E2	
29.040	PVB022-2 MX360069H REF: See Workcard	MOS HRS/MSC AFL	4000		0				30-OCT-2001 3846 2751	7846	2106.80 / 1893.20	
291121	PUMP:NO. 3 HYDRAULIC PUMP								OVERHAUL		E3	
29.050	PV3022-2 MX600496H REF: See Workcard	MOS HRS/MSC AFL	4000		0				02-JUN-2000 2690 1894	6690	950.80 / 3049.20	
291163	VALVE:REPLACE HYDRAULIC RESERVOIR AIR PRESSURE REDUCING VALVE DIAPHRAGM								24-JAN-2001	24-JAN-2007	OVD / 78	F7
29.090		MOS HRS/MSC AFL	72						3255 2299			
+ 291164	VALVE:FUNCTIONAL TEST HYDRAULIC RESERVOIR AIR PRESSURE REDUCING VALVE								24-JAN-2001	24-JAN-2007	OVD / 78	F7
29.090		MOS HRS/MSC AFL	72						3255 2299			
291165	VALVE:CLEAN HYDRAULIC RESERVOIR AIR PRESSURE REDUCING VALVE FILTER								29-NOV-2004	29-NOV-2008	16 / 31.83	
29.090		MOS HRS/MSC AFL	48						4906.8 3334			
+ 292126	PUMP-MOTOR:CHECK HYDRAULIC ELECTRO- PUMP-MOTOR BRUSHES								16-JAN-2004			F7
29.300		MOS HRS/MSC AFL	2400						4727.7 3233	7127.7	1388.50 / 1011.50	
+ 292131	PUMP:FUNCTIONAL CHECK HYDRAULIC ELECTRO- PUMP								18-JAN-2002			F7
29.300		MOS HRS/MSC AFL	4800						4004 2873	8804	3064.80 / 1735.20	
<b>CHAPTER 30 ICE AND RAIN PROTECTION</b>												
301121	COUPLING:LEAK TEST LEFT OUTBOARD SLAT TELESCOPIC COUPLING AND SWIVELING TORQUE MEASUREMENT								22-MAR-2006	22-MAR-2007	OVD / 16.07	W1
30.020		MOS HRS/MSC AFL	12						5273.4 3520			
301136	COUPLING:LEAK TEST LEFT INBOARD SLAT TELESCOPIC COUPLING AND SWIVELING TORQUE MEASUREMENT								10-APR-2007	10-APR-2008	9 / 3.47	W1
30.030		MOS HRS/MSC AFL	12						5665.4 3746			
301151	COUPLING:LEAK TEST RIGHT OUTBOARD SLAT TELESCOPIC COUPLING AND SWIVELING TORQUE MEASUREMENT								10-APR-2007	10-APR-2008	9 / 3.47	W2
30.020		MOS HRS/MSC AFL	12						5665.4 3746			

Model : FALCON 50  
Owner : BENTLEY DOWNERS GROVE LUXURY  
Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
301166	COUPLING:LEAK TEST RIGHT INBOARD SLAT TELESCOPIC COUPLING AND SWIVELING TORQUE MEASUREMENT	MOS	12	10-APR-2007	10-APR-2008	9 / 3.47	W2
30.030	REF: See Workcard	HRS/MSC AFL		5665.4 3746			
+ 302136	VALVE:FUNCTIONAL TEST NO. 2 ENGINE "S" DUCT ANTI-ICING VALVE	MOS		16-JAN-2004			E2
30.060	REF: GENERIC NO REF	HRS/MSC AFL	4000	4727.7 3233	8727.7	2988.50 / 1011.50	
+ 302171	VALVE:FUNCTIONAL TEST NO. 1 ENGINE AIR INTAKE ANTI-ICING VALVE	MOS		16-JAN-2004			E1
30.070	REF: GENERIC NO REF	HRS/MSC AFL	4000	4727.7 3233	8727.7	2988.50 / 1011.50	
+ 302181	VALVE:FUNCTIONAL TEST NO. 2 ENGINE AIR INTAKE ANTI-ICING VALVE	MOS		16-JAN-2004			E2
30.060	REF: GENERIC NO REF	HRS/MSC AFL	4000	4727.7 3233	8727.7	2988.50 / 1011.50	
+ 302191	VALVE:FUNCTIONAL TEST NO. 3 ENGINE AIR INTAKE ANTI-ICING VALVE	MOS		16-JAN-2004			E3
30.070	REF: GENERIC NO REF	HRS/MSC AFL	4000	4727.7 3233	8727.7	2988.50 / 1011.50	
+ 304106	MOTOR:CHECK/REPLACE PILOT WINDSHIELD WIPER MOTOR BRUSHES	MOS		14-DEC-1981			F3
30.110	REF: See Workcard	HRS/MSC AFL	10000	0 0	10000	4260.80 / 5739.20	
+ 304116	MOTOR:CHECK/REPLACE COPILOT WINDSHIELD WIPER MOTOR BRUSHES	MOS		14-DEC-1981			F3
30.110	REF: See Workcard	HRS/MSC AFL	10000	0 0	10000	4260.80 / 5739.20	
<b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b>							
+ 316016	CONTACT:FUNCTIONAL TEST COCKPIT VOICE RECORDER ACCELERATION CONTACT	MOS	24	25-SEP-2006	25-SEP-2008	14 / 9.97	
31.120	REF: See Workcard	HRS/MSC AFL		5434.7 3611			
316021	BEACON:COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON	MOS	72	09-MAR-2002	OVERHAUL 09-MAR-2008	8 / 64.5	
31.100	REF: GENERIC NO REF	HRS/MSC AFL		4100 2930			
+ 316026	BEACON:FUNCTIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON	MOS	24	11-JUL-2006	11-JUL-2008	12 / 12.43	
31.100	REF: See Workcard	HRS/MSC AFL		5352.4 3560			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
316031	BEACON:REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY	MOS		11-JUL-2006	<b>SCRAP</b>	61 / 12.43	
31.100		HRS/MSC	DUE	5352.4	<b>01-SEP-2012 M</b>		
	REF: GENERIC CMM	AFL		3560			
+ 316036	BEACON:CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON	MOS	24	11-JUL-2006	<b>11-JUL-2008</b>	12 / 12.43	
31.100		HRS/MSC		5352.4			
	REF: GENERIC CMM	AFL		3560			
316041	BEACON:RECERTIFY COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON	MOS	216	13-AUG-1998	<b>13-AUG-2016</b>	109 / 107.37	
31.100		HRS/MSC		1792			
	REF: GENERIC NO REF	AFL		1233			
<b>CHAPTER 32 LANDING GEAR</b>							
+ 320021	LANDING GEAR:DIMENSIONAL CHECK NOSE LANDING GEAR AND CHECK FOR CORROSION	MOS	72	29-NOV-2004	<b>29-NOV-2010</b>	40 / 31.83	L3
32.920		HRS/MSC		4906.8			
	REF: See Workcard	AFL		3334			
+ 320026	LANDING GEAR:DIMENSIONAL CHECK LEFT MAIN LANDING GEAR AND CHECK FOR CORROSION	MOS	72	29-NOV-2004	<b>29-NOV-2010</b>	40 / 31.83	L1
32.930		HRS/MSC		4906.8			
	REF: See Workcard	AFL		3334			
+ 320031	LANDING GEAR:DIMENSIONAL CHECK RIGHT MAIN LANDING GEAR AND CHECK FOR CORROSION	MOS	72	29-NOV-2004	<b>29-NOV-2010</b>	40 / 31.83	L2
32.930		HRS/MSC		4906.8			
	REF: See Workcard	AFL		3334			
321101	LANDING GEAR:LEFT MAIN LANDING GEAR	MOS		29-NOV-2004	<b>LIFE LIMIT</b>		L1
32.010	C23791-1009	HRS/MSC		4906.8			
	U205	AFL	20000	3334	<b>19847</b>	16042 / 3958	
	REF: See Workcard		3487				
321102	END-FITTING:LEFT MAIN LANDING GEAR SHOCK ABSORBER END-FITTING	MOS	144	29-NOV-2004	<b>OVERHAUL</b>		L1
32.020	D53360	HRS/MSC		4906.8	<b>29-NOV-2016</b>	112 / 31.83	
	29A	AFL	6000	3334	<b>9334</b>	5529 / 3958	
	REF: GENERIC NO REF		3487				
321103	SHOCK ABSORBER:LEFT MAIN LANDING GEAR SHOCK ABSORBER	MOS	144	29-NOV-2004	<b>OVERHAUL</b>		L1
32.020	C23975-1007	HRS/MSC		4906.8	<b>29-NOV-2016</b>	112 / 31.83	
	U213	AFL	6000	3334	<b>9334</b>	5529 / 471	
	REF: See Workcard		0				
321104	SLEEVE:LEFT MAIN LANDING GEAR ACTUATOR STRUT DASH-POT SLEEVE	MOS		29-NOV-2004	<b>LIFE LIMIT</b>		L1
32.040	C23791-1009	HRS/MSC		4906.8			
	U205	AFL	20000	3334	<b>19847</b>	16042 / 3958	
	REF: GENERIC NO REF		3487				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
Owner : BENTLEY DOWNERS GROVE LUXURY  
Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #										NEXT DUE (ENH) AFH		
321105	END-FITTING:REPLACE LEFT MAIN LANDING GEAR SHOCK ABSORBER END-FITTING (MANDATORY REF 5-40-00)	MOS								29-NOV-2004	LIFE LIMIT		L1
32.020		HRS/MSC								4906.8			
	REF: GENERIC NO REF	AFL	20000				3487			3334	19847	16042 / 471	
321106	LANDING GEAR:RIGHT MAIN LANDING GEAR	MOS								29-NOV-2004	LIFE LIMIT		L2
32.010	C23792-1009	HRS/MSC								4906.8			
	U205	AFL	20000	3487						3334	19847	16042 / 3958	
	REF: See Workcard												
321107	END-FITTING:RIGHT MAIN LANDING GEAR SHOCK ABSORBER END-FITTING	MOS	144		0					17-FEB-1993	OVERHAUL	OVD / 173.23	L2
32.030	D50493	HRS/MSC			0					765	17-FEB-2005		
	SN-UNKNOWN	AFL	6000		0					491	6491	2686 / 3314	
	REF: GENERIC NO REF												
321108	SHOCK ABSORBER:RIGHT MAIN LANDING GEAR SHOCK ABSORBER	MOS	144		0					29-NOV-2004	OVERHAUL	112 / 31.83	L2
32.030	C23796-1007	HRS/MSC			0					4906.8	29-NOV-2016		
	U213	AFL	6000		0					3334	9334	5529 / 471	
	REF: See Workcard												
321109	SLEEVE:RIGHT MAIN LANDING GEAR STRUT ACTUATOR DASH-POT SLEEVE	MOS								29-NOV-2004	LIFE LIMIT		L2
32.050	C23792-1009	HRS/MSC								4906.8			
	U205	AFL	20000	3487						3334	19847	16042 / 3958	
	REF: GENERIC NO REF												
321110	END-FITTING:REPLACE RIGHT MAIN LANDING GEAR SHOCK ABSORBER END-FITTING (MANDATORY REF 5-40-00)	MOS								14-DEC-1981	LIFE LIMIT		L2
32.030		HRS/MSC								0			
	REF: GENERIC NO REF	AFL	20000							0	20000	16195 / 3805	
321117	SHAFT:LEFT REAR MAIN LANDING GEAR BEARING SHAFT	MOS								17-FEB-1993	LIFE LIMIT		L1
32.060	D52554-1	HRS/MSC		765						765			
	SN-UNKNOWN	AFL	18670	491						491	18670	14865 / 3805	
	REF: GENERIC NO REF												
321118	SHAFT:RIGHT REAR MAIN LANDING GEAR BEARING SHAFT	MOS								17-FEB-1993	LIFE LIMIT		L2
32.070	D52554-1	HRS/MSC		765						765			
	SN-UNKNOWN	AFL	18670	491						491	18670	14865 / 3805	
	REF: GENERIC NO REF												
321119	BARREL:LEFT MAIN LANDING GEAR BARREL	MOS	144		0					29-NOV-2004	OVERHAUL	112 / 31.83	L1
32.020	C23793	HRS/MSC			0					4906.8	29-NOV-2016		
	U205	AFL	6000		0					3334	9334	5529 / 471	
	REF: GENERIC NO REF												
321120	BARREL:RIGHT MAIN LANDING GEAR BARREL	MOS	144		0					29-NOV-2004	OVERHAUL	112 / 31.83	L2
32.030	C23794-1005	HRS/MSC			0					4906.8	29-NOV-2016		
	U205	AFL	6000		0					3334	9334	5529 / 471	
	REF: GENERIC NO REF												

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
322101	LANDING GEAR:NOSE LANDING GEAR C23787-1007	MOS								29-NOV-2004	LIFE LIMIT		L3
32.180	U231 REF: See Workcard	HRS/MSC AFL	20000	3487						4906.8 3334	19847	16042 / 3958	
322103	SHOCK ABSORBER:NOSE LANDING GEAR SHOCK ABSORBER C23789-1003	MOS	144		0					29-NOV-2004	OVERHAUL 29-NOV-2016	112 / 31.83	L3
32.190	U239 REF: See Workcard	HRS/MSC AFL	6000		0					4906.8 3334	9334	5529 / 471	
322104	BARREL:NOSE LANDING GEAR BARREL C23788-1006	MOS	144		0					29-NOV-2004	OVERHAUL 29-NOV-2016	112 / 31.83	L3
32.190	U231 REF: GENERIC NO REF	HRS/MSC AFL	6000		0					4906.8 3334	9334	5529 / 471	
322112	YOKE ASSEMBLY:NOSE LANDING GEAR TELESCOPIC STRUT YOKE ASSEMBLY GA58346	MOS	144		0					29-NOV-2004	OVERHAUL 29-NOV-2016	112 / 31.83	L3
32.210	46 REF: GENERIC NO REF	HRS/MSC AFL	6000		0					4906.8 3334	9334	5529 / 471	
324306	VALVE:LEFT ANTI-SKID SERVO VALVE 9542732-2	MOS	300	0						14-DEC-1981	OVERHAUL 14-DEC-2006	OVD / 307.33	L1
32.600	JAN81-1729 REF: GENERIC NO REF	HRS/MSC AFL		0						0 0			
324311	VALVE:RIGHT ANTI-SKID SERVO VALVE 9542732-2	MOS	300		0					07-MAY-2002	OVERHAUL 07-MAY-2027	237 / 62.57	L2
32.600	MAY81-1775D REF: GENERIC NO REF	HRS/MSC AFL			0					4117 2944			
<b>CHAPTER 33 LIGHTS</b>													
+ 332111	UNIT:FUNCTIONAL TEST LEFT EMERGENCY LIGHTING (114L1) UNIT	MOS	12							25-SEP-2006	25-SEP-2007	2 / 9.97	F4
33.100	REF: See Workcard	HRS/MSC AFL								5434.7 3611			
332121	UNIT:FUNCTIONAL TEST RIGHT EMERGENCY LIGHTING (114L2) UNIT	MOS	12							25-SEP-2006	25-SEP-2007	2 / 9.97	
33.110	REF: AMM 33-501	HRS/MSC AFL								5434.7 3611			
332131	UNIT:FUNCTIONAL TEST FRONT EMERGENCY LIGHTING (113L) UNIT	MOS	12							25-SEP-2006	25-SEP-2007	2 / 9.97	
33.120	REF: AMM 33-501	HRS/MSC AFL								5434.7 3611			
335103	UNIT:SERVICE LEFT EMERGENCY LIGHTING (114L1) UNIT	MOS	12							11-JUL-2006	11-JUL-2007	0 / 12.43	
33.100	REF: See Workcard	HRS/MSC AFL								5352.4 3560			

Model : FALCON 50  
Owner : BENTLEY DOWNERS GROVE LUXURY  
Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
335113	UNIT:SERVICE RIGHT EMERGENCY LIGHTING (114L2) UNIT	MOS	12							11-JUL-2006	11-JUL-2007	0 / 12.43	
33.110		HRS/MSC								5352.4			
	REF: See Workcard	AFL								3560			
335133	UNIT:SERVICE FRONT EMERGENCY LIGHTING (113L) UNIT	MOS	12							11-JUL-2006	11-JUL-2007	0 / 12.43	
33.120		HRS/MSC								5352.4			
	REF: See Workcard	AFL								3560			
<b>CHAPTER 34 NAVIGATION</b>													
341013	CHANGE:CALIBRATE STAND-BY AIRSPEED INDICATOR CHANGE	MOS	24							10-DEC-2003	CALIBRATE 10-DEC-2005	OVD / 43.47	
	REF:	AFL											
+ 341125	ALTIMETER:TEST PILOT ALTIMETER (FAR 91.411)	MOS	24							06-MAY-2005	MANDATORY 06-MAY-2007	OVD / 26.6	F3
34.040		HRS/MSC											
	REF: FAR 91.411	AFL											
+ 341130	ALTIMETER:TEST COPILOT ALTIMETER (FAR 91.411)	MOS	24							06-MAY-2005	MANDATORY 06-MAY-2007	OVD / 26.6	F3
34.040		HRS/MSC											
	REF: FAR 91.411	AFL											
+ 342040	BATTERY:VOLTAGE TEST STANDBY HORIZON (POWER SUPPLY 23F) BATTERY	MOS	3							10-APR-2007	10-JUL-2007	0 / 3.47	F2
34.380		HRS/MSC	100							5665.4	5765.4	26.20 / 73.80	
	REF: See Workcard	AFL								3746			
+ 342254	COMPUTER:TEST PILOT AIR DATA COMPUTER (FAR 91.411)	MOS	24							06-MAY-2005	MANDATORY 06-MAY-2007	OVD / 26.6	F2
34.510		HRS/MSC											
	REF: FAR 91.411	AFL											
+ 342259	ALTIMETER:TEST STAND BY ALTIMETER (FAR 91.411)	MOS	24							06-MAY-2005	MANDATORY 06-MAY-2007	OVD / 26.6	F3
34.530		HRS/MSC											
	REF: FAR 91.411	AFL											
+ 342292	COMPUTER:OPERATIONAL TEST COPILOT AIR DATA COMPUTER	MOS	6							10-APR-2007	10-OCT-2007	3 / 3.47	F2
34.520	PKG 1,2,22,9	HRS/MSC	300							5665.4	5965.4	226.20 / 73.80	
	REF: See Workcard	AFL								3746			
+ 342293	COMPUTER:TEST COPILOT AIR DATA COMPUTER (FAR 91.411)	MOS	24							06-MAY-2005	MANDATORY 06-MAY-2007	OVD / 26.6	F2
34.520		HRS/MSC											
	REF: FAR 91.411	AFL											

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 345191	TRANSPONDER:TEST NO. 1 ATC	TRANSPONDER	(FAR 91.413)										
34.820		MOS 24								06-MAY-2005	<b>MANDATORY</b> 06-MAY-2007	OVD / 26.6	F4
	REF: FAR 91.413	HRS/MSC AFL											
+ 345216	TRANSPONDER:TEST NO. 2 ATC	TRANSPONDER	(FAR 91.413)										
34.820		MOS 24								06-MAY-2005	<b>MANDATORY</b> 06-MAY-2007	OVD / 26.6	F4
	REF: FAR 91.413	HRS/MSC AFL											
345331	TRANSPONDER:FUNCTIONAL TEST NO. 1 ATC	TRANSPONDER											
34.820		MOS 24								06-MAY-2005	<b>06-MAY-2007</b>	OVD / 26.6	
	REF: See Workcard	HRS/MSC AFL											
345332	TRANSPONDER:FUNCTIONAL TEST NO. 2 ATC	TRANSPONDER											
34.820		MOS 24								06-MAY-2005	<b>06-MAY-2007</b>	OVD / 26.6	
	REF: See Workcard	HRS/MSC AFL											
+ 346021	BATTERY:RECONDITION/SERVICE	INS BATTERY											
34.890		MOS 12								09-APR-2007	<b>09-APR-2008</b>	9 / 3.5	F7
	REF: See Workcard	HRS/MSC AFL								5665.4 3746			
<b>CHAPTER 35 OXYGEN</b>													
350101	CYLINDER:OXYGEN CYLINDER												
35.020	6084A33-UUUC	MOS 288	121							26-AUG-1999	<b>LIFE LIMIT</b> 26-JUL-2013	72 / 215.93	F4
	921835	HRS/MSC AFL								2311 1616			
+ 350106	CYLINDER:HYDROSTATIC TEST	OXYGEN CYLINDER											
35.020		MOS 36								31-MAR-2005	<b>MANDATORY</b> 31-MAR-2008	8 / 27.77	F4
	REF: GENERIC NO REF	HRS/MSC AFL								4911.1 3339			
350121	VALVE:OXYGEN PRESSURE REDUCING VALVE												
35.060	RDN1000	MOS 72			0					01-AUG-2002	<b>OVERHAUL</b> 01-AUG-2008	12 / 59.77	F4
	386	HRS/MSC AFL			0					4191.1 2986			
	REF: GENERIC NO REF				0								
351101	MASK:PILOT OXYGEN MASK												
35.080	MA1012-00	MOS 72			0					29-NOV-2004	<b>OVERHAUL</b> 29-NOV-2010	40 / 31.83	F3
	S18519	HRS/MSC AFL			0					4906.8 3334			
	REF: GENERIC NO REF				0								
351104	MASK:OPERATIONAL TEST PILOT OXYGEN MASK												
35.080		MOS 36								29-NOV-2004	<b>29-NOV-2007</b>	4 / 31.83	F3
	REF: See Workcard	HRS/MSC AFL								4906.8 3334			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE					DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
WORKCARD	PART#/PKG SERIAL #										
351126	MASK:COPILOT OXYGEN MASK										
35.080	MA1012-00 3175 REF: GENERIC NO REF	MOS HRS/MSC AFL	72		0			24-JAN-2001 3255 2299	OVERHAUL 24-JAN-2007 OVD / 78	F3	
351129	MASK:OPERATIONAL TEST COPILOT OXYGEN MASK										
35.080		MOS HRS/MSC AFL	36					29-NOV-2004 4906.8 3334	29-NOV-2007 4 / 31.83	F3	
	REF: See Workcard										
351151	VALVE:ALTITUDE VALVE										
35.100	RCA70 990 REF: GENERIC NO REF	MOS HRS/MSC AFL	72		0			29-NOV-2004 4906.8 3334	OVERHAUL 29-NOV-2010 40 / 31.83	F3	
+ 353106	CYLINDER:OVERHAUL FIRST AID OXYGEN CYLINDER										
35.160		MOS HRS/MSC AFL	60					18-FEB-2004	MANDATORY 18-FEB-2009 19 / 41.2	F4	
	REF: GENERIC NO REF										
<b>CHAPTER 36 PNEUMATIC</b>											
361103	PIPE:REPLACE NO. 1 ENGINE EXPANSION PIPE LININGS										
36.010		MOS HRS/MSC AFL	4000					09-JAN-2002 3992 2862	7992 2252.80 / 1747.20	E1	
	REF: GENERIC NO REF										
+ 361105	PIPE:LEAK TEST NO. 1 ENGINE EXPANSION PIPE										
36.010		MOS HRS/MSC AFL	4000					09-JAN-2002 3992 2862	7992 2252.80 / 1747.20	E1	
	REF: GENERIC NO REF										
361108	PIPE:REPLACE NO. 2 ENGINE EXPANSION PIPE LININGS										
36.020		MOS HRS/MSC AFL	4000					09-JAN-2002 3992 2862	7992 2252.80 / 1747.20	E2	
	REF: GENERIC NO REF										
+ 361110	PIPE:LEAK TEST NO. 2 ENGINE EXPANSION PIPE										
36.020		MOS HRS/MSC AFL	4000					09-JAN-2002 3992 2862	7992 2252.80 / 1747.20	E2	
	REF: GENERIC NO REF										
361113	PIPE:REPLACE NO. 3 ENGINE EXPANSION PIPE LININGS										
36.010		MOS HRS/MSC AFL	4000					09-JAN-2002 3992 2862	7992 2252.80 / 1747.20	E3	
	REF: GENERIC NO REF										
+ 361115	PIPE:LEAK TEST NO. 3 ENGINE EXPANSION PIPE										
36.010		MOS HRS/MSC AFL	4000					09-JAN-2002 3992 2862	7992 2252.80 / 1747.20	E3	
	REF: GENERIC NO REF										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
Owner : BENTLEY DOWNERS GROVE LUXURY  
Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 361126	VALVE:FUNCTIONAL CHECK NO. 1 (23H1) HP BLEED AIR SHUTOFF VALVE	MOS								16-JAN-2004			E1
36.030		HRS/MSC	4000							4727.7	8727.7	2988.50 / 1011.50	
	REF: GENERIC NO REF	AFL								3233			
+ 361141	VALVE:FUNCTIONAL CHECK NO. 2 (23H2) ENGINE HP BLEED AIR SHUTOFF VALVE	MOS								24-NOV-2003			E2
36.040		HRS/MSC	4000							4694.2	8694.2	2955 / 1045	
	REF: GENERIC NO REF	AFL								3208			
+ 361156	VALVE:FUNCTIONAL CHECK NO. 3 (23H3) ENGINE HP BLEED AIR SHUTOFF VALVE	MOS								09-JAN-2002			E3
36.050		HRS/MSC	4000							3992.1	7992.1	2252.90 / 1747.10	
	REF: GENERIC NO REF	AFL								2862			
+ 361166	VALVE:FUNCTIONAL TEST PRESSURE REGULATING VALVE	MOS								15-SEP-2000			E2
36.060		HRS/MSC	4000							2948	6948	1208.80 / 2791.20	
	REF: GENERIC NO REF	AFL								2083			
<b>CHAPTER 49 AIRBORNE AUXILIARY POWER</b>													
APU Model : T-62T-40C3A/3A1 Serial # 861812 Part # 160981-200													
+ 490010	APU - ACCOMPLISH 6 MONTH/125 HOUR/250 CYCLE INSPECTION	MOS	6							10-APR-2007	10-OCT-2007	3 / 3.47	
49.010		HRS/MSC	125							4216	4341	101 / 24	
	REF: MSC SB-T-62T-49-77	APUS	250							7255	7505	250 / 0	
+ 490020	APU - ACCOMPLISH 6 MONTH/250 HOUR/500 CYCLE INSPECTION	MOS	6							10-APR-2007	10-OCT-2007	3 / 3.47	
49.015		HRS/MSC	250							4216	4466	226 / 24	
	REF: MSC SB-T-62T-49-77	APUS	500							7255	7755	500 / 0	
+ 490030	APU - ACCOMPLISH 12 MONTH/500 HOUR/1000 CYCLE INSPECTION	MOS	12							10-APR-2007	10-APR-2008	9 / 3.47	
49.020		HRS/MSC	500							4216	4716	476 / 24	
	REF: MSC SB-T-62T-49-77	APUS	1000							7255	8255	1000 / 0	
+ 490040	APU - ACCOMPLISH 12 MONTH/1000 HOUR/2000 CYCLE INSPECTION	MOS	12							10-APR-2007	10-APR-2008	9 / 3.47	
49.025		HRS/MSC	1000							4216	5216	976 / 24	
	REF: MSC SB-T-62T-49-77	APUS	2000							7255	9255	2000 / 0	
+ 490050	APU - ACCOMPLISH 24 MONTH/1500 HOUR/3000 CYCLE INSPECTION	MOS	24							19-DEC-2005	19-DEC-2007	5 / 19.17	
49.030		HRS/MSC	1500							3866	5366	1126 / 374	
	REF: MSC SB-T-62T-49-77	APUS	3000							6795	9795	2540 / 460	
491010	ROTOR:APU - TURBINE ROTOR										LIFE LIMIT		
49.035	167222-1	MOS								03-JUN-2001			
	V39-H177K	HRS/MSC	1712							2670			
	REF: See Workcard	APUS	9000	2268						5111	11843	4588 / 4412	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
491020	ROTOR:APU - COMPRESSOR ROTOR										LIFE LIMIT		
49.040	M167200-1	MOS								03-JUN-2001			
	V42-C2715	HRS/MSC		743						2670			
	REF: See Workcard	APUS	18000	921						5111	22190	14935 / 3065	
+ 493256	APU -- CK APU IGNITER PLUG												
		MOS	12							10-APR-2007	10-APR-2008	9 / 3.47	
		HRS/MSC	1000							4216	5216	976 / 24	
	REF:	APUS	2000							7255	9255	2000 / 0	
+ 499110	APU - SOAP CHECK OIL												
49.110		MOS	6							10-APR-2007	10-OCT-2007	3 / 3.47	
		HRS/MSC	250							4216	4466	226 / 24	
	REF: GENERIC NO REF	APUS	500							7255	7755	500 / 0	
<b>CHAPTER 52 DOORS</b>													
+ 521127	DOOR:CHECK PASSENGER/CREW DOOR STRUCTURE												F4
52.020		MOS	72							29-NOV-2004	29-NOV-2010	40 / 31.83	
		HRS/MSC								4906.8			
	REF: CMM 52-15-01	AFL								3334			
+ 521128	DOOR:CHECK PASSENGER/CREW DOOR NO PLAY IN HINGES												F4
52.020		MOS	72							29-NOV-2004	29-NOV-2010	40 / 31.83	
		HRS/MSC								4906.8			
	REF: CMM 52-15-01	AFL								3334			
+ 521129	DOOR:CHECK PASSENGER/CREW DOOR CONDITION OF CABLES												F4
52.020		MOS	72							29-NOV-2004	29-NOV-2010	40 / 31.83	
		HRS/MSC								4906.8			
	REF: CMM 52-15-01	AFL								3334			
521130	DOOR:LUBRICATE PASSENGER/CREW DOOR INTERNAL HINGES												F4
52.020		MOS	72							29-NOV-2004	29-NOV-2010	40 / 31.83	
		HRS/MSC								4906.8			
	REF: CMM 52-15-01	AFL								3334			
522101	EXIT:LEFT EMERGENCY EXIT										LIFE LIMIT		F4
52.040	F50B296001A2	MOS								14-DEC-1981			
	SN-UNKNOWN	HRS/MSC		0						0			
	REF: GENERIC NO REF	AFL	26718	0						0	26718	22913 / 3805	
+ 522112	EXIT:UNLOCKING TEST LEFT EMERGENCY EXIT FROM INSIDE (MANDATORY REF 5-40-00)										MANDATORY 5-40		F4
52.040		MOS	13							26-OCT-2006	26-NOV-2007	4 / 8.93	
		HRS/MSC								5464.7			
	REF: See Workcard	AFL								3641			
522121	EXIT:RIGHT EMERGENCY EXIT										LIFE LIMIT		F4
52.040	F50B296001A2	MOS								14-DEC-1981			
	SN-UNKNOWN	HRS/MSC		0						0			
	REF: GENERIC NO REF	AFL	26718	0						0	26718	22913 / 3805	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
+ 522132	EXIT:UNLOCKING TEST RIGHT EMERGENCY EXIT FROM INSIDE (MANDATORY REF 5-40-00)				MANDATORY 5-40		F4
52.040	REF: See Workcard	MOS HRS/MSC AFL	13	26-OCT-2006 5464.7 3641	26-NOV-2007	4 / 8.93	
+ 525102	OPERATIONAL TEST NO.2 S-DUCT DOOR INDICATING SYSTEM (MANDATORY REF 5-40-00)				MANDATORY 5-40		
52.080	REF: See Workcard	MOS HRS/MSC AFL	10000	25-SEP-2006 5434.7 3611	15434.7	9695.50 / 304.50	
<b>CHAPTER 53 FUSELAGE</b>							
530059	NON DESTRUCTIVE TEST OF THE COCKPIT WINDOW FRAMES, PILOT AND COPILOT WINDSHIELD. LH/RH FRONT WINDOW, LH/RH SIDE WINDOW, LH/RH REAR WINDOW (MANDATORY REF 5-40-00)				MANDATORY 5-40		
53.300	REF: AMM 688.0/0	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530060	VISUAL INSPECTION OF SKIN PANELS IN T2,T3 AND T4 SECTIONS (LONGITUDINAL CRACKS)				MANDATORY 5-40		
53.310	REF: AMM 688.0/1	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530061	NON DESTRUCTIVE TEST OF THE CORNERS OF THE PASSENGER / CREW DOOR FRAME				MANDATORY 5-40		
53.320	REF: AMM 688.0/2	MOS HRS/MSC AFL	31250		31250	27445	
530062	NON DESTRUCTIVE TEST OF THE FUSELAGE FRAMEWORK AROUND THE WINDOWS IN T2 AND T3 SECTIONS (LONGITUDINAL CRACKS)				MANDATORY 5-40		
53.330	REF: AMM 688.0/3	MOS HRS/MSC AFL	31250		31250	27445	
530063	NON DESTRUCTIVE TEST NOSE LANDING GEAR WELL RADIUS (MANDATORY REF 5-40-00)				MANDATORY 5-40		
53.340	REF: AMM 688.0/4	MOS HRS/MSC AFL	31250		31250	27445	
530064	VISUAL INSPECTION OF THE FLOOR PANEL IN THE ALLEY WAY BETWEEN FRAME 26 AND 29						
53.305	REF: AMM 53-500	MOS HRS/MSC AFL	10000	14-DEC-1981 0 0	10000	6195 / 3805	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE						DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ	Warr Exp			
WORKCARD	PART#/PKG SERIAL #											
530065	VISUAL INSPECTION OF THE ANGLE BETWEEN FRAME 27 FOOT AND FLOOR, AND THE FLOOR PANEL IN THE ALLEYWAY BETWEEN FRAME 26 AND 29 (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.360		MOS							14-DEC-1981			
	REF: AMM 53-500	HRS/MSC							0			
		AFL	10000						0	10000	6195 / 3805	
530066	VISUAL INSPECT BAGGAGE COMPARTMENT DOOR (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.370		MOS							14-DEC-1981			
	REF: AMM 688.0/7	HRS/MSC							0			
		AFL	26299						0	26299	22494 / 3805	
530067	VISUAL INSPECT FRAME 34 IN UPPER AND LOWER PARTS (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.142		MOS							14-DEC-1981			
	REF: AMM 688.0/8	HRS/MSC							0			
		AFL	20000						0	20000	16195 / 3805	
530068	VISUAL INSPECT FLOOR OMEGAS AT FRAMES 18-19 (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.145		MOS							14-DEC-1981			
	REF: AMM 688.0/9	HRS/MSC							0			
		AFL	27500						0	27500	23695 / 3805	
530070	VISUAL INSPECT COCKPIT UPPER SKIN AT THE WINDSHIELD AND GLASS FRAME ASSEMBLY ATTACHMENT (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.152		MOS							14-DEC-1981			
	REF: AMM 688.1/1	HRS/MSC							0			
		AFL	20000						0	20000	16195 / 3805	
530071	MAPPING LOWER WING CENTER SECTION PANEL (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.155		MOS	360						14-DEC-1981	14-DEC-2011	53 / 307.33	
	REF: AMM 688.1/2	HRS/MSC							0			
		AFL	20000						0	20000	16195 / 3805	
530073	VISUAL INSPECT WING CENTER SECTION LOWER PANELS (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.165		MOS							14-DEC-1981			
	REF: AMM 688.1/4	HRS/MSC							0			
		AFL	20000						0	20000	16195 / 3805	
530074	NON DESTRUCTIVE TEST WING CENTER SECTION LOER PANELS SPLICE (MANDATORY REF 5-40-00)									MANDATORY 5-40		
53.172		MOS							14-DEC-1981			
	REF: AMM 688.1/5	HRS/MSC							0			
		AFL	20000						0	20000	16195 / 3805	

Model : FALCON 50  
Owner : BENTLEY DOWNERS GROVE LUXURY  
Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp	(ENH) AFH	LABOR HRS		
530075	NON DESTRUCTIVE TEST EMERGENCY EXIT FRAME EDGING (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.175	REF: AMM 688.1/6	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530076	NON DESTRUCTIVE TEST FINGER PLATE OF THE CIRCUMFERENCIAL SPLICE AT FRAME 19 AND 26 (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.180	REF: AMM 688.1/7	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530078	NON DESTRUCTIVE CHECK FRAME 35 VERTICAL BEAM (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.185	REF: AMM 688.1/9	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530079	NON DESTRUCTIVE CHECK FLOOR BETWEEN FRAMES 31 AND 35 (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.195	REF: AMM 688.2/0	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530080	VISUAL INSPECT LOWER FIN FRONT SPAR (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.205	REF: AMM 688.2/1	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530081	NON DESTRUCTIVE CHECK REAR PASSENGER DOOR FRAME (FR 12) BETWEEN RIB 17 AND 18 (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.215	REF: AMM 688.2/2	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530090	VISUAL INSPECT PYLONS UPPER FLANGE RIB AT FRAME 32 (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.222	REF: AMM 688.9/0	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
530102	INSPECT/CHECK BUILT-IN FUSELAGE TANKS (MANDATORY REF 5-40-00)				<b>MANDATORY 5-40</b>		
53.225	REF: See Workcard	MOS HRS/MSC AFL	74	29-NOV-2004 4906.8 3334	29-JAN-2011	42 / 31.83	
530131	VISUAL INSPECTION OF ATTACHMENT FITTING OF NOSE LANDING GEAR ACTUATOR						
53.228	REF: AMM 53-400	MOS HRS/MSC AFL	10000	14-DEC-1981 0 0	10000	6195 / 3805	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
530132	VISUAL INSPECTION OF ATTACHMENT FITTING OF NOSE LANDING GEAR ACTUATOR (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
53.228		MOS HRS/MSC AFL	10000							14-DEC-1981 0 0	<b>10000</b>	6195 / 3805	
REF: AMM 53-400													
+ 530211	INSPECT PILOT/COPILOT WINDOW FRAME LINKING SCREWS WITH FRAME 0												F3
53.090		MOS HRS/MSC AFL	10525				0			14-DEC-1981 0 0	<b>10525</b>	6720 / 3805	
REF: See Workcard													
530212	INSPECT PILOT/COPILOT WINDOW FRAME LINKING SCREWS WITH FRAME 0 (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
53.235		MOS HRS/MSC AFL	6674							14-DEC-1981 0 0	<b>6674</b>	2869 / 3805	
REF: See Workcard													
530222	INSPECT BAGGAGE COMPARTMENT FRAME 35 LOWER SECTION (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
53.100		MOS HRS/MSC AFL	20000							14-DEC-1981 0 0	<b>20000</b>	16195 / 3805	
REF: GENERIC NO REF													
530227	INSPECT RIGHT BAD WEATHER WINDOW FRAME (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
53.110		MOS HRS/MSC AFL	10050							14-DEC-1981 0 0	<b>10050</b>	6245 / 3805	
REF: AMM 53-040													
530237	INSPECT LEFT REAR WINDOW FRAME (MANDATORY REF 5-40-00)												
53.265		MOS HRS/MSC AFL	12000							14-DEC-1981 0 0	<b>12000</b>	8195 / 3805	
REF: See Workcard													
530239	INSPECT RIGHT REAR WINDOW FRAME (MADATORY REF 5-40-00)												
53.275		MOS HRS/MSC AFL	12000							14-DEC-1981 0 0	<b>12000</b>	8195 / 3805	
REF: See Workcard													
+ 530246	INSPECT PASSENGER DOOR LOCKING HOOKS												F4
53.160		MOS HRS/MSC AFL	11435				0			14-DEC-1981 0 0	<b>11435</b>	7630 / 3805	
REF: See Workcard													
530247	INSPECT PASSENGER DOOR LOCKING HOOKS (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
53.290		MOS HRS/MSC AFL	11435							14-DEC-1981 0 0	<b>11435</b>	7630 / 3805	
REF: See Workcard													

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE					DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
				TSN	TSO	TSR	TSI	ADJ			
WORKCARD	PART#/PKG SERIAL #										
530252	VISUAL INSPECT ANGLE BETWEEN FLOOR AND BEAM IN T3 SECTION (MANDATORY REF 5-40-00)	MOS						14-DEC-1981			
53.302		HRS/MSC						0			
	REF: GENERIC NO REF	AFL	20000					0	20000	16195 / 3805	
530307	NON DESTRUCTIVE TEST OF VERTICAL POSTS ON SCREW MOUNTED WINDOWS (MANDATORY REF 5-40-00)								<b>MANDATORY 5-40</b>		
53.270		MOS						14-DEC-1981			
	REF: AMM 53-295	HRS/MSC						0			
		AFL	20000					0	20000	16195 / 3805	
530327	FAIRING:VISUAL INSPECT FLIGHT COMPARTMENT REMOVABLE WINDOW FAIRING COCKPIT WINDOW LOWER FRAMES (TRIM REMOVED) (MANDATORY REF 5-40-00)								<b>MANDATORY 5-40</b>		
53.210		MOS	360					14-DEC-1981	14-DEC-2011	53 / 307.33	
	REF: AMM 53-280	HRS/MSC						0			
		AFL	20000					0	20000	16195 / 3805	
<b>CHAPTER 54 NACELLES/PYLONS</b>											
540021	VISUAL INSPECT FOR CRACKS ON LATERAL ENGINES FRONT AND REAR MOUNTS (MANDATORY REF 5-40-00)								<b>MANDATORY 5-40</b>		
54.075		MOS						14-DEC-1981			
	REF: AMM 688.9/1	HRS/MSC						0			
		AFL	20000					0	20000	16195 / 3805	
540022	VISUAL INSPECT ENGINE 2 HOISTING FITTING PLATE AND MOUNTS (MANDATORY REF 5-40-00)								<b>MANDATORY 5-40</b>		
54.082		MOS						14-DEC-1981			
	REF: AMM 688.2/3	HRS/MSC						0			
		AFL	20000					0	20000	16195 / 3805	
<b>CHAPTER 55 STABILIZERS</b>											
551002	VISUAL INSPECT FRONT AND REAR UPPER PANELS BETWEEN THE HORIZONTAL STABILIZER ROOT AND RIB 2 (MANDATORY REF 5-40-00)								<b>MANDATORY 5-40</b>		
55.045		MOS						14-DEC-1981			
	REF: AMM 706.0/0	HRS/MSC						0			
		AFL	20000					0	20000	16195 / 3805	
552003	VISUAL INSPECT ELEVATORS SKIN AND ELEVATOR HINGE FITTINGS (MANDATORY REF 5-40-00)								<b>MANDATORY 5-40</b>		
55.050		MOS						14-DEC-1981			
	REF: AMM 706.1/0	HRS/MSC						0			
		AFL	20000					0	20000	16195 / 3805	
554003	VISUAL INSPECT RUDDER SKIN AND THE RUDDER HINGE FITTINGS (MANDATORY REF 5-40-00)								<b>MANDATORY 5-40</b>		
55.055		MOS						14-DEC-1981			
	REF: See Workcard	HRS/MSC						0			
		AFL	20000					0	20000	16195 / 3805	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
+ 555002	DIMENSIONAL CHECK HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY REF 5-40-00)				MANDATORY 5-40		
55.040	REF: See Workcard	MOS HRS/MSC AFL	3750	29-NOV-2004 4906.8 3334	7084	3279 / 471	
555002A	NON DESTRUCTIVE TEST FORWARD AND REAR FITTINGS OF FIN AND HORIZONTAL STABILIZER (MANDATORY REF 5-40-00)				MANDATORY 5-40		
55.062	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
555003	VISUAL INSPECT HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS ON STRUCTURE SIDE AND ON STABILIZER SIDE (MANDATORY REF 5-40-00)				MANDATORY 5-40		
55.065	REF: AMM 706.3/1	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
<b>CHAPTER 57 WINGS</b>							
570012	MAPPING LOWER WING PANELS (MANDATORY REF 5-40-00)				MANDATORY 5-40		
57.165	REF: AMM 728.0/0	MOS HRS/MSC AFL	360 20000	14-DEC-1981 0 0	14-DEC-2011 20000	53 / 307.33 16195 / 3805	
570014	VISUAL INSPECT LOWER WING PANELS (MANDATORY REF 5-40-00)				MANDATORY 5-40		
57.172	REF: AMM 728.0/2	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
570015	NON DESTRUCTIVE TEST WING FRONT SPAR (EXCEPT BETWEEN RIBS 8 AND 9) (MANDATORY REF 5-40-00)				MANDATORY 5-40		
57.175	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
570016	NON DESTRUCTIVE TEST WING FRONT SPAR BETWEEN RIBS 8 AND 9 (MANDATORY REF 5-40-00)				MANDATORY 5-40		
57.182	REF: AMM 728.0/4	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	
570017	NON DESTRUCTIVE TEST WING REAR SPAR 2 (MANDATORY REF 5-40-00)				MANDATORY 5-40		
57.185	REF: AMM 728.0/5	MOS HRS/MSC AFL	20000	14-DEC-1981 0 0	20000	16195 / 3805	

Model : FALCON 50  
Owner : BENTLEY DOWNERS GROVE LUXURY  
Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
570018	NON DESTRUCTIVE TEST WING REAR SPAR 1 (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
57.192		MOS								14-DEC-1981			
	REF: AMM 728.0/6	HRS/MSC								0			
		AFL	20000							0	<b>20000</b>	16195 / 3805	
570019	NON DESTRUCTIVE TEST WING REAR SPAR SPLICE (BETWEEN RIBS 6 AND 8) (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
57.195		MOS								14-DEC-1981			
	REF: AMM 728.0/7	HRS/MSC								0			
		AFL	20000							0	<b>20000</b>	16195 / 3805	
570302	DETAILED INSPECTION/CHECK WING AND CENTER WING STRUCTURAL FUEL TANKS (MANDATORY REF 5-40-00)										<b>29-JAN-2011</b>	42 / 31.83	
57.205		MOS	74							29-NOV-2004			
	REF: See Workcard	HRS/MSC								4906.8			
		AFL								3334			
575103	VISUAL INSPECT AILERON SKIN AND HINGE FITTINGS (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
57.210		MOS								14-DEC-1981			
	REF: AMM 728.1/0	HRS/MSC								0			
		AFL	20000							0	<b>20000</b>	16195 / 3805	
575181	HINGE:LEFT OUTBOARD AIRBRAKE CENTRAL HINGE										<b>LIFE LIMIT</b>		
57.230	F50B165003001	MOS	0							14-DEC-1981			
	SN-UNKNOWN	HRS/MSC	0							0			
	REF: GENERIC NO REF	AFL	20000	0						0	<b>20000</b>	16195 / 3805	
575186	HINGE:RIGHT OUTBOARD AIRBRAKE CENTRAL HINGE										<b>LIFE LIMIT</b>		
57.230	F50B165003001	MOS	0							14-DEC-1981			
	SN-UNKNOWN	HRS/MSC	0							0			
	REF: GENERIC NO REF	AFL	20000	0						0	<b>20000</b>	16195 / 3805	
575205	VISUAL INSPECT FLAP TRACKS AND ROLLERS (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
57.222		MOS								14-DEC-1981			
	REF: AMM 728.1/1	HRS/MSC								0			
		AFL	20000							0	<b>20000</b>	16195 / 3805	
575405	VISUAL INSPECT SLAT TRACKS (MANDATORY REF 5-40-00)										<b>MANDATORY 5-40</b>		
57.225		MOS								14-DEC-1981			
	REF: AMM 728.1/2	HRS/MSC								0			
		AFL	20000							0	<b>20000</b>	16195 / 3805	
<b>CHAPTER 71</b>													
<b>POWER PLANT</b>													
712102	MOUNT:REPLACE NO. 2 ENGINE LEFT FRONT SHOCK MOUNT RESILIENT BLOCK												E2
71.045		MOS								16-JAN-2004			
	REF: AMM 71-021	HRS/MSC	5000							4727.7	<b>9727.7</b>	3988.50 / 1011.50	
		AFL								3233			

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
712103	MOUNT:NON DESTRUCTIVE TEST NO. 2 ENGINE LEFT FRONT SHOCK MOUNT METAL COMPONENTS	MOS								16-JAN-2004			E2
71.045	REF: AMM 71-021	HRS/MSC AFL	5000							4727.7 3233	9727.7	3988.50 / 1011.50	
712112	MOUNT:REPLACE NO. 2 ENGINE RIGHT FRONT SHOCK MOUNT RESILIENT BLOCK	MOS								16-JAN-2004			E2
71.046	REF: AMM 71-021	HRS/MSC AFL	5000							4727.7 3233	9727.7	3988.50 / 1011.50	
712113	MOUNT:NON DESTRUCTIVE TEST NO. 2 ENGINE RIGHT FRONT SHOCK MOUNT METAL COMPONENTS	MOS								16-JAN-2004			E2
71.046	REF: AMM 71-021	HRS/MSC AFL	5000							4727.7 3233	9727.7	3988.50 / 1011.50	
712117	MOUNT:REPLACE NO. 2 ENGINE REAR SHOCK MOUNT RESILIENT BLOCK	MOS								16-JAN-2004			E2
71.047	REF: AMM 71-021	HRS/MSC AFL	5000							4727.7 3233	9727.7	3988.50 / 1011.50	
712118	MOUNT:NON DESTRUCTIVE TEST NO. 2 ENGINE REAR SHOCK MOUNT METAL COMPONENTS	MOS								16-JAN-2004			E2
71.047	REF: AMM 71-021	HRS/MSC AFL	5000							4727.7 3233	9727.7	3988.50 / 1011.50	
<b>ENGINE NO. 1 Model : TFE731-3 Serial # P76385 Part # TFE731-3-1C</b>													
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION	MOS								26-DEC-2003			
71.010	REF: EMM 72-00-00	HRS/MSC ENC	1400							4624.4 3218	(6024.4) 6128.9	389.70 / 1010.30	
<b>ENGINE NO. 2 Model : TFE731-3 Serial # P76254 Part # TFE731-3-1C</b>													
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION	MOS								18-DEC-2003			
71.010	REF: EMM 72-00-00	HRS/MSC ENC	1400							4506.7 3138	(5906.7) 6127.7	388.50 / 1011.50	
<b>ENGINE NO. 3 Model : TFE731-3 Serial # P76384 Part # TFE731-3-1C</b>													
+ 710120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION	MOS								28-JUL-2004			
71.010	REF: EMM 72-00-00	HRS/MSC ENC	1400							4505.3 3112	(5905.3) 6284.5	545.30 / 854.70	
<b>CHAPTER 72 ENGINE</b>													
<b>ENGINE NO. 1 Model : TFE731-3 Serial # P76385 Part # TFE731-3-1C</b>													
+ 723110	NO. 1 ENGINE - INSPECT COMPRESSOR CORE	MOS								26-DEC-2003			
72.010	REF: GENERIC NO REF	HRS/MSC ENC	4200							4624.4 3218	(8824.4) 8928.9	3189.70 / 1010.30	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #										NEXT DUE ( ENH ) AFH		
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS								26-DEC-2003			
72.030		HRS/MSC	1400							4624.4	(6024.4) 6128.9	389.70 / 1010.30	
	REF: EMM 72-40-04	ENC								3218			
725010	DISC:NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC	MOS		0						17-JAN-2001	LIFE LIMIT		
72.040		HRS/MSC		0						3185.2			
	REF: GENERIC NO REF	ENC	3000	0						2308	5308	1575 / 1425	
725020	DISC:NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC	MOS		0						17-JAN-2001	LIFE LIMIT		
72.050		HRS/MSC		0						3185.2			
	REF: GENERIC NO REF	ENC	3000	0						2308	5308	1575 / 1425	
725030	DISC:NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC	MOS		0						10-AUG-1998	LIFE LIMIT		
72.060		HRS/MSC		0						1722.7			
	REF: GENERIC NO REF	ENC	7000	0						1243	8243	4510 / 2490	
725040	DISC:NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC	MOS		0						14-DEC-1981	LIFE LIMIT		
72.070		HRS/MSC		0						0			
	REF: EMM 72-50-06	ENC	7000	0						0	7000	3267 / 3733	
725050	DISC:NO. 1 ENGINE - FAN ROTOR DISC	MOS		0						10-AUG-1998	LIFE LIMIT		
72.090		HRS/MSC		0						1722.7			
	REF: GENERIC NO REF	ENC	10000	0						1243	11243	7510 / 2490	
725060	DISC:NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC	MOS		0						14-DEC-1981	LIFE LIMIT		
72.100		HRS/MSC		0						0			
	REF: GENERIC NO REF	ENC	10000	0						0	10000	6267 / 3733	
725070	DISC:NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC	MOS		0						14-DEC-1981	LIFE LIMIT		
72.110		HRS/MSC		0						0			
	REF: GENERIC NO REF	ENC	10000	0						0	10000	6267 / 3733	
725080	DISC:NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC	MOS		0						14-DEC-1981	LIFE LIMIT		
72.120		HRS/MSC		0						0			
	REF: GENERIC NO REF	ENC	10000	0						0	10000	6267 / 3733	
725090	DISC:NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC	MOS		0						14-DEC-1981	LIFE LIMIT		
72.130		HRS/MSC		0						0			
	REF: GENERIC NO REF	ENC	10000	0						0	10000	6267 / 3733	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE (ENH) AFH		
725110	IMPELLER:NO. 1 ENGINE - HIGH PRESSURE IMPELLER 3073398-3	MOS		10-AUG-1998	LIFE LIMIT		
72.150	985332200746 REF: GENERIC NO REF	HRS/MSC ENC	0 10000	1722.7 1243		7510 / 2490	
725130	SHAFT:NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3072545-1	MOS		14-DEC-1981	LIFE LIMIT		
72.170	1P-18367 REF: GENERIC NO REF	HRS/MSC ENC	0 12000	0 0		8267 / 3733	
725140	PLATE:NO. 1 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE 3072411-1	MOS		14-DEC-1981	LIFE LIMIT		
72.180	1-18040-206 REF: GENERIC NO REF	HRS/MSC ENC	0 10000	0 0		6267 / 3733	
+ 726120	GEARBOX:NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX	MOS		26-DEC-2003			
72.260	REF: EMM 72-60-02	HRS/MSC ENC	4200	4624.4 3218	(8824.4) 8928.9	3189.70 / 1010.30	
+ 726310	NO. 1 ENGINE - INSPECT STARTER/GENERATOR ACCESSORY DRIVE SPLINE	MOS		26-DEC-2003			
72.280	REF: EMM 72-60-01	HRS/MSC ENC	1400	4624.4 3218	(6024.4) 6128.9	389.70 / 1010.30	
+ 727110	NO. 1 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS		26-DEC-2003			
72.300	REF: EMM 72-70-06	HRS/MSC ENC	4200	4624.4 3218	(8824.4) 8928.9	3189.70 / 1010.30	
<b>ENGINE NO. 2 Model : TFE731-3 Serial # P76254 Part # TFE731-3-1C</b>							
+ 723110	NO. 2 ENGINE - INSPECT COMPRESSOR CORE	MOS		18-DEC-2003			
72.010	REF: GENERIC NO REF	HRS/MSC ENC	4200	4506.7 3138	(8706.7) 8927.7	3188.50 / 1011.50	
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS		18-DEC-2003			
72.030	REF: EMM 72-40-04	HRS/MSC ENC	1400	4506.7 3138	(5906.7) 6127.7	388.50 / 1011.50	
725010	DISC:NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3072351-5	MOS		16-JAN-2001	LIFE LIMIT		
72.040	000322901608 REF: GENERIC NO REF	HRS/MSC ENC	0 3000	3066.5 2228		1575 / 1425	
725020	DISC:NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3072542-5	MOS		16-JAN-2001	LIFE LIMIT		
72.050	000322905533 REF: GENERIC NO REF	HRS/MSC ENC	0 3000	3066.5 2228		1575 / 1425	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #										NEXT DUE ( ENH ) AFH		
725030	DISC:NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3074097-1	MOS								24-OCT-1998	LIFE LIMIT		
72.060	975332201912 REF: GENERIC NO REF	HRS/MSC ENC	7000	0						1722.7 1243		4590 / 2410	
725040	DISC:NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC 3072314-2	MOS								14-DEC-1981	LIFE LIMIT		
72.070	9-12112-1417 REF: EMM 72-50-06	HRS/MSC ENC	7000	0						0 0		3347 / 3653	
725050	DISC:NO. 2 ENGINE - FAN ROTOR DISC 3073563-2	MOS								24-OCT-1998	LIFE LIMIT		
72.090	960322907143 REF: GENERIC NO REF	HRS/MSC ENC	10000	0						1722.7 1243		7590 / 2410	
725060	DISC:NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3070440-8	MOS								14-DEC-1981	LIFE LIMIT		
72.100	9-12112-2825 REF: GENERIC NO REF	HRS/MSC ENC	10000	0						0 0		6347 / 3653	
725070	DISC:NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072416-2	MOS								14-DEC-1981	LIFE LIMIT		
72.110	9-03160-1212 REF: GENERIC NO REF	HRS/MSC ENC	10000	0						0 0		6347 / 3653	
725080	DISC:NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397-1	MOS								14-DEC-1981	LIFE LIMIT		
72.120	9-03160-1413 REF: GENERIC NO REF	HRS/MSC ENC	10000	0						0 0		6347 / 3653	
725090	DISC:NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3071652-9	MOS								14-DEC-1981	LIFE LIMIT		
72.130	9-12112-3020 REF: GENERIC NO REF	HRS/MSC ENC	10000	0						0 0		6347 / 3653	
725110	IMPELLER:NO. 2 ENGINE - HIGH PRESSURE IMPELLER 3073393-1	MOS								24-OCT-1998	LIFE LIMIT		
72.150	985332200929 REF: GENERIC NO REF	HRS/MSC ENC	10000	0						1722.7 1243		7590 / 2410	
725130	SHAFT:NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3072545-1	MOS								14-DEC-1981	LIFE LIMIT		
72.170	0P-13530 REF: GENERIC NO REF	HRS/MSC ENC	12000	0						0 0		8347 / 3653	
725140	PLATE:NO. 2 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE 3072411-1	MOS								14-DEC-1981	LIFE LIMIT		
72.180	8-18040-9756 REF: GENERIC NO REF	HRS/MSC ENC	10000	0						0 0		6347 / 3653	

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
+ 726120	GEARBOX:NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX	MOS		18-DEC-2003			
72.260		HRS/MSC 4200		4506.7	(8706.7) 8927.7	3188.50 / 1011.50	
	REF: EMM 72-60-02	ENC		3138			
+ 726310	NO. 2 ENGINE - INSPECT STARTER/GENERATOR ACCESSORY DRIVE SPLINE	MOS		18-DEC-2003			
72.280		HRS/MSC 1400		4506.7	(5906.7) 6127.7	388.50 / 1011.50	
	REF: EMM 72-60-01	ENC		3138			
+ 727110	NO. 2 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY	MOS		18-DEC-2003			
72.300		HRS/MSC 4200		4506.7	(8706.7) 8927.7	3188.50 / 1011.50	
	REF: EMM 72-70-06	ENC		3138			
<b>ENGINE NO. 3 Model : TFE731-3 Serial # P76384 Part # TFE731-3-1C</b>							
+ 723110	NO. 3 ENGINE - INSPECT COMPRESSOR CORE	MOS		03-JUN-2001			
72.010		HRS/MSC 4200		3119.2	(7319.2) 7698.4	1959.20 / 2240.80	
	REF: GENERIC NO REF	ENC		2267			
+ 724120	NO. 3 ENGINE - INSPECT COMBUSTION PLENUM CASE	MOS		28-JUL-2004			
72.030		HRS/MSC 1400		4505.3	(5905.3) 6284.5	545.30 / 854.70	
	REF: EMM 72-40-04	ENC		3112			
725010	DISC:NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC	MOS	0	03-JUN-2001			<b>LIFE LIMIT</b>
72.040	3072351-5	HRS/MSC 0		3119.2			
	000322905490	ENC 3000	0	2267		5267	1722 / 1278
	REF: GENERIC NO REF						
725020	DISC:NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC	MOS	0	03-JUN-2001			<b>LIFE LIMIT</b>
72.050	3072542-5	HRS/MSC 0		3119.2			
	000322905641	ENC 3000	0	2267		5267	1722 / 1278
	REF: GENERIC NO REF						
725030	DISC:NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC	MOS	0	03-JUN-2001			<b>LIFE LIMIT</b>
72.060	3074097-1	HRS/MSC 0		3119.2			
	985332200557	ENC 7000	0	2267		9267	5722 / 1278
	REF: GENERIC NO REF						
725040	DISC:NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC	MOS	0	03-JUN-2001			<b>LIFE LIMIT</b>
72.070	3072316-3	HRS/MSC 0		3119.2			
	000322904639	ENC 7000	0	2267		9267	5722 / 1278
	REF: EMM 72-50-06						
725050	DISC:NO. 3 ENGINE - FAN ROTOR DISC	MOS	1344	03-JUN-2001			<b>LIFE LIMIT</b>
72.090	3073563-2	HRS/MSC 1344		3119.2			
	970322902495	ENC 10000	986	2267		11281	7736 / 2264
	REF: GENERIC NO REF						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #		TSN TSO TSR TSI ADJ Warr Exp		NEXT DUE ( ENH ) AFH		
725060	DISC:NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3072395-1	MOS		14-DEC-1981	LIFE LIMIT		
72.100	1-03160-1959 REF: GENERIC NO REF	HRS/MSC ENC	0 10000	0 0	0 10000	6455 / 3545	
725070	DISC:NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072396-1	MOS		14-DEC-1981	LIFE LIMIT		
72.110	0-12112-3412 REF: GENERIC NO REF	HRS/MSC ENC	0 10000	0 0	0 10000	6455 / 3545	
725080	DISC:NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397	MOS		14-DEC-1981	LIFE LIMIT		
72.120	0-12112-3568 REF: GENERIC NO REF	HRS/MSC ENC	0 10000	0 0	0 10000	6455 / 3545	
725090	DISC:NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3072398	MOS		14-DEC-1981	LIFE LIMIT		
72.130	0-12112-3637 REF: GENERIC NO REF	HRS/MSC ENC	0 10000	0 0	0 10000	6455 / 3545	
725110	IMPELLER:NO. 3 ENGINE - HIGH PRESSURE IMPELLER 3073398-3	MOS		03-JUN-2001	LIFE LIMIT		
72.150	005332200222 REF: GENERIC NO REF	HRS/MSC ENC	0 10000	0 0	3119.2 2267	8722 / 1278	12267
725130	SHAFT:NO. 3 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3072545-1	MOS		03-JUN-2001	LIFE LIMIT		
72.170	OOP29112 REF: GENERIC NO REF	HRS/MSC ENC	0 12000	0 0	3119.2 2267	10722 / 1278	14267
725140	PLATE:NO. 3 ENGINE - HIGH PRESSURE ROTOR SEAL PLATE 3072411-1	MOS		03-JUN-2001	LIFE LIMIT		
72.180	6-18040-4419 REF: GENERIC NO REF	HRS/MSC ENC	3609 10000	2947	3119.2 2267	5775 / 4225	9320
+ 726120	GEARBOX:NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX MOS			03-JUN-2001	LIFE LIMIT		
72.260	REF: EMM 72-60-02	HRS/MSC ENC	4200		3119.2 2267	1959.20 / 2240.80	(7319.2) 7698.4
+ 726310	NO. 3 ENGINE - INSPECT STARTER/GENERATOR ACCESSORY DRIVE SPLINE MOS			28-JUL-2004	LIFE LIMIT		
72.280	REF: EMM 72-60-01	HRS/MSC ENC	1400		4505.3 3112	545.30 / 854.70	(5905.3) 6284.5
+ 727110	NO. 3 ENGINE - PERIODIC INSPECT FAN SUPPORT ASSEMBLY MOS			03-JUN-2001	LIFE LIMIT		
72.300	REF: EMM 72-70-06	HRS/MSC ENC	4200		3119.2 2267	1959.20 / 2240.80	(7319.2) 7698.4

**CHAPTER 73 ENGINE FUEL AND CONTROL**

ENGINE NO. 1 Model : TFE731-3 Serial # P76385 Part # TFE731-3-1C

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

Model : FALCON 50  
 Owner : BENTLEY DOWNERS GROVE LUXURY  
 Operator : BENTLEY DOWNERS GROVE LUXURY

A/C Serial #: 082 A/C Reg. #: N582EJ

Aircraft HRS: 5739.2 Landings: 3805

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TSN	TSO	TSR	TSI	ADJ	Warr Exp	COMPLIANCE	DISPOSITION NEXT DUE ( ENH ) AFH	Time Remaining / Total Time	AREA PRICE LABOR HRS
WORKCARD	PART#/PKG SERIAL #												
+ 731120	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT	MOS								28-MAR-2006			
73.020		HRS/MSC	600							5170.1	(5770.1) 5874.6	135.40 / 464.60	
	REF: EMM 73-21-02	ENC											
<b>ENGINE NO. 2 Model : TFE731-3 Serial # P76254 Part # TFE731-3-1C</b>													
+ 731120	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT	MOS								28-MAR-2006			
73.020		HRS/MSC	600							5052.4	(5652.4) 5873.4	134.20 / 465.80	
	REF: EMM 73-21-02	ENC											
<b>ENGINE NO. 3 Model : TFE731-3 Serial # P76384 Part # TFE731-3-1C</b>													
+ 731120	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT	MOS								28-MAR-2006			
73.020		HRS/MSC	600							4894.4	(5494.4) 5873.6	134.40 / 465.60	
	REF: EMM 73-21-02	ENC											
<b>CHAPTER 78 EXHAUST</b>													
783301	DOOR:LEFT THRUST REVERSER CLAMSHELL DOOR										LIFE LIMIT		
	F50B583130	MOS		0						14-DEC-1981			
78.105	SN-UNKNOWN	HRS/MSC		0						0			
	REF: GENERIC NO REF	AFL	20000	0						0	20000	16195 / 3805	
783311	DOOR:RIGHT THRUST REVERSER CLAMSHELL DOOR										LIFE LIMIT		
	F50B583130	MOS		0						14-DEC-1981			
78.105	SN-UNKNOWN	HRS/MSC		0						0			
	REF: GENERIC NO REF	AFL	20000	0						0	20000	16195 / 3805	
<b>CHAPTER 79 OIL</b>													
<b>ENGINE NO. 1 Model : TFE731-3 Serial # P76385 Part # TFE731-3-1C</b>													
790120	NO. 1 ENGINE - CHANGE OIL												
		MOS								26-DEC-2003			
79.020		HRS/MSC	1400							4624.4	(6024.4) 6128.9	389.70 / 1010.30	
	REF: EMM 72-00-00	ENC								3218			
<b>ENGINE NO. 2 Model : TFE731-3 Serial # P76254 Part # TFE731-3-1C</b>													
790120	NO. 2 ENGINE - CHANGE OIL												
		MOS								18-DEC-2003			
79.020		HRS/MSC	1400							4506.7	(5906.7) 6127.7	388.50 / 1011.50	
	REF: EMM 72-00-00	ENC								3138			
<b>ENGINE NO. 3 Model : TFE731-3 Serial # P76384 Part # TFE731-3-1C</b>													
790120	NO. 3 ENGINE - CHANGE OIL												
		MOS								28-JUL-2004			
79.020		HRS/MSC	1400							4505.3	(5905.3) 6284.5	545.30 / 854.70	
	REF: EMM 72-00-00	ENC								3112			