



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-01 051201	INSPECTION DOCUMENT 01	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		450		1989.3	450
5-12-02 051202	INSPECTION DOCUMENT 02	SBJD			MTH 25-Feb-2011 HRS 887.3 LDG 931		900		1787.3	248
5-12-03 051203	INSPECTION DOCUMENT 03	SBJD			MTH 16-Aug-2012 HRS 1280.5 LDG 1510		1350		2630.5	1091.2
5-12-04 051204	INSPECTION DOCUMENT 04	*CF			MTH 28-Nov-2007 HRS 0		1800		1800	260.7
5-12-05 051205	INSPECTION DOCUMENT 05	*CF			MTH 28-Nov-2007 HRS 0		3150		3150	1610.7
5-12-06 051206	INSPECTION DOCUMENT 06	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		12		31-May-2018	11 m 10 d
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK): INSPECTION DOCUMENT 06	KDXR		C352TS Y-649981	MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		12		31-May-2018	11 m 10 d
5-12-07 051207	INSPECTION DOCUMENT 07	KFXE			MTH 21-Jun-2016 HRS 1471.3 LDG 1749		24		30-Jun-2018	12 m 9 d
5-12-08	INSPECTION DOCUMENT 08	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		36			
B323001 051208 : LG	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST): INSPECTION DOCUMENT 08	KDXR		40005369-2 5368	MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		36		31-May-2020	35 m 10 d
B324002 051208 : EB	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST): INSPECTION DOCUMENT 08	KDXR		40005399-1 5440	MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		36		31-May-2020	35 m 10 d
5-12-10	INSPECTION DOCUMENT 10	SBJD			MTH 04-Feb-2014 HRS LDG		60			
B262004 051210 : FB	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST): INSPECTION DOCUMENT 10	SBJD		30401102-2 57207B1	MTH 04-Feb-2014		60		28-Feb-2019	20 m 7 d
5-12-11 051211	INSPECTION DOCUMENT 11	SBJD			MTH 17-Apr-2014 HRS 1417.1 LDG 1719		72		30-Apr-2020	34 m 9 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION): INSPECTION DOCUMENT 11	SBJD		C352TS Y-649981	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		72		30-Apr-2020	34 m 9 d
5-12-12	INSPECTION DOCUMENT 12	SBJD			MTH 17-Jan-2014 HRS LDG		144			



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
B262101 <i>051212</i>	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST): INSPECTION DOCUMENT 12	SBJD		C352TS Y-649981	MTH 17-Jan-2014		144		31-Jan-2026	103 m 10 d
5-12-13 <i>051213</i>	INSPECTION DOCUMENT 13	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		12 450		31-May-2018 1989.3	11 m 10 d 450
5-12-14 <i>051214</i>	INSPECTION DOCUMENT 14	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		12 900		31-May-2018 2439.3	11 m 10 d 900
5-12-15 <i>051215</i>	INSPECTION DOCUMENT 15	KFXE			MTH 21-Jun-2016 HRS 1471.3 LDG 1749		24 1350		30-Jun-2018 2821.3	12 m 9 d 1282
5-12-16 <i>051216</i>	INSPECTION DOCUMENT 16	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		36 1350		31-May-2020 2889.3	35 m 10 d 1350
5-12-17 <i>051217</i>	INSPECTION DOCUMENT 17	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		36 1800		31-May-2020 3339.3	35 m 10 d 1800
5-12-18 <i>051218</i>	INSPECTION DOCUMENT 18	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		36 2250		31-May-2020 3789.3	35 m 10 d 2250
5-12-20 <i>051220</i>	INSPECTION DOCUMENT 20	KFXE			MTH 21-Jun-2016 HRS 1471.3 LDG 1749		48 2700		30-Jun-2020 4171.3	36 m 9 d 2632
5-12-21 <i>051221</i>	INSPECTION DOCUMENT 21	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		12		31-May-2018	11 m 10 d
5-12-22	INSPECTION DOCUMENT 22	KFXE			MTH 05-Aug-2016		24			
B341001 AIRSPEED <i>051222 : A/S</i>	CALIBRATION TEST INDICATOR 14 CFR PART 91.411: INSPECTION DOCUMENT 22	KFXE		261440-1143 295469A	MTH 05-Aug-2016		24		31-Aug-2018	14 m 10 d
B341001 NO. 1 <i>051222 : ADC</i>	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411: INSPECTION DOCUMENT 22	KFXE		011-01110-00 43800527	MTH 05-Aug-2016		24		31-Aug-2018	14 m 10 d
B341001 NO. 2 <i>051222 : ADC#2</i>	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411: INSPECTION DOCUMENT 22	KFXE		011-01110-00 43805931	MTH 05-Aug-2016		24		31-Aug-2018	14 m 10 d
B341001 STANDBY <i>051222 : STDBY</i>	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411: INSPECTION DOCUMENT 22	KFXE		162350-1161 176282B	MTH 05-Aug-2016		24		31-Aug-2018	14 m 10 d
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01): INSPECTION DOCUMENT 22	KFXE			MTH 05-Aug-2016		24		31-Aug-2018	14 m 10 d
B345000 LEFT <i>051222 : XPDR1</i>	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413 : INSPECTION DOCUMENT 22	KFXE		011-00779-01 84805014	MTH 05-Aug-2016		24		31-Aug-2018	14 m 10 d



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
B345000 RIGHT <i>051222 : XPDR2</i>	CALIBRATION TEST TRANSPONDER	KFXE	14 CFR	PART 91.413 : INSPECTION DOCUMENT 22 011-00779-01 84805021	MTH 05-Aug-2016		24		31-Aug-2018	14 m 10 d
5-12-26 <i>051226</i>	INSPECTION DOCUMENT 26	SBJD			DAYS 04-Dec-2015 HRS 1456.7 LDG 1741		14			
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL	SBJD		SPECIAL (NDI): INSPECTION DOCUMENT 28 3-1640 0252			A/R			
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL	SBJD		SPECIAL (NDI): INSPECTION DOCUMENT 28 3-1640 0134			A/R			
B324000	DETAILED INSPECTION NOSE LANDING GEAR WHEEL			SPECIAL (NDI): INSPECTION DOCUMENT 28 3-1642 0076			A/R			
5-12-30 <i>051230</i>	INSPECTION DOCUMENT 30	KFXE			MTH 21-Jun-2016 HRS 1471.3 LDG 1749		48 1800		30-Jun-2020 3271.3	36 m 9 d 1732
5-12-31 <i>051231</i>	INSPECTION DOCUMENT 31	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		450		1989.3	450
5-12-32 <i>051232</i>	INSPECTION DOCUMENT 32	SBJD			MTH 08-Jan-2013 HRS 1388.4 LDG 1677		72 1800		31-Jan-2019 3477	19 m 10 d 1679
5-12-33 <i>051233</i>	INSPECTION DOCUMENT 33	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		36 900		31-May-2020 2439.3	35 m 10 d 900
5-12-34	INSPECTION DOCUMENT 34	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		6 450			
B243003	FUNCTIONAL CHECK MAIN SHIP BATTERY	KDXR		TELEDYNE GILL LEAD-ACID BATTERY (CAPACITY CHECK): INSPECTION DOCUMENT 34 7639-30LT G02908638	MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		6 450		30-Nov-2017 1989.3	5 m 9 d 450
5-12-35	INSPECTION DOCUMENT 35	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		6		30-Nov-2017	5 m 9 d
5-12-MA <i>0512MA</i>	INSPECTION DOCUMENT MA	SBJD			MTH 16-Aug-2012 HRS 1280.5 LDG 1510		500		1780.5	241.2
5-12-MB <i>0512MB</i>	INSPECTION DOCUMENT MB	SBJD			MTH 25-Feb-2011 HRS 887.3 LDG 931		950		1837.3	298
5-12-MC <i>0512MC</i>	INSPECTION DOCUMENT MC	*CF			MTH 28-Nov-2007 HRS 0		4000		4000	2460.7
5-12-MD <i>0512MD</i>	INSPECTION DOCUMENT MD	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		12		31-May-2018	11 m 10 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-ME <i>0512ME</i>	INSPECTION DOCUMENT ME	KDXR			MTH 29-Nov-2016 HRS 1515.8 LDG 1790		36 1400		30-Nov-2019 2915.8	29 m 9 d 1376.5
5-12-MF <i>0512MF</i>	INSPECTION DOCUMENT MF	*CF			MTH 28-Nov-2007 HRS 0		12000		12000	10460.7
5-12-MG <i>0512MG</i>	INSPECTION DOCUMENT MG	*CF			MTH 28-Nov-2007 HRS 0		5000		5000	3460.7
5-12-MH <i>0512MH</i>	INSPECTION DOCUMENT MH	*CF			MTH 28-Nov-2007 HRS 0		8250		8250	6710.7
5-12-MI <i>0512MI</i>	INSPECTION DOCUMENT MI	*CF			MTH 28-Nov-2007 HRS 0		12000		12000	10460.7
5-12-MJ <i>0512MJ</i>	INSPECTION DOCUMENT MJ	*CF			MTH 28-Nov-2007 HRS 0		10600		10600	9060.7
5-12-MK <i>0512MK</i>	INSPECTION DOCUMENT MK	*CF			MTH 28-Nov-2007 HRS 0		10400		10400	8860.7
080001	ACCOMPLISH AIRCRAFT WEIGHT AND BALANCE	SBJD			MTH 17-Apr-2014 HRS 1417.1 LDG 1719		A/R			
0521009A	ENVIRO SYSTEMS 12 MONTH INSPECTION	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		12		31-May-2018	11 m 10 d
262003A LEFT <i>262003 : L</i>	REPLACE FIRE EXT CARTRIDGE	SBJD		13083-5 09012018	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		72	3	31-Oct-2018	16 m 10 d
262003A RIGHT <i>262003 : R</i>	REPLACE FIRE EXT CARTRIDGE	SBJD		13083-5 09012018	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		72	3	31-Oct-2018	16 m 10 d
B351001 <i>051210 : OXY</i>	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST	SBJD		4441073-040 0324-041	MTH 11-Feb-2014		60		28-Feb-2019	20 m 7 d
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798		12 450		31-May-2018 1989.3	11 m 10 d 450
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KDXR			MTH 23-May-2017 HRS 1539.3 LDG 1798		12 450		31-May-2018 1989.3	11 m 10 d 450
710010 E1	COMPRESSOR WASH	SBJD			MTH 04-Dec-2015 HRS 1456.7 LDG 1741		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
710010 E2	COMPRESSOR WASH	SBJD			MTH 04-Dec-2015 HRS 1456.7 LDG 1741		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.										
720001A E1	ENGINE PRESERVATION	SBJD			MTH 07-Jul-2015 HRS 1456.7 LDG 1741		3			
PERFORMED PRESERVATION ON ENGINE LH, I.A.W EMM PRATT & WHITNEY CANADA PN 3072691 REV. 20.										
720001A E2	ENGINE PRESERVATION	SBJD			MTH 07-Jul-2015 HRS 1456.7 LDG 1741		3			
PERFORMED PRESERVATION ON ENGINE LH, I.A.W EMM PRATT & WHITNEY CANADA PN 3072691 REV. 20.										
720000 E1	PERFORM ENGINE OVERHAUL				MTH 28-Nov-2007 HRS 0		3500		3500	1960.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
720000 E2	PERFORM ENGINE OVERHAUL				MTH 28-Nov-2007 HRS 0		3500		3500	1960.7
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION *CF				MTH 28-Nov-2007 HRS 0	1	1750	1	1750	210.7
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION *CF				MTH 28-Nov-2007 HRS 84.9	1	1750	1	1834.9	295.6
720003 E1	INSPECT LOW UTILIZATION ENGINE *CF				MTH 28-Nov-2007		144		30-Nov-2019	29 m 9 d
720003 E2	INSPECT LOW UTILIZATION ENGINE *CF				MTH 28-Nov-2007		144		30-Nov-2019	29 m 9 d
720210 E1	BORESCOPE INSPECTION OF THE FUEL SHUTOFF CABLE WIRE CORE FOR BROKEN STRANDS WHERE THE WIRE CORE EXITS THE CABLE	SBJD			MTH 19-Apr-2012 HRS 1197.4 LDG 1381		12 450			
720210 E2	BORESCOPE INSPECTION OF THE FUEL SHUTOFF CABLE WIRE CORE FOR BROKEN STRANDS WHERE THE WIRE CORE EXITS THE CABLE	SBJD			MTH 19-Apr-2012 HRS 1197.4 LDG 1381		12 450			
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER				MTH HRS		1750		1750	210.7
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER				MTH HRS		1750		1834.9	295.6
731020 E1	CHECK/REPLACE FUEL FILTER ELEMENT KDXR				MTH 23-May-2017 HRS 1539.3 LDG 1798		12 900		31-May-2018 2439.3	11 m 10 d 900
731020 E2	CHECK/REPLACE FUEL FILTER ELEMENT KDXR				MTH 23-May-2017 HRS 1539.3 LDG 1798		12 900		31-May-2018 2439.3	11 m 10 d 900
731055 E1	REPLACE FUEL MANIFOLD			PN SN-UNKNOWN	MTH 28-Nov-2007 HRS 0		1750		1750	210.7
731055 E2	REPLACE FUEL MANIFOLD			35C4658-01 UNK2	MTH 28-Nov-2007 HRS 84.9		1750		1834.9	295.6
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN	MTH 28-Nov-2007 HRS 0		1750		1750	210.7
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH			PN SN-UNKNOWN	MTH 28-Nov-2007 HRS 84.9		1750		1834.9	295.6
772001 E1	FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS AND ASSEMBLY				MTH 28-Nov-2007 HRS 0		1750		1750	210.7
772001 E2	FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS AND ASSEMBLY				MTH 28-Nov-2007 HRS 84.9		1750		1834.9	295.6
790015 E1	REPLACE OIL FILTER ELEMENT SBJD				MTH 01-Oct-2010 HRS 806.7 LDG 864		900		1706.7	167.4
790015 E2	REPLACE OIL FILTER ELEMENT SBJD				MTH 25-Feb-2011 HRS 887.3 LDG 931		900		1787.3	248

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
794020 E1	REPLACE NO. 4 BEARING FRONT CARBON SEAL	*CF			MTH 28-Nov-2007 HRS 0		1750		1750	210.7
794020 E2	REPLACE NO. 4 BEARING FRONT CARBON SEAL	*CF			MTH 28-Nov-2007 HRS 84.9		1750		1834.9	295.6



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
212002	UNDER FLOOR BLOWER ASSY. *CF			0113-12 1260	MTH 28-Nov-2007		O/C			
213001	KAPS II CONTROLLER 9912661-6	*CF		52811-102 927	MTH 28-Nov-2007		O/C			
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7	*CF		52812-102 848	MTH 28-Nov-2007		O/C			
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7	*CF		52812-102 846	MTH 28-Nov-2007		O/C			
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14	ICT		1133610-4 160	MTH 14-Jul-2008 ACH 136		O/C	0		
215002	CONDENSOR ASSEMBLY 9912583-7	*CF		1134620-3 NSN	MTH 28-Nov-2007		O/C			
215003	RECEIVER DRYER ASSY 9912583-3	ICT		1134275-1 -	MTH 14-Jul-2008 ACH 136		O/C	0		
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7	*CF		1133300-1 173	MTH 28-Nov-2007		O/C			
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7	*CF		1133300-1 174	MTH 28-Nov-2007		O/C			
215005	VANE AXIAL BLOWER ASSY.			PN SN-UNKNOWN	MTH 28-Nov-2007		O/C	0		
215007	FREON A/C ASSY MOTOR SBJD			1134146-6 1486A	MTH 18-Mar-2013 HRS 1417.1 LDG 1719		O/C	4 0 0		
221001 AILERON	GSA 80 TORQUE SERVO *CF			011-00877-00 66305054	MTH 28-Nov-2007		O/C	0		
221001 RUDDER	GSA 80 TORQUE SERVO KMKY			011-00877-00 66306138	MTH 16-Nov-2016 HRS 1512.6 LDG 1790		O/C			
221002 ELEVATOR	GSA 81 TORQUE SERVO *CF			011-00878-10 71305031	MTH 28-Nov-2007		O/C			
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO *CF			011-00878-10 71305036	MTH 28-Nov-2007		O/C			
221003 AILERON	GSM 85A SERVO MOUNT *CF			011-01436-A2 10905012	MTH 28-Nov-2007		O/C			
221003 ELEVATOR	GSM 85A SERVO MOUNT *CF			011-01436-A0 11205016	MTH 28-Nov-2007		O/C			
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT *CF			011-01436-A1 11305008	MTH 28-Nov-2007		O/C			
221003 RUDDER	GSM 85 SERVO MOUNT SBJD			011-01436-A3 11005147	MTH 22-Aug-2012 HRS 1289.6 LDG 1521		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
221004	GMC 710 AFCS CONTROLLER	KFXE		011-01020-00 87805150	MTH 05-Aug-2016 HRS 1472.2 LDG 1750		O/C	0		
231002 NO. 1	GMA 1347D AUDIO PANEL	*CF		011-01257-00 48401231	MTH 28-Nov-2007		O/C			
231002 NO. 2	GMA 1347D AUDIO PANEL	SBJD		011-01257-00 48405488	MTH 25-Jun-2014 HRS 1420.1 LDG 1722		O/C			
231003 NO. 1	VHF COMM ANTENNA	*CF		VHF10-829 0105	MTH 28-Nov-2007		O/C			
231003 NO. 2	VHF COMM ANTENNA	KFXE		VHF10-829 2391	MTH 21-Jun-2016 HRS 1471.3 LDG 1749		O/C	0		0
243001 LEFT	DIGITAL GCU 9912682-1	ICT		GCSG550-4 1183H	MTH 18-Jan-2008 HRS 20		O/C	0		
243001 RIGHT	DIGITAL GCU 9912682-1	SBJD		GCSG550-4 1148H	MTH 11-Nov-2014 HRS 1420.1 LDG 1722		O/C			
243002	EMER INST BATTERY	KDXR		CBS24 00793	MTH 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		O/C			
243007	MAIN SHIP BATTERY	KFXE		7639-30LT G02908638	MTH 21-Jun-2016 HRS 1471.3 LDG 1749		O/C	0		0
243015	RELAY DISCONNECT BATTERY S3155-1	*CF		A-931F CP-67909	MTH 28-Nov-2007		O/C			
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	*CF		7018920-5 0224	MTH 28-Nov-2007		O/C			
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	*CF		7018920-5 0225	MTH 28-Nov-2007		O/C			
245003	FLAP CONTROL MODULE	*CF		7018916-9 0134	MTH 28-Nov-2007		O/C			
245005 LEFT	ICE PROTECTION CONTROL	*CF		7018917-9 0146	MTH 28-Nov-2007		O/C			
245005 RIGHT	ICE PROTECTION CONTROL	*CF		7018918-13 0121A	MTH 28-Nov-2007		O/C			
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL	*CF		7018919-9 0205	MTH 28-Nov-2007		O/C			
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL	*CF		7018919-9 0210	MTH 28-Nov-2007		O/C			
245008	DOOR MONITOR	SBJD		7018921-8 0411	MTH 28-Jul-2010 HRS 788.3 LDG 849		O/C	0		0

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
245009	LANDING GEAR MONITOR	TBA		7018923-12 0141	MTH 15-Jun-2008		O/C			
245010 LEFT	START CONTROL	*CF		7018924-5 0210	MTH 28-Nov-2007		O/C			
245010 RIGHT	START CONTROL	*CF		7018924-5 0211	MTH 28-Nov-2007		O/C			
245011	FLAP MONITOR	*CF		7018925-11 0160	MTH 28-Nov-2007		O/C			
245012 LEFT	SPEEDBRAKE ASSY	*CF		7018926-1 0240	MTH 28-Nov-2007		O/C			
245012 RIGHT	SPEEDBRAKE ASSY	*CF		7018926-1 0235	MTH 28-Nov-2007		O/C			
245013	DIAGNOSTIC UNIT	*CF		7018927-7 0178	MTH 28-Nov-2007		O/C			
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3	*CF		85-230-2 0722-559M2	MTH 28-Nov-2007		O/C			
251001	GLARESHIELD ASSEMBLY	*CF		4319027-13 98399-1	MTH 28-Nov-2007		O/C			
256001 NO. 1 <i>256001A : 1</i>	LIFE VEST	SBJD		3500-147 K0600124	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	10 0 0		
256001 NO. 2 <i>256001A : 2</i>	LIFE VEST	SBJD		3500-147 K0700195	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	10 0 0		
256001 NO. 3 <i>256001A : 3</i>	LIFE VEST	SBJD		3500-147 K0700230	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	10 0 0		
256001 NO. 4 <i>256001A : 4</i>	LIFE VEST	SBJD		3500-147 M0209659	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	10 0 0		
256001 NO. 5 <i>256001A : 5</i>	LIFE VEST	SBJD		3500-101P M0706917	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	10 0 0		
256001 NO. 6 <i>256001A : 6</i>	LIFE VEST	SBJD		3500-101P 00809762	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	10 0 0		
256002	ELT BATTERY	SBJD		452-0133 361883-003	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		60	0 0 0	30-Apr-2019	22 m 9 d
256004	ELT ANTENNA	*CF		110-340 159885	MTH 28-Nov-2007		O/C			
256007 <i>256001</i>	ELT PROCESSOR C406N	SBJD		453-5060 03886	MTH 12-Aug-2011 HRS 1024.6 LDG 1152		O/C		1024.6 1152	
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 208155	MTH 28-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 208160	MTH 28-Nov-2007		O/C			
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	*CF		30401102-2 57207B1	MTH 28-Nov-2007		O/C	0		
262003 LEFT	FIRE EXT CARTRIDGE	SBJD		13083-5 09012018	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		72	3 0 0	31-Oct-2018	16 m 10 d
Manufacture Date: 11-Oct-2012										
262003 RIGHT	FIRE EXT CARTRIDGE	SBJD		13083-5 09012018	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		72	3 0 0	31-Oct-2018	16 m 10 d
Manufacture Date: 11-Oct-2012										
262004	PORTABLE FIRE EXTINGUISHER	SBJD		C352TS Y-649981	MTH 17-Jan-2014		O/C	0		
271001 LEFT	CONTROL WHEEL ASSY	*CF		4319065-1 1157	MTH 28-Nov-2007		O/C			
271001 RIGHT	CONTROL WHEEL ASSY	*CF		4319065-2 1158	MTH 28-Nov-2007		O/C			
273001	RUDDER TRIM ACTUATOR 9912639-2	*CF		SYLC-53361-1 0103	MTH 28-Nov-2007		O/C			
273002	AILERON TRIM ACTUATOR 9912639-2	*CF		SYLC-53361-1 NSN	MTH 28-Nov-2007		O/C			
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1	*CF		MP50Y-1 080	MTH 28-Nov-2007		O/C			
275002 LEFT	FLAP ACTUATOR 9912640-1	SBJD		41013930-105 0231	MTH 25-Feb-2011 HRS 887.3 LDG 931		O/C	0 0 0		
275002 RIGHT	FLAP ACTUATOR 9912640-2	*CF		41013930-106 0148	MTH 28-Nov-2007		O/C			
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY	SBJD		9914344-59 0581	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	0 0 0		
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY	SBJD		9914344-59 0494	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	0 0 0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-1	SBJD		41014070-104 0620	MTH 12-May-2010 HRS 751.8 LDG 818		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR 9912641-1	SBJD		41014070-104 0150	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C			
282001 LEFT	PRIMARY EJECTOR 9912190-5	*CF		LR45300A 1BC31	MTH 28-Nov-2007		O/C			
282001 RIGHT	PRIMARY EJECTOR 9912190-5	*CF		LR45300A 1BC11	MTH 28-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
282002	TRANSFER VALVE 9914103-6	*CF		ZSV57 07-0201121	MTH 28-Nov-2007		O/C			
282003 LEFT	DC FUEL PUMP 9912553-1	*CF		1C7-23 C1228	MTH 28-Nov-2007		O/C			
282003 RIGHT	DC FUEL PUMP 9912553-1	*CF		1C7-23 C1268	MTH 28-Nov-2007		O/C			
282004 L1	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C118	MTH 28-Nov-2007		O/C			
282004 L2	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C120	MTH 28-Nov-2007		O/C			
282004 R1	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C158	MTH 28-Nov-2007		O/C			
282004 R2	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C243	MTH 28-Nov-2007		O/C			
282005 LEFT	VALVE-FUEL MOTOR 9912014-3	*CF		AV24B1507 AA119627	MTH 28-Nov-2007		O/C			
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3	*CF		AV24B1507 AA119626	MTH 28-Nov-2007		O/C			
284001 L1	FUEL PROBE 9912664-1	*CF		020-251-001 0205	MTH 28-Nov-2007		O/C			
284001 L2	FUEL PROBE 9912664-2	*CF		020-251-002 0149	MTH 28-Nov-2007		O/C			
284001 L3	FUEL PROBE 9912664-3	*CF		020-251-003 0205	MTH 28-Nov-2007		O/C			
284001 L4	FUEL PROBE 9912664-4	*CF		020-251-004 0210	MTH 28-Nov-2007		O/C			
284001 L5	FUEL PROBE 9912664-5	*CF		020-251-005 0187	MTH 28-Nov-2007		O/C			
284001 R1	FUEL PROBE 9912664-1	*CF		020-251-001 0204	MTH 28-Nov-2007		O/C			
284001 R2	FUEL PROBE 9912664-2	*CF		020-251-002 0211	MTH 28-Nov-2007		O/C			
284001 R3	FUEL PROBE 9912664-3	*CF		020-251-003 0201	MTH 28-Nov-2007		O/C			
284001 R4	FUEL PROBE 9912664-4	*CF		020-251-004 0211	MTH 28-Nov-2007		O/C			
284001 R5	FUEL PROBE 9912664-5	*CF		020-251-005 0202	MTH 28-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284002	SIGNAL CONDITIONER 9912664-6	LBG		367-350-001 1034	MTH 08-Apr-2008		O/C			
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2	*CF		HM50C-3 057B	MTH 28-Nov-2007 HRS 0		7000	0	7000	5460.7
291002	HYDRAULIC CHECK VALVE *CF			CV02-267 NSN	MTH 28-Nov-2007		O/C			
291003	HYDRAULIC SYS PRESSURE GAUGE *CF			19940933-1 -	MTH 28-Nov-2007		O/C			
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4	*CF		80665 NSN	MTH 28-Nov-2007		O/C			
291007	HYDRAULIC MANIFOLD 9912657-14	*CF		8257-3 0006	MTH 28-Nov-2007		O/C			
291008	HYDRAULIC RELIEF VALVE 9912657-2	*CF		2672 0006	MTH 28-Nov-2007		O/C			
291009	BRAKE PRESSURE SWITCH 9912657-3	*CF		80664 0011	MTH 28-Nov-2007		O/C			
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5	*CF		4251 NSN	MTH 28-Nov-2007		O/C			
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7	*CF		4252 NSN	MTH 28-Nov-2007		O/C			
291011	HYDRAULIC DUMP VALVE 9912657-15	*CF		9625-1 0009	MTH 28-Nov-2007		O/C			
291012	HYDRAULIC RESERVOIR ASSEMBLY *CF			7017005-24 NSN	MTH 28-Nov-2007		O/C			
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2	SBJD		7550-2 0120	MTH 18-Mar-2013 HRS 1417.1 LDG 1719		O/C			
301001 LEFT	WING DE-ICE BOOT 9912662-17	SBJD		P35-4D5317-17 MDDK840	MTH 12-Aug-2011 HRS 1024.6 LDG 1152		O/C	0	0	0
301001 RIGHT	WING DE-ICE BOOT 9912662-10	*CF		P35-4D5317-12 MZQS140	MTH 28-Nov-2007		O/C			
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT 9912662-3	*CF		P29S4D5317-05 MZPX150	MTH 28-Nov-2007		O/C			
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT 9912662-4	KFXE		P29S4D5317-06 NDI9630	MTH 21-Jun-2016 HRS 1471.3 LDG 1749		O/C	0	0	0
301004 L1	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4404A	MTH 28-Nov-2007		O/C			
301004 L2	DE-ICE PRESSURE SWITCH *CF			1106P55-1 4426A	MTH 28-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301004 L3	DE-ICE PRESSURE SWITCH	KFXE		1106P55-1 11066A	MTH 21-Jun-2016 HRS 1471.3 LDG 1749		O/C	0		
301004 R1	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4418A	MTH 28-Nov-2007		O/C			
301004 R2	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4403A	MTH 28-Nov-2007		O/C			
301004 R3	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4416A	MTH 28-Nov-2007		O/C			
301004	VERT DE-ICE BOOT 9912662-13	*CF		P29S4D5317-13 MZSL370	MTH 28-Nov-2007		O/C			
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY	*CF		5285-00-3 1295	MTH 28-Nov-2007		O/C			
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY	*CF		5285-00-3 1216	MTH 28-Nov-2007		O/C			
302002 LEFT	TEMP SWITCH	*CF		1173T0759 4144	MTH 28-Nov-2007		O/C			
302002 RIGHT	TEMP SWITCH	*CF		1173T0759 4114	MTH 28-Nov-2007		O/C			
304001 L1	DE-ICE VALVE	*CF		3D2353-06 N072817	MTH 28-Nov-2007		O/C			
304001 L2	DE-ICE VALVE	*CF		3D2353-06 N072410	MTH 28-Nov-2007		O/C			
304002 LEFT	WINDSHIELD CONTROLLER	KSWF		7098108-1 0146A	MTH 04-Nov-2016 HRS 1508.1 LDG 1786		O/C	4		
304002 RIGHT	WINDSHIELD CONTROLLER	*CF		7018108-25 0118	MTH 28-Nov-2007		O/C	0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY	*CF		7041020-5 40	MTH 28-Nov-2007 LDG 0	1	20000	0	20001	18203
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY	*CF		7041020-6 38	MTH 28-Nov-2007 LDG 0	1	20000	0	20001	18203
321001	NOSE LANDING GEAR TRUNNION	*CF		7042020-1 39	MTH 28-Nov-2007		O/C			
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY	SBJD		7041050-3 44	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		12000	1719	12000	10202
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY	SBJD		7041050-3 43	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		12000	1719	12000	10202
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY	*CF		7041030-1 44	MTH 28-Nov-2007 LDG 0	1	20000	0	20001	18203

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY	*CF		7041030-2 44	MTH 28-Nov-2007 LDG 0	1	20000	0	20001	18203
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK	*CF		6327504-6 1703	MTH 28-Nov-2007		O/C			
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK	*CF		6327504-6 1698	MTH 28-Nov-2007		O/C			
322002	NOSE GEAR FORK & PISTON ASSEMBLY	*CF		7042040-1 NSN	MTH 28-Nov-2007		O/C			
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR	*CF		9912655-1 FA100036-001 FA100036-1-0070	MTH 28-Nov-2007 LDG 0	1	12000	0	12001	10203
322010 LEFT	MAIN LANDING GEAR HYDRAULIC ACTUATOR	*CF		9912653-5 FA100104-001 FA100104-1-0048	MTH 28-Nov-2007 LDG 0	1	12000	0	12001	10203
322010 RIGHT	MAIN LANDING GEAR HYDRAULIC ACTUATOR	*CF		9912653-6 FA100105-001 FA100105-1-0052	MTH 28-Nov-2007 LDG 0	1	12000	0	12001	10203
322011	NOSE LANDING GEAR ACTUATOR	*CF		9912654-2 FA100087-001 FA100087-1-0086	MTH 28-Nov-2007 LDG 0	1	12000	0	12001	10203
322202	SHIMMY DAMPER	*CF		7042030-2 NSN	MTH 28-Nov-2007		O/C			
322205 NOSE	LANDING GEAR STRUT ASSEMBLY	*CF		7042010-4 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
322206 NOSE	LANDING GEAR DRAG BRACE ASSY	*CF		7042120-1 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
323001 LEFT	LANDING GEAR ASSEMBLY	*CF		7041010-5 40	MTH 28-Nov-2007		O/C			
323001 RIGHT	LANDING GEAR ASSEMBLY	*CF		7041010-6 38	MTH 28-Nov-2007		O/C			
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE	*CF		9914678-3 40005369-2 5368	MTH 28-Nov-2007		288	7	30-Apr-2031	166 m 9 d
Manufacture Date: 30-Apr-2007										
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE	*CF		9914678-4 40005399-1 5440	MTH 28-Nov-2007		288	6	31-May-2031	167 m 10 d
Manufacture Date: 31-May-2007										
323003	EMER BLOW DOWN BTL PRESSURE GAUGE	*CF		19940931-1 -	MTH 28-Nov-2007		O/C			
324001 LEFT	MAIN LANDING GEAR TIRE	SBJD		9912646-1 021-523-0 3061S00197	MTH 16-Oct-2013 HRS 1417.1 LDG 1719		O/C	0		
324001 RIGHT	MAIN LANDING GEAR TIRE	SBJD		9912646-1 021-523-0 3065S00222	MTH 16-Oct-2013 HRS 1417.1 LDG 1719		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324002	NOSE LANDING GEAR TIRE 9912649-1	SBJD		079-606-0 2082S00469	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		O/C	0 0 0		
324003 LEFT	MAIN LANDING GEAR WHEEL 9912645-1	SBJD		3-1640 0252	MTH 16-Oct-2013 HRS 1417.1 LDG 1719		O/C			
324003 RIGHT	MAIN LANDING GEAR WHEEL 9912645-1	SBJD		3-1640 0134	MTH 16-Oct-2013 HRS 1417.1 LDG 1719		O/C			
324004	NOSE LANDING GEAR WHEEL 9912648-1	SBJD		3-1642 0076	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		O/C		1394	
324005 LEFT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KDXR		2-1706-1 0899	MTH 13-Dec-2016 HRS 1515.8 LDG 1790		O/C	0 0 0		
324005 RIGHT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KDXR		2-1706-1 1024	MTH 13-Dec-2016 HRS 1515.8 LDG 1790		O/C	0 0 0		
324006 LEFT	SHUTTLE VALVE 9914689-4	*CF		5145-1 NSN	MTH 28-Nov-2007		O/C			
324006 RIGHT	SHUTTLE VALVE 9914689-4	*CF		5145-1 NSN	MTH 28-Nov-2007		O/C			
324007	BRAKE METERING VALVE 9912650-9	*CF		84-75 0082	MTH 28-Nov-2007		O/C			
324101 LEFT	WHEEL SPEED SENSOR 9912650-5	*CF		466-23-1 NSN	MTH 28-Nov-2007		O/C			
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5	*CF		466-23-1 NSN	MTH 28-Nov-2007		O/C			
324101	PARKING BRAKE VALVE 9912388-10	*CF		98433-1 0079	MTH 28-Nov-2007		O/C			
324102	ANTISKID CONTROL UNIT 9912650-1	*CF		556-3 302820136	MTH 28-Nov-2007		O/C			
324103	ANTISKID CONTROL VALVE 9912650-6	*CF		211-134-1 0025	MTH 28-Nov-2007		O/C			
324104	EMERGENCY BRAKE VALVE 9912651-1	*CF		72298 0073	MTH 28-Nov-2007		O/C			
324105	EMER BRAKE BOTTLE PRESSURE GAUGE *CF			19940931-1 -	MTH 28-Nov-2007		O/C			
325001	BUNGE ASSEMBLY *CF			7042072-9 NSN	MTH 28-Nov-2007		O/C			
334001 LEFT	POWER SUPPLY 9912677-3	*CF		82004-1 000236	MTH 28-Nov-2007		O/C			
334001 RIGHT	POWER SUPPLY 9912677-3	*CF		82004-1 000247	MTH 28-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
334002	GROUND RECOGNITION LIGHT 9912679-3	*CF		84003-2 000100	MTH 28-Nov-2007		O/C			
334003 LEFT	ANTI-COLLISION LIGHT 9912679-1	*CF		84005-1 000186	MTH 28-Nov-2007 HRS 0	1	8000	0	8001	6461.7
334003 RIGHT	ANTI-COLLISION LIGHT 9912679-2	*CF		84005-2 000179	MTH 28-Nov-2007 HRS 0	1	8000	0	8001	6461.7
341001	SWAAT UNIT 9912689-1	*CF		0863B2 105	MTH 28-Nov-2007		O/C			
341002 NO. 1	GDC 74B AIRDATA SYSTEM 9912679-1	*CF		011-01110-00 43800527	MTH 28-Nov-2007		O/C			
341002 NO. 2	GDC 74B AIRDATA SYSTEM 9912679-1	SBJD		011-01110-00 43805931	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		O/C			
341003 NO. 1	GTP 59 OAT PROBE SYSTEM 9912679-1	*CF	1	011-00978-00 47908739	MTH 28-Nov-2007		O/C			
341003 NO. 2	GTP 59 OAT PROBE SYSTEM 9912679-1	*CF	1	011-00978-00 47908601	MTH 28-Nov-2007		O/C			
341004 LEFT	PITOT PROBE 9912678-1	*CF		0851LN 254829	MTH 28-Nov-2007		O/C			
341004 RIGHT	PITOT PROBE 9912678-1	*CF		0851LN 254756	MTH 28-Nov-2007		O/C			
342001 STANDBY	ALTIMETER S3100-465	*CF		162350-1161 176282B	MTH 28-Nov-2007		O/C			
342002 AIRSPEED	INDICATOR 9912678-1	SBJD		261440-1143 295469A	MTH 12-Aug-2011 HRS 1024.6 LDG 1152		O/C	0 0 0		
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE 9912678-1	*CF		011-00831-00 46706515	MTH 28-Nov-2007		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE 9912678-1	*CF		011-00831-00 46706541	MTH 28-Nov-2007		O/C			
342003	MAGNETIC COMPASS 9912678-1	SBJD		S2800-821 N/A	MTH 12-Aug-2011 HRS 1024.6 LDG 1152		O/C	0 0 0		
342004 NO. 1	GDU 1040A DISPLAY 9912678-1	*CF		011-00916-00 86800519	MTH 28-Nov-2007		O/C			
342004 NO. 2	GDU 1040A DISPLAY 9912678-1	*CF		011-00916-00 86800514	MTH 28-Nov-2007		O/C			
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517	SBJD		011-00868-10 42000361	MTH 25-Feb-2011 HRS 887.3 LDG 931		O/C	7		
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517	SBJD		011-00868-10 42006838	MTH 27-Jan-2011 HRS 887.3 LDG 931		O/C	508.3		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342006 NO. 1	GMU 44 MAGNETOMETER	SBJD		011-00870-00 47510696	MTH 25-Feb-2011 HRS 887.3 LDG 931		O/C	10		
342006 NO. 2	GMU 44 MAGNETOMETER	SBJD		011-00870-00 47505642	MTH 25-Feb-2011 HRS 887.3 LDG 931		O/C	5		
342007	GDU 1500 MFD UNIT	*CF		011-01108-00 43200711	MTH 28-Nov-2007		O/C			
342008	ATTITUDE INDICATOR S3100-513	*CF		4200-21 J07-11221	MTH 28-Nov-2007		O/C			
344001	GWX 68 WEATHER RADAR	SBJD		011-00883-20 47202590	MTH 12-Aug-2011 HRS 1024.6 LDG 1152		O/C			
344002	GDL 69 WEATHER DATA LINK	*CF		011-00987-00 47758129	MTH 28-Nov-2007		O/C			
345001	GPS/WAAS/XM ANTENNA	*CF		013-00245-00 5009	MTH 28-Nov-2007		O/C			
345002 RIGHT	TRANSPONDER	*CF		011-00779-01 84805021	MTH 28-Nov-2007		O/C			
345003 LEFT	TRANSPONDER	*CF		011-00779-01 84805014	MTH 28-Nov-2007		O/C			
345004	GCU 475 FLIGHT MGMT CONTROL UNIT	KFXE		011-01054-00 27000126	MTH 05-Aug-2016 HRS 1472.2 LDG 1750		O/C	0 0 0		
345005	ADF RECEIVER	*CF		013-00166-00 NSN	MTH 28-Nov-2007		O/C			
345006	ADF ANTENNA	*CF		013-00165-00 3124	MTH 28-Nov-2007		O/C			
345007	MARKER BEACON ANTENNA	*CF		MB10-754-2 0059	MTH 28-Nov-2007		O/C			
345008	GLIDE SLOPE ANTENNA	*CF		RGS10-48 12358	MTH 28-Nov-2007		O/C			
345009 LEFT	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 0523	MTH 28-Nov-2007		O/C			
345009 RIGHT	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 0505	MTH 28-Nov-2007		O/C			
345009 UPPER	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 0503	MTH 28-Nov-2007		O/C			
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 0493	MTH 28-Nov-2007		O/C			
345010	VOR/LOC ANTENNA	*CF		VT10-767-3 0374	MTH 28-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345011	KN63 DME TRANSCEIVER	*CF	7	066-01070-0001 31205	MTH 28-Nov-2007		O/C			
345013	RMI CONVERTER	*CF		013-00167-00 NSN	MTH 28-Nov-2007		O/C			
345014	GPS/WAAS/ ANTENNA	*CF		013-00244-00 5072	MTH 28-Nov-2007		O/C			
345015	DME ANTENNA	*CF		L10-611-14 0511	MTH 28-Nov-2007		O/C			
346010	TAS PROCESSOR	*CF		066-01152-0101 KTA810-1596	MTH 28-Nov-2007		O/C			
346011 BOTTOM	TAS ANTENNA	*CF		L10-611-14 0511	MTH 28-Nov-2007		O/C			
346011 TOP	TAS ANTENNA	*CF		071-01599-0100 NSN	MTH 28-Nov-2007		O/C			
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT	HUR		010-00386-10 15W005275	MTH 15-Feb-2008 HRS 85		O/C	0		
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT	*CF		011-01105-01 15W005068	MTH 28-Nov-2007		O/C			
350001	OXYGEN BOTTLE	*CF		4441073-040 0324-041	MTH 28-Nov-2007		180	10	31-Jan-2022	55 m 10 d
Manufacture Date: 31-Jan-2007										
350002	OXYGEN PRESSURE GAUGE C668512-0101	*CF		MD97-1 E07-10094	MTH 28-Nov-2007		O/C			
351001 LEFT	CREW OXYGEN MASK 9914067-41	SBJD		MC10-16-101 SE52371	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		72	4	31-Dec-2019	30 m 10 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41	SBJD		MC10-16-101 120201	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		72	3	31-Jan-2020	31 m 10 d
361001 LEFT	PRECOOLER 9914402-7	*CF		8315-2 T0103	MTH 28-Nov-2007		O/C			
361001 RIGHT	PRECOOLER 9914402-7	*CF		8315-2 T0113	MTH 28-Nov-2007		O/C			
361002 LEFT	VARIABLE VENTURI VALVE ASSY	*CF		2601-34 1807	MTH 28-Nov-2007		O/C			
361002 RIGHT	VARIABLE VENTURI VALVE ASSY	*CF		2601-34 1786	MTH 28-Nov-2007		O/C			
361003	SERVICE AIR REGULATOR ASSY 9912510-2	*CF		1H75-23 6BC24	MTH 28-Nov-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361004 LEFT	B/A SHUTOFF VALVE	*CF		5253-00-1 0125A	MTH 28-Nov-2007		O/C			
361004 RIGHT	B/A SHUTOFF VALVE	*CF		5253-00-1 0126A	MTH 28-Nov-2007		O/C			
361101 R1	DE-ICE VALVE	*CF		3D2353-06 N064790	MTH 28-Nov-2007		O/C			
361101 R2	DE-ICE VALVE	*CF		3D2353-06 N072490	MTH 28-Nov-2007		O/C			
522001	CABIN DOOR SEAL 9912674-3	SBJD		S-22560-3 N/A	MTH 18-Mar-2013 HRS 1417.1 LDG 1719		O/C	0 0 0		
522002	ESCAPE HATCH SEAL 9912675-1	*CF		S-22561 056	MTH 28-Nov-2007		O/C			
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-3 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-4 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-11 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-10 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
534101 FWD	ENGINE BEAM	*CF		7012061-3 0046	MTH 28-Nov-2007		O/C			
552001 LEFT	ELEVATOR ASSEMBLY	*CF		7034001-7 0000024	MTH 28-Nov-2007		O/C			
552001 RIGHT	ELEVATOR ASSEMBLY	*CF		7034001-8 0000025	MTH 28-Nov-2007		O/C			
553001	VERTICAL STABILIZER ASSY	*CF		7031001-801-7 -	MTH 28-Nov-2007		O/C			
561001 LEFT	WINDSHIELD 9912745-5	*CF		P03100-5 000106	MTH 28-Nov-2007		O/C			
561001 RIGHT	WINDSHIELD 9912745-6	*CF		P03100-6 000109	MTH 28-Nov-2007		O/C			
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1	*CF		93310-1 1195	MTH 28-Nov-2007		O/C			
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2	*CF		93310-2 1186	MTH 28-Nov-2007		O/C			
562003 L1	CABIN WINDOW 9912747-13	SBJD		93320-13 1049	MTH 10-Aug-2010 HRS 788.3 LDG 849		O/C	0 0 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
562003 L2	CABIN WINDOW 9912747-13	SBJD		93320-13 1052	MTH 10-Aug-2010 HRS 788.3 LDG 849		O/C	0		
562003 L3	CABIN WINDOW 9912747-13	SBJD		93320-13 1053	MTH 10-Aug-2010 HRS 788.3 LDG 849		O/C	0		
562003 R1	CABIN WINDOW 9912747-13	SBJD		93320-13 1054	MTH 10-Aug-2010 HRS 788.3 LDG 849		O/C	0		
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-13	SBJD		93320-13 1055	MTH 10-Aug-2010 HRS 788.3 LDG 849		O/C	0		
562003 R3	CABIN WINDOW 9912747-13	SBJD		93320-13 1073	MTH 10-Aug-2010 HRS 788.3 LDG 849		O/C	0		
572001 LEFT WING	FWD SPAR	*CF		7022022-1 45468	MTH 28-Nov-2007		O/C			
572001 RIGHT WING	FWD SPAR	*CF		7022022-2 32189	MTH 28-Nov-2007		O/C			
572002 LEFT WING	REAR SPAR	*CF		7022032-3 32307	MTH 28-Nov-2007		O/C			
572002 RIGHT WING	REAR SPAR	*CF		7022032-4 32308	MTH 28-Nov-2007		O/C			
572003 LEFT WING	MAIN SPAR	*CF		7022027-1 32305	MTH 28-Nov-2007		O/C			
572003 RIGHT WING	MAIN SPAR	*CF		7022027-2 32306	MTH 28-Nov-2007		O/C			
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-5 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-6 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-9 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-10 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-5 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-6 NSN	MTH 28-Nov-2007 LDG 0		20000	0	20000	18202
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1	*CF		7051001-1 24	MTH 28-Nov-2007		O/C			
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0271	MTH 28-Nov-2007 HRS 0	1	4000	0	4001	2461.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0263	MTH 28-Nov-2007 HRS 0	1	4000	0	4001	2461.7
712001 RIGHT	ENG CHANNEL-FWD MOUNT	*CF		7051001-2 70	MTH 28-Nov-2007		O/C			
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0252	MTH 28-Nov-2007 HRS 0	1	4000	0	4001	2461.7
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0275	MTH 28-Nov-2007 HRS 0	1	4000	0	4001	2461.7
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK1685	MTH 28-Nov-2007 HRS 0	1	8000	0	8001	6461.7
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK1687	MTH 28-Nov-2007 HRS 0	1	8000	0	8001	6461.7
712003 AFT	ENGINE BEAM	*CF		7012066-2 0046	MTH 28-Nov-2007		O/C			
712003 LEFT	AFT ENGINE MOUNT CHANNEL	*CF		7051001-3 21	MTH 28-Nov-2007		O/C			
712003 RIGHT	AFT ENGINE MOUNT CHANNEL	*CF		7051001-4 54	MTH 28-Nov-2007		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	*CF		35C0510-01 LB0098	MTH 28-Nov-2007		E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	SBJD		35C0510-01 LB0096	MTH 25-Feb-2011 HRS 887.3 LDG 931		E/C	806.7		
720010 E1	FAN ROTOR	*CF		35C1940-01 TXA1B3285	MTH 28-Nov-2007 LDG 80	1	10500	0	10581	8783
720010 E2	FAN ROTOR	*CF		35C1940-01 TXA1B3069	MTH 28-Nov-2007 LDG 155	1	10500	0	10656	8858
721010 E1	HP TURBINE DISK	*CF		35C2311-01 A0026EWY	MTH 28-Nov-2007 LDG 80	1	5250	0	5331	3533
721010 E2	HP TURBINE DISK	*CF		35C2311-01 A0026EX4	MTH 28-Nov-2007 LDG 155	1	5250	0	5406	3608
721020 E1	LP TURBINE DISK	*CF		35C2372-01 A0028B20	MTH 28-Nov-2007 LDG 80	1	10500	0	10581	8783
721020 E2	LP TURBINE DISK	*CF		35C2372-01 A0027218	MTH 28-Nov-2007 LDG 155	1	10500	0	10656	8858
723010 E1	IMPELLER AND SHAFT ASSEMBLY	*CF		35C4888-01 A0026T06	MTH 28-Nov-2007 LDG 80	1	10500	0	10581	8783
723010 E2	IMPELLER AND SHAFT ASSEMBLY	*CF		35C3656-01 AAPPXNN2026	MTH 28-Nov-2007 LDG 155	1	10500	0	10656	8858

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
725010 E1	HP COMPRESSOR ROTOR	*CF		35C3661-01 TXA1B2299	MTH 28-Nov-2007 LDG 80	1	10500	0	10581	8783
725010 E2	HP COMPRESSOR ROTOR	*CF		35C3661-01 TXA1B2298	MTH 28-Nov-2007 LDG 155	1	10500	0	10656	8858
726010 E1	AGB STARTER MAGNETIC SEAL			PN SN-UNKNOWN	MTH 28-Nov-2007 HRS 0		1750	0	1750	210.7
726010 E2	AGB STARTER MAGNETIC SEAL			PN SN-UNKNOWN	MTH 28-Nov-2007 HRS 84.9		1750	0	1834.9	295.6
730001 LEFT	ENGINE FUEL PRESSURE SWITCH 9912033-2	*CF		1103P0448 7731	MTH 28-Nov-2007		O/C			
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH 9912033-2	*CF		1103P0448 7930	MTH 28-Nov-2007		O/C			
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1	*CF		TFF1573-4 0650-006	MTH 28-Nov-2007		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9912417-1	*CF		TFF1573-4 0723-017	MTH 28-Nov-2007		O/C			
732101 E1	FUEL METERING UNIT	*CF		35C0794-03 15276395	MTH 28-Nov-2007		O/C			
732101 E2	FUEL METERING UNIT	*CF		35C0794-03 15280263	MTH 28-Nov-2007		O/C			
741001 E1	IGNITION EXCITER	*CF		35C3895-01 15226815	MTH 28-Nov-2007		O/C			
741001 E2	IGNITION EXCITER	*CF		35C3895-01 15276069	MTH 28-Nov-2007		O/C			
741002 E1 LEFT	IGNITER CABLE	*CF		35C0844-01 NSN	MTH 28-Nov-2007		O/C			
741002 E2 LEFT	IGNITER CABLE	*CF		35C0844-01 NSN	MTH 28-Nov-2007		O/C			
741003 E1 RIGHT	IGNITER CABLE	*CF		35C0799-01 NSN	MTH 28-Nov-2007		O/C			
741003 E2 RIGHT	IGNITER CABLE	*CF		35C0799-01 NSN	MTH 28-Nov-2007		O/C			
741004 E1 INBOARD	SPARK IGNITER	SBJD		35C2353-02 N/A	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		O/C	0		
741004 E2 INBOARD	SPARK IGNITER	SBJD		35C2353-02 N/A	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		O/C	0		
741005 E1 OUTBOARD	SPARK IGNITER	ICT		35C2353-01 WDA5911	MTH 03-Sep-2008 HRS 339		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
741005 E2 OUTBOARD	SPARK IGNITER	SBJD		35C2353-02 N/A	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		O/C	0		
751003 E1	BLEED VALVE ACTUATOR	*CF		35C2851-01 15240602	MTH 28-Nov-2007		O/C			
751003 E2	BLEED VALVE ACTUATOR	*CF		35C2851-01 15288809	MTH 28-Nov-2007		O/C			
761001 E1	FADEC 9912637-2	SBJD		35C4035-03 07-267	MTH 25-Feb-2011 HRS 887.3 LDG 931		O/C			
761001 E2	FADEC 9912637-2	SBJD		35C4035-03 07-201	MTH 25-Feb-2011 HRS 887.3 LDG 931		O/C			
791001 E1	FUEL TO OIL HEAT EXCHANGER	*CF		35C3778-01 WA29944	MTH 28-Nov-2007		O/C			
791001 E2	FUEL TO OIL HEAT EXCHANGER	*CF		35C3778-01 WA29936	MTH 28-Nov-2007		O/C			
793001 E1	OIL TEMP SENSOR	*CF		102-00083 05980	MTH 28-Nov-2007		O/C			
793001 E2	OIL TEMP SENSOR	*CF		102-00083 06101	MTH 28-Nov-2007		O/C			
793002 E1	OIL PRESSURE TRANSMITTER	*CF		APTE-304A-250G 7390-10-285	MTH 28-Nov-2007		O/C			
793002 E2	OIL PRESSURE TRANSMITTER	*CF		APTE-304A-250G 7473-5-420	MTH 28-Nov-2007		O/C			
793010 E1	CHIP COLLECTOR			PN SN-UNKNOWN	MTH 28-Nov-2007		O/C	0		
793010 E2	CHIP COLLECTOR			PN SN-UNKNOWN	MTH 28-Nov-2007		O/C	0		
801000 LEFT	STARTER GENERATOR 9912676-1	SBJD		MG94E-1 601B	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		1500			?
801000 RIGHT	STARTER GENERATOR 9912676-1	SBJD		MG94E-1 702B	MTH 08-Jan-2013 HRS 1388.4 LDG 1677		1500	0	2888.4	1349.1



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2) INFORMATIONAL									
MOC :										
SL CIL-99-03 REV 01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)									
		SBJD		RECOMMENDED	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED WITH CIL-99-03 R1 ACCORDING TO INSTRUCTIONS PARAGRAPH 03 TABLE 02 OF THIS CIL AND CPCP PROGRAM CESSNA 510. NO DISCREPANCY FOUND.										
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01) RECOMMENDED									
MOC :										
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW INFORMATIONAL									
MOC :										
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL									
MOC :										
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS									
		SBJD		RECOMMENDED	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		-			N/A
MOC : NOT APPLICABLE - VERIFIED CIL-99-02 ACCORDING TO PARAGRAPH "COMPLIANCE" OF THIS CIL. NO ACTION REQUIRED BECAUSE THE AIRCRAFT IS NOT OPERATED IN EUROPEAN AIRPORT WITH RUNWAY TREATED WITH FLUID ANTI-ICE RDI.										
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL									
MOC :										
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05) INFORMATIONAL									
MOC :										
SL 510-21-01 21SL-01	COMPRESSOR ISOLATOR MOUNT INSPECTION SBJD RECOMMENDED									
					MTH 17-Apr-2014 HRS 1417.1 LDG 1719		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED WITH SL510-21-01 ACCORDING TO PARAGRAPHS 01, 02, 03 AND 05 OF THIS SL. PERFORMED COMPRESSOR ISOLATOR MOUNT INSPECTION. CHECKED OK.										
SL 510-21-02 REV 01	CABIN ALTITUDE MODULE INSPECTION MANDATORY									
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO -0061 THRU -0181.										
ASL 510-22-01 22ASL01	AUTOPILOT SERVO GUARD PIN INSPECTION BJD MANDATORY									
					MTH 16-Dec-2009 HRS 590		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT OPTIONAL						A/R			
MOC :										
SL 510-24-03 24SL-03	CREW ALERTING SYSTEM (CAS) ELECTRICAL WIRING INSPECTION	BJD		MANDATORY	MTH 17-Jul-2009 HRS 445		A/R			Complete
MOC : COMPLIED WITH										
SL 510-24-06 24SL-06	FUSE LIMITER INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-24-06 - ELECTRICAL POWER - FUSE LIMITER INSPECTION, ACCORDING TO INSTRUCTIONS PARAGRAPH 1 THRU 5.										
SL 510-24-08 REV 01	STARTER/GENERATOR INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-24-08 R1 - ELECTRICAL POWER - STARTER/GENERATOR INSPECTION, ACCORDING TO INSTRUCTIONS PARAGRAPH 1 THRU 5.										
SL 510-24-08 24SL-08	STARTER/GENERATOR INSPECTION (SUPERSEDED BY SL510-24-08 REV 01)			MANDATORY	MTH	70	A/R			
MOC :										
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION MANDATORY				MTH		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.										
SL 510-24-11 REV 01	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION MANDATORY				MTH		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER -										
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01)			MANDATORY			A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0153 THRU 51-0279, -0281 THRU -0285, -0291 THRU -0294, AND -0296 ONLY.										
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION MANDATORY				MTH		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0253 THRU 510-0323 ONLY.										
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION	SBJD		MANDATORY	MTH 12-Aug-2011 HRS 1024.6 LDG 1152		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED WITH SL510-24-13 "THROTTLE QUADRANT WIRE BUNDLE INSPECTION" ACCORDING TO INSTRUCTIONS CONTAINED IN PARAGRAPHS (01 THROUGH 10) THIS SL.										
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01)	KSWF		MANDATORY	DAYS 15-Oct-2016 HRS 1500 LDG 1786		-			Complete
MOC : COMPLIED WITH										
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT OPTIONAL						A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER			DISCRETIONARY			A/R			
	MOC :									
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION	SBJD		MANDATORY	DAYS 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SL510-25-02 - EQUIPMENT/FURNISHINGS - CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION, ACCORDING TO INSTRUCTIONS PARAGRAPH 1, 2 AND 3.									
SB 510-27-01 27SB-01	AILERON SHIELD SEALANT REVISION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SB 510-27-01 - FLIGHT CONTROLS - AILERON SHIELD SEALANT REVISION, ACCORDING TO INSTRUCTIONS PARAGRAPH 2.									
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION	SBJD		RECOMMENDED	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED WITH SB 510-27-02 ACCORDING TO PARAGRAPHS 01 TO 16 OF THIS SB. APPPLIED KIT P/N SB510-27-02 (NEW - FORM 8130-3 # 4109455 ISSUED BY CESSNA AIRCRAFT COMPANY ON 01/30/2014), IAW SB INSTRUCTIONS. CHECKED OK.									
SL 510-27-01 27SL-01	FLAP ACTUATOR INSTALLATION SETSCREW INSPECTION	SBJD		RECOMMENDED	MTH 14-Jul-2008 HRS 276.6 LDG 279		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SL510-27-01, FLAP ACTUATOR INSTALLATION SETSCREW INSPECTION. ACCOMPLISHED FLAP ACT SETSCREW PRIME AND BOND.									
SL 510-27-02 27SL-02	CONTROL YOKE ASSEMBLY TIE STRAP INSPECTION	BJD		MANDATORY	MTH 17-Jul-2009 HRS 445		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-27-05 27SL-05	FLAP ACTUATOR INSPECTION	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 653.5 LDG 683		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SL 510-27-05 (FLIGHT CONTROLS - FLAP ACTUATOR INSPECTION), I.A.W. INSTRUCTIONS ON SL. NO DISCREPANCY WAS FOUND.									
SB 510-28-02 28SB-02	LOCKING FUEL CAP INSTALLATION	ICT		OPTIONAL	MTH 27-Jul-2008 HRS 302		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-28-01 28SL-01	LEFT AND RIGHT FUEL PROBE WIRE BUNDLE ASSEMBLY INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SL510-28-01 - FUEL - LEFT AND RIGHT FUEL PROBE WIRE BUNDLE ASSEMBLY INSPECTION, ACCORDING TO PARAGRAPH 1 THRU 6.									
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT			DISCRETIONARY			-			
	MOC :									
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT			DISCRETIONARY			A/R			
	MOC :									
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT			MANDATORY	MTH		A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE C/W IN PRODUCTION SERIAL NUMBERS -0041 AND ON.									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION	SBJD		MANDATORY	MTH 17-Apr-2014 HRS 1417.1 LDG 1719	-				Complete
MOC : COMPLIED WITH - ACCOMPLISHED WITH SB510-30-05 ACCORDING TO PARAGRAPHS 01, 02, 03(A-1), 04 AND 05 OF THIS SB. CHECKED OK.										
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT			RECOMMENDED		-				
MOC :										
ASL 510-30-02 30ASL02	WATER SEPARATOR DRAIN CAP	ICT		MANDATORY	MTH 14-Jul-2008 HRS 276		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES									
INFORMATIONAL										
MOC :										
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)						A/R			
INFORMATIONAL										
MOC :										
SB 510-31-01 31SB-01	MASTER CAUTION WARNING LIGHT WIRING MODIFICATION			DISCRETIONARY	MTH		A/R			
MOC :										
SL 510-31-03	COCKPIT SWITCH WIRE BUNDLE ASSEMBLY (WBA) INSPECTION			MANDATORY	MTH		A/R			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO AIRCRAFT SERIAL NUMBERS -0156 THRU -0164, -0167 THRU -0191, -0193 THRU -0215, -0218 THRU -0220, -0223, -0225 THRU -0227.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION									
INFORMATIONAL										
MOC :										
SL 510-32-02 REV 01 32SL-02 : 510R1	EMERGENCY GEAR RELEASE INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-32-02R1 - LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION, ACCORDING TO INSTRUCTIONS PARAGRAPH 1.										
SL 510-32-03 32SL-03	RIGHT BRAKE STOP BRACKET INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-32-03 - LANDING GEAR - RIGHT BRAKE STOP BRACKET INSPECTION, ACCORDING TO PARAGRAPH 1 THRU 4(1) AND 5 THRU 7.										
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION	SBJD		RECOMMENDED	MTH 16-Dec-2014 HRS 1420.1 LDG 1722					Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL 510-32-05 IN ACCORDANCE WITH PARAGRAPHS 1-(A), 2 (B) (1) (A) (B) , 2 (A) (B) (C) (D) (E) (F) (G) (H) (I), 3 -A. CHECK IN SOIL OK										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION	KDXR		MANDATORY	DAYS 23-May-2017 HRS 1539.3 LDG 1798 ACH 933.9		-			N/A
MOC : NOT APPLICABLE - NO ACTION REQUIRED DUE TO BRAKE SERIAL NUMBERS										
SB 510-34-02 34SB-02	HARDWARE AND SOFTWARE UPDATE FOR GARMIN G1000 AVIONICS	ICT		MANDATORY	MTH 14-Jul-2008 HRS 276		A/R			Complete
MOC : COMPLIED WITH										
SB 510-34-09 34SB-09	GARMIN G1000 SOFTWARE VERSION 010-00435-16 UPGRADE	SBJD		RECOMMENDED	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-34-09 - NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-16 UPGRADE, ACCORDING TO INSTRUCTIONS PARAGRAPH 1 THRU 17.										
SB 510-34-10 34SB-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE	SBJD		MANDATORY	MTH 12-Aug-2011 HRS 1024.6 LDG 1152		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED WITH SB510-34-11 "GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE" ACCORDING TO INSTRUCTIONS CONTAINED IN PARAGRAPHS (01 THROUGH 19) OF THIS SB.										
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT	SBJD		MANDATORY	MTH 17-Apr-2014 HRS 1417.1 LDG 1719		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED WITH SB510-34-12 R1 ACCORDING TO PARAGRAPHS 01(A) TO 09(C) OF THIS SB. APPLIED KIT P/N SB510-34-12 (NEW - FORM 8130-3 # 4047389 ISSUED BY CESSNA AIRCRAFT COMPANY ON 12/02/2013), IAW SB INSTRUCTIONS. CHECKED OK.										
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	SBJD		MANDATORY	MTH 21-Jun-2012 HRS 1237.2 LDG 1119		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB 510-34-14, I.A.W. INSTRUCTIONS OF THE SB - FORM 8130-3 # 3494531, DATED JUN/01/2012, ISSUED BY CESSNA.										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHSR SOFTWARE UPDATE			MANDATORY	MTH HRS		6 300		31-Mar-2017 1781.08	-2 m 21 d 241.78 Over Due
MOC :										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)			OPTIONAL			-			
MOC :										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE INFORMATIONAL									
MOC :										
SL 510-34-03 34SL-03	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING			INFORMATIONAL	MTH		A/R			
MOC :										
SL 510-34-04 34SL-04	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0816	BJD		MANDATORY	MTH 16-Dec-2009 HRS 590		A/R			Complete
MOC : COMPLIED WITH										
SL 510-34-09 34SL-09	GROUNDING STRIP INSPECTION	SBJD		MANDATORY	MTH 16-Dec-2009 HRS 590.6 LDG 641		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL 510-34-09 (NAVIGATION - GROUNDING STRIP INSPECTION), I.A.W. INSTRUCTIONS ON SL - FORM 8130-3 N?. 2571836, DATED NOV/17/2009, EMITTED BY CESSNA.										
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A			INFORMATIONAL			A/R			
MOC :										
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1	SBJD		RECOMMENDED	MTH 25-Feb-2011 HRS 887.3 LDG 931		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-34-15 - NAVIGATION - TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX68 WEATHER RADAR MOD. 1, I.A.W PARAG. 01 TO 03 THIS SL.										
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE			INFORMATIONAL			A/R			
MOC :										
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSUE			INFORMATIONAL			A/R			
MOC :										
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA			INFORMATIONAL			A/R			
MOC :										
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS			INFORMATIONAL			A/R			
MOC :										
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS			INFORMATIONAL			A/R			
MOC :										
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION			INFORMATIONAL			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL			INFORMATIONAL			-			
MOC :										
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT			RECOMMENDED	MTH HRS		12 450		04-May-2018 1985.47	New Req
MOC :										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KFXE		MANDATORY	MTH HRS 1471.3 LDG 1749		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NO. NOT INCLUDED IN SB MCF-SBU-35-001										
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)	SBJD		MANDATORY	MTH 15-Dec-2011 HRS 1095.1 LDG 1248		-			N/A
MOC : NOT APPLICABLE - VERIFIED SL 510-35-01, I.A.W PARAGRAPHS 1 AND 2 PAGE 2. NOT APPLICABILITY THE SERIAL NUMBER OF MASKS INSTALLED PN MC10-16-101 SN 122859 SN 122846.										
SB 510-52-03 52SB-03	NOSE BAGGAGE DOOR HINGE IMPROVEMENT	ICT		RECOMMENDED	MTH 14-Jul-2008 HRS 276		A/R			Complete
MOC : COMPLIED WITH										
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION			DISCRETIONARY			A/R			
MOC :										
SL 510-52-01 REV 01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-52-01 - DOORS - CABIN ENTRY DOOR HINGE FASTENER INSPECTION, ACCORDING TO INSTRUCTIONS PARAGRAPH 5 AND 6.										
SL 510-52-03 52SL-03	DOOR FRAME CORNER FASTENER INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL510-52-03 - DOORS - DOOR FRAME CORNER FASTENER INSPECTION, ACCORDING TO INSTRUCTIONS PARAGRAPH 1 THRU 2A.										
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR			INFORMATIONAL			A/R			
MOC :										
SB 510-53-01 53SB-01	AFT CABIN STRUCTURE INSPECTION	SBJD		MANDATORY	DAYS 26-Feb-2010 HRS 653.5 LDG 683		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB 510-53-01 (FUSELAGE AFT CABIN STRUCTURE INSPECTION), I.A.W. INSTRUCTIONS PARAGRAPHS 1, 2, 3 AND 4. NO DISCREPANCY WAS FOUND.										
ASL 510-53-02 REV 02 53ASL02 : 510R2	TAILCONE SEALANT INSPECTION	BJD		MANDATORY	MTH 16-Dec-2009 HRS 590		A/R			Complete
MOC : COMPLIED WITH										
SL 510-53-01 53SL-01	FORWARD PRESSURE BULKHEAD INSPECTION	ICT		RECOMMENDED	MTH 14-Jul-2008 HRS 276		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 510-53-03	FUSELAGE - DRAIN HOLE INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
<p>MOC : COMPLIED WITH - ACCOMPLISHED SL510-53-03 - FUSELAGE - DRAIN HOLE INSPECTION, ACCORDING TO INSTRUCTIONS ITEMS 1A, 1B, 1C AND 3A.</p>										
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS			DISCRETIONARY			-			
<p>MOC :</p>										
ASL 510-54-01 54ASL01	PYLON RAM AIR DUCT VISUAL INSPECTION	BJD		MANDATORY	MTH 16-Dec-2009 HRS 590		A/R			Complete
<p>MOC : COMPLIED WITH</p>										
SL 510-55-01 55SL-01	HORIZONTAL STABILIZER RIB INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
<p>MOC : COMPLIED WITH - ACCOMPLISHED SL510-55-01 - STABILIZERS - HORIZONTAL STABILIZER RIB INSPECTION.</p>										
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02)	SBJD		MANDATORY	DAYS 12-Aug-2011 HRS 1024.6 LDG 1152		A/R			Complete
<p>MOC : COMPLIED WITH - ACCOMPLISHED WITH SL510-55-02R1 "HORIZONTAL STABILIZER SEALANT INSPECTION" ACCORDING TO INSTRUCTIONS CONTAINED IN PARAGRAPHS (01 THROUGH 04) THIS SL.</p>										
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01)			MANDATORY			A/R			
<p>MOC :</p>										
SB 510-56-02 56SB-02	CABIN WINDOW FROST PANE MODIFICATION			DISCRETIONARY	MTH		A/R			
<p>MOC :</p>										
SL 510-56-01 56SL-01	WINDSHIELD WIRE BUNDLE ASSEMBLY INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			Complete
<p>MOC : COMPLIED WITH - ACCOMPLISHED SL510-56-01 - WINDOWS - WINDSHIELD WIRE BUNDLE ASSEMBLY INPECTION, ACCORDING TO INSTRUCTION PARAGRAPH 1 THRU 2N.</p>										
SL 510-57-01 REV 01 57SL-01 : 510R1	FLAP HINGE INSPECTION	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		-			Complete
<p>MOC : COMPLIED WITH - ACCOMPLISHED SL510-57-01R1 - WINGS - FLAP HINGE INSPECTION, ACCORDING TO INSTRUCTIONS PARAGRAPH 1, 2 AND 6.</p>										
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS			CATEGORY 5	MTH 31-Aug-2007		-			Complete
<p>MOC : COMPLIED WITH</p>										
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS			CATEGORY 5	MTH 07-Sep-2007		-			Complete
<p>MOC : COMPLIED WITH</p>										
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE			CATEGORY 9	MTH 31-Aug-2007		-			Complete
<p>MOC : COMPLIED WITH</p>										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE			CATEGORY 9	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING			CATEGORY 5	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING			CATEGORY 5	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE			CATEGORY 9	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE			CATEGORY 9	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY			CATEGORY 7	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY			CATEGORY 7	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 8	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 8	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 6	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 6	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63019 R1 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 R1 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 9	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 9	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 7	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER			CATEGORY 7	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY			CATEGORY 8	MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY			CATEGORY 8	MTH 07-Sep-2007		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63028 R1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY			CATEGORY 5	MTH		-			
E1	MOC :									
SB PW600-72-63028 R1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY			CATEGORY 5	MTH		-			
E2	MOC :									
SB PW600-72-63031 R1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7			A/R			
E1	MOC :									
SB PW600-72-63031 R1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7			A/R			
E2	MOC :									
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF		CATEGORY 7	MTH		-			
E1	MOC :									
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF		CATEGORY 7	MTH		-			
E2	MOC :									
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE	*CF		CATEGORY 8	MTH		-			
E1	MOC :									
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE	*CF		CATEGORY 8	MTH		-			
E2	MOC :									
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY			CATEGORY 7	MTH		-			
E1	MOC :									
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY			CATEGORY 7	MTH		-			
E2	MOC :									
SB PW600-72-63037 R1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY			CATEGORY 7	MTH		-			
E1	MOC :									
SB PW600-72-63037 R1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY			CATEGORY 7	MTH		-			
E2	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63043 R1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER			CATEGORY 6	MTH		-			
E1										
	MOC :									
SB PW600-72-63043 R1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER			CATEGORY 6	MTH		-			
E2										
	MOC :									
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW600-72-63045 R1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
E1										
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63045 R1 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY						-			
MOC :										
SB PW600-72-63051 R2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES						-			
CATEGORY 6										
E1										
MOC :										
SB PW600-72-63051 R2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES						-			
CATEGORY 6										
E2										
MOC :										
SB PW600-72-63051 R3	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES						-			
CATEGORY 6										
E1										
MOC :										
SB PW600-72-63051 R3	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES						-			
CATEGORY 6										
E2										
MOC :										
SB PW600-72-63052 R1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF						A/R			
CATEGORY 7										
E1										
MOC :										
SB PW600-72-63052 R1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF						A/R			
CATEGORY 7										
E2										
MOC :										
SB PW600-72-63053 R1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS						-			
CATEGORY 7										
E1										
MOC :										
SB PW600-72-63053 R1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS						-			
CATEGORY 7										
E2										
MOC :										
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER				MTH		-			
CATEGORY 7										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER									
	MOC :			CATEGORY 7	MTH		-			
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST									
	MOC :			CATEGORY 9			-			
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST									
	MOC :			CATEGORY 9			-			
SB PW600-72-63059 R2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY									
	MOC :						-			
E1										
	MOC :									
SB PW600-72-63059 R2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY									
	MOC :						-			
E2										
	MOC :									
SB PW600-72-63062 R1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL									
	MOC :						A/R			
E1										
	MOC :									
SB PW600-72-63062 R1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL									
	MOC :						A/R			
E2										
	MOC :									
SB PW600-72-63064 R2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY									
	MOC :						-			
E1										
	MOC :									
SB PW600-72-63064 R2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY									
	MOC :						-			
E2										
	MOC :									
SB PW600-72-63065 R1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF									
	MOC :			CATEGORY 7			-			
E1										
	MOC :									
SB PW600-72-63065 R1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF									
	MOC :			CATEGORY 7			-			
E2										
	MOC :									
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER									
	MOC :			CATEGORY 7	MTH		-			



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER			CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63068 R1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63068 R1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH		A/R			
MOC :										
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY			CATEGORY 6	MTH		A/R			
MOC :										
SB PW600-72-63072 R1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
MOC :										
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7			-			
MOC :										
SB PW600-72-63076 R1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63076 R1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW600-72-63077 R1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63077 R1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR			CATEGORY 6			A/R			
MOC :										
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR			CATEGORY 6			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63080 R2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			-			
MOC :										
E1										
SB PW600-72-63080 R2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			-			
MOC :										
E2										
SB PW600-72-63081 R1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 5			A/R			
MOC :										
E1										
SB PW600-72-63081 R1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 5			A/R			
MOC :										
E2										
SB PW600-72-63083 R1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7			-			
MOC :										
E1										
SB PW600-72-63083 R1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7			-			
MOC :										
E2										
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
MOC :										
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7						
	MOC :									
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63087 R2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL			CATEGORY 3	MTH 13-Sep-2013 HRS 1417.1 LDG 1719					Complete
E1	MOC : COMPLIED WITH - ACCOMPLISHED WITH SB PW600-72-63087 R2 ACCORDING TO INSTRUCTIONS OF PARAGRAPH 3 OF THIS SB. REPROGRAMED THE FADEC USING THE CDROM PN 35C6157-01. RE-IDENTIFIED FADEC WITH P/N 01R35C5731-01. USED LABEL KIT PN 35C5902-01 (NEW - FAA FORM 8130-3 # 3760166 ISSUED BY CESSNA AIRCRAFT COMPANY ON 02/21/2013), IAW SB PWC INSTRUCTIONS.									
SB PW600-72-63087 R2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL			CATEGORY 3	MTH 13-Sep-2013 HRS 1417.1 LDG 1719					Complete
E2	MOC : COMPLIED WITH - ACCOMPLISHED WITH SB PW600-72-63087 R2 ACCORDING TO INSTRUCTIONS OF PARAGRAPH 3 OF THIS SB. REPROGRAMED THE FADEC USING THE CDROM PN 35C6157-01. RE-IDENTIFIED FADEC WITH P/N 01R35C5731-01. USED LABEL KIT PN 35C5902-01 (NEW - FAA FORM 8130-3 # 3760166 ISSUED BY CESSNA AIRCRAFT COMPANY ON 02/21/2013), IAW SB PWC INSTRUCTIONS.									
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63089 R2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6						
E1	MOC :									
SB PW600-72-63089 R2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6						
E2	MOC :									
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7						
MOC :										
SB PW600-72-63091 R1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6						
MOC :										
E1										
SB PW600-72-63091 R1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6						
MOC :										
E2										
SB PW600-72-63091 R2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6						
MOC :										
E1										
SB PW600-72-63091 R2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6						
MOC :										
E2										
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF			CATEGORY 6						
MOC :										
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF			CATEGORY 6						
MOC :										
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT			CATEGORY 7						
MOC :										
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT			CATEGORY 7						
MOC :										
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET			CATEGORY 6						
MOC :										
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET			CATEGORY 6						
MOC :										
SB PW600-72-63094 R1 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7						
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63094 R1 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7						
	MOC :									
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF			CATEGORY 7						
	MOC :									
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF			CATEGORY 7						
	MOC :									
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7						
	MOC :									
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY			CATEGORY 7						
	MOC :									
SB PW600-72-63097 R1 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
	MOC :									
SB PW600-72-63097 R1 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
	MOC :									
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5						
	MOC :									
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY			CATEGORY 5						
	MOC :									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7						
	MOC :									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET			CATEGORY 7						
	MOC :									
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT									
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT									
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			RECOMMENDED		MTH				
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY			RECOMMENDED	MTH		-			
MOC :										
SB PW600-72-63102 R1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			RECOMMENDED			-			
MOC :										
SB PW600-72-63102 R1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			RECOMMENDED			-			
MOC :										
SB PW600-72-63102 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			RECOMMENDED			-			
MOC :										
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
MOC :										
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH						-			
MOC :										
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
MOC :										
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7			-			
MOC :										
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5			-			
MOC :										
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5			-			
MOC :										
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
MOC :										
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7			-			
MOC :										
ASB PW600-72-A63071 R1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
MOC :										
E1		SBJD		CATEGORY 3	MTH 26-Feb-2010 HRS 653.5 LDG 725		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED CF2010-03, I.A.W. INCORPORATION PWC SB PW600-72-A-63071 AND CESSNA ASL510-73-02.										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASB PW600-72-A63071 R1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
		SBJD		CATEGORY 3	MTH 26-Feb-2010 HRS 738.4 LDG 795		A/R			Complete
E2	MOC : COMPLIED WITH - ACCOMPLISHED CF2010-03, I.A.W. CORPORATION SB PWC PW600-72-A-63071 AND CESSNA ASL510-73-02.									
SB PW600-73-63030 R1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS									
				CATEGORY 7			A/R			
E1	MOC :									
SB PW600-73-63030 R1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS									
				CATEGORY 7			A/R			
E2	MOC :									
ASL 510-73-01 LEFT 73ASL01 : L	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 653.5 LDG 683		A/R			Complete
	MOC : COMPLIED WITH - THIS ASL IS NOT EFFECTIVE DUE THE INCORPORATION OF THE ASL 510-73-02.									
ASL 510-73-01 RIGHT 73ASL01 : R	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 653.5 LDG 683		-			Complete
	MOC : COMPLIED WITH - THIS ASL IS NOT EFFECTIVE DUE THE INCORPORATION OF THE ASL 510-73-02.									
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 653.5 LDG 683		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED ASL 510-73-02. (ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC SB A63071 - TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE - REPLACED OF), I.A.W. INSTRUCTIONS ON ASL. NO DISCREPANCY WAS FOUND.									
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 653.5 LDG 683		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED ASL 510-73-02. (ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC SB A63071 - TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE - REPLACED OF), I.A.W. INSTRUCTIONS ON ASL. NO DISCREPANCY WAS FOUND.									
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE									
				CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE									
				CATEGORY 6			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63080 R1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			A/R			
E1	MOC :									
SB PW600-72-63080 R1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			A/R			
E2	MOC :									
SB PW600-72-63082 E1	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH		A/R			
	MOC :									
SB PW600-72-63082 E2	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH		A/R			
	MOC :									
ASB PW600-72-A63061 R2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3	MTH 25-Feb-2011 HRS 887.3 LDG 931		A/R			Complete
E1	MOC : COMPLIED WITH - ACCOMPLISHED ASB A63061 R2 (PW600-72-A63061) - TURBOFAN ENGINE - ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT / MODIFICATION OF.									
ASB PW600-72-A63061 R2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3	MTH 25-Feb-2011 HRS 887.3 LDG 931		A/R			Complete
E2	MOC : COMPLIED WITH - ACCOMPLISHED ASB A63061 R2 (PW600-72-A63061) - TURBOFAN ENGINE - ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT / MODIFICATION OF.									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASB PW600-72-A63069 R1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
				CATEGORY 3	MTH		A/R			
E1	MOC :									
ASB PW600-72-A63069 R1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
				CATEGORY 3	MTH		A/R			
E2	MOC :									
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN				MTH 31-Aug-2007	-				Complete
				CATEGORY 7						
	MOC : COMPLIED WITH									
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN				MTH 07-Sep-2007	-				Complete
				CATEGORY 7						
	MOC : COMPLIED WITH									
SB PW600-73-63011 R1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)				MTH 31-Aug-2007	-				Complete
				CATEGORY 8						
E1	MOC : COMPLIED WITH									
SB PW600-73-63011 R1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC)				MTH 07-Sep-2007	-				Complete
				CATEGORY 8						
E2	MOC : COMPLIED WITH									
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY				MTH 31-Aug-2007	-				Complete
				CATEGORY 7						
	MOC : COMPLIED WITH									
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY				MTH 07-Sep-2007	-				Complete
				CATEGORY 7						
	MOC : COMPLIED WITH									
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT				MTH 31-Aug-2007	-				Complete
				CATEGORY 8						
	MOC : COMPLIED WITH									
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT				MTH 07-Sep-2007	-				Complete
				CATEGORY 8						
	MOC : COMPLIED WITH									
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY				MTH 31-Aug-2007	-				Complete
				CATEGORY 7						
	MOC : COMPLIED WITH									
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY				MTH 07-Sep-2007	-				Complete
				CATEGORY 7						
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	*CF		CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	*CF		CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS	*CF		CATEGORY 8	MTH		-			
	MOC :									
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS	*CF		CATEGORY 8	MTH		-			
	MOC :									
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS			CATEGORY 6	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS			CATEGORY 6	MTH		-			
MOC :										
SB PW600-75-63054 R1 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA)			CATEGORY 7	MTH		-			
MOC :										
SB PW600-75-63054 R1 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA)			CATEGORY 7	MTH		-			
MOC :										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087									
		SBJD		MANDATORY	MTH 13-Sep-2013 HRS 1417.1 LDG 1719		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED WITH SB510-76-01 R2 ACCORDING TO INSTRUCTIONS BY PARAGRAPHS 01 THROUGH 12 OF THIS SB. APPLIED SB PW600-72-63087 R2. REPROGRAMED THE FADEC USING THE CDROM PN 35C6157-01. RE-IDENTIFIED FADEC WITH P/N 01R35C5731-01. USED LABEL KIT PN 35C5902-01 (NEW - FAA FORM 8130-3 # 3760166 ISSUED BY CESSNA AIRCRAFT COMPANY ON 02/21/2013), IAW SB PWC INSTRUCTIONS.										
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8	MTH		-			
MOC :										
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8	MTH		-			
MOC :										
SL 510-79-01 79SL-01	OIL PRESSURE TRANSMITTER INSPECTION				MTH 26-Feb-2010 HRS 653.5 LDG 683		-			Complete
		SBJD		MANDATORY						
MOC : COMPLIED WITH - VERIFIED SL 510-79-01 (OIL - OIL PRESSURE TRANSMITTER INSPECTION), NOT APPLICABLE BY SERIAL NUMBER ON OIL PRESSURE TRANSMITTER. INSTALLED ON ENGINES S/N LH 7390-10-285 AND RH 7473-5-420.										
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION				DAYS 12-Aug-2011 HRS 1024.6 LDG 1152		A/R			Complete
		SBJD		MANDATORY						
MOC : COMPLIED WITH - ACCOMPLISHED WITH SL510-79-02 "OIL PRESSURE TRANSMITTER CONNECTION INSPECTION" ACCORDING TO INSTRUCTIONS CONTAINED IN PARAGRAPHS (01 THROUGH 09) THIS SL.										
SB PW600-72-63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH		-			
MOC :										
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY						-			
MOC :										
SB PW600-72-63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW600-79-63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS				MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS				MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				MTH 31-Aug-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				MTH 07-Sep-2007		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				MTH		-			
	MOC :									
SB PW600-79-63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER CATEGORY 7				MTH		-			
	MOC :									
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7				MTH		-			
	MOC :									
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH CATEGORY 7				MTH		-			
	MOC :									
SB PW600-79-63047 R2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS									
				CATEGORY 3	MTH		-			
E1	MOC :									
SB PW600-79-63047 R2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS									
				CATEGORY 3	MTH		-			
E2	MOC :									
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)									
					INFORMATIONAL					
	MOC :									
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS									
					INFORMATIONAL		A/R			
	MOC :									
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION									
					INFORMATIONAL		A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2012-08-07	B/E AEROSPACE, CONTINUOUS FLOW	SBJD			MTH 16-Aug-2012 HRS 1280.5 LDG 1510	-				N/A
	MOC : NOT APPLICABLE - VERIFIED AD 2012-08-07 ACCORDING TO PARAGRAPH "C" APPLICABILITY, NO ACTION IS NOT NECESSARY, BECAUSE THE SEATS ARE INSTALLED IN THE AIRCRAFT MANUFACTURER'S IPECO AND NOT THE MANUFACTURER SICMA AERO SEAT. FOR MORE DETAILS SEE FCDA.									
FAA 2010-04-16 (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS	SBJD		MANDATORY	DAYS 28-Jul-2010 HRS 788.3 LDG 849		A/R			N/A
	MOC : NOT APPLICABLE									
FAA 2010-04-16 (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS	SBJD		MANDATORY	DAYS 28-Jul-2010 HRS 788.3 LDG 849		A/R			N/A
	MOC : NOT APPLICABLE									
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS	SBJD		MANDATORY	MTH 28-Jul-2010 HRS 788.3 LDG 849		A/R			N/A
	MOC : NOT APPLICABLE - VERIFIED AD2010-04-16 TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI . N/A, THIS AD NOT AFFECT THE COMPONENT INSTALLED, FIRE EXTINGUISHER MANUFACTURED BY AMEREX P/N: C352TS S/N: X-350195. FOR MORE DETAILS SEE FCDA									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
	MOC :									
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	SBJD		MANDATORY	MTH 04-Dec-2015 HRS 1456.7 LDG 1741		-			N/A
	MOC : NOT APPLICABLE - IN DISPLAYS INSTALLED IN THE AIRCRAFT. INSTALLED DISPLAY MANUFACTURED: GARMIM 1000									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	SBJD		MANDATORY	MTH 04-Dec-2015 HRS 1456.7 LDG 1741		-			N/A
	MOC : NOT APPLICABLE - IN DISPLAYS INSTALLED IN THE AIRCRAFT. INSTALLED DISPLAY MANUFACTURED: GARMIM 1000									
FAA 2010-11-05	APPLIANCE AD - INSPECT FOR AND REMOVE SUBSTANDARD OXYGEN CYLINDERS FROM AIRPLANE	SBJD		MANDATORY	DAYS 28-Jul-2010 HRS 788.3 LDG 849		A/R			N/A
	MOC : NOT APPLICABLE - VERIFIED AD2010-11-05, NOT APPLICABLE ON THE CILINDER PART NUMBER INSTALLED. CILINDER P/N 4441073-040 INSTALLED. FOR MORE DETAILS SEE FCDA.									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2011-14-08	AIRWORTHINESS DIRECTIVES; B/E AEROSPACE, CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY, PART NUMBERS 174006-(), 174080-(), 174085-(), 174095-(), 174097-(), AND 174098-()	SBJD			MTH 16-Aug-2012 HRS 1280.5 LDG 1510		36			N/A
	MOC : NOT APPLICABLE - VERIFIED AD 2011-14-08 IN ACCORDANCE WITH PARAGRAPH "C", NOT NECESSARY TO PERFORM ANY SERVICE BECAUSE THE INSTALLED MASK P/N 289-601-441-1 HAVE BEEN MANUFACTURED BY AVOX / SCOTT. FOR MORE DETAILS SEE FCDA.									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1	KFXE		MANDATORY	MTH 05-Aug-2016 HRS 1472.2 LDG 1750		-			N/A
	MOC : NOT APPLICABLE - DUE TO EQUIPMENT NOT INSTALLED									
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL.	KFXE		MANDATORY	MTH 05-Aug-2016 HRS 1472.2 LDG 1750		-			N/A
	MOC : NOT APPLICABLE - DUE TO EQUIPMENT NOT INSTALLED									
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT.	KFXE		MANDATORY	MTH 05-Aug-2016 HRS 1472.2 LDG 1750		-			N/A
	MOC : NOT APPLICABLE - DUE TO EQUIPMENT NOT INSTALLED									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES.	KFXE		MANDATORY	MTH 05-Aug-2016 HRS 1472.2 LDG 1750		-			N/A
	MOC : NOT APPLICABLE - DUE TO EQUIPMENT NOT INSTALLED									
TCCA CF-2010-03 E1	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 653.5 LDG 725		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED CF2010-03, I.A.W. INCORPORATION PWC SB PW600-72-A-63071 AND CESSNA ASL510-73-02.									
TCCA CF-2010-03 E2	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 738.4 LDG 795		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED CF2010-03, I.A.W. CORPORATION SB PWC PW600-72-A-63071 AND CESSNA ASL510-73-02.									
FAA 2010-17-06 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 653.5 LDG 715		-			Complete
	MOC : COMPLIED WITH - PCW BY COMPLIANCE WITH CF 2010-03 COMMENTS: ACCOMPLISHED CF2010-03, I.A.W. CORPORATION SB PWC PW600-72-A-63071 AND CESSNA ASL510-73-02.									



CESCOM 10 - Aircraft Status Report

Owner: **BARON 55 INC**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0046** Unit: **0046** Reg No: **N85TV**
 Airworthiness: **28-Nov-2007**
 Print Date: **21-Jun-2017 7:03AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1539.3	1798	21-Jun-2017	.2
ENG 1	1539.3	1718	21-Jun-2017	.28
ENG 2	1454.4	1643	21-Jun-2017	.28
AIR COND	933.9		21-Jun-2017	.4

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2010-17-06 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	SBJD		MANDATORY	MTH 26-Feb-2010 HRS 738.4 LDG 795		-			Complete

**MOC : COMPLIED WITH - PCW BY COMPLIANCE WITH CF 2010-03 COMMENTS: ACCOMPLISHED CF2010-03,
 I.A.W. CORPORATION SB PWC PW600-72-A-63071 AND CESSNA ASL510-73-02.**