

# COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

EMAIL: CAMSREPORTS@HOTMAIL.COM

PHONE: (305) 744-3333 FAX: (888) 575-3499

<b>1/28/2023</b>	<b>REGISTERED OWNER</b>	CHRYSLER AVIATION INC	<b>OPERATOR</b>	Chrysler Aviation Inc
	<b>ADDRESS</b>		<b>ADDRESS</b>	7120 HAVENHURST AVE VAN NUYS, CA 91406
	<b>PHONE</b>		<b>PHONE</b>	(818) 987-6634
	<b>CONTACT</b>		<b>CONTACT</b>	Max Bucher
	<b>TITLE</b>		<b>TITLE</b>	
	<b>FAX</b>		<b>FAX</b>	

## AIRFRAME

<b>AIRCRAFT MAKE</b>	CHALLENGER
<b>AIRCRAFT MODEL</b>	601-3A
<b>AIRCRAFT YEAR</b>	1988
<b>SERIAL NUMBER</b>	5017
<b>AIRCRAFT REGISTRATION NO.</b>	N404HG
<b>TOTAL TIME AIRFRAME</b>	11680.2
<b>TOTAL AIRCRAFT LANDINGS</b>	6583
<b>INSPECTION PROGRAM</b>	FAR 91.409(f,1)
<b>TOTAL TIME APU</b>	8273.0

## LEFTHAND ENGINE

<b>SERIAL NUMBER</b>	3050271
<b>MAKE</b>	GENERAL ELECTRIC
<b>MODEL</b>	CF34-3A
<b>TIME SINCE NEW</b>	11574.9
<b>CYCLES SINCE NEW</b>	6516
<b>TIME SINCE OVERHAUL</b>	5620.2
<b>CYCLES SINCE OVERHAUL</b>	3241
<b>TIME SINCE HOT SECTION</b>	2662.9
<b>CYCLES SINCE HOT SECTION</b>	1700
<b>TBO</b>	6000

## RIGHTHAND ENGINE

<b>SERIAL NUMBER</b>	350268
<b>MAKE</b>	GENERAL ELECTRIC
<b>MODEL</b>	CF34-3A
<b>TIME SINCE NEW</b>	11475.5
<b>CYCLES SINCE NEW</b>	6492
<b>TIME SINCE OVERHAUL</b>	5546.2
<b>CYCLES SINCE OVERHAUL</b>	3207
<b>TIME SINCE HOT SECTION</b>	2662.9
<b>CYCLES SINCE HOT SECTION</b>	1700
<b>TBO</b>	6000

All target dates projected in this report have been calculated using your estimated MONTHLY AVERAGE utilization of **25 HOURS AND 25 CYCLES**.

If your utilization is higher than the one's listed above then **BEWARE THE ITEMS WILL COME DUE EARLIER THAN THE PROJECTED TARGET DATES.**

# AIRFRAME HOURS REPORT

## CHALLENGER 5017

1/28/2023  
N404HG

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
98		SB 601-0626 (ACTUATOR PINS)					1000	10603.0		-1077.2	02/25/2018
98		SB 601-0304			8/19/2016	10201.1	1200	11401.1	1479.1	-279.1	02/27/2022
34		RVSM HEIGHT MONITORING PROGRAM			5/17/2019	10696.2	1000	11696.2	984.0	16.0	02/16/2023
050012	*	INSPECTION, AIRFRAME 100 HOUR			9/08/2022	11649.3	100	11749.3	30.9	69.1	04/20/2023
99	*	AD 95-17-14 (HORIZ STAB TRIM ACT)			9/08/2022	11649.3	100	11749.3	30.9	69.1	04/20/2023
24-33-00-302	*	BATTERY	MAIN	CHECK	1/20/2023	11678.8	100	11778.8	1.4	98.6	05/26/2023
76-10-00-101	*	GEARBOX, THROTTLE CONTROL	LH	FUNC TEST	11/29/2019	10788.4	1000	11788.4	891.8	108.2	06/06/2023
76-10-00-101	*	GEARBOX, THROTTLE CONTROL	RH	FUNC TEST	11/29/2019	10788.4	1000	11788.4	891.8	108.2	06/06/2023
30-40-00-213	*	WINDSHIELD	RH	RAIN TEST	1/16/2022	11399.3	400	11799.3	280.9	119.1	06/19/2023
30-40-00-213	*	WINDSHIELD	LH	RAIN TEST	1/16/2022	11399.3	400	11799.3	280.9	119.1	06/19/2023
57-30-00-403B	*	FUEL TANK WATER DRAIN HOLES	STA68.7	VISUAL	4/29/2019	10686.7	1136	11822.7	993.5	142.5	07/18/2023
57-30-00-403C	*	FUEL TANK WATER DRAIN HOLES	STA 48	VISUAL	6/27/2019	10706.5	1193	11899.5	973.7	219.3	10/18/2023
53-30-00-156	*	CABIN WINDOW CUTOUPS		NDT	11/02/2021	11299.8	600	11899.8	380.4	219.6	10/18/2023
57-30-00-117	*	WING PLANK-WS65.0, STR 14,15 (CENTER)	RH LOWER	NDT	11/02/2021	11299.8	600	11899.8	380.4	219.6	10/18/2023
57-30-00-117	*	WING PLANK-WS65.0, STR 14,15 (CENTER)	LH LOWER	NDT	11/02/2021	11299.8	600	11899.8	380.4	219.6	10/18/2023
57-30-00-122	*	WING PLANK-WS65.0, STR 10 CENTER	LH LOWER	NDT	11/02/2021	11299.8	600	11899.8	380.4	219.6	10/18/2023
57-30-00-122	*	WING PLANK-WS65.0, STR 10 CENTER	RH LOWER	NDT	11/02/2021	11299.8	600	11899.8	380.4	219.6	10/18/2023
57-30-00-126	*	WING UPPER COVER	RH	VISUAL	6/27/2019	10706.5	1200	11906.5	973.7	226.3	10/26/2023
57-30-00-126	*	WING UPPER COVER	LH	VISUAL	6/27/2019	10706.5	1200	11906.5	973.7	226.3	10/26/2023
050016	*	INSPECTION, AIRFRAME 600 HOUR			11/18/2021	11328.0	600	11928.0	352.2	247.8	11/21/2023
050014	*	INSPECTION, AIRFRAME 300 HOUR			7/29/2022	11634.7	300	11934.7	45.5	254.5	11/29/2023
57-30-00-150	*	WING PLANK-WS65.75, STR 17	RH LWR	NDT	9/07/2012	9547.9	2400	11947.9	2132.3	267.7	12/15/2023
57-30-00-150	*	WING PLANK-WS65.75, STR 17	LH LWR	NDT	9/07/2012	9547.9	2400	11947.9	2132.3	267.7	12/15/2023
57-20-00-116	*	WING TIP-EXTERNAL SURFACE	RH	VISUAL	9/07/2012	9547.9	2400	11947.9	2132.3	267.7	12/15/2023
57-20-00-116	*	WING TIP-EXTERNAL SURFACE	LH	VISUAL	9/07/2012	9547.9	2400	11947.9	2132.3	267.7	12/15/2023
57-40-00-178	*	WING/FUSE ATTACH FIT LUG FS424	RH	VISUAL	1/06/1988	0.0	12000	12000.0	11680.2	319.8	02/15/2024
57-40-00-178	*	WING/FUSE ATTACH FIT LUG FS424	LH	VISUAL	1/06/1988	0.0	12000	12000.0	11680.2	319.8	02/15/2024
53-10-00-118	*	LONGITUDINAL FLOOR BEAMS-FS513.0		VISUAL	1/06/1988	0.0	12000	12000.0	11680.2	319.8	02/15/2024
57-40-00-170	*	FLIGHT SPOILER WING/HINGE ATTACH PT	RH	NDT	2/09/2011	9017.3	3000	12006.6	2673.6	326.4	02/23/2024
57-40-00-170	*	FLIGHT SPOILER WING/HINGE ATTACH PT	LH	NDT	2/09/2011	9017.3	3000	12006.6	2673.6	326.4	02/23/2024
53-10-00-122	*	TRANSVERSE BEAM-AFT PRESS BULKHEAD	FS621.0	VISUAL	2/04/2005	6006.6	6000	12006.6	5673.6	326.4	02/23/2024
71-10-26-206	*	CORE COWL FIXED SIDE PANEL	RH	VISUAL	2/09/2011	9017.3	3000	12006.6	2673.6	326.4	02/23/2024
71-10-26-206	*	CORE COWL FIXED SIDE PANEL	LH	VISUAL	2/09/2011	9017.3	3000	12006.6	2673.6	326.4	02/23/2024
71-10-26-206	*	CORE COWL FIXED SIDE PANEL	RH		2/09/2011	9017.3	3000	12006.6	2673.6	326.4	02/23/2024
71-10-26-206	*	CORE COWL FIXED SIDE PANEL	LH		2/09/2011	9017.3	3000	12006.6	2673.6	326.4	02/23/2024
57-30-00-402E	*	WING FUEL ACCESS HOLES-540GB		NDT	12/04/2019	10791.8	1247	12038.8	888.4	358.6	04/02/2024
57-30-00-403	*	FUEL TANK WATER DRAIN HOLES	STA 5	VISUAL	12/04/2019	10791.8	1247	12038.8	888.4	358.6	04/02/2024
53-20-00-403A	*	PRESS FLOOR, FS605.-621, LBL27-RBL27		VISUAL	12/27/2018	10578.6	1562	12140.6	1101.6	460.4	08/02/2024
57-30-00-402A	*	WING FUEL ACCESS HOLES-550AB, 640FB		NDT	2/14/2020	10871.0	1306	12177.0	809.2	496.8	09/15/2024
57-30-00-402F	*	WING FUEL ACCESS HOLES-540DB		NDT	2/14/2020	10871.0	1313	12184.0	809.2	503.8	09/23/2024
57-30-00-402G	*	WING FUEL ACCESS HOLES-650AB		NDT	2/14/2020	10871.0	1313	12184.0	809.2	503.8	09/23/2024
57-30-00-402J	*	WING FUEL ACCESS HOLES-640GB		NDT	2/14/2020	10871.0	1313	12184.0	809.2	503.8	09/23/2024
57-30-00-403A	*	FUEL TANK WATER DRAIN HOLES	STA48	VISUAL	2/14/2020	10871.0	1356	12227.0	809.2	546.8	11/14/2024

**AIRFRAME HOURS REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
57-30-00-403D	*	FUEL TANK WATER DRAIN HOLES	STA 68.7	VISUAL	2/14/2020	10871.0	1356	12227.0	809.2	546.8	11/14/2024
57-30-00-402B	*	WING FUEL ACCESS HOLES-640DB		NDT	9/23/2020	10924.8	1383	12307.8	755.4	627.6	02/19/2025
57-30-00-402H	*	WING FUEL ACCESS HOLES-640DB		NDT	9/23/2020	10924.8	1387	12311.8	755.4	631.6	02/23/2025
57-30-00-402K	*	WING FUEL ACCESS HOLE-540-640-650EB		NDT	9/23/2020	10924.8	1387	12311.8	755.4	631.6	02/23/2025
57-30-00-402C	*	WING FUEL ACCESS HOLES-550GB		NDT	9/23/2020	10924.8	1410	12334.8	755.4	654.6	03/23/2025
53-20-00-403B	*	HORIZ SIDE FLANGE,FS605.00,BL27.00		NDT	4/29/2019	10686.7	1668	12354.7	993.5	674.5	04/16/2025
53-10-00-123	*	FWD PRESS BULKHEAD WEB-FS202.75		VISUAL	1/30/2006	6404.8	6000	12404.8	5275.4	724.6	06/15/2025
99	*	AD 74-08-09 LAV FIRE PROTECTION			3/11/2022	11473.6	1000	12473.6	206.6	793.4	09/06/2025
27-31-11-101	*	PITCH FEEL SIMULATOR		FUNC TEST	2/24/2021	11046.1	1500	12546.1	634.1	865.9	12/02/2025
27-31-11-101	*	PITCH FEEL SIMULATOR	#2	FUNC TEST	2/24/2021	11046.1	1500	12546.1	634.1	865.9	12/02/2025
57-10-00-103	*	WING PLANK-REAR SPAR WS166	RH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-119	*	WING PLANK AUX SPAR HOLE-WS85.0	RH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-119	*	WING PLANK AUX SPAR HOLE-WS85.0	LH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-120	*	WING PLANK-WS88.0,BTWN STR 14, 15	LH LOWER	VISUAL	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-121	*	WING PLANK-WS45.0,STR 14,15 CENTER	RH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-10-00-103	*	WING PLANK-REAR SPAR WS166	LH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-121	*	WING PLANK-WS45.0,STR 14,15 CENTER	LH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-124	*	WING PLANK-WS45.0,STR 10 CENTER	RH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-124	*	WING PLANK-WS45.0,STR 10 CENTER	LH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-125	*	WING PLANK-WS45.0,STR 15,16	RH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-125	*	WING PLANK-WS45.0,STR 15,16	LH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
53-10-00-104	*	KEEL LONGERON		NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-127	*	WING PLANK-AFT EDGE-WS163.0 - 170.5	LH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-128	*	WING PLANKS-WS86.0,STR 14-17	RH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-30-00-127	*	WING PLANK-AFT EDGE-WS163.0 - 170.5	RH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
57-10-00-102	*	WING PLANK-REAR SPAR WS178 & WS189	LH LOWER	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
71-10-00-101	*	NOSE COWL ACT SUPPORT FIT-ATT LUGS	RH FWD	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
71-10-00-101	*	NOSE COWL ACT SUPPORT FIT-ATT LUGS	LH FWD	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
71-10-00-101	*	NOSE COWL ACT SUPPORT FIT-ATT LUGS	RH FWD	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
71-10-00-101	*	NOSE COWL ACT SUPPORT FIT-ATT LUGS	LH FWD	NDT	12/16/2021	11359.0	1200	12559.0	321.2	878.8	12/17/2025
53-40-00-195	*	OVERWING EMERG EXIT-SURROUND/FITING		VISUAL	5/03/2016	10175.9	2400	12575.9	1504.3	895.7	01/06/2026
52-20-00-105	*	OVERWING EMERG EXIT ATTACH FITTINGS		VISUAL	5/03/2016	10175.9	2400	12575.9	1504.3	895.7	01/06/2026
53-10-00-106	*	WINDSHIELD LOWER SILL FS209.0		VISUAL	12/04/2019	10791.8	1800	12591.8	888.4	911.6	01/25/2026
050018	*	INSPECTION,AIRFRAME 1200 HOUR			1/14/2022	11399.3	1200	12599.3	280.9	919.1	02/03/2026
56-10-00-102	*	WINDSHIELD & SIDE WINDOW GLAZING		PRISM CHK	1/14/2022	11399.3	1200	12599.3	280.9	919.1	02/03/2026
21-30-11-211	*	OUTFLOW VALVE	PRIMARY	FUNC TEST	1/14/2022	11399.3	1200	12599.3	280.9	919.1	02/03/2026
21-30-11-211	*	OUTFLOW VALVE	SECONDARY	FUNC TEST	1/14/2022	11399.3	1200	12599.3	280.9	919.1	02/03/2026
57-30-00-120	*	WING PLANK-WS88.0,BTWN STR 14, 15	RH LOWER	VISUAL	1/14/2022	11399.3	1200	12599.3	280.9	919.1	02/03/2026
53-10-00-102	*	WINDSHIELD UPPER SILL FS234.0 BL2.5		VISUAL	1/14/2022	11399.3	1200	12599.3	280.9	919.1	02/03/2026
53-10-00-105	*	FLOOR BEAM ATTACH TO PRESS BULKHEAD	FS621.0	VISUAL	1/06/1988	0.0	12600	12600.0	11680.2	919.8	02/04/2026
57-30-00-402D	*	WING FUEL ACCESS HOLES-540FB		NDT	9/23/2020	10924.8	1691	12615.8	755.4	935.6	02/23/2026
78-30-00-401A	*	T/R MAIN TRACK UPPER FLANGE	LOC C	NDT	7/29/2022	11634.7	1016	12650.7	45.5	970.5	04/06/2026
27-39-00-104	*	STICK PUSHER CAPSTAN SHAFT (SPS)		FUNC TEST	11/18/2021	11328.0	1500	12828.0	352.2	1147.8	11/05/2026

**AIRFRAME HOURS REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
78-30-00-104	*	T/R MAIN TRACKS LOWER FLANGE	RH	NDT	1/30/2006	6404.8	6600	13004.8	5275.4	1324.6	06/05/2027
78-30-00-104	*	T/R MAIN TRACKS LOWER FLANGE	LH	NDT	1/30/2006	6404.8	6600	13004.8	5275.4	1324.6	06/05/2027
78-30-00-101	*	T/R MAIN TRACK AFT LUGS	RH	NDT	11/02/2021	11299.8	1800	13099.8	380.4	1419.6	09/27/2027
78-30-00-101	*	T/R MAIN TRACK AFT LUGS	LH	NDT	11/02/2021	11299.8	1800	13099.8	380.4	1419.6	09/27/2027
57-30-00-142	*	FUEL TANK WATER DRAIN PORT-WS48.0	RH	VISUAL	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-142	*	FUEL TANK WATER DRAIN PORT-WS48.0	LH	VISUAL	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-143	*	WING PLANK CTR-HOLE-WS220.0,STR10	RH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-143	*	WING PLANK CTR-HOLE-WS220.0,STR10	LH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-10-00-108	*	WING PLANK-REAR SPAR WS148.0	RH LOWER	VISUAL	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-10-00-108	*	WING PLANK-REAR SPAR WS148.0	LH LOWER	VISUAL	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-118	*	WING PLANK MLG TRUNNION-WS65.75	RH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-118	*	WING PLANK MLG TRUNNION-WS65.75	LH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-139	*	WING PLANK-WS148.0, STR 8,9	RH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-139	*	WING PLANK-WS148.0, STR 8,9	LH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-140	*	WING PLANK-WS148.0, STR 15	RH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-140	*	WING PLANK-WS148.0, STR 15	LH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-141	*	WING PANEL CTR-HOLE-WS112.0,STR10	RH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
57-30-00-141	*	WING PANEL CTR-HOLE-WS112.0,STR10	LH LOWER	NDT	12/16/2021	11359.0	1800	13159.0	321.2	1478.8	12/07/2027
05	*	INSPECTION,AIRFRAME 1800 HOUR			1/14/2022	11399.3	1800	13199.3	280.9	1519.1	01/24/2028
53-30-00-162	*	STRINGER SPLICE-FS513.0,STRINGER 13		VISUAL	1/06/1988	7453.6	6000	13453.6	4226.6	1773.4	11/25/2028
53-30-00-403A	*	FUSELAG SKIN FS235,BL6-ZONE 114,122		NDT	1/06/1988	0.0	13503	13503.0	11680.2	1822.8	01/23/2029
34-11-11-101	*	PITOT STATIC HEADS	RH	REPLACE	5/20/2021	11111.3	9600	13568.3	7711.9	1888.1	04/11/2029
274002-001	*	ACTUATOR,PITCH TRIM		REPLACE	8/01/2009	8227.9	13200	13768.9	11111.3	2088.7	12/08/2029
050024	*	INSPECTION,AIRFRAME 2400 HOUR			1/16/2022	11399.3	2400	13799.3	280.9	2119.1	01/13/2030
56-10-00-104	*	WINDSHIELD & SIDE WINDOW T PLATE	LH	NDT	1/16/2022	11399.3	2400	13799.3	280.9	2119.1	01/13/2030
56-10-00-104	*	WINDSHIELD & SIDE WINDOW T PLATE	RH	NDT	1/16/2022	11399.3	2400	13799.3	280.9	2119.1	01/13/2030
12		SERVICE,2400 HOUR ITEMS			1/16/2022	11399.3	2400	13799.3	280.9	2119.1	01/13/2030
71-10-00-102	*	NACELE STRUCTURE @ ENG JOINT	RH FWD	NDT	1/06/1988	0.0	13800	13800.0	11680.2	2119.8	01/14/2030
71-10-00-102	*	NACELE STRUCTURE @ ENG JOINT	LH FWD	NDT	1/06/1988	0.0	13800	13800.0	11680.2	2119.8	01/14/2030
55-50-00-220	*	BOLT,VERTICAL STAB TO RUDDER HINGE	LOWER	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
55-50-00-221	*	BOLT,HORIZONTAL STAB TO ELEV HINGE	RH OUTBD	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
050026	*	INSPECTION,AIRFRAME 4800 HOUR			3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
21-51-31-212	*	SWITCH, AIR CONDITIONING OVERHEAT	RH	FUNC TEST	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
21-51-31-212	*	SWITCH, AIR CONDITIONING OVERHEAT	LH	FUNC TEST	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
27-39-00-103	*	STALL PROTECTION SYSTEM,SIDESLIP		FUNC TEST	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
27-33-11-217	*	ELEVATOR FLUTTER DAMPERS	LH OUTBD	TEST	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
27-33-11-217	*	ELEVATOR FLUTTER DAMPERS	LH INBD	TEST	3/05/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
27-33-11-217	*	ELEVATOR FLUTTER DAMPERS	RH OUTBD	TEST	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
27-33-11-217	*	ELEVATOR FLUTTER DAMPERS	RH INBD	TEST	3/05/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
27-13-21-206	*	DAMPER,AILERON FLUTTER FAULT ISO	RH	TEST	3/05/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
27-13-21-206	*	DAMPER,AILERON FLUTTER FAULT ISO	LH	TEST	3/05/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
28-25-21-222	*	VALVES,APU RETURN LINE CHECK		LEAK CK	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
29-10-00-205	*	VALVE,MAIN SYSTEMS RESERVOIR CHECK	SYS #1	BENCH CK	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030

**AIRFRAME HOURS REPORT  
CHALLENGER 5017**

1/28/2023  
N404HG

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
29-10-00-205	*	VALVE,MAIN SYSTEMS RESERVOIR CHECK	SYS #2	BENCH CK	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
29-10-00-206	*	VALVE,MAIN SYSTEMS RESERVOIR CHECK	SYS #3	BENCH CK	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON INBOARD HINGE	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON INBOARD HINGE	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON MID INBD HINGE	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON MID INBD HINGE	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON MID OUTBD HNGE	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON MID OUTBD HNGE	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON OUTBOARD HINGE	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-215	*	BOLT,WING TO AILERON OUTBOARD HINGE	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,INBOARD FLAP INBD HINGE INBD	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
78-30-00-102	*	T/R MAIN UPPER PYLON TRACKS	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,INBOARD FLAP INBD HINGE INBD	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,INBOARD FLAP INBD HINGE OUTBD	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,INBOARD FLAP INBD HINGE OUTBD	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
78-30-00-102	*	T/R MAIN UPPER PYLON TRACKS	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,OUTBD FLAP OUTBD HINGE INBD	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,OUTBD FLAP OUTBD HINGE INBD	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,OUTBD FLAP MID HINGE OUTBD	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,OUTBD FLAP MID HINGE OUTBD	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,OUTBD FLAP OUTBD HINGE OUTBD	LH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
53-10-00-116	*	FWD PRESS BULKHEAD VERT STIFFENERS		VISUAL	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-40-00-216	*	BOLT,OUTBD FLAP OUTBD HINGE OUTBD	RH	NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
53-10-00-117	*	FUSELAGE FRAME DRAG ANGLE-FS755		NDT	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
57-51-00-185	*	AILERON	RH	VISUAL	2/15/2018	10418.8	3600	14018.8	1261.4	2338.6	10/04/2030
57-51-00-185	*	AILERON	LH	VISUAL	2/15/2018	10418.8	3600	14018.8	1261.4	2338.6	10/04/2030
55-20-00-108	*	ELEVATOR/HORIZ STAB PCU HINGES	LH	NDT	1/12/2007	6836.8	7200	14036.8	4843.4	2356.6	10/25/2030
55-20-00-108	*	ELEVATOR/HORIZ STAB PCU HINGES	RH	NDT	1/12/2007	6836.8	7200	14036.8	4843.4	2356.6	10/25/2030
78-30-00-105	*	T/R SERVICE PYLON SUPPORT RAIL	RH	NDT	1/12/2007	6836.8	7200	14036.8	4843.4	2356.6	10/25/2030
78-30-00-105	*	T/R SERVICE PYLON SUPPORT RAIL	LH	NDT	1/12/2007	6836.8	7200	14036.8	4843.4	2356.6	10/25/2030
53-10-00-131	*	KEEL LONGERON LINKS & BOLTS	FS395.75	VISUAL	1/06/1988	0.0	14400	14400.0	11680.2	2719.8	01/04/2032
31		FLIGHT DATA RECORDER		BENCH CK	11/18/2022	11678.8	3000	14678.8	1.4	2998.6	12/04/2032
55-10-00-103	*	HORIZ STAB REAR SPAR UPPER CAP	RIB 1,BL6	NDT	1/18/2019	10614.0	4200	14814.0	1066.2	3133.8	05/15/2033
53-10-00-113	*	REAR PRESS BULKHEAD WEB		VISUAL	1/18/2019	10614.0	4200	14814.0	1066.2	3133.8	05/15/2033
27-40-16-101	*	ACTUATOR,HSTB PITCH TRIM		OVERHAUL	8/01/2009	8227.9	6600	14827.9	3452.3	3147.7	06/01/2033
53-10-00-140	*	FWD PRESS BULKHEAD WEB WL79.5-91.7		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-104	*	ENGINE MOUNT YOKE LOWER LUG	RH	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-141	*	NLG BEAM WEB BELOW DRAG BEAM		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-104	*	ENGINE MOUNT YOKE LOWER LUG	LH	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-142	*	NLG DRAG STRUT AT FS 213.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-105	*	ENGINE MOUNT UPPER LINK	RH FWD	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-143	*	NLG BEAM VERT STIFFENER CLIP-FS215.		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-105	*	ENGINE MOUNT UPPER LINK	LH FWD	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033

**AIRFRAME HOURS REPORT**  
**CHALLENGER 5017**

1/28/2023  
N404HG

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
53-10-00-144	*	NLG BEAM UPPER CAP-FS210.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-106	*	ENGINE MOUNT UPPER BOLTS	RH FWD	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-145	*	WING PLANK-WS45.0,STR8	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-145	*	NLG BEAM LOWER CAP AT FS224.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-106	*	ENGINE MOUNT UPPER BOLTS	LH FWD	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-145	*	WING PLANK-WS45.0,STR8	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-403B	*	FUSELAG SKIN FS235,BL6-ZONE 115,121		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-146	*	OVERWING EMERG EXIT-SURROUND STRUCT		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-147	*	PAX DOOR FRAMES-FS310.0 & FS349.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-148	*	FRAME ASSY PRESS BULKHEAD-VERT STIF	FS621.0	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-149	*	REAR PRESS BULKHEAD-FS621-FRAME CAP		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-101	*	WING PLANK & REAR SPAR WS 45.0/WS47	RH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-150	*	REAR PRESS BULKHEAD VERT STIFFENER		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-153	*	WING PLANK @ MLG CUTOOT	RH LWR	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-101	*	WING PLANK & REAR SPAR WS 45.0/WS47	LH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-151	*	OUTER FLANGE CAP SPLICE ANGLE		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-153	*	WING PLANK @ MLG CUTOOT	LH LWR	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-152	*	FRAME SPLICE-FS672.2,STRINGER 6		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-155	*	WING PLANK-WS242.0, STR 9	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-153	*	FUSE FRAM FS755/WEB BL5.5/WL125-131		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-156	*	WING PLANK-WS242.0,OTBD/INBD	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-178	*	FUSELAGE WING ATTACH FRAME-FS424		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-155	*	WING PLANK-WS242.0, STR 9	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-190	*	MACHINED STRAP-FS409.0,LBL6.0-RBL6.			1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-156	*	WING PLANK-WS242.0,OTBD/INBD	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-106	*	WING PLANK-FRONT SPAR WS29.42	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-191	*	FUSE FRAME CAP-FS409.0,LBL18,RBL18			1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-159	*	WING PLANK-WS264.0, STR 6,7	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-106	*	WING PLANK-FRONT SPAR WS29.42	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-195	*	BONDED DOUBLER AFT OF FS617.00		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-159	*	WING PLANK-WS264.0, STR 6,7	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-104	*	WING PLANK-FRONT SPAR WS45.0	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-20-00-155	*	FLOOR WEB ADJ TO PRESS BULKHEAD	PILOTS	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-160	*	WING PLANK CTRLIN SPLICE AFT STR8/9	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-104	*	WING PLANK-FRONT SPAR WS45.0	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-160	*	WING PLANK CTRLIN SPLICE AFT STR8/9	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-158	*	LIGHT FUSELAGE FRAMES		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-162	*	WING PLANK-WS242.0, STR 7	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-162	*	WING PLANK-WS242.0, STR 7	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-109	*	WING PLANK-REAR SPAR-WS 242.0	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-160	*	FUSELAGE SKIN PANEL FS625.3,STR 0.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-109	*	WING PLANK-REAR SPAR-WS 242.0	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-164	*	CABIN WINDOW SURROUNDING STRUCTURE		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033

**AIRFRAME HOURS REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
53-30-00-166	*	SKIN/STRINGER SPLICE FA559.0,STR 0.		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-111	*	WING PLANK-REAR SPAR-WS 260.0	RH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-169	*	WING TO FUSELAGE ATTACH FRAME-FS513		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-40-00-182	*	WING/FUSELAGE ATT LUG FS473 BL45.0	RH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-111	*	WING PLANK-REAR SPAR-WS 260.0	LH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-171	*	STRINGER SPLICE AT FS473.0,STR 3		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-40-00-182	*	WING/FUSELAGE ATT LUG FS473 BL45.0	LH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-112	*	WING PLANK-REAR SPAR-WS 217/222	RH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-172	*	SKIN SPLICE AT STRINGER 0 -FS 439.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-112	*	WING PLANK-REAR SPAR-WS 217/222	LH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-173	*	SKIN SPLICE-FS424.0 - FS439.0,STR 8		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-113	*	REAR SPAR/WING PLANK @ WS219.0	RH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-174	*	STRINGER SPLICE-STR 1 L&R FS718.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-113	*	REAR SPAR/WING PLANK @ WS219.0	LH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-175	*	FUSE STR SPLICE AT STR 0,FWD FS718.		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-114	*	WING PLANK-WS314.5,BUTT STRAP	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-176	*	BAGGAGE DOOR & SURROUNDING STRUCTUR		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-114	*	WING PLANK-WS314.5,BUTT STRAP	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-177	*	PRESS SKIN/FLOOR ANGLE WL73		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-115	*	WING PLANK-WS315,BUTT STRAP	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-179	*	VERT STAB-FUSE FRAME REF VS 55.625%	STR 5	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-10-00-115	*	WING PLANK-WS315,BUTT STRAP	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-20-00-403D	*	PRESS FLOOR SKIN		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-40-00-183	*	INTEGRAL WING ATTACH FR LUGS-FS424.		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-40-00-185	*	INTEGRAL FRAME ATTACH LUGS -FS473.0	BL 45.0	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-40-00-186	*	INTEGRAL FRAME ATTACH LUGS -FS513.0	BL	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-40-00-192	*	INTEGRAL FRAME ATTACH BOLTS-FS424.0		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-40-00-193	*	INTEGRAL FRAME ATTACH BOLTS-FS473		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-40-00-194	*	INTEGRAL FRAME ATTACH BOLTS-FS513		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-166	*	FUSELAGE SKIN PANEL FS559.0,STR 0.		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-30-00-191	*	SKIN CIRCUM SPLICE FS559 STR10L/10R		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
54-10-00-101	*	ENG SUPPORTING BEAM UPPER CAP	FS625.3	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
54-10-00-102	*	PYLON SPAR/FUSELAGE FRAME ATTACH	FS672.2	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
54-10-00-103	*	PYLON SPAR UPPER CAP FS 625.3		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
54-10-00-104	*	PYLON CANTED RIB UPPER SPLICE	FS672.2	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
54-30-00-105	*	PYLON UPPER SKIN - FS 682.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-10-00-102	*	HORIZ STAB REAR SPAR-CENTERLINE		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-10-00-104	*	HORIZ STAB-REAR SPAR UPPER CAP/SPLC		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-10-00-105	*	HORIZ STAB FRONT SPAR UPRR CAP SPLC	BL 6.0	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-10-00-106	*	HORIZ STAB-UPPER STRINGER 1-BL 6.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-10-00-107	*	HORIZ STAB - CENTERLINE RIB		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-129	*	WING PLANKS-WS163, STR 15	RH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-20-00-109	*	ELEVATOR,SKIN & FRONT SPAR		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033

**AIRFRAME HOURS REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
57-30-00-129	*	WING PLANKS-WS163, STR 15	LH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-110	*	VERT STAB - MID SPAR CAP AT RIB 1		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-110	*	INTEGRAL ATTACH FR-FS 513.0,BL 16.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-130	*	WING PLANKS-WS148.0, STR19	RH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-111	*	VERT STAB - FRONT SPAR		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-111	*	OVERWING EMERGENCY EXIT & SURROUND		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-130	*	WING PLANKS-WS148.0, STR19	LH LOWER	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-112	*	VERT STAB-FRONT SPAR FS755,WL137.5		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-131	*	WING PLANK-WS127.5,STR 9,10	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-113	*	VERT STAB-STRINGER SPLICE		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-131	*	WING PLANK-WS127.5,STR 9,10	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-114	*	VS STRINGER SPLICE 31.875% 55.625%	RIB 2,3	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
78-30-00-106	*	T/R SVC PYLON UPPER SUPPORT BED	RH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-114	*	REAR PRESS BULKHEAD AT FS 621.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-132	*	WING PLANK-CENTERLINE SPLICE	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-115	*	VERT STAB-ACCESS HOLE-SKIN CUTOUT		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
78-30-00-106	*	T/R SVC PYLON UPPER SUPPORT BED	LH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-132	*	WING PLANK-CENTERLINE SPLICE	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-116	*	VERT STAB - REAR SPAR		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-51-00-186	*	AILERON UPPER/LOWER SKIN/FRONT SPAR	RH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-133	*	WING PLANK-WS94.0, STR 23	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-117	*	VERT STAB-FRONT SPAR CAP @ RIB 1		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-120	*	VERT ANGLE FWD FACE ENG SUPP BEAM	FS625.3	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-51-00-186	*	AILERON UPPER/LOWER SKIN/FRONT SPAR	LH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-133	*	WING PLANK-WS94.0, STR 23	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-118	*	VERT STAB-REAR SPAR WEB @ RIB 7		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-55-00-196	*	FLIGHT SPOILER UPPER/LOWER SKIN	RH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-134	*	WING PLANK-WS106.4, STR 10	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-30-00-119	*	VERT STAB-SPAR CAP SPLICE STRAP	FRONT	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-55-00-196	*	FLIGHT SPOILER UPPER/LOWER SKIN	LH	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-134	*	WING PLANK-WS106.4, STR 10	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-124	*	LONGITUDINAL FLOOR BEAMS-FS484.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-135	*	WING PLANK-WS106.4, STR 15,16	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-40-00-121	*	RUDDER, SKIN & FRONT SPAR		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-135	*	WING PLANK-WS106.4, STR 15,16	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-50-00-122	*	VERT STAB PITCH TRIM ACT PIVOT LUGS		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-136	*	WING PLANK-WS199.0, STR 6,7	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-50-00-123	*	VERT/HORIZ STAB PIVOT FITTING		NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-136	*	WING PLANK-WS199.0, STR 6,7	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-50-00-124	*	HORIZ STAB-PIVOT FITTING LUGS		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-137	*	WING PLANK-WS199.0, STR 17	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
55-50-00-125	*	HORIZ STAB BATHTUB FITTINGS		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-137	*	WING PLANK-WS199.0, STR 17	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033



# AIRFRAME HOURS REPORT

## CHALLENGER 5017

1/28/2023  
N404HG

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
53-10-00-130	*	LONGERON-UNDERFLOOR-FS513,BL45		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-138	*	WING PLANK-WS220.0, STR 7	RH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
57-30-00-138	*	WING PLANK-WS220.0, STR 7	LH LOWER	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-133	*	PAX DOOR & SURROUNDING STRUCTURE		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-135	*	FUSELAGE FRAME CAP ANGLE-FS755.0		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-136	*	FUSELAGE FRAME , FS755.0 VERT. STAB		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-137	*	FWD PRESS BULKHEAD VERT MEMBER		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-138	*	FUSE FRAME FS235.0 UPPER CAP ANGLE		VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-103	*	ENGINE MOUNT THRUST FITTING	RH AFT	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
53-10-00-139	*	FLOOR CONNECTION CLIPS AT BL13.0	PILOTS	VISUAL	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
71-20-00-103	*	ENGINE MOUNT THRUST FITTING	LH AFT	NDT	1/06/1988	0.0	15000	15000.0	11680.2	3319.8	12/24/2033
34-11-11-101	*	PITOT STATIC HEADS	LH	REPLACE	12/14/2003	5568.0	9600	15168.0	6112.2	3487.8	07/14/2034
55-40-00-120	*	RUDDER SUPPORT & PCU HINGE FITTINGS		NDT	9/07/2012	7864.2	7800	15600.0	3880.2	3919.8	12/14/2035
78-30-00-103	*	T/R MAIN TRACK ATTACH FITTINGS	RH	NDT	2/10/2022	11437.0	5400	16837.0	243.2	5156.8	01/07/2040
78-30-00-103	*	T/R MAIN TRACK ATTACH FITTINGS	LH	NDT	2/10/2022	11437.0	5400	16837.0	243.2	5156.8	01/07/2040
53-10-00-125	*	INTERCOSTALS & CLIPS-FS621-FS625.3		VISUAL	9/07/2012	9547.9	7800	17347.9	2132.3	5667.7	09/11/2041
53-10-00-126	*	PRESS BULKHEAD STIFFENER-FS621.0		VISUAL	2/09/2011	9017.3	8400	17400.0	2680.2	5719.8	11/12/2041
55-50-00-127	*	ELEVATOR HINGE BOLTS	LH INBD	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
050028	*	INSPECTION,AIRFRAME 9600 HOUR			10/08/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
56-10-00-106	*	WINDSHIELD/SIDE WINDOW FASTENERS		NDT	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
21-20-11-203	*	VALVE,COLD AIR CHECK	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
21-20-11-203	*	VALVE,COLD AIR CHECK	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-10-00-110	*	WING BOX INTERNAL STRUCTURE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-10-00-110	*	WING BOX INTERNAL STRUCTURE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
53-30-00-167	*	FUSELAGE SKIN @ NLG CUTOUT-FS235.0		VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON OUTBOARD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON MID OUTBOARD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON MID INBOARD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON INBOARD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON OUTBOARD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON MID OUTBOARD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON MID INBOARD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
28-21-11-212	*	FLAPPER CK VALVES,COLLECTOR TANK	LH	CHECK	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-188	*	BOLTS,AILERON INBOARD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
28	*	FLAPPER VALVES,COLLECTOR TANKS	LH	CHECK	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
28-21-11-212	*	FLAPPER CK VALVES,COLLECTOR TANK	RH	CHECK	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-198	*	BOLT,FLIGHT SPOILER OUTBOARD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-198	*	BOLT,FLIGHT SPOILER MID OUTBD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-198	*	BOLT,FLIGHT SPOILER MID INBD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
30-11-00-202	*	WING ANTI-ICING		FUNC CK	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-198	*	BOLT,FLIGHT SPOILER INBOARD HINGE	RH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
53-50-00-226	*	TAILCONE INTERIOR SURFACE		INSPECT	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-198	*	BOLT,FLIGHT SPOILER OUTBOARD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047

**AIRFRAME HOURS REPORT  
CHALLENGER 5017**

1/28/2023  
N404HG

ATA CODE	FAA	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAIN	
57-40-00-198	*	BOLT, FLIGHT SPOILER MID OUTBD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-198	*	BOLT, FLIGHT SPOILER MID INBD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
57-40-00-198	*	BOLT, FLIGHT SPOILER INBOARD HINGE	LH	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
53-10-00-127	*	SIDE PANEL END POST-FS280.0		NDT	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
53-10-00-128	*	OVERWING FLOOR INTERCOSTAL		VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
53-10-00-129	*	CLEAT-FRAME TO LONGERON		VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-126	*	RUDDER HINGE BOLTS	LOWER	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-126	*	RUDDER HINGE BOLTS	MID/LOWER	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-126	*	RUDDER HINGE BOLTS	MID/UPPER	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-126	*	RUDDER HINGE BOLTS	UPPER	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-127	*	ELEVATOR HINGE BOLTS	RH OTBD	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-127	*	ELEVATOR HINGE BOLTS	LH OTBD	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-127	*	ELEVATOR HINGE BOLTS	RH MID	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-127	*	ELEVATOR HINGE BOLTS	LH MID	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-50-00-127	*	ELEVATOR HINGE BOLTS	RH INBD	VISUAL	9/07/2012	9547.9	9600	19147.9	2132.3	7467.7	08/11/2047
55-00-00-101	*	ACTUATOR, PITCH TRIM		VISUAL	4/06/2015	10000.9	10000	20000.9	1679.3	8320.7	05/30/2050
57-10-00-102	*	WING PLANK-REAR SPAR WS178 & WS189	RH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
57-10-00-102	*	WING PLANK-REAR SPAR WS178 & WS189	LH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
57-10-00-103	*	WING PLANK-REAR SPAR WS166	RH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
57-10-00-103	*	WING PLANK-REAR SPAR WS166	LH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
57-30-00-127	*	WING PLANK-AFT EDGE-WS163.0 - 170.5	RH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
57-30-00-127	*	WING PLANK-AFT EDGE-WS163.0 - 170.5	LH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
57-30-00-128	*	WING PLANKS-WS86.0, STR 14-17	RH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
57-30-00-128	*	WING PLANKS-WS86.0, STR 14-17	LH LOWER	NDT	4/22/2016	10173.2	10200	20373.2	1507.0	8693.0	08/20/2051
53-40-00-195	*	OVERWING EMERG EXIT-SURROUND/FITNG		VISUAL	5/03/2016	10175.1	10200	20375.1	1505.1	8694.9	08/22/2051
52-20-00-105	*	OVERWING EMERG EXIT ATTACH FITTINGS		VISUAL	5/03/2016	10175.9	10200	20375.9	1504.3	8695.7	08/23/2051
53-10-00-103	*	UNDERFLOOR PRESSURE BULKHEAD FS409		VISUAL	7/15/2005	6218.0	15000	21218.0	5462.2	9537.8	05/30/2054
53-20-00-403C	*	PRESS FLOOR, FS473, FS513, BL36-BL43		NDT	4/22/2019	10686.7	12381	23067.7	993.5	11387.5	06/27/2060
53-10-00-412	*	PRESS BULKHEAD FS409		NDT/VISUL	1/06/1988	0.0	24017	24017.0	11680.2	12336.8	08/10/2063

NOTE: \* INDICATES FAA MANDATORY REQUIREMENT.

**CALENDAR REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A A	DESCRIPTION	LOCATION	ACTION	DATE ACCOMPLISHED	INTERVAL	DATE DUE
98		SB 601-0631 I (LUGS)				48 mos	09/26/2017
98		SB 601-0626 (ACTUATOR PINS)				5 yrs	02/25/2018
05	*	AIRCRAFT REGISTRATION			1/31/2019	3 yrs	01/31/2022
25	*	ELT RE-REGISTRATION			11/09/2020	2 yrs	11/09/2022
050042	*	INSPECTION, AIRFRAME 12 MONTH			2/23/2022	12 mos	02/23/2023
34		BATTERY, INS	#2	CAP CHK	3/11/2022	12 mos	03/11/2023
34		BATTERY, INS	#3	CAP/ELECT	3/11/2022	12 mos	03/11/2023
34		BATTERY, INS	#3	REPLACE	3/11/2019	48 mos	03/11/2023
34	*	BATTERY, INS	#1	CAP CHK	3/11/2022	12 mos	03/11/2023
33-50-00-203	*	POWER SUPPLY, EMERGENCY LIGHTING	AFT	TEST	3/11/2022	12 mos	03/11/2023
34-23-11-209	*	BATTERY/CHARGER UNIT	#3	CAP CHECK	3/11/2022	12 mos	03/11/2023
23	*	CVR ULB		OPS CHK	3/12/2021	24 mos	03/12/2023
25		FIRST AID KIT		INSPECT	4/13/2022	12 mos	04/13/2023
25	*	LIFE VESTS		VISUAL	4/13/2022	12 mos	04/13/2023
050040	*	INSPECTION, AIRFRAME 6 MONTH			1/20/2023	6 mos	07/20/2023
33-50-00-203	*	POWER SUPPLY, CABIN EMERGENCY	FWD	TEST	7/29/2022	12 mos	07/29/2023
34		BATTERY, FMS	#1	REPLACE	8/12/2021	24 mos	08/12/2023
25	*	ELT		INSPECT	9/28/2022	12 mos	09/28/2023
31	*	BATTERY, UNDERWATER LOCATOR BEACON	FDR	REPLACE	10/19/2017	6 yrs	10/19/2023
34		FLIGHT DATA RECORDER		DATA DUMP	11/18/2022	12 mos	11/18/2023
23	*	BATTERY, UNDERWATER LOCATOR BEACON		INSPECT	11/18/2021	2 yrs	11/18/2023
31	*	BATTERY, UNDERWATER LOCATOR BEACON	FDR	INSPECT	11/18/2021	24 mos	11/18/2023
34		BATTERY, FMS	#2	REPLACE	1/14/2022	24 mos	01/14/2024
050048	*	INSPECTION, AIRFRAME 48 MONTH			2/14/2020	48 mos	02/14/2024
35-10-00-205		MASK, CREW OXYGEN	PILOTS	OVERHAUL	2/15/2018	72 mos	02/15/2024
C55-00-812	*	CPCP, RUDDER EXTERNAL SKIN & ATTACH		VISUAL	2/21/2021	36 mos	02/21/2024
34-13-00-101	*	AIR DATA COMPUTER	#2	FUNC TEST	2/23/2022	24 mos	02/23/2024
34-11-00-205	*	ALTIMETER PITOT STATIC (FAR91.411)	PILOT	CALIBRATE	2/23/2022	24 mos	02/23/2024
34-11-00-205	*	ALTIMETER PITOT STATIC (FAR91.411)	COPILOT	CALIBRATE	2/23/2022	24 mos	02/23/2024
34-11-00-205	*	COMPUTER, AIR DATA (FAR91.411)	#1	CALIBRATE	2/23/2022	24 mos	02/23/2024
34-11-00-205	*	COMPUTER, AIR DATA (FAR91.411)	#2	CALIBRATE	2/23/2022	24 mos	02/23/2024
34-11-00-203	*	PITOT STATIC/TEMP SENSING (411/413)	PILOT	LEAK TEST	2/23/2022	24 mos	02/23/2024
34-54-00-210	*	TRANSPONDER (FAR91.413)	LH	FUNC TEST	2/23/2022	24 mos	02/23/2024
34-54-00-210	*	TRANSPONDER (FAR91.413)	RH	FUNC TEST	2/23/2022	24 mos	02/23/2024
34-62-00-303		BATTERY, CLOCK	PILOT	REPLACE	2/23/2022	24 mos	02/23/2024
34-62-00-303		BATTERY, CLOCK	COPILOTS	REPLACE	2/23/2022	24 mos	02/23/2024
34-11-00-205	*	ALTIMETER PITOT STATIC (FAR91.411)	STANDBY	CALIBRATE	2/23/2022	24 mos	02/23/2024
34-11-00-203	*	PITOT STATIC/TEMP SENSING (411/413)	COPILOT	LEAK TEST	2/23/2022	24 mos	02/23/2024
34-11-00-203	*	PITOT STATIC/TEMP SENSING (411/413)	STANDBY	LEAK TEST	2/23/2022	24 mos	02/23/2024
34-13-00-101	*	AIR DATA COMPUTER		FUNC TEST	2/23/2022	24 mos	02/23/2024
34-11-00-206	*	INDICATOR, AIRSPEED	STANDBY	CALIBRATE	2/23/2022	24 mos	02/23/2024
050044	*	INSPECTION, AIRFRAME 24 MONTH			2/23/2022	24 mos	02/23/2024
34-13-00-101		RVSM INSPECTION			2/23/2022	24 mos	02/23/2024
35-10-11-203	*	BOTTLE, CREW OXYGEN	COCKPIT	HYDRO	2/24/2021	36 mos	02/24/2024

**CALENDAR REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	DATE ACCOMPLISHED	INTERVAL	DATE DUE
050046	*	INSPECTION, AIRFRAME 36 MONTH			2/25/2021	36 mos	02/25/2024
55-50-00-217	*	HORIZ STAB HINGE FITTING AT BL15.25		VISUAL	2/25/2021	36 mos	02/25/2024
55-50-00-218	*	HORIZ STAB PCU FITTINGS		VISUAL	2/25/2021	36 mos	02/25/2024
05		AIRCRAFT WEIGH			2/25/2021	3 yrs	02/25/2024
C55-00-805	*	CPCP, VERT STAB REAR SPAR STRUCTURE		VISUAL	2/25/2021	36 mos	02/25/2024
C55-00-813	*	CPCP, ELEVATOR EXTERNAL SKIN	LH	VISUAL	2/25/2021	36 mos	02/25/2024
C55-00-813	*	CPCP, ELEVATOR EXTERNAL SKIN	RH	VISUAL	2/25/2021	36 mos	02/25/2024
26-25-00-212	*	BOTTLE, H2O PORTABLE		FUNC TEST	4/13/2022	24 mos	04/13/2024
25		BATTERY, ELT		REPLACE	10/03/2019	5 yrs	10/03/2024
242306-001	*	SQUIB, AIR DRIVEN GEN UPLOCK (MFG)		REPLACE	1/20/2020	60 mos	01/20/2025
23-71-11-204	*	BATTERY, UNDERWATER LOCATOR BEACON	CVR	REPLACE	3/11/2019	6 yrs	03/11/2025
242306-001	*	SQUIB, AIR DRIVEN GEN UPLOCK (SVC)		REPLACE	9/24/2021	42 mos	03/24/2025
26-23-11-210	*	BOTTLE, ENGINE FIRE EXTINGUISHER	LH	HYDRO	9/23/2020	60 mos	09/23/2025
26-23-11-210	*	BOTTLE, ENGINE FIRE EXTINGUISHER	RH	HYDRO	9/23/2020	60 mos	09/23/2025
25	*	RAFT, LIFE	#1	RECERTIFY	11/18/2022	36 mos	11/18/2025
25	*	RAFT, LIFE	#2	RECERTIFY	11/18/2022	36 mos	11/18/2025
35-10-00-204	*	BOTTLE, CREW OXYGEN		REPLACE	2/12/2002	24 yrs	02/12/2026
26-25-00-213	*	BOTTLE, PORTABLE FIRE EXTINGUISHER	COCKPIT	RECHARGE	2/14/2020	6 yrs	02/14/2026
26-25-00-213	*	BOTTLE, PORTABLE FIRE EXTINGUISHER	CABIN FWD	HYDRO	2/25/2021	5 yrs	02/25/2026
35	*	BOTTLE, CABIN OXYGEN	PORTABLE	HYDRO	2/25/2021	60 mos	02/25/2026
34		BATTERY, INS	#1	REPLACE	3/11/2022	4 yrs	03/11/2026
34		BATTERY, INS	#2	REPLACE	3/11/2022	4 yrs	03/11/2026
26-21-11-207	*	BOTTLE, FIREX	APU	HYDRO	7/29/2022	60 mos	07/29/2027
35-10-00-205		MASK, CREW OXYGEN	COPILOTS	OVERHAUL	8/06/2021	72 mos	08/06/2027
26-25-00-213	*	BOTTLE, PORTABLE FIRE EXTINGUISHER	CABIN FWD	RECHARGE	9/24/2021	6 yrs	09/24/2027
35-10-11-203	*	BOTTLE, CABIN OXYGEN	#2	HYDRO	11/18/2022	60 mos	11/18/2027
050050	*	INSPECTION, AIRFRAME 60 MONTH			11/18/2022	60 mos	11/18/2027
53-30-00-221	*	CABIN WINDOW CUTOUS		NDT	11/18/2022	60 mos	11/18/2027
35-10-11-203	*	BOTTLE, CABIN OXYGEN	#1	HYDRO	11/18/2022	60 mos	11/18/2027
53-30-00-224	*	FUSELAGE SKINS (EXTERNAL)	LOWER	NDT	12/04/2019	96 mos	12/04/2027
55-10-00-205	*	HORIZ STAB INTERNAL STRUCTURE		VISUAL	2/15/2018	120 mos	02/15/2028
53-00-00-232	*	FUSELAGE INTERNAL-202.75 TO 621.00	ABOVE FLR	VISUAL	2/15/2018	120 mos	02/15/2028
32-10-00-238	*	MLG	LH	OVERHAUL	2/15/2018	120 mos	02/15/2028
32-10-00-238	*	MLG	RH	OVERHAUL	2/15/2018	120 mos	02/15/2028
32-20-00-240	*	NLG		OVERHAUL	2/15/2018	120 mos	02/15/2028
30-13-00-205	*	SWITCHES, ANTI ICE BLEED AIR THERMAL		FUNC TEST	2/15/2018	120 mos	02/15/2028
28-10-21-207	*	AUXILIARY FUEL TANKS	FWD/AFT	BORESCOPE	2/15/2018	120 mos	02/15/2028
53-00-00-204	*	FUSELAGE INTERNAL-FS169 TO 202.75		VISUAL	2/15/2018	120 mos	02/15/2028
C53-00-803	*	CPCP, FUSELAGE STRUCTURE INTERNAL	FS169-202	VISUAL	2/15/2018	120 mos	02/15/2028
C53-00-820	*	CPCP, FUSE STRUCTURE INTERNAL (RECU)	ABOVE FLR	VISUAL	2/15/2018	120 mos	02/15/2028
262300-005	*	CARTRIDGE, FIRE EXTINGUISHER	APU	REPLACE	1/18/2019	120 mos	01/18/2029
262300-001	*	CARTRIDGE, FIRE EXTINGUISHER	LH #1	REPLACE	9/23/2020	120 mos	09/23/2030
262300-002	*	CARTRIDGE, FIRE EXTINGUISHER	LH #2	REPLACE	9/23/2020	120 mos	09/23/2030
262300-003	*	CARTRIDGE, FIRE EXTINGUISHER	RH #1	REPLACE	9/23/2020	120 mos	09/23/2030

**CALENDAR REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	DATE ACCOMPLISHED	INTERVAL	DATE DUE
262300-004	*	CARTRIDGE, FIRE EXTINGUISHER	RH #2	REPLACE	9/23/2020	120 mos	09/23/2030
72-00-00-218	*	INSPECTION, ENGINE BORESCOPE	LH		2/26/2021	10 yrs	02/26/2031
72-00-00-218	*	INSPECTION, ENGINE BORESCOPE	RH		2/26/2021	10 yrs	02/26/2031
25	*	VEST, LIFE	#3	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#4	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#5	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#6	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#7	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#8	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#9	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#10	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#11	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	PILOT	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	COPILOT	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#12	RECERTIFY	4/01/2021	10 yrs	04/01/2031
25	*	VEST, LIFE	#2	RECERTIFY	4/01/2021	10 yrs	04/01/2031
35	*	BOTTLE, CABIN OXYGEN	#1	REPLACE	11/14/2017	15 yrs	11/14/2032
35	*	BOTTLE, CABIN OXYGEN	#2	REPLACE	11/14/2017	15 yrs	11/14/2032
26-25-00-213	*	BOTTLE, PORTABLE FIRE EXTINGUISHER	CABIN FWD	HYDRO	1/06/2021	144 mos	01/06/2033
26-25-00-213	*	BOTTLE, PORTABLE FIRE EXTINGUISHER	COCKPIT	HYDRO	11/01/2021	144 mos	11/01/2033

**NOTE: \* INDICATES FAA MANDATORY REQUIREMENT.**

**AIRFRAME LANDINGS REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE	
					DATE	LANDING		NEXT DUE	CURRENT	REMAIN		
98		SB 601-0631 I (LUGS)					7900	7900		1317	09/26/2017	
98		SB 601-0501 (PRESS BULKHEAD FS409)				4/21/2020	6046	600	6646	537	63	04/13/2023
27-50-16-101	*	ACTUATOR, OUTER FLAP	LH OTBD	RESTORE	5/12/2010	4653	2000	6653	1930	70	04/22/2023	
27-50-16-101	*	ACTUATOR, OUTER FLAP	LH INBD	RESTORE	5/12/2010	4653	2000	6653	1930	70	04/22/2023	
27-50-16-101	*	ACTUATOR, OUTER FLAP	RH INBD	RESTORE	5/12/2010	4653	2000	6653	1930	70	04/22/2023	
27-50-16-101	*	ACTUATOR, OUTER FLAP	RH OTBD	RESTORE	5/12/2010	4653	2000	6653	1930	70	04/22/2023	
57-40-00-173	*	FLAP HINGE SUPPORTS	LH INBD	NDT	8/07/2018	5772	1200	6972	811	389	05/08/2024	
57-40-00-173	*	FLAP HINGE SUPPORTS	RH INBD	NDT	8/07/2018	5772	1200	6972	811	389	05/08/2024	
99	*	AD 2004-09-37 FLAP VANE BRACKET					7000	7000		417	06/11/2024	
52-12-00-204	*	DOOR, DOWNWARD OPENING PAX/CREW		VISUAL	1/25/2022	6406	600	7006	177	423	06/18/2024	
99	*	AD 2013-03-08 ENGINE SUPPORT BEAMS					7800	7800		1217	01/27/2027	
53-10-00-198	*	BEAM, ENGINE SUPPORT		VISUAL	1/06/1988	0	7800	7800	6583	1217	01/27/2027	
57-40-01-101	*	FLAP HINGE BOX FWD LUGS	LH INBD	NDT	1/06/1988	0	7900	7900	6583	1317	05/27/2027	
57-40-01-101	*	FLAP HINGE BOX FWD LUGS	RH INBD	NDT	1/06/1988	0	7900	7900	6583	1317	05/27/2027	
57-40-00-174	*	FLAP HINGE BOX FWD LUGS	LH OTBD	NDT	1/06/1988	0	8000	8000	6583	1417	09/24/2027	
57-40-00-174	*	FLAP HINGE BOX FWD LUGS	RH OTBD	NDT	1/06/1988	0	8000	8000	6583	1417	09/24/2027	
57-53-00-161	*	FLAP VANE SUPPORT STRUTS-171.94,296	LH OTBD	NDT	1/06/1988	0	9000	9000	6583	2417	01/06/2031	
57-53-00-161	*	FLAP VANE SUPPORT STRUTS-171.94,296	RH OTBD	NDT	1/06/1988	0	9000	9000	6583	2417	01/06/2031	
99	*	AD 2018-09-17 RUDDER PEDAL TUBES					9000	9000		2417	01/06/2031	
53-10-01-101	*	DOOR, PAX UPPER LATCH PINS		NDT	1/06/1988	0	9000	9000	6583	2417	01/06/2031	
57-53-00-190	*	FLAP VANE SUPPORT BRACKETS	LH INBD	NDT	4/01/2000	2582	7000	9582	4001	2999	12/04/2032	
57-53-00-190	*	FLAP VANE SUPPORT BRACKETS	RH INBD	NDT	4/01/2000	2582	7000	9582	4001	2999	12/04/2032	
575317-004	*	SUPPORT BEAM, FLAP ACTUATOR	#4	REPLACE	1/06/1988	0	9600	9600	6583	3017	12/26/2032	
575317-005	*	SUPPORT BEAM, FLAP ACTUATOR	#5	REPLACE	1/06/1988	0	9600	9600	6583	3017	12/26/2032	
575317-006	*	SUPPORT BEAM, FLAP ACTUATOR	#6	REPLACE	1/06/1988	0	9600	9600	6583	3017	12/26/2032	
575317-001	*	SUPPORT BEAM, FLAP ACTUATOR	#1	REPLACE	1/06/1988	0	9600	9600	6583	3017	12/26/2032	
575317-002	*	SUPPORT BEAM, FLAP ACTUATOR	#2	REPLACE	1/06/1988	0	9600	9600	6583	3017	12/26/2032	
575317-003	*	SUPPORT BEAM, FLAP ACTUATOR	#3	REPLACE	1/06/1988	0	9600	9600	6583	3017	12/26/2032	
57-53-00-191	*	FLAP VANE SUPPORT BLADES	LH OTBD	NDT	1/06/1988	0	10000	10000	6583	3417	04/20/2034	
57-53-00-191	*	FLAP VANE SUPPORT BLADES	RH OTBD	NDT	1/06/1988	0	10000	10000	6583	3417	04/20/2034	
57-53-00-193	*	FLAP FRONT SPAR	LH OTBD	NDT	1/06/1988	0	10000	10000	6583	3417	04/20/2034	
57-53-00-193	*	FLAP FRONT SPAR	RH OTBD	NDT	1/06/1988	0	10000	10000	6583	3417	04/20/2034	
572000-001	*	AILERON ANTI-FLOAT SPRING	LH	REPLACE	1/06/1988	0	10000	10000	6583	3417	04/20/2034	
572000-002	*	AILERON ANTI-FLOAT SPRING	RH	REPLACE	1/06/1988	0	10000	10000	6583	3417	04/20/2034	
57-40-00-177	*	WING RIB BACKUP FITTING WS 127.25	LH	NDT	1/12/2007	3745	7000	10745	2838	4162	09/30/2036	
57-40-00-177	*	WING RIB BACKUP FITTING WS 127.25	RH	NDT	1/12/2007	3745	7000	10745	2838	4162	09/30/2036	
57-53-00-189	*	FLAP FRONT SPAR	LH INBD	VISUAL	1/06/1988	0	11000	11000	6583	4417	08/02/2037	
57-53-00-189	*	FLAP FRONT SPAR	RH INBD	VISUAL	1/06/1988	0	11000	11000	6583	4417	08/02/2037	
53-10-00-197	*	REAR PRESS BULKHEAD WEB-FS621	FWD FACE	NDT	1/06/1988	0	12000	12000	6583	5417	11/14/2040	
78	*	T/R ROD END, 2 O'CLOCK ACTUATOR	LH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044	
78	*	T/R ROD END, 2 O'CLOCK ACTUATOR	RH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044	
78	*	T/R ROD END, 4 O'CLOCK ACTUATOR	LH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044	
78	*	T/R ROD END, 4 O'CLOCK ACTUATOR	RH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044	

**AIRFRAME LANDINGS REPORT**  
**CHALLENGER 5017**

1/28/2023  
N404HG

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDING		NEXT DUE	CURRENT	REMAIN	
78	*	T/R ROD END, 8 O'CLOCK ACTUATOR	LH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
78	*	T/R ROD END, 8 O'CLOCK ACTUATOR	RH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
78	*	T/R ROD END, 10 O'CLOCK ACTUATOR	LH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
78	*	T/R ROD END, 10 O'CLOCK ACTUATOR	RH	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-001		ROD END, THRUST REVERSER	#1	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-002		ROD END, THRUST REVERSER	#2	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-003		ROD END, THRUST REVERSER	#3	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-004		ROD END, THRUST REVERSER	#4	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-005		ROD END, THRUST REVERSER	#5	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-006		ROD END, THRUST REVERSER	#6	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-007		ROD END, THRUST REVERSER	#7	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
783040-008		ROD END, THRUST REVERSER	#8	REPLACE	5/09/2022	6492	6500	12992	91	6409	02/17/2044
322012-001	*	FITTING, NLG MAIN		REPLACE	1/06/1988	0	14100	14100	6583	7517	10/09/2047
53-10-01-102	*	SPLICE STRAP & SKIN STRNGER 20L-20R	FS559, 621	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
54-10-00-106	*	RIB UP CAP, SKIN, DOUBLR FS672.2-682		NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
54-10-00-106	*	RIB UPPER CAP, SKIN/DOUBLR FS672-682		NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-53-00-154	*	SUPPORT, FLAP VANE INTERMEDIATE	LH OUTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-53-00-180	*	FLAP VANE END RAMPS-171.94, 296.0	LH OUTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
32-00-00-245	*	VALVE, MLG SELECTOR		OVERHAUL	1/06/1988	0	15000	15000	6583	8417	09/23/2050
53-10-00-134	*	PRESS FLOOR-WING TIE BEAM-FS460.0		VISUAL	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-53-00-154	*	SUPPORT, FLAP VANE INTERMEDIATE	RH OUTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-163	*	FLAP HI-LOKS HINGE BOX/FWD FITTING	LH INBD	VISUAL	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-53-00-180	*	FLAP VANE END RAMPS-171.94, 296.0	RH OUTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-163	*	FLAP HI-LOKS HINGE BOX/FWD FITTING	RH INBD	VISUAL	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-164	*	FLAP ARMS - FWD UPPER LUGS - WS 220	LH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-164	*	FLAP ARMS - FWD UPPER LUGS - WS 220	RH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-165	*	FLAP ARM LOWER LUGS	LH INBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-165	*	FLAP ARM LOWER LUGS	RH INBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-166	*	FLAP HINGE BOX FWD ATTACH FITTINGS	LH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-166	*	FLAP HINGE BOX FWD ATTACH FITTINGS	RH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-167	*	FLAP VANE MAIN SUPPORT FITTINGS	LH OTBD	VISUAL	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-167	*	FLAP VANE MAIN SUPPORT FITTINGS	RH OTBD	VISUAL	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-171	*	FLAP HINGE BOX LOWER FLANGE SUPPORT	LH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-171	*	FLAP HINGE BOX LOWER FLANGE SUPPORT	RH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-172	*	FLAP FORWARD LUGS	LH INBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-172	*	FLAP FORWARD LUGS	RH INBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
98		SB 601-0610 (FWD LUGS)					15000	15000		8417	09/23/2050
57-53-00-175	*	FLAP VANE MID SUPPORT FITTINGS	LH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-53-00-175	*	FLAP VANE MID SUPPORT FITTINGS	RH OTBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-53-00-181	*	OUTBOARD FLAP FORWARD LUGS	LH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-53-00-181	*	OUTBOARD FLAP FORWARD LUGS	RH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-179	*	FLAP VANE CARRIAGES	LH INBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-179	*	FLAP VANE CARRIAGES	RH INBD	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050

**AIRFRAME LANDINGS REPORT  
CHALLENGER 5017**

1/28/2023  
N404HG

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDING		NEXT DUE	CURRENT	REMAIN	
57-40-00-197	*	BOLT, INBOARD FLAP INBD HINGE INBD	LH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, INBOARD FLAP INBD HINGE INBD	RH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, INBOARD FLAP INBD HINGE OUTBD	LH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, INBOARD FLAP INBD HINGE OUTBD	RH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, OUTBD FLAP OUTBD HINGE INBD	LH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, OUTBD FLAP OUTBD HINGE INBD	RH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, OUTBD FLAP MID HINGE OUTBD	LH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, OUTBD FLAP MID HINGE OUTBD	RH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, OUTBD FLAP OUTBD HINGE OUTBD	LH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
57-40-00-197	*	BOLT, OUTBD FLAP OUTBD HINGE OUTBD	RH	NDT	1/06/1988	0	15000	15000	6583	8417	09/23/2050
78	*	ACTUATOR, T/R 2 O'CLOCK BALLSCREW	LH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
78	*	ACTUATOR, T/R 2 O'CLOCK BALLSCREW	RH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
78	*	ACTUATOR, T/R 4 O'CLOCK BALLSCREW	LH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
78	*	ACTUATOR, T/R 4 O'CLOCK BALLSCREW	RH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
78	*	ACTUATOR, T/R 8 O'CLOCK BALLSCREW	LH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
78	*	ACTUATOR, T/R 8 O'CLOCK BALLSCREW	RH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
78	*	ACTUATOR, T/R 10 O'CLOCK BALLSCREW	LH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
78	*	ACTUATOR, T/R 10 O'CLOCK BALLSCREW	RH	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-002		BALLSCREW, ACTUATOR GEARBOX	#2	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-008		BALLSCREW, ACTUATOR GEARBOX	#1	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-003		BALLSCREW, ACTUATOR GEARBOX	#3	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-004		BALLSCREW, ACTUATOR GEARBOX	#4	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-005		BALLSCREW, ACTUATOR GEARBOX	#5	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-006		BALLSCREW, ACTUATOR GEARBOX	#6	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-007		BALLSCREW, ACTUATOR GEARBOX	#7	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
783001-008		BALLSCREW, ACTUATOR GEARBOX	#8	REPLACE	1/06/1988	0	16000	16000	6583	9417	01/05/2054
322013-001	*	AXLE FITTING, NLG		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
32	*	FITTING, NLG AXLE		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322104-001	*	PIN, NLG PIVOT (TRUNION)		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322118-001	*	PIN, NLG SLIDE TUBE TO END FITTING		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322105-001	*	TUBE, NLG SHOCK STRUT SLIDING		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322113-001	*	LINK, NLG DRAG BRACE LOWER		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322106-001	*	LINK, NLG DRAG BRACE (FORGING)	UPPER	REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322107-001	*	LINK, NLG DRAG BRACE	UPPER	REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
32	*	PIN, NLG DRAG BRACE UPPER PIVOT	LH	REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322117-001	*	PIN, NLG DRAG BRACE UPPER HINGE		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322115-001	*	PIN, NLG ATTACH (MAIN FRM TO DRAG BR		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
322118-001	*	SLIDING TUBE/END FIT SPECIAL BOLT		REPLACE	1/06/1988	0	19480	19480	6583	12897	06/12/2065
574000-001	*	PIN, MLG SIDE BRACE TO A/C FITTING	LH	REPLACE	10/08/2012	5191	30000	30000	6583	23417	01/04/2100
574000-002	*	PIN, MLG SIDE BRACE TO A/C FITTING	RH	REPLACE	10/08/2012	5191	30000	34048	2535	27465	04/24/2113
32	*	MLG PIN, SIDE STAY	LH	REPLACE	2/05/1992	702	46099	46801	5881	40218	03/18/2155
32	*	MLG PIN, SIDE STAY	RH	REPLACE	2/05/1992	702	46099	46801	5881	40218	03/18/2155
32	*	MLG FITTING, MAIN	LH	REPLACE	1/06/1988	0	48758	48758	6583	42175	08/22/2161



**AIRFRAME LANDINGS REPORT  
CHALLENGER 5017**

1/28/2023  
N404HG

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDING		NEXT DUE	CURRENT	REMAIN	
32	*	MLG FITTING, MAIN	RH	REPLACE	1/06/1988	0	48758	48758	6583	42175	08/22/2161
32	*	MLG PIN, PINTLE	LH	REPLACE	9/07/2012	5191	50405	49497	7491	42914	01/25/2164
32	*	MLG PIN, PINTLE	RH	REPLACE	9/07/2012	5191	50405	49497	7491	42914	01/25/2164
321040-001	*	MLG AXLE	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321040-002	*	MLG AXLE	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321701-001	*	MLG ARM, TRAILING	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321701-002	*	MLG ARM, TRAILING	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
783001-001	*	T/R ACTUATOR, BALLSCREW	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321013-001	*	MLG CYLINDER, SHOCK STRUT	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
783001-002	*	T/R ACTUATOR, BALLSCREW	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321013-002	*	MLG CYLINDER, SHOCK STRUT	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321700-001	*	MLG PISTON, SHOCK STRUT	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321700-002	*	MLG PISTON, SHOCK STRUT	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321011-001	*	MLG PIN, SHOCK STRUT LOWER	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321011-002	*	MLG PIN, SHOCK STRUT LOWER	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321756-001	*	MLG PIN, PIVOT	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321756-002	*	MLG PIN, PIVOT	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
99	*	AD 2018-17-02 HSTA ATTACH PINS					50000	50000		43417	09/20/2165
321758-001	*	MLG STUD, DOOR	LH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
321758-002	*	MLG STUD, DOOR	RH	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
323013-001	*	MLG PISTON ROD, SIDE STAY	#1	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
323013-002	*	MLG PISTON ROD, SIDE STAY	#2	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
323012-001	*	MLG CYLINDER, SIDE STAY	LH	REPLACE	9/07/2012	5191	50000	50000	6583	43417	09/20/2165
323012-002	*	MLG CYLINDER, SIDE STAY	RH	REPLACE	9/07/2012	5191	50000	50000	6583	43417	09/20/2165
274300-002	*	HSTA INST ATTACH PIN	LOWER	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
274300-003	*	HSTA INST ATTACH PIN	UPPER	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
274300-001	*	HSTA INST ATTACH PIN	LOWER	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
274300-004	*	HSTA INST ATTACH PIN	UPPER	REPLACE	1/06/1988	0	50000	50000	6583	43417	09/20/2165
323002-001	*	NLG UPLOCK		REPLACE	1/06/1988	0	52065	52065	6583	45482	07/03/2172
32	*	MLG PIN, SHOCK STRUT UPPER	LH	REPLACE	1/06/1988	0	53175	53175	6583	46592	02/25/2176
32	*	MLG PIN, SHOCK STRUT UPPER	RH	REPLACE	1/06/1988	0	53175	53175	6583	46592	02/25/2176
323005-001	*	MLG ACTUATOR ASSY, UPLOCK	RH	REPLACE	1/06/1988	0	61008	61008	6583	54425	11/21/2201
323005-001	*	MLG ACTUATOR ASSY, UPLOCK	LH	REPLACE	2/04/2008	4048	61008	64142	3449	57559	03/08/2212
323015-001	*	MLG BOLT, EYE SIDESTAY	LH	REPLACE	10/08/2012	5191	65360	65360	6583	58777	03/09/2216
323015-002	*	MLG BOLT, EYE SIDESTAY	RH	REPLACE	10/08/2012	5191	65360	65360	6583	58777	03/09/2216

NOTE: \* INDICATES FAA MANDATORY REQUIREMENT.

**APU REPORT  
CHALLENGER 5017**

1/28/2023  
N404HG

ATA CODE	FAA	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAIN	
49-10-60-201	*	APU INLET DUCT SCREENS		VISUAL	9/07/2012	6938.0	1500	8438.0	1335.0	165.0	08/14/2023
49-10-60-202	*	APU LOWER RUBBER BOOT		VISUAL	9/07/2012	6938.0	1500	8438.0	1335.0	165.0	08/14/2023
49-10-20-202	*	APU CRADLE ASSY		VISUAL	9/07/2012	6938.0	1500	8438.0	1335.0	165.0	08/14/2023
49-10-60-204	*	APU INLET DUCT		VISUAL	9/07/2012	6938.0	1500	8438.0	1335.0	165.0	08/14/2023
49-10-10-201	*	APU ENCLOSURE DRAINS		OPS TEST	11/17/2016	7439.0	1000	8439.0	834.0	166.0	08/15/2023
49	*	INSPECTION,APU 1000 HOUR			11/17/2016	7439.0	1000	8439.0	834.0	166.0	08/15/2023
49-43-04-201	*	APU EXTERNAL REMOTE SWITCH		OPS TEST	11/17/2016	7439.0	1000	8439.0	834.0	166.0	08/15/2023
49-80-00-201	*	APU EXHAUST SYSTEM		DETAIL	11/17/2016	7439.0	1000	8439.0	834.0	166.0	08/15/2023
49-81-00-201	*	APU EXHAUST SHIELD & VISOR ASSY		DETAIL	11/17/2016	7439.0	1000	8439.0	834.0	166.0	08/15/2023
49-10-10-203	*	APU ENCLOSURE ASSY		DETAIL	7/01/2021	7946.8	500	8446.8	326.2	173.8	08/24/2023
49	*	INSPECTION,APU 500 HOUR			7/01/2021	7946.8	500	8446.8	326.2	173.8	08/24/2023
24-22-00-214	*	APU ADAPTER OIL CHANGE			7/01/2021	7946.8	500	8446.8	326.2	173.8	08/24/2023
49-51-00-301	*	APU FILTER,LOAD CONTROL VALVE	APU	RESTORE	7/01/2021	7946.8	500	8446.8	326.2	173.8	08/24/2023
49-31-00-201	*	APU FUEL SYSTEM COMPONENTS		VISUAL	7/01/2021	7946.8	500	8446.8	326.2	173.8	08/24/2023
49-31-00-202	*	APU FUEL FILTER DIFF PRESS INDICATR		VISUAL	7/01/2021	7946.8	500	8446.8	326.2	173.8	08/24/2023
49-90-03-201	*	APU MAGNETIC CHIP DETECTOR		DETAIL	7/01/2021	7946.8	500	8446.8	326.2	173.8	08/24/2023
49-10-60-203	*	APU UPPER & LOWER INLET DUCT		VISUAL	11/22/2008	5475.0	3000	8475.0	2798.0	202.0	09/27/2023
49	*	INSPECTION,APU 1500 HOUR			9/07/2012	6938.0	1500	8475.0	1298.0	202.0	09/27/2023
49	*	INSPECTION,APU 3000 HOUR			11/22/2008	5475.0	3000	8475.0	2798.0	202.0	09/27/2023
49-15-01-201	*	APU DRAINS		OPS TEST	11/22/2008	5475.0	3000	8475.0	2798.0	202.0	09/27/2023
49-52-00-204	*	APU TRANSITION BLEED AIR DUCT		VISUAL	11/22/2008	5475.0	3000	8475.0	2798.0	202.0	09/27/2023
49-90-00-201	*	APU OIL SYSTEM COMPONENTS		VISUAL	11/22/2008	5475.0	3000	8475.0	2798.0	202.0	09/27/2023
49-90-03-202	*	APU OIL FILTER ELEMENT		DISCARD	12/08/2020	7866.0	1000	8866.0	407.0	593.0	01/08/2025
49-90-00-202	*	APU OIL		DISCARD	12/05/2020	7866.0	1000	8866.0	407.0	593.0	01/08/2025
49-42-01-201	*	APU MOTOR, STARTER		OVERHAUL	11/10/2011	6694.0	2500	9194.0	1579.0	921.0	02/06/2026
49-10-20-201	*	APU MOUNT SYSTEM		VISUAL	11/17/2016	7439.0	2000	9439.0	834.0	1166.0	11/27/2026
49	*	INSPECTION,APU 2000 HOUR			11/17/2016	7439.0	2000	9439.0	834.0	1166.0	11/27/2026
49-43-02-201	*	APU IGNITER PLUG		DETAIL	11/17/2016	7439.0	2000	9439.0	834.0	1166.0	11/27/2026
28-25-21-222	*	VALVES,APU RETURN LINE CHECK		LEAK CK	3/03/2011	9017.3	4800	13817.3	2662.9	2137.1	02/04/2030
24-22-16-207	*	APU FILTER ELEMENT,GENERATOR ADAPT	APU	REPLACE	9/03/2021	7977.0	2500	10477.0	296.0	2204.0	04/25/2030
491000-001	*	APU TURBINE ROTOR		REPLACE	11/22/2008	5475.0	10000	15475.0	2798.0	7202.0	09/26/2046
49	*	APU COMPRESSOR ROTOR		REPLACE	11/22/2008	5475.0	20000	25475.0	2798.0	17202.0	08/04/2079

NOTE: \* INDICATES FAA MANDATORY REQUIREMENT.

**LEFT ENGINE HOURS REPORT  
GENERAL ELECTRIC 3050271**

**1/28/2023  
N404HG**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T		N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						P A R T \$	L B R \$	
050012	*	INSPECTION, ENGINE	100 HOUR	LH		ENG HRS	9/08/2022	69.1	PART \$	0.00	04/20/2023
5-21-00		N/A	N/A			100 eng	11544.0		LBR \$	0.00	
050014	*	INSPECTION, ENGINE	300 HOUR	LH		ENG HRS	7/29/2022	255.0	PART \$	0.00	11/30/2023
5-21-00		N/A	N/A			300 eng	11529.9		LBR \$	0.00	
050016	*	INSPECTION, ENGINE	600 HOUR	LH		ENG HRS	1/14/2022	319.1	PART \$	0.00	02/14/2024
5-21-00		N/A	N/A			600 eng	11294.0		LBR \$	0.00	
72-00-00-215	*	ENGINE VARIABLE VANES		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350271	VISUAL		3000 eng	8912.0		LBR \$	0.00	
72-00-00-215	*	ENGINE COMPRESSOR CASINGS		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350271	VISUAL		3000 eng	8912.0		LBR \$	0.00	
72-00-00-215	*	ENGINE COMPRESSOR		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350271	BORESCOPE		3000 eng	8912.0		LBR \$	0.00	
72-00-00-217	*	ENGINE ACCESSORY GEARBOX MOUNTS		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350271	DETAIL		3000 eng	8912.0		LBR \$	0.00	
72-00-00-221	*	ENGINE 6 O'CLOCK C-SUMP SCAVENGE		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		N/A	N/A	CHECK		3000 eng	8912.0		LBR \$	0.00	
72-00-00-222	*	ENGINE LPT STATOR (6020T15G14)		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		N/A	N/A	VISUAL		3000 eng	8912.0		LBR \$	0.00	
72-00-00-223	*	ENGINE HPT STAGE 1,2 SHROUDS		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		N/A	N/A	VISUAL		3000 eng	8912.0		LBR \$	0.00	
72-00-00-224	*	ENGINE THERMOCOUPLE HARNESS		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		N/A	N/A	INSPECT		3000 eng	8912.0		LBR \$	0.00	
72-00-00-225	*	ENGINE TURBINE NOZZLES		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		N/A	N/A	VISUAL		3000 eng	8912.0		LBR \$	0.00	
72-00-00-226	*	ENGINE SWIRLERS		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		N/A	N/A	DETAIL		3000 eng	8912.0		LBR \$	0.00	
72-00-00-227	*	ENGINE PRIMARY SWIRLERS		LH		ENG HRS	3/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		N/A	N/A	VISUAL		3000 eng	8912.0		LBR \$	0.00	

**LEFT ENGINE HOURS REPORT  
GENERAL ELECTRIC 3050271**

**1/28/2023  
N404HG**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R							
72-00-00-228 5-20-15 rev 42	*	ENGINE STAGE 1,2 NOZZLE		LH		ENG HRS 3000 eng	3/03/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		N/A	N/A	VISUAL						
72-00-00-229 5-20-15 rev 42	*	ENGINE COMBUSTION LINER		LH		ENG HRS 3000 eng	3/03/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		N/A	N/A	VISUAL						
72-00-00-230 5-20-15 rev 42	*	ENGINE FUEL INJECTOR HEAT SHIELDS		LH		ENG HRS 3000 eng	3/03/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		N/A	N/A	CHECK						
72-00-00-231 5-20-15 rev 42	*	ENGINE FAN DISK		LH		ENG HRS 3000 eng	2/08/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		N/A	N/A	VISUAL						
72 05-11-05	*	SEAL, #5 BEARING CARBON		LH		ENG HRS 3000 eng	3/03/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		4074T58P11	N/A	REPLACE						
050025E 5-21-00	*	INSPECTION,ENGINE 3000 HOUR		LH		ENG HRS 3000 eng	3/03/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		CF34	350271							
72 05-11-05	*	RING,HPT STATOR STAGE 2 NOZZLE		LH		ENG HRS 3000 eng	2/03/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		4019T91P03	UNKNOWN	REPLACE						
73-10-11-204 5-20-15 rev 42	*	ENGINE FUEL PUMP ASSEMBLY		LH		ENG HRS 3000 eng	2/09/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		6052T03P03	CGWE0025	VISUAL						
73-20-11-206 5-20-15 rev 42	*	ENGINE FUEL CONTROL		LH		ENG HRS 3000 eng	2/09/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		6047T74P11	WYG49708	VISUAL						
79-21-01-202 5-20-15 rev 42	*	ENGINE C-SUMP SCAVENGE SCREENS		LH		ENG HRS 3000 eng	2/09/2011 8912.0	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11912.0
		N/A	N/A	DETAIL						
72-00-00-218 5-21-00		ENGINE OVERHAUL		LH		ENG HRS 6000 eng	3/24/2005 5954.7	379.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	04/27/2024 11954.7
		CF34	350271							
99	*	AD 2009-07-12 HP ROTOR 4-STEP SEAL		LH		ENG HRS 6000 eng		379.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	04/27/2024 11954.7
72 5-11-02	*	STUDS,HPT STAGE 2		LH		ENG HRS 6000 eng	5/13/2005 6028.7	453.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	07/25/2024 12028.7
		UNKNOWN	UNKNOWN	REPLACE						
050018 5-21-00	*	INSPECTION,ENGINE 1200 HOUR		LH		ENG HRS 1200 eng	1/14/2022 11294.0	919.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	02/03/2026 12494.0
		CF34A-3A	3050271							

**LEFT ENGINE HOURS REPORT  
GENERAL ELECTRIC 3050271**

1/28/2023  
N404HG

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T	N E X T D U E	
		P A R T N U M B E R	P A R T S E R I A L N U M B E R								
72-00-00-218	*	INSPECTION, ENGINE BORESCOPE		LH		ENG HRS	2/26/2021	2365.9	PART \$	0.00	11/06/2030
5-21-00		CF34	350271			3000 eng	10940.8		LBR \$	0.00	
									MHR:	0.0	

**LEFT ENGINE CYCLES REPORT**  
**GENERAL ELECTRIC 3050271**

1/28/2023  
N404HG

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T		N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						P A R T \$	L B R \$	
722150-001	*	DISK, FAN		LH		ENG CYC	1/06/1988		PART \$	0.00	03/27/2031
5-11-02		6020T62G04	GATLH090	REPLACE		9000 cyc	0	2484	LBR \$	0.00	9000
									MHR:	0.0	
99	*	AD 97-06-14 (FAN DISK)		LH		ENG CYC			PART \$	0.00	03/27/2031
						9000 cyc		2484	LBR \$	0.00	9000
									MHR:	0.0	
724642-001		COOLING PLATE, HPT STAGE #2 AFT		LH		ENG CYC	2/03/2011		PART \$	0.00	02/20/2032
05-11-03 P.803		5023T97P02	NCE4353W			6000 cyc	4816	2759	LBR \$	0.00	9275
									MHR:	0.0	
724632-001		PLATE, STAGE 1 AFT COOLING		LH		ENG CYC	2/03/2011		PART \$	0.00	03/15/2037
05-11-03 P.803		5041T70P03	FEB01864	REPLACE		6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
724628-001	*	SEAL, BALANCE AIR PISTON		LH		ENG CYC	2/03/2011		PART \$	0.00	03/15/2037
05-11-03		6078T90P01	NCE695FU	REPLACE		6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
724620-001	*	SHAFT, HPT		LH		ENG CYC	2/03/2011		PART \$	0.00	03/15/2037
05-11-03		6017T00P05	GEE1GF3E	REPLACE		6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
724611-001	*	DISK, STAGE 1 TURBINE		LH		ENG CYC	2/11/2011		PART \$	0.00	03/15/2037
05-11-03		6078T93P02	GATHPECA	REPLACE		6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
724612-001	*	DISK, STAGE 2 TURBINE		LH		ENG CYC	2/03/2011		PART \$	0.00	03/15/2037
05-11-03 P.803		6078T94P02	GATHPFEO	REPLACE		6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
724638-001	*	COUPLING, OUTER TORQUE		LH		ENG CYC	2/03/2011		PART \$	0.00	03/15/2037
05-11-03 P.803		5041T67P02	BEA1441A	REPLACE		6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
724636-001	*	COUPLING, INNER TORQUE		LH		ENG CYC	2/03/2011		PART \$	0.00	03/15/2037
05-11-03 P.803		5079T02P01	GATHPF24	REPLACE		6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
724630-001		COOLING PLATE, HPT STAGE #1 FWD		LH		ENG CYC	2/03/2011		PART \$	0.00	03/15/2037
05-11-03		4027T15P02	NCE367FJ			6000 cyc	4816	4300	LBR \$	0.00	10816
									MHR:	0.0	
723318-001	*	SHAFT, FORWARD COMPRESSOR		LH		ENG CYC	3/19/2005		PART \$	0.00	07/08/2038
5-11-02		5037T01P03	GATKB218	REPLACE		11740	3275	4700	LBR \$	0.00	11216
						----			MHR:	0.0	
723326-001	*	SEAL, REAR SHAFT CDP		LH		ENG CYC	1/06/1988		PART \$	0.00	12/22/2048
5-11-02		4019T38P01	PAMD0059	REPLACE		14400	0	7884	LBR \$	0.00	14400
						----			MHR:	0.0	
725338-001	*	CONE, TURBINE DRIVE		LH		ENG CYC	2/03/2011		PART \$	0.00	03/24/2049
05-11-04		4922T18P01	GATKJ506	REPLACE		15000	4816	7960	LBR \$	0.00	14476
						----			MHR:	0.0	

**LEFT ENGINE CYCLES REPORT**  
**GENERAL ELECTRIC 3050271**

1/28/2023  
N404HG

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R							
722151-001	*	SHAFT, FAN DRIVE		LH		ENG CYC	1/06/1988		PART \$ 0.00	12/12/2050
5-11-01		6036T78P02	CWE01948	REPLACE		15000	0	8484	LBR \$ 0.00	15000
						----			MHR: 0.0	
723322-001	*	DISK, STAGE 2 COMPRESSOR		LH		ENG CYC	1/06/1988		PART \$ 0.00	12/12/2050
5-11-02		6036T91P01	GATJB019	REPLACE		15000	0	8484	LBR \$ 0.00	15000
						----			MHR: 0.0	
723320-001	*	DISK, STAGE 1 COMPRESSOR		LH		ENG CYC	3/19/2005		PART \$ 0.00	09/15/2061
5-11-02		6087T00G02	GATHEGJA	REPLACE		15000	3275	11759	LBR \$ 0.00	18275
						----			MHR: 0.0	
72	*	SPOOL, COMPRESSOR FORWARD		LH		ENG CYC	3/19/2005		PART \$ 0.00	09/15/2061
5-11-02		6078T56P05	GWN094GH	REPLACE		15000	3275	11759	LBR \$ 0.00	18275
						----			MHR: 0.0	
72	*	DISK, STAGE 3 TURBINE		LH		ENG CYC	2/03/2011		PART \$ 0.00	10/09/2066
05-11-04		6078T91P02	XAEJ1842	REPLACE		15000	4816	13300	LBR \$ 0.00	19816
						----			MHR: 0.0	
725326-001	*	DISK, STAGE 6 TURBINE		LH		ENG CYC	2/03/2011		PART \$ 0.00	10/09/2066
05-11-04		6078T89P03	GATHP2MP	REPLACE		15000	4816	13300	LBR \$ 0.00	19816
						----			MHR: 0.0	
725325-001	*	DISK, STAGE 5 TURBINE		LH		ENG CYC	2/03/2011		PART \$ 0.00	10/09/2066
05-11-04		6078T92P02	GATHP6PJ	REPLACE		15000	4816	13300	LBR \$ 0.00	19816
						----			MHR: 0.0	
99	*	AD 99-22-10 REPLACE STG 9 HCP DISK		LH		ENG CYC			PART \$ 0.00	05/17/2067
						20000		13484	LBR \$ 0.00	20000
						----			MHR: 0.0	
723330-001	*	SPOOL, COMPRESSOR REAR		LH		ENG CYC	3/19/2005		PART \$ 0.00	04/11/2068
5-11-02		5087T46P02	GWN08M01	REPLACE		17000	3275	13759	LBR \$ 0.00	20275
						----			MHR: 0.0	
72	*	DISK, STAGE 4 TURBINE		LH		ENG CYC	2/03/2011		PART \$ 0.00	05/05/2073
05-11-04		6078T02P04	XAEJ0871	REPLACE		17000	4816	15300	LBR \$ 0.00	21816
						----			MHR: 0.0	
723351-001	*	DISK, STAGE 9 COMPRESSOR		LH		ENG CYC	3/19/2005		PART \$ 0.00	02/18/2078
05-11-03		6087T01P03	NCE62984	REPLACE		20000	3275	16759	LBR \$ 0.00	23275
						----			MHR: 0.0	
722210-001	*	SHAFT, COMPRESSOR REAR		LH		ENG CYC	3/19/2005		PART \$ 0.00	12/28/2087
5-11-02		6087T03P03	GWN08RPD	REPLACE		23000	3275	19759	LBR \$ 0.00	26275
						----			MHR: 0.0	
725330-001	*	SEAL, STAGE 3/4 TURBINE		LH		ENG CYC	2/03/2011		PART \$ 0.00	08/15/2097
05-11-04		4922T20P01	PAMF9929	REPLACE		29730	4816	22690	LBR \$ 0.00	29206
						----			MHR: 0.0	
725534-001	*	SEAL, STAGE 5/6 TURBINE		LH		ENG CYC	2/03/2011		PART \$ 0.00	08/15/2097
05-11-04		4922T22P01	HAAC5521	REPLACE		29730	4816	22690	LBR \$ 0.00	29206
						----			MHR: 0.0	

**LEFT ENGINE CYCLES REPORT**  
**GENERAL ELECTRIC 3050271**

1/28/2023  
**N404HG**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION A C T I O N	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E	
		PART NUMBER	PART SERIAL NUMBER								
725332-001	*	SEAL, STAGE 4/5 TURBINE		LH		ENG CYC	2/03/2011	22690	PART \$	0.00	08/15/2097
05-11-04		4922T21P01	PAME7846	REPLACE		29730 ----	4816		LBR \$	0.00	
725314-001	*	SHAFT, REAR TURBINE		LH		ENG CYC	2/03/2011	27450	PART \$	0.00	04/06/2113
05-11-04		4922T19P01	GATEY175	REPLACE		34490 ----	4816		LBR \$	0.00	
722151-001	*	SHAFT, FAN FORWARD		LH		ENG CYC	1/06/1988	31764	PART \$	0.00	06/08/2127
5-11-02		6017T63P04	GATJL798	REPLACE		38280 ----	0		LBR \$	0.00	
									MHR:	0.0	



**RIGHT ENGINE HOURS REPORT**  
**GENERAL ELECTRIC 350268**

**1/28/2023**  
**N404HG**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T		N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						P A R T \$	M H R	
050012	*	INSPECTION, ENGINE	100 HOUR	RH		ENG HRS	9/08/2022	69.1	PART \$	0.00	04/20/2023
5-21-00		N/A	N/A			100 eng	11444.6		LBR \$	0.00	11544.6
050014	*	INSPECTION, ENGINE	300 HOUR	RH		ENG HRS	7/29/2022	255.0	PART \$	0.00	11/30/2023
5-21-00		N/A	N/A			300 eng	11430.5		LBR \$	0.00	11730.5
050016	*	INSPECTION, ENGINE	600 HOUR	RH		ENG HRS	1/14/2022	319.1	PART \$	0.00	02/14/2024
5-21-00		N/A	N/A			600 eng	11194.6		LBR \$	0.00	11794.6
72-00-00-215	*	ENGINE VARIABLE VANES		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	VISUAL		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-215	*	ENGINE COMPRESSOR CASINGS		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	VISUAL		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-215	*	ENGINE COMPRESSOR		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	BORESCOPE		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-217	*	ENGINE ACCESSORY GEARBOX MOUNTS		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	DETAIL		3000 eng	8812.6		LBR \$	0.00	11812.6
050025E	*	INSPECTION, ENGINE	3000 HOUR	RH		ENG HRS	2/09/2011	337.1	PART \$	0.00	03/07/2024
5-21-00		N/A	N/A			3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-221	*	ENGINE 6 O'CLOCK C-SUMP SCAVENGE		RH		ENG HRS	2/09/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	CHECK		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-222	*	ENGINE LPT STATOR (6020T15G14)		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	VISUAL		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-223	*	ENGINE HPT STAGE 1,2 SHROUDS		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	VISUAL		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-224	*	ENGINE THERMOCOUPLE HARNESS		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	INSPECT		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-225	*	ENGINE TURBINE NOZZLES		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	VISUAL		3000 eng	8812.6		LBR \$	0.00	11812.6
72-00-00-226	*	ENGINE SWIRLERS		RH		ENG HRS	2/03/2011	337.1	PART \$	0.00	03/07/2024
5-20-15 rev 42		CF34	350268	DETAIL		3000 eng	8812.6		LBR \$	0.00	11812.6

**RIGHT ENGINE HOURS REPORT**  
**GENERAL ELECTRIC 350268**

1/28/2023  
N404HG

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R							
72-00-00-227 5-20-15 rev 42	*	ENGINE PRIMARY SWIRLERS		RH		ENG HRS 3000 eng	2/03/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		CF34	350268	VISUAL						
72-00-00-228 5-20-15 rev 42	*	ENGINE STAGE 1,2 NOZZLE		RH		ENG HRS 3000 eng	2/03/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		CF34	350268	VISUAL						
72-00-00-229 5-20-15 rev 42	*	ENGINE COMBUSTION LINER		RH		ENG HRS 3000 eng	2/03/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		CF34	350268	VISUAL						
72-00-00-230 5-20-15 rev 42	*	ENGINE FUEL INJECTOR HEAT SHIELDS		RH		ENG HRS 3000 eng	2/03/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		CF34	350268	CHECK						
72-00-00-231 5-20-15 rev 42	*	ENGINE FAN DISK		RH		ENG HRS 3000 eng	2/09/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		CF34	350268	VISUAL						
72 05-11-05	*	SEAL,#5 BEARING CARBON		RH		ENG HRS 3000 eng	2/03/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		4074T58P11	350268	REPLACE						
72 05-11-05	*	RING,HPT STATOR STAGE 2 NOZZLE		RH		ENG HRS 3000 eng	2/03/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		4019T91P03	UNKNOWN	REPLACE						
73-10-11-204 5-20-15 rev 42	*	ENGINE FUEL PUMP ASSEMBLY		RH		ENG HRS 3000 eng	2/09/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		6052T06P05	CGWE0057	VISUAL						
73-20-11-206 5-20-15 rev 42	*	ENGINE FUEL CONTROL		RH		ENG HRS 3000 eng	2/09/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		6047T74P11	WYG49704	VISUAL						
79-21-01-202 5-20-15 rev 42	*	ENGINE C-SUMP SCAVENGE SCREENS		RH		ENG HRS 3000 eng	2/09/2011 8812.6	337.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	03/07/2024 11812.6
		N/A	N/A	DETAIL						
72-00-00-218 5-21-00		ENGINE OVERHAUL		RH		ENG HRS 6000 eng	5/13/2005 5929.3	453.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	07/25/2024 11929.3
		CF34	350268							
99	*	AD 2009-07-12 HP ROTOR 4-STEP SEAL		RH		ENG HRS 6000 eng		453.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	07/25/2024 11929.3
72 5-11-02	*	STUDS,HPT STAGE 2		RH		ENG HRS 6000 eng	5/13/2005 5929.3	453.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	07/25/2024 11929.3
		UNKNOWN	UNKNOWN	REPLACE						
050018 5-21-00	*	INSPECTION,ENGINE 1200 HOUR		RH		ENG HRS 1200 eng	1/14/2022 11194.6	919.1	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	02/03/2026 12394.6
		CF34A-3A	350268							

**RIGHT ENGINE HOURS REPORT  
GENERAL ELECTRIC 350268**

1/28/2023  
N404HG

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION A C T I O N	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E	
		PART NUMBER	PART SERIAL NUMBER								
72-00-00-218	*	INSPECTION, ENGINE BORESCOPE		RH		ENG HRS	2/26/2021	2365.9	PART \$	0.00	11/06/2030
5-21-00		CF34	350268			3000 eng	10841.4		LBR \$	0.00	
									MHR:	0.0	

**RIGHT ENGINE CYCLES REPORT**  
**GENERAL ELECTRIC 350268**

1/28/2023  
N404HG

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T		N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						P A R T \$	L B R \$	
72 5-11-02	*	DISK, FAN		RH		ENG CYC 9000 cyc	1/06/1988 1827	2499	PART \$ LBR \$ MHR:	0.00 0.00 0.0	04/14/2031 8991
		6020T62G04	GATKA405	REPLACE							
99	*	AD 97-06-14 (FAN DISK)		RH		ENG CYC 9000 cyc		2508	PART \$ LBR \$ MHR:	0.00 0.00 0.0	04/25/2031 9000
724632-001 05-11-03 P.803		PLATE, STAGE 1 AFT COOLING		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		5041T70P03	FEB02416	REPLACE							
724628-001 05-11-03	*	SEAL, BALANCE AIR PISTON		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		6078T90P01	NCE988FP	REPLACE							
724620-001 05-11-03	*	SHAFT, HPT		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		6017T00P05	GEE1GEG6	REPLACE							
724611-001 05-11-03	*	DISK, STAGE 1 TURBINE		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		6078T93P02	GATHPAJ8	REPLACE							
724612-001 05-11-03 P.803	*	DISK, STAGE 2 TURBINE		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		6078T94P02	GATHPFE2	REPLACE							
724638-001 05-11-03 P.803	*	COUPLING, OUTER TORQUE		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		5041T67P02	BEA1276A	REPLACE							
724636-002 05-11-03 P.803	*	COUPLING, INNER TORQUE		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		5079T02P01	GATHPG6T	REPLACE							
724642-001 05-11-03 P.803		COOLING PLATE, HPT STAGE #2 AFT		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		5023T97P02	NCE837AC								
724630-001 05-11-03		COOLING PLATE, HPT STAGE #1 FWD		RH		ENG CYC 6000 cyc	2/03/2011 4792	4300	PART \$ LBR \$ MHR:	0.00 0.00 0.0	03/15/2037 10792
		4027T15P02	NCE365FJ								
723318-001 5-11-02	*	SHAFT, FORWARD COMPRESSOR		RH		ENG CYC 11740 ----	4/07/2005 3285	4723	PART \$ LBR \$ MHR:	0.00 0.00 0.0	08/04/2038 11215
		5037T01P03	GATKB212	REPLACE							
723326-001 5-11-02	*	SEAL, REAR SHAFT CDP		RH		ENG CYC 14400 ----	4/07/2005 3285	7383	PART \$ LBR \$ MHR:	0.00 0.00 0.0	05/01/2047 13875
		4019T38P01	PAMC7514	REPLACE							
725338-002 05-11-04	*	CONE, TURBINE DRIVE		RH		ENG CYC 15000 ----	2/03/2011 4792	7982	PART \$ LBR \$ MHR:	0.00 0.00 0.0	04/19/2049 14474
		4922T18P01	GATKJ504	REPLACE							

**RIGHT ENGINE CYCLES REPORT**  
**GENERAL ELECTRIC 350268**

1/28/2023  
N404HG

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T		N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						P A R T \$	L B R \$	
723322-001	*	DISK, STAGE 2 COMPRESSOR		RH		ENG CYC	4/07/2005	7983	PART \$	0.00	04/20/2049
5-11-02		6036T91P01	GATJB040	REPLACE		15000	3285		LBR \$	0.00	14475
722151-001	*	SHAFT, FAN DRIVE		RH		ENG CYC	3/05/1998	8499	PART \$	0.00	12/30/2050
5-11-01		6036T78P02	CWE01953	REPLACE		15000	1827		LBR \$	0.00	14991
723320-001	*	DISK, STAGE 1 COMPRESSOR		RH		ENG CYC	4/07/2005	11793	PART \$	0.00	10/26/2061
5-11-02		6087T00G02	GATHEGJR	REPLACE		15000	3285		LBR \$	0.00	18285
72	*	SPOOL, COMPRESSOR FORWARD		RH		ENG CYC	4/07/2005	11793	PART \$	0.00	10/26/2061
5-11-02		6078T56P05	GWN094GJ	REPLACE		15000	3285		LBR \$	0.00	18285
72	*	DISK, STAGE 3 TURBINE		RH		ENG CYC	2/03/2011	13300	PART \$	0.00	10/09/2066
05-11-04		6078T91P02	XAEJ1847	REPLACE		15000	4792		LBR \$	0.00	19792
725326-001	*	DISK, STAGE 6 TURBINE		RH		ENG CYC	2/03/2011	13300	PART \$	0.00	10/09/2066
05-11-04		6078T89P03	GATHRT75	REPLACE		15000	4792		LBR \$	0.00	19792
725325-001	*	DISK, STAGE 5 TURBINE		RH		ENG CYC	2/03/2011	13300	PART \$	0.00	10/09/2066
05-11-04		6078T92P02	GATHP5F6	REPLACE		15000	4792		LBR \$	0.00	19792
99	*	AD 99-22-10 REPLACE STG 9 HCP DISK		RH		ENG CYC		13508	PART \$	0.00	06/15/2067
						20000			LBR \$	0.00	20000
723330-001	*	SPOOL, COMPRESSOR REAR		RH		ENG CYC	4/07/2005	13793	PART \$	0.00	05/22/2068
5-11-02		5087T46P02	GATHCLT3	REPLACE		17000	3285		LBR \$	0.00	20285
72	*	DISK, STAGE 4 TURBINE		RH		ENG CYC	2/03/2011	15300	PART \$	0.00	05/05/2073
05-11-04		6078T02P04	XAEJ0884	REPLACE		17000	4792		LBR \$	0.00	21792
723351-001	*	DISK, STAGE 9 COMPRESSOR		RH		ENG CYC	4/07/2005	16793	PART \$	0.00	03/31/2078
05-11-03		6087T01P03	NCE8167W	REPLACE		20000	3285		LBR \$	0.00	23285
722210-001	*	SHAFT, COMPRESSOR REAR		RH		ENG CYC	4/07/2005	19793	PART \$	0.00	02/07/2088
5-11-02		6087T03P03	GWN07E3A	REPLACE		23000	3285		LBR \$	0.00	26285
72	*	SEAL, STAGE 3/4 TURBINE		RH		ENG CYC	2/03/2011	22712	PART \$	0.00	09/10/2097
05-11-04		4922T20P01	PAMF9938	REPLACE		29730	4792		LBR \$	0.00	29204
72	*	SEAL, STAGE 5/6 TURBINE		RH		ENG CYC	2/03/2011	22712	PART \$	0.00	09/10/2097
05-11-04		4922T22P01	HAAC5524	REPLACE		29730	4792		LBR \$	0.00	29204

**RIGHT ENGINE CYCLES REPORT  
GENERAL ELECTRIC 350268**

**1/28/2023  
N404HG**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION A C T I O N	COMP #	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	C O S T	N E X T D U E
		PART NUMBER	PART SERIAL NUMBER							
72 05-11-04	*	SEAL, STAGE 4/5 TURBINE		RH		ENG CYC 29730 ----	2/03/2011 4792	22712	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	09/10/2097 29204
		4922T21P01	PAME7844	REPLACE						
72 05-11-04	*	SHAFT, REAR TURBINE		RH		ENG CYC 34490 ----	2/03/2011 4792	27472	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	05/02/2113 33964
		4922T19P01	GATEY178	REPLACE						
722152-002 5-11-02	*	SHAFT, FAN FORWARD		RH		ENG CYC 38280 ----	3/05/1998 1827	32898	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	02/28/2131 39390
		6017T63P05	GATBM601	REPLACE						

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 2000-01-51</b>		TO PREVENT A FUEL FIRE DUE TO ELECTRICAL SPARKS CONTACTING THE MAINT. LIGHT HOUSING OF THE FUEL PANEL	CANADAIR	DATE:	DATE:
1/26/2000	ONE TIME		N/A BY AIRCRAFT MODEL		TIME:
				LD/CY:	LD/CY:
<b>AD 2000-19-01</b>		TO PREVENT WATER FREEZING ON THE BRAKE WHILE THE AIRPLANE IS IN FLIGHT	CANADAIR	DATE:	DATE:
10/25/2000	ONE TIME		N/A BY AIRCRAFT MODEL		TIME:
				LD/CY:	LD/CY:
<b>AD 2000-24-01</b>		INSTALLATION OF PROTECTION SHIELDS IN THE WHEEL BAY OF THE MAIN LANDING GEAR	CANADAIR	DATE: 2/07/2001	DATE:
12/19/2000	ONE TIME		C/W SB 601-0507		TIME:
				LD/CY:	LD/CY:
<b>AD 2001-15-17</b>		MODIFY THE ALTITUDE ENCODER INPUTS OF THE CTL-92 TRANSPONDER CONTROL PANELS	ROCKWELL COLLINS	DATE: 11/09/2001	DATE:
8/20/2001	ONE TIME		N/A		TIME:
				LD/CY:	LD/CY:
<b>AD 2001-15-24</b>		MODIFICATION OF THE WIRING FOR INTERNAL FUEL/DEFUEL PANEL	CANADAIR	DATE:	DATE:
9/10/2001	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		TIME:
				LD/CY:	LD/CY:
<b>AD 2001-22-14</b>		REPLACEMENT OF FIRE EXTINGUISHER SYSTEM CARTRIDGES	OVERLAND AVIATION	DATE: 5/14/2002	DATE:
12/10/2001	ONE TIME		N/A		TIME: 4789.0
				LD/CY: 2614	LD/CY:
<b>AD 2002-06-06</b>		TEST AND OR MODIFY COLLINS TDR-94 TRANSPONDERS	ROCKWELL COLLINS	DATE: 3/06/2004	DATE:
5/03/2002	ONE TIME		N/A EQUIPMENT NOT INSTALLED		TIME: 5655.0
				LD/CY: 3073	LD/CY:
<b>AD 2002-08-08(a)</b>		PERFORM DETAIL INSPECTION OF THE IDG CABLES ON LH/RH ENGINES TO DETECT CHAFING	CANADAIR	DATE:	DATE:
5/08/2002	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		TIME:
				LD/CY:	LD/CY:
<b>AD 2003-08-12</b>		DETAIL INSPECTION TO DETECT CRACKS OF THE INBOARD FLAP ACTUATOR BEAM SUPERSEDED BY AD 2004-09-37	CANADAIR	DATE: 4/03/2002	DATE:
5/08/2003	ONE TIME		C/W SB 601-0538 PART C		TIME: 4742.0
				LD/CY: 2598	LD/CY:
<b>AD 2003-22-12(a)</b>		TO PREVENT FLAT SPOTS ON THE POTENTIOMETER OF THE AOA DUE TO WEAR	CANADAIR	DATE: 12/14/2003	DATE:
12/12/2003	ONE TIME		FOUND P/C/W		TIME: 5568.4
				LD/CY: 3021	LD/CY:
<b>AD 2003-26-14</b>		REPLACEMENT OF HAND HELD FAULTY FIRE EXTINGUISHERS WHICH DO NOT FULLY DISCHARGE	WATER KIDDE	DATE: 4/30/2004	DATE:
2/20/2004	ONE TIME		N/A		TIME:
				LD/CY:	LD/CY:
<b>AD 2004-08-16</b>		MODIFY NARCO AT150 TRANSPONDERS TO PREVENT NOT RESPONDING & RECOGNIZING S MODE INTERROGRATIONS	NARCO AVIONICS	DATE: 10/06/2005	DATE:
6/01/2004	ONE TIME		N/A BY TRANSPONDER MANUFACTURE		TIME:
				LD/CY:	LD/CY:
<b>AD 2004-09-37 H</b>		DETAIL INSPECTION TO DETECT CRACKS OF THE INBOARD FLAP ACTUATOR BEAM	CANADAIR	DATE:	DATE:
6/11/2004	ONE TIME				TIME:
				LD/CY:	LD/CY: 7000
<b>AD 2004-25-19</b>		PERFORM A LINEARITY TEST OF EACH AOA TRANSDUCER	CANADAIR	DATE: 1/08/2014	DATE:
1/04/2005	ONE TIME		N/A BY PART NUMBER INSTALLED		TIME: 9668.1
				LD/CY: 5277	LD/CY:

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 2004-25-19 1/04/2005	ONE TIME	REVISE THE (AFM) TO PROVIDE CREW WITH PROCEDURES & LIMITS FOR OPERATING WITH OUT-OF-TOLERANCE AOA TRANSDUSERS	CANADAIR N/A BY PART NUMBER INSTALLED	DATE: 1/09/2014 TIME: 9668.1 LD/CY: 5277	DATE: TIME: LD/CY:
AD 2004-25-19 1/04/2005	ONE TIME	PERFORM A LINEARITY TEST OF EACH AOA TRANSDUCER	CANADAIR N/A BY PART NUMBER INSTALLED	DATE: 1/08/2014 TIME: 9668.1 LD/CY: 5277	DATE: TIME: LD/CY:
AD 2005-04-07 2/22/2005	ONE TIME	AFM REVISION TO PREVENT POSSIBLE CONTROL ON TAKE-OFF RESULTING FROM FROST, ICE, THIS AD SUPERSEDED BY AD 2008-08-03	CANADAIR REVISED AFM	DATE: 2/21/2005 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 2005-11-04 5/27/2005	ONE TIME	MODIFICATION TO PREVENT POSSIBLE INTERFERENCE WITH PILOT/COPILOT MICROPHONE CONTROL COLUMN JACKS	CANADAIR N/A BY AIRCRAFT SERIAL NUMBER	DATE: 1/08/2014 TIME: 9668.1 LD/CY: 5277	DATE: TIME: LD/CY:
AD 2005-11-04 2/22/2005	ONE TIME	AFM REVISION TO PREVENT POSSIBLE INTERFERENCE WITH PILOT/COPILOT MICROPHONE CONTROL COLUMN JACKS	CANADAIR N/A BY AIRCRAFT SERIAL NUMBER	DATE: 1/08/2014 TIME: 9668.1 LD/CY: 5277	DATE: TIME: LD/CY:
AD 2005-15-04 8/30/2005	ONE TIME	ADD SERIAL NUMBERS AND PART NUMBERS FOR LIFE LIMITED LANDING GEAR PARTS LISTED IN THE SB SUPERSEDED BY AD 2014-15-13	CANADAIR C/W ASB A601-0546	DATE: 1/08/2014 TIME: 9668.1 LD/CY: 5277	DATE: TIME: LD/CY:
AD 2005-26-04 1/25/2006	ONE TIME	SEND REPORT OF MEASUREMENT FINDINGS	CANADAIR C/W SB 601-0555	DATE: 9/18/2005 TIME: 6282.7 LD/CY: 3441	DATE: TIME: LD/CY:
AD 2005-26-04 1/25/2006	ONE TIME	MEASURE THE CLEARANCE BETWEEN THE YOKE & THE LOWER SIDE OF THE GIMBAL PIN HEAD ON THE HSTA	CANADAIR N/A BY AIRCRAFT MODEL	DATE: 9/18/2005 TIME: 6282.7 LD/CY: 3941	DATE: TIME: LD/CY:
AD 2006-02-04 2/24/2006	ONE TIME	MODIFY & RIG THE ADJUSTABLE RUDDER BALANCE SPRING ASSEMBLY FOR THE RUDDER CONTROL SURFACE	CANADAIR C/W ASB 601-0549	DATE: 7/10/2006 TIME: 6612.9 LD/CY: 3620	DATE: TIME: LD/CY:
AD 2006-18-04 9/01/2006	ONE TIME	REVISE THE EMERGENCY PROCEDURES OF (AFM) TO ADVISE THE FLIGHTCREW OF ADDITIONAL SUPERSEDED BY AD 2006-22-06	CANADAIR N/A BY AIRCRAFT MODEL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 2006-25-16 1/19/2007	ONE TIME	CORROSION PREVENTION AND CONTROL 12 MONTH ITEMS	BOMBARDIER PREVIOUSLY C/W	DATE: 1/08/2014 TIME: 9668.1 LD/CY: 5277	DATE: TIME: LD/CY:
AD 2007-05-11 3/20/2007	ONE TIME	REVISE THE EMERGENCY PROCEDURES OF (AFM) TO ADVISE THE FLIGHTCREW OF ADDITIONAL PROCEDURES WITH STABILIZER TRIM RUN AWAY	CANADAIR N/A BY AIRCRAFT MODEL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
AD 2007-07-12 4/18/2007	ONE TIME	DETERMINE P/N & MOD LEVEL OF NZ-2000 NAV COMPUTER & IC-800 INTERGRATED AVIONICS SUPERSEDED BY AD 2009-08-01	HONEYWELL C/W A23-6111-008 R1	DATE: 2/04/2008 TIME: 7453.6 LD/CY: 4048	DATE: TIME: LD/CY:
AD 2007-14-02 8/16/2007	ONE TIME	REPLACE DEFECTIVE SELECTOR VALVES OF THE NLG & NOSE GEAR DOOR P/N 750006000 S/N 0001 THROUGH 0767	CANADAIR C/W ASB 601-0558	DATE: 2/04/2008 TIME: 7453.6 LD/CY: 4048	DATE: TIME: LD/CY:



**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 2008-08-06</b>		AFM REVISION TO PREVENT POSSIBLE CONTROL ON TAKE-OFF RESULTING FROM FROST, ICE, SNOW OR SLUSH ON WINGS	CANADAIR	DATE: 2/27/2007	DATE:
4/21/2008	ONE TIME		REVISED AFM	TIME: 6924.6	TIME:
				LD/CY: 3790	LD/CY:
<b>AD 2008-21-09</b>		AFM REVISION TO PREVENT POSSIBLE CONTROL ON TAKE-OFF RESULTING FROM FROST, ICE, SNOW OR SLUSH ON WINGS	CANADAIR	DATE: 2/27/2007	DATE:
10/31/2008	ONE TIME		REVISED AFM	TIME: 6924.6	TIME:
				LD/CY: 3790	LD/CY:
<b>AD 2009-06-05</b>	R1	REVIEW AIRCRAFT MAINTENANCE RECORDS TO DETERMINE IF PICCOLO DUCTS OR COMPLETE LEADING EDGE REPLACED SINCE 8/1/2000	CANADAIR	DATE: 3/06/2011	DATE:
4/01/2010	ONE TIME		C/W ASB 601-0585	TIME: 8630.0	TIME:
				LD/CY: 4655	LD/CY:
<b>AD 2009-08-01</b>		SOFTWARE UPDATE OF NZ-2000 NAV COMPUTER & IC-800 INTERGRATED AVIONICS COMPUTER	HONEYWELL	DATE: 12/23/2009	DATE:
5/14/2009	ONE TIME		N/A BY EFFECTIVITY	TIME: 8440.7	TIME:
				LD/CY: 4574	LD/CY:
<b>AD 2009-14-03</b>		REVISE THE NORMAL PROCEDURES OF THE AFM BY INSERTING APPLICABLE TEMP REVISION ABOUT STALL PROTECTION SYS TEST	BOMBARDIER	DATE: 2/27/2009	DATE:
8/12/2009	ONE TIME		C/W AFM REVISION	TIME: 8315.1	TIME:
				LD/CY: 4519	LD/CY:
<b>AD 2009-23-09</b>		INSPECT THE (ADG) AIR DRIVEN GENERATOR POWER FEEDER HARNESS TO DETERMINE THE WIRE TYPE	BOMBARDIER	DATE: 10/08/2012	DATE:
12/14/2009	ONE TIME		C/W SB 601-0591 ON 2/9/2008	TIME: 9547.9	TIME:
				LD/CY: 5191	LD/CY:
<b>AD 2009-24-18</b>		REVISE THE AIRWORTHINESS LIMITATIONS SECTION OF THE INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENTS	BOMBARDIER	DATE: 2/19/2011	DATE:
1/08/2010	ONE TIME		FOUND P/C/W ON 1/20/2010	TIME: 9017.3	TIME:
				LD/CY: 4867	LD/CY:
<b>AD 2010-10-26</b>		DO AN INSPECTION OF THE SELECT VALVE OF THE NLG & NOSE GEAR DOOR FOR P/N 601R75146-1 IS INSTALLED	CANADAIR	DATE: 2/18/2011	DATE:
6/25/2010	ONE TIME		N/A BY PART NUMBER	TIME: 9017.3	TIME:
				LD/CY: 4867	LD/CY:
<b>AD 2010-14-05</b>		REPLACEMENT OF #2 BRAKE ACCUMULATOR PN 601R75138-1,601R75138-3,08-60163-001/ SUPERSEDED BY AD 2019-08-08	CANADAIR	DATE: 10/01/2010	DATE:
8/05/2010	ONE TIME		N/A BY PART NUMBER	TIME: 8867.4	TIME:
				LD/CY: 4788	LD/CY:
<b>AD 2011-01-09</b>		INSPECT AIRCRAFT RECORDS TO DETERMINE IF PBE PROTECTIVE BREATHING EQUIP P/N 119003-11 & EFFECTED S/N'S ARE INSTALLED	B/E AEROSPACE	DATE: 5/09/2011	DATE:
2/09/2011	ONE TIME		N/A EQUIPMENT NOT INSTALLED	TIME: 9097.6	TIME:
				LD/CY: 4921	LD/CY:
<b>AD 2011-09-09</b>		ACCOMPLISH 30-11-00-101 ON WING ANTI-ICING	CANADAIR	DATE: 1/08/2014	DATE:
8/19/2011	ONE TIME		C/W SB 601-0590 NOT C/W	TIME: 9668.1	TIME:
				LD/CY: 5277	LD/CY:
<b>AD 2011-09-09</b>		REVISING TIME LIMITS/ MAINTENANCE CHECKS FOR ANTI-ICING	CANADAIR	DATE: 1/08/2014	DATE:
8/19/2011	ONE TIME		N/A SB 601-590 NOT C/W	TIME: 9668.1	TIME:
				LD/CY: 5277	LD/CY:
<b>AD 2011-09-09</b>		ACCOMPLISH 30-11-00-101 ON WING ANTI-ICING	CANADAIR	DATE: 1/08/2014	DATE:
8/19/2011	ONE TIME		N/A SB 601-590 NOT C/W	TIME: 9668.1	TIME:
				LD/CY: 5277	LD/CY:
<b>AD 2011-21-08</b>		DO A VISUAL INSPECTION OF THE SEAT BACKREST LINKS P/N 90-000200-104-1 OR 90-000200-104-2	SICMA AERO	DATE: 4/03/2012	DATE:
11/23/2011	ONE TIME		N/A BY SEAT MANUFACTURE	TIME: 9388.2	TIME:
				LD/CY: 5092	LD/CY:

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 2012-17-01</b>		TIRE TREAD SEPARATIONS & TREAD AREA BULGES ON MLG TIRES , APPLIES TO BRAZILIAN TIRE SIZE H29X9.0-15 299K63-1	GOODYEAR AVIATION	DATE:	DATE:
9/13/2012	ONE TIME		N/A BY AIRCRAFT MODEL	TIME:	TIME:
				LD/CY:	LD/CY:
<b>AD 2012-21-11</b>		INSPECTION AND CORRECTIVE ACTION OF THE OXYGEN CPA WIRING HARNESS WITH OXY REGULATOR P/N 806370-2	CANADAIR	DATE: 3/10/2017	DATE:
12/04/2012	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	TIME: 10332.8	TIME:
				LD/CY: 5669	LD/CY:
<b>AD 2013-03-08</b>		PERFORM INSPECTION OF ENGINE SUPPORT BEAM UPPER AND LOWER WEBS FOR CRACKS	CANADAIR	DATE:	DATE:
3/19/2013	ONE TIME			TIME:	TIME:
				LD/CY:	LD/CY: 7800
<b>AD 2013-03-08</b>		REVISE MAINTENANCE INSPECTION PROGRAM TO INCLUDE TASK 53-10-00-198, 53-30-00-155 OR 605 TR 5-2-9	CANADAIR	DATE: 3/12/2013	DATE:
3/19/2013	ONE TIME		C/W REVISED MAINT DOCS	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 2013-05-06</b>		MODIFY THE LEFT-HAND ENGINE UPPER CORE COWL	CANADAIR	DATE: 4/22/2016	DATE:
4/24/2013	ONE TIME		C/W SB 601-0609 OR SB 604-71-005	TIME: 9590.3	TIME:
				LD/CY:	LD/CY:
<b>AD 2013-22-05</b>		INSPECT PITOT STATIC DRAIN BOTTLES FOR DFFECTIVE BOTTLES & REPLACE	CANADAIR	DATE: 12/18/2015	DATE:
12/05/2013	ONE TIME		N/A BY PART NUMBER INSTALLED	TIME: 10114.5	TIME:
				LD/CY: 0	LD/CY:
<b>AD 2014-03-17</b>		DO A DETAILED VISUAL INSPECTION FOR INCORRECT ORIENTATION & ANY FRACTURING SUPERSEDED BY AD 2015-02-23	CANADAIR	DATE: 3/19/2015	DATE:
3/06/2014	ONE TIME		COMPLIED WITH SB A601-0627	TIME: 9724.0	TIME:
				LD/CY: 5307	LD/CY:
<b>AD 2014-17-51</b>		DO A DETAILED VISUAL INSPECTION FOR INCORRECT ORIENTATION & ANY FRACTURING SUPERSEDED BY AD 2016-08-15	CANADAIR	DATE: 12/18/2015	DATE:
3/06/2014	ONE TIME		C/W FASTENER INSPECTION	TIME: 10114.5	TIME:
				LD/CY: 5552	LD/CY:
<b>AD 2017-19-06</b>		REVISE INSPECTION PROGRAM TO INCORP LIFE LIMITS FOR SIDE FITTING SHAFT & FITTING PIN OF MLG	CANADAIR	DATE: 10/19/2017	DATE:
10/27/2017	ONE TIME		COMPLIED WITH	TIME: 10392.7	TIME:
				LD/CY: 5706	LD/CY:
<b>AD 2017-22-06</b>		INSPECT FOR FUEL LEAKS IN THE ENGINE & APU ELECTRICAL FUEL PUMP CARTRIDGE SUPERSEDED BY AD 2021-26-23	CANADAIR	DATE: 11/14/2017	DATE:
10/30/2017	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	TIME: 10392.7	TIME:
				LD/CY: 5706	LD/CY:
<b>AD 2018-09-17</b>		DO A DETAIL OR EDDY CURRENT INSPECTION OF BOTH PILOT-SIDE RUDDER PEDAL TUBES FOR CRACKING	CANADAIR	DATE:	DATE:
6/25/2018	ONE TIME			TIME:	TIME:
				LD/CY:	LD/CY: 9000
<b>AD 2018-17-02</b>		MODIFY THE MAINT MANUAL TO INCORPORATE SERIALIZING THE HOR STAB TRIM ACTUATOR HSTA UPPER LOWER ATTACH PINS & TRUNNIONS	CANADAIR	DATE: 11/09/2018	DATE:
9/19/2018	ONE TIME		COMPLIED WITH	TIME:	TIME:
				LD/CY:	LD/CY:
<b>AD 2018-17-02</b>		MODIFY THE MAINT MANUAL TO INCORPORATE SERIALIZING THE HOR STAB TRIM ACTUATOR HSTA UPPER LOWER ATTACH PINS & TRUNNIONS	CANADAIR	DATE:	DATE:
9/19/2018	ONE TIME			TIME:	TIME:
				LD/CY:	LD/CY: 50000
<b>AD 2018-17-02 (i)</b>		MODIFY THE MAINT MANUAL TO INCORPORATE SERIALIZING THE HOR STAB TRIM ACTUATOR HSTA UPPER LOWER ATTACH PINS & TRUNNIONS	CANADAIR	DATE: 9/08/2022	DATE:
9/19/2018	ONE TIME		COMPLIED WITH	TIME: 11649.3	TIME:
				LD/CY: 6559	LD/CY:

## AIRFRAME AIRWORTHINESS DIRECTIVE CHALLENGER 5017

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 2018-21-14</b>		REPLACEMENT OF OXY MASK INFLATABLE HARNESS ASSEMBLY P/N MXH20-1 OR MXH21-1	ZODIAC	DATE: 3/18/2022 TIME: 11476.1 LD/CY: 6451	DATE: TIME: LD/CY:
3/27/2019	ONE TIME		N/A BY PART NUMBER INSTALLED		
<b>AD 2019-08-08</b>		INSPECT SYSTEM ACCUMULATORS 1,2,3 & BRAKE ACCUMULATORS #2 & #3	CANADAIR	DATE: 5/01/2020 TIME: LD/CY:	DATE: TIME: LD/CY:
8/05/2010	ONE TIME		N/A BY PART NUMBER INSTALLED		
<b>AD 2019-15-01</b>		PERFORM AN INSPECTION TO VERIFY THE MLG SIDE STAY ACTUATOR P/N 19011-103 OR -105 WITH SPLIT BEARING P/N 104467672	CANADAIR	DATE: 4/01/2020 TIME: LD/CY:	DATE: TIME: LD/CY:
9/19/2019	ONE TIME		N/A BY SERIAL NUMBER		
<b>AD 2019-15-01</b>		PERFORM AN INSPECTION TO VERIFY THE MLG SIDE STAY ACTUATOR P/N 19011-103 OR -105 WITH SPLIT BEARING P/N 104467672	CANADAIR	DATE: 4/01/2020 TIME: LD/CY:	DATE: TIME: LD/CY:
9/19/2019	ONE TIME		N/A BY SERIAL NUMBER		
<b>AD 2019-20-03</b>		MODIFY UNIVERSAL SERIAL BUS (USB) RECEPTACLES LOCATED IN THE FLIGHT DECK SUPERCEDED BY AD 2022-15-08	CANADAIR	DATE: 11/20/2019 TIME: 10773.0 LD/CY: 5973	DATE: TIME: LD/CY:
11/19/2019	ONE TIME		NOT APPLICABLE		
<b>AD 2020-18-51</b>		REVISION OF AFM AIRCRAFT FLIGHT MANUAL PROHIBITING IFR OR NIGHT VFR FLIGHT IF WITH ATTITUDE INDICATOR P/N 306171	BENDIX/KING	DATE: 9/23/2020 TIME: 10924.8 LD/CY: 6074	DATE: TIME: LD/CY:
8/28/2020	ONE TIME				
<b>AD 2020-19-13</b>		CHECK EACH PORTABLE OXYGEN BOTTLE INSTALLATION TO DETERMINE THE P/N	CANADAIR	DATE: 10/04/2020 TIME: 10931.9 LD/CY: 6085	DATE: TIME: LD/CY:
11/03/2020	ONE TIME		N/A BY PART NUMBER INSTALLED		
<b>AD 2021-25-13</b>		REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM	CANADAIR	DATE: 2/10/2022 TIME: 11437.0 LD/CY: 6423	DATE: TIME: LD/CY:
2/15/2022	ONE TIME		COMPLIED WITH		
<b>AD 2021-26-23</b>		INSPECT FOR FUEL LEAKS IN THE ENGINE & APU ELECTRICAL FUEL PUMP CARTRIDGE CANISTER ELEC CONNECTIONS & CONDUITS	CANADAIR	DATE: 2/10/2021 TIME: 11437.0 LD/CY: 6423	DATE: TIME: LD/CY:
2/25/2022	ONE TIME		N/A BY PART SERIAL NUMBER INSTALLED		
<b>AD 2022-10-10</b>		AFM REVISION TO ADDRESS WING STALL DURNING A LANDING FLARE CAUSED BY WING ANTI-ICING	CANADAIR	DATE: 8/29/2022 TIME: 11649.3 LD/CY: 6559	DATE: TIME: LD/CY:
7/05/2022	ONE TIME		COMPLIED WITH		
<b>AD 2022-12-13</b>		AFM REVISION TO ADDRESS AUTOPILOT DOES NOT ACCOUNT FOR ENGINE FAILURE WHILE CAPTURING AN ALTITUDE	CANADAIR	DATE: 9/26/2022 TIME: 11663.1 LD/CY: 6663	DATE: TIME: LD/CY:
10/19/2022	ONE TIME		COMPLIED WITH		
<b>AD 74-08-09</b>	R3	INSPECT LAVATORY WASTE RECEPTACLE: TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS DROPPED IN RECEPT	T-CATEGORY	DATE: 3/11/2022 TIME: 11473.6 LD/CY: 6447	DATE: TIME: LD/CY: 12473.6
3/28/2012	RECURRS		INSPECTED LAV RECEPTICLE & PLACARD		
<b>AD 81-13-51</b>		TO DETECT DRAGGING WHEEL BRAKES WHEEL BRAKE P/N 600-85083-55	CANADAIR	DATE: 1/13/2013 TIME: 9554.0 LD/CY:	DATE: TIME: LD/CY:
6/19/1981	ONE TIME		N/A		
<b>AD 82-01-01</b>		TO PREVENT ASYMMETRIC SPOILER DEPLOYMENT	CANADAIR	DATE: 1/13/2013 TIME: 9554.0 LD/CY:	DATE: TIME: LD/CY:
1/04/1982	ONE TIME		N/A BY MODEL		

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER LOCATION	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
EFFECTIVE DATE	RECURRS		METHOD		
AD 82-04-05		TO PREVENT THE FAILURE OF THE AILERON POWER CONTROL UNIT	CANADAIR	DATE: 1/13/2013 TIME: 9554.0	DATE: TIME:
3/04/1982	RECURRS	P/N 2771931-101	N/A BY MODEL	LD/CY:	LD/CY:
AD 82-06-04		PREVENT JAMMING OF THE MAIN ENTRY DOOR UNLATCHING SYSTEM	CANADAIR	DATE: 1/13/2013 TIME: 9554.0	DATE: TIME:
3/22/1982	ONE TIME		N/A BY MODEL	LD/CY:	LD/CY:
AD 82-06-05		TO ENSURE CORRECT FUNCTIONING OF THE LANDING GEAR MANUAL RELEASE CONTROL SYSTEM	CANADAIR	DATE: 1/13/2013 TIME: 9554.0	DATE: TIME:
3/22/1982	ONE TIME		N/A BY MODEL	LD/CY:	LD/CY:
AD 82-06-06		TO PREVENT DAMAGE TO THE FLAP DRIVE SHAFTS	CANADAIR	DATE: 1/13/2013 TIME: 9554.0	DATE: TIME:
3/22/1982	RECURRS		N/A BY MODEL	LD/CY:	LD/CY:
AD 82-09-51		LOSS OF NORMAL BRAKING	CANADAIR	DATE: 1/13/2013 TIME: 9554.0	DATE: TIME:
9/09/1982	ONE TIME		N/A BY MODEL	LD/CY:	LD/CY:
AD 82-21-04		PS-835 EMERGENCY POWER SUPPLY INSTALLATIONS: TO PREVENT A FALSE INDICATION THAT EMERG POWER IS AVAILABLE	J.E.T. ELECTRONICS	DATE: 1/01/2012 TIME:	DATE: TIME:
10/21/1982	ONE TIME		N/A EQUIPMENT NOT INSTALLED	LD/CY:	LD/CY:
AD 84-02-08		TO PREVENT POSSIBLE USE OF IMPROPERLY CHARGED OXYGEN CYLINDERS, BLEED DOWN THE CYLINDERS & RECHARGE	SCOTT AVIATION	DATE: 1/01/2012 TIME:	DATE: TIME:
2/09/1984	ONE TIME		N/A EQUIPMENT NOT INSTALLED	LD/CY:	LD/CY:
AD 84-18-07		INSPECT FIRE EXTINGUISHER DISCHARGE CARTRIDGES	WALTER KIDDE	DATE: 7/26/1988 TIME:	DATE: TIME:
9/21/1984	ONE TIME		INSPECTION OF FIRE CARTRIDGES	LD/CY:	LD/CY:
AD 85-26-03		TO PREVENT THE BLOCKAGE OF OXYGEN FLOW DUE TO THE INCOMPLETELY DRILLED OXYGEN CONNECTORS	SCOTT AVIATION	DATE: 1/01/2012 TIME:	DATE: TIME:
12/30/1985	ONE TIME		N/A CABIN MASKS P/N 289-601-245	LD/CY:	LD/CY:
AD 86-10-02 a	R1	TO ENSURE THAT THE FLUTTER DOES NOT OCCUR IN THE EVENT OF FAILURE OF ANY TWO HYDRAULIC SYSTEMS	CANADAIR	DATE: 4/03/2002 TIME: 4742.4	DATE: TIME:
2/09/1990	ONE TIME		N/A BY PART NUMBER INSTALLED	LD/CY: 2582	LD/CY:
AD 87-06-09		REPLACEMENT OF MECHANICAL CIRCUIT BREAKERS INSTALLED AFTER 07/23/84	MECHANICAL	DATE: 3/12/2013 TIME: 9564.6	DATE: TIME:
4/17/1987	ONE TIME		N/A BY DATE CODE	LD/CY: 5199	LD/CY:
AD 87-16-07		TO ELIMINATE ERRONEOUS DISPLAY OF THE ANGLE OR ATTACK FAST/SLOW PRESENTATION EFIS SYSTEM ONLY	SPERRY	DATE: 8/19/1988 TIME: 0.0	DATE: TIME:
8/20/1987	ONE TIME		N/A	LD/CY: 0	LD/CY:
AD 87-17-06		AM-SAFE INCORPORATED OCCUPANT RESTRAINT SYSTEM ASSEMBLIES	AM-SAFE	DATE: 8/19/1988 TIME: 0.0	DATE: TIME:
9/22/1987	ONE TIME		N/A	LD/CY: 0	LD/CY:
AD 87-20-05		REPLACEMENT OF DEFECTIVE LAP SEAT BELT ASSEMBLIES C22F PART NUMBER 1107177 ALL DASH NUMBERS	PACIFIC SCIENTIFIC	DATE: 8/19/1988 TIME: 0.0	DATE: TIME:
10/26/1987	ONE TIME		N/A	LD/CY: 0	LD/CY:

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 88-19-10		INSTALL AFM REV & COCKPIT PLACARD ABOUT FLIGHT DIRECTOR & AUTOPILOT COUPLED APPROACHES WITHOUT RADIO ALTIMETER	CANADAIR	DATE: 3/12/2013 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
10/05/1988	ONE TIME		C/W BY FM REVISION		
AD 89-02-05		TO ELIMINATE CYLINDERS WHICH MAY LEAK DUE TO CERTAIN MATERIAL USED IN THEIR FABRICATION; CYLINDER P/N 630104-205	BF GOODRICH	DATE: 1/01/2012 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
2/13/1989	ONE TIME		N/A BY RAFT MANUFACTURE		
AD 89-02-10	R1	SPERRY FMZ-800 FLIGHT MANAGEMENT SYSTEM (FMS) NAVIGATION COMPUTERS P/N 7004402 -801,-811 OR -832	HONEYWELL, INC.	DATE: 6/28/2000 TIME: 3872.4 LD/CY: 2104	DATE: TIME: LD/CY:
2/06/1989	ONE TIME		C/W BY INSTALL NZ 2000		
AD 89-06-01		TO PREVENT THE IMPROPER FUNCTIONING OF THE CARBON DIOXIDE INFLATORS ON TSO-C13 LIFE PRESERVERS & TSO-C72 FLOTATION DEVC	SWITLIK	DATE: 3/12/2013 TIME: 9564.6 LD/CY: 5197	DATE: TIME: LD/CY:
4/03/1989	ONE TIME		N/A BY MANUFACTURE		
AD 89-09-02		TO PREVENT THE POSSIBILITY OF THE SAFETY BELTS FROM BECOMING DIFFICULT TO RELEASE OR JAMMED WHEN ACTUATED THRU 90 DEGREES	DAVIS	DATE: 3/12/2013 TIME: 9564.6 LD/CY: 5197	DATE: TIME: LD/CY:
5/24/1989	ONE TIME		N/A BY MANUFACTURE		
AD 89-20-06		TO PREVENT FMS NAVIGATION ERRORS CAUSED BY AN ERRONEOUS OMEGA/VLF SENSOR. FMZ-800 FLIGHT MANAGEMENT SYSTEMS	HONEYWELL, INC.	DATE: 12/08/1989 TIME: 453.0 LD/CY: 291	DATE: TIME: LD/CY:
10/10/1989	ONE TIME		AIRCRAFT FLIGHT MANUAL REVISION		
AD 91-10-05		TO PREVENT MALFUNCTIONING OF THE LANYARD RELEASE PIN THAT COULD PREVENT THE FLOW OF PASSENGER OXYGEN.	O2 CORPORATION	DATE: 8/01/1991 TIME: LD/CY:	DATE: TIME: LD/CY:
6/03/1991	ONE TIME		C/W		
AD 91-15-15		PREVENT FAILURE OF A CREWMEMBER TO REMOVE THE POUCH FROM THE BRACKET IN CASE OF A FIRE; MODEL 4566M37B-042N	E.I. DUPONT DE	DATE: 3/12/2013 TIME: 9564.6 LD/CY: 5197	DATE: TIME: LD/CY:
8/15/1991	ONE TIME		N/A BY MANUFACTURE		
AD 91-19-01 b		TO PREVENT LOSS OF EMERGENCY POWER TO THE ESSENTIAL BUS WHEN THE AIR DRIVEN GENERATOR IS DEPLOYED	CANADAIR	DATE: 11/19/1991 TIME: 1135.0 LD/CY: 677	DATE: TIME: LD/CY:
9/24/1991	ONE TIME		C/W BY MOD OF WIRE HARNESS		
AD 92-13-09 c		TO PREVENT SEVERE DAMAGE TO AN AIRPLANE IN THE EVENT OF AN ENGINE FIRE	CANADAIR	DATE: 12/06/1989 TIME: 453.0 LD/CY: 291	DATE: TIME: LD/CY:
7/23/1992	ONE TIME		C/W BY MOD OF ENG FIRE SYS		
AD 92-20-04		PERFORM VISUAL INSPECTION OF UNSHROUDED PORTION OF SENSING LINE IN AFT EQUIP BAY TO DETECT DAMAGE OR DEFORMATION	CANADAIR	DATE: 1/01/2012 TIME: LD/CY:	DATE: TIME: LD/CY:
11/17/1992	ONE TIME		N/A SB 601-0262 NOT INSTALLED		
AD 92-20-44		TO PREVENT THE PRESENCE OF FUEL VAPORS IN THE AFT EQUIPMENT BAY	CANADAIR	DATE: 2/05/1992 TIME: LD/CY:	DATE: TIME: LD/CY:
11/17/1992	ONE TIME	SUPERSEDES AD 91-17-02	N/A PER ASB A601-0381		
AD 93-04-02		PREVENT A MID AIR COLLISION OR NEAR MISS SITUATION CAUSED BY FAILURE OF MODE S TRANSPONDERS P/N CPN 622-9210-002	ROCKWELL	DATE: 1/01/2012 TIME: LD/CY:	DATE: TIME: LD/CY:
3/26/1993	ONE TIME		N/A TRANSPONDER P/N 622-9210-308		
AD 93-22-04		SUPERSEDED BY AD 95-18-07	CANADAIR	DATE: 3/12/2013 TIME: 9564.6 LD/CY: 5199	DATE: TIME: LD/CY:
	ONE TIME		FOUND P/C/W		

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 93-23-01</b>		PREVENT EXPLOSIONS OF GALLEY WATER HEATERS & COFFEE MAKERS	NORDSKOG	DATE: 3/12/2013	DATE:
12/07/1993	ONE TIME		N/A EQUIPMENT NOT INSTALLED	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 94-01-04</b>		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL; P/N 4066010-901,-902,-903	HONEYWELL	DATE: 3/12/2013	DATE:
2/04/1994	ONE TIME		N/A BY P/N INSTALLED	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 94-01-05</b>		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL	ALLIED SIGNAL	DATE: 3/12/2013	DATE:
2/04/1994	ONE TIME		N/A BY P/N INSTALLED	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 94-01-06</b>		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL	ROCKWELL	DATE: 3/12/2013	DATE:
2/04/1994	ONE TIME		N/A BY P/N INSTALLED	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 94-08-15</b>		TO PREVENT ASYMMETRIC DEPLOYMENT OR RETRACTION (BLOW BACK) OF THE FLAPS	CANADAIR	DATE: 3/12/2013	DATE:
5/20/1994	ONE TIME		FOUND P/C/W 5/10/94	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 94-14-03</b>		PREVENT EXPLOSIONS OF GALLEY WATER HEATERS & COFFEE MAKERS; NUPRO PRESS RELIEF VALVE P/N SS-2C4-65	NORDSKOG	DATE: 3/12/2013	DATE:
8/01/1994	ONE TIME		N/A BY P/N INSTALLED	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 94-14-08(a)</b>		PERFORM VISUAL INSPECTION OF THE WIRING HARNESS OF THE ADG TO DETECT CHAFING	CANADAIR	DATE: 3/12/2013	DATE:
8/10/1994	ONE TIME		P/C/W A601-0370 11/19/1991	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 94-14-08(b)</b>		PERFORM MODIFICATION OF THE WIRING HARNESS OF THE ADG	CANADAIR	DATE: 1/13/2013	DATE:
8/10/1994	ONE TIME		P/C/W SB601-0370 11/19/1991	TIME:	TIME:
				LD/CY:	LD/CY:
<b>AD 94-21-06</b>		PREVENT THE INABILITY OF PASSENGERS OR CREW TO EGRESS FROM THEIR SEATS DURING EMERGENCY SITUATION	PACIFIC SCIENTIFIC	DATE: 3/12/2013	DATE:
11/25/1994	ONE TIME		N/A BY MANUFACTURE	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 95-01-01</b>		PREVENT FAILURE OF THE TRANSPONDER TO RESPOND PROPERLY TO MODE S INTERROGATION MODEL TRT 250 TRANSPONDERS	TERRA CORPORATION	DATE: 3/12/2013	DATE:
2/06/1995	ONE TIME		N/A BY MODEL NUMBER	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 95-03-06 a</b>		TO PREVENT INADVERTENT SHUTDOWN OF AN ENGINE WHILE THE AIRPLANE IS TAXIING OR IN FLIGHT	CANADAIR	DATE: 3/12/2013	DATE:
3/31/1995	ONE TIME		FOUND P/C/W ON 12/18/93	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 95-03-06 c</b>		TO PREVENT INADVERTENT SHUTDOWN OF AN ENGINE WHILE THE AIRPLANE IS TAXIING OR IN FLIGHT	CANADAIR	DATE: 3/12/2013	DATE:
3/31/1995	ONE TIME		FOUND P/C/W ON 3/17/95	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 95-03-06 e</b>		TO PREVENT INADVERTENT SHUTDOWN OF AN ENGINE WHILE THE AIRPLANE IS TAXIING OR IN FLIGHT	CANADAIR	DATE: 3/12/2013	DATE:
3/31/1995	ONE TIME		FOUND P/C/W ON 3/17/95	TIME: 9564.6	TIME:
				LD/CY: 5199	LD/CY:
<b>AD 95-10-06 (2)</b>		TO PREVENT FAILURE OF THE SHAFT PIN, WHICH COULD LEAD TO INABILITY OF THE PILOT TO MANUALLY DEPLOY ADG	CANADAIR	DATE: 1/12/2012	DATE:
6/12/1995	ONE TIME		N/A P/C/W SB 601-0430 ON 8/12/94	TIME:	TIME:
				LD/CY:	LD/CY:

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 95-10-06 a		TO PREVENT FAILURE OF THE SHAFT PIN, WHICH COULD LEAD TO INABILITY OF THE PILOT TO MANUALLY DEPLOY ADG	CANADAIR	DATE: 1/01/2012	DATE:
6/12/1995	ONE TIME		N/A P/C/W SB 601-0430 ON 8/12/94	TIME:	TIME:
				LD/CY:	LD/CY:
AD 95-10-06 b			TO PREVENT FAILURE OF THE SHAFT PIN, WHICH COULD LEAD TO INABILITY OF THE PILOT TO MANUALLY DEPLOY ADG	CANADAIR	DATE: 1/01/2012
6/12/1995	ONE TIME	N/A P/C/W SB 601-0430 ON 8/12/94		TIME:	TIME:
				LD/CY:	LD/CY:
AD 95-17-14			TO PREVENT UNCOMMANDED MOVEMENT OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA)	CANADAIR	DATE: 9/08/2022
9/12/1995	RECURRS	SI A600-0645, SI A601-0443		TIME: 11649.3	TIME: 11749.3
				LD/CY: 6559	LD/CY:
AD 95-17-14			TO PREVENT UNCOMMANDED MOVEMENT OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA)	CANADAIR	DATE: 1/24/2009
9/12/1995	ONE TIME	C/W SI A601-0443		TIME: 7941.1	TIME:
				LD/CY: 4306	LD/CY:
AD 95-18-07 a			TO PREVENT LOSS OF RUDDER CONTROL	CANADAIR	DATE: 1/12/2012
10/30/1995	ONE TIME	N/A P/C/W SB A601-0421 ON 9/15/93		TIME:	TIME:
				LD/CY:	LD/CY:
AD 95-18-07 b			TO PREVENT LOSS OF RUDDER CONTROL	CANADAIR	DATE: 9/15/1993
10/30/1995	ONE TIME	PREVIOUSLY COMPLIED WITH		TIME:	TIME:
				LD/CY:	LD/CY:
AD 95-22-01			TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK & POSSIBLE ELECTROMAGNETIC INTERFERENCE SUPERSEDES AD 90-14-06	AEROSPACE LIGHTING	DATE: 3/05/1996
12/04/1995	ONE TIME	INSPECTED I/A/W SB IB 90-001		TIME: 2332.0	TIME:
				LD/CY: 1279	LD/CY:
AD 96-19-15			TO PREVENT IMPROPER OPERATION OF THE NOSE LANDING GEAR DOOR & CONSEQUENT INABILITY TO EXTEND THE NLG	CANADAIR	DATE: 1/01/2012
9/10/1996	ONE TIME	N/A BY AIRCRAFT SERIAL NUMBER		TIME:	TIME:
				LD/CY:	LD/CY:
AD 97-11-10			TO PREVENT RESTRICTED OXYGEN FLOW MASKS P/N 174290-14, 174290-24 174290-34,174290-44,174290-54	PURITAN BENNETT	DATE: 8/18/1997
6/23/1997	ONE TIME	REPLACED MASKS		TIME:	TIME:
				LD/CY:	LD/CY:
AD 97-14-11			TO DETECT & CORRECT FATIGUE CRACKING IN THE UNDERFLOOR PRESSURE BULKHEAD OF THE FUSELAGE	CANADAIR	DATE:
7/22/1997	ONE TIME	N/A BY AIRCRAFT MODEL		TIME:	TIME:
				LD/CY:	LD/CY:
AD 97-18-10			PREVENT THE DIRECT CURRENT (DC) POWER DISTRIBUTION SYSTEM FROM SHORT CIRCUITING	CANADAIR	DATE:
10/14/1997	ONE TIME	N/A BY AIRCRAFT MODEL		TIME:	TIME:
				LD/CY:	LD/CY:
AD 97-19-11 (G)			TO PREVENT DAMAGE TO THE AILERON HINGE FITTINGS DUE TO FAILURE OF THE SHEAR PINS, SUPERSEDES AD 95-26-07	CANADAIR	DATE:
10/21/1997	ONE TIME	N/A BY AIRCRAFT MODEL		TIME:	TIME:
				LD/CY:	LD/CY:
AD 97-24-02	R1		TO DETECT & CORRECT FATIGUE CRACKING IN THE UNDERFLOOR PRESSURE BULKHEAD OF THE FUSELAGE	CANADAIR	DATE: 1/30/2003
12/03/1997	ONE TIME	C/W SB 601-0501		TIME: 5103.6	TIME:
				LD/CY: 2790	LD/CY:
AD 97-25-11			TO PREVENT THE CIRCUIT BREAKER ON THE BATTERY BUS FROM OPENING DURING FLIGHT	CANADAIR	DATE:
6/25/1998	ONE TIME	N/A BY AIRCRAFT SERIAL NUMBER		TIME:	TIME:
				LD/CY:	LD/CY:

**AIRFRAME AIRWORTHINESS DIRECTIVE  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 98-03-02</b>		TO PREVENT ELECTRICAL ARCING BETWEEN THE INTERNAL WIRING & CASING OF THE ANTI NOISE FILTER ON THE APU	CANADAIR	DATE:	DATE:
3/06/1998	ONE TIME		N/A BY AIRCRAFT MODEL		TIME:
				LD/CY:	LD/CY:
<b>AD 98-04-45</b>		TO PREVENT FAILURE OF LUGS AND/OR PINS SUPERSEDES AD 94-24-02	CANADAIR	DATE:	DATE:
4/03/1998	ONE TIME		N/A BY AIRCRAFT MODEL		TIME:
				LD/CY:	LD/CY:
<b>AD 98-25-10</b>		TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM; MODELS CS,CT,FM,FN,GK,GL,JD,JE,JT,JU,MD,ME,MM,MN,NB,PM,PN,RG,RH	AIRCRAFT BELTS	DATE: 2/11/1999	DATE:
1/14/2000	ONE TIME		N/A EQUIPMENT NOT INSTALLED		TIME:
				LD/CY:	LD/CY:
<b>AD 99-08-21</b>		TO PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE MASKS	PURITAN BENNETT	DATE: 9/15/1999	DATE:
6/02/1999	ONE TIME		N/A BY MASKS PART NUMBER		TIME:
				LD/CY:	LD/CY:
<b>AD 99-09-52 (C)</b>		IF ANY DAMAGE REPAIRED, REPLACE CABLE	CANADAIR	DATE:	DATE:
RH	ONE TIME		N/A BY AIRCRAFT MODEL		TIME:
4/20/1999				LD/CY:	LD/CY:
<b>AD 99-23-22</b>		TO PREVENT FALSE TRAFFICE ALERT COLLISION AVOIDANCE SYSTEM (TCAS II) AD CANCELLED AS OF 4/30/2000	TRANSPORT	DATE: 3/14/2000	DATE:
11/29/1999	ONE TIME		N/A BY TRANSPONDER PART NUMBER		TIME:
				LD/CY:	LD/CY:
<b>AD 99-26-16</b>		TO PREVENT DAMAGE TO HYDRAULIC & FUEL LINES RESULTING FROM FAILURE OF MLG	CANADAIR	DATE: 3/14/2000	DATE:
2/01/2000	ONE TIME		C/W SB 601-0482		TIME: 3701.0
				LD/CY: 2011	LD/CY:



**LH ENGINE AIRWORTHINESS DIRECTIVE  
GENERAL ELECTRIC 3050271**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 2000-03-03</b>		TO PREVENT CRITICAL LIFE LIMITED ROTATING ENGINE PART FAILURE	GENERAL ELECTRIC	DATE: 12/18/2001	DATE:
LH	ONE TIME		N/A BY ENGINE MODEL	TIME: 4654.3	TIME:
5/30/2001				LD/CY: 2528	LD/CY:
<b>AD 2001-12-06 (d)</b>		REPLACEMENT OF NO. 5 BEARING ROTATING AIR SEAL P/N 4019T60G01 WITH P/N 4019T60G03	GENERAL ELECTRIC	DATE: 2/03/2011	DATE:
LH	ONE TIME		SEALS REPLACED 2/3/2011	TIME: 8912.0	TIME:
7/20/2001				LD/CY: 2957	LD/CY:
<b>AD 2002-05-02</b>		TO PREVENT CRITICAL LIFE-LIMITED ROTATING ENGINE PART FAILURE	GENERAL ELECTRIC	DATE: 12/18/2001	DATE:
LH	ONE TIME		N/A BY ENGINE MODEL	TIME: 4654.6	TIME:
4/12/2002				LD/CY: 2528	LD/CY:
<b>AD 2002-23-02</b>		REVISE THE LIFE LIMITED ROTATING ENGINE PARTS	GENERAL ELECTRIC	DATE:	DATE:
LH	ONE TIME		N/A BY ENGINE MODEL	TIME:	TIME:
12/26/2002				LD/CY:	LD/CY:
<b>AD 2003-05-10(a2)</b>		TO PERFORM A VISUAL INSPECTION AND CLEANING OF SCAVENGE SCREENS IN THE B-SUMP OIL SCAVENGE SYS	GENERAL ELECTRIC	DATE: 3/24/2005	DATE:
LH	ONE TIME		N/A BY DATE OF OVERHAUL	TIME: 5954.7	TIME:
11/18/2003				LD/CY:	LD/CY:
<b>AD 2004-26-02</b>		TO PREVENT FAILURE OF HIGH PRESS COMP (HPC) FORWARD SPOOLS P/N 6078T56P03 & 6078T56P04	GENERAL ELECTRIC	DATE:	DATE:
LH	ONE TIME		N/A P/N 6078T56P05 INSTALLED	TIME:	TIME:
1/26/2005				LD/CY:	LD/CY:
<b>AD 2005-18-16</b>		THIS AD IS TO RE-IMPOSE LIFE LIMITS ON THE HTP ROTATION COMPONENTS DELETED GENERAL ELECTRICS MANUAL	GENERAL ELECTRIC	DATE:	DATE:
LH	ONE TIME		N/A BY ENGINE MODEL	TIME:	TIME:
10/13/2005				LD/CY:	LD/CY:
<b>AD 2006-04-12</b>		REPLACEMENT OF STAGE 5 LPT DISK P/N 6078T92P01 & STAGE 6 LPT DISK P/N 6089T89P01	GENERAL ELECTRIC	DATE:	DATE:
LH	ONE TIME		N/A BY P/N INSTALLED	TIME:	TIME:
3/30/2006				LD/CY:	LD/CY:
<b>AD 2009-07-12</b>		REMOVAL OF THE 4 STEP SEALS & INCORPORATE THE 8-STEP SEALS	GENERAL ELECTRIC	DATE:	DATE:
LH	ONE TIME			TIME:	TIME: 11954.7
5/07/2009				LD/CY:	LD/CY:
<b>AD 2009-26-09 (o)</b>		REMOVE FROM SVC TIER 1, 2 FAN DISKS REMOVED FROM SVC BY 09/30/2018	GENERAL ELECTRIC	DATE: 1/14/2008	DATE:
LH	ONE TIME		COMPLIED WITH	TIME:	TIME:
2/11/2010				LD/CY:	LD/CY:
<b>AD 2010-01-04</b>		INPECT FAN BLADE ABRADABLE RUB STRIP FOR WEAR SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
LH	ONE TIME		N/A	TIME:	TIME:
1/25/2010				LD/CY:	LD/CY:
<b>AD 2010-01-04</b>		EDDY CURRENT INSPECTION OF THE FAN BLADES FOR CRACKS P/N 6018T30P14 SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
LH	ONE TIME		N/A BY PN.	TIME:	TIME:
1/25/2010				LD/CY:	LD/CY:
<b>AD 2010-01-04</b>		EDDY CURRENT INSPECTION OF THE FAN BLADES FOR CRACKS P/N 6018T30P14 SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
LH	ONE TIME		N/A BY PN.	TIME:	TIME:
1/25/2010				LD/CY:	LD/CY:
<b>AD 2010-01-04</b>		REMOVE THE FAN BLADES P/N 6018T30P14 OR P/N 6036T78P02 SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
LH	ONE TIME		N/A BY PN.	TIME:	TIME:
1/25/2010				LD/CY:	LD/CY:

**LH ENGINE AIRWORTHINESS DIRECTIVE  
GENERAL ELECTRIC 3050271**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 2010-01-04</b>		INSPECTION OF FAN BLADE P/N 6018T30P14	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
LH		ABRADABLE RUB STRIP		TIME:	TIME:
1/25/2010	ONE TIME	SUPERSEDES AD 2009-24-11	N/A BY PN.	LD/CY:	LD/CY:
<b>AD 2010-01-04</b>		EDDY CURRENT INSPECTION OF THE FAN	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
LH		BLADES FOR CRACKS P/N 6018T30P14		TIME:	TIME:
1/25/2010	ONE TIME	SUPERSEDES AD 2009-24-11	N/A BY PN.	LD/CY:	LD/CY:
<b>AD 2010-01-04</b>		REMOVE THE FAN BLADES P/N 4923T56G08	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
LH				TIME:	TIME:
1/25/2010	ONE TIME	SUPERSEDES AD 2009-24-11	N/A BY PN.	LD/CY:	LD/CY:
<b>AD 88-06-07</b>		TO PREVENT AN ENGINE FLAMEOUT OR	GENERAL ELECTRIC	DATE: 1/13/2013	DATE:
LH		UNCOMMANDED POWER ROLL BACK		TIME:	TIME:
3/23/1988	ONE TIME		N/A BY OVERHAUL DATE	LD/CY:	LD/CY:
<b>AD 97-06-14</b>		TO PREVENT FAN DISK RUPTURE;REMOVE FROM	GENERAL ELECTRIC	DATE:	DATE:
LH		SERVICE FAN DISK P/N 6020T62G04,		TIME:	TIME:
3/11/1997	ONE TIME	6020T62G05, 6078T00G01, 5921T54G01		LD/CY:	LD/CY: 9000
<b>AD 97-06-15</b>		REPLACEMENT OF HPC STAGE 1 ROTOR DISK	GENERAL ELECTRIC	DATE:	DATE:
LH		PART NO. 6040T79G01		TIME:	TIME:
3/14/1997	ONE TIME		N/A BY P/N	LD/CY:	LD/CY:
<b>AD 99-11-08</b>		TO PREVENT UNCOMMANDED ENGINE	GENERAL ELECTRIC	DATE:	DATE:
LH		ACCELERATIONS		TIME:	TIME:
7/27/1999	ONE TIME	SUPERSEDED BY AD 99-23-26	N/A BY DATE OF OVERHAUL	LD/CY:	LD/CY:
<b>AD 99-22-10(a)</b>		REPLACEMENT OF FORWARD HPC SPOOLS	GENERAL ELECTRIC	DATE:	DATE:
LH		P/N 6078T56P01		TIME:	TIME:
12/27/1999	ONE TIME		N/A P/N 6078T56P05 INSTALLED	LD/CY:	LD/CY:
<b>AD 99-22-10(a4)</b>		REPLACEMENT OF STAGE 9 HCP DISKS	GENERAL ELECTRIC	DATE:	DATE:
LH		P/N 6087T01P03 OR 6087T01P04		TIME:	TIME:
12/27/1999	ONE TIME			LD/CY:	LD/CY: 20000
<b>AD 99-23-26(a)</b>		MFC: REPLACE BUNA-N PREFORMED PACKINGS	GENERAL ELECTRIC	DATE: 12/13/1999	DATE:
LH		O-RINGS OR INSTALL A MFC WITH FLANG		TIME:	TIME:
12/27/1999	ONE TIME	GROVE THAT CONFORMS WITH ASB 73-0026	P/C/W/ N/A BY OVERHAUL DATE	LD/CY:	LD/CY:

**RH ENGINE AIRWORTHINESS DIRECTIVE  
GENERAL ELECTRIC 350268**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 2000-03-03		TO PREVENT CRITICAL LIFE LIMITED ROTATING ENGINE PART FAILURE	GENERAL ELECTRIC	DATE: 12/18/2001	DATE:
RH			N/A BY ENGINE MODEL	TIME: 4654.3	TIME:
5/30/2001	ONE TIME			LD/CY: 2528	LD/CY:
AD 2001-12-06 (a)		CHECK OF MAGNETIC CHIP DETECTOR INDICATORS	GENERAL ELECTRIC	DATE:	DATE:
RH				TIME:	TIME: 100.0
7/20/2001	ONE TIME			LD/CY:	LD/CY:
AD 2001-12-06 (d)		REPLACEMENT OF NO. 5 BEARING ROTATING AIR SEAL P/N 4019T60G01 WITH P/N 4019T60G03	GENERAL ELECTRIC	DATE: 2/03/2011	DATE:
RH				TIME: 8812.6	TIME:
7/20/2001	ONE TIME			LD/CY: 2883	LD/CY:
AD 2002-05-02		TO PREVENT CRITICAL LIFE-LIMITED ROTATING ENGINE PART FAILURE	GENERAL ELECTRIC	DATE: 12/18/2001	DATE:
RH			N/A BY ENGINE MODEL	TIME: 4654.3	TIME:
4/12/2002	ONE TIME			LD/CY: 2528	LD/CY:
AD 2002-23-02		REVISE THE LIFE LIMITED ROTATING ENGINE PARTS	GENERAL ELECTRIC	DATE:	DATE:
RH			N/A BY ENGINE MODEL	TIME:	TIME:
12/26/2002	ONE TIME			LD/CY:	LD/CY:
AD 2003-05-10(a2)		TO PERFORM A VISUAL INSPECTION AND CLEANING OF SCAVENGE SCREENS IN THE B-SUMP OIL SCAVENGE SYS	GENERAL ELECTRIC	DATE: 5/13/2005	DATE:
RH			N/A BY OVERHAUL DATE	TIME: 5929.3	TIME:
11/18/2003	ONE TIME			LD/CY:	LD/CY:
AD 2004-26-02		TO PREVENT FAILURE OF HIGH PRESS COMP (HPC) FORWARD SPOOLS P/N 6078T56P03 & 6078T56P04	GENERAL ELECTRIC	DATE:	DATE:
RH			N/A P/N 6078T56P05 INSTALLED	TIME:	TIME:
1/26/2005	ONE TIME			LD/CY:	LD/CY:
AD 2005-18-16		THIS AD IS TO RE-IMPOSE LIFE LIMITS ON THE HTP ROTATION COMPONENTS DELETED GENERAL ELECTRICS MANUAL	GENERAL ELECTRIC	DATE:	DATE:
RH			N/A BY ENGINE MODEL	TIME:	TIME:
10/13/2005	ONE TIME			LD/CY:	LD/CY:
AD 2006-04-12		REPLACEMENT OF STAGE 5 LPT DISK P/N 6078T92P01 & STAGE 6 LPT DISK P/N 6089T89P01	GENERAL ELECTRIC	DATE:	DATE:
RH			N/A BY P/N INSTALLED	TIME:	TIME:
3/30/2006	ONE TIME			LD/CY:	LD/CY:
AD 2009-07-12		REMOVAL OF THE 4 STEP SEALS & INCORPORATE THE 8-STEP SEALS	GENERAL ELECTRIC	DATE:	DATE:
RH				TIME:	TIME: 11929.3
5/07/2009	ONE TIME			LD/CY:	LD/CY:
AD 2009-26-09 (o)		REMOVE FROM SVC TIER 1, 2 FAN DISKS REMOVED FROM SVC BY 09/30/2018	GENERAL ELECTRIC	DATE: 1/14/2008	DATE:
RH			COMPLIED WITH	TIME:	TIME:
2/11/2010	ONE TIME			LD/CY:	LD/CY:
AD 2010-01-04		INPECT FAN BLADE ABRADABLE RUB STRIP FOR WEAR SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
RH			N/A	TIME:	TIME:
1/25/2010	ONE TIME			LD/CY:	LD/CY:
AD 2010-01-04		EDDY CURRENT INSPECTION OF THE FAN BLADES FOR CRACKS P/N 6018T30P14 SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
RH			N/A BY PN.	TIME:	TIME:
1/25/2010	ONE TIME			LD/CY:	LD/CY:
AD 2010-01-04		REMOVE THE FAN BLADES P/N 6018T30P14 SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC	DATE: 2/14/2014	DATE:
RH			N/A BY PN.	TIME:	TIME:
1/25/2010	ONE TIME			LD/CY:	LD/CY:

**RH ENGINE AIRWORTHINESS DIRECTIVE  
GENERAL ELECTRIC 350268**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>AD 2010-01-04</b> RH 1/25/2010	ONE TIME	EDDY CURRENT INSPECTION OF THE FAN BLADES FOR CRACKS P/N 6018T30P14 SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC N/A BY PN.	DATE: 2/14/2014 TIME: LD/CY:	DATE: TIME: LD/CY:
<b>AD 2010-01-04</b> RH 1/25/2010	ONE TIME	REMOVE THE FAN BLADES P/N 4923T56G08 SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC N/A BY PN.	DATE: 2/14/2014 TIME: LD/CY:	DATE: TIME: LD/CY:
<b>AD 2010-01-04</b> RH 1/25/2010	ONE TIME	INSPECTION OF FAN BLADE P/N 6018T30P14 ABRADABLE RUB STRIP SUPERSEDES AD 2009-24-11	GENERAL ELECTRIC N/A BY PN.	DATE: 2/14/2014 TIME: LD/CY:	DATE: TIME: LD/CY:
<b>AD 88-06-07</b> RH 3/23/1988	ONE TIME	TO PREVENT AN ENGINE FLAMEOUT OR UNCOMMANDED POWER ROLL BACK	GENERAL ELECTRIC N/A BY OVERHAUL DATE	DATE: 1/13/2013 TIME: LD/CY:	DATE: TIME: LD/CY:
<b>AD 97-06-14</b> RH 3/11/1997	ONE TIME	TO PREVENT FAN DISK RUPTURE; REMOVE FROM SERVICE FAN DISK P/N 6020T62G04, 6020T62G05, 6078T00G01, 5921T54G01	GENERAL ELECTRIC	DATE: TIME: LD/CY:	DATE: TIME: LD/CY: 9000
<b>AD 97-06-15</b> RH 3/14/1997	ONE TIME	REPLACEMENT OF HPC STAGE 1 ROTOR DISK PART NO. 6040T79G01	GENERAL ELECTRIC N/A BY P/N	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
<b>AD 99-11-08</b> RH 7/27/1999	ONE TIME	TO PREVENT UNCOMMANDED ENGINE ACCELERATIONS SUPERSEDED BY AD 99-23-26	GENERAL ELECTRIC N/A BY DATE OF OVERHAUL	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
<b>AD 99-22-10(a)</b> RH 12/27/1999	ONE TIME	REPLACEMENT OF FORWARD HPC SPOOLS P/N 6078T56P01	GENERAL ELECTRIC N/A P/N 6078T56P05 INSTALLED	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
<b>AD 99-22-10(a4)</b> RH 12/27/1999	ONE TIME	REPLACEMENT OF STAGE 9 HCP DISKS P/N 6087T01P03 OR 6087T01P04	GENERAL ELECTRIC	DATE: TIME: LD/CY:	DATE: TIME: LD/CY: 20000
<b>AD 99-23-26(a)</b> RH 12/27/1999	ONE TIME	MFC: REPLACE BUNA-N PREFORMED PACKINGS O-RINGS OR INSTALL A MFC WITH FLANG GROVE THAT CONFORMS WITH ASB 73-0026	GENERAL ELECTRIC P/C/W N/A BY OVERHAUL DATE.	DATE: 12/13/1999 TIME: LD/CY:	DATE: TIME: LD/CY:

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

1/28/2023  
N404HG

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 23-3727		RAYTHEON SB- CONTROL COLUMN MICRO-PHONE JACK MODIFICATION	BOMBARDIER	Mandatory	DATE:
5/01/2005	ONE TIME	STC SA4900SW	N/A BY AIRCRAFT SERIAL NUMBER		DATE: TIME: LD/CY:
SB 601-0092	4	LANDING GEAR - MODIFICATION - STEER BY WIRE SYSTEM - IMPROVEMENTS	BOMBARDIER	Recommended	DATE: 7/26/1988
LH	ONE TIME		C/W AT BUILD		DATE: TIME: 0.0 LD/CY: 0
12/08/1988					DATE: TIME: LD/CY:
SB 601-0134	2	WINGS - MODIFICATION - INBOARD FLAP HINGE FORWARD FAIRINGS - UPPER EDGE STRENGTHENING	BOMBARDIER	Recommended	DATE: 7/26/1988
3/28/1988	ONE TIME		C/W AT BUILD		DATE: TIME: 0.0 LD/CY: 0
SB 601-0151	2	AIR CONDITIONING - ICE AND RAIN PROTECTION MODIFICATION - CABIN AIR AND ANTI-ICE DUCTS - CONNECTIONS	BOMBARDIER	Recommended	DATE: 6/09/1989
3/03/1989	ONE TIME		C/W AT BUILD		DATE: TIME: 0.0 LD/CY: 0
SB 601-0179	R1	FUSELAGE - MODIFICATION - PASSENGER DOOR FRAME - ADDITION OF DRAIN HOLES AND TUBES	BOMBARDIER	Recommended	DATE: 11/28/1988
10/14/1988	ONE TIME		C/W AT BUILD		DATE: TIME: 0.0 LD/CY: 0
SB 601-0191	R1	ELECTRICAL POWER - MODIFICATION - AFT DISTRIBUTION BOX (JB4) VENT SCREEN COVER	BOMBARDIER	Recommended	DATE: 3/11/1989
6/20/1988	ONE TIME		C/W AT BUILD		DATE: TIME: 0.0 LD/CY: 0
SB 601-0202		WINGS - MODIFICATION - AUXILIARY SPARS ASSEMBLIES AND ACCESS PANELS DEFLECTOR PLATES & DRAIN HOLES.	BOMBARDIER	Optional	DATE: 7/26/1988
8/31/1987	ONE TIME		KIT NO. 601K-0202		DATE: TIME: 0.0 LD/CY: 0
SB 601-0211		HYDRAULIC POWER - MODIFICATION NO. 3 HYDRAULIC SYSTEM - ECOLOGY DRAIN BOTTLES.	BOMBARDIER	Recommended	DATE: 11/28/1988
4/20/1988	ONE TIME		C/W		DATE: TIME: 0.0 LD/CY: 0
SB 601-0217	R3	FUEL - MODIFICATION - REFUEL/DEFUEL FUEL SPILLAGE PREVENTION.	BOMBARDIER	Recommended	DATE: 6/09/1989
3/17/1989	ONE TIME		C/W		DATE: TIME: 0.0 LD/CY: 0
SB 601-0224	R1	FLIGHT CONTROLS- MODIFICATION - GROUND SPOILER ACTUATORS - DELETION OF LIFE LIMITING LOCKS	BOMBARDIER	Optional	DATE: 5/25/2007
7/13/1990	ONE TIME		C/W		DATE: TIME: 7106.1 LD/CY: 3881
SB 601-0231	R1	NAVIGATION - MODIFICATION - LASER INERTIAL REFERENCE SYSTEM - ADDITION OF A THIRD UNIT	BOMBARDIER	Optional	DATE: 7/26/1988
11/22/1993	ONE TIME		C/W		DATE: TIME: 18.0 LD/CY: 10
SB 601-0232		ELECTRICAL/ELECTRONIC - MODIFICATION JUNCTION BOXES NO. 10 TO 13 IMPROVED GROMMET INSTALLATION	BOMBARDIER	Optional	DATE: 7/26/1988
11/20/1987	ONE TIME		C/W		DATE: TIME: 18.0 LD/CY: 10
SB 601-0236		DOORS - MODIFICATION - PASSENGER CREW/ ENTRANCE DOOR SEAL IMPROVEMENT.	BOMBARDIER	Optional	DATE: 7/26/1988
9/30/1987	ONE TIME		C/W		DATE: TIME: 18.0 LD/CY: 10
SB 601-0242	1	LANDING GEAR - MODIFICATION - STEER BY WIRE - RELIABILITY IMPROVEMENTS	BOMBARDIER	Recommended	DATE: 7/26/1988
LH	ONE TIME		C/W		DATE: TIME: 18.0 LD/CY: 10
7/06/1989					DATE: TIME: LD/CY:

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
<b>SB 601-0254</b>		AIRBORENE AUXILIARY POWER - MODIFICATION	BOMBARDIER	Optional	DATE: 7/26/1988	DATE:
		APU INSTALLATION - SPIRAL WRAP ADDITION.			TIME: 18.0	TIME:
12/11/1987	ONE TIME		C/W		LD/CY: 10	LD/CY:
<b>SB 601-0255</b>		ELECTRICAL PANELS & MULTIPURPOSE	BOMBARDIER	Recommended	DATE: 7/26/1988	DATE:
		PARTS - MODIFICATION - CENTER PEDESTAL			TIME: 18.0	TIME:
3/08/1988	ONE TIME	HARNES ROUTING.	C/W		LD/CY: 10	LD/CY:
<b>SB 601-0261</b>		FUEL - MODIFICATION - REFUEL/DEFUEL	BOMBARDIER	Optional	DATE: 7/26/1988	DATE:
		CONTROL PANEL - DECAL			TIME: 18.0	TIME:
1/29/1988	ONE TIME		C/W		LD/CY: 10	LD/CY:
<b>SB 601-0264</b>		ELECTRICAL/ELECTRONIC PANELS &	BOMBARDIER	Optional	DATE: 7/26/1988	DATE:
		MULTIPURPOSE COMPONENTS MODIFICATION			TIME: 18.0	TIME:
1/11/1988	ONE TIME	CENTER INSTRUMENT PANEL - CONNECTOR	C/W		LD/CY: 10	LD/CY:
<b>SB 601-0267</b>	R2	LANDING GEAR - MODIFICATION - NOSE	BOMBARDIER	Recommended	DATE: 7/26/1988	DATE:
		LANDING GEAR SHOCK STRUT			TIME: 18.0	TIME:
1/27/1992	ONE TIME		C/W		LD/CY: 10	LD/CY:
<b>SB 601-0269</b>		HYDRAULIC POWER - SPECIAL CHECK	BOMBARDIER	Recommended	DATE: 6/05/1989	DATE:
		MODIFICATION - PRESSURE MANIFOLD			TIME: 0.0	TIME:
12/07/1988	ONE TIME	RELIEF VALVE REPLACEMENT	C/W		LD/CY: 0	LD/CY:
<b>SB 601-0270</b>		DOORS - MODIFICATION - PASSENGER/CREW	BOMBARDIER	Optional	DATE: 8/08/1992	DATE:
		ENTRANCE DOOR - SUPPORT MECHANISM			TIME: 0.0	TIME:
1/23/1989	ONE TIME	IMPROVEMENT.	C/W		LD/CY: 0	LD/CY:
<b>SB 601-0274</b>		FUEL - MODIFICATION - REFUEL/DEFUEL	BOMBARDIER	Optional	DATE: 9/06/1988	DATE:
		CONTROL PANEL - COVER ASSEMBLY			TIME: 0.0	TIME:
7/14/1988	ONE TIME	REWORK.	C/W		LD/CY: 0	LD/CY:
<b>SB 601-0275</b>	1	NAVIGATION - MODIFICATION - ELECTRONIC	BOMBARDIER	Recommended	DATE: 7/26/1988	DATE:
		FLIGHT INSTRUMENT SYSTEM UNIT			TIME: 0.0	TIME:
7/05/1988	ONE TIME	REPLACEMENT & WIRING REWORK	C/W		LD/CY: 0	LD/CY:
<b>SB 601-0276</b>	R1	AUTO FLIGHT - MODIFICATION - FLIGHT	BOMBARDIER	Recommended	DATE: 10/03/1988	DATE:
		GUIDANCE COMPUTERS REPLACEMENT.			TIME: 0.0	TIME:
8/22/1988	ONE TIME		C/W		LD/CY: 0	LD/CY:
<b>SB 601-0277</b>		NAVIGATION - MODIFICATION - FLIGHT	BOMBARDIER	Recommended	DATE: 7/26/1988	DATE:
		MANAGEMENT - NAVIGATION COMPUTER			TIME: 0.0	TIME:
5/10/1988	ONE TIME		C/W		LD/CY: 0	LD/CY:
<b>SB 601-0278</b>		NAVIGATION - MODIFIATION - MULTIFUNCTION	BOMBARDIER	Recommended	DATE: 7/26/1988	DATE:
		DISPLAY SYMBOL GENERATOR - CHECKLIST			TIME: 0.0	TIME:
5/01/1988	ONE TIME	MODULE INSTALLATION	C/W		LD/CY: 0	LD/CY:
<b>SB 601-0279</b>		COMMUNICATIONS - MODIFICATION	BOMBARDIER	Recommended	DATE: 12/13/1989	DATE:
		COCKPIT VOICE RECORDER LOCKWIRE			TIME: 0.0	TIME:
10/20/1988	ONE TIME	SECURING HARDWARE	C/W		LD/CY: 0	LD/CY:
<b>SB 601-0280</b>	R2	PLACARDS & MARKINGS/LANDING GEAR	BOMBARDIER	Recommended	DATE: 6/09/1989	DATE:
		MODIFICATION-INCREASED MTOW - 44,600 LBS			TIME: 307.0	TIME:
9/24/1989	ONE TIME		C/W		LD/CY: 191	LD/CY:

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
<b>SB 601-0281</b>	R2	COMMUNICATIONS - MODIFICATION - AUDIO ELECTRIC UNIT (AEU) - COCKPIT VOICE RECORDER (CVR) AUDIO LEVELS	BOMBARDIER	Recommended	DATE: 9/18/1989 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
1/18/1991	ONE TIME		C/W			
<b>SB 601-0282</b>		AIR CONDITIONING - MODIFICATION - GROUND COOLING FAN - ADDITION OF SPACER	BOMBARDIER	Optional	DATE: 12/06/1989 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
2/21/1989	ONE TIME		C/W			
<b>SB 601-0285</b>	R2	LANDING GEAR- SPECIAL CHECK MODIFICATION NLG & MLG HARNESS ASSEMBLIES - REPLACEMENT REROUTING	BOMBARDIER	Recommended	DATE: 8/08/1992 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
12/15/1997	ONE TIME		C/W			
<b>SB 601-0288</b>	R2	PNEUMATIC - SPECIAL CHECK/MODIFICATION BLEED AIR DISTRIBUTION 10TH & 14TH STAGE DUCT ASSEMBLY BLEED HOLE LOCATION	BOMBARDIER	Recommended	DATE: 2/05/1992 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
8/30/1991	ONE TIME		C/W			
<b>SB 601-0290</b>	R2	AIRBORNE AUXILIARY POWER - MODIFICATION EXHAUST SHEILD - CRACK PREVENTION	BOMBARDIER	Recommended	DATE: 12/15/1993 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
5/15/1993	ONE TIME		C/W			
<b>SB 601-0294</b>		LIGHTS - MODIFICATION -INTEGRAL LIGHTING LAMP DIMMER POWER SUPPLY CIRCUIT BREAKER AND WIRING REPLACEMENT	BOMBARDIER	Optional	DATE: 12/09/1992 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
1/05/1990	ONE TIME		C/W			
<b>SB 601-0299</b>		LANDING GEAR - MODIFICATION MANUAL RELEASE SYSTEM CABLE SUPPORT BRACKET RELOCATION	BOMBARDIER	Recommended	DATE: 4/20/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
11/15/1989	ONE TIME		C/W			
<b>SB 601-0302</b>		ELECTRICAL POWER/ SPECIAL CHECK RECERTIFICATION BATTERY CONNECTOR WIRE CONNECTION	BOMBARDIER	Recommended	DATE: 11/30/1988 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
2/06/1989	ONE TIME		C/W			
<b>SB 601-0303</b>		LANDIN GEAR - SPECIAL CHECK/MODIFICATION MAIN LANDING GEAR SHOCK STRUT REBOUND RING.	BOMBARDIER	Recommended	DATE: 12/06/1989 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
LH 7/14/1989	ONE TIME		N/A			
<b>SB 601-0304</b>	R1	FLIGHT CONTROLS - SPECIAL CHECK/MOD ELEVATOR CONTROL LEVERS - STRESS CORROSION	BOMBARDIER	Recommended	DATE: 8/19/2016 TIME: 10201.1 LD/CY: 5605	DATE: TIME: 11401.1 LD/CY:
5/10/1991	RECURRS		C/W			
<b>SB 601-0305</b>		NAVIGATION-AUTO FLIGHT MODIFICATION - IRU MOUNTING TRAY PLATFORM IMPROVED RIGIDITY	BOMBARDIER	Recommended	DATE: 4/20/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
7/07/1989	ONE TIME		C/W			
<b>SB 601-0306</b>		NAVIGATION - MODIFICATION - LASER INERTIAL REFERENCE SYSTEM ELIMINATE NO AIR ANNUNCIATIONS DURING POWER UP	BOMBARDIER	Recommended	DATE: 4/20/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
9/22/1989	ONE TIME		C/W			
<b>SB 601-0307</b>		HYDRAULIC POWER - MODIFICATION MAIN SYSTEM - REPLACEMENT OF THE TUBE ASSEMBLY.	BOMBARDIER	Recommended	DATE: 7/23/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
1/09/1990	ONE TIME		C/W			
<b>SB 601-0308</b>		AUTOPILOT- MODIFICATION - FLIGHT GUDANCE COMPUTERS - REPLACEMENT.	BOMBARDIER	Recommended	DATE: 1/17/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
7/17/1989	ONE TIME		C/W			

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
<b>SB 601-0310</b>	R2	AIR CONDITIONING - MODIFICATION	BOMBARDIER	Recommended	DATE: 2/05/1992	DATE:
1/10/1992	ONE TIME	AIR CONDITIONING UNIT (ACU) INTRODUCTION OF WATER EXTRACTOR	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0312</b>		FLIGHT CONTROLS - SPECIAL CHECK	BOMBARDIER	Recommended	DATE: 2/09/1990	DATE:
11/24/1989	ONE TIME	REPLACEMENT - FLAP ACTUATORS - RETAINING RING	N/A		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0313</b>		AIRBORNE AUXILIARY POWER - MODIFICATION	BOMBARDIER	Optional	DATE: 11/28/1990	DATE:
9/14/1990	ONE TIME	APU GEARBOX - OIL CASE VENT FITTING AND DRAIN ADAPTOR	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0318</b>	R2	MODIFY NACA SCOOP VENT LINE	BOMBARDIER		DATE: 8/08/1992	DATE:
3/13/2002	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0320</b>	R1	FUEL - MODIFICAION - PRIMARY	BOMBARDIER	Recommended	DATE: 2/05/1992	DATE:
6/22/1992	ONE TIME	EJECTOR PUMP & FUEL FEED TUBE CONNCTOR ASSEMBLY	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0322</b>		PLACARDS & MARKINGS - MODIFICATION ADG	BOMBARDIER	Recommended	DATE: 1/18/1991	DATE:
9/21/1990	ONE TIME	RESTOW PUMP - ADDITION OF WARNING PLACARD.	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0328</b>		HYDRAULIC POWER/LANDING GEAR -	BOMBARDIER	Recommended	DATE: 7/19/1990	DATE:
5/29/1990	ONE TIME	MODIFICATION - RUN-AROUND/BYPASS VALVE SCREW REPLACEMENT	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0331</b>		LANDING GEAR - MODIFICATION - MAIN	BOMBARDIER	Optional	DATE: 6/06/1991	DATE:
10/12/1990	ONE TIME	LANDING GEAR REMOVAL OF WHEEL SPEED SENSOR SET SCREW.	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0335</b>	R1	DOORS/FUSELAGE - SPECAIL CHECK	BOMBARDIER	Recommended	DATE: 2/05/1992	DATE:
8/26/1991	ONE TIME	MODIFICATION - PASSENGER DOOR STAIR COUNTER BALANCE SYSTEM. REINFORCEMENT	C/W		TIME: 1171.0	TIME:
					LD/CY: 702	LD/CY:
<b>SB 601-0356</b>	R3	ELECTRICAL POWER/ FUSELAGE	BOMBARDIER	Recommended	DATE: 11/19/1981	DATE:
5/31/1995	ONE TIME	MODIFICATION MAIN BATTERY AND AFT EQUIPMENT BAY VENTING AND DRAINAGE	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0361</b>	R1	FUEL - MODIFICATION - AUXILIARY TANK	BOMBARDIER	Recommended	DATE: 2/05/1992	DATE:
11/25/1991	ONE TIME	FUEL LINES - ELIMINATION OF POSSIBLE CHAFING	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0364</b>		WINGS/FUEL SPECIAL CHECK/MODIFICATION	BOMBARDIER	Recommended	DATE: 8/08/1992	DATE:
11/18/1991	ONE TIME	WING TANK FUEL ACCESS PANELS - INTRODUCTION OF CONDUCTIVE GASKET	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0369</b>		MODIFICATION - WATER EXTRACTOR DRAIN	BOMBARDIER	Recommended	DATE: 2/05/1992	DATE:
1/10/1992	ONE TIME	HOSES - ADDITION OF CLAMPS AND INLINE RESTRICTORS.	C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0373</b>		SPECIAL CHECK / MODIFICATION - EMERGENCY	BOMBARDIER	Recommended	DATE: 12/15/1993	DATE:
LH	ONE TIME	EXTENSION - MAIN LANDING GEAR MANUAL			TIME: 0.0	TIME:
3/26/1993		RELEASE CABLE AND DUMP VALVE LEVER	C/W		LD/CY: 0	LD/CY:



**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 601-0375		MODIFICATION - AIR CONDITIONING UNIT (ACU) DUCTS - PREVENTION OF CONNECTOR SEPERATION.	BOMBARDIER	Recommended	DATE: 8/08/1992 TIME: 0.0 LD/CY: 0
3/20/1992	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0377	R1	MODIFICATION - PITOT - STATIC SYSTEM - INTRODUCTION OF PITOT - STATIC HEAD WITH HEATED BASE	BOMBARDIER	Recommended	DATE: 1/11/1993 TIME: 0.0 LD/CY: 0
1/15/1993	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0385		BRAZILIAN REGISTRATION REQUIREMENTS- SERVICING AND EMERGENCY PLACARDS/CABIN ALTITUDE PRESSURE INDICATING/OVERSPEED	BOMBARDIER	Optional	DATE: 1/06/1988 TIME: 0.0 LD/CY: 0
10/30/1998	ONE TIME		N/A		DATE: TIME: LD/CY:
SB 601-0386		MODIFICATION - TAIL CONE FUEL TANK - REPLACEMENT OF DUMP VALVE SUPPORT BRACKET AND/OR FLANGED FITTING	BOMBARDIER	Recommended	DATE: 2/08/2012 TIME: 9330.0 LD/CY: 5055
3/27/1992	ONE TIME		N/A		DATE: TIME: LD/CY:
SB 601-0392	R1	SPECIAL / CHECK MODIFICATION - RH ENGINE FUEL FEED LINE - CLEARANCE WITH FOUR-TEENTH (14TH) STAGE AIR SHUTOFF VALVE	BOMBARDIER	Recommended	DATE: 8/08/1992 TIME: 0.0 LD/CY: 0
1/15/1993	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0393	1	MODIFICATION - PITOT-STATIC DRAIN LINE - ADDITION OF CLAMPS AND CLAMPING PLATE	BOMBARDIER	Recommended	DATE: 4/23/1992 TIME: 0.0 LD/CY: 0
1/15/1993	ONE TIME		N/A		DATE: TIME: LD/CY:
SB 601-0395	R1	SPECIALCHECK / REWORK - PASSENGER / CREW ENTERANCE DOOR - LATCHING MECHANISM	BOMBARDIER	Recommended	DATE: 8/08/1992 TIME: 0.0 LD/CY: 0
6/25/1993	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0397		MODIFICATION - NAVIGATION COMPUTERS - INTRODUCTION OF N-Z 9102 / NZ-9112 SOFTWARE	BOMBARDIER	Recommended	DATE: 8/08/1992 TIME: 0.0 LD/CY: 0
6/22/1992	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0401		SPECIAL CHECK / REWORK AND MODIFICATION AVIONIC MOUNTING TRAYS - ADDITION OF SHIMS AND FASTNERS.	BOMBARDIER	Recommended	DATE: 11/30/1994 TIME: 0.0 LD/CY: 0
2/28/1994	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0408	R1	MODIFICATION - USE OF CF34-3A2 ( LEC II) ENGINES	BOMBARDIER	Optional	DATE: 3/17/1993 TIME: 0.0 LD/CY: 0
1/27/1994	ONE TIME		N/A		DATE: TIME: LD/CY:
SB 601-0410		SPECIAL CHECK / MODIFICATION - THROTTLE QUADRANT - INADVERTENT SHUT-OFF	BOMBARDIER	Recommended	DATE: 3/16/1995 TIME: 0.0 LD/CY: 0
11/01/1993	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0411	R1	SPECIAL CHECK / REWORK / MODIFICATION - AUTOPILOT SYSTEM - WIRE SPLICES, GROUND STUDS AND FLIGHT GUIDANCE COMPUTER	BOMBARDIER	Recommended	DATE: 11/30/1994 TIME: 0.0 LD/CY: 0
6/23/1994	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0412		MODIFICATION - WHEEL BIN BRUSHES - INTRODUCTION OF THREE-PIECE WHEEL-BIN BRUSH	BOMBARDIER	Optional	DATE: 12/16/1999 TIME: 0.0 LD/CY: 0
9/15/1994	ONE TIME		C/W		DATE: TIME: LD/CY:
SB 601-0414		MODIFICATION - PRESSURE TRANSDUCERS - INTRODUCTION OF SAFTEY LOCK-WIRE	BOMBARDIER	Recommended	DATE: 11/29/1994 TIME: 0.0 LD/CY: 0
3/25/1994	ONE TIME		C/W		DATE: TIME: LD/CY:

## AIRFRAME & APPLIANCE SB REPORT CHALLENGER 5017

1/28/2023  
N404HG

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
<b>SB 601-0418</b>		MODIFICATION N- APU STARTING AND IGNITION - REMOVAL OF APU AUXILIARY BATTERY - AMPS 500	BOMBARDIER C/W	Optional	DATE: 1/27/1998 TIME: 2869.0 LD/CY: 1575	DATE: TIME: LD/CY:
8/31/1995	ONE TIME					
<b>SB 601-0420</b>		REWORK - BENT UP TRAILING EDGE (BUTE) DOOR REPLACE ACTUATOR TAPER PINS	BOMBARDIER N/A BY AIRCRAFT SERIAL NUMBER	Recommended	DATE: 1/01/2012 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
9/15/1995	ONE TIME					
<b>SB 601-0422</b>		SPECIAL CHECK / REWORK - JUNCTION BOX NO. 5 (JB5) - TERMINAL BLOCK PIN SIZES	BOMBARDIER C/W	Recommended	DATE: 12/02/1994 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
6/23/1994	ONE TIME					
<b>SB 601-0424</b>		SPECIAL CHECK / MODIFICATION - AIR DRIVE GENERATOR (ADG), GENERATOR CONTROL UNIT (GCU) - REPLACEMENT	BOMBARDIER N/A	Recommended	DATE: 4/15/1994 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
5/15/1994	ONE TIME					
<b>SB 601-0425</b>		MODIFICATION - ADF SYSTEM - WIRING CHANGE TO THE ADF CONTROL UNIT	BOMBARDIER C/W	Recommended	DATE: 3/03/1995 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
2/15/1995	ONE TIME					
<b>SB 601-0426</b>	R1	SPECIAL CHECK / MODIFICATION - RUDDER QUADRANT ASSEMBLY - INTRODUCTION OF SUB-ASSEMBLY, PART NO. K600-92600-3 OR -7	BOMBARDIER N/A	Recommended	DATE: 11/29/1994 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
11/15/1994	ONE TIME					
<b>SB 601-0427</b>		MODIFICATION - CENTER - PEDESTAL PANEL ASSEMBLIES - IMPROVED AIR FLOW	BOMBARDIER C/W	Recommended	DATE: 12/16/1999 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
6/15/1994	ONE TIME					
<b>SB 601-0428</b>		SPECIAL CHECK / REWORK - SHIELDED WIRE WIRE INSTALLATION	BOMBARDIER C/W	Recommended	DATE: 7/07/2001 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
2/29/1996	ONE TIME					
<b>SB 601-0429</b>		MODIFICATION - FUEL CONTROL UNIT (FCU) INTRODUCTION OF PART NO. 6078T55P05	BOMBARDIER N/A	Recommended	DATE: 1/14/1994 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
1/14/1994	ONE TIME					
<b>SB 601-0430</b>		SPECIAL CHECK AND MODIFICATION - AIR-DRIVEN GENERATOR - UPLOCK ASSEMBLY REPLACEMENT	BOMBARDIER C/W	Recommended	DATE: 8/12/1994 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
4/25/1994	ONE TIME					
<b>SB 601-0431</b>		REWORK - STALL PROTECTION SYSTEM WIRING ADD SLEEVE TO TRANZORB IN JUNCTION BOX 13 (JB13)	BOMBARDIER C/W	Recommended	DATE: 1/27/1998 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
6/15/1994	ONE TIME					
<b>SB 601-0433</b>	R1	MODIFICATION - WING ANTI-ICE SYSTEM - COUPLING ASSEMBLY.	BOMBARDIER C/W	Recommended	DATE: 3/14/1995 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
11/30/1995	ONE TIME					
<b>SB 601-0435</b>		MODIFICATION - WING TANK FUEL ACCESS PANELS, PART NO. 601R10906-17 & CONDUCTIVE GASKET, PART NO. 600-10910-3.	BOMBARDIER C/W	Recommended	DATE: 2/23/1996 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
9/15/1994	ONE TIME					
<b>SB 601-0436</b>		MODIFICATION - RE-ACTIVATE THE MASTER CHIP DETECTOR SYSTEM.	BOMBARDIER N/A	Recommended	DATE: 5/15/1995 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
5/15/1995	ONE TIME					

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
<b>SB 601-0438</b>		MODIFICATION - FLAAP YSTEM - ASYMMETRY / OVERSPEED DETECTOR AND BRAKE UNIT WIRING HARNESS	BOMBARDIER	Recommended	DATE: 3/13/1995	DATE:
6/23/1994	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0440</b>		MODIFICATION - FLAP ACTUATORS ATTACHMENT BOLT REPLACEMENT	BOMBARDIER	Recommended	DATE: 12/20/1995	DATE:
3/31/1995	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0442</b>		SPECIAL CHECK / REWORK PRESSURIZATION - OUTFLOW VALVE - DIAPHRAM	BOMBARDIER	Recommended	DATE: 3/31/1995	DATE:
2/15/1995	ONE TIME		N/A		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0446</b>		MODIFICATION - NOSE GEAR DOOR ACTUATOR IMPROVEMENT TO GROUND LOCKING CAPABILITY	BOMBARDIER	Recommended	DATE: 1/29/1998	DATE:
LH	ONE TIME		C/W		TIME: 0.0	TIME:
2/29/1996					LD/CY: 0	LD/CY:
<b>SB 601-0447</b>		MODIFICATION - RIGHT ENGINE VIBRATION TRANSDUCER ROUTING OF WIRES	BOMBARDIER	Recommended	DATE: 1/07/1996	DATE:
RH	ONE TIME		C/W		TIME: 0.0	TIME:
10/31/1995					LD/CY: 0	LD/CY:
<b>SB 601-0449</b>	R1	MODIFY OXYGEN CYLINDER REGULATOR ASSEMBLY	BOMBARDIER		DATE: 8/08/1995	DATE:
	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0450</b>		AIRCONDITIONING-MODIFICATION-AIR CONDITIONING UNITS (ACU)-ACUS INHIBIT DURING EITHER ENGINE START	BOMBARDIER	Optional	DATE: 4/08/1999	DATE:
4/16/2001	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0452</b>		MODIFICATION - RIGHT MAIN WHEEL BIN - REPLACEMENT OF FASTNERS ON THE INBOARD ACCESS PANEL 144-BZ	BOMBARDIER	Optional	DATE: 8/25/1997	DATE:
8/31/1995	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0454</b>		REWORK NLG DOOR MECHANISM - SPRING BUNGEE ASSEMBLY	BOMBARDIER		DATE: 5/15/1995	DATE:
	ONE TIME		N/A		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0456</b>		SPECIAL CHECK / REWORK - CIRCUIT BREAKER PANEL D (CBP-D) ELECTRICAL WIRE HARNESS PROTECTION	BOMBARDIER	Recommended	DATE: 1/12/1996	DATE:
9/29/1995	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0457</b>		MODIFICATION - STALL PROTECTION SYSTEM SAFETY STICK SHAKER CONNECTOR WITH LOCKWIRE	BOMBARDIER	Recommended	DATE: 1/04/1996	DATE:
8/15/1995	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0460</b>		MODIFICATION - APU BLEED AIR DUCT - CHECK VALVE RELIABILITY IMPROVEMENT	BOMBARDIER	Recommended	DATE: 4/19/1996	DATE:
2/29/1996	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0462</b>	T1	SPECIAL CHECK / REWORK- AFT ENGINE MOUNT SUPPORT RIB FASTNERS	BOMBARDIER	Recommended	DATE: 12/23/1996	DATE:
6/14/1996	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:
<b>SB 601-0470</b>		MODIFICATION - FS169.00 BULKHEAD - ADDITION OF RADOME VENT TUBE	BOMBARDIER	Optional	DATE: 12/19/1996	DATE:
9/30/1996	ONE TIME		C/W		TIME: 0.0	TIME:
					LD/CY: 0	LD/CY:

## AIRFRAME & APPLIANCE SB REPORT CHALLENGER 5017

1/28/2023  
N404HG

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 601-0472		SPECIAL CHECK / MODIFICATION - MGL DOOR MECHINISM - POSSIBLE FOULING BETWEEN CRANK AND DOOR STRUT LINK	BOMBARDIER	Recommended	DATE: 4/22/1996	DATE:
LH	ONE TIME		C/W		TIME: 0.0	TIME:
5/04/1996					LD/CY: 0	LD/CY:
SB 601-0473		SPECIAL CHECK/REWORK - ELECTRICAL HARNESS - INCORRECT INSTALLATION OF SOLDER SLEEVE	BOMBARDIER	Recommended	DATE: 9/30/1996	DATE:
LH	ONE TIME		N/A		TIME: 0.0	TIME:
9/30/1996					LD/CY: 0	LD/CY:
SB 601-0474		SPECIAL CHECK / MODIFICATION - FOWARD ENGINE MOUNT - REPLACEMENT OF NUTS AND DAMAGED BOLTS	BOMBARDIER	Recommended	DATE: 12/31/1996	DATE:
LH	ONE TIME		C/W		TIME: 2565.0	TIME:
6/14/1996					LD/CY: 1415	LD/CY:
SB 601-0474		SPECIAL CHECK / MODIFICATION - FOWARD ENGINE MOUNT - REPLACEMENT OF NUTS AND DAMAGED BOLTS	BOMBARDIER	Recommended	DATE: 12/31/1996	DATE:
RH	ONE TIME		C/W		TIME: 2565.0	TIME:
6/14/1996					LD/CY: 1415	LD/CY:
SB 601-0475		MODIFICATION -THROTTLE QUADRANT ASSEMBLY THROTTLE LEVERS CAN POSSIBLY LOCK IN THE IDLE POSITION	BOMBARDIER	Recommended	DATE: 1/01/2012	DATE:
LH	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		TIME:	TIME:
10/15/1996					LD/CY:	LD/CY:
SB 601-0475		MODIFICATION -THROTTLE QUADRANT ASSEMBLY THROTTLE LEVERS CAN POSSIBLY LOCK IN THE IDLE POSITION	BOMBARDIER	Recommended	DATE: 1/01/2012	DATE:
RH	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		TIME:	TIME:
10/15/1996					LD/CY:	LD/CY:
SB 601-0476		REWORK-WING ANTI ICING DUCTING INSTALLATION OF MISSING BOOT-COVERS AT FS621.00	BOMBARDIER	Recommended	DATE: 12/15/1995	DATE:
LH	ONE TIME		N/A		TIME:	TIME:
12/15/1995					LD/CY:	LD/CY:
SB 601-0477		MODIFICATION -FLAP SYSTEM - INTRODUCTION OF NEW PROXIMINTY SWITCHES IN THE BRAKE DETECTOR UNIT	BOMBARDIER	Recommended	DATE: 1/29/1998	DATE:
LH	ONE TIME		C/W		TIME:	TIME:
6/28/1996					LD/CY:	LD/CY:
SB 601-0478		MODIFICATION - INTRODUCTION OF A LEAD ACID BATTERY / CHARGER FOR IRS NO. 1, NO. 2 AND NO. 3.	BOMBARDIER	Optional	DATE: 7/02/1996	DATE:
LH	ONE TIME		C/W		TIME:	TIME:
1/31/1996					LD/CY:	LD/CY:
SB 601-0479	R1	MODIFICATION - STALL PROTECTION SYSTEM ADDITION OF A TIME DELAY RELAY	BOMBARDIER	Optional	DATE: 2/27/1998	DATE:
LH	ONE TIME		C/W		TIME:	TIME:
9/30/1996					LD/CY:	LD/CY:
SB 601-0482		HYDRAULIC POWER-MODIFICATION-HYDRAULIC TUBES,MAIN LANDING GEAR BAY INSTALL NEW RE-ROUTED TUBES	BOMBARDIER	Recommended	DATE: 1/29/1998	DATE:
LH	ONE TIME		C/W		TIME:	TIME:
6/16/1997					LD/CY:	LD/CY:
SB 601-0482		HYDRAULIC POWER-MODIFICATION-HYDRAULIC TUBES,MAIN LANDING GEAR BAY INSTALL NEW RE-ROUTED TUBES	BOMBARDIER	Recommended	DATE: 1/29/1998	DATE:
LH	ONE TIME		C/W		TIME:	TIME:
6/16/1997					LD/CY:	LD/CY:
SB 601-0485	R2	APU ENCLOSURE- IMPROVE LEAK RESISTANCE AND DRAINAGE	BOMBARDIER	Recommended	DATE: 7/10/2006	DATE:
LH	ONE TIME		N/A		TIME: 6612.9	TIME:
3/10/2010					LD/CY: 3620	LD/CY:
SB 601-0491		RVSM QUALIFICATIONS	BOMBARDIER		DATE: 1/26/1998	DATE:
LH	ONE TIME		C/W		TIME: 2869.0	TIME:
					LD/CY: 1575	LD/CY:

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
<b>SB 601-0494</b>		MODIFICATION-REPLACE THE NOSE LANDING GEAR SELECTOR VALVE AND NOSE GEAR DOOR SELECTOR VALVE PART 55540-2 WITH 55540-5	BOMBARDIER	Recommended	DATE: 2/02/1998 TIME: 2869.3 LD/CY: 1575
LH	ONE TIME		C/W		
6/16/1997					
<b>SB 601-0498</b>		SPECIAL CHECK/REWORK-CONTROL COLUMN TORQUE TUBE SUPPORT BEARINGS & PITCH DISCONNECT CABLE	BOMBARDIER	Recommended	DATE: 12/20/1999 TIME: LD/CY:
	ONE TIME		C/W		
10/29/1999					
<b>SB 601-0501</b>		SPECIAL CHECK - INSPECTION OF THE UNDERFLOOR PRESSURE BULKHEAD AT FS409.00	BOMBARDIER	Recommended	DATE: 4/21/2020 TIME: 10874.7 LD/CY: 6046
	RECURRS		COMPLIED WITH		
9/12/1997					DATE: 6646 TIME: LD/CY:
<b>SB 601-0505 (A)</b>		SPECIAL CHECK/REWORK-PRESSURIZATION CONTROL-CHECK VALVES,P/N 2770080-102 INSTALLATION	BOMBARDIER	Recommended	DATE: 7/09/1998 TIME: LD/CY:
	ONE TIME		C/W		
5/29/1998					
<b>SB 601-0505 (B)</b>		SPECIAL CHECK/REWORK-PRESSURIZATION CONTROL-CHECK VALVES,P/N 2770080-102 INSTALLATION	BOMBARDIER	Recommended	DATE: 7/09/1998 TIME: LD/CY:
	ONE TIME		C/W		
5/29/1998					
<b>SB 601-0507</b>		MODIFICATION-MAIN LANDING GEAR BAY FAIRING-ADD A PROTECTION SHIELD AGAINST ICE BUILD UP ON AILERON CABLES	BOMBARDIER	Recommended	DATE: 10/28/1998 TIME: 3115.1 LD/CY: 1695
	ONE TIME		C/W		
6/30/1998					
<b>SB 601-0509</b>	R1	MODIFICATION-BATTERY SYSTEM- ADDITION OF PROTECTIVE RESISTOR	BOMBARDIER	Recommended	DATE: 7/12/2001 TIME: LD/CY:
	ONE TIME		C/W		
9/15/2000					
<b>SB 601-0510</b>		STALL PROTECTION SYSTEM-DORMANT FAILURES IN THE STALL PROTECTION SYSTEM (SPS) COMPUTER	BOMBARDIER	Recommended	DATE: 2/27/2007 TIME: 6924.6 LD/CY: 3790
	ONE TIME		C/W		
9/05/2003					
<b>SB 601-0513</b>		MODIFICATION-ENGINE STANDBY & APU FUEL FEED SYSTEM-REPLACEMENT OF FLEXIBLE FUEL HOSES	BOMBARDIER		DATE: 6/28/2000 TIME: 3872.4 LD/CY: 2104
	ONE TIME		C/W		
<b>SB 601-0516</b>	R1	MDOFICATION-BATTERY SYSTEM- INSTALLATION OF BATTERY CHARGER OUTPUT PROTECTION	BOMBARDIER	Recommended	DATE: 11/30/1999 TIME: LD/CY:
	ONE TIME		C/W		
6/30/2000					
<b>SB 601-0525</b>		MODIFICATION/CHECK - FUEL FEED SYSTEM - EXAMINE FOR CHAFING ON THE FUEL FEED LINES & ADD BRACKETS & CLAMPS	BOMBARDIER	Recommended	DATE: 11/30/1999 TIME: LD/CY:
	ONE TIME		C/W		
11/30/1999					
<b>SB 601-0526</b>	R1	MODIFICATION -WHEEL ON WHEEL PROXIMITY SWITCHES-PREVENT UNCOMMANDED OF THE ADG ON THE GROUND	BOMBARDIER	Recommended	DATE: 12/20/2000 TIME: LD/CY:
	ONE TIME		C/W		
10/31/2000					
<b>SB 601-0527</b>		MDOFICATION-NAV LIGHTS- CHANGE OF CIRCUIT BREAKER RATING FROM 3 AMPS TO 2 AMPS	BOMBARDIER	Recommended	DATE: 12/16/1999 TIME: LD/CY:
	ONE TIME		C/W		
10/29/1999					
<b>SB 601-0528</b>		SPECIAL CHECK/MOD-APU-PREVENTION OF FUSELAGE SKIN HEAT DAMAGE UNDER & AFT OF THE APU EXHAUST SHIELD	BOMBARDIER	Recommended	DATE: 12/28/2000 TIME: LD/CY:
	ONE TIME		C/W		
10/17/2000					

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
SB 601-0534 9/28/2001	ONE TIME	MODIFICATION- CONVERSION OF THE MAIN BATTERY, P/N 600-59151-11 TO A-13	BOMBARDIER N/A	Recommended DATE: 11/07/2001 TIME: LD/CY:	DATE: TIME: LD/CY:
SB 601-0537 A 1/30/2004	R1 ONE TIME	ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR	BOMBARDIER C/W	Recommended DATE: 7/11/2004 TIME: 5797.0 LD/CY: 3153	DATE: TIME: LD/CY:
SB 601-0538 9/30/2002	ONE TIME	POSSIBLE FAILURE OF ENGINE THROTTLE PUSH PULL CONTROL ASSY	BOMBARDIER C/W	Recommended DATE: 7/10/2004 TIME: 5797.0 LD/CY: 3153	DATE: TIME: LD/CY:
SB 601-0546 5/09/2011	R3 ONE TIME	NLG AND MLG COMPONENT SERIALIZATION	BOMBARDIER C/W	Recommended DATE: 9/07/2012 TIME: 9547.9 LD/CY: 5191	DATE: TIME: LD/CY:
SB 601-0548	ONE TIME	SPECIAL CHECK/REWORK- IDG SYSTEM & AUX AC GENERATION SYSTEM- REPLACEMENT OF FAULTILY MANUFACTURED IDG AND APU GEN.'S	BOMBARDIER N/A BY AIRCRAFT SERIAL NUMBER	Recommended DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
SB 601-0549 4/04/2003	ONE TIME	INTRODUCTION OF AN ADJUSTABLE BALANCE SPRING ASSEMBLY FOR THE RUDDER CONTROL SURFACE	BOMBARDIER C/W	Recommended DATE: 7/10/2006 TIME: 6612.9 LD/CY: 3620	DATE: TIME: LD/CY:
SB 601-0551 8/30/2002	ONE TIME	PLACARDS AND MARKINGS	BOMBARDIER C/W	Recommended DATE: 7/30/2003 TIME: 6390.9 LD/CY: 2924	DATE: TIME: LD/CY:
SB 601-0552 12/15/2003	R1 ONE TIME	SPECIAL CHECK / MOD- WING PLACARDS AND MARKINGS- PAINTED OVERWING ANTI-SLIP WALKWAY (PART A)	BOMBARDIER C/W	Recommended DATE: 12/12/2003 TIME: 5568.4 LD/CY: 3021	DATE: TIME: LD/CY:
SB 601-0553 4/30/2003	ONE TIME	WING FLAP SYSTEM- SERIALIZATION OF FLAP ACTUATOR BEAMS	BOMBARDIER C/W	Recommended DATE: 2/11/2005 TIME: 6006.6 LD/CY: 3294	DATE: TIME: LD/CY:
SB 601-0555 1/31/2005	ONE TIME	POSSIBLE MIGRATION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) LOWER GIMBAL PIN	BOMBARDIER C/W	Recommended DATE: 9/18/2005 TIME: 6282.7 LD/CY: 3441	DATE: TIME: LD/CY:
SB 601-0556 1/23/2003	ONE TIME	EXAMINE PICCOLO TUBE & CONNECTING DUCT INSTALLATION ON LH & RH WINGS	BOMBARDIER C/W	Recommended DATE: 12/22/2003 TIME: 5573.8 LD/CY: 3025	DATE: TIME: LD/CY:
SB 601-0558 2/23/2009	R3 ONE TIME	END CAPS ON NLG SELECTOR VALVE AND NOSE GEAR DOOR SELECTOR VALVE COULD HAVE BEEN INCORRECTLY LOCKWIRED DURING ASSY	BOMBARDIER N/A BY P/N	Recommended DATE: 5/07/2008 TIME: 7453.6 LD/CY: 4048	DATE: TIME: LD/CY:
SB 601-0561 10/31/2003	ONE TIME	POSSIBLE CHAFING ON ELECTRICAL HARNESS LOCATED ON THE APU SUPPORT STRUCTURE	BOMBARDIER C/W	Recommended DATE: 5/24/2004 TIME: 5755.0 LD/CY: 3126	DATE: TIME: LD/CY:
SB 601-0563 A 2/27/2004	ONE TIME	PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY	BOMBARDIER C/W	Recommended DATE: 7/11/2004 TIME: 5797.0 LD/CY: 3153	DATE: TIME: LD/CY:

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
SB 601-0563 B 2/27/2004	ONE TIME	PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY	BOMBARDIER C/W	Recommended DATE: 7/10/2004 TIME: 5797.0 LD/CY: 3153	DATE: TIME: LD/CY:
SB 601-0563 C 2/27/2004	ONE TIME	PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY	BOMBARDIER N/A BY PARTR S/N	Recommended DATE: 7/10/2004 TIME: 5797.0 LD/CY: 3153	DATE: TIME: LD/CY:
SB 601-0565 10/05/2006	ONE TIME	AERODYNAMIC FAIRINGS - INSTALLATION OF DECALS ON THE TAIL CONE ASSEMBLY	BOMBARDIER N/A PRE SB 601-0262	Recommended DATE: 8/26/2008 TIME: LD/CY:	DATE: TIME: LD/CY:
SB 601-0566 3/31/2004	ONE TIME	OUTBOARD FLAP ACTUATORS WITH NON-CONFORMANT TRUNNION BLOCK ROTATION	BOMBARDIER C/W	Recommended DATE: 1/28/2006 TIME: 6408.8 LD/CY: 3501	DATE: TIME: LD/CY:
SB 601-0568 4/16/2007	1 ONE TIME	GENERAL - INTRODUCTION OF THE 36-150 (CL) AUXILIARY POWER UNIT (APU)	BOMBARDIER COMPLIED WITH	Optional DATE: 1/22/2009 TIME: 7941.1 LD/CY: 4306	DATE: TIME: LD/CY:
SB 601-0573 7/21/2005	ONE TIME	APU BLEED AIR SUPPLY - INSTALLATION OF THE RESTRICTOR IN THE APU BLEED AIR DUCTING	BOMBARDIER N/A PER SB 601-0568	Recommended DATE: 1/24/2009 TIME: 7941.1 LD/CY: 4306	DATE: TIME: LD/CY:
SB 601-0574 2/08/2007	R1 ONE TIME	FIRE DETECTION - IMPROVED HARNESS ROUTING FOR JET PIPE SENSING ELEMENT	BOMBARDIER N/A BY EFFECTIVITY	Recommended DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
SB 601-0575 6/29/2005	ONE TIME	WING ANTI-ICING - INSPECTION OF STANDBY THERMAL SWITCHES FOR PRESENCE OF THERMAL COMPOUND	BOMBARDIER C/W	Recommended DATE: 9/07/2012 TIME: 9547.9 LD/CY: 5191	DATE: TIME: LD/CY:
SB 601-0576 8/30/2006	R1 ONE TIME	RUDDER - REPLACEMENT OF RUDDER SYSTEM STOP BOLT P/N 600-92689-1	BOMBARDIER C/W	Recommended DATE: 1/12/2007 TIME: 6836.8 LD/CY: 3745	DATE: TIME: LD/CY:
SB 601-0580 5/28/2007	R1 ONE TIME	GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU)	BOMBARDIER N/A BY AIRCRAFT SERIAL NUMBER	Optional DATE: 1/24/2009 TIME: 7941.1 LD/CY: 4306	DATE: TIME: LD/CY:
SB 601-0581 2/11/2008	ONE TIME	ACTIVATION OF THE 36-150 (CL) APU	BOMBARDIER N/A BY AIRCRAFT SERIAL NUMBER	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
SB 601-0583 A 5/31/2006	ONE TIME	THROTTLE CONTROLS - INSPECTION/REPLACEMENT OF THE THROTTLE GEAR BOX P/N 2100140-003/-005/-007	BOMBARDIER C/W	Recommended DATE: 1/12/2007 TIME: 6836.8 LD/CY: 3745	DATE: TIME: LD/CY:
SB 601-0583 B 5/31/2006	ONE TIME	THROTTLE CONTROLS - INSPECTION/REPLACEMENT OF THE THROTTLE GEAR BOX P/N 2100140-003/-005/-007	BOMBARDIER C/W	Recommended DATE: 1/12/2007 TIME: 6836.8 LD/CY: 3745	DATE: TIME: LD/CY:
SB 601-0585 11/30/2006	ONE TIME	WING ANTI-ICING - ANTI-ICE PICCOLO DUCTS INSPECTION/REPLACEMENT	BOMBARDIER C/W	Recommended DATE: 3/06/2011 TIME: 8630.0 LD/CY: 4655	DATE: TIME: LD/CY:

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 601-0586	R2	FLOOR - ADDITION OF SEAT TRACK EXTENSIONS- BORESCOPE & FOD REMOVAL	BOMBARDIER Recommended	DATE: 1/05/2015 TIME: 9933.4 LD/CY: 5439	DATE: TIME: LD/CY:
4/28/2008	ONE TIME		N/A		
SB 601-0586	R3	FLOOR - ADDITION OF SEAT TRACK EXTENSIONS	BOMBARDIER Recommended	DATE: 1/05/2015 TIME: 9933.4 LD/CY: 5439	DATE: TIME: LD/CY:
7/21/2008	ONE TIME		N/A TO CABIN SEAT INSTALLATION		
SB 601-0587		PASSENGER/CREW ENTRANCE DOOR - PASSENGER DOOR FOOT INSPECTION AND REWORK	BOMBARDIER Recommended	DATE: 1/12/2007 TIME: 6836.8 LD/CY: 3745	DATE: TIME: LD/CY:
12/11/2006	ONE TIME		C/W		
SB 601-0588		INTRODUCAION OF THE 36-150(CL) AUXILIARY POWER UNIT (APU) STAINLESS STEEL EXHAUST EXTENSION	BOMBARDIER Optional	DATE: 1/24/2009 TIME: 7941.1 LD/CY: 4306	DATE: TIME: LD/CY:
3/17/2008	ONE TIME		C/W		
SB 601-0589 A		RESISTANCE TEST & REPLACEMENT OF COMBUSTION ZONE SENSING ELEMENTS WHERE REQUIRED	BOMBARDIER Recommended	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
2/26/2007	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		
SB 601-0589 B		RESISTANCE TEST & REPLACEMENT OF COMBUSTION ZONE SENSING ELEMENTS WHERE REQUIRED	BOMBARDIER Recommended	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
2/26/2007	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		
SB 601-0591		AIR-DRIVEN GENERATOR SYSTEM - REPLACEMENT OF CHAFING ADG POWER FEED WIRE	BOMBARDIER Recommended	DATE: 2/04/2008 TIME: 7453.6 LD/CY: 4048	DATE: TIME: LD/CY:
7/23/2007	ONE TIME		C/W		
SB 601-0596		INSPECT THE UNDER FLOOR SUPPORT CHANNEL FOR FOD AND CLEAN THE AREA	BOMBARDIER Recommended	DATE: 10/30/2009 TIME: 8358.7 LD/CY: 4538	DATE: TIME: LD/CY:
7/21/2008	ONE TIME		N/A		
SB 601-0597 1	R2	INSP & POSSIBLE REPLACE OF SYSTEM ACCUM 1,2,3 & BRAKE ACCUM 2,3 FOR PART NOS 08-60163-002 & 08-60164-002	BOMBARDIER Recommended	DATE: 10/01/2010 TIME: 8867.4 LD/CY: 4788	DATE: TIME: LD/CY:
6/11/2015	ONE TIME		N/A BY PART NUMBER		
SB 601-0598	R1	NLG TOWING STRAP PLACARD INSTALLTION	BOMBARDIER Optional	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
10/13/2016	ONE TIME		N/A		
SB 601-0604	R1	INSTALLTION OF NEW SILICONE RUBBER SEAL TO PREVENT WATER INGRESS	BOMBARDIER Recommended	DATE: 7/23/2011 TIME: 9163.0 LD/CY: 4956	DATE: TIME: LD/CY:
5/06/2014	ONE TIME		C/W		
SB 601-0607	R1	ACU EXHAUST DUCT FLANGE & FUSELAGE SKIN MATING SURFACES	BOMBARDIER Recommended	DATE: 2/09/2011 TIME: 9017.3 LD/CY: 4867	DATE: TIME: LD/CY:
7/24/2015	ONE TIME		C/W		
SB 601-0608	R1	TAKE-OFF SAFETY ENHANCEMENT (TOSE) WING ANTI-ICE WIRING MODIFICATION TO PREVENT NUISANCE INDICATION ON TAKE-OFF	BOMBARDIER Recommended	DATE: 1/12/2012 TIME: 9327.2 LD/CY: 5052	DATE: TIME: LD/CY:
6/27/2011	ONE TIME		C/W		
SB 601-0610		SPECIAL CHECK - INBOARD FLAPS - FORWARD LUGS	BOMBARDIER Recommended	DATE: TIME: LD/CY:	DATE: TIME: LD/CY:
4/27/2011	ONE TIME				15000



**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 601-0612		INSP & TORQUING,IF REQ'D,OF THE BOLTS ATTACHING THE FLOOR BEAM ASSY INST'D OVER THE FWD & AFT AUX FUEL TANKS	BOMBARDIER	Recommended	DATE: 11/10/2011 TIME: 9257.9 LD/CY: 5021	DATE: TIME: LD/CY:
7/05/2011	ONE TIME		N/A			
SB 601-0614		VERIFICATION AND REPLACEMENT OF CREW OXYGEN MASK INFLATABLE HARNESS	BOMBARDIER	Recommended	DATE: 9/07/2012 TIME: 9547.9 LD/CY: 5191	DATE: TIME: LD/CY:
8/15/2011	ONE TIME		C/W			
SB 601-0615 I		REPLACEMENT OF THE APU OIL FILTER ELEMENT	BOMBARDIER	Recommended	DATE: 1/20/2011 TIME: 9017.3 LD/CY: 4867	DATE: TIME: LD/CY:
11/14/2011	ONE TIME		C/W			
SB 601-0617	R3	REPLACEMENT OF PITOT-STATIC VISUAL DRAIN BOTTLES TO LARGER CAPACITY BOTTLES	BOMBARDIER	Recommended	DATE: 1/05/2012 TIME: 9327.2 LD/CY: 5052	DATE: TIME: LD/CY:
12/20/2012	ONE TIME		C/W			
SB 601-0625		IDG AND HYD SYSTEMS 1 & 2. AFT EQUIP BAY RIGHT IDG POWER CABLE AND ADJACENT HYD LINES SUPPORT BRACKETS	BOMBARDIER	Recommended	DATE: 9/19/2012 TIME: 9547.9 LD/CY: 5191	DATE: TIME: LD/CY:
1/13/2014	ONE TIME		C/W			
SB 601-0626		HORIZONTAL STAB TRIM-ACTUATING SYSTEM (HSTA)- SERIALIZATION OF THE ACTUATOR PINS	BOMBARDIER	Recommended	DATE: TIME: LD/CY:	DATE: 2/25/2018 TIME: 10603.0 LD/CY:
4/21/2017	ONE TIME					
SB 601-0631 I		FLAP HINGE BOX. FORWARD LUGS EDGE TO EDGE DISTANCE	BOMBARDIER	Recommended	DATE: TIME: LD/CY: 0	DATE: 9/26/2017 TIME: LD/CY: 7900
9/26/2013	ONE TIME					
SB 601-0648		SPECIAL CHECK/MODIFICATION-RUDDER CONTROL SYSTEM- INSPECTION OF RUDDER LOAD LIMITER	BOMBARDIER	Recommended	DATE: 11/18/2022 TIME: 11678.8 LD/CY: 6581	DATE: TIME: LD/CY:
12/07/2020	ONE TIME		COMPLIED WITH			
SB 601-1056		MODIFICATION- EXHAUST NOZZLE FAIRING - INSTALLATION OF NEW BOLTS AND BUSHINGS.	BOMBARDIER	Recommended	DATE: 4/20/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
9/19/1988	ONE TIME		C/W			
SB 601-1058	R2	MODIFICATION-THRUST REVERSER- DEPLOY MICROSWITCH TARGET	BOMBARDIER	Recommended	DATE: 4/20/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
10/16/1989	ONE TIME		C/W			
SB 601-1061	R1	MODIFICATION- THRUST REVERSER BLOCKER DOORS - IMPROVED RETENTION	BOMBARDIER	Recommended	DATE: 1/18/1991 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
11/02/1990	ONE TIME		C/W			
SB 601-1064		SPECIAL CHECK / MODIFICATION- ANTI-ICE SYSTEM - PRESSURE RELIEF VALVE	BOMBARDIER	Recommended	DATE: 6/09/1989 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
2/28/1989	ONE TIME		C/W			
SB 601-1065		MODIFICATION - AUTO-THROTTLE RETARDER CONTROL - CABLE PROTECTION	BOMBARDIER	Recommended	DATE: 1/14/1998 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
10/25/1989	ONE TIME		C/W			
SB 601-1066	R1	MODIFICATION - THRUST REVERSER TORQUE BOX - DRAINAGE	BOMBARDIER	Recommended	DATE: 4/20/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
12/04/1990	ONE TIME		C/W			

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
<b>SB 601-1068</b>	R1	MODIFICATION - EXHAUST NOZZLE FAIRING - FIRE SENSING CABLE	BOMBARDIER	Recommended	DATE: 1/16/1996 TIME: 2332.0 LD/CY: 1279	DATE: TIME: LD/CY:
12/06/1990	ONE TIME		C/W LH			
<b>SB 601-1070</b>		SPECIAL CHECK / MODIFICATION / REWORK - THRUST REVERSER UPPER PYLON CASCADES.	BOMBARDIER	Recommended	DATE: 1/17/1991 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
8/31/1990	ONE TIME		C/W			
<b>SB 601-1071</b>	R1	REWORK - THRUST REVERSER - INTERLOCKING LATCH FITTING ATTACH RIVETS.	BOMBARDIER	Recommended	DATE: 10/19/1992 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
4/15/1993	ONE TIME		C/W LH & RH			
<b>SB 601-1072</b>		MODIFICATION - EXHAUST NOZZLE FAIRING - PREVENTION OF THE HEAT SHIELD DELAMINATION.	BOMBARDIER	Optional	DATE: 2/05/1992 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
LH 4/26/1991	ONE TIME		C/W			
<b>SB 601-1072</b>		MODIFICATION - EXHAUST NOZZLE FAIRING - PREVENTION OF THE HEAT SHIELD DELAMINATION.	BOMBARDIER	Optional	DATE: 2/05/1992 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
RH 4/26/1991	ONE TIME		C/W			
<b>SB 601-1074</b>		SPECIAL CHECK AND MODIFICATION - CONTROLEX CABLE - TANG WEAR AND SPIRAL WRAP ADDITION.	BOMBARDIER	Recommended	DATE: 12/14/2003 TIME: 5568.4 LD/CY: 3021	DATE: TIME: LD/CY:
LH 7/13/1990	ONE TIME		C/W			
<b>SB 601-1074</b>		SPECIAL CHECK AND MODIFICATION - CONTROLEX CABLE - TANG WEAR AND SPIRAL WRAP ADDITION.	BOMBARDIER	Recommended	DATE: 12/14/2003 TIME: 5568.4 LD/CY: 3021	DATE: TIME: LD/CY:
RH 7/13/1990	ONE TIME		C/W			
<b>SB 601-1074</b>		SPECIAL CHECK AND MODIFICATION - CONTROLEX CABLE - TANG WEAR AND SPIRAL WRAP ADDITION.	BOMBARDIER	Recommended	DATE: 3/20/2002 TIME: 4742.4 LD/CY: 2582	DATE: TIME: LD/CY:
RH 7/13/1990	ONE TIME		C/W			
<b>SB 601-1074</b>		SPECIAL CHECK AND MODIFICATION - CONTROLEX CABLE - TANG WEAR AND SPIRAL WRAP ADDITION.	BOMBARDIER	Recommended	DATE: 3/20/2002 TIME: 4742.4 LD/CY: 2582	DATE: TIME: LD/CY:
LH 7/13/1990	ONE TIME		C/W			
<b>SB 601-1075</b>		MODIFICATION - THRUST REVERSER - BLOCKER DOOR LINK HOUSING COVERS	BOMBARDIER	Optional	DATE: 1/18/1991 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
4/30/1990	ONE TIME		C/W			
<b>SB 601-1078</b>		SPECIAL CHECK / MODIFICATION - UPPER ACCESS COWL - CLEARANCE WITH BALLSCREW ACTUATORS.	BOMBARDIER	Recommended	DATE: 1/18/1991 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
LH 7/13/1990	ONE TIME		C/W			
<b>SB 601-1078</b>		SPECIAL CHECK / MODIFICATION - UPPER ACCESS COWL - CLEARANCE WITH BALLSCREW ACTUATORS.	BOMBARDIER	Recommended	DATE: 1/18/1991 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
RH 7/13/1990	ONE TIME		C/W			
<b>SB 601-1079</b>		SPECIAL CHECK / MODIFICATION - THRUST REVERSER - PNEUMATIC DRIVE UNIT FLEXSHAFT BOLTS.	BOMBARDIER	Recommended	DATE: 11/28/1990 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
9/14/1990	ONE TIME		C/W			
<b>SB 601-1083</b>		MODIFICATION - CORE COWL DOORS - IMPROVED FIRE RESITANCE AND CONTAINMENT.	BOMBARDIER	Recommended	DATE: 12/01/1994 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
LH 3/31/1995	ONE TIME		C/W			

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 601-1083		MODIFICATION - CORE COWL DOORS - IMPROVED FIRE RESITANCE AND CONTAINMENT.	BOMBARDIER	Recommended	DATE: 12/01/1994	DATE:
RH	ONE TIME		C/W		TIME: 0.0	TIME:
3/31/1995					LD/CY: 0	LD/CY:
SB 601-1084		SPECIAL CHECK / MODIFICATION - THRUST REVERSER - BLOCKER DOORS AND SOUND ATTENUATING MATERIAL (SAM) PANELS.	BOMBARDIER	Recommended	DATE: 2/23/1996	DATE:
	ONE TIME		C/W		TIME: 2332.0	TIME:
12/15/1999					LD/CY: 1279	LD/CY:
SB 601-1088		SPECIAL CHECK / MODIFICATION - THRUST REVERSER - BALLSCREW ACTUATOR	BOMBARDIER	Recommended	DATE: 6/27/1994	DATE:
	ONE TIME		N/A		TIME: 0.0	TIME:
6/27/1994					LD/CY: 0	LD/CY:
SB 601-1093		SPECIAL CHECK / REWORK OF HYDRAULIC HOSE ASSEMBLY ON ENGINE DRIVEN PUMPS.	BOMBARDIER	Recommended	DATE: 9/30/1996	DATE:
	ONE TIME		N/A		TIME: 0.0	TIME:
9/30/1996					LD/CY: 0	LD/CY:
SB 601-1100	R1	SPECIAL CHECK/REWORK-THRUST REVERSER EXAMINE CONDITION OF ACTUATOR ATTACHMENT FITTINGS	BOMBARDIER	Recommended	DATE: 12/13/2001	DATE:
	ONE TIME		C/W		TIME: 0.0	TIME:
10/19/2001					LD/CY: 0	LD/CY:
SB A600-0432		WINGS SPECIAL CHECK/MODIFICATION - AILERON - HINGE/ACTUATOR FITTING	BOMBARDIER	Mandatory	DATE: 2/07/1994	DATE:
	ONE TIME		N/A		TIME: 0.0	TIME:
11/25/1985					LD/CY: 0	LD/CY:
SB A601-0309		FIRE PROTECTION - SPECIAL CHECK MODIFICATION -ENGINE FIRE PROTECTION SENSOR SYSTEM WIRING& SQUIB WIRING	BOMBARDIER	Mandatory	DATE: 12/05/1989	DATE:
	ONE TIME		C/W		TIME:	TIME:
9/08/1989					LD/CY:	LD/CY:
SB A601-0332	R1	FLIGHT CONTROLS - MODIFICATION STALL PROTECTION SYSTEM STICK PUSHER	BOMBARDIER	Mandatory	DATE: 7/19/1990	DATE:
	ONE TIME		C/W		TIME: 0.0	TIME:
5/22/1990					LD/CY: 0	LD/CY:
SB A601-0374	R1	SPECIAL CHECK AND MODIFICATION - THROTTLE QUADRANT - IDLE STOP PAWL	CANADAIR	Mandatory	DATE: 3/25/2012	DATE:
	ONE TIME		N/A BY P/N		TIME: 9382.4	TIME:
9/30/1992					LD/CY: 5088	LD/CY:
SB A601-0380		MODIFICATION - HORIZONTAL STABILIZER / ELEVATOR INBOARD HINGE FITTING FASTNERS	CANADAIR	Mandatory	DATE: 12/09/1992	DATE:
	ONE TIME		C/W		TIME: 0.0	TIME:
5/31/1991					LD/CY: 0	LD/CY:
SB A601-0381	R2	SPECIAL CHECK / MODIFICATION - PRESSURE REFUEL / DEFUEL SYSTEM RELOCATION OF SENSING LINE	CANADAIR	Mandatory	DATE: 2/05/1992	DATE:
	ONE TIME		N/A		TIME: 0.0	TIME:
1/27/1992					LD/CY: 0	LD/CY:
SB A601-0519		STALL PROTECTION SYSTEM-INSPECTION & REPLACEMENT OF ANGLE OF ATTACK (AOA) VANE DECALS	BOMBARDIER	Mandatory	DATE: 11/04/1999	DATE:
	ONE TIME		C/W		TIME: 0.0	TIME:
7/30/1999					LD/CY: 0	LD/CY:
SB A601-0532	R1	VISUALLY INSPECT ALL 12 VANE BRACKETS FOR CRACKS AND TEST THE FLAPS	BOMBARDIER	Recommended	DATE: 4/03/2002	DATE:
	ONE TIME		C/W		TIME: 4742.0	TIME:
7/08/2002					LD/CY: 2598	LD/CY:
SB A601-0540		SPECIAL CHECK- FLAPS- VISUALLY EXAMINE FLAP ACTUATOR BEAM VANE BRACKETS FOR POSSIBLE CRACKS	BOMBARDIER	Recommended	DATE: 2/07/2001	DATE:
	ONE TIME		C/W		TIME: 0.0	TIME:
12/08/2000					LD/CY: 0	LD/CY:

**AIRFRAME & APPLIANCE SB REPORT  
CHALLENGER 5017**

**1/28/2023  
N404HG**

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
SB A601-0550 A 2/27/2004	ONE TIME	SPECIAL CHK / MOD- ANGLE-OF-ATTACK(AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OUT-OF-TOLERANCE AOA TRANSDUCER ASSYS	BOMBARDIER COMPLIED WITH	Recommended DATE: 4/03/2002 TIME: 4742.4 LD/CY: 2598	DATE: TIME: LD/CY:
SB A601-0550 B 2/27/2004	ONE TIME	SPECIAL CHK / MOD- ANGLE-OF-ATTACK(AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OUT-OF-TOLERANCE AOA TRANSDUCER ASSYS	BOMBARDIER COMPLIED WITH	Recommended DATE: 4/03/2002 TIME: 4742.4 LD/CY: 2598	DATE: TIME: LD/CY:
SB A601-0554 1/30/2004	R1 ONE TIME	SPECIAL CHECK-PLATES / SKINS- POSSIBLE DEVELOPEMENT OF CRACK(S) ON LOWER WING PLANK AT WS148.02 (REAR SPAR)	BOMBARDIER C/W	Recommended DATE: 5/28/2003 TIME: 5299.3 LD/CY: 2876	DATE: TIME: LD/CY:
SB A601-0556 1/23/2003	ONE TIME	WING ANTI-ICING- EXAMINE PICCOLO TUBE AND CONNECTING DUCT INSTALLATION ON LH AND RH WINGS	BOMBARDIER C/W	Recommended DATE: 12/22/2003 TIME: 5573.8 LD/CY: 3025	DATE: TIME: LD/CY:
SB A601-0627 A 12/09/2014	ONE TIME	INBOARD FLAP HINGE BOX FORWARD ATTACHMENT FITTINGS FASTENERS	BOMBARDIER C/W PART A, PART B DOES NOT APPLY	Recommended DATE: 3/19/2014 TIME: 9724.0 LD/CY: 5307	DATE: TIME: LD/CY:
SB A601-0627 A 12/09/2014	ONE TIME	INBOARD FLAP HINGE BOX FORWARD ATTACHMENT FITTINGS FASTENERS	BOMBARDIER COMPLIED WITH	Recommended DATE: 3/19/2015 TIME: 9724.0 LD/CY: 5307	DATE: TIME: LD/CY:
SB A601-0627 A 12/09/2014	ONE TIME	INBOARD FLAP HINGE BOX FORWARD ATTACHMENT FITTINGS FASTENERS	BOMBARDIER COMPLIED WITH	Recommended DATE: 3/19/2014 TIME: 9724.0 LD/CY: 5307	DATE: TIME: LD/CY:
SB A601-0627 B 12/09/2014	ONE TIME	INBOARD FLAP HINGE BOX FORWARD ATTACHMENT FITTINGS FASTENERS	BOMBARDIER COMPLIED WITH	Recommended DATE: 3/19/2014 TIME: 9724.0 LD/CY: 5307	DATE: TIME: LD/CY:
SB A601-1087 4/25/1994	ONE TIME	MODIFICATION - FIRE PROTECTION - HARNESS RE-ROUTING.	BOMBARDIER N/A	Mandatory DATE: 4/25/1994 TIME: LD/CY:	DATE: TIME: LD/CY:
SB A601-1087 4/25/1994	ONE TIME	MODIFICATION - FIRE PROTECTION - HARNESS RE-ROUTING.	BOMBARDIER N/A	Mandatory DATE: 4/25/1994 TIME: LD/CY:	DATE: TIME: LD/CY: