



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
051220 RVSM	INSPECT PHASE 20-RVSM/ADC/ALT	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24		31-Dec-2020	9 m 20 d
051233	INSPECT (GILL)	SRQ		MTH 15-Nov-2019 HRS 5509 LDG 3775		12 800		30-Nov-2020 6309	8 m 19 d 800
5-12-01 051201	PHASE 1	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24 300		31-Dec-2020 5807.2	9 m 20 d 298.2
5-12-02 051202	PHASE 2	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24 300		31-Dec-2020 5807.2	9 m 20 d 298.2
5-12-03 051203	PHASE 3	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24 300		31-Dec-2020 5807.2	9 m 20 d 298.2
5-12-04 051204	PHASE 4	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24 300		31-Dec-2020 5807.2	9 m 20 d 298.2
5-12-05 051205	PHASE 5	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		36 1200		31-Dec-2021 6707.2	21 m 20 d 1198.2
5-12-08	PHASE 8 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 15-Nov-2019 HRS 5509 LDG 3775		6			
A262003 AFT 051208 : A	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	SRQ	C352TS SN-UNKNOWN	MTH 15-Nov-2019		6		31-May-2020	2 m 20 d
A262003 FORWARD 051208 : F	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	SRQ	C352TS SN-UNKNOWN	MTH 15-Nov-2019		6		31-May-2020	2 m 20 d
5-12-0B 051200B	PHASE B	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		150		5657.2	148.2
5-12-11	PHASE 11 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 15-Nov-2019 HRS 5509 LDG 3775		6			
B342004 051211	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY LEAD ACID PS835 BATTERY PACK: PHASE 11	SRQ	501-1228-03 80167	MTH 15-Nov-2019 HRS 5509 LDG 3775		6		31-May-2020	2 m 20 d
5-12-12	PHASE 12			MTH HRS		3600		8943.48	3434.48
5-12-13 051213	PHASE 13	HUR		MTH 27-May-2005 HRS 4985		5000		9985	4476
5-12-14 051214	PHASE 14			MTH 13-Sep-1985 HRS 0		10000		10000	4491
5-12-15 051215	PHASE 15			MTH 13-Sep-1985 HRS 0		10000		10000	4491
5-12-16 051216	PHASE 16			MTH 13-Sep-1985 HRS 0		10000		10000	4491
5-12-17 051217	PHASE 17			MTH 13-Sep-1985 HRS 0		10000		10000	4491
5-12-18 051218	PHASE 18	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		12		31-Dec-2019	-2 m 11 d

Over Due



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24			
A341006 051220	CHECK STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24		31-Dec-2020	9 m 20 d
B341001 LEFT 051220 : L-A/S	CALIBRATION TEST AIR SPEED INDICATOR OVERSPEED WARNING SWITCH, DIFFERENTIAL PRESSURE SWITCH (AIRPLANES NOT CERTIFIED FOR RVSM): PHASE 20	SRQ	C661063-0104 155ABC	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
B341001 RIGHT 051220 : R-A/S	CALIBRATION TEST AIR SPEED INDICATOR OVERSPEED WARNING SWITCH, DIFFERENTIAL PRESSURE SWITCH (AIRPLANES NOT CERTIFIED FOR RVSM): PHASE 20	SRQ	C661063-0104 221ABC	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
B341003 NO. 1 051220 : ADC	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	SRQ	7024900-30302 02060395	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
B341003 STANDBY 051220 : STDBY	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	SRQ	570-24929-013 W17858H	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
B341004 STANDBY 051220 : STDBY	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	SRQ	570-24929-013 W17858H	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
B341005 LEFT 051220 : L	LEAK TEST STATIC SYSTEM: PHASE 20	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24		31-Dec-2020	9 m 20 d
B341005 RIGHT 051220 : R	LEAK TEST STATIC SYSTEM: PHASE 20	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24		31-Dec-2020	9 m 20 d
B341107 NO. 1 051220 : ADC	CHECK AIR DATA COMPUTER (AIRPLANES CERTIFIED FOR RVSM) : PHASE 20	SRQ	7024900-30302 02060395	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
B341107 STANDBY 051220 : STDBY	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	SRQ	570-24929-013 W17858H	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24			
A237003 051221 : CVR	INSPECT COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	SRQ	DK120 AT115148	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24		31-Dec-2020	9 m 20 d
B237004 051221 : CVR	OPERATIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	SRQ	DK120 AT115148	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24		31-Dec-2020	9 m 20 d
B345001 LEFT 051221	CALIBRATION TEST TRANSPONDER TRANSPONDER SYSTEM: PHASE 21	SRQ	066-01143-2101 1283	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
B345001 RIGHT 051221 : R	CALIBRATION TEST TRANSPONDER TRANSPONDER SYSTEM: PHASE 21	SRQ	066-01143-2101 1287	MTH 20-Dec-2018		24		31-Dec-2020	9 m 20 d
5-12-22	PHASE 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		36			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B326003 051222 : GEAR	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE : PHASE 22	SRQ	212940-2 3449	MTH 20-Dec-2017		36		31-Dec-2020	9 m 20 d
5-12-23	PHASE 23 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		60			
B262002 AFT 051223 : ATR	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23	SRQ	9912048-3 14448C1	MTH 19-May-2017		60		31-May-2022	26 m 20 d
B262002 FORWARD 051223 : FTR	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23	SRQ	9912048-3 16279C1	MTH 19-May-2017		60		31-May-2022	26 m 20 d
5-12-26 051226	PHASE 26	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24 3000		31-Dec-2020 8507.2	9 m 20 d 2998.2
5-12-30 051230 : ACM	PHASE 30	HUR		MTH 27-May-2005 HRS 4985		600		5585	76
5-12-32 051232	PHASE 32			MTH 13-Sep-1985 LDG 0		15000		15000	11225
5-12-33 051233	PHASE 33			MTH 13-Sep-1985 LDG 0		15000		15000	11225
5-12-40 051240	PHASE 40 NOT USED	*CF		MTH 13-Sep-1985		A/R			
5-12-43 051243	PHASE 43 NOT USED	*CF		MTH 13-Sep-1985		A/R			
5-12-47	PHASE 47 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		144			
B262003 AFT 051247 : A	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47	SRQ	C352TS SN-UNKNOWN	MTH 20-Dec-2018		144		31-Dec-2030	129 m 20 d
B262003 FORWARD 051247 : F	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47	SRQ	C352TS SN-UNKNOWN	MTH 20-Dec-2018		144		31-Dec-2030	129 m 20 d
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		72			
B262004 AFT 051248 : A	INSPECT PORTABLE FIRE EXTINGUISHER FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48	SRQ	C352TS SN-UNKNOWN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		72		31-Dec-2024	57 m 20 d
B262004 FORWARD 051248 : F	INSPECT PORTABLE FIRE EXTINGUISHER FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48	SRQ	C352TS SN-UNKNOWN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		72		31-Dec-2024	57 m 20 d
5-12-49 051249	PHASE 49	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		36 1200		31-Dec-2021 6707.2	21 m 20 d 1198.2
5-12-51	PHASE 51 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		60			
B350003 051251 : OXY	HYDROSTATIC TEST PORTABLE OXYGEN BOTTLE (DOT 3AA): PHASE 51	SRQ	PN SN-UNKNOWN	MTH 20-Dec-2018		60		31-Dec-2023	45 m 20 d



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-52 051252	PHASE 52	SRQ	MTH	20-Dec-2018		12		31-Dec-2019	-2 m 11 d
			HRS	5507.2					
			LDG	3773					Over Due
5-12-53 051253	PHASE 53	SRQ	MTH	20-Dec-2018		72		31-Dec-2024	57 m 20 d
			HRS	5507.2		2400		7907.2	2398.2
			LDG	3773					
5-12-54	PHASE 54		MTH	13-Sep-1985					
			HRS	0		13200		13200	7691
5-12-55	PHASE 55		MTH	13-Sep-1985					
			HRS	0		15600		15600	10091
5-12-56	PHASE 56		MTH	13-Sep-1985					
			HRS	0		15600		15600	10091
5-12-57	PHASE 57		MTH						
			HRS			10000		10000	4491
5-12-58	PHASE 58		MTH						
			HRS			300		5915.57	406.57
5-12-59	PHASE 59		MTH						
			ACH			500		725.87	725.87
5-12-MA	PHASE MA		MTH						
			HRS			300		5723.95	214.95
5-12-MB	PHASE MB		MTH	13-Sep-1985					
			LDG	0		10000		10000	6225
050001 E1	ENGINE OVERTEMPERATURE		MTH	13-Sep-1985		A/R			
050001 E2	ENGINE OVERTEMPERATURE		MTH	13-Sep-1985		A/R			
050002 E1	ENGINE OVERSPEED		MTH	13-Sep-1985		A/R			
050002 E2	ENGINE OVERSPEED		MTH	13-Sep-1985		A/R			
050003 E1	ENGINE IMMERSION IN WATER		MTH	13-Sep-1985		A/R			
050003 E2	ENGINE IMMERSION IN WATER		MTH	13-Sep-1985		A/R			
050004 E1	ENGINE DROPPED DURING HANDLING		MTH	13-Sep-1985		A/R			
050004 E2	ENGINE DROPPED DURING HANDLING		MTH	13-Sep-1985		A/R			
050005 E1	FOREIGN OBJECT DAMAGE (FOD)		MTH	13-Sep-1985		A/R			
050005 E2	FOREIGN OBJECT DAMAGE (FOD)		MTH	13-Sep-1985		A/R			
050006 E1	LOSS OF OIL		MTH	13-Sep-1985		A/R			
050006 E2	LOSS OF OIL		MTH	13-Sep-1985		A/R			
050007 E1	ENGINE WINDMILLING		MTH	13-Sep-1985		A/R			
050007 E2	ENGINE WINDMILLING		MTH	13-Sep-1985		A/R			
050008 E1	LIGHTNING STRIKE		MTH	13-Sep-1985		A/R			
050008 E2	LIGHTNING STRIKE		MTH	13-Sep-1985		A/R			
050009 E1	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT		MTH	13-Sep-1985		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
050009 E2	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT			MTH 13-Sep-1985		A/R			
050010 E1	HEAVY / HARD LANDING			MTH 13-Sep-1985		A/R			
050010 E2	HEAVY / HARD LANDING			MTH 13-Sep-1985		A/R			
050011 E1	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH 13-Sep-1985		A/R			
050011 E2	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH 13-Sep-1985		A/R			
050012 E1	ENGINE WITH HIGH TURBINE BLADE DISTRESS			MTH 13-Sep-1985		A/R			
050012 E2	ENGINE WITH HIGH TURBINE BLADE DISTRESS			MTH 13-Sep-1985		A/R			
050013 E1	STARTER GENERATOR FAIL INDICATION			MTH 13-Sep-1985		A/R			
050013 E2	STARTER GENERATOR FAIL INDICATION			MTH 13-Sep-1985		A/R			
050014 E1	HYDRAULIC PUMP FAILURE			MTH 13-Sep-1985		A/R			
050014 E2	HYDRAULIC PUMP FAILURE			MTH 13-Sep-1985		A/R			
057110 E1	MINOR INSPECTION	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24 300		31-Dec-2020 (5807.2)5807.2	9 m 20 d 298.2
057110 E2	MINOR INSPECTION	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24 300		31-Dec-2020 (5807.2)5807.2	9 m 20 d 298.2
215012	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS 1134104-1, -5 ORFWA1134104-1, -5 ONLY)		PN SN-UNKNOWN	MTH ACH		500		590.25	590.25
262003 AFT LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	SRQ	13083-5 42348	MTH 18-Nov-2019		72	4	31-Jul-2025	64 m 20 d
262003 AFT RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	SRQ	13083-5 42356	MTH 18-Nov-2019		72	4	31-Jul-2025	64 m 20 d
262003 FORWARD LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	SRQ	13083-5 42370	MTH 18-Nov-2019		72	4	31-Jul-2025	64 m 20 d
262003 FORWARD RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	SRQ	13083-5 42374	MTH 18-Nov-2019		72	4	31-Jul-2025	64 m 20 d
B350004 051222 : OXY	HYDROSTATIC TEST OXYGEN CYLINDER ASSEMBLY DOT 3HT 1850 OR DOT 3FC1850 OR MANUFACTURED UNDER DOT-SP-8162.	SRQ	176176-64 1096-615149	MTH 20-Dec-2018		36		31-Dec-2021	21 m 20 d
710000 E1	TURBINE WASH			MTH 13-Sep-1985		A/R			
710000 E2	TURBINE WASH			MTH 13-Sep-1985		A/R			
710010 E1	OVERHAUL			MTH 20-Jul-1994 HRS 3322		3500		(6822)6822	1313



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
710010 E2	OVERHAUL		MTH	20-Jul-1994 HRS 3322		3500		(6822)6822	1313
710020 E1	HOT SECTION INSPECTION HUR		MTH	06-Aug-2007 HRS 5068		1800		(6868)6868	1359
710020 E2	HOT SECTION INSPECTION HUR		MTH	06-Aug-2007 HRS 5068		1800		(6868)6868	1359
710030 E1	INSPECT INTERMEDIATE CASE FOR CORROSION		MTH			A/R			
710030 E2	INSPECT INTERMEDIATE CASE FOR CORROSION		MTH			A/R			
720010 E1	OIL ANALYSIS		MTH	13-Sep-1985		A/R			
720010 E2	OIL ANALYSIS		MTH	13-Sep-1985		A/R			
725040 E1	REPLACE HIGH TURBINE BLADES		MTH	20-Jul-1994 HRS 3322		O/C	1035		
725040 E2	REPLACE HIGH TURBINE BLADES		MTH	20-Jul-1994 HRS 3322		O/C	1035		
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER		UA530768-4 3237	MTH HRS 0	13-Sep-1985	A/R		(6822)6822	1313
731025 E2	VISUALLY INSPECT FUEL-OIL COOLER		UA530768-4 3260	MTH HRS 0	13-Sep-1985	A/R		(6822)6822	1313
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE		2524995 SN-UNKNOWN	MTH HRS 0	13-Sep-1985	1800		(6822)6822	1313
731035 E2	VISUALLY INSPECT MOTIVE FLOW VALVE		2524995 SN-UNKNOWN	MTH HRS 0	13-Sep-1985	1800		(6822)6822	1313
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE		25607-2 3184	MTH HRS 0	13-Sep-1985	1800		(6822)6822	1313
731090 E2	VISUALLY INSPECT FLOW DIVIDER VALVE		25607-2 3227	MTH HRS 0	13-Sep-1985	1800		(6822)6822	1313
741030 E1 LOWER	VISUAL INSPECT IGNITION EXCITER SRQ		NB01201 K3733	MTH HRS 5507.2 LDG 3773	20-Dec-2018	24 300		31-Dec-2020 (5807.2)5807.2	9 m 20 d 298.2
741030 E1 UPPER	VISUAL INSPECT IGNITION EXCITER SRQ		NB01201 K3736	MTH HRS 5507.2 LDG 3773	20-Dec-2018	24 300		31-Dec-2020 (5807.2)5807.2	9 m 20 d 298.2
741030 E2 LOWER	VISUAL INSPECT IGNITION EXCITER SRQ		NB01201 K3722	MTH HRS 5507.2 LDG 3773	20-Dec-2018	24 300		31-Dec-2020 (5807.2)5807.2	9 m 20 d 298.2
741030 E2 UPPER	VISUAL INSPECT IGNITION EXCITER SRQ		NB01201 K3734	MTH HRS 5507.2 LDG 3773	20-Dec-2018	24 300		31-Dec-2020 (5807.2)5807.2	9 m 20 d 298.2
792010 E1	CHANGE OIL	DUB		MTH HRS 5479.8 LDG 3759	30-Apr-2013	O/C			
792010 E2	CHANGE OIL	DUB		MTH HRS 5479.8 LDG 3759	30-Apr-2013	O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION VALVE HUR			27441482-06 4AN28	MTH 23-Dec-1997 HRS 3896		O/C	0		
212003	BLOWER 9912070-1	THV		19A2338 1574	MTH 08-Dec-1989 HRS 2069		O/C	0		
212004	CABIN OVERHEAD FAN 9912323-2	HUR		BC61A-901-2 SN-UNKNOWN	MTH 13-Jul-2004 HRS 4886		1000	0	5886	377
212005 LEFT	CABIN DIVIDER BLOWER 5515129-4	*CF		WS2107F30 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
212005 RIGHT	CABIN DIVIDER BLOWER 5515129-4	*CF		WS2107F30 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
212009	CABIN UNDERFLOOR ACTUATOR *CF			NYLC50466 637	MTH 13-Sep-1985		O/C			
212010	DOOR ACTUATOR MOTOR ASSY 9910059-3	*CF		5A3032 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
212027 212006	DEFOG FAN	5NN		5703-3 27	MTH 20-Jan-1996 HRS 3517		3500	0	7017	1508
213001	CABIN PRESS INDICATOR 3001J14	*CF		C668511-0102 18013	MTH 13-Sep-1985		O/C			
213002	OUTFLOW VALVE CONTROLLER ALN			130356-15 109383	MTH 17-Jan-1992 HRS 3050		O/C	0		
213003	CABIN RATE OF CLIMB INDICATOR 35060-1128	*CF		C668513-0101 W13393H	MTH 13-Sep-1985		O/C			
213007 LEFT	OUTFLOW VALVE	*CF		103576-36 1141637	MTH 13-Sep-1985		O/C			
213007 RIGHT	OUTFLOW VALVE	*CF		103576-36 1141622	MTH 13-Sep-1985		O/C			
213009 LEFT	BLEED AIR FLOW CONTROL VALVE DUB			1988-00-1 259	MTH 20-Sep-1995 HRS 3484		O/C	0		
213009 RIGHT	BLEED AIR FLOW CONTROL VALVE DUB			34E16-3 10850549	MTH 22-Aug-1995 HRS 3469		O/C	3453		
213013	PNEUMATIC RELAY	*CF		130358-1 941465	MTH 13-Sep-1985		O/C			
215001	REFRIGERATION PACKAGE 9912069-25	*CF		782343-1 850521	MTH 13-Sep-1985		O/C			
215004	AIR CYCLE MACHINE 9912069-1	*CF		738384-26P1 850573	MTH 13-Sep-1985 HRS 0		5000	0	5000	-509
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										Over Due
215005	BYPASS VALVE 9912069-1	*CF		754751-2 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
215015	COMPRESSOR DRIVE MOTOR			PN SN-UNKNOWN	MTH 13-Sep-1985		O/C	0		
216002	TEMP CONTROL UNIT 9912069-22	HUR		754661-5 C93013087	MTH 20-Dec-1996 HRS 3693		O/C	0		
216003	DUCT TEMP SENSOR 9912069-14	HUR		754691-1 02095384	MTH 03-Jun-2003 HRS 4696		O/C	0		
216004	CABIN TEMP SENSOR 9912069-15	*CF		754681-1 84082328	MTH 13-Sep-1985		O/C			
216005	CENTRIFUGAL BLOWER *CF			3A1003-10 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
221008	AUTOPILOT COMPUTER SP-200	THV		4008519-945 87014093	MTH 06-Oct-1987 HRS 934		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
221009	AUTOPILOT CONTROLLER PC-500	THW		4018639-909 85062641	MTH 16-Dec-1985 HRS 36		O/C	0		
221010 AFT	AILERON AUTOPILOT SERVO SM-200	*CF		4006719-906 85051852	MTH 13-Sep-1985		O/C			
221010 FORWARD	ELEVATOR AUTOPILOT SERVO SM-200	*CF		4006719-914 85041778	MTH 13-Sep-1985		O/C			
221010 MID	RUDDER AUTOPILOT SERVO SM-200	*CF		4006719-906 85059933	MTH 13-Sep-1985		O/C			
230010 237001	COCKPIT VOICE RECORDER GA-100	HUR		GA100-0000 00361	MTH 27-May-2005 HRS 4985		O/C	0		
230017 237010	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON 266-E0305-00	SRQ		DK120 AT115148	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		72	0 0 0	01-Jun-2023	38 m 21 d
231003	HF RECEIVER/EXCITER KTR-953	ALN		064-1015-01 U27093	MTH 06-Mar-1992 HRS 3053		O/C	0		
231004	HF ANTENNA COUPLER KAC-952	HUR		064-1017-01 U12633	MTH 23-Dec-1997 HRS 3896		O/C	843		
231005	HF CONTROL HEAD KCU-951	ALN		064-1016-03 U6297	MTH 06-Mar-1992 HRS 3053		O/C	0		
231014	SELCAL DECODER --	ALN		1200006-006 133	MTH 06-Mar-1992 HRS 3053		O/C	0		
232002 NO. 2	COMM ANTENNA NO. 2	*CF		VFS10-108-1 1376	MTH 13-Sep-1985		O/C			
232003 NO. 1	COMM ANTENNA NO. 1	HUR		VFS10-90-7 1280	MTH 06-Aug-2007 HRS 5068		O/C	0		
232004	AIRBIRNE COMMUNICATION TRANSCEIVER *CF			400-0115 688	MTH 13-Sep-1985		O/C			
232005 CABIN	CONTROL PHONE CABIN	*CF		400-0116 1066	MTH 13-Sep-1985		O/C			
232006	COCKPIT CONTROL *CF			400-0117 613	MTH 13-Sep-1985		O/C			
232007 NO. 1	AIRBORNE COMMUNICATION ANTENNA -- NO. 1	HUR		CI-120-1-L 261798	MTH 12-Oct-2009 HRS 5228		O/C	0		
232007 NO. 2	AIRBORNE COMMUNICATION ANTENNA -- NO. 2	HUR		CI-120-1-L 261797	MTH 12-Oct-2009 HRS 5228		O/C	0		
232007	AIRBORNE COMMUNICATION ANTENNA HUR			121-0011-000 3396	MTH 06-Aug-2007 HRS 5068		O/C	0		
232010 BOTTOM	NO.2 COMM TRANSCEIVER VHF-22A			622-6152-001 22935	MTH 06-Oct-1994 HRS 3322		O/C	1219		
232010 TOP	NO.1 COMM TRANSCEIVER VHF-22C	HUR		822-1113-001 25127	MTH 06-Aug-2007 HRS 5068		O/C	0		
232011	AVIONICS CONTROL PANEL HUR			1U619-001 1145	MTH 22-May-2001 HRS 4406		O/C	0		
235001 LEFT	AUDIO AMPLIFIER LEFT	*CF		5640-1 579	MTH 13-Sep-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
235001 RIGHT	AUDIO AMPLIFIER	DUB		5640-1 581	MTH 28-Jul-1995 HRS 3456		O/C	3456		
237006	REMOTE MIKE --	ALN		93-A055-95 369	MTH 21-Feb-1990 HRS 2136		O/C	0		
242001 BOTTOM	NO.2 AC INVERTER	THV		PC-350-4A 9914254-1 2265	MTH 28-Aug-1989 HRS 1909		O/C	0		
242001 TOP	NO.1 AC INVERTER	*CF		PC-350 9914254-1 2016	MTH 13-Sep-1985		O/C			
243001 LEFT	STARTER/GENERATOR	HUR		23085-004-1 9912125-3 94123	MTH 31-Jul-2009 HRS 5208		1000	0	6208	699
243001 RIGHT	STARTER/GENERATOR	HUR		23085-004 9912125-4 390	MTH 13-Jul-2004 HRS 4886		1000	0	5886	377
243003 LEFT	GENERATOR CONTROL UNIT	THU		51539-006F 9912039-6 2805AB	MTH 22-Jul-1991 HRS 2764		O/C	0		
243003 RIGHT	GENERATOR CONTROL UNIT	THU		51539-006F 9912039-6 2914AB	MTH 22-Jul-1991 HRS 2764		O/C	0		
243004 LEFT	AMMETER	THU		C662501-0104 237	MTH 07-Jul-1986 HRS 292		O/C	0		
243004 RIGHT	AMMETER	*CF		C662501-0104 153	MTH 13-Sep-1985		O/C			
243005	VOLTMETER	*CF		C662502-0101 1385	MTH 13-Sep-1985		O/C			
243007	BATTERY	SRQ		7638-44 G03049978	MTH 15-Nov-2019 HRS 5509 LDG 3775		O/C	0 0 0		
243008	BATTERY TEMPERATURE MODULE	THV		1529-1 1400	MTH 23-Oct-1990 HRS 2466		O/C	0		
243009	BATTERY TEMPERATURE GAGE	*CF		1229-1 1257	MTH 13-Sep-1985		O/C			
243011	CURRENT VOLTAGE CONTROLLER	THV		1301-1 1430A	MTH 29-Oct-1990 HRS 2479		O/C	0		
243012	CURRENT SENSOR	ALN		1302-1 1277	MTH 17-Jan-1992 HRS 3050		O/C	0		
243013	BATT DISCONNECT K69 RELAY	*CF		A876K SN-UNKNOWN	MTH 13-Sep-1985		O/C			
243014 243010	BATTERY TEMPERATURE SENSOR	*CF		1166-1 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
243015 243010 : G	TEMPERATURE SENSOR GAGE	*CF		1166-1 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
245001 CENTER	5 VOLT LIGHT DIMMER	THV		1505-1 3300	MTH 30-Oct-1989 HRS 2009		O/C	0		
245001 LEFT	5 VOLT LIGHT DIMMER	HUR		273-1 0003085	MTH 27-Mar-2012 HRS 5412.1 LDG 3721		O/C			
245001 RIGHT	5 VOLT LIGHT DIMMER			273-1 2856	MTH 06-Oct-1994 HRS 3322		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
245002	BAROMETRIC PRESSURE SWITCH 9910095-6	HUR		GB300NA161 0701678	MTH 06-Aug-2007 HRS 5068		O/C	0		
245003 LEFT	START K7 RELAY	*CF		A703C SN-UNKNOWN	MTH 13-Sep-1985		O/C			
245003 RIGHT	START K8 RELAY	*CF		A703C SN-UNKNOWN	MTH 13-Sep-1985		O/C			
245004 LEFT	POWER K13 RELAY	*CF		A703P SN-UNKNOWN	MTH 13-Sep-1985		O/C			
245004 RIGHT	POWER K12 RELAY	*CF		A703P SN-UNKNOWN	MTH 13-Sep-1985		O/C			
252010	CLOCK/SIGN ASSEMBLY -- ICT			1207-0049 56754	MTH 10-Jul-1986 HRS 295		O/C	0		
256002	LOCATOR BEACON TRANSMITTER S3100-22			3000-1 319405	MTH 06-Oct-1994 HRS 3322		O/C	0		
256003	REPLACE LOCATOR BEACON TRANSMITTER BATTERY 2020BATTERY	SRQ		2020 SN-UNKNOWN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		24	0 0 0	01-Nov-2020	7 m 21 d
256004 LEFT	LOCATOR BEACON ANTENNA	HUR		ELT10-177-1 1249	MTH 06-Aug-2007 HRS 5068		O/C	0		
256004 RIGHT	LOCATOR BEACON ANTENNA	HUR		ELT10-177-2 1196	MTH 06-Aug-2007 HRS 5068		O/C	0		
261001 LEFT	ENGINE FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
261001 RIGHT	ENGINE FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
261002 LEFT	FIRE DETECTION CONTROL UNIT 9912036-2	*CF		377-02808 8509028	MTH 13-Sep-1985		O/C			
261002 RIGHT	FIRE DETECTION CONTROL UNIT 9912036-2	*CF		377-02808 8509036	MTH 13-Sep-1985		O/C			
262001 AFT	ENGINE FIRE EXTINGUISHER SRQ			9912048-3 14448C1	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		O/C			
262001 FORWARD	ENGINE FIRE EXTINGUISHER SRQ			9912048-3 16279C1	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		O/C			
262002 AFT	PORTABLE FIRE EXTINGUISHER SRQ			C352TS SN-UNKNOWN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		O/C	0 0 0		
262002 FORWARD	PORTABLE FIRE EXTINGUISHER SRQ			C352TS SN-UNKNOWN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		O/C	0 0 0		
262101 AFT LEFT	FIRE EXTINGUISHER CARTRIDGE SRQ			13083-5 42348	MTH 18-Nov-2019 HRS 5509 LDG 3775		72	0 0	31-Jul-2025	64 m 20 d
<i>262003 : AL</i>										
Manufacture Date: 22-Jul-2019										
262101 AFT RIGHT	FIRE EXTINGUISHER CARTRIDGE SRQ			13083-5 42356	MTH 18-Nov-2019 HRS 5509 LDG 3775		72	0 0	31-Jul-2025	64 m 20 d
<i>262003 : AR</i>										
Manufacture Date: 22-Jul-2019										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262101 FORWARD LEFT <i>262003 : FL</i> Manufacture Date: 22-Jul-2019	FIRE EXTINGUISHER CARTRIDGE SRQ	SRQ		13083-5 42370	MTH 18-Nov-2019 HRS 5509 LDG 3775		72	0 0	31-Jul-2025	64 m 20 d
262101 FORWARD RIGHT <i>262003 : FR</i> Manufacture Date: 22-Jul-2019	FIRE EXTINGUISHER CARTRIDGE SRQ	SRQ		13083-5 42374	MTH 18-Nov-2019 HRS 5509 LDG 3775		72	0 0	31-Jul-2025	64 m 20 d
271001	AILERON TRIM TAB ACTUATOR HUR	HUR		5565450-890 SN-UNKNOWN	MTH 23-Dec-1997 HRS 3896		O/C	0		
272001	RUDDER TRIM TAB ACTUATOR 5565450-71	*CF		5565450-71 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
273002	ELECTRIC ELEVATOR TRIM ACTUATOR DUB	DUB		44430-3357 T329A	MTH 20-Dec-1995 HRS 3508		O/C	0		
273003 LEFT	ELEVATOR TRIM TAB ACTUATOR ALN	ALN		5565450-79 SN-UNKNOWN	MTH 17-Jan-1992 HRS 3050		O/C	0		
273003 RIGHT	ELEVATOR TRIM TAB ACTUATOR 5565450-80	ALN		5565450-80 SN-UNKNOWN	MTH 17-Jan-1992 HRS 3050		O/C	0		
275003 LEFT	FLAP ACTUATOR 9912007-1	*CF		55800-1 292	MTH 13-Sep-1985		O/C			
275003 RIGHT	FLAP ACTUATOR 9912007-1	HUR		55800-1 483	MTH 06-Mar-1998 HRS 3971		O/C	0		
275004 LEFT WING LEFT INBOARD	-AFT FLAP ROLLER	HUR		CC50380 NSN	MTH 06-Aug-2007 HRS 5068 LDG 3507		5000	0	8507	4732
275004 LEFT WING LEFT OUTBOARD	-AFT FLAP ROLLER	HUR		CC50380 NSN	MTH 12-Oct-2009 HRS 5228 LDG 3619		5000	0 0	8619	4844
275004 LEFT WING RIGHT INBOARD	-AFT FLAP ROLLER			CC50380 SN-UNKNOWN	MTH 13-Sep-1985 HRS 75 LDG 0		5000	59	5000	1225
275004 LEFT WING RIGHT OUTBOARD	-AFT FLAP ROLLER			CC50380 SN-UNKNOWN	MTH 13-Sep-1985 HRS 75 LDG 0		5000	59	5000	1225
275004 RIGHT WING LEFT INBOARD	-AFT FLAP ROLLER			CC50380 SN-UNKNOWN	MTH 13-Sep-1985 HRS 75 LDG 0		5000	59	5000	1225
275004 RIGHT WING LEFT OUTBOARD	-AFT FLAP ROLLER	HUR		CC50380 NSN	MTH 06-Aug-2007 HRS 5068 LDG 3507		5000	0	8507	4732
275004 RIGHT WING RIGHT INBOARD	-AFT FLAP ROLLER	HUR		CC50380 NSN	MTH 06-Aug-2007 HRS 5068 LDG 3507		5000	0	8507	4732
275004 RIGHT WING RIGHT OUTBOARD	-AFT FLAP ROLLER			CC50380 SN-UNKNOWN	MTH 13-Sep-1985 HRS 75 LDG 0		5000	59	5000	1225
276001 LEFT	SPEED BRAKES ACTUATOR 6527550-1	*CF		50115-1 118	MTH 13-Sep-1985		O/C			
276001 RIGHT	SPEED BRAKES ACTUATOR 9912344-1	HUR		55850-1 1230	MTH 19-Oct-1999 HRS 4234		O/C	0		
282001 LEFT	MOTOR DRIVEN FUEL PUMP 9912017-2	ICT		1C7-12 1AA12	MTH 23-Oct-1985 HRS 13		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282001 RIGHT	MOTOR DRIVEN FUEL PUMP 9912017-2	*CF		1C7-12 7K162	MTH 13-Sep-1985		O/C			
284001 LEFT	LOW LEVEL FUEL SWITCH	HUR		L15M-3 6129	MTH 22-May-2001 HRS 4406		O/C	0		
284001 RIGHT	LOW LEVEL FUEL SWITCH	HUR		L15M-3 5907	MTH 22-May-2001 HRS 4406		O/C	0		
284002 LEFT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 15059	MTH 13-Sep-1985		O/C			
284002 RIGHT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 15079R	MTH 13-Sep-1985		O/C			
284007	FUEL QUANTITY INDICATOR 9912147-12	THV		VSDL-OC403D 73J	MTH 19-Jun-1987 HRS 748		O/C	0		
291001	HYDRAULIC RESERVOIR ASSEMBLY 9912052-12	THV		40500-7 26S	MTH 17-Jan-1991 HRS 2563		O/C	0		
291002 LEFT	ENGINE HYDRAULIC PUMP 9912062-3	*CF		4120-004000 66	MTH 13-Sep-1985		O/C			
291002 RIGHT	ENGINE HYDRAULIC PUMP 9912062-3	*CF		4120-004000 92	MTH 13-Sep-1985		O/C			
291005 LEFT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	*CF		3520020100-4 2042	MTH 13-Sep-1985		O/C			
291005 RIGHT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	THV		3520020100-4 2681	MTH 23-Jan-1991 HRS 2572		O/C	0		
291007 LEFT	HYDRAULIC FIREWALL SHUTOFF VALVE *CF			149145 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
291007 RIGHT	HYDRAULIC FIREWALL SHUTOFF VALVE *CF			149145 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
291012	HYDRAULIC BY-PASS VALVE - *CF			2710971 757	MTH 13-Sep-1985		O/C			
301001 AFT	ANTI-ICE PUMP	ALN		XA9511C010 A27387	MTH 02-Mar-1992 HRS 3053		O/C	0		
301001 FORWARD	ANTI-ICE PUMP	HUR		XA9511C005 D13586	MTH 22-May-2001 HRS 4406		O/C	464		
301002 LEFT	LOW PRESSURE SWITCH	THV		PO67B078 K10184	MTH 09-Jun-1988 HRS 1235		O/C	0		
301002 RIGHT	LOW PRESSURE SWITCH *CF			PO67B078 E5285	MTH 13-Sep-1985		O/C			
301003	ANTI-ICE TANK ASSY *CF			6514007-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
301004	ANTI-ICE FLUID INDICATOR *CF			19-435-02 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
301005 LEFT	SURF SOLENOID VALVE *CF			FV137 T56183	MTH 13-Sep-1985		O/C			
301005 RIGHT	SURF SOLENOID VALVE *CF			FV137 T12383	MTH 13-Sep-1985		O/C			
301005	SOLENOID VALVE *CF			FV137 T55183	MTH 13-Sep-1985		O/C			
301006 LEFT INBOARD	HORIZONTAL STABILIZER PANEL *CF			D3717 SN-UNKNOWN	MTH 13-Sep-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301006 LEFT OUTBOARD	HORIZONTAL STABILIZER PANEL *CF			D3715 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
301006 RIGHT INBOARD	HORIZONTAL STABILIZER PANEL *CF			D3718 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
301006 RIGHT OUTBOARD	HORIZONTAL STABILIZER PANEL *CF			D3716 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
301007 LEFT NO.1	WING PANEL *CF			D3709 851H9	MTH 13-Sep-1985		O/C			
301007 LEFT NO.2	WING PANEL *CF			D3731 851D7	MTH 13-Sep-1985		O/C			
301007 LEFT NO.3	WING PANEL *CF			D3729 851D5	MTH 13-Sep-1985		O/C			
301007 LEFT NO.4	WING PANEL *CF			D3703 851D3	MTH 13-Sep-1985		O/C			
301007 LEFT NO.5	WING PANEL *CF			D3701 851B1	MTH 13-Sep-1985		O/C			
301007 RIGHT NO.1	WING PANEL *CF			D3710 851S10	MTH 13-Sep-1985		O/C			
301007 RIGHT NO.2	WING PANEL *CF			D3732 851C8	MTH 13-Sep-1985		O/C			
301007 RIGHT NO.3	WING PANEL *CF			D3730 851E6	MTH 13-Sep-1985		O/C			
301007 RIGHT NO.4	WING PANEL *CF			D3704 851C4	MTH 13-Sep-1985		O/C			
301007 RIGHT NO.5	WING PANEL *CF			D3702 851C2	MTH 13-Sep-1985		O/C			
301008 LEFT	FAIRING PANEL *CF			D3714 85X14	MTH 13-Sep-1985		O/C			
301008 RIGHT	FAIRING PANEL *CF			D3713 85T13	MTH 13-Sep-1985		O/C			
301009 LEFT	SURF PROPORTIONER *CF			PU306DW38 B35985	MTH 13-Sep-1985		O/C			
301009 RIGHT	SURF PROPORTIONER *CF			PU306DW38 B1285	MTH 13-Sep-1985		O/C			
301010	ENGINE PROPORTIONER THV			PU306DC39 D24985	MTH 07-Jan-1986 HRS 40		O/C	0		
301011	HOR/STB PROPORTIONER *CF			PU306DT41 E21885	MTH 13-Sep-1985		O/C			
301012	ICE DETECTOR	HUR		0871DN1 0013	MTH 27-Mar-2012 HRS 5412.1 LDG 3721		O/C			
301013 <i>301016</i>	SURF PUMP CHECK VALVE *CF			FV121 A17385	MTH 13-Sep-1985		O/C			
301014 LEFT	FAIRING PANEL PRESSURE SWITCH THV			PO67L015 H2787	MTH 27-Sep-1989 HRS 1955		O/C	0		
301014 LEFT INBOARD	FAIRING PANEL PRESSURE SWITCH *CF			PO67L025 D13485	MTH 13-Sep-1985		O/C			
301014 RIGHT	FAIRING PANEL PRESSURE SWITCH THV			PO67L025 M9285	MTH 06-Feb-1986 HRS 65		O/C	0		
301014 RIGHT INBOARD	FAIRING PANEL PRESSURE SWITCH *CF			PO67L025 E1785	MTH 13-Sep-1985		O/C			
301016 LEFT	WING PANEL PRESSURE SWITCH *CF			PO67LC035 E15585	MTH 13-Sep-1985		O/C			
301016 RIGHT	WING PANEL PRESSURE SWITCH *CF			PO67LC035 E3485	MTH 13-Sep-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301017 LEFT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 D21985	MTH 13-Sep-1985		O/C			
301017 LEFT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 F4885	MTH 13-Sep-1985		O/C			
301017 RIGHT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 F3985	MTH 13-Sep-1985		O/C			
301017 RIGHT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 F2785	MTH 13-Sep-1985		O/C			
301018 <i>301015 : PUMP</i>	ENGINE PUMP CHECK VALVE *CF			FV147 J21484	MTH 13-Sep-1985		O/C			
301019 LEFT	SURF TEE CHECK VALVE *CF			FV147 D16085	MTH 13-Sep-1985		O/C			
301019 RIGHT	SURF TEE CHECK VALVE *CF			FV147 D16385	MTH 13-Sep-1985		O/C			
301020	SURF INBD CHECK VALVE *CF			FV147 D15385	MTH 13-Sep-1985		O/C			
301021	SURF TO ENGINE CHECK VALVE *CF			FV147 J22984	MTH 13-Sep-1985		O/C			
302003 LEFT	ENGINE BLEED AIR VALVE 9912402-16	HUR		1946-00-16 3894C	MTH 06-Aug-2007 HRS 5068		O/C	0		
302003 RIGHT	ENGINE BLEED AIR VALVE 9912086-3	*CF		229715 1109	MTH 13-Sep-1985		O/C			
302004 LEFT	ANTI ICE TEMP SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
302004 RIGHT	ANTI ICE TEMP SWITCH HUR			21548-2-19-6 SN-UNKNOWN	MTH 23-Dec-1997 HRS 3896		O/C	0		
303001 LEFT	PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
303001 RIGHT	PITOT TUBE HUR			PH502 SN-UNKNOWN	MTH 20-Dec-1996 HRS 3693		O/C	0		
303002 LEFT	PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
303002 RIGHT <i>303003 : RT</i>	CO-PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
303003 LEFT	CO-PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
303003 RIGHT <i>303002 : RB</i>	PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
304001	HOT AIR TEMPERATURE MONITOR- 5514120	*CF		1169-1 1411	MTH 13-Sep-1985		O/C			
304002	HEAT EXCHANGER 9912041-4	*CF		10663A 213	MTH 13-Sep-1985		O/C			
304004	ALCOHOL PUMP *CF			476411 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
304005	TEMPERATURE CONTROL VALVE 9912085-1	*CF		27241287 10M0109	MTH 13-Sep-1985		O/C			
304006	TEMPERATURE CONTROLLER 9912085-2	*CF		27231272 5AA26	MTH 13-Sep-1985		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
304009	WINDSHIELD BLEED AIR VALVE 9912086-4	HUR		67410-2 3123ABCDEGK	MTH 31-Jul-2009 HRS 5208		O/C	0		
312001 RIGHT	CLOCK	THV		811B 21008	MTH 06-May-1986 HRS 194		O/C	0		
312002 LEFT	CLOCK BATTERY	SRQ		811-BATT-1 NSN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		36	0 0 0	31-Dec-2021	21 m 20 d
312003 LEFT <i>312001 : L</i>	DIGITAL CLOCK	THV		811B24A 21520	MTH 18-Aug-1986 HRS 355		O/C	0		
312003 RIGHT	DIGITAL CLOCK	EGHH		811-BATT-1 SN-UNKNOWN	MTH 15-Oct-2010 HRS 5326 LDG 3671		O/C			
313001	FLIGHT HOURMETER 85071	5NN		C664503-0104 SN-UNKNOWN	MTH 20-Jan-1996 HRS 3517		O/C	0		
313003 RIGHT	ACCELEROMETER AG-222	ICT		7000992 4241	MTH 23-Oct-1985 HRS 13		O/C	0		
313003	ACCELEROMETER AG-222	THV		7000992 4973	MTH 10-Aug-1988 HRS 1337		O/C	0		
321001 LEFT	MAIN LANDING GEAR ASSY BOH			6641000-820 2	MTH 06-Oct-1994 HRS 3322 LDG 2533			25800 0	28333	24558
321002 RIGHT	MAIN LANDING GEAR ASSY 6641000	*CF		6641000-4 S0070	MTH 13-Sep-1985 LDG 0			25800 0	25800	22025
321003 LEFT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0	1793	21500	1793	21500	17725
321003 RIGHT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0	1793	21500	1793	21500	17725
322001	NOSE LANDING GEAR ASSY 6642000-2	*CF		6642000-2 S0076	MTH 13-Sep-1985 LDG 0		23900	0	23900	20125
322002	NOSE GEAR SHIMMY DAMPER THV			5543001-3 1317	MTH 18-Dec-1986 HRS 539 LDG 419		O/C	0		
322004	NOSE LANDING GEAR FORK *CF			5542300-2 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0		13800	0	13800	10025
322005	NOSE GEAR ACTUATOR FITTING *CF			5511169-1 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0		23900	0	23900	20125
322006 LEFT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	*CF		6613056-1 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0		11600	0	11600	7825
322006 RIGHT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	*CF		6613056-2 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0		11600	0	11600	7825
322007	NOSE GEAR TRUNNION *CF			5542301-9 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0		23900	0	23900	20125
322008	NOSE LANDING GEAR PISTON WELD ASSEMBLY *CF			6642100-2 SN-UNKNOWN	MTH 13-Sep-1985 LDG 0		13800	0	13800	10025
323001 LEFT MAIN LANDING GEAR	SIDE BRACE ACTUATOR 9912111-1	HUR		2-7442-3 DA1217	MTH 28-May-2008 HRS 5154 LDG 3558			25800 1851	27507	23732

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323002 RIGHT MAIN LANDING GEAR	SIDE BRACE ACTUATOR 9912111-4	HUR		1523100-8 572	MTH 12-Oct-2009 HRS 5228 LDG 3619		25800	2604	26815	23040
323003 NOSE LANDING GEAR	ACTUATOR 9912120-1	*CF		2-7406-2 702	MTH 13-Sep-1985 LDG 0		23900	0	23900	20125
323004 LEFT	LANDING GEAR UPLOCK ACTUATOR 5527500	HUR		5527504-2 WMP3307	MTH 27-May-2005 HRS 4985 LDG 3440		O/C	0		
323004 NOSE	LANDING GEAR UPLOCK ACTUATOR 5527500-2	*CF		5527504-2 588	MTH 13-Sep-1985		O/C			
323004 RIGHT	LANDING GEAR UPLOCK ACTUATOR 5517000	HUR		5527504-2 3559	MTH 06-Aug-2007 HRS 5068 LDG 3507		O/C	0		
323006	EMERGENCY GEAR AIR BOTTLE 9912103-3	SRQ		212940-2 3449	MTH 20-Dec-2018 HRS 5507.2 LDG 3773	-48	288		28-Feb-2026	71 m 17 d
Manufacture Date: 01-Feb-2006										
323007	GEAR CONTROL VALVE *CF			2710969 1386	MTH 13-Sep-1985		O/C			
323008	DUMP VALVE *CF			AS19400-1 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
323019	EMERGENCY AIR BOTTLE GAGE *CF			2341128 SN-UNKNOWN	MTH 13-Sep-1985		O/C	0		
324001 LEFT	MAIN WHEEL ASSEMBLY 9912222-2	HUR		40-202 484	MTH 27-Mar-2012 HRS 5412.1 LDG 3721		O/C			
324001 RIGHT	MAIN WHEEL ASSEMBLY 9912222-2	HUR		40-202 332	MTH 27-Mar-2012 HRS 5412.1 LDG 3721		O/C			
324002	NOSE WHEEL ASSEMBLY 5542103-2	HUR		9544207-7 10310	MTH 06-Aug-2007 HRS 5068 LDG 3507		O/C	0		
324003 LEFT	BRAKE ASSEMBLY HUR			30-161A 264	MTH 06-Feb-2008 HRS 5123 LDG 3545		O/C	0		
324004 RIGHT	BRAKE ASSEMBLY HUR			30-161A 431	MTH 23-Oct-2008 HRS 5173 LDG 3571		O/C	0		
324005 LEFT	MAIN TIRE SRQ			220K28-1 SN-UNKNOWN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		O/C	0 0 0		
324005 RIGHT	MAIN TIRE SRQ			220K28-1 SN-UNKNOWN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		O/C	0 0 0		
324006	NOSE TIRE 9914070-1	HUR		031-613-8 6026W00164	MTH 06-Aug-2007 HRS 5068 LDG 3507		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324011 LEFT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	*CF		12A085-11 2852	MTH 13-Sep-1985		O/C			
324011 RIGHT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	THU		12A085-11 2586	MTH 09-Jun-1986 HRS 241 LDG 189		O/C		0	
324012 LEFT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		12A085-12 2926	MTH 13-Sep-1985		O/C			
324012 RIGHT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	THV		12A085-12 916884	MTH 17-Jan-1989 HRS 1590 LDG 1246		O/C		0	
324014	EMERGENCY AIR BRAKE VALVE 9912105-1	*CF		53640 698A	MTH 13-Sep-1985		O/C			
324019	BRAKE PRESSURE PUMP ASSY 9912166-2	*CF		634343 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
324020	BRAKE CONTROL BOX 9912305-6	*CF		42-707-1 263	MTH 13-Sep-1985		O/C			
324021	POWER BRAKE ANTI-SKID VALVE 9912305-7	*CF		38-707-1 251	MTH 13-Sep-1985		O/C			
324023	ACCUMULATOR THV			57C57652 377	MTH 23-Jan-1991 HRS 2572		O/C		0	
324024 LEFT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 1568	MTH 13-Sep-1985		O/C			
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 1531	MTH 13-Sep-1985		O/C			
324025	PRESSURE SWITCH 9912163-1	*CF		1206P25 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
324026	POWER BRAKE ASSEMBLY MOTOR THU			30-2 1924	MTH 10-Jul-1991 HRS 2755		O/C		0	
324101	PARKING BRAKE VALVE *CF			AS20800-6 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
325001	BUNGEE ASSEMBLY 5565624-15	*CF		5565624-15 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
326002 LEFT	M/G UP & LOCKED SWITCH *CF			65430087 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
326002 RIGHT	M/G UP & LOCKED SWITCH *CF			65430087 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
326003 LEFT	M/G DOWN & LOCK SWITCH *CF			602EN16-6B SN-UNKNOWN	MTH 13-Sep-1985		O/C			
326003 RIGHT	M/G DOWN & LOCK SWITCH THV			602EN16-6B SN-UNKNOWN	MTH 08-Mar-1989 HRS 1670 LDG 1311		O/C		0	
326004	N/G DOWN & LOCK SWITCH THV			602EN16-6B SN-UNKNOWN	MTH 08-Oct-1987 HRS 941 LDG 742		O/C		0	
326005	N/G UP&LOCKED SWITCH *CF			CM3597-1 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
331001	ANNUNCIATOR PANEL -- 9912119-1	*CF		950D-0240-001 100	MTH 13-Sep-1985		O/C			
331011	EL PANEL-115V INVERTER *CF			EM2044-1 246	MTH 13-Sep-1985		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
332001 NO.2	INDIRECT LIGHTING POWER UNIT	HUR		AL5112 37010	MTH 13-Jul-2004 HRS 4886		O/C	0		
332002 AFT	INDIRECT LIGHTING INVERTER	THV		18.996 505	MTH 25-Sep-1987 HRS 914		O/C	0		
332002 FORWARD	INDIRECT LIGHTING INVERTER	HUR		18.994 4349	MTH 13-Jul-2004 HRS 4886		O/C	1765		
334002	VERT FIN ANTI-COLLISION LIGHT ASSEMBLY *CF			40-0100-21 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
334003 LEFT	STROBE LIGHT POWER SUPPLY 9910368-2	HUR		60-2799-1 APS14703	MTH 22-May-2001 HRS 4406		O/C	0		
334003 RIGHT	STROBE LIGHT POWER SUPPLY 9910368-2	HUR		60-2799-1 APS14686	MTH 22-May-2001 HRS 4406		O/C	0		
335001	EMERGENCY BATTERY PACK SRQ			41B020BA01301 NSN	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		O/C	0 0 0		
341001 LEFT	AIR SPEED INDICATOR AW2837AB05	HUR		C661063-0104 155ABC	MTH 06-Aug-2007 HRS 5068		O/C	0		
341001 RIGHT	AIR SPEED INDICATOR AW2837AB05	HUR		C661063-0104 221ABC	MTH 23-Dec-1997 HRS 3896		O/C	0		
341002 STANDBY	ALTIMETER	UNK		570-24929-013 W17858H	MTH 27-Nov-2018		O/C			
341004	OAT GAUGE 162BL507D	THV		C668510-0401 2108	MTH 15-Jul-1986 HRS 306		O/C	0		
341005	OVERSPEED WARNING SWITCH 9912076-12	HUR		D2RA45C-24 112	MTH 06-Aug-2007 HRS 5068		O/C	0		
341010	AOA INDICATOR	*CF		SLZ9987 CR1205C	MTH 13-Sep-1985		O/C			
341013	AOA TRANSMITTER	HVR		SLZ7306 LS1111A	MTH 22-May-2001 HRS 4406		O/C	5844		
341014	AOA TRANSMITTER INDEXER *CF			SLZ9374 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
341018	V NAV CONTROL DISPLAY VN-800	HUR		7000472-901 03021165	MTH 13-Jul-2004 HRS 4886		O/C	0		
341019 LEFT	ALTIMETER BA-141	*CF		4016341-905 85053095	MTH 13-Sep-1985		O/C			
341020	V-NAV COMPUTER CONTROL VN-212	*CF		4020571-904 85062045	MTH 13-Sep-1985		O/C			
342001	MAGNETIC COMPASS C2400-L4V2W-5B	HUR		C660501-0301 SN-UNKNOWN	MTH 03-Jun-2003 HRS 4696		O/C	0		
342002 -	TURN & BANK IND --	THV		PN SN-UNKNOWN	MTH 02-Jan-1990 HRS 2103		O/C	0		
342003 RIGHT	HORIZON GYRO 1U149-002-2	*CF		C661056-0202 T33911H	MTH 13-Sep-1985		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342021 LEFT	VERTICAL SPEED INDICATOR ALN			C661006-0101 W20285G	MTH 21-Feb-1990 HRS 2136		O/C	0		
342021 RIGHT	VERTICAL SPEED INDICATOR *CF			C661006-0101 W9686H	MTH 13-Sep-1985		O/C			
342041 RIGHT	FLIGHT DIRECTOR COMPUTER FZ-500	HUR		4018369-905 SN-UNKNOWN	MTH 23-Dec-1997 HRS 3896		O/C	0		
342041	FLIGHT DIRECTOR COMPUTER FZ-500	HUR		4018369-905 85064852	MTH 23-Dec-1997 HRS 3896		O/C	574		
342042 LEFT	AP/FD MODE SELECTOR MS-205	*CF		4020570-903 85041449	MTH 13-Sep-1985		O/C			
342042 RIGHT	AP/FD MODE SELECTOR MS-205	ICT		4020570-903 85031441	MTH 23-Oct-1985 HRS 13		O/C	0		
342043 LEFT	VERTICAL GYRO VG-14A	*CF		7000622-901 85035276	MTH 13-Sep-1985		O/C			
342043 RIGHT	VERTICAL GYRO VG-14A			7000622-901 85105487	MTH 02-Sep-1987 HRS 890		O/C	0		
342044 LEFT	RATE GYRO RG-204	*CF		7007453-903 85050336	MTH 13-Sep-1985		O/C			
342046 NO. 1 342048	AIR DATA COMPUTER AZ-252	UNK		7024900-30302 02060395	MTH 27-Nov-2018		O/C			
342047 LEFT	ADI INDICATOR AD-650	HUR		7000466-951 81010592	MTH 06-Mar-1998 HRS 3971		O/C	3958		
342047 RIGHT	ADI INDICATOR AD-650	HUR		7000466-951 85062442	MTH 06-Mar-1998 HRS 3971		O/C	3971		
342048 STANDBY	ADC/ALTIMETER --	HUR		70251N02D04 031112430	MTH 13-Jul-2004 HRS 4886		O/C	0		
342049 LEFT	DIR GYRO SYN COMPASS C-14D	HUR		4020577-3 5090110	MTH 06-Aug-2007 HRS 5068		O/C	1473		
342049 RIGHT	DIR GYRO SYN COMPASS C-14D	HUR		4020577-3 85023554	MTH 23-Dec-1997 HRS 3896		O/C	3896		
342050 LEFT	FLUX VALVE FX-220	HUR		2594484 02045208	MTH 03-Jun-2003 HRS 4696		O/C	140		
342050 RIGHT	FLUX VALVE FX-220	HUR		2594484 7034625	MTH 13-Jul-2001 HRS 4433		O/C	0		
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 85048036	MTH 13-Sep-1985		O/C			
342053 LEFT	HSI INDICATOR RD-650A	HUR		7000469-909 81030646	MTH 06-Aug-2007 HRS 5068		O/C	0		
342053 RIGHT	HSI INDICATOR RD-550A	BOH		7001179-901 80080146	MTH 09-Jun-1995 HRS 3436		O/C	3436		
342063 -	REMOTE HDG CONTROL -- ICT			4026206-924 85072767	MTH 23-Oct-1985 HRS 13		O/C	0		
342063	REMOTE HDG CONTROL RI-106	*CF		4026206-923 85032645	MTH 13-Sep-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342064	STANDBY GYRO POWER SUPPLY PS-835C	HUR		501-1228-03 80167	MTH 06-Aug-2007 HRS 5068		O/C	0		
342065	STAND-BY GYRO AI-804			501-1197-05 2519	MTH 06-Oct-1994 HRS 3322		O/C	0		
342072	JET STATIC CONVERTER *CF			501-1318-01 2069	MTH 13-Sep-1985		O/C			
344002	RADAR INDICATOR DI-2007	*CF		MI585277 3158	MTH 13-Sep-1985		O/C			
344004	RADAR RECEIVER/TRANSMITTER RT-3002	THV		MI585222-1 3270	MTH 14-Aug-1986 HRS 351		O/C	0		
344005	RADAR ANTENNA AP-3001	THV		MI585224-2 2936	MTH 16-Jun-1989 HRS 1840		O/C	0		
344021 LEFT	TAWS/RMI INDICATOR ST3400	HUR		ST3400-102 2454	MTH 27-May-2005 HRS 4985		O/C	0		
344021 RIGHT	TAWS/RMI INDICATOR RMI-30	THV		622-4938-004 5966	MTH 05-Oct-1991 HRS 2906		O/C	0		
344022	RADIO ALTIMETER TRANSCIEVER RT-300	THV		7001840-905 84051241	MTH 22-Nov-1989 HRS 2054		O/C	0		
344023 AFT	RADIO ALTM ANTENNA AT-224	*CF		4010504 28732	MTH 13-Sep-1985		O/C			
344023 FORWARD	RADIO ALTM ANTENNA AT-224	*CF		4010504 28904	MTH 13-Sep-1985		O/C			
344025	GPS RCVR/DSPY --	ALN		GPS-100 91600645	MTH 16-Jan-1992 HRS 3050		O/C	0		
345004 BOTTOM	ANT-TRANSPONDER --	HUR		DMNI50-2-2 90840	MTH 06-Aug-2007 HRS 5068		O/C	0		
345004 FORWARD BOTTOM	ANT-TRANSPONDER --	HUR		DMNI50-2-2 91191	MTH 06-Aug-2007 HRS 5068		O/C	0		
345004 LEFT	TRANSPONDER ANTENNA *CF			DMN150-2 28732	MTH 13-Sep-1985		O/C			
345004 RIGHT	TRANSPONDER ANTENNA *CF			DMN150-2 28904	MTH 13-Sep-1985		O/C			
345004 TOP	ANT-TRANSPONDER --	HUR		DMNI50-2-2 90886	MTH 06-Aug-2007 HRS 5068		O/C	0		
345004 TOP FORWARD	ANT-TRANSPONDER --	HUR		DMNI50-2-2 91054	MTH 06-Aug-2007 HRS 5068		O/C	0		
345007 LEFT	DME ANTENNA 85226	HUR		DMNI50-2-2 112397	MTH 06-Aug-2007 HRS 5068		O/C	0		
345007 RIGHT	DME ANTENNA	HUR		DMNI50-2-2 113071	MTH 06-Aug-2007 HRS 5068		O/C	0		
345010	NAV ANTENNA *CF			DMN4-17-1B 24417	MTH 13-Sep-1985		O/C			
345011 LEFT	ADF RECEIVER ADF-60A			622-2362-001 16716	MTH 06-Oct-1994 HRS 3322		O/C	1126		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345011 RIGHT	ADF RECEIVER ADF-60A	HUR		622-2362-001 16520	MTH 23-Dec-1997 HRS 3896		O/C	3880		
345012 RIGHT	ADF CONTROL	*CF		156 T2227B	MTH 13-Sep-1985		O/C			
345012	ADF CONTROL	ICT		156 T2247B	MTH 10-Jul-1986		O/C			
345014 LEFT	ADF LOOP ANTENNA APA-80	*CF		622-2363-001 17278	MTH 13-Sep-1985		O/C			
345014 RIGHT	ADF LOOP ANTENNA APA-80	HUR		622-2363-001 39117	MTH 23-Dec-1997 HRS 3896		O/C	0		
345017	MARKER BEACON ANTENNA *CF			16D00400-2 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
345018 RIGHT	ANTENNA-RNAV --	ICT		805C0520 870	MTH 23-Oct-1985 HRS 13		O/C	0		
345018	GLIDESCOPE ANTENNA *CF			RGS1048 9412	MTH 13-Sep-1985		O/C			
345019	RNAV CONTROL DISPLAY THV			805D0550-24 765	MTH 12-Aug-1991 HRS 2810		O/C	0		
345020	R-NAV RECIEVER	TOL		805D0500 645	MTH 01-Feb-1989 HRS 1613		O/C	0		
345022	RNAV ANTENNA	TOL		805C0565-01 582	MTH 01-Feb-1989 HRS 1613		O/C	0		
345023	R-NAV MODULE	TOL		805A0585 686B	MTH 01-Feb-1989 HRS 1613		O/C	0		
345024	PRE-AMP --	ICT		805D0530 832	MTH 23-Oct-1985 HRS 13		O/C	0		
345032 BOTTOM	NO.2 NAVIGATION TRANSCEIVER VIR-32	THV		622-6137-001 2739	MTH 09-May-1988 HRS 1214		O/C	0		
345032 TOP	NO.1 NAVIGATION TRANSCEIVER VIR-32	*CF		622-6137-001 2607	MTH 13-Sep-1985		O/C			
345034 LEFT	TRANSPONDER MST-67A	HUR		066-01143-2101 1283	MTH 06-Aug-2007 HRS 5068		O/C	4		
345034 RIGHT	TRANSPONDER MST-67A	HUR		066-01143-2101 1287	MTH 06-Aug-2007 HRS 5068		O/C	4		
345035 LEFT	DME INDICATOR 339F-12A	*CF		622-2012-201 4014	MTH 13-Sep-1985		O/C			
345035 RIGHT	DME INDICATOR 339F-12B	ICT		622-2175-201 2966	MTH 23-Oct-1985 HRS 13		O/C	0		
345036 LEFT	DME INTERROGATOR DME-42	*CF		622-6263-001 1305	MTH 13-Sep-1985		O/C			
345036 RIGHT	DME INTERROGATOR DME-42	ICT		622-6263-001 2293	MTH 23-Oct-1985 HRS 13		O/C	0		
345068	DATA-NAV BANK --	TOL		805D0570-01 101A	MTH 01-Feb-1989 HRS 1613		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345093	FDR ACCELEROMETER -- ALN			011-00013-00 5151	MTH 16-Jan-1992 HRS 3050		O/C	0		
346012 BOTTOM	TCAS ANTENNA	HUR		S72-1735-1 58313053	MTH 06-Aug-2007 HRS 5068		O/C	0		
346012 TOP	TCAS ANTENNA	HUR		S72-1735-1 12294	MTH 06-Aug-2007 HRS 5068		O/C	0		
347005 LEFT	TCAS/VSI INDICATOR IVSI-81D	HUR		066-01171-2804 23873	MTH 06-Aug-2007 HRS 5068		O/C	0		
347005 RIGHT	TCAS/VSI INDICATOR IVA-81D	HUR		066-01171-2804 23875	MTH 06-Aug-2007 HRS 5068		O/C	0		
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 6310	MTH 13-Sep-1985		O/C	0		
351004 LEFT	CREW OXYGEN MASK	HUR		174045-15 002928	MTH 06-Aug-2007 HRS 5068		O/C	0		
351004 RIGHT	CREW OXYGEN MASK	HUR		174045-15 6399	MTH 06-Aug-2007 HRS 5068		O/C	0		
351005	OXYGEN REGULATOR	HUR		172170-01 4292	MTH 06-Aug-2007 HRS 5068		O/C	0		
351006	OXYGEN CYLINDER ASSEMBLY ZC369-64	EGHH		176176-64 1096-615149	MTH 15-Oct-2010 HRS 5326 LDG 3671		288	0	31-Oct-2034	175 m 20 d
361003	PNEUMATIC REGULATOR 9912043-2	*CF		38E85-5C RF1372	MTH 13-Sep-1985		O/C			
361005 RIGHT	GYRO PRESSURE GAGE	*CF		C668515-0101 6470	MTH 13-Sep-1985		O/C			
361006 BOTTOM	FORWARD INST BA PRESS REGULATOR	*CF		3H64-4 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
361006 TOP	FORWARD INST BA PRESS REGULATOR	*CF		3H64-4 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
361007	PRESSURE DOOR SEAL HOSE *CF			CM2939-4-15 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
361008 LEFT	CHECK VALVE	THV		1H95-3 1M0014	MTH 06-Oct-1988 HRS 1446		O/C	0		
361008 RIGHT	CHECK VALVE	HUR		1H95-3 6BB11	MTH 06-Aug-2007 HRS 5068		O/C	0		
383002	TOILET PUMP	5NN		5725 SN-UNKNOWN	MTH 20-Jan-1996 HRS 3517		O/C	0		
521001	CABIN DOOR SEAL 9912075-3	THV		S15501 SN-UNKNOWN	MTH 19-Mar-1990 HRS 2161		O/C	0		
526001	CABIN DOOR STEP 6519009	*CF		6519009-44 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
561001 LEFT	MAIN WINDSHIELD ASSY, (LH) 9912064-15	HUR		E149000-101 SN-UNKNOWN	MTH 06-Aug-2007 HRS 5068		O/C	0		
561002 RIGHT	MAIN WINDSHIELD ASSY, (LH) 9912064-12	*CF		E149000-10 8	MTH 13-Sep-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561003	FOUL WEATHER WINDOW *CF			5511275-7 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
561005 LEFT INBOARD	FLIGHT COMPARTMENT WINDOW *CF			5511285-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
561005 LEFT OUTBOARD	FLIGHT COMPARTMENT WINDOW *CF			5511285-3 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
561005 RIGHT INBOARD	FLIGHT COMPARTMENT WINDOW *CF			5511285-6 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
561005 RIGHT OUTBOARD	FLIGHT COMPARTMENT WINDOW *CF			5511285-4 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 LEFT NO. 1	CABIN WINDOW *CF			5591005-6 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 LEFT NO. 2	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 LEFT NO. 3	CABIN WINDOW *CF			5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 LEFT NO. 4	CABIN WINDOW *CF			5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 LEFT NO. 5	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 LEFT NO. 6	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 RIGHT NO. 1	CABIN EMERGENCY DOOR WINDOW *CF			5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 RIGHT NO. 2	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 RIGHT NO. 3	CABIN WINDOW *CF			5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 RIGHT NO. 4	CABIN WINDOW *CF			5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 RIGHT NO. 5	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
562001 RIGHT NO. 6	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
712001 LEFT	AFT ENGINE ISOLATOR 9912172-7			LM420SA23 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		3500	0	6822	1313
712001 RIGHT	AFT ENGINE ISOLATOR 9912172-7			LM420SA23 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		3500	0	6822	1313
712002 LEFT BOTTOM	FWD ENGINE ISOLATOR 9912172-9			LM420SA31 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		3500	0	6822	1313
712002 LEFT TOP	FWD ENGINE ISOLATOR 9912172-8			LM420SA30 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		3500	0	6822	1313
712002 RIGHT BOTTOM	FWD ENGINE ISOLATOR 9912172-9			LM420SA31 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		3500	0	6822	1313
712002 RIGHT TOP	FWD ENGINE ISOLATOR 9912172-8			LM420SA30 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		3500	0	6822	1313
71EN1 NO. 1	ENGINE 3018700			JT15D-4B 102140	MTH 20-Jul-1994 HRS 3322		E/C	0		
<i>710001 : E1**L</i>										
71EN2 NO. 2	ENGINE 3018700			JT15D-4B 102146	MTH 20-Jul-1994 HRS 3322		E/C	0		
<i>710001 : E2**R</i>										
722001 E1	OIL PUMP			3030391 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		
722001 E2	OIL PUMP			3030391 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
723001 E1	ENGINE FAN --			3018020 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		
723001 E2	ENGINE FAN --			3018020 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		
723010 E1	CENTRIFUGAL IMPELLER			3033532 3C378	MTH 20-Jul-1994 HRS 3280 LDG 2533		8200	2509	(8224)8224	4449
723010 E2	CENTRIFUGAL IMPELLER			3033531 3C388	MTH 20-Jul-1994 HRS 3280 LDG 2533		8200	2509	(8224)8224	4449
723020 E1	LOW PRESSURE BOOST COMPRESSOR HUB			3021112 6P764	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
723020 E2	LOW PRESSURE BOOST COMPRESSOR HUB			3021112 6P784	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
723030 E1	LOW PRESSURE COMPRESSOR HUB			3018018 7P550	MTH 20-Jul-1994 HRS 3280 LDG 2533		13750	2509	(13774)13774	9999
723030 E2	LOW PRESSURE COMPRESSOR HUB			3018018 7P537	MTH 20-Jul-1994 HRS 3280 LDG 2533		13750	2509	(13774)13774	9999
725010 E1	HIGH PRESSURE TURBINE ROTOR DISK			3023411 5Y357	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
725010 E2	HIGH PRESSURE TURBINE ROTOR DISK			3023411 23A018	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
725020 E1	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK			3022212 7P380	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
725020 E2	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK			3022212 7P329	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
725030 E1	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK			3021213 7P740	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
725030 E2	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK			3021213 7P711	MTH 20-Jul-1994 HRS 3280 LDG 2533		14000	2509	(14024)14024	10249
725071 E1	COMBUSTION LINER			3105149-01 6C986	MTH 20-Jul-1994 HRS 3322		O/C	0		
725071 E2	COMBUSTION LINER			3105149-01 6C957	MTH 20-Jul-1994 HRS 3322		O/C	0		
731004 LEFT	LOW FUEL PRESSURE SWITCH 9912033-1 *CF			1103P92 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
731004 RIGHT	LOW FUEL PRESSURE SWITCH 9912033-1 *CF			1103P92 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
732002	ENGINE SYNC CONTROL 5560001 HUR			213787 13906574	MTH 27-May-2005 HRS 4985		O/C	0		
732003	ENGINE SYNC ACTUATOR *CF			5485-066 2000226	MTH 13-Sep-1985		O/C			
733002	FUEL FLOW INDICATOR 9912147-16 *CF			VSDL-OC208E 321	MTH 13-Sep-1985		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731010 E1	FUEL PUMP 3026909			025493-401-05 489	MTH 20-Jul-1994 HRS 3322		O/C	0		
731010 E2	FUEL PUMP 3026909			025493-401-05 473	MTH 20-Jul-1994 HRS 3322		O/C	0		
731020 E1	FUEL-OIL COOLER 3015303			UA530768-4 3237	MTH 20-Jul-1994 HRS 3322		O/C	0		
731020 E2	FUEL-OIL COOLER 3015303			UA530768-4 3260	MTH 20-Jul-1994 HRS 3322		O/C	0		
731030 E1	MOTIVE FLOW VALVE 3017930			2524995 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		
731030 E2	MOTIVE FLOW VALVE 3017930			2524995 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		
731040 E1	FLOW DIVIDER VALVE 3024476			25607-2 3184	MTH 20-Jul-1994 HRS 3322		O/C	0		
731040 E2	FLOW DIVIDER VALVE 3024476			25607-2 3227	MTH 20-Jul-1994 HRS 3322		O/C	0		
732004 E1	SOLENOID FUEL VALVE 3029591			3244758-1 A99211	MTH 20-Jul-1994 HRS 3322		O/C	0		
732004 E2	SOLENOID FUEL VALVE 3029591			3244758-1 A99219	MTH 20-Jul-1994 HRS 3322		O/C	0		
732010 E1	FUEL CONTROL UNIT 3030251			3244759-3 A92485	MTH 20-Jul-1994 HRS 3322		O/C	0		
732010 E2	FUEL CONTROL UNIT 3030251			3244759-3 A92106	MTH 20-Jul-1994 HRS 3322		O/C	0		
733010 E1	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 1520B	MTH 11-Jan-1991 HRS 2562		O/C	0	0	
733010 E2	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 1192B	MTH 11-Jan-1991 HRS 2562		O/C	0	0	
741010 E1 LOWER	IGNITION EXCITER			NB01201 K3733	MTH 20-Jul-1994 HRS 3322		O/C	0		
741010 E2 LOWER	IGNITION EXCITER			NB01201 K3722	MTH 20-Jul-1994 HRS 3322		O/C	0		
741015 E1 UPPER	IGNITION EXCITER 3033378			NB01201 K3736	MTH 20-Jul-1994 HRS 3322		O/C	0		
741015 E2 UPPER	IGNITION EXCITER 3033378			NB01201 K3734	MTH 20-Jul-1994 HRS 3322		O/C	0		
742010 E1 OUTBOARD	IGNITER PLUG	HUR		FHE-246-4 NSN	MTH 12-Oct-2009 HRS 5228		O/C	0		
742010 E2 OUTBOARD	IGNITER PLUG	HUR		FHE-246-4 NSN	MTH 12-Oct-2009 HRS 5228		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
742020 E1 INBOARD	IGNITER PLUG 3030595	HUR		FHE-246-4 NSN	MTH 12-Oct-2009 HRS 5228		O/C	0		
742020 E2 INBOARD	IGNITER PLUG 3030595	HUR		FHE-246-4 NSN	MTH 12-Oct-2009 HRS 5228		O/C	0		
742030 E1 SHORT	IGNITER LEAD	HUR		53067-21 NSN	MTH 06-Aug-2007 HRS 5068		O/C	0		
742030 E2 SHORT	IGNITER LEAD 3027939			10-395428-1 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		
742040 E1 LONG	IGNITER LEAD			3107371-02 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C	0		
742040 E2 LONG	IGNITER LEAD	HUR		53067-38.5 SN-UNKNOWN	MTH 22-May-2001 HRS 4406		O/C	0		
750010 E1	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531			KW15632 3487	MTH 20-Jul-1994 HRS 3322		O/C	0		
750010 E2	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531			KW15632 3493	MTH 20-Jul-1994 HRS 3322		O/C	0		
761005	SOLENOID ASSEMBLY 9912110-1	*CF		U-183238-001 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
771001 LEFT BOTTOM	TACH N2 GENERATOR 9912034-1	*CF		22A623 7211	MTH 13-Sep-1985		O/C			
771001 LEFT TOP	TACH N1 GENERATOR 9912034-1	DUB		22A623 101	MTH 30-Apr-2013 HRS 5479.8 LDG 3759		O/C	0 0		
771001 RIGHT BOTTOM	TACH N2 GENERATOR 9912034-1	*CF		22A623 7238	MTH 13-Sep-1985		O/C			
771001 RIGHT TOP	TACH N1 GENERATOR 9912034-1	*CF		22A623 6978	MTH 13-Sep-1985		O/C			
771002	N2 TURBINE RPM INDICATOR 9912147-25	DUB		DDL-OC110A 153ABC	MTH 03-Sep-2010 HRS 5326 LDG 3671		O/C			
771003	N1 FAN RPM INDICATOR 9912147-24	HUR		VSDL-OC410AD 221EBA	MTH 06-Aug-2007 HRS 5068 LDG 3507		O/C	0 0 0		
772003 772001	ITT INDICATOR 9912147-34	*CF		VSDL-OC419L 18301	MTH 13-Sep-1985		O/C			
781001 LEFT	EXHAUST NOZZLE CONE *CF			9912110-7-S7 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
781001 RIGHT	EXHAUST NOZZLE CONE *CF			9912110-7-S7 SN-UNKNOWN	MTH 13-Sep-1985		O/C			
783001 LEFT	THRUST REVERSER ASSEMBLY 9912110-1	*CF		202-0000-1 RC1630	MTH 13-Sep-1985		O/C			
783001 RIGHT	THRUST REVERSER ASSEMBLY 9912110-1	*CF		202-0000-3 RC1631	MTH 13-Sep-1985		O/C			
783002 LEFT	CONTROL VALVE *CF			65680 846	MTH 13-Sep-1985		O/C			
783002 RIGHT	CONTROL VALVE *CF			65680 839	MTH 13-Sep-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
783003 LEFT	THREE WAY VALVE *CF			13027-4 1575	MTH 13-Sep-1985		O/C			
783003 RIGHT	THREE WAY VALVE *CF			13027-4 1577	MTH 13-Sep-1985		O/C			
783005 LEFT	THRUST REVERSER DOOR 9912110-1 *CF			202-0001-501 RC1630	MTH 13-Sep-1985		O/C			
783005 RIGHT	THRUST REVERSER DOOR 9912110-1 *CF			202-0001-502 RC1631	MTH 13-Sep-1985		O/C			
783006 LEFT	THRUST REVERSER DOOR 9912110-1 *CF			202-0002-501 RC1630	MTH 13-Sep-1985		O/C			
783006 RIGHT	THRUST REVERSER DOOR 9912110-1 *CF			202-0002-502 RC1631	MTH 13-Sep-1985		O/C			
783007 LEFT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-1 RC1630	MTH 13-Sep-1985		O/C			
783007 RIGHT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-1 RC1631	MTH 13-Sep-1985		O/C			
783008 LEFT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-3 RC1630	MTH 13-Sep-1985		O/C			
783008 RIGHT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-5 RC1631	MTH 13-Sep-1985		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT 9912110-1 *CF			202-0012-1 RC1630	MTH 13-Sep-1985		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT 9912110-1 *CF			202-0012-1 RC1631	MTH 13-Sep-1985		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1701	MTH 13-Sep-1985		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1727	MTH 13-Sep-1985		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1736	MTH 13-Sep-1985		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1718	MTH 13-Sep-1985		O/C			
793001	OIL TEMPERATURE INDICATOR 9912147-11 HUR			VSDL-OC219F 269FA	MTH 22-May-2001 HRS 4406		O/C		0	
793002 LEFT	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 71482	MTH 13-Sep-1985		O/C			
793002 RIGHT	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 70966	MTH 13-Sep-1985		O/C			
793003	OIL PRESSURE INDICATOR 9912147-10 *CF			VSDL-OC204H 245A	MTH 13-Sep-1985		O/C			
793004 LEFT	OIL PRESSURE TRANSMITTER 9912164-1 THV			123479 38211	MTH 12-Jan-1989 HRS 1587		O/C		0	
793004 RIGHT	OIL PRESSURE TRANSMITTER 9912164-1 THV			123479 38412	MTH 28-Apr-1986 HRS 179		O/C		0	
792003 E1	OIL FILTER			3015330 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C		0	
792003 E2	OIL FILTER			3015330 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C		0	
832001 E1	MAIN GEAR BOX ASSY --			3018390 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C		0	
832001 E2	MAIN GEAR BOX ASSY --			3018390 SN-UNKNOWN	MTH 20-Jul-1994 HRS 3322		O/C		0	



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)		INFORMATIONAL			-			
	MOC :								
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)		RECOMMENDED			-			
	MOC :								
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)		RECOMMENDED MTH			-			
	MOC :								
SL S550-03-02 R01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)		INFORMATIONAL			-			
	MOC :								
SL S550-99-04 R07	CESCOM PRICES (THIS SL IS CANCELS SLS550-99-04 R6 AND PREVIOUS)		INFORMATIONAL			-			
	MOC :								
SL S550-99-07	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS		INFORMATIONAL			A/R			
	MOC :								
SL S550-99-08	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION		INFORMATIONAL			A/R			
	MOC :								
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW		INFORMATIONAL			-			
	MOC :								
SB S550-11-01 <i>11SB-01</i>	GROSS WEIGHT INCREASE (SUPERSEDED BY S550-11-01 R01)	THU	RECOMMENDED	MTH 30-May-1986 HRS 234		A/R			Complete
	MOC : COMPLIED WITH								
SB S550-11-03 <i>11SB-03</i>	SEAT PLACARD INSTALLATIONS AND EMERGENCY EXIT HANDLE GUARD DECAL REPLACEMENT (SUPERSEDED BY S550-11-03 R01)	THV	MANDATORY	MTH 22-Jul-1987 HRS 804		A/R			Complete
	MOC : COMPLIED WITH								
SB S550-11-04 <i>11SB-04</i>	AIRSPPEED LIMITATIONS PLACARD REPLACEMENT	THV	MANDATORY	MTH 11-Aug-1988 HRS 1342		A/R			Complete
	MOC : COMPLIED WITH								
SB S550-11-05 <i>11SB-05</i>	FLAP NO STEP PLACARD INSTALLATION	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
	MOC : COMPLIED WITH								
SB S550-11-06 <i>11SB-06</i>	FIRE EXTINGUISHER PLACARD INSTALLATION		OPTIONAL	MTH		A/R			
	MOC :								
SL S550-11-01 <i>11SL-01</i>	DATA PLATE RELOCATION		OPTIONAL	MTH		A/R			
	MOC :								
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)		INFORMATIONAL			-			
	MOC :								
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS		INFORMATIONAL			-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	MOC :									
SL S550-20-01 R27	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SLS550-20-01 R28)			INFORMATIONAL			A/R			
	MOC :									
SL S550-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
	MOC :									
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
	MOC :			NOT APPLICABLE - NO FREON AIR INSTALLED						
SL CIL-21-02	ENVIRONMENTAL HOUR METER INSTALLATION (SUPERSEDED BY CIL-21-02 R01)			OPTIONAL			-			
	MOC :									
SB S550-21-03 R01	FREON AIR CONDITIONING SYSTEM INSTALLATION - CANCELLED			CANCELLED	MTH		A/R			
<i>21SB-03 : S55R1</i>										
	MOC :									
SB S550-21-05	SUPPLEMENTAL COCKPIT AIR DISTRIBUTION SYSTEM			OPTIONAL	MTH		A/R			
<i>21SB-05</i>										
	MOC :			- OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME						
SB S550-21-08	TAILCONE RAM AIR INLET PRESSURIZATION VALVE INSTALLATION	TOL		OPTIONAL	MTH 01-Feb-1989 HRS 1613		A/R			Complete
<i>21SB-08</i>										
	MOC :			COMPLIED WITH						
SB S550-21-09 R02	TAILCONE FRESH AIR DUCT MODIFICATION (SUPERSEDED BY S550-21-09 R03)	ALN		OPTIONAL	MTH 21-Feb-1990 HRS 2136		A/R			Complete
<i>21SB-09 : S55R2</i>										
	MOC :			COMPLIED WITH						
SB S550-21-10	AIR DUCT RETENTION IMPROVEMENT (SUPERSEDED BY S550-21-10 R01)	THV		RECOMMENDED	MTH 16-Oct-1991 HRS 2923		A/R			Complete
<i>21SB-10</i>										
	MOC :			COMPLIED WITH						



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-21-11 <i>21SB-11</i>	ACM BLEED AIR DUCT SUPPORT CLAMP INSTALLATION	THV		MTH HRS OPTIONAL	07-Mar-1991 2613		A/R			Complete
MOC : COMPLIED WITH										
SB S550-21-12 <i>21SB-12</i>	TAILCONE PRESSURE VALVE ACTUATOR WIRING MODIFICATION			OPTIONAL MTH			A/R			
MOC :										
SB S550-21-13	OUTFLOW VALVE REPLACEMENT	EGHH		MANDATORY MTH HRS LDG	01-Nov-2011 5411 3720		A/R			N/A
MOC : NOT APPLICABLE - SBS550-21-13 N/A - ORIGINAL OUTFLOW VALVES STILL FITTED.										
SB S550-21-14 <i>21SB-14</i>	ADDITIONAL OUTFLOW VALVE REPLACEMENTS	DUB		MANDATORY MTH HRS	25-Oct-1995 3495		A/R			Complete
MOC : COMPLIED WITH										
SB S550-21-15 <i>21SB-15</i>	AIR CONDITIONING - COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION			OPTIONAL MTH			A/R			
MOC :										
SB S550-21-16 <i>21SB-16</i>	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT			DISCRETIONARY MTH			A/R			
MOC :										
SB S550-21-17	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL			A/R			
MOC :										
SL S550-21-02 <i>21SL-02</i>	TAILCONE FRESH AIR DUCT ROUTING INSPECTION	THV		RECOMMENDED MTH HRS	16-Oct-1991 2923		A/R			Complete
MOC : COMPLIED WITH										
SL S550-21-05 <i>21SL-05</i>	AIR CONDITIONING - TRANSMITTAL OF FORT WORTH AIRWORKS, INC. SERVICE BULLETIN 99-101, EVAPORATOR MODULE INSTALLATION 1250240 AND 1134240 SERIES.	HYR		RECOMMENDED MTH HRS	22-May-2001 4406		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SB S550-23-05 R03 <i>23SB-05 : S55R3</i>	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS	HUR		RECOMMENDED MTH			A/R			
MOC :										
SB S550-23-07 <i>23SB-07</i>	STATIC WICK REPLACEMENT	*CF		OPTIONAL MTH			A/R			
MOC :										
SB S550-23-08 R01 <i>23SB-08 : S55R1</i>	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION			OPTIONAL MTH			A/R			
MOC :										
SB S550-23-09 <i>23SB-09</i>	VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT (SUPERSEDED BY S550-23-09 R01)	HVR		MANDATORY MTH HRS	22-May-2001 4406		A/R			Complete
MOC : COMPLIED WITH										
SL S550-23-01 <i>23SL-01</i>	MICROPHONE REPLACEMENT PROGRAM	THV		RECOMMENDED MTH HRS	28-Oct-1988 1495		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-23-02 23SL-02	STATIC DISCHARGE WICK MODIFICATION	THU		OPTIONAL	MTH 17-Jul-1989 HRS 1867		A/R			Complete
MOC : COMPLIED WITH										
SL S550-23-14 23SL-14	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE			RECOMMENDED	MTH		A/R			
MOC :										
SB S550-24-04 24SB-04	LEFT CIRCUIT BREAKER PANEL BUSSING MODIFICATION (SUPERSEDED BY S550-24-04 R01)	ICT		MANDATORY	MTH 10-Jul-1986 HRS 295		A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-06 24SB-06	TKS FLUID PUMP SEPARATE CIRCUIT BREAKER INSTALLATION (SUPERSEDED BY S550-24-06 R01)	TOL		OPTIONAL	MTH 15-Jul-1987 HRS 796		A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-07 R01 24SB-07 : S55R1	CIRCUIT BREAKER PANEL SUPPORT BRACKET AND COVER REPLACEMENT	TOL		MANDATORY	MTH 15-Jul-1987 HRS 796		A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-08 24SB-08	LH AND RH PITOT STATIC CIRCUIT BREAKER REPLACEMENT AND CABIN FAN POWER BUS BAR CHANGE	TOL		MANDATORY	MTH 22-Jan-1987 HRS 563		A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-11 24SB-11	RIGHT PYLON WIRE BUNDLE PROTECTION	ALN		MANDATORY	MTH 21-Feb-1990 HRS 2136		A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-12 24SB-12	CONTROL WHEEL ELECTRICAL CABLE REPLACEMENT (SUPERSEDED BY S550-24-12 R01)			OPTIONAL	MTH		A/R			
MOC :										
SB S550-24-14 R01 24SB-14 : S55R1	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION	HUR		RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-14 24SB-14	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION (SUPERSEDED BY S550-24-14 R01)	ALN		RECOMMENDED	MTH 17-Jan-1992 HRS 3050		A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-15 24SB-15	WING WIRE BUNDLE ROUTING MODIFICATION	HUR		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-24-17 24SB-17	AVIONICS POWER RELAYS REPLACEMENT	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB S550-24-18 24SB-18	WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	HUR		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-24-19 R01 24SB-19 : S55R1	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION W.S. 44.0 AND W.S. 54.07	HUR		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-24-21 R01 24SB-21 : S55R1	OVERVOLTAGE MONITOR SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-24-22 24SB-22	BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-24-23 R01 24SB-23 : S55R1	MAIN POWER WIRE ANCHOR IMPROVEMENT			RECOMMENDED	MTH		A/R			
MOC :										
SB S550-24-24	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER REPLACEMENT			OPTIONAL			A/R			
MOC :										
SL S550-24-01 R01 24SL-01 : S55R1	TAILCONE WIRE BUNDLE REROUTING AND CLAMPING	POU		RECOMMENDED	MTH HRS 1213	04-May-1988	A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-24-02A R01	PILOT ADVISORY, AC POWER INVERTER FAILURES	HUR		MANDATORY	MTH HRS 5412.1 LDG 3721	27-Mar-2012	A/R			N/A
MOC : NOT APPLICABLE - ASL S550-24-02 PILOT ADVISORY AC POWER INVERTER FAILURES N/A BY EQUIPMENT FITTED.										
SL S550-24-04	KGS SPC38B INVERTER UPDATE	HUR		MANDATORY	MTH HRS 5412.1 LDG 3721	27-Mar-2012	A/R			N/A
MOC : NOT APPLICABLE - ASL S550-24-02 PILOT ADVISORY AC POWER INVERTER FAILURES N/A BY EQUIPMENT FITTED.										
SL S550-24-06 24SL-06	500 HOUR MID-LIFE BEARING CHANGE FOR 9912125-1 (23085-004 AND 23085-004 MOD A) STARTER GENERATORS	THV		RECOMMENDED	MTH HRS 1967	11-Oct-1989	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-07 24SL-07	COCKPIT CIRCUIT BREAKER INSPECTION/REPLACEMENT	THV		RECOMMENDED	MTH HRS 2334	13-Aug-1990	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-08 24SL-08	DELETE THE 500 HOUR MID-LIFE BEARING CHANGE REQUIREMENT FOR THE 9912125-1 (23085-004 MOD A) STARTER/GENERATOR	THV		RECOMMENDED	MTH HRS 2923	16-Oct-1991	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-10 24SL-10	ANTI-ICE RELAY BASE ORIENTATION INSPECTION/MODIFICATION (SUPERSEDED BY SLS550-24-10 R01)	ALN		RECOMMENDED	MTH HRS 3050	17-Jan-1992	A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-08 25SB-08	CABIN DISPLAY UNIT REPLACEMENT AND SIGN INSTALLATION	ICT		MANDATORY	MTH HRS 295	10-Jul-1986	A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-25-09 25SB-09	CREW SEAT BACK MODIFICATION THU			OPTIONAL MTH	30-Jun-1989 HRS 1856		A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-10 25SB-10	THREE BOOK JEPP CASE INSTALLATION			OPTIONAL MTH			A/R			
MOC :										
SB S550-25-11 25SB-11	LOCATOR BEACON RESET CIRCUIT VOLTAGE LIMIT RESISTOR REMOVAL ICT			MANDATORY MTH	10-Jul-1986 HRS 295		A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-12 25SB-12	TAILCONE ACCESS DOOR STRAP INSTALLATION THV			OPTIONAL MTH	19-Sep-1986 HRS 405		A/R			Complete
MOC : COMPLIED WITH										
ASB S550-25-16A 25SBA16	INTERIOR CABINETRY ELECTRICAL POWER SOURCE DISABLEMENT POU			MANDATORY MTH	03-Apr-1987 HRS 629		A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-18 25SB-18	PASSENGER SEAT ARMREST RELEASE LEVER REPLACEMENT			OPTIONAL MTH			A/R			
MOC :										
SB S550-25-20 25SB-20	FORWARD REFRESHMENT CENTER OVERBOARD DRAIN RELOCATION (SUPERSEDED BY S550-25-20 R01) TOL			RECOMMENDED MTH	11-Jan-1991 HRS 2562		A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-21 25SB-21	CREW SEAT PAN REPLACEMENT			OPTIONAL MTH			A/R			
MOC :										
SB S550-25-29 R02 25SB-29 : S55R2	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY S550-25-29 R03)			OPTIONAL			A/R			
MOC : - SERVICE BULLETIN ON HOLD.										
SB S550-25-29 R03 25SB-29 : S55R2	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			A/R			
MOC :										
SB S550-25-30 R01 25SB-30 : S55R1	GLAESHIELD LEATHER STRIP INSTALLATION			OPTIONAL MTH			A/R			
MOC :										
SL S550-25-02 R03 25SL-02 : S55R3	INTERIOR CABINETRY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION (SUPERSEDED BY SLS550-25-02 R04) THV			MANDATORY MTH	18-Feb-1987 HRS 589		A/R			Complete
MOC : COMPLIED WITH										
SL S550-25-02 R04 25SL-02 : S55R4	INTERIOR CABINETRY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION THV			MANDATORY MTH	12-Dec-1988 HRS 1549		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-25-03A	INTERIOR CABINETRY WIRING TO ACCESSORY HEATERS EGHH			MANDATORY MTH	01-Nov-2011 HRS 5411 LDG 3720		A/R			N/A
MOC : NOT APPLICABLE - ASLS550-25-03 N/A - SLS550-25-02 R4 COMPLIED WITH.										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-25-04 25SL-04	SWITLIK INFLATABLE LIFE PRESERVER INSPECTION	THV		MTH HRS	25-Apr-1988 1201		A/R			Complete
MOC : COMPLIED WITH										
SL S550-25-07 25SL-07	TRANSMITTAL OF EASTERN AERO MARINE SERVICE BULLETIN SBV-25-2, EQUIPMENT/FURNISHINGS - LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT OF CO2 INFLATOR - MANDATORY	HUR		MANDATORY MTH HRS	23-Dec-1997 3896		A/R			Complete
MOC : COMPLIED WITH										
SL S550-25-08 25SL-08	EQUIPMENT/FURNISHINGS - GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT	HYR		RECOMMENDED MTH HRS	22-May-2001 4406		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	SRQ		MANDATORY MTH HRS LDG	20-Dec-2018 5507.2 3773		-			Complete
MOC : COMPLIED WITH - FIRE BOTTLE CARTRIDGE GROUND STUD										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)			MANDATORY MTH			-			
MOC :										
SB S550-26-02 26SB-02	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	HUR		MANDATORY MTH HRS	27-May-2005 4985		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-26-01A 26ASL01	TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 -THERMISTORS DETECTORS	HUR		MANDATORY MTH HRS	06-Aug-2007 5068		A/R			Complete
MOC : COMPLIED WITH										
SB S550-27-05 27SB-05	RUDDER TRIM WHEEL BEARING INSPECTION/REPLACEMENT (SUPERSEDED BY S550-27-05 R01)	THV		RECOMMENDED MTH HRS	13-Aug-1990 2334		A/R			Complete
MOC : COMPLIED WITH										
SB S550-27-06 27SB-06	EXTENDED PEDESTAL AILERON PULLEY BRACKET MODIFICATION (SUPERSEDED BY S550-27-06 R01)	HUR		RECOMMENDED MTH			A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-27-07 R01 27SB-07 : S55R1	AILERON CONTROL QUADRANT BOLT INSPECTION/REPLACEMENT (SUPERSEDED BY S550-27-07 R02)	BON		MANDATORY MTH HRS	13-Jan-1993 3172		A/R			Complete
MOC : COMPLIED WITH										
SB S550-27-08 27SB-08	AILERON/RUDDER INTERCONNECT CLAMP MODIFICATION	HUR		RECOMMENDED MTH HRS	22-May-2001 4406		A/R			Complete
MOC : COMPLIED WITH										
SB S550-27-09 27SB-09	FLIGHT CONTROLS - TRIM TAB ACTUATOR GREASE FITTING INSTALLATION			OPTIONAL MTH			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-27-01 27SL-01	ELEVATOR CONTROL PUSH ROD ASSEMBLY INSPECTION/RIVET REPLACEMENT	POU		RECOMMENDED	MTH 03-Apr-1987 HRS 629		A/R			Complete
MOC : COMPLIED WITH										
SL S550-27-05 27SL-05	FLAP/ELEVATOR TRIM MIXER ACTUATOR ASSEMBLY INSPECTION/REPLACEMENT	HYR		RECOMMENDED	MTH 22-May-2001 HRS 4406		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL S550-27-07 R01 27SL-07 : S55R1	RUDDER/AILERON INTERCONNECT BOLT INSPECTION	HUR		MANDATORY	MTH 19-Feb-1999 HRS 4114		A/R			Complete
MOC : COMPLIED WITH										
SL S550-27-07 27SL-07	RUDDER/AILERON INTERCONNECT BOLT INSPECTION (SUPERSEDED BY SLS550-27-07 R01)	HUR		SUPERSEDED	MTH 19-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH										
SL S550-27-08 27SL-08	RUDDER PEDAL SUPPORT INSPECTION	HUR		RECOMMENDED	MTH 12-Oct-2009 HRS 5228		A/R			Complete
MOC : COMPLIED WITH										
SB S550-28-03 28SB-03	WING LEADING EDGE RIB FLAPPER VALVES INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB S550-28-04 28SB-04	MOTIVE FLOW FUEL LINE INSPECTION AND SUPPORT INSTALLATION	HUR		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-28-05 28SB-05	FUEL SYSTEM PLUMBING CLAMP ADDITIONS	HUR		RECOMMENDED	MTH HRS		150			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-28-06 28SB-06	IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY			OPTIONAL	MTH		A/R			
MOC :										
SB S550-28-07 28SB-07	FUEL LINE SUPPORT INSTALLATION			RECOMMENDED	MTH		A/R			
MOC :										
SB S550-28-08 28SB-08	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	HUR		MANDATORY	MTH 13-Jul-2004 HRS 4886		A/R			Complete
MOC : COMPLIED WITH										
SB S550-28-09 R01 28SB-09	FUEL - FUEL CHECK VALVE MODIFICATION			RECOMMENDED			A/R			
MOC :										
SB S550-28-09 28SB-09	FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY S550-28-09 R01)			RECOMMENDED	MTH	3	A/R			
OPERATOR CHOOSES TO PERFORM AT NEXT PHASE 5.										
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-28-01 R03 28SL-01 : S55R3	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SL S550-28-01 28SL-01	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION (SUPERSEDED BY SLS550-28-01 R01)	ALN	RECOMMENDED	MTH 17-Jan-1992 HRS 3050		A/R			Complete
MOC : COMPLIED WITH									
ASL SLS550-28-03A 28SLA03	TRANSMITTAL OF PARKER HANNIFIN CORPORATION -AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS (SUPERSEDED BY SLS550-28-03A R01)	HUR	MANDATORY	MTH 20-Dec-1996 HRS 3693		A/R			Complete
MOC : COMPLIED WITH									
SB S550-29-01 29SB-01	ECOLOGY (OVERFLOW) BOTTLE INSTALLATION		OPTIONAL	MTH		A/R			
MOC :									
SL S550-29-02 29SL-02	HYDRAULIC LINE INSPECTION (SUPERSEDED BY SLS550-29-02 R01)	THV	RECOMMENDED	MTH 19-Jun-1990 HRS 2260		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-			
MOC :									
ASL S550-30-05 R02 30SLA05 : S55R2	TKS ANTI-ICE SYSTEM PROPORTIONING UNIT CONNECTIONS	THV	MANDATORY	MTH 28-Jan-1986 HRS 62		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-11 30SB-11	ICE DETECTOR REPLACEMENT (SUPERSEDED BY S550-30-11 R01)	TOL	RECOMMENDED	MTH 01-Feb-1989 HRS 1613		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-13 30SB-13	WING WIRE BUNDLE ROUTING MODIFICATION	THV	RECOMMENDED	MTH 12-Dec-1990 HRS 2538		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-14 30SB-14	FLUID ANTI-ICE SYSTEM WING CUFF AND FAIRING PANELS INSPECTION AND PURGE CYCLE MODIFICATION (SUPERSEDED BY S550-30-14 R01)	TOL	MANDATORY	MTH 11-Jan-1991 HRS 2562		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-15 30SB-15	ANTI-ICE SYSTEM IMPROVEMENT	ALN	RECOMMENDED	MTH 17-Jan-1992 HRS 3050		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-16 30SB-16	ICE DETECTOR TEST CYCLE TIME DELAY MODIFICATION (SUPERSEDED BY S550-30-16 R01)	ALN	RECOMMENDED	MTH 17-Jan-1992 HRS 3050		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-30-17 30SB-17	WINDSHIELD BLEED AIR ORIFICE INSPECTION/REMOVAL (SUPERSEDED BY S550-30-17 R01)	THU		MANDATORY	MTH 26-Jul-1991 HRS 2775		A/R			Complete
MOC : COMPLIED WITH										
SB S550-30-18 30SB-18	TKS AUXILIARY TANK SEALER REMOVAL	HUR		RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-30-04A 30SLA04	TKS PROPORTIONING UNIT INSPECTION/REPLACEMENT	ICT		MANDATORY	MTH 27-Nov-1985 HRS 18		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-30-05A 30SLA05	ICE & RAIN PROTECTION - TKS ANTI-ICE SYSTEM PROPORTIONING UNIT CONNECTIONS	THV		MANDATORY	MTH 07-Jan-1986 HRS 40		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
MOC :										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION			RECOMMENDED	MTH HRS		300		5946.1	437.1
MOC :										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
MOC :										
SB S550-32-01 R01 32SB-01 : S55R1	LANDING GEAR - INSTALLATION OF CLEVELAND WHEELS AND BRAKES (SUPERSEDED BY S550-32-01 R02)	THV		OPTIONAL	MTH 22-Oct-1987 HRS 955		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-01 32SB-01	LANDING GEAR - INSTALLATION OF CLEVELAND WHEELS AND BRAKES (SUPERSEDED BY S550-32-01 R01)	THV		OPTIONAL	MTH 17-Apr-1987 HRS 648		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-02 R02 32SB-02 : S55R2	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R03)	TOL		RECOMMENDED	MTH 01-Feb-1989 HRS 1613		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-02 32SB-02	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R01)	TOL		RECOMMENDED	MTH 15-Jul-1987 HRS 796		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-04 32SB-04	MAIN LANDING GEAR DOORS REPLACEMENT (IMPROVED SLUSH AND SNOW OPERATION) (SUPERSEDED BY S550-32-04 R01)			OPTIONAL	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-32-05 R01 <i>32SB-05 : S55R1</i>	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R02)	THV	MANDATORY	MTH 08-Mar-1989 HRS 1670		A/R			Complete
MOC : COMPLIED WITH									
SB S550-32-05 <i>32SB-05</i>	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R01)	THV	MANDATORY	MTH 12-Dec-1988 HRS 1549		A/R			Complete
MOC : COMPLIED WITH									
SB S550-32-07 <i>32SB-07</i>	BF GOODRICH BRAKES AND WHEELS INSTALLATION (SUPERSEDED BY S550-32-07 R01)		OPTIONAL	MTH		A/R			
MOC :									
SB S550-32-08 <i>32SB-08</i>	INCREASED MAXIMUM GEAR EXTEND SPEED		OPTIONAL	MTH		A/R			
MOC :									
SB S550-32-11 <i>32SB-11</i>	BF GOODRICH BRAKE BLEEDER BLOCK INSTALLATION AND HOSE REPLACEMENT (SUPERSEDED BY S550-32-11 R01)		OPTIONAL	MTH		A/R			
MOC :									
SB S550-32-12 <i>32SB-12</i>	MAIN LANDING GEAR WHEEL WELL AFT SPAR BOX HYDRAULIC/PNEUMATIC LINES GROMMET REPLACEMENT	HUR	RECOMMENDED	MTH 13-Jul-2004 HRS 4886		A/R			Complete
MOC : COMPLIED WITH									
SB S550-32-13 <i>32SB-13</i>	ANTISKID DRIVE CLIP REPLACEMENT	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SB S550-32-15 <i>32SB-15</i>	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SB S550-32-16 <i>32SB-16</i>	ANTISKID SYSTEM DIODE REMOVAL	HYR	RECOMMENDED	MTH 22-May-2001 HRS 4406		A/R			Complete
MOC : COMPLIED WITH									
SB S550-32-18 R02 <i>32SB-18 : S55R2</i>	LANDING GEAR ON GROUND OPERATION MODIFICATION		RECOMMENDED	MTH		A/R			
MOC :									
SB S550-32-19 R01 <i>32SB-19 : S55R1</i>	LANDING GEAR - PARKING BRAKE CABLE REPLACEMENT		OPTIONAL	MTH		A/R			
MOC :									
SB S550-32-21 R01	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS		RECOMMENDED	HRS		300		5814.78	305.78
MOC :									
SB S550-32-21	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS (SUPERSEDED BY S550-32-21 R01)		RECOMMENDED			-			
MOC :									
SL S550-32-02 <i>32SL-02</i>	MAIN LANDING GEAR WHEEL-HALF SEALS FOR COLD WEATHER OPERATION	ATW	OPTIONAL	MTH 18-Dec-1985 HRS 38		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL SLS550-32-03A 32SLA03	INSPECTION OF MAIN LANDING GEAR TORQUE LINK CONNECTING HARDWARE	THV		MANDATORY	MTH 11-Feb-1986 HRS 71		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-05 32SL-05	NOSE GEAR STEERING LOWER JOINT BEARING INSPECTION	POU		RECOMMENDED	MTH 04-May-1988 HRS 1213		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-06 32SL-06	CLEVELAND BRAKE INSPECTION	THV			MTH 25-Apr-1988 HRS 1201		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-09 32SL-09	MAIN LANDING GEAR PISTON AXLE ADAPTER AND AXLE CORROSION INSPECTION, REMOVAL, AND PREVENTION	THV		RECOMMENDED	MTH 14-Aug-1989 HRS 1897		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-32-10A 32SLA10	INSPECTION OF MAIN LANDING GEAR UPPER AND LOWER TORQUE LINK CONNECTING HARDWARE	POU		MANDATORY	MTH 04-May-1988 HRS 1213			DAILY DAILY DAILY		Complete
MOC : COMPLIED WITH										
SL S550-32-11 32SL-11	UPLOCK ACTUATOR HYDRAULIC LINE INSPECTION	THV		RECOMMENDED	MTH 20-Nov-1989 HRS 2052		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-13 32SL-13	MAIN LANDING GEAR AXLE INTERNAL CORROSION INSPECTION	TOL		RECOMMENDED	MTH 13-Jul-1989 HRS 1861		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-15 32SL-15	BFGOODRICH BRAKE SHUTTLE VALVE INSPECTION/REPLACEMENT	HUR		MANDATORY	MTH 27-Mar-2012 HRS 5412.1 LDG 3721		A/R			N/A
MOC : NOT APPLICABLE - ASL S550-32-15 BF GOODRICH BRAKE SHUTTLE VALVE INSPECTION/REPLACEMENT N/A BY EQUIPMENT FITTED.										
SL S550-32-17 32SL-17	LANDING GEAR EMERGENCY EXTENSION CONTROL ASSEMBLY PIN INSPECTION	THV		RECOMMENDED	MTH 19-Jun-1990 HRS 2260		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-21 32SL-21	STRUT EXTENSION INSPECTION AND PISTON UPPER BEARING RETENTION IMPROVEMENT (SUPERSEDED BY SLS550-32-21 R01)	THV		RECOMMENDED	MTH 09-Aug-1991 HRS 2805		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-22 32SL-22	EMERGENCY LANDING GEAR BLOWDOWN BOTTLE LEVER SAFETY WIRE INSPECTION/REPLACEMENT	THV		RECOMMENDED	MTH 13-Aug-1990 HRS 2334		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-32-24 32SL-24	MAIN LANDING GEAR DRAG BRACE ATTACH NUT REPLACEMENT	THV	RECOMMENDED	MTH 12-Dec-1990 HRS 2538		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-26 32SL-26	NOSE AND MAIN LANDING GEAR UPLOCK SPRING INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-32-26 R01)	THV	RECOMMENDED	MTH 04-Jan-1991 HRS 2561		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-27 32SL-27	ANTI-SKID SYSTEM CONTROL UNIT CALIBRATION VERIFICATION	THV	RECOMMENDED	MTH 13-Mar-1991 HRS 2617		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-29 32SL-29	NOSE LANDING GEAR UPLOCK LINE INSPECTION	THV	RECOMMENDED	MTH 20-Sep-1991 HRS 2873		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-30 32SL-30	LANDING GEAR HANDLE LOCKING SOLENOID RIGGING INSPECTION	THV	RECOMMENDED	MTH 16-Oct-1991 HRS 2923		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-34 32SL-34	NOSE GEAR TRUNNION FINISH INSPECTION/REFINISH	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-37 32SL-37	BRAKE AND SPOILER/SPEEDBRAKE EXTENDED HYDRAULIC LINE(S) ROUTING INSTPECTION/MODIFICATION	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-40 32SL-40	CLEVELAND SERVICE BULLETIN ESB7028 BRAKE ASSEMBLY BOLT REPLACEMENT	BOH	MANDATORY	MTH 09-Oct-1993 HRS 3280		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-41 R01 32SL-41 : S55R1	TEIJIN SEIKI MAIN AND NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/ REPLACEMENT (SUPERSEDED BY SLS550-32-41 R02)	BOH	RECOMMENDED	MTH 09-Oct-1993 HRS 3280		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-45 32SL-45	NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY AND WIDE DOOR ATTACH HARDWARE INSPECTION / REPLACEMENT *KAT UPDATED	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-46 32SL-46	MAIN LANDING GEAR EXTEND PNEUMATIC LINE CLEARANCE INSPECTION (SUPERSEDED BY SLS550-32-46 R01)	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-48 32SL-48	TRANSMITTAL OF PARKER HANNIFIN CORP. CLEVELAND WHEEL & BRAKES SERVICE BULLETIN SB7054 - CITATION BRAKE ASSY - BRAKE ROTOR DISC - INSPECT/REPLACE	HUR	MANDATORY	MTH 23-Dec-1997 HRS 3896 LDG 2854		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-32-52 R01 32SL-52 : S55R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SL S550-32-54 32SL-54	EMERGENCY GEAR RELEASE INSPECTION	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			Complete
MOC : COMPLIED WITH										
SL CIL-33-01	LIGHTS - TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
MOC :										
SB S550-33-01 33SB-01	LANDING LIGHT RELOCATION (SUPERSEDED BY S550-33-01 R01)			OPTIONAL	MTH		A/R			
MOC :										
SB S550-33-04 R01 33SB-04 : S55R1	AFT CABIN PSU LIGHT WIRE REPLACEMENT (SUPERSEDED BY S550-33-04 R02)	TOL		MANDATORY	MTH 27-Jan-1988 HRS 1075		A/R			Complete
MOC : COMPLIED WITH										
SB S550-33-04 33SB-04	AFT CABIN PSU LIGHT WIRE REPLACEMENT (SUPERSEDED BY S550-33-04 R01)	TOL		MANDATORY	MTH 27-Jan-1988 HRS 1075		A/R			Complete
MOC : COMPLIED WITH										
SB S550-33-06 33SB-06	AFT CABIN PSU LIGHT POWER SUPPLY REPLACEMENT	THU		RECOMMENDED	MTH 17-Jul-1989 HRS 1867		A/R			Complete
MOC : COMPLIED WITH										
SB S550-33-07 33SB-07	LANDING LIGHT ELECTRICAL CIRCUIT MODIFICATION (SUPERSEDED BY S550-33-07 R01)			OPTIONAL	MTH		A/R			
MOC :										
SB S550-33-08 33SB-08	INDIRECT LIGHTING CONNECTOR CONTACT INSPECTION/REPLACEMENT	THV		RECOMMENDED	MTH 24-Jan-1991 HRS 2572		A/R			Complete
MOC : COMPLIED WITH										
SB S550-33-09 R01 33SB-09 : S55R1	LANDING LIGHT BULB PROTECTION (SUPERSEDED BY S550-33-09 R02)			OPTIONAL	MTH		A/R			
MOC :										
SB S550-33-11 R01 33SB-11 : S55R1	WING TIP NAV/COLLISION LIGHT MODIFICATION	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB S550-33-12 R03 33SB-12 : S55R3	WING TIP MOUNTED LANDING LIGHT INSTALLATION	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB S550-33-13 33SB-13	LANDING LIGHT CIRCUIT SWITCH MODULE INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB S550-33-14 33SB-14	INDIRECT LIGHTING LAMP AND CONNECTOR UPGRADE			OPTIONAL	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-33-15 R01 33SB-15 : S55R1	LIGHTS - EMERGENCY LIGHTING BATTERY PACK UPGRADE		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-33-15	LIGHTS - EMERGENCY LIGHTING BATTERY PACK UPGRADE (SUPERSEDED BY S550-33-15 R01)	EGHH	OPTIONAL	MTH	15-Oct-2010	A/R			Complete
HRS 5326 LDG 3671									
MOC : COMPLIED WITH - SBS550-33-15 CARRIED OUT.									
SB S550-33-16 33SB-16	LED TAIL POSITION LIGHT INSTALLATION		OPTIONAL	MTH		A/R			
MOC : - SERVICE BULLETIN ON HOLD.									
SL S550-33-03 R02 33SL-03 : S55R2	CABIN INDIRECT LIGHTING SYSTEM INSPECTION	HUR	RECOMMENDED	MTH	23-Dec-1997	A/R			Complete
HRS 3896									
MOC : COMPLIED WITH									
SL S550-33-03 33SL-03	CABIN INDIRECT LIGHTING SYSTEM INSPECTION (SUPERSEDED BY SLS550-33-03 R01)	THV	RECOMMENDED	MTH	24-Jan-1991	A/R			Complete
HRS 2572									
MOC : COMPLIED WITH									
SL S550-33-06 33SL-06	LANDING LIGHT SWITCH INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-33-06 R01)	BOH	MANDATORY	MTH	06-Oct-1994	A/R			Complete
MOC : COMPLIED WITH									
SB S550-34-06 34SB-06	STATIC LINE REROUTE	POU	MANDATORY	MTH	03-Apr-1987	A/R			Complete
HRS 629									
MOC : COMPLIED WITH									
SB S550-34-10 R01	NAV 2 WIRING CHANGE		MANDATORY			A/R			
MOC :									
SB S550-34-17 R01 34SB-17 : S55R1	STATIC PORT DOUBLER INSTALLATION	HUR	RECOMMENDED	MTH	13-Jul-2004	A/R			Complete
HRS 4886									
MOC : COMPLIED WITH									
SB S550-34-25 R01 34SB-25 : S55R1	STARTER-GENERATOR AND GCU FILTER INSTALLATION	HUR	RECOMMENDED	MTH	19-Dec-1997	A/R			Complete
HRS 3896									
MOC : COMPLIED WITH									
ASB S550-34-26 R01 34SBA26 : S55R1	VG14A VERTICAL GYRO INSPECTION	THV	MANDATORY	MTH	13-Nov-1989	A/R			Complete
HRS 2042									
MOC : COMPLIED WITH									
SB S550-34-27 34SB-27	VN-212 SIGNAL GROUND WIRING MODIFICATION		OPTIONAL	MTH		A/R			
MOC :									
SB S550-34-35 34SB-35	COPILOT ALTIMETER INSTALLATION - KOLLSMAN		OPTIONAL	MTH		A/R			
MOC :									
SB S550-34-36 34SB-36	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION (SUPERSEDED BY S550-34-36 R01)	HUR	OPTIONAL	MTH	13-Jul-2004	A/R			Complete
HRS 4886									
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-34-37 34SB-37	TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE	HUR		OPTIONAL	MTH 06-Aug-2007 HRS 5068		A/R			Complete
MOC : COMPLIED WITH										
SB S550-34-38 34SB-38	SANDEL ST3400 TAWS INSTALLATION	HUR		OPTIONAL	MTH 27-May-2005 HRS 4985		A/R			Complete
MOC : COMPLIED WITH										
SB S550-34-39 34SB-39	SIGMA-TEK CONTROL PANEL INSTALLATION	HUR		OPTIONAL	MTH 06-Aug-2007 HRS 5068		A/R			Complete
MOC : COMPLIED WITH										
SB S550-34-40	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
MOC :										
SL S550-34-01 34SL-01	COLLINS VIR-32 NAVIGATION RECEIVER SERVICE BULLETIN 14	TOL		RECOMMENDED	MTH 27-Jan-1988 HRS 1075		A/R			Complete
MOC : COMPLIED WITH										
SL S550-34-06 34SL-06	DORNE AND MARGOLIN DMN4-17-4 NAV ANTENNA COUPLER INSPECTION			RECOMMENDED	MTH		A/R			
MOC :										
ASL SLS550-34-15A	KLN 89B, KLN 90B AND KLN 900 GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS	HUR		MANDATORY	MTH 27-Mar-2012 HRS 5412.1 LDG 3721		A/R			N/A
MOC : NOT APPLICABLE - ASL S550-34-15 NAVIGATION GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS N/A BY EQUIPMENT FITTED.										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	SRQ		MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
SB S550-35-03 R01 35SB-03 : S55R1	EROS OXYGEN MASK INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB S550-35-04 R01 35SB-04 : S55R1	CHAFING PROTECTION INSTALLATION OF TAILCONE LINES AND WIRE BUNDLES	HUR		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL S550-35-03	OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL S550-35-04 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL S550-35-04	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SLS550-35-04 R01)	HUR		MANDATORY	MTH 27-Mar-2012 HRS 5412.1 LDG 3721		-			N/A
MOC : NOT APPLICABLE - SL S550-35-04 OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SB MXH-35-240 N/A BY PART NUMBER.										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-36-02 36SB-02	DOOR SEAL PLUMBING INSPECTION AND MODIFICATION	ALN		MTH RECOMMENDED	17-Jan-1992 3050		A/R			Complete
MOC : COMPLIED WITH										
SB S550-36-04 R01 36SB-04 : S55R1	ENGINE BLEED AIR CONNECTOR IMPROVEMENT			MTH OPTIONAL			A/R			
MOC :										
SB S550-36-05 36SB-05	DOOR SEAL VALVE REPLACEMENT			OPTIONAL MTH			A/R			
MOC :										
ASL S550-52-03	DOORS - EMERGENCY EXIT INSPECTION	HUR		MANDATORY	DAYS 27-Mar-2012 HRS 5412.1 LDG 3721		A/R			Complete
MOC : COMPLIED WITH - ASL S550-52-03 EMERGENCY EXIT INSPECTION CARRIED OUT.										
SB S550-52-02 52SB-02	ENTRY STEP ASSEMBLY IMPROVEMENT (SUPERSEDED BY S550-52-02 R01)	TOL		RECOMMENDED	MTH 22-Jan-1987 HRS 563		A/R			Complete
MOC : COMPLIED WITH										
SB S550-52-04 52SB-04	TAILCONE BAGGAGE DOOR RESTRAINT CABLE INSTALLATION	THV		OPTIONAL	MTH 11-Jan-1990 HRS 2110		A/R			Complete
MOC : COMPLIED WITH										
SB S550-52-05 52SB-05	BAGGAGE DOOR POSITIVE SAFETY LOCK INSTALLATION (SUPERSEDED BY S550-52-05 R01)	THV		RECOMMENDED	MTH 19-Jan-1990 HRS 2122		A/R			Complete
MOC : COMPLIED WITH										
SB S550-52-06 52SB-06	WIDE DOOR INSTALLATION (SUPERSEDED BY S550-52-06 R01)			OPTIONAL	MTH		A/R			
MOC :										
SB S550-52-08 52SB-08	WIDE DOOR RETRACT CABLE MODIFICATION (SUPERSEDED BY S550-52-08 R01)			OPTIONAL	MTH		A/R			
MOC :										
SB S550-52-09 52SB-09	ENTRY DOOR STEP CATCH COVER INSTALLATION (WITH STANDARD DOOR AND STEP)	HUR		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL S550-52-01 52SL-01	NOSE AND TAILCONE BAGGAGE DOOR INSPECTION	THV		RECOMMENDED	MTH 11-Jan-1990 HRS 2110		A/R			Complete
MOC : COMPLIED WITH										
SL S550-52-02 52SL-02	EMERGENCY EXIT INNER HANDLE ATTACH SCREW INSPECTION/REPLACEMENT	BOH		MANDATORY	MTH 08-Oct-1992 HRS 3140		A/R			Complete
MOC : COMPLIED WITH										
SB S550-53-01 53SB-01	TAILCONE BALLAST INSTALLATION (SUPERSEDED BY S550-53-01 R01)			OPTIONAL	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-53-05 R01 <i>53SB-05 : S55R1</i>	TAILCONE BAGGAGE COMPARTMENT GUSSET INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-05 R02)	ALN	RECOMMENDED	MTH 17-Jan-1992 HRS 3050		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-08 <i>53SB-08</i>	FRAME BRACE INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-08 R01)	HUR	RECOMMENDED	MTH 19-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-09 <i>53SB-09</i>	CABIN INTERIOR ATTACH/CONTACT POINT CORROSION PROTECTION (SUPERSEDED BY S550-53-09 R01)	HUR	RECOMMENDED	MTH 19-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-10 <i>53SB-10</i>	FLIGHT CREW SEAT RAIL AND BEAM RIVETS INSPECTION/INSTALLATION	HUR	RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-53-11 <i>53SB-11</i>	DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT		OPTIONAL	MTH		A/R			
MOC :									
SB S550-53-12 <i>53SB-12</i>	MAP COMPARTMENT ASSEMBLY INSPECTION/REPLACEMENT	HUR	RECOMMENDED	MTH 19-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-14 <i>53SB-14</i>	AN3-5A BOLT INSPECTION/REPLACEMENT	HUR	RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-15 <i>53SB-15</i>	FUSELAGE MOISTURE DRAIN INSTALLATION		OPTIONAL	MTH		A/R			
MOC :									
SB S550-53-16 <i>53SB-16</i>	FUSELAGE - MAIN CARRY-THRU LUG INSPECTION	HUR	RECOMMENDED	MTH 13-Jul-2004 HRS 4886		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-17 <i>53SB-17</i>	WHEEL WELL BOX/SKIN GAP IMPROVEMENT		OPTIONAL	MTH		A/R			
MOC :									
SL S550-53-01 <i>53SL-01</i>	NOSE BAGGAGE AND TAILCONE ACCESS DOOR LATCH INSPECTION	POU	RECOMMENDED	MTH 03-Apr-1987 HRS 629		A/R			Complete
MOC : COMPLIED WITH									
SL S550-53-03 <i>53SL-03</i>	DORSAL FIN VANE INSPECTION		RECOMMENDED	MTH		A/R			
MOC :									
SL S550-53-04 R01 <i>53SL-04 : S55R1</i>	INTERCOSTAL DRAINAGE PATH INSPECTION		RECOMMENDED	MTH		A/R			
MOC :									
SB S550-54-01 <i>54SB-01</i>	PYLON FAIRING DRAIN HOLE INSTALLATION	THV	MANDATORY	MTH 14-Mar-1986 HRS 117		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
<i>SL S550-55-01 R01</i> <i>55SL-01 : S55R1</i>	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION THU		RECOMMENDED	MTH 06-Apr-1990 HRS 2185		A/R			Complete
	MOC : COMPLIED WITH								
<i>SL S550-55-01</i> <i>55SL-01</i>	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION (SUPERSEDED BY SLS550-55-01 R1) THV		RECOMMENDED	MTH 06-Apr-1990 HRS 2185		A/R			Complete
	MOC : COMPLIED WITH								
<i>SB S550-57-01</i> <i>57SB-01</i>	RIGHT WING ACCESS PANEL INSTALLATION OPTIONAL			MTH		A/R			
	MOC :								
<i>SB S550-57-02</i> <i>57SB-02</i>	VORTEX GENERATOR REMOVAL (SUPERSEDED BY S550-57-02 R01) OPTIONAL			MTH		A/R			
	MOC :								
<i>SB S550-57-03</i> <i>57SB-03</i>	FLAP ACTUATOR UPPER BELLCRANK BRACKET REPLACEMENT (SUPERSEDED BY S550-57-03 R01) ALN		RECOMMENDED	MTH 17-Jan-1992 HRS 3050		A/R			Complete
	MOC : COMPLIED WITH								
<i>SB S550-57-06 R01</i> <i>57SB-06 : S55R1</i>	STUB WING DOUBLER INSTALLATION OPTIONAL			MTH		A/R			
	MOC :								
<i>SB S550-57-06</i> <i>57SB-06</i>	STUB WING DOUBLER INSTALLATION (SUPERSEDED BY S550-57-06 R01) OPTIONAL			MTH		A/R			
	MOC :								
<i>SB S550-57-07</i> <i>57SB-07</i>	FLAP PROTECTOR INSTALLATION (SUPERSEDED BY S550-57-07 R01) OPTIONAL			MTH		A/R			
	MOC :								
<i>SB S550-57-09</i> <i>57SB-09</i>	FLAP VENT HOLES INSTALLATION HUR		RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
	MOC : COMPLIED WITH								
<i>ASL SLS550-57-01A</i> <i>57SLA01</i>	FLAP DRAIN HOLE INSPECTION THV		MANDATORY	MTH 26-May-1988 HRS 1233		A/R			Complete
	MOC : COMPLIED WITH								
<i>SL S550-57-02</i> <i>57SL-02</i>	AILERON EXTERNAL BALANCE WEIGHT INSPECTION TOL		RECOMMENDED	MTH 13-Jul-1989 HRS 1861		A/R			Complete
	MOC : COMPLIED WITH								
<i>SL S550-71-01</i> <i>71SL-01</i>	JT15D-4B MINIMUM FUEL FLOW ADJUSTMENT TOL		RECOMMENDED	MTH 15-Jul-1987 HRS 796		A/R			Complete
	MOC : COMPLIED WITH								
<i>SL S550-71-02</i> <i>71SL-02</i>	ENGINE BREATHING TUBE EXTENSION OPTIONAL			MTH		A/R			
	MOC :								
<i>SL S550-72-04</i> <i>72SL-04</i>	IMPROVED RETENTION OF P3 AIR-TO-FUEL CONTROL BOSS POU		RECOMMENDED	MTH 04-May-1988 HRS 1213		A/R			Complete
	MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-72-05 72SL-05	JT15D FAN BLADE INSPECTION THV			RECOMMENDED	MTH 20-May-1987 HRS 704		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-06 R02 72SL-06 : S55R2	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R03) THV			RECOMMENDED	MTH 28-Oct-1988 HRS 1495		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-06 72SL-06	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R01) THV			RECOMMENDED	MTH 28-Dec-1987 HRS 1038		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-07 72SL-07	LOW COMPRESSOR CASE DAMPENING RING INSTALLATION (SUPERSEDED BY SLS550-72-07 R01) THV			RECOMMENDED	MTH 28-Oct-1988 HRS 1495		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-72-09A LEFT ENGINE 72SLA09 : S550L	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED) MIV			CANCELLED	MTH 28-Oct-1988 HRS 1495		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-72-09A RIGHT ENGINE 72SLA09 : S550R	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED) MIV			CANCELLED	MTH 28-Oct-1988 HRS 1495		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-11 R01 72SL-11 : S55R1	JT15D-4B HIGH TURBINE BLADE SHIFT HUR			RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-11 72SL-11	JT15D-4B HIGH TURBINE BLADE SHIFT (SUPERSEDED BY SLS550-72-11 R01) THV			RECOMMENDED	MTH 08-Oct-1991 HRS 2911		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-19 72SL-19	TRANSMITTAL OF P&WC SERVICE LETTER JT15D-023 REPLACEMENT OF OIL PUMP PLUG HYR			RECOMMENDED	MTH 22-May-2001 HRS 4406		A/R			Complete
MOC : COMPLIED WITH										
SB JT15D-72-7001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26) RECOMMENDED						-			
MOC :										
SB JT15D-72-7001 R25 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26) RECOMMENDED						-			
MOC :										
SB JT15D-72-7001 R26 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27) RECOMMENDED						-			
MOC :										
SB JT15D-72-7001 R26 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27) RECOMMENDED						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7001 R27 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7001 R27 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7002 R42 E1	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43)			CATEGORY 3			A/R			
	MOC :									
SB JT15D-72-7002 R42 E2	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43)			CATEGORY 3			A/R			
	MOC :									
SB JT15D-72-7002 R43 E1	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R43 E2	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7003 R35 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R35 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R36 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)						-			
	MOC :									
SB JT15D-72-7003 R36 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)						-			
	MOC :									
SB JT15D-72-7003 R37 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R38)						-			
	MOC :									
SB JT15D-72-7003 R37 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R38)						-			
	MOC :									
SB JT15D-72-7003 R38 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R39)						-			
	MOC :									
SB JT15D-72-7003 R38 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R39)						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7003 R40 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			A/R			
MOC :										
SB JT15D-72-7003 R40 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			A/R			
MOC :										
SB JT15D-72-7144 R20 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
MOC :										
SB JT15D-72-7144 R20 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
MOC :										
SB JT15D-72-7144 R21 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
MOC :										
SB JT15D-72-7144 R21 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
MOC :										
SB JT15D-72-7244 R05 E1	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
MOC :										
SB JT15D-72-7244 R05 E2	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
MOC :										
SB JT15D-72-7288 R04 E1	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7288 R04 E2	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7292 R01 E1	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
MOC :										
SB JT15D-72-7292 R01 E2	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
MOC :										
SB JT15D-72-7364 R03 E1	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
MOC :										
SB JT15D-72-7364 R03 E2	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
MOC :										
SB JT15D-72-7459 R01 E1	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7459 R01 E2	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
MOC :										
SB JT15D-72-7459 R02 E1	REPLACEMENT OF IGNITER			CATEGORY 8			-			
MOC :										
SB JT15D-72-7459 R02 E2	REPLACEMENT OF IGNITER			CATEGORY 8			-			
MOC :										
SB JT15D-72-7522 R06 E1	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
MOC :										
SB JT15D-72-7522 R06 E2	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
MOC :										
SB JT15D-72-7522 R07 E1	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7522 R07 E2	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7588 R02 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
MOC :										
SB JT15D-72-7588 R02 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
MOC :										
SB JT15D-72-7589 R01 E1	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
MOC :										
SB JT15D-72-7589 R01 E2	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
MOC :										
SB JT15D-72-7618 R02 E1	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										
SB JT15D-72-7618 R02 E2	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										
SB JT15D-72-7618 R03 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										
SB JT15D-72-7618 R03 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7621 R01 E1	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7						
	MOC :									
SB JT15D-72-7621 R01 E2	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7						
	MOC :									
SB JT15D-72-7625 R01 E1	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 R01 E2	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 E1	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 E2	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7627 E1	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6						
	MOC :									
SB JT15D-72-7627 E2	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6						
	MOC :									
SB JT15D-72-7633 E1	ALTERNATE SOURCE RETAINING RING			CATEGORY 7						
	MOC :									
SB JT15D-72-7633 E2	ALTERNATE SOURCE RETAINING RING			CATEGORY 7						
	MOC :									
SB JT15D-72-7634 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3						
	MOC :									
SB JT15D-72-7634 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3						
	MOC :									
SB JT15D-72-7636 E1	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7						
	MOC :									
SB JT15D-72-7636 E2	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7						
	MOC :									
SB JT15D-72-7639 R01 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)			CATEGORY 3	MTH HRS		400		(6346.68)6346.68	837.68
	MOC :									
SB JT15D-72-7639 R01 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)			CATEGORY 3	MTH HRS		400		(6346.68)6346.68	837.68
	MOC :									
SB JT15D-72-7639 R02 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7639 R02 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3			-			
MOC :										
SB JT15D-72-7639 R03 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB JT15D-72-7639 R03 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB JT15D-72-7639 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4			-			
MOC :										
SB JT15D-72-7639 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4			-			
MOC :										
SB JT15D-72-7640 E1	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
MOC :										
SB JT15D-72-7640 E2	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
MOC :										
SB JT15D-72-7642 R01 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
MOC :										
SB JT15D-72-7642 R01 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
MOC :										
SB JT15D-72-7642 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 9			-			
MOC :										
SB JT15D-72-7642 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 9			-			
MOC :										
SB JT15D-72-7643 E1	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
MOC :										
SB JT15D-72-7643 E2	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
MOC :										
SB JT15D-72-7644 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
MOC :										
SB JT15D-72-7644 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
MOC :										
ASB S550-73-01A R03	9912031-6 FUEL FLOW TRANSMITTER INSPECTION				MTH 11-Jan-1991 HRS 2562		N/A			Complete
73SBA01 : S55R3										
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB S550-73-01A 73SBA01	9912031-6 FUEL FLOW TRANSMITTER INSPECTION (SUPERSEDED BY S550-73-01A R01)	THV	MANDATORY	MTH 25-Jul-1989 HRS 1877		A/R			Complete
MOC : COMPLIED WITH									
SB S550-73-02 R01 73SB-02 : S55R1	9912031-6 FUEL FLOW TRANSMITTER THREAD INSPECTION	TOL	MANDATORY	MTH 11-Jan-1991 HRS 2562		A/R			Complete
MOC : COMPLIED WITH									
SB S550-73-02 73SB-02	9912031-6 FUEL FLOW TRANSMITTER THREAD INSPECTION (SUPERSEDED BY S550-73-02 R01)	THV	MANDATORY	MTH 19-Jun-1990 HRS 2260		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-74-01 R01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE	SRQ	MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			Complete
MOC : COMPLIED WITH									
SL CIL-74-01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R01)		MANDATORY	DAYS		-			
MOC :									
SL S550-74-02 74SL-02	IGNITION - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF	HYR	RECOMMENDED	MTH 22-May-2001 HRS 4406		A/R			Complete
MOC : COMPLIED WITH									
SB S550-78-04 78SB-04	EXHAUST - THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION (SUPERSEDED BY S550-78-04 R01)	THV	RECOMMENDED	MTH 07-Nov-1991 HRS 2965		A/R			Complete
MOC : COMPLIED WITH									
SB S550-78-05 78SB-05	EXHAUST - THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT		OPTIONAL	MTH		A/R			
MOC :									
SL S550-78-02 78SL-02	THRUST REVERSER JUNCTION BOX MODIFICATION (SUPERSEDED BY SLS550-78-02 R01)	TOL	RECOMMENDED	MTH 15-Jul-1987 HRS 796		A/R			Complete
MOC : COMPLIED WITH									
SL S550-78-04 R02 78SL-04 : S55R2	THRUST REVERSER DOOR MODIFICATION	THV	RECOMMENDED	MTH 09-Aug-1991 HRS 2805		A/R			Complete
MOC : COMPLIED WITH									
SL S550-78-04 78SL-04	THRUST REVERSER DOOR MODIFICATION (SUPERSEDED BY SLS550-78-04 R01)	ALN	RECOMMENDED	MTH 21-Feb-1990 HRS 2136		A/R			Complete
MOC : COMPLIED WITH									
SL S550-78-05 78SL-05	THRUST REVERSER SYSTEM OPERATIONAL TEST (SUPERSEDED BY SLS550-78-05 R01)	THV	RECOMMENDED	MTH 11-Oct-1990 HRS 2444		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-78-08 78SL-08	THRUST REVERSER STANG FAIRING SUPPORT FORMER REPLACEMENT	HUR		RECOMMENDED	MTH 23-Dec-1997 HRS 3896		A/R			Complete
MOC : COMPLIED WITH										
SL S550-78-10 78SL-10	TRANSMITTAL OF NORDAM SERVICE BULLETIN CITSII 78-12 R1, EXHAUST - THRUST REVERSER - REPLACEMENT OF THRUST REVERSER STANG FAIRING SUPPORT FORMER (SUPERSEDED BY SLS550-78-10 R01)	HVR		RECOMMENDED	MTH 22-May-2001 HRS 4406		A/R			Complete
MOC : COMPLIED WITH - SERVICE INFORMATION ITEM COMPLIED WITH PREVIOUSLY. DATE AND OR HOURS UNKNOWN.										
SB S550-80-01 80SB-01	STARTING - REPLACEMENT OF SUPPRESSION DIODE WITH TRANSZORB			OPTIONAL	MTH		A/R			
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1990-07-10 <i>21AD-01</i>	TO PREVENT FAILURE OF THE ELEVATOR OR RUDDER CONTROL CABLES	THV		SUPERSEDED	MTH 06-Apr-1990 HRS 2185		-			Complete
MOC : COMPLIED WITH										
FAA 1993-05-15	MODIFY THE THRUST REVERSER THROTTLE LOAD LIMITER	EGHH		MANDATORY	MTH 01-Nov-2011 HRS 5411 LDG 3720		A/R			Complete
MOC : COMPLIED WITH - AD1993-05-15 COMPLIED WITH IAW SBS550-78-04 (CARRIED OUT 07-NOV-1991 @ 2965 HOURS).										
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	SRQ		MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	SRQ		MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		A/R			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		A/R			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	SRQ		MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	SRQ		MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY	SRQ		MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA	SRQ		MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO FREON AIR INSTALLED										
FAA 1988-06-02	ELECTRICAL POWER			MANDATORY			-			
MOC :										
FAA 1987-03-15 25AD-01	SUPERSEDED BY AD 1988-24-16 THV			SUPERSEDED	MTH 18-Feb-1987 HRS 589		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1988-24-16 25AD-03	TO PRECLUDE WIRING FAILURE, WHICH CAN RESULT IN CABIN SMOKE AND/OR FIRE	THV	MANDATORY	MTH 12-Dec-1988 HRS 1549		A/R			Complete
MOC : COMPLIED WITH									
FAA 1989-06-01 25AD-04	APPLIANCE AD - TO PREVENT THE IMPROPER FUNCTIONING OF THE CO2 INFLATORS	THV	MANDATORY	MTH 24-May-1989 HRS 1798		A/R			Complete
MOC : COMPLIED WITH									
FAA 1998-25-10 25AD-07	APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM	HUR	MANDATORY	MTH 19-Feb-1999 HRS 4114		A/R			Complete
MOC : COMPLIED WITH									
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2		MANDATORY	MTH		-			
MOC :									
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK		MANDATORY			-			
MOC :									
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS		MANDATORY			-			
MOC :									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT		MANDATORY	MTH		-			
MOC :									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	SRQ		MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY ELT INSTALLED, POINTER									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	SRQ	MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY ELT INSTALLED, POINTER									
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	SRQ	MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY ELT INSTALLED, POINTER									
FAA 2001-22-14 26AD-01	APPLIANCE AD - TO PREVENT DAMAGE TO FIRE EXTINGUISHING SYSTEM COMPONENTS CAUSED BY A FIRE EXTINGUISHING SYSTEM BOTTLE CARTRIDGE ACTIVATING WITH EXCESSIVE ENERGETIC	HUR	MANDATORY	MTH 03-Jun-2003 HRS 4696		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2006-04-10 26AD-02	SUPERSEDED BY 2007-11-17	HUR	SUPERSEDED	MTH 06-Aug-2007 HRS 5068		-			Complete
MOC : COMPLIED WITH									
FAA 2007-11-17 26AD-06	ENSURE FIRE EXTINGUISHING BOTTLES ARE ACTIVATED IN THE EVENT OF AN ENGINE OR APU FIRE	HUR	MANDATORY	MTH 28-May-2008 HRS 5154		A/R			Complete
MOC : COMPLIED WITH									
FAA 2010-04-16 PARA (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT	EGHH	MANDATORY	DAYS 15-Oct-2010 HRS 5326 LDG 3671		A/R			N/A
MOC : NOT APPLICABLE - AD 2010-04-16 (G) CARRIED OUT - N/A BY EQUIPMENT FITTED.									
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER	EGHH	MANDATORY	DAYS 15-Oct-2010 HRS 5326 LDG 3671		A/R			N/A
MOC : NOT APPLICABLE - AD 2010-04-16 (H) CARRIED OUT - N/A BY EQUIPMENT FITTED.									
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI	EGHH	MANDATORY	MTH 15-Oct-2010 HRS 5326 LDG 3671		A/R			N/A
MOC : NOT APPLICABLE - AD 2010-04-16 CARRIED OUT - N/A BY EQUIPMENT FITTED.									
FAA 2006-06-03 28AD-02	PREVENT FUEL VAPOR IGNITION	HUR	MANDATORY	MTH 06-Aug-2007 HRS 5068		A/R			Complete
MOC : COMPLIED WITH									
FAA 1985-24-04 30AD-01	TO PREVENT HAZARDOUS ACCUMULATION OF ICE ON THE INBOARD WING LEADING EDGE DURING FLIGHT IN ICING CONDITIONS	THV	MANDATORY	MTH 07-Jan-1986 HRS 40		A/R			Complete
MOC : COMPLIED WITH									
FAA 1985-25-10 30AD-02	TO PREVENT HAZARDOUS ACCUMULATION OF ICE ON THE WING LEADING EDGE AND HORIZONTAL STABILIZER DURING FLIGHT IN ICING CONDITIONS	THV	MANDATORY	MTH 28-Jan-1986 HRS 62		A/R			Complete
MOC : COMPLIED WITH									
FAA 1986-01-02 32AD-01	SUPERSEDED BY 1988-13-03	THV	SUPERSEDED	MTH 11-Feb-1986 HRS 71		-			Complete
MOC : COMPLIED WITH									
FAA 1988-13-03 R01 32AD-02 : S55R1	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS	THV	MANDATORY	MTH 16-Mar-1989 HRS 1681		A/R			Complete
MOC : COMPLIED WITH									
FAA 1988-13-03 32AD-02	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS (SUPERSEDED BY 1988-13-03 R01)	THV	SUPERSEDED	MTH 28-Jun-1988 HRS 1269		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1990-07-08 <i>33AD-02</i>	APPLIANCE AD - SUPERSEDED BY AD 1990-07-08 R1	THV	SUPERSEDED	MTH 13-Aug-1990 HRS 2334		-			Complete
MOC : COMPLIED WITH									
FAA 1990-14-06 <i>33AD-03</i>	APPLIANCE AD - SUPERSEDED BY AD 1995-22-01	THV	SUPERSEDED	MTH 24-Jan-1991 HRS 2572		-			Complete
MOC : COMPLIED WITH									
FAA 1990-03-02 <i>34AD-01</i>	APPLIANCE AD - SUPERSEDED BY AD 1990-06-13	ALN	SUPERSEDED	MTH 21-Feb-1990 HRS 2136		-			Complete
MOC : COMPLIED WITH									
FAA 1990-06-13 <i>34AD-02</i>	APPLIANCE AD - TO PREVENT ERRONEOUS ATTITUDE DISPLAY	THV	MANDATORY	MTH 06-Apr-1990 HRS 2185		A/R			Complete
MOC : COMPLIED WITH									
FAA 1998-25-02 <i>34AD-06</i>	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	HUR	MANDATORY	MTH 19-Feb-1999 HRS 4114		A/R			Complete
MOC : COMPLIED WITH									
FAA 2001-23-17 <i>34AD-26</i>	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	HUR	MANDATORY	MTH 06-Aug-2007 HRS 5068		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2003-13-08 <i>34AD-13</i>	APPLIANCE AD - TERRAIN AWARENESS WARNING SYSTEMS (TAWS)	HUR	MANDATORY	MTH 28-May-2008 HRS 5154		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2004-08-15 <i>34AD-14</i>	APPLIANCE AD - CORRECTION: GOODRICH AVIONICS SYSTEMS, INC TAWS8000 TERRAIN AWARENESS WARNING SYSTEM	HUR	MANDATORY	MTH 06-Aug-2007 HRS 5068		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2006-16-18 <i>34AD-34</i>	APPLIANCE AD - SUPERSEDED BY AD 2006-16-18 R01	HUR	SUPERSEDED	MTH 06-Aug-2007 HRS 5068		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION		MANDATORY	MTH		-			
MOC :									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.		MANDATORY	MTH		-			
MOC :									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS		MANDATORY			-			
MOC :									
FAA 1994-19-06 <i>35AD-01</i>	APPLIANCE AD - TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING	DUB	MANDATORY	MTH 25-Oct-1995 HRS 3495		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1999-08-21 <i>35AD-02</i>	APPLIANCE AD - TO PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE OXYGEN MASKS			MANDATORY	MTH 19-Oct-1999 HRS 4234		A/R			Complete
MOC : COMPLIED WITH										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011			MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES			MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES			MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER			MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).			MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1			MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."			MANDATORY	DAYS 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT			MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	SRQ	MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - BY EQUIPMENT INSTALLED									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12		MANDATORY	MTH		-			
MOC :									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY	MTH		-			
MOC :									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	SRQ	MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO PBE DEVICES INSTALLED									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	SRQ	MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO PBE DEVICES INSTALLED									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	SRQ	MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO PBE DEVICES INSTALLED									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	SRQ	MANDATORY	MTH 20-Dec-2018 HRS 5507.2 LDG 3773		-			N/A
MOC : NOT APPLICABLE - NO PBE DEVICES INSTALLED									
FAA 1988-11-07 57AD-01	TO PREVENT LOSS OF A FLAP PANEL	THV	MANDATORY	MTH 26-May-1988 HRS 1233		A/R			Complete
MOC : COMPLIED WITH									
AD 72-01	JT15D FAN BLADE INSP	THV		MTH 20-May-1987 HRS 704		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
AD 72-03	HP TURB. BLADE SHIFT	THU		MTH 14-May-1991 HRS 2696		-			Complete
	MOC : COMPLIED WITH								
AD 72-04	GAS GEN CASE INSP	THV		MTH 18-Nov-1991 HRS 2988		-			Complete
	MOC : COMPLIED WITH								
FAA 1988-22-03 E1	HT BLADE SHIFT INSP	MIV	SUPERSEDED	MTH 28-Oct-1988 HRS 1495		-			Complete
	MOC : COMPLIED WITH								
FAA 1988-22-03 E2	HT BLADE SHIFT INSP	MIV	SUPERSEDED	MTH 28-Oct-1988 HRS 1495		-			Complete
	MOC : COMPLIED WITH								
FAA 1993-18-08 E1	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	HUR	MANDATORY	MTH 19-Feb-1999 HRS 4114		-			Complete
	MOC : COMPLIED WITH								
FAA 1993-18-08 E2	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	HUR	MANDATORY	MTH 19-Feb-1999 HRS 4114		-			Complete
	MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
21FO-04A <i>21FO-04 : 550/A</i>	COCKPIT AIR SUPPLEMENTAL FACTORY OPTION	*CF		179A FO	MTH 13-Sep-1985		-			
23FO-06D <i>23FO-06 : 550/D</i>	FLITEFONE IV WULFSBERG FACTORY OPTION	*CF		674D FO	MTH 13-Sep-1985		-			
24FO-01B <i>24FO-01 : 550/B</i>	BATTERY & MONITOR FOR 20 CELL FACTORY OPTION	*CF		12B FO	MTH 13-Sep-1985		-			
25FO-05J <i>25FO-05 : 550/J</i>	STRGE DRAWER #3 AFT FCG SEAT LATERL TRACK FACTORY OPTION	*CF		104J FO	MTH 13-Sep-1985		-			
25FO-05L <i>25FO-05 : 550/L</i>	STRGE DRAWER #4 AFT FCG SEAT LATERL TRACK FACTORY OPTION	*CF		104L FO	MTH 13-Sep-1985		-			
25FO-05M <i>25FO-05 : 550/M</i>	STRGE DRAWER #5 FWD FCG SEAT LATERL TRACK FACTORY OPTION	*CF		104M FO	MTH 13-Sep-1985		-			
25FO-10B <i>25FO-10 : 550/B</i>	CENTER CLUB SEATING FACTORY OPTION	*CF		112B FO	MTH 13-Sep-1985		-			
25FO-20U <i>25FO-20 : 550/U</i>	EXECUTIVE TABLE LH USED W/CENTER CLUB FACTORY OPTION	*CF		124U FO	MTH 13-Sep-1985		-			
25FO-20V <i>25FO-20 : 550/V</i>	EXECUTIVE TABLE RH USED W/CENTER CLUB FACTORY OPTION	*CF		124V FO	MTH 13-Sep-1985		-			
25FO-22B <i>25FO-22 : 550/B</i>	FLUSH TOILET AFT RELIEF TUBE ONLY FACTORY OPTION	*CF		131B FO	MTH 13-Sep-1985		-			
25FO-24M <i>25FO-24 : 550/M</i>	MAGAZINE RACK LH W/AFT CABIN DIVIDER FACTORY OPTION	*CF		134M FO	MTH 13-Sep-1985		-			
25FO-25A <i>25FO-25 : 550/A</i>	CARPET RUNNER CABIN AISLE FACTORY OPTION	*CF		136A FO	MTH 13-Sep-1985		-			
25FO-37 <i>25FO-37 : 550/J</i>	CHIMES UNIT FACTORY OPTION	*CF		166 FO	MTH 13-Sep-1985		-			
27FO-01A <i>27FO-01 : 550/A</i>	ELECTRIC TRIM SWITCH COPILOT FACTORY OPTION	*CF		33A FO	MTH 13-Sep-1985		-			
33FO-02B <i>33FO-02 : 550/B</i>	LIGHT-RECOGNITION WING-TIP MOUNTED FACTORY OPTION	*CF		49B FO	MTH 13-Sep-1985		-			
34FO-03 <i>34FO-03 : 550/J</i>	HORIZON GYRO ELECTRIC STANDBY FACTORY OPTION	*CF		142 FO	MTH 13-Sep-1985		-			
34FO-04 <i>34FO-04 : 550/J</i>	LOCATOR BEACON EMERGENCY FACTORY OPTION	*CF		175 FO	MTH 13-Sep-1985		-			
34FO-07D <i>34FO-07 : 550/D</i>	2ND TRANSPONDER- COLLINS TDR-90 FACTORY OPTION	*CF		623D FO	MTH 13-Sep-1985		-			
34FO-15B <i>34FO-15 : 550/B</i>	FLIGHT DIRECTOR LH-5 " SINGLE CUE SPERRY FACTORY OPTION	*CF		679B FO	MTH 13-Sep-1985		-			
34FO-15J <i>34FO-15 : 550/J</i>	FLIGHT DIRECTOR REM CRS & HDG SGL SPERRY FACTORY OPTION	*CF		679J FO	MTH 13-Sep-1985		-			



CESCOM 10 - Aircraft Status Report

Owner: **COMMANDER INVESTMENTS LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0068**
 Unit: **0068** Reg No: **N7070A**
 Airworthiness: **13-Sep-1985**
 Print Date: **11-Mar-2020 1:27PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	5509	3775	18-Nov-2019	0
ENG 1	5509	3775	18-Nov-2019	0
ENG 2	5509	3775	18-Nov-2019	0

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
34FO-94F <i>34FO-94 : 550/F</i>	RADIO ALTIMETER SPERRY AA-300 FACTORY OPTION	*CF		673F FO	MTH 13-Sep-1985		-			
35FO-02B <i>35FO-02 : 550/B</i>	OXYGEN SYSTEM 64 CUBIC FEET FACTORY OPTION	*CF		66B FO	MTH 13-Sep-1985		-			
73FO-01C <i>73FO-01 : 550/C</i>	ENGINE SYNCHRONIZING INSTRUMENT W/TH REV FACTORY OPTION	*CF		76C FO	MTH 13-Sep-1985		-			
78FO-01	THRUST REVERSERS FACTORY OPTION	*CF		193 FO	MTH 13-Sep-1985		-			