

Status Report

FALCON 900DX
S/N 615 N232SF

OWNER: WESTPORT RED LLC
ADDRESS: 10773 NW 58 ST. PMB605
MIAMI FL 33178
PHONE:
FAX:

OPERATOR: WESTPORT RED LLC
ADDRESS: 10773 NW 58 ST. PMB605
MIAMI FL 33178
PHONE:
FAX:

OPERATOR: EM TURBINES CORP
ADDRESS: 15001 NW 42ND AVE
OPA LOCKA FL 33054
PHONE:
FAX:

ANALYST: LAMEQA VOGT
EMAIL: LVOGT@CAMPSYSTEMS.COM

+1-631-648-7026 (DIRECT)
877-411-CAMP (2267) (OFFICE)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 615/N232SF **MODEL:** FALCON 900DX **MANUFACTURER:** DASSAULT AVIATION S.A.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	19-OCT-2007	3683.9 A/C HRS	as of 06-SEP-2019	A/C HRS	as of ___/___/___
MANUFACTURER DATE:	19-OCT-2007	2130 AFL	as of 06-SEP-2019	AFL	as of ___/___/___
		3225 APH	as of 17-SEP-2018	APH	as of ___/___/___
		0 APS	as of 05-FEB-2018	APS	as of ___/___/___

APU SERIAL/PART: P-531/3800188-2 **MODEL:** GTCP36-150(F) **MANUFACTURER:** HONEYWELL

INSTALLED ON 20-MAY-2011		LAST ACTUALS		CURRENT ACTUAL	
1368 APU HRS		3225 APU HRS	as of 17-SEP-2018	APU HRS	as of ___/___/___
0 APUS		0 APUS	as of 05-FEB-2018	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: P112719/3060000-4 **MODEL:** TFE731-60-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 14-JUN-2019		LAST ACTUALS		CURRENT ACTUAL	
3636.3 ENG. HRS	0 A/C HRS	3683.9 ENG. HRS	as of 06-SEP-2019	ENG. HRS	as of ___/___/___
2081 ENC		2130 ENC	as of 06-SEP-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: P112720/3060000-4 **MODEL:** TFE731-60-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 15-APR-2015		LAST ACTUALS		CURRENT ACTUAL	
2591.7 ENG. HRS	2591.7 A/C HRS	3683.9 ENG. HRS	as of 06-SEP-2019	ENG. HRS	as of ___/___/___
1611 ENC		2130 ENC	as of 06-SEP-2019	ENC	as of ___/___/___

ENGINE NO. 3 SERIAL/PART: P112691/3060000-4 **MODEL:** TFE731-60-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 15-APR-2015		LAST ACTUALS		CURRENT ACTUAL	
2595.5 ENG. HRS	2591.7 A/C HRS	3683.9 ENG. HRS	as of 06-SEP-2019	ENG. HRS	as of ___/___/___
1612 ENC		2130 ENC	as of 06-SEP-2019	ENC	as of ___/___/___



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
05-07-00-200-800-T01	TRANSITION PACKAGE 1							
	PKG 201	MOS					17-SEP-2018	
		HRS/MSC	-				3480.2	
	REF:	AFL					2027	
<hr/>								
05-07-00-200-800-T02	TRANSITION PACKAGE 2							
	PKG 202	MOS					17-SEP-2018	
		HRS/MSC	-				3480.2	
	REF:	AFL					2027	
<hr/>								
05-07-00-200-800-T03	TRANSITION PACKAGE 3							
	PKG 203	MOS					17-SEP-2018	
		HRS/MSC	-				3480.2	
	REF:	AFL					2027	
<hr/>								
05-08-00-200-800-05	12 M/800 FH INSPECTION							
+								
	PKG 5	MOS	12	+1m			14-JUN-2019	14-JUN-2020
		HRS/MSC	800	+40			3636.3	4436.3
	REF: MPD 05-10-00	AFL					2081	4476.3
<hr/>								
05-08-00-200-800-06	24 M/1600 FH INSPECTION							
+								
	PKG 6	MOS	24	+1m	-26		14-JUN-2019	19-MAY-2021
		HRS/MSC	1600	+40			3636.3	5236.3
	REF: MPD 05-10-00	AFL					2081	5276.3



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-08-00-200-800-07	36 M/2400 FH INSPECTION							
+								
	PKG 7	MOS	36			14-JUN-2019	14-JUN-2022	14-JUL-2022
		HRS/MSC	2400	+1m		3636.3	6036.3	6076.3
	REF: MPD 05-10-00	AFL				2081		
05-08-00-200-800-15	12 M INSPECTION							
+								
	PKG 15	MOS	12			14-JUN-2019	14-JUN-2020	14-JUL-2020
		HRS/MSC		+1m		3636.3		
	REF: MPD 05-10-00	AFL				2081		
05-08-00-200-800-16	24 M INSPECTION							
+								
	PKG 16	MOS	24			14-JUN-2019	19-MAY-2021	19-JUN-2021
		HRS/MSC		+1m	-26	3636.3		
	REF: MPD 05-10-00	AFL				2081		
05-08-00-200-800-17	36 M INSPECTION							
+								
	PKG 17	MOS	36			14-JUN-2019	14-JUN-2022	14-JUL-2022
		HRS/MSC		+1m		3636.3		
	REF: MPD 05-10-00	AFL				2081		
05-08-00-200-800-21	1B INSPECTION							
+								
	PKG 21	MOS				15-JUN-2017		
		HRS/MSC	1600	+40		3125.5	4725.5	4765.5
	REF: MPD 05-10-00	AFL				1867		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-08-00-200-800-22	2B INSPECTION							
+	PKG 22	MOS				15-JUN-2017		
		HRS/MSC	3200	+40		3125.5	6325.5	6365.5
	REF: MPD 05-10-00	AFL				1867		
05-08-00-200-800-23	3B INSPECTION							
+	PKG 23	MOS				19-OCT-2007		
		HRS/MSC	4800	+40	-74.5	0	4725.5	4765.5
	REF: MPD 05-10-00	AFL				0		
05-08-00-200-800-24	4B INSPECTION							
	PKG 24	MOS				19-OCT-2007		
		HRS/MSC	6400	+40	-74.5	0	6325.5	6365.5
	REF: MPD 05-10-00	AFL				0		
05-08-00-200-800-31	1C INSPECTION							
+	PKG 31	MOS	72	+2m		19-NOV-2013	19-NOV-2019	19-JAN-2020
		HRS/MSC				2320.42		
	REF: MPD 05-10-00	AFL	3750			1495	5245	
05-08-00-200-800-32	2C INSPECTION							
+	PKG 32	MOS	144	+2m	31	19-OCT-2007	19-NOV-2019	19-JAN-2020
		HRS/MSC				0		
	REF: MPD 05-10-00	AFL	7500		-2255	0	5245	



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-08-00-200-800-33	3C INSPECTION							
+								
	PKG 33	MOS	216	+2m	31	19-OCT-2007	19-NOV-2025	19-JAN-2026
		HRS/MSC				0		
	REF: MPD 05-10-00	AFL	11250		-2255	0	8995	
<hr/>								
ENGINE NO. 1	Model : TFE731-20/-40/-50/-60	Serial # P112719	Part # 3060000-4					
057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION							
+								
	PKG 1	MOS				17-SEP-2018		
		HRS/MSC	150	+100		3480.2	(3630.2) 3630.2	3730.2
	REF: GENERIC NO REF	ENC				2027		
<hr/>								
057120	NO. 1 ENGINE - 500 TO 650 HOUR INSPECTION							
+								
	PKG 2	MOS				08-DEC-2017		
		HRS/MSC	600	+50		3236.1	(3836.1) 3836.1	3886.1
	REF: GENERIC NO REF	ENC				1920		
<hr/>								
057125	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION							
	PKG 3	MOS				17-SEP-2018		
		HRS/MSC	800	+50		3480.2	(4280.2) 4280.2	4330.2
	REF: GENERIC NO REF	ENC				2027		
<hr/>								
057130	NO. 1 ENGINE - 1000 TO 1300 HOUR INSPECTION							
+								
	PKG 4	MOS				06-APR-2015		
		HRS/MSC	1200	+100		2591.7	(3791.7) 3791.7	3891.7
	REF: GENERIC NO REF	ENC				1611		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#2: S/N P112720

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057135	NO. 1 ENGINE - 1500 TO 1650 HOUR INSPECTION								
	PKG 5	MOS					06-APR-2015		
		HRS/MSC	1600	+50			2591.7	(4191.7) 4191.7	4241.7
	REF: GENERIC NO REF	ENC					1611		
ENGINE NO. 2 Model : TFE731-20/-40/-50/-60 Serial # P112720 Part # 3060000-4									
057110	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION								
+	PKG 1	MOS					17-SEP-2018		
		HRS/MSC	150	+100			3480.2	(3630.2) 3630.2	3730.2
	REF: GENERIC NO REF	ENC					2027		
057120	NO. 2 ENGINE - 500 TO 650 HOUR INSPECTION								
+	PKG 2	MOS					08-DEC-2017		
		HRS/MSC	600	+50			3236.1	(3836.1) 3836.1	3886.1
	REF: GENERIC NO REF	ENC					1920		
057125	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION								
	PKG 3	MOS					17-SEP-2018		
		HRS/MSC	800	+50			3480.2	(4280.2) 4280.2	4330.2
	REF: GENERIC NO REF	ENC					2027		
057130	NO. 2 ENGINE - 1000 TO 1300 HOUR INSPECTION								
+	PKG 4	MOS					07-APR-2015		
		HRS/MSC	1200	+100			2591.7	(3791.7) 3791.7	3891.7
	REF: GENERIC NO REF	ENC					1611		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057135	NO. 2 ENGINE - 1500 TO 1650 HOUR INSPECTION							
	PKG 5	MOS				07-APR-2015		
		HRS/MSC	1600	+50		2591.7	(4191.7) 4191.7	4241.7
	REF: GENERIC NO REF	ENC				1611		
<hr/>								
ENGINE NO. 3 Model : TFE731-20/-40/-50/-60 Serial # P112691 Part # 3060000-4								
057110	NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION							
+	PKG 1	MOS				17-SEP-2018		
		HRS/MSC	150	+100		3480.2	(3630.2) 3630.2	3730.2
	REF: GENERIC NO REF	ENC				2027		
<hr/>								
057120	NO. 3 ENGINE - 500 TO 650 HOUR INSPECTION							
+	PKG 2	MOS				08-DEC-2017		
		HRS/MSC	600	+50		3236.1	(3836.1) 3836.1	3886.1
	REF: GENERIC NO REF	ENC				1920		
<hr/>								
057125	NO. 3 ENGINE - 500 TO 850 HOUR INSPECTION							
	PKG 3	MOS				17-SEP-2018		
		HRS/MSC	800	+50		3480.2	(4280.2) 4280.2	4330.2
	REF: GENERIC NO REF	ENC				2027		
<hr/>								
057130	NO. 3 ENGINE - 1000 TO 1300 HOUR INSPECTION							
+	PKG 4	MOS				08-APR-2015		
		HRS/MSC	1200	+100		2595.5	(3795.5) 3795.5	3895.5
	REF: GENERIC NO REF	ENC				1612		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691
3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057135	NO. 3 ENGINE - 1500 TO 1650 HOUR INSPECTION							
	PKG 5	MOS				08-APR-2015		
	REF: GENERIC NO REF	HRS/MSC ENC	1600	+50		2595.5 1612	(4195.5) 4195.5	4245.5



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
6895-170901	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 7 DATED SEPTEMBER 2017						(EBT)		
REQUIREMENT CHANGE FORMS	REF: GENERIC NO REF	MOS HRS/MSC - AFL							
6895-170901A	REVIEW FALCON 900DX MAINTENANCE MANUAL CHAPTER 5-40 REVISION 10 - SEPTEMBER 2017						(EBT)		
REQUIREMENT CHANGE FORMS	REF: GENERIC NO REF	MOS HRS/MSC - AFL							
APU Model : GTCP36-150(F) Serial # P-531 Part # 3800188-2									
A009-170607	APU - REVIEW GTCP36-150(F) MM REV 7						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF A009	MOS HRS/MSC - APUS							
A009-171115	APU - REVIEW GTCP-150(F) EMM TR 49-42						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF A009	MOS HRS/MSC - APUS							
A009-180112	APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	MOS HRS/MSC - APUS							
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4									
E004-180118	NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM REV 13						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#2: S/N P112720

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E004-180802	NO. 1 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004-180802	MOS HRS/MSC - ENC							

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4

E004-180118	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM REV 13				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							

E004-180802	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004-180802	MOS HRS/MSC - ENC							

ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4

E004-180118	NO. 3 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM REV 13				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							

E004-180802	NO. 3 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004-180802	MOS HRS/MSC - ENC							

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE						19-OCT-2007		
24.220	REF: AMM 05-50-00-100-801	MOS HRS/MSC A/R AFL					0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT								
09.010		MOS					19-OCT-2007		
	REF: AMM 05-50-00-200-801	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-802-01	CHECK AFTER HAILSTORM								
51.050		MOS					19-OCT-2007		
	REF: AMM 05-50-00-200-802	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE								
51.040		MOS					19-OCT-2007		
	REF: AMM 05-50-00-200-803	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING								
32.710		MOS					19-OCT-2007		
	REF: AMM 05-50-00-200-804	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE								
51.030		MOS					19-OCT-2007		
	REF: AMM 05-50-00-200-805	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-806-01	CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS								
		MOS					19-OCT-2007		
	REF: AMM 05-50-00-200-806	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-809-01	INSPECTION AFTER SLAT EXTENSION IN OVERSPEED CONDITION								
57.310		MOS					19-OCT-2007		
	REF: AMM 05-50-00-200-809	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-810-01	INSPECTION AFTER FLAP EXTENSION IN OVERSPEED CONDITION								
57.320	REF: AMM 05-50-00-200-810	MOS HRS/MSC AFL	A/R				19-OCT-2007 0 0		
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION								
	REF: AMM 05-50-00-200-812	MOS HRS/MSC AFL	A/R				19-OCT-2007 0 0		
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING								
	REF: AMM 05-50-00-200-813	MOS HRS/MSC AFL	A/R				19-OCT-2007 0 0		
05-50-00-620-801-01	INSPECTIONS AND ANTI-CORROSION TREATMENTS AT SHORT TIME INTERVAL								
	REF: AMM 05-50-00-620-801	MOS HRS/MSC AFL	A/R				30-AUG-2016 2978 1794		
05-50-00-620-801-02	INSPECTIONS AND ANTI-CORROSION TREATMENTS AT MEDIUM TIME INTERVAL								
	REF: AMM 05-50-00-620-801	MOS HRS/MSC AFL	A/R				19-OCT-2007 0 0		
05-50-00-620-803-01	SPECIFIC MAINTENANCE FOR AIRCRAFT OPERATING IN COLD WEATHER								
05.040	REF: AMM 05-50-00-620-803	MOS HRS/MSC AFL	A/R				11-FEB-2011 1541.42 872		
05-50-00-620-804-01	PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES								
51.070	REF: AMM 05-50-00-620-804	MOS HRS/MSC AFL	A/R				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-620-805-02	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION	MOS					19-OCT-2007		
	REF:	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-801-01	CHECK AND DECONTAMINATION OF THE AIR CONDITIONING SYSTEM AFTER POLLUTION	MOS					19-OCT-2007		
21.540	REF: AMM 05-50-00-700-801	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-803-01	CHECK AFTEER FIRE EXTINGUISHER PERCUSSION	MOS					19-OCT-2007		
20.030	REF: SL 20-350	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-806-01	CHECK AFTER LANDING ON A TAR-MACADAM RUNWAY IN VERY HOT WEATHER	MOS					19-OCT-2007		
32.700	REF: AMM 05-50-00-700-806	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-807-01	ACCOMPLISH CHECK AFTER LANDING ON DRY OR DIRT RUNWAY	MOS					19-OCT-2007		
32.680	REF: AMM 05-50-00-700-807	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING	MOS					19-OCT-2007		
32.670	REF: AMM 05-50-00-700-808	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-810-01	CHECK AFTER A FLIGHT THROUGH SAND	MOS					19-OCT-2007		
	REF: AMM 05-50-00-700-810	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE	MOS					19-OCT-2007		
	REF: AMM 05-50-00-700-818	HRS/MSC AFL	A/R				0 0		
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES	MOS					19-OCT-2007		
	REF: AMM 05-50-00-700-822	HRS/MSC AFL	A/R				0 0		
05-50-00-730-801-01	CHECK AFTER INCIDENT ON THE HYDRAULIC SYSTEM - FILTER CLOGGING	MOS					19-OCT-2007		
29.190	REF: AMM 05-50-00-730-801	HRS/MSC AFL	A/R				0 0		
05-50-00-730-801-02	CHECK AFTER INCIDENT ON THE HYDRAULIC SYSTEM - PUMP FAILURE	MOS					19-OCT-2007		
29.190	REF: AMM 05-50-00-730-801	HRS/MSC AFL	A/R				0 0		
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING	MOS					19-OCT-2007		
	REF: AMM 05-50-00-730-802	HRS/MSC AFL	A/R				0 0		
05-50-00-860-801-01	CHECK AND PREPERATION FOR FLIGHT WITH ONE ENGINE INOPERATIVE	MOS					19-OCT-2007		
	REF: AMM 05-50-00-860-801	HRS/MSC AFL	A/R				0 0		
+ 05-50-00-910-801-01 (s)	PERFORM AIRCRAFT CHECK FLIGHT						PKG		
05.020	PKG 31	MOS	72	+2m			21-NOV-2013		
	REF: AMM 05-50-00-910-801	HRS/MSC AFL					2322.35 1496		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-60-00-200-801-01	PERFORM BASIC INSPECTION								
05.010		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
	REF: See Workcard	HRS/MSC	400	+40			3636.3	4036.3	4076.3
		AFL					2081		
+ 05-60-00-200-801-03	PERFORM BASIC INSPECTION - SERVICING OPERATIONS								
05.010		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
	REF: See Workcard	HRS/MSC	400	+40			3636.3	4036.3	4076.3
		AFL					2081		
10-10-00-550-801-09	PERFORM PRE-STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 8 WEEKS								
		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	A/R				0		
		AFL					0		
CHAPTER 08		LEVELING AND WEIGHING							
+ 08-10-00-910-801-01	WEIGHING THE AIRCRAFT								
		MOS					19-OCT-2007		
	REF:	HRS/MSC	O/C				0		
		AFL					0		
CHAPTER 09		TOWING AND TAXING							
09-10-00-910-810-01	DEBOGGING OF AIRCRAFT								
09.020		MOS					19-OCT-2007		
	REF: AMM 09-10-00-910-810	HRS/MSC	A/R				0		
		AFL					0		
CHAPTER 10		PARKING, MOORING, STORE AND RET TO SERV							
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS								
10.020		MOS					19-OCT-2007		
	REF: AMM 10-10-00-200-801	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10-00-550-801-01	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS								
20.010		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-02	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS TO TWELVE MONTHS								
20.010		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-03	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWELVE MONTHS TO EIGHTEEN MONTHS								
		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-04	PERFORM PERIODIC CHECKS EVERY MONTH DURING THE STORAGE PERIOD								
20.010		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-05	PERFORM PERIODIC (STORAGE) CHECKS EVERY TWO MONTHS								
20.010		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-06	PERFORM PERIODIC CHECKS EVERY SIX MONTHS DURING THE STORAGE PERIOD								
20.010		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-07	REMOVAL OF AIRCRAFT FROM STORAGE AFTER TWO MONTHS								
20.010		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10-00-550-801-08	REMOVAL OF THE AIRCRAFT FROM STORAGE AFTER MORE THAN TWO MONTHS								
20.010		MOS					19-OCT-2007		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C				0		
		AFL					0		
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL								
10.010		MOS					19-OCT-2007		
	REF: AMM 10-20-00-910-802	HRS/MSC	A/R				0		
		AFL					0		
CHAPTER 11 PLACARDS AND MARKINGS									
11-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE INTERIOR AND EXTERIOR PLACARDS						PKG		
	PKG 31	MOS	72	+2m			05-MAR-2014		
		HRS/MSC					2375.55		
SMM	REF: AMM 11-00-00-210-801	AFL	3750				1530		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
20-30-00-330-801-01	TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT								
51.060		MOS					19-OCT-2007		
	REF: AMM 20-30-00-330-801	HRS/MSC	A/R				0		
		AFL					0		
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR								
20.020		MOS					19-OCT-2007		
	REF: SL 20-318	HRS/MSC	A/R				0		
		AFL					0		
20-31-00-910-801-01	ACCOMPLISH GROUND DE-ICING AND PREVENTIVE ANTI-ICING PROCEDURE								
20.050		MOS					19-OCT-2007		
	REF: SL 20-625	HRS/MSC	A/R				0		
		AFL					0		
20-33-00-300-804-01	TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS								
		MOS					19-OCT-2007		
	REF: AMM 20-33-00-300-804	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20-41-00-910-801-01	TIGHTENING TORQUES FOR SINGLE FLARE COUPLINGS	MOS					19-OCT-2007		
	REF:	HRS/MSC	O/C				0		
		AFL					0		
20-60-00-370-813-01	ACCOMPLISH PAINT REMOVAL ON COMPOSITE HORIZONTAL STABILIZER	MOS					19-OCT-2007		
20.040	REF: SL 20-615	HRS/MSC	A/R				0		
		AFL					0		
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (L2GF)	MOS					19-OCT-2007		
	D22801500	HRS/MSC	O/C				0		
	B223	AFL					0		
	REF:								
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (R2GF)	MOS					19-OCT-2007		
	D22802500	HRS/MSC	O/C				0		
	B223	AFL					0		
	REF:								
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (L2GF5)	MOS					19-OCT-2007		
	PN	HRS/MSC	O/C				0		
	SN-UNKNOWN	AFL					0		
	REF:								
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (R2GF5)	MOS					19-OCT-2007		
	PN	HRS/MSC	O/C				0		
	SN-UNKNOWN	AFL					0		
	REF:								
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (3GF)	MOS					19-OCT-2007		
	D22811500-2	HRS/MSC	O/C				0		
	B226	AFL					0		
	REF:								

CHAPTER 21 AIR CONDITIONING

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20-01-350-801-01	RESTORATION LEFT AIR FLOW LIMITER (OVERHAUL) 2742A020100 00856 REF: AMM 21-20-01-350-801	MOS HRS/MSC AFL	4800	+3%			19-OCT-2007 0 0	4800	4944
21.040 OVERHAUL									
21-20-01-350-801-02	RESTORATION RIGHT AIR FLOW LIMITER (OVERHAUL) 2742A020100 00857 REF: AMM 21-20-01-350-801	MOS HRS/MSC AFL	4800	+3%			19-OCT-2007 0 0	4800	4944
21.040 OVERHAUL									
21-20-01-900-801-01	LEFT AIR FLOW LIMITER 2742A020100 00856 REF: AMM 21-20-01-900-801	MOS HRS/MSC AFL	H/T		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
21.040									
21-20-01-900-801-02	RIGHT AIR FLOW LIMITER 2742A020100 00857 REF: AMM 21-20-01-900-801	MOS HRS/MSC AFL	H/T		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
21.040									
+ 21-30-00-790-802-01 (s)	IN-FLIGHT CHECK OF THE CABIN SEALING PKG 21 REF: AMM 21-30-00-790-802	MOS HRS/MSC AFL	1600	+40			PKG 15-JUN-2017 3125.5 1867		
21.160									
21-30-01-900-801-01	CABIN PRESSURIZATION CONTROLLER 92162A010101 00275 REF: AMM 21-30-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
21.520									
+ 21-31-00-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM PNEUMATIC ACTUATOR PKG 21 REF: AMM 21-31-00-720-801	MOS HRS/MSC AFL	1600	+40			PKG 15-JUN-2017 3125.5 1867		
21.220									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-31-00-720-801-02 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM PRESSURE RELIEF VALVE						PKG		
21.220	PKG 21 REF: AMM 21-31-00-720-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 21-31-01-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE OVERHEAT INDICATING SYSTEM						PKG		
21.020	PKG 21 REF: AMM 21-31-01-720-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
21-31-09-350-801-01 (s)	RESTORATION NOSE CONE FAN (REPLACEMENT OF BEARINGS)								
21.050	AE1103A01 00589 REF: AMM 21-31-09-350-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
21-31-09-900-801-01	NOSE CONE FAN								
21.050	AE1103A01 00589 REF: AMM 21-31-09-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 21-32-00-710-801-01 (s)	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM						PKG		
21.170	PKG 21 REF: AMM 21-32-00-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 21-32-00-710-802-01 (s)	OPERATIONAL TEST OF THE PRESSURIZATION SYSTEM EMERGENCY SUPPLY						PKG		
21.180	PKG 21 REF: AMM 21-32-00-710-802	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 21-32-00-790-801-01 (s)	LEAK CHECK AROUND THE LEFT STATIC PRESSURE PROBE						PKG		
21.530 RVSM	PKG 16 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-00-790-801-02 (s)	LEAK CHECK AROUND THE RIGHT STATIC PRESSURE PROBE						PKG		
21.530	PKG 16	MOS	24	+1m			14-JUN-2019		
RVSM	REF: AMM 21-32-00-790-801	HRS/MSC					3636.3		
		AFL					2081		
21-32-00-790-801-03 (s)	LEAK CHECK AROUND THE LEFT STAND-BY STATIC PRESSURE PROBE						PKG		
	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 21-32-00-790-801	HRS/MSC					3636.3		
		AFL					2081		
21-32-00-790-801-04 (s)	LEAK CHECK AROUND THE RIGHT STAND-BY STATIC PRESSURE PROBE						PKG		
	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 21-32-00-790-801	HRS/MSC					3636.3		
		AFL					2081		
21-32-06-200-801-01	CLEANING MAIN ELECTRO-PNEUMATIC REGULATION VALVE SEAT								
21.230	2097N030700	MOS					08-NOV-2018		
	02466	HRS/MSC	1640	+3%			3516.7	5156.7	5205.9
	REF: AMM 21-32-06-200-801	AFL					2041		
21-32-06-200-801-02	CLEANING EMERGENCY PNEUMATIC REGULATION VALVE SEAT								
21.240	2099P030700	MOS					08-NOV-2018		
	02425	HRS/MSC	1640	+3%			3516.7	5156.7	5205.9
	REF: AMM 21-32-06-200-801	AFL					2041		
+ 21-32-06-200-801-03	CHECK MAIN ELECTRO-PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS								
21.230	2097N030700	MOS					08-NOV-2018		
	02466	HRS/MSC	1640				3516.7	5156.7	
	REF: AMM 21-32-06-200-801	AFL					2041		
21-32-06-200-801-03A	CHECK MAIN ELECTRO-PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)								
21.230	2097N030700	MOS					08-NOV-2018		
CMR	02466	HRS/MSC	1640				3516.7	5156.7	
	REF: AMM 21-32-06-200-801	AFL					2041		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-32-06-200-801-04	CHECK EMERGENCY PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS								
21.240	2099P030700 02425 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				08-NOV-2018 3516.7 2041	5156.7	
21-32-06-200-801-04A	CHECK EMERGENCY PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)								
21.240 CMR	2099P030700 02425 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				08-NOV-2018 3516.7 2041	5156.7	
21-32-06-200-801-05	CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES								
21.535	REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640	+3%			14-JUN-2019 3636.3 2081	5276.3	5325.5
21-32-06-200-801-05A	CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY REF. 05-40/20)								
21.535 CMR	REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	7500				14-JUN-2019 3636.3 2081	11136.3	
+ 21-32-06-720-801-01	FUNCTIONAL TEST MAIN ELECTRO-PNEUMATIC REGULATION VALVE								
21.230	2097N030700 02466 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	4840	+3%			19-OCT-2007 0 0	4840	4985.2
+ 21-32-06-720-801-01A	FUNCTIONAL TEST MAIN ELECTRO-PNEUMATIC REGULATION VALVE (MANDATORY REF. 5-40/20)								
21.230 CMR	2097N030700 02466 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	8860				19-OCT-2007 0 0	8860	
+ 21-32-06-720-801-02	FUNCTIONAL TEST EMERGENCY PNEUMATIC REGULATION VALVE								
21.240	2099P030700 02425 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	4840	+3%			19-OCT-2007 0 0	4840	4985.2

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-32-06-720-801-02A	FUNCTIONAL TEST EMERGENCY PNEUMATIC REGULATION VALVE (MANDATORY REF. 5-40/20)								
21.240	2099P030700 02425 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	8860				19-OCT-2007 0 0	8860	
21-32-06-900-801-01	MAIN ELECTRO-PNEUMATIC REGULATION VALVE								
21.230	2097N030700 02466 REF: AMM 21-32-06-900-801	MOS HRS/MSC AFL	O/C	TSN:48 TSN:1768.92 TSN:1063			12-OCT-2011 1768.92 1063		
21-32-06-900-802-01	EMERGENCY PNEUMATIC REGULATION VALVE								
21.240	2099P030700 02425 REF: AMM 21-32-06-900-802	MOS HRS/MSC AFL	O/C	TSN:48 TSN:1768.92 TSN:1063			12-OCT-2011 1768.92 1063		
+ 21-32-17-200-801-01 (s)	INSPECTION OF THE LH BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG		
21.190	PKG 21 REF: AMM 21-32-17-200-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
21-32-17-200-801-02 (s)	INSPECTION OF THE RH BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG		
	PKG 21 REF: AMM 21-32-17-200-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 21-32-17-720-801-01 (s)	FUNCTIONAL TEST OF THE LH BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG		
21.200	PKG 31 REF: AMM 21-32-17-720-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
21-32-17-720-801-02 (s)	FUNCTIONAL TEST OF THE RH BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG		
	PKG 31 REF: AMM 21-32-17-720-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-33-710-801-01	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE								
21.030	PKG 5 REF: AMM 21-32-33-710-801	MOS HRS/MSC AFL	12 800	+1m +40			14-JUN-2019 3636.3 2081	14-JUN-2020 4436.3	14-JUL-2020 4476.3
+ 21-32-37-200-801-01 (s)	INSPECTION OF THE NEGATIVE PRESSURE RELIEF VALVES IN BAGGAGE COMPARTMENT								
21.210	PKG 21 REF: AMM 21-32-37-200-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 21-32-37-720-801-01	FUNCTIONAL TEST LH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 1345 REF: AMM 21-32-37-720-801	MOS HRS/MSC AFL	4000	+3%			19-OCT-2007 0 0	4000	4120
+ 21-32-37-720-801-02	FUNCTIONAL TEST RH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 1346 REF: AMM 21-32-37-720-801	MOS HRS/MSC AFL	4000	+3%			19-OCT-2007 0 0	4000	4120
+ 21-32-41-200-801-01 (s)	INSPECTION OF THE NICOTINE CABIN AIR FILTER CARTRIDGE								
21.250	PKG 31 REF: AMM 21-32-41-200-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 21-52-00-710-801-01 (s)	OPERATIONAL TEST OF THE WATER REINJECTION SYSTEM								
21.400	PKG 22 REF: AMM 21-52-00-710-801	MOS HRS/MSC AFL	3200	+40			15-JUN-2017 3125.5 1867		
21-52-05-350-801-01	RESTORATION TURBO COOLING UNIT (OVERHAUL)								
21.350 OVERHAUL	3269B0202 280 REF: AMM 21-52-05-350-801	MOS HRS/MSC AFL	3000	+3%				? ?	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-52-05-610-801-01	TURBOCOOLER OIL SERVICING - TURBOCOOLER (504HN) OIL TOP-UP	MOS					14-JUN-2019		
21.545	REF:	HRS/MSC AFL	200	+10%			3636.3 2081	3836.3	3856.3
21-52-05-610-801-02 (s)	DRAINING AND REFILLING OF THE TURBO COOLING UNIT TURBOCOOLER OIL	MOS	12	+1m			14-JUN-2019		
21.350	PKG 5,201 REF: AMM 21-52-05-610-801	HRS/MSC AFL	800	+40			3636.3 2081		
+ 21-52-05-700-801-01	TURBOCOOLER OIL LEVEL CHECK - TURBOCOOLER (504HN)	MOS					17-SEP-2018		
	REF: AMM 21-52-05-700-801	HRS/MSC AFL	O/C				3480.2 2027		
21-52-05-900-801-01	TURBO COOLING UNIT	MOS					14-JUN-2019		
21.350	3269B0202 280 REF: AMM 21-52-05-900-801	HRS/MSC AFL	H/T				3636.3 2081		
+ 21-52-09-210-802-01	GENERAL VISUAL INSPECTION OF THE ECU HEAT EXCHANGER GRID	MOS					14-JUN-2018		
21.360	REF: AMM 21-52-09-210-802	HRS/MSC AFL	O/C				3406.6 1988		
21-52-18-100-801-01	CLEANING OF THE HP WATER SEPARATOR FILTER	MOS	24	+1m	-26		14-JUN-2019	19-MAY-2021	19-JUN-2021
21.370	REF: AMM 21-52-18-100-801	HRS/MSC AFL	1200	+40			3636.3 2081	4836.3	4876.3
+ 21-52-19-200-801-01	INSPECTION/CHECK OF THE LP WATER SEPARATOR COMPONENTS	MOS	6	+1m	-89		14-JUN-2019	17-SEP-2019	17-OCT-2019
21.380	REF: AMM 21-52-19-200-801	HRS/MSC AFL					3636.3 2081		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-21-350-801-01	RESTORATION TURBO FAN (OVERHAUL)								
21.410	TVT107-28H4	MOS					19-OCT-2007		
OVERHAUL	00625	HRS/MSC					0		
	REF: AMM 21-52-21-350-801	AFL	3000	+3%			0	3000	3090
21-52-21-900-801-01	TURBO FAN								
21.410	TVT107-28H4	MOS		TSN:0			19-OCT-2007		
	00625	HRS/MSC	H/T	TSN:0			0		
	REF: AMM 21-52-21-900-801	AFL		TSN:0			0		
21-52-33-900-801-01	TURBINE ANTI-ICING ELECTRIC VALVE								
21.390	784723-3	MOS		TSR:3			20-MAR-2011		
	822	HRS/MSC	O/C	TSR:0			1585.92		
	REF: AMM 21-52-33-900-801	AFL		TSR:0			897		
+ 21-67-01-220-801-01	DETAILED INSPECTION OF THE AFT SATCOM RACK FAN								
		MOS					19-MAY-2017		
		HRS/MSC	O/C				3080		
	REF: AMM 21-67-01-220-801	AFL					1850		
21-67-09-710-801-01	OPERATIONAL TEST OF THE AFT SATCOM RACK COOLING VALVE								
		MOS					19-MAY-2017		
		HRS/MSC	O/C				3080		
	REF: AMM 21-67-09-710-801	AFL					1850		
+ 21-71-01-350-801-01	RESTORATION LEFT OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)								
36.010	20425-1	MOS					19-OCT-2007		
	6523	HRS/MSC	5000	+3%			0	5000	5150
	REF: AMM 21-71-01-350-801	AFL					0		
+ 21-71-01-350-801-02	RESTORATION RIGHT OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)								
36.010	20425-1	MOS					19-OCT-2007		
	6522	HRS/MSC	5000	+3%			0	5000	5150
	REF: AMM 21-71-01-350-801	AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-90-01-900-801-01	AFT SATCOM RACK B97-26-555 C60553 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
212801	COCKPIT CONDITIONING ELECTRIC VALVE BYLB51003 1142 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212806	CABIN CONDITIONING ELECTRIC VALVE BYLB51003 1147 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212811	BAGGAGE COMPARTMENT SUPPLY ELECTRIC VALVE B97-26-551 C60607 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212816	BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE 3188-000 445 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212821	AERATOR CHECK VALVE CYLB50712 836 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212826	CREW COLD AIR CHECK VALVE CYLB51162-2 834 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212831	PASSENGER COLD AIR CHECK VALVE								
21.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
212836	CREW AIR CONDITIONING CHECK VALVE								
21.110	CYLB51111 817 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212841	PASSENGERS AIR CONDITIONING CHECK VALVE								
21.110	CYLB51111 833 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212846	AERATOR PRESSURE REGULATING VALVE								
21.120	3313-300 682 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212851	NOSE CONE PNEUMATIC ACTUATOR								
21.130	7021-200 C88801 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			15-JUN-2017 3125.5 1867		
212856	NOSE CONE OVERPRESSURE VALVE								
21.140	6025-300 C69750 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
212861	NOSE CONE THERMOSTAT								
21.150	784756-1 990 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213801	CROSS-FEED VALVE								
21.280	VC1005-1 0690 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
213806	CABIN AUTOMATIC ALTITUDE CONTROL								
21.290	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
213811	EMERGENCY PRESSURIZATION CONTROLLER								
21.300	912AB0102 00534 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
213816	LH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 1345 REF: AMM 21-32-37-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
213821	RH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 1346 REF: AMM 21-32-37-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
213826	NO. 1 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE								
21.310	985C63-21 F94600 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
213831	NO. 2 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE								
21.310	985C63-21 F49999 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213836	NO. 1 HP/LP TURBINE BRAKE CHECK VALVE 33409001	MOS		TSN:0			19-OCT-2007		
21.320	0537 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213841	NO. 2 HP/LP TURBINE BRAKE CHECK VALVE 33409001	MOS		TSN:0			19-OCT-2007		
21.320	0538 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213846	NO. 1 ENGINE PRESSURE SUPPLY CHECK VALVE 33409001	MOS		TSN:0			19-OCT-2007		
21.330	0539 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213851	NO. 2 ENGINE PRESSURE SUPPLY CHECK VALVE 33409001	MOS		TSN:0			19-OCT-2007		
21.330	0540 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213856	APU SUPPLY PRESSURE CHECK VALVE 33409001	MOS		TSN:0			19-OCT-2007		
21.330	0541 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213861	ALTITUDE/DELTA P TRIPLE INDICATOR PN	MOS		TSN:0			19-OCT-2007		
21.260	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213866	PRESSURIZATION JET PUMP FGFB722602A2	MOS		TSN:0			19-OCT-2007		
21.340	667 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215801	PRIMARY HEAT EXCHANGER								
21.420	11-831149-2 E0428 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
215811	HP WATER SEPARATOR								
21.370	8903D04 00570 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:36 TSN:0 TSN:0			14-OCT-2015 2761.8 1696		
215816	LP WATER SEPARATOR								
21.380	B31WA3023 00662 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			17-SEP-2018 3480.2 2027		
215821	TURBINE ANTI-ICING TUBING SENSOR								
21.430	784646 749 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
215831	TURBINE ANTI-ICING AMPLIFIER								
21.440	784688-1 0576 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
215836	BLOWER BY-PASS ELECTRIC VALVE								
21.450	BYLB51035-1 656 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
215841	ECU OVERHEATING SENSOR								
21.460	RP482-00 DAAA00219 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215A04	COALESCER B31WA3010-053 01563 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-MAY-2017 3080 1850		
215A05	COALESCER SLEEVE B31WA3010-053 00977 REF:	MOS HRS/MSC AFL	O/C	TSR:5 TSR:0 TSR:0			12-OCT-2011 1768.92 1063		
216801	COCKPIT THERMOSTAT 150T346 1663 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
216806	CABIN THERMOSTAT 150T346 1664 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
216811	CABIN TEMPERATURE REGULATION DUAL ELECTRIC VALVE BYLB51226-002 448 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
216816	COCKPIT TEMPERATURE REGULATION DUAL ELECTRIC VALVE BYLB51034-003 452 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
216821	COCKPIT DUCT TEMPERATURE SENSOR AYLF50425 2541 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216826	CABIN DUCT TEMPERATURE SENSOR								
21.490	AYLF50425 2542 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
216831	COCKPIT THERMO RESISTOR								
21.500	HYLZ-50514-043 1574J REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-OCT-2017 3218.6 1910		
216836	CABIN THERMO RESISTOR								
21.500	HYLZ50514-042 1660J REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-JAN-2009 729.67 403		
216841	CONDITIONING PANEL								
21.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
216A01	CABIN TEMPERATURE CONTROLLER								
	990-8000-008 07050039264 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
21GJL01	PLUMBING SUPPLY OF WINDSHIELD ASSY, (LH)								
CUSTOMER CODE	308A0641914 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2011 1587.08 899		
CHAPTER 22		AUTO FLIGHT							
22-00-05-900-801-01	NO. 2A ACTUATOR I/O (AIOP MODULE 2A) MODULE								
22.050	7028432-1902 1308G952 REF: AMM 22-00-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-00-05-900-801-02	NO. 1A ACTUATOR I/O (AIOP MODULE 1A) MODULE								
22.050	7028432-1902 1308G956 REF: AMM 22-00-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
22-00-05-900-801-02	NO. 2B ACTUATOR I/O (AIOP MODULE 2B) MODULE								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
22-00-05-900-801-03	NO. 1A ACTUATOR I/O (AIOP MODULE 1A) MODULE								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
22-00-05-900-801-03	NO. 2B ACTUATOR I/O (AIOP MODULE 2B) MODULE								
22.050	7028432-1902 1308G996 REF: AMM 22-00-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
22-00-05-900-801-04	NO. 1B ACTUATOR I/O (AIOP MODULE 1B) MODULE								
22.050	7028432-1902 1308G985 REF: AMM 22-00-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
+ 22-10-00-710-801-01	OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)								
22.080	PKG 16 REF: AMM 22-10-00-710-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081	14-JUN-2021	14-JUL-2021
RVSM									
22-10-01-900-801-01	AILERON AUTOPILOT SERVO MOTOR								
22.020	6256-173 1537 REF: AMM 22-10-05-900-801	MOS HRS/MSC AFL	O/C				11-JUL-2012 2003.08 1244		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-10-07-700-801-01 (s)	CHECK OF THE AILERON AUTOPILOT SERVO MOTOR CABLES AND PULLEY						PKG		
22.020	PKG 31	MOS	72	+2m			19-NOV-2013		
RVSM	REF: AMM 22-10-07-700-801	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 22-10-07-700-801-02 (s)	CHECK OF THE ELEVATOR AUTOPILOT SERVO MOTOR CABLES AND PULLEY						PKG		
22.030	PKG 31	MOS	72	+2m			19-NOV-2013		
RVSM	REF: AMM 22-10-07-700-801	HRS/MSC					2320.42		
		AFL	3750				1495		
22-13-01-900-801-01	YAW DAMPER LINEAR ACTUATOR								
22.040	3-8486-3	MOS					04-JUN-2010		
	1557	HRS/MSC	O/C				1265.33		
	REF: AMM 22-13-01-900-801	AFL					706		
22-30-05-900-801-01	NO. 1 ENGINE AUTOTHROTTLE SERVO MOTOR								
22.070	6256-171	MOS			TSN:0		19-OCT-2007		
	441	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 22-30-05-900-801	AFL			TSN:0		0		
22-30-05-900-801-02	NO. 2 ENGINE AUTOTHROTTLE SERVO MOTOR								
22.070	6256-171	MOS					11-AUG-2011		
	226	HRS/MSC	O/C				1726.83		
	REF: AMM 22-30-05-900-801	AFL					1024		
22-30-05-900-801-03	NO. 3 ENGINE AUTOTHROTTLE SERVO MOTOR								
22.070	6256-171	MOS					01-JUL-2011		
	452	HRS/MSC	O/C				1670.33		
	REF: AMM 22-30-05-900-801	AFL					991		
221012	ELEVATOR AUTOPILOT SERVO MOTOR								
22.030	6256-173	MOS			TSN:0		19-OCT-2007		
	576	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 22-10-05-900-801	AFL			TSN:0		0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221801	GUIDANCE PANEL								
22.060	7028660-903 06100345 REF: AMM 22-10-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 23 COMMUNICATIONS									
23-11-05-900-801-01	NO. 1 VHF ANTENNA								
23.080	21-38-2 9862 REF: AMM 23-11-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-AUG-2010 1404.83 769		
23-11-05-900-801-02	NO. 2 VHF ANTENNA								
23.080	S65-8280-10 310-14182 REF: AMM 23-11-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
23-11-05-900-801-03	NO. 3 VHF ANTENNA								
23.080	S65-8280-10 310-16521 REF: AMM 23-11-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
23-11-07-900-801-01	NO. 1 VDR MODULE								
23.090	7026201-812 04020571 REF: AMM 23-11-07-900-801	MOS HRS/MSC AFL	O/C				19-DEC-2011 1832.42 1109		
23-11-07-900-801-02	NO. 2 VDR MODULE								
23.090	7026201-812 08044518 REF: AMM 23-11-07-900-801	MOS HRS/MSC AFL	O/C				23-JUN-2011 1665.92 985		
23-11-09-900-801-01	NO. 3 VDR MODULE								
23.090	7026201-814 08125799 REF: AMM 23-11-09-900-801	MOS HRS/MSC AFL	O/C				15-APR-2015 2591.7 1611		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-11-17-710-801-01 (s)	OPERATIONAL TEST OF THE "VHF 1 EMER" RADIO TUNING SWITCH						PKG		
23.010	PKG 21 REF: AMM 23-11-17-710-801	MOS HRS/MSC AFL	1600 +40				15-JUN-2017 3125.5 1867		
23-11-17-710-801-01A	OPERATIONAL TEST "VHF 1 EMER" RADIO TUNING SWITCH (MANDATORY REF 5-40/20)								
23.010 CMR	PN SN-UNKNOWN REF: AMM 23-11-17-710-801	MOS HRS/MSC AFL	1640				15-JUN-2017 3125.5 1867	4765.5	
23-12-01-900-801-01	NO. 1 HF TRANSCEIVER								
23.030	822-0102-001 2974 REF: AMM 23-12-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
23-12-01-900-801-02	NO. 2 HF TRANSCEIVER								
23.030	822-0102-001 2947 REF: AMM 23-12-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
23-12-09-900-801-01	NO. 1 AMPLIFIER COUPLER								
23.040	622-8114-002 6911 REF: AMM 23-12-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
23-12-09-900-801-02	NO. 2 AMPLIFIER COUPLER								
23.040	622-8114-002 6892 REF: AMM 23-12-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
23-12-13-900-801-01	HF ANTENNA								
23.020	F50B312001B2 TED467 REF: AMM 23-12-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-17-47-710-801-01	OPERATIONAL TEST OF THE COCKPIT RINGER INHIBIT FUNCTION	MOS					19-MAY-2017		
	REF: AMM 23-17-47-710-801	HRS/MSC AFL	O/C				3080 1850		
+ 23-50-00-710-802-01 (s)	OPERATIONAL TEST PILOT "BKUP" AUDIO SWITCH	MOS					PKG		
23.140	PKG 21	HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
	REF: AMM 23-50-00-710-802								
23-50-00-710-802-01A	OPERATIONAL TEST PILOT "BKUP" AUDIO SWITCH (MANDATORY REF 5-40/20)	MOS					15-JUN-2017		
23.140	REF: AMM 23-50-00-710-802	HRS/MSC AFL	1640				3125.5 1867		4765.5
CMR									
+ 23-50-00-710-802-02 (s)	OPERATIONAL TEST COPILOT "BKUP" AUDIO SWITCH	MOS					PKG		
23.140	PKG 21	HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
	REF: AMM 23-50-00-710-802								
23-50-00-710-802-02A	OPERATIONAL TEST COPILOT "BKUP" AUDIO SWITCH (MANDATORY REF 5-40/20)	MOS					15-JUN-2017		
23.140	REF: AMM 23-50-00-710-802	HRS/MSC AFL	1640				3125.5 1867		4765.5
CMR									
+ 23-60-00-760-801-01 (s)	CHECK OF STATIC DISCHARGER, CONDITION, RESISTANCE AND BONDING	MOS					PKG		
23.130	PKG 21	HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
	REF: AMM 23-60-00-760-801								
231826	NO. 1 HF CONTROL UNIT	MOS					19-OCT-2007		
23.050	PN	HRS/MSC AFL	O/C		TSN:0		0		
	SN-UNKNOWN				TSN:0		0		
	REF: GENERIC NO REF				TSN:0		0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231831	NO. 2 HF CONTROL UNIT								
23.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
231836	NO. 1 HF BRIDGING AMPLIFIER								
23.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
231841	NO. 2 HF BRIDGING AMPLIFIER								
23.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
231846	HF DUAL CAPACITOR								
23.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
231871	NO. 1 VHF CONTROL								
23.100	7511900-94102 06103014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:1400.92 TSN:765			19-AUG-2010 1400.92 765		
231876	NO. 2 VHF CONTROL								
23.100	7511900-94102 06082805 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:1400.92 TSN:765			19-AUG-2010 1400.92 765		
231879	NO. 3 VHF CONTROL								
23.100	7026240-901 07020952 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231881	"VHF 1 EMER" RADIO TUNING SWITCH								
23.010	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
231A08	SIGMA7 HANDSET								
	500905-20-02-1 0607-3387 REF:	MOS HRS/MSC AFL	O/C				09-FEB-2011 1541.42 872		
231A28	NO. 1 WIRELESS LAN ANTENNA								
	S65-5366-31S 235-0429 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
231A29	NO. 2 WIRELESS LAN ANTENNA								
	S65-5366-31S 235-0444 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
231A32	SATCOM #1 ANTENNA								
	0476-A-00377 1360 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
231A34	SATCOM HIGH POWER AMPLIFIER								
	405014A-THD 81009319 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		
231A35	SATCOM DATA UNIT								
	405035A-THD 80990272 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231A36	ANTENNA SATCOM DRIVER 0811-A-0001 1462 REF:	MOS HRS/MSC AFL	O/C				08-JUN-2012 1972.17 1216		
231A37	SATCOM DUPLEXER 405013A 1435-0015 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		
231A40	CONFIGURATION SATCOM MODULE 40540A-001 80990015 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		
231A60	SATCOM DATA ROUTER 1233-F-2191-10 373 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		
231A68	COCKPIT PRINTER 700750-1415 48401159 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			01-APR-2009 816 444		
231B03	NO. 1 CABIN SATELLITE TELEPHONE CORDLESS HANDSET 463092-110 227721 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-NOV-2013 2322.35 1496		
231B09	NO. 1 PHONE HANDSET 405621B-THW 81011235 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231B10	NO. 2 PHONE HANDSET 405622B-THW 81018896 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		
231B36	LH#1 CABIN SPEAKERS 990-4019-002 07050039324 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2006 0 0		
231B37	LH#2 CABIN SPEAKERS 990-4019-002 07050039325 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2006 0 0		
231B38	LH#3 CABIN SPEAKERS 990-4019-002 07050039326 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2006 0 0		
231B39	LH#4 CABIN SPEAKERS 990-4019-002 07050039327 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2006 0 0		
231B40	LH#5 CABIN SPEAKERS 990-4019-002 07050039328 REF:	MOS HRS/MSC AFL	O/C						
231B41	RH#1 CABIN SPEAKER 990-4019-002 07050039329 REF:	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231B42	RH#2 CABIN SPEAKERS 990-4019-002 07050039330 REF:	MOS HRS/MSC AFL	O/C						
231B43	RH#3 CABIN SPEAKERS 990-4019-002 07050039331 REF:	MOS HRS/MSC AFL	O/C						
231B44	RH#4 CABIN SPEAKERS 990-4019-002 07050039332 REF:	MOS HRS/MSC AFL	O/C						
231B45	RH#5 CABIN SPEAKERS 990-4019-002 07050039607 REF:	MOS HRS/MSC AFL	O/C						
232801	SELCAL RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
2332A1	IR SENSOR 990-4131-001 02040003650 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2009 1054.5 582		
233806	PILOT AUDIO CONTROL 7511900-94102 07073859 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233811	COPILOT AUDIO CONTROL								
23.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
233A06	PA AMPLIFIER								
	990-4132-002 07050039097 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233A07	PA NO.2 AMPLIFIER								
	990-4132-002 07050039098 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233A15	VIDEO CABIN FWD MONITOR-								
	990-4177-106 07010035427 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233A41	DISC VIDEO PLAYER								
	996-4718-001 07050039140 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233A42	NO. 2 DISC VIDEO PLAYER								
	996-4720-001 12100065579 REF:	MOS HRS/MSC AFL	O/C				01-FEB-2013 2161.42 1362		
233A53	MHR RECEIVER								
	990-6913-001 07110044970 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2009 1054.5 582		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233B01	CABIN MANAGEMENT SYSTEM ENVIRONMENT CONTROLLER 990-6812-001 07050039433 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233B02	CABIN MANAGEMENT SYSTEM ENTERTAINMENT CONTROLLER 990-6800-004 07050039278 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233B03	CABIN MANAGEMENT SYSTEM PROGRAMMING INTERFACE 990-6820-001 07030037353 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233B15	CABIN MANAGEMENT SYSTEM REMOTE CONTROL 990-2116-113 07060039634 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233B41	NO. 1 CABIN PLUG-IN MONITOR RECEPTACLE 0100-042 0701K146 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233B42	NO. 2 CABIN PLUG-IN MONITOR RECEPTACLE 0100-042 0701K148 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
233B43	NO. 3 CABIN PLUG-IN MONITOR RECEPTACLE 0100-042 0701K157 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
233B44	NO. 4 CABIN PLUG-IN MONITOR RECEPTACLE 0100-042 0701K172 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0			
233B51	NO. 1 LEFT 8.4" MONITOR- 8403-037 0705E072 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0			
233B52	NO. 1 RIGHT 8.4" MONITOR- 8403-037 0705E073 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0			
233B53	NO. 2 LEFT 8.4" MONITOR- 8403-037 0705E015 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0			
233B60	MAIN ENTRANCE DOOR CABIN MANAGEMENT SYSTEM (MHS/MHL) SWITCH PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C							
237A06	DISPLAY CABIN CONTROL 990-5750-001 07060039649 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0			
CHAPTER 24 ELECTRICAL POWER										
+ 24-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE FEEDTHROUGH 11FT / 12FT						PKG			
	PKG 16	MOS	24	+1m			14-JUN-2019			
		HRS/MSC					3636.3			
	REF: AMM 24-00-00-220-801	AFL					2081			

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-20-05-710-801-01 (s)	OPERATIONAL TEST OF THE GROUND FAULT (GFI) INTERRUPTER PKG 21	DAYS		+40			PKG 17-SEP-2018		
SMM	REF: AMM 24-20-05-710-801	HRS/MSC AFL	1600	+40			3480.2 2027		
+ 24-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE VOLTAGE MONITORING CIRCUITS PKG 21	MOS					PKG 15-JUN-2017		
24.030	REF: AMM 24-30-00-710-801	HRS/MSC AFL	1600	+40			3125.5 1867		
24-30-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 ENGINE VOLTAGE MONITORING CIRCUIT PKG 21	MOS					PKG 15-JUN-2017		
24.030	REF: AMM 24-30-00-710-801	HRS/MSC AFL	1600	+40			3125.5 1867		
24-30-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 ENGINE VOLTAGE MONITORING CIRCUIT PKG 21	MOS					PKG 15-JUN-2017		
24.030	REF: AMM 24-30-00-710-801	HRS/MSC AFL	1600	+40			3125.5 1867		
24-30-00-710-801-04 (s)	OPERATIONAL TEST OF THE APU VOLTAGE MONITORING CIRCUIT PKG 21	MOS					PKG 15-JUN-2017		
24.030	REF: AMM 24-30-00-710-801	HRS/MSC AFL	1600	+40			3125.5 1867		
+ 24-30-00-710-802-01 (s)	OPERATIONAL TEST OF THE APU SHUTDOWN SAFETIES WITH " MASTER" APU CONTROL PKG 21	MOS					PKG 15-JUN-2017		
24.090	REF: AMM 24-30-00-710-802	HRS/MSC AFL	1600	+40			3125.5 1867		
24-30-08-900-801-01	AUXILIARY BATTERY PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
				TSN:0 TSN:0 TSN:0					



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-09-900-801-01	APU GENERATOR CONTROL								
24.110	D22-600 1028 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C	TSN:3084			19-NOV-2013 2320.42 1495		
24-31-09-900-801-02	NO. 1 GENERATOR CONTROL								
24.100	D22-600 2308 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
24-31-09-900-801-03	NO. 2 GENERATOR CONTROL								
24.100	D22-600 2311 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
24-31-09-900-801-04	NO. 3 GENERATOR CONTROL								
24.100	D22-600 2310 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
24-31-13-350-801-01	RESTORATION ENGINE NO.1 STARTER/GENERATOR (OVERHAUL)								
24.040 OVERHAUL	8060-160 3284 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	1240	+3%			17-SEP-2018 3480.2 2027	4720.2	4757.4
24-31-13-350-801-02	RESTORATION ENGINE NO.2 STARTER/GENERATOR (OVERHAUL)								
24.050 OVERHAUL	8060-160 1366 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	1240	+3%			17-SEP-2018 3480.2 2027	4720.2	4757.4
24-31-13-350-801-03	RESTORATION ENGINE NO.3 STARTER/GENERATOR (OVERHAUL)								
24.040 OVERHAUL	8060-160 2954 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	1240	+3%			12-OCT-2015 2761.8 1696	4001.8	4039

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-13-350-801-04	RESTORATION APU STARTER/GENERATOR (OVERHAUL)								
24.060	8060-160 1808 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL APH					14-JUN-2019		
			1240	+3%			3180	4420	4457.2
24-31-13-900-802-01	NO. 1 STARTER/GENERATOR								
24.040	8060-160 3284 REF: AMM 24-31-13-900-802	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
				TSO:0 TSO:0 TSO:0					
24-31-13-900-802-02	NO. 2 STARTER/GENERATOR								
24.050	8060-160 1366 REF: AMM 24-31-13-900-802	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
				TSN:0 TSN:0 TSN:0					
24-31-13-900-802-03	NO. 3 STARTER/GENERATOR								
24.040	8060-160 2954 REF: AMM 24-31-13-900-802	MOS HRS/MSC AFL	O/C				12-OCT-2015 2761.8 1696		
				TSO:61					
24-31-13-900-802-04	APU STARTER/GENERATOR								
24.060	8060-160 1808 REF: AMM 24-31-13-900-802	MOS HRS/MSC AFL APH	O/C				14-JUN-2019		
			0	TSO:0 TSO:0			3180		
24-31-17-220-803-01	CHECK NO. 1 STARTER/GENERATOR BRUSHES								
24.040	8060-160 3284 REF: See Workcard	MOS HRS/MSC AFL	600	+60			17-SEP-2018 3480.2 2027	4080.2	4140.2
24-31-17-220-803-02	CHECK NO. 2 STARTER/GENERATOR BRUSHES								
24.050	8060-160 1366 REF: See Workcard	MOS HRS/MSC AFL	600	+60			17-SEP-2018 3480.2 2027	4080.2	4140.2

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-17-220-803-03	CHECK NO. 3 STARTER/GENERATOR BRUSHES								
24.040	8060-160 2954 REF: See Workcard	MOS HRS/MSC AFL	600	+60			22-MAR-2018 3341.1 1960	3941.1	4001.1
24-31-17-960-801-01	REPLACEMENT ENGINE NO.1 STARTER/GENERATOR BRUSHES								
24.040	8060-160 3284 REF: AMM 24-31-17-960-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
24-31-17-960-801-02	REPLACEMENT ENGINE NO.2 STARTER/GENERATOR BRUSHES								
24.050	8060-160 1366 REF: AMM 24-31-17-960-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
24-31-17-960-801-03	REPLACEMENT ENGINE NO.3 STARTER/GENERATOR BRUSHES								
24.040	8060-160 2954 REF: AMM 24-31-17-960-801	MOS HRS/MSC AFL	O/C				12-OCT-2015 2761.8 1696		
24-31-17-960-801-04	REPLACEMENT APU STARTER/GENERATOR BRUSHES								
24.060	8060-160 1808 REF: AMM 24-31-17-960-801	MOS HRS/MSC AFL APH	O/C	0			14-JUN-2019 3180		
24-32-01-350-801-01	RESTORATION NO. 1 MAIN BATTERY (OVERHAUL) (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.070 OVERHAUL	405CH10 S04899 REF: AMM 24-32-01-350-801	MOS HRS/MSC AFL	33 1700	+3% +3%			10-NOV-2017 3218.6	10-AUG-2020 4918.6	09-SEP-2020 4969.6
24-32-01-350-801-02	RESTORATION NO. 2 MAIN BATTERY (OVERHAUL) (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.080 OVERHAUL	405CH10 RO4375 REF: AMM 24-32-01-350-801	MOS HRS/MSC AFL	33 1700	+3% +3%			10-NOV-2017 3218.6	10-AUG-2020 4918.6	09-SEP-2020 4969.6

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-01-700-801-01	REGULAR CHECK NO. 1 MAIN BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.070	405CH10 S04899 REF: AMM 24-32-01-700-801	MOS HRS/MSC AFL	17 850	+1m +85			14-JUN-2019 3636.3 2081	14-NOV-2020 4486.3	14-DEC-2020 4571.3
24-32-01-700-801-02	REGULAR CHECK NO. 2 MAIN BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.080	405CH10 RO4375 REF: AMM 24-32-01-700-801	MOS HRS/MSC AFL	17 850	+1m +85			14-JUN-2019 3636.3 2081	14-NOV-2020 4486.3	14-DEC-2020 4571.3
+ 24-32-01-700-802-01 (s)	REGULAR CHECK NO. 1 MAIN BATTERY (CONCORD LEAD / ACID BATTERY ONLY)								
24.070	405CH10 S04899 REF: AMM 24-32-01-700-802	MOS HRS/MSC AFL	N/A				18-DEC-2014 2487.9 1574		
+ 24-32-01-700-802-02 (s)	REGULAR CHECK NO. 2 MAIN BATTERY (CONCORD LEAD / ACID BATTERY ONLY)								
24.080	405CH10 RO4375 REF: AMM 24-32-01-700-802	MOS HRS/MSC AFL	N/A				18-DEC-2014 2487.9 1574		
24-32-01-900-801-01	NO. 1 MAIN BATTERY								
24.070	405CH10 S04899 REF: AMM 24-32-01-900-801	MOS HRS/MSC AFL	O/C			TSO:19 TSO:417.7 TSO:171	14-JUN-2019 3636.3 2081		
24-32-01-900-801-02	NO. 2 MAIN BATTERY								
24.080	405CH10 RO4375 REF: AMM 24-32-01-900-801	MOS HRS/MSC AFL	O/C			TSO:19 TSO:417.7 TSO:171	14-JUN-2019 3636.3 2081		
24-32-01-960-801-01 (s)	DISCARD NO. 1 MAIN BATTERY (CONCORD LEAD / ACID BATTERY ONLY)								
24.070	405CH10 S04899 REF: AMM 24-32-01-960-801	MOS HRS/MSC AFL	N/A				18-DEC-2014 2487.9 1574		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-01-960-801-02 (s)	DISCARD NO. 2 MAIN BATTERY (CONCORD LEAD / ACID BATTERY ONLY)								
24.080	405CH10 RO4375 REF: AMM 24-32-01-960-801	MOS HRS/MSC AFL	N/A				18-DEC-2014 2487.9 1574		
24-32-09-610-801-01	SERVICE STAND-BY HORIZON STAND-BY BATTERY (SAFT BATTERY ONLY)								
24.200	785229 0291 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019	14-JUN-2020	24-JUN-2020
24-32-09-610-801-02	SERVICE NO. 1 MAU AVIONIC STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.205	804745 1102 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019	14-JUN-2020	24-JUN-2020
24-32-09-610-801-03	SERVICE NO. 2 MAU AVIONIC STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.205	804745 1106 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019	14-JUN-2020	24-JUN-2020
24-32-09-610-801-04	SERVICE NO. 1 DISPLAY UNIT STAND-BY BATTERY (SAFT BATTERY ONLY)								
24.210	800864 0766 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019	14-JUN-2020	24-JUN-2020
24-32-09-610-801-05	SERVICE NO. 2 DISPLAY UNIT STAND-BY BATTERY (SAFT BATTERY ONLY)								
24.210	800864 0888 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019	14-JUN-2020	24-JUN-2020
+ 24-32-09-710-802-01	OPERATIONAL TEST STAND-BY HORIZON STAND-BY BATTERY (SECURAPLANE BATTERY ONLY)								
24.200	785229 0291 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A				18-DEC-2014 2487.9 1574		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-32-09-710-802-02	OPERATIONAL TEST NO. 1 MAU AVIONIC STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY)								
24.205	804745 1102 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A						
+ 24-32-09-710-802-03	OPERATIONAL TEST NO. 2 MAU AVIONIC STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY)								
24.205	804745 1106 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A						
+ 24-32-09-710-802-04	OPERATIONAL TEST NO. 1 DISPLAY UNIT STAND-BY BATTERY (SECURAPLANE BATTERY ONLY)								
24.210	800864 0766 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A						
+ 24-32-09-710-802-05	OPERATIONAL TEST NO. 2 DISPLAY UNIT STAND-BY BATTERY (SECURAPLANE BATTERY ONLY)								
24.210	800864 0888 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A						
24-32-09-900-801-01	NO. 1 MAU AVIONIC STAND-BY BATTERY								
24.205	804745 1102 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C					14-JUN-2019 3636.3 2081	
24-32-09-900-801-02	NO. 2 MAU AVIONIC STAND-BY BATTERY								
24.205	804745 1106 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C	TSN:52 TSN:874.5 TSN:385				14-JUN-2019 3636.3 2081	
24-32-09-900-801-03	NO. 1 DISPLAY UNIT STAND-BY BATTERY								
24.210	800864 0766 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C	TSR:9 TSR:156.1 TSR:54				14-JUN-2019 3636.3 2081	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-900-801-04	NO. 2 DISPLAY UNIT STAND-BY BATTERY								
24.210	800864 0888 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C	TSR:9 TSR:156.1 TSR:54			14-JUN-2019 3636.3 2081		
24-32-09-900-801-05	STAND-BY HORIZON STAND-BY BATTERY								
24.200	785229 0291 REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C	TSN:122 TSR:54 TSN:2820.3 TSR:1148.4 TSN:1637 TSR:507			14-JUN-2019 3636.3 2081		
24-32-09-960-802-01	DISCARD STAND-BY HORIZON STAND-BY BATTERY PACK (SECURAPLANE BATTERY ONLY)								
24.200	785229 0291 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	O/C				18-DEC-2014 2487.9 1574		
24-32-09-960-802-02	DISCARD NO. 1 MAU AVIONIC STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY)								
24.205	804745 1102 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	O/C						
24-32-09-960-802-03	DISCARD NO. 2 MAU AVIONIC STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY)								
24.205	804745 1106 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	O/C						
24-32-09-960-802-04	DISCARD NO. 1 DISPLAY UNIT STAND-BY BATTERY PACK (SECURAPLANE BATTERY ONLY)								
24.210	800864 0766 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	O/C						
24-32-09-960-802-05	DISCARD NO. 2 DISPLAY UNIT STAND-BY BATTERY PACK (SECURAPLANE BATTERY ONLY)								
24.210	800864 0888 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-13-720-801-01	CAPACITY TEST AUXILIARY BATTERY BATTERY PN SN-UNKNOWN REF: AMM 24-32-13-720-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
24-33-05-220-803-01 24.060	CHECK APU STARTER/GENERATOR BRUSHES 8060-160 1808 REF: See Workcard	MOS HRS/MSC AFL APH		600	+60		14-JUN-2019 3180	3780	3840
+ 24-40-00-720-801-01 (s) 24.170	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB PKG 21 REF: AMM 24-40-00-720-801	MOS HRS/MSC AFL		1600	+40		PKG 15-JUN-2017 3125.5 1867		
+ 24-41-00-720-801-01 (s) 24.190	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE FUNCTION REF: AMM 24-41-00-720-801	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
24-41-00-720-801-02 (s) 24.190	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES REF: AMM 24-41-00-720-801	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
+ 24-41-00-720-801-03 24.190	CHECK OF GPU VOLTAGE TIME DELAY RELAY REF: AMM 24-41-00-720-801	MOS HRS/MSC AFL	N/A						
24-61-01-900-801-01 (s) 24.010	MAIN ELECTRICAL BOX PN SN-UNKNOWN REF: AMM 24-61-01-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-63-13-710-801-01 (s)	OPERATIONAL TEST OF THE DOME LIGHT CONTROL PCB (CRASH CONDITION)						PKG		
24.215	PKG 21 REF: AMM 24-63-13-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
24-90-01-900-801-01	GROUND FAULT (GFI) INTERRUPTER 106072-1 13820307 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
241P01	(R905LP) POWER SUPPLY AL2004 37203 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		16-SEP-2010 1416.58 780		
241P02	(765LP) POWER SUPPLY AL2004 37384 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		11-FEB-2011 1541.42 872		
242A01	AC (115V) INVERTER SS120-A 213 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
243806	BATTERY BLOWER VA0906XXA 11684 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
243811	UPPER ELECTRICAL PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243816	LEFT DC VOLTMETER								
24.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
243821	RIGHT DC VOLTMETER								
24.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
243826	LEFT DC AMMETER								
24.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
243831	RIGHT DC AMMETER								
24.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
243836	BATTERY TEMPERATURE DUAL INDICATOR								
24.160	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
243A01	(C15) PRINTED CIRCUIT								
CUSTOMER CODE	801GC01Y04 847 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			13-FEB-2010 1151.83 626		
243A11	DERIVATION SHUNT								
	6137A 7207 REF:	MOS HRS/MSC AFL	O/C	TSN:39			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
244801	GROUND POWER RECEPTACLE								
24.170	C0BAQXH0004 21375 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
24SG03	NO.3 SARTER GENERATOR NEGATIVE WIRE								
CUSTOMER CODE	FGFB691011028E3 1057 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-SEP-2010 1418.92 782		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
+ 25-00-01-200-801-01	INSPECTION OF THE ONBOARD KIT								
25.065	REF: AMM 25-00-01-200-801	MOS HRS/MSC AFL	O/C				19-MAY-2017 3080 1850		
+ 25-00-05-200-801-01 (s)	INSPECTION OF THE CREW AND PASSENGER SEAT HARNESSSES AND SAFETY BELTS								
25.010	PKG 31 REF: AMM 25-00-05-200-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
25-11-01-900-801-01	PILOT SEAT								
25.030	132-051-103 06T3731 REF: AMM 25-11-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
25-11-01-900-801-02	COPILOT SEAT								
25.030	132-050-103 07T0421 REF: AMM 25-11-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
25-11-13-640-801-01 (s)	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTING								
25.020	PKG 21 REF: AMM 25-11-13-640-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-13-640-801-02 (s)	GREASING OF THE COPILOT SEAT ACTUATOR ROD END-FITTING						PKG		
25.020	PKG 21	MOS					15-JUN-2017		
	REF: AMM 25-11-13-640-801	HRS/MSC	1600	+40			3125.5		
		AFL					1867		
25-11-19-900-801-01	PILOT SEAT LOCKING PIN SPRINGS								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
25-11-19-900-801-02	COPILOT SEAT LOCKING PIN SPRINGS								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
25-11-19-960-801-01 (s)	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS						PKG		
	PKG 31	MOS	72	+2m			17-AUG-2016		
	REF: AMM 25-11-19-960-801	HRS/MSC					2978		
		AFL	3750				1794		
25-11-19-960-801-02 (s)	REPLACEMENT OF THE COPILOT SEAT LOCKING PIN SPRINGS						PKG		
	PKG 31	MOS	72	+2m			17-AUG-2016		
	REF: AMM 25-11-19-960-801	HRS/MSC					2978		
		AFL	3750				1794		
25-11-25-200-801-01 (s)	INSPECTION OF THE PILOT SEAT ROLLER PINS						PKG		
25.180	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 25-11-25-200-801	HRS/MSC					2320.42		
		AFL	3750				1495		
25-11-25-200-801-02 (s)	INSPECTION OF THE COPILOT SEAT ROLLER PINS						PKG		
25.180	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 25-11-25-200-801	HRS/MSC					2320.42		
		AFL	3750				1495		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-12-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE THIRD CREW MEMBER SEAT PKG 5,201 REF: AMM 25-12-00-210-801	MOS HRS/MSC AFL	12 800	+1m +40			PKG 14-JUN-2019 3636.3 2081		
25-12-00-900-801-01	THIRD CREW MEMBER SEAT PN SN-UNKNOWN REF: AMM 25-12-00-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
25-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR ASSIST HANDLE PKG 31 REF: AMM 25-20-00-210-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		
SMM									
25-20-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE AFT LAVATORY DOOR ASSIST HANDLE PKG 31 REF: AMM 25-20-00-210-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		
25-20-00-220-801-04	INSPECTION/TEST OF WASTE CONTAINERS 25.090 REF: AMM 25-20-00-220-801	MOS HRS/MSC AFL	1000	+40			19-MAY-2017 3080 1850	4080	4120
25-20-00-220-802-01 (s)	INSPECTION OF DOORS, DRAWERS AND THEIR RESPECTIVE LATCHING MECHANISMS PKG 31 REF: AMM 25-20-00-220-802	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		
SMM									
25-20-00-220-802-02 (s)	INSPECTION OF THE POP OUT WORK SURFACE PKG 31 REF: AMM 25-20-00-220-802	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		
SMM									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20-00-220-802-03	INSPECTION OF THE ICE DRAWERS	MOS					19-MAY-2017		
	REF: AMM 25-20-00-220-802	HRS/MSC AFL	O/C				3080 1850		
25-20-00-220-802-04 (s)	INSPECTION OF THE TRACKING MAGAZINE RACK	MOS	72	+2m			19-MAY-2017		
	PKG 31	HRS/MSC AFL					3080 1850		
	REF: AMM 25-20-00-220-802		3750						
25-20-00-220-802-05 (s)	OPERATIONAL TEST OF TAMBOUR DOOR POWER CUT OFF FUNCTION	MOS	72	+2m			19-NOV-2013		
	PKG 31	HRS/MSC AFL					2320.42 1495		
	SMM REF: AMM 25-20-00-220-802		3750						
25-21-00-220-801-01 (s)	DETAILED INSPECTION OF THE SINGLE AND DOUBLE PASSENGER SEATS	MOS	36	+1m			14-JUN-2019		
	PKG 7	HRS/MSC AFL	2400	+40			3636.3 2081		
	REF: AMM 25-21-00-220-801								
25-21-00-220-801-02 (s)	DETAILED INSPECTION OF THE PASSENGER DIVAN	MOS	36	+1m			14-JUN-2019		
	PKG 7	HRS/MSC AFL	2400	+40			3636.3 2081		
	REF: AMM 25-21-00-220-801								
25-21-00-710-801-01	OPERATIONAL TEST PASSENGER SEATS	MOS					19-MAY-2017		
	REF: GENERIC NO REF	HRS/MSC AFL	O/C				3080 1850		
25-22-01-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES IN LOCATIONS OTHER THAN EMERGENCY EXIT	MOS	72	+2m			19-NOV-2013		
	PKG 31	HRS/MSC AFL					2320.42 1495		
	SMM REF: AMM 25-22-01-210-801		3750						

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-22-05-220-802-01 (s)	DETAILED INSPECTION OF THE DINING TABLE PKG 31	MOS	72	+2m			PKG 19-NOV-2013 2320.42		
SMM	REF: AMM 25-22-05-220-802	HRS/MSC AFL		3750			1495		
25-22-05-820-801-01	ADJUSTMENT OF THE DINING TABLE MOTOR BELT	MOS					19-OCT-2007		
	REF:	HRS/MSC AFL	O/C				0 0		
25-23-00-220-801-01	DETAILED INSPECTION OF THE CABINETS AND ASSOCIATED STRUCTURE	MOS					19-NOV-2013 2320.42		
	REF: See Workcard	HRS/MSC AFL	O/C				1495		
25-30-16-710-801-01	OPERATIONAL CHECK ESPRESSO MAKER HFE96-28B 01129AT	DAYS	60				14-JUN-2019 3636.3	13-AUG-2019	3836.3
SMM	REF:	HRS/MSC AFL	200				2081		
25-30-16-900-801-01	COFFEE MAKER PN NOT INSTALLED	MOS					06-MAR-2019 3580.3		
	REF:	HRS/MSC AFL	O/C				2067		
25-30-33-900-801-01	HIGH TEMP OVEN 91127-002 32419	MOS					15-APR-2008 335.83		
	REF:	HRS/MSC AFL	O/C				169		
25-33-09-210-801-01	INSPECTION OF THE COFFEE MAKER / ESPRESSO MACHINE	DAYS					14-JUN-2018 3406.6		
	REF: AMM 25-33-09-210-801	HRS/MSC AFL	N/A				1988		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-33-17-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN PKG 7 REF: AMM 25-33-17-210-801	MOS HRS/MSC AFL	36 2400	+1m +40			PKG 14-JUN-2019 3636.3 2081		
+ 25-33-17-710-801-01	OPERATIONAL TEST MICROWAVE OVEN DOOR ELECTRICAL POWER CUT-OFF FUNCTION 400-1338-04-L 11-12-49670 REF: AMM 25-33-17-710-801	MOS HRS/MSC AFL	2400	+3%			05-MAR-2014 2375.55 1530	4775.55	4847.55
25-33-50-900-801-01	PILOT FLASHLIGHT P2-07-0009-520 SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		14-JUN-2019 3636.3 2081		
25-33-50-900-801-02	COPILOT FLASHLIGHT P2-07-0011-500 N/A REF: GENERIC CMM	MOS HRS/MSC AFL	O/C		TSN:65 TSO:0 TSN:1284.05 TSO:0 TSN:569 TSO:0		14-JUN-2019 3636.3 2081		
+ 25-60-00-200-801-02 (s)	INSPECTION OF THE SAFETY EQUIPMENT PKG 16 25.060 REF:	MOS HRS/MSC AFL	24	+1m			PKG 14-JUN-2019 3636.3 2081		
25-60-00-200-801-03 (s)	INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT PKG 16 REF: AMM 25-60-00-200-801	MOS HRS/MSC AFL	24	+1m			PKG 14-JUN-2019 3636.3 2081		
25-60-01-900-801-01	NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60-01-900-801-02	NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207) MANDATORY REF: See Workcard	MOS HRS/MSC AFL	12				14-JUN-2019 3636.3 2081	14-JUN-2020	
+ 25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT UNIT CONTROLS 25.070 REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
+ 25-61-00-710-801-02 (s)	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT COCKPIT CONTROLS PKG 17 REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	36	+1m			PKG 14-JUN-2019 3636.3 2081		
+ 25-61-00-710-801-03 (s)	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT PKG 17 REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	36	+1m			PKG 14-JUN-2019 3636.3 2081		
25-61-01-710-801-01	OPERATIONAL TEST EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON G-SWITCH 01N65900 08502738 REF: AMM 25-61-01-710-801	MOS HRS/MSC AFL	60	+3%			26-AUG-2016	26-AUG-2021	20-OCT-2021
25-61-01-900-802-01	EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON 01N65900 08502738 REF: AMM 25-61-01-900-802	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-AUG-2016 2978 1794		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-13-960-801-01	DISCARD EMERGENCY LOCATOR TRANSMITTER (ELT) BEACON BATTERY PACK								
	01N65900	MOS					29-AUG-2016		01-APR-2022 M
25.070	08502738	HRS/MSC	DUE				2978		
LIFE LIMIT	REF: AMM 25-61-13-960-801	AFL					1794		
25-61-21-900-801-01	EMERGENCY LOCATOR TRANSMITTER ANTENNA								
	01N65900	MOS		TSN:0			19-OCT-2007		
25.080	06511358	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-61-21-900-801	AFL		TSN:0			0		
+ 25-62-01-720-801-01	FUNCTIONAL CHECK COCKPIT VOICE RECORDER UNDERWATER ACOUSTIC BEACON								
	DK140	MOS	25	+3%			15-MAY-2018	15-JUN-2020	07-JUL-2020
25.170	ST66234	HRS/MSC					3366.3		
	REF: AMM 25-62-01-720-801	AFL					1970		
+ 25-62-01-720-801-02	FUNCTIONAL CHECK DIGITAL FLIGHT DATA RECORDER UNDERWATER ACOUSTIC BEACON								
	DK120/90	MOS	25	+3%			17-SEP-2018	17-OCT-2020	09-NOV-2020
25.175	AT50232	HRS/MSC					3480.2		
	REF: AMM 25-62-01-720-801	AFL					2027		
25-62-05-960-801-01	DISCARD COCKPIT VOICE RECORDER UNDERWATER ACOUSTIC BEACON BATTERY								
	DK140	MOS					10-NOV-2017		01-JUL-2020 M
25.170	ST66234	HRS/MSC	DUE				3218.6		
LIFE LIMIT	REF: AMM 25-62-05-960-801	AFL					1910		
25-62-05-960-801-02	DISCARD DIGITAL FLIGHT DATA RECORDER UNDERWATER ACOUSTIC BEACON BATTERY								
	DK120/90	MOS					11-AUG-2016		01-JUL-2023 M
25.175	AT50232	HRS/MSC	DUE				2965.9		
LIFE LIMIT	REF: AMM 25-62-05-960-801	AFL					1786		
25-63-00-350-801-01	RESTORATION NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT (OVERHAUL)								
	PN	MOS					19-OCT-2007		
	NOT INSTALLED	HRS/MSC	N/A				0		
	REF: AMM 25-63-00-350-801	AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63-00-350-801-02	RESTORATION NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT (OVERHAUL) PN NOT INSTALLED REF: AMM 25-63-00-350-801	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
+ 25-63-00-710-801-01	OPERATIONAL TEST NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: AMM 25-63-00-710-801	DAYS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
+ 25-63-00-710-801-02	OPERATIONAL TEST NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: AMM 25-63-00-710-801	DAYS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
+ 25-63-01-960-801-02	DISCARD NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT BATTERY PN NOT INSTALLED REF: AMM 25-63-01-960-801	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
25-64-13-200-801-01 25.160	INSPECT NO. 1 LIFE RAFT 1218FAUL-7KO-1-301 12UL-01197 REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			14-JUN-2019 3636.3 2081	14-JUN-2022	16-JUL-2022
25-64-13-200-801-02 25.160	INSPECT NO. 2 LIFE RAFT 1218FAUL-7KO-1-301 12UL-01198 REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			14-JUN-2019 3636.3 2081	14-JUN-2022	16-JUL-2022
25-64-13-200-801-03 25.165	INSPECT NO. 3 LIFE RAFT PN NOT INSTALLED REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-13-200-801-04	INSPECT NO. 4 LIFE RAFT PN NOT INSTALLED REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	O/C						
25-64-13-350-801-01	RESTORATION NO. 1 LIFE RAFT (OVERHAUL) 1218FAUL-7KO-1-301 12UL-01197 REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	72	+3%			14-JUN-2019 3636.3 2081	14-JUN-2025	18-AUG-2025
OVERHAUL									
25-64-13-350-801-02	RESTORATION NO. 2 LIFE RAFT (OVERHAUL) 1218FAUL-7KO-1-301 12UL-01198 REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	72	+3%			14-JUN-2019 3636.3 2081	14-JUN-2025	18-AUG-2025
OVERHAUL									
25-64-13-350-801-03	RESTORATION NO. 3 LIFE RAFT (OVERHAUL) PN NOT INSTALLED REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	N/A						
25-64-13-350-801-04	RESTORATION NO. 4 LIFE RAFT (OVERHAUL) PN NOT INSTALLED REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	N/A						
25-64-13-900-801-01	NO. 1 LIFE RAFT 1218FAUL-7KO-1-301 12UL-01197 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:140 TSO:0 TSN:3636.3 TSO:0 TSN:2081 TSO:0	14-JUN-2019 3636.3 2081		
25-64-13-900-801-02	NO. 2 LIFE RAFT 1218FAUL-7KO-1-301 12UL-01198 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:140 TSO:0 TSN:3636.3 TSO:0 TSN:2081 TSO:0	14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-13-900-801-03	NO. 3 LIFE RAFT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
25.165									
25-64-13-900-801-04	NO. 4 LIFE RAFT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
25.165									
25-64-17-200-802-01	INSPECTION PILOT LIFE VEST S-21450-6311 38792 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	10-MAR-2020 M	04-MAY-2020
25.100									
25-64-17-200-802-02	INSPECTION COPILOT LIFE VEST 63600-505 L3365476 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			27-JUN-2016	30-APR-2026 M	24-JUN-2026
25.100									
25-64-17-200-802-03	INSPECTION THIRD CREW MEMBER LIFE VEST S-21450-6311 24905 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	10-MAR-2020 M	04-MAY-2020
25.105									
25-64-17-200-803-01	INSPECTION NO. 1 PASSENGER LIFE VEST S-11250-1300 87-55129 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAR-2022 M	13-MAY-2022
25.110									
25-64-17-200-803-02	INSPECTION NO. 2 PASSENGER LIFE VEST S-11250-1300 87-55124 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAR-2022 M	13-MAY-2022
25.110									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-200-803-03 25.115	INSPECTION NO. 3 PASSENGER LIFE VEST P0723E105P 249995 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAR-2022 M	13-MAY-2022
25-64-17-200-803-04 25.115	INSPECTION NO. 4 PASSENGER LIFE VEST P0723E105P 653548 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAR-2022 M	13-MAY-2022
25-64-17-200-803-05 25.120	INSPECTION NO. 5 PASSENGER LIFE VEST S-11250-1300 87-55144 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAR-2022 M	13-MAY-2022
25-64-17-200-803-06 25.120	INSPECTION NO. 6 PASSENGER LIFE VEST P0723E105P 780659 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAR-2022 M	13-MAY-2022
25-64-17-200-803-07 25.125	INSPECTION NO. 7 PASSENGER LIFE VEST S-21450-631 47408-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	10-MAR-2020 M	04-MAY-2020
25-64-17-200-803-08 25.125	INSPECTION NO. 8 PASSENGER LIFE VEST S-21450-631 4844 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	10-MAR-2020 M	04-MAY-2020
25-64-17-200-803-09 25.130	INSPECTION NO. 9 PASSENGER LIFE VEST S-21450-631 8898-1151 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAY-2022	13-JUL-2022

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-200-803-10	INSPECTION NO. 10 PASSENGER LIFE VEST S-21450-631 293-48-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAY-2022	13-JUL-2022
25.130									
25-64-17-200-803-11	INSPECTION NO. 11 PASSENGER LIFE VEST S-21450-631 86507-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			19-MAY-2017	19-MAY-2022	13-JUL-2022
25.135									
25-64-17-200-803-12	INSPECTION NO. 12 PASSENGER LIFE VEST S-21450-6311 81081-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			09-NOV-2017	09-NOV-2022	02-JAN-2023
25.135									
25-64-17-200-803-13	INSPECTION NO. 13 PASSENGER LIFE VEST S-21450-6311 29530-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			09-NOV-2017	09-NOV-2022	02-JAN-2023
25.140									
25-64-17-200-803-14	INSPECTION NO. 14 PASSENGER LIFE VEST S-21450-6311 58723 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+3%			09-NOV-2017	09-NOV-2022	02-JAN-2023
25.140									
25-64-17-200-803-15	INSPECTION NO. 15 PASSENGER LIFE VEST PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAR-2007 0 0		
25.145									
25-64-17-200-803-16	INSPECTION NO. 16 PASSENGER LIFE VEST PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-MAR-2007 0 0		
25.145									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-802-01	RESTORATION PILOT LIFE VEST (OVERHAUL OR DISCARD) S-21450-6311 38792 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.190 OVERHAUL									
25-64-17-350-802-02	RESTORATION COPILOT LIFE VEST (OVERHAUL OR DISCARD) 63600-505 L3365476 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	120	+3%			01-JUN-2016	01-JUN-2026	19-SEP-2026
25.190 OVERHAUL									
25-64-17-350-802-03	RESTORATION THIRD CREW MEMBER LIFE VEST (OVERHAUL OR DISCARD) S-21450-6311 24905 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.190 OVERHAUL									
25-64-17-350-803-01	RESTORATION NO. 1 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-11250-1300 87-55129 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.195 OVERHAUL									
25-64-17-350-803-02	RESTORATION NO. 2 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-11250-1300 87-55124 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.195 OVERHAUL									
25-64-17-350-803-03	RESTORATION NO. 3 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) P0723E105P 249995 REF:	MOS HRS/MSC AFL	60	+3%			19-MAY-2017 3080 1850	19-MAY-2022	13-JUL-2022
25.195 OVERHAUL									
25-64-17-350-803-04	RESTORATION NO. 4 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) P0723E105P 653548 REF:	MOS HRS/MSC AFL	60	+3%			19-MAY-2017 3080 1850	19-MAY-2022	13-JUL-2022
25.195 OVERHAUL									



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-05	RESTORATION NO. 5 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-11250-1300 87-55144 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.195 OVERHAUL									
25-64-17-350-803-06	RESTORATION NO. 6 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) P0723E105P 780659 REF:	MOS HRS/MSC AFL	60	+3%			19-MAY-2017 3080 1850	19-MAY-2022	13-JUL-2022
25.195 OVERHAUL									
25-64-17-350-803-07	RESTORATION NO. 7 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-631 47408-1141 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.195 OVERHAUL									
25-64-17-350-803-08	RESTORATION NO. 8 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-631 4844 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.195 OVERHAUL									
25-64-17-350-803-09	RESTORATION NO. 9 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-631 8898-1151 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.195 OVERHAUL									
25-64-17-350-803-10	RESTORATION NO. 10 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-631 293-48-1141 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.130 OVERHAUL									
25-64-17-350-803-11	RESTORATION NO. 11 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-631 86507-1141 REF:	MOS HRS/MSC AFL	120	+3%			19-MAY-2017 3080 1850	19-MAY-2027	06-SEP-2027
25.195 OVERHAUL									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-12	RESTORATION NO. 12 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-6311 81081-1141 REF:	MOS HRS/MSC AFL	120	+3%			09-NOV-2017 3218.6 1910	09-MAR-2020	M 27-JUN-2020
25.195 OVERHAUL									
25-64-17-350-803-13	RESTORATION NO. 13 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-6311 29530-1141 REF:	MOS HRS/MSC AFL	120	+3%			09-NOV-2017 3218.6 1910	09-MAR-2020	M 27-JUN-2020
25.195 OVERHAUL									
25-64-17-350-803-14	RESTORATION NO. 14 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) S-21450-6311 58723 REF:	MOS HRS/MSC AFL	120	+3%			09-NOV-2017 3218.6 1910	09-MAR-2020	M 27-JUN-2020
25.195 OVERHAUL									
25-64-17-350-803-15	RESTORATION NO. 15 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				01-MAR-2007 0 0		
25.195									
25-64-17-350-803-16	RESTORATION NO. 16 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				01-MAR-2007 0 0		
25.195									
25-64-17-350-803-17 (s)	RESTORATION NO. 17 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
25.195									
25-64-17-350-803-18 (s)	RESTORATION NO. 18 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
25.195									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-19 (s)	RESTORATION NO. 19 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.195	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
25-64-17-900-802-01	PILOT LIFE VEST								
25.100	S-21450-6311 38792 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-802-02	COPILOT LIFE VEST								
25.100	63600-505 L3365476 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			24-AUG-2016 2978 1794		
25-64-17-900-802-03	THIRD CREW MEMBER LIFE VEST								
25.105	S-21450-6311 24905 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-01	NO. 1 PASSENGER LIFE VEST								
25.110	S-11250-1300 87-55129 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-02	NO. 2 PASSENGER LIFE VEST								
25.110	S-11250-1300 87-55124 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-03	NO. 3 PASSENGER LIFE VEST								
25.115	P0723E105P 249995 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-04	NO. 4 PASSENGER LIFE VEST P0723E105P 653548 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-05	NO. 5 PASSENGER LIFE VEST S-11250-1300 87-55144 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-06	NO. 6 PASSENGER LIFE VEST P0723E105P 780659 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-07	NO. 7 PASSENGER LIFE VEST S-21450-631 47408-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-08	NO. 8 PASSENGER LIFE VEST S-21450-631 4844 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-09	NO. 9 PASSENGER LIFE VEST S-21450-631 8898-1151 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-10	NO. 10 PASSENGER LIFE VEST S-21450-631 293-48-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-11	NO. 11 PASSENGER LIFE VEST								
25.135	S-21450-631 86507-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			19-MAY-2017 3080 1850		
25-64-17-900-803-12	NO. 12 PASSENGER LIFE VEST								
25.135	S-21450-6311 81081-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:128 TSO:0 TSN:3218.6 TSO:0 TSN:1910 TSO:0			09-NOV-2017 3218.6 1910		
25-64-17-900-803-13	NO. 13 PASSENGER LIFE VEST								
25.140	S-21450-6311 29530-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:128 TSO:0 TSO:0 TSO:0			09-NOV-2017 3218.6 1910		
25-64-17-900-803-14	NO. 14 PASSENGER LIFE VEST								
25.140	S-21450-6311 58723 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:128 TSO:0 TSO:0 TSO:0			09-NOV-2017 3218.6 1910		
25-64-17-900-803-15 (s)	NO. 15 PASSENGER LIFE VEST								
25.145	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			01-MAR-2007 0 0		
25-64-17-900-803-16 (s)	NO. 16 PASSENGER LIFE VEST								
25.145	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			01-MAR-2007 0 0		
25-64-17-900-803-17	NO. 17 PASSENGER LIFE VEST								
25.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-18	NO. 18 PASSENGER LIFE VEST								
25.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
25-64-17-900-803-19	NO. 19 PASSENGER LIFE VEST								
25.155	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
25-64-17-900-804-01	NO. 1 INFANT LIFE VEST								
	PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
25-90-18-900-801-01	ESPRESSO MAKER								
	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
25-90-19-900-801-01	MICROWAVE OVEN								
	400-1338-04-L 11-12-49670 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			05-MAR-2014 2375.55 1530		
25-90-21-900-801-01	HIGH TEMPERATURE OVEN								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
251811	PILOT SEAT ACTUATOR								
25.020	8260 1739 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251816	COPILOT SEAT ACTUATOR								
25.020	8260 1744 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
251821 (s)	PILOT SEAT BELT								
25.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
251826 (s)	COPILOT SEAT BELT								
25.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
251831 (s)	PILOT SEAT HARNESS								
25.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
251836 (s)	COPILOT SEAT HARNESS								
25.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
251A03	THIRD CREW MEMBER SEAT								
	303703-1 34363 REF:	MOS HRS/MSC AFL	O/C						
252A61	CABIN DIVAN SEAT								
	FJ900-ALP2D10GKM PD1735 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252A63	CABIN DIVAN SEAT FJ900A-RP2D10GKMQ PD1736 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
253A01	ESPRESSO MAKER HFE96-28B 01129AT REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-NOV-2013 2320.42 1495		
256891	COCKPIT VOICE RECORDER UNDERWATER ACOUSTIC BEACON DK140 ST66234 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-NOV-2017 3218.6 1910		
256896	DIGITAL FLIGHT DATA RECORDER UNDERWATER ACOUSTIC BEACON DK120/90 AT50232 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2016 2965.9 1786		
256A54	FIRST AID KIT AFAK1.0 060616002 REF:	MOS HRS/MSC AFL	O/C	TSO:9 TSO:156.1 TSO:54			14-JUN-2019 3636.3 2081		
+ 256A56	INSPECT FIRST AID KIT AFAK1.0 060616002 REF:	MOS HRS/MSC AFL	DUE				14-JUN-2019 3636.3 2081	09-NOV-2019 M	
31-57-01-710-801-01	OPERATIONAL TEST OF THE LOW-HEIGHT CONSOLE TABLE MICROSWITCH AND ALERT SYSTEM REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				19-NOV-2013 2320.42 1495		
N/A EQUIPMENT NOT INSTALLED									

CHAPTER 26 FIRE PROTECTION

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-10-00-720-801-01	FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR 36017090040013 102458 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C	+3%			19-OCT-2007 0 0	7500	7725
+ 26-10-00-720-801-02	FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR 360113190040017 235395 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C	+3%			15-APR-2015 2591.7 1611	10091.7	10316.7
+ 26-10-00-720-801-03	FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR 36017090040013 102034 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C	+3%			19-OCT-2007 0 0	7500	7725
+ 26-10-00-720-801-04	FUNCTIONAL TEST APU FIRE DETECTOR 3601-81-900-400 106588 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL APH	5000	+3%			12-OCT-2011 1768.92 1063 1487	6487	6637
+ 26-10-00-720-802-01 (s)	FUNCTIONAL TEST OF THE LEFT MAIN LANDING GEAR PINPOINT FIRE DETECTOR PKG 22 REF: AMM 26-10-00-720-802	MOS HRS/MSC AFL	3200	+40			PKG 15-JUN-2017 3125.5 1867		
+ 26-10-00-720-802-02 (s)	FUNCTIONAL TEST OF THE RIGHT MAIN LANDING GEAR PINPOINT FIRE DETECTOR PKG 22 REF: AMM 26-10-00-720-802	MOS HRS/MSC AFL	3200	+40			PKG 15-JUN-2017 3125.5 1867		
26-10-17-900-801-01	LEFT MAIN LANDING GEAR PINPOINT FIRE DETECTOR HB160 UK0652 REF: AMM 26-10-17-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-19-900-801-01	NO. 1 ENGINE FIRE DETECTOR								
26.010	36017090040013 102458 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
26-10-19-900-801-02	NO. 2 ENGINE FIRE DETECTOR								
26.020	360113190040017 235395 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
26-10-19-900-801-03	NO. 3 ENGINE FIRE DETECTOR								
26.010	36017090040013 102034 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
26-10-19-900-801-04	APU FIRE DETECTOR								
26.030	3601-81-900-400 106588 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	TSN:18 TSN:0 TSN:0			12-OCT-2011 1768.92 1063		
26-20-00-760-801-01	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (R5WB), (R6WB) AND (22WB)								
26.090	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
26-20-00-760-801-02	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (R3WB) AND (R4WB)								
26.090	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				12-OCT-2011 1768.92 1063		
26-20-00-760-801-03	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (L5WB) AND (L6WB)								
26.090	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-00-760-801-04	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (L3WB) AND (L4WB)								
26.090	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				12-OCT-2011 1768.92 1063		
26-20-00-760-801-05	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (9WB)								
26.090	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
+ 26-20-01-760-801-01 (s)	CHECK OF THE CORRECT OPERATION OF NO. 1 ENGINE "DISCH 1" FIRE EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
26-20-01-760-801-02 (s)	CHECK OF THE CORRECT OPERATION OF NO. 1 ENGINE "DISCH 2" FIRE EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 26-20-01-760-801-03 (s)	CHECK OF THE CORRECT OPERATION OF NO. 2 ENGINE "DISCH 1" FIRE EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
26-20-01-760-801-04 (s)	CHECK OF THE CORRECT OPERATION OF NO. 2 ENGINE "DISCH 2" FIRE EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 26-20-01-760-801-05 (s)	CHECK OF THE CORRECT OPERATION OF NO. 3 ENGINE "DISCH 1" FIRE EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-01-760-801-06 (s)	CHECK OF THE CORRECT OPERATION OF NO. 3 ENGINE "DISCH 2" FIRE EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 26-20-01-760-801-07 (s)	CHECK OF THE CORRECTION OPERATION OF "FIRE APU" EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 26-20-01-760-801-08 (s)	CHECK OF THE CORRECT OPERATION OF "FIRE BAG COMP" EXTINGUISHER CONTROL SWITCH/LIGHT						PKG		
26.100	PKG 31 REF: AMM 26-20-01-760-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
26-20-01-900-801-01 (s)	EXTINGUISHING FIRE PANEL								
26.080	PN SN-UNKNOWN REF: AMM 26-20-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 26-20-09-220-801-01	WEIGHT CHECK 504WB APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER								
26.110	863470-01 UE003104 REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%			14-JUN-2019	14-DEC-2020	30-DEC-2020
+ 26-20-09-220-801-02	WEIGHT CHECK 505WB ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER								
26.120	PART UNKNOWN SERIAL UNKNOWN REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%			14-JUN-2019	14-DEC-2020	30-DEC-2020
+ 26-20-09-220-801-03	WEIGHT CHECK 506WB ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER								
26.130	863470-01 UE003174 REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%			14-JUN-2019	14-DEC-2020	30-DEC-2020



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-09-220-801-04 26.140	WEIGHT CHECK 508WB ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER 863470-01 UE003175 REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%			14-JUN-2019	14-DEC-2020	30-DEC-2020
+ 26-20-09-220-801-05 26.150	WEIGHT CHECK 507WB ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER 863470-01 UE003176 REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%			14-JUN-2019	14-DEC-2020	30-DEC-2020
+ 26-20-09-350-801-01 26.110 MANDATORY	RESTORATION 504WB APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 863470-01 UE003104 REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				29-APR-2015	29-APR-2025	
+ 26-20-09-350-801-02 26.120 MANDATORY	RESTORATION 505WB ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) PART UNKNOWN SERIAL UNKNOWN REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				14-JUN-2019	14-JUN-2029	
+ 26-20-09-350-801-03 26.130 MANDATORY	RESTORATION 506WB ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 863470-01 UE003174 REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				29-APR-2015	29-APR-2025	
+ 26-20-09-350-801-04 26.140 MANDATORY	RESTORATION 508WB ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 863470-01 UE003175 REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				29-APR-2015	29-APR-2025	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-09-350-801-05	RESTORATION 507WB ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.150	863470-01 UE003176 REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				29-APR-2015	29-APR-2025	
MANDATORY									
26-20-09-900-801-01	504WB APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER								
26.110	863470-01 UE003104 REF: AMM 26-20-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JUN-2016 2938.3 1769		
26-20-09-900-801-02	505WB ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER								
26.120	PART UNKNOWN SERIAL UNKNOWN REF: AMM 26-20-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-JUN-2019 3636.3 2081		
26-20-09-900-801-03	506WB ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER								
26.130	863470-01 UE003174 REF: AMM 26-20-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-AUG-2016 2978 1794		
26-20-09-900-801-04	508WB ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER								
26.140	863470-01 UE003175 REF: AMM 26-20-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
26-20-09-900-801-05	507WB ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER								
26.150	863470-01 UE003176 REF: AMM 26-20-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-AUG-2016 2978 1794		
26-20-11-700-801-01	CHECKING APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHING LINES FOR CLOGGING								
26.220	REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-11-700-801-02	CHECKING ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING								
26.220	REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
26-20-11-700-801-03	CHECKING ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING								
26.220	REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
26-20-11-700-801-04	CHECKING ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING								
26.220	REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
26-20-11-700-801-05	CHECKING ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING								
26.220	REF: AMM 26-20-11-700-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
+ 26-20-11-700-801-07 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE A								
	PKG 31	MOS	72	+2m			19-OCT-2007		
	REF:	HRS/MSC AFL	3750				0 0		
+ 26-20-11-700-801-08 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE B								
	PKG 31	MOS	72	+2m			19-OCT-2007		
	REF:	HRS/MSC AFL	3750				0 0		
+ 26-20-11-700-801-09 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE C								
	PKG 31	MOS	72	+2m			19-OCT-2007		
	REF:	HRS/MSC AFL	3750				0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-11-700-801-10 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE D PKG 31	MOS	72	+2m			PKG 19-OCT-2007 0 0		
	REF:	AFL	3750				0 0		
+ 26-20-11-700-801-11 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE E PKG 31	MOS	72	+2m			PKG 19-OCT-2007 0 0		
	REF:	AFL	3750				0 0		
+ 26-20-11-700-801-12 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE F PKG 31	MOS	72	+2m			PKG 19-OCT-2007 0 0		
	REF:	AFL	3750				0 0		
+ 26-20-11-700-801-13 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE G PKG 31	MOS	72				PKG 19-OCT-2007 0 0		
	REF: GENERIC NO REF	AFL	3750				0 0		
26-20-12-900-801-01	NO. 1 ENGINE EXTINGUISHER SHUTTLE VALVE 861585	MOS			TSN:0		19-OCT-2007		
26.200	5113	HRS/MSC	A/R		TSN:0		0		
REPLACE	REF: AMM 26-20-12-900-801	AFL			TSN:0		0		
26-20-12-900-801-02	NO. 3 ENGINE EXTINGUISHER SHUTTLE VALVE 861585	MOS			TSN:0		19-OCT-2007		
26.200	5114	HRS/MSC	A/R		TSN:0		0		
REPLACE	REF: AMM 26-20-12-900-801	AFL			TSN:0		0		
26-20-12-900-801-03	NO. 2 ENGINE EXTINGUISHER LEFT SHUTTLE VALVE 861585	MOS			TSN:0		19-OCT-2007		
26.210	5126	HRS/MSC	A/R		TSN:0		0		
REPLACE	REF: AMM 26-20-12-900-801	AFL			TSN:0		0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-12-900-801-04	NO. 2 ENGINE EXTINGUISHER RIGHT SHUTTLE VALVE								
	861585	MOS		TSN:0			19-OCT-2007		
26.210	5127	HRS/MSC	A/R	TSN:0			0		
REPLACE	REF: AMM 26-20-12-900-801	AFL		TSN:0			0		
26-20-12-960-801-01	DISCARD NO. 1 ENGINE EXTINGUISHER SHUTTLE VALVE								
	861585	MOS					19-OCT-2007		
26.160	5113	HRS/MSC	A/R				0		
REPLACE	REF: AMM 26-20-12-960-801	AFL					0		
26-20-12-960-801-02	DISCARD NO. 3 ENGINE EXTINGUISHER SHUTTLE VALVE								
	861585	MOS					19-OCT-2007		
26.160	5114	HRS/MSC	A/R				0		
REPLACE	REF: AMM 26-20-12-960-801	AFL					0		
26-20-12-960-801-03	DISCARD NO. 2 ENGINE EXTINGUISHER LEFT SHUTTLE VALVE								
	861585	MOS					19-OCT-2007		
26.160	5126	HRS/MSC	A/R				0		
REPLACE	REF: AMM 26-20-12-960-801	AFL					0		
26-20-12-960-801-04	DISCARD NO. 2 ENGINE EXTINGUISHER RIGHT SHUTTLE VALVE								
	861585	MOS					19-OCT-2007		
26.160	5127	HRS/MSC	A/R				0		
REPLACE	REF: AMM 26-20-12-960-801	AFL					0		
26-20-13-900-802-01	ENGINE 1 FIRST-SHOOT PERCUSSION GREEN (L3WB) CARTRIDGE								
	862710-00	MOS		TSN:8			19-MAY-2017		
26.235	NSN	HRS/MSC	H/T	TSN:0			3080		
	REF: AMM 26-20-13-900-802	AFL		TSN:0			1850		
26-20-13-900-802-02	ENGINE 3 FIRST-SHOOT PERCUSSION GREEN (R3WB) CARTRIDGE								
	862710-00	MOS		TSN:8			19-MAY-2017		
26.235	NSN	HRS/MSC	H/T	TSN:0			3080		
	REF: AMM 26-20-13-900-802	AFL		TSN:0			1850		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-900-802-03	ENGINE 2 SECOND-SHOOT LH PERCUSSION RED (L4WB) CARTRIDGE								
26.235	862710-00 NSN REF: AMM 26-20-13-900-802	MOS HRS/MSC AFL	H/T	TSN:8 TSN:0 TSN:0			19-MAY-2017 3080 1850		
26-20-13-900-802-04	ENGINE 2 SECOND-SHOOT RH PERCUSSION RED (R4WB) CARTRIDGE								
26.235	862700-00 NSN REF: AMM 26-20-13-900-802	MOS HRS/MSC AFL	H/T	TSN:11 TSN:0 TSN:0			22-AUG-2016 2978 1794		
26-20-13-900-802-05	ENGINE 1 SECOND-SHOOT PERCUSSION GREEN (L5WB) CARTRIDGE								
26.235	PN SN-UNKNOWN REF: AMM 26-20-13-900-802	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			14-JUN-2019 3636.3 2081		
26-20-13-900-802-06	ENGINE 3 SECOND-SHOOT PERCUSSION GREEN (R5WB) CARTRIDGE								
26.235	862700-00 NSN REF: AMM 26-20-13-900-802	MOS HRS/MSC AFL	H/T				13-APR-2010 1225.08 671		
26-20-13-900-802-07	ENGINE 2 FIRST-SHOOT LH PERCUSSION RED (L6WB) CARTRIDGE								
26.235	PN SN-UNKNOWN REF: AMM 26-20-13-900-802	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			14-JUN-2019 3636.3 2081		
26-20-13-900-802-08	ENGINE 2 FIRST-SHOOT RH PERCUSSION RED (R6WB) CARTRIDGE								
26.235	862710-00 NSN REF: AMM 26-20-13-900-802	MOS HRS/MSC AFL	H/T	TSN:8 TSN:0 TSN:0			19-MAY-2017 3080 1850		
26-20-13-900-804-01	APU PERCUSSION CARTRIDGE								
26.240	PN SN-UNKNOWN REF: AMM 26-20-13-900-804	MOS HRS/MSC AFL	H/T				14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-900-804-02	BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE								
26.240	PN SN-UNKNOWN REF: AMM 26-20-13-900-804	MOS HRS/MSC AFL	H/T				14-JUN-2019 3636.3 2081		
26-20-13-960-801-01	DISCARD ENGINE 1 FIRST-SHOOT PERCUSSION GREEN (L3WB) CARTRIDGE (SERVICE LIFE)								
26.120 SCRAP	862710-00 NSN REF:	MOS HRS/MSC AFL	120				19-MAY-2017	19-MAY-2027	
26-20-13-960-801-01M	DISCARD ENGINE 1 FIRST-SHOOT PERCUSSION GREEN (L3WB) CARTRIDGE (LIFE LIMIT)								
26.120 LIFE LIMIT	862710-00 NSN REF:	MOS HRS/MSC AFL	144				01-SEP-2016	01-SEP-2028	
26-20-13-960-801-02	DISCARD ENGINE 3 FIRST-SHOOT PERCUSSION GREEN (R3WB) CARTRIDGE (SERVICE LIFE)								
26.140 SCRAP	862710-00 NSN REF:	MOS HRS/MSC AFL	120				19-MAY-2017	19-MAY-2027	
26-20-13-960-801-02M	DISCARD ENGINE 3 FIRST-SHOOT PERCUSSION GREEN (R3WB) CARTRIDGE (LIFE LIMIT)								
26.140 LIFE LIMIT	862710-00 NSN REF:	MOS HRS/MSC AFL	144				01-SEP-2016	01-SEP-2028	
26-20-13-960-801-03	DISCARD ENGINE 2 SECOND-SHOOT LH PERCUSSION RED (L4WB) CARTRIDGE (SERVICE LIFE)								
26.120 SCRAP	862710-00 NSN REF:	MOS HRS/MSC AFL	120				19-MAY-2017	19-MAY-2027	
26-20-13-960-801-03M	DISCARD ENGINE 2 SECOND-SHOOT LH PERCUSSION RED (L4WB) CARTRIDGE (LIFE LIMIT)								
26.120 LIFE LIMIT	862710-00 NSN REF:	MOS HRS/MSC AFL	144				01-SEP-2016	01-SEP-2028	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-04 26.140 SCRAP	DISCARD ENGINE 2 SECOND-SHOOT RH PERCUSSION RED (R4WB) CARTRIDGE (SERVICE LIFE) 862700-00 NSN REF:	MOS HRS/MSC AFL	120				22-AUG-2016	22-AUG-2026	
26-20-13-960-801-04M 26.140 LIFE LIMIT	DISCARD ENGINE 2 SECOND-SHOOT RH PERCUSSION RED (R4WB) CARTRIDGE (LIFE LIMIT) 862700-00 NSN REF:	MOS HRS/MSC AFL	144				01-SEP-2015	01-SEP-2027	
26-20-13-960-801-05 26.130 SCRAP	DISCARD ENGINE 1 SECOND-SHOOT PERCUSSION GREEN (L5WB) CARTRIDGE (SERVICE LIFE) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				14-JUN-2019	14-JUN-2029	
26-20-13-960-801-05M 26.130 LIFE LIMIT	DISCARD ENGINE 1 SECOND-SHOOT PERCUSSION GREEN (L5WB) CARTRIDGE (LIFE LIMIT) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				14-JUN-2019	14-JUN-2031	
26-20-13-960-801-06 26.150 SCRAP	DISCARD ENGINE 3 SECOND-SHOOT PERCUSSION GREEN (R5WB) CARTRIDGE (SERVICE LIFE) 862700-00 NSN REF:	MOS HRS/MSC AFL	120				13-APR-2010 1225.08 671	13-APR-2020	
26-20-13-960-801-06M 26.150 LIFE LIMIT	DISCARD ENGINE 3 SECOND-SHOOT PERCUSSION GREEN (R5WB) CARTRIDGE (LIFE LIMIT) 862700-00 NSN REF:	MOS HRS/MSC AFL	144				22-DEC-2008 0 0	22-DEC-2020	
26-20-13-960-801-07 26.130 SCRAP	DISCARD ENGINE 2 FIRST-SHOOT LH PERCUSSION RED (L6WB) CARTRIDGE (SERVICE LIFE) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				14-JUN-2019	14-JUN-2029	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-07M 26.130 LIFE LIMIT	DISCARD ENGINE 2 FIRST-SHOOT LH PERCUSSION RED (L6WB) CARTRIDGE (LIFE LIMIT) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				14-JUN-2019	14-JUN-2031	
26-20-13-960-801-08 26.150 SCRAP	DISCARD ENGINE 2 FIRST-SHOOT RH PERCUSSION RED (R6WB) CARTRIDGE (SERVICE LIFE) 862710-00 NSN REF:	MOS HRS/MSC AFL	120				19-MAY-2017	19-MAY-2027	
26-20-13-960-801-08M 26.150 LIFE LIMIT	DISCARD ENGINE 2 FIRST-SHOOT RH PERCUSSION RED (R6WB) CARTRIDGE (LIFE LIMIT) 862710-00 NSN REF:	MOS HRS/MSC AFL	144				01-SEP-2016	01-SEP-2028	
26-20-13-960-801-09 26.110 SCRAP	DISCARD APU PERCUSSION CARTRIDGE (SERVICE LIFE) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				14-JUN-2019	14-JUN-2029	
26-20-13-960-801-09M 26.110 LIFE LIMIT	DISCARD APU PERCUSSION CARTRIDGE (LIFE LIMIT) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				14-JUN-2019	14-JUN-2031	
26-20-13-960-801-10 26.110 SCRAP	DISCARD BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (SERVICE LIFE) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				14-JUN-2019	14-JUN-2029	
26-20-13-960-801-10M 26.110 LIFE LIMIT	DISCARD BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (LIFE LIMIT) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				14-JUN-2019	14-JUN-2031	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-15-720-801-01	WEIGHING COCKPIT PORTABLE EXTINGUISHER C-352 C-90385943 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	O/C				06-SEP-2018		
26.170									
+ 26-20-15-720-801-02	WEIGHING FORWARD CABIN PORTABLE EXTINGUISHER C-352 C-90385807 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	O/C				06-SEP-2018		
26.180									
+ 26-20-15-720-801-03	WEIGHING REAR CABIN PORTABLE EXTINGUISHER 898052 Y-172086 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	24	+3%			14-JUN-2019	14-JUN-2021	05-JUL-2021
26.190									
+ 26-20-15-790-801-01	HYDROSTATIC CHECK COCKPIT PORTABLE EXTINGUISHER C-352 C-90385943 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144	+3%			19-MAY-2017	19-MAY-2029	28-SEP-2029
26.170									
+ 26-20-15-790-801-02	HYDROSTATIC CHECK FORWARD CABIN PORTABLE EXTINGUISHER C-352 C-90385807 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144	+3%			19-MAY-2017	19-MAY-2029	28-SEP-2029
26.180									
+ 26-20-15-790-801-03	HYDROSTATIC CHECK REAR CABIN PORTABLE EXTINGUISHER 898052 Y-172086 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144	+3%			01-NOV-2011	01-NOV-2023	10-MAR-2024
26.190									
26-20-15-900-801-01	COCKPIT PORTABLE EXTINGUISHER C-352 C-90385943 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2017 3080 1850		
26.170					TSN:0 TSN:0 TSN:0				

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-15-900-801-02	FORWARD CABIN PORTABLE EXTINGUISHER								
26.180	C-352 C-90385807 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-MAY-2017 3080 1850		
26-20-15-900-801-03	REAR CABIN PORTABLE EXTINGUISHER								
26.190	898052 Y-172086 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-JUN-2012 1972.17 1216		
26-20-15-900-801-04	BAGGAGE COMPARTMENT PORTABLE EXTINGUISHER								
	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
26-90-01-900-801-01	DISPOSABLE FIRE EXTINGUISHER								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
261021	BAGGAGE COMPARTMENT SMOKE DETECTOR								
26.040	FR2220 FW927 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
261042	RIGHT MAIN LANDING GEAR PINPOINT FIRE DETECTOR								
26.050	HB160 UK0653 REF: AMM 26-10-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
261816	NO.1 AND NO.3 ENGINE FIRE MONITOR BOX								
26.060	6342-01 1432 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261821	NO.2 AND APU ENGINE FIRE MONITOR BOX								
26.070	6342-01 1438 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 27 FLIGHT CONTROLS									
27-00-00-220-801-01A	VISUAL INSPECTION OF FLIGHT CONTROL HYDRAULIC COMPONENTS FOR EXTERNAL LEAKS (MANDATORY 5-40)								
27.580 CMR	REF: AMM 27-00-00-220-801	MOS HRS/MSC AFL	4000				19-OCT-2007 0 0	4000	
27-00-00-640-801-01 (s)	PRESSURE GREASING OF LEFT AILERON SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
27-00-00-640-801-02 (s)	PRESSURE GREASING OF RIGHT AILERON SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
27-00-00-640-801-03 (s)	PRESSURE GREASING RUDDER SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
27-00-00-640-801-04 (s)	PRESSURE GREASING ELEVATOR SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
27-00-00-640-802-01 (s)	PRESSURE GREASING/LUBRICATION OF FLIGHT CONTROL BEARING AND HINGE PINS								
27.035	PKG 32 REF: AMM 27-00-00-640-802	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-640-802-02 (s)	PRESSURE GREASING/LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN THE NON PRESSURIZED AREA						PKG		
27.035	PKG 32	MOS	144	+2m			19-OCT-2007	0	
	REF: AMM 27-00-00-640-802	HRS/MSC AFL	7500				0	0	
+ 27-00-00-640-805-01 (s)	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - ROLL PRESSURE SEALED BOX						PKG		
27.050	PKG 32	MOS	144	+2m			19-OCT-2007	0	
	REF: AMM 27-00-00-640-805	HRS/MSC AFL	7500				0	0	
+ 27-00-00-640-805-02 (s)	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - YAW PRESSURE SEALED BOX						PKG		
27.050	PKG 32	MOS	144	+2m			19-OCT-2007	0	
	REF: AMM 27-00-00-640-805	HRS/MSC AFL	7500				0	0	
+ 27-00-00-640-805-03 (s)	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - PITCH PRESSURE SEALED BO						PKG		
27.050	PKG 32	MOS	144	+2m			19-OCT-2007	0	
	REF: AMM 27-00-00-640-805	HRS/MSC AFL	7500				0	0	
+ 27-00-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO.1 SYSTEM FLIGHT CONTROLS						PKG		
27.010	PKG 21	MOS	1600	+40			14-JUN-2019	3636.3	2081
	REF: AMM 27-00-00-710-801	HRS/MSC AFL					2081		
+ 27-00-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO.2 SYSTEM FLIGHT CONTROLS						PKG		
27.010	PKG 21	MOS	1600	+40			14-JUN-2019	3636.3	2081
	REF: AMM 27-00-00-710-801	HRS/MSC AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-00-00-710-802-01 (s)	OPERATIONAL TEST OF AILERON TRIM SYSTEM						PKG		
27.015	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 27-00-00-710-802	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 27-00-00-710-802-02 (s)	OPERATIONAL TEST OF EMERGENCY AILERON TRIM SYSTEM						PKG		
27.015	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 27-00-00-710-802	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 27-00-00-710-802-03 (s)	OPERATIONAL TEST OF RUDDER TRIM SYSTEM						PKG		
27.015	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 27-00-00-710-802	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 27-00-00-720-804-01 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF LH ROLL AAFU						PKG		
27.045	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF:	HRS/MSC					0		
		AFL	7500				0		
+ 27-00-00-720-804-01A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF LH ROLL AAFU (MANDATORY REF 5-40-20)								
27.045		MOS					19-OCT-2007		
CMR	REF:	HRS/MSC	10000				0		10000
		AFL					0		
+ 27-00-00-720-804-02 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF LH ROLL AAFU						PKG		
27.045	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF:	HRS/MSC					0		
		AFL	7500				0		
+ 27-00-00-720-804-02A	CHECK CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF LH ROLL AAFU (MANDATORY 5-40)								
27.045		MOS					19-OCT-2007		
CMR	REF:	HRS/MSC	10000				0		10000
		AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-00-00-720-804-03 (s)	CHECK CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF RH ROLL AAFU						PKG		
27.045	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF:	HRS/MSC					0		
		AFL	7500				0		
+ 27-00-00-720-804-03A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF RH ROLL AAFU (MANDATORY 5-40)						19-OCT-2007		
27.045		MOS					0	10000	
CMR	REF:	HRS/MSC	10000				0		
		AFL					0		
+ 27-00-00-720-804-04 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF RH ROLL AAFU						PKG		
	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF:	HRS/MSC					0		
		AFL	7500				0		
+ 27-00-00-720-804-04A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF RH ROLL AAFU (MANDATORY 5-40)						19-OCT-2007		
		MOS					0	10000	
CMR	REF:	HRS/MSC	10000				0		
		AFL					0		
+ 27-00-00-720-804-05 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF YAW AAFU						PKG		
	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF:	HRS/MSC					0		
		AFL	7500				0		
+ 27-00-00-720-804-05A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF YAW AAFU (MANDATORY 5-40)						19-OCT-2007		
		MOS					0	10000	
CMR	REF:	HRS/MSC	10000				0		
		AFL					0		
+ 27-00-00-720-804-06 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF YAW AAFU						PKG		
	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF:	HRS/MSC					0		
		AFL	7500				0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-00-00-720-804-06A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF YAW AAFU (MANDATORY 5-40)	MOS					19-OCT-2007		
CMR	REF:	HRS/MSC	10000				0		10000
		AFL					0		
+ 27-00-00-720-804-07 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF PITCH AAFU	MOS	144	+2m			19-OCT-2007		
	PKG 32	HRS/MSC					0		
	REF:	AFL	7500				0		
+ 27-00-00-720-804-07A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF PITCH AAFU (MANDATORY 5-40)	MOS					19-OCT-2007		
CMR	REF:	HRS/MSC	10000				0		10000
		AFL					0		
+ 27-00-00-720-804-08 (s)	CHECK CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF PITCH AAFU	MOS	144	+2m			19-OCT-2007		
	PKG 32	HRS/MSC					0		
	REF:	AFL	7500				0		
+ 27-00-00-720-804-08A	CHECK CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF PITCH AAFU (MANDATORY 5-40)	MOS					19-OCT-2007		
CMR	REF:	HRS/MSC	10000				0		10000
		AFL					0		
+ 27-00-00-790-804-01 (s)	CHECK OF THE INTERNAL LEAKS OF LEFT AILERON SERVO-ACTUATORS	MOS	216	+2m			19-OCT-2007		
	PKG 33	HRS/MSC					0		
27.040	REF: AMM 27-00-00-790-804	AFL	11250				0		
27-00-00-790-804-02 (s)	CHECK OF THE INTERNAL LEAKS OF RIGHT AILERON SERVO-ACTUATORS	MOS	216	+2m			19-OCT-2007		
	PKG 33	HRS/MSC					0		
27.040	REF: AMM 27-00-00-790-804	AFL	11250				0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-00-00-790-804-03 (s)	CHECK OF THE INTERNAL LEAKS OF RUDDER SERVO-ACTUATORS						PKG		
27.040	PKG 33	MOS	216	+2m			19-OCT-2007		
	REF: AMM 27-00-00-790-804	HRS/MSC AFL	11250				0 0		
+ 27-00-00-790-804-04 (s)	CHECK OF THE INTERNAL LEAKS OF ELEVATOR SERVO-ACTUATORS						PKG		
27.040	PKG 33	MOS	216	+2m			19-OCT-2007		
	REF: AMM 27-00-00-790-804	HRS/MSC AFL	11250				0 0		
27-00-00-900-801-01	LH ROLL CONTROL ROD								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
27-00-00-900-801-02	RH ROLL CONTROL ROD								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
27-00-00-900-801-03	YAW CONTROL ROD								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
27-00-00-960-801-01	REPLACEMENT LH ROLL CONTROL ROD								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF:	AFL					0		
27-00-00-960-801-02	REPLACEMENT RH ROLL CONTROL ROD								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF:	AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-960-801-03	REPLACEMENT YAW CONTROL ROD PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
27-00-00-960-801-04	REPLACEMENT PITCH CONTROL ROD PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
27-12-01-900-801-01 27.145	LEFT AILERON SERVO ACTUATOR 103117-05 1631 REF: AMM 27-12-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-12-01-900-801-02 27.145	RIGHT AILERON SERVO ACTUATOR 103117-06 1639 REF: AMM 27-12-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-13-01-640-805-01 (s) 27.600	LUBRICATION OF THE ROLL PRESSURE-SEALED-BOX BELLCRANK OUTSIDE PRESSURIZED AREA PKG 31 REF: AMM 27-13-01-640-805	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		
27-13-01-640-806-01 (s)	LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA PKG 31 REF: AMM 27-13-01-640-806	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		
27-13-01-640-807-01 (s) 27.100	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA PKG 31 REF: AMM 27-13-01-640-807	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-13-01-640-808-01 (s)	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
27.095	PKG 16 REF: AMM 27-13-01-640-808	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
27-13-03-960-801-01 (s)	REMOVAL / INSTALLATION OF THE FR15 ROLL BELLCRANKS FOR INSPECTION AND REPLACEMENT OF BALL BEARINGS						PKG		
27.585	PKG 31 REF: AMM 27-13-03-220-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
27-13-03-960-801-02 (s)	REMOVAL / INSTALLATION OF THE FR15 ROLL BELLCRANKS FOR INSPECTION AND REPLACEMENT OF BALL BEARINGS						PKG		
27.585	PKG 31 REF: AMM 27-13-03-220-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
+ 27-14-01-350-801-01	RESTORATION AILERON TRIM ACTUATOR (FUNCTIONAL TEST)								
27.125	021057-37 9770 REF: AMM 27-14-01-350-801	MOS HRS/MSC AFL	144	+3%			19-OCT-2007 0 0	19-OCT-2019	28-FEB-2020
27-14-01-900-801-01	AILERON TRIM ACTUATOR								
27.125	021057-37 9770 REF: AMM 27-14-01-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
+ 27-14-03-350-801-01	RESTORATION AILERON EMERGENCY ACTUATOR (FUNCTIONAL TEST)								
27.130	021127-01 1141 REF: AMM 27-14-03-350-801	MOS HRS/MSC AFL	144	+3%			19-OCT-2007 0 0	19-OCT-2019	28-FEB-2020
27-14-03-900-801-01	AILERON EMERGENCY ACTUATOR								
27.130	021127-01 1141 REF: AMM 27-14-03-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-14-05-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAY BOX						PKG		
27.110	PKG 32	MOS	144	+2m			19-OCT-2007		
		HRS/MSC					0		
	REF: AMM 27-14-05-720-801	AFL	7500				0		
+ 27-14-05-720-801-01A	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAY BOX (MANDATORY REF 5-40-20)						19-OCT-2007		
27.110		MOS					0	20000	
CMR	REF: AMM 27-14-05-720-801	HRS/MSC	20000				0		
		AFL					0		
27-15-01-640-801-01 (s)	PRESSURE GREASE OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS						PKG		
27.105	PKG 32	MOS	144	+2m			19-OCT-2007		
		HRS/MSC					0		
	REF: AMM 27-15-01-640-801	AFL	7500				0		
+ 27-15-01-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK						PKG		
27.120	PKG 31	MOS	72	+2m			19-NOV-2013		
		HRS/MSC					2320.42		
	REF: AMM 27-15-01-720-801	AFL	3750				1495		
27-15-01-900-801-01	AILERON ARTHUR Q-UNIT						19-OCT-2007		
27.150	8421-6	MOS			TSN:0		0		
	1116	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 27-15-01-900-801	AFL			TSN:0		0		
+ 27-15-05-350-801-01	RESTORATION AILERON ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST / SERVICING)						19-OCT-2007	19-OCT-2019	28-FEB-2020
27.135	105124	MOS	144	+3%			0		
	766	HRS/MSC					0		
	REF: AMM 27-15-05-350-801	AFL					0		
27-15-05-900-801-01	AILERON ARTIFICIAL FEEL UNIT						19-OCT-2007		
27.135	105124	MOS			TSN:0		0		
	766	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 27-15-05-900-801	AFL			TSN:0		0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15-07-640-801-01 (s)	PRESSURE GREASING LEFT OF THE LH ROLL AUXILIARY AFU (AAFU) BEARING						PKG		
27.115	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF: AMM 27-15-07-640-801	HRS/MSC					0		
		AFL	7500				0		
27-15-07-640-801-02 (s)	PRESSURE GREASING OF THE RH ROLL AUXILIARY AFU (AAFU) BEARING						PKG		
	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF: AMM 27-15-07-640-801	HRS/MSC					0		
		AFL	7500				0		
+ 27-22-01-350-801-01	RESTORATION RUDDER SERVO ACTUATOR (FUNCTIONAL TEST)								
27.190	103103-18	MOS					19-OCT-2007		
	1326	HRS/MSC	4000				0		4000
	REF: AMM 27-22-01-350-801	AFL					0		
+ 27-22-01-350-801-01A	RESTORATION RUDDER SERVO ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40)								
27.190	103103-18	MOS					19-OCT-2007		
CMR	1326	HRS/MSC	4000				0		4000
	REF: AMM 27-22-01-350-801	AFL					0		
27-22-01-900-801-01	RUDDER SERVO ACTUATOR								
27.190	103103-18	MOS			TSN:0		19-OCT-2007		
	1326	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 27-22-01-900-801	AFL			TSN:0		0		
27-23-01-640-806-01 (s)	LUBRICATION OF YAW CONTROL LINKAGE HINGES OUTSIDE PRESSURIZED AREA						PKG		
27.160	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 27-23-01-640-806	HRS/MSC					2320.42		
		AFL	3750				1495		
27-23-01-640-807-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						PKG		
27.165	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 27-23-01-640-807	HRS/MSC					2320.42		
		AFL	3750				1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-23-01-640-808-01 (s)	GREASING OF YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
27.160	PKG 16 REF: AMM 27-23-01-640-808	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 27-24-01-350-801-01	RESTORATION YAW TRIM ACTUATOR (FUNCTIONAL TEST)								
27.185	021057-36 9761 REF: AMM 27-24-01-350-801	MOS HRS/MSC AFL	144	+3%			19-OCT-2007 0 0	19-OCT-2019	28-FEB-2020
27-24-01-900-801-01	YAW TRIM ACTUATOR								
27.185	021057-36 9761 REF: AMM 27-24-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
27-24-01-900-801-02	YAW MAIN ARTIFICIAL FEEL UNIT								
27.175	105125 776 REF: AMM 27-24-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 27-24-05-720-802-01 (s)	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS						PKG		
27.170	PKG 32 REF: AMM 27-24-05-720-802	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
+ 27-24-05-720-802-01A	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS (MANDATORY REF 5-40-20)								
27.170 CMR	REF: AMM 27-24-05-720-802	MOS HRS/MSC AFL	20000				19-OCT-2007 0 0	20000	
+ 27-25-05-350-801-01	RESTORATION YAW MAIN ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST / SERVICING)								
27.175	105125 776 REF: AMM 27-25-05-350-801	MOS HRS/MSC AFL	144	+3%			19-OCT-2007 0 0	19-OCT-2019	28-FEB-2020

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-25-07-350-801-01	RESTORATION YAW AUXILIARY ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST / SERVICING)								
27.175	105070-04 1881 REF: AMM 27-25-07-350-801	MOS HRS/MSC AFL	144	+3%			19-OCT-2007 0 0	19-OCT-2019	28-FEB-2020
27-25-07-900-801-01	YAW AUXILIARY ARTIFICIAL FEEL UNIT								
27.175	105070-04 1881 REF: AMM 27-25-07-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
27-31-01-640-801-01 (s)	GREASING OF THE PILOT CONTROL COLUMN (AND WHEEL)						PKG		
27.345	PKG 32 REF: AMM 27-31-01-640-801	MOS HRS/MSC AFL	144	+2m 7500			19-OCT-2007 0 0		
27-31-01-640-801-02 (s)	GREASING OF THE COPILOT CONTROL COLUMN (AND WHEEL)						PKG		
27.345	PKG 32 REF: AMM 27-31-01-640-801	MOS HRS/MSC AFL	144	+2m 7500			19-OCT-2007 0 0		
27-31-01-900-801-01	PILOT CONTROL COLUMN								
27.345	VLP302-10 132 REF: AMM 27-31-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
27-31-01-900-801-02	COPILOT CONTROL COLUMN								
27.345	VLC302-10 132 REF: AMM 27-31-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 27-32-01-350-801-01	RESTORATION ELEVATOR SERVO ACTUATOR (FUNCTIONAL TEST)								
27.235	103144-04 439 REF: AMM 27-32-01-350-801	MOS HRS/MSC AFL	10000	+3%			19-OCT-2007 0 0	10000	10300

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-32-01-350-801-01A	RESTORATION ELEVATOR SERVO ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-20)								
27.235	103144-04	MOS					19-OCT-2007		
CMR	439	HRS/MSC	14000				0		14000
	REF: AMM 27-32-01-350-801	AFL					0		
+ 27-32-01-350-801-01B (s)	RESTORATION ELEVATOR SERVO ACTUATOR DAMPER (FUNCTIONAL TEST) (MANDATORY REF 5-40-20)								
27.235	103144-04	MOS					19-OCT-2007		
CMR	439	HRS/MSC	14000				0		
	REF: AMM 27-32-01-350-801	AFL					0		
27-32-01-900-801-01	ELEVATOR SERVO ACTUATOR								
27.235	103144-04	MOS		TSN:0			19-OCT-2007		
	439	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-32-01-900-801	AFL		TSN:0			0		
27-33-01-640-806-01 (s)	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.205	PKG 31	MOS	72	+2m			19-NOV-2013		
		HRS/MSC					2320.42		
	REF: AMM 27-33-01-640-806	AFL	3750				1495		
27-33-01-640-807-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHING IN PRESSURIZED AREA						PKG		
27.195	PKG 31	MOS	72	+2m			19-NOV-2013		
		HRS/MSC					2320.42		
	REF: AMM 27-33-01-640-807	AFL	3750				1495		
27-33-01-640-808-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHING OUTSIDE PRESSURIZED AREA						PKG		
27.200	PKG 16	MOS	24	+1m			14-JUN-2019		
		HRS/MSC					3636.3		
	REF: AMM 27-33-01-640-808	AFL					2081		
27-33-01-900-801-03	PITCH CONTROL ROD								
	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-35-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM						PKG		
27.225	PKG 22 REF: AMM 27-35-00-720-801	MOS HRS/MSC AFL	3200	+40			15-JUN-2017 3125.5 1867		
27-35-01-640-801-01 (s)	PRESSURE GREASE OF THE ELEVATOR ARTHUR Q-UNIT BEARINGS						PKG		
27.215	PKG 32 REF: AMM 27-35-01-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
27-35-01-900-801-01	ELEVATOR ARTHUR Q-UNIT								
27.215	106126-01 482 REF: AMM 27-35-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 27-35-05-350-801-01	RESTORATION PITCH MAIN ARTIFICIAL FEEL UNIT (FUNCTIONAL/TEST / SERVICING)								
27.230	105122-02 757 REF: AMM 27-35-05-350-801	MOS HRS/MSC AFL	144	+3%			19-OCT-2007 0 0	19-OCT-2019	28-FEB-2020
27-35-07-640-801-01 (s)	PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS						PKG		
27.220	PKG 32 REF: AMM 27-35-07-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
27-35-07-900-801-01	ELEVATOR AUXILIARY ARTIFICIAL FEEL UNIT								
27.240	105045-13 5599 REF: AMM 27-35-07-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 27-40-00-720-801-01 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM						PKG		
27.275	PKG 21 REF: AMM 27-40-00-720-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-40-01-210-802-01	VISUAL CHECK HORIZONTAL STABILIZER ELECTRIC ACTUATOR								
27.285	021121-12 1157 REF: AMM 27-40-01-210-802	MOS HRS/MSC AFL	72 3750	+3% +3%			19-NOV-2013 2320.42 1495	19-NOV-2019 5245	23-JAN-2020 5357.5
27-40-01-350-801-01	RESTORATION HORIZONTAL STABILIZER ELECTRIC ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT)								
27.285	021121-12 1157 REF: AMM 27-40-01-350-801	MOS HRS/MSC AFL	144 7500	+3% +3%			19-OCT-2007 0 0	19-OCT-2019 7500	28-FEB-2020 7725
27-40-01-640-802-01 (s)	GREASING OF HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW								
27.260	PKG 5,201 REF: AMM 27-40-01-640-802	MOS HRS/MSC AFL	12 800	+1m +40			PKG 14-JUN-2019 3636.3 2081		
27-40-01-900-801-01	HORIZONTAL STABILIZER ELECTRIC ACTUATOR								
27.285	021121-12 1157 REF: AMM 27-40-01-900-801	MOS HRS/MSC AFL	O/C		TSN:73 TSN:2320.42 TSN:1495		19-NOV-2013 2320.42 1495		
27-40-05-900-801-01	HORIZONTAL STABILIZER POSITION REPEATER BOX								
27.310	016095-02 678 REF: AMM 27-40-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 27-40-15-710-801-01 (s)	OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY								
27.295	PKG 32 REF: AMM 27-40-15-710-801	MOS HRS/MSC AFL	144 7500	+2m			PKG 19-OCT-2007 0 0		
+ 27-40-15-710-801-01A	OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY (MANDATORY REF 5-40-20)								
27.295 CMR	REF: AMM 27-40-15-710-801	MOS HRS/MSC AFL	16000				19-OCT-2007 0 0	16000	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-40-17-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX						PKG		
27.280	PKG 23	MOS					19-OCT-2007		
	REF: AMM 27-40-17-720-801	HRS/MSC	4800	+40			0		
		AFL					0		
+ 27-40-17-720-801-01A	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX (MANDATORY REF 5-40-20)								
27.280		MOS					19-OCT-2007		
CMR	REF: AMM 27-40-17-720-801	HRS/MSC	5000				0	5000	
		AFL					0		
27-50-00-640-801-01 (s)	GREASING/LUBRICATION OF FLAP MECHANISMS						PKG		
27.590	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 27-50-00-640-801	HRS/MSC					3636.3		
		AFL					2081		
27-50-00-710-801-01	OPERATIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM								
		MOS					11-FEB-2011		
	REF: AMM 27-50-00-710-801	HRS/MSC	O/C				1541.42		
		AFL					872		
+ 27-50-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM						PKG		
27.335	PKG 21	MOS					14-JUN-2019		
	REF: AMM 27-50-00-720-801	HRS/MSC	1600	+40			3636.3		
		AFL					2081		
27-50-00-720-801-02	FUNCTIONAL TEST FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM - USING THE STAND-BY ELECTRICAL PUMP								
		MOS					19-OCT-2007		
	REF: AMM 27-50-00-720-801	HRS/MSC	O/C				0		
		AFL					0		
+ 27-50-00-720-802-01	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM								
27.330		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
	REF: AMM 27-50-00-720-802	HRS/MSC	400	+40			3636.3	4036.3	4076.3
		AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50-00-720-802-01A	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)								
27.330		MOS					14-JUN-2019		
CMR	REF: AMM 27-50-00-720-802	HRS/MSC AFL	450				3636.3 2081		4086.3
27-50-00-720-803-01 (s)	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE						PKG		
27.560	PKG 22	MOS					15-JUN-2017		
	REF: AMM 27-50-00-720-803	HRS/MSC AFL	3200	+40			3125.5 1867		
27-52-01-900-801-01 (s)	POWER FLAPS DRIVE UNIT								
27.375	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 27-52-01-900-801	AFL			TSN:0		0		
27-52-13-200-801-01 (s)	CHECK / GREASING OF THE LH WING FLAP CONTROL ROD SPLINES						PKG		
27.350	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 27-52-13-200-801	HRS/MSC AFL	3750				2320.42 1495		
27-52-13-200-801-02 (s)	CHECK / GREASING OF THE RH WING FLAP CONTROL ROD SPLINES						PKG		
	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 27-52-13-200-801	HRS/MSC AFL	3750				2320.42 1495		
27-53-01-220-801-01	CLEANING/CHECK OF THE LEFT OUTBOARD FLAP ACTUATOR OF THE ACTUATING SCREW								
27.595		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
	REF: AMM 27-53-01-220-801	HRS/MSC AFL	400	+40			3636.3 2081	4036.3	4076.3
27-53-01-220-801-02	CLEANING/CHECK OF THE LEFT INBOARD FLAP EXTERNAL ACTUATOR OF THE ACTUATING SCREW								
27.595		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
	REF: AMM 27-53-01-220-801	HRS/MSC AFL	400	+40			3636.3 2081	4036.3	4076.3

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-220-801-03	CLEANING/CHECK OF THE LEFT INBOARD FLAP INTERNAL ACTUATOR OF THE ACTUATING SCREW								
27.595	REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	12 400	+1m +40			14-JUN-2019 3636.3 2081	14-JUN-2020 4036.3	14-JUL-2020 4076.3
27-53-01-220-801-04	CLEANING/CHECK OF THE RIGHT INBOARD FLAP INTERNAL ACTUATOR OF THE ACTUATING SCREW								
27.595	REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	12 400	+1m +40			14-JUN-2019 3636.3 2081	14-JUN-2020 4036.3	14-JUL-2020 4076.3
27-53-01-220-801-05	CLEANING/CHECK OF THE RIGHT INBOARD FLAP EXTERNAL ACTUATOR OF THE ACTUATING SCREW								
27.595	REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	12 400	+1m +40			14-JUN-2019 3636.3 2081	14-JUN-2020 4036.3	14-JUL-2020 4076.3
27-53-01-220-801-06	CLEANING/CHECK OF THE RIGHT OUTBOARD FLAP ACTUATOR OF THE ACTUATING SCREW								
27.595	REF: AMM 27-53-01-220-801	MOS HRS/MSC AFL	12 400	+1m +40			14-JUN-2019 3636.3 2081	14-JUN-2020 4036.3	14-JUL-2020 4076.3
27-53-01-350-801-01	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL)								
27.360 OVERHAUL	1-5319-3 766 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	4500				19-OCT-2007 0 0	4500	
27-53-01-350-801-01A	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
RETEX	1-5319-3 766 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	4500				19-OCT-2007 0 0	4500	
27-53-01-350-801-02	RESTORATION LH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL)								
27.365 OVERHAUL	5318-3 2830 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	3500				19-OCT-2007 0 0	3500	



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-350-801-02A	RESTORATION LH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	5318-3	MOS					19-OCT-2007		
	2830	HRS/MSC					0		
RETEX	REF: AMM 27-53-01-350-801	AFL	3500				0		3500
27-53-01-350-801-03	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL)								
	5318-3	MOS					19-OCT-2007		
27.370	2827	HRS/MSC					0		
OVERHAUL	REF: AMM 27-53-01-350-801	AFL	3500				0		3500
27-53-01-350-801-03A	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	5318-3	MOS					19-OCT-2007		
	2827	HRS/MSC					0		
RETEX	REF: AMM 27-53-01-350-801	AFL	3500				0		3500
27-53-01-350-801-04	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL)								
	5318-3	MOS					19-OCT-2007		
27.371	2828	HRS/MSC					0		
OVERHAUL	REF: AMM 27-53-01-350-801	AFL	3500				0		3500
27-53-01-350-801-04A	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	5318-3	MOS					19-OCT-2007		
	2828	HRS/MSC					0		
RETEX	REF: AMM 27-53-01-350-801	AFL	3500				0		3500
27-53-01-350-801-05	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL)								
	5318-3	MOS					19-OCT-2007		
27.366	2829	HRS/MSC					0		
OVERHAUL	REF: AMM 27-53-01-350-801	AFL	3500				0		3500
27-53-01-350-801-05A	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	5318-3	MOS					19-OCT-2007		
	2829	HRS/MSC					0		
RETEX	REF: AMM 27-53-01-350-801	AFL	3500				0		3500

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-350-801-06	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL)								
27.361	2-5319-3	MOS					19-OCT-2007		
OVERHAUL	766	HRS/MSC					0		
	REF: AMM 27-53-01-350-801	AFL	4500				0		4500
27-53-01-350-801-06A	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	2-5319-3	MOS					19-OCT-2007		
RETEX	766	HRS/MSC					0		
	REF: AMM 27-53-01-350-801	AFL	4500				0		4500
27-53-01-640-802-01	GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK								
27.605		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
		HRS/MSC	400	+40			3636.3	4036.3	4076.3
	REF: AMM 27-53-01-640-802	AFL					2081		
27-53-01-640-802-02	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK								
27.605		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
		HRS/MSC	400	+40			3636.3	4036.3	4076.3
	REF: AMM 27-53-01-640-802	AFL					2081		
27-53-01-640-802-03	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK								
27.605		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
		HRS/MSC	400	+40			3636.3	4036.3	4076.3
	REF: AMM 27-53-01-640-802	AFL					2081		
27-53-01-640-802-04	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK								
27.605		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
		HRS/MSC	400	+40			3636.3	4036.3	4076.3
	REF: AMM 27-53-01-640-802	AFL					2081		
27-53-01-640-802-05	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK								
27.605		MOS	12	+1m			14-JUN-2019	14-JUN-2020	14-JUL-2020
		HRS/MSC	400	+40			3636.3	4036.3	4076.3
	REF: AMM 27-53-01-640-802	AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-640-802-06	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK								
27.605	REF: AMM 27-53-01-640-802	MOS HRS/MSC AFL	12 400	+1m +40			14-JUN-2019 3636.3 2081	14-JUN-2020 4036.3	14-JUL-2020 4076.3
27-53-01-720-803-01	CHECK LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY								
27.360	REF: AMM 27-53-01-720-803	1-5319-3 766 AFL					19-OCT-2007 0 0	3000	
27-53-01-720-803-01A	CHECK LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (MANDATORY REF 5-40)								
RETEX	REF: AMM 27-53-01-720-803	1-5319-3 766 AFL		3000			19-OCT-2007 0 0	3000	
27-53-01-720-803-02	CHECK LH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY								
27.365	REF: AMM 27-53-01-720-803	5318-3 2830 AFL		3000			25-NOV-2009 1054.5 582	3582	
27-53-01-720-803-02A	CHECK LH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (MANDATORY REF 5-40)								
RETEX	REF: AMM 27-53-01-720-803	5318-3 2830 AFL		3000			25-NOV-2009 1054.5 582	3582	
27-53-01-720-803-03	CHECK LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY								
27.370	REF: AMM 27-53-01-720-803	5318-3 2827 AFL		3000		TSI:582	25-NOV-2009 1054.5 582	3000	
27-53-01-720-803-03A	CHECK LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (MANDATORY REF 5-40)								
RETEX	REF: AMM 27-53-01-720-803	5318-3 2827 AFL		3000		TSI:582	25-NOV-2009 1054.5 582	3000	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-720-803-04 27.371	CHECK RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY 5318-3 2828 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL	3000	TSI:582			25-NOV-2009 1054.5 582		3000
27-53-01-720-803-04A RETEX	CHECK RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (MANDATORY REF 5-40) 5318-3 2828 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL	3000	TSI:582			25-NOV-2009 1054.5 582		3000
27-53-01-720-803-05 27.366	CHECK RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY 5318-3 2829 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL	3000	TSI:582			25-NOV-2009 1054.5 582		3000
27-53-01-720-803-05A RETEX	CHECK RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (MANDATORY REF 5-40) 5318-3 2829 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL	3000	TSI:582			25-NOV-2009 1054.5 582		3000
27-53-01-720-803-06 27.361	CHECK RH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY 2-5319-3 766 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL	3000				19-OCT-2007 0 0		3000
27-53-01-720-803-06A RETEX	CHECK RH OUTBOARD FLAP SCREW JACK SCREW/ NUT PLAY (MANDATORY REF 5-40) 2-5319-3 766 REF: AMM 27-53-01-720-803	MOS HRS/MSC AFL	3000				19-OCT-2007 0 0		3000
27-53-01-900-803-01 27.360	LH OUTBOARD FLAP SCREW JACK 1-5319-3 766 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-900-803-02	LH INBOARD FLAP LATERAL SCREW JACK								
27.365	5318-3 2830 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-53-01-900-803-03	LH INBOARD FLAP CENTER SCREW JACK								
27.370	5318-3 2827 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-53-01-900-803-04	RH INBOARD FLAP CENTER SCREW JACK								
27.371	5318-3 2828 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-53-01-900-803-05	RH INBOARD FLAP LATERAL SCREW JACK								
27.366	5318-3 2829 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-53-01-900-803-06	RH OUTBOARD FLAP SCREW JACK								
27.361	2-5319-3 766 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-53-01-960-801-01	DISCARD LH OUTBOARD FLAP SCREW JACK								
27.360 LIFE LIMIT	1-5319-3 766 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	16000				19-OCT-2007 0 0		16000
27-53-01-960-801-02	DISCARD LH INBOARD FLAP LATERAL SCREW JACK								
27.365 LIFE LIMIT	5318-3 2830 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	15000				19-OCT-2007 0 0		15000

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-960-801-03	DISCARD LH INBOARD FLAP CENTER SCREW JACK								
	5318-3	MOS					19-OCT-2007		
27.370	2827	HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-53-01-960-801	AFL	15000				0		15000
27-53-01-960-801-04	DISCARD RH INBOARD FLAP CENTER SCREW JACK								
	5318-3	MOS					19-OCT-2007		
27.371	2828	HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-53-01-960-801	AFL	15000				0		15000
27-53-01-960-801-05	DISCARD RH INBOARD FLAP LATERAL SCREW JACK								
	5318-3	MOS					19-OCT-2007		
27.366	2829	HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-53-01-960-801	AFL	15000				0		15000
27-53-01-960-801-06	DISCARD RH OUTBOARD FLAP SCREW JACK								
	2-5319-3	MOS					19-OCT-2007		
27.361	766	HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-53-01-960-801	AFL	16000				0		16000
+ 27-60-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIRBRAKES IN NORMAL MODE						PKG		
	PKG 21	MOS					15-JUN-2017		
27.410		HRS/MSC	1600	+40			3125.5		
	REF: AMM 27-60-00-710-801	AFL					1867		
27-61-00-720-801-01	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU HARDWARE" RELAY)								
		MOS					14-JUN-2018		
27.340		HRS/MSC	600	+40			3406.6	4006.6	4046.6
	REF: AMM 27-61-00-720-801	AFL					1988		
27-61-00-720-801-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU HARDWARE" RELAY) (MANDATORY REF 05-40/20)								
		MOS					14-JUN-2018		
27.340		HRS/MSC	650				3406.6	4056.6	
CMR	REF: AMM 27-61-00-720-801	AFL					1988		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-61-00-720-802-01	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("LH THROTTLE" AND "RH THROTTLE" RELAYS)								
27.565	REF: AMM 27-61-00-720-802	MOS HRS/MSC AFL	600	+40			14-JUN-2018 3406.6 1988	4006.6	4046.6
+ 27-61-00-720-802-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("LH THROTTLE" AND "RH THROTTLE" RELAYS) (MANDATORY REF 05-40/20)								
27.565 CMR	REF: AMM 27-61-00-720-802	MOS HRS/MSC AFL	650				14-JUN-2018 3406.6 1988	4056.6	
+ 27-61-00-720-803-01	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU SOFTWARE" RELAY)								
27.570	REF: AMM 27-61-00-720-803	MOS HRS/MSC AFL	1240				19-MAY-2017 3080 1850	4320	
+ 27-61-00-720-803-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT ("BSCU SOFTWARE" RELAY) (MANDATORY REF 05-40/20)								
27.570 CMR	REF: AMM 27-61-00-720-803	MOS HRS/MSC AFL	1240				19-MAY-2017 3080 1850	4320	
+ 27-61-00-720-806-01	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT (MONITORING SYSTEM)								
27.575	REF: AMM 27-61-00-720-806	MOS HRS/MSC AFL	600	+40			14-JUN-2018 3406.6 1988	4006.6	4046.6
+ 27-61-00-720-806-01A	FUNCTIONAL TEST OF THE AUTOMATIC AIRBRAKE EXTENSION CIRCUIT (MONITORING SYSTEM) (MANDATORY REF 05-40/20)								
27.575 CMR	REF: AMM 27-61-00-720-806	MOS HRS/MSC AFL	650				14-JUN-2018 3406.6 1988	4056.6	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-01-900-801-01	LEFT OUTBOARD AIRBRAKE MICROSWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-61-01-900-801-02	LEFT CENTER AIRBRAKE MICROSWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-61-01-900-801-03	LEFT INBOARD AIRBRAKE MICROSWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-61-01-900-801-04	RIGHT INBOARD AIRBRAKE MICROSWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-61-01-900-801-05	RIGHT CENTER AIRBRAKE MICROSWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-61-01-900-801-06	RIGHT OUTBOARD AIRBRAKE MICROSWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-62-01-900-801-01	LEFT OUTBOARD AIRBRAKE ACTUATOR 106091-07 7822 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-62-01-900-801-02	LEFT MIDDLE AIRBRAKE ACTUATOR								
27.420	106091-08 7798 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-62-01-900-801-03	LEFT INBOARD AIRBRAKE ACTUATOR								
27.425	106091-09 7809 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-62-01-900-801-04	RIGHT INBOARD AIRBRAKE ACTUATOR								
27.425	106091-09 7810 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-62-01-900-801-05	RIGHT MIDDLE AIRBRAKE ACTUATOR								
27.420	106091-08 7799 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-62-01-900-801-06	RIGHT OUTBOARD AIRBRAKE ACTUATOR								
27.415	106091-07 7824 REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 27-80-00-710-804-02	OPERATIONAL TEST OF THE SLATS IN NORMAL AND EMERGENCY MODES - EMERGENCY MODE								
		MOS HRS/MSC AFL	10000	+40			19-OCT-2007 0 0	10000	10040
	REF:								
+ 27-80-00-710-807-01	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH SOLENOID - OUTBOARD SLAT MANIFOLD								
		MOS HRS/MSC AFL	1000	+40			14-JUN-2018 3406.6 1988	4406.6	4446.6
	REF: AMM 27-80-00-710-807								

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-80-00-710-809-01 (s)	OPERATIONAL TEST OF SLAT STALL 1 AND STALL 2 FUNCTIONS PKG 21	MOS					PKG 15-JUN-2017 3125.5 1867		
	REF: AMM 27-80-00-710-809	HRS/MSC AFL	1600	+40					
+ 27-80-00-710-809-01A	OPERATIONAL TEST OF SLAT STALL 1 AND STALL 2 FUNCTIONS (MANDATORY 5-40)	MOS					15-JUN-2017 3125.5 1867	4965.5	
CMR	REF: AMM 27-80-00-710-809	HRS/MSC AFL	1840						
27-80-00-720-801-01 (s)	FUNCTIONAL TEST OF THE SLATS - NORMAL MODE PKG 21	MOS					PKG 14-JUN-2019 3636.3 2081		
27.465	REF: AMM 27-80-00-720-801	HRS/MSC AFL	1600	+40					
27-80-00-720-801-01A	FUNCTIONAL TEST OF THE SLATS - NORMAL MODE (MANDATORY 5-40)	MOS					14-JUN-2019 3636.3 2081	5476.3	
27.465	REF: AMM 27-80-00-720-801	HRS/MSC AFL	1840						
CMR									
27-80-00-720-801-02 (s)	FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE PKG 21	MOS					PKG 15-JUN-2017 3125.5 1867		
27.465	REF: AMM 27-80-00-720-801	HRS/MSC AFL	1600	+40					
27-80-00-720-801-02A	FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE (MANDATORY 5-40)	MOS					15-JUN-2017 3125.5 1867	4965.5	
27.465	REF: AMM 27-80-00-720-801	HRS/MSC AFL	1840						
CMR									
27-80-00-720-801-03 (s)	FUNCTIONAL TEST OF THE SLATS -EMERGENCY MODE PKG 21	MOS					PKG 15-JUN-2017 3125.5 1867		
27.465	REF: AMM 27-80-00-720-801	HRS/MSC AFL	1600	+40					

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-00-720-801-03A	FUNCTIONAL TEST OF THE SLATS - EMERGENCY MODE (MANDATORY 5-40)								
27.465		MOS					15-JUN-2017		
CMR	REF: AMM 27-80-00-720-801	HRS/MSC AFL	1840				3125.5 1867		4965.5
27-80-05-900-801-01	LEFT INBOARD SLAT ACTUATOR								
27.520	106132-05	MOS		TSN:0			19-OCT-2007		
	5402	HRS/MSC AFL	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801			TSN:0			0		
27-80-05-900-801-02	RIGHT INBOARD SLAT ACTUATOR								
27.520	106132-05	MOS		TSN:0			19-OCT-2007		
	5404	HRS/MSC AFL	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801			TSN:0			0		
27-80-05-900-801-03	LEFT OUTBOARD SLAT OUTBOARD ACTUATOR								
27.525	106132-08	MOS		TSN:0			19-OCT-2007		
	5486	HRS/MSC AFL	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801			TSN:0			0		
27-80-05-900-801-04	RIGHT OUTBOARD SLAT OUTBOARD ACTUATOR								
27.525	106132-08	MOS		TSN:0			19-OCT-2007		
	5487	HRS/MSC AFL	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801			TSN:0			0		
27-80-05-900-801-05	LEFT OUTBOARD SLAT INBOARD ACTUATOR								
27.530	106132-06	MOS		TSN:0			19-OCT-2007		
	5501	HRS/MSC AFL	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801			TSN:0			0		
27-80-05-900-801-06	RIGHT OUTBOARD SLAT INBOARD ACTUATOR								
27.530	106132-06	MOS		TSN:0			19-OCT-2007		
	5502	HRS/MSC AFL	O/C	TSN:0			0		
	REF: AMM 27-80-05-900-801			TSN:0			0		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-05-900-801-07	LEFT OUTBOARD SLAT EMERGENCY ACTUATOR								
27.535	106132-07 5445 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
27-80-05-900-801-08	RIGHT OUTBOARD SLAT EMERGENCY ACTUATOR								
27.535	106132-07 5446 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 27-80-17-720-802-01 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH						PKG		
27.470	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			15-JUN-2017 3125.5 1867		
+ 27-80-17-720-802-02 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH						PKG		
27.470	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			15-JUN-2017 3125.5 1867		
+ 27-80-17-720-802-03 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH						PKG		
27.475	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			15-JUN-2017 3125.5 1867		
+ 27-80-17-720-802-04 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH						PKG		
27.475	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			15-JUN-2017 3125.5 1867		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-80-17-720-802-05 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH						PKG		
27.480	PKG 22	MOS					15-JUN-2017		
	REF: AMM 27-80-17-720-802	HRS/MSC AFL	3200	+40			3125.5 1867		
+ 27-80-17-720-802-06 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH						PKG		
	PKG 22	MOS					15-JUN-2017		
	REF: AMM 27-80-17-720-802	HRS/MSC AFL	3200	+40			3125.5 1867		
+ 27-80-17-720-802-07 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH						PKG		
	PKG 22	MOS					15-JUN-2017		
	REF: AMM 27-80-17-720-802	HRS/MSC AFL	3200	+40			3125.5 1867		
+ 27-80-17-720-802-08 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH						PKG		
	PKG 22	MOS					15-JUN-2017		
	REF: AMM 27-80-17-720-802	HRS/MSC AFL	3200	+40			3125.5 1867		
+ 27-80-17-720-802-09 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - FLAP MICROSWITCH						PKG		
	PKG 22	MOS					15-JUN-2017		
	REF: AMM 27-80-17-720-802	HRS/MSC AFL	3200	+40			3125.5 1867		
27-80-23-720-801-01	FUNCTIONAL TEST INBOARD SLAT VALVE BOX								
27.495	108117-06	MOS	144	+3%			19-OCT-2007	19-OCT-2019	28-FEB-2020
	667	HRS/MSC					0		
	REF: AMM 27-80-23-720-801	AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270801	TRIM/AIRBRAKE CONTROL								
27.060	013015-18 2157 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
270806	TRIPLE TRIM INDICATOR								
27.065	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
270816	SLATS/FLAPS CONTROL								
27.075	6-7061 1036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
270821	PILOT RUDDER BAR PEDAL								
27.080	FE230-002 FR0086 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
270826	COPILOT RUDDER BAR PEDAL								
27.080	FE213-003 FR0646 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
270831	PILOT PEDALS ADJUSTMENT ROD BOX								
27.085	4505-1 1861 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
270836	COPILOT PEDALS ADJUSTMENT ROD BOX								
27.085	4505-1 1862 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270841	PILOT COLUMN WHEEL								
27.055	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
270842	COPILOT COLUMN WHEEL								
27.055	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
271191	LEFT AILERON AUXILIARY ARTIFICIAL FEEL UNIT								
27.140	105045-12 5591 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
271192	RIGHT AILERON AUXILIARY ARTIFICIAL FEEL UNIT								
27.140	105045-12 5592 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
273806	PITCH MAIN ARTIFICIAL FEEL UNIT								
27.230	105122-02 757 REF: AMM 27-35-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
273821	Q-UNIT ELEVATOR SERVO VALVE								
27.245	108019-13 2106 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
273826	ELEVATOR Q-UNIT BOX								
27.250	062198-02 146 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:9 TSN:.17 TSN:0			28-JUL-2008 500.83 261		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275801	FLAP MOTOR-GEAR ASSEMBLY								
27.380	4440-6 803 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
275836	LEFT DOUBLE ANGLE GEARBOX								
27.385	1-5593 789 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
275841	RIGHT DOUBLE ANGLE GEARBOX								
27.385	2-5593 779 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
275846	LEFT INTERMEDIATE TRANSFER FLAP GEARBOX								
27.390	5592 1426 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
275851	RIGHT INTERMEDIATE TRANSFER FLAP GEARBOX								
27.390	5592 1427 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
275856	LEFT FLAP POSITION TRANSMITTER								
27.395	1-4414-2 1440 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
275861	RIGHT FLAP POSITION TRANSMITTER								
27.395	2-4414-2 1176 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276801	INBOARD/OUTBOARD AIRBRAKE SELECTOR VALVE								
27.430	65670-1 3759AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276806	MIDDLE AIRBRAKE SELECTOR VALVE								
27.430	65670-1 3760AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276811	AIRBRAKE HOLD VALVE								
27.435	D25AB1704 652 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276816	AIRBRAKE ACCUMULATOR PRESSURE GAUGE								
27.440	18040100 037302 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276821	LEFT OUTBOARD AIRBRAKE RESTRICTOR								
27.445	C24370-202 H3160 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276826	RIGHT OUTBOARD AIRBRAKE RESTRICTOR								
27.445	C24370-202 H3161 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276831	LEFT INBOARD AIRBRAKE RESTRICTOR								
27.450	C24370-302 H3227 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276836	RIGHT INBOARD AIRBRAKE RESTRICTOR								
27.450	C24370-302 H3228 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276841	LEFT MIDDLE AIRBRAKE RESTRICTOR								
27.455	C24370-402 H3322 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
276846	RIGHT MIDDLE AIRBRAKE RESTRICTOR								
27.455	C24370-402 H3323 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278061	SLATS MANIFOLD								
27.490	108143-01 426 REF:	MOS HRS/MSC AFL	O/C	TSN:196 TSR:4 TSR:0 TSR:0			01-FEB-2019 3549.1 2057		
278811	INBOARD SLAT VALVE BOX								
27.495	108117-06 667 REF: AMM 27-80-23-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278816	OUTBOARD SLAT STANDBY ELECTRIC DISTRIBUTOR								
27.510	65670-1 3761AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278821	INBOARD SLAT STANDBY ELECTRIC DISTRIBUTOR								
27.515	65670-1 3802 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278866	LEFT ACTUATOR STANDBY RESTRICTOR VALVE								
27.540	FCFA1875150D MA1562 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278871	RIGHT ACTUATOR STANDBY RESTRICTOR VALVE								
27.540	FCFA1875150D MA1561 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278876	OUTBOARD SLAT RESTRICTOR CHECK VALVE								
27.545	C24815000 FM1054 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278881	LEFT INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR								
27.550	C24346-102 H0753 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278886	RIGHT INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR								
27.550	C24346-102 H0754 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278891	LEFT OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE								
27.555	C24370-102 H3023 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
278896	RIGHT OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE								
27.555	C24370-102 H3024 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-41-13-640-801-01	GREASING/LUBRICATION OF THE SLAT MECHANISMS								
27.460	PKG 16 REF: AMM 27-80-00-640-801	MOS HRS/MSC AFL	24	+1m		-26	14-JUN-2019 3636.3 2081	19-MAY-2021	19-JUN-2021
CHAPTER 28 FUEL									
28-00-00-280-801-01 (s)	TEST FUEL CONTAMINATION DETECTION						PKG		
28.010	PKG 15 REF: AMM 28-00-00-280-801	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
28-00-00-910-803-01	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD							19-OCT-2007	
	REF:	MOS HRS/MSC AFL	O/C				0 0		
28-00-00-910-803-02	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - GRAVITY POURING METHOD							19-OCT-2007	
	REF:	MOS HRS/MSC AFL	O/C				0 0		
28-00-00-910-803-03	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - FUEL INJECTION METHOD							14-JUN-2019	
	REF:	MOS HRS/MSC AFL	O/C				3636.3 2081		
28-00-00-910-803-04	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - GRAVITY POURING METHOD							19-OCT-2007	
	REF:	MOS HRS/MSC AFL	O/C				0 0		
28-00-00-910-803-06	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING / REPLACEMENT OF FILTERS							19-OCT-2007	
	REF:	MOS HRS/MSC AFL	O/C				0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-910-804-01	MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS								
28.510	REF: AMM 28-00-00-910-804	MOS HRS/MSC AFL	A/R				19-OCT-2007 0 0		
+ 28-10-00-280-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE FUEL TANK FLAPPER VALVES						PKG		
28.020	PKG 31 REF: AMM 28-10-00-280-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
28-21-01-900-801-01 (s)	NO. 1 ENGINE LOW PRESSURE PUMP								
28.320	PN SN-UNKNOWN REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
28-21-01-900-801-02 (s)	NO. 2 ENGINE LOW PRESSURE (NORMAL) PUMP								
28.330	PN SN-UNKNOWN REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
28-21-01-900-801-03 (s)	NO. 2 ENGINE LOW PRESSURE (STAND-BY) PUMP								
28.330	PN SN-UNKNOWN REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
28-21-01-900-801-04 (s)	NO. 3 ENGINE LOW PRESSURE PUMP								
28.320	PN SN-UNKNOWN REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
28-21-05-900-801-01	BP1 MANIFOLD								
28.340	L88A31-662-1 C73399 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-05-900-801-02	BP2 MANIFOLD L88A31-692 20346 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C	TSO:0			04-JUN-2010 1265.33 706		
28.340									
28-21-05-900-801-03	BP3 MANIFOLD L88A31-664-1 20141 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
28.340									
+ 28-21-13-710-801-01 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
76.130									
+ 28-21-13-710-801-01A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV (MANDATORY 5-40) REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	11600				19-NOV-2013 2320.42 1495	13920.42	
76.130									
CMR									
+ 28-21-13-710-801-02 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
76.140									
+ 28-21-13-710-801-02A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV (MANDATORY 5-40) REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	11600				19-NOV-2013 2320.42 1495	13920.42	
76.140									
CMR									
+ 28-21-13-710-801-03 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72	+2m			PKG 17-SEP-2018 3480.2 2027		
76.150									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-21-13-710-801-03A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV (MANDATORY 5-40)								
76.150		MOS					17-SEP-2018		
CMR	REF: AMM 28-21-13-710-801	HRS/MSC	11600				3480.2		15080.2
		AFL					2027		
+ 28-21-13-710-802-01 (s)	OPERATIONAL TEST OF SHUT-OFF VALVES CLOSING - BP 1 MANIFOLD ENGINE SOV (L321WB)						PKG		
76.130	PKG 31	MOS	72	+2m			15-APR-2015		
	REF: AMM 28-21-13-790-801	HRS/MSC					2591.7		
		AFL	3750				1611		
+ 28-21-13-710-802-02 (s)	OPERATIONAL TEST OF SHUT-OFF VALVES CLOSING - BP 2 MANIFOLD ENGINE SOV (M321WB)						PKG		
76.140	PKG 31	MOS	72	+2m			15-APR-2015		
	REF: AMM 28-21-13-790-801	HRS/MSC					2591.7		
		AFL	3750				1611		
+ 28-21-13-710-802-03 (s)	OPERATIONAL TEST OF SHUT-OFF VALVES CLOSING - BP 3 MANIFOLD ENGINE SOV (R321WB)						PKG		
76.150	PKG 31	MOS	72	+2m			15-APR-2015		
	REF: AMM 28-21-13-790-801	HRS/MSC					2591.7		
		AFL	3750				1611		
+ 28-21-14-720-801-01	FUNCTIONAL TEST BP1 MANIFOLD THERMAL EXPANSION								
28.340	L88A31-662-1	MOS					19-OCT-2007		
	C73399	HRS/MSC	10000	+3%			0		10000 10300
	REF: AMM 28-21-14-720-801	AFL					0		
+ 28-21-14-720-801-02	FUNCTIONAL TEST BP2 MANIFOLD THERMAL EXPANSION								
28.340	L88A31-692	MOS					04-JUN-2010		
	20346	HRS/MSC	10000	+3%			1265.33		11265.33 11565.33
	REF: AMM 28-21-14-720-801	AFL					706		
+ 28-21-14-720-801-03	FUNCTIONAL TEST BP3 MANIFOLD THERMAL EXPANSION								
28.340	L88A31-664-1	MOS					19-OCT-2007		
	20141	HRS/MSC	10000	+3%			0		10000 10300
	REF: AMM 28-21-14-720-801	AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-17-790-801-01	SEALING TEST OF THE APU FUEL SHUT-OFF VALVE								
49.010		MOS					19-OCT-2007		
	REF: AMM 28-21-17-790-801	HRS/MSC	A/R				0		
		AFL					0		
+ 28-21-25-710-801-01 (s)	OPERATIONAL TEST OF THE CROSSFEED UNITS						PKG		
28.315	PKG 7	MOS	36	+1m			14-JUN-2019		
	REF: AMM 28-21-25-710-801	HRS/MSC	2400	+40			3636.3		
		AFL					2081		
28-21-25-900-801-01	NO. 1 ENGINE BOOSTER CROSSFEED UNIT								
28.160	L88A31-665-2	MOS				TSN:0	19-OCT-2007		
	C70729	HRS/MSC	O/C			TSN:0	0		
	REF: AMM 28-21-25-900-801	AFL				TSN:0	0		
28-21-25-900-801-02	NO. 3 ENGINE BOOSTER CROSSFEED UNIT								
28.160	L88A31-666-2	MOS				TSN:0	19-OCT-2007		
	C73511	HRS/MSC	O/C			TSN:0	0		
	REF: AMM 28-21-25-900-801	AFL				TSN:0	0		
28-21-27-900-801-01 (s)	LP 3-1 BOOSTER CROSSFEED VALVE ACTUATOR								
28.490	PN	MOS				TSN:0	19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0		
	REF: AMM 28-21-27-900-801	AFL				TSN:0	0		
28-21-27-900-801-02 (s)	LP 1-3 BOOSTER CROSSFEED VALVE ACTUATOR								
28.500	PN	MOS				TSN:0	19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0		
	REF: AMM 28-21-27-900-801	AFL				TSN:0	0		
+ 28-21-29-100-801-01 (s)	CLEANING OF THE LH CROSSFEED UNIT FILTER						PKG		
28.310	PKG 5,201	MOS	12	+1m			14-JUN-2019		
	REF: AMM 28-21-29-100-801	HRS/MSC	800	+40			3636.3		
		AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-29-100-801-02 (s)	CLEANING OF OF THE RH CROSSFEED UNIT FILTER						PKG		
28.310	PKG 5,201	MOS	12	+1m			14-JUN-2019		
	HRS/MSC		800	+40			3636.3		
	REF: AMM 28-21-29-100-801	AFL					2081		
28-21-29-100-801-03 (s)	CLEANING OF OF THE BOOSTER PUMP 2 UNIT FILTER						PKG		
28.310	PKG 5,201	MOS	12	+1m			14-JUN-2019		
	HRS/MSC		800	+40			3636.3		
	REF: AMM 28-21-29-100-801	AFL					2081		
28-30-00-680-802-01	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE LH TANK GROUP								
		MOS					06-SEP-2019		
		HRS/MSC	O/C				3683.9		
	REF: AMM 28-30-00-680-802	AFL					2130		
28-30-00-680-802-02	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE RH TANK GROUP								
		MOS					19-OCT-2007		
		HRS/MSC	O/C				0		
	REF: AMM 28-30-00-680-802	AFL					0		
28-30-00-680-802-03	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE CENTER TANK GROUP								
		MOS					19-OCT-2007		
		HRS/MSC	O/C				0		
	REF: AMM 28-30-00-680-802	AFL					0		
28-30-00-680-802-04	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - FUEL SAMPLING								
		MOS					19-OCT-2007		
		HRS/MSC	O/C				0		
	REF: AMM 28-30-00-680-802	AFL					0		
28-30-00-680-802-06	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY								
		MOS	2	+5d			14-JUN-2019	14-AUG-2019	19-AUG-2019
		HRS/MSC					3636.3		
	REF: AMM 28-30-00-680-802	AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-30-00-680-803-01	DRAINING OF THE GRAVITY DEFUELING LINE	DAYS					04-JUN-2010		
28.480	REF: AMM 28-30-00-680-803	HRS/MSC AFL	O/C				1265.33 706		
+ 28-30-00-680-804-01	DRAINING WATER FROM THE FUEL TANKS	MOS	2	+5d			14-JUN-2019	14-AUG-2019	19-AUG-2019
	REF: AMM 28-30-00-680-802	HRS/MSC AFL					3636.3 2081		
28-30-11-960-802-01	DISCARD OF THE FUEL DRAIN CAPS	MOS					19-OCT-2007		
	REF:	HRS/MSC AFL	O/C				0 0		
+ 28-41-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL QUANTITY INDICATING SYSTEM						PKG		
28.420	PKG 22	MOS					15-JUN-2017		
	REF: AMM 28-41-00-720-801	HRS/MSC AFL	3200	+40			3125.5 1867		
28-41-01-900-801-01	FUEL QUANTITY MANAGEMENT COMPUTER								
28.405	738325-1-8	MOS					09-OCT-2012		
	00450	HRS/MSC	O/C				2097.25		
	REF: AMM 28-41-01-900-801	AFL					1305		
+ 28-43-01-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR						PKG		
28.470	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 28-43-01-720-801	HRS/MSC AFL	3750				2320.42 1495		
28-70-01-780-801-01 (s)	CHECK FOR CORRECT CALIBRATION OF THE PRESSURE GAUGE						PKG		
28.215	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 28-70-01-780-801	HRS/MSC AFL	3750				2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-70-05-790-801-01	SEALING TEST PRESSURE REDUCING VALVE OF THE NON-RETURN VALVE OF THE PRESSURE REDUCER VALVE								
28.270	B14DE2080 936 REF: AMM 28-70-05-790-801	MOS HRS/MSC AFL	7500	+3%			19-OCT-2007 0 0	7500	7725
28-70-05-900-801-01	PRESSURE REDUCING VALVE								
28.270	B14DE2080 936 REF: AMM 28-70-05-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
28-70-09-350-801-01	RESTORATION LEFT PRESSURIZATION VALVE BOX (FILTER CLEANING AND CALIBRATION CHECK)								
28.220	B04BA1005 1959 REF: AMM 28-70-09-350-801	MOS HRS/MSC AFL	5000	+3%			19-OCT-2007 0 0	5000	5150
28-70-09-350-801-02	RESTORATION RIGHT PRESSURIZATION VALVE BOX (FILTER CLEANING AND CALIBRATION CHECK)								
28.220	B04BA1006 1865 REF: AMM 28-70-09-350-801	MOS HRS/MSC AFL	5000	+3%			19-NOV-2013 2320.42 1495	7320.42	7470.42
28-70-09-900-801-01	LEFT PRESSURIZATION VALVE BOX								
28.220	B04BA1005 1959 REF: AMM 28-70-09-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
28-70-09-900-801-02	RIGHT PRESSURIZATION VALVE BOX								
28.220	B04BA1006 1865 REF: AMM 28-70-09-900-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
28-70-13-350-801-01	RESTORATION LEFT WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST/LEAK TEST)								
	B06GA1051 2727 REF: AMM 28-70-13-350-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-13-350-801-02	RESTORATION RIGHT WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST/LEAK TEST)								
	B06GA1051	MOS					19-OCT-2007		
	2728	HRS/MSC	O/C				0		
	REF: AMM 28-70-13-350-801	AFL					0		
28-70-13-720-802-01	FUNCTIONAL TEST LEFT WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1051	MOS					19-OCT-2007		
	2727	HRS/MSC	5000	+3%			0	5000	5150
	REF: AMM 28-70-13-720-802	AFL					0		
28-70-13-720-802-02	FUNCTIONAL TEST RIGHT WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1051	MOS					19-OCT-2007		
	2728	HRS/MSC	5000	+3%			0	5000	5150
	REF: AMM 28-70-13-720-802	AFL					0		
28-70-13-900-801-01	LEFT WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1051	MOS				TSN:0	19-OCT-2007		
	2727	HRS/MSC	O/C			TSN:0	0		
	REF: AMM 28-70-13-900-801	AFL				TSN:0	0		
28-70-13-900-801-02	RIGHT WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1051	MOS				TSN:0	19-OCT-2007		
	2728	HRS/MSC	O/C			TSN:0	0		
	REF: AMM 28-70-13-900-801	AFL				TSN:0	0		
28-70-17-130-801-01 (s)	CLEANING OF OF FUEL TANK NO. 1 ENGINE PRESSURIZATION AIR FILTER						PKG		
28.200	PKG 21	MOS					15-JUN-2017		
		HRS/MSC	1600	+40			3125.5		
	REF: AMM 28-70-17-130-801	AFL					1867		
28-70-17-130-801-02 (s)	CLEANING OF FUEL TANK NO. 2 ENGINE PRESSURIZATION AIR FILTER						PKG		
28.200	PKG 21	MOS					15-JUN-2017		
		HRS/MSC	1600	+40			3125.5		
	REF: AMM 28-70-17-130-801	AFL					1867		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-21-900-801-01	LH VENT VALVE								
28.140	B97F38-653 C72386 REF: AMM 28-70-21-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28-70-21-900-801-02	RH VENT VALVE								
28.140	B97F38-653 C72387 REF: AMM 28-70-21-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28-70-21-900-801-03 (s)	MSC VENT VALVE								
28.140	PN SN-UNKNOWN REF: AMM 28-70-21-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281801	PRESSURIZATION PRESSURE FUEL GAUGE								
28.025	MPMC50701-01 1038 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281803	FRONT TANK FRONT DRAIN								
28.030	142D12-1 A77952 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281806	LEFT WING INBOARD TANK DRAIN								
28.040	142D12-1 C58570 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281808	RIGHT WING INBOARD TANK DRAIN								
28.040	142D12-1 J17289 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:19 TSN:0 TSN:0			06-JUN-2016 2921.4 1760		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281811	FRONT TANK REAR DRAIN								
28.045	142G12-32 C28359 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281813	LEFT FRONT TANK DRAIN								
28.050	142G12-32 C28364 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281816	RIGHT FRONT TANK DRAIN								
28.050	142G12-32 C36942 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281818	RIGHT CENTERWING TANK DRAIN								
28.055	142G12-32 C36943 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281821	REAR TANK DRAIN								
28.060	142G12-32 C36954 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281823	TANK COMPARTMENT SERVICING DRAIN								
28.065	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281826	NO. 1 ENGINE FEEDER TANK DRAIN								
28.070	142G12-32 C36955 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281828	NO. 2 ENGINE FEEDER TANK DRAIN								
28.070	142G12-32 C36956 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281831	NO. 3 ENGINE FEEDER TANK DRAIN								
28.070	142G12-32 C48003 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281833 (s)	NO. 3 ENGINE REAR FEEDER TANK DRAIN								
28.075	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281836	REFUELING PRESSURE CONNECTOR								
28.080	K97-63-206 C39081 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281838	LEFT TANK FUELING ELECTRIC VALVE								
28.085	L94Z31-201 C72790 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281841	RIGHT TANK FUELING ELECTRIC VALVE								
28.085	L94Z31-201 C72791 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281843	CENTER WING TANK FUELING ELECTRIC VALVE								
28.090	L94Z31-201 C72792 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281846	SERVICE COMPARTMENT TANK FUELING ELECTRIC VALVE								
28.095	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281848	LEFT WING TANKS NON-RETURN VALVE								
28.100	L96Z31-201 C65874 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281851	RIGHT WING TANKS NON-RETURN VALVE								
28.100	L96Z31-201 C65875 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281853	CENTER WING TANKS NON-RETURN VALVE								
28.105	L96Z31-201 C65876 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281856 (s)	NO. 2 ENGINE FEEDER TANK NON-RETURN VALVE								
28.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281858 (s)	LOW LEVEL DETECTION BOX								
28.115	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281861 (s)	1000 LBS LEVEL DETECTION BOX								
28.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281863 (s)	LOW LEVEL THERMISTOR RELAY BOX								
28.125	722700-3-0 00156 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
281866	PRESSURE FUELING PANEL								
28.130	798909-1-1 798909IN00386 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-JAN-2014 2352.25 1512		
281868	REFUELING MANIFOLD								
28.135	K99-31-007-1 C64957 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281878	WING TANK CROSSFEED VALVE								
28.145	L87B63-653 C42166 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281881	TANK TRANSFER ELECTRIC VALVE								
28.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281883	TANK TRANSFER MANUAL VALVE								
28.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
281891	SERVICING COMPARTMENT FEEDER TANK NON-RETURN VALVE								
28.165	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281893	SERVICING COMPARTMENT TANK FUEL GAUGE								
28.170	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282811	NO. 1 ENGINE PUMP BOOSTER								
28.250	P99C31-604 C64948 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282812	NO. 2 ENGINE PUMP (NORMAL) BOOSTER								
28.260	P99C31-604 175 REF:	MOS HRS/MSC AFL	O/C	TSR:3 TSN:5808 TSR:0 TSR:0			22-OCT-2015 2761.8 1696		
282813	NO. 3 ENGINE PUMP BOOSTER								
28.250	P99C31-604 C78816 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282814	NO. 2 ENGINE PUMP (STAND-BY) BOOSTER								
28.260	P99C31-604 C82989 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282816	NO. 2 ENGINE UNIT PUMP								
28.265	L88A31-206-1 C42156 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282826 (s)	NO. 1 ENGINE NON-RETURN VALVE								
28.280	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282831 (s)	NO. 2 ENGINE NON-RETURN VALVE								
28.285	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282846	NO. 1 ENGINE PRESSURIZATION AIR FILTER								
28.300	018500AA000NF0A M178690-012 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282851	NO. 2 ENGINE PRESSURIZATION AIR FILTER								
28.300	018500AA000NF0A M178690-013 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
282866 (s)	FUELING SELECTOR SWITCH								
28.305	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284801	NO. 1 ENGINE LOW PRESSURE PRESSURE SWITCH								
28.360	8G1256-1 3529 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284802	NO. 2 ENGINE LOW PRESSURE PRESSURE SWITCH								
28.360	8G1256-1 3530 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284803	NO. 3 ENGINE LOW PRESSURE PRESSURE SWITCH								
28.360	8G1256-1 3531 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284806	LEFT WING INBOARD GAUGE 764934-1-0 0805 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			06-OCT-2012 2093.58 1301		
284811	RIGHT WING INBOARD GAUGE 764934-1-0 1331 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-AUG-2013 2295.75 1469		
284816	LEFT WING MIDDLE GAUGE 764-933-1-0 0551 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284821	RIGHT WING MIDDLE GAUGE 764933-1-0 2031 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C				28-JUN-2019 3642.7 2087		
284826	LEFT WING OUTBOARD GAUGE 764-932-1-0 0251 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284831	RIGHT WING OUTBOARD GAUGE 764-932-1-0 0565 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284836	FRONT TANK REAR GAUGE 764939-3-0 0197 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284841 (s)	FRONT TANK FRONT GAUGE								
28.380	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284846	NO. 1 ENGINE FEEDER TANK GAUGE								
28.385	764936-1-0 0550 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284851	NO. 3 ENGINE FEEDER TANK GAUGE								
28.385	764936-1-0 0551 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-OCT-2007 0 0		
284856	LEFT WING CENTRAL GAUGE								
28.390	764935-3-0 1844 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			06-SEP-2019 3683.9 2130		
284861	RIGHT WING CENTRAL GAUGE								
28.390	764935-3-0 0568 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284866	NO. 2 ENGINE FEEDER TANK GAUGE								
28.385	764940-1-0 0199 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284871	REAR TANK GAUGE								
28.395	764941-3-0 0180 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284876 (s)	LEFT FUEL GAUGE AMPLIFIER								
28.400	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284881 (s)	RIGHT FUEL GAUGE AMPLIFIER								
28.400	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284891 (s)	LEFT TANK FRONT GAUGE								
28.410	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
284893 (s)	RIGHT TANK FRONT GAUGE								
28.410	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501A (s)	LEFT WING INBOARD QUANTITY GAUGE								
28.425	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501B (s)	RIGHT WING INBOARD QUANTITY GAUGE								
28.425	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501C (s)	LEFT WING MIDDLE QUANTITY GAUGE								
28.430	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28501D (s)	RIGHT WING MIDDLE QUANTITY GAUGE								
28.430	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501E (s)	LEFT WING OUTBOARD QUANTITY GAUGE								
28.435	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501F (s)	RIGHT WING OUTBOARD QUANTITY GAUGE								
28.435	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501G (s)	LEFT WING CENTER SECTION QUANTITY GAUGE								
28.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501H (s)	RIGHT WING CENTER SECTION QUANTITY GAUGE								
28.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501I (s)	NO. 1 ENGINE FEEDER TANK QUANTITY GAUGE								
28.445	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501J (s)	NO. 2 ENGINE FEEDER TANK QUANTITY GAUGE								
28.445	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28501K (s)	NO. 3 ENGINE FEEDER TANK QUANTITY GAUGE								
28.445	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501L (s)	LEFT TANK FRONT QUANTITY GAUGE								
28.450	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501M (s)	RIGHT TANK FRONT QUANTITY GAUGE								
28.455	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501N (s)	FRONT TANK REAR QUANTITY GAUGE								
28.455	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501P (s)	FRONT TANK FRONT QUANTITY GAUGE								
28.455	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501Q (s)	REAR TANK QUANTITY GAUGE								
28.460	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
28501R	SERVICING COMPARTMENT TANK QUANTITY GAUGE								
28.465	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
286A11	CONTROL REFUELING MICRO-SWITCH 52503 841 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-FEB-2009 740.75 407			
CHAPTER 29 HYDRAULIC POWER										
+ 29-10-00-720-801-01 (s)	FUNCTIONAL TEST NO.1 OF THE NO. 1 MAIN HYDRAULIC SYSTEM						PKG			
29.020	PKG 31 REF: AMM 29-10-00-720-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495			
+ 29-10-00-720-801-02 (s)	FUNCTIONAL TEST NO.2 OF THE NO. 2 MAIN HYDRAULIC SYSTEM						PKG			
29.020	PKG 31 REF: AMM 29-10-00-720-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495			
29-11-01-350-801-01	RESTORATION NO. 1 HYDRAULIC PUMP (OVERHAUL)									
29.030 OVERHAUL	4204501 AE41 REF: AMM 29-11-01-350-801	MOS HRS/MSC AFL	3240	+3%			22-MAR-2018 3341.1 1960	6581.1	6678.3	
29-11-01-350-801-02	RESTORATION NO. 2 HYDRAULIC PUMP (OVERHAUL)									
29.030 OVERHAUL	4204501 BD126 REF: AMM 29-11-01-350-801	MOS HRS/MSC AFL	3240	+3%			15-APR-2015 2591.7 1611	5831.7	5928.9	
29-11-01-350-801-03	RESTORATION NO. 3 HYDRAULIC PUMP (OVERHAUL)									
29.030 OVERHAUL	4204501 AE214 REF: AMM 29-11-01-350-801	MOS HRS/MSC AFL	3240	+3%			22-MAR-2018 3341.1 1960	6581.1	6678.3	
29-11-01-900-801-01	NO. 1 HYDRAULIC PUMP									
29.030	4204501 AE41 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T	TSO:2 TSO:0 TSO:0			22-MAR-2018 3341.1 1960			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-01-900-801-02	NO. 2 HYDRAULIC PUMP								
29.030	4204501 BD126 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T	TSR:0 TSR:0 TSR:0			15-APR-2015 2591.7 1611		
29-11-01-900-801-03	NO. 3 HYDRAULIC PUMP								
29.030	4204501 AE214 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T	TSO:2 TSO:0 TSO:0			22-MAR-2018 3341.1 1960		
29-11-25-900-801-01	NO. 1 SYSTEM STAND-BY PUMP PRESSURE SWITCH								
29.150	15H0090PH 1160 REF: AMM 29-20-07-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
29-11-25-900-801-02	NO. 2 SYSTEM STAND-BY PUMP PRESSURE SWITCH								
29.150	15H0090PH 1537 REF: AMM 29-20-07-900-801	MOS HRS/MSC AFL	O/C	TSN:12 TSN:0 TSN:0			01-FEB-2019 3549.1 2057		
29-11-25-900-801-03	NO. 1 PUMP PRESSURE SWITCH								
29.180	15H0088PH 2910 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2009 1054.5 582		
29-11-25-900-801-04	NO. 2 PUMP PRESSURE SWITCH								
29.180	15H0088PH 2912 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2009 1054.5 582		
29-11-25-900-801-05	NO. 3 PUMP PRESSURE SWITCH								
29.180	15H0088PH 3717 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-25-960-801-01	DISCARD NO. 1 PUMP PRESSURE SWITCH 15H0088PH 2910 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C				25-NOV-2009 1054.5 582		
29-11-25-960-801-02	DISCARD NO. 2 PUMP PRESSURE SWITCH 15H0088PH 2912 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C				25-NOV-2009 1054.5 582		
29-11-25-960-801-03	DISCARD NO. 3 PUMP PRESSURE SWITCH 15H0088PH 3717 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
29-13-09-960-801-01 (s)	REPLACEMENT OF THE STANDBY PUMP FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
29-13-09-960-801-02 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 1 RETURN FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
29-13-09-960-801-03 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 2 RETURN FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
29-13-09-960-801-04 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 3 RETURN FILTER PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-13-09-960-801-05 (s)	REPLACEMENT OF THE SYSTEM 1 GENERAL RETURN FILTER PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
	REF: AMM 29-13-09-960-801		3750						
29-13-09-960-801-06 (s)	REPLACEMENT OF THE SYSTEM 2 GENERAL RETURN FILTER PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
	REF: AMM 29-13-09-960-801		3750						
29-13-09-960-801-07 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 1 DELIVERY FILTER PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
	REF: AMM 29-13-09-960-801		3750						
29-13-09-960-801-08 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 2 DELIVERY FILTER PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
	REF: AMM 29-13-09-960-801		3750						
29-13-09-960-801-09 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 3 DELIVERY FILTER PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 19-NOV-2013 2320.42 1495		
	REF: AMM 29-13-09-960-801		3750						
29-14-01-680-801-01	DRAINING OF THE NO.1 HYDRAULIC SYSTEM RESERVOIR	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
29.040	REF: AMM 29-14-01-680-801								
29-14-01-680-801-02	DRAINING OF THE NO.2 HYDRAULIC SYSTEM RESERVOIR	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
29.040	REF: AMM 29-14-01-680-801								

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-14-01-900-801-01	NO. 1 SYSTEM HYDRAULIC RESERVOIR								
29.050	029029-08 856 REF: AMM 29-14-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
29-14-01-900-801-02	NO. 2 SYSTEM HYDRAULIC RESERVOIR								
29.050	029029-07 720 REF: AMM 29-14-01-900-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
29-14-11-900-801-01	NO. 1 SYSTEM HYDRAULIC ACCUMULATOR								
29.070	60967-1 EFS1355 REF: AMM 29-14-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
29-14-11-900-801-02	NO. 2 SYSTEM HYDRAULIC ACCUMULATOR								
29.070	60967-1 EFS1356 REF: AMM 29-14-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 29-20-00-720-801-02	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - SYSTEM 2								
	REF:	MOS HRS/MSC AFL	5000	+40			19-OCT-2007 0 0	5000	5040
29-20-01-900-801-01	STAND-BY ELECTRIC PUMP ASSEMBLY								
29.120	42032 BE580 REF: AMM 29-20-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 29-20-03-220-801-01	CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (3ML)								
29.120	42032 BE580 REF: AMM 29-20-03-220-801	MOS HRS/MSC AFL	5000	+3%			19-OCT-2007 0 0	5000	5150

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-20-03-720-801-01	FUNCTIONAL TEST STAND-BY ELECTRIC PUMP ASSEMBLY MOTOR								
29.120	42032 BE580 REF: AMM 29-20-03-720-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
29-20-05-900-801-01	ELECTRIC PUMP STAND-BY SELECTOR								
29.140	B94A13-205 C54020 REF: AMM 29-20-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
29-20-07-960-801-01	DISCARD NO. 1 SYSTEM STAND-BY PUMP PRESSURE SWITCH								
29.150	15H0090PH 1160 REF: AMM 29-20-07-960-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
29-20-07-960-801-02	DISCARD NO. 2 SYSTEM STAND-BY PUMP PRESSURE SWITCH								
29.150	15H0090PH 1537 REF: AMM 29-20-07-960-801	MOS HRS/MSC AFL	O/C				01-FEB-2019 3549.1 2057		
291811	NO. 1 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR								
29.060	034001 863 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
291816	NO. 2 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR								
29.060	034001 864 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
291831	NO. 1 SYSTEM PRESSURE HOLDING VALVE ACCUMULATOR GAUGE								
29.080	18040100 028088 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291836	NO. 1 SYSTEM PRESSURE ACCUMULATOR GAUGE								
	18040100	MOS		TSN:0			19-OCT-2007		
29.090	030540	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291841	NO. 2 SYSTEM PRESSURE ACCUMULATOR GAUGE								
	18040100	MOS		TSN:0			19-OCT-2007		
29.090	037272	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291846	NO. 1 SYSTEM HYDRAULIC MANIFOLD								
	AEB937-81	MOS		TSN:0			19-OCT-2007		
29.100	0263	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291851	NO. 2 SYSTEM HYDRAULIC MANIFOLD								
	AEB938-81	MOS		TSN:0			19-OCT-2007		
29.100	0586	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291856	NO. 1 SYSTEM PRESSURE HOLDING VALVE								
	70073	MOS		TSN:0			19-OCT-2007		
29.110	0736	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291861	NO. 2 SYSTEM PRESSURE HOLDING VALVE								
	70073	MOS		TSN:0			19-OCT-2007		
29.110	624	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
291A07	NO. 1 SYSTEM HYDRAULIC RETURN "RET" FILTER								
	AC9607F10	MOS					26-NOV-2010		
	NSN	HRS/MSC	O/C				1469.42		
	REF:	AFL					832		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291A08	NO. 2 SYSTEM HYDRAULIC RETURN "RET" FILTER AC3255F8Y60 NSN REF:	MOS HRS/MSC AFL	O/C				25-MAR-2013 2253.42 1424		
293801	NO. 1 SYSTEM PRESSURE TRANSMITTER 64279-530-2 5297 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
293806	NO. 2 SYSTEM PRESSURE TRANSMITTER 64279-530-2 5298 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
293811 (s)	NO. 1 SYSTEM QUANTITY-PRESSURE INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
293816 (s)	NO. 2 SYSTEM QUANTITY-PRESSURE INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 30 ICE AND RAIN PROTECTION									
+ 30-00-00-960-801-01 (s)	REPLACE OF THE ANTI-ICING SYSTEM WIGGINS COUPLING SEALS PKG 32 REF: AMM 30-00-00-960-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
30-11-00-720-801-01	FUNCTIONAL TEST LH INBOARD SLAT TELESCOPIC DUCT 5036-600 533 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480	+3%			19-NOV-2013 2320.42 1495	4800.42 3495	4874.82 3555

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-11-00-720-801-02	FUNCTIONAL TEST RH INBOARD SLAT TELESCOPIC DUCT								
30.010	5036-700 519 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480 +3% 2000 +3%				19-NOV-2013 2320.42 1495	4800.42 3495	4874.82 3555
30-11-00-720-801-03	FUNCTIONAL TEST LH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-600 912 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480 +3% 2000 +3%				19-NOV-2013 2320.42 1495	4800.42 3495	4874.82 3555
30-11-00-720-801-04	FUNCTIONAL TEST RH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-700 902 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480 +3% 2000 +3%				19-NOV-2013 2320.42 1495	4800.42 3495	4874.82 3555
30-11-00-900-801-01	LH INBOARD SLAT TELESCOPIC DUCT								
30.010	5036-600 533 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSN:73 TSN:2320.42 TSN:1495			19-NOV-2013 2320.42 1495		
30-11-00-900-801-02	RH INBOARD SLAT TELESCOPIC DUCT								
30.010	5036-700 519 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSN:73 TSN:2320.42 TSN:1495			19-NOV-2013 2320.42 1495		
30-11-00-900-801-03	LH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-600 912 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSN:73 TSN:2320.42 TSN:1495			19-NOV-2013 2320.42 1495		
30-11-00-900-801-04	RH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-700 902 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	TSN:73 TSN:2320.42 TSN:1495			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-11-17-200-803-01 (s)	INSPECTION OF THE WING ANTI-ICING SYSTEM GENERAL CONNECTOR COUPLINGS						PKG		
30.210	PKG 31 REF: AMM 30-11-17-200-803	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 30-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE AIR INTAKE ANTI-ICING SYSTEM						PKG		
30.090	PKG 21 REF: AMM 30-20-00-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 30-20-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO.2 ENGINE AIR INTAKE ANTI-ICING SYSTEM						PKG		
30.090	PKG 21 REF: AMM 30-20-00-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 30-20-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 ENGINE AIR INTAKE ANTI-ICING SYTEM						PKG		
30.090	PKG 21 REF: AMM 30-20-00-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 30-20-01-700-801-01	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L3HA)								
30.100	6911C020200 00716 REF: AMM 30-20-01-700-801	MOS HRS/MSC AFL	5000	+3%			19-OCT-2007 0 0	5000	5150
+ 30-20-01-700-801-02	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M3HA)								
30.100	6911C020200 00718 REF: AMM 30-20-01-700-801	MOS HRS/MSC AFL	5000	+3%			19-OCT-2007 0 0	5000	5150



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-20-01-700-801-03	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R3HA)								
30.100	6911C020200 00723 REF: AMM 30-20-01-700-801	MOS HRS/MSC AFL	5000	+3%			19-OCT-2007 0 0	5000	5150
+ 30-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM								
30.150	PKG 21 REF: AMM 30-30-00-710-801	MOS HRS/MSC AFL	1600	+40			PKG 15-JUN-2017 3125.5 1867		
+ 30-41-00-710-801-01 (s)	OPERATIONAL TEST OF THE COCKPIT WINDSHIELD DE-ICING SYSTEMS								
30.160	PKG 23 REF: AMM 30-41-00-710-801	MOS HRS/MSC AFL	4800	+40			PKG 19-OCT-2007 0 0		
30-43-05-900-801-01	PILOT WINDSHIELD WIPER MOTOR								
30.170	4267568 26254 REF: AMM 30-43-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 30-43-09-220-801-01	CHECK PILOT WINDSHIELD WIPER MOTOR BRUSHES								
30.170	4267568 26254 REF: AMM 30-43-09-220-801	MOS HRS/MSC AFL	15000	+3%			19-OCT-2007 0 0	15000	15450
+ 30-43-09-220-801-02	CHECK COPILOT WINDSHIELD WIPER MOTOR BRUSHES								
30.170	4267575 26251 REF: AMM 30-43-09-220-801	MOS HRS/MSC AFL	15000	+3%			19-OCT-2007 0 0	15000	15450
+ 30-90-00-710-801-01 (s)	OPERATIONAL TEST OF THE BRAKE HEATING SYSTEM								
30.030	REF: AMM 30-90-00-710-801	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301801	WING ANTI-ICING VALVE								
30.040	BYLB52642 338 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
301806	LEFT WING ANTI-ICING PRESSURE SWITCH								
30.050	8G1199-5 2779 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
301811	RIGHT WING ANTI-ICING PRESSURE SWITCH								
30.050	8G1199-5 2780 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
301816	COCKPIT TEMPERATURE CONDITIONING PROBE								
30.060	RP493-00 DAAB01018 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-JUN-2010 1265.33 706		
301821	S-DUCT ANTI-ICING TEMPERATURE PROBE								
30.070	RP493-00 DAAB01016 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-JUN-2010 1265.33 706		
301826	WING ANTI-ICING TEMPERATURE PROBE								
30.080	RP493-00 DAAB01017 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-JUN-2010 1265.33 706		
302031	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE								
30.100	6911C020200 00716 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302032	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE								
30.100	6911C020200 00718 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302033	NO. 3 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE								
30.100	6911C020200 00723 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302801	ENGINE S-DUCT ANTI-ICING VALVE								
30.110	BYLB52643 334 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302806	NO. 1 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH								
30.120	8G1199-5 2717 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302811	NO. 2 ENGINE DUCT ANTI-ICING PRESSURE SWITCH								
30.130	8G1199-5 2720 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302816	NO. 2 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH								
30.120	8G1199-5 2732 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302821	NO. 3 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH								
30.120	8G1199-5 2733 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302826	NO. 1 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH								
30.140	8G1340-5 667 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302831	NO. 2 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH								
30.140	8G1340-5 668 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
302836	NO. 3 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH								
30.140	8G1340-5 674 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
304012	COPILOT WINDSHIELD WIPER MOTOR								
30.170	4267575 26251 REF: AMM 30-43-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
304801	PILOT WINDSHIELD TEMPERATURE REGULATOR								
30.180	AV30559060030-1 1532 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
304806	COPILOT WINDSHIELD TEMPERATURE REGULATOR								
30.180	AV30559060030-1 1533 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
304811	LEFT SIDE WINDOW TEMPERATURE REGULATOR								
30.190	AV30564060030 1518 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304816	REAR WINDOW TEMPERATURE REGULATOR								
30.190	AV30564060030 1519 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-11-33-900-801-01 (s)	LEFT OVERHEAD PANEL CONTROL PCB								
31.220	PN SN-UNKNOWN REF: AMM 31-11-33-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-11-33-900-801-02 (s)	RIGHT OVERHEAD PANEL CONTROL PCB								
31.220	PN SN-UNKNOWN REF: AMM 31-11-33-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 31-31-00-710-802-01 (s)	OPERATIONAL TEST OF THE DIGITAL FLIGHT DATA RECORDER								
31.120	PKG 17 REF: AMM 31-31-00-710-802	MOS HRS/MSC AFL	36	+1m			PKG 14-JUN-2019 3636.3 2081		
31-31-00-720-801-01	FUNCTIONAL TEST OF THE DIGITAL FLIGHT DATA RECORDER (88-PARAMETER)								
31.120	REF: See Workcard	MOS HRS/MSC AFL	O/C				01-FEB-2013 2161.42 1362		
31-31-00-970-801-01	DOWNLOAD OF THE DIGITAL FLIGHT DATA RECORDER								
31.120	REF: AMM 31-31-00-970-801	MOS HRS/MSC AFL	A/R				19-NOV-2013 2320.42 1495		
+ 31-31-09-710-801-01	OPERATIONAL TEST COCKPIT VOICE RECORDER ACCELERATION CONTACT								
23.160	400-10B 5791 REF: AMM 31-31-09-710-801	MOS HRS/MSC AFL	240	+3%			03-MAY-2015 2609 1621	03-MAY-2035	09-DEC-2035

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-31-09-710-801-02	OPERATIONAL TEST DIGITAL FLIGHT DATA RECORDER ACCELERATION CONTACT								
31.090	400-10B 5788 REF: AMM 31-31-09-710-801	MOS HRS/MSC AFL	240	+3%			03-MAY-2015 2609 1621	03-MAY-2035	09-DEC-2035
31-31-09-900-801-01	COCKPIT VOICE RECORDER ACCELERATION CONTACT								
23.160	400-10B 5791 REF: AMM 31-31-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-APR-2009 816 444		
31-31-09-900-801-02	DIGITAL FLIGHT DATA RECORDER ACCELERATION CONTACT								
31.090	400-10B 5788 REF: AMM 31-31-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-APR-2009 816 444		
31-31-31-900-801-01	DIGITAL FLIGHT DATA RECORDER								
31.120	980-4710-003 00859 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-FEB-2007 0 0		
31-31-35-700-801-01 (s)	CHECK AUTOPILOT FORCE SENSORS								
22.010	PKG 17 REF: AMM 31-31-35-700-801	MOS HRS/MSC AFL	36	+1m			PKG 14-JUN-2019 3636.3 2081		
31-31-37-900-801-01	YAW CONTROL POSITION POTENTIOMETER								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-31-37-900-801-02	ROLL CONTROL POSITION POTENTIOMETER								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-37-900-801-03	PITCH CONTROL POSITION POTENTIOMETER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 31-31-50-710-801-01 (s)	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER PKG 17 23.150 REF: AMM 31-31-50-710-801	MOS HRS/MSC AFL	36	+1m			PKG 14-JUN-2019 3636.3 2081		
31-31-50-970-801-01	DOWNLOAD OF THE COCKPIT VOICE RECORDER REF: AMM 31-31-50-970-801	MOS HRS/MSC AFL	A/R				19-NOV-2013 2320.42 1495		
31-31-51-900-801-01	COCKPIT VOICE RECORDER 980-6044-002 010-02163 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		
31-31-53-710-801-01	OPERATIONAL TEST OF THE RECORDER INDEPENDENT (RIPS) POWER SUPPLY REF: AMM 31-31-53-710-801	MOS HRS/MSC AFL	N/A						
31-31-53-900-801-01	RECORDER INDEPENDENT (RIPS) POWER SUPPLY PN SN-UNKNOWN REF: AMM 31-31-53-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-31-53-900-802-01	RECORDER INDEPENDENT POWER SUPPLY BATTERY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-55-900-801-01	MICROPHONE VOICE RECORDER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-32-00-970-801-01	DOWNLOAD QUICK ACCESS (QAR) RECORDER PN NOT INSTALLED REF: AMM 31-32-00-970-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER PN NOT INSTALLED REF: AMM 31-32-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-32-05-960-801-01	REPLACE QUICK ACCESS (QAR) RECORDER BATTERY PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
31-41-05-900-801-01	NO. 1 MAU 1 POWER SUPPLY MODULE 7024440-1901 06106494 REF: AMM 31-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-01	MAU-1/SLOT 8 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-01	NO. 1 AIR FLOW BLOCKAGE MODULE 7027208-1903 1301J116 REF: AMM 31-41-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-17-900-801-02	MAU-1/SLOT 15 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-02	NO. 2 AIR FLOW BLOCKAGE MODULE 7027208-1903 1301J121 REF: AMM 31-41-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-41-17-900-801-03	MAU-2/SLOT 4 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-03	NO. 3 AIR FLOW BLOCKAGE MODULE 7027208-1903 1301J118 REF: AMM 31-41-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-41-17-900-801-04	MAU-2/SLOT 8 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-04	NO. 4 AIR FLOW BLOCKAGE MODULE 7027208-1903 1301J117 REF: AMM 31-41-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-41-17-900-801-05	MAU-2/SLOT 15 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-17-900-801-06	MAU-1/SLOT 3 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-07	MAU-1/SLOT 7 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-08	MAU-2/SLOT 3 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-41-17-900-801-09	MAU-2/SLOT 7 (AFBM) AIR FLOW BLOCKAGE MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-00-710-801-01	OPERATIONAL TEST OF THE DATA ACQUISITION SYSTEM - MODULAR AVIONICS UNIT (MAU) REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
31-42-01-900-801-01	REMOVAL / INSTALLATION OF THE NIC / PROCESSOR MODULES - NIC/PROC 1 MODULE (L5FQ) 7038231-1901 13095247 REF: AMM 31-42-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-42-01-900-801-02	REMOVAL / INSTALLATION OF THE NIC / PROCESSOR MODULES - NIC/PROC 2 MODULE (L6FQ) 7038231-1902 13095190 REF: AMM 31-42-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-01-900-801-03	REMOVAL / INSTALLATION OF THE NIC / PROCESSOR MODULES - NIC/PROC 3 MODULE (R5FQ)								
31.170	7038231-1901 13095059 REF: AMM 31-42-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-42-01-900-801-04	REMOVAL / INSTALLATION OF THE NIC / PROCESSOR MODULES - NIC/PROC 4 MODULE (R6FQ)								
31.170	7038231-1902 13095203 REF: AMM 31-42-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-42-05-900-801-01	REMOVAL / INSTALLATION OF THE CONTROL I/O 2 MODULE - CONTROL I/O MODULE 2 (R7FQ)								
31.195	7026531-1902 06091048 REF: AMM 31-42-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-09-900-801-01	REMOVAL / INSTALLATION OF THE CONTROL/VIDEO I/O 1 MODULE - CONTROL I/O VIDEO MODULE 1 (L7FQ)								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-11-710-801-01	TESTS AFTER INSTALLATION OF THE CUSTOM I/O 1 MODULE - CUSTOM I/O 1 MODULE (L12FQ)								
	7028425-1901 06110490 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
31-42-11-710-802-01	TESTS AFTER INSTALLATION OF THE CUSTOM I/O 2 MODULE - CUSTOM I/O 2 MODULE (R12FQ)								
	7028425-1901 06110491 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
31-42-11-900-801-01	REMOVAL / INSTALLATION OF THE CUSTOM I/O (CSIO) MODULES - CUSTOM I/O 1 MODULE (L12FQ)								
31.200	7028425-1901 06110490 REF: AMM 31-42-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-11-900-801-02	REMOVAL / INSTALLATION OF THE CUSTOM I/O (CSIO) MODULES - CUSTOM I/O 2 MODULE (R12FQ)								
31.200	7028425-1901 06110491 REF: AMM 31-42-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-13-710-801-01	TESTS AFTER INSTALLATION OF THE GENERIC I/O 1 MODULE - GENERIC I/O 1 MODULE (L13FQ)								
	7025365-1901 06102576 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
31-42-13-710-802-01	TESTS AFTER INSTALLATION OF THE GENERIC I/O 2 MODULE - GENERIC I/O 2 MODULE (R13FQ)								
	7025365-1901 06102606 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
31-42-13-900-801-01	REMOVAL / INSTALLATION OF THE GENERIC I/O (GIO) MODULES - GENERIC I/O 1 MODULE (L13FQ)								
31.190	7025365-1901 06102576 REF: AMM 31-42-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-13-900-801-02	REMOVAL / INSTALLATION OF THE GENERIC I/O (GIO) MODULES - GENERIC I/O 2 MODULE (R13FQ)								
31.190	7025365-1901 06102606 REF: AMM 31-42-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-17-900-801-01	REMOVAL / INSTALLATION OF THE ASCB BUS COUPLERS - BUS COUPLER (L73FV)								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-17-900-801-02	REMOVAL / INSTALLATION OF THE ASCB BUS COUPLERS - BUS COUPLER (R73FV)								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-21-900-801-01	REMOVAL / INSTALLATION OF THE DATABASE MODULES (DBM) - DATABASE MODULE 1 (L14FQ)								
34.265	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
31-42-21-900-801-02	REMOVAL / INSTALLATION OF THE DATABASE MODULES (DBM) - DATABASE MODULE 2 (R14FQ)								
34.265	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
31-42-25-900-801-01	REMOVAL / INSTALLATION OF THE NIC / PROC APM - APM 1 (L8FV)								
31.130	7519272-901 06105337 REF: AMM 31-42-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-25-900-801-02	REMOVAL / INSTALLATION OF THE NIC / PROC APM - APM 2 (R8FV)								
31.130	7519272-901 06105344 REF: AMM 31-42-25-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-42-25-910-801-01	AIRCRAFT PERSONALITY MODULE (APM) SETTINGS TOOL USER GUIDE								
	REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
31-43-01-900-801-01 (s)	NO. 1 MODULAR RADIO CABINET								
34.190	PN SN-UNKNOWN REF: AMM 31-43-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-43-01-900-801-02 (s)	NO. 2 MODULAR RADIO CABINET								
34.190	PN SN-UNKNOWN REF: AMM 31-43-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-43-05-900-801-01	NO. 1 NETWORK INTERFACE MODULE								
34.185	7517964-913 10127563 REF: AMM 31-43-05-900-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
31-43-05-900-801-02 (s)	NO. 2 NETWORK INTERFACE MODULE								
34.185	7517964-913 08104852 REF: AMM 31-43-05-900-801	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			01-FEB-2019 3549.1 2057		
31-60-00-710-801-20 (s)	OPERATIONAL TEST OF THE CENTRAL DISPLAY SYSTEM (CDS) - TEST OF THE CURSOR CONTROL DEVICE AND REVERSION COMMANDS						PKG		
31.020	PKG 21 REF: AMM 31-60-00-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
31-60-00-710-801-20A	OPERATIONAL TEST OF THE CENTRAL DISPLAY SYSTEM (CDS) - TEST OF THE CURSOR CONTROL DEVICE AND REVERSION COMMANDS (MANDATORY 5-40)								
31.040 CMR	REF: AMM 31-60-00-710-801	MOS HRS/MSC AFL	1640				15-JUN-2017 3125.5 1867	4765.5	
31-60-05-900-801-01	LEFT CHECKLIST CONTROLLER								
31.100	7030900-907 06090570 REF: AMM 31-60-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-60-05-900-801-02	RIGHT CHECKLIST CONTROLLER								
31.100	7030900-905 06100577 REF: AMM 31-60-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-60-06-900-801-01	PILOT CURSOR CONTROL								
31.210	7028640-901 06100591 REF: AMM 31-60-06-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-09-900-801-01	PILOT MULTIFUNCTION KEYBOARD								
31.185	7028560-921 06030439 REF: AMM 31-60-09-900-801	MOS HRS/MSC AFL	O/C				15-APR-2015 2591.7 1611		
31-60-13-900-801-01	LEFT PRIMARY FLIGHT DISPLAY								
31.175	7028140-901 06112088 REF: AMM 31-60-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
31-60-13-900-801-02	RIGHT PRIMARY FLIGHT DISPLAY								
31.175	7028140-905 07102727 REF: AMM 31-60-13-900-801	MOS HRS/MSC AFL	O/C				08-JUN-2012 1972.17 1216		
31-60-17-900-801-01	NO. 1 ADVANCED GRAPHIC MODULE								
31.140	7036410-1903 13099844 REF: AMM 31-60-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-60-17-900-801-02	NO. 3 ADVANCED GRAPHIC MODULE								
31.140	7036410-1903 1309A043 REF: AMM 31-60-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-60-17-900-801-03	NO. 4 ADVANCED GRAPHIC MODULE								
31.140	7036410-1903 1309A028 REF: AMM 31-60-17-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
31-60-17-900-801-04	NO. 2 ADVANCED GRAPHIC MODULE								
31.140	7036410-1903 10036123 REF: AMM 31-60-17-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-NOV-2013 2322.35 1496		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-21-900-801-01	REVERSION CONTROLLER								
31.215	7029270-903 07010352 REF: AMM 31-60-21-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
314012	NO. 1 MAU 2 POWER SUPPLY MODULE								
31.150	7024440-1901 06106516 REF: AMM 31-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
314013	NO. 3 MAU 1 POWER SUPPLY MODULE								
31.155	7024440-1901 06106517 REF: AMM 31-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
314014	NO. 3 MAU 2 POWER SUPPLY MODULE								
31.160	7024440-1901 06106522 REF: AMM 31-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
314042	NO. 2 CONTROL I/O MODULE								
31.195	7026534-1902 06102107 REF: AMM 31-42-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
314313 (s)	NO. 3 NETWORK INTERFACE MODULE								
34.185	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
315801 (s)	WARNING AUDIO UNIT								
31.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
315806 (s)	WARNING PANEL								
31.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
316013	UPPER MULTIFUNCTION DISPLAY								
31.180	7028140-901 06071861 REF: AMM 31-60-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
316014	LOWER MULTIFUNCTION DISPLAY								
31.180	7028140-901 06061806 REF: AMM 31-60-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
316022	COPILOT MULTIFUNCTION KEYBOARD								
31.185	7028560-921 07030692 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-APR-2015 2591.7 1611		
316042	COPILOT CURSOR CONTROL								
31.210	7028640-901 06100592 REF: AMM 31-60-06-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 32 LANDING GEAR									
+ 32-00-00-700-801-01	CHECK OF THE NOSE LANDING GEAR LEG UPLOCK								
32.170	REF: AMM 32-00-00-700-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
+ 32-00-00-700-801-02	CHECK OF THE LEFT MAIN LANDING GEAR LEG UPLOCK								
32.190	REF: AMM 32-00-00-700-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-00-00-700-801-03	CHECK OF THE RIGHT MAIN LANDING GEAR LEG UPLOCK								
32.190	REF: AMM 32-00-00-700-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
32-10-00-640-801-01	LUBRICATION OF THE LH MAIN LANDING GEARS (MLG) AND MLG DOORS								
32.010	REF: AMM 32-10-00-640-801	MOS HRS/MSC AFL	8 400	+1m	-120		14-JUN-2019 3636.3 2081	14-OCT-2019 2481	14-NOV-2019
+ 32-10-00-640-801-02	LUBRICATION OF THE RH MAIN LANDING GEARS (MLG) AND MLG DOORS								
32.010	REF: AMM 32-10-00-640-801	MOS HRS/MSC AFL	8 400	+1m	-120		14-JUN-2019 3636.3 2081	14-OCT-2019 2481	14-NOV-2019
+ 32-11-00-220-801-01	DETAILED INSPECTION LEFT MAIN LANDING GEAR LEG FOR DIMENSION AND ABSENCE OF CORROSION								
32.020	D22801500 B223 REF: AMM 32-11-00-220-801	MOS HRS/MSC AFL	72	+8m			19-NOV-2013 2320.42 1495	19-NOV-2019	19-JUL-2020
+ 32-11-00-220-801-02	DETAILED INSPECTION RIGHT MAIN LANDING GEAR LEG FOR DIMENSION AND ABSENCE OF CORROSION								
32.030	D22802500 B223 REF: AMM 32-11-00-220-801	MOS HRS/MSC AFL	72	+8m			19-NOV-2013 2320.42 1495	19-NOV-2019	19-JUL-2020
32-11-00-350-801-01	RESTORATION LEFT MAIN LANDING GEAR LEG (OVERHAUL)								
32.040 OVERHAUL	D22801500 B223 REF: AMM 32-11-00-350-801	MOS HRS/MSC AFL	144 6000	+3%			19-OCT-2007 0 0	19-OCT-2019 6000	28-FEB-2020
32-11-00-350-801-02	RESTORATION RIGHT MAIN LANDING GEAR LEG (OVERHAUL)								
32.040 OVERHAUL	D22802500 B223 REF: AMM 32-11-00-350-801	MOS HRS/MSC AFL	144 6000	+3%			19-OCT-2007 0 0	19-OCT-2019 6000	28-FEB-2020

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-900-801-01	LEFT MAIN LANDING GEAR LEG								
32.020	D22801500 B223 REF: AMM 32-11-00-900-801	MOS HRS/MSC AFL	H/T	TSN:85 TSN:2320.42 TSN:1495			19-NOV-2013 2320.42 1495		
32-11-00-900-801-02	RIGHT MAIN LANDING GEAR LEG								
32.030	D22802500 B223 REF: AMM 32-11-00-900-801	MOS HRS/MSC AFL	H/T	TSN:85 TSN:2320.42 TSN:1495			19-NOV-2013 2320.42 1495		
32-11-00-960-801-01	REPLACEMENT LEFT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS)								
32.715 LIFE LIMIT	D22801500 B223 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000	TSI:0 TSI:0			01-OCT-2006 0 0	20000	
32-11-00-960-801-01A	REPLACEMENT LEFT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS) (MANDATORY REF 5-40)								
MANDATORY 5-40	D22801500 B223 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000	TSI:1495			19-NOV-2013 2320.42 1495	20000	
32-11-00-960-801-02	REPLACEMENT RIGHT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS)								
32.715 LIFE LIMIT	D22802500 B223 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000	TSI:0 TSI:0			01-OCT-2006 0 0	20000	
32-11-00-960-801-02A	REPLACEMENT RIGHT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS) (MANDATORY REF 5-40)								
MANDATORY 5-40	D22802500 B223 REF: AMM 32-11-00-960-801	MOS HRS/MSC AFL	20000	TSI:1495			19-NOV-2013 2320.42 1495	20000	
32-11-05-780-801-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE LEFT MAIN LANDING GEAR (MLG) SHOCK ABSORBER						PKG		
32.055	PKG 21 REF: AMM 32-11-05-780-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-05-780-801-02 (s)	CHECK OF THE CHARGING PRESSURE OF THE RIGHT MAIN LANDING GEAR (MLG) SHOCK ABSORBER						PKG		
32.055	PKG 21 REF: AMM 32-11-05-780-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
32-11-05-900-801-01 (s)	LEFT MAIN LANDING GEAR SHOCK ABSORBER								
32.040	PN SN-UNKNOWN REF: AMM 32-11-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
32-11-05-900-801-02 (s)	RIGHT MAIN LANDING GEAR SHOCK ABSORBER								
32.040	PN SN-UNKNOWN REF: AMM 32-11-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
32-11-21-900-801-01	LEFT MAIN LANDING GEAR STRUT								
32.050	D22791400-5 B277 REF: AMM 32-11-21-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
32-11-21-900-801-02	RIGHT MAIN LANDING GEAR STRUT								
32.050	D22792400-5 B271 REF: AMM 32-11-21-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
+ 32-11-25-220-801-01	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)								
	REF: AMM 32-11-25-220-801	MOS HRS/MSC AFL	72	+2m			19-OCT-2007 0 0	19-OCT-2019 M	19-DEC-2019
+ 32-11-25-220-801-02	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)								
	REF: AMM 32-11-25-220-801	MOS HRS/MSC AFL	72	+2m			19-OCT-2007 0 0	19-OCT-2019 M	19-DEC-2019

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-25-220-801-03	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)	MOS HRS/MSC AFL	72	+2m			19-OCT-2007 0 0	19-OCT-2019 M	19-DEC-2019
	REF: AMM 32-11-25-220-801								
+ 32-11-25-220-801-04	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)	MOS HRS/MSC AFL	72	+2m			19-OCT-2007 0 0	19-OCT-2019 M	19-DEC-2019
	REF: AMM 32-11-25-220-801								
32-12-25-900-801-01	LEFT MAIN LANDING GEAR DOORS ACTUATOR CYLINDER	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
	VN1031-2 1575 REF: AMM 32-12-25-900-801								
32-12-25-900-801-02	RIGHT MAIN LANDING GEAR DOORS ACTUATOR CYLINDER	MOS HRS/MSC AFL	O/C				23-JAN-2015 2519.8 1586		
	VN1031-2 1885 REF: AMM 32-12-25-900-801								
32-20-00-640-801-01	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS	MOS HRS/MSC AFL	8	+1m		-120	14-JUN-2019 3636.3 2081	14-OCT-2019	14-NOV-2019
	32.070 REF: AMM 32-20-00-640-801		400					2481	
+ 32-21-00-220-801-01	DETAILED INSPECTION NOSE LANDING GEAR LEG FOR DIMENSION AND ABSENCE OF CORROSION	MOS HRS/MSC AFL	72	+8m			19-NOV-2013 2320.42 1495	19-NOV-2019	19-JUL-2020
	32.080 D22811500-2 B226 REF: AMM 32-21-00-220-801								
32-21-00-350-801-01	RESTORATION NOSE LANDING GEAR LEG (OVERHAUL)	MOS HRS/MSC AFL	144	+3%			19-OCT-2007 0 0	19-OCT-2019	28-FEB-2020
	32.090 OVERHAUL D22811500-2 B226 REF: AMM 32-21-00-350-801		6000					6000	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-00-900-801-01	NOSE LANDING GEAR LEG								
32.080	D22811500-2 B226 REF: AMM 32-21-00-900-801	MOS HRS/MSC AFL	H/T	TSN:73 TSN:2320.42 TSN:1495			19-NOV-2013 2320.42 1495		
32-21-00-960-801-01	REPLACEMENT NOSE LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS)								
32.720 LIFE LIMIT	D22811500-2 B226 REF: AMM 32-21-00-960-801	MOS HRS/MSC AFL	20000				19-OCT-2007 0 0	20000	
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS) (MANDATORY REF 5-40)								
MANDATORY 5-40	D22811500-2 B226 REF: AMM 32-21-00-960-801	MOS HRS/MSC AFL	20000	TSI:1495			19-NOV-2013 2320.42 1495	20000	
+ 32-21-01-780-801-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE NOSE LANDING GEAR (NLG) SHOCK ABSORBER						PKG		
32.095	PKG 21 REF: AMM 32-21-01-780-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 32-21-01-780-802-01	CHECK OF THE CHARGING PRESSURE OF THE NOSE LANDING GEAR (NLG) SHOCK ABSORBER BY APPLYING A ROTATIONAL TORQUE								
32.095	REF: AMM 32-21-01-780-802	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
32-21-01-900-801-01 (s)	NOSE LANDING GEAR SHOCK ABSORBER								
32.090	PN SN-UNKNOWN REF: AMM 32-21-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 32-21-09-220-801-01 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING								
	PKG 31 REF: AMM 32-21-09-220-801	MOS HRS/MSC AFL	72	+2m			19-OCT-2007 0 0	19-OCT-2019 M 19-DEC-2019	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-21-09-220-801-02 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING								
	PKG 31	MOS	72	+2m			19-OCT-2007	19-OCT-2019 M	19-DEC-2019
		HRS/MSC					0		
	REF: AMM 32-21-09-220-801	AFL	3750				0		
+ 32-21-09-220-801-03 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING								
	PKG 31	MOS	72	+2m			19-OCT-2007	19-OCT-2019 M	19-DEC-2019
		HRS/MSC					0		
	REF: AMM 32-21-09-220-801	AFL	3750				0		
+ 32-21-09-220-801-04 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING								
	PKG 31	MOS	72	+2m			19-OCT-2007	19-OCT-2019 M	19-DEC-2019
		HRS/MSC					0		
	REF: AMM 32-21-09-220-801	AFL	3750				0		
32-21-09-900-801-01	NOSE LANDING GEAR TELESCOPIC YOKE ASSEMBLY								
32.105	GA62269	MOS					12-DEC-2017		
	B4523	HRS/MSC	H/T				3247.6		
	REF: AMM 32-21-09-900-801	AFL					1920		
32-22-01-350-801-01	RESTORATION NOSE LANDING GEAR TELESCOPIC YOKE ASSEMBLY (OVERHAUL)								
32.105	GA62269	MOS	120	+3%			12-DEC-2017	12-MAY-2025	30-AUG-2025
	B4523	HRS/MSC					3247.6		
OVERHAUL	REF: AMM 32-22-01-350-801	AFL	6000	+3%			1920	7920	8100
32-22-01-900-801-01	NOSE LANDING GEAR TELESCOPIC TUBE								
32.100	D23334000-2	MOS					19-OCT-2007		
	B471	HRS/MSC	O/C				0		
	REF: AMM 32-22-01-900-801	AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-22-13-900-801-01	NOSE LANDING GEAR ACTUATOR								
32.110	D22795001 MM357 REF: AMM 32-22-13-900-801	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 32-30-00-720-801-01 (s)	FUNCTIONAL OF EXTENSION/RETRACTION TEST OF LANDING GEARS AND DOORS NORMAL OPERATION						PKG		
32.120	PKG 21 REF: AMM 32-30-00-720-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 32-30-00-720-801-02 (s)	FUNCTIONAL OF EXTENSION/RETRACTION TEST OF LANDING GEARS AND DOORS HYDRAULIC EMERGENCY OPERATION						PKG		
32.120	PKG 21 REF: AMM 32-30-00-720-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
+ 32-30-00-720-801-03 (s)	FUNCTIONAL OF EXTENSION/RETRACTION TEST OF LANDING GEARS AND DOORS MECHANICAL EMERGENCY OPERATION						PKG		
32.120	PKG 21 REF: AMM 32-30-00-720-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
32-30-13-900-801-01	NORMAL/EMERGENCY SELECTOR VALVE CHECK VALVE								
32.240	C24816000 1176 REF: AMM 32-30-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 32-31-00-700-801-01 (s)	CHECK OF THE LANDING GEARS RETRACTION INHIBITION ON THE GROUND						PKG		
32.150	PKG 21 REF: AMM 32-31-00-700-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
32-32-00-640-801-01 (s)	LUBRICATION OF THE NOSE LANDING GEAR (NLG) MECHANICAL EMERGENCY RELEASE CONTROL						PKG		
32.140	PKG 16 REF: AMM 32-32-00-640-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-32-00-640-801-02 (s)	CHECK OF THE NOSE LANDING GEAR (NLG) MECHANICAL EMERGENCY RELEASE CONTROL ACTUATION FORCE PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 14-JUN-2019 3636.3 2081		
	REF: AMM 32-32-00-640-801								
32-32-00-640-801-03	LUBRICATION OF THE MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY RELEASE CONTROLS PKG 16	MOS HRS/MSC AFL	24	+1m		-26	14-JUN-2019 3636.3 2081	19-MAY-2021	19-JUN-2021
	REF: AMM 32-32-00-640-801								
32-32-00-640-801-04 (s)	CHECK OF THE MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY RELEASE CONTROL ACTUATION FORCE PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 14-JUN-2019 3636.3 2081		
	REF: AMM 32-32-00-640-801								
32-32-00-700-801-01	CHECK AFTER LANDING GEAR EMERGENCY EXTENSION	MOS HRS/MSC AFL	A/R				19-OCT-2007 0 0		
32.690	REF: AMM 32-32-00-700-801								
32-32-05-900-801-01	LH MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY EXTENSION CABLE PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
	REF: AMM 32-32-05-900-801								
32-32-05-900-801-02	RH MAIN LANDING GEAR (MLG) EMERGENCY EXTENSION CABLE PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
	REF: AMM 32-32-05-900-801								
32-32-17-640-801-01 (s)	LUBRICATION OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 14-JUN-2019 3636.3 2081		
32.130	REF: AMM 32-32-17-640-801								

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-32-17-640-801-02 (s)	CHECK OF CONTROL ACTUATION LOADS PKG 16	MOS	24	+1m			PKG 14-JUN-2019 3636.3 2081		
	REF: AMM 32-32-17-640-801	HRS/MSC AFL							
32-32-17-900-801-01 (s)	LANDING GEAR EXTENSION FLEXIBLE EMERGENCY CONTROL PN	MOS					19-OCT-2007		
32.160	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 32-32-17-900-801	AFL			TSN:0		0		
+ 32-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE BRAKE LINKAGE CONTROL PKG 16	MOS	24	+1m			PKG 14-JUN-2019 3636.3 2081		
32.340	REF: AMM 32-41-00-220-801	HRS/MSC AFL							
32-41-02-900-801-01	NO. 1 BRAKE SYSTEM COMPUTER UNIT 6007613-1	MOS					19-OCT-2007		
32.510	JUN06-0209	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 32-41-02-900-801	AFL			TSN:0		0		
32-41-02-900-801-02	NO. 2 BRAKE SYSTEM COMPUTER UNIT 6007613-1	MOS					18-AUG-2016		
32.510	FEB08-0304	HRS/MSC	O/C		TSR:0		2978		
	REF: AMM 32-41-02-900-801	AFL			TSR:0		1794		
32-41-07-610-801-01 (s)	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS PKG 31	MOS	72	+2m			PKG 19-NOV-2013 2320.42 1495		
32.350	REF: AMM 32-41-07-610-801	HRS/MSC AFL	3750						
32-41-09-720-801-01 (s)	FUNCTIONAL TEST OF THE LEFT HYDRAULIC FUSE PKG 22	MOS					PKG 15-JUN-2017 3125.5 1867		
32.400	REF: AMM 32-41-09-720-801	HRS/MSC AFL	3200	+40					

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-09-720-801-02 (s)	FUNCTIONAL TEST OF THE RIGHT HYDRAULIC FUSE						PKG		
32.400	PKG 22	MOS					15-JUN-2017		
	REF: AMM 32-41-09-720-801	HRS/MSC	3200	+40			3125.5		
		AFL					1867		
32-41-33-900-801-01	LH OUTBOARD BRAKE TEMPERATURE SENSOR								
	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
32-41-33-900-801-02	RH INBOARD BRAKE TEMPERATURE SENSOR								
	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
32-41-33-900-801-03	LH OUTBOARD BRAKE TEMPERATURE SENSOR								
	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
32-41-33-900-801-04	RH OUTBOARD BRAKE TEMPERATURE SENSOR								
	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
32-41-49-900-801-01	LEFT INBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.310	6007617-2	MOS		TSN:0			19-OCT-2007		
	SEP06-0449	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-49-900-801	AFL		TSN:0			0		
32-41-49-900-801-02	RIGHT INBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.320	6007617-2	MOS		TSN:0			19-OCT-2007		
	SEP06-0450	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-41-49-900-801	AFL		TSN:0			0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-49-900-801-03	LEFT OUTBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.310	6007617-2 SEP06-0451 REF: AMM 32-41-49-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-41-49-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.320	6007617-2 SEP06-0459 REF: AMM 32-41-49-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-42-00-610-801-01	SERVICING OF THE PARK BRAKE CONTROL - SERVICING OF THE PARK BRAKE CONTROL CABLE								
32.370	REF: AMM 32-42-00-610-801	MOS HRS/MSC AFL	O/C				19-MAY-2017 3080 1850		
+ 32-42-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - PARK BRAKE SYSTEM								
32.280	PKG 22 REF: AMM 32-42-05-720-801	MOS HRS/MSC AFL	3200	+40			PKG 16-AUG-2016 2978 1794		
32-42-05-780-801-01	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR								
	REF: AMM 32-42-05-780-801	MOS HRS/MSC AFL	O/C				14-JUN-2018 3406.6 1988		
+ 32-42-05-780-801-02 (s)	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (520GC)								
	PKG 6 REF:	MOS HRS/MSC AFL	24	+1m +40			PKG 14-JUN-2019 3636.3 2081		
32-42-05-900-801-01	PARK BRAKE ACCUMULATOR								
32.470	60967-1 EFS1304 REF: AMM 32-42-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-42-13-900-801-01 (s)	PARK BRAKE FLEXIBLE CONTROL								
32.360	PN SN-UNKNOWN REF: AMM 32-42-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES								
		MOS HRS/MSC AFL	2	+5d			14-JUN-2019 3636.3 2081	14-AUG-2019	19-AUG-2019
REF: AMM 32-44-00-220-801									
+ 32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES								
		MOS HRS/MSC AFL	2	+5d			14-JUN-2019 3636.3 2081	14-AUG-2019	19-AUG-2019
REF: AMM 32-44-00-780-801									
32-44-01-280-801-01	SPECIAL DETAILED INSPECTION LEFT NOSE LANDING GEAR WHEEL SUBASSEMBLY								
32.270	5014199-1 JAN02-0021 REF: AMM 32-44-01-280-801	MOS HRS/MSC AFL	500	+3%			06-MAR-2019 3580.3 2067	2567	2582
32-44-01-280-801-02	SPECIAL DETAILED INSPECTION RIGHT NOSE LANDING GEAR WHEEL SUBASSEMBLY								
32.275	5014199-1 JAN02-0026 REF: AMM 32-44-01-280-801	MOS HRS/MSC AFL	500	+3%			06-MAR-2019 3580.3 2067	2567	2582
32-44-01-350-801-01	RESTORATION LEFT NOSE LANDING GEAR WHEEL (OVERHAUL)								
32.270 OVERHAUL	5014199-1 JAN02-0021 REF: AMM 32-44-01-350-801	MOS HRS/MSC AFL	1000	+3%	TSI:752		06-MAR-2019 3580.3 2067	2315	2345
32-44-01-350-801-02	RESTORATION RIGHT NOSE LANDING GEAR WHEEL (OVERHAUL)								
32.275 OVERHAUL	5014199-1 JAN02-0026 REF: AMM 32-44-01-350-801	MOS HRS/MSC AFL	1000	+3%	TSI:752		06-MAR-2019 3580.3 2067	2315	2345

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-01-900-801-01	LEFT NOSE LANDING GEAR WHEEL 5014199-1 JAN02-0021 REF: AMM 32-44-01-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSO:752 TSR:0			06-MAR-2019 3580.3 2067		
32.270									
32-44-01-900-801-02	RIGHT NOSE LANDING GEAR WHEEL 5014199-1 JAN02-0026 REF: AMM 32-44-01-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSO:752 TSR:0			06-MAR-2019 3580.3 2067		
32.275									
32-44-05-900-801-01	LEFT NOSE LANDING GEAR TIRE M13301IND02 8154S242 REF: AMM 32-44-05-900-801	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			06-MAR-2019 3580.3 2067		
32.270									
32-44-05-900-801-02	RIGHT NOSE LANDING GEAR TIRE M13301IND02 8073S233 REF: AMM 32-44-05-900-801	MOS HRS/MSC AFL	O/C	TSN:12 TSN:0 TSN:0			06-MAR-2019 3580.3 2067		
32.275									
32-44-09-280-801-01	SPECIAL DETAILED INSPECTION LEFT OUTBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLY 5014197 JAN02-0048 REF: AMM 32-44-09-280-801	MOS HRS/MSC AFL	400	+3%			15-JUN-2017 3125.5 1867	2267	2279
32.260									
32-44-09-280-801-02	SPECIAL DETAILED INSPECTION LEFT INBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLY 5014197MIC FEB09-0904 REF: AMM 32-44-09-280-801	MOS HRS/MSC AFL	400	+3%				?	?
32.250									
32-44-09-280-801-03	SPECIAL DETAILED INSPECTION RIGHT INBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLY 5014197 MAY09-0968 REF: AMM 32-44-09-280-801	MOS HRS/MSC AFL	400	+3%				2267 M	2279
32.255									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-09-280-801-04	SPECIAL DETAILED INSPECTION RIGHT OUTBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLY								
32.265	5014197 JUN08-0792 REF: AMM 32-44-09-280-801	MOS HRS/MSC AFL	400	+3%			15-JUN-2017 3125.5 1867	2267	2279
32-44-09-350-801-01	RESTORATION LEFT OUTBOARD MAIN LANDING GEAR WHEEL (OVERHAUL)								
32.260 OVERHAUL	5014197 JAN02-0048 REF: AMM 32-44-09-350-801	MOS HRS/MSC AFL	700	+3%			15-JUN-2017 3125.5 1867	2567	2588
32-44-09-350-801-02	RESTORATION LEFT INBOARD MAIN LANDING GEAR WHEEL (OVERHAUL)								
32.250 OVERHAUL	5014197MIC FEB09-0904 REF: AMM 32-44-09-350-801	DAYS HRS/MSC AFL	700	+3%				? ?	
32-44-09-350-801-03	RESTORATION RIGHT INBOARD MAIN LANDING GEAR WHEEL (OVERHAUL)								
32.255 OVERHAUL	5014197 MAY09-0968 REF: AMM 32-44-09-350-801	MOS HRS/MSC AFL	700	+3%				2195 M	2216
32-44-09-350-801-04	RESTORATION RIGHT OUTBOARD MAIN LANDING GEAR WHEEL (OVERHAUL)								
32.265 OVERHAUL	5014197 JUN08-0792 REF: AMM 32-44-09-350-801	MOS HRS/MSC AFL	700	+3%			15-JUN-2017 3125.5 1867	2567	2588
32-44-09-900-801-01	LEFT OUTBOARD MAIN LANDING GEAR WHEEL								
32.260	5014197 JAN02-0048 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
32-44-09-900-801-02	LEFT INBOARD MAIN LANDING GEAR WHEEL								
32.250	5014197MIC FEB09-0904 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C				14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-09-900-801-03	RIGHT INBOARD MAIN LANDING GEAR WHEEL 5014197 MAY09-0968 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-NOV-2018 3516.7 2041		
32-44-09-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR WHEEL 5014197 JUN08-0792 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C	TSR:58 TSR:1159.78 TSR:532			17-SEP-2018 3480.2 2027		
32-44-13-900-801-01	LEFT OUTBOARD MAIN LANDING GEAR TIRE M06201IND04 7199S109 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
32-44-13-900-801-02	LEFT INBOARD MAIN LANDING GEAR TIRE M06201IND04 8182S519 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-JUN-2019 3636.3 2081		
32-44-13-900-801-03	RIGHT INBOARD MAIN LANDING GEAR TIRE M06201IND04 8041S148 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			08-NOV-2018 3516.7 2041		
32-44-13-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR TIRE M06201IND04 8049S128 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
32-44-17-900-801-01	LEFT OUTBOARD MAIN LANDING GEAR BRAKE 5014198 MAY13-0840 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-17-900-801-02	LEFT INBOARD MAIN LANDING GEAR BRAKE 5014198 MAY05-0240 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	O/C	TSO:0 TSN:2547 TSO:0 TSN:1136 TSO:0			19-NOV-2013 2320.42 1495		
32-44-17-900-801-03	RIGHT INBOARD MAIN LANDING GEAR BRAKE 5014198 FEB02-0061 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	O/C	TSO:4 TSO:0 TSO:0			08-NOV-2018 3516.7 2041		
32-44-17-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR BRAKE 5014198 FEB06-0312 REF: AMM 32-44-17-900-801	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			31-MAY-2011 1641.5 959		
32-50-01-900-801-01 (s)	REPEATER STEERING BOX PN SN-UNKNOWN REF: AMM 32-50-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-50-05-900-801-01 (s)	STEERING HYDRAULIC UNIT PN SN-UNKNOWN REF: AMM 32-50-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-50-13-900-801-01	STEERING SERVOVALVE A25455004-1 00398 REF: AMM 32-50-13-900-801	MOS HRS/MSC AFL	O/C	TSN:237			06-MAR-2019 3580.3 2067		
32-61-49-900-801-01 (s)	LEFT MAIN LANDING GEAR PROXIMITY SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-02	LH MLG BRACE ACTUATOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-03	RH MLG BRACE ACTUATOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-04	RH MLG BRACE ACTUATOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-05	LH MLG UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-06	RH MLG UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-07	NLG UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-08	NLG UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-09	LH UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-10	LH UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-11	RH UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-12	RH UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-13	LH MLG LEG OUTBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-14	LH MLG LEG INBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-15	RH MLG LEG OUTBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-16	RH MLG LEG INBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-17	NLG DRAG BRACE LH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-18	NLG DRAG BRACE RH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-19	NLG LEG LH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-20	NLG LEG RH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-21	NLG LH DOOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
32-61-49-900-801-22	NLG RH DOOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321A02	PROX L/INB (L2GF2) SENSOR D22884000-1 B1606 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-FEB-2011 1565.58 876		
322801	NOSE LANDING GEAR STRUT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323801	NOSE LANDING GEAR LEG UPLOCK C24245006-3 H1612 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323811	NOSE LANDING GEAR TELESCOPIC STRUT UNLOCKING RESTRICTOR VALVE A24508-5180 H2892 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323816	NOSE LANDING GEAR UNLOCKING GEAR RESTRICTOR VALVE A24508-5090 H2635 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323821	LEFT MAIN LANDING GEAR LEG UPLOCK C24244007-3 H1099 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323826	RIGHT MAIN LANDING GEAR LEG UPLOCK C24245007-3 H1761 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323831	NORMAL/EMERGENCY SELECTOR VALVE								
32.200	B94B09-202-1 C53266 REF: AMM 32-30-13-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323836	GEAR/DOOR CONTROL UNIT								
32.210	BHC1031-2 787 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323841	LEFT MAIN LANDING GEAR DOOR MAIN UPLOCK								
32.220	C24257002-2 H2286 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323846	RIGHT MAIN LANDING GEAR DOOR MAIN UPLOCK								
32.220	C24257002-2 H2287 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323851	LEFT MAIN GEAR EXTENSION ACTUATOR GEAR RESTRICTOR VALVE								
32.230	A24508-5220 H2842 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
323856	RIGHT MAIN GEAR EXTENSION ACTUATOR GEAR RESTRICTOR VALVE								
32.230	A24508-5220 H2843 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324155 (s)	LEFT NOSE LANDING GEAR TACHOMETER- GENERATOR								
32.330	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324156 (s)	RIGHT NOSE LANDING GEAR TACHOMETER- GENERATOR								
32.330	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324801 (s)	NORMAL/EMERGENCY BRAKE DISTRIBUTOR								
32.420	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324803	PARK/EMERGENCY BRAKE VALVE								
32.430	6007618-1 MAR060107 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324811 (s)	NORMAL BRAKE ELECTRIC DISTRIBUTOR								
32.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324813	EMERGENCY BRAKE ELECTRIC DISTRIBUTOR								
32.440	65670-1 3803AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324816 (s)	PARKING BRAKE ACCUMULATOR OVERPRESSURE VALVE								
32.450	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324826	PARKING BRAKE ACCUMULATOR CHECK VALVE								
32.460	A24515 FM3868 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324836	LEFT BRAKE NORMAL PRESSURE SWITCH								
32.480	90000961-1 0217 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324841	RIGHT BRAKE NORMAL PRESSURE SWITCH								
32.480	90000961-1 0215 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324843 (s)	LEFT MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH								
32.490	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324846	RIGHT MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH								
32.490	90000961-1 0216 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324851	PARKING BRAKE PRESSURE SWITCH								
32.500	90000961-1 0222 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324861 (s)	LEFT NORMAL BRAKING SERVOVALVE								
32.520	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324863 (s)	RIGHT NORMAL BRAKING SERVOVALVE								
32.520	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324866 (s)	LEFT BRAKING SYSTEM FILTER								
32.530	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324871 (s)	RIGHT BRAKING SYSTEM FILTER								
32.530	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324876 (s)	PARKING BRAKE SYSTEM FILTER								
32.305	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324881 (s)	LEFT BRAKE NORMAL RESTRICTOR VALVE								
32.540	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324886	RIGHT BRAKE NORMAL RESTRICTOR VALVE								
32.540	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324891	LEFT HAND BRAKE (BSCU1) CONTROL SERVOVALVE								
32.650	6007614-2 0390 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324893	LEFT HAND BRAKE (BSCU2) CONTROL SERVOVALVE								
32.660	6007614-2 0391 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324896	RIGHT HAND BRAKE (BSCU1) CONTROL SERVOVALVE								
32.650	6007614-2 0400 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
324898	RIGHT HAND BRAKE (BSCU2) CONTROL SERVOVALVE								
32.660	6007614-2 0401 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
325801	STEERING SLIDING DISTRIBUTOR VALVE								
32.590	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
325806	STEERING CONTROL BOX								
32.600	287837-1 H1608 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
325811	STEERING AMPLIFIER								
32.610	C24242010 H0749 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
326002	LEFT MAIN LANDING GEAR PROXIMITY (L12GA2) SENSOR								
32.620	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
326003	RIGHT MAIN LANDING GEAR PROXIMITY (R12GA1) SENSOR								
32.630	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
326004	RIGHT MAIN LANDING GEAR PROXIMITY (R12GA2) SENSOR								
32.630	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
326005	NOSE LANDING GEAR PROXIMITY (3GF1) SENSOR								
32.640	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
326006	NOSE LANDING GEAR PROXIMITY (3GF2) SENSOR								
32.640	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 33 LIGHTS									
33-10-02-900-801-01	OVERHEAD PANEL								
	419-49-47K2K2F 726019 REF:	MOS HRS/MSC AFL	O/C				22-JUN-2013 2261.25 1434		
33-40-37-900-801-01	LEFT LANDING LIGHT								
33.100	751-1002-001 HPL-000190 REF: AMM 33-40-37-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-JUL-2014		
33-40-37-900-801-02	RIGHT LANDING LIGHT								
33.100	751-1002-001 HPL-000260 REF: AMM 33-40-37-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-JUL-2014		
33-40-41-900-801-01	TAXI LIGHT								
	4626 NO SN REF: AMM 33-40-41-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-OCT-2012 2102.08 1311		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-41-960-801-01	REPLACEMENT TAXI LIGHT BULB 4626 NO SN REF: AMM 33-40-41-960-801	MOS HRS/MSC AFL	O/C				06-JAN-2014 2356 1516		
33-50-00-710-804-01 (s)	OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EMERGENCY LIGHTING SYSTEM PKG 23 REF:	MOS HRS/MSC AFL	4800	+40			PKG 19-OCT-2007 0 0		
+ 33-50-00-720-801-01 33.180	FUNCTIONAL TEST NO.1 EMERGENCY LIGHTING (EPS 1) POWER SUPPLY SYSTEM D734-02-001 2611 REF: AMM 33-50-00-720-801	MOS HRS/MSC AFL	O/C				15-JUN-2017		
+ 33-50-00-720-801-02 33.180	FUNCTIONAL TEST NO.2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY SYSTEM D734-02-001 2256 REF: AMM 33-50-00-720-801	MOS HRS/MSC AFL	O/C						
+ 33-50-00-720-801-03 33.190	FUNCTIONAL TEST NO.3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY SYSTEM D734-02-001 257 REF: AMM 33-50-00-720-801	MOS HRS/MSC AFL	O/C						
33-50-05-350-801-01 OVERHAUL	RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (L7011LP) P2-07-0009-520 SN-UNKNOWN REF: AMM 33-50-05-350-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019 3636.3 2081	14-JUN-2020	24-JUN-2020
33-50-05-350-801-02 OVERHAUL	RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (R7011LP) P2-07-0011-500 N/A REF: AMM 33-50-05-350-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019 3636.3 2081	14-JUN-2020	24-JUN-2020

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-05-350-803-01	RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (L7011LP) P2-07-0009-520 SN-UNKNOWN REF: AMM 33-50-05-350-803	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
33-50-05-350-803-02	RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASHLIGHT (R7011LP) P2-07-0011-500 N/A REF: AMM 33-50-05-350-803	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
33-50-17-900-801-01	AFT CABIN DIVIDER SELF LUMINOUS EXIT SIGN (R1700LE) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 33-50-17-960-801-01	DISCARD OF THE AFT CABIN DIVIDER SELF LUMINOUS EXIT SIGN - AFT CABIN DIVIDER SELF LUMINOUS EXIT SIGN (R1700LE) PN SN-UNKNOWN REF: AMM 33-50-17-960-801	MOS HRS/MSC AFL	-				29-AUG-2016 2978 1794		
33-50-33-610-801-01	SERVICING NO.1 EMERGENCY LIGHTING (EPS 1) POWER SUPPLY D734-02-001 2611 REF: AMM 33-50-33-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019 3636.3 2081	14-JUN-2020	24-JUN-2020
33-50-33-610-801-02	SERVICING NO.2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY D734-02-001 2256 REF: AMM 33-50-33-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019 3636.3 2081	14-JUN-2020	24-JUN-2020
33-50-33-610-801-03	SERVICING NO.3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY D734-02-001 257 REF: AMM 33-50-33-610-801	MOS HRS/MSC AFL	12	+3%			14-JUN-2019 3636.3 2081	14-JUN-2020	24-JUN-2020

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-33-900-801-01	LEFT COCKPIT EMERGENCY LIGHTING (EPS 1) POWER SUPPLY								
33.180	D734-02-001 2611 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C	TSN:24 TSN:510.8 TSN:214			14-JUN-2019 3636.3 2081		
33-50-33-900-801-02	RIGHT COCKPIT EMERGENCY LIGHTING (EPS 2) POWER SUPPLY								
33.180	D734-02-001 2256 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C				14-JUN-2019 3636.3 2081		
33-50-33-900-801-03	CABIN EMERGENCY LIGHTING (EPS 3) POWER SUPPLY								
33.190	D734-02-001 257 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C				14-JUN-2019 3636.3 2081		
33-50-33-900-801-04	NO. 2 CABIN EMERGENCY LIGHTING (EPS 4) POWER SUPPLY								
	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
33-50-33-960-801-04	REPLACEMENT NO. 2 CABIN EMERGENCY LIGHTING (EPS 4) POWER SUPPLY								
	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
33-50-37-900-801-01	NO. 1 EMERGENCY POWER SUPPLY (EPS) BATTERY PACK (PAGE)								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
33-50-37-900-801-02	NO. 2 EMERGENCY POWER SUPPLY (EPS) BATTERY PACK (PAGE)								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-37-900-801-03	NO. 3 EMERGENCY POWER SUPPLY (EPS) BATTERY PACK (PAGE)								
	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
33-50-37-960-802-01	REPLACE PACK BATTERY PACK								
33.180	PN	MOS					15-JUN-2017		
	SN-UNKNOWN	HRS/MSC	O/C				3125.5		
	REF: AMM 33-50-37-900-801	AFL					1867		
33-50-37-960-802-02	REPLACE PACK BATTERY PACK								
33.180	PN	MOS					01-JUL-2015		
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: AMM 33-50-37-900-801	AFL							
33-50-37-960-802-03	REPLACE PACK BATTERY PACK								
33.190	PN	MOS					01-JUL-2015		
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: AMM 33-50-37-900-801	AFL							
33-90-01-200-801-01S (s)	INSPECTION OF THE AFT CABIN DIVIDER LUMINOUS VERTICAL EXIT SIGN								
	PKG 31	MOS	72				19-NOV-2013		
		HRS/MSC					2320.42		
	REF: SMM 33-90-01	AFL	3750				1495		
331801	PILOT DIMMER BOX								
33.010	24-01	MOS		TSN:0			19-OCT-2007		
	052020	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
331806	COPILOT DIMMER BOX								
33.010	24-01	MOS		TSN:0			19-OCT-2007		
	052021	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331811	PILOT FLUORESCENT GLARESHIELD TUBE C0566F100	MOS		TSN:0			19-OCT-2007		
33.020	196 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331816	COPILOT FLUORESCENT GLARESHIELD TUBE PN	MOS		TSN:0			19-OCT-2007		
33.020	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331821	LEFT FLUORESCENT STRIP TUBE C0567F100	MOS		TSN:0			19-OCT-2007		
33.030	200 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331826	CENTER FLUORESCENT STRIP TUBE PN	MOS		TSN:0			19-OCT-2007		
33.030	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331831	RIGHT FLUORESCENT STRIP TUBE PN	MOS		TSN:0			19-OCT-2007		
33.030	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331836	GLARESHIELD/STRIP POWER SUPPLY PN	MOS		TSN:0			19-OCT-2007		
33.040	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
331841	PILOT LIGHTING INSTRUMENT TRANSFORMER 96PS002	MOS		TSN:0			19-OCT-2007		
33.050	1221 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331846	COPILOT LIGHTING INSTRUMENT TRANSFORMER								
33.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
334801	VERTICAL STABILIZER ANTI-COLLISION LIGHT								
33.060	01-0790044-09 07087-07106 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			06-DEC-2010 1473 835		
334803	REAR STROBE/NAVIGATION LIGHT								
33.070	39-54-21 2117 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
334806	VERTICAL STABILIZER ANTI-COLLISION POWER SUPPLY								
33.080	39-42-4 835 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
334811	FUSELAGE ANTI-COLLISION POWER SUPPLY								
33.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
334821	TAXI LIGHT								
33.110	4060622 87704 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
334823	LEFT WING STROBE LIGHT								
33.120	03-9001-0003 299940007 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:5 TSN:0 TSN:0			04-APR-2017 3086.4 1852		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334826	RIGHT WING STROBE LIGHT 03-9001-0004 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2014 2375.55 1530		
334828	LEFT WING STROBE POWER SUPPLY PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-MAY-2014 2375.9 1530		
334831	RIGHT WING STROBE POWER SUPPLY PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-MAY-2014 2375.9 1530		
334833	FUSELAGE LOW POWER SUPPLY 39-44-31 1544 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
334836	FUSELAGE ANTI-COLLISION LIGHT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
334841	LEFT WING ICE DETECTION LIGHT 4371567 568 REF: AMM 33-40-45-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
334842	RIGHT WING ICE DETECTION LIGHT 4371574 556 REF: AMM 33-40-45-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334A11	PULSE LIGHT CONTROL BOX FE892-02 0431 REF:	MOS HRS/MSC AFL	O/C	TSR:3			24-DEC-2010 1502.08 846		
334A27	LEFT WING ANTI-COLLISION LIGHT 03-9503-5003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-MAY-2014 2375.9 1530		
334A28	RIGHT WING ANTI-COLLISION LIGHT 03-9503-5004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			20-MAY-2014 2375.9 1530		
334A31	LEFT UPPER LOGO LIGHT 4368394 572 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
334A32	RIGHT UPPER LOGO LIGHT 4382051 611 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

CHAPTER 34 NAVIGATION

+ 34-10-00-720-801-01	FUNCTIONAL TEST PILOT DIGITAL AIR DATA MODULE HG1153CA01 06111909 REF: AMM 34-10-00-720-801	MOS HRS/MSC AFL	24	+3%			31-JAN-2018 3282.1 1930	31-JAN-2020	22-FEB-2020
34.050 RVSM									
+ 34-10-00-720-801-02	FUNCTIONAL TEST COPILOT DIGITAL AIR DATA MODULE HG1153CA01 06111908 REF: AMM 34-10-00-720-801	MOS HRS/MSC AFL	24	+3%			31-JAN-2018 3282.1 1930	31-JAN-2020	22-FEB-2020
34.060 RVSM									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-10-01-900-801-01	REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE AIR TEMPERATURE PROBE (52FL)								
34.125	102AU1CK A66490 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 34-10-11-720-801-01 (s)	CHECK OF THE ELECTRICAL ZERO SETTING OF LEFT ANGLE-OF-ATTACK SENSOR						PKG		
27.485	PKG 21 REF: AMM 34-10-11-720-801	MOS HRS/MSC AFL	1600	+40			19-NOV-2013 2320.42 1495		
34-10-11-720-801-02	CHECK OF THE ELECTRICAL ZERO SETTING OF RIGHT ANGLE-OF-ATTACK SENSOR								
27.485	PKG 21 REF: AMM 34-10-11-720-801	MOS HRS/MSC AFL	1600	+40			19-NOV-2013 2320.42 1495	3920.42	3960.42
34-10-11-900-801-01	LEFT ANGLE-OF-ATTACK SENSOR								
27.500	861CAU2 0965A REF: AMM 34-10-11-900-801	MOS HRS/MSC AFL	O/C				27-NOV-2008 654.25 359		
34-10-11-900-801-02	RIGHT ANGLE-OF-ATTACK SENSOR								
27.500	861CAU2 1717A REF: AMM 34-10-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-11-00-790-801-01	LEAK TEST STATIC PRESSURE SYSTEM								
	REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
34-11-00-790-801-02	LEAK TEST TOTAL PRESSURE SYSTEM								
	REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00-790-801-03	LEAK TEST STATIC PRESSURE SYSTEM	MOS					19-OCT-2007		
	REF:	HRS/MSC	O/C				0		
		AFL					0		
34-11-00-790-801-04	LEAK TEST TOTAL PRESSURE SYSTEM	MOS					19-OCT-2007		
	REF:	HRS/MSC	O/C				0		
		AFL					0		
34-11-00-790-801-05	LEAK TEST STATIC PRESSURE SYSTEM	MOS					19-OCT-2007		
	REF:	HRS/MSC	O/C				0		
		AFL					0		
34-11-00-790-801-06	LEAK TEST TOTAL PRESSURE SYTEM	MOS					19-OCT-2007		
	REF:	HRS/MSC	O/C				0		
		AFL					0		
+ 34-11-01-200-801-01	CHECK OF THE LEFT TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS					14-JUN-2018		
34.090	REF: AMM 34-11-01-200-801	HRS/MSC	O/C				3406.6		
		AFL					1988		
34-11-01-200-801-02	CHECK OF THE RIGHT TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS					14-JUN-2018		
34.090	REF: AMM 34-11-01-200-801	HRS/MSC	O/C				3406.6		
		AFL					1988		
34-11-01-200-801-03	CHECK OF THE STAND-BY TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS					14-JUN-2018		
34.090	REF: AMM 34-11-01-200-801	HRS/MSC	O/C				3406.6		
		AFL					1988		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-01-900-801-01	LEFT PITOT PRESSURE TOTAL PROBE								
34.110	50520 3991 REF: AMM 34-11-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-11-01-900-801-02	RIGHT PITOT PRESSURE TOTAL PROBE								
34.110	50520 3992 REF: AMM 34-11-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-11-01-900-801-03	STAND-BY PITOT PRESSURE TOTAL PROBE								
34.110	50520 3993 REF: AMM 34-11-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-11-05-900-801-01	LEFT STATIC PRESSURE PROBE								
34.120	C16757AA 160 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:130 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
34-11-05-900-801-02	RIGHT STATIC PRESSURE PROBE								
34.120	C16757AA 96 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:140 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
+ 34-14-01-700-881-01	TEST PILOT DIGITAL AIR DATA MODULE (FAR 91.411)								
34.050 MANDATORY	HG1153CA01 06111909 REF: FAR 91.411	MOS HRS/MSC AFL	24				31-JAN-2018	31-JAN-2020	
+ 34-14-01-700-881-02	TEST COPILOT DIGITAL AIR DATA MODULE (FAR 91.411)								
34.060 MANDATORY	HG1153CA01 06111908 REF: FAR 91.411	MOS HRS/MSC AFL	24				31-JAN-2018	31-JAN-2020	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-14-01-900-802-01	PILOT DIGITAL AIR DATA MODULE								
34.050	HG1153CA01 06111909 REF: AMM 34-14-01-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-AUG-2007 0 0		
34-14-01-900-802-02	COPILOT DIGITAL AIR DATA MODULE								
34.060	HG1153CA01 06111908 REF: AMM 34-14-01-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-AUG-2007 0 0		
+ 34-18-01-700-881-01	TEST STATIC PRESSURE SYSTEM (FAR 91.411)								
34.100 MANDATORY	REF: FAR 91.411	MOS HRS/MSC AFL	24				31-JAN-2018 3282.1 1930	31-JAN-2020	
+ 34-21-00-700-801-01 (s)	CHECK OF THE GENERAL-PURPOSE BUSES TO THE NO. 1 INERTIAL REFERENCE UNIT (IRU)								
34.560	PKG 23 REF: AMM 34-21-00-700-801	MOS HRS/MSC AFL	4800	+40			PKG 19-OCT-2007 0 0		
+ 34-21-00-700-801-01A	CHECK OF THE GENERAL-PURPOSE BUSES TO THE NO. 1 INERTIAL REFERENCE UNIT (IRU) (MANDATORY REF 5-40/20)								
34.550 CMR	REF: AMM 34-21-00-700-801	MOS HRS/MSC AFL	5000				19-OCT-2007 0 0	5000	
34-21-00-700-801-02 (s)	CHECK CHECK OF THE GENERAL-PURPOSE BUSES TO THE NO. 2 INERTIAL REFERENCE UNIT (IRU)								
	PKG 23 REF: AMM 34-21-00-700-801	MOS HRS/MSC AFL	4800	+40			19-OCT-2007 0 0		
34-21-00-700-801-02A	CHECK OF THE GENERAL-PURPOSE BUSES TO THE NO. 2 INERTIAL REFERENCE UNIT (MANDATORY REF 5-40/20)								
CMR	REF: AMM 34-21-00-700-801	MOS HRS/MSC AFL	5000				19-OCT-2007 0 0	5000	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21-00-700-801-03 (s)	CHECK CHECK OF THE GENERAL-PURPOSE BUSES TO THE NO. 3 INERTIAL REFERENCE UNIT (IRU) PKG 23	MOS					PKG		
	REF: AMM 34-21-00-700-801	HRS/MSC AFL	4800	+40			19-OCT-2007 0 0		
34-21-01-900-801-01	NO. 1 INERTIAL REFERENCE UNIT HG2100AB02	MOS					19-OCT-2007		
34.130	56012403 REF: AMM 34-21-01-900-801	HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	0 0 0	
34-21-01-900-801-02	NO. 2 INERTIAL REFERENCE UNIT HG2100AB02	MOS					19-OCT-2007		
34.130	56013089 REF: AMM 34-21-01-900-801	HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	0 0 0	
34-21-01-900-801-03	NO. 3 INERTIAL REFERENCE UNIT PN	MOS					19-OCT-2007		
34.130	SN-UNKNOWN REF: AMM 34-21-01-900-801	HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	0 0 0	
34-21-09-900-801-01	NO. 1 IRS CONFIGURATION MODULE 7519272-901	MOS					19-OCT-2007		
34.055	06095278 REF: AMM 34-21-09-900-801	HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	0 0 0	
34-21-09-900-801-02	NO. 2 IRS CONFIGURATION MODULE 7519272-901	MOS					19-OCT-2007		
34.055	06105331 REF: AMM 34-21-09-900-801	HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	0 0 0	
34-23-00-720-801-01	FUNCTIONAL TEST AIR (ADU) DATA UNIT 27300-01-01	MOS	24	+3%			31-JAN-2018	31-JAN-2020	22-FEB-2020
34.010	M019170 REF: AMM 34-23-00-720-801	HRS/MSC AFL					3282.1 1930		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-23-00-720-801-02	FUNCTIONAL TEST SECONDARY FLIGHT (SFD) DISPLAY UNIT								
34.010	39216-00-02 M019501 REF: AMM 34-23-00-720-801	MOS HRS/MSC AFL	24	+3%			31-JAN-2018 3282.1 1930	31-JAN-2020	22-FEB-2020
34-23-01-900-801-01	SECONDARY FLIGHT (SFD) DISPLAY UNIT								
34.010	39216-00-02 M019501 REF: AMM 34-23-01-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
+ 34-23-05-700-881-01	TEST AIR (ADU) DATA UNIT (FAR 91.411)								
34.010 MANDATORY	27300-01-01 M019170 REF: FAR 91.411	MOS HRS/MSC AFL	24				31-JAN-2018	31-JAN-2020	
34-23-05-900-801-01	AIR (ADU) DATA UNIT								
34.010	27300-01-01 M019170 REF: AMM 34-23-05-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
34-25-00-820-801-01	SWING/COMPENSATE STAND-BY MAGNETIC COMPASS								
34.180 CALIBRATE	KCA0105W AW936 REF: AMM 34-25-00-820-801	MOS HRS/MSC AFL	24				22-MAR-2018 3341.1 1960	22-MAR-2020	
+ 34-31-00-710-801-01	OPERATIONAL TEST HUD								
34.525	REF: AMM 34-31-00-710-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
34-31-01-900-801-01	HEAD-UP GUIDANCE SUSTEM (HGS) OVERHEAD UNIT								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-31-05-900-801-01	HEAD-UP GUIDANCE (HGS) COMBINER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-31-09-900-801-01	HEAD-UP GUIDANCE SYSTEM (HGS) COMPUTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-32-01-100-801-01 34.565	CLEAN OF THE ENHANCED FLIGHT VISION SYSTEM (EFVS) INFRARED (ISU) SENSOR UNIT REF: AMM 34-32-01-100-801	MOS HRS/MSC AFL	O/C				11-FEB-2011 1541.42 872		
34-32-01-780-801-01 34.565	PRESSURE CHECK OF THE ENHANCED FLIGHT VISION SYSTEM (EFVS) INFRARED (ISU) SENSOR UNIT REF: AMM 34-32-01-780-801	MOS HRS/MSC AFL	N/A				11-FEB-2011 1541.42 872		
34-32-01-900-801-01 34.565	ENHANCED FLIGHT VISION SYSTEM (EFVS) INFRARED (ISU) SENSOR UNIT PN NOT INSTALLED REF: AMM 34-32-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-32-05-100-801-01 34.570	CLEAN OF THE ENHANCED FLIGHT VISION SYSTEM (EFVS) INFRARED (IRW) WINDOW REF: AMM 34-32-05-100-801	MOS HRS/MSC AFL	O/C				11-FEB-2011 1541.42 872		
34-32-05-900-801-01 34.570	ENHANCED FLIGHT VISION SYSTEM (EFVS) INFRARED (IRW) WINDOW PN NOT INSTALLED REF: AMM 34-32-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-32-09-960-801-01	ENHANCED FLIGHT VISION SYSTEM (EFVS) AIRCRAFT IDENTIFICATION (AIT) TAG								
34.575	PN NOT INSTALLED REF: AMM 34-32-09-960-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-41-01-900-801-01	WEATHER RADAR								
34.270	PN SN-UNKNOWN REF: AMM 34-41-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-42-01-820-801-01	CALIBRATION NO. 1 RADIO-ALTIMETER TRANSCEIVER								
34.280	7001840-932 0610D088 REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	25	+3%			14-JUN-2019 3636.3 2081	14-JUL-2021	06-AUG-2021
34-42-01-820-801-02	CALIBRATION NO. 2 RADIO-ALTIMETER TRANSCEIVER								
34.280	PN SN-UNKNOWN REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
34-42-01-900-801-01	NO. 1 RADIO-ALTIMETER TRANSCEIVER								
34.280	7001840-932 0610D088 REF: AMM 34-42-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-42-01-900-801-02	NO. 2 RADIO-ALTIMETER TRANSCEIVER								
34.280	PN SN-UNKNOWN REF: AMM 34-42-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-42-CUS-3001 (s)	CHECK EGPWS COMPUTER DATABASE AND UPDATE WITH THE LASTEST REVISION IF NECESSARY								
CUSTOMER CODE	REF:	MOS HRS/MSC AFL	A/R				02-DEC-2018 3524.23 2048		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-44-01-900-801-01	TCAS TRANSCEIVER								
34.310	7517900-55020 20008130 REF: AMM 34-44-01-900-801	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
34-44-05-900-801-01	TCAS LOWER ANTENNA								
34.320	7514081-913 ANE46651 REF: AMM 34-44-05-900-801	MOS HRS/MSC AFL	O/C	TSN:5 TSN:0 TSN:0			30-OCT-2015 2761.8 1696		
34-44-05-900-801-02	TCAS UPPER ANTENNA								
34.320	7514081-913 ANE25563 REF: AMM 34-44-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-45-01-900-801-01	EGPWS COMPUTER								
31.205	7028419-1904 06101342 REF: AMM 34-45-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-51-01-900-802-01	NO. 1 VOR/ILS DATA LINK (VIDL) MODULE								
34.400	7056202-802 06102158 REF: AMM 34-51-01-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-51-01-900-802-02	NO. 2 VOR/ILS DATA LINK (VIDL) MODULE								
34.400	7026202-802 06102144 REF: AMM 34-51-01-900-802	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-51-05-900-801-01	NO. 1 VOR/LOC ANTENNA								
34.380	DMN4-45-3 10466 REF: AMM 34-51-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-51-05-900-801-02	NO. 2 VOR/LOC ANTENNA								
34.380	DMN4-45-3 10467 REF: AMM 34-51-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-51-17-900-801-01	REMOVAL / INSTALLATION OF THE MARKER ANTENNA - MARKER ANTENNA (8RS)								
34.430	S35-1000-1 6162 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-52-05-900-801-01	NO. 1 DME ANTENNA								
34.450	DMNI50-2-2 109607 REF: AMM 34-52-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-52-05-900-801-02	NO. 2 DME ANTENNA								
34.450	DMNI50-2-2 109610 REF: AMM 34-52-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
34-53-05-900-801-01	NO. 1 ADF LOOP ANTENNA								
34.420	7510300-901 1408M989 REF: AMM 34-53-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-OCT-2015 2761.8 1696		
34-53-05-900-801-02	NO. 2 ADF LOOP ANTENNA								
34.420	7510300-901 0606A624 REF: AMM 34-53-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 34-54-00-700-881-01	TEST NO. 1 ATC TRANSPONDER (FAR 91.413)								
34.300 MANDATORY	7517402-970 0804E033 REF: FAR 91.413	MOS HRS/MSC AFL	24				31-JAN-2018	31-JAN-2020	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-54-00-700-881-02	TEST NO. 2 ATC TRANSPONDER (FAR 91.413) 7517402-970 34.300 MANDATORY 0804E102 REF: FAR 91.413	MOS HRS/MSC AFL	24				31-JAN-2018	31-JAN-2020	
+ 34-54-00-720-802-01	FUNCTIONAL TEST NO. 1 ATC TRANSPONDER 7517402-970 34.300 RVSM 0804E033 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			31-JAN-2018 3282.1 1930	31-JAN-2020	22-FEB-2020
+ 34-54-00-720-802-02	FUNCTIONAL TEST NO. 2 ATC TRANSPONDER 7517402-970 34.300 RVSM 0804E102 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			31-JAN-2018 3282.1 1930	31-JAN-2020	22-FEB-2020
34-54-05-900-801-01	NO. 1 ATC LOWER ANTENNA DMNI50-2-2 34.350 109608 REF: AMM 34-54-05-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
34-54-05-900-801-02	NO. 1 ATC UPPER ANTENNA DMNI50-2-2 34.350 109609 REF: AMM 34-54-05-900-801	MOS HRS/MSC AFL	O/C				14-JUN-2019 3636.3 2081		
34-54-05-900-801-03	NO. 2 ATC LOWER ANTENNA DMNI50-2-2 34.360 109653 REF: AMM 34-54-05-900-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
34-54-05-900-801-04	NO. 2 ATC UPPER ANTENNA DMNI50-2-2 34.360 109659 REF: AMM 34-54-05-900-801	MOS HRS/MSC AFL	O/C				14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-55-01-900-801-01	NO. 1 GPS MODULE								
34.175	245-604067-100 07092518 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-NOV-2013 2320.42 1495		
34-55-01-900-801-02	NO. 2 GPS MODULE								
34.175	245-604067-100 12015777 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-JAN-2014 2356 1516		
34-55-05-900-801-01	NO. 1 GPS ANTENNA								
34.520	S67-1575-137 773-1340 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
34-55-05-900-801-02	NO. 2 GPS ANTENNA								
34.520	S67-1575-137 773-1341 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
+ 34-58-01-710-881-01	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)								
34.390 MANDATORY	REF: FAR 91.171	DAYS HRS/MSC AFL	30				17-JUN-2019	16-JUL-2019 M	
34-90-10-900-801-01	CONTROL DISPLAY UNIT (CDU) (GNS-XLS BATTERY ONLY) BATTERY								
	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
342801	STAND-BY MAGNETIC COMPASS								
34.180	KCA0105W AW936 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342A11	REPLACE 7034056-1901 13071636 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
343801	NO. 1 RADIO-ALTIMETER TRANSMITTER ANTENNA S67-2002-13 545-3133 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
343806	NO. 1 RADIO-ALTIMETER RECEPTION ANTENNA S67-2002-13 545-3134 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
343811	NO. 2 RADIO-ALTIMETER TRANSMITTER ANTENNA PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
343816	NO. 2 RADIO-ALTIMETER RECEPTION ANTENNA PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
344816	NO. 1 ATC TRANSPONDER 7517402-970 0804E033 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-NOV-2013 2320.42 1495		
344817	NO. 2 ATC TRANSPONDER 7517402-970 0804E102 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344831	NO. 1 WEATHER RADAR CONTROL								
34.370	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
344832	NO. 2 WEATHER RADAR CONTROL								
34.370	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
344A01	WEATHER RADAR TRANSCEIVER								
	7021450-801 08018098 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-DEC-2010 1474.67 837		
345083	NO. 3 VOR/ILS DATA LINK (VIDL) MODULE								
34.400	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345423	NO. 3 GPS ANTENNA								
34.520	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345801	NO. 1 ADF RECEIVER								
34.410	7510114-855 0607B023 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345802	NO. 2 ADF RECEIVER								
34.410	7510114-855 0607B028 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345818	GLIDE SLOPE ANTENNA								
34.430	DMN25-2 5620 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345821	NO. 1 DME TRANSCEIVER								
34.440	7510184-855 0607B366 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345822	NO. 2 DME TRANSCEIVER								
34.440	7510184-855 060B332 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345831	AFIS DATA MANAGEMENT UNIT								
34.460	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345836	AFIS CONFIGURATION MODULE								
34.470	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345838	AFIS ANTENNA								
34.480	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345846	GPWS INVERTER								
34.500	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345851	NO. 1 GPS SENSOR								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345852	NO. 2 GPS SENSOR								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345853	NO. 3 GPS SENSOR								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345875	NO. 1 MODULAR AVIONICS UNIT								
34.195	7029782-1920 06101596 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345876	NO. 2 MODULAR AVIONICS UNIT								
34.195	7029782-1920 06111600 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345921	NO. 1 MAU POWER SUPPLY AIR MANAGEMENT (PS-AMBM 2) MODULE								
34.245	7029308-1901 06100420 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
345922	NO. 2 MAU POWER SUPPLY AIR MANAGEMENT (PS-AMBM 2) MODULE								
34.245	7029308-1901 06110438 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345928	MAU-1 NO. 5 PROCESSOR (ECL,FMS1,TOLD1) MODULE								
34.255	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
345929	MAU-2 NO. 6 PROCESSOR (FMS2,TOLD2) MODULE								
34.255	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	O/C				19-NOV-2013 2320.42 1495		
346031	DATA MANAGEMENT UNIT								
34.140	7031051-902 06010728 REF: AMM 45-90-01-900-801	MOS HRS/MSC AFL	O/C				10-OCT-2017 3218.6 1910		
349801	ENHANCED FLIGHT VISION SYSTEM (EFVS) COOLING FAN								
34.580	PN NOT INSTALLED REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
349803	ENHANCED FLIGHT VISION SYSTEM (EFVS) CONTROL PANEL								
34.585	PN NOT INSTALLED REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
349806	ENHANCED FLIGHT VISION SYSTEM (EFVS) "EVS" PUSH-BUTTON								
34.590	PN NOT INSTALLED REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
349808	ENHANCED FLIGHT VISION SYSTEM (EFVS) VIDEO FILTER								
34.595	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
349811	NO. 1 ENHANCED FLIGHT VISION SYSTEM (EFVS) (9939NH) FUSE								
34.600	PN NOT INSTALLED REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
349812	NO. 2 ENHANCED FLIGHT VISION SYSTEM (EFVS) (9949NH) FUSE								
34.600	PN NOT INSTALLED REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
349816	ENHANCED FLIGHT VISION SYSTEM (EFVS) INVERTER								
34.605	PN NOT INSTALLED REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 35 OXYGEN									
35-10-05-350-801-01	RESTORATION PILOT OXYGEN MASK (OVERHAUL)								
35.040	MC10-12-151 SE10365 REF: AMM 35-10-05-350-801	MOS HRS/MSC AFL	72	+3%			10-DEC-2015 2810.5 1714	10-DEC-2021	14-FEB-2022
OVERHAUL									
35-10-05-350-801-02	RESTORATION COPILOT OXYGEN MASK (OVERHAUL)								
35.050	MC10-12-151 117445 REF: AMM 35-10-05-350-801	MOS HRS/MSC AFL	72	+3%			10-DEC-2015 2810.5 1714	10-DEC-2021	14-FEB-2022
OVERHAUL									
35-10-05-350-801-03	RESTORATION THIRD CREW MEMBER OXYGEN MASK (OVERHAUL)								
35.060	MC10-12-151 110228 REF: AMM 35-10-05-350-801	MOS HRS/MSC AFL	72	+3%			10-DEC-2015 2810.5 1714	10-DEC-2021	14-FEB-2022
OVERHAUL									
+ 35-10-05-710-801-01 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)								
35.040	PKG 15 REF: AMM 35-10-05-710-801	MOS HRS/MSC AFL	12	+1m			PKG 14-JUN-2019 3636.3 2081		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10-05-710-801-02 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)						PKG		
35.050	PKG 15 REF: AMM 35-10-05-710-801	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
+ 35-10-05-710-801-03 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)						PKG		
35.060	PKG 15 REF: AMM 35-10-05-710-801	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
35-10-05-900-801-01	PILOT OXYGEN MASK								
35.040	MC10-12-151 SE10365 REF: AMM 35-10-05-900-801	MOS HRS/MSC AFL	H/T			TSO:0 TSO:0 TSO:0	08-JUN-2012 1972.17 1216		
35-10-05-900-801-02	COPILOT OXYGEN MASK								
35.050	MC10-12-151 117445 REF: AMM 35-10-05-900-801	MOS HRS/MSC AFL	H/T			TSO:1 TSO:0 TSO:0	12-OCT-2011 1768.92 1063		
35-10-05-900-801-03	THIRD CREW MEMBER OXYGEN MASK								
35.060	MC10-12-151 110228 REF: AMM 35-10-05-900-801	MOS HRS/MSC AFL	O/C			TSO:1 TSO:0 TSO:0	12-OCT-2011 1768.92 1063		
35-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS AND SMOKE MASKS						PKG		
35.225	PKG 16 REF: AMM 35-20-00-210-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 35-20-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM						PKG		
35.080	PKG 21 REF: AMM 35-20-00-720-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-20-00-720-801-01A	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM (MANDATORY REF 5-40-20)								
35.080		MOS					15-JUN-2017		
CMR	REF: AMM 35-20-00-720-801	HRS/MSC AFL	1640				3125.5 1867		4765.5
35-20-01-900-801-01	PASSENGER OXYGEN CONTROLLER								
35.090	448833-4	MOS		TSR:0			03-FEB-2011		
	317	HRS/MSC	O/C	TSR:0			1541.42		
	REF: AMM 35-20-01-900-801	AFL		TSR:0			872		
35-20-09-900-801-01	NO. 1 PASSENGER OXYGEN MASK								
35.100	289-601-228	MOS		TSN:0			04-FEB-2011		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			1541.42		
	REF:	AFL		TSN:0			872		
35-20-09-900-801-02	NO. 2 PASSENGER OXYGEN MASK								
35.100	289-601-228	MOS		TSN:0			22-AUG-2016		
	NSN	HRS/MSC	O/C	TSN:0			2978		
	REF:	AFL		TSN:0			1794		
35-20-09-900-801-03	NO. 3 PASSENGER OXYGEN MASK								
35.110	289-601-228	MOS		TSN:0			22-AUG-2016		
	NSN	HRS/MSC	O/C	TSN:0			2978		
	REF:	AFL		TSN:0			1794		
35-20-09-900-801-04	NO. 4 PASSENGER OXYGEN MASK								
35.110	289-601-228	MOS		TSN:0			22-AUG-2016		
	NSN	HRS/MSC	O/C	TSN:0			2978		
	REF:	AFL		TSN:0			1794		
35-20-09-900-801-05	NO. 5 PASSENGER OXYGEN MASK								
35.120	289-601-228	MOS		TSN:0			22-AUG-2016		
	NSN	HRS/MSC	O/C	TSN:0			2978		
	REF:	AFL		TSN:0			1794		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-06	NO. 6 PASSENGER OXYGEN MASK								
35.120	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
35-20-09-900-801-07	NO. 7 PASSENGER OXYGEN MASK								
35.130	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-OCT-2015 2761.8 1696		
35-20-09-900-801-08	NO. 8 PASSENGER OXYGEN MASK								
35.130	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
35-20-09-900-801-09	NO. 9 PASSENGER OXYGEN MASK								
35.140	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
35-20-09-900-801-10	NO. 10 PASSENGER OXYGEN MASK								
35.140	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
35-20-09-900-801-11	NO. 11 PASSENGER OXYGEN MASK								
35.150	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-2007 0 0		
35-20-09-900-801-12	NO. 12 PASSENGER OXYGEN MASK								
35.150	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-13	NO. 13 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JAN-2006 0 0		
35-20-09-900-801-14	NO. 14 PASSENGER OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
35-20-09-900-801-15	NO. 15 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JAN-2006 0 0		
35-20-09-900-801-16	NO. 16 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:53 TSN:1265.33 TSN:706			04-JUN-2010 1265.33 706		
35-20-09-900-801-17	NO. 17 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2006 0 0		
35-20-09-900-801-18	NO. 18 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2006 0 0		
35-20-09-900-801-19	NO. 19 PASSENGER OXYGEN MASK 289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-05-210-801-01 (s)	INSPECTION OF THE RISLAN TUBE ASSEMBLY PKG 21	MOS					PKG 15-JUN-2017		
SMM	REF: AMM 35-21-05-210-801	HRS/MSC AFL	1600	+40			3125.5 1867		
35-30-01-960-801-01	DISCARD PILOT PROTECTIVE BREATHING EQUIPMENT HOOD 802300-14	MOS	120				21-JUN-2016	21-JUN-2026	
35.210	E15040241	HRS/MSC AFL							
LIFE LIMIT	REF: AMM 35-30-01-960-801								
35-30-01-960-801-02	DISCARD COPILOT PROTECTIVE BREATHING EQUIPMENT HOOD PN	MOS							
35.210	NOT INSTALLED	HRS/MSC AFL	N/A						
	REF: AMM 35-30-01-960-801								
35-30-05-210-801-01	GENERAL VISUAL INSPECTION PORTABLE OXYGEN CYLINDER (INCLUDING MASKS) 894-20330	MOS	12	+3%			14-JUN-2019	14-JUN-2020	24-JUN-2020
35.220	P06060287	HRS/MSC AFL					3636.3 2081		
	REF: AMM 35-30-05-210-801								
+ 35-30-05-350-801-01	RESTORATION PORTABLE OXYGEN CYLINDER (OVERHAUL) (INCLUDING MASKS) 894-20330	MOS	60	+3%			12-JUL-2016	12-JUL-2021	05-SEP-2021
35.220	P06060287	HRS/MSC AFL							
OVERHAUL	REF: AMM 35-30-05-350-801								
35-30-05-900-801-01	PORTABLE OXYGEN CYLINDER 894-20330	MOS			TSN:123 TSO:1		18-AUG-2016		
35.220	P06060287	HRS/MSC AFL	H/T		TSO:0 TSO:0		2978 1794		
	REF: GENERIC NO REF								
35-30-09-100-801-01	CLEANING OF PORTABLE OXYGEN CYLINDER MASKS 894-20330	MOS	12	+3%			14-JUN-2019	14-JUN-2020	24-JUN-2020
35.220	P06060287	HRS/MSC AFL					3636.3 2081		
	REF: AMM 35-30-09-100-801								

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-40-01-720-801-01	FUNCTIONAL TEST OF THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY 176219-115 1682-17808 REF:	MOS HRS/MSC AFL	60					05-DEC-2019 M	
35-40-01-790-801-01 35.010	HYDROSTATIC TEST OXYGEN CYLINDER 176219-115 1682-17808 REF: AMM 35-40-01-790-801	MOS HRS/MSC AFL	O/C				05-DEC-2014		
35-40-01-900-801-01 35.010	OXYGEN CYLINDER 176219-115 1682-17808 REF: AMM 35-40-01-900-801	MOS HRS/MSC AFL	H/T				05-DEC-2014 2464.4 1569		
35-40-01-960-801-01 35.010 LIFE LIMIT	DISCARD OXYGEN CYLINDER 176219-115 1682-17808 REF: AMM 35-40-01-960-801	MOS HRS/MSC AFL	180				28-FEB-2007	28-FEB-2022	
35-40-05-720-801-01 35.010	FUNCTIONAL TEST OXYGEN CYLINDER PRESSURE REDUCE VALVE 176219-115 1682-17808 REF: AMM 35-40-05-720-801	MOS HRS/MSC AFL	O/C				05-DEC-2014		
350801 35.020	HP PRESSURE CYLINDER GAUGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	19-OCT-2007 0 0	
351801 35.070	PILOT OXYGEN MASK HOSE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	19-OCT-2007 0 0	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351806	COPILOT OXYGEN MASK HOSE								
35.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
351811	PILOT OXYGEN COUPLING								
35.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
351812	COPILOT OXYGEN COUPLING								
35.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
352831	NO. 1 THERAPEUTIC MASK								
35.200	289-601-228 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2006 0 0		
352832	NO. 2 THERAPEUTIC MASK								
35.200	289-601-228 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2006 0 0		
352A15	NO. 20 PASSENGER OXYGEN MASK								
	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
352A16	NO. 21 PASSENGER OXYGEN MASK								
	289-601-228 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352A17	NO. 22 PASSENGER OXYGEN MASK 289-601-228 N/A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2016 2978 1794		
353801	PILOT PROTECTIVE BREATHING EQUIPMENT HOOD 802300-14 E15040241 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			21-JUN-2016 2938.3 1769	13-JUN-2026 M	
353802	COPILOT PROTECTIVE BREATHING EQUIPMENT HOOD PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T						
CHAPTER 36 PNEUMATIC									
+ 36-00-01-710-802-01 (s)	OPERATIONAL TEST OF ARINC LINK BETWEEN BASC AND MAU PKG 24 REF: AMM 36-00-01-710-802	MOS HRS/MSC AFL	6400	+40			PKG 19-OCT-2007 0 0		
36-00-01-710-802-01A	OPERATIONAL TEST OF ARINC LINK BETWEEN BASC AND MAU (MANDATORY 5-40) REF: AMM 36-00-01-710-802	MOS HRS/MSC AFL	9000				19-OCT-2007 0 0	9000	
36-00-05-900-801-01	AUTOMATIC BLEED OVERRIDE (ABOC) CONTROLLER 733702-1-2 00145 REF: AMM 36-00-05-900-801	MOS HRS/MSC AFL	O/C				11-FEB-2011 1541.42 872		
36-10-02-900-801-01	NO. 1 ENGINE HIGH PRESSURE BLEED AIR ELECTRIC VALVE 6038A040002 01100 REF: AMM 36-10-02-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			23-SEP-2015 2756.1 1690		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-10-02-900-801-02	NO. 2 ENGINE HIGH PRESSURE BLEED AIR ELECTRIC VALVE 6038A030002 01143 REF: AMM 36-10-02-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
36-10-02-900-801-03	NO. 3 ENGINE HIGH PRESSURE BLEED AIR ELECTRIC VALVE 6038A030002 01184 REF: AMM 36-10-02-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
36-10-33-350-801-01	RESTORATION NO. 1 ENGINE BLEED AIR ARTICULATED PIPE (OVERHAUL) PN SN-UNKNOWN REF: AMM 36-10-33-350-801	MOS HRS/MSC AFL	5000	+3%			19-OCT-2007 0 0	5000	5150
36-10-33-350-801-02	RESTORATION NO. 3 ENGINE BLEED AIR ARTICULATED PIPE (OVERHAUL) PN SN-UNKNOWN REF: AMM 36-10-33-350-801	MOS HRS/MSC AFL	5000	+3%			19-OCT-2007 0 0	5000	5150
361801	LEFT OZONE CONVERTER 20425-1 6523 REF: AMM 21-71-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
361802	RIGHT OZONE CONVERTER 20425-1 6522 REF: AMM 21-71-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
361806	BLEED AIR SYSTEM COMPUTER 92138C030800 00533 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-FEB-2011 1541.42 872		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361811	NO. 1 ENGINE BLEED AIR ARTICULATED PIPE								
36.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
361812	NO. 3 ENGINE BLEED AIR ARTICULATED PIPE								
36.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
362801	NO. 1 ENGINE TEMPERATURE PROBE								
36.040	RP482-00 DAAA00220 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
362802	NO. 2 ENGINE TEMPERATURE PROBE								
36.040	RP482-00 DAAA00221 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
362803	NO. 3 ENGINE TEMPERATURE PROBE								
36.040	RP482-00 DAAA00222 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
362806	WING HIGH/LOW PRESSURE TRANSMITTER								
36.050	ZRA233-01 3163 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-DEC-2013 2338.17 1508		
362811	S-DUCT HIGH/LOW PRESSURE TRANSMITTER								
36.060	ZRA233-01 1873 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

CHAPTER 38 WATER/WASTE

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-00-00-610-801-01 (s)	SERVICING OF THE WATER SUPPLY SYSTEM						PKG		
38.070	PKG 16 REF: AMM 38-00-00-610-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
38-10-00-210-801-01 (s)	DETAILED INSPECTION OF WATER SYSTEM COMPONENTS						PKG		
SMM	PKG 31 REF: AMM 38-10-00-210-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
38-10-00-670-801-01	STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION								
38.020	REF: AMM 38-10-00-670-801	MOS HRS/MSC AFL	6	+1m	-89		14-JUN-2019 3636.3 2081	17-SEP-2019	17-OCT-2019
38-11-01-250-801-01	INSPECT (EDDY CURRENT) WATER TANK FOR STRESS CRACKS								
	REF:	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
38-11-01-900-801-01	POTABLE WATER TANK								
	FGFB738500EQUEVC BATCH 110302036 REF:	MOS HRS/MSC AFL	O/C				01-FEB-2013 2161.42 1362		
38-13-01-960-801-01	REPLACEMENT OF THE MAIN FILTER CARTRIDGE								
	REF: AMM 38-13-01-960-801	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
38-13-09-900-801-01	FORWARD WATER HEATER								
	PN SN-UNKNOWN REF: AMM 38-13-09-900-802	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-13-55-710-801-01	OPERATIONAL TEST OF THE LAVATORY WATER SOLENOID/PAD REF: AMM 38-13-55-710-801	MOS HRS/MSC AFL	O/C				01-FEB-2013 2161.42 1362		
38-15-01-710-801-01	OPERATIONAL TEST OF THE AFT VANITY ULTRA-VIOLET (UV) STERILIZER REF: AMM 38-15-01-710-801	MOS HRS/MSC AFL	N/A				19-OCT-2007 0 0		
38-15-09-900-801-01	ULTRA-VIOLET (UV) LAMP PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	O/C						
38-15-09-960-801-01	REPLACEMENT ULTRA-VIOLET (UV) LAMP PN NOT INSTALLED REF: AMM 38-15-09-960-801	MOS HRS/MSC AFL	N/A						
38-15-17-100-801-01	CLEANING OF THE UV STERILIZER QUARTZ SLEEVE PKG 201 REF: AMM 38-15-17-100-801	MOS HRS/MSC AFL	N/A				PKG		
+ 38-30-00-710-801-01	OPERATIONAL TEST OF THE DRAIN MAST ANTI-ICING SYSTEMS 30.200 REF: AMM 38-30-00-710-801	MOS HRS/MSC AFL	O/C				11-FEB-2011 1541.42 872		
38-31-01-900-801-01	FRONT DRAIN MAST PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-34-17-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FORWARD TOILET DRAIN CONTROL PKG 17 REF: AMM 38-34-17-210-801	MOS HRS/MSC AFL	36	+1m			PKG 14-JUN-2019 3636.3 2081		
38-34-21-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE AFT TOILET DRAIN CONTROL PKG 17 REF: AMM 38-34-21-210-801	MOS HRS/MSC AFL	36	+1m			PKG 14-JUN-2019 3636.3 2081		
381801 38.030	POTABLE WATER TWO WAYS VALVE 879B14-13 F26971 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-DEC-2011 1835.58 1113		
381A10	WATER GALLEY HEATER 7700244-503 06-11-40092 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
381A12	FRONT DRAIN WATER MAST MAT-302706-A 999 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-NOV-2013 2320.42 1495		
381A13	DRAIN WATER AFT MAST MAT-200506 S1WS14 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
381A15	WATER (35MD) GAUGE 5050 KN795 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381A18	GALLEY WATER DRAIN VALVE F2M45303-505 M0295VD0609	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495	19-NOV-2019	5245
SMM	REF:		3750						
381F01	REPLACE GALLEY WATER FILTER	MOS HRS/MSC AFL	16 800				17-SEP-2018 3480.2 2027	17-JAN-2020 4280.2	
SMM	REF:								
382A01	FORWARD LAVATORY FAUCET CONTROL 4620-50 231	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
SMM	REF:								
383A05	AFT LAVATORY WATER DRAIN VALVE F2M45303-503 N/A	MOS HRS/MSC AFL	72 H/T	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495	19-NOV-2019	
SMM	REF:								
38GJL01	AFT TOILET DRAIN PLUG 2651-126C 16890426	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			06-NOV-2010 1449.92 818		
SMM	REF:								
CHAPTER 45	CENTRAL MAINT SYSTEM								
45-10-01-900-801-01	CENTRAL MAINTENANCE COMPUTER MODULE 7034055-1901 13073227	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-NOV-2013 2320.42 1495		
45.020	REF: AMM 45-10-01-900-801								
45-90-00-860-801-01B	LOAD BLUE CD-ROM DATA BASE UPDATE	MOS HRS/MSC AFL	DUE				06-SEP-2019 3683.9 2130	25-SEP-2019 M	
SMM	REF:								

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
45-90-00-860-801-01R	LOAD RED CD-ROM DATA BASE UPDATE	MOS					06-SEP-2019	09-OCT-2019 M	
	REF:	HRS/MSC AFL	DUE				3683.9 2130		
+ 45-92-00-700-801-01	CHECK SOFTWARE MODULES INTEGRITY	MOS					19-OCT-2007		
45.010	REF: GENERIC NO REF	HRS/MSC AFL	O/C				0 0		
45-92-00-700-801-02	INTEGRITY CHECK OF SOFTWARE IN AVIONICS MODULES - CHECK INDIVIDUAL MODULES	MOS					19-OCT-2007		
45.010	REF: GENERIC NO REF	HRS/MSC AFL	O/C				0 0		
CHAPTER 46 INFORMATION SYSTEMS									
46-20-02-720-801-01	FUNCTIONAL TEST LH ELECTRONIC DISPLAY (EDU) UNIT BATTERY	MOS					19-OCT-2007		
	PN NOT INSTALLED	HRS/MSC AFL	N/A				0 0		
	REF: AMM 46-20-02-720-801								
46-20-02-720-801-02	FUNCTIONAL TEST RH ELECTRONIC DISPLAY (EDU) UNIT BATTERY	MOS					19-OCT-2007		
	PN NOT INSTALLED	HRS/MSC AFL	N/A				0 0		
	REF: AMM 46-20-02-720-801								
46-90-03-900-801-01	LH ELECTRONIC DISPLAY (EDU) UNIT	MOS					19-OCT-2007		
	PN NOT INSTALLED	HRS/MSC AFL	O/C	TSN:0			0 0		
	REF: GENERIC NO REF			TSN:0					
46-90-03-900-801-02	RH ELECTRONIC DISPLAY (EDU) UNIT	MOS					19-OCT-2007		
	PN NOT INSTALLED	HRS/MSC AFL	O/C	TSN:0			0 0		
	REF: GENERIC NO REF			TSN:0					

CHAPTER 49 AIRBORNE AUXILIARY POWER

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
496301	APU T5 INDICATOR								
49.003	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C 0	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
496401	APU N1 TACHOMETER								
49.004	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C 0	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
49APU1	APU								
49.APU1	3800188-2 P-531 REF: AMM 49-10-01-900-802	MOS HRS/MSC AFL	E/C	TSN:1368			20-MAY-2011 1631.75 942		
APU Model : GTCP36-150(F) Serial # P-531 Part # 3800188-2									
491010	APU - TURBINE ROTOR								
LIFE LIMIT	3615880-1 060134510004 REF: GENERIC NO REF	MOS HRS/MSC APUS	10000	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		10000
491020	APU - COMPRESSOR ROTOR								
LIFE LIMIT	3822101-1 060350106455 REF: GENERIC NO REF	MOS HRS/MSC APUS	100000	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		100000
+ 491025	APU - VISUAL CHECK COMPRESSOR ROTOR								
	3822101-1 060350106455 REF: MM 49-20-00	MOS HRS/MSC APUS	4500				05-MAR-2014 2048		6548

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493010	APU - FUEL CONTROL								
49.030	3882730-9 31185 REF: GENERIC NO REF	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
493020	APU - REMOVE AND REPLACE FUEL CONTROL FUEL FILTER ELEMENT								
	3882730-9 31185 REF: MM 49-30-52	MOS HRS/MSC APUS	1000				14-JUN-2019 3180	4180	
493030	APU - ORIFICE FITTING								
	PN SN-UNKNOWN REF: MM 49-30-56	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
493040	APU - FUEL SHUTOFF VALVE								
	109844-1 472 REF: MM 49-30-54	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
+ 493050	APU - CHECK FUEL NOZZLE FLOW RATE								
	REF: MM 49-20-00	MOS HRS/MSC APUS	4500				10-AUG-2006 0 0	4500	
493060	APU - CONTROLLER								
	2118306-3 26-540 REF: MM 49-60-46	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
493070	APU - LOAD CONTROL VALVE								
	109812-10 3831 REF: MM 49-50-33	MOS HRS/MSC APUS	O/C	TSO:30 TSO:0 TSO:0			10-OCT-2017 2967		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494010	APU - IGNITION UNIT 3888000-2 060218071272 REF: MM 49-40-32	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
494020	APU - IGNITOR PLUG 3888002-2 NSN REF: MM 49-40-33	MOS HRS/MSC APUS	O/C				01-FEB-2013 1867 0		
+ 494030	APU - INSPECT/CLEAN IGNITOR PLUG 3888002-2 NSN REF: MM 49-40-33	MOS HRS/MSC APUS	750				10-NOV-2017 2989	3739	
497010	APU - MOTION PICK UP TRANSDUCER PN SN-UNKNOWN REF: MM 49-60-43	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
497020	APU - IMMERSION THERMOCOUPLE PN SN-UNKNOWN REF: MM 49-60-45	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
497030	APU - HOURMETER PN SN-UNKNOWN REF: MM 49-70-41	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		
499010	APU - ROTARY OIL PUMP PN SN-UNKNOWN REF: MM 49-90-51	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			10-AUG-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 499020	APU - REMOVE AND INSPECT	MAGNETIC DRAIN PLUG							
		MOS	17				11-JUN-2018	11-NOV-2019	
		HRS/MSC	750				3118	3868	
	REF: MM 49-90-46	APUS							
499030 (s)	APU - DRAIN AND REFILL OIL								
		MOS					26-APR-2011		
		HRS/MSC	O/C				1367		
	REF: MM 49-20-00	APUS							
499040	APU - REMOVE AND REPLACE	OIL FILTER ELEMENT							
		MOS					11-JUN-2018		
		HRS/MSC	500				3118	3618	
	REF: MM 49-90-47	APUS							
499050	APU - PRESSURE REGULATING VALVE								
	PN	MOS		TSN:0			10-AUG-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: MM 49-90-52	APUS		TSN:0			0		
499060	APU - HIGH OIL TEMPERATURE SWITCH								
	3888030-1	MOS					26-APR-2011		
	NSN	HRS/MSC	O/C				1367		
	REF: MM 49-60-46	APUS							
499070	APU - LOW OIL PRESSURE SWITCH								
	3876001-8	MOS					26-APR-2011		
	07915	HRS/MSC	O/C				1367		
	REF: MM 49-60-43	APUS							
+ 499110	APU - SOAP CHECK OIL								
		MOS					17-SEP-2018		
		HRS/MSC	500				3225	3725	
	REF: SIL SIL APU-49	APUS							

CHAPTER 51 STD PRACTICES AND STRUCT-GENRL

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 51-00-00-200-801-01 (s)	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 12M OR 800FH INSPECTION						PKG		
	PKG 5	MOS	12	+1m			14-JUN-2019		
	REF:	HRS/MSC	800	+40			3636.3		
		AFL					2081		
+ 51-00-00-200-802-01 (s)	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 24M OR 1600FH INSPECTION						PKG		
	PKG 6	MOS	24	+1m			14-JUN-2019		
	REF:	HRS/MSC	1600	+40			3636.3		
		AFL					2081		
+ 51-00-00-200-803-01 (s)	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 1C INSPECTION						PKG		
	PKG 31	MOS	72	+2m			19-OCT-2007		
	REF:	HRS/MSC					0		
		AFL	3750				0		
CHAPTER 52 DOORS									
+ 52-00-00-200-801-01 (s)	INSPECTION/CHECK OF THE PASSENGER DOORS SEALS						PKG		
53.120	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 52-00-00-200-801	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 52-00-00-200-801-02 (s)	INSPECTION/CHECK OF THE BAGGAGE COMPARTMENT DOORS SEALS						PKG		
53.120	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 52-00-00-200-801	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 52-00-00-200-801-03 (s)	INSPECTION/CHECK OF THE SERVICING COMPARTMENT DOORS SEALS						PKG		
53.120	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 52-00-00-200-801	HRS/MSC					2320.42		
		AFL	3750				1495		
52-00-00-640-801-01 (s)	LUBRICATION OF SERVICE DOORS						PKG		
52.010	PKG 15	MOS	12	+1m			14-JUN-2019		
	REF: AMM 52-00-00-640-801	HRS/MSC					3636.3		
		AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-00-610-801-01	SERVICING OF THE PASSENGER DOOR								
52.020	PKG 17 REF: AMM 52-10-00-610-801	MOS HRS/MSC AFL	36	+1m			14-JUN-2019 3636.3 2081	14-JUN-2022	14-JUL-2022
+ 52-10-00-610-802-01 (s)	SERVICING OF THE PASSENGER DOOR SAFETY CATCH						PKG 14-JUN-2019 3636.3 2081		
52-10-00-610-802-01 (s)	PKG 17 REF: AMM 52-10-00-610-802	MOS HRS/MSC AFL	36	+1m					
52-10-00-640-801-01 (s)	LUBRICATION OF THE PASSENGER DOOR LOWER MECHANISM ROLLERS						PKG 19-OCT-2007 0 0		
52.020	PKG 32 REF: AMM 52-10-00-640-801	MOS HRS/MSC AFL	144	+2m					
+ 52-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER DOOR MECHANISM						PKG 19-NOV-2013 2320.42 1495		
52-10-00-720-801-01 (s)	PKG 31 REF: AMM 52-10-00-720-801	MOS HRS/MSC AFL	72	+2m					
52-10-01-900-801-01	PASSENGER DOOR						19-OCT-2007 0 0		
52.020	PN SN-UNKNOWN REF: AMM 52-10-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0				
52-10-03-900-801-01	PASSENGER DOOR PNEUMATIC ACTUATOR						18-AUG-2016 2965.9 1786		
52.150	222900-1M03 2610 REF: AMM 52-10-03-900-801	MOS HRS/MSC AFL	H/T		TSN:0 TSN:0 TSN:0				
52-10-03-960-801-01	DISCARD PASSENGER DOOR PNEUMATIC ACTUATOR						08-JUN-2016	08-JUN-2021	
52.150	222900-1M03 2610 REF: AMM 52-10-03-960-801	MOS HRS/MSC AFL	60						
LIFE LIMIT									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-09-900-801-01	PASSENGER DOOR REDUCING GEAR MOTOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
52-20-00-610-801-01 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN PKG 16 REF: AMM 52-20-00-610-801	MOS HRS/MSC AFL	24				14-JUN-2019 3636.3 2081		
52-20-00-610-801-01A	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40) 52.040 CMR REF: AMM 52-20-00-610-801	MOS HRS/MSC AFL	24				14-JUN-2019 3636.3 2081	14-JUN-2021	
+ 52-20-00-610-801-02 (s)	SERVICING OF THE EMERGENCY EXIT DOOR PKG 16 REF: AMM 52-20-00-610-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 52-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT FROM OUTSIDE PKG 21 REF: AMM 52-20-00-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
52-20-01-900-801-01	EMERGENCY EXIT F10A293001059 SN-UNKNOWN REF: AMM 52-20-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-APR-2015 2591.7 1611		
52-30-00-610-801-01 (s)	SERVICING OF THE BAGGAGE COMPARTMENT DOOR PKG 21 REF: AMM 52-30-00-610-801	MOS HRS/MSC AFL	1600	+40			19-MAY-2017 3080 1850		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-30-00-710-801-01 (s)	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM						PKG		
52.060	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 52-30-00-710-801	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 52-30-00-710-801-01A	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM (MANDATORY 5-40)								
52.060		MOS					19-NOV-2013		
CMR	REF: AMM 52-30-00-710-801	HRS/MSC	8000				2320.42		10320.42
		AFL					1495		
52-30-01-900-801-01	BAGGAGE COMPARTMENT DOOR								
52.050	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 52-30-01-900-801	AFL					0		
52-40-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE ACCESS PANELS AND DOORS						PKG		
52.090	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 52-40-00-210-801	HRS/MSC					3636.3		
		AFL					2081		
52-41-07-610-801-01 (s)	SERVICING OF NOSE LANDING GEAR (NLG) WELL CEILING DOOR						PKG		
52.100	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 52-41-07-610-801	HRS/MSC					3636.3		
		AFL					2081		
52-50-00-710-801-01 (s)	INSPECTION/TEST OF THE BLOWOUT DOORS/PANELS						PKG		
52.155	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 52-50-00-710-801	HRS/MSC					2320.42		
		AFL	3750				1495		
52-53-00-610-801-01 (s)	SERVICING OF THE CABIN / BAGGAGE COMPARTMENT DOOR						PKG		
52.110	PKG 17	MOS	36	+1m			14-JUN-2019		
	REF: AMM 52-53-00-610-801	HRS/MSC					3636.3		
		AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-54-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF CABIN DOORS, DIVDERS AND BULKHEADS PKG 31	MOS	72	+2m			PKG 19-NOV-2013 2320.42		
SMM	REF: AMM 52-54-00-210-801	HRS/MSC AFL	3750				1495		
52-54-05-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR - INSPECTION OF THE GALLEY POCKET SLIDING DOOR PKG 31	MOS	72	+2m			PKG 19-MAY-2017 3080		
	REF: AMM 52-54-05-210-801	HRS/MSC AFL	3750				1850		
52-54-05-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR - INSPECTION OF MOUNTING LOCATIONS, LAMINATE AND MECHANISM PKG 31	MOS	72	+2m			PKG 19-NOV-2013 2320.42		
	REF: AMM 52-54-05-210-801	HRS/MSC AFL	3750				1495		
52-55-00-610-801-01 (s)	SERVICING OF THE S-DUCT DOOR PKG 16	MOS	24	+1m			PKG 14-JUN-2019 3636.3		
52.120	REF: AMM 52-55-00-610-801	HRS/MSC AFL					2081		
52-60-09-610-801-01 (s)	SERVICE OF THE MECHANIC'S SERVICING COMPARTMENT (MSD) DOOR PKG 17	MOS	36	+1m			PKG 14-JUN-2019 3636.3		
52.080	REF: AMM 52-60-09-610-801	HRS/MSC AFL					2081		
+ 52-70-00-710-802-01 (s)	OPERATIONAL TEST OF THE PASSENGER DOOR INDICATING SYSTEM PKG 6,203	MOS	24	+1m			PKG 14-JUN-2019 3636.3		
52.130	REF: AMM 52-70-00-710-802	HRS/MSC AFL	1600	+40			2081		
+ 52-70-00-710-802-02 (s)	OPERATIONAL TEST OF THE ENGINE S-DUCT INSPECTION DOOR INDICATING SYSTEM PKG 17,203	MOS	24	+1m			PKG 14-JUN-2019 3636.3		
52.130	REF: AMM 52-70-00-710-802	HRS/MSC AFL	1600	+40			2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-70-00-710-802-03 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6,203	MOS	24	+1m			14-JUN-2019		
	REF: AMM 52-70-00-710-802	HRS/MSC	1600	+40			3636.3		
		AFL					2081		
+ 52-70-00-710-802-04 (s)	TEST OF SERVICING COMPARTMENT DOOR INDICATIONS						PKG		
52.130	PKG 6,203	MOS	24	+1m			14-JUN-2019		
	REF: AMM 52-70-00-710-802	HRS/MSC	1600	+40			3636.3		
		AFL					2081		
+ 52-70-00-710-802-05 (s)	OPERATIONAL TEST OF THE FORWARD TOILET SERVICING DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6,203	MOS	24	+1m			14-JUN-2019		
	REF: AMM 52-70-00-710-802	HRS/MSC	1600	+40			3636.3		
		AFL					2081		
+ 52-70-00-710-802-06 (s)	OPERATIONAL TEST OF THE CABIN/ BAGGAGE COMPARTMENT COMMUNICATION DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6,203	MOS	24	+1m			14-JUN-2019		
	REF: AMM 52-70-00-710-802	HRS/MSC	1600	+40			3636.3		
		AFL					2081		
521051	PASSENGER DOOR COMPENSATION ACTUATOR								
52.030	PN	MOS				TSN:0	19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0		
	REF: GENERIC NO REF	AFL				TSN:0	0		
523801	BAGGAGE COMPARTMENT DOOR REDUCER MOTOR								
52.070	4220-5	MOS				TSR:8	01-FEB-2019		
	559	HRS/MSC	O/C			TSN:9727 TSR:0	3549.1		
	REF: GENERIC NO REF	AFL				TSN:4215 TSR:0	2057		
524801	MECHANIC'S SERVICING COMPARTMENT (MSD) DOOR								
52.080	PN	MOS				TSN:0	19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0		
	REF: GENERIC NO REF	AFL				TSN:0	0		

CHAPTER 53 FUSELAGE

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00-00-200-803-01	INSPECTION OF THE FUSELAGE SKIN -FRAME 4 TO FRAME 30								
53.150		MOS					19-OCT-2007		
	REF: AMM 53-00-00-200-803	HRS/MSC					0		
		AFL	11250				0		11250
+ 53-00-00-200-803-01A	INSPECTION OF THE FUSELAGE SKIN -FRAME 4 TO FRAME 30 (MANDATORY REF. 5-40-10)								
53.150		MOS					19-OCT-2007		
FD	REF: AMM 53-00-00-200-803	HRS/MSC					0		
		AFL	11250				0		11250
53-00-00-200-803-02	DETAILED INSPECTION IN SPECIFIC AREAS OF FUSELAGE SKIN- FROM FRAME 4 TO FRAME 30								
53.310		MOS					19-OCT-2007		
	REF: AMM 53-00-00-200-803	HRS/MSC					0		
		AFL	11250				0		11250
53-00-00-200-803-02A	DETAILED INSPECTION IN SPECIFIC AREAS OF FUSELAGE SKIN- FROM FRAME 4 TO FRAME 30 (MANDATORY REF. 5-40-10)								
53.310		MOS					19-OCT-2007		
FD	REF: AMM 53-00-00-200-803	HRS/MSC					0		
		AFL	11250				0		11250
+ 53-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION						PKG		
53.010	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 53-00-00-210-801	HRS/MSC					3636.3		
		AFL					2081		
53-00-00-210-801-01C (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION (CPCP)								
		MOS	25				14-JUN-2019		
CPCP	REF: AMM 53-00-00-210-801	HRS/MSC					3636.3		
		AFL					2081		
53-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION						PKG		
53.300	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 53-00-00-220-801	HRS/MSC					2320.42		
		AFL	3750				1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00-00-220-801-01C (s)	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION (CPCP)	MOS	74				19-OCT-2007		
CPCP	REF: AMM 53-00-00-220-801	HRS/MSC AFL					0 0		
+ 53-10-00-200-808-01 (s)	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY	MOS	12	+1m			14-JUN-2019		
53.110	PKG 15 REF: AMM 53-10-00-200-808	HRS/MSC AFL					3636.3 2081		
53-10-00-200-808-01C (s)	INSPECTION OF THE NOSE LANDING GEAR (NLG) (CPCP)	MOS	13				14-JUN-2019		
CPCP	REF: AMM 53-10-00-200-808	HRS/MSC AFL					3636.3 2081		
+ 53-10-00-200-810-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN -FRAME 0 TO FRAME 4	MOS					19-OCT-2007		
53.140	REF: AMM 53-10-00-200-810	HRS/MSC AFL	7500				0 0		7500
+ 53-10-00-200-810-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN -FRAME 0 TO FRAME 4 (MANDATORY REF. 5-40-10)	MOS					19-OCT-2007		
53.140	REF: AMM 53-10-00-200-810	HRS/MSC AFL	7500				0 0		7500
53-10-00-200-810-02	DETAILED INSPECTION IN SPECIFIC AREAS OF THE FUSELAGE SKIN -FRAME 0 TO FRAME 4	MOS					19-OCT-2007		
53.305	REF: AMM 53-10-00-200-810	HRS/MSC AFL	11250				0 0		11250
53-10-00-200-810-02A	DETAILED INSPECTION IN SPECIFIC AREAS OF THE FUSELAGE SKIN -FRAME 0 TO FRAME 4 (MANDATORY REF. 5-40-10)	MOS					19-OCT-2007		
53.305	REF: AMM 53-10-00-200-810	HRS/MSC AFL	11250				0 0		11250

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT						PKG		
53.0301	PKG 16 REF: AMM 53-10-00-210-802	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 53-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE STATIC PRESSURE PROBES AND OF THE FUSELAGE SKIN IN THE PROBE AREAS						PKG		
53.280 RVSM	PKG 16 REF: AMM 53-10-00-220-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 53-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT						PKG		
53.0302	PKG 31 REF: AMM 53-10-00-220-802	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
53-10-00-220-802-01C (s)	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)								
CPCP	REF: AMM 53-10-00-220-802	MOS HRS/MSC AFL	74				19-NOV-2013 2320.42 1495		
+ 53-10-01-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE FRAME 0 STIFFENER TIP						PKG		
53.190	PKG 32 REF: AMM 53-10-01-250-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
+ 53-10-03-220-801-03 (s)	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS - DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS						PKG		
	PKG 32 REF: AMM 53-10-03-220-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-03-220-801-03C (s)	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS - DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)								
		MOS	148				19-OCT-2007		
		HRS/MSC					0		
CPCP	REF: AMM 53-10-03-220-801	AFL					0		
+ 53-10-03-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING						PKG		
	PKG 33	MOS	216	+2m			19-OCT-2007		
53.180		HRS/MSC					0		
	REF: AMM 53-10-03-250-801	AFL	11250				0		
+ 53-10-03-250-801-01A	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING (MANDATORY REF. 5-40-10)								
		MOS					19-OCT-2007		
53.180		HRS/MSC					0		
FD	REF: AMM 53-10-03-250-801	AFL	11250				0		11250
+ 53-10-11-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE SPLICE AT FRAME 11						PKG		
	PKG 33	MOS	216	+2m			19-OCT-2007		
53.295		HRS/MSC					0		
	REF: AMM 53-10-11-250-801	AFL	11250				0		
53-10-11-250-801-01A	SPECIAL DETAILED INSPECTION OF THE SPLICE AT FRAME 11 (MANDATORY 5-40)								
		MOS					19-OCT-2007		
53.295		HRS/MSC					0		
FD	REF: AMM 53-10-11-250-801	AFL	11250				0		11250
+ 53-10-39-220-801-01 (s)	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES						PKG		
	PKG 31	MOS	72	+2m			19-NOV-2013		
53.220		HRS/MSC					2320.42		
	REF: AMM 53-10-39-220-801	AFL	3750				1495		
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (CPCP)								
		MOS	74				19-NOV-2013		19-JAN-2020
		HRS/MSC					2320.42		
CPCP	REF: AMM 53-10-39-220-801	AFL					1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-39-220-802-01 (s)	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						PKG		
53.260	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF: AMM 53-10-39-220-802	HRS/MSC					0		
		AFL	7500				0		
53-10-39-220-802-01C (s)	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (CPCP)								
CPCP	REF: AMM 53-10-39-220-802	MOS	148				19-OCT-2007		
		HRS/MSC					0		
		AFL					0		
+ 53-11-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA						PKG		
53.0201	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 53-11-00-210-801	HRS/MSC					3636.3		
		AFL					2081		
53-11-00-210-801-01C (s)	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)								
CPCP	REF: AMM 53-11-00-210-801	MOS	25				14-JUN-2019		
		HRS/MSC					3636.3		
		AFL					2081		
+ 53-11-00-760-801-01 (s)	CHECK OF THE NOSE CONE ELECTRICAL BONDING						PKG		
53.265	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 53-11-00-760-801	HRS/MSC					3636.3		
		AFL					2081		
53-11-01-900-801-01	NOSE CONE								
53.210	PN	MOS				TSN:0	19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0		
	REF: See Workcard	AFL				TSN:0	0		
53-11-21-960-801-01	REPLACEMENT OF THE NOSE CONE SEAL								
53.290	PKG 31	MOS					19-NOV-2013		
	REF: AMM 53-11-21-960-801	HRS/MSC					2320.42		
		AFL	7500				1495		8995

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN						PKG		
53.0401	PKG 16 REF: AMM 53-30-00-210-802	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 53-30-00-220-801-01 (s)	DETAILED INSPECTION 2 OF THE PASSENGER CABIN UNDER THE FLOOR						PKG		
53.0402	PKG 31 REF: AMM 53-30-00-220-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
53-30-00-220-801-01C (s)	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR (CPCP)								
CPCP	REF: AMM 53-30-00-220-801	MOS HRS/MSC AFL	74				19-NOV-2013 2320.42 1495		
+ 53-30-00-220-807-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN ABOVE THE FLOOR						PKG		
53.0402	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
+ 53-30-00-250-801-01 (s)	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES						PKG		
53.170	PKG 31 REF: AMM 53-30-00-250-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
+ 53-30-00-250-801-01A	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES (MANDATORY 5-40)								
53.170	REF: AMM 53-30-00-250-801	MOS HRS/MSC AFL	3750				19-NOV-2013 2320.42 1495	5245	
+ 53-30-00-250-802-01 (s)	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS						PKG		
53.160	PKG 32 REF: AMM 53-30-00-250-802	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-00-250-802-01A	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS (MANDATORY REF. 5-40-10)								
53.160		MOS					19-OCT-2007		
FD	REF: AMM 53-30-00-250-802	HRS/MSC AFL	7500				0 0		7500
+ 53-40-00-200-804-01 (s)	INSPECTION OF THE LEFT MAIN LANDING GEAR (MLG) BAYS						PKG		
53.100	PKG 15	MOS	12	+1m			14-JUN-2019		
	REF: AMM 53-40-00-200-804	HRS/MSC AFL					3636.3 2081		
53-40-00-200-804-01C (s)	INSPECTION OF THE LEFT MAIN LANDING GEAR (MLG) BAYS (CPCP)								
		MOS	13				14-JUN-2019		
CPCP	REF: AMM 53-40-00-200-804	HRS/MSC AFL					3636.3 2081		
+ 53-40-00-200-804-02 (s)	INSPECTION OF THE RIGHT MAIN LANDING GEAR (MLG) BAYS						PKG		
53.100	PKG 15	MOS	12	+1m			14-JUN-2019		
	REF: AMM 53-40-00-200-804	HRS/MSC AFL					3636.3 2081		
53-40-00-200-804-02C (s)	INSPECTION OF THE RIGHT MAIN LANDING GEAR (MLG) BAYS (CPCP)								
		MOS	13				14-JUN-2019		
CPCP	REF: AMM 53-40-00-200-804	HRS/MSC AFL					3636.3 2081		
+ 53-40-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS						PKG		
53.0601	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 53-40-00-210-802	HRS/MSC AFL					3636.3 2081		
53-40-00-210-802-01C (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)								
		MOS	25				14-JUN-2019		
CPCP	REF: AMM 53-40-00-210-802	HRS/MSC AFL					3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-40-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS						PKG		
53.0602	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 53-40-00-220-801	HRS/MSC					2320.42		
		AFL	3750				1495		
53-40-00-220-801-01C (s)	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)								
CPCP	REF: AMM 53-40-00-220-801	MOS	74				19-NOV-2013		
		HRS/MSC					2320.42		
		AFL					1495		
+ 53-40-00-220-802-01 (s)	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS						PKG		
53.050	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 53-40-00-220-802	HRS/MSC					2320.42		
		AFL	3750				1495		
53-40-00-220-802-01C (s)	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)								
CPCP	REF: AMM 53-40-00-220-802	MOS	74				19-NOV-2013		
		HRS/MSC					2320.42		
		AFL					1495		
+ 53-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE LH WING UPPER WING ROOT BOLT RECESSES						PKG		
57.040	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 53-41-00-220-801	HRS/MSC					3636.3		
		AFL					2081		
53-41-00-220-801-01C (s)	DETAILED INSPECTION OF THE UPPER LH WING ROOT BOLT RECESSES (CPCP)								
CPCP	REF: AMM 53-41-00-220-801	MOS	25				14-JUN-2019		
		HRS/MSC					3636.3		
		AFL					2081		
+ 53-41-00-220-801-02 (s)	DETAILED INSPECTION OF THE RH WING UPPER WING ROOT BOLT RECESSES						PKG		
57.040	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 53-41-00-220-801	HRS/MSC					3636.3		
		AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-220-801-02C (s)	DETAILED INSPECTION OF THE UPPER RH WING ROOT BOLT RECESSES (CPCP)	MOS	25				14-JUN-2019		
CPCP	REF: AMM 53-41-00-220-801	HRS/MSC AFL					3636.3 2081		
+ 53-41-00-220-802-01 (s)	DETAILED INSPECTION OF THE LH WING - LOWER ROOT BOLT RECESSES	MOS	72	+2m			19-NOV-2013		
53.130	PKG 31	HRS/MSC AFL	3750				2320.42 1495		
REF: AMM 53-41-00-220-802									
+ 53-41-00-220-802-01A	DETAILED INSPECTION OF THE LH WING - LOWER WING ROOT BOLT RECESSES (MANDATORY REF. 5-40-10)	MOS					19-NOV-2013		
53.130		HRS/MSC AFL	7500				2320.42 1495		8995
FD	REF: AMM 53-41-00-220-802								
+ 53-41-00-220-802-02 (s)	DETAILED INSPECTION OF THE RH WING - LOWER ROOT BOLT RECESSES	MOS	72	+2m			19-NOV-2013		
	PKG 31	HRS/MSC AFL	3750				2320.42 1495		
REF: AMM 53-41-00-220-802									
+ 53-41-00-220-802-02A	DETAILED INSPECTION OF THE RH WING - LOWER ROOT BOLT RECESSES (MANDATORY REF. 5-40-10)	MOS					19-NOV-2013		
		HRS/MSC AFL	7500				2320.42 1495		8995
MANDATORY 5-40	REF: AMM 53-41-00-220-802								
53-41-00-620-802-01	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - UPPER LEFT WING ROOT BOLT RECESSES	MOS					19-NOV-2013		
57.050		HRS/MSC AFL	O/C				2320.42 1495		
REF: AMM 53-41-00-620-802									
53-41-00-620-802-02	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - UPPER RIGHT WING ROOT BOLT RECESSES	MOS					19-NOV-2013		
57.050		HRS/MSC AFL	O/C				2320.42 1495		
REF: AMM 53-41-00-620-802									

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-01-640-801-01 (s)	LUBRICATION OF THE LH WING TO FUSELAGE CONNECTING LINK ROD						PKG		
57.020	PKG 31	MOS	72	+2m			19-NOV-2013	2320.42	1495
	REF: AMM 53-41-01-640-801	HRS/MSC					2320.42		
		AFL	3750				1495		
53-41-01-640-801-02 (s)	LUBRICATION OF THE RH WING TO FUSELAGE CONNECTING LINK ROD						PKG		
57.020	PKG 31	MOS	72	+2m			19-NOV-2013	2320.42	1495
	REF: AMM 53-41-01-640-801	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 53-50-00-210-804-02 (s)	GENERAL VISUAL INSPECTION OF THE MECHANIC'S SERVICING COMPARTMENT						PKG		
53.0801	PKG 15	MOS	12	+1m			14-JUN-2019	3636.3	2081
	REF: AMM 53-50-00-210-804	HRS/MSC					3636.3		
		AFL					2081		
53-50-00-210-804-02C (s)	GENERAL VISUAL INSPECTION OF THE MECHANIC'S SERVICING COMPARTMENT (CPCP)						PKG		
CPCP		MOS	13				14-JUN-2019	3636.3	2081
	REF: AMM 53-50-00-210-804	HRS/MSC					3636.3		
		AFL					2081		
+ 53-50-00-210-806-01 (s)	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT						PKG		
53.0701	PKG 16	MOS	24	+1m			14-JUN-2019	3636.3	2081
	REF: AMM 53-50-00-210-806	HRS/MSC					3636.3		
		AFL					2081		
53-50-00-210-806-01C (s)	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)						PKG		
CPCP		MOS	25				14-JUN-2019	3636.3	2081
	REF: AMM 53-50-00-210-806	HRS/MSC					3636.3		
		AFL					2081		
+ 53-50-00-210-807-01 (s)	GENERAL VISUAL INSPECTION OF THE APU AREA						PKG		
53.090	PKG 15,202	MOS	12	+1m			14-JUN-2019	3636.3	2081
	REF: AMM 53-50-00-210-807	HRS/MSC					3636.3		
		AFL					2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-50-00-220-803-01 (s)	DETAILED INSPECTION 2 OF THE BAGGAGE COMPARTMENT						PKG		
53.0702	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 53-50-00-220-803	HRS/MSC					2320.42		
		AFL	3750				1495		
53-50-00-220-803-01A	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (MANDATORY 5-40)								
MANDATORY 5-40	REF: AMM 53-50-00-220-803	MOS					19-NOV-2013		
		HRS/MSC					2320.42		5245
		AFL	3750				1495		
53-50-00-220-803-01C (s)	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)								
CPCP	REF: AMM 53-50-00-220-803	MOS	74				19-NOV-2013		
		HRS/MSC					2320.42		
		AFL					1495		
+ 53-50-00-220-805-01 (s)	DETAILED INSPECTION/CHECK SERVICING COMPARTMENT						PKG		
53.0802	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 53-50-00-220-805	HRS/MSC					2320.42		
		AFL	3750				1495		
53-50-00-220-805-01C (s)	DETAILED INSPECTION OF THE MECHANIC'S SERVICING COMPARTMENT (CPCP)								
CPCP	REF: AMM 53-50-00-220-805	MOS	74				19-NOV-2013		
		HRS/MSC					2320.42		
		AFL					1495		
53-50-00-220-807-01	DETAILED INSPECTION OF THE FRAME 30 UPPER PART								
	REF: AMM 53-50-00-220-807	MOS					19-OCT-2007		
		HRS/MSC					0		5000
		AFL	5000				0		
53-50-00-220-807-01A	DETAILED INSPECTION OF THE FRAME 30 UPPER PART (MANDATORY 5-40)								
MANDATORY 5-40	REF: AMM 53-50-00-220-807	MOS					19-OCT-2007		
		HRS/MSC					0		5000
		AFL	5000				0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-50-30-250-802-01 (s)	EDDY CURRENT INSPECTION OF THE REAR EDGE OF BEAMS AT FRAME 30						PKG		
53.200	PKG 32	MOS	144	+2m			19-OCT-2007		
	REF: AMM 53-50-30-250-802	HRS/MSC					0		
		AFL	7500				0		
+ 53-60-00-760-801-01	CHECK OF THE FUSELAGE VENTRAL FAIRING ELECTRICAL BONDING								
53.270	PKG 17	MOS	36	+1m			14-JUN-2019	14-JUN-2022	14-JUL-2022
	REF: AMM 53-60-00-760-801	HRS/MSC					3636.3		
		AFL					2081		
+ 53-80-00-200-801-01 (s)	CHECK OF THE FUSELAGE CONDENSATION AND STREAM WATER DRAINS						PKG		
51.010	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 53-80-00-200-801	HRS/MSC					3636.3		
		AFL					2081		
53-80-01-710-801-01	OPERATIONAL TEST OF THE "AFT WATER LEAK" WATER DETECTION SYSTEM PCB								
	REF: AMM 53-80-01-710-801	MOS							
		HRS/MSC	N/A						
		AFL							
53-80-01-710-801-02	OPERATIONAL TEST OF THE "AFT WATER LEAK" WATER DETECTION SYSTEM SENSOR								
	REF: AMM 53-80-01-710-801	MOS					19-OCT-2007		
		HRS/MSC	N/A				0		
		AFL					0		
53-80-01-900-801-01	"AFT WATER LEAK" WATER DETECTION SYSTEM SENSOR								
	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 53-80-01-900-801	AFL					0		
							0		
+ 53-80-09-710-801-01 (s)	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS						PKG		
51.020	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 53-80-09-710-801	HRS/MSC					2320.42		
		AFL	3750				1495		

CHAPTER 54 NACELLES/PYLONS

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-00-00-210-810-01 (s)	GENERAL VISUAL INSPECTION OF THE NO.1 ENGINE NACELLE AND PYLON						PKG		
54.0102	PKG 5,201	MOS	12	+1m			14-JUN-2019		
	REF: AMM 54-00-00-210-810	HRS/MSC	800	+40			3636.3		
		AFL					2081		
+ 54-00-00-210-810-02 (s)	GENERAL VISUAL INSPECTION OF THE NO.3 ENGINE NACELLE AND PYLON						PKG		
54.0201	PKG 5,201	MOS	12	+1m			14-JUN-2019		
	REF: AMM 54-00-00-210-810	HRS/MSC	800	+40			3636.3		
		AFL					2081		
+ 54-00-00-210-811-01 (s)	GENERAL VISUAL INSPECTION OF THE NO.2 ENGINE NACELLE						PKG		
54.0301	PKG 5,201	MOS	12	+1m			14-JUN-2019		
	REF: AMM 54-00-00-210-811	HRS/MSC	800	+40			3636.3		
		AFL					2081		
+ 54-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE NO. 1 ENGINE NACELLE AND PYLON						PKG		
54.0105	PKG 32	MOS	144	+2m			15-APR-2015		
	REF: AMM 54-00-00-220-801	HRS/MSC					2591.7		
		AFL	7500				1611		
54-00-00-220-801-01C (s)	DETAILED INSPECTION OF THE NO. 1 ENGINE NACELLE AND PYLON (CPCP)								
CPCP		MOS	148				15-APR-2015		
	REF: AMM 54-00-00-220-801	HRS/MSC					2591.7		
		AFL					1611		
+ 54-00-00-220-801-02 (s)	DETAILED INSPECTION OF THE NO.3 ENGINE NACELLE AND PYLON						PKG		
54.0202	PKG 32	MOS	144	+2m			15-APR-2015		
	REF: AMM 54-00-00-220-801	HRS/MSC					2591.7		
		AFL	7500				1611		
54-00-00-220-801-02C (s)	DETAILED INSPECTION OF THE NO. 3 ENGINE NACELLE AND PYLON (CPCP)								
CPCP		MOS	148				15-APR-2015		
	REF: AMM 54-00-00-220-801	HRS/MSC					2591.7		
		AFL					1611		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-11-00-610-801-01 (s)	SERVICING OF THE NO. 1 ENGINE COWLINGS						PKG		
54.040	PKG 16 REF: AMM 54-11-00-610-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
54-11-00-610-801-02 (s)	SERVICING OF THE NO. 2 ENGINE COWLINGS						PKG		
54.040	PKG 16 REF: AMM 54-11-00-610-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
54-11-00-610-801-03	SERVICING OF THE NO. 3 ENGINE COWLINGS								
54.040	PKG 16 REF: AMM 54-11-00-610-801	MOS HRS/MSC AFL	24	+1m	-26		14-JUN-2019 3636.3 2081	19-MAY-2021	19-JUN-2021
+ 54-11-00-760-801-01 (s)	CHECK OF THE ENGINE COWLING ELECTRICAL BONDING						PKG		
54.075	PKG 16 REF: AMM 54-11-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
54-13-05-900-801	ENGINE #2 AFTER BODY								
	FGFB583D1 TR224SL231 REF:	MOS HRS/MSC AFL	O/C				28-APR-2012 1936.92 1187		
+ 54-42-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE NO. 2 ENGINE S-DUCT						PKG		
54.050	PKG 15 REF: AMM 54-42-00-210-801	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
CHAPTER 55		STABILIZERS							
+ 55-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT						PKG		
55.0101	PKG 16 REF: AMM 55-00-00-210-801	MOS HRS/MSC AFL	24 4000	+1m			14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-00-00-210-801-01C (s)	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF THE ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)	MOS	25				14-JUN-2019		
CPCP	REF: AMM 55-00-00-210-801	HRS/MSC AFL					3636.3 2081		
+ 55-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT						PKG		
55.0102	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 55-00-00-220-801	HRS/MSC AFL	3750				2320.42 1495		
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)	MOS	74				19-NOV-2013	19-JAN-2020	
CPCP	REF: AMM 55-00-00-220-801	HRS/MSC AFL					2320.42 1495		
+ 55-00-00-760-801-01 (s)	CHECK OF THE RUDDER STABILIZER MOVABLE SURFACE ELECTRICAL BONDING						PKG		
55.120	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 55-00-00-760-801	HRS/MSC AFL					3636.3 2081		
+ 55-00-00-760-801-02 (s)	CHECK OF THE LEFT ELEVATOR STABILIZER MOVABLE SURFACE ELECTRICAL BONDING						PKG		
55.120	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 55-00-00-760-801	HRS/MSC AFL					3636.3 2081		
+ 55-00-00-760-801-03 (s)	CHECK OF THE RIGHT ELEVATOR STABILIZER MOVABLE SURFACE ELECTRICAL BONDING						PKG		
55.120	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 55-00-00-760-801	HRS/MSC AFL					3636.3 2081		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-00-270-801-01	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS								
55.020		MOS	288	+2m			19-OCT-2007	19-OCT-2031	19-DEC-2031
	REF: AMM 55-10-00-270-801	HRS/MSC					0		
		AFL	11250				0	11250	
+ 55-10-00-270-801-01A	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS (MANDATORY REF. 5-40-10)								
55.020		MOS					19-OCT-2007		
FD	REF: AMM 55-10-00-270-801	HRS/MSC					0		
		AFL	11250				0	11250	
55-10-00-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER ELECTRICAL ACTUATOR FRONT TORQUE LINK AND ACTUATOR UPPER HINGE						PKG		
27.270	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 55-10-00-640-802	HRS/MSC					3636.3		
		AFL					2081		
55-10-03-640-801-01 (s)	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM						PKG		
55.060	PKG 16	MOS	24	+1m			14-JUN-2019		
	REF: AMM 55-10-03-640-801	HRS/MSC					3636.3		
		AFL					2081		
55-10-03-900-801-01	LEFT SPRING LOADED FAIRING								
55.070	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 55-10-03-900-801	AFL					0		
							0		
55-10-03-900-801-02	RIGHT SPRING LOADED FAIRING								
55.070	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 55-10-03-900-801	AFL					0		
							0		
+ 55-10-31-220-801-01 (s)	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS						PKG		
55.030	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 55-10-31-220-801	HRS/MSC					2320.42		
		AFL	3750				1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY REF. 5-40-10)								
55.030		MOS					19-NOV-2013		
FD	REF: AMM 55-10-31-220-801	HRS/MSC					2320.42		
		AFL	3750				1495		5245
55-10-33-640-801-01	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS								
27.255		MOS	36	+1m			14-JUN-2018	14-JUN-2021	14-JUL-2021
	REF: AMM 55-10-33-640-801	HRS/MSC	600	+40			3406.6	4006.6	4046.6
		AFL					1988		
+ 55-10-39-220-801-01	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE								
55.040		MOS					19-OCT-2007		
	REF: AMM 55-10-39-220-801	HRS/MSC					0		
		AFL	11250				0		11250
+ 55-10-39-220-801-01A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE (MANDATORY REF. 5-40-10)								
55.040		MOS					19-OCT-2007		
FD	REF: AMM 55-10-39-220-801	HRS/MSC					0		
		AFL	11250				0		11250
+ 55-10-39-220-801-02	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE								
55.040		MOS					19-OCT-2007		
	REF: AMM 55-10-39-220-801	HRS/MSC					0		
		AFL	11250				0		11250
+ 55-10-39-220-801-02A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE (MANDATORY REF. 5-40-10)								
55.040		MOS					19-OCT-2007		
FD	REF: AMM 55-10-39-220-801	HRS/MSC					0		
		AFL	11250				0		11250

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-01-900-801-01	LEFT ELEVATOR								
55.090	FGFC341 300 REF: AMM 55-20-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
55-20-01-900-801-02	RIGHT ELEVATOR								
55.090	FGFC342 297 REF: AMM 55-20-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 55-20-03-640-801-01 (s)	LUBRICATION OF THE ELEVATOR BEARINGS						PKG		
55.080	PKG 32 REF: AMM 55-20-03-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
55-20-03-640-802-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES						PKG		
27.180	PKG 15 REF: AMM 55-20-03-640-802	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
55-20-05-640-801-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL BEARINGS AND UJOINTS						PKG		
27.265	PKG 5,201 REF: AMM 55-20-05-640-801	MOS HRS/MSC AFL	12	+1m	800	+40	14-JUN-2019 3636.3 2081		
+ 55-30-00-270-801-01	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS								
55.050	REF: AMM 55-30-00-270-801	MOS HRS/MSC AFL	288	+2m	11250		19-OCT-2007 0 0	19-OCT-2031	19-DEC-2031
								11250	
+ 55-30-00-270-801-01A	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS (MANDATORY REF. 5-40-10)								
55.050	REF: AMM 55-30-00-270-801	MOS HRS/MSC AFL	11250				19-OCT-2007 0 0		
FD								11250	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-01-900-801-01	RUDDER								
55.110	FGFB321B5 TW549 REF: AMM 55-40-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
+ 55-40-05-640-801-01 (s)	LUBRICATION OF THE RUDDER BEARINGS						PKG		
55.100	PKG 32 REF: AMM 55-40-05-640-801	MOS HRS/MSC AFL	144 7500	+2m			19-OCT-2007 0 0		
55-40-05-640-802-01 (s)	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES						PKG		
27.155	PKG 15 REF: AMM 55-40-05-640-802	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
CHAPTER 56 WINDOWS									
56-10-01-900-801-01	PILOT WINDSHIELD ASSY, (LH)								
56.020	SPSF900-2-8-3 2471 REF: AMM 56-10-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-10-01-900-801-02	COPILOT WINDSHIELD ASSY, (LH)								
56.020	SPSF900-3-8-3 2484 REF: AMM 56-10-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-10-01-900-801-03	FRONT WINDSHIELD ASSY, (LH)								
56.020	SPSF900-1-7-3 855 REF: AMM 56-10-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-10-07-900-801-01	RIGHT LATERAL WINDOW								
56.030	SPSF900-5-8-2 2182 REF: AMM 56-10-07-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-FEB-2012 1893 1156		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-09-640-801-01 (s)	LUBRICATION OF THE OPENING WINDOW MECHANISM						PKG		
56.010	PKG 16 REF: AMM 56-10-09-640-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
56-10-09-900-801-01	OPENING WINDOW								
56.010	SPSF900-4-6-2 2671 REF: AMM 56-10-09-900-801	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			16-NOV-2011 1804.5 1091		
56-10-11-900-801-01	LEFT REAR WINDOW								
56.040	SPSF900-6-8-2 3217 REF: AMM 56-10-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-10-11-900-801-02	RIGHT REAR WINDOW								
56.040	SPSF900-7-8-2 3252 REF: AMM 56-10-11-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-01	NO. 1 LEFT PASSENGER CABIN WINDOW								
56.050	SPSF2M8-3-0 15859 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-02	NO. 2 LEFT PASSENGER CABIN WINDOW								
56.050	SPSF2M8-3-0 15861 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-03	NO. 3 LEFT PASSENGER CABIN WINDOW								
56.060	SPSF2M8-3-0 15862 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-04	NO. 4 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 15863 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-05	NO. 5 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 15864 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-06	NO. 6 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 15865 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-07	NO. 7 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 15866 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-08	NO. 8 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 15867 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-09	NO. 9 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 15868 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-10	NO. 10 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 15869 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-11	NO. 11 LEFT PASSENGER CABIN WINDOW								
56.100	SPSF2M8-3-0 15870 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-12	NO. 12 LEFT PASSENGER CABIN WINDOW								
56.100	SPSF2M8-3-0 15871 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-13	NO. 1 RIGHT PASSENGER CABIN WINDOW								
56.110	SPSF2M8-3-0 15872 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-14	NO. 2 RIGHT PASSENGER CABIN WINDOW								
56.110	SPSF2M8-3-0 15873 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-15	NO. 3 RIGHT PASSENGER CABIN WINDOW								
56.120	SPSF2M8-3-0 15874 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-16	NO. 4 RIGHT PASSENGER CABIN WINDOW								
56.120	SPSF2M8-3-0 15875 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-17	NO. 5 RIGHT PASSENGER CABIN WINDOW								
56.130	SPSF2M8-3-0 15876 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-18	NO. 6 RIGHT PASSENGER CABIN WINDOW								
56.130	SPSF2M8-3-0 15877 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-19	NO. 7 RIGHT PASSENGER CABIN WINDOW								
56.140	SPSF2M8-3-0 15878 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-20	NO. 8 RIGHT PASSENGER CABIN WINDOW								
56.140	SPSF2M8-3-0 15879 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-21	NO. 9 RIGHT PASSENGER CABIN WINDOW								
56.150	SPSF2M8-3-0 15880 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-22	NO. 10 RIGHT PASSENGER CABIN WINDOW								
56.150	SPSF2M8-3-0 15881 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-23	NO. 11 RIGHT PASSENGER CABIN WINDOW								
56.160	SPSF2M8-3-0 15882 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
56-20-05-900-801-24	NO. 12 RIGHT PASSENGER CABIN WINDOW								
56.160	SPSF2M8-3-0 17503 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

CHAPTER 57 WINGS

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE LEFT WING						PKG		
57.0101	PKG 16	MOS	24	+1m			14-JUN-2019	3636.3	2081
	REF: AMM 57-00-00-210-801	HRS/MSC	4000					3636.3	2081
		AFL						2081	
57-00-00-210-801-01C (s)	GENERAL VISUAL INSPECTION OF THE LH WING (CPCP)								
CPCP		MOS	25				14-JUN-2019	3636.3	2081
	REF: AMM 57-00-00-210-801	HRS/MSC						3636.3	2081
		AFL						2081	
+ 57-00-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE RIGHT WING						PKG		
57.0101	PKG 16	MOS	24	+1m			14-JUN-2019	3636.3	2081
	REF: AMM 57-00-00-210-801	HRS/MSC	4000					3636.3	2081
		AFL						2081	
57-00-00-210-801-02C (s)	GENERAL VISUAL INSPECTION OF THE RH WING (CPCP)								
CPCP		MOS	25				14-JUN-2019	3636.3	2081
	REF: AMM 57-00-00-210-801	HRS/MSC						3636.3	2081
		AFL						2081	
+ 57-00-00-220-802-01 (s)	DETAILED INSPECTION OF THE LEFT WING						PKG		
57.0102	PKG 31	MOS	72	+2m			19-NOV-2013	2320.42	1495
	REF: AMM 57-00-00-220-802	HRS/MSC	3750					2320.42	1495
		AFL						1495	
57-00-00-220-802-01C (s)	DETAILED INSPECTION OF THE LH WING (CPCP)								
CPCP		MOS	74				19-NOV-2013	2320.42	1495
	REF: AMM 57-00-00-220-802	HRS/MSC						2320.42	1495
		AFL						1495	
+ 57-00-00-220-802-02 (s)	DETAILED INSPECTION OF THE RIGHT WING						PKG		
57.0102	PKG 31	MOS	72	+2m			19-NOV-2013	2320.42	1495
	REF: AMM 57-00-00-220-802	HRS/MSC	3750					2320.42	1495
		AFL						1495	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-220-802-02C (s)	DETAILED INSPECTION OF THE RH WING (CPCP)								
CPCP	REF: AMM 57-00-00-220-802	MOS HRS/MSC AFL	74				19-NOV-2013 2320.42 1495		
+ 57-00-00-760-801-01 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LHAILERON						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 57-00-00-760-801-02 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RHAILERON						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 57-00-00-760-801-03 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LHFLAPS						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 57-00-00-760-801-04 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RHFLAPS						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 57-00-00-760-801-05 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LHSLATS						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 57-00-00-760-801-06 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RHSLATS						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00-00-760-801-07 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AIRBRAKES						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
+ 57-00-00-760-801-08 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AIRBRAKES						PKG		
57.245	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
57-00-01-900-801-01	LEFT WING								
57.220	FGFD101 825MA/201/1120 REF: AMM 57-00-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
57-00-01-900-801-02	RIGHT WING								
57.220	FGFD102 823MA200/1120 REF: AMM 57-00-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
57-10-00-290-801-01 (s)	ENDOSCOPE INSPECTION WING TANKS						PKG		
57.110	PKG 31 REF: AMM 57-10-00-290-801	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
57-10-00-290-801-01C (s)	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)								
CPCP	REF: AMM 57-10-00-290-801	MOS HRS/MSC AFL	74				19-NOV-2013 2320.42 1495		
57-10-01-210-801-01	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS								
57.030	REF: AMM 57-10-01-210-801	MOS HRS/MSC AFL	11250				19-OCT-2007 0 0	11250	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-01-210-801-01A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS (MANDATORY REF. 5-40-10)								
57.030		MOS					19-OCT-2007		
FD	REF: AMM 57-10-01-210-801	HRS/MSC AFL	11250				0 0		11250
57-10-09-900-801-01	LEFT WINGLET								
	F20-0002-3	MOS		TSN:0			14-APR-2014		
	A109	HRS/MSC	O/C	TSN:0			2375.92		
	REF: GENERIC NO REF	AFL		TSN:0			1530		
57-10-09-900-801-02	RIGHT WINGLET								
	F20-0002-4	MOS		TSN:0			14-APR-2014		
	A109	HRS/MSC	O/C	TSN:0			2375.92		
	REF: GENERIC NO REF	AFL		TSN:0			1530		
57-10-14-220-801-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9								
57.325		MOS					19-OCT-2007		
	REF: AMM 57-10-14-220-801	HRS/MSC AFL	11250				0 0		11250
57-10-14-220-801-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 (MANDATORY REF. 5-40-10)								
57.325		MOS					19-OCT-2007		
FD	REF: AMM 57-10-14-220-801	HRS/MSC AFL	11250				0 0		11250
57-10-14-220-802-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9								
57.330		MOS					19-OCT-2007		
	REF: AMM 57-10-14-220-802	HRS/MSC AFL	11250				0 0		11250
57-10-14-220-802-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO 9 (MANDATORY REF. 5-40-10)								
57.330		MOS					19-OCT-2007		
FD	REF: AMM 57-10-14-220-802	HRS/MSC AFL	11250				0 0		11250

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-15-220-801-01	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3								
57.340		MOS					19-OCT-2007		
	REF: AMM 57-10-15-220-801	HRS/MSC					0		
		AFL	11250				0		11250
57-10-15-220-801-01A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO 3 (MANDATORY REF. 5-40-10)								
57.340		MOS					19-OCT-2007		
FD	REF: AMM 57-10-15-220-801	HRS/MSC					0		
		AFL	11250				0		11250
57-10-15-220-802-01	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17								
57.335		MOS					19-OCT-2007		
	REF: AMM 57-10-15-220-802	HRS/MSC					0		
		AFL	11250				0		11250
57-10-15-220-802-01A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 (MANDATORY REF. 5-40-10)								
57.335		MOS					19-OCT-2007		
FD	REF: AMM 57-10-15-220-802	HRS/MSC					0		
		AFL	11250				0		11250
+ 57-10-15-250-801-01	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE								
57.130		MOS					19-OCT-2007		
	REF: AMM 57-10-15-250-801	HRS/MSC					0		
		AFL	11250				0		11250
+ 57-10-15-250-801-01A	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE (MANDATORY REF. 5-40-10)								
57.130		MOS					19-OCT-2007		
	REF: AMM 57-10-15-250-801	HRS/MSC					0		
		AFL	11250				0		11250
57-45-01-900-801-01	LEFT INBOARD SLAT								
57.140	FGFB133B3	MOS		TSN:140			14-JUN-2019		
	322/793RA	HRS/MSC	O/C	TSN:3636.3			3636.3		
	REF: AMM 57-45-01-900-801	AFL		TSN:2081			2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-45-01-900-801-02	RIGHT INBOARD SLAT								
57.140	FGFB143B2 323/788RA REF: AMM 57-45-01-900-801	MOS HRS/MSC AFL	O/C	TSN:140 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
57-45-13-900-801-01	LEFT OUTBOARD SLAT								
57.150	FGFB135A7 519/1045RA REF: AMM 57-45-13-900-801	MOS HRS/MSC AFL	O/C	TSN:140 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
57-45-13-900-801-02	RIGHT OUTBOARD SLAT								
57.150	FGFB145A3 512/1036RA REF: AMM 57-45-13-900-801	MOS HRS/MSC AFL	O/C	TSN:140 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
+ 57-45-25-250-801-01 (s)	EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 5 AND 10						PKG		
57.300	PKG 33 REF: AMM 57-45-25-250-801	MOS HRS/MSC AFL	216	+2m 11250			19-OCT-2007 0 0		
+ 57-45-25-250-801-02 (s)	EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 1 AND 4						PKG		
	PKG 33 REF: AMM 57-45-25-250-801	MOS HRS/MSC AFL	216	+2m 11250			19-OCT-2007 0 0		
+ 57-55-00-700-801-01 (s)	CHECK OF THE FLAP LATERAL CLEARANCE						PKG		
57.250	PKG 31 REF: AMM 57-55-00-700-801	MOS HRS/MSC AFL	72	+2m 3750			19-NOV-2013 2320.42 1495		
57-55-01-900-801-01	LEFT INBOARD FLAP ASSEMBLY								
57.180	FGFB161A5 LE409 REF: AMM 57-55-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-55-01-900-801-02	RIGHT INBOARD FLAP ASSEMBLY								
57.180	FGFB162A5 LE409 REF: AMM 57-55-01-900-801	MOS HRS/MSC AFL	O/C	TSN:140 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
57-55-05-900-801-01	LEFT OUTBOARD FLAP ASSEMBLY								
57.190	FGFB163A3 LE878 REF: AMM 57-55-05-900-801	MOS HRS/MSC AFL	O/C	TSN:140 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
57-55-05-900-801-02	RIGHT OUTBOARD FLAP ASSEMBLY								
57.190	FGFB164A3 LE878 REF: AMM 57-55-05-900-801	MOS HRS/MSC AFL	O/C	TSN:140 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
+ 57-55-07-220-801-01 (s)	DETAILED INSPECTION 2 OF THE PROTECTION ON THE LEFT WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
57.160	PKG 31 REF: AMM 57-55-07-220-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 57-55-07-220-801-02 (s)	DETAILED INSPECTION 2 OF THE PROTECTION ON THE RIGHT WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
57.160	PKG 31 REF: AMM 57-55-07-220-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 57-55-11-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FOREFLAP BRACKETS						PKG		
57.170	PKG 31 REF: AMM 57-55-11-210-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
57-55-13-640-801-01 (s)	GREASING/LUBRICATION OF THE LEFT WING FLAP ROLLERS AND TRACKS						PKG		
57.345	PKG 5,201 REF: AMM 57-55-13-640-801	MOS HRS/MSC AFL	12 800	+1m +40			14-JUN-2019 3636.3 2081		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-55-13-640-801-02 (s)	GREASING/LUBRICATION OF THE RIGHT WING FLAP ROLLERS AND TRACKS						PKG		
57.345	PKG 5,201 REF: AMM 57-55-13-640-801	MOS HRS/MSC AFL	12 800	+1m +40			14-JUN-2019 3636.3 2081		
+ 57-55-21-250-801-01 (s)	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5						PKG		
57.200	PKG 31 REF: AMM 57-55-21-250-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
57-60-01-900-801-01	LEFTAILERON								
57.210	F50B151B9 437/IAOI/548 REF: AMM 57-60-01-900-801	MOS HRS/MSC AFL	O/C			TSN:73 TSR:0 TSN:2320.42 TSR:0 TSN:1495 TSR:0	19-NOV-2013 2320.42 1495		
57-60-01-900-801-02	RIGHTAILERON								
57.210	F50B152B9 435IAOSI/547 REF: AMM 57-60-01-900-801	MOS HRS/MSC AFL	O/C			TSN:140 TSN:3636.3 TSN:2081	14-JUN-2019 3636.3 2081		
+ 57-60-05-640-801-01 (s)	PRESSURE LUBRICATION OF THE LEFTAILERON BEARINGS						PKG		
57.210	PKG 31 REF: AMM 57-60-05-640-801	MOS HRS/MSC AFL	72 3750	+2m			19-NOV-2013 2320.42 1495		
+ 57-60-05-640-801-02 (s)	PRESSURE LUBRICATION OF THE RIGHTAILERON BEARINGS						PKG		
57.210	PKG 31 REF: AMM 57-60-05-640-801	MOS HRS/MSC AFL	72 3750	+2m			14-JUN-2019 3636.3 2081		
57-60-05-640-802-01	LUBRICATION OF THE LEFTAILERON CONTROL SURFACE HINGES								
27.090	PKG 15 REF: AMM 57-60-05-640-802	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081	14-JUN-2020	14-JUL-2020

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-05-640-802-02 (s)	LUBRICATION OF THE RIGHT AILERON CONTROL SURFACE HINGES						PKG		
27.090	PKG 15 REF: AMM 57-60-05-640-802	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
57-70-01-900-801-01	LEFT OUTBOARD AIRBRAKE								
57.230	FGFC169A1METG SN804 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
57-70-01-900-801-02	LEFT MIDDLE AIRBRAKE								
57.230	FGFC169A1METG SN803 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
57-70-01-900-801-03	LEFT INBOARD AIRBRAKE								
57.230	FGFC167 SN399 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
57-70-01-900-801-04	RIGHT INBOARD AIRBRAKE								
57.240	FGFC168 SN400 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
57-70-01-900-801-05	RIGHT MIDDLE AIRBRAKE								
57.240	FGFC169A1METD SN795 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
57-70-01-900-801-06	RIGHT OUTBOARD AIRBRAKE								
57.240	FGFC169A1METD SN794 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-03-640-801-01 (s)	LUBRICATION OF THE AIRBRAKE HINGES						PKG		
27.400	PKG 15,202 REF: AMM 57-70-03-640-801	MOS HRS/MSC AFL	12	+1m			14-JUN-2019 3636.3 2081		
CHAPTER 71 POWER PLANT									
71-00-00-910-802-01	RUN-UP INSPECTION ENGINE 1								
71.090	REF: AMM 71-00-00-910-802	MOS HRS/MSC AFL	O/C				14-JUN-2019 3636.3 2081		
71-00-00-910-802-02	RUN-UP INSPECTION ENGINE 2								
71.090	REF: AMM 71-00-00-910-802	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
71-00-00-910-802-03	RUN-UP INSPECTION ENGINE 3								
71.090	REF: AMM 71-00-00-910-802	MOS HRS/MSC AFL	O/C				23-NOV-2018 3524.4 2048		
71-00-00-910-803-01	ACCOMPLISH END OF INSPECTION RUN-UP								
71.080	REF: AMM 71-00-00-910-803	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
+ 71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 1 FRONT MOUNT								
54.060	REF: AMM 71-20-02-250-801	MOS HRS/MSC AFL	11250				19-OCT-2007 0 0	11250	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-02-250-801-01A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 1 FRONT MOUNT (MANDATORY 5-40)								
54.060		MOS					19-OCT-2007		
FD	REF: AMM 71-20-02-250-801	HRS/MSC AFL	11250				0 0		11250
+ 71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 3 FRONT MOUNT								
54.060		MOS					19-OCT-2007		
	REF: AMM 71-20-02-250-801	HRS/MSC AFL	11250				0 0		11250
71-20-02-250-801-02A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 3 FRONT MOUNT (MANDATORY 5-40)								
54.060		MOS					19-OCT-2007		
FD	REF: AMM 71-20-02-250-801	HRS/MSC AFL	11250				0 0		11250
+ 71-20-07-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT								
54.070		MOS					19-OCT-2007		
	REF: AMM 71-20-07-250-801	HRS/MSC AFL	11250				0 0		11250
71-20-07-250-801-01A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT (MANDATORY 5-40)								
54.070		MOS					19-OCT-2007		
FD	REF: AMM 71-20-07-250-801	HRS/MSC AFL	11250				0 0		11250
+ 71-20-07-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT								
54.070		MOS					19-OCT-2007		
	REF: AMM 71-20-07-250-801	HRS/MSC AFL	11250				0 0		11250

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-07-250-801-02A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT (MANDTAORY 5-40)								
54.070		MOS					19-OCT-2007		
FD	REF: AMM 71-20-07-250-801	HRS/MSC AFL	11250				0 0		11250
71-20-17-230-801-01	SPECIAL DETAIL INSPECTION NO. 2 ENGINE LEFT FRONT SHOCK ABSORBER RUBBER CORE								
71.040	LM833SA13	MOS					19-OCT-2007		
LIFE LIMIT	NSN	HRS/MSC	6000	+3%			0		6000 6180
	REF: AMM 71-20-17-230-801	AFL					0		
71-20-17-230-801-02	SPECIAL DETAIL INSPECTION NO. 2 ENGINE RIGHT FRONT SHOCK ABSORBER RUBBER CORE								
71.040	LM833SA13	MOS					19-OCT-2007		
LIFE LIMIT	NSN	HRS/MSC	6000	+3%			0		6000 6180
	REF: AMM 71-20-17-230-801	AFL					0		
710801	NO. 2 ENGINE LEFT FRONT SHOCK ABSORBER								
71.040	LM833SA13	MOS					19-OCT-2007		
	NSN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
710802	NO. 2 ENGINE RIGHT FRONT SHOCK ABSORBER								
71.040	LM833SA13	MOS					19-OCT-2007		
	NSN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
712201	NO. 1 ENGINE FORWARD UPPER MOUNT								
71.020	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
712202	NO. 2 ENGINE FORWARD MOUNT								
71.020	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712203	NO. 3 ENGINE FORWARD UPPER MOUNT								
71.020	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
712204	NO. 1 ENGINE FORWARD LOWER MOUNT								
71.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
712206	NO. 3 ENGINE FORWARD LOWER MOUNT								
71.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
712210	NO. 1 ENGINE AFT MOUNT								
71.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
712211	NO. 2 ENGINE AFT MOUNT								
71.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
712212	NO. 3 ENGINE AFT MOUNT								
71.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	3060000-4 P112719 REF: AMM 71-00-01-900-801	MOS HRS/MSC AFL	E/C	TSN:3636.3			14-JUN-2019 3636.3 2081		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN2	NO. 2 ENGINE								
71.EN2	3060000-4 P112720 REF: AMM 71-00-05-900-801	MOS HRS/MSC AFL	E/C	TSN:2591.7			15-APR-2015 2591.7 1611		
71EN3	NO. 3 ENGINE								
71.EN3	3060000-4 P112691 REF: AMM 71-00-01-900-801	MOS HRS/MSC AFL	E/C	TSN:2595.5			15-APR-2015 2591.7 1611		
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4									
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								
	REF: See Workcard	MOS HRS/MSC ENC	2500	+100	-91.7		06-APR-2015 2591.7 1611	(5000) 5000	5100
+ 710130 (s)	NO. 1 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY						PKG		
	PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		
+ 710140 (s)	NO. 1 ENGINE - INSPECT INLET/FAN AREA						PKG		
	PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		
+ 714010 (s)	NO. 1 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS						PKG		
	PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		
+ 715010 (s)	NO. 1 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS						PKG		
	PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI) REF: See Workcard	MOS HRS/MSC ENC	2500	+100		-91.7	07-APR-2015 2591.7 1611	(5000) 5000	5100
+ 710130 (s)	NO. 2 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		
+ 710140 (s)	NO. 2 ENGINE - INSPECT INLET/FAN AREA PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		
+ 714010 (s)	NO. 2 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		
+ 715010 (s)	NO. 2 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4									
+ 710120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI) REF: See Workcard	MOS HRS/MSC ENC	2500	+100		-95.5	08-APR-2015 2595.5 1612	(5000) 5000	5100
+ 710130 (s)	NO. 3 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			17-SEP-2018 3480.2 2027		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710140 (s)	NO. 3 ENGINE - INSPECT INLET/FAN AREA PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			PKG 17-SEP-2018 3480.2 2027		
+ 714010 (s)	NO. 3 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 17-SEP-2018 3480.2 2027		
+ 715010 (s)	NO. 3 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 17-SEP-2018 3480.2 2027		

CHAPTER 72	ENGINE								
ENGINE NO. 1	Model : TFE731-60-1C	Serial # P112719	Part # 3060000-4						
72-00-00-200-006	NO. 1 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION	MOS HRS/MSC ENC	A/R				31-OCT-2006 0 0		
72-00-00-200-007	NO. 1 ENGINE - ACCIDENT OR INCIDENT	MOS HRS/MSC ENC	A/R				31-OCT-2006 0 0		
72-00-00-200-008	NO. 1 ENGINE - LIGHTING STRIKE	MOS HRS/MSC ENC	A/R				31-OCT-2006 0 0		
72-00-00-200-009	NO. 1 ENGINE - OVERTEMPERATURE	MOS HRS/MSC ENC	A/R				31-OCT-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719
3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-010	NO. 1 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-011	NO. 1 ENGINE - OVERSPEED	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-012	NO. 1 ENGINE - LPC1 BLADE BORESCOPE	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-013	NO. 1 ENGINE - HP IMPELLER BORESCOPE	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-014	NO. 1 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
720012	NO. 1 ENGINE - INPUT SHAFT	MOS					31-OCT-2006		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF			TSN:0			0		
720013	NO. 1 ENGINE - FAN STATOR VANE	MOS					31-OCT-2006		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF			TSN:0			0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720014	NO. 1 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720016	NO. 1 ENGINE - N1 MONOPOLE LEAD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720018	NO. 1 ENGINE - LPT1 SHROUD SEGMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720019	NO. 1 ENGINE - 1ST LPT NOZZLE RETAINING PIN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720110	NO. 1 ENGINE - ACCESSORY GEARBOX 3060827-2 S-2447 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
+ 720210	NO. 1 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				31-OCT-2006 0 0		
720211	NO. 1 ENGINE - LPT2 BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720212	NO. 1 ENGINE - HPT BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720213	NO. 1 ENGINE - FUEL NOZZLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720214	NO. 1 ENGINE - A/G/B BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720215	NO. 1 ENGINE - A/G/B COVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720216	NO. 1 ENGINE - AIR OIL SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720217	NO. 1 ENGINE - ROTOR SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
720218	NO. 1 ENGINE - FUEL PUMP DRIVE GEARSHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE	MOS					31-OCT-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
+ 723010 (s)	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH	MOS					PKG		
	PKG 5	HRS/MSC	1600	+50			06-APR-2015		
	REF: LMM 72-00-00	ENC					2591.7		
							1611		
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC	MOS					31-OCT-2006		
	3060625-1	HRS/MSC			TSN:0		0		
	060322901432	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC	MOS					31-OCT-2006		
	3060611-1	HRS/MSC			TSN:0		0		
	050322904784	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC	MOS					31-OCT-2006		
	3060671-2	HRS/MSC			TSN:0		0		
	060322901628	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 061217200030	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		(10000) 10000
LIFE LIMIT	REF: GENERIC NO REF								
725050	NO. 1 ENGINE - FAN DISC 3060241-1 061365102103	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		(20000) 20000
LIFE LIMIT	REF: GENERIC NO REF								
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 060316001369	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		(10000) 10000
LIFE LIMIT	REF: GENERIC NO REF								
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 060316000253	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		(10000) 10000
LIFE LIMIT	REF: GENERIC NO REF								
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 060316002054	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		(20000) 20000
LIFE LIMIT	REF: GENERIC NO REF								
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 060350104289	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		(20000) 20000
LIFE LIMIT	REF: GENERIC NO REF								
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 06P27004	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
	REF: See Workcard								

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 060322903584	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
LIFE LIMIT	REF: GENERIC NO REF		8000					(8000) 8000	
725130	NO. 1 ENGINE - FAN SPINNER 3060242-2 062784300385	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
LIFE LIMIT	REF: GENERIC NO REF		20000					(20000) 20000	
725140	NO. 1 ENGINE - FAN DRIVE SHAFT 3060291-2 061366304262	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
725150 (s)	NO. 1 ENGINE - VISUALLY INSPECT FAN BYPASS DUCT BLEED/SERVICE STRUT BOSS PKG 2	MOS HRS/MSC ENC	600	+50			PKG 08-DEC-2017 3236.1 1920		
725160	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 060350103682	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
LIFE LIMIT	REF: GENERIC NO REF		7000					(7000) 7000	
725170	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-3 06P29359	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
725180	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-4 06P26657	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
	REF: See Workcard								

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725210	NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 060322903451	MOS HRS/MSC		TSN:0 TSN:0			31-OCT-2006 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	(10000) 10000	
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-7 07P19631	MOS HRS/MSC	O/C	TSO:0 TSO:0			06-APR-2015 2591.7		1611
	REF: GENERIC NO REF	ENC		TSO:0			1611		
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 061756501232	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-OCT-2006 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-9 14-3300-03447	MOS HRS/MSC	O/C	TSO:0 TSO:0			06-APR-2015 2591.7		1611
	REF: LMM 05-10-01	ENC		TSO:0			1611		
725250	NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 03P29364	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-OCT-2006 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 06P29433	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-OCT-2006 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725270	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 061756501207	MOS HRS/MSC	O/C	TSN:0 TSN:0			31-OCT-2006 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 726010	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)	MOS					31-OCT-2006		
	REF: See Workcard	HRS/MSC ENC	5000	+200			0 0	(5000) 5000	5200
726020	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY	PN					31-OCT-2006		
	REF: See Workcard	SN-UNKNOWN ENC	O/C		TSN:0 TSN:0		0 0		
727010 (s)	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY	PKG 4					PKG 06-APR-2015		
	REF: See Workcard	MOS HRS/MSC ENC	1200	+100			2591.7 1611		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4									
72-00-00-200-006	NO. 2 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION	MOS					22-NOV-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-200-007	NO. 2 ENGINE - ACCIDENT OR INCIDENT	MOS					22-NOV-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-200-008	NO. 2 ENGINE - LIGHTING STRIKE	MOS					22-NOV-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-200-009	NO. 2 ENGINE - OVERTEMPERATURE	MOS					22-NOV-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-010	NO. 2 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				22-NOV-2006 0 0		
72-00-00-200-011	NO. 2 ENGINE - OVERSPEED REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				22-NOV-2006 0 0		
72-00-00-200-012	NO. 2 ENGINE - LPC1 BLADE BORESCOPE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				22-NOV-2006 0 0		
72-00-00-200-013	NO. 2 ENGINE - HP IMPELLER BORESCOPE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				22-NOV-2006 0 0		
72-00-00-200-014	NO. 2 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				22-NOV-2006 0 0		
720012	NO. 2 ENGINE - INPUT SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720013	NO. 2 ENGINE - FAN STATOR VANE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720014	NO. 2 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720016	NO. 2 ENGINE - N1 MONOPOLE LEAD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720018	NO. 2 ENGINE - LPT1 SHROUD SEGMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720019	NO. 2 ENGINE - 1ST LPT NOZZLE RETAINING PIN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720110	NO. 2 ENGINE - ACCESSORY GEARBOX 3060827-2 S-2450 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
+ 720210	NO. 2 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				22-NOV-2006 0 0		
720211	NO. 2 ENGINE - LPT2 BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#2: S/N P112720

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720212	NO. 2 ENGINE - HPT BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720213	NO. 2 ENGINE - FUEL NOZZLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720214	NO. 2 ENGINE - A/G/B BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720215	NO. 2 ENGINE - A/G/B COVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720216	NO. 2 ENGINE - AIR OIL SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720217	NO. 2 ENGINE - ROTOR SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
720218	NO. 2 ENGINE - FUEL PUMP DRIVE GEARSHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE	MOS					22-NOV-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK	MOS					22-NOV-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE	MOS					22-NOV-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
+ 723010 (s)	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH	MOS					PKG		
	PKG 5	HRS/MSC	1600	+50			07-APR-2015		
	REF: LMM 72-00-00	ENC					2591.7		
							1611		
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC	MOS					22-NOV-2006		
	3060625-1	HRS/MSC			TSN:0		0		
	060322900837	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC	MOS					22-NOV-2006		
	3060611-1	HRS/MSC			TSN:0		0		
	050322904785	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC	MOS					22-NOV-2006		
	3060671-2	HRS/MSC			TSN:0		0		
	060322901790	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 061217200210	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		(10000) 10000
LIFE LIMIT	REF: GENERIC NO REF								
725050	NO. 2 ENGINE - FAN DISC 3060241-1 061365102102	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		(20000) 20000
LIFE LIMIT	REF: GENERIC NO REF								
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 060316002092	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		(10000) 10000
LIFE LIMIT	REF: GENERIC NO REF								
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 060316001063	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		(10000) 10000
LIFE LIMIT	REF: GENERIC NO REF								
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 060316001271	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		(20000) 20000
LIFE LIMIT	REF: GENERIC NO REF								
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 060350104325	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		(20000) 20000
LIFE LIMIT	REF: GENERIC NO REF								
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 06P28112	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
	REF: See Workcard								

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 060322903604	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
LIFE LIMIT	REF: GENERIC NO REF		8000					(8000) 8000	
725130	NO. 2 ENGINE - FAN SPINNER 3060242-2 062784300353	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
LIFE LIMIT	REF: GENERIC NO REF		20000					(20000) 20000	
725140	NO. 2 ENGINE - FAN DRIVE SHAFT 3060291-2 061366304244	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
725150 (s)	NO. 2 ENGINE - VISUALLY INSPECT FAN BYPASS DUCT BLEED/SERVICE STRUT BOSS PKG 2	MOS HRS/MSC ENC	600	+50			PKG 08-DEC-2017 3236.1 1920		
725160	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 060350103677	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
LIFE LIMIT	REF: GENERIC NO REF		7000					(7000) 7000	
725170	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-3 06P29356	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
725180	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-4 06P25398	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
	REF: See Workcard								

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#2: S/N P112720

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725210	NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 060322903443 REF: GENERIC NO REF	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		(10000) 10000
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-7 14-3300-01743 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-APR-2015 2591.7 1611		
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 061756501419 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-9 14-3300-03446 REF: LMM 05-10-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			07-APR-2015 2591.7 1611		
725250	NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 06P27869 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 06P29435 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
725270	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 061756501575 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#2: S/N P112720
3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 726010	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)	MOS					22-NOV-2006		
	REF: See Workcard	HRS/MSC ENC	5000	+200			0 0	(5000) 5000	5200
726020	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY	PN					22-NOV-2006		
	REF: See Workcard	SN-UNKNOWN ENC	O/C		TSN:0 TSN:0		0 0		
727010 (s)	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY	PKG 4					PKG		
	REF: See Workcard	MOS HRS/MSC ENC	1200	+100			07-APR-2015 2591.7 1611		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4									
72-00-00-200-006	NO. 3 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION	MOS					15-JUN-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-200-007	NO. 3 ENGINE - ACCIDENT OR INCIDENT	MOS					15-JUN-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-200-008	NO. 3 ENGINE - LIGHTING STRIKE	MOS					15-JUN-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-200-009	NO. 3 ENGINE - OVERTEMPERATURE	MOS					15-JUN-2006		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-010	NO. 3 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				15-JUN-2006 0 0		
72-00-00-200-011	NO. 3 ENGINE - OVERSPEED REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				15-JUN-2006 0 0		
72-00-00-200-012	NO. 3 ENGINE - LPC1 BLADE BORESCOPE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				15-JUN-2006 0 0		
72-00-00-200-013	NO. 3 ENGINE - HP IMPELLER BORESCOPE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				15-JUN-2006 0 0		
72-00-00-200-014	NO. 3 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				15-JUN-2006 0 0		
720012	NO. 3 ENGINE - INPUT SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720013	NO. 3 ENGINE - FAN STATOR VANE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720014	NO. 3 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720016	NO. 3 ENGINE - N1 MONOPOLE LEAD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720018	NO. 3 ENGINE - LPT1 SHROUD SEGMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720019	NO. 3 ENGINE - 1ST LPT NOZZLE RETAINING PIN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720110	NO. 3 ENGINE - ACCESSORY GEARBOX 3060827-2 S-2341 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
+ 720210	NO. 3 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				15-JUN-2006 0 0		
720211	NO. 3 ENGINE - LPT2 BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720212	NO. 3 ENGINE - HPT BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720213	NO. 3 ENGINE - FUEL NOZZLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720214	NO. 3 ENGINE - A/G/B BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720215	NO. 3 ENGINE - A/G/B COVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720216	NO. 3 ENGINE - AIR OIL SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720217	NO. 3 ENGINE - ROTOR SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
720218	NO. 3 ENGINE - FUEL PUMP DRIVE GEARSHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721001	NO. 3 ENGINE - PRESERVATION OF ENGINE	MOS					15-JUN-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721002	NO. 3 ENGINE - PERFORM ENGINE PRESERVATION CHECK	MOS					15-JUN-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721003	NO. 3 ENGINE - DE-PRESERVATION OF ENGINE	MOS					15-JUN-2006		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
+ 723010 (s)	NO. 3 ENGINE - CHECK CARBON SEAL HEALTH	MOS					PKG		
	PKG 5	HRS/MSC	1600	+50			08-APR-2015		
	REF: LMM 72-00-00	ENC					2595.5		
							1612		
725010	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC	MOS					15-JUN-2006		
	3060625-1	HRS/MSC			TSN:0		0		
	050322904835	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				
725020	NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC	MOS					15-JUN-2006		
	3060611-1	HRS/MSC			TSN:0		0		
	050322904689	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				
725030	NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC	MOS					15-JUN-2006		
	3060671-2	HRS/MSC			TSN:0		0		
	060322900127	ENC	12000		TSN:0		0		(12000) 12000
LIFE LIMIT	REF: GENERIC NO REF				TSN:0				

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 12-156111-00458	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			08-APR-2015 2595.5 1612	(11612) 11612	
LIFE LIMIT	REF: GENERIC NO REF								
725050	NO. 3 ENGINE - FAN DISC 3060241-1 060322901054	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0	(20000) 20000	
LIFE LIMIT	REF: GENERIC NO REF								
725060	NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 050316003658	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0	(10000) 10000	
LIFE LIMIT	REF: GENERIC NO REF								
725070	NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 060316000250	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0	(10000) 10000	
LIFE LIMIT	REF: GENERIC NO REF								
725080	NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 050316004265	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0	(20000) 20000	
LIFE LIMIT	REF: GENERIC NO REF								
725090	NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 050350107820	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0	(20000) 20000	
LIFE LIMIT	REF: GENERIC NO REF								
725110	NO. 3 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 06P08114	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
	REF: See Workcard								

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725120	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 060322902625	MOS HRS/MSC		TSN:0 TSN:0			15-JUN-2006 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8000	TSN:0			0	(8000) 8000	
725130	NO. 3 ENGINE - FAN SPINNER 3060242-2 062784300168	MOS HRS/MSC		TSN:0 TSN:0			15-JUN-2006 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:0			0	(20000) 20000	
725140	NO. 3 ENGINE - FAN DRIVE SHAFT 3060291-2 050339001263	MOS HRS/MSC	O/C	TSN:0 TSN:0			15-JUN-2006 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725150 (s)	NO. 3 ENGINE - VISUALLY INSPECT FAN BYPASS DUCT BLEED/SERVICE STRUT BOSS PKG 2	MOS HRS/MSC	600	+50			08-DEC-2017 3236.1		
	REF: LMM 72-70-05	ENC					1920		
725160	NO. 3 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 050350109981	MOS HRS/MSC		TSN:0 TSN:0			15-JUN-2006 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	7000	TSN:0			0	(7000) 7000	
725170	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-3 06P17181	MOS HRS/MSC	O/C	TSN:0 TSN:0			15-JUN-2006 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725180	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-4 07P12345	MOS HRS/MSC	O/C	TSN:0 TSN:0			15-JUN-2006 0		
	REF: See Workcard	ENC		TSN:0			0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725210	NO. 3 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 060322900262 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0	(10000) 10000	
725220	NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-7 13-3300-03657 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			08-APR-2015 2595.5 1612		
725230	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 06P15204 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
725240	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-9 00P14261 REF: LMM 05-10-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			08-APR-2015 2595.5 1612		
725250	NO. 3 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 06P17606 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
725260	NO. 3 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 06P17131 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
725270	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 06P10527 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 726010	NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)	MOS					15-JUN-2006		
	REF: See Workcard	HRS/MSC ENC	5000	+200			0 0	(5000) 5000	5200
726020	NO. 3 ENGINE - TRANSFER GEARBOX ASSEMBLY	MOS					15-JUN-2006		
	PN SN-UNKNOWN REF: See Workcard	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
727010 (s)	NO. 3 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY	MOS					PKG		
	PKG 4 REF: See Workcard	HRS/MSC ENC	1200	+100			08-APR-2015 2595.5 1612		
727A01	NO. 3 ENGINE - FAN BYPASS DUCT	MOS					11-FEB-2011		
	3060742-4 061469500663 REF:	HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		1545.17 873		
CHAPTER 73 ENGINE FUEL AND CONTROL									
+ 73-20-01-710-802-01 (s)	OPERATIONAL TEST NO. 1 ENGINE OF THE ENGINE DIGITAL ELECTRONIC COMPUTER (DEEC) POWER SUPPLY	MOS					PKG		
76.160	PKG 21 REF: AMM 73-20-01-710-802	HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		
73-30-02-710-801-01 (s)	OPERATIONAL TEST OF THE FUEL FILTER CLOGGING DETECTION	MOS					PKG		
73.110	PKG 22 REF: AMM 73-30-02-710-801	HRS/MSC AFL	3200	+40			15-JUN-2017 3125.5 1867		
733213	NO.1 ENGINE FUEL PRESSURE SWITCH	MOS					19-OCT-2007		
73.040	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733214	NO.2 ENGINE FUEL PRESSURE SWITCH								
73.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733215	NO.3 ENGINE FUEL PRESSURE SWITCH								
73.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733225	NO.1 ENGINE FUEL THERMOCOUPLE								
73.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733226	NO.2 ENGINE FUEL THERMOCOUPLE								
73.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733227	NO.3 ENGINE FUEL THERMOCOUPLE								
73.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733801	NO. 1 ENGINE FUEL TEMPERATURE PROBE								
73.090	56B17 M7400 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733802	NO. 2 ENGINE FUEL TEMPERATURE PROBE								
73.090	56B17 N0131 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733803	NO. 3 ENGINE FUEL TEMPERATURE PROBE								
73.090	56B17 N0133 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733811	NO.1 ENGINE FUEL FLOW TRANSMITTER								
73.100	9-127-14 107467-250 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733812	NO.2 ENGINE FUEL FLOW TRANSMITTER								
73.100	9-127-14 107467-270 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
733813	NO.3 ENGINE FUEL FLOW TRANSMITTER								
73.100	9-127-14 107467-271 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4

730110	NO. 1 ENGINE - FUEL CONTROL UNIT								
	3070800-49 20233 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:11 TSR:0 TSR:0			23-NOV-2018 3524.4 2048		
730120 (s)	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT								
	PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			PKG 14-JUN-2019 3636.3 2081		
730130	NO. 1 ENGINE - ENGINE FUEL PUMP								
	3060760-4 2082 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731110	NO. 1 ENGINE - PRESSURE LIMITER VALVE 3070685-12 16972 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 2254 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
732120	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: LMM 73-21-04	MOS HRS/MSC ENC	N/A				31-OCT-2006 0 0		
73A001	NO. 1 ENGINE - FUEL IMPEDING BYPASS 98505-8660-120 0900 CUSTOMER CODE REF:	MOS HRS/MSC ENC	O/C				23-JUN-2011 1665.92 985		

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4

730110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-39 18508 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
730120 (s)	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			PKG 14-JUN-2019 3636.3 2081		
730130	NO. 2 ENGINE - ENGINE FUEL PUMP 3060760-4 2069 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731110	NO. 2 ENGINE - PRESSURE LIMITER VALVE 3070685-12 16973 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 2253 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
732120	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: LMM 73-21-04	MOS HRS/MSC ENC	N/A				22-NOV-2006 0 0		
732A02	NO. 2 ENGINE - DIFFERENTIAL PRESSURE INDICATOR 5913809-2 1588 REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-JUL-2011 1670.33 991		
73A001	NO. 2 ENGINE - FUEL IMPEDING BYPASS 98505-8660-120 0708 CUSTOMER CODE REF:	MOS HRS/MSC ENC	O/C				23-JUN-2011 1665.92 985		

ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4

730110	NO. 3 ENGINE - FUEL CONTROL UNIT 3070800-79 19740 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:6 TSR:0 TSR:0			23-NOV-2018 3524.4 2048		
730120 (s)	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600 +50				PKG 14-JUN-2019 3636.3 2081		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730130	NO. 3 ENGINE - ENGINE FUEL PUMP 3060760-4 1987 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
731110	NO. 3 ENGINE - PRESSURE LIMITER VALVE 3070685-12 16749 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
731120	NO. 3 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 2157 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
732120	NO. 3 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: LMM 73-21-04	MOS HRS/MSC ENC	N/A				15-JUN-2006 0 0		
CHAPTER 74 IGNITION									
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4									
740110	NO. 1 ENGINE - IGNITION UNIT PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:152 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 N/A REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2009 1054.5 582		
+ 740140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: See Workcard	MOS HRS/MSC ENC	1600	+50			PKG 06-APR-2015 2591.7 1611		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 N/A REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2009 1054.5 582		
+ 740160 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 06-APR-2015 2591.7 1611		
+ 740210 (s)	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 2 REF: LMM 74-00-01	MOS HRS/MSC ENC	600	+50			PKG 08-DEC-2017 3236.1 1920		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4									
740110	NO. 2 ENGINE - IGNITION UNIT PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-APR-2015 2591.7 1611		
+ 740140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: See Workcard	MOS HRS/MSC ENC	1600	+50			PKG 07-APR-2015 2591.7 1611		
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-APR-2015 2591.7 1611		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740160 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 07-APR-2015 2591.7 1611		
+ 740210 (s)	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 2 REF: LMM 74-00-01	MOS HRS/MSC ENC	600	+50			PKG 08-DEC-2017 3236.1 1920		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4									
740110	NO. 3 ENGINE - IGNITION UNIT PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		15-JUN-2006 0 0		
740130	NO. 3 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 N/A REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		25-NOV-2009 1058.25 583		
+ 740140 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: See Workcard	MOS HRS/MSC ENC	1600	+50			PKG 08-APR-2015 2595.5 1612		
740150	NO. 3 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 N/A REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		25-NOV-2009 1058.25 583		
+ 740160 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 08-APR-2015 2595.5 1612		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740210 (s)	NO. 3 ENGINE - OPERATIONAL CHECK	IGNITION SYSTEM					PKG		
	PKG 2	MOS					08-DEC-2017		
	REF: LMM 74-00-01	HRS/MSC	600	+50			3236.1		
		ENC					1920		

CHAPTER 75 AIR

ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4

754210	NO. 1 ENGINE - INLET TEMPERATURE SENSOR								
	3070816-14	MOS					31-OCT-2006		
75.010	061789322039	HRS/MSC	O/C				0		
	REF: See Workcard	ENC					0		

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4

754210	NO. 2 ENGINE - INLET TEMPERATURE SENSOR								
	3070816-14	MOS					22-NOV-2006		
75.010	061789322038	HRS/MSC	O/C				0		
	REF: See Workcard	ENC					0		

ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4

754210	NO. 3 ENGINE - INLET TEMPERATURE SENSOR								
	70060133-1	MOS					23-NOV-2018		
75.010	1616901770019	HRS/MSC	O/C				3524.4		
	REF: See Workcard	ENC					2048		

CHAPTER 76 ENGINE CONTROLS

+ 76-10-00-220-801-01	CHECK NO. 1 ENGINE OF THE NO. 1 ENGINE THROTTLE LEVERS FOR FRICTION POINTS								
		MOS					19-MAY-2017		
76.010		HRS/MSC	O/C				3080		
	REF: AMM 76-10-00-220-801	AFL					1850		

+ 76-10-00-220-801-02	CHECK NO. 2 ENGINE OF THE NO. 2 ENGINE THROTTLE LEVERS FOR FRICTION POINTS								
		MOS					19-MAY-2017		
76.010		HRS/MSC	O/C				3080		
	REF: AMM 76-10-00-220-801	AFL					1850		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-10-00-220-801-03	CHECK NO. 3 ENGINE OF THE NO. 3 ENGINE THROTTLE LEVERS FOR FRICTION POINTS								
76.010	REF: AMM 76-10-00-220-801	MOS HRS/MSC AFL	O/C				19-MAY-2017 3080 1850		
76-10-00-220-802-01	MEASUREMENT NO. 1 ENGINE OF THE NO. 1 ENGINE THROTTLE LEVER OPERATING FORCES								
76.110	REF: AMM 76-10-00-220-802	MOS HRS/MSC AFL	O/C				15-APR-2015 2591.7 1611		
76-10-00-220-802-02	MEASUREMENT NO. 2 ENGINE OF THE NO. 2 ENGINE THROTTLE LEVER OPERATING FORCES								
76.110	REF: AMM 76-10-00-220-802	MOS HRS/MSC AFL	O/C				15-APR-2015 2591.7 1611		
76-10-00-220-802-03	MEASUREMENT NO. 3 ENGINE OF THE NO. 3 ENGINE THROTTLE LEVER OPERATING FORCES								
76.110	REF: AMM 76-10-00-220-802	MOS HRS/MSC AFL	O/C				15-APR-2015 2591.7 1611		
76-10-01-900-801-01	THROTTLE QUADRANT ASSEMBLY								
76.090	FGFD771100A2 239 REF: AMM 76-10-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
76-10-21-640-802-01 (s)	LUBRICATION NO. 1 ENGINE OF THE NO. 1 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS								
76.020	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		
76-10-21-640-802-02 (s)	LUBRICATION NO. 2 ENGINE OF THE NO. 2 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS								
76.020	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			PKG 19-NOV-2013 2320.42 1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-10-21-640-802-03 (s)	LUBRICATION NO. 3 ENGINE OF THE NO. 3 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS						PKG		
76.020	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72	+2m			19-NOV-2013 2320.42 1495		
76-10-21-900-801-01	NO. 1 ENGINE TELEFLEX CONTROL CABLE								
76.060	PN SN-UNKNOWN REF: AMM 76-10-21-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
76-10-21-900-801-02	NO. 3 ENGINE TELEFLEX CONTROL CABLE								
76.060	PN SN-UNKNOWN REF: AMM 76-10-21-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
76-10-21-900-802-01	NO. 2 ENGINE TELEFLEX CONTROL CABLE								
76.070	PN SN-UNKNOWN REF: AMM 76-10-21-900-802	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-OCT-2007 0 0		
76-10-25-640-801-01 (s)	GREASING OF THE ENGINE 1 TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARING						PKG		
76.080	PKG 32 REF: AMM 76-10-25-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
76-10-25-640-801-02 (s)	GREASING OF THE ENGINE 2 TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARING						PKG		
	PKG 32 REF: AMM 76-10-25-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		
76-10-25-640-801-03 (s)	GREASING OF THE ENGINE 3 TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARING						PKG		
76.080	PKG 32 REF: AMM 76-10-25-640-801	MOS HRS/MSC AFL	144	+2m			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-10-33-820-801-01 (s)	CHECK NO. 1 ENGINE NO. 1 ENGINE THROTTLE CABLE TENSION						PKG		
76.120	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 76-10-33-820-801	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 76-10-33-820-801-02 (s)	CHECK NO. 2 ENGINE NO. 2 ENGINE THROTTLE CABLE TENSION						PKG		
76.120	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 76-10-33-820-801	HRS/MSC					2320.42		
		AFL	3750				1495		
+ 76-10-33-820-801-03 (s)	CHECK NO. 3 ENGINE NO. 3 ENGINE THROTTLE CABLE TENSION						PKG		
76.120	PKG 31	MOS	72	+2m			19-NOV-2013		
	REF: AMM 76-10-33-820-801	HRS/MSC					2320.42		
		AFL	3750				1495		
76-10-33-900-801-01	NO. 1 ENGINE THROTTLE CONTROL CABLE								
76.050	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 76-10-33-900-801	AFL			TSN:0		0		
76-10-33-900-801-02	NO. 2 ENGINE THROTTLE CONTROL CABLE								
76.050	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 76-10-33-900-801	AFL			TSN:0		0		
76-10-33-900-801-03	NO. 3 ENGINE THROTTLE CONTROL CABLE								
76.050	PN	MOS					19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 76-10-33-900-801	AFL			TSN:0		0		
761207	NO. 1 ENGINE POWER LEVER CONTROL								
76.100	4387537	MOS					23-OCT-2015		
	16269	HRS/MSC	O/C		TSN:8		2761.8		
	REF: GENERIC NO REF	AFL			TSN:0		1696		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761208	NO. 2 ENGINE POWER LEVER CONTROL 4387567	MOS		TSN:0			19-OCT-2007		
76.100	16085 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
761209	NO. 3 ENGINE POWER LEVER CONTROL 4387567	MOS		TSN:0			08-JUN-2012		
76.100	16191 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			1972.17 1216		
762011	NO. 1 ENGINE FUEL SHUTOFF VALVE PN	MOS		TSN:0			19-OCT-2007		
76.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
762012	NO. 2 ENGINE FUEL SHUTOFF VALVE PN	MOS		TSN:0			19-OCT-2007		
76.140	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
762013	NO. 3 ENGINE FUEL SHUTOFF VALVE PN	MOS		TSN:0			19-OCT-2007		
76.150	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4									
761210	NO. 1 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM 2118882-2009	MOS					14-JUN-2019		
76.010	17-AY0187 OPERATOR REQUEST REF: See Workcard	HRS/MSC ENC	50				3636.3 2081	(3686.3)	3686.3
761310	NO. 1 ENGINE - SURGE BLEED VALVE 978812-7-1	MOS		TSN:0			31-OCT-2006		
76.020	12705 REF: See Workcard	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761320	NO. 1 ENGINE - SOLENOID CONTROL VALVE								
76.030	109696-6-1 12363 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:152 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
761330	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL								
76.040	2118882-2009 17-AY0187 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4									
761210	NO. 2 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM								
76.010 OPERATOR REQUEST	2118882-2009 124-AY0019 REF: See Workcard	MOS HRS/MSC ENC	50				14-JUN-2019 3636.3 2081	(3686.3) 3686.3	
761310	NO. 2 ENGINE - SURGE BLEED VALVE								
76.020	978812-7-1 12693 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
761320	NO. 2 ENGINE - SOLENOID CONTROL VALVE								
76.030	109696-6-1 12347 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
761330	NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL								
76.040	2118882-2009 124-AY0019 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4									
761210	NO. 3 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM								
76.010 OPERATOR REQUEST	2118882-2009 56-AY0119 REF: See Workcard	MOS HRS/MSC ENC	50				14-JUN-2019 3636.3 2081	(3686.3) 3686.3	

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
761310	NO. 3 ENGINE - SURGE BLEED VALVE									
76.020	978812-7-1 12534 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0			
761320	NO. 3 ENGINE - SOLENOID CONTROL VALVE									
76.030	109696-6-1 11692 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0			
761330	NO. 3 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL									
76.040	2118882-2009 56-AY0119 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0			
CHAPTER 77 ENGINE INDICATING										
+ 77-11-00-710-801-01 (s)	OPERATIONAL TEST OF THE " ENG 2 FAIL" WARNING INDICATION						PKG			
77.050	PKG 21 REF: AMM 77-11-00-710-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867			
+ 77-11-00-710-801-01A	OPERATIONAL TEST OF THE " ENG 2 FAIL" WARNING INDICATION (MANDATORY REF 5-40-00)									
77.050 CMR	REF: AMM 77-11-00-710-801	MOS HRS/MSC AFL	1800				15-JUN-2017 3125.5 1867	4925.5		
77-30-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE VIBRATION MONITORING COMPUTER (EVMC) - EVMC 1 (L2EZ)									
77.080	C12438AB01 1161 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0			
77-30-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE VIBRATION MONITORING COMPUTER (EVMC) - EVMC 2 (M2EZ)									
77.080	C12438AB01 1162 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0			

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
77-30-01-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE VIBRATION MONITORING COMPUTER (EVMC) - EVMC 3 (R2EZ)								
77.080	C12438AB01 1163 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4									
771210	NO. 1 ENGINE - N1 COMPENSATOR								
77.010	3060735-6 061309700570 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
771220	NO. 1 ENGINE - N2 TRANSDUCER								
77.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
772210	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS								
77.030	3060763-4 1416901745977 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			06-APR-2015 2591.7 1611		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4									
771210	NO. 2 ENGINE - N1 COMPENSATOR								
77.010	3060735-6 061309700573 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
771220	NO. 2 ENGINE - N2 TRANSDUCER								
77.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
772210	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS								
77.030	3060763-4 1416901745985 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-APR-2015 2591.7 1611		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4									
771210	NO. 3 ENGINE - N1 COMPENSATOR								
	3060735-7	MOS		TSN:0			15-JUN-2006		
77.010	071309700401	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		
771220	NO. 3 ENGINE - N2 TRANSDUCER								
	PN	MOS		TSN:0			15-JUN-2006		
77.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		
772210	NO. 3 ENGINE - ITT THERMOCOUPLE HARNESS								
	3060763-4	MOS		TSN:0			08-APR-2015		
77.030	1416901745988	HRS/MSC	O/C	TSN:0			2595.5		
	REF: See Workcard	ENC		TSN:0			1612		
CHAPTER 78 EXHAUST									
+ 78-30-00-210-801-01 (s) GENERAL VISUAL INSPECTION OF THE THRUST REVERSER									
	PKG 5,201	MOS	12	+1m			14-JUN-2019		
78.010		HRS/MSC	800	+40			3636.3		
	REF: AMM 78-30-00-210-801	AFL					2081		
+ 78-30-00-720-801-01 (s) FUNCTIONAL TEST OF THE THRUST REVERSER SYSTEM WITH ENGINE SHUT DOWN									
	PKG 31	MOS	72	+2m			14-JUN-2019		
78.020		HRS/MSC					3636.3		
	REF: AMM 78-30-00-720-801	AFL	3750				2081		
78-31-00-640-802-01 (s) GREASE OF THE THRUST REVERSER DOOR HINGE BOLTS									
	PKG 31	MOS	72	+2m			19-NOV-2013		
78.030		HRS/MSC					2320.42		
	REF: AMM 78-31-00-640-802	AFL	3750				1495		
78-31-00-640-803-01 (s) GREASING OF THE LINK ROD HINGE BOLTS									
	PKG 31	MOS	72	+2m			19-NOV-2013		
78.050		HRS/MSC					2320.42		
	REF: AMM 78-31-00-640-803	AFL	3750				1495		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-00-640-803-02 (s)	GREASING OF THE DOOR LATCH HOOKS						PKG		
78.050	PKG 16 REF: AMM 78-31-00-640-803	MOS HRS/MSC AFL	24	+1m			14-JUN-2019 3636.3 2081		
78-31-01-250-801-01	SPECIAL DETAILED INSPECTION LEFT THRUST REVERSER CLAMSHELL DOOR CLOSE OUT FITTING								
78.060	FGFB583701100D3 SL252 REF: AMM 78-31-01-250-801	MOS HRS/MSC AFL	2000	+3%			17-SEP-2018 3480.2 2027	4027	4087
78-31-01-250-801-02	SPECIAL DETAILED INSPECTION RIGHT THRUST REVERSER CLAMSHELL DOOR CLOSE OUT FITTING								
78.060	FGFB583701200D3 SL250 REF: AMM 78-31-01-250-801	MOS HRS/MSC AFL	2000	+3%			17-SEP-2018 3480.2 2027	4027	4087
78-31-01-250-801-03	SPECIAL DETAILED INSPECTION LEFT THRUST REVERSER CLAMSHELL DOOR BEAMS AND FITTINGS								
78.060	FGFB583701100D3 SL252 REF: AMM 78-31-01-250-801	MOS HRS/MSC AFL	4000	+3%			19-OCT-2007 0 0	4000	4120
78-31-01-250-801-04	SPECIAL DETAILED INSPECTION RIGHT THRUST REVERSER CLAMSHELL DOOR BEAMS AND FITTINGS								
78.060	FGFB583701200D3 SL250 REF: AMM 78-31-01-250-801	MOS HRS/MSC AFL	4000	+3%			19-OCT-2007 0 0	4000	4120
78-31-13-900-801-01	THRUST REVERSER CONTROL HYDRAULIC ACTUATOR								
78.070	F2MA581717-015 5564 REF: AMM 78-31-13-900-801	MOS HRS/MSC AFL	O/C				17-SEP-2018 3480.2 2027		
+ 78-32-00-760-801-01 (s)	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT								
78.080	PKG 21 REF: AMM 78-32-00-760-801	MOS HRS/MSC AFL	1600	+40			15-JUN-2017 3125.5 1867		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 78-32-00-760-801-01A	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT (MANDATORY REF 5-40-20)								
78.080		MOS					15-JUN-2017		
CMR	REF: AMM 78-32-00-760-801	HRS/MSC AFL	1800				3125.5 1867		4925.5
78-32-09-900-801-01	THRUST REVERSER ASSEMBLY								
78.170	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 78-32-09-900-801	AFL		TSN:0			0		
783801	THRUST REVERSER SYSTEM ACCUMULATOR								
78.130	60909-1	MOS		TSN:0			19-OCT-2007		
	EFS0245	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
783806	THRUST REVERSER ACCUMULATOR PRESSURE GAUGE								
78.140	PN	MOS		TSN:0			19-OCT-2007		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
783811	THRUST REVERSER HYDRAULIC CONTROL VALVE								
78.150	F2MA581792-007	MOS		TSN:0			19-OCT-2007		
	A30040458	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
783816	THRUST REVERSER HYDRAULIC PRESSURE SWITCH								
78.160	2365-15	MOS		TSN:0			19-OCT-2007		
	3881	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
783826	LEFT THRUST REVERSER CLAMSHELL DOOR								
78.060	FGFB583701100D3	MOS		TSN:0			19-OCT-2007		
	SL252	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783831	RIGHT THRUST REVERSER CLAMSHELL DOOR								
78.060	FGFB583701200D3 SL250 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
783836	THRUST REVERSER UPPER PRIMARY ACTUATOR								
78.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
783841	THRUST REVERSER LOWER PRIMARY ACTUATOR								
78.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
783846	UPPER BOX LATCH ACTUATOR								
78.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
783851	LOWER BOX LATCH ACTUATOR								
78.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
783856	THRUST REVERSER CONTROL UNIT PRINTED CIRCUIT BOARD								
78.200	FE1851-1 143 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JAN-2012 1849.08 1120		
784801	NO. 2 ENGINE THROTTLE CONTROL LEVER ELECTRO-MAGNET								
78.180	A861TS4RF900 1848 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
784806	THRUST REVERSER CONTROL LEVER ELECTRO-MAGNET								
78.190	A861TS4RF50 1851 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
CHAPTER 79 OIL									
793201	NO. 1 ENGINE OIL PRESSURE SWITCH								
79.030	8G1529 679 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
793202	NO. 2 ENGINE OIL PRESSURE SWITCH								
79.030	8G1529 680 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
793203	NO. 3 ENGINE OIL PRESSURE SWITCH								
79.030	8G1529 654 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-OCT-2007 0 0		
793213	NO. 1 ENGINE OIL TEMPERATURE PROBE								
79.040	56B17 N0130 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
793214	NO. 2 ENGINE OIL TEMPERATURE PROBE								
79.040	56B17 N0134 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		
793215	NO. 3 ENGINE OIL TEMPERATURE PROBE								
79.040	56B17 N0135 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-OCT-2007 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793801	NO. 1 ENGINE OIL PRESSURE TRANSMITTER 64279-543-1	MOS		TSN:18			22-MAR-2018		
79.160	6651 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			3341.1 1960		
793802	NO. 2 ENGINE OIL PRESSURE TRANSMITTER 64279-543-1	MOS					19-OCT-2007		
79.160	5063 REF: GENERIC NO REF	HRS/MSC AFL	O/C				0 0		
793803	NO. 3 ENGINE OIL PRESSURE TRANSMITTER 64279-543-1	MOS					19-OCT-2007		
79.160	5038 REF: GENERIC NO REF	HRS/MSC AFL	O/C				0 0		
793811	NO. 1 ENGINE OIL LEVEL GAUGE 764849-1-0	MOS		TSN:0			19-OCT-2007		
79.170	325 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
793812	NO. 2 ENGINE OIL LEVEL GAUGE 764849-1-0	MOS		TSN:0			19-OCT-2007		
79.170	349 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
793813	NO. 3 ENGINE OIL LEVEL GAUGE 764849-1-0	MOS		TSN:0			19-OCT-2007		
79.170	351 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
793816	ENGINE OIL GAUGE AMPLIFIER PN	MOS		TSN:0			19-OCT-2007		
79.180	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793821	ENGINE OIL LEVEL INDICATOR GAUGE								
79.190	722446 1261 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-APR-2011 1591.58 904		
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112719 Part # 3060000-4									
790110	NO. 1 ENGINE - OIL PUMP								
79.010	3060785-3 021405700232 REF: See Workcard	MOS HRS/MSC ENC	O/C				14-JUN-2019 3636.3 2081		
+ 790130 (s)	NO. 1 ENGINE - ANALYZE ENGINE OIL AND FILTER						PKG		
79.020	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			17-SEP-2018 3480.2 2027		
790140 (s)	NO. 1 ENGINE - CHANGE OIL						PKG		
79.030	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			06-APR-2015 2591.7 1611		
+ 790150 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK						PKG		
79.040	PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			08-DEC-2017 3236.1 1920		
790160 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						PKG		
79.040	PKG 1 REF: See Workcard	MOS HRS/MSC ENC	150	+100			17-SEP-2018 3480.2 2027		
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE								
79.130	PN SN-UNKNOWN REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C			TSN:152 TSN:3636.3 TSN:2081	14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792210	NO. 1 ENGINE - UPPER RIGHT OIL COOLER								
79.050	160556-5 811 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
792220	NO. 1 ENGINE - UPPER LEFT OIL COOLER								
79.060	160556-6 769 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER								
79.070	160554-5 2263 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER								
79.080	160554-6 2191 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE								
79.090	PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
792260	NO. 1 ENGINE - OIL TEMPERATURE VALVE								
79.100	158465-6 12324 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
793001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTION UNIT								
79.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:152 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#1: S/N P112719

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE								
79.110	PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 0 0		
+ 793315 (s)	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH						PKG		
79.110	PN PKG 4 SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100			06-APR-2015 2591.7 1611		
793320	NO. 1 ENGINE - FUEL/OIL COOLER								
79.120	3060709-4 2310 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	TSN:152 TSN:3636.3 TSN:2081			14-JUN-2019 3636.3 2081		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112720 Part # 3060000-4									
790110	NO. 2 ENGINE - OIL PUMP								
79.010	3060785-3 021405700545 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:6 TSO:0 TSO:0			22-MAR-2018 3341.1 1960		
+ 790130 (s)	NO. 2 ENGINE - ANALYZE ENGINE OIL AND FILTER						PKG		
79.020	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			17-SEP-2018 3480.2 2027		
790140 (s)	NO. 2 ENGINE - CHANGE OIL						PKG		
79.030	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			07-APR-2015 2591.7 1611		
+ 790150 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK						PKG		
79.040	PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			08-DEC-2017 3236.1 1920		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#2: S/N P112720

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790160 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 1	MOS					PKG		
79.040	REF: See Workcard	HRS/MSC ENC	150	+100			17-SEP-2018 3480.2 2027		
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE PN	MOS					22-NOV-2006		
79.130	SN-UNKNOWN REF: LMM 79-20-08	HRS/MSC ENC	O/C				0 0		
792210	NO. 2 ENGINE - UPPER RIGHT OIL COOLER 160556-5	MOS					22-NOV-2006		
79.050	801 REF: LMM 79-20-10	HRS/MSC ENC	O/C				0 0		
792220	NO. 2 ENGINE - UPPER LEFT OIL COOLER 160556-6	MOS					22-NOV-2006		
79.060	749 REF: LMM 79-20-10	HRS/MSC ENC	O/C				0 0		
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER 160554-5	MOS					22-NOV-2006		
79.070	2257 REF: LMM 79-20-10	HRS/MSC ENC	O/C				0 0		
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER 160554-6	MOS					22-NOV-2006		
79.080	2186 REF: LMM 79-20-10	HRS/MSC ENC	O/C				0 0		
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE PN	MOS					22-NOV-2006		
79.090	SN-UNKNOWN REF: LMM 79-20-02	HRS/MSC ENC	O/C				0 0		

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792260	NO. 2 ENGINE - OIL TEMPERATURE VALVE								
79.100	158465-6 12330 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
792A01	NO. 2 ENGINE - REGULATOR VALVE								
	38-87006-3022-4 08970 REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			08-JUN-2012 1972.17 1216		
793001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTION UNIT								
79.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE								
79.110	3060782-2 E12201 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			29-SEP-2012 2086.08 1292		
+ 793315 (s)	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								
79.110	3060782-2 PKG 4 E12201 REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100			PKG 07-APR-2015 2591.7 1611		
793320	NO. 2 ENGINE - FUEL/OIL COOLER								
79.120	3060709-4 2306 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-2006 0 0		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112691 Part # 3060000-4									
790110	NO. 3 ENGINE - OIL PUMP								
79.010	3060785-2 061405700130 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790130 (s)	NO. 3 ENGINE - ANALYZE ENGINE OIL AND FILTER PKG 1	ENGINE OIL AND FILTER MOS					PKG		
79.020	REF: LMM 72-00-00	HRS/MSC ENC	150	+100			17-SEP-2018 3480.2 2027		
790140 (s)	NO. 3 ENGINE - CHANGE OIL PKG 4	MOS					PKG		
79.030	REF: LMM 72-00-00	HRS/MSC ENC	1200	+100			08-APR-2015 2595.5 1612		
+ 790150 (s)	NO. 3 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK PKG 2	MOS					PKG		
79.040	REF: See Workcard	HRS/MSC ENC	600	+50			08-DEC-2017 3236.1 1920		
790160 (s)	NO. 3 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 1	MOS					PKG		
79.040	REF: See Workcard	HRS/MSC ENC	150	+100			17-SEP-2018 3480.2 2027		
792008	NO. 3 ENGINE - OIL FLOW REDUCTION VALVE PN	MOS							
79.130	SN-UNKNOWN REF: LMM 79-20-08	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		15-JUN-2006 0 0		
792210	NO. 3 ENGINE - UPPER RIGHT OIL COOLER 160556-5	MOS							
79.050	742 REF: LMM 79-20-10	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		15-JUN-2006 0 0		
792220	NO. 3 ENGINE - UPPER LEFT OIL COOLER 160556-6	MOS							
79.060	720 REF: LMM 79-20-10	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		15-JUN-2006 0 0		

Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691

3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792230	NO. 3 ENGINE - LOWER LEFT OIL COOLER								
79.070	160554-5 2161 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
792240	NO. 3 ENGINE - LOWER RIGHT OIL COOLER								
79.080	160554-6 2099 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
792250	NO. 3 ENGINE - PRESSURE BREATHER VALVE								
79.090	PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
792260	NO. 3 ENGINE - OIL TEMPERATURE VALVE								
79.100	158465-6 12136 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
793001	NO. 3 ENGINE - ENGINE OIL CHIP DETECTION UNIT								
79.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-JUN-2006 0 0		
793310	NO. 3 ENGINE - OIL FILTER BYPASS VALVE								
79.110	3060782-2 E12197 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			29-SEP-2012 2089.83 1293		
+ 793315 (s)	NO. 3 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH						PKG		
79.110	3060782-2 PKG 4 E12197 REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100			08-APR-2015 2595.5 1612		



Status Report

FALCON 900DX S/N 615 (N232SF): 3683.9 HRS, 2130 AFL as of 06-Sep-2019

ENGINE#3: S/N P112691
3683.9 HRS, 2130 ENC

Owner/Operator: WESTPORT RED LLC

Report Date: 01-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793320	NO. 3 ENGINE - FUEL/OIL COOLER								
	3060709-4	MOS		TSN:0			15-JUN-2006		
79.120	2211	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 79-20-07	ENC		TSN:0			0		