

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
0500300	A 300 Hour Inspection	9/1/21	13,788.3	11,465.0	9/30/22	14,088.3		133	135.6					12 mths	300.0	
0500600	B 600 Hour Inspection	9/1/21	13,788.3	11,465.0	9/1/23	14,388.3		469	435.6					24 mths	600.0	
0501200	C 1200 Hour Inspection	2/20/20	13,164.6	10,975.0	2/20/24	14,364.6		641	411.9					48 mths	1,200.0	
0502400	D 2400 Hour inspection	7/3/17	11,983.6	9,836.0	7/3/25	14,383.6		1,140	430.9					96 mths	2,400.0	
0503000	3000 Landing Inspection	2/19/15	11,103.3	9,053.0			12,053.0			473.0						3,000.0
0503010	Major Landing Gear Inspection	6/21/06		6,096.0			12,096.0			516.0						6,000.0
0503020	12 Year 6000 Ldg Airframe Inspection	7/3/17	11,983.6	9,836.0	8/2/28		15,836.0	2,266		4,256.0				144 mths		6,000.0
0503030	12,000 Hour Inspection	7/3/17	11,983.6	9,836.0		17,983.6			4,030.9						6,000.0	
0504010	Lt Eng 150/250 Hr Inspection	11/24/21	13,478.2	11,151.0		13,628.2			129.2						150.0	
0504015	Rt Eng 150/250 Hr Inspection	11/24/21	13,417.9	11,063.0		13,567.9			129.2						150.0	
0504020	Lt Eng 300/400 Hr Inspection	11/24/21	13,478.2	11,151.0		13,778.2			279.2						300.0	
0504025	Rt Eng 300/400 Hr Inspection	11/24/21	13,417.9	11,063.0		13,717.9			279.2						300.0	
0504030	Lt Eng Fuel Filter Replace	7/13/20	12,889.6	10,692.0		13,539.6			40.6						650.0	
0504035	Rt Eng Fuel Filter Replace	7/13/20	12,829.3	10,604.0		13,479.3			40.6						650.0	
0504040	Lt Eng 600/800 Hour Inspection	9/18/20	12,996.2	10,797.0		13,776.2			277.2						780.0	
0504045	Rt Eng 600/800 Hour Inspection	11/9/20	13,035.3	10,773.0		13,815.3			376.6						780.0	
0504047	Lt Eng 1000/1500 Hr Insp	9/19/18	12,198.2	10,030.0		13,598.2			99.2						1,400.0	
0504048	Rt Eng 1000/1500 Hr Insp	9/18/20	12,935.9	10,709.0		14,335.9			897.2						1,400.0	
0504050	Lt Eng 2100 Hour (MPI) Insp	9/19/18	12,198.2	10,030.0		14,298.2			799.2						2,100.0	
0504055	Rt Eng 2100 Hour (MPI) Insp	5/4/17	11,469.6	9,334.0		13,569.6			130.9						2,100.0	
0504060	Lt Eng 4200 Hr (Core) Insp	10/31/13	10,045.5	8,050.0		14,245.5			746.5						4,200.0	
0504065	Rt Eng 4200 Hr (Core) Insp	3/1/12	9,276.0	7,269.0		13,476.0			37.3						4,200.0	
0506010	150/200 Hr Lt Thrust Rev Insp	11/24/21	13,931.9	11,566.0		14,081.9			129.2						150.0	
0506015	150/200 Hr Rt Thrust Rev Insp	11/24/21	13,931.9	11,566.0		14,081.9			129.2						150.0	
0506020	300/400 Hr Lt Thrust Rev Insp	11/24/21	13,931.9	11,566.0		14,231.9			279.2						300.0	
0506025	300/400 Hr Rt Thrust Rev Insp	11/24/21	13,931.9	11,566.0		14,231.9			279.2						300.0	
0506030	600/800 Hr Lt Thrust Rev Insp	11/24/21	13,931.9	11,566.0		14,531.9			579.2						600.0	
0506035	600/800 Hr RT Thrust Rev Insp	11/24/21	13,931.9	11,566.0		14,531.9			579.2						600.0	
0506040	1400/1500 Hr Lt Thrust Rev Ins	4/27/18	12,513.6	10,298.0		13,913.6			-39.1						1,400.0	
0506045	1400/1500 Hr Rt Thrust Rev Ins	4/27/18	12,513.6	10,298.0		13,913.6			-39.1						1,400.0	

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
0506100	12 Month Raisbeck Aft Locker Insp	9/1/21	13,788.3	11,465.0	9/1/22			104						12 mths		
0506110	300 Hr Raisbeck Aft Locker Insp	9/1/21	13,788.3	11,465.0		14,088.3			135.6						300.0	
0506120	600 Hr Raisbeck Aft Locker Insp	9/1/21	13,788.3	11,465.0		14,388.3			435.6						600.0	
0507010	Garmin GTN 750 Visual Inspection (Per GTN Manual Section 4.4)	9/29/21	13,830.6	11,501.0	9/29/22			132						12 mths		
0507020	Garmin GTN 750 Bonding Check (Per GTN manual section 4.5)	6/16/21	13,713.4	11,390.0	6/16/31	15,713.4		3,314	1,760.7					120 mths	2,000.0	
0507030	Garmin GDL 69 Visual Inspection (Per GDI manual pg 4-3)	9/29/21	13,830.6	11,501.0	9/29/22			132						12 mths		
0507040	Garmin GDL 69 Electrical Bonding Check (G DL manual pg 4-4)	6/16/21	13,713.4	11,390.0	6/16/31	15,713.4		3,314	1,760.7					120 mths	2,000.0	
0508010	FAR 91.411 RVSM IFR Static Ck	9/28/20	13,459.3	11,223.0	9/28/22			131						24 mths		
0508020	FAR91.413 Xponder RVSM Ck	9/28/20	13,459.3	11,223.0	9/28/22			131						24 mths		
0508025	RVSM Inflight Auto Pilot Altitude Hold Ck (Task 8)( Weststar)	9/30/20	13,465.8	11,225.0	9/30/22			133						24 mths		
0508050	RVSM 24 Month Inspection	9/28/20	13,459.3	11,223.0	9/28/22			131						24 mths		
0508060	RVSM 96 Month Inspection	7/13/20	13,343.3	11,106.0	7/13/28			2,246						96 mths		
0508065	RVSM 144 Month Inspection	8/2/16	11,702.3	9,592.0	8/2/28			2,266						144 mths		
0508070	RVSM Left Pitot Probe Replace	5/4/18	12,518.5	10,305.0		14,664.9			712.2						10,000.0	
0508075	RVSM Right Pitot Probe Replace	8/9/04	7,361.3	5,665.0		17,361.3			3,408.6						10,000.0	
0508100	Weigh Aircraft	7/13/20	13,343.3	11,106.0	7/13/23			419						36 mths		
0508200	Yearly Avionics Check	9/29/21	13,830.6	11,501.0	9/29/22			132						12 mths		
0508300	Port Firex Monthly Check	12/29/21	13,949.9	11,577.0	1/29/22			-111						1 mths		
0508400	Cockpit Firex Weight Check	11/24/21	13,931.9	11,566.0	11/24/22			188						12 mths		
0509200	Engine Deec Download	11/24/21	13,931.9	11,561.0	12/24/21			-147						1 mths		
1222002 G	#1 Lead Acid Batt Check	11/24/21	13,931.9	11,566.0	5/24/22			4						6 mths		
1222002 G	# 2 Lead Acid Batt Check	11/24/21	13,931.9	11,566.0	5/24/22			4						6 mths		
1223010 D	Primary Emer Power Supply Ck (6 Month)	9/1/21	13,788.3	11,465.0	3/1/22			-80						6 mths		
1223010 D	Secondary Emer power Supply Ck (6 month)	9/29/21	13,830.6	11,501.0	3/29/22			-52						6 mths		
1223015 D	Primary Emer Power Supply Ck (12 Month)	2/23/21	13,608.2	11,315.0	2/23/22			-86						12 mths		
1223015 D	Secondary Emer power Supply Ck (12 month)	9/29/21	13,830.6	11,501.0	9/29/22			132						12 mths		
2130007 H	Cabin Leak Rate Check	10/20/21	13,877.9	11,536.0		15,077.9			1,125.2						1,200.0	

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
2431015 C	Lt Bendix Generator Ovhl ( S/N 1361)	12/29/21	13,949.9	11,577.0		15,949.9			1,997.2						2,000.0	
2431015 C	Rt Bendix Generator Ovhl (S/N 1434)	8/18/20	13,409.3	11,165.0		15,409.3			1,456.6						2,000.0	
2431016 C	Lt Bendix Gen Bearing Replace (S/N 1361)	12/29/21	13,949.9	11,577.0		14,999.9			1,047.2						1,050.0	
2431016 C	Rt Bendix Gen Bearing Replace(S/N 1434)	2/18/20	13,409.3	11,315.0		14,459.3			506.6						1,050.0	
2431017 H	Battery Connector Inspection	9/1/21	13,788.3	11,465.0		14,088.3			135.6						300.0	
2431030 E	Lt Gen Drive Spline Insp & Lub	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0	
2431030 E	Rt Gen Drive Spline Insp & Lub	7/1/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0	
2431045 G	Rt Ess A & B Bus (40 Amp) CB	7/3/17	11,983.6	9,836.0	1/22/30		15,836.0	2,804		4,256.0				144 mths		6,000.0
2431047 G	Lt Ess A & B Bus (40 Amp) CB	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths		6,000.0
2431049 G	Main Bus Tie(50 Amp)CB	7/3/17	11,983.6	9,836.0	1/22/30		15,836.0	2,804		4,256.0				144 mths		6,000.0
2432010 B	Main Battery Instalation Insp (6 Month)	9/1/21	13,788.3	11,465.0	3/1/22				-80					6 mths		
2561000	Inspect Life Vest	8/18/17	12,040.2	9,917.0	8/18/22				90					60 mths		
2561005	Inspect Life Vest	8/18/17	12,040.2	9,917.0	8/18/22				90					60 mths		
2561010	Inspect Life Vest	8/18/17	12,040.2	9,917.0	8/18/22				90					60 mths		
2561015	Inspect Life Vest	8/18/17	12,040.2	9,917.0	8/18/22				90					60 mths		
2561020	Inspect Life Vest	8/18/17	12,040.2	9,917.0	8/18/22				90					60 mths		
2561025	Inspect Life Vest	9/6/17	12,058.0	9,939.0	9/6/22				109					60 mths		
2561030	Inspect Life Vest	9/6/17	12,058.0	9,939.0	9/6/22				109					60 mths		
2561035	Inspect Life Vest	9/6/17	12,058.0	9,939.0	9/6/22				109					60 mths		
2561040	Inspect Life Vest	9/6/17	12,058.0	9,939.0	9/6/22				109					60 mths		
2561045	Inspect Life Vest	9/6/17	12,058.0	9,939.0	9/6/22				109					60 mths		
2561050	Inspect Life Vest	9/6/17	12,058.0	9,939.0	9/6/22				109					60 mths		
2561060	Life Raft (EAM 4 Man)	6/14/16	11,643.2	9,537.0	6/30/17				-1,785					12 mthe		
2561070	Life Raft (EAM 4 Man)(S/N TV04111)	10/15/21	13,857.2	11,520.0	10/31/22				164					12 mthe		
2561080	Life Raft (EAM 6 Man)	3/30/21	13,640.7	11,348.0	3/31/22				-50					12 mthe		
2561090	Life Raft (EAM T6 Man) (S/N TAN06015)	10/20/21	13,893.6	11,545.0	10/20/22				153					12 mths		
2561100	Life Raft (EAM T9 Man)(S/N TAN 09010)	9/30/21	13,857.2	11,520.0	9/30/22				133					12 mths		
2561110	Life Raft (EAM T9 Man)(S/N TAN 09011)	11/2/21	13,893.6	11,545.0	11/2/22				166					12 mths		
2561120	Life Raft (Goodrich 10/15 Man)	11/30/21			11/30/22				194					12 mths		
2561130	Life Raft (Goodrich 10/15 Man)	11/30/21			11/30/22				194					12 mths		

\* Interval -- dys = days, mths = months, yrs = years, mthe = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
256200	First Aid Kit Inspection	7/2/21	13,731.5	11,406.0	7/2/22			43						12 mths		
2563001	ELT F/T & ELT Batt Insp	7/15/21	13,739.6	11,419.0	7/15/22			56						12 mths		
2563010	ELT Battery Replace	5/24/19	12,904.2	10,703.0	7/13/24			785						60 mths		
2563020	ELT Beacon Registration Renewal	5/26/21	13,693.8	11,380.0	5/26/23			371						24 mths		
2564000	CVR Annual Check	7/15/21	13,739.6	11,419.0	7/15/22			56						12 mths		
2565000 AA	CVR ULB F/T, Clean & Test Batt	3/9/21	13,613.4	11,322.0	3/9/23			293						24 mths		
2566000 F	CVR ULB Battery Replace	3/9/21	13,613.4	11,322.0	6/9/28			2,212						87 mths		
2567010	TCAS 1 600/24 month Insp Per 337 Dated 8/6/04	9/1/21	13,788.3	11,465.0	9/1/23	14,388.3		469	435.6					24 mths	600.0	
2567020	TCAS 1 Antenna Insp Cracks & Corrosion Per 337 Dated 8/6/04	11/24/21	13,931.9	11,566.0	11/24/29	16,331.9		2,745	2,379.2					96 mths	2,400.0	
2567030	TCAS KA-815 Lower Antenna Feedthru Eddy Current Insp Per 337	8/6/04	7,361.3			17,361.3			3,408.6						10,000.0	
2567040	TCAS FWD Bulkhead Feedthru Eddy Current Insp Per 337 Dated 8/6/4	8/6/04	7,361.3			37,361.3			23,408.6						30,000.0	
25680010	WAAS/XM Antenna Detailed Visual Insp (Per 337 dated 11/24/15)	11/25/15	11,414.0	9,348.0						7,768.0						10,000.0
25680020	Omni Antenna Install FS 397 Eddy Current (per 337 date 11/24/15)	11/25/15	11,414.0	9,348.0						2,518.0						4,750.0
2610020 U	Lt Eng Fire Det Elem Insp	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0	
2610020 U	Rt Eng Fire Det Elem Insp	7/1/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0	
2620025 Q	Hydro Test Lt Eng Fire-X	5/24/19	12,904.2	10,703.0	5/24/24			735						60 mths		
2620025 Q	Hydro Test Rt Eng Fire-X	5/24/19	12,904.2	10,703.0	5/24/24			735						60 mths		
2620030 C	Hydro Test Cockpit Port Firex	12/17/14	11,027.4	8,978.0	12/17/26			1,672						144 mths		
2620040 V	Lt Eng Fire Ext Cartridge Replace	5/13/20	13,170.9	10,979.0	5/13/26			1,454						72 mths		
2620040 V	Rt Eng Fire Ext Cartridge Replace	5/13/20	13,170.9	10,979.0	5/13/26			1,454						72 mths		
2620042 P	Ck Eng Fire Bottles (6 Mouth)	9/1/21	13,788.3	11,465.0	3/1/22			-80						6 mths		
2710009 F	Aileron Primary Control Cables Replace	9/21/16	11,704.5	9,596.0		14,104.5			151.8						2,400.0	
2710010 E	Aileron Lt/Rt Drive Yoke Bolts Replace	11/11/16	11,784.4	9,665.0		15,384.4			1,431.7						3,600.0	
2710014 E	Aileron Lt/Rt Cent Hinge Bolts Replace	11/11/16	11,784.4	9,665.0		15,384.4			1,431.7						3,600.0	
2710016 G	Aileron Assy Lt & Rt Replace	10/17/80				20,000.0			6,047.3						20,000.0	
2710020 E	Aileron Lt & Rt Clevis Bolts Replace	3/8/90	1,490.2			21,490.2			7,537.5						20,000.0	
2710021 M	Aileron Lt & Rt Inbrd & Outbrd Hinge Bolts Replace	10/17/80				20,000.0			6,047.3						20,000.0	

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
2710023 E	Aileron Pulley Assy Lt & Rt Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2710025 E	Aileron Clevis Lt & Rt Replaced	10/17/80				20,000.0				6,047.3					20,000.0	
2710027 E	Aileron Yoke Assy Lt & Rt Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2710029 E	Aileron Bearing SupportLt & Rt Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2710031 E	Aileron Hinge Bracket Lt & Rt Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2720012 F	Rudder Primary Control Cables Replace	9/21/16	11,704.5	9,596.0		14,104.5				151.8					2,400.0	
2720018 E	Rudder Assy Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2720021 E	Rudder Hinge Bolts Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2720023 E	Rudder Lower Bearing Assy Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2720024 E	Rudder Hinge Assembly, Upper Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2720025 E	Rudder Hinge Assembly, Center Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2730015 F	Elev Primary Control Cable Replace	9/21/16	11,704.5	9,596.0		14,104.5				151.8					2,400.0	
2730016 E	Lt Elevator Assy Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2730016 E	Rt Elevator Assy Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2730020 E	Elev Hinge Bracket Outbrd, Center, Inbrd on Horz Stab	10/17/80				20,000.0				6,047.3					20,000.0	
2730021 E	Elevator Bellcranks Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2730023 E	Elevator Dual Push-Pull Tubes	10/17/80				20,000.0				6,047.3					20,000.0	
2730024 E	Elevator Hinge Bolts Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2730027 R	Elevator Downspring Assy Attach Bolt Replace	7/1/17	11,983.6	9,836.0	1/20/30		15,836.0	2,802			4,256.0			144 mths		6,000.0
2730033 AB	Lt & Rt Control Column Fluorescent Pentetrant Inspection		11,704.5			14,104.5				151.8					2,400.0	
2730036 AB	Elevator Bellcrank Eddy Current Inspection	11/24/21	13,920.9	11,561.0	11/24/29	16,320.9		2,745		2,368.2				96 mths	2,400.0	
2740010 E	Horz Stab Hinge Pin Replace	10/11/80				20,000.0				6,047.3					20,000.0	
2740011 G	Horz Stab Actuator Attach Bolts Replace	9/21/16	11,704.5	9,596.0	9/21/28		15,596.0	2,316			4,016.0			144 mths		6,000.0
2740021 Q	Horizontal Stab Actuator Ovhl	6/15/21	13,716.0	11,389.0		14,316.0				363.3					600.0	
2750002 E	Flap Nose Roller Bushings Replace	10/20/21	13,877.9	11,536.0		15,077.9				1,125.2					1,200.0	
2750017 F	Flap Inbrd Hinge Fitting on Flaps Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2750019 F	Flap Outbrd Hinge Fitting on Flap Replace	10/17/80				20,000.0				6,047.3					20,000.0	
2750021 E	Flap Inbrd/Outbrd Track Assy Lt & Rt Replace	10/17/80				20,000.0				6,047.3					20,000.0	

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *			
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES	
2750023 E	Flap Lt Inbrd Nose Roller Track Replace	10/17/80				20,000.0			6,047.3						20,000.0		
2750023 E	Flap Rt Inbrd Nose Roller Track Replace	6/21/06	7,926.4			27,926.4			13,973.7						20,000.0		
2750024 E	Flap Lt Otbrd Nose Roller Track Replace	10/17/80				20,000.0			6,047.3						20,000.0		
2750024 E	Flap Rt Otbrd Nose Roller Track Replace	10/17/80				20,000.0			6,047.3						20,000.0		
2750034 G	Flap Sector Mounting Bolt Replace	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths			6,000.0
2750044 H	Flap Cam Follower Bearings Visual	10/20/21	13,877.9	11,536.0		15,077.9			1,125.2						1,200.0		
2750058 Z	Flap Nose Roller Support Arm & Leading Edge Rib Replace	9/19/18	12,651.9	10,444.0			13,444.0			1,864.0							3,000.0
2760066 E	Spoiler Lt&Rt 1/4" Actuator Bolt Replace	7/19/10	8,991.2	6,982.0		17,991.2			4,038.5						9,000.0		
2760067 E	Spoiler Lt&Rt 5/16 Attach Bolts Replace	7/19/10	8,991.2	6,982.0		17,991.2			4,038.5						9,000.0		
2760068 E	Spoiler Lt & Rt 5/16" Pivot Bolt Replace	7/19/10	8,991.2	6,982.0		17,991.2			4,038.5						9,000.0		
2760069 E	Spoiler Assy Lt & Rt Replace	9/19/18	12,651.9	10,444.0		19,764.8			5,812.1						9,000.0		
2760071 E	Spoiler Actuator Arm Lt & Rt Replace	7/19/10	8,991.2	6,982.0		17,991.2			4,038.5						9,000.0		
2760075 E	Spoiler Lt & Rt Actuator Assy Replace	10/17/80				20,000.0			6,047.3						20,000.0		
2760076 E	Spoiler Lt&Rt Actuator Fitting and Bolt Replace	10/17/80				20,000.0			6,047.3						20,000.0		
2812003 M	Insp Outbrd Wing Tank by Tip Tank	2/20/20	13,164.6	10,975.0	2/20/22			-89						24 mths			
2812011 R	Tip Tank Inspection	2/20/20	13,164.6	10,975.0	2/20/22			-89						24 mths			
2812020 L	Insp Wing Tank WS 72	2/20/20	13,164.6	10,975.0	2/20/22			-89						24 mths			
2820002 G	Fuel Hoses Except Eng Nacelle	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths			6,000.0
2900001 G	Hyd Hoses Except LDG & Eng comp	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths			6,000.0
3020001 U	Lt Eng Nacelle Insp	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0		
3020001 U	Rt Eng Nacelle Insp	7/1/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0		
3200010	Left Main Landing Gear Tires	5/25/21	13,681.5	11,372.0													
3200020	Right Main Landing Gear Tires	10/13/21	13,857.2	11,520.0													
3200030	Left Main Landing Gear Brakes	8/18/20	13,409.3	11,165.0													
3200040	Right Main Landing Gear Brakes	10/13/21	13,857.2	11,520.0													
3210003 G	Hyd Hoses On Landing Gear (Teflon Installed)	2/28/08	8,299.5	6,354.0													
3211080 E	Lt & Rt Main Gear Actuator Pillar Assy Replace	10/17/80					18,000.0			6,420.0							18,000.0
3211082 E	Nose Gear Strut Replace	10/17/80					20,000.0			8,420.0							20,000.0

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
3211083 E	Nose Gear Actuator Replace	12/18/03		5,530.0			22,507.0			10,927.0						20,000.0
3211084 E	Lt & Rt Main Gear Actuator Attach Pin Replace (P/N 541101)	6/21/06	7,926.4	6,096.0			26,096.0			14,516.0						20,000.0
3211087 E	Main Gear Actuator Lt Replace	6/21/06		6,096.0			20,017.0			8,437.0						20,000.0
3211087 E	Main Gear Actuator Rt Replace	4/9/04		5,616.0			22,143.0			10,563.0						20,000.0
3211099 Q	LT Main Gear Strut Replace (Upper Cylinder )	8/17/04	7,368.3	5,672.0			22,172.0			10,592.0						16,500.0
3211099 Q	LT Main Gear Strut Replace (Lower Piston Assy)	10/17/80					16,500.0			4,920.0						16,500.0
3211099 Q	Rt Main Gear Strut Replace (Upper Cylinder )	12/17/14	11,027.4	8,978.0			25,478.0			13,898.0						16,500.0
3211099 Q	Rt Main Strut Replace (Lower Piston Assy)	10/17/80					16,500.0			4,920.0						16,500.0
3211102 V	Lt & Rt Main Landing Gear Torque Links Replace (P/N 23411119)	7/22/14	10,843.6	8,784.0			14,784.0			3,204.0						6,000.0
3233013 L	Emer Air Hoses Gear & Brakes Replace	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths		6,000.0
3243040 G	Hyd Brake Hoses On Strut & In Wheel Well Replacel (Teflon)	1/27/11	9,261.8	7,227.0												
3244024 R	RH Gear Down Safety Switch & Anti-Skid Contacts Functional Test	9/1/21	13,788.3	11,465.0			14,988.3			1,035.6					1,200.0	
3255001 C	Nose Steering Act 2000 Hr Insp	1/17/19	12,763.8	10,553.0			14,611.0			658.3					2,000.0	
3500016 R	Hydro Ck Oxygen Cylinder (DOT3AA1800)	7/3/17	11,983.6	9,836.0	4/14/22				-36					60 mths		
3510021 P	EROS Lt & Rt Oxy Mask Overhaul	9/21/16	11,704.5	9,596.0	7/30/22				71					72 mths		
3610006 R	Vis/Hydro Check Emergency Air Bottle	7/17/19	12,963.1	10,767.0	7/17/25				1,154					6 yrs		
3610045 P	Lt Eng Bleed Air Hose Ins	9/19/18	12,651.9	10,444.0			14,751.9			799.2					2,100.0	
3610045 P	Rt Eng Bleed Air Hose Ins	7/1/17	11,983.6	9,836.0			14,083.6			130.9					2,100.0	
3610055 R	12 Year X-Ray Inspection Emergency Air Bottle	7/29/05														
3610055 R	24 Year X-Ray Inspection Emergency Air Bottle	10/1/93	5,061.5													
3610055 R	30 Year X-Ray Insp Emergency Air Bottle	6/1/99			6/1/29				2,569					30 yrs		
3610056 R	Scrap Emergency Air Bottle (40 YR)	6/1/99	5,061.5		6/1/39				6,221					40 yrs		
5210025 L	Fuse Door Cut-out, Cabin Struc	7/15/21	13,739.6	11,419.0	7/15/23				421					24 mths		
5320006 J	Aft Pressure Bulkhead Insp	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths		6,000.0
5322000 T	Keelbeam Attach Bolts Replace	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths		6,000.0

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
5331014 W	(12 Yr) Upper Fuselage Skin Under Aft Oxygen Line Fairing Insp	3/3/16			3/3/28			2,114						144 mths		
5450043 J	Lt Pylon/Engine Fwd Beam Structure Insp	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0	
5450043 J	Rt Pylon/Engine Fwd Beam Structure Insp	7/3/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0	
5450044 H	Lt Engine Beam Support Fittings Eddy Current	7/3/17	11,983.6	9,836.0	7/3/29		15,836.0	2,601		4,256.0				144 mths		6,000.0
5450044 H	Rt Engine Beam Support Fittings Eddy Current	7/1/17	11,983.6	9,836.0	7/1/29		15,836.0	2,599		4,256.0				144 mths		6,000.0
5450045 J	Lt Pylon/Engine Aft Beam Support Structure Insp	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0	
5450045 J	Rt Pylon/Engine Aft Beam Support Structure Insp	7/3/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0	
56120023 G	Windshield Prism Check (600 Hr) One Time insp	1/23/10	8,845.2	6,857.0												
5710145 P	Insp Wing Inbrd Dry Bay	2/20/20	13,164.6	10,975.0	2/20/22			-89						24 mths		
5750046 H	Flap Track Support Fit Visual	2/20/20	13,164.6	10,975.0		14,364.6			411.9						1,200.0	
7110021 G	Fuel Hoses In Eng Nacelle Area (Teflon)	1/27/11	9,261.8	7,227.0												
7110022 G	Hyd Hoses In Eng Nacelle Area (Teflon)	1/27/11	9,261.8	7,227.0												
7120024 E	Lt Eng Mount Castings Insp	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0	
7120024 E	Rt Eng Mount Castings Insp	7/3/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0	
7120029 E	Fwd Mount Castings (Mag Partical Insp) Lt & Rt	7/3/17	11,983.6	9,836.0	7/3/29			2,601						144 mths		
7120029 E	Fwd Mont Casting Attach Bolts (Mag Part) Lt & Rt	7/3/17	11,983.6	9,836.0	7/3/29			2,601						144 mths		
7120029 E	FWD Up & Low Shock Mount To Eng Attach Bolts (Mag Part) Lt&Rt	7/3/17	11,983.6	9,836.0	7/3/29			2,601						144 mths		
7120029 E	Aft Mount & Attach Bolt (Mag Part) Lt&Rt	7/3/17	11,983.6	9,836.0	7/3/29			2,601						144 mths		
7120029 E	Aft Mount Isolator Assy Attach Bolts (Mag Part) Lt&Rt	7/3/17	11,983.6	9,836.0	7/3/29			2,601						144 mths		
7120036 K	Lt Eng Fwd Shock Mount Covers Replace(L M-833-3)	10/31/13	10,499.2	8,464.0		14,699.2			746.5						4,200.0	
7120036 K	Rt Eng Fwd Shock Mnt Covers Replace (LM -833-3)	11/25/15	11,414.0	9,348.0		14,608.0			655.3						4,200.0	
7120037 L	Lt Eng Aft Isolator Assy Replace	7/3/17	11,983.6	9,836.0		19,164.9			5,212.2						8,400.0	
7120037 L	Rt Eng Aft Isolator Assy Replace	7/3/17	11,983.6	9,836.0		19,920.1			5,967.4						8,400.0	
7120038 E	Lt Eng Fwd Mount Attach Bolts	10/17/80				20,000.0			6,047.3						20,000.0	

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end



## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *			
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES	
7120038 E	Rt Eng Fwd Mount Attach Bolts	10/17/80				20,000.0			6,047.3						20,000.0		
7120039 E	Lt Eng Aft Eng Attach Bolts	2/21/97	3,462.6			23,462.6			9,509.9						20,000.0		
7120039 E	Rt Eng Aft Eng Attach Bolts	10/17/80				20,000.0			6,047.3						20,000.0		
7120040 V	Lt Eng Fwd Up/Lwr Shock Support Bolt Replace	10/17/80				20,000.0			6,047.3						20,000.0		
7120040 V	Rt Eng Fwd Up/Lwr Shock Support Bolt Replace	10/17/80				20,000.0			6,047.3						20,000.0		
7120041 E	Lt Eng Aft Shock Mount Attach Bolt Replace	10/17/80				20,000.0			6,047.3						20,000.0		
7120041 E	Rt Eng Aft Shock Mount Attach Bolt Replace	10/17/80				20,000.0			6,047.3						20,000.0		
7120063 Q	Lt Fwd/Aft Eng Mnt Isolat Insp	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0		
7120063 Q	Rt Fwd/Aft Eng Mnt Isolat Insp	7/3/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0		
7120064 K	Lt Eng Fwd Shock Mount Bolts Replace (Cover Bolts)	10/31/13	10,499.2	8,464.0		14,699.2			746.5						4,200.0		
7120064 K	Rt Eng Fwd Shock Mount Bolts Replace (Cover Bolts)	7/3/17	11,983.6	9,836.0		13,894.2			-58.5						4,200.0		
7120065 L	Lt Eng Upper Fwd Shock Mount Mounting Assy Replace(LM-833-1)	4/19/08	8,367.3	6,402.0		15,475.5			1,522.8						8,400.0		
7120065 L	Lt Eng Lower Fwd Shock Mount Mounting Assy Replace(LM-833-1)	4/19/08	8,367.3	6,402.0		15,475.5			1,522.8						8,400.0		
7120065 L	Rt Eng Upper Fwd Shock Mount Mounting Assy Replace(LM-833-1)	11/25/15	11,414.0	9,348.0		14,114.4			161.7						8,400.0		
7120065 L	Rt Eng Lower Fwd Shock Mount Mounting Assy Replace(LM-833-1)	11/25/15	11,414.0	9,348.0		14,114.4			161.7						8,400.0		
7120066 L	Rt Eng Fwd Upr Sck Mnt Housing (LM-833-2)	11/25/15	11,414.0	9,348.0		14,114.4			161.7						8,400.0		
7120066 L	Rt Eng Fwd Lwr Sck Mnt Housing(LM-833-2)	11/25/15	11,414.0	9,348.0		14,114.4			161.7						8,400.0		
7120066 L	Lt Eng Fwd Upr Sck Mnt Housing(LM-833-2)	4/19/08	8,367.3	6,402.0		15,475.5			1,522.8						8,400.0		
7120066 L	Lt Eng Fwd Lwr Sck Mnt Housing(LM-833-2)	4/19/08	8,367.3	6,402.0		15,475.5			1,522.8						8,400.0		
7120067 T	Lt Aft Eng Att Bolt Fluorescent Penetrant Insp	9/19/18	12,651.9	10,444.0		14,751.9			799.2						2,100.0		
7120067 T	Rt Aft Eng Att Bolt Fluorescent Penetrant Insp	7/3/17	11,983.6	9,836.0		14,083.6			130.9						2,100.0		
72-10-010	Left Fan Rotor Disc and Hub	9/24/11	9,238.2	7,261.0			12,295.0			1,130.0							10,000.0
72-10-020	Lt Axial Comp Disc 1st Stage	9/24/13	10,045.5	8,050.0			18,050.0			6,885.0							10,000.0
72-10-030	Lt Axial Comp Disc 2nd Stage	9/24/13	10,045.5	8,050.0			28,050.0			16,885.0							20,000.0

\* Interval -- dys = days, mths = months, yrs = years, mthe = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
72-10-040	Lt Axial Comp Disc 3rd Stage	9/24/13	10,045.5	8,050.0			18,050.0			6,885.0						10,000.0
72-10-050	Lt Axial Comp Disc 4th Stage	9/24/13	10,045.5	8,050.0			28,050.0			16,885.0						20,000.0
72-10-070	Lt Comp Radial Impeller HP	9/24/13	10,045.5	8,050.0			18,050.0			6,885.0						10,000.0
72-10-075	Lt HPC Shaft	9/24/13	10,045.5	8,050.0			20,050.0			8,885.0						12,000.0
72-10-080	Lt Disc HP Turbine	9/24/13	10,045.5	8,050.0			18,050.0			6,885.0						10,000.0
72-10-090	Lt HPT Rotor Seal Plate	9/24/13	10,045.5	8,050.0			18,050.0			6,885.0						10,000.0
72-10-100	Lt 1st Stage LP Turb Rotor Dis	9/24/13	10,045.5	8,050.0			12,450.0			1,285.0						4,400.0
72-10-110	Lt 2st Stage LP Turb Rotor Dis	9/24/13	10,045.5	8,050.0			12,550.0			1,385.0						4,500.0
72-10-120	Lt 3rd Stage LP Turb Rotor Dis	9/24/13	10,045.5	8,050.0			17,550.0			6,385.0						9,500.0
72-20-010	Rt Fan Rotor Disc And Hub	5/17/96	2,945.1	2,260.0			12,260.0			1,183.0						10,000.0
72-20-020	Rt Axial Comp Disc 1st Stage	1/12/12	9,276.0	7,269.0			17,269.0			6,192.0						10,000.0
72-20-030	Rt Axial Comp Disc 2nd Stage	1/12/12	9,276.0	7,269.0			27,269.0			16,192.0						20,000.0
72-20-040	Rt Axial Comp Disc 3rd Stage	1/12/12	9,276.0	7,269.0			17,269.0			6,192.0						10,000.0
72-20-050	Rt Axial Comp Disc 4th Stage	1/12/12	9,276.0	7,269.0			27,269.0			16,192.0						20,000.0
72-20-070	Rt Comp Radial Impeller HP	1/12/12	9,276.0	7,269.0			17,269.0			6,192.0						10,000.0
72-20-075	Rt HPC Shaft	1/12/12	9,276.0	7,269.0			19,269.0			8,192.0						12,000.0
72-20-080	Rt Disc HPT	1/12/12	9,276.0	7,269.0			17,269.0			6,192.0						10,000.0
72-20-090	Rt HPT Rotor Seal Plate	1/12/12	9,276.0	7,269.0			17,269.0			6,192.0						10,000.0
72-20-100	Rt 1st Stage LP Turb Rotor Dis	1/12/12	9,276.0	7,269.0			11,669.0			592.0						4,400.0
72-20-110	Rt 2nd Stage LP Turb Rotor Dis	1/12/12	9,276.0	7,269.0			11,769.0			692.0						4,500.0
72-20-120	Rt 3rd Stage LP Turb Rotor Dis	5/4/17	11,469.6	9,334.0			16,972.0			5,895.0						9,500.0
7611001 E	Lt Eng F/T Fuel Computer ITT	9/19/18	12,651.9	10,444.0			14,751.9			799.2						2,100.0
7611001 E	Rt Eng F/T Fuel Computer ITT	7/3/17	11,983.6	9,836.0			14,083.6			130.9						2,100.0
7810005 U	Lt Eng Exhaust Nozzle Insp	9/19/18	12,651.9	10,444.0			14,751.9			799.2						2,100.0
7810005 U	Rt Eng Exhaust Nozzle Insp	7/3/17	11,983.6	9,836.0			14,083.6			130.9						2,100.0
8010004 E	Lt Eng Starter Oil Change	9/19/18	12,651.9	10,444.0			14,751.9			799.2						2,100.0
8010004 E	Rt Eng Starter Oil Change	7/3/17	11,983.6	9,836.0			14,083.6			130.9						2,100.0
99-04-0308	AD 04-03-08 Forward Engine Beam Shear Web inspection	6/27/19	12,941.8	10,745.0			14,141.8			189.1						1,200.0
99-07-0418	AD 07-04-18 Fuel Pump Switch	6/27/08	8,412.2	6,436.0												

\* Interval -- dys = days, mths = months, yrs = years, mths = months - end

## VENTURA AIR SERVICES AIRCRAFT STATUS SHEET

<b>Tail Number: N136JP</b>		Hours and Cycles reading: 5/20/2022		
MANUFACTURER	MODEL	SERIAL #	HOURS	CYCLES
Learjet	Learjet 35A	35A-359	13,952.7	11580.0
		ENGINE 1	13,499.0	11165.0
		ENGINE 2	13,438.7	11077.0

ATA CODE	DESCRIPTION	LAST COMPLIED WITH			NEXT DUE			REMAINING			REMAINING WITH GRACE			INTERVAL *		
		DATE	HOURS	CYCLES	DATE	HOURS	CYCLES	DAYS	HOURS	CYCLES	DAYS	HOURS	CYCLES	DATE	HOURS	CYCLES
99-18-1904	AD 18-19-04 Flap Nose Roller Sup Arm & Leading Edge Rib Replace	9/19/18	12,651.9	10,444.0												
99-74-0809	AD 74-08-09 R3 Acft Lavatory Ins	12/29/21	13,949.9	11,577.0		14,949.9			997.2						1,000.0	
99-82-0105	AD 82-01-05 R2 Stall Warning Accelerometer Check	9/1/21	13,788.3	11,465.0		14,113.3			160.6						325.0	
GPS Data Base	GPS Data Base Update	12/29/21	13,949.9	11,577.0	1/19/22			-121						28 dys		
Registration	Aircraft Registration Renewal	9/14/19	13,030.4	10,856.0	9/30/22			133						36 mthe		
Soap Check	Right Engine Soap Check Base Line	5/3/21	13,147.7	10,858.0												
VOR30DAY	VOR/VOT 30 Day Check	1/22/22	8,266.2	6,331.0	2/21/22			-88						30 dys		

\* Interval -- dys = days, mths = months, yrs = years, mthe = months - end