

Status Report

**LEARJET 60 (EMP)
S/N 60 232 N211BD**

OWNER: KONFARA COMPANY, LLC
ADDRESS: 20225 SCOTTSDALE ROAD
 SCOTTSDALE AZ 85255-6456
PHONE: 480-948-2910
FAX: 480-948-4639

OPERATOR: DISCOUNT TIRE FLIGHT DEPARTMENT
ADDRESS: 15050 N. 78TH WAY
 SCOTTSDALE AZ 85260
PHONE: 480-948-2910
FAX: 480-948-4639

ANALYST: LANCE HAYDEN
EMAIL: LHAYDEN@CAMPSYSTEMS.COM

+1-316-462-2408 (DIRECT)
 1-866-581-2267 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 60 232/N211BD **MODEL:** LEARJET 60 (EMP) **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 27-JUN-2001	6774.5 A/C HRS	as of 31-MAR-2020	_____ A/C HRS	as of ____/____/____
	5614 AFL	as of 31-MAR-2020	_____ AFL	as of ____/____/____
	2990 APH	as of 31-MAR-2020	_____ APH	as of ____/____/____
	1492 ACH	as of 13-MAR-2020	_____ ACH	as of ____/____/____

APU SERIAL/PART: SP-E010353/4503135 **MODEL:** T-20G-10C3A (CIMMS) **MANUFACTURER:** HAMILTON SUNDSTRAND CORPORATION

INSTALLED ON 05-DEC-2018	LAST ACTUALS		CURRENT ACTUAL	
2780 APU HRS	2990 APU HRS	as of 31-MAR-2020	_____ APU HRS	as of ____/____/____
5816 APUS	6348 APUS	as of 31-MAR-2020	_____ APUS	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: PCE-CA0307/31B4067-04 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 20-AUG-2017		LAST ACTUALS		CURRENT ACTUAL	
5900.1 ENG. HRS	5651.6 A/C HRS	6723 ENG. HRS	as of 31-MAR-2020	_____ ENG. HRS	as of ____/____/____
4746 ENC		5567 ENC	as of 31-MAR-2020	_____ ENC	as of ____/____/____

ENGINE NO. 2 SERIAL/PART: PCE-CA0308/31B4067-04 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 20-AUG-2017		LAST ACTUALS		CURRENT ACTUAL	
5904.2 ENG. HRS	5951.6 A/C HRS	6727.1 ENG. HRS	as of 31-MAR-2020	_____ ENG. HRS	as of ____/____/____
4747 ENC		5568 ENC	as of 31-MAR-2020	_____ ENC	as of ____/____/____



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
000001 EMP	12 MONTH SERVICE AND CONDITION CHECK							
	PKG 40	MOS	12	+14d/-14d	-12	31-OCT-2019	19-OCT-2020	02-NOV-2020
	REF: EMP PACKAGES	HRS/MSC AFL				6654.5 5490		
000002 EMP	600 HOUR / 36 MONTH INSPECTIONS							
	PKG 41	MOS	36	+14d/-14d		31-OCT-2019	31-OCT-2022	14-NOV-2022
	REF: EMP PACKAGES	HRS/MSC AFL	600	+25/-25		6654.5 5490	7254.5	7279.5
000003 EMP	1200 HOUR / 72 MONTH INSPECTIONS							
	PKG 42	MOS	72	+14d/-14d		31-OCT-2019	31-OCT-2025	14-NOV-2025
	REF: EMP PACKAGES	HRS/MSC AFL	1200	+25/-25		6654.5 5490	7854.5	7879.5
000004 EMP	2400 HOUR / 108 MONTH INSPECTIONS							
	PKG 43	MOS	108	+14d/-14d			27-JUN-2022	11-JUL-2022
	REF: EMP PACKAGES	HRS/MSC AFL	2400	+25/-25			6982.6	7007.6
000005 EMP	36 MONTH ZONAL INSPECTIONS							
	PKG 44	MOS	36	+14d/-14d	-11	31-OCT-2019	20-OCT-2022	03-NOV-2022
	REF: EMP PACKAGES	HRS/MSC AFL				6654.5 5490		



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
000006 EMP	72 MONTH ZONAL INSPECTIONS							
	PKG 45	MOS	72				16-APR-2021	M 30-APR-2021
	REF: EMP PACKAGES	HRS/MSC AFL						
000007 EMP	108 MONTH ZONAL INSPECTIONS							
	PKG 46	MOS	108				16-APR-2024	M 30-APR-2024
	REF: EMP PACKAGES	HRS/MSC AFL						
000010 EMP	RVSM INSPECTIONS							
	PKG 47	MOS	24			19-OCT-2018	19-OCT-2020	02-NOV-2020
	REF: EMP PACKAGES	HRS/MSC AFL				6341.2 5193		
000015 EMP	3000 LANDING INSPECTION							
	PKG 48	MOS						
	REF: EMP PACKAGES	HRS/MSC AFL	3000				6000	M 6025
000016 EMP	MAJOR LANDING INSPECTION							
	PKG 51	MOS						
	REF: EMP PACKAGES	HRS/MSC AFL	6000				6000	M 6025

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
000017 EMP	12000 HOUR AIRFRAME INSPECTION							
	PKG 52	MOS						
	REF: EMP PACKAGES	HRS/MSC AFL	12000	+25/-25			12000 M	12025
000018 EMP	12 YEAR AIRFRAME INSPECTION							
	PKG 53	MOS	144	+14d/-14d			27-JUN-2025 M	11-JUL-2025
	REF: EMP PACKAGES	HRS/MSC AFL	6000	+25/-25			9269 M	9294
ENGINE NO. 1 Model : PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0307 Part # 31B4067-04								
052000	NO. 1 ENGINE - MINOR INSPECTION ITEMS							
	PKG 0	MOS	24	+14d/-14d		05-APR-2019	05-APR-2021	19-APR-2021
	REF: GENERIC NO REF	HRS/MSC ENC	600	+25/-25		6380.5	(6980.5) 7032	7005.5
						5258		
ENGINE NO. 2 Model : PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0308 Part # 31B4067-04								
052000	NO. 2 ENGINE - MINOR INSPECTION ITEMS							
	PKG 0	MOS	24	+14d/-14d		05-APR-2019	05-APR-2021	19-APR-2021
	REF: GENERIC NO REF	HRS/MSC ENC	600	+25/-25		6384.5	(6984.5) 7031.9	7009.5
						5259		
CHAPTER 12 SERVICING								
12CUS1	MONTHLY PACKAGE							
	PKG 35	DAYS	30			30-MAR-2020	29-APR-2020	
	REF:	HRS/MSC AFL				6774.5		
						5614		
CHAPTER 70 STANDARD PRACTICES - ENGINES								



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
700010	LEFT ENGINE INSPECTION-AIRFRAME ITEMS							
	PKG 29	MOS				20-AUG-2017		
		HRS/MSC	3850			5951.6		9801.6
	REF: GENERIC CUSTOM	AFL				4793		
700020	RIGHT ENGINE INSPECTION-AIRFRAME ITEMS							
	PKG 30	MOS				20-AUG-2017		
		HRS/MSC	3850			5951.6		9801.6
	REF: GENERIC CUSTOM	AFL				4793		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
CI60-161011	REVIEW LEARJET 60 EINSPECTOR REVISION 2016.10.11								
		MOS						29-OCT-2016	
		HRS/MSC -						5670.3	
REQUIREMENT CHANGE FORMS	REF: RCF CI60	AFL						4516	
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04									
EC24-160516	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0								
		MOS						22-JUN-2016	
		HRS/MSC -						5538.1	
REQUIREMENT CHANGE FORMS	REF: RCF EC24	ENC						4383	
EC24-170116	NO. 1 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2								
		MOS						(EBT)	
		HRS/MSC -							
REQUIREMENT CHANGE FORMS	REF:	ENC							
EC24-180214	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1								
		MOS						(EBT)	
		HRS/MSC -							
REQUIREMENT CHANGE FORMS	REF: RCF EC24	ENC							
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
EC24-160516	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0								
		MOS						22-JUN-2016	
		HRS/MSC -						5542.2	
REQUIREMENT CHANGE FORMS	REF: RCF EC24	ENC						4384	
EC24-170116	NO. 2 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2								
		MOS						(EBT)	
		HRS/MSC -							
REQUIREMENT CHANGE FORMS	REF:	ENC							



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-180214	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-PATS-490005	VISUALLY INSPECT ALL MOUNT PARTS AND FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE	MOS					16-OCT-2017		
	REF: SMM 49-11-03	HRS/MSC 3000 AFL					6008.7		9008.7
05-PATS-490006	PERFORM EXHAUST & INLET DOUBLER FRAMES & STRINGERS	MOS					27-JUN-2001		
	REF: SMM 49-11-03	HRS/MSC 10000 AFL APH ACH					0 0 0 0		10000
053310 (s)	PERFORM CABIN AND LIGHTING CHECK	MOS					PKG		
	PKG 35	DAYS 30 HRS/MSC					30-MAR-2020 6774.5		
CUSTOMER CODE	REF:	AFL					5614		

APU Model : T-20G-10C3A (CIMMS) Serial # SP-E010353 Part # 4503135

05-PATS-490001	APU - INSPECT APU PER MANUFACTURERS INSTRUCTIONS	MOS					31-OCT-2019		
	REF: SMM 49-11-03	HRS/MSC 200 APUS					2917		3117
05-PATS-490002	APU - VISUAL INSPECTION APU SUPPORT STRUCTURE	MOS	12				31-OCT-2019		31-OCT-2020
	REF: SMM 49-11-03	HRS/MSC APUS					2917		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-PATS-490004	APU - DETAILED INSPECTION APU SUPPORT STRUCTURE	MOS HRS/MSC APUS	3000				19-OCT-2018 2771 5794	5771	
	REF: SMM 49-11-03								
05-T20G-490001	APU - PERFORM OIL LEVEL CHECK	MOS HRS/MSC APUS	1				31-MAR-2020 2990 6348	30-APR-2020	
	REF: MM 49-20-00								
05-T20G-490002	APU - CHECK EXTERNAL FUEL AND OIL LEAKAGE, AIR INLET AND EXHAUST DUCTS FOR OBSTRUCTION AND ATTACHING BOLTS AND SCREWS FOR ATTACHMENT AND SECURITY	MOS HRS/MSC APUS	500				29-NOV-2018 2778 5810	3278	
	REF: MM 49-20-00								
05-T20G-HS-490003	APU - PERFORM APU OIL & FILTER CHANGE	MOS HRS/MSC APUS	24 500				29-NOV-2018 2778 5810	29-NOV-2020 3278	
	REF: See Workcard								
05-T20G-HS-490004	APU - VISUAL INSPECTION ENGINE HARNESS	MOS HRS/MSC APUS	500				29-NOV-2018 2778 5810	3278	
	REF: MM 49-20-00								
05-T20G-HS-490005	APU - INSPECT IGNITER PLUG 160544-1 NSN	MOS HRS/MSC APUS	500				29-NOV-2018 2778 5810	3278	
	REF: MM 49-20-00								
05-T20G-HS-490006	APU - INSPECT COMBUSTOR FUEL DRAIN LINE	MOS HRS/MSC APUS	500				29-NOV-2018 2778 5810	3278	
	REF: MM 49-20-00								



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-T20G-HS-490007	APU - INSPECT OIL OVERFILL TUBE ASSEMBLY FOR CLEANLINESS AND OBSTRUCTIONS	MOS					29-NOV-2018		
	REF: MM 49-20-00	HRS/MSC	500				2778		3278
		APUS					5810		
05-T20G-HS-490010	APU - INSPECT APU HOUSING, COVERS AND BRACKETS	MOS					29-NOV-2018		
	REF: MM 49-20-00	HRS/MSC	500				2778		3278
		APUS					5810		
05-T20G-HS-490011	APU - REPLACE FUEL INLET FILTER	MOS	24				31-MAR-2020	31-MAR-2022	
	REF: MM 49-20-00	HRS/MSC	500				2990		3490
		APUS					6348		

CHAPTER 05-50 TIME LIMITS/MAINTENANCE CHECKS

ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04

055012	NO. 1 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)	MOS					17-MAY-2001		
	REF: See Workcard	HRS/MSC	A/R				0		
		ENC					0		

UNSCHEDULED MAINTENANCE CHECK

ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04

055012	NO. 2 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)	MOS					18-MAY-2001		
	REF: See Workcard	HRS/MSC	A/R				0		
		ENC					0		

UNSCHEDULED MAINTENANCE CHECK

CHAPTER 08 LEVELING AND WEIGHING

082000	WEIGHT AND BALANCE	MOS					27-JUN-2013		
	REF: AMM 08-20-00	HRS/MSC	A/R				4582.6		
		AFL					3269		

CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1000001 EMP (s)	REVIEW MAJOR LANDING GEAR PRE-INSPECTION CHECKLIST PKG 51	MOS					PKG	27-JUN-2001	
	REF: AMM 05-10-26	HRS/MSC AFL	6000	+25/-25			0	0	
1000002 EMP (s)	REVIEW 12 YEAR AIRFRAME PRE-INSPECTION CHECKLIST PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	
	REF: AMM 05-10-27	HRS/MSC AFL	6000	+25/-25			0	0	
1000003 EMP (s)	REVIEW 12,000 HOUR PRE-INSPECTION CHECKLIST PKG 52	MOS					PKG	27-JUN-2001	
	REF: AMM 05-10-28	HRS/MSC AFL	12000	+25/-25			0	0	
CHAPTER 11 PLACARDS AND MARKINGS									
1130001 EMP (s)	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS PKG 43	MOS	108	+14d/-14d			PKG	27-JUN-2001	
	REF: AMM 11-30-00	HRS/MSC AFL	2400	+25/-25			0	0	
113013-701	EXIT PLACARD AC-12-1 239	MOS			N:0			14-DEC-2001	
	REF:	HRS/MSC AFL	O/C		N:0			18	
					N:0			14	
113013-702	EXIT PLACARD AC12LF 977	MOS			N:0			14-DEC-2001	
	REF:	HRS/MSC AFL	O/C		N:0			18	
					N:0			14	
113014-701	EXIT PLACARD AC12LF 232	MOS			N:0			14-DEC-2001	
	REF:	HRS/MSC AFL	O/C		N:0			18	
					N:0			14	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
113015-701	EXIT PLACARD AC12LF 231 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
113015-702	EXIT PLACARD AC12LF 929 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
CHAPTER 12 SERVICING									
1210053 EMP (s)	CHECK EMERGENCY AIR PRESSURE GAGE FOR PROPER AIR PRESSURE (1800 TO 3000 PSI) PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1210054 EMP (s)	CHECK OXYGEN PRESSURE GAGE FOR PROPER INFLATION (1500 TO 1850 PSI) PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1210056 EMP (s)	CHECK HYDRAULIC AND THRUST REVERSER ACCUMULATORS PRECHARGE (850 PSI) PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
+ 1210063 EMP (s)	NOSE GEAR SHOCK STRUT - SERVICE PKG 41 REF: AMM 12-10-03	MOS HRS/MSC AFL	36	+14m/-14m +25/-25			PKG 31-OCT-2019 6654.5 5490		
+ 1210064 EMP (s)	LEFT MAIN GEAR SHOCK STRUT - SERVICE PKG 41 REF: AMM 12-10-04	MOS HRS/MSC AFL	36	+14m/-14m +25/-25			PKG 31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 1210064 EMP (s)	RIGHT MAIN GEAR SHOCK STRUT - SERVICE PKG 41	MOS	36	+14m/-14m			PKG	31-OCT-2019	
	REF: AMM 12-10-04	HRS/MSC AFL	600	+25/-25			6654.5 5490		
1221001 EMP (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR ATTACH FITTING PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL					6654.5 5490		
1221002 EMP (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR PISTON ROD FELT WIPER PKG 41	MOS	36	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL	600	+25/-25			6654.5 5490		
1221003 EMP (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR DOWN-LOCK SWITCH BALL PKG 42	MOS	72	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL	1200	+25/-25			6654.5 5490		
1221004 EMP (s)	LUBRICATE HINGES ON NOSE LANDING GEAR DOORS PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL					6654.5 5490		
1221005 EMP (s)	LUBRICATE HINGES ON MAIN LANDING GEAR DOORS PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL					6654.5 5490		
1221006 EMP (s)	LUBRICATE THRUST REVERSER IDLER LINKS AND DRIVE LINKS PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-04	HRS/MSC AFL					6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1221007 EMP (s)	LUBRICATE NOSE LANDING GEAR UPLATCH ACTUATOR PISTON ROD FELT WIPERS PKG 42	MOS	72	+14d/-14d			PKG	31-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6654.5 5490		
1221008 EMP (s)	LUBRICATE MAIN LANDING GEAR DOOR ACTUATOR (48C48608) PISTON ROD FELT WIPERS PKG 42	MOS	72	+14d/-14d			PKG	31-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6654.5 5490		
1221010 EMP (s)	LUBRICATE MAIN LANDING GEAR AFT TRUNNION PIN PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL					6654.5 5490		
1221011 EMP (s)	LUBRICATE MAIN LANDING GEAR FORWARD TRUNNION PIN PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL					6654.5 5490		
1221012 EMP (s)	LUBRICATE MAIN LANDING GEAR TORQUE LINK BUSHINGS PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL					6654.5 5490		
1221013 EMP (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR STRUT ATTACH POINT PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-01	HRS/MSC AFL					6654.5 5490		
1221017 EMP (s)	LUBRICATE FLAP CAM FOLLOWERS PKG 40	MOS	12	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 12-21-02	HRS/MSC AFL					6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1221019 EMP (s)	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	N/A				PKG 31-OCT-2019 6654.5 5490		
1221020 EMP (s)	LUBRICATE SINGLE POINT REFUELING ACCESS DOOR HINGES PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221021 EMP (s)	LUBRICATE EMERGENCY EXIT/BAGGAGE DOOR HINGES AND LATCH PINS PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221023 EMP (s)	LUBRICATE TOILET SERVICING DOOR HINGE PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221024 EMP (s)	LUBRICATE TAILCONE EQUIPMENT DOOR HINGE AND LATCH PINS PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221025 EMP (s)	LUBRICATE TAILCONE BAGGAGE DOOR HINGE AND LATCH PINS PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221026 EMP (s)	LUBRICATE R/H AVIONICS DOOR(S) HINGES PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	N/A				PKG 19-OCT-2018 6341.2 5193		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1221027 EMP (s)	LUBRICATE L/H AVIONICS DOOR(S) HINGES PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	N/A				PKG 19-OCT-2018 6341.2 5193		
1221028 EMP (s)	LUBRICATE UPPER AND LOWER ENTRY DOOR HINGES AND LATCH PINS PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221029 EMP (s)	LUBRICATE LOWER NACELLE HINGES PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221030 EMP (s)	LUBRICATE OXYGEN SERVICING ACCESS DOOR HINGE PKG 40 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221036 EMP (s)	LUBRICATE SPOILER ACTUATOR PISTON ROD FELT WIPER PKG 41 REF: AMM 12-21-02	MOS HRS/MSC AFL	36	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
1221038 EMP (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) WING ATTACH POINTS PKG 40 REF: AMM 12-21-01	MOS HRS/MSC AFL	N/A				PKG 19-OCT-2018 6341.2 5193		
1221039 EMP (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 2327100) PISTON ROD FELT WIPER PKG 41 REF: AMM 12-21-01	MOS HRS/MSC AFL	N/A				PKG 20-APR-2018 6183.5 5035		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1221040 EMP (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) ACTUATOR DOWN-LOCK SWITCH BALL PKG 42 REF: AMM 12-21-01	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 20-OCT-2016 5658.5 4503		
1221041 EMP (s)	LUBRICATE THRUST REVERSERS GUIDE RODS PKG 40 REF: AMM 12-21-04	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1221043 EMP (s)	LUBRICATE NOSE LANDING GEAR TRUNNION PINS PKG 40 REF: AMM 12-21-01	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1223010-001 EMP	PERFORM OPERATIONAL CHECK NO. 1 EMERGENCY POWER BATTERY 501-1712-02 2848 REF: AMM 24-32-01	MOS HRS/MSC AFL	6	+14d/-14d			21-JAN-2020 6722.6 5565	21-JUL-2020	04-AUG-2020
1223010-002 EMP	PERFORM OPERATIONAL CHECK NO. 2 EMERGENCY POWER BATTERY 501-1712-02 2584 REF: AMM 24-32-01	MOS HRS/MSC AFL	6	+14d/-14d			21-JAN-2020 6722.6 5565	21-JUL-2020	04-AUG-2020
1223015-001 EMP	PERFORM NO. 1 EMERGENCY POWER BATTERY DISCHARGE CHECK 501-1712-02 2848 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d		-12	31-OCT-2019 6654.5 5490	19-OCT-2020	02-NOV-2020
1223015-002 EMP	PERFORM NO. 2 EMERGENCY POWER BATTERY DISCHARGE CHECK 501-1712-02 2584 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d		-12	31-OCT-2019 6654.5 5490	19-OCT-2020	02-NOV-2020

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1223030-001 EMP (s)	PERFORM NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK EMERGENCY EXIT LIGHT BATTERY SUPPLY MODULE CHARGING PROCEDURES M6088352-025 PKG 40 A00593695-01 REF: AMM 12-23-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1223030-002 EMP (s)	PERFORM NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK EMERGENCY EXIT LIGHT BATTERY SUPPLY MODULE CHARGING PROCEDURES M6088352-025 PKG 40 A0066757-01(B) REF: AMM 12-23-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
1230000 EMP (s)	CHECK FLUID LEVEL IN ALCOHOL ANTI-ICE TANK PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
205052	NO. 3 110 VOLT, AC OUTLET 106003-4 5810507 REF:	MOS HRS/MSC AFL					18-OCT-2007 2773.7 1622		
205053	110 VOLT, AC 106003-4 5760507 REF:	MOS HRS/MSC AFL					18-OCT-2007 2773.7 1622		
205056	110 VOLT, AC 106001-3 6850207 REF:	MOS HRS/MSC AFL					18-OCT-2007 2773.7 1622		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
206100	PERFORM PRECIPITATION STATIC (P-STATIC) TEST								
		MOS					18-OCT-2007		
		HRS/MSC	O/C				2773.7		
	REF:	AFL					1622		
CHAPTER 21 AIR CONDITIONING									
212001	COCKPIT AIR CHECK VALVE								
	6600423-7	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: See Workcard	AFL							
212003	LEFT CABIN AIR CHECK VALVE								
	6600423-10	MOS		N:0			27-JUN-2001		
	532	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
212004	RIGHT CABIN AIR CHECK VALVE								
	3202188-1	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: See Workcard	AFL							
212007	AFT EVAPORATOR BLOWER ASSEMBLY								
	66-0261-2	MOS		R:0			10-JUN-2016		
	K32180	HRS/MSC	O/C	R:0			5583.7		
	REF: AMM 21-51-10	AFL		R:0			4421		
212007A	INSPECT AFT EVAPORATOR BLOWER ASSEMBLY BRUSHES								
	66-0261-2	MOS					10-JUN-2016		
	K32180	HRS/MSC	O/C				5583.7		
	REF: GENERIC CUSTOM	AFL					4421		
212008	FWD EVAPORATOR BLOWER ASSEMBLY								
	66-0251-4	MOS		R:0			19-AUG-2019		
	1075AB	HRS/MSC	O/C	R:0			6611.6		
	REF: AMM 21-51-08	AFL		R:0			5456		



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2121004 EMP (s)	INSPECT POSITIVE VENTILATION CHECK VALVE PKG 48 REF: AMM 21-31-04	MOS HRS/MSC AFL	3000	+25/-25			PKG 27-JUN-2001 0 0		
212101	CABIN EVAPORATOR BLOWER 66-0261-2 6602612-014 REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C				18-MAY-2009 3347.5 2107		
212104	COCKPIT EVAPORATOR BLOWER EM607-2 SN-UNKNOWN REF: AMM 21-21-04	MOS HRS/MSC AFL	O/C						
2130005 EMP (s)	BORESCOPE INSPECT PRIMARY AND SECONDARY OUTFLOW VALVE POPPETS AND SEATS FOR CONTAMINATION PKG 43 REF: AMM 21-30-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
2130007 EMP	PERFORM CABIN LEAK RATE CHECK REF: AMM 21-30-00	MOS HRS/MSC AFL	1200	+25/-25			31-OCT-2019 6654.5 5490	7854.5	7879.5
213001	PRIMARY OUTFLOW VALVE 6600812-10 41-C0072 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
2130012 EMP (s)	PERFORM FUNCTIONAL TEST OF PRESSURIZATION SYSTEM VACUUM PUMP HEATING ELEMENT PKG 41 N/A BY A/C SERIAL NUMBER REF: AMM 21-30-12	MOS HRS/MSC AFL	N/A				PKG 20-APR-2018 6183.5 5035		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213002	SECONDARY OUTFLOW VALVE 6600812-11 31-B0258 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
213003	CABIN AIR PRESSURE SELECTOR 6600812-13 41-B0240 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
213004	CABIN PRESSURE CONTROLLER 6600812-014 31-F0231 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
213005	MANUAL PRESSURE CONTROLLER 6600812-9 1135C REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
2130064 EMP (s)	REMOVE AND REPLACE CABIN AIR FILTER PKG 42 REF: AMM 21-30-06	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25				PKG 31-OCT-2019 6654.5 5490	
2130069 EMP (s)	PERFORM OPERATIONAL CHECK OF CABIN PRESSURIZATION SYSTEM PKG 41 REF: AMM 21-30-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25				PKG 31-OCT-2019 6654.5 5490	
2130070 EMP (s)	PERFORM FUNCTIONAL TEST OF CABIN PRESSURIZATION SYSTEM PKG 43 REF: AMM 21-30-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25				PKG 27-JUN-2001 0 0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213009	EMERGENCY DEPRESSURIZATION SWITCH 95-6A-14-H6-58284 SN-UNKNOWN REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C						
213010	CABIN PRESSURE INDICATOR 6608506-004 0708A REF: AMM 21-30-10	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-JUN-2013 4582.6 3269		
213011	VACUUM REGULATOR 6600812-6 605D REF: AMM 21-30-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
213012	VACUUM PUMP 6600812-015 41-1539 REF: AMM 21-30-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
213013	VACUUM CHECK VALVE 6600812-016 21-3361 REF: AMM 21-30-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
213101	LEFT EMERGENCY PRESSURIZATION VALVE 6600252-3 845 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
2131010 EMP (s)	PERFORM FUNCTIONAL TEST OF CABIN PRESSURE WARNING SYSTEM PKG 43 REF: AMM 21-30-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213102	RIGHT EMERGENCY PRESSURIZATION VALVE 6600252-3 854 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
213103	LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 493 REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
213104	RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 639 REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 18 14		
213105	LEFT CONDITIONED AIR CHECK VALVE 6600210-5 7108AC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
213106	RIGHT CONDITIONED AIR CHECK VALVE 6600210-5 7112AC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
213107	POSITIVE VENTILATION CHECK VALVE 9519-1-1 SN-UNKNOWN REF: AMM 21-31-04	MOS HRS/MSC AFL	O/C						
213181	LEFT CHECK, AIR VALVE 6600210-11 6624AC REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213182	RIGHT CHECK, AIR VALVE 6600210-11 6620AC REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
2132004 EMP (s)	PERFORM FUNCTIONAL TEST OF EMERGENCY PRESSURIZATION SYSTEM PKG 42 REF: AMM 21-31-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
2132030 EMP (s)	INSPECT CABIN (PASSENGER) CONDITIONED AIR CHECK VALVES PKG 48 REF: AMM 21-31-03	MOS HRS/MSC AFL	3000	+25/-25			PKG 27-JUN-2001 0 0		
2132031 EMP (s)	INSPECT CABIN AIR AND COCKPIT AIR CHECK VALVES PKG 48 REF: See Workcard	MOS HRS/MSC AFL	3000	+25/-25			PKG 27-JUN-2001 0 0		
214001	FLOW CONTROL VALVE 320335-3 220 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			20-JUN-2019 6554.4 5408		
214002	HEAT EXCHANGER 6608060-009 A103 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
214101	COCKPIT HEATER 7600804-2 SN-UNKNOWN REF: AMM 21-41-01	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2142002 EMP (s)	PERFORM FUNCTIONAL TEST OF AUXILIARY CABIN HEAT SYSTEM PKG 42 REF: AMM 21-42-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
214201	LEFT AUXILIARY CABIN HEATER 6608521-004 0335 REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-OCT-2007 2773.7 1622		
214202	RIGHT AUXILIARY CABIN HEATER 6608521-003 0213 REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C				28-OCT-2013 4710.3 3413		
214203	AUXILIARY HEAT OVERTEMPERATURE MONITOR BOX 6018166-004 MRP421264-01 REF: AMM 21-42-02	MOS HRS/MSC AFL	O/C	N:3175 N:1961			06-JAN-2009 3189 1978		
2150000 EMP (s)	CHECK REFRIGERATION (AIR CONDITIONING) SYSTEM COMPONENTS INSTALLATION FOR PROPER V-BELT TENSION, SECURITY OF MOUNTING, AND GENERAL CONDITION (REFER TO 5-10-00). IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND SHAFT) PKG 41 REF: See Workcard	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
2150006 EMP (s)	PERFORM REFRIGERATION COMPRESSOR MOTOR BRUSH WEAR INSPECTION PKG 42 REF: AMM 21-50-02	MOS HRS/MSC AFL	N/A				PKG 31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215001	FREON COMPRESSOR JBS223-1 T-M22565-06 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0			17-JUN-2016 5586.7 4425		
2150017 EMP (s)	PERFORM A FLUORESCENT PENETRANT INSPECTION OF THE AIR CONDITIONER COMPRESSOR MOTOR FAN BLADES. PARTICULAR ATTENTION SHOULD BE GIVEN TO THE FAN BLADES IN THE AREA OF THE HUB PKG 42 REF: NDT 21-50-01	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			20-OCT-2016 5658.5 4503		
215003	CONDENSER 7608061-1 858 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
2150036 EMP	INSPECT FREON COMPRESSOR DRIVE (R134) MOTOR WEAR ES61134-3 149 REF: AMM 21-51-02	MOS HRS/MSC AFL ACH	1200	+25/-25			20-APR-2018 6183.5 5035 1172.5	2372.5	2397.5
2150037 EMP	OVERHAUL FREON COMPRESSOR DRIVE (R134) MOTOR ES61134-3 149 OVERHAUL REF: AMM 21-51-02	MOS HRS/MSC AFL ACH	2000	+25/-25			20-APR-2018 6183.5 5035 1172.5	3172.5	3197.5
215004	RECEIVER/DRYER ES43030-2 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-SEP-2015 5305.2 4095		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2150048 EMP (s)	PERFORM FUNCTIONAL TEST OF REFRIGERATION SYSTEM PRESSURE SWITCH PKG 43 REF: AMM 21-50-05	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
215006	COCKPIT EVAPORATOR 6019530-610 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						
215007 (s) OVERHAUL	FREON COMPRESSOR DRIVE (R134) MOTOR ES61134-3 149 REF: AMM 21-51-02	MOS HRS/MSC AFL ACH	2000	O:0 O:0 O:0 +25/-25			20-APR-2018 6183.5 5035 1172.5		
215008	COCKPIT EVAPORATOR PRESSURE REGULATOR VALVE ORIT-6-0/50-5/8-SAE SN-UNKNOWN REF: AMM 21-50-08	MOS HRS/MSC AFL	O/C						
215009	CABIN EVAPORATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
215010	CABIN EXPANSION VALVE ES26104-1 SN-UNKNOW REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-SEP-2015 5305.2 4095		
215012	FREON MOTOR CONTROL BOX 5418598-021 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215016	FREON MOTOR DIFFERENTIAL CURRENT SENSOR 268-1 206020145 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				20-JUL-2006 2471.3 1390	
215017	COMPRESSOR MOTOR HOURMETER 89094-12 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C					09-JAN-2012 4109.2 2746	
215031	ABSOLUTE PRESSURE SWITCH EC45C-47 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
215043	AFT EVAPORATOR 66-0260-1 109 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
215044	FORWARD EVAPORATOR 66-0250-2 193 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
215049	COCKPIT EXPANSION VALVE ES26105-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				09-SEP-2015 5305.2 4095	
215120	CONDENSER FAN 6608059-6 SN-UNKNOWN REF: AMM 21-50-02	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216001	REGULATING, SERVO AIR (TEMPERATURE CONTROL) VALVE 625734-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
216002	CREW TEMPERATURE SELECTOR 6600423-12 SN-UNKNOWN REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C						
216004	TEMPERATURE CONTROL INDICATOR 6608472-1 274 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
216005	COCKPIT TEMPERATURE CONTROLLER 625734-2 064C-378 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C				28-APR-2014 4916.3 3630		
216006	CABIN TEMPERATURE CONTROLLER 625734-2 090C-0907 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C				28-APR-2014 4916.3 3630		
216007	COCKPIT TEMPERATURE SENSOR 627962-1 110C-15949 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C				28-APR-2014 4916.3 3630		
216008	CABIN TEMPERATURE SENSOR 627962-1 021C-15987 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C				28-APR-2014 4916.3 3630		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216009	COCKPIT TEMPERATURE SENSOR BLOWER 627962-1 SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C						
216011	COCKPIT SKIN TEMPERATURE SENSOR 6600423-5 031C-6298 REF: AMM 21-60-06	MOS HRS/MSC AFL APH ACH	O/C	N:0 N:0 N:0 N:0 N:0			27-JUN-2001 0 0 0 0		
216012	CABIN SKIN TEMPERATURE SENSOR 6600423-5 031C-6297 REF: AMM 21-60-06	MOS HRS/MSC AFL APH ACH	O/C	N:0 N:0 N:0 N:0 N:0			27-JUN-2001 0 0 0 0		
216013	COCKPIT TEMPERATURE CONTROL VALVE 5581065 237 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			30-JUL-2014 4970 3691		
216014	CABIN TEMPERATURE CONTROL VALVE 6600423-017 466 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
216015	COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 5085 REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C				21-APR-2014 4906.6 3620		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216016	CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 5030 REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C					21-APR-2014 4906.6 3620	
216017	SERVO AIR PRESSURE REGULATOR 6600245-004 820 REF: AMM 21-60-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
216018	COCKPIT AIR DISTRIBUTION CHECK VALVE 6600423-7 SN-UNKNOWN REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C						
216019	CABIN AIR DISTRIBUTION CHECK VALVE 6600423-7 942 REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
216020	COCKPIT DUCT TEMPERATURE SENSOR 6600423-4 031C-16283 REF: AMM 21-60-11	MOS HRS/MSC AFL APH ACH	O/C	N:0 N:0 N:0 N:0 N:0				27-JUN-2001 0 0 0 0	
216021	CABIN DUCT TEMPERATURE SENSOR 6600423-4 031C-16289 REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	N:4938.5 N:3653				29-MAY-2014 4938.5 3653	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216022	COCKPIT DUCT OVERHEAT THERMOSTAT 3000-141-18 SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C						
216023	CABIN DUCT OVERHEAT THERMOSTAT 3000-141-18 SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C						
216024	CLIMATE CONTROL BOX 6018448-013 A00476927-01 REF: AMM 21-60-13	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			02-APR-2018 6168.7 5017		
216050	MEMBRANE, CABIN TEMPERATURE SWITCH 9077-000010-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
216101	CABIN TEMPERATURE INDICATOR 6608486-1 209 REF: AMM 21-61-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
CHAPTER 22 AUTO FLIGHT									
221001	AUTOPILOT CONTROLLER 6608507-002 1190 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			16-AUG-2019 6611.6 5456		
221002	AUTOPILOT ELECTRICAL BOX 5418442-014 SN-UNKNOWN REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C						



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221003	PITCH SERVO ACTUATOR 622-5027-102 35C3Y REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0				13-MAR-2019 6424 5293	
221004	PITCH SERVO MOUNT 622-5029-101 F5LG REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
221006	ROLL SERVO ACTUATOR 622-5027-102 DCTK REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
221009	YAW SERVO ACTUATOR 622-5027-102 DG9P REF: AMM 22-10-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
221010	YAW SERVO MOUNT 622-5029-101 FG4R REF: AMM 22-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
221011	ROLL SERVO MOUNT 6080014-2 DK7F REF: AMM 22-10-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
221012	REMOTE TUNING RELAY BOX 6018161-003 073185 REF: AMM 22-10-12	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0				04-FEB-2006 2208.2 1235	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2211016 EMP (s)	CHECK PRIMARY YAW DAMPER SERVO ACTUATOR AND SERVO MOUNT CLUTCH TORQUE PKG 52 REF: See Workcard	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
2211034 EMP (s)	CHECK ROLL SERVO CABLE TENSION PKG 42 REF: AMM 22-10-11	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
2211039 EMP (s)	CHECK PITCH SERVO AND YAW SERVO CABLE TENSION PKG 42 REF: See Workcard	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
2212013 EMP (s)	CHECK PITCH SERVO MOUNT CLUTCH TORQUE PKG 52 REF: AMM 22-10-04	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
2213006 EMP (s)	CHECK AUTOPILOT ROLL SERVO MOUNT CLUTCH TORQUE PKG 52 REF: AMM 22-10-11	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
222001	MACH TRIM COMPUTER (MOD 7) 501-1132-04 1161 REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C				31-JAN-2013 4466.7 3130		
222002	MACH TRIM ADAPTER 902-1-2 106 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C		R:0 R:0 R:0		28-SEP-2012 4346.6 3005		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
223001	SWITCHING UNIT 3188105-17 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
225001	YAW FORCE INTERFACE BOX 6018101V1-001 SN-UNKNOWN REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C						
225002	PILOT FORCE SENSOR 6608498-3 1753 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
225003	COPILOT FORCE SENSOR 6608498-3 1752 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
CHAPTER 23 COMMUNICATIONS									
231087	CABIN BRIEFER CONTROLLER HUCAB-2-GP 89176 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
231098	RIGHT PASSENGER SPEAKER AMPLIFIER 240-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
231101	NO. 1 VHF TRANSCEIVER (MOD 2,3,5,7,8,9,10,11,12,13,14,15,17,21,22,25,27,28,30,31,32,33,36,37,40) 822-1115-001 02NW REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C				25-SEP-2018 6345.6 5200		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231102	NO. 2 VHF TRANSCEIVER (MOD 2,3,5,7,8,9,10,11,12,13,14,15,17,21,22,25,27,28,36) 822-1115-001 4VUG REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C				25-SEP-2018 6345.6 5200		
231103	NO. 1 VHF ANTENNA VF10-347 5164 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-FEB-2006 2208.2 1235		
231104	NO. 2 VHF ANTENNA VF10-347 5228 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUL-2006 2471.3 1390		
231180	NO. 1 HF AUDIO AMPLIFIER 2688178-003 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
231181	NO. 2 HF AUDIO AMPLIFIER 2688178-003 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
2312002-001 EMP (s)	PERFORM PRIMARY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHf 1050 SYSTEM 064-1017-01 PKG 40 17482 REF: AMM 23-12-08	MOS HRS/MSC AFL	N/A				19-OCT-2018 6341.2 5193		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2312002-002 EMP (s)	PERFORM STANDBY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM PKG 40 REF: AMM 23-12-08	MOS HRS/MSC AFL	N/A				19-OCT-2018 6341.2 5193		
231201	NO. 1 HF RECEIVER/EXCITER 064-1015-01 32467 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	R:5 N:5826.5 R:149 N:4674 R:149			05-JUN-2017 5896.1 4749		
231203	PRIMARY POWER AMPLIFIER/ANTENNA COUPLER (MOD 3,4,6,7,8,9,10,11,13) 064-1017-01 17482 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C						
231205	HF ANTENNA 8002565 SN-UNKNOWN REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-DEC-2013 4749 3460		
231207	NO. 1 HF CONTROL UNIT 064-1016-03 4126 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			13-DEC-2012 4443.4 3103		
231209	HF AUDIO ADAPTER 2688178-1 SN-UNKNOWN REF: AMM 23-12-05	MOS HRS/MSC AFL	O/C						
231211	(CBR8) HF REMOTE CIRCUIT BREAKER 10RC1C-25 7470 REF: AMM 23-12-07	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231271	HF GROUND ASSEMBLY 6088411-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
231401	SELCAL CONTROL PANEL 5489328-11 SN-UNKNOWN REF: AMM 23-14-01	MOS HRS/MSC AFL	O/C						
231402	SELCAL DECODER 2800-0012-105 1012253 REF: AMM 23-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
231501	PASSENGER BRIEFER CONTROL PANEL 6608478-2 SN-UNKNOWN REF: AMM 23-15-01	MOS HRS/MSC AFL	O/C						
231502	PASSENGER BRIEFER COMPUTER 6608478-1 SN-UNKNOWN REF: AMM 23-15-02	MOS HRS/MSC AFL	O/C						
232005	FWD ATG 4000 ANTENNA P12949 523056 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
232005A	HIGH FREQUENCY EDDY CURRENT INSP. P12949 523056 REF:	MOS HRS/MSC AFL	96 2400				17-OCT-2016 5658.5 4503	17-OCT-2024 8058.5	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232006	AFT ATG 4000 ANTENNA P12949 523073 REF:	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
232006A	HIGH FREQUENCY EDDY CURRENT INSP. REF:	MOS HRS/MSC AFL	96 2400				21-OCT-2016 5658.5 4503	21-OCT-2024 8058.5	
232020	COCKPIT IRIDIUM SATCOM HANDSET P12248-001 1224810824 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-MAY-2008 2950.2 1775		
232025	CABIN IRIDIUM SATCOM HANDSET P12192-002 1219238034 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-AUG-2019 6611.6 5456		
232120	BLUE SKY DUAL ANTENNA S67-1575-165 449-1919 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JUN-2007 2733.2 1580		
232501	AIRCELL AXCESS IRIDIUM SATCOM TRANSCEIVER (MOD 1,2,3,4) P12023 1202314359 REF:	MOS HRS/MSC AFL	O/C				22-OCT-2016 5662.2 4507		
232503	AIRCELL AXCESS IRIDIUM SATCOM DUAL ANTENNA S67-1575-165 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-MAY-2008 2950.5 1775		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232505	AIRCELL AXCESS IRIDIUM SATCOM ACA P12347 1234710476 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-MAY-2008 2950.5 1775		
232508	IRIDIUM SATCOM ROUTER P12083-001 1208370186 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-JUL-2008 3002.7 1828		
232511	FWD ANTENNA VISUAL INSPECTION REF:	MOS HRS/MSC AFL	25000					25000	
232524	AFT ANTENNA VISUAL INSPECTION REF:	MOS HRS/MSC AFL	25000					25000	
233000	PASSENGER BRIEFER AMPLIFIER 990-3081-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
233001	LEFT FORWARD CABIN STEREO SPEAKER EN-MT-60-8 SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C						
233002	RIGHT FORWARD CABIN STEREO SPEAKER EN-MT-60-8 03991046 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233003	LEFT AFT CABIN STEREO SPEAKER EN-MT-60-8 SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C						
233004	RIGHT AFT CABIN STEREO SPEAKER EN-MT-60-8 SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C						
233005	PASSENGER SPEAKER AMPLIFIER 240-001 SN-UNKNOWN REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C						
233007	DVD PLAYER 305000062 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
233023	FORWARD WOOFER, CABIN SPEAKER EN-W-60-4 050100684 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
233024	AFT WOOFER, CABIN SPEAKER EN-W-60-4 050100683 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
233030	CONFIGURATION MODULE 31990-1 11757 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-JUN-2007 2733.2 1580		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233040	INFRARED REMOTE CONTROL IFR-485-10-01 060100856 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				14-DEC-2001 18 14		
233084	FORWARD 15.1 LCD COLOR DISPLAY AI-LCD151-01-1 110200243 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-DEC-2002 781 523		
234101	INTERPHONE AUDIO AMPLIFIER MODEL 204 1810 REF: AMM 23-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
235001	PILOT AUDIO CONTROL PANEL 802-002 555 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-OCT-2018 6325.7 5184		
235002	COPILOT AUDIO CONTROL PANEL 802-002 538 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-MAR-2017 5797.5 4654		
235003	LEFT AUDIO AMPLIFIER 700-002 661 REF: AMM 23-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
235004	RIGHT AUDIO AMPLIFIER 700-002 662 REF: AMM 23-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2360021 EMP (s)	PERFORM FUNCTIONAL TEST OF STATIC DISCHARGERS PKG 43 REF: AMM 23-60-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
2360022 EMP (s)	PERFORM FUNCTIONAL TEST OF STATIC DISCHARGERS PKG 43 REF: AMM 23-60-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
237001	COCKPIT VOICE (CVR) RECORDER 1603-02-03 244 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
237002	CVR REMOTE MICROPHONE AMPLIFIER 1635-02 260 REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
237003	CVR REMOTE AREA MICROPHONE 16301-01 1120 REF: AMM 23-70-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
237004	CVR INERTIA SWITCH 3L0-453/8 09985 REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
237021	CVR UNDERWATER LOCATOR (ULB) BEACON DK120 SC15657 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JUN-2007 2733.2 1580		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237021B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000 DK120 SC15657 REF: AMM 25-63-00	MOS HRS/MSC AFL	72				05-APR-2019 6431.9 5305	05-APR-2025	
237032	AUDIO/VIDEO AMPLIFIER AV9665 040500350 REF:	MOS HRS/MSC AFL	O/C	O:24 O:0 O:0			08-NOV-2011 4077.4 2729		
237071	AUDIO/VIDEO, AIRSHOW SWITCH 912000 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
238001	NO. 1 RADIO TUNING (RTU) UNIT (MOD 8, 11, 12, 18, 19) 822-1825-102 1XTWV REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			12-FEB-2018 6135.8 4984		
238002	NO. 2 RADIO TUNING (RTU) UNIT (MOD 8,11,12,14,15,17,18,19) 822-1825-102 4VFW REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			01-OCT-2019 6654 5489		
239004	MASTER, DPI SWITCH SP-60-006 030100996 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
239005	AUDIO INTERNATIONAL SWITCH SP-60-003 030100484 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
239007	NO. 1 SWITCHING MODULE MSM9660 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
239008	NO. 2 SWITCHING MODULE MSM9660 050100942 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
239009	NO. 3 SWITCHING MODULE MSM9660 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
239015	ORDINANCE SIGN SWITCH SP-60-004 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
239016	AUDIO AMPLIFIER AV-9665 060101131 REF: AMM 23-41-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			09-JAN-2012 4109.2 2746		
239501	ATG 4000 P13989 1398917960 REF:	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
23CUS1	VISUAL INSPECTION OF THE ATG 4000 SYSTEM REF:	MOS HRS/MSC AFL	96 2400				21-OCT-2016 5658.5 4503	21-OCT-2024 8058.5	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23CUS2	DIGITAL DATA ADAPTER 08090021-6 112 REF:	MOS HRS/MSC AFL	O/C					17-OCT-2016 5658.5 4503	
23CUS3	AIRCELL CONFIGURATION MODULE P14126 1412616213 REF:	MOS HRS/MSC AFL	O/C					17-OCT-2016 5658.5 4503	
CHAPTER 24 ELECTRICAL POWER									
05-10-29-B2432010 (s)	INSPECT MAIN AIRCRAFT BATTERY INSTALLATION	MOS HRS/MSC AFL	6	+14d/-14d				02-JAN-2017 5712.7	
240000	STATIC INVERTER SS200 492 REF:	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			12-MAY-2006 2361.2 1330	
242001	LEFT PRIMARY AC POWER INVERTER 6608483-1 80106 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C		R:0			24-SEP-2009 3495.2 2238	
242002	RIGHT SECONDARY AC POWER INVERTER 6608483-1 1866 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			27-JUN-2001 0 0	
242003	POWER MONITOR INDICATOR 11003-003 A01016 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C		R:0 R:0 R:0			06-MAR-2020 6770 5610	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242009	NO. 1 GROUND FAULT TRANSFORMER N717-9018 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
242010	NO. 2 GROUND FAULT TRANSFORMER N717-9018 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
242016	GENERATOR CONTROL PANEL 6081023-813 SN-UNKNOWN REF: AMM 24-30-02	MOS HRS/MSC AFL	O/C						
242031	DC AMMETER SENSOR 256-1 SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C						
242032	NO. 1 DC CURRENT SENSOR 952-500-C 2703 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C					14-DEC-2001 18 14	
242033	NO. 2 DC CURRENT SENSOR 952-500-C SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C						
242051-01	CB10 CIRCUIT BREAKER SM600BA75N1 050129 REF:	MOS HRS/MSC AFL	O/C					14-DEC-2001 18 14	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242081	1200 VA, 115 VAC, 60 HZ INVERTER 2D1200-1A-1011 SN-UNKNOWN REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C						
243001	NO. 1 STARTER/GENERATOR 400SG138Q-2 2984 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:4.2 O:6			11-MAR-2020 6770 5610		
243002	NO. 2 STARTER/GENERATOR 400SG138Q-2 3696 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-JAN-2020 6722.6 5565		
243003	APU STARTER/GENERATOR 400SG159Q 2886 REF: SMM 49-11-02	MOS HRS/MSC AFL	O/C	O:0			14-FEB-2020 6733.2 5579		
243003A	OVERHAUL/REPLACE APU STARTER/GENERATOR BRUSHES 400SG159Q 2886 REF:	MOS HRS/MSC AFL APH	1000				20-FEB-2020 6747 5590 2970	3970	
243003B	APU STARTER GENERATOR "BRUSH CHECK" 400SG159Q 2886 REF:	MOS HRS/MSC AFL APH	150				14-FEB-2020 6733.2 5579 2970	3120	
243005	LEFT (GCU) GENERATOR CONTROL UNIT GCS505-16B 1532B REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C	N:5193.8 N:3966			14-MAY-2015 5193.8 3966		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243006	RIGHT (GCU) GENERATOR CONTROL UNIT GCS505-16B 1530B REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C	N:5193.8 N:3966			14-MAY-2015 5193.8 3966		
243007	A11 GENERATOR CURRENT TRANSFORMER GTSG-700 2862 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
243008	2A11 GENERATOR CURRENT TRANSFORMER GTSG-700 2873 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
243009	A12 GENERATOR CURRENT TRANSFORMER GTSG-700 2874 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
243010	2A12 GENERATOR CURRENT TRANSFORMER GTSG-700 2866 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
243011	LEFT DC AMMETER CURRENT SENSOR 256-1 4FBHY REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2012 4266.5 2911		
243012	RIGHT DC AMMETER CURRENT SENSOR 256-1 42CRW REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C				06-OCT-2011 4037.8 2697		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243025	CURRENT TRANSFORMER CTSG700 2754 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
243026	CURRENT TRANSFORMER CTSG700 2891 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
243027	CURRENT TRANSFORMER 6018400V3-004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
243028	CURRENT TRANSFORMER 6018400V3-004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
243062	NO. 1 EMERGENCY POWER BATTERY (MOD 1,2,3,4) 501-1712-02 2848 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C				06-OCT-2011 4037.8 2697		
243063	NO. 2 EMERGENCY POWER BATTERY (MOD 1,2,3,4,7,8) 501-1712-02 2584 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C				18-NOV-2010 3822.8 2516		
2431025-001 EMP	OVERHAUL NO. 1 STARTER/GENERATOR 400SG138Q-2 2984 REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	+25/-25			11-MAR-2020 6770 5610	7770	7795

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2431025-002 EMP	OVERHAUL NO. 2 STARTER/GENERATOR 400SG138Q-2 3696 REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	+25/-25			21-JAN-2020 6722.6 5565	7722.6	7747.6
OVERHAUL									
2432000 EMP (s)	PERFORM OPERATIONAL CHECK OF DC POWER DISTRIBUTION SYSTEM PKG 43 REF: AMM 24-50-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
2432001 EMP (s)	PERFORM EMERGENCY DC POWER DISTRIBUTION SYSTEM - OPERATIONAL CHECK PKG 42 REF: AMM 24-51-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
+ 2432003 EMP (s)	PERFORM OPERATIONAL CHECK OF AC POWER SYSTEM PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
243201	PERFORM EMERGENCY BATTERY REBUS REF:	MOS HRS/MSC AFL	12				31-OCT-2019 6654.5 5490	31-OCT-2020	
SMM									
2432010 EMP (s)	INSPECT BATTERY INSTALLATION AS FOLLOWS: BATTERY CASES FOR CONDITION AND THAT LIDS ARE PROPERLY SECURED. STRUCTURE UNDER BATTERIES FOR TRACES OF ELECTROLYTE OR CORROSION. BATTERY VENT TUBES FOR KINKS, OBSTRUCTIONS, AND SECURITY OF ATTACHMENT. VENT FITTINGS AND INLET AND OUTLET FITTINGS FOR OBSTRUCTIONS, CORROSION, AND SECURITY OF ATTACHMENT. CLEAN AND/OR SECURE AS REQUIRED PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243301	NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK M6088352-025 A00593695-01 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:9 R:191.1 R:153				07-JAN-2011 3850.3 2532	
243302	NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK M6088352-025 A0066757-01(B) REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:9 R:191.1 R:153				07-JAN-2011 3850.3 2532	
244002	GROUND POWER MONITOR- 3118487-2 SN-UNKNOWN REF: AMM 24-40-02	MOS HRS/MSC AFL	O/C						
245050	NO. 1 110 VOLT, AC OUTLET 106003-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
245051	NO. 2 110 VOLT, AC OUTLET 106003-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
245054	NO. 5 110 VOLT AC OUTLET 106003-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
245055	NO. 6 110 VOLT, AC OUTLET 106003-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24HAW1	NO. 1 HAWKER BATTERY 9750W0370 UN-KNOWN REF:	MOS HRS/MSC AFL	O/C	N:0			23-JAN-2019 6399		
24HAW1A	NO.1 BATTERY CAP CHECK 9750W0370 UN-KNOWN REF:	DAYS HRS/MSC AFL	550 3500	+55/-55 +350/-350			23-JAN-2019 6399	26-JUL-2020 9899	19-SEP-2020 10249
24HAW2	NO. 2 HAWKER BATTERY 9750W0370 UN-KNOWN REF:	MOS HRS/MSC AFL	O/C	N:0			23-JAN-2019 6399		
24HAW2A	NO.2 BATTERY CAP CHECK 9750W0370 UN-KNOWN REF:	DAYS HRS/MSC AFL	550 3500	+55/-55 +350/-350			23-JAN-2019 6399	26-JUL-2020 9899	19-SEP-2020 10249
25CUS1	EFB # 1 A1490 F9FSP9Y4FLML REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2016 5707.6 4568		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
250000	STEREO/PAGE AMPLIFIER M3081 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
251001	PILOT CREW SEAT 3A213-0007-01-2 36724 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2510010 EMP (s)	CHECK CREW SEATS AND SEAT BELTS FOR OPERATION, SECURITY OF MOUNTING, AND GENERAL CONDITION PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			31-OCT-2019 6654.5 5490	PKG	
251002	COPILOT CREW SEAT 3A213-0008-01-2 36421 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
251005	PILOT LIGHTED CHART HOLDER 10-62-01 3319 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
251006	COPILOT LIGHTED CHART HOLDER 10-62-01 UNK-3322 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
2520008 EMP (s)	PERFORM VISUAL INSPECTION PASSENGER SEAT AND SEAT BELTS PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			31-OCT-2019 6654.5 5490	PKG	
252001	LEFT FORWARD PASSENGER SEAT 303690-1HST 18736 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:76 N:2773.7 N:1622			18-OCT-2007 2773.7 1622		
252001A	LEFT FORWARD SEAT HYDROLOCK UL32-010SP1 56408 REF:	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			28-SEP-2012 4346.6 3005		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252002	RIGHT FORWARD PASSENGER SEAT 303690-2ST SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C				20-AUG-2008 3039.3 1860		
252003	LEFT MID PASSENGER SEAT 303690-3ST 16969 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:76 N:2773.7 N:1622			18-OCT-2007 2773.7 1622		
252003A	LEFT MID SEAT HYDROLOCK UL32-010 SP 1 BATCH # 12-06D 39-60D REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-FEB-2008 2856.8 1694		
CUSTOMER CODE									
252004	RIGHT MID PASSENGER SEAT 303690-4ST 16967 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:76 N:2773.7 N:1622			18-OCT-2007 2773.7 1622		
252004A	RIGHT MID SEAT HYDROLOCK UL-32-010 SP 1 BATCH # 12-06D REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-FEB-2008 2856.8 1694		
CUSTOMER CODE									
252005	LEFT AFT PASSENGER SEAT 303690-1HS 18737 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:76 N:2773.7 N:1622			18-OCT-2007 2773.7 1622		
252005A	LEFT AFT SEAT HYDROLOCK UL32-010 SP 1 BATCH 39-06D REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-FEB-2008 2856.8 1694		
CUSTOMER CODE									

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252006	RIGHT AFT PASSENGER SEAT 303690-2HS 18739 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:76 N:2773.7 N:1622				18-OCT-2007 2773.7 1622	
252006A	RIGHT AFT SEAT HYDROLOCK UL32-010SP1 56407 CUSTOMER CODE REF:	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0				28-SEP-2012 4346.6 3005	
253009	LEFT FORWARD COLD CATHODE LAMP INVERTER 6900115 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
253010	RIGHT FORWARD COLD CATHODE LAMP INVERTER 6900115 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
253052	VOLTAGE REGULATOR T2688253-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
253090	AM/FM/CASSETTE STEREO CTP-010-401 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
254015	TOILET TIMER 9060-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
254025	TOILET PUMP 5250-10 P6673 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-SEP-2010 3782.6 2478		
254051	TOILET MACERATOR 5300-1 M3465 REF:	MOS HRS/MSC AFL	O/C				30-JUL-2016 5621.5 4466		
255050	MICROWAVE OVEN 400-1726-01-L 07-06-41307 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-OCT-2007		
255050A	ANNUAL INSPECTION MICROWAVE OVEN M100367ICT-SMM-1 (25-35-13) 400-1726-01-L 07-06-41307 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	N/A				17-OCT-2007		
256001	EMERGENCY LOCATOR TRANSMITTER (ELT) (MOD 8) 453-5000-(366) 08755 REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-OCT-2017 6008.7 4845		
256001A	INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000-(366) 08755 REF: AMM 25-62-00	MOS HRS/MSC AFL	12	+14d/-14d			06-NOV-2019 6654.5 5490	06-NOV-2020	20-NOV-2020
256003	ELT CONTROLLER 453-0030 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256010	ELT/NAV INTERFACE 455-6500 00675 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
256061	NO. 1 LIFE VEST P01074-201 10090680016 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256061A	INSPECT NO. 1 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680016 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256062	NO. 2 LIFE VEST P01074-201 10090680010 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256062A	INSPECT NO. 2 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680010 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256063	NO. 3 LIFE VEST P01074-201 10090680014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256063A	INSPECT NO. 3 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680014 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256064	NO. 4 LIFE VEST P01074-201 10090680009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256064A	INSPECT NO. 4 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680009 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256065	NO. 5 LIFE VEST P01074-201 10090680025 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256065A	INSPECT NO. 5 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680025 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256066	NO. 6 LIFE VEST P01074-201 10090680020 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256066A	INSPECT NO. 6 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680020 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256067	NO. 7 LIFE VEST P01074-201 10090680018 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256067A	INSPECT NO. 7 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680018 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256068	NO. 8 LIFE VEST P01074-201 10090680017 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256068A	INSPECT NO. 8 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201 10090680017 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256071	PILOT LIFE VEST P01074-201WC 10090690002 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256071A	INSPECT PILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201WC 10090690002 REF: See Workcard	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	
256072	COPILOT LIFE VEST P01074-201WC 10090690005 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			07-JAN-2011 3850.3 2532		
256072A	INSPECT COPILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS P01074-201WC 10090690005 REF: AMM 25-61-00	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256076	FIRST AID KIT 500142 9406104B REF: GENERIC NO REF	MOS HRS/MSC AFL	12	N:0 N:0 N:0			08-JUL-2019 6570.9 5426	31-JUL-2020	
2561005 EMP (s)	PERFORM INSPECTION OF LIFE VEST PKG 40 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				PKG 31-OCT-2019 6654.5 5490		
256116	ELT REMOTE SWITCH PANEL DMU264-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
256202	ELT ANTENNA 110-337 1043074 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
2563001 EMP (s)	INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERIES (IF INSTALLED) 453-5000-(366) PKG 40 08755 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
2564000 EMP	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY PACK 453-5000-(366) 08755 REF: AMM 25-62-00	MOS HRS/MSC AFL	DUE				19-OCT-2018 6341.2 5193	01-OCT-2023 M	
2565000 EMP	CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON DK120 SC15657 REF: AMM 25-63-00	MOS HRS/MSC AFL	24	+14d/-14d	-4		05-APR-2019 6431.9 5305	01-APR-2021	15-APR-2021

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2566000 EMP (s)	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON CVR/FDR ULB BATTERY DK120 SC15657 REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE				05-APR-2019 6431.9 5305	31-DEC-2024 M	
LIFE LIMIT									
2571002 EMP (s)	PERFORM FUNCTIONAL TEST OF NOSE AVIONICS COMPARTMENT EXHAUST BLOWERS AND THEIR RESPECTIVE CONTROL TEMPERATURE SWITCHES PKG 43 REF: AMM 25-71-01	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0		
257101	NOSE AVIONICS EXHAUST BLOWER 026977 SN-UNKNOWN REF: AMM 25-71-01	MOS HRS/MSC AFL	O/C						
258010	AIRSHOW DIGITAL INTERFACE UNIT 920040 295 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		R:0 R:0 R:0		11-DEC-2014 5073.5 3818		
258011	INFRARED REMOTE EYE - ROSEN 0500-006 0704P021 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		22-JUN-2007 2733.2 1580		
258012	CABIN CONTROLLER 0300-407 0703P015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		22-JUN-2007 2733.2 1580		
258016	FORWARD 10.4 LCD COLOR, AIRSHOW 400 DISPLAY AI-LCD-104HB SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
258017	AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY AI-LCD-104HB SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
25CUS01 (s)	CHECK AIRCRAFT STOCK EXPIRATION DATES PKG 35 REF:	DAYS HRS/MSC AFL	30				PKG 30-MAR-2020 6774.5 5614		
25CUS1A ICA	LITHIUM POLYMER BATTERY (IPAD) A1490 F9FSP9Y4FLML REF:	MOS HRS/MSC AFL	12				22-JUL-2019 6586.9 5442	22-JUL-2020	
25CUS2	EFB # 2 A1490 F9FSQAM7FLML REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2016 5707.6 4568		
25CUS2A ICA	LITHIUM POLYMER BATTERY A1490 F9FSQAM7FLML REF:	MOS HRS/MSC AFL	12				22-JUL-2019 6586.9 5442	22-JUL-2020	
CHAPTER 26 FIRE PROTECTION									
261001	NO. 1 FIRE DETECTION CONTROL UNIT 377-02833 0106-004 REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
261002	NO. 2 FIRE DETECTION CONTROL UNIT 377-02833 0106-005 REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2610020-001 EMP (s)	INSPECT ENGINE TAILCONE FIRE DETECTOR ELEMENT FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION PKG 29 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				PKG 20-AUG-2017 5951.6 4793		
2610020-002 EMP (s)	INSPECT ENGINE TAILCONE FIRE DETECTOR ELEMENT FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				PKG 20-AUG-2017 5951.6 4793		
261006	TAILCONE BLEED AIR OVERHEAT (E267) CONTROL BOX 35009-20 SN-UNKNOWN REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C						
261007	TAILCONE BLEED AIR OVERHEAT (E268) CONTROL BOX 35009-20 D6685 REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C				31-JAN-2013 4466.7 3130		
261207	BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY FR2222 703 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C				14-DEC-2001 18 14		
261301	FORWARD TAILCONE BLEED AIR SENSING ELEMENT 35620-3-255 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2013 4466.7 3130		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261302	MID TAILCONE BLEED AIR SENSING ELEMENT 35584-3-255 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2013 4466.7 3130		
261303	AFT TAILCONE BLEED AIR SENSING ELEMENT 35680-3-255 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-JAN-2013 4466.7 3130		
2614000 EMP (s)	PERFORM FUNCTIONAL TEST OF BAGGAGE COMPARTMENT SMOKE DETECTOR SYSTEM PKG 42 REF: AMM 26-12-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
2620010 EMP (s)	PERFORM WEIGHT CHECK OF ENGINE FIRE EXTINGUISHER CONTAINERS. AFTER INSTALLATION OF CONTAINERS, PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM PKG 42 REF: AMM 26-21-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
2620026-001 EMP	HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER BOTTLE 32700004-1 21491C1 REF: AMM 26-21-03	MOS HRS/MSC AFL	60	+14d/-14d			09-MAR-2016 09-MAR-2021	23-MAR-2021	
2620026-002 EMP	HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE 32700004-1 21490C1 REF: AMM 26-21-03	MOS HRS/MSC AFL	60	+14d/-14d			09-MAR-2016 09-MAR-2021	23-MAR-2021	
2620030-001 EMP	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER A344T Y-215481 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d			01-AUG-2012 01-AUG-2024	15-AUG-2024	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2620030-002 EMP	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER A344T Y-215479 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d			01-AUG-2012	01-AUG-2024	15-AUG-2024
2620030-003 EMP	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER C352TS F-362066 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d			01-AUG-2012	01-AUG-2024	15-AUG-2024
2620040-001 EMP	REPLACE FORWARD/FORWARD ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE 30903823 SN-UNKNOWN REF: AMM 26-21-04 Manufacture Date: 01-AUG-2017	MOS HRS/MSC AFL	108	+14d/-14d	N:0 N:0		16-OCT-2017 6008.7 4845	01-AUG-2026	15-AUG-2026
2620040-001A EMP	SERVICE LIFE FORWARD/FORWARD ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE REF: AMM 26-21-04	MOS HRS/MSC AFL	72	+14d/-14d			13-OCT-2017	13-OCT-2023	27-OCT-2023
2620040-002 EMP	REPLACE FORWARD/AFT ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE 30903823 SN-UNKNOWN REF: AMM 26-21-04 Manufacture Date: 01-AUG-2017	MOS HRS/MSC AFL	108	+14d/-14d	N:0 N:0		16-OCT-2017 6008.7 4845	01-AUG-2026	15-AUG-2026
2620040-002A EMP	SERVICE LIFE FORWARD/AFT ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE REF: AMM 26-21-04	MOS HRS/MSC AFL	72	+14d/-14d			13-OCT-2017	13-OCT-2023	27-OCT-2023
2620040-003 EMP	REPLACE AFT/FORWARD ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE 30903823 SN-UNKNOWN REF: AMM 26-21-04 Manufacture Date: 01-AUG-2017	MOS HRS/MSC AFL	108	+14d/-14d	N:0 N:0		16-OCT-2017 6008.7 4845	01-AUG-2026	15-AUG-2026

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2620040-003A EMP	SERVICE LIFE AFT/FORWARD ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE	MOS	72	+14d/-14d			13-OCT-2017	13-OCT-2023	27-OCT-2023
LIFE LIMIT	REF: AMM 26-21-04	HRS/MSC AFL							
2620040-004 EMP	REPLACE AFT/AFT ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE 30903823 SN-UNKNOWN	MOS	108	+14d/-14d			16-OCT-2017 6008.7	01-AUG-2026	15-AUG-2026
LIFE LIMIT	REF: AMM 26-21-04 Manufacture Date: 01-AUG-2017	HRS/MSC AFL		N:0 N:0			4845		
2620040-004A EMP	SERVICE LIFE AFT/AFT ENGINE FIRE EXTINGUISHER (HTL) CARTRIDGE	MOS	72	+14d/-14d			13-OCT-2017	13-OCT-2023	27-OCT-2023
LIFE LIMIT	REF: AMM 26-21-04	HRS/MSC AFL							
2620041 EMP (s)	INSPECT CABIN PORTABLE HAND HELD FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE PKG 40	MOS	12	+14d/-14d			31-OCT-2019 6654.5		
	REF: GENERIC NO REF	HRS/MSC AFL					5490		
2620042-001 EMP	CHECK FORWARD FIRE EXTINGUISHER BOTTLE PRESSURE GAGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY 32700004-1 21491C1	MOS	600	+25/-25			29-MAR-2019 6431.9	7031.9	7056.9
	REF: AMM 26-21-00	HRS/MSC AFL					5305		
2620042-002 EMP	CHECK AFT FIRE EXTINGUISHER BOTTLE PRESSURE GAGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY 32700004-1 21490C1	MOS	600	+25/-25			29-MAR-2019 6431.9	7031.9	7056.9
	REF: AMM 26-21-00	HRS/MSC AFL					5305		
2620045 EMP (s)	INSPECT COPILOT PORTABLE HAND HELD FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE PKG 40	MOS	12	+14d/-14d			31-OCT-2019 6654.5		
	REF: GENERIC NO REF	HRS/MSC AFL					5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2620045 EMP (s)	INSPECT PILOT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE						PKG		
	PKG 40	MOS	12	+14d/-14d				31-OCT-2019	
		HRS/MSC						6654.5	
	REF: GENERIC NO REF	AFL						5490	
262013	FORWARD FIRE EXTINGUISHER BOTTLE								
	32700004-1	MOS		N:177 O:58				10-MAR-2016	
	21491C1	HRS/MSC	O/C	N:5484.2 O:1538.5				5484.2	
	REF: AMM 26-21-03	AFL		N:4305 O:1694				4305	
262014	AFT FIRE EXTINGUISHER BOTTLE								
	32700004-1	MOS		N:177 O:58				10-MAR-2016	
	21490C1	HRS/MSC	O/C	N:5484.2 O:1538.5				5484.2	
	REF: AMM 26-21-03	AFL		N:4305 O:1694				4305	
262041	PILOT PORTABLE FIRE EXTINGUISHER								
	A344T	MOS		N:9				15-MAY-2013	
	Y-215481	HRS/MSC	O/C	N:0				4580.7	
	REF: GENERIC NO REF	AFL		N:0				3268	
262042	COPILOT PORTABLE FIRE EXTINGUISHER								
	A344T	MOS		N:9				15-MAY-2013	
	Y-215479	HRS/MSC	O/C	N:0				4580.7	
	REF: GENERIC NO REF	AFL		N:0				3268	
262045	NO. 1 ENGINE FIRE - PULL SWITCH								
	6608480-3	MOS		N:0				27-JUN-2001	
	524	HRS/MSC	O/C	N:0				0	
	REF: AMM 26-21-01	AFL		N:0				0	
262046	NO. 2 ENGINE FIRE - PULL SWITCH								
	6608480-3	MOS		N:0				27-JUN-2001	
	553	HRS/MSC	O/C	N:0				0	
	REF: AMM 26-21-01	AFL		N:0				0	



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262050	APU FIRE EXTINGUISHER 50-1200 06-1014 REF: SMM 49-61-01	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			08-FEB-2007 2633.5 1489 888		
262050C	INSPECT APU FIRE EXTINGUISHER WEIGHT CHECK AND REPLACE AS NECESSARY 50-1200 06-1014 REF: SMM 49-11-03	MOS HRS/MSC AFL	12				25-MAR-2020	25-MAR-2021	
262050D	CONTINUITY CHECK APU FIRE EXTINGUISHER PRESSURE SWITCH IAW SAFECRAFT CMM 26-20-02 50-1200 06-1014 REF: CMM 26-20-02	MOS HRS/MSC AFL	12				31-OCT-2019 6654.5 5490	31-OCT-2020	
262051	CABIN PORTABLE FIRE EXTINGUISHER C352TS F-362066 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-MAY-2013 4580.7 3268		
262057	APU FIRE BOTTLE SQUIB 30900000M 0245WA REF: See Workcard Manufacture Date: 20-JAN-2016	MOS HRS/MSC AFL	60				08-MAR-2016 5484.2 4305	20-JAN-2021	
26AGENT	SPECTRUM FX (FIRE SUPPRESSION AGENT) SPECTRUMFX 192392 REF:	MOS HRS/MSC AFL	-					31-AUG-2021 M	
U2610020A	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT REF:	MOS HRS/MSC AFL	3600	+50			20-AUG-2017 5951.6 4793	9551.6	9601.6

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U2610020B	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT	MOS					20-AUG-2017		
	REF:	HRS/MSC	3600	+50			5951.6	9551.6	9601.6
		AFL					4793		
CHAPTER 27 FLIGHT CONTROLS									
27-51-06-082	LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
27-51-06-082	LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
27-51-06-082	RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
27-51-06-082	RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
27-51-06-085	LEFT FLAP LEADING EDGE RIB								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
27-51-06-085	RIGHT FLAP LEADING EDGE RIB								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2700011 EMP (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	0
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	0
2700013 EMP (s)	INSPECT WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (FLAPS, AILERONS, AND SPOILERS), ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERFERENCE, AND GENERAL CONDITION. INSPECT PARENT STRUCTURE ELEMENTS AS WELL AS THOSE ON THE MOVEABLE SURFACES PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	0
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	0
2700019 EMP (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	0
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	0
2700020 EMP (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	0
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	0
2700022 EMP (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	0
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	0
2700023 EMP (s)	INSPECT WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (RUDDER AND ELEVATORS), ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERFERENCE, AND GENERAL CONDITION. INSPECT PARENT STRUCTURE ELEMENTS AS WELL AS THOSE ON THE MOVEABLE SURFACES PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	0
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	0

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2700031 EMP (s)	CHECK ELEVATOR AND RUDDER CONTROL CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEY, PULLEY BRACKETS, AND GUARDS FOR SECURITY AND GENERAL CONDITION						PKG		
	PKG 42	MOS	72	+14d/-14d			31-OCT-2019		
		HRS/MSC	1200	+25/-25			6654.5		
	REF: GENERIC NO REF	AFL					5490		
2700032 EMP (s)	CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION						PKG		
	PKG 42	MOS	72	+14d/-14d			31-OCT-2019		
		HRS/MSC	1200	+25/-25			6654.5		
	REF: GENERIC NO REF	AFL					5490		
2700052 EMP (s)	CHECK USING THE PROPER COCKPIT CONTROLS, CHECK FLAPS, SPOILERS, HORIZONTAL STABILIZER, AND TRIM TABS FOR PROPER OPERATION AND ACCURATE INDICATION						PKG		
	PKG 42	MOS	72	+14d/-14d			31-OCT-2019		
		HRS/MSC	1200	+25/-25			6654.5		
	REF: See Workcard	AFL					5490		
2700062 EMP (s)	CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION						PKG		
	PKG 42	MOS	72	+14d/-14d			31-OCT-2019		
		HRS/MSC	1200	+25/-25			6654.5		
	REF: GENERIC NO REF	AFL					5490		
2710005 EMP (s)	HOLD CHECK CONTROL WHEEL IN A FIXED POSITION AND APPLY UP AND DOWN LOADS ON THE AILERON TRAILING EDGE. OBSERVE AILERON DRIVE ASSEMBLY AREA FOR WEAR IN SHAFT KEYWAYS, FAILURE OF BEARINGS, AND AILERON YOKE SLIPPAGE						PKG		
	PKG 42	MOS	72	+14d/-14d			31-OCT-2019		
		HRS/MSC	1200	+25/-25			6654.5		
	REF: GENERIC NO REF	AFL					5490		
2710010-001 EMP	REPLACE * LEFT AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)								
		MOS					31-OCT-2019		
		HRS/MSC	3600				6654.5		10254.5
LIFE LIMIT	REF: AMM 27-10-02	AFL					5490		
2710010-002 EMP	REPLACE * RIGHT AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)								
		MOS					31-OCT-2019		
		HRS/MSC	3600				6654.5		10254.5
LIFE LIMIT	REF: AMM 27-10-02	AFL					5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2710013-001 EMP	REPLACE * LEFT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)	MOS					28-DEC-2009		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	3600				3549.6 2286	7149.6	
2710013-002 EMP	REPLACE * RIGHT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)	MOS					28-DEC-2009		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	3600				3549.6 2286	7149.6	
2710016 EMP	LEFT * AILERON ASSEMBLY (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0 N:0			0 0 0	20000	
2710016 EMP	RIGHT * AILERON ASSEMBLY (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0 N:0			0 0 0	20000	
2710020 EMP	LEFT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0 N:0			0 0 0	20000	
2710020 EMP	RIGHT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0 N:0			0 0 0	20000	
2710021 EMP	LEFT INBOARD * AILERON INBOARD AND OUTBOARD HINGE BOLTS (AN4H12A) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0 N:0			0 0 0	20000	
2710021 EMP	LEFT OUTBOARD * AILERON INBOARD AND OUTBOARD HINGE BOLTS (AN4H12A) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0 N:0			0 0 0	20000	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2710021 EMP	RIGHT INBOARD * AILERON INBOARD AND OUTBOARD HINGE BOLTS (AN4H12A) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL		N:0			0		
2710021 EMP	RIGHT OUTBOARD * AILERON INBOARD AND OUTBOARD HINGE BOLTS (AN4H12A) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL		N:0			0		
2710022 EMP	LEFT * AILERON SECTOR (5425015) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-10	AFL		N:0			0		
2710022 EMP	RIGHT * AILERON SECTOR (5425015) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-10	AFL		N:0			0		
2710024 EMP	LEFT * AILERON CLEVIS (2324517) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL		N:0			0		
2710024 EMP	REPLACE * AILERON CLEVIS (2324517) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL					0		
2710024 EMP	RIGHT * AILERON CLEVIS (2324517) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL		N:0			0		
2710026 EMP	LEFT * AILERON YOKE ASSEMBLY (2324511) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL		N:0			0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2710026 EMP	REPLACE * AILERON YOKE ASSEMBLY (2324511) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	
2710026 EMP	RIGHT * AILERON YOKE ASSEMBLY (2324511) (AWL*)	MOS		N:0			27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0			0 0	20000	
2710028 EMP	LEFT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)	MOS		N:0			27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0			0 0	20000	
2710028 EMP (s)	REPLACE * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		
2710028 EMP	RIGHT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)	MOS		N:0			27-JUN-2001		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000	N:0 N:0			0 0	20000	
2710031 EMP	LEFT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)	MOS		N:0			27-JUN-2001		
LIFE LIMIT	REF: AMM 57-40-00	HRS/MSC AFL	20000	N:0 N:0			0 0	20000	
2710031 EMP	RIGHT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)	MOS		N:0			27-JUN-2001		
LIFE LIMIT	REF: AMM 57-40-00	HRS/MSC AFL	20000	N:0 N:0			0 0	20000	
2710032 EMP (s)	CHECK AILERON, RUDDER, AND ELEVATOR CONTROL SYSTEM CABLE TENSIONS						PKG		
	PKG 42	MOS	72	+14d/-14d			31-OCT-2019		
	REF: See Workcard	HRS/MSC AFL	1200	+25/-25			6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2710036 EMP	REPLACE * PRIMARY AILERON CONTROL SYSTEM CABLES (AWL*)	MOS					31-OCT-2019		
LIFE LIMIT	REF: AMM 27-10-07	HRS/MSC AFL	2400				6654.5 5490	9054.5	
2710044 EMP (s)	CHECK AILERON AND FLAP SYSTEM CONTROL CABLE TENSIONS	MOS	72	+14d/-14d			31-OCT-2019		
	PKG 42	HRS/MSC AFL	1200	+25/-25			6654.5 5490		
	REF: See Workcard								
2710045 EMP (s)	REMOVE CONTROL WHEEL SECTOR COVER AND TURNBUCKLE COVERPLATE FROM CONTROL COLUMN. MOVE CONTROL WHEEL TO BOTH EXTREME RIGHT AND LEFT WHILE INSPECTING FOR FRAYED OR DAMAGED CABLES	MOS	72	+14d/-14d			31-OCT-2019		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6654.5 5490		
2710046 EMP (s)	DISASSEMBLE CONTROL COLUMN AS REQUIRED TO INSPECT PULLEYS, BEARINGS, ELECTRICAL WIRING FOR PROPER ROUTING AND CHAFING, AND CONTROL COLUMNS FOR GENERAL CONDITION	MOS	108	+14d/-14d			27-JUN-2001		
	PKG 43	HRS/MSC AFL	2400	+25/-25			0 0		
	REF: AMM 27-30-06								
271019	AILERON TRIM ACTUATOR	MOS					27-JUN-2001		
	6600156-034	HRS/MSC	O/C		N:0		0		
	B0050	AFL			N:0		0		
	REF: AMM 27-10-11				N:0		0		
271025	PILOT CONTROL WHEEL	MOS					27-JUN-2001		
	2415151-017	HRS/MSC	O/C		N:0		0		
	2601	AFL			N:0		0		
	REF: AMM 27-10-01				N:0		0		
271026	COPILOT CONTROL WHEEL	MOS					27-JUN-2001		
	2415151-018	HRS/MSC	O/C		N:0		0		
	2593	AFL			N:0		0		
	REF: AMM 27-10-01				N:0		0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271027	PILOT CONTROL COLUMN 5415150-18-622 MRP477452-01 REF: AMM 27-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
271126	AILERON TRIM POSITION INDICATOR 6608217-21 224 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
271131	LEFT AILERON POSITION SENSOR 501-1123-03 81613 REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			29-MAY-2014 4938.5 3653		
271132	RIGHT AILERON POSITION SENSOR 501-1123-03 6714 REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
271701	* LEFT AILERON ASSEMBLY (AWL*) 2424000-283 W620 REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
LIFE LIMIT									
271702	* RIGHT AILERON ASSEMBLY (AWL*) 2424000-295 W639 REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
LIFE LIMIT									
272001	* RUDDER ASSEMBLY (AWL*) 5433000-20 W448 REF: AMM 27-20-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
LIFE LIMIT									
2720016 EMP	REPLACE * RUDDER ASSEMBLY (5433000) (AWL*) REF: AMM 27-20-01	MOS HRS/MSC AFL	20000				27-JUN-2001 0 0	20000	
LIFE LIMIT									

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2720020 EMP	REPLACE * RUDDER HINGE BOLTS (NAS6205 AND NAS464P5) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-20-01	HRS/MSC AFL	20000				0 0	20000	
2720022 EMP	REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-20-09	HRS/MSC AFL	20000				0 0	20000	
2720026 EMP	REPLACE * RUDDER HINGE BRACKETS (5431055 AND 5431056) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 55-30-00	HRS/MSC AFL	20000				0 0	20000	
2720027 EMP (s)	CHECK RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS FOR SECURITY, PROPER OPERATION, AND CLEARANCES						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+25/-25			0 0		
2720029 EMP	REPLACE PRIMARY RUDDER CONTROL SYSTEM CABLES	MOS					31-OCT-2019		
LIFE LIMIT	REF: AMM 27-20-10	HRS/MSC AFL	2400	+25/-25			6654.5 5490	9054.5	9079.5
272007	RUDDER TRIM TAB 5433300-29 SN-UNKNOWN REF: AMM 27-20-02	MOS							
		HRS/MSC AFL	O/C						
272013	RUDDER TRIM TAB ACTUATOR 6600156-033 B0058 REF: AMM 27-20-03	MOS					27-JUN-2001		
		HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
272026	RUDDER TRIM INDICATOR 6608217-20 252 REF: AMM 27-20-06	MOS					27-JUN-2001		
		HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272031	PILOT RUDDER PEDAL ACTUATOR EM423-4 711 REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C				22-AUG-2017 5954 4794		
272032	COPILOT RUDDER PEDAL ACTUATOR EM423-4 646 REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C				07-JUN-2017 5899.4 4754		
273001	* LEFT ELEVATOR ASSEMBLY (AWL*) 2434000-177 W598 REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
2730016 EMP	LEFT * ELEVATOR ASSEMBLY (2434000) (AWL*) PN SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
2730016 EMP	RIGHT * ELEVATOR ASSEMBLY (2434000) (AWL*) PN SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
273002	* RIGHT ELEVATOR ASSEMBLY (AWL*) 2434000-178 W628 REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
2730021 EMP	LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*) PN SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	
2730021 EMP	RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*) PN SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			27-JUN-2001 0 0	20000	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2730022 EMP	LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-01	AFL		N:0			0		
2730022 EMP	RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-01	AFL		N:0			0		
2730024 EMP	LEFT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 04-11-00	AFL		N:0			0		
2730024 EMP	RIGHT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 04-11-00	AFL		N:0			0		
2730030 EMP	REPLACE * PRIMARY ELEVATOR CONTROL SYSTEM CABLES (AWL*)								
		MOS					31-OCT-2019		
		HRS/MSC	2400				6654.5		9054.5
LIFE LIMIT	REF: GENERIC NO REF	AFL					5490		
2730031 EMP	REPLACE * HINGE BRACKETS (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD) (LOCATED ON HORIZONTAL STABILIZER ASSEMBLY) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 27-30-01	AFL					0		
+ 2730036 EMP	ELEVATOR BELLCRANKS - PERFORM EDDY CURRENT INSPECTION								
	PKG 43	MOS	24				(EBT)		16-DEC-2021
		HRS/MSC	600						7280.9
	REF: NDT 27-30-01	AFL							
273013	STALL WARNING COMPUTER								
	6608263-18	MOS		R:0			27-APR-2010		
	1112	HRS/MSC	O/C	R:0			3659.2		
	REF: AMM 27-31-02	AFL		R:0			2379		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273017	PILOT STICK SHAKER 6608289-3 791A REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
273018	COPILOT STICK SHAKER 6608289-3 810A REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
2731000 EMP (s)	PERFORM STALL WARNING SYSTEM FUNCTIONAL TEST PKG 41 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
273101	PILOT STALL WARNING TRANSDUCER 25147A-12 GST03719 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
273102	COPILOT STALL WARNING TRANSDUCER 6608263-019 1011 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C				23-DEC-2009 3548.7 2286		
273105	PILOT ANGLE-OF-ATTACK (AOA) INDICATOR 6608515-2 05064827 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C				23-DEC-2009 3548.7 2286		
2731050 EMP (s)	PERFORM VISUAL INSPECTION ANGLE-OF-ATTACK VANES REF:	MOS HRS/MSC AFL	A/R				27-JUN-2001 0 0		
273106	COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR 6608515-2 01043955 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2731075 EMP (s)	PERFORM FUNCTIONAL TEST OF STALL WARNING ALTITUDE SWITCHES PKG 43 REF: AMM 27-31-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
274001	HORIZONTAL STABILIZER 2332000-60 W340 REF: AMM 27-40-01	MOS HRS/MSC AFL		N:0 N:0 N:0			27-JUN-2001 0 0		
2740010 EMP	REPLACE * HORIZONTAL STABILIZER HINGE PIN (2331028) (AWL*) REF: AMM 27-40-01	MOS HRS/MSC AFL	20000				27-JUN-2001 0 0	20000	
2740011 EMP	REPLACE * HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6) (AWL*) REF: AMM 27-40-02	MOS HRS/MSC AFL	144 6000				27-JUN-2013 4582.6 3269	27-JUN-2025 9269	
2740020 EMP (s)	REMOVE STABILIZER ACTUATOR. INSPECT UPPER AND LOWER ATTACHMENT STRUCTURE FOR FATIGUE CRACKS, DISTORTION, WEAR, CORROSION, AND GENERAL SECURITY PKG 53 REF: AMM 27-40-02	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			27-JUN-2001 0 0		
2740021 EMP	OVERHAUL HORIZONTAL STABILIZER ACTUATOR 5435005-028 219 REF: AMM 27-40-02	MOS HRS/MSC AFL	600	+25/-25			31-OCT-2019 6654.5 5490	7254.5	7279.5
274003	HORIZONTAL STABILIZER ACTUATOR CONTROLLER 6608444-2 1143A REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C		R:0 R:0 R:0		08-JAN-2006 2160.3 1213		
274010	TRIM-IN-MOTION DETECTOR 6608326-004 0117118 REF: AMM 27-41-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274013 (s)	HORIZONTAL STABILIZER ACTUATOR								
	5435005-028	MOS		O:0			31-OCT-2019		
	219	HRS/MSC	600	+25/-25			6654.5		
OVERHAUL	REF: AMM 27-40-02	AFL		O:0			5490		
274062	PITCH TRIM INDICATOR								
	6608514-1	MOS		N:0			27-JUN-2001		
	259	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-40-04	AFL		N:0			0		
274070	STABILIZER POSITION SWITCH								
	CS402-3	MOS		N:0			27-JUN-2001		
	9828	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-40-06	AFL		N:0			0		
274072	STABILIZER POSITION SENSOR								
	501-1123-03	MOS		N:0			27-JUN-2001		
	6715	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
2750002-001 EMP	REPLACE LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)								
		MOS					31-OCT-2019		
		HRS/MSC	1200	+25/-25			6654.5	7854.5	7879.5
LIFE LIMIT	REF: AMM 27-50-01	AFL					5490		
2750002-002 EMP	REPLACE RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)								
		MOS					31-OCT-2019		
		HRS/MSC	1200	+25/-25			6654.5	7854.5	7879.5
LIFE LIMIT	REF: AMM 27-50-01	AFL					5490		
275001	* LEFT FLAP ASSEMBLY (AWL*)								
	6025010-031	MOS		N:0			27-JUN-2001		
	W399	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0		10000
275002	* RIGHT FLAP ASSEMBLY (AWL*)								
	6025010-028	MOS		N:0			27-JUN-2001		
	W1397	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0		10000

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2750025 EMP (s)	REPLACE * INBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625023) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	MOS HRS/MSC AFL	6000				0 0 0		
2750026 EMP	REPLACE * OUTBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625024) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	MOS HRS/MSC AFL	6000				0 0 0		6000
2750027 EMP	LEFT INBOARD * INBOARD AND OUTBOARD FLAP TRACK ASSEMBLY (6022515) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	PN SN-UNKNOWN AFL	20000	N:0 N:0 N:0			0 0 0		20000
2750027 EMP	LEFT OUTBOARD * INBOARD AND OUTBOARD FLAP TRACK ASSEMBLY (6022515) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	PN SN-UNKNOWN AFL	20000	N:0 N:0 N:0			0 0 0		20000
2750027 EMP	RIGHT INBOARD * INBOARD AND OUTBOARD FLAP TRACK ASSEMBLY (6022515) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	PN SN-UNKNOWN AFL	20000	N:0 N:0 N:0			0 0 0		20000
2750027 EMP	RIGHT OUTBOARD * INBOARD AND OUTBOARD FLAP TRACK ASSEMBLY (6022515) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	PN SN-UNKNOWN AFL	20000	N:0 N:0 N:0			0 0 0		20000
2750028 EMP	REPLACE * INBOARD NOSE ROLLER TRACK (FLAP) (2322511) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	MOS HRS/MSC AFL	20000				0 0 0		20000
2750029 EMP (s)	REPLACE * OUTBOARD NOSE ROLLER TRACK (FLAP) (2322512) (AWL*)							27-JUN-2001	
LIFE LIMIT	REF: AMM 27-50-01	MOS HRS/MSC AFL	20000				0 0 0		



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2750030 EMP	LEFT * FLAP ASSEMBLY (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0	10000	
2750030 EMP	RIGHT * FLAP ASSEMBLY (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0	10000	
2750031 EMP	REPLACE * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-1 THRU -8) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC	N/A				0		
NOT APPLICABLE	REF: AMM 27-50-01	AFL					0		
2750033 EMP	LEFT * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0	10000	
2750033 EMP (s)	REPLACE * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000				0		
2750033 EMP	RIGHT * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0	10000	
2750034-002 EMP	REPLACE WING FLAP SECTOR MOUNTING BOLT WHICH SECURES FLAP SECTOR								
		MOS	144	+14d/-14d			27-JUN-2013	27-JUN-2025	11-JUL-2025
		HRS/MSC					4582.6		
LIFE LIMIT	REF: AMM 27-50-01	AFL	6000	+25/-25			3269	9269	9294
2750035-001 EMP	REPLACE LEFT * FLAP SECTOR (2625031) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	6000				0	6000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2750035-002 EMP	REPLACE RIGHT * FLAP SECTOR (2625031) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0		6000
2750044-001 EMP	LEFT FLAP CAM FOLLOWER BEARINGS - PERFORM DETAILED VISUAL INSPECTION OF BEARING	MOS					31-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6654.5 5490	7854.5	7879.5
2750044-002 EMP	RIGHT FLAP CAM FOLLOWER BEARINGS - PERFORM DETAILED VISUAL INSPECTION OF BEARING	MOS					31-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6654.5 5490	7854.5	7879.5
2750049 EMP	LEFT INBOARD * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-13 THRU -22, -801 THRU -822) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-50-01	PN SN-UNKNOWN AFL	20000	N:0 N:0 N:0			0 0 0		20000
2750049 EMP	LEFT OUTBOARD * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-13 THRU -22, -801 THRU -822) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-50-01	PN SN-UNKNOWN AFL	20000	N:0 N:0 N:0			0 0 0		20000
2750049 EMP (s)	REPLACE * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-13 THRU -22, -801 THRU -822) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		
2750049 EMP	RIGHT INBOARD * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-13 THRU -22, -801 THRU -822) (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-50-01	PN SN-UNKNOWN AFL	20000	N:0 N:0 N:0			0 0 0		20000



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2750049 EMP	RIGHT OUTBOARD * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-13 THRU -22, -801 THRU -822) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000	N:0			0		20000
2750050 EMP	LEFT * UPPER FLAP SECTOR BRACKET ASSEMBLY ((6022511-005, -006, -009, -010, -803, -804, -805, -806) {6022500V1-001, -002}) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000	N:0			0		20000
2750050 EMP (s)	REPLACE * UPPER FLAP SECTOR BRACKET ASSEMBLY ((6022511-005, -006, -009, -010, -803, -804, -805, -806) {6022500V1-001, -002}) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0		
2750050 EMP	RIGHT * UPPER FLAP SECTOR BRACKET ASSEMBLY ((6022511-005, -006, -009, -010, -803, -804, -805, -806) {6022500V1-001, -002}) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000	N:0			0		20000
2750051 EMP	REPLACE * INBOARD FLAP TRACK HINGE FITTING (P/N 6025022) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0		20000
2750052 EMP	REPLACE * OUTBOARD FLAP TRACK HINGE FITTING (P/N 6025021) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0		20000
+ 2750058 EMP	* LEFT FLAP LEADING EDGE RIB - REPLACE (AWL*)								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	N/A				0		
LIFE LIMIT	REF: See Workcard	AFL					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 2750058 EMP	* LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				27-JUN-2001 0 0		
2750058 EMP	* LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				27-JUN-2001 0 0		
2750058 EMP	* RIGHT FLAP LEADING EDGE RIB - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				27-JUN-2001 0 0		
LIFE LIMIT									
+ 2750058 EMP	* RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				27-JUN-2001 0 0		
+ 2750058 EMP	* RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				27-JUN-2001 0 0		
275010	FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSEMBLY 6018336-4 A01854329-01 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C				03-SEP-2014 5000.5 3729		
275012	FLAP POSITION POTENTIOMETER RV4SAYSD102A SN-UNKNOWN REF: AMM 27-50-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2007 2655.2 1505		
275019	LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH CS402-3 9605 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275020	RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH CS402-3 9637 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
275021	LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 9597 REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
275022	RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 9684 REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
275031	FLAP CONTROL (FLAP/SPOILER) VALVE 6600362-1 129 REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C				01-JUN-2007 2728.1 1574		
275036	FLAP RESTRICTOR VALVE 2R1047-0312 2152 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
275037	LEFT FLAP ACTUATOR 6600493-2 0363 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
275038	RIGHT FLAP ACTUATOR 6600493-2 0354 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
275200	FLAP POSITION INDICATOR 6608475-004 139 REF: AMM 27-50-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275213	FLAP PRESSURE RELIEF VALVE AN6245A4 18862 REF: AMM 27-50-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
2760003 EMP (s)	INSPECT SPOILER ACTUATOR INSTALLATION FOR SECURITY, SUPPORT STRUCTURE CRACKS, AND GENERAL CONDITION PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490	PKG	
276001	* LEFT SPOILER ASSEMBLY (AWL*) 2422510-137 077 REF: AMM 27-60-01	MOS HRS/MSC AFL APH ACH	4500	N:0 N:0 N:0			28-DEC-2009 3548.7 2286		8048.7
276002	* RIGHT SPOILER ASSEMBLY (AWL*) 2492001-802 W2030S REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	N:0 N:0 N:0			28-SEP-2012 4346.6 3005		8846.6
2760030 EMP (s)	INSPECT SPOILER AND HINGE INSTALLATION FOR SECURITY, CRACKS, AND GENERAL CONDITION PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490	PKG	
2760031 EMP (s)	INSPECT SPOILER CENTER ANGLE BRACKET RIVETS, LOWER SKIN CENTER RIB AND SUBSPAR RIVETS FOR EVIDENCE OF WORKING. WITH SPOILERS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO SPOILER TRAILING EDGE. CHECK MOTION AT CENTER HINGE. INSPECT SPOILER ACTUATOR MECHANISM AND HINGE INSTALLATION FOR SECURITY, CRACKS, AND GENERAL CONDITION. (SEE FIGURE) PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0	PKG	
2760040 EMP (s)	PERFORM FUNCTIONAL TEST OF SPOILER RESTRICTOR BYPASS VALVE COMPUTER CIRCUITRY AND WIRING PKG 43 REF: AMM 27-60-03	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0	PKG	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2760050 EMP (s)	PERFORM FUNCTIONAL TEST OF SPOILER (UP LIMIT) SWITCH PKG 52	MOS	12000	+25/-25			PKG 27-JUN-2001 0 0		
	REF: AMM 27-60-05	AFL							
2760059-001 EMP	REPLACE * 5/16 LEFT SPOILER ATTACH BOLTS (NAS464-P5A14) (AWL*)	MOS	4500				28-SEP-2012 4346.6 3005	8846.6	
LIFE LIMIT	REF: AMM 27-60-01	AFL							
2760059-002 EMP	REPLACE * 5/16 RIGHT SPOILER ATTACH BOLTS (NAS464-P5A14) (AWL*)	MOS	4500				28-SEP-2012 4346.6 3005	8846.6	
LIFE LIMIT	REF: AMM 27-60-01	AFL							
2760060-001 EMP	REPLACE * LEFT SPOILER ASSEMBLY (2422510 AND 2492001) (AWL*)	MOS	4500				28-SEP-2012 4346.6 3005	8846.6	
LIFE LIMIT	REF: AMM 27-60-01	AFL							
2760060-002 EMP	REPLACE * RIGHT SPOILER ASSEMBLY (2422510 AND 2492001) (AWL*)	MOS	4500				28-SEP-2012 4346.6 3005	8846.6	
LIFE LIMIT	REF: AMM 27-60-01	AFL							
2760061-001 EMP	REPLACE * LEFT SPOILER ACTUATOR ARM ASSEMBLY (2422511) (AWL*)	MOS	4500				28-SEP-2012 4346.6 3005	8846.6	
LIFE LIMIT	REF: AMM 27-60-04	AFL							
2760061-002 EMP	REPLACE * RIGHT SPOILER ACTUATOR ARM ASSEMBLY (2422511) (AWL*)	MOS	4500				28-SEP-2012 4346.6 3005	8846.6	
LIFE LIMIT	REF: AMM 27-60-04	AFL							
2760062-001 EMP	REPLACE * LEFT SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)	MOS	4500				28-SEP-2012 4346.6 3005	8846.6	
LIFE LIMIT	REF: AMM 27-60-04	AFL							



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2760062-002 EMP	REPLACE * RIGHT SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)	MOS					28-SEP-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4346.6 3005		8846.6
2760063-001 EMP	REPLACE * LEFT SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)	MOS					28-SEP-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4346.6 3005		8846.6
2760063-002 EMP	REPLACE * RIGHT SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)	MOS					28-SEP-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4346.6 3005		8846.6
2760064L0 EMP	REPLACE * LEFT OUTBOARD SPOILER HINGE BOLT (AN4-13) (AWL*)	MOS					28-SEP-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4346.6 3005		8846.6
2760064LI EMP	REPLACE * LEFT INBOARD SPOILER INBOARD/OUTBOARD HINGE BOLT (AN4-13) (AWL*)	MOS					28-SEP-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4346.6 3005		8846.6
2760064R0 EMP	REPLACE * RIGHT OUTBOARD SPOILER HINGE BOLT (AN4-13) (AWL*)	MOS					28-SEP-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4346.6 3005		8846.6
2760064RI EMP	REPLACE * RIGHT INBOARD SPOILER INBOARD/OUTBOARD HINGE BOLT (AN4-13) (AWL*)	MOS					28-SEP-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4346.6 3005		8846.6
2760078-001 EMP	REPLACE * LEFT SPOILER ACTUATOR ASSEMBLY (AWL*)	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	10000				0 0		10000

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2760078-002 EMP	REPLACE * RIGHT SPOILER ACTUATOR ASSEMBLY (AWL*) 2417015-5 2083	MOS HRS/MSC	10000				27-JUN-2001 0		10000
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
2760079-001 EMP	REPLACE * LEFT SPOILER ACTUATOR ATTACH FITTING (2422513) AND BOLT (BACB30NJ4D10, BACB30UU4-10D) (AWL*)	MOS HRS/MSC	10000				27-JUN-2001 0		10000
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
2760079-002 EMP	REPLACE * RIGHT SPOILER ACTUATOR ATTACH FITTING (2422513) AND BOLT (BACB30NJ4D10, BACB30UU4-10D) (AWL*)	MOS HRS/MSC	10000				27-JUN-2001 0		10000
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
276010	SPOILER COMPUTER MOD 10 6608454-3 1563	MOS HRS/MSC	O/C	R:0 R:0			18-DEC-2015 5410.1		
	REF: AMM 27-60-02	AFL		R:0			4214		
276013	* LEFT SPOILER ACTUATOR ASSEMBLY (AWL*) 2417015-5 2082	MOS HRS/MSC	10000	N:64 R:0 N:2572.1 R:0			05-OCT-2006 2572.1		10000
LIFE LIMIT	REF: AMM 27-60-04	AFL		N:1441 R:0			1441		
276014	* RIGHT SPOILER ACTUATOR ASSEMBLY (AWL*) 2417015-5 2083	MOS HRS/MSC	10000	N:64 R:0 N:2572.1 R:0			05-OCT-2006 2572.1		10000
LIFE LIMIT	REF: AMM 27-60-04	AFL		N:1441 R:0			1441		
276037	LEFT SPOILER POSITION SENSOR 501-1123-03 80607	MOS HRS/MSC	O/C	N:0 N:0			10-MAY-2011 3930.7		
	REF: AMM 27-60-07	AFL		N:0			2602		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276038	RIGHT SPOILER POSITION SENSOR 501-1123-03 6696 REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
276043	SPOILER POTENTIOMETER RV4ASAYSD102A SN-UNKNOWN REF: AMM 27-60-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-FEB-2006 2208.2 1235		
276049	SPOILER POSITION INDICATOR 6608476-3 254 REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
276128	SPOILER MANIFOLD VALVE 2627052-003 1053 REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	N:64 O:0 N:2572.1 O:0 N:1441 O:0			05-OCT-2006 2572.1 1441		
276265	WHEEL SPEED DETECTION BOX 6081044-805366-005 MRP516732-01 REF: AMM 27-60-12	MOS HRS/MSC AFL	O/C				18-OCT-2007 2773.7 1622		
CHAPTER 28 FUEL									
280003	LEFT WING DEFUEL VALVE 6600145-3 3722 REF: AMM 28-00-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
280004	RIGHT WING DEFUEL VALVE 6600145-3 3558 REF: AMM 28-00-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281007	LEFT CHECK, CROSSFLOW VALVE 7600004-1 1010253 REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281008	RIGHT CHECK, CROSSFLOW VALVE 7600004-1 1010255 REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281027	FWD FUSELAGE FUEL CELL 6600500-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
281028	AFT FUSELAGE FUEL CELL 6600501-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
281201	AFT FUSELAGE FUEL CELL 501847 114877 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:786.4 R:0 N:447 R:0			21-AUG-2017 5951.6 4793		
281202	FORWARD FUSELAGE FUEL CELL 501848 T003015 REF: AMM 28-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0			21-AUG-2017 5951.6 4793		
2812030 EMP (s)	REMOVE LOWER SURFACE ACCESS PLATES, INSPECT INTERIOR AND EXTERIOR WING STRUCTURE FOR EVIDENCE OF FUEL LEAKAGE, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, BACTERIAL GROWTH, FILIFORM CORROSION, AND GENERAL CONDITION. INSPECT WING FLAPPER VALVES FOR FREEDOM OF MOVEMENT, SECURITY, POSITIVE SEAL, AND GENERAL CONDITION PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
LIFE LIMIT									

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2812060 EMP (s)	PERFORM OPERATIONAL CHECK OF WING LOW FUEL WARNING SYSTEM PKG 42	MOS	72	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 28-14-00	HRS/MSC AFL	1200	+25/-25			6654.5 5490		
2812070 EMP (s)	PERFORM OPERATIONAL CHECK OF FUEL CROSSFLOW VALVE AND MOTIVE FLOW CONTROL VALVES PKG 43	MOS	108	+14d/-14d			PKG	27-JUN-2001	
	REF: See Workcard	HRS/MSC AFL	2400	+25/-25			0 0		
281301	LEFT WING FUEL VENT FLOAT VALVE 6600346-2	MOS			N:0			27-JUN-2001	
	3787	HRS/MSC	O/C		N:0			0	
	REF: AMM 28-13-01	AFL			N:0			0	
2813011 EMP (s)	DEFUEL FUSELAGE FUEL CELL AND PERFORM FUEL CELL STATIC ELECTRICAL BONDING RESISTANCE CHECK. CHECK FUSELAGE FUEL CELL FOR CLEANLINESS PKG 48	MOS					PKG	27-JUN-2001	
	REF: AMM 28-12-00	HRS/MSC AFL	3000	+25/-25			0 0		
281302	RIGHT WING FUEL VENT FLOAT VALVE 6600346-2	MOS			N:0			27-JUN-2001	
	3796	HRS/MSC	O/C		N:0			0	
	REF: AMM 28-13-01	AFL			N:0			0	
281303	FUSELAGE FUEL VENT FLOAT VALVE 6600346-2	MOS			N:0			27-JUN-2001	
	3777	HRS/MSC	O/C		N:0			0	
	REF: AMM 28-13-01	AFL			N:0			0	
281307	LEFT FUEL CELL PRESSURE RELIEF VALVE RV62-2	MOS			N:0			27-JUN-2013	
	410189	HRS/MSC	O/C		N:0			4582.6	
	REF: AMM 28-13-07	AFL			N:0			3269	
281308	RIGHT FUEL CELL PRESSURE RELIEF VALVE RV62-2	MOS			N:0			27-JUN-2013	
	4101819	HRS/MSC	O/C		N:0			4582.6	
	REF: AMM 28-13-07	AFL			N:0			3269	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281309	FUSELAGE FLAME ARRESTOR 9909018-101 430 REF: AMM 28-13-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281401	LEFT FUSELAGE CELL TRANSFER PUMP 2380060-052 C4683 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-JUN-2013 4582.6 3269		
281402	RIGHT FUSELAGE CELL TRANSFER PUMP 2380060-052 C3764 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-JUN-2013 4582.6 3269		
2814021 EMP (s)	PERFORM FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES PKG 43 REF: AMM 28-13-07	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
281403	LEFT INBOARD WING SCAVENGE JET PUMP 2326023-32 SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C						
2814039 EMP (s)	PERFORM FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK VACUUM RELIEF VALVE PKG 43 REF: AMM 28-13-06	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
2814041 EMP (s)	PERFORM BENCH CHECK OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES PKG 53 REF: AMM 28-13-07	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
281407	LEFT OUTBOARD WING SCAVENGE JET PUMP 2326023-32 SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281409	LEFT SCAVENGE PUMP 2380060-42 B5175 REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	O:18 O:0 O:0			22-JUN-2010 3733.1 2443		
281410	RIGHT SCAVENGE PUMP 2380060-42 C220 REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			22-JUN-2010 3733.1 2443		
281411	LEFT FUEL TRANSFER VALVE 6600355-005 60611189 REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-JUN-2017 5926.3 4772		
281412	RIGHT FUEL TRANSFER VALVE 6600355-4 1030774 REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281414	FUSELAGE HIGH-LEVEL FLOAT SWITCH L14F-94 230 REF: AMM 28-14-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281415	LEFT FUEL TRANSFER PRESSURE INDICATING SWITCH 7600002-3 1073 REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281416	RIGHT FUEL TRANSFER PRESSURE INDICATING SWITCH 7600002-3 1083 REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281417	LEFT WING HIGH-LEVEL FLOAT SWITCH L15H-59 1342-1362 REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAY-2017 5881.3 4732		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281418	RIGHT WING HIGH-LEVEL FLOAT SWITCH L15H-59 1363-1391 REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAY-2017 5881.3 4732		
281419	LEFT WING LOW-LEVEL FLOAT SWITCH L15H-8 11341 REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
281420	RIGHT WING LOW-LEVEL FLOAT SWITCH L15H-8 10995 REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
2820003 EMP (s)	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AIRCRAFT (PRESSURE)	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
TEFLON	REF: AMM 28-00-00								
2820010 EMP (s)	CLEAN/LEAK CHECK LOW PRESSURE FUEL FILTERS. ON AIRCRAFT EQUIPPED WITH PAPER FILTERS, REMOVE AND REPLACE FILTERS PKG 41 REF: See Workcard	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490	PKG	
2820020 EMP (s)	PERFORM OPERATIONAL CHECK OF FUEL SUPPLY SHUTOFF VALVE AND HYDRAULIC SUPPLY SHUTOFF VALVES PKG 42 REF: See Workcard	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490	PKG	
282003	LEFT STANDBY PUMP 2380060-49 C3529 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2820030 EMP (s)	INSPECT FUEL SUPPLY LINE CHECK VALVE ORIFICES FOR CONDITION AND CLEANLINESS PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	
	REF: AMM 28-20-03	AFL	6000	+25/-25			0	0	
282004	RIGHT STANDBY PUMP 2380060-49	MOS		N:0			27-JUN-2001		
	C3533	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-02	AFL		N:0			0		
282005	LEFT FUEL FILTER ASSEMBLY 6600488-4	MOS		N:0			27-JUN-2001		
	1727	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-04	AFL		N:0			0		
282006	RIGHT FUEL FILTER ASSEMBLY 6600488-4	MOS		N:0			27-JUN-2001		
	1743	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-04	AFL		N:0			0		
282007	LEFT ENGINE FUEL SHUTOFF VALVE EM91-119	MOS		R:0			27-JUN-2013		
	10-020179	HRS/MSC	O/C	R:0			4582.6		
	REF: AMM 28-20-05	AFL		R:0			3269		
282008	RIGHT ENGINE FUEL SHUTOFF VALVE 6600355-4	MOS							
	10410179	HRS/MSC	O/C						
	REF: AMM 28-20-05	AFL							
282009	LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE 6600354-4	MOS		R:0			28-DEC-2009		
	070207270	HRS/MSC	O/C	R:0			3549.6		
	REF: AMM 28-20-06	AFL		R:0			2287		
282010	RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE 6600354-4	MOS					27-JUN-2001		
	10312628	HRS/MSC	O/C				0		
	REF: AMM 28-20-06	AFL					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282011	LEFT ENGINE RELIEF VALVE 7600005-1 10202145 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282012	RIGHT ENGINE RELIEF VALVE 7600005-1 10202152 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282013	FUEL CONTROL RELAY PANEL 6018810-005 SN-UNKNOWN REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C						
282015	LEFT WING PILOT VALVE 2780610-102 1947 REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282016	RIGHT WING PILOT VALVE 2780610-102 1959 REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282017	LEFT WING REFUELING SHUTOFF VALVE 2780614-102 1273 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282018	RIGHT WING REFUELING SHUTOFF VALVE 2780614-102 1272 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282019	FUSELAGE PILOT VALVE 2780610-102 SN-UNKNOWN REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282020	FUSELAGE VENT VALVE 2780612-104 1009 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-JUL-2012 4267.5 2915		
282021	REFUELING CHECK VALVE 2780623-101 636 REF: AMM 28-20-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282022	FUSELAGE REFUELING SHUTOFF VALVE 2780624-102 748 REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282023	FUEL SOLENOID VALVE 2780613-101 0693 REF: AMM 28-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282024	PRESSURE REFUELING ADAPTER 2780609-101 751 REF: AMM 28-20-16	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282025	LEFT PRECHECK VALVE 2780615-102 1335 REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
282025-01	#1 FUEL SHUTOFF VALVE EM91-119 10-202179 REF:	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-JUN-2013 4582.6 3269		
282026	RIGHT PRECHECK VALVE 2780615-102 1355 REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282026-01	#2 FUEL SHUTOFF VALVE 6600355-4 10410179 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
284001	LEFT INBOARD WING (MT5) FUEL PROBE 2326014-016 07051217 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				28-DEC-2009 3548.7 2286		
284002	RIGHT INBOARD WING (MT6) FUEL PROBE 2326014-12 12110874A REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-JUL-2015 5263.3 4033		
284003	LEFT OUTBOARD WING (MT7) FUEL PROBE 2326014-9 06082190A REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				28-SEP-2012 4346.6 3005		
284004	RIGHT OUTBOARD WING (MT8) FUEL PROBE 2326014-9 09062343 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				02-JUL-2012 4267.5 2915		
284005	LEFT INBOARD WING EXTENSION STA 189 (MT9) FUEL PROBE 2826003-6 10111708A REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				28-SEP-2012 4346.6 3005		
284006	RIGHT INBOARD WING EXTENSION STA 189 (MT10) FUEL PROBE 2826003-6 10121731 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JAN-2012 4119.7 2764		
284007	LEFT OUTBOARD WING EXTENSION STA 244 (MT11) FUEL PROBE 2826003-3 07081519 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				27-APR-2010 3659.2 2379		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284008	RIGHT OUTBOARD WING EXTENSION STA 244 (MT12) FUEL PROBE 2826003-3 11121733 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				02-JUL-2012 4267.5 2915		
284009	FUSELAGE (MT18) FUEL PROBE 0118KTU01 008364 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
284011	LEFT ENGINE LOW FUEL PRESSURE SWITCH 7600002-2 3993 REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
284012	RIGHT ENGINE LOW FUEL PRESSURE SWITCH 7600002-2 3998 REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
284013	FUEL QUANTITY INDICATOR TRACKED ITEM 6608529-001 FM8554 REF: AMM 28-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-JUL-2012 4267.5 2915		
284019	FUEL, LEFT WING, INBD PROBE 2326014-16 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
CHAPTER 29 HYDRAULIC POWER									
2900001 EMP	REPLACE HYDRAULIC HOSE ASSEMBLIES (EXCLUDING HOSES FOR THE LANDING GEAR AND THOSE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
TEFLON	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2900004 EMP (s)	PERFORM HYDRAULIC RESERVOIR PRESSURE RELIEF VALVE BENCH FUNCTIONAL TEST PKG 43 REF: AMM 29-00-08	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
2900005 EMP (s)	PERFORM HYDRAULIC RESERVOIR VACUUM RELIEF VALVE BENCH FUNCTIONAL TEST PKG 43 REF: AMM 29-00-08	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
290002	HYDRAULIC PRESSURE REGULATOR 55950-2 0556 REF: AMM 29-00-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-JAN-2011 3850.3 2532		
290003	HYDRAULIC RESERVOIR 5417007-35 SN-UNKNOWN REF: AMM 29-00-03	MOS HRS/MSC AFL	O/C						
290005	PRESSURE REGULATOR CHECK VALVE 496-4D2-1/4 SN-UNKNOWN REF: AMM 29-00-05	MOS HRS/MSC AFL	O/C						
2910008 EMP (s)	REMOVE HYDRAULIC RESERVOIR PRESSURE REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION PKG 42 REF: See Workcard	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
2910009 EMP (s)	REMOVE/CLEAN OR REPLACE AUXILIARY HYDRAULIC PUMP FILTER PKG 43 REF: AMM 29-20-02	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
291001	LEFT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE 6600355-2 10402437 REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2910019 EMP	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS	MOS					31-OCT-2019		
LIFE LIMIT	REF: AMM 29-10-03	HRS/MSC AFL	600	+25/-25			6654.5 5490	7254.5	7279.5
291002	RIGHT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE	MOS					27-JUN-2001		
	6600355-2	HRS/MSC	O/C	N:0			0		
	10402438	AFL		N:0			0		
	REF: AMM 29-10-01								
2910023 EMP (s)	INSPECT HYDRAULIC RESERVOIR FILLER FILTER ELEMENT AND REPLACE IF REQUIRED	MOS	108	+14d/-14d			27-JUN-2001		
	PKG 43	HRS/MSC	2400	+25/-25			0		
	REF: AMM 29-00-04	AFL					0		
2910024 EMP (s)	INSPECT HYDRAULIC FILTERS (PRESSURE AND RETURN) DIFFERENTIAL PRESSURE INDICATORS FOR BYPASS INDICATION	MOS	36	+14d/-14d			31-OCT-2019		
	PKG 41	HRS/MSC	600	+25/-25			6654.5		
	REF: AMM 29-10-03	AFL					5490		
2910025 EMP (s)	REMOVE HYDRAULIC RESERVOIR PRESSURE REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION	MOS	N/A				31-OCT-2019		
	PKG 41	HRS/MSC					6654.5		
NOT APPLICABLE	REF: See Workcard	AFL					5490		
291003	LEFT ENGINE DRIVEN HYDRAULIC PUMP	MOS					13-FEB-2016		
	6607066-1	HRS/MSC	O/C	O:1			5458.3		
	K0788AB	AFL		O:0			4277		
	REF: AMM 29-10-02			O:0					
291004	RIGHT ENGINE DRIVEN HYDRAULIC PUMP	MOS					23-DEC-2014		
	6607066-1	HRS/MSC	O/C	O:2			5089.2		
	277486AB	AFL		O:0			3840		
	REF: AMM 29-10-02			O:0					

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291005	HYDRAULIC PRESSURE FILTER ASSEMBLY M8815/1A-10 0252 REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
291006	HYDRAULIC RETURN FILTER ASSEMBLY M8815/1A-10 0257 REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
291007	HYDRAULIC SYSTEM ACCUMULATOR MS28700-3 8423-10711 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
291008	HYDRAULIC THRUST REVERSER ACCUMULATOR 088424010 8424-20961T REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				25-FEB-2016 5467.9 4292	
291015	HYDRAULIC RELIEF VENT VALVE 2380103-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
291020	HYDRAULIC RESERVOIR RELIEF VALVE 5120T8TT20 10301750 REF: AMM 29-00-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				20-JUL-2006 2471.3 1390	
291220	THRUST REVERSER ISOLATION VALVE 6607070-1 236 REF: AMM 78-30-27	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
291225	HYDRAULIC PRESSURE RELIEF VALVE 1280 253 REF: AMM 29-00-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2920000 EMP (s)	PERFORM THRUST REVERSER HYDRAULIC RETURN LINE CHECK VALVE FUNCTIONAL TEST PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	
	REF: AMM 29-10-05	AFL	6000	+25/-25			0	0	
292001	AUXILIARY HYDRAULIC PUMP 6600248-1	MOS		N:0			27-JUN-2001		
	01814	HRS/MSC	O/C	N:0			0		
	REF: AMM 29-20-01	AFL		N:0			0		
293001	HYDRAULIC PRESSURE MT15 TRANSDUCER 124058-3000	MOS		N:0			27-JUN-2001		
	42337	HRS/MSC	O/C	N:0			0		
	REF: AMM 29-30-01	AFL		N:0			0		
		APH		N:0			0		
		ACH		N:0			0		
293002	AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH 730626	MOS					30-MAY-2007		
	F1447	HRS/MSC	O/C				2728.1		
	REF: AMM 29-30-02	AFL					1574		
293003	HYDRAULIC PRESSURE INDICATOR 6608401-13	MOS		N:0			27-JUN-2001		
	441	HRS/MSC	O/C	N:0			0		
	REF: AMM 29-30-03	AFL		N:0			0		
293005	LEFT HYDRAULIC PUMP PRESSURE SWITCH 730635	MOS		N:0			27-JUN-2001		
	A473	HRS/MSC	O/C	N:0			0		
	REF: AMM 29-30-04	AFL		N:0			0		
293006	RIGHT HYDRAULIC PUMP PRESSURE SWITCH 730635	MOS		N:0			27-JUN-2001		
	A485	HRS/MSC	O/C	N:0			0		
	REF: AMM 29-30-04	AFL		N:0			0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293010	HYDRAULIC SYSTEM PRESSURE GAUGE S-218-2 1497 REF: AMM 29-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				24-JAN-2012 4120.2 2765	
293015	THRUST REVERSER HYDRAULIC PRESSURE GAUGE S-218-2 1626 REF: AMM 29-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				22-JAN-2009 3202.5 1989	
CHAPTER 30 ICE AND RAIN PROTECTION									
3010001 EMP (s)	PERFORM WING ANTI-ICE CHECK VALVE OPERATIONAL CHECK PKG 41 REF: AMM 30-10-08	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25				PKG 31-OCT-2019 6654.5 5490	
301001	WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE 6600259-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						
301002	WING RT10 ANTI-ICE TEMPERATURE SENSOR FG-101PM SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C						
301003	WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR FG-101PM SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C						
301004	WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR FG-101PM SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301006	WING TEMPERATURE INDICATOR 6608210-32 530 REF: AMM 30-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
301007	LEFT WING ANTI-ICE BYPASS VALVE 27441482-13 3AU12 REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
301008	RIGHT WING ANTI-ICE BYPASS VALVE 27441482-13 3AU16 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
301014	WING ANTI-ICE VALVE 6600259-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						
301015	LEFT WING ANTI-ICE CHECK VALVE 1H95-8 4AU30 REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
301016	RIGHT WING ANTI-ICE CHECK VALVE 1H95-8 4AU31 REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
301101	HORIZONTAL STABILIZER ANTI-ICE CONTROLLER 6608485-1 206300144 REF: AMM 30-11-01	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			06-OCT-2010 3795.9 2495		
301103	LEFT HORIZONTAL STABILIZER HEAT BLANKET (BOOT) 4065-3481 18-66083 REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-OCT-2018 6341.2 5193		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301104	RIGHT HORIZONTAL STABILIZER HEAT BLANKET (BOOT) 4065-3481 1866058 REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-OCT-2018 6341.2 5193		
301109	CBR9 REMOTE CIRCUIT BREAKER SM600BA40A1 61985 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
301110	CBR10 REMOTE CIRCUIT BREAKER SM600BA40A1 98520 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-NOV-2009 3546 2283		
301111	CBR11 REMOTE CIRCUIT BREAKER SM600BA40A1 61986 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3020001-001 EMP (s)	INSPECT NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 29 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				20-AUG-2017 5951.6 4793		PKG
3020001-002 EMP (s)	INSPECT NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				20-AUG-2017 5951.6 4793		PKG
302101	LEFT NACELLE ANTI-ICE SHUTOFF VALVE 27441482-09 6AU41 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302102	RIGHT NACELLE ANTI-ICE SHUTOFF VALVE 27441482-09 5BD18 REF: See Workcard	MOS HRS/MSC AFL	O/C				14-SEP-2019 6629.4 5466		
302103	LEFT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 3241TW REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
302104	RIGHT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 3248TW REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
303001	LEFT PITOT HEAT MONITOR- 6608317-7 3020 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
303002	RIGHT PITOT HEAT MONITOR- 6608317-7 3001 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
303003	STANDBY PITOT HEAT MONITOR- 6608317-7 3010 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3040008 EMP (s)	PERFORM FUNCTIONAL TEST OF WINDSHIELD ANTI-ICE SYSTEM TIMER CIRCUIT PKG 43 REF: AMM 30-40-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
304001	WINDSHIELD ANTI-ICE SHUTOFF VALVE 6600201-1 192 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304002	WINDSHIELD ANTI-ICE MODULATING VALVE 27241287-12 2AU9 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
304003	WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE 6600203-1 1AU13 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
304004	WINDSHIELD ANTI-ICE HEAT EXCHANGER 6600351-2 1041 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
304005	WINDSHIELD ANTI-ICE TEMPERATURE SENSOR 6600203-7 11AT48 REF: AMM 30-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
304007	LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH 6600141-3 6080DA REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C				27-JUN-2013 4582.6 3269		
304007	WINDSHIELD ANTI-ICE VALVE 6600201-1 52 REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			05-SEP-2019 6623.2 5461		
304008	RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH 6600141-3 6081DA REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C				27-JUN-2013 4582.6 3269		
304009	LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH 6600141-13 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304010	RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH 6600141-13 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C						
304102	ALCOHOL ANTI-ICE FLOAT SWITCH L14F-74 610 REF: AMM 30-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
304104	ALCOHOL PRESSURE RELIEF VALVE 6608260-3 1395 REF: AMM 30-41-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
304105	ANTI-ICE THREE-WAY SHUTOFF VALVE 6608258-2 1640 REF: AMM 30-41-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
304106	ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE 6608257-1 2019A REF: AMM 30-41-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-OCT-2016 5670.3 4516		
3050003 EMP (s)	PERFORM OPERATIONAL CHECK OF ALCOHOL ANTI-ICE SYSTEM PKG 42 REF: AMM 30-41-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
3050009 EMP (s)	CLEAN ALCOHOL ANTI-ICE FILTER ELEMENT. REPLACE FILTER ELEMENT IF MADE OF PAPER PKG 43 REF: AMM 30-41-03	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
308001	LEFT ICE DETECT LAMP 0871HJ1 0026 REF: AMM 30-80-01	MOS HRS/MSC AFL APH ACH	O/C	N:0 N:0 N:0 N:0 N:0			14-DEC-2001 18 14		
308002	RIGHT ICE DETECT LAMP 3118120-1 SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
308003-701	ICE DETECTOR 0871HJ1 0291 REF:	MOS HRS/MSC AFL	O/C				19-MAR-2020 6774.5 5614		
U3020001A	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION REF:	MOS HRS/MSC AFL	3600	+50			20-AUG-2017 5951.6 4793	9551.6	9601.6
U3020001B	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION REF:	MOS HRS/MSC AFL	3600	+50			20-AUG-2017 5951.6 4793	9551.6	9601.6
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
3110000 EMP (s)	CHECK EQUIPMENT INSTALLATIONS BETWEEN FORWARD PRESSURE BULKHEAD AND INSTRUMENT PANEL FOR SECURITY OF MOUNTING, WIRE ROUTING, AND CLEARANCES OF WIRING AND PLUMBING PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0		
311016	RIGHT UPPER ISOLATION, PITOT/STATIC VALVE 6600473-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312001	PILOT CREW CLOCK M877 23808 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-APR-2018 6183.5 5035		
312002	COPILOT CREW CLOCK M877 12228 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
312011	REPLACE PILOT DIGITAL CLOCK BATTERY PN SN-UNKNOWN REF: CMM STANDARD AND OPTIONAL FEATURES	MOS HRS/MSC AFL	24	N:0 N:0 N:0			31-MAR-2020 6774.5 5614	31-MAR-2022	
312012	REPLACE COPILOT DIGITAL CLOCK BATTERY PN SN-UNKNOWN REF: CMM STANDARD AND OPTIONAL FEATURES	MOS HRS/MSC AFL	24	N:0 N:0 N:0			31-MAR-2020 6774.5 5614	31-MAR-2022	
313018	FDR INERTIA SWITCH 3L0-453/8 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
314002	IAPS CARD CAGE 822-0269-001 FJ6D REF: AMM 31-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
314011	1A PWR-851A POWER SUPPLY CARD 622-8365-003 1286 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C				21-APR-2009 3324.7 2085		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314012	2A PWR-851A POWER SUPPLY CARD 622-8365-003 FLJP REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
314013	1B PWR-851A POWER SUPPLY CARD 622-8365-003 FNPR REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
314014	2B PWR-851A POWER SUPPLY CARD 622-8365-003 FNPT REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
314021	1A FLIGHT CONTROL CARD 822-0592-407 FFMV REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:115			08-FEB-2010 3590 2313		
314022	2A FLIGHT CONTROL CARD 822-0592-407 770 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			05-APR-2019 6431.9 5305		
314033	1B FLIGHT MANAGEMENT - FMC 852C CARD 622-9925-205 SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C						
314034	2B FLIGHT MANAGEMENT - FMC 852C CARD 622-9925-205 SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C						
314101	DATA ACQUISITION UNIT (MOD 1,2,3) 622-9344-001 5LTM REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C				23-MAR-2007 2673.1 1523		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3151001 EMP (s)	PERFORM AUTOPILOT-DATA CONCENTRATOR UNIT (DCU) OPERATIONAL CHECK OF AUTOPILOT AURAL WARNING PKG 41	MOS					PKG	31-OCT-2019	
N/A BY A/C SERIAL NUMBER	REF: AMM 31-51-00	HRS/MSC AFL	N/A				6654.5 5490		
315101	AURAL WARNING CONTROL UNIT(MOD STATUS A) 6608108-2 1775 REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	R:38 R:0 R:0			13-NOV-2014 5062 3805		
315102	TONE GENERATOR 6608445-3 SN-UNKNOWN REF: AMM 31-51-02	MOS HRS/MSC AFL	O/C						
315103	AURAL WARNING MIXER 1882-1 573 REF: AMM 31-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
315201	GLARESHIELD ANNUNCIATOR PANEL 6608482-1 0118025 REF: AMM 31-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3160001 EMP (s)	PERFORM ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) FUNCTIONAL TEST PKG 41	MOS					PKG	31-OCT-2019	
N/A BY A/C SERIAL NUMBER	REF: AMM 31-60-03	HRS/MSC AFL	N/A				6654.5 5490		
316001	PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY (MOD 1,2,7,8,11,12,15,16,18,22,27,33) 622-9345-026 1078 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			28-OCT-2016 5670.3 4516		
316002	COPILOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-026 2846 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-NOV-2016 5696.9 4542		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316004	MULTIFUNCTION DISPLAY 622-9434-026 F5PC REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
316010	NO. 1 MULTIFUNCTION, PILOTS DISPLAY 622-9434-024 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
316011	NO. 1 DISPLAY IMT-871 TRAY 822-0278-001 FDJM REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
316011	NO. 2 MULTIFUNCTION, PILOTS DISPLAY 622-9434-026 F9HR REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
316012	NO. 2 DISPLAY IMT-871 TRAY 822-0278-001 D7HK REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
316013	NO. 3 DISPLAY IMT-871 TRAY 822-0278-001 FGLC REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
316014	NO. 4 DISPLAY IMT-871 TRAY 822-0278-001 FDJN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
316101	SENSOR DISPLAY UNIT 622-9735-002 H7PL REF: AMM 31-61-01	MOS HRS/MSC AFL	O/C				23-MAR-2007 2673.1 1523		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316102	SDD-640A SENSOR DISPLAY DRIVER UNIT (MOD 1,2) 622-9347-001 F9VR REF: AMM 31-61-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
CHAPTER 32 LANDING GEAR									
05-11-00-E3211084R (s)	REPLACE RIGHT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)	MOS HRS/MSC AFL					27-JUN-2001 0 0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	20000						
321003 EMP	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
TEFLON	REF: GENERIC NO REF	AFL							
321001	* LEFT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*) 6041100-035 021	MOS HRS/MSC AFL		N:0 N:0 N:0			27-JUN-2001 0 0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500						16500
321002	* RIGHT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*) 6041100-042 021	MOS HRS/MSC AFL		N:0 N:0 N:0			27-JUN-2001 0 0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500						16500
321003	* LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*) 2341131-001 N/A	MOS HRS/MSC AFL	6000	N:0 N:0 N:0			20-OCT-2016 5658.5 4503		10503
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000						
321004	* RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*) 2341131-001 N/A	MOS HRS/MSC AFL	6000	N:0 N:0 N:0			20-OCT-2016 5658.5 4503		10503
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321005	* LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
321006	* RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
3211020 EMP (s)	INSPECT INTERIOR AND EXTERIOR OF MAIN LANDING GEAR AXLE FOR WEAR AND CORROSION						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001		
		HRS/MSC	2400	+25/-25			0		
	REF: AMM 32-11-00	AFL					0		
3211021 EMP	LEFT * MAIN GEAR ACTUATOR. (2327100, 6027100, AND 6600264) (HARD SURFACE RUNWAY LANDING ONLY) (AWL*)								
	PN	MOS		N:0			17-AUG-2013		
	SN-UNKNOWN	HRS/MSC		N:0			4641		
LIFE LIMIT	REF: AMM 32-31-01	AFL	20000	N:0			3337	23337	
3211021 EMP	RIGHT * MAIN GEAR ACTUATOR. (2327100, 6027100, AND 6600264) (HARD SURFACE RUNWAY LANDING ONLY) (AWL*)								
	PN	MOS		N:0			24-NOV-2008		
	SN-UNKNOWN	HRS/MSC		N:0			3172.1		
LIFE LIMIT	REF: AMM 32-31-01	AFL	20000	N:0			1959	21959	
3211030 EMP (s)	REMOVE AND REPLACE RETAINER RING LOCKSCREW FROM NOSE LANDING GEAR STRUT (P/N AN500A6-10)						PKG		
	PKG 41	MOS	36	+14d/-14d			31-OCT-2019		
		HRS/MSC	600	+25/-25			6654.5		
LIFE LIMIT	REF: AMM 32-21-00	AFL					5490		
3211040 EMP (s)	CLEAN AND EDDY CURRENT INSPECT UPPER CYLINDER						PKG		
	PKG 51	MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: NDT 32-40-02	AFL	6000	+25/-25			0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3211050 EMP (s)	DEFLATE STRUTS AND STROKE FROM FULLY EXTENDED TO FULLY COMPRESSED POSITIONS. NOTE BINDING TENDENCIES DURING STROKING, PARTICULARLY NEAR THE FULLY COMPRESSED POSITION						PKG		
	PKG 51	MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		
3211058 EMP (s)	DISASSEMBLE COMPLETELY MAIN LANDING GEAR STRUTS AND ACTUATORS. REMOVE AXLES AND PISTONS FROM HUBS. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. CONDUCT FLUORESCENT PENETRANT OR MAGNETIC PARTICLE INSPECTION OF ALL COMPONENTS. PAY PARTICULAR ATTENTION TO THE MAIN GEAR UPPER TRUNNION AREAS AND LOWER GLAND NUT OF THE CYLINDER FORGING FOR CRACKS						PKG		
	PKG 51	MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: NDT 32-13-01	AFL	6000	+25/-25			0		
3211060 EMP (s)	DISASSEMBLE COMPLETELY NOSE LANDING GEAR STRUT AND ACTUATOR. REMOVE AXLES AND PISTONS FROM HUBS. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. CONDUCT FLUORESCENT PENETRANT OR MAGNETIC PARTICLE INSPECTION OF ALL COMPONENTS						PKG		
	PKG 51	MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: See Workcard	AFL	6000	+25/-25			0		
3211061 EMP (s)	VISUAL INSPECT NOSE GEAR TRUNNION AXLE AND INSTALLATION AREA OF TRUNNION FOR CRACKS, CORROSION, AND DAMAGE. (REFER TO 5-10-00). IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION IS NOT FOUND, CONDUCT FLUORESCENT PENETRANT INSPECTION OF AXLE PORTION THAT IS EXPOSED FROM CYLINDER. (REFER TO NDI MANUAL [NDI-2], PARTS 5 AND 6, CHAPTER 32)						PKG		
	PKG 51	MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		
3211066 EMP	REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-32-01	AFL	6000	+25/-25			0	6000	6025
3211073 EMP	REPLACE * NOSE GEAR STRUT AND ACTUATOR (2342100 AND 2317100) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-21-00	AFL	10000				0	10000	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3211074 EMP	LEFT * MAIN GEAR UPPER BEARING (6041104) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
EMP LJ	REF: AMM 32-11-00	AFL		N:0			0		
3211074 EMP (s)	REPLACE * MAIN GEAR UPPER BEARING (6041104) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC	N/A				0		
NOT APPLICABLE	REF: AMM 32-11-00	AFL					0		
3211074 EMP	RIGHT * MAIN GEAR UPPER BEARING (6041104) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
EMP LJ	REF: AMM 32-11-00	AFL		N:0			0		
3211079 EMP	LEFT * MAIN GEAR ASSEMBLY (6041100) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500	N:0			0		16500
3211079 EMP	REPLACE * MAIN GEAR ASSEMBLY (6041100) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500				0		16500
3211079 EMP	RIGHT * MAIN GEAR ASSEMBLY (6041100) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500	N:0			0		16500
3211084 EMP	LEFT * MAIN GEAR ACTUATOR ATTACH PIN (5441101) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	20000	N:0			0		20000
3211084 EMP	REPLACE * MAIN GEAR ACTUATOR ATTACH PIN (5441101) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	20000				0		20000

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3211084 EMP	RIGHT * MAIN GEAR ACTUATOR ATTACH PIN (5441101) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	20000	N:0			0		20000
3211091-001 EMP	REPLACE * LEFT MAIN GEAR UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0		6000
3211091-002 EMP	REPLACE * RIGHT MAIN GEAR UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0		6000
3211092-001 EMP	REPLACE * LEFT MAIN GEAR UPPER BEARING (7600839) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0		6000
3211092-002 EMP	REPLACE * RIGHT MAIN GEAR UPPER BEARING (7600839) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0		6000
3211093-001 EMP (s)	REPLACE * LEFT MAIN GEAR LOWER BEARING (6041105) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0		
3211093-002 EMP	REPLACE * RIGHT MAIN GEAR LOWER BEARING (6041105) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0		6000
3211098 EMP	LEFT * MAIN GEAR ACTUATOR PILLAR ASSEMBLY (2341123-15, -17, AND -23) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-05	AFL	20000	N:0			0		20000

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3211098 EMP	REPLACE * MAIN GEAR ACTUATOR PILLAR ASSEMBLY (2341123-15, -17, AND -23) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-31-05	AFL	20000				0		20000
3211098 EMP	RIGHT * MAIN GEAR ACTUATOR PILLAR ASSEMBLY (2341123-15, -17, AND -23) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-05	AFL	20000	N:0			0		20000
3211100-001 EMP	REPLACE * LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)								
	2341131-001	MOS					20-OCT-2016		
	N/A	HRS/MSC					5658.5		
LIFE LIMIT	REF: AMM 32-11-01	AFL	6000				4503		10503
3211100-002 EMP	REPLACE * RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)								
	2341131-001	MOS					20-OCT-2016		
	N/A	HRS/MSC					5658.5		
LIFE LIMIT	REF: AMM 32-11-01	AFL	6000				4503		10503
3211100-003 EMP	REPLACE * LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-01	AFL	6000				0		6000
3211100-004 EMP	REPLACE * RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)								
	PN	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-01	AFL	6000				0		6000
3211101 EMP	LEFT * MAIN LANDING GEAR ASSEMBLY (2394105) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500	N:0			0		16500
3211101 EMP	REPLACE * MAIN LANDING GEAR ASSEMBLY (2394105) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500				0		16500

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3211101 EMP	RIGHT * MAIN LANDING GEAR ASSEMBLY (2394105) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	16500	N:0			0		16500
321501	LEFT HYDRAULIC, GEAR RETRACTION RESTRICTOR								
	1R3665-035	MOS		N:0			27-JUN-2001		
	D6833	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-31-04	AFL		N:0			0		
321502	RIGHT HYDRAULIC, GEAR RETRACTION RESTRICTOR								
	1R3665-035	MOS		N:0			27-JUN-2001		
	D6864	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-31-04	AFL		N:0			0		
321511	LEFT HYDRAULIC, GEAR EXTENSION RESTRICTOR								
	1R3665-051	MOS		N:0			27-JUN-2001		
	D3605	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-31-04	AFL		N:0			0		
321512	RIGHT HYDRAULIC, GEAR EXTENSION RESTRICTOR								
	1R3665-051	MOS		N:0			27-JUN-2001		
	D3616	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-31-04	AFL		N:0			0		
321515	LEFT HYDRAULIC RESTRICTOR								
	1R3665-035	MOS		N:0			27-JUN-2001		
	D6970	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
321516	RIGHT HYDRAULIC RESTRICTOR								
	1R3665-059	MOS		N:0			27-JUN-2001		
	D2135	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
322001	* NOSE GEAR STRUT ASSEMBLY (AWL*)								
	2342100-030	MOS		N:0			27-JUN-2001		
	020	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-21-00	AFL	10000	N:0			0		10000

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322002	NOSE LANDING GEAR & STEERING ASSEMBLY STRUT 2342003-090 020 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3221010 EMP (s)	INSPECT INTERIOR AND EXTERIOR OF NOSE LANDING GEAR AXLE FOR WEAR AND CORROSION PKG 43 REF: AMM 32-21-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0		
3230010 EMP (s)	PERFORM LANDING GEAR RETRACTION AND EXTENSION CHECK. CHECK AUTOMATIC BRAKE SNUBBING AND LANDING LIGHTS FOR RETRACT CUTOFF PKG 42 REF: AMM 32-30-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		
323019	LEFT MAIN LANDING GEAR SQUAT SWITCH 426EN9-8 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C						
323020	RIGHT MAIN LANDING GEAR SQUAT SWITCH 426EN12-8 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C						
323031	* LEFT MAIN LANDING GEAR ACTUATOR (AWL*) 6600264-008 1489 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			17-AUG-2013 4641 3337		23337
323032	* RIGHT MAIN LANDING GEAR ACTUATOR (AWL*) 6600264-007 126 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	N:0 N:3277			10-MAR-2020 6770 5610		22333
323036	LEFT MAIN LANDING GEAR ACTUATOR ATTACH PIN 5441101-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323037	RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PIN 5441101-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
323043	LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 6600085-009 0541 REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			08-MAY-2007 2702.6 1551		
323044	RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 6600085-009 0879 REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	O:29 O:0 O:0			31-OCT-2019 6654.5 5490		
323055	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 5465 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:58 R:0 N:2554.1 R:0 N:1427 R:0			05-OCT-2006 2572.1 1441		
323056	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 5348 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			05-OCT-2006 2572.1 1441		
323057	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR 2417016-1 5348 REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
323058	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR 2417016-1 5341 REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
323073	* NOSE LANDING GEAR ACTUATOR (AWL*) 2317100-016 KL0001 REF: AMM 32-32-01	MOS HRS/MSC AFL		N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441	10000	
LIFE LIMIT			10000						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323079	NOSE LANDING GEAR UPLOCK ACTUATOR 2417016-1 5369 REF: AMM 32-32-02	MOS HRS/MSC AFL	O/C	N:144 O:85 N:4582.6 O:2221.4 N:3269 O:1939			27-JUN-2013 4582.6 3269		
323080	UPLOCK, NOSE LANDING GEAR FREEFALL ACTUATOR 2417016-1 5359 REF: AMM 32-33-05	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
323098	GEAR DOOR CONTROL VALVE 6600361-1 1285 REF: AMM 32-30-08	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
323099	SELECT, LANDING GEAR VALVE 48C48641 1572 REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
3231030 EMP (s)	INSPECT INBOARD ATTACHMENT OF MAIN GEAR ACTUATOR FOR SECURITY, LOOSENESS, OVERLOAD INDICATIONS, AND FATIGUE CRACKS. THE PILLAR ATTACHMENTS TO SPARS 7 AND 8 ARE TO BE SPECIFICALLY INSPECTED FOR DISCREPANT CONDITIONS. PILLAR REMOVAL IS REQUIRED TO FACILITATE DEFINITIVE INSPECTION. MAGNETIC PARTICLE INSPECT PILLAR PKG 51 REF: GENERIC NO REF	MOS HRS/MSC AFL	6000	+25/-25			PKG 27-JUN-2001 0 0		
323105	NOSE LANDING GEAR SHUTTLE VALVE 2SV0413 D17002 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
323110	NOSE LANDING GEAR UPLATCH SHUTTLE VALVE 2SV0413 SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3232003 EMP (s)	PERFORM DETAILED CHECK ON NOSE LANDING GEAR FREE FALL UPLATCH ACTUATOR PKG 42	MOS	72	+14d/-14d			PKG	31-OCT-2019	
	REF: AMM 32-33-05	HRS/MSC AFL	1200	+25/-25			6654.5 5490		
323205	LEFT MAIN LANDING GEAR EXTEND SHUTTLE VALVE 92465	MOS					27-JUN-2001		
	4180	HRS/MSC	O/C				0		
	REF: AMM 32-00-01	AFL					0		
323210	RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE 92465	MOS					27-JUN-2001		
	4247	HRS/MSC	O/C				0		
	REF: AMM 32-00-01	AFL					0		
323222	* LEFT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*) 2341123-023	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-05	AFL	20000	N:0			0		20000
323223	* RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*) 2341123-023	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF: AMM 32-31-05	AFL	20000	N:0			0		20000
3233007 EMP (s)	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS	MOS					27-JUN-2001		
	REF: GENERIC NO REF	HRS/MSC	O/C				0		
TEFLON		AFL					0		
3233010 EMP (s)	PERFORM FUNCTIONAL TEST OF LANDING GEAR EMERGENCY BLOWDOWN EXTENSION SYSTEM PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	
	REF: AMM 32-33-00	HRS/MSC					0		
		AFL	6000	+25/-25			0		
3233011 EMP (s)	PERFORM FUNCTIONAL TEST OF LANDING GEAR EMERGENCY FREEFALL SYSTEM PKG 53	MOS	144	+14d/-14d			PKG	27-JUN-2001	
	REF: AMM 32-33-00	HRS/MSC					0		
		AFL	6000	+25/-25			0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3233012 EMP (s)	PERFORM EMERGENCY AIR EXTENSION SYSTEM AND EMERGENCY BRAKE SYSTEM PLUMBING LEAKAGE CHECK PKG 42 REF: See Workcard	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
3233020 EMP (s)	PERFORM FUNCTIONAL TEST OF EMERGENCY BRAKE SYSTEM PKG 53 REF: AMM 32-43-00	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
323305	LEFT MAIN LANDING GEAR DOOR SHUTTLE VALVE 2SV0413 D17115 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
323310	RIGHT MAIN LANDING GEAR DOOR SHUTTLE VALVE 95930 1244 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			06-JAN-2012 4109.2 2746		
323315	LEFT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE 95930 1001 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
323320	RIGHT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE 95930 1003 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
323401	AFT EMERGENCY GEAR BLOWDOWN EXTENSION VALVE 6600078-6 2192 REF: AMM 32-33-02	MOS HRS/MSC AFL	O/C	N:4212 N:2856			30-APR-2012 4212 2856		
323402	FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE 6600078-6 810 REF: AMM 32-33-03	MOS HRS/MSC AFL	O/C				24-FEB-2017 5768.6 4621		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323405	LEFT CHECK, FREEFALL VALVE 7600833-001 0196 REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
323406	RIGHT CHECK, FREEFALL VALVE 7600833-001 SN-UNKNOWN REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C						
323409	UPPER EMERGENCY GEAR EXTENSION RESTRICTOR 6R7742S-0135 4619 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
323410	LOWER EMERGENCY GEAR EXTENSION RESTRICTOR 6R7742S-0135 4559 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
323430	NO. 1 EMERGENCY AIR BLOWDOWN SHUTTLE VALVE 92465 3876 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
324001	NOSE TIRE 184F10-2 81142712 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				24-FEB-2020 6752 5593		
324007	ASSEMBLY, NOSE WHEEL 9544207-4 OCT08-10723 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				24-FEB-2020 6752 5593		
324013	NO. 1 MAIN LANDING GEAR TIRE 178K43-1 82792725 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-FEB-2020 6752 5593		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324014	NO. 2 MAIN LANDING GEAR TIRE 178K43-1 80652803 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JAN-2020 6722.6 5565		
324015	NO. 3 MAIN LANDING GEAR TIRE 178K43-1 80752745 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-FEB-2020 6747 5590		
324016	NO. 4 MAIN LANDING GEAR TIRE 178K43-1 82992658 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-FEB-2020 6747 5590		
324037	NO. 1 MAIN LANDING GEAR WHEEL 5011740 SEP96-637/MAR07-2441 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			24-FEB-2020 6752 5593		
324038	NO. 2 MAIN LANDING GEAR WHEEL 5011740 NOV07-2706/NOV06-2387 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			20-JAN-2020 6722.6 5565		
324039	NO. 3 MAIN LANDING GEAR WHEEL 5011740 JAN99-1044 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-FEB-2020 6747 5590		
324040	NO. 4 MAIN LANDING GEAR WHEEL 5011740 OCT02-1866/FEB02-67 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-FEB-2020 6747 5590		
324045 (s)	PERFORM BRAKE WEAR CHECK PKG 35 REF:	DAYS HRS/MSC AFL	30				PKG 30-MAR-2020 6774.5 5614		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324048	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 MAR11-1400 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-APR-2019 6431.9 5305		
324049	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 MAR11-1406 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-APR-2019 6431.9 5305		
324050	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 NOV03-0053 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-APR-2019 6431.9 5305		
324051	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 MAY09-1182 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-APR-2019 6431.9 5305		
324061	NO. 1 POWER BRAKE, PILOTS VALVE 3321200-2 1647 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324062	NO. 2 POWER BRAKE, PILOTS VALVE 3321200-2 1646 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324063	NO. 1 POWER BRAKE, COPILOTS VALVE 3321200-2 1639 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324064	NO. 2 POWER BRAKE, COPILOTS VALVE 3321200-2 1648 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324085	NO. 1 HYDRAULIC, BRAKE FUSE 2380114-1 6744 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324086	NO. 2 HYDRAULIC, BRAKE FUSE 2380114-1 6735 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324109	NO. 3 HYDRAULIC, BRAKE FUSE 2380114-1 6766 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324110	NO. 4 HYDRAULIC, BRAKE FUSE 2380114-1 6739 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324133	AFT PARKING BRAKE VALVE 6600392-2 1000 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324134	FWD PARKING BRAKE VALVE 6600392-2 1016 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324145	NO. 1 WHEEL SPEED TRANSDUCER 40-911 7193 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
324146	NO. 2 WHEEL SPEED TRANSDUCER 40-911 7192 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324147	NO. 3 WHEEL SPEED TRANSDUCER 40-911 7185 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
324148	NO. 4 WHEEL SPEED TRANSDUCER 40-911 7197 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
324169	LEFT ANTI-SKID VALVE 39-309-2 2425 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324170	RIGHT ANTI-SKID VALVE 39-309-2 2424 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	N:64 R:0 N:2572.1 R:0 N:1441 R:0			05-OCT-2006 2572.1 1441		
324175	ANTI-SKID CONTROL 42-379-1 1792B REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3242001 EMP (s)	PERFORM OPERATIONAL CHECK ON THE ANTI-SKID VALVES PKG 41 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
3243023 EMP (s)	CHECK POWER BRAKE VALVES FOR SECURITY, OPERATION, AND LEAKS. ENSURE POWER BRAKE VALVE LEVER CONTACTS MECHANICAL STOP PKG 43 REF: AMM 32-41-02	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
3243024 EMP (s)	PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE ON THE POWER BRAKE VALVE PKG 41 REF: GENERIC NO REF	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3243030 EMP (s)	PERFORM FUNCTIONAL TEST OF HYDRAULIC BRAKE FUSES PKG 43 REF: AMM 32-41-03	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
3243040 EMP (s)	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN THE WHEEL WELL AREA REF: GENERIC NO REF	MOS HRS/MSC AFL	60 2400	+14d/-14d +25/-25			27-JUN-2001 0 0		
3243050 EMP (s)	PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE ON THE POWER BRAKE VALVE PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
3244020 EMP (s)	REMOVE/CLEAN ANTI-SKID VALVE FILTERS PKG 41 REF: AMM 32-42-01	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
324501	EMERGENCY BRAKE CONTROL VALVE 63500-2 278A REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C		O:0 O:0 O:0		25-JUN-2010 3733.1 2443		
324505	LEFT MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C						
324510	RIGHT MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0614 4299 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
324601	NO. 1 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D17146 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324602	NO. 2 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D17163 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
324603	NO. 3 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D17154 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
324604	NO. 4 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D17133 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
325001	NOSE WHEEL STEERING ACTUATOR 6608468-8 1276 REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
325005	NOSE WHEEL STEERING COMPUTER 6608468-011 1301 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
325015	LEFT RUDDER POSITION SENSOR 501-1123-03 6560 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
325016	RIGHT RUDDER POSITION SENSOR 501-1123-03 6551 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
325019	NOSE WHEEL STEERING ACTUATOR GEARBOX 3142020-3 238 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325020	NOSE WHEEL STEERING FOLLOW UP ASSEMBLY 2618274-10 245 REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
325024	RIGHT NOSE WHEEL STEERING FOLLOWUP 6608288-1 1756 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
325025	LEFT NOSE WHEEL STEERING FOLLOWUP 6608288-1 1741 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
325628	AFT EMERGENCY GEAR CONTROL VALVE 6600078-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
326011	SQUAT SWITCH RELAY BOX 6018325-008 SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C						
CHAPTER 33 LIGHTS									
331004 EMP (s)	CHECK OPERATION OF INTERIOR LIGHTING SYSTEMS: A. FLIGHT COMPARTMENT LIGHTING. (1) MAP LIGHTS. (2) GLARESHIELD FLOODLIGHTS. (3) INSTRUMENT/INDICATOR LIGHTS. (4) PANEL LIGHTS. (5) LIGHT DIMMING CONTROL PANELS. (6) GLARESHIELD WARNING LIGHTS AND AUTOMATIC DIMMING BY PHOTO CELL. (7) ELECTROLUMINESCENT PANEL LIGHTS. B. PASSENGER COMPARTMENT LIGHTING. (1) AISLE LIGHTS. (2) CABIN FLOODLIGHTS. (3) CONVENIENCE LIGHTS. (4) LAVATORY LIGHTS. (5) WARNING LIGHTS PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			31-OCT-2019 6654.5 5490		
331003	FLOOD LIGHTS POWER SUPPLY INVERTER 6900115 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331201	LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY 6900115 SN-UNKNOWN REF: AMM 33-12-02	MOS HRS/MSC AFL	O/C						
331202	RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY 6900115 SN-UNKNOWN REF: AMM 33-12-02	MOS HRS/MSC AFL	O/C						
331303	QUAD EL (ELECTROLUMINESCENT) POWER SUPPLY SDA 16 367 REF: AMM 33-13-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
331401	PILOT DIMMING CONTROL BOX LT-48G 1301 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
331402	COPILOT DIMMING CONTROL BOX LT-48G 1344 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
331403	CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX LT-48G 2719-2721 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-MAR-2014 4873.2 3592		
331404	PEDESTAL DIMMING CONTROL BOX LT-48E 2792 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
331405	FUEL QUANTITY INDICATOR DIMMING CONTROL BOX LT-48E 2800 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331505	NO. 1 CONTROL, CABIN LIGHTING MODULE MS1850 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
331506	NO. 2 CONTROL, CABIN LIGHTING MODULE MS1850 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
331601	LEFT ACS DIMMER CONTROL BOX LT-48G 1351 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
331602	RIGHT ACS DIMMER CONTROL BOX LT-48G 1345 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
331701	LEFT AFT LIGHT DIMMING (E215) CONTROL BOX 2618262-9 SN-UNKNOWN REF: AMM 33-17-01	MOS HRS/MSC AFL	O/C						
331801	LEFT FORWARD LIGHT DIMMING (AE9) CONTROL BOX 2618262-9 SN-UNKNOWN REF: AMM 33-18-01	MOS HRS/MSC AFL	O/C						
332001	OVERHEAD INDIRECT LIGHTING (PS2) INVERTER 6608477-1 4805 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
332002	OVERHEAD INDIRECT LIGHTING (2PS2) INVERTER 6900115-000 6750 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C				18-OCT-2007 2773.7 1622		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332003	OVERHEAD INDIRECT LIGHTING (3PS2) INVERTER 6900115-000 6481 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-SEP-2009 3480.4 2226		
332004	OVERHEAD INDIRECT LIGHTING (4PS2) INVERTER 6900115-000 6864 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C				30-OCT-2012 4398.1 3055		
332005	OVERHEAD INDIRECT LIGHTING (5PS2) INVERTER 6608477-1 4804 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
332006	OVERHEAD INDIRECT LIGHTING (6PS2) INVERTER 6608477-1 6865 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:9 N:0 N:0			05-JUL-2012 4267.5 2915		
332007	OVERHEAD INDIRECT LIGHTING (7PS2) INVERTER 6900115-000 6864 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-OCT-2012 4398.1 3055		
332009	INDIRECT LIGHTING CONTROL MS1836 SN-UNKNOWN REF: AMM 33-20-09	MOS HRS/MSC AFL	O/C						
332010	ALTERNATE/MOMENTARY SWITCHING MODULE MS1881 SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C						
332014	ZONE BACK LIGHTING CONTROL MS1839 SN-UNKNOWN REF: AMM 33-20-14	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332028	NO. 8 POWER, LIGHTING INVERTER SUPPLY 6608477-1 4789 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
332030	LIGHTING POWER SUPPLY 6900115-000 6984 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-MAY-2017 5844.7 4706		
332036	LAVATORY LIGHTING INVERTER 6608477-1 4791 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
332038	LAVATORY LIGHTING INVERTER 6608477-1 4737 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
334301	UPPER STROBE/BEACON LIGHT GE16386-9-2 AF0354 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-DEC-2005 2144.4 1197		
334302	LOWER STROBE/BEACON LIGHT GE 16386-9-1 1618746 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0			30-JAN-2019 6399.4 5267		
334401	WING ICE INSPECTION LIGHT GLJ-140 12370 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
334502	RECOGNITION LIGHT PULSE CONTROL UNIT 2401S AR00284 REF: AMM 33-45-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335001	EMERGENCY EXIT LIGHTING PANEL M6088221-012 MAN045664-01A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-DEC-2005 2144.4 1197		
335505	PILOT FLASHLIGHT P2-07-0024-001 N/A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-SEP-2018 6312.6 5174		
335505A	REPLACE PILOT FLASHLIGHT BATTERY P2-07-0025-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	60	N:0 N:0 N:0			11-FEB-2019 6405.8 5273	11-FEB-2024	
335506	COPILOT FLASHLIGHT P2-07-0022-001 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-FEB-2014 4838 3560		
335506A	REPLACE CO-PILOT FLASHLIGHT BATTERY P2-07-0025-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	60	N:0 N:0 N:0			11-FEB-2019 6405.8 5273	11-FEB-2024	
335508	CREW AIR LIFE 2R LED FLASHLIGHT SYSTEM UNKNOWN SN-UNKNOWN REF:	MOS HRS/MSC AFL	A/R				20-FEB-2014		
335508A	INSPECT THE AIR LITE 2R FLASHLIGHT SYSTEM PER CHECKLIST - SEE ATTACHMENT UNKNOWN SN-UNKNOWN REF:	DAYS HRS/MSC AFL	30				30-MAR-2020 6774.5 5614	29-APR-2020	
335508B	INSPECT AIR LITE 2R FLASHLIGHT SYTEM PER CHECKLIST UNKNOWN SN-UNKNOWN REF:	MOS HRS/MSC AFL	3				02-MAR-2020 6759.4 5604	02-JUN-2020	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 34	NAVIGATION								
05-10-30-RVSM-W3411015 (s)	PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00)	MOS HRS/MSC AFL	12	+14d/-14d			20-OCT-2016 5658.5 4503		
	REF: AMM 34-17-00								
256001AA	FAR 91.207D CHECK	MOS HRS/MSC AFL	12				07-NOV-2019 6655 5491	07-NOV-2020	
	REF:								
34-00-FAR-91.171	CHECK VOR FAR 91.171	MOS HRS/MSC AFL	1				31-MAR-2020 6774.5 5614	30-APR-2020	
	REF: FAR FAR 91.171								
34-00-FAR-91.217	PERFORM ALTITUDE DATA TRANSMISSION TEST	MOS HRS/MSC AFL	A/R				10-JAN-2006 2144.4		
	REF: FAR FAR 91.217								
34-00-FAR-91.411	RECERTIFY PITOT-STATIC SYSTEM	MOS HRS/MSC AFL	24				19-OCT-2018 6341.2 5193	19-OCT-2020	
	REF: FAR FAR 91.411								
340000	PERFORM KONFARA COMPANY AVIONICS CHECK SHEET	MOS HRS/MSC AFL	12				31-OCT-2019 6654.5 5490	31-OCT-2020	
CUSTOMER CODE	REF:								
340005	VERIFY AIRCRAFT GEOMETRIC HEIGHT MEASUREMENT ELEMENT (AGHME) MONITORING FLIGHT	MOS HRS/MSC AFL	24				11-JAN-2019 6460.3 5336	11-JAN-2021	
CUSTOMER CODE	REF:								

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340010	PERFORM NAVIGATION DATABASE UPDATE	DAYS					19-MAR-2020	23-APR-2020 M	
CUSTOMER CODE	REF:	HRS/MSC AFL	DUE				6774.5 5614		
341020	LEFT PITOT/STATIC PROBE	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 34-11-02	HRS/MSC AFL	15000	+25/-25	N:0		0	15000	15025
341020A	VERIFY LEFT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016	MOS	24	+14d/-14d			19-OCT-2018	19-OCT-2020	02-NOV-2020
		HRS/MSC AFL					6341.2 5193		
341020B	DETAILED VISUAL INSPECTION LEFT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064	MOS	24	+14d/-14d			19-OCT-2018	19-OCT-2020	02-NOV-2020
		HRS/MSC AFL					6341.2 5193		
341025	RIGHT PITOT/STATIC PROBE	MOS					27-JUN-2001		
LIFE LIMIT	REF: AMM 34-11-02	HRS/MSC AFL	15000	+25/-25	N:0		0	15000	15025
341025A	VERIFY RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016	MOS	24	+14d/-14d			19-OCT-2018	19-OCT-2020	02-NOV-2020
		HRS/MSC AFL					6341.2 5193		
341025B	DETAILED VISUAL INSPECTION RIGHT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064	MOS	24	+14d/-14d			19-OCT-2018	19-OCT-2020	02-NOV-2020
		HRS/MSC AFL					6341.2 5193		
341026	PITOT/STATIC PROBE	MOS					27-JUN-2001		
		HRS/MSC AFL	O/C		N:0		0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341049	RADIO (ALT-4000) ALTIMETER 822-0615-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
3411010 EMP (s)	CHECK PITOT TUBES, STATIC AND PITOT LINES, DRAIN LINES, AND WIRING FOR CONDITION AND SECURITY. CHECK STATIC PORTS AND PITOT/STATIC PROBES FOR DISTORTION. CHECK OPERATION OF DRAIN VALVES PKG 42 REF: AMM 34-11-02	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		
3411012 EMP (s)	CHECK AIR TEMPERATURE SENSOR OR AIR DATA COMPUTER STATIC, PITOT, AND DRAIN LINES FOR CONDITION AND SECURITY. CHECK OPERATION OF DRAIN VALVES PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		
3411014 EMP (s)	PERFORM PITOT-STATIC PROBE DRAIN HOLE CHECK PKG 41 REF: AMM 34-11-02	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		
3411015 EMP	PERFORM CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM, RVSM CONTINUED AIRWORTHINESS PKG 47 REF: AMM 34-17-00	MOS HRS/MSC AFL	12	+14d/-14d		-1	16-OCT-2019 15-OCT-2020	29-OCT-2020	
3411016 EMP (s)	LEFT PRIMARY PITOT-STATIC PROBES - VERIFY PITCH AND YAW ALIGNMENT PKG 47 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d			19-OCT-2018 6341.2 5193		
3411016 EMP (s)	RIGHT PRIMARY PITOT-STATIC PROBES - VERIFY PITCH AND YAW ALIGNMENT. PKG 47 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d			19-OCT-2018 6341.2 5193		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3411016 EMP (s)	VERIFY PITCH AND YAW ALIGNMENT PKG 47 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d			19-OCT-2018		
3411017 EMP	REPLACE LEFT PITOT/STATIC PROBE LEFT PRIMARY PITOT/STATIC PROBE (856KR7) 856KR7 205310 REF: AMM 34-11-02	MOS HRS/MSC AFL	15000	+25/-25			27-JUN-2001 0 0	15000	15025
LIFE LIMIT									
3411018 EMP	REPLACE RIGHT PITOT/STATIC PROBE RIGHT PRIMARY PITOT/STATIC PROBE (856KR8) 856KR8 206022 REF: AMM 34-11-02	MOS HRS/MSC AFL	15000	+25/-25			27-JUN-2001 0 0	15000	15025
LIFE LIMIT									
3411025 EMP	PERFORM FUNCTIONAL TEST OF THE AIR DATA SYSTEM REF: AMM 34-17-00	MOS HRS/MSC AFL	24	+14d/-14d			19-OCT-2018 6341.2 5193	19-OCT-2020	02-NOV-2020
3411031 EMP (s)	PERFORM FUNCTIONAL TEST OF STATIC SHUTOFF (ISOLATION) VALVES PKG 42 REF: AMM 34-11-00	MOS HRS/MSC AFL	72	+14d/-14d			31-OCT-2019 6654.5 5490		
341105	PILOT RIGHT STATIC SHUTOFF VALVE 6600473-1 SN-UNKNOWN REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C						
341106	COPILOT RIGHT STATIC SHUTOFF VALVE 6600473-2 1846 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		
3411061 EMP (s)	PERFORM FUNCTIONAL TEST ON PITOT/STATIC PROBE HEAT CURRENT SENSING RELAY PKG 41 REF: AMM 30-30-01	MOS HRS/MSC AFL	36	+14d/-14d			31-OCT-2019 6654.5 5490		



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3411064 EMP (s)	LEFT PITOT-STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION PKG 47 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d			PKG 19-OCT-2018 6341.2 5193		
3411064 EMP (s)	PERFORM DETAILED VISUAL INSPECTION OF THE PITOT-STATIC PROBE PKG 47 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d			PKG 16-OCT-2018		
3411064 EMP (s)	RIGHT PITOT-STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION PKG 47 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d			PKG 19-OCT-2018 6341.2 5193		
341107	PILOT LEFT STATIC SHUTOFF VALVE 6600473-1 1779 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341108	COPILOT LEFT STATIC SHUTOFF VALVE 6600473-1 1839 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341111	STANDBY ALTIMETER 8047-700-53 7508B REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C				14-JUL-2017 5932.9 4776		
341111A	RECERTIFY STANDBY ALTIMETER 8047-700-53 7508B REF: See Workcard	MOS HRS/MSC AFL	24				15-OCT-2018	15-OCT-2020	
341133	NO. 1 AIR DATA COMPUTER (MOD 2,3,7,9,11,12,22,23,25,29,36,42,44,49,56,59,62,63,68) 822-0389-429 901 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C				28-OCT-2016 5670.3 4516		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341133A	RECERTIFY NO. 1 LOWER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM 822-0389-429 901 REF: See Workcard	MOS HRS/MSC AFL	24				15-OCT-2018	15-OCT-2020	
341134	NO. 2 AIR DATA COMPUTER (MOD 2,3,7,9,11,12,22,23,25,26,29,30,33,36,42,44,49,50,56,59,60,62,63,68) 822-0389-429 3785 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C	R:0 R:0			04-OCT-2014 5023.8 3760		
341134A	RECERTIFY NO. 2 UPPER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM 822-0389-429 3785 REF: See Workcard	MOS HRS/MSC AFL	24				18-OCT-2018	18-OCT-2020	
341135	NO. 3 (ADC) AIR DATA COMPUTER 501-1797-20 SN-UNKNOWN REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C						
341150	FLIGHT DATA ACQUISITION UNIT 2231230-7 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
341225	STANDBY AIRSPEED INDICATOR 2C131 (02B7C9) 639 REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341401	RADIO ALTIMETER TRANSCEIVER (MOD 1,2,3,4,5,6,7,8,9,10,12) 622-2855-011 2484 REF: AMM 34-14-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-JUL-2015 5260.6 4031		
341402	RADIO ALTIMETER CONVERTER (MOD 1,2,3,4,5) 622-7209-002 D9KW REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C				23-MAR-2007 2673.1 1523		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341403	AFT RADIO ALTIMETER ANTENNA 622-0954-002 F8DK REF: AMM 34-14-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341404	FORWARD RADIO ALTIMETER ANTENNA 622-0954-002 F8DJ REF: AMM 34-14-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341703	FORWARD SIGNAL INTERFACE ADAPTER 622-9732-003 DMTW REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341704	AFT SIGNAL INTERFACE ADAPTER 622-9732-003 F35X REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341705	PILOT AIR DATA REFERENCE PANEL 622-9500-002 FJ4X REF: AMM 34-17-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341706	COPILOT AIR DATA REFERENCE PANEL 622-9500-002 FJ4W REF: AMM 34-17-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341707	TAT SENSOR PROBE 102AU1AG A36836 REF: AMM 34-17-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
341801	STANDBY MACH/AIRSPEED INDICATOR 39310-J2057 SN-UNKNOWN REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342001	MAGNETIC COMPASS MAGNETOMETER 501-1826-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
342025	AHRS COOLING FAN 011035 101125679 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
342055	NO. 1 FLUX DETECTOR UNIT 622-5812-001 101882 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-SEP-2019 6629.4 5466		
342056	NO. 2 FLUX DETECTOR UNIT 622-5812-001 33929 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C				03-MAR-2006 2251.3 1259		
342057	NO. 1 INTERNAL COMPENSATOR (ICU-85) UNIT (MOD 1,2) 622-6189-002 2472T REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-FEB-2006 2208.2 1235		
342058	NO. 2 INTERNAL COMPENSATOR (ICU-85) UNIT (MOD 1,2) 622-6189-002 DWRV REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C				23-MAR-2007 2673.1 1523		
342301	STANDBY GYRO 501-1197-05 SN-UNKNOWN REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C						
342401	MAGNETIC COMPASS C-2350L4-M23 SN-UNKNOWN REF: AMM 34-24-01	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342410	NO. 1 ATTITUDE/HEADING (AHC-3000) COMPUTER 822-1378-850 33BTK REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			13-JAN-2020 6710.1 5552		
342411	NO. 2 ATTITUDE/HEADING (AHC-3000) COMPUTER 822-1378-850 4RKTK REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C				21-OCT-2016 5658.5 4503		
342412	NO. 1 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000) 822-1200-004 47NMV3 REF: AMM 34-26-06	MOS HRS/MSC AFL	O/C				21-OCT-2016 5658.5 4503		
342413	NO. 2 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000) 822-1200-004 47NMV4 REF: AMM 34-26-06	MOS HRS/MSC AFL	O/C				21-OCT-2016 5658.5 4503		
342501	STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR 501-1567-02 1951 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			13-MAR-2017 5780.9 4630		
342514	NO. 5 POWER, IAPS SUPPLY 622-8365-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
342605	AUXILIARY SWITCHING UNIT 6018141-1 SN-UNKNOWN REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C						
343007	MARKER BEACON (37X-2) ANTENNA 522-0854-069 52841 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344007	NO. 1 GPS 1075-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
344008	NO. 2 GPS 1075-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
344020	NO. 1 OMEGA NAVIGATION SYSTEM SENSOR 100-601200-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
344021	NO. 2 OMEGA NAVIGATION SYSTEM SENSOR 100-601200-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
344063	NO. 1 INPUT/OUTPUT CHANNEL A 851A CARD 622-9343-234 FHFP REF:	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
344064	NO. 2 INPUT/OUTPUT CHANNEL A 851A CARD 622-9343-224 FFXJ REF:	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
344065	NO. 1 INPUT/OUTPUT CHANNEL B 851A CARD 622-9343-234 FFXH REF:	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
344066	NO. 2 INPUT/OUTPUT CHANNEL B 851A CARD 622-9343-234 F9CF REF:	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344111	LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 40N7M2 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2013 4582.6 3269		
344112	UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 8FMU REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
344142	TCAS (TTR-920) PROCESSOR 622-8971-420 SN-UNKNOWN REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C						
344143	TCAS TRANSMITTER (MOD 2,3,4,5,7,8,9,11) 822-1294-032 160751 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
344151	STORMSCOPE PROCESSOR 78-8060-6086-5 JFP11000793 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
344153	STORMSCOPE DISPLAY 78-8060-5900-8 FSD03401594 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-FEB-2020 6727 5571		
344155	STORMSCOPE ANTENNA 78-8051-9200-8 JSA08003812 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
344171	NO. 1 VHF/NAV ANTENNA DMN4-15 SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344176	NO. 2 VHF/NAV ANTENNA DMN4-15 SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C						
344201	EFIS RADAR (ERP) PANEL 6608222-002 SN-UNKNOWN REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C						
344513	TAWS COMPUTER 3010-00-00 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
344515	TAWS CONFIGURATION MODULE 30101 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
344520	TERRAIN AWARENESS ISOLATION BOX M6088265-001 MAN051896-01B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:102 R:0 N:3549.6 R:0 N:2287 R:0			28-DEC-2009 3549.6 2287		
344806	WEATHER RADAR ARTU (MOD 1,2,3,4,5,6,7,8,9,10,11,13,14,15,16,18,19,20,21,22,23,24,26,27,28,29,30,31,33,35,36) 622-8440-004 279ML REF:	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-APR-2019 6442.2 5314		
344807	PILOT EFIS RADAR CONTROL PANEL 1015-1-11 222 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-APR-2019 6442.2 5314		
344808	COPILOT EFIS RADAR CONTROL PANEL 1015-1-11 583 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345001	NO. 1 ADF (ADF-462) RECEIVER (MOD 1,2,3,4,5,6,7,8,9) 622-7382-101 4CJC REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
345002	NO. 2 ADF (ADF-462) RECEIVER (MOD 1,2,3,4,5,6,7,8,9) 622-7382-101 53FU REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
345005	ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER (MOD 1,2,3,4,5,6,7) 965-0976-040-206-206 8111 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
345011	NO. 1 DME (DME-442) RECEIVER (MOD 1,2,3,4,5,6,7,8,9) 622-7309-101 F73H REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
345012	NO. 2 DME (DME-442) RECEIVER (MOD 1,2,3,4,5,6,7,8,9) 622-7309-101 D4NH REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
345013	ADF, DUAL (ANT-462B) ANTENNA 622-7384-001 FC9L REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
345021	NO. 1 VHF (VIR 432) RECEIVER (MOD 1,2,3,4,5,6,7,8,9,12,13) 622-7194-201 DVPK REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
345022	NO. 2 VHF (VIR 432) RECEIVER (MOD 1,2,3,4,5,6,7,8,9,12,13) 622-7194-201 DY6W REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345031	NO. 1 NAVIGATION COMPUTER 1190-01-1110 SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C						
345032	NO. 2 NAVIGATION COMPUTER 1190-01-1110 SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C						
345043	LEFT NAVIGATION (BLADE) ANTENNA DMN4-45 8797 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
345044	RIGHT NAVIGATION (BLADE) ANTENNA DMN4-45 8820 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
345045	NO. 1 VHF/NAV ANTENNA DMN4-15 SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C						
345046	NO. 2 VHF/NAV ANTENNA DMN4-15 SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C						
345048	NO. 1 VLF ANTENNA 418-312-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
345049	NO. 2 VLF ANTENNA 418-312-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345079	PRIMARY ATC TRANSPONDER (MOD 1,2,3,4,5,6,7,8,9,10,11,12,13,14,15,16,18) 622-9210-501 4TD1N REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
345079A	RECERTIFY PRIMARY ATC TRANSPONDER 622-9210-501 4TD1N REF: See Workcard	MOS HRS/MSC AFL	24				18-OCT-2018	18-OCT-2020	
345080	SECONDARY ATC TRANSPONDER (MOD 1,2,3,4,5,6,7,8,9,10,11,12,13,14,15,16,18,22,24) 622-9210-501 4TD1P REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				17-OCT-2016 5658.5 4503		
345080A	RECERTIFY SECONDARY ATC TRANSPONDER 622-9210-501 4TD1P REF: See Workcard	MOS HRS/MSC AFL	24				18-OCT-2018	18-OCT-2020	
345091	NO. 1 TRANSPONDER ANTENNA CI100-2 SN-UNKNOWN REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C						
345092	NO. 2 TRANSPONDER ANTENNA CI100-60-30 503009 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	N:0 N:0			21-OCT-2016 5658.5 4503		
345108	ADF PRIMARY ANTENNA 622-7383-001 SN-UNKNOWN REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C						
3453003 EMP (s)	INSPECT ANTENNA INSTALLATIONS FOR SECURITY, CORROSION, AND PROPER TENSION OF HF ANTENNA WIRE PKG 42 REF: AMM 23-12-03	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346004	DATA BASE - DBU-4000 UNIT 622-9865-002 SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C						
346015	NO. 1 FLIGHT MANAGEMENT SYSTEM CDU 3017-41-221 372 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			23-DEC-2019 6699.8 5538		
346016	NO. 2 FLIGHT MANAGEMENT SYSTEM CDU 3017-41-221 371 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			10-OCT-2018 6333.7 5190		
346017	NO. 3 FLIGHT MANAGEMENT SYSTEM CDU 1016-1-110 SN-UNKNOWN REF: AMM 34-60-00	MOS HRS/MSC AFL	O/C						
346021	PRIMARY FMS DATA TRANSFER (DTU) UNIT 1408-00-1 674 REF: AMM 34-61-04	MOS HRS/MSC AFL	O/C				23-DEC-2009 3548.7 2286		
346025	NO. 1 FMS CONFIGURATION MODULE 30171 390 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-DEC-2009 3548.7 2286		
346026	NO. 2 FMS CONFIGURATION MODULE 30171 407 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-DEC-2009 3548.7 2286		
346031	PILOT ALTITUDE AWARENESS PANEL 822-0328-004 DHDF REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346032	COPILOT ALTITUDE AWARENESS PANEL 822-0328-004 DK5P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
346041	COURSE HEADING PANEL 622-7397-006 CWCP REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
346055	CONFIGURATION, AFIS MODULE 31990-1 11757 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JUN-2007 2733.2 1580		
346071	UNILINK CONFIGURATION MODULE 10651 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
346090	AFIS DATA MANAGEMENT UNIT 400-045500-0003 3937 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JUN-2007 2733.2 1580		
346091	DATA TRANSFER, AFIS UNIT 15655-0101 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
346092	AFIS ANTENNA VF10-347 5403 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JUN-2007 2733.2 1580		
347510	FORWARD GPS ANTENNA 10708 5869 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C				23-DEC-2009 3548.7 2286		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
347511	AFT GPS ANTENNA 10708 5875 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C				23-DEC-2009 3548.7 2286		
34AHSM1	NO.1 AHS MOUNT MMT-3010 822-1290-003 47Y9X9 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-OCT-2016 5658.5 4503		
34AHSM2	NO. 2 AHS MOUNT MMT-3010 822-1290-003 47Y9X8 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-OCT-2016 5658.5 4503		
34CUS1	AHC-3000 VISUAL INSPECTION REF:	MOS HRS/MSC AFL	12				31-OCT-2019 6654.5 5490	31-OCT-2020	
34CUS2	ACH-3000 TEST BONDING CHECK REF:	MOS HRS/MSC AFL	24				19-OCT-2018 6341.2 5193	19-OCT-2020	
CHAPTER 35 OXYGEN									
3500000 EMP (s)	PERFORM FUNCTIONAL TEST OF OXYGEN SYSTEM PKG 42 REF: AMM 35-00-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
3500023 EMP	HYDROSTATIC TEST DORSAL OXYGEN CYLINDER OXYGEN CYLINDER (STEEL, DOT3HT1850) 176194-76 0753-832723 REF: GENERIC NO REF	MOS HRS/MSC AFL	36	+14d/-14d	-5		18-APR-2018	13-APR-2021	27-APR-2021

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350003	NOSE OXYGEN SYSTEM PRESSURE TRANSDUCER 124058-2000 40499 REF: AMM 35-00-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
350004	DORSAL OXYGEN SYSTEM PRESSURE TRANSDUCER 124058-2000 SN-UNKNOWN REF: AMM 35-00-02	MOS HRS/MSC AFL	O/C						
3500040 EMP (s)	CHECK CREWMEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) FOIL POUCH FOR VACUUM SEAL INTEGRITY. IF VACUUM SEAL IS BROKEN, REPLACE EQUIPMENT PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		
3500050 EMP	REPLACE PROTECTIVE BREATHING (PBE) EQUIPMENT 802300-14 E11050917 REF: AMM 25-60-00	MOS HRS/MSC AFL	120	+14d/-14d	I:1		22-JUN-2011 3964.5 2630	27-MAY-2021	10-JUN-2021
3500054 EMP	REPLACE DORSAL OXYGEN CYLINDER OXYGEN CYLINDER (STEEL, DOT3HT1850) 176194-76 0753-832723 REF: AMM 35-00-01	MOS HRS/MSC AFL	288	+14d/-14d	I:105		28-SEP-2012 4346.6 3005	28-DEC-2027	11-JAN-2028
350006	DORSAL OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY 172180-05 0753 REF: AMM 35-00-03	MOS HRS/MSC AFL	O/C				08-FEB-2007 2633.5		
350008	DORSAL OXYGEN PRESSURE INDICATOR 6608401-20 235 REF: AMM 35-00-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
351001	PILOT OXYGEN MASK MC10-15-176 93435 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	O:12 O:0 O:0			08-JUN-2017 5899.4 4754		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351001A (s)	OVERHAUL PILOT OXYGEN MASK MC10-15-176 93435 REF:	MOS HRS/MSC AFL	72	+14d/-14d			08-JUN-2017 5899.4 4754		
351002	COPILOT OXYGEN MASK MC10-15-176 88069 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C				04-OCT-2018 6325.7 5184		
3510020 EMP (s)	PERFORM FUNCTIONAL TEST OF OXYGEN MASK ON AIRCRAFT EQUIPPED WITH E.R.O.S. AVIATION CREW MASKS PKG 43 REF: AMM 35-10-01	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
3510027-001 EMP	OVERHAUL PILOT OXYGEN MASK MC10-15-176 93435 REF: AMM 35-10-01 OVERHAUL	MOS HRS/MSC AFL	72	+14d/-14d			23-JUN-2016	23-JUN-2022	07-JUL-2022
3510027-002 EMP	OVERHAUL COPILOT OXYGEN MASK MC10-15-176 88069 REF: AMM 35-10-01 OVERHAUL	MOS HRS/MSC AFL	72	+14d/-14d			15-DEC-2017	15-DEC-2023	29-DEC-2023
351025	OXYGEN SYSTEM PRESSURE SWITCH P24028 0947 REF: AMM 35-00-07	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		
351071	PILOT CREW OXYGEN MASK BOX 6008802-1 SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C						
351072	COPILOT CREW OXYGEN MASK BOX MXP302 SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352027	PASSENGER OXYGEN CONTROL VALVE P21004-3 0129 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
352031	FORWARD SELECTOR, OXYGEN VALVE ZVC256 10509219 REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
352032	AFT SELECTOR, OXYGEN VALVE ZVC256 1012963 REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
352033	RIGHT AFT SELECTOR, OXYGEN VALVE ZVC179 0061312 REF: AMM 35-00-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUN-2001 0 0	
353001	L1 OXYGEN MASK DROP BOX 833-812-02 0387 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				14-DEC-2001 18 14	
353002	R1 OXYGEN MASK DROP BOX 833-812-02 0404 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				14-DEC-2001 18 14	
353003	L2 OXYGEN MASK DROP BOX 833-812-01 0341 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				14-DEC-2001 18 14	
353004	R3 OXYGEN MASK DROP BOX 833-812-02 0406 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				14-DEC-2001 18 14	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
353005	L3 OXYGEN MASK DROP BOX 833-812-01 0348 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
353006	R4 OXYGEN MASK DROP BOX 833-812-02 0407 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
353007	R2 OXYGEN MASK DROP BOX 833-812-01 0346 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
CHAPTER 36 PNEUMATIC									
05-11-00-W3610011	REPLACE ENGINE BLEED AIR CHECK VALVES REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2013 4582.6 3269		
3610008-001 EMP	REPLACE LEFT ENGINE PYLON BLEED AIR SEALS REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
3610008-002 EMP	REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C				27-JUN-2001 0 0		
3610009 EMP	REPLACE TAILCONE BLEED AIR SEALS (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C				28-SEP-2012 4346.6 3005		
NOT APPLICABLE									

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361001	NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE 7608071-1 257 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3610011 EMP	REPLACE ENGINE BLEED AIR CHECK VALVE (6608295-3) REF: AMM 36-10-06	MOS HRS/MSC AFL	2400	+25/-25			27-JUN-2013 4582.6 3269	6982.6	7007.6
361002	NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE 7608071-1 272 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3610037 EMP (s)	PERFORM VISUAL INSPECTION OF HIGH PRESSURE BLEED AIR CHECK VALVES PKG 43 REF: AMM 36-10-06	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
3610039 EMP (s)	PERFORM OPERATIONAL CHECK OF BLEED AIR CHECK VALVES PKG 42 REF: AMM 36-10-03	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
3610057L EMP	X-RAY INSPECT NO. 1 EMERGENCY AIR BOTTLES (P/N 6600194-008) 6600194-008 00095 REF:	MOS HRS/MSC AFL	108				19-FEB-2014	19-FEB-2023	
3610057R EMP	X-RAY INSPECT NO. 2 EMERGENCY AIR BOTTLES (P/N 6600194-008) 6600194-008 00288 REF:	MOS HRS/MSC AFL	108				08-FEB-2014	08-FEB-2023	
361007	LEFT MIXING VALVE CONTROL BOX 5418553-19 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3610071L EMP	PERFORM VISUAL INSPECTION NO. 1 EMERGENCY AIR BOTTLES (P/N 6600194-008) AND ICC HYDROSTATIC TEST (P/N 6600194-008)								
	6600194-008	MOS	36				01-APR-2019	01-APR-2022	
	00095	HRS/MSC							
EMP LJ	REF:	AFL							
3610071R EMP	PERFORM NO. 2 EMERGENCY AIR BOTTLES (P/N 6600194-008) VISUAL INSPECTION AND HYDROSTATIC TEST								
	6600194-008	MOS	36				28-MAR-2019	28-MAR-2022	
	00288	HRS/MSC					6431.9		
EMP LJ	REF:	AFL					5305		
3610074 EMP	NO. 1 EMERGENCY AIR BOTTLES (P/N 6600194-008)								
	6600194-008	MOS	180	+14d/-14d	N:0		27-MAR-2014	19-FEB-2029	05-MAR-2029
	00095	HRS/MSC					4887.6		
LIFE LIMIT	REF: AMM 36-15-01	AFL					3604		
	Manufacture Date: 19-FEB-2014								
3610074 EMP	NO. 2 EMERGENCY AIR BOTTLES (P/N 6600194-008)								
	6600194-008	MOS	180	+14d/-14d	N:0		27-MAR-2014	08-FEB-2029	22-FEB-2029
	00288	HRS/MSC					4887.4		
LIFE LIMIT	REF: AMM 36-15-01	AFL					3604		
	Manufacture Date: 08-FEB-2014								
361008	RIGHT MIXING VALVE CONTROL BOX								
	5418553-19	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: See Workcard	AFL							
361011	LEFT BLEED AIR MIXING VALVE								
	1H106-9	MOS					08-NOV-2007		
	12AW30	HRS/MSC	O/C				2795.7		
	REF: See Workcard	AFL					1649		
361012	RIGHT BLEED AIR MIXING VALVE								
	1H106-8	MOS					19-APR-2006		
	10AH16	HRS/MSC	O/C				2354		
	REF: See Workcard	AFL					1327		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361013	NO. 1 BLEED AIR CHECK VALVE 6608295-3 2104 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:85 N:2221.4 N:1939			27-JUN-2013 4582.6 3269		
361014	NO. 2 BLEED AIR CHECK VALVE 6608295-3 2125 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:85 N:2221.4 N:1939			27-JUN-2013 4582.6 3269		
361015	LEFT BLEED AIR CHECK VALVE M942-2 1027 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
361016	RIGHT BLEED AIR CHECK VALVE M942-2 1044 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
361017	NO. 1 BLEED AIR (1 1/4) CHECK VALVE 6600210-10 7183 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
361018	NO. 2 BLEED AIR (1 1/4) CHECK VALVE 6600210-10 7093 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
3620001 EMP (s)	PERFORM FUNCTIONAL TEST PERFORM FUNCTIONAL TEST OF PYLON OVERHEAT THERMOSTAT, DUCT TEMPERATURE SENSOR, AND ELECTRICAL SYSTEM PKG 43 REF: See Workcard	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0	PKG	
362001	LANDING GEAR/BRAKE AIR PRESSURE INDICATOR 6608401-12 381 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362003	PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER 124058-5000 40338 REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
362004	SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER 124058-5000 42089 REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
362019	NO. 1 INBOARD OVERHEAT SWITCH 6600213-5 000221 REF: AMM 36-20-04	MOS HRS/MSC AFL	O/C				27-MAR-2008 2884.4 1714		
362020	NO. 2 INBOARD OVERHEAT SWITCH 6600213-5 175076 REF: AMM 36-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
362025	NO. 1 OUTBOARD OVERHEAT SWITCH 6600213-5 172716 REF:	MOS HRS/MSC AFL	O/C	N:144 N:4582.6 N:3269			27-JUN-2013 4582.6 3269		
362026	NO. 2 OUTBOARD OVERHEAT SWITCH 6600213-5 172740 REF:	MOS HRS/MSC AFL	O/C	N:144 N:4582.6 N:3269			27-JUN-2013 4582.6 3269		
CHAPTER 38	WATER/WASTE								
381009	FORWARD TOILET DRAIN, HEATED MAST 116393-101C 1120 REF: AMM 38-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381010	AFT TOILET DRAIN, HEATED MAST 116393-101 SN-UNKNOWN REF: AMM 38-32-01	MOS HRS/MSC AFL	O/C				27-JUN-2013 4582.6 3269		
381070	LAVATORY SINK PUMP 100-000-21 031789 REF: AMM 12-10-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-FEB-2020 6747 5590		
382015	NO. 1 HOT WATER TANK HLWC-03205-1 SN-UNKNOWN REF: AMM 12-10-12	MOS HRS/MSC AFL	O/C						
382016	NO. 2 HOT WATER TANK HLWC-03205-1 SN-UNKNOWN REF: AMM 12-10-12	MOS HRS/MSC AFL	O/C						
383101	LAVATORY TOILET ASSEMBLY 9060-10 U1889 REF: AMM 38-31-01	MOS HRS/MSC AFL APH ACH	O/C	N:0 N:0 N:0 N:0 N:0			14-DEC-2001 18 14 0 0		
CHAPTER 49	AIRBORNE AUXILIARY POWER								
490025	APU COCKPIT PANEL POWER SUPPLY 201-6-038-9 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
490101	COCKPIT APU CONTROL PANEL 201-6-035-9 AA145671 REF: SMM 49-01-01	MOS HRS/MSC AFL	O/C	N:15			27-JUN-2016 5596.6 4439		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
490102	APU RELAY BOX 201-6-028-9 4666-12 REF: SMM 49-01-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-FEB-2006 2208.2 1235		
490103	(ESU / DESU) ELECTRONIC SEQUENCE UNIT 160935-203B 0093 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-DEC-2018 6368.9 5229		
490105	APU (GCU) GENERATOR CONTROL UNIT GCSG505-16G 1206C REF: SMM 49-01-05	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			02-APR-2018 6168.7 5017		
490106	BITE ANNUNCIATOR BOX 161212-100 SN-UNKNOWN REF: SMM 49-01-06	MOS HRS/MSC AFL	O/C						
490109	UPPER CURRENT TRANSFORMER GTSG-700 SN-UNKNOWN REF: SMM 49-01-09	MOS HRS/MSC AFL	O/C						
493101	APU FUEL SHUTOFF VALVE EM91-41 10529538 REF: SMM 49-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
493102	APU FUEL BOOST PUMP 1500-00-22 2198 REF: SMM 49-31-02	MOS HRS/MSC AFL	O/C	O:0 N:2173 O:0 N:1347 O:0			06-AUG-2018 6270.8 5125		
496103	APU FIRE HORN 430-M1 19367 REF: SMM 49-61-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
496103	APU FIRE WARNING HORN 430-M1 19367 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-DEC-2001 18 14		
498010	EXHAUST (APU) DUCT 801-6-015-9 4892-177 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
49APU1 49.APU1	APU 4503135 SP-E010353 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C	N:2780			05-DEC-2018 6368.9 5229		
APU Model : T-20G-10C3A (CIMMS) Serial # SP-E010353 Part # 4503135									
490102	APU - BYTE BOX 161212-100 0692 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			25-MAY-2001 0 0		
490103	APU - ELECTRONIC SENSOR (ESU) UNIT 160935-203B 0093 REF:	MOS HRS/MSC APUS	O/C	R:0 R:0 R:0			30-DEC-2005		
492020	APU - IGNITER 160544-1 NSN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			29-NOV-2018 2778 5810		
492320	APU - SPEED (MAGNETIC PICK-UP) SENSOR 169080-1 A290 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			02-MAR-2012 1649 3383		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493001	APU - FUEL CONTROL 160962-6 2495499 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			25-MAY-2001 0 0		
493007	APU - ASSEMBLY, FUEL ATOMIZER 4504283A 04-05-35 REF:	MOS HRS/MSC APUS	O/C	R:0 R:0 R:0			11-SEP-2012 1697 3495		
493055	APU - ATOMIZER CUP MOTOR 4951372 M184 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			11-SEP-2012 1697 3495		
493102	APU - FUEL PUMP 161627-2 V61-T-0287 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			25-MAY-2001 0 0		
495001	APU - TURBINE WHEEL 164253-3 HB017 REF:	MOS HRS/MSC APUS	3500	N:0 N:0 N:0			11-SEP-2012 1697 3495	6995	
495005	APU - COMPRESSOR WHEEL 160915-4 H390B REF:	MOS HRS/MSC APUS	7000	N:0 N:0 N:0			11-SEP-2012 1697 3495	10495	
CHAPTER 52	DOORS								
521001	UPPER PASSENGER/CREW DOOR 5410501-117 W174 REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521002	LOWER PASSENGER/CREW DOOR 5410536-032 W282 REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
5210020 EMP (s)	INSPECT UPPER AND LOWER DOOR HINGE INSTALLATIONS FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT EDGES OF HINGE INSTALLATION WHILE RACKING THE DOORS WITH ALTERNATING LOADS. IF HINGE INSTALLATION CONDITION REQUIRES A MORE THOROUGH INSPECTION, USE X-RAYS TO OBTAIN DEFINITIVE INSPECTION RESULTS PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0		
521003	UPPER PASSENGER/CREW DOOR HANDLE 6600480-1 277 REF: AMM 52-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
5210030 EMP (s)	REMOVE TENSION FITTINGS AND PLATES FROM PASSENGER/CREW DOORS (SIX ON EACH DOOR) MAGNETIC PARTICLE INSPECT FOR EVIDENCE OF CRACKS PKG 48 REF: AMM 52-10-17	MOS HRS/MSC AFL	3000	+25/-25			27-JUN-2001 0 0		
521004	UPPER PASSENGER/CREW DOOR LOCK ASSEMBLY AS848 SG5916065 REF: AMM 52-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
5210040 EMP (s)	CLEAN ARM GUIDES OF PASSENGER/CREW UPPER DOOR AND VISUALLY CHECK FOR CRACKS (SEE FIGURE X) PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			27-JUN-2001 0 0		
5210042 EMP (s)	INSPECT CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR SEALS FOR ADHESION, CUTS, AND ABRASION; LATCH FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY PKG 41 REF: GENERIC NO REF	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5210052 EMP (s)	VERIFY UPPER AND LOWER DOOR HANDLE MECHANISM: GAIN ACCESS TO UPPER AND LOWER DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION						PKG		
	PKG 53	MOS	144	+14d/-14d			27-JUN-2001		
		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		
+ 5210054 EMP	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE - REPLACE								
		MOS	36	+14d/-14d			(EBT)	30-APR-2021	M 14-MAY-2021
		HRS/MSC							
	REF: GENERIC NO REF	AFL	1200	+25/-25				6244	M 6269
5210056 EMP (s)	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE						PKG		
	PKG 42	MOS	72				31-OCT-2019		
		HRS/MSC	1200				6654.5		
	REF: GENERIC NO REF	AFL					5490		
5210060 EMP (s)	INSPECT ENTIRE LENGTH OF LOWER DOOR CABLES FOR EVIDENCE OF FRAYING OR OTHER DAMAGE. DOOR ACCESS PANELS MUST BE REMOVED						PKG		
	PKG 41	MOS	36	+14d/-14d			31-OCT-2019		
		HRS/MSC	600	+25/-25			6654.5		
	REF: AMM 52-10-10	AFL					5490		
5210065 EMP (s)	CLEAN LATCH ARM OF PASSENGER/CREW LOWER DOOR AND VISUALLY INSPECT FOR CRACKS. (SEE FIGURE)						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001		
		HRS/MSC	2400	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
5210070 EMP (s)	EDDY CURRENT INSPECT AROUND LOWER CABIN DOOR LATCH ARM FASTENERS AND PERIPHERY OF ARM PIN EYES FOR CRACKS						PKG		
	PKG 53	MOS	144	+14d/-14d			27-JUN-2001		
		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		
5210086 EMP (s)	CHECK LOWER CABIN DOOR MECHANISM. OPEN UPPER AND LOWER CABIN DOORS. MOVE LOWER DOOR HANDLE TOWARD THE OPEN AND CLOSED POSITIONS WHILE RESTRAINING THE DOOR PIN MOVEMENT. CHECK FOR SECURITY AND FREE PLAY IN MECHANISM. EXCESSIVE FREE PLAY MAY BE DUE TO MECHANISM FAILURE, EXCESSIVE WEAR, OR DEFORMATION. CHECK DOOR DAMPER FOR LEAKS AND CORRECT OPERATION						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001		
		HRS/MSC	2400	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521010	FORWARD PASSENGER/CREW LOWER DOOR CABLE 6015550-003 SN-UNKNOWN REF: AMM 52-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-JUL-2016 5602.6 4446	
521011	AFT PASSENGER/CREW LOWER DOOR CABLE 6015550-002 SN-UNKNOWN REF: AMM 52-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				13-MAY-2019 6478 5350	
521012	LOWER PASSENGER/CREW DOOR DAMPER 6600425-2 1375 REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				24-MAY-2011 3945.7 2611	
522000	EMERGENCY EXIT / BAGGAGE DOOR 6011501-13 W244 REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C					27-JUN-2001 0 0	
5220010 EMP (s)	CHECK EMERGENCY EXIT/BAGGAGE DOOR HINGE INSTALLATION FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT HINGE INSTALLATIONS WHILE RACKING THE DOOR WITH ALTERNATING LOADS PKG 43 REF: AMM 52-20-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25				27-JUN-2001 0 0	
5220020 EMP (s)	CHECK EMERGENCY EXIT/BAGGAGE DOOR HANDLE AND CONTROL ASSEMBLY FREE PLAY CHECK. OPEN DOOR AND REMOVE UPHOLSTERY TO GAIN ACCESS TO ROD CONTROL ASSEMBLY. RESTRAIN THE DOOR PINS AND MOVE THE EMERGENCY EXIT/BAGGAGE DOOR HANDLE TOWARD THE CLOSED POSITION AND THEN TO THE OPEN POSITION. OBSERVE INNER DOOR HANDLE FREE PLAY RELATIVE TO ROD CONTROL ASSEMBLY. CHECK FOR CORRECT DOOR DAMPER OPERATION PKG 43 REF: AMM 52-20-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25				27-JUN-2001 0 0	
5220021 EMP (s)	VERIFY EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM: GAIN ACCESS TO EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION PKG 53 REF: AMM 52-20-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25				27-JUN-2001 0 0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
522025	EMERGENCY EXIT/BAGGAGE DAMPER 12754-0012-003 SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C						
5230021 EMP (s)	PERFORM OPERATIONAL CHECK TAILCONE BAGGAGE AND TAILCONE ACCESS DOOR WARNING SYSTEMS PKG 42 REF: AMM 52-70-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
523101	TAILCONE BAGGAGE DOOR 6011552-17 231-1590 REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		
523102	TAILCONE BAGGAGE HANDLE 6600480-2 268 REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		
5240005 EMP (s)	PERFORM AFT AVIONICS DOOR GAP AND MISMATCH INSPECTION PKG 47 REF: AMM 52-40-01	MOS HRS/MSC AFL	24	+14d/-14d			PKG 16-OCT-2018		
524001	LEFT NOSE AVIONICS DOOR 6010430-003 0185 REF:	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		
524002	RIGHT NOSE AVIONICS DOOR 6010430-004 0185 REF:	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		
524003	LEFT FORWARD NOSE AVIONICS DOOR 5410430-27 SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
524004	RIGHT FORWARD NOSE AVIONICS DOOR 5410430-28 SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C						
524005	LEFT AFT NOSE AVIONICS DOOR 5410431-23 SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C						
524006	RIGHT AFT NOSE AVIONICS DOOR 5410431-22 SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C						
524007	TAILCONE AVIONICS DOOR 5412500-21 0136 REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
527005	CREW DOOR WARNING BOX ASSEMBLY 5418316-10 A00465646-01 REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C				27-FEB-2012 4163.6 2799		
527006	EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY 5418316-10 A01907508-07 REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-FEB-2012 4163.6 2799		
528001	LEFT INBOARD MAIN LANDING GEAR DOOR 6022161-015 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C						
528002	RIGHT INBOARD MAIN LANDING GEAR DOOR 6022161-808 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
528003	LEFT OUTBOARD MAIN LANDING GEAR DOOR 6022151-007 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C						
528004	RIGHT OUTBOARD MAIN LANDING GEAR DOOR 6022151-008 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C						
528101	LEFT NOSE LANDING GEAR DOOR 5410450-19 60-232 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
528102	RIGHT NOSE LANDING GEAR DOOR 5410450-20 60-232 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
CHAPTER 53 FUSELAGE									
5311006 EMP (s)	REMOVE NOSE GEAR TRUNNION FITTINGS AND VISUALLY INSPECT NOSE GEAR TRUNNION FITTING AREA IN FORWARD FUSELAGE FOR CRACKS, CORROSION, AND PERMANENT DEFORMATION. (REFER TO 5-10-00). EDDY CURRENT INSPECT NOSE GEAR TRUNNION FITTING ATTACH HOLES AND TRUNNION AXLE BOSS PKG 51 REF: NDT 53-61-02	MOS HRS/MSC AFL	6000	+25/-25			PKG 27-JUN-2001 0 0		
5311007 EMP (s)	EDDY CURRENT INSPECT UPPER ATTACHMENT AREA OF NOSE GEAR ACTUATOR FOR CRACKS, CORROSION, PERMANENT DEFORMATION, AND ATTACHMENT FITTING SECURITY PKG 53 REF: NDT 53-60-01	MOS HRS/MSC AFL	144	+14d/-14d			PKG 27-JUN-2001 0 0		
5313000 EMP (s)	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK PKG 47 REF: AMM 53-11-01	MOS HRS/MSC AFL	24	+14d/-14d			PKG 16-OCT-2018		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5314011 EMP (s)	INSPECT BELOW FLOORBOARD FOR CORROSION, GENERAL CONDITION, AND FATIGUE CRACKS PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
5314040 EMP (s)	CHECK EMERGENCY EXIT/BAGGAGE DOOR FUSELAGE FRAMING STRUCTURE: CONDUCT X-RAY INSPECTION OF FUSELAGE DOOR FRAMING STRUCTURE IN AREA OF BORDERING INNER SKIN. PAY PARTICULAR ATTENTION TO HINGES, HINGE ATTACHMENTS, CORNER DOUBLERS, AND THE LATCH PIN AND RECEPTACLE SUPPORT STRUCTURE. REMOVAL OF INNER SKIN NOT REQUIRED UNLESS X-RAY RESULTS SHOW EVIDENCE OF CRACK OR CORROSION PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
5314070 EMP (s)	CHECK UPPER AND LOWER CABIN DOOR HINGES AND FUSELAGE FRAMING STRUCTURE: A. VISUALLY INSPECT ACCESSIBLE STRUCTURE FOR SECURITY, GENERAL CONDITION, EXCESSIVE WEAR OR LOOSENESS, AND FATIGUE CRACKS. B. CONDUCT X-RAY INSPECTION OF UPPER AND LOWER HINGES, ATTACHING STRUCTURE, AND FRAMING MEMBERS. REMOVAL OF SECONDARY INNER SKIN NOT REQUIRED UNLESS X-RAY RESULTS INDICATE POSSIBLE CRACKS OR CORROSION OR IF INTERNAL/EXTERNAL VISUAL INSPECTION INDICATES EXCESSIVE WEAR OR LOOSENESS PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
5321000 EMP (s)	CHECK FUSELAGE FRAMES AND STRINGERS: GAIN ACCESS TO ALL FUSELAGE FRAMES AND STRINGERS FROM FRAME 6 TO AFT PRESSURE BULKHEAD. CONDUCT AN INTERIOR VISUAL INSPECTION OF ALL FUSELAGE FRAMES AND STRINGERS. PARTICULAR ATTENTION SHOULD BE GIVEN TO ALL FRAME SPLICES PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
5321020 EMP (s)	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. TAP-TEST FLOOR PANEL, WHICH SUPPORTS THE ELECTRICAL EQUIPMENT, TO CHECK FOR UNBONDING OF UPPER SURFACE PLATE FROM THE HONEYCOMB CORE STRUCTURE. VISUALLY INSPECT FOR CORROSION, PARTICULARLY IN THE AREA OF THE THREADED INSERTS. CHECK FOR LOOSE THREADED INSERTS AND ANY OTHER DAMAGE TO FLOOR PANEL PKG 48 REF: GENERIC NO REF	MOS HRS/MSC AFL	3000	+25/-25			PKG 27-JUN-2001 0 0		
5321021 EMP (s)	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. VISUALLY INSPECT FLOOR PANEL WHICH SUPPORTS THE ELECTRICAL EQUIPMENT AND FRAMES 25, 26, AND 26A FOR CORROSION AND ANY OTHER DAMAGE PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5321040 EMP (s)	VERIFY WITH WING/FUSELAGE FAIRINGS REMOVED, USE FLASHLIGHT AND MIRROR TO VISUALLY INSPECT THE HONEYCOMB SUPPORT ANGLE SEGMENTS AT THE OUTBOARD ENDS OF THE FORWARD BAGGAGE FLOOR FOR FATIGUE CRACKS, CORROSION, FASTENER SECURITY, AND GENERAL CONDITION						PKG		
	PKG 48	MOS						27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	3000	+25/-25				0	
5321042 EMP (s)	IDENTIFY BAGGAGE FLOOR/OVER WING AREA A. INSPECT ENTIRE AREA FOR CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT THE SEGMENTED HONEYCOMB FLOOR SUPPORT ANGLES AT THE OUTBOARD EDGES FOR FATIGUE CRACKS, FASTENER SECURITY, AND GENERAL CONDITION. B. INSPECT FRAME 26A AREA (CAPS AND WEBS) FOR FATIGUE CRACKS AT FASTENER HOLES. UPON INSPECTION COMPLETION, CLEAN AND RE-PRIME AS REQUIRED						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5321048 EMP (s)	INSPECT BAGGAGE FLOOR/OVER WING AREA PER MM INSTRUCTIONS PARAGRAPH A, B, C, D, AND E						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5321049 EMP (s)	PERFORM VISUAL INSPECTION OVERWING CUTOUT RADIUS AT FS 346 AND FS 421 (FRAMES 24 AND 31 FUSELAGE SKIN PANELS)						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5321050 EMP (s)	INSPECT ACCESSIBLE PORTIONS OF LOWER CAP OF THE FRAME 26A AREA, AND ADJACENT FLOOR STRUCTURE, FRAME 24 - 26A. VISUALLY INSPECT FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5321055 EMP (s)	CLEAN/VISUALLY INSPECT WING-TO-FUSELAGE ATTACHMENT FITTINGS WITH THE AID OF 10X MAGNIFICATION, FLASHLIGHT, AND MIRROR, ALL EIGHT (8) WING-TO-FUSELAGE ATTACHMENT FITTINGS. INSPECT FITTINGS AND SUPPORT STRUCTURE FOR CRACKS, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5321060 EMP (s)	CLEAN/VISUALLY INSPECT ALL EIGHT WING/FUSELAGE FITTINGS WING/FUSELAGE FITTINGS, (FOUR PER SIDE). USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, VISUALLY INSPECT FITTINGS AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY. CONDUCT EDDY CURRENT INSPECTION OF LUG AREAS AT SPARS 2, 5, 7, AND 8 FOR FATIGUE CRACKS						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5321079 EMP (s)	PERFORM AFT PRESSURE BULKHEAD A. REMOVE FUEL BLADDER AND VISUALLY INSPECT BULKHEAD FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, OR OTHER DAMAGE. VISUALLY INSPECT SUPPORTING STRUCTURE ALONG FLOOR, FRAME PERIPHERY, AND CENTERLINE BEAM FOR FATIGUE CRACKS, FASTENER SECURITY, CORROSION, OR OTHER DEGRADATION						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5321081 EMP (s)	VISUALLY INSPECT FORWARD PRESSURE BULKHEAD FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5321085 EMP (s)	VISUAL INSPECT FORWARD PRESSURE BULKHEAD FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION. GAIN ACCESS TO THE FORWARD SIDE OF THE FORWARD PRESSURE BULKHEAD AND INSPECT PRESSURE BULKHEAD VERTICAL MEMBERS FOR FATIGUE CRACKS AND THE PRESSURE BULKHEAD FOR FASTENER CONDITION, CRACKS, AND DEFORMATION						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5321087 EMP (s)	INSPECT AFT PRESSURE BULKHEAD PER MM INSTRUCTIONS PARAGRAPH A, B, C, D, E, AND F						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: AMM 53-10-01	AFL						0	
5322000 EMP	REPLACE KEELBEAM ATTACHMENT BOLTS								
		MOS	144	+14d/-14d				27-JUN-2013	27-JUN-2025
		HRS/MSC						4582.6	11-JUL-2025
LIFE LIMIT	REF: AMM 53-10-02	AFL	6000	+25/-25				3269	9269

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5323065 EMP (s)	INSPECT CIRCUMFERENTIAL SKIN SPLICES: CONDUCT A GENERAL VISUAL INTERNAL AND EXTERNAL INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW:A. FRAMES 8, 17, 20, 25, AND 26.B. ON AIRCRAFT 60-002, FRAME 12.C. ON AIRCRAFT 60-003 AND SUBSEQUENT, FRAME 13.D. ON AIRCRAFT 60-002 THRU 60-093, FRAME 20B.INSPECT FOR CORROSION, FATIGUE CRACKS, LOOSE OR WORKING FASTENERS, AND GENERAL SECURITY						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5323106 EMP (s)	INSPECT LONGITUDINAL SKIN SPLICES (PRESSURE CABIN): A. CONDUCT AN INTERNAL AND EXTERNAL VISUAL INSPECTION OF THE LONGITUDINAL SKIN SPLICES ALONG THE MAIN "T" STRINGERS AT STRINGERS 4L, 6L, 7AL, 18L, 23L, 2R, 6R, 8R, AND 18R						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5323107 EMP (s)	INSPECT CIRCUMFERENTIAL SKIN SPLICES: CONDUCT AN X-RAY INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW:A. FRAMES 17, 20, 25, AND 26.B. ON AIRCRAFT 60-002, FRAME 12.C. ON AIRCRAFT 60-003 AND SUBSEQUENT, FRAME 13.D. ON AIRCRAFT 60-002 THRU 60-093, FRAME 20B.CONDUCT SPECIFIC X-RAY INSPECTIONS OF THE CIRCUMFERENTIAL SKIN SPLICES IN THE PRESSURE CABIN ACROSS THE TOP OF THE FUSELAGE FROM STRINGER 8L TO 8R						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5323108 EMP (s)	X-RAY INSPECT LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) THE LONGITUDINAL SKIN SPLICES ALONG THE MAIN "T" STRINGERS AT STRINGERS 4L, 6L, 18L, 23L, 2R, 6R, AND 18R						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5323146 EMP (s)	INSPECT EXTERNAL SKIN CUTOUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT)						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5323158 EMP (s)	INSPECT EXTERIOR OF THE SKIN, GIVING PARTICULAR ATTENTION TO LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR FASTENER CONDITION, FATIGUE CRACKS, AND GENERAL SPLICE CONDITION						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5323162 EMP (s)	VISUALLY INSPECT EXTERNAL LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR EVIDENCE OF FATIGUE CRACKS, WORKING RIVETS, CORROSION, AND GENERAL CONDITION						PKG		
	PKG 48	MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	3000	+25/-25			0		
5331012 EMP	REMOVE * ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION (AWL*)								
		MOS	49				20-OCT-2016	20-NOV-2020	
		HRS/MSC					5658.5		
AIRWORTHINESS	REF: AMM 53-30-02	AFL					4503		
5331017 EMP	INSPECTION OF UPPER FUSELAGE SKIN UNDER THE AFT OXYGEN LINE FAIRING								
		MOS	144	+14d/-14d			(EBT)	06-OCT-2028	20-OCT-2028
		HRS/MSC							
	REF: AMM 53-50-06	AFL							
5331030 EMP (s)	VISUAL INSPECTION OF THE TAILCONE STRUCTURE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. FROM THE TAILCONE ACCESS DOOR OPENING, VISUALLY INSPECT ACCESSIBLE AREAS OF INTERNAL TAILCONE STRUCTURE (FRAMES, STRINGERS, ETC.) AND CHECK FOR DISTORTION, CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION						PKG		
	PKG 52	MOS					27-JUN-2001		
		HRS/MSC	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
5340001 EMP (s)	PERFORM EDDY CURRENT INSPECTION ON FORWARD BEAM SUPPORT FITTING						PKG		
	PKG 52	MOS					27-JUN-2001		
		HRS/MSC	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
5340002 EMP (s)	VISUALLY INSPECT FORWARD ENGINE BEAM ASSEMBLY						PKG		
	PKG 52	MOS					27-JUN-2001		
		HRS/MSC	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
5340003 EMP (s)	PERFORM VISUAL INSPECTION FORWARD ENGINE BEAM STABILIZER STRUCTURE						PKG		
	PKG 52	MOS					27-JUN-2001		
		HRS/MSC	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5340004 EMP (s)	EDDY CURRENT INSPECT AFT BEAM SUPPORT FITTING PKG 52 REF: NDT 53-40-02	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
5340005 EMP (s)	PERFORM VISUAL INSPECTION AFT ENGINE BEAM PKG 52 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
5340006 EMP (s)	VISUALLY INSPECT AFT ENGINE BEAM AND FRAME STRUCTURE PKG 52 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
535001	RADOME 5410420-27 0237 REF: AMM 53-50-01	MOS HRS/MSC AFL	O/C		R:0 R:0 R:0		27-JUN-2013 4582.6 3269		
5350010 EMP (s)	VISUALLY INSPECT KEELBEAM, FORWARD AND AFT ATTACH FITTINGS ON KEELBEAM AND ON AIRCRAFT, FOR CRACKS AND GENERAL CONDITION PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
5350020 EMP (s)	INSPECT UNDERWING KEELBEAM AND ATTACHMENTS FOR SECURITY, CORROSION, FASTENER CONDITION, FATIGUE CRACKS, AND PERMANENT DEFORMATION. ALSO INSPECT ATTACHING FITTINGS, FORWARD OF FRAME 24 AND AFT OF FRAME 31, FOR SIMILAR EFFECTS PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
5350051 EMP (s)	VISUALLY INSPECT UNDERWING KEELBEAM REMOVED ASSEMBLY FOR CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO END FITTINGS COMMON TO BEAM ASSEMBLY AS WELL AS THOSE MATING FITTINGS FORWARD OF FRAME 24 AND AFT OF FRAME 31 PKG 52 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		

CHAPTER 54 NACELLES/PYLONS

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5450002 EMP (s)	VISUALLY INSPECT ENGINE SUPPORT STRUCTURE PKG 52	MOS					PKG	27-JUN-2001	
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0	0	
CHAPTER 55 STABILIZERS									
5510040 EMP (s)	CHECK WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCTURE ATTACHING BOLTS, AND BOLT RETAINERS FOR WEAR, LOOSENESS, FREE PLAY, CRACKS, SECURITY, AND GENERAL CONDITION PKG 43	MOS					PKG	27-JUN-2001	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+25/-25			0	0	
5510050 EMP (s)	PERFORM HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER) PER MM INSPECTIONS PARAGRAPH A, B, AND C PKG 53	MOS					PKG	27-JUN-2001	
	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			0	0	
5510060 EMP (s)	GENERAL VISUAL INSPECT HORIZONTAL STABILIZER PKG 52	MOS					PKG	27-JUN-2001	
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0	0	
5510061 EMP (s)	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER PKG 52	MOS					PKG	27-JUN-2001	
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0	0	
5510062 EMP (s)	CLEAN/VISUALLY INSPECT THE HORIZONTAL STABILIZER HINGE PIN FOR WEAR AND CORROSION (INCLUDING THE INTERNAL SURFACE OF THE PIN). APPLY A COAT OF EPOXY PRIMER TO THE INTERNAL SURFACE OF THE PIN PRIOR TO REINSTALLATION. MAGNETIC PARTICLE INSPECT PIN FOR CRACKS PKG 52	MOS					PKG	27-JUN-2001	
	REF: NDT 55-30-01	HRS/MSC AFL	12000	+25/-25			0	0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5520000 EMP (s)	INSPECT ELEVATOR: WITH PUSH-PULL TUBES DISCONNECTED FROM ELEVATOR BELLCRANKS, MOVE EACH ELEVATOR SURFACE THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR SMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, RUST OR CORROSION, TURNING ON BOLT RATHER THAN BEARING, AND GENERAL CONDITION						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5520010 EMP (s)	CHECK WITH CONTROL COLUMN FIXED, APPLY ALTERNATE UP AND DOWN LOADS TO THE ELEVATOR TRAILING EDGE. INSPECT EACH ELEVATOR HINGE LOCATION FOR LOOSENESS, FREE PLAY, FATIGUE CRACKS, AND GENERAL SECURITY						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5520020 EMP (s)	INSPECT ELEVATOR PER MM INSTRUCTIONS ON THIS WORK CARD						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5530003 EMP (s)	INSPECT VERTICAL STABILIZER PER MM INSTRUCTIONS ON THIS WORK CARD						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
553001	VERTICAL STABILIZER								
	5431000-030	MOS						27-JUN-2001	
	W430	HRS/MSC	O/C					0	
	REF: GENERIC NO REF	AFL						0	
5530010 EMP (s)	INSPECT VERTICAL STABILIZER PER MM INSTRUCTIONS ON THIS WORK CARD						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5540010 EMP (s)	INSPECT WITH RUDDER PEDALS RESTRAINED, APPLY ALTERNATING LEFT AND RIGHT LOADS TO THE RUDDER TRAILING EDGE. OBSERVE RUDDER HINGE FITTING ATTACHMENTS FOR LOOSENESS, FREE PLAY, AND GENERAL SECURITY						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5540011 EMP (s)	INSPECT RUDDER: WITH CABLES DISCONNECTED AT AFT BELLCRANK LOCATION. MOVE RUDDER THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR SMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, TURNING ON BOLT RATHER THAN BEARING, RUST OR CORROSION, AND GENERAL CONDITION						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001		
		HRS/MSC	2400	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
5540020 EMP (s)	INSPECT RUDDER PER MM INSTRUCTIONS ON THIS WORK CARD						PKG		
	PKG 52	MOS					27-JUN-2001		
		HRS/MSC	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
CHAPTER 56 WINDOWS									
5600008-001 EMP	PERFORM LEFT NO. 1 CABIN WINDOW OPTICAL PRISM INSPECTION								
	LA6600405-32	MOS					13-NOV-2015		
	1214	HRS/MSC	C/C				5392.7		
	REF: GENERIC NO REF	AFL					4192		
5600008-002 EMP	PERFORM LEFT NO. 2 CABIN WINDOW OPTICAL PRISM INSPECTION								
	6600405-10	MOS					27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	C/C				0		
	REF: GENERIC NO REF	AFL					0		
5600008-003 EMP	PERFORM LEFT NO. 3 CABIN WINDOW OPTICAL PRISM INSPECTION								
	LA6600405-32	MOS					10-APR-2015		
	1187	HRS/MSC	C/C				5172.1		
	REF: GENERIC NO REF	AFL					3945		
5600008-004 EMP	PERFORM LEFT NO. 4 CABIN WINDOW OPTICAL PRISM INSPECTION								
	LA6600405-32	MOS					19-OCT-2018		
	10061	HRS/MSC	600	+25/-25			6341.2	6941.2	6966.2
	REF: GENERIC NO REF	AFL					5193		
5600008-005 EMP	PERFORM LEFT NO. 5 CABIN WINDOW OPTICAL PRISM INSPECTION								
	LA6600405-19	MOS					07-JAN-2013		
	2395	HRS/MSC	C/C				4443.4		
	REF: GENERIC NO REF	AFL					3103		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5600008-006 EMP	PERFORM RIGHT NO. 1 CABIN WINDOW OPTICAL PRISM INSPECTION 6600405-10 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				27-JUN-2001 0 0		
5600008-007 EMP	PERFORM RIGHT NO. 2 CABIN WINDOW OPTICAL PRISM INSPECTION LA6600405-32 1215 REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				13-NOV-2015 5392.7 4192		
5600008-008 EMP	PERFORM RIGHT NO. 3 CABIN WINDOW OPTICAL PRISM INSPECTION LA6600405-32 1358 REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				03-OCT-2014 5023 3758		
5600008-009 EMP	PERFORM RIGHT NO. 4 CABIN WINDOW OPTICAL PRISM INSPECTION 6600405-10 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				27-JUN-2001 0 0		
5600008-010 EMP	PERFORM RIGHT NO. 5 CABIN WINDOW OPTICAL PRISM INSPECTION 6600405-10 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				27-JUN-2001 0 0		
5600008-011 EMP	PERFORM EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY OPTICAL PRISM INSPECTION LA660405-18 1257 REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				28-DEC-2009 3548.7 2286		
5610002 EMP (s)	INSPECT INTERIOR AND EXTERIOR SURFACE OF WINDSHIELD FOR CRAZING, INCLUDING VISIBLE PORTION UNDER RETAINERS FOR CRACKS, CLEANLINESS, SECURITY, AND GENERAL CONDITION. AREA UNDER ANTI-ICE DUCT SHALL BE INSPECTED BY VIEWING THE EPOXY-PRIMED OUTER SURFACE OF THE WINDSHIELD FROM THE COCKPIT. VISUALLY VERIFY INTEGRITY OF THE EPOXY-PRIMED SURFACE PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		PKG

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561001	LEFT WINDSHIELD ASSY 6600394-1 945 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
5610010 EMP (s)	INSPECT WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE) PER WORK CARD PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
561002	RIGHT WINDSHIELD ASSY 6600394-2 1504 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-FEB-2020 6726.5 5570		
5610022-001 EMP	PRISM CHECK LEFT 6600394-1 945 REF: NDT 56-10-01	MOS HRS/MSC AFL	C/C				28-JAN-2008 2855.7 1639		
5610022-002 EMP	PRISM CHECK RIGHT 6600394-2 1504 REF: NDT 56-10-01	MOS HRS/MSC AFL	600	+25/-25			05-FEB-2020 6726.5 5570	7326.5	7351.5
5610024 EMP (s)	INSPECT WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE) PER MM INSTRUCTIONS ON THIS WORK CARD PKG 43 REF: GENERIC NO REF	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 27-JUN-2001 0 0		
561009	LEFT COCKPIT CREW WINDOW 6600403-5 463 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
561010	RIGHT COCKPIT CREW WINDOW 6600402-2 934 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5620001 EMP (s)	CHECK CABIN WINDOWS AND FRAMING MEMBERS: A. VISUALLY INSPECT ACCESSIBLE STRUCTURE FOR SECURITY, GENERAL CONDITION, AND FATIGUE CRACKS. . B. CONDUCT X-RAY INSPECTION OF SUPPORT STRUCTURE. (REFER TO NDI MANUAL [NDI-2], PART 2, 56-20-01						PKG		
	PKG 53	MOS	144	+14d/-14d			27-JUN-2001	0	
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		
5620007 EMP (s)	CHECK CABIN WINDOWS: USING PRISM TECHNIQUES, INSPECT WINDOWS FOR CRACKS, CHIPS, DELAMINATION, OR OTHER DAMAGE. THIS INSPECTION IS ALSO CAPABLE OF VISUALLY ASSESSING THE CONDITION OF THE ATTACHING FASTENERS. BROWN DISCOLORATIONS IN THE AREA OF THE FASTENERS MAY INDICATE CORRODED FASTENERS. REMOVE AND INSPECT SUCH FASTENERS FOR RUST, CORROSION, AND GENERAL CONDITION						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001	0	
	REF: GENERIC NO REF	AFL	2400	+25/-25			0		
562011	LEFT NO. 1 CABIN WINDOW								
	LA6600405-32	MOS		N:0			15-JAN-2014		
	1214	HRS/MSC	O/C	N:0			4789.4		
	REF: AMM 56-20-01	AFL		N:0			3503		
562013	LEFT NO. 2 CABIN WINDOW								
	6600405-10	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: AMM 56-20-01	AFL							
562015	LEFT NO. 3 CABIN WINDOW								
	LA6600405-32	MOS		N:0			05-JUN-2013		
	1187	HRS/MSC	O/C	N:0			4582.6		
	REF: AMM 56-20-01	AFL		N:0			3269		
562017	LEFT NO. 4 CABIN WINDOW								
	LA6600405-32	MOS		N:0			19-OCT-2018		
	10061	HRS/MSC	O/C	N:0			6341.2		
	REF: AMM 56-20-01	AFL		N:0			5193		
562019	LEFT NO. 5 CABIN WINDOW								
	LA6600405-19	MOS		N:0			24-MAY-2011		
	2395	HRS/MSC	O/C	N:0			3945.7		
	REF: AMM 56-20-01	AFL		N:0			2611		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562022	RIGHT NO. 1 CABIN WINDOW 6600405-10 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C						
562024	RIGHT NO. 2 CABIN WINDOW LA6600405-32 1215 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JAN-2014 4789.4 3503		
562026	RIGHT NO. 3 CABIN WINDOW LA6600405-32 1358 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-OCT-2014 5023 3758		
562028	RIGHT NO. 4 CABIN WINDOW 6600405-10 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C						
562030	RIGHT NO. 5 CABIN WINDOW 6600405-10 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C						

CHAPTER 57 WINGS

5710040 EMP (s)	CLEAN AND CONDUCT A GENERAL EXTERNAL AND INTERNAL VISUAL INSPECTION OF THE WING CENTER SECTION, PAYING PARTICULAR ATTENTION TO THE LOWER SKIN AT THE FUEL PUMP LOCATIONS AND THE SPLICE DETAILS AT BL 0.0, AS ACCESSIBLE. INSPECT FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, DEFORMATION, AND FASTENER/JOINT CONDITION						PKG		
	PKG 53	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			27-JUN-2001 0 0		
	REF: GENERIC NO REF								
5710045 EMP (s)	REMOVE LOWER SURFACE ACCESS PLATES FROM WS 92 INBOARD TO BL 0.0 INCLUDING FUEL PUMPS AT WS 6.0 AND 11.0. VISUALLY INSPECT THE PERIPHERY OF THESE CUTOUTS FOR FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. CONDUCT EDDY CURRENT INSPECTIONS ADJACENT TO THE PERIPHERAL FASTENERS AROUND THESE CUT-OUT AREAS. (HOLE AND SURFACE PROBES)						PKG		
	PKG 52	MOS HRS/MSC AFL	12000	+25/-25			27-JUN-2001 0 0		
	REF: GENERIC NO REF								

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710050 EMP (s)	X-RAY INSPECT THE WING UPPER AND LOWER STRUCTURE IN THE CENTERLINE DOUBLER AREA. INSPECT FOR FATIGUE CRACKS, CORROSION, LOOSE OR MISSING FASTENERS, AND GENERAL SECURITY						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5710055 EMP (s)	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER STRUCTURE INBOARD OF THE WING-TO-FUSELAGE FITTINGS AND FORWARD OF SPAR 5. INSPECT FOR CORROSION, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. IF CORROSION IS FOUND, WING REMOVAL FROM FUSELAGE MAY BE REQUIRED TO PERMIT A MORE EXTENSIVE INSPECTION						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5710060 EMP (s)	CONDUCT AN EDDY CURRENT INSPECTION FOR THE FOLLOWING WING STRUCTURAL AREAS: A. SURFACE OF ACCESSIBLE AREAS OF LOWER DOUBLER FROM BL 0.0 TO OUTBOARD END OF DOUBLER ALONG SPARS 4, 5, AND 7, AND LOWER SKIN ADJACENT TO THE OUTBOARD TWO (2) INCHES OF DOUBLER FINGERS. B. SKIN ADJACENT TO FASTENER ROWS ALONG LOWER SURFACE FOR SPARS 4, 5, AND 7 FROM OUTBOARD END OF DOUBLER TO WS 60.0. C. SKIN ADJACENT TO LOWER SURFACE ACCESS PLATE FASTENERS FROM BL 0.0 TO WS 53.04. LOWER WING SKIN SPLICE AT WS 244						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5710062 EMP (s)	REMOVE THE ACCESS COVER AT WS 73.0 BETWEEN SPARS 4/5 AND 6/7. INSPECT ALL HOLES AT THIS LOCATION IN THE SPAR AND SKIN USING AN EDDY CURRENT HOLE PROBE						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5710065 EMP (s)	EDDY CURRENT AREA AROUND FASTENERS COMMON TO TRUNNION FITTINGS						PKG		
	PKG 48	MOS						27-JUN-2001	
		HRS/MSC						0	
	REF: NDT 57-12-01	AFL	3000	+25/-25				0	
5710066 EMP (s)	CONTACT CONDUCT A VISUAL AND EDDY CURRENT INSPECTION HAS DIRECT PER THIS WORK CARD						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710070 EMP (s)	CLEAN UPPER AND LOWER CENTERLINE SPLICE PLATE (SPAR 2 TO 5 AND 7 TO 8) ADJACENT TO BL 0.0 RIB CAP. VISUALLY INSPECT THESE AREAS FOR CORROSION, FATIGUE CRACKS, WORKING FASTENERS, AND GENERAL SECURITY						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5710071 EMP (s)	EDDY CURRENT INSPECT THE LOWER SPLICE PLATE ALONG THE CENTERLINE FASTENER ROWS						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5710140 EMP (s)	REMOVE UPPER WING-TO-FUSELAGE FAIRINGS AND INSPECT WING SKINS, WING-TO-FUSELAGE ATTACH FITTINGS, AND ADJACENT STRUCTURE FOR CORROSION, FASTENER SECURITY, CRACKS, PERMANENT DEFORMATION, PROTECTIVE COATING, AND GENERAL CONDITION. EXAMINE EXPOSED EDGE OF HONEYCOMB DIVAN FLOOR FOR CORROSION AND SECURITY OF BOND BETWEEN CORE AND FACESHEETS						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5710141 EMP (s)	CHECK WING-TO-FUSELAGE ATTACH POINTS FOR SECURITY (THAT PORTION VISIBLE THROUGH WHEEL WELLS)						PKG		
	PKG 43	MOS	108	+14d/-14d				27-JUN-2001	
		HRS/MSC	2400	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
5710142 EMP (s)	VERIFY WITH WING-TO-FUSELAGE FAIRING REMOVED, CLEAN AND VISUALLY INSPECT ALL EIGHT WING-TO-FUSELAGE FITTINGS (FOUR PER SIDE). USING A 10X MAGNIFYING GLASS, ADEQUATE LIGHTING, AND MIRROR, INSPECT FITTINGS AND SUPPORT STRUCTURES FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY						PKG		
	PKG 53	MOS	144	+14d/-14d				27-JUN-2001	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
5710143 EMP (s)	CLEAN/VISUALLY INSPECT USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE) AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY. CONDUCT EDDY CURRENT INSPECTION OF FITTING LUG AREAS FOR FATIGUE CRACKS						PKG		
	PKG 52	MOS						27-JUN-2001	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710144 EMP (s)	CHECK WHEEL WELL AND CENTER SECTION OF WING FOR GENERAL CONDITION OF SKIN, SPARS, ATTACH FITTINGS AND SUPPORTING STRUCTURE, LANDING GEAR RIB, AND TRUNNION FITTINGS. CHECK FOR DEFORMATION, FATIGUE CRACKS, PROTECTIVE FINISH CONDITION, AND GENERAL SECURITY						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001		
		HRS/MSC	2400	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
572001	LEFT WINGLET ASSEMBLY								
	2822650-43	MOS		N:0			27-JUN-2001		
	309	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-20-01	AFL		N:0			0		
5720011 EMP (s)	PERFORM FLAP SUPPORT FITTING EDDY CURRENT INSPECTION (ALUMINUM, P/N 6022521-1 THRU 6022521-8)						PKG		
	PKG 43	MOS	108	+14d/-14d			27-JUN-2001		
		HRS/MSC	2400	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
5720012 EMP	EDDY CURRENT INSPECT FLAP SUPPORT FITTING (TITANIUM, P/N 6022521-13 THRU 6022521-20)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: NDT 57-40-03	AFL	10000	+25/-25			0	10000	10025
5720012 EMP	EDDY CURRENT INSPECT LEFT FLAP SUPPORT FITTING (TITANIUM, P/N 6022521-13 THRU 6022521-20)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: NDT 57-40-03	AFL	10000	+25/-25			0	10000	10025
5720012 EMP	EDDY CURRENT INSPECT RIGHT FLAP SUPPORT FITTING (TITANIUM, P/N 6022521-13 THRU 6022521-20)								
		MOS					27-JUN-2001		
		HRS/MSC					0		
	REF: NDT 57-40-03	AFL	10000	+25/-25			0	10000	10025
572002	RIGHT WINGLET ASSEMBLY								
	2822650-44	MOS		N:0			27-JUN-2001		
	304	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-20-01	AFL		N:0			0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5720020 EMP (s)	VISUALLY INSPECT INTERNAL AND EXTERNAL AREA OF WING WHEEL WELL STRUCTURE, PAYING PARTICULAR ATTENTION TO MAIN LANDING GEAR ACTUATOR UPPER ATTACHMENT AND LANDING GEAR RIB STRUCTURE AT WS 53.04						PKG		
	PKG 53	MOS	144	+14d/-14d			27-JUN-2001	0	
	REF: GENERIC NO REF	AFL	6000	+25/-25			0	0	
5720021 EMP (s)	VISUALLY INSPECT INTERNAL AND EXTERNAL AREAS OF WING STRUCTURE ADJACENT TO LANDING GEAR RIB WS 53.04 (BETWEEN SPARS 4 AND 8). INSPECT TRUNNION FITTINGS FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, ELONGATION OF TRUNNION PIN HOLES, AND GENERAL SECURITY. CHECK MAIN LANDING GEAR TRUNNION BUSHING I.D. FOR DIMENSIONAL CONFORMITY FOR EVIDENCE OF A HARD LANDING. IF EVIDENCE OF A HARD LANDING EXISTS, CONDUCT HARD LANDING INSPECTION. EDDY CURRENT INSPECT AREAS OF TRUNNION FITTINGS AT SPAR 5 AND SPAR 7						PKG		
	PKG 51	MOS					27-JUN-2001	0	
	REF: GENERIC NO REF	AFL	6000	+25/-25			0	0	
5720025 EMP (s)	INSPECT BY X-RAY THE OUTBOARD LOWER WING SKIN FROM WS 31 TO WS 61						PKG		
	PKG 53	MOS	144	+14d/-14d			27-JUN-2001	0	
	REF: GENERIC NO REF	AFL	6000	+25/-25			0	0	
5720040 EMP (s)	INSPECT THE JOINT AT WS 181 THAT SPLICES THE WING TO THE OUTER WING EXTENSION. VISUALLY INSPECT FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, AND GENERAL SECURITY						PKG		
	PKG 53	MOS	144	+14d/-14d			27-JUN-2001	0	
	REF: GENERIC NO REF	AFL	6000	+25/-25			0	0	
572025	LEFT FRONT WINGLET SPAR FITTING								
	6022621-1	MOS					27-JUN-2001	0	
	R-479	HRS/MSC	O/C		N:0		0	0	
	REF: GENERIC NO REF	AFL			N:0		0	0	
572026	RIGHT FRONT WINGLET SPAR FITTING								
	6022621-2	MOS					27-JUN-2001	0	
	R-512	HRS/MSC	O/C		N:0		0	0	
	REF: GENERIC NO REF	AFL			N:0		0	0	
572027	LEFT AFT WINGLET SPAR FITTING								
	6022622-1	MOS					27-JUN-2001	0	
	R-508	HRS/MSC	O/C		N:0		0	0	
	REF: GENERIC NO REF	AFL			N:0		0	0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
572028	RIGHT AFT WINGLET SPAR FITTING 6022622-2 R-537 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
5730012 EMP (s)	DETAILED INSPECT AILERON BRUSH SEALS PKG 40 REF: AMM 57-30-07	MOS HRS/MSC AFL	12	+14d/-14d			31-OCT-2019 6654.5 5490		
5740001 EMP (s)	CHECK WITH LEADING EDGE ASSEMBLIES REMOVED. INSPECT FORWARD SIDE OF SPAR 1 FOR EVIDENCE OF FATIGUE CRACKS, OVERHEAT (DISCOLORED PRIMER), GENERAL CORROSION, LOOSE OR MISSING FASTENERS, FILIFORM CORROSION, AND GENERAL CONDITION PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d 6000 +25/-25			27-JUN-2001 0 0		
5740002 EMP (s)	CHECK WITH LEADING EDGE LOWER CUFF FAIRING ASSEMBLIES REMOVED. INSPECT LOWER WING SKIN COVERED BY CUFF FAIRING AND INNER SURFACE OF CUFF FOR EVIDENCE OF FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, CORROSION, AND GENERAL CONDITION PKG 53 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d 6000 +25/-25			27-JUN-2001 0 0		
5750020 EMP (s)	CHECK WITH FLAPS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO FLAP TRAILING EDGE. INSPECT INBOARD AND OUTBOARD FLAP TRACKS AND NOSE ROLLER SUPPORT STRUCTURE FOR CRACKS, DISTORTION, FASTENER CONDITION, EVIDENCE OF CHAFING OR INTERFERENCE, AND GENERAL SECURITY PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d 1200 +25/-25			31-OCT-2019 6654.5 5490		
5750030 EMP (s)	INSPECT FLAP NOSE ROLLER BUSHINGS. REPLACE FLAP NOSE ROLLER IF WORN TO A DIAMETER LESS THAN 0.744 INCH. REPLACE FLAP NOSE ROLLER TRACK IF SLOT EXCEEDS 0.775 INCH AT ANY POINT WITH FLAPS FULLY EXTENDED. ENSURE THAT A POSITIVE CLEARANCE EXISTS BETWEEN NOSE ROLLERS AND AFT END OF NOSE ROLLER TRACKS (2 EACH SIDE) PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d 1200 +25/-25			31-OCT-2019 6654.5 5490		
5750047-001 EMP (s)	VISUALLY INSPECT LEFT FLAP PER WORK CARD INSTRUCTIONS PKG 48 REF: GENERIC NO REF	MOS HRS/MSC AFL	3000	+25/-25			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5750047-002 EMP (s)	VISUALLY INSPECT RIGHT FLAP PER WORK CARD INSTRUCTIONS PKG 48	MOS					PKG	27-JUN-2001	
EMP LJ	REF:	AFL	3000	+25/-25			0	0	
5750050 EMP (s)	INSPECT FLAP UPPER AND LOWER SURFACES FOR SKIN CRACKS, LOOSE RIVETS, AND OTHER DAMAGE. CHECK NOSE ROLLERS FOR FREEDOM OF ROTATION. PAY PARTICULAR ATTENTION TO NOSE ROLLER SUPPORT STRUCTURE FOR CRACKS PKG 41	MOS	36	+14d/-14d			PKG	31-OCT-2019	
	REF: GENERIC NO REF	AFL	600	+25/-25			6654.5	5490	
5760010 EMP (s)	INSPECT AILERON PER WORK CARD INSTRUCTIONS PKG 52	MOS					PKG	27-JUN-2001	
	REF: GENERIC NO REF	AFL	12000	+25/-25			0	0	
CHAPTER 71 POWER PLANT									
7110021-001 EMP	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS						27-JUN-2001	
EMP LJ	REF: GENERIC NO REF	AFL	O/C				0	0	
7110021-002 EMP	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS						27-JUN-2001	
EMP LJ	REF: GENERIC NO REF	AFL	O/C				0	0	
7110022-001 EMP	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIREWALL)	MOS						27-JUN-2001	
EMP LJ	REF: GENERIC NO REF	AFL	O/C				0	0	
7110022-002 EMP	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIREWALL)	MOS						27-JUN-2001	
EMP LJ	REF: GENERIC NO REF	AFL	O/C				0	0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711005	LEFT ENGINE INLET COWL 282-0211-505 592 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			13-AUG-2008 3030 1851		
711006	RIGHT ENGINE INLET COWL 282-02-11-507 603 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-OCT-2016 5658.5 4503		
711011	LEFT ENGINE UPPER ACCESS COWL 266-0212-511 592 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711012	RIGHT ENGINE UPPER ACCESS COWL 266-0212-521 593 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711013	LEFT ENGINE LOWER ACCESS COWL 266-0211-533 592 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711014	RIGHT ENGINE LOWER ACCESS COWL 266-0211-535 593 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711015	LEFT ENGINE PYLON APRON ASSEMBLY 6080001-009 592 REF: AMM 71-10-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711016	RIGHT ENGINE PYLON APRON ASSEMBLY 6080001-010 593 REF: AMM 71-10-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711021	LEFT ENGINE OUTER FAN DUCT 266-0075-517 CFND0166 REF: AMM 71-10-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711022	RIGHT ENGINE OUTER FAN DUCT 266-0075-519 CFNR0164 REF: AMM 71-10-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711023	LEFT ENGINE LEFT FORWARD CORE COWL 266-0261-501 592 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711024	RIGHT ENGINE LEFT FORWARD CORE COWL 266-0261-501 593 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711027	LEFT ENGINE UPPER AFT CORE COWL 266-0263-511 592 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711028	RIGHT ENGINE UPPER AFT CORE COWL 266-0263-511 593 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711029	LEFT ENGINE LOWER AFT CORE COWL 266-0263-509 592 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
711030	RIGHT ENGINE LOWER AFT CORE COWL 266-0263-509 593 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120048 EMP	LEFT * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-98C, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 71-20-05	AFL		N:0			0		
7120048 EMP	REPLACE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC	20000				0	20000	
LIFE LIMIT	REF: AMM 71-20-05	AFL					0		
7120048 EMP	RIGHT * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-98C, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 71-20-05	AFL		N:0			0		
7120049 EMP	LEFT * AFT ENGINE ATTACH BOLTS (NAS6206-36, 77458-6H18, AND S700B1092-6-24)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 71-20-10	AFL		N:0			0		
7120049 EMP	REPLACE * AFT ENGINE ATTACH BOLTS (NAS6206-36, 77458-6H18, AND S700B1092-6-24) (AWL*)								
		MOS					27-JUN-2001		
		HRS/MSC	20000				0	20000	
LIFE LIMIT	REF: AMM 71-20-10	AFL					0		
7120049 EMP	RIGHT * AFT ENGINE ATTACH BOLTS (NAS6206-36, 77458-6H18, AND S700B1092-6-24) (AWL*)								
	PN	MOS		N:0			27-JUN-2001		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 71-20-10	AFL		N:0			0		
712005	LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR								
	266D0820-501	MOS		N:0			27-JUN-2001		
	LK0880	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-20-05	AFL		N:0			0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120051 EMP (s)	PERFORM FLUORESCENT PENETRANT INSPECTION FORWARD ENGINE BEAM INTERMEDIATE FITTING PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-01	AFL					0	0	
7120052 EMP (s)	FLUORESCENT PENETRANT INSPECT FORWARD ENGINE MOUNT YOKE PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-02	AFL					0	0	
7120053 EMP (s)	PERFORM FLUORESCENT PENETRANT INSPECTION BOLT/FORWARD INTERMEDIATE FITTING TO FORWARD BEAM SUPPORT FITTING PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-03	AFL					0	0	
7120054 EMP (s)	FLUORESCENT PENETRANT INSPECT BOLT/FORWARD YOKE TO INTERMEDIATE FITTING PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-04	AFL					0	0	
7120055 EMP (s)	PERFORM FLUORESCENT PENETRANT INSPECTION BOLT/FORWARD YOKE TO ISOLATOR PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-05	AFL					0	0	
7120056 EMP (s)	FLUORESCENT PENETRANT INSPECT BOLT/FORWARD ENGINE ISOLATOR TO ENGINE CASE PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-06	AFL					0	0	
7120057 EMP (s)	PERFORM FLUORESCENT PENETRANT INSPECTION FORWARD ENGINE ISOLATOR PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-07	AFL					0	0	
7120058 EMP (s)	FLUORESCENT PENETRANT INSPECT AFT ENGINE ISOLATORS PKG 52	MOS	12000	+25/-25			PKG	27-JUN-2001	
	REF: NDT 71-20-08	AFL					0	0	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120059 EMP (s)	PERFORM FLUORESCENT PENETRANT INSPECTION AFT MOUNT LINKS PKG 52 REF: NDT 71-20-09	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
712006	RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-505 LK0921 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
7120060 EMP (s)	FLUORESCENT PENETRANT INSPECT BOLT/AFT ISOLATOR TO SUPPORT FITTING PKG 52 REF: NDT 71-20-10	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
7120061 EMP (s)	PERFORM FLUORESCENT PENETRANT INSPECTION BOLT/AFT ISOLATOR TO MOUNT LINKS PKG 52 REF: NDT 71-20-11	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
7120062 EMP (s)	FLUORESCENT PENETRANT INSPECT BOLT/MOUNT LINKS TO ENGINE CASE PKG 52 REF: NDT 71-20-12	MOS HRS/MSC AFL	12000	+25/-25			PKG 27-JUN-2001 0 0		
7120068L EMP	INSPECTION CHECK OF FORWARD AND AFT ENGINE MOUNT ISOLATORS AND ASSOCIATED PARTS REF: See Workcard	MOS HRS/MSC AFL	3850				20-AUG-2017 5951.6 4793	9801.6	
7120068R EMP	INSPECTION/CHECK FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS REF: See Workcard	MOS HRS/MSC AFL	3850				20-AUG-2017 5951.6 4793	9801.6	
712007	LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-505 LK0914 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712008	RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-501 LK0872 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
712009	LEFT ENGINE FORWARD MOUNT YOKE 266-0803-503 SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C						
712010	RIGHT ENGINE FORWARD MOUNT YOKE 266-0803-503 SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C						
712011	LEFT ENGINE AFT VIBRATION ISOLATOR 266D0820-503 LK0788 REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
712012	RIGHT ENGINE AFT VIBRATION ISOLATOR 266D0820-503 LK0779 REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
712015	LEFT ENGINE LOWER AFT MOUNT LINK 266-0807-505 SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C						
712016	RIGHT ENGINE LOWER AFT MOUNT LINK 266-0807-505 SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C						
71EN1 71.EN1	NO. 1 ENGINE 31B4067-04 PCE-CA0307 REF: See Workcard	MOS HRS/MSC AFL	E/C	N:5900.1			20-AUG-2017 5651.6 4793		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN2	NO. 2 ENGINE 31B4067-04 PCE-CA0308 REF: See Workcard	MOS HRS/MSC AFL	E/C	N:5904.2			20-AUG-2017 5951.6 4793		
7614000 EMP (s)	PERFORM FUNCTIONAL TEST OF APR (AUTOMATIC PERFORMANCE RESERVE) SYSTEM PKG 41 REF: AMM 76-14-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			31-OCT-2019 6654.5 5490		
M7120068B	INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS REF: See Workcard	MOS HRS/MSC AFL	3600	+25/-25			20-AUG-2017 5951.6 4793	9551.6	9576.6
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04									
05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION REF: GENERIC NO REF	MOS HRS/MSC ENC	3850	+50			27-DEC-2009 3548.7 2286	(7398.7) 7450.2	7448.7
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS REF: GENERIC NO REF	MOS HRS/MSC ENC	1200	+25/-25			31-OCT-2019 6603 5443	(7803) 7854.5	7828
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR REF: GENERIC NO REF	MOS HRS/MSC ENC	600	+25/-25			31-OCT-2019 6603 5443	(7203) 7254.5	7228

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID 31B4197-05 ARK0883T REF: EMM 75-30-02	MOS HRS/MSC ENC	1500	+300/-300			05-APR-2019 6380.5 5258	(7880.5) 7932	8180.5
05-P&W-710020	NO. 1 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR REF: GENERIC NO REF	MOS HRS/MSC ENC	3850	+50			28-DEC-2009 3548.7 2286	(7398.7) 7450.2	7448.7
710000	NO. 1 ENGINE - COMPRESSOR WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	A/R				20-AUG-2017 5900.1 4746		
710050	NO. 1 ENGINE - RUN ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-MAR-2020 6723 5567		
715020	NO. 1 ENGINE - ENGINE WIRE HARNESS 30B3089-02 AA20604A REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C		R:0 R:0 R:0		12-MAY-2006 2361.2 1330		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION REF: GENERIC NO REF	MOS HRS/MSC ENC	3850	+50			27-DEC-2009 3501.3 2240	(7351.3) 7398.7	7401.3

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS REF: GENERIC NO REF	MOS HRS/MSC ENC	1200	+25/-25			31-OCT-2019 6607.1 5444	(7807.1) 7854.5	7832.1
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR REF: GENERIC NO REF	MOS HRS/MSC ENC	600	+25/-25			31-OCT-2019 6607.1 5444	(7207.1) 7254.5	7232.1
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID 31B4197-05 ARK0094T REF: EMM 75-30-02	MOS HRS/MSC ENC	1500	+300/-300			05-APR-2019 6384.5 5259	(7884.5) 7931.9	8184.5
05-P&W-710020	NO. 2 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR REF: GENERIC NO REF	MOS HRS/MSC ENC	3850	+50			28-DEC-2009 3501.3 2240	(7351.3) 7398.7	7401.3
710000	NO. 2 ENGINE - COMPRESSOR WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	A/R				20-AUG-2017 5904.2 4747		
710050	NO. 2 ENGINE - RUN ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				31-MAR-2020 6727.1 5568		
715020	NO. 2 ENGINE - ENGINE WIRE HARNESS 30B3089-02 AA22568A REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C		R:0 R:0 R:0		12-MAY-2006 2361.2 1330		
715025	NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR 30B3088-02 0139 REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C		O:0 O:0 O:0		12-MAY-2006 2361.2 1330		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 72	ENGINE								
72CUS1	NO. 1 ENGINE OIL SAMPLE	MOS	6				31-MAR-2020	30-SEP-2020	
	REF:	HRS/MSC AFL					6774.5 5614		
72CUS2	NO. 2 ENGINE OIL SAMPLE	MOS	6				31-MAR-2020	30-SEP-2020	
	REF:	HRS/MSC AFL					6774.5 5614		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04									
72000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION	MOS	180	+12m			20-AUG-2017	20-AUG-2032	20-AUG-2033
	REF: EMM 72-00-00	HRS/MSC ENC					5900.1 4746		
723001	NO. 1 ENGINE - FAN HUB	MOS					17-MAY-2001		
	30B2256	HRS/MSC			N:0		0		
	A000NKNR	ENC	12000		N:0		0	(12000) 12047	
LIFE LIMIT	REF: EMM 72-30-01								
723002	NO. 1 ENGINE - FAN CASE ASSEMBLY	MOS					26-JUL-2017		
	31B5237-01	HRS/MSC	O/C		R:0		5900.1		
	4K774	ENC			R:0		4746		
	REF: EMM 72-30-01								
723003	NO. 1 ENGINE - CENTRIFUGAL IMPELLER	MOS					17-MAY-2001		
	30B4565-01	HRS/MSC			N:0		0		
	A000RPKO	ENC	7000		N:0		0	(7000) 7047	
LIFE LIMIT	REF: EMM 72-30-01								
723005	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR	MOS					19-MAR-2011		
	30B6551-01	HRS/MSC			N:0		3850.3		
	TXA1C3372	ENC	12000		N:0		2532	(14532) 14579	
LIFE LIMIT	REF: EMM 72-30-01								

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723005A	NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR) 30B6551-01 TXA1C3372	MOS HRS/MSC	N/A				19-MAR-2011 3850.3		
NOT APPLICABLE	REF: EMM 72-00-00	ENC					2532		
723008	NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B4745-01 43B561	MOS HRS/MSC					17-MAY-2001 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8500				0	(8500) 8547	
725101	NO. 1 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A004MATK	MOS HRS/MSC					20-AUG-2017 5900.1		
LIFE LIMIT	REF: EMM 72-50-01	ENC	3100				4746	(7847) 7894	
725102	NO. 1 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A003YXC4	MOS HRS/MSC					20-AUG-2017 5900.1		
LIFE LIMIT	REF: EMM 72-50-01	ENC	3300				4746	(8047) 8094	
725103	NO. 1 ENGINE - STAGE 3 TURBINE DISC 30A1833 59B570	MOS HRS/MSC					17-MAY-2001 0		
LIFE LIMIT	REF: EMM 72-50-01	ENC	10000				0	(10000) 10047	
725104	NO. 1 ENGINE - STAGE 4 TURBINE DISC 30A1834 68B816	MOS HRS/MSC					17-MAY-2001 0		
LIFE LIMIT	REF: EMM 72-50-01	ENC	10000				0	(10000) 10047	
725105	NO. 1 ENGINE - STAGE 5 TURBINE DISC 30A1835 59B955	MOS HRS/MSC					17-MAY-2001 0		
LIFE LIMIT	REF: EMM 72-50-01	ENC	10000				0	(10000) 10047	
725107	NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A0040BTF	MOS HRS/MSC					20-AUG-2017 5900.1		
LIFE LIMIT	REF: EMM 72-50-01	ENC	4800				4746	(9546) 9593	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725109	NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B26726-01 A003WEB1	MOS HRS/MSC					11-AUG-2017 5900.1		
LIFE LIMIT	REF: EMM 72-50-01	ENC	4400	N:0			4746	(9146) 9193	
725111	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 AWE013388	MOS HRS/MSC					27-DEC-2009 3548.7		
LIFE LIMIT	REF: EMM 72-50-01	ENC	4000	N:0			2286	(6287) 6334	
+ 726011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)	MOS HRS/MSC	7700	+50			17-MAY-2001 0	(7700) 7751.5	7750
	REF: GENERIC NO REF	ENC					0		
727001	NO. 1 ENGINE - COMBUSTION CHAMBER LINER 30B2704 SN-UNKNOWN	MOS HRS/MSC	O/C						
	REF: EMM 72-40-01	ENC							
+ 727001A	NO. 1 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER 30B2704 SN-UNKNOWN	MOS HRS/MSC	3850	+50			27-DEC-2009 3548.7	(7398.7) 7450.2	7448.7
	REF: EMM 72-40-01	ENC					2286		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION	MOS	180				20-AUG-2017	20-AUG-2032	
	REF: EMM 72-00-00	HRS/MSC ENC					5904.2 4747		
723001	NO. 2 ENGINE - FAN HUB 30B2256 A000PM3B	MOS HRS/MSC					18-MAY-2001 0		
LIFE LIMIT	REF: EMM 72-30-01	ENC	12000	N:0			0	(12000) 12046	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723002	NO. 2 ENGINE - FAN CASE ASSEMBLY 31B5237-01 9H042 REF: EMM 72-30-01	MOS HRS/MSC ENC	O/C	R:0 R:0 R:0			26-JUL-2017 5904.2 4747		
723003	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 30B4565-01 A000RPHX REF: EMM 72-30-01	MOS HRS/MSC ENC	7000	N:0 N:0 N:0			18-MAY-2001 0 0	(7000) 7046	
723005	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B6531-01 TXA1B1512 REF: EMM 72-30-01	MOS HRS/MSC ENC	12000	N:67 N:1727.9 N:1530			21-NOV-2012 4383.1 3035	(13505) 13551	
723005A	NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR) 30B6531-01 TXA1B1512 REF: EMM 72-00-00	MOS HRS/MSC ENC	300	+25			21-OCT-2019 6608.1 5444	(6908.1) 6955.5	6933.1
723008	NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B4745-01 43B564 REF: GENERIC NO REF	MOS HRS/MSC ENC	8500	N:0 N:0 N:0			18-MAY-2001 0 0	(8500) 8546	
725101	NO. 2 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A003X1D9 REF: EMM 72-50-01	MOS HRS/MSC ENC	3100	N:0			20-AUG-2017 5904.2 4747	(7848) 7894	
725102	NO. 2 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A003XWE2 REF: EMM 72-50-01	MOS HRS/MSC ENC	3300	N:0			20-AUG-2017 5904.2 4747	(8048) 8094	
725103	NO. 2 ENGINE - STAGE 3 TURBINE DISC 30A1833 59B572 REF: EMM 72-50-01	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			18-MAY-2001 0 0	(10000) 10046	

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725104	NO. 2 ENGINE - STAGE 4 TURBINE DISC 30A1834 68B821	MOS HRS/MSC		N:0 N:0			18-MAY-2001 0		
LIFE LIMIT	REF: EMM 72-50-01	ENC	10000	N:0			0	(10000) 10046	
725105	NO. 2 ENGINE - STAGE 5 TURBINE DISC 30A1835 59B951	MOS HRS/MSC		N:0 N:0			18-MAY-2001 0		
LIFE LIMIT	REF: EMM 72-50-01	ENC	10000	N:0			0	(10000) 10046	
725107	NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A003WF8Y	MOS HRS/MSC					20-AUG-2017 5904.2		
LIFE LIMIT	REF: EMM 72-50-01	ENC	4800	N:0			4747	(9547) 9593	
725109	NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B6726-01 A0040BTM	MOS HRS/MSC		N:0			11-AUG-2017 5904.2		
LIFE LIMIT	REF: EMM 72-50-01	ENC	4400	N:0			4747	(9147) 9193	
725111	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 AWE013273	MOS HRS/MSC		N:0 N:0			27-DEC-2009 3501.3		
LIFE LIMIT	REF: EMM 72-50-01	ENC	4000	N:0			2240	(6241) 6287	
+ 726011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)	MOS					18-MAY-2001		
		HRS/MSC	7700	+50			0	(7700) 7747.4	7750
	REF: GENERIC NO REF	ENC					0		
+ 727001A	NO. 2 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER 30B2704 SN-UNKNOWN	MOS HRS/MSC					27-DEC-2009 3501.3		
	REF: EMM 72-40-01	ENC	3850	+50			2240	(7351.3) 7398.7	7401.3

CHAPTER 73 ENGINE FUEL AND CONTROL

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733101	LEFT ENGINE FUEL FLOW TRANSMITTER 7600021-1 607780 REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C				13-MAR-2020 6770 5610		
733102	RIGHT ENGINE FUEL FLOW TRANSMITTER 7600021-1 614050 REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	N:115 N:119			13-MAR-2020 6770 5610		
733103	LEFT ENGINE FUEL FLOW INDICATOR 6608488-001 3825 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			24-FEB-2012 4163.6 2799		
733104	RIGHT ENGINE FUEL FLOW INDICATOR 6608488-001 3610 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-DEC-2005 2144.4 1197		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04									
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT REF: EMM 73-10-03	MOS HRS/MSC ENC	12 1200	+25/-25			31-MAR-2020 6723 5567	31-MAR-2021 (7923) 7974.5	7948
+ 05-P&W-730005	NO. 1 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE REF: EMM 73-10-04	MOS HRS/MSC ENC	1800	+600/-600			05-APR-2019 6380.5 5258	(8180.5) 8232	8780.5
731004	NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE 31B5832-04 1XR13374 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			04-APR-2019 6380.5 5258		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005	NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE 31B5832-04 1UL03147 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			04-APR-2019 6380.5 5258		
+ 731012	NO. 1 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP 30B1910 SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
OVERHAUL									
+ 731013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 30B1669 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 731014	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY REF: EMM 73-10-04	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
OVERHAUL									
+ 731022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY) 32448701-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 731023	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK 31B5132-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 731024	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY REF: EMM 73-10-04	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
OVERHAUL									
+ 731025	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE 26240-5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7200) 7251.5	M 7250

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731044	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - INLET	MOS					17-MAY-2001		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	7700	+50			0 0	(7700) 7751.5	7750
+ 731045	NO. 1 ENGINE - DISCARD - FUEL SHUT-OFF CABLE	MOS					17-MAY-2001		
DISCARD	REF: EMM 73-10-05	HRS/MSC ENC	7700	+50			0 0	(7700) 7751.5	7750
+ 731055	NO. 1 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF	MOS					17-MAY-2001		
OVERHAUL	REF: EMM 73-10-05	HRS/MSC ENC	7700	+50			0 0	(7700) 7751.5	7750
732001	NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL	MOS					17-MAY-2001		
	31B4469-06	HRS/MSC	O/C				0		
	1891668	ENC					0		
	REF: EMM 73-20-01								
+ 732002	NO. 1 ENGINE - REPLACE TRIM PLUG	MOS	120				17-MAY-2001		
	PKG 0	HRS/MSC					0	05-APR-2021 M	
	REF: EMM 73-20-02	ENC					0	(6980.5) 7032 M	
732005	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC	MOS					(EBT)		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	ENC		N:0					
	REF: EMM 73-20-02			N:0					
+ 732011	NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU	MOS					17-MAY-2001		
	31B4469-06	HRS/MSC	7700	+50			0	(7700) 7751.5	7750
	1891668	ENC					0		
	REF: GENERIC NO REF								
+ 732012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC	MOS					17-MAY-2001		
	PN	HRS/MSC	7700	+50			0	(7700) 7751.5	7750
	SN-UNKNOWN	ENC					0		
	REF: GENERIC NO REF								

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 732013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR) 30B3089-02 AA20604A REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 732021	NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 31B4469-06 1891668 REF: EMM 73-20-01	MOS HRS/MSC ENC	N/A				17-MAY-2001 0 0		
732101	NO. 1 ENGINE - ENGINE FADEC 822821-6-004 01080264 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:52 N:229 N:143			26-OCT-2005 2055.5 1160		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
05-P&W-730001	NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT MOS HRS/MSC ENC REF: EMM 73-10-03	12 1200		+25/-25			31-MAR-2020 6727.1 5568	31-MAR-2021 (7927.1) 7974.5	7952.1
+ 05-P&W-730005	NO. 2 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE MOS HRS/MSC ENC REF: EMM 73-10-04	1800		+600/-600			05-APR-2019 6384.5 5259	(8184.5) 8231.9	8784.5
731001	NO. 2 ENGINE - FUEL PUMP PF4-038-11C MX641666A REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C				18-MAY-2001 0 0		
731002	NO. 2 ENGINE - MOTIVE FLOW VALVE 3244870-1 C37400 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C				18-MAY-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731003	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH 30B1669 0734 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C				18-MAY-2001 0 0		
731004	NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE 31B5832-04 1TP04890 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			04-APR-2019 6384.5 5259		
731005	NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE 31B5832-04 1NS11182 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			04-APR-2019 6384.5 5259		
+ 731012	NO. 2 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP PF4-038-11C MX641666A REF: EMM 73-10-02	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
OVERHAUL									
+ 731013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 30B1669 0734 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 731014	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY REF: EMM 73-10-04	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
OVERHAUL									
+ 731022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY) 3244870-1 C37400 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 731023	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK 26100-8 0998 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731024	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY	MOS					18-MAY-2001		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
+ 731025	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE	MOS					18-MAY-2001		
	26240-5 0759 REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
731026	NO. 2 ENGINE - FUEL WASTE EJECTOR	MOS					18-MAY-2001		
	26100-8 0998 REF: EMM 73-10-03	HRS/MSC ENC	O/C				0 0		
+ 731044	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - INLET	MOS					18-MAY-2001		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
+ 731045	NO. 2 ENGINE - DISCARD - FUEL SHUT-OFF CABLE	MOS					18-MAY-2001		
DISCARD	REF: EMM 73-10-05	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
731051	NO. 2 ENGINE - FUEL START & DUMP VALVE	MOS					18-MAY-2001		
	26240-5 0759 REF: EMM 73-10-05	HRS/MSC ENC	O/C				0 0		
+ 731055	NO. 2 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF	MOS					18-MAY-2001		
OVERHAUL	REF: EMM 73-10-05	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
732001	NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL	MOS					18-MAY-2001		
	31B4469-06 1891673 REF: EMM 73-20-01	HRS/MSC ENC	O/C				0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 732002	NO. 2 ENGINE - REPLACE TRIM PLUG PKG 0 REF: EMM 73-20-02	MOS HRS/MSC ENC	120				18-MAY-2001 0 0	05-APR-2021 M (6984.5) 7031.9 M	
732005	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN SN-UNKNOWN REF: EMM 73-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			(EBT)		
+ 732011	NO. 2 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU 31B4469-06 1891673 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 732012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 732013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR) 30B3089-02 AA22568A REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 732021	NO. 2 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 31B4469-06 1891673 REF: EMM 73-20-01	MOS HRS/MSC ENC	N/A				18-MAY-2001 0 0		
732101	NO. 2 ENGINE - ENGINE FADEC 822821-6-004 01080265 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:229 N:143			26-OCT-2005 2055.5 1160		

CHAPTER 74 IGNITION

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
743002	NO. 2 ENGINE WARNING LIGHT BOX 6018314-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
743003	ENGINE WARNING LIGHT BOX 6018314-005 MRP334533-01 REF: AMM 74-30-03	MOS HRS/MSC AFL	O/C	R:0 R:0			20-JUN-2011 3964.5 2630		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04									
741001	NO. 1 ENGINE - NO. 1 IGNITION EXCITER 30B1619 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C						
741002	NO. 1 ENGINE - NO. 2 IGNITION EXCITER 31B4636-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C						
741003	NO. 1 ENGINE - NO. 1 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			(EBT)		
741004	NO. 1 ENGINE - NO. 2 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			(EBT)		
+ 741011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX 30B1619 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 741012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX 31B4636-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 741021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 741022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 741031	NO. 1 ENGINE - REPLACE - NO. 1 IGNITER PLUGS 31B5168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 741032	NO. 1 ENGINE - REPLACE - NO. 2 IGNITER PLUGS 31B5168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
742025	NO. 1 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				11-MAR-2016 5432.7		
742026	NO. 1 ENGINE - NO. 2 IGNITER PLUG 31B5168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				11-MAR-2016 5432.7		

ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741001	NO. 2 ENGINE - NO. 1 IGNITION EXCITER 9047980-21 NN01159586 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				18-MAY-2001 0 0		
741002	NO. 2 ENGINE - NO. 2 IGNITION EXCITER 9047980-21 NN92080340 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			02-AUG-2006 2500.2 1400		
741003	NO. 2 ENGINE - NO. 1 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			(EBT)		
741004	NO. 2 ENGINE - NO. 2 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			(EBT)		
+ 741011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX 9047980-21 NN01159586 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 741012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX 9047980-21 NN92080340 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 741021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 741022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 741031	NO. 2 ENGINE - REPLACE - NO. 1 IGNITER PLUGS 31B3168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
REPLACE									
+ 741032	NO. 2 ENGINE - REPLACE - NO. 2 IGNITER PLUGS 31B3168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
REPLACE									
742025	NO. 2 ENGINE - NO. 1 IGNITER PLUG 31B3168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				11-MAR-2016 5436.8		
742026	NO. 2 ENGINE - NO. 2 IGNITER PLUG 31B3168-01 N/A REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				11-MAR-2016 5436.8		
CHAPTER 75 AIR									
ENGINE NO. 1	Model : PW305A	Serial # PCE-CA0307	Part # 31B4067-04						
+ 751011	NO. 1 ENGINE - OVERHAUL - ANTI-ICING VALVE 31B5108-01 SN-UNKNOWN REF: EMM 75-10-01	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
OVERHAUL									
+ 753001	NO. 1 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES REF: EMM 75-30-01	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
OVERHAUL									
+ 753002	NO. 1 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
DISCARD									

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER	MOS					17-MAY-2001		
	REF: GENERIC NO REF	HRS/MSC	7700	+50			0	(7700) 7751.5	7750
		ENC					0		
+ 753012	NO. 1 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID	MOS					17-MAY-2001		
DISCARD	REF: EMM 75-30-02	HRS/MSC	N/A				0		
		ENC					0		
+ 753014	NO. 1 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR	MOS					17-MAY-2001		
DISCARD	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		ENC					0		
+ 753024	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR	MOS					17-MAY-2001		
	REF: GENERIC NO REF	HRS/MSC	7700	+50			0	(7700) 7751.5	7750
		ENC					0		
753081	NO. 1 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID	MOS					03-OCT-2014		
	31B4197-05	HRS/MSC	O/C	O:0			4971.5		
	ARK0883T	ENC		O:0			3711		
	REF: EMM 75-30-02			O:0					
753082	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT	MOS					(EBT)		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	ENC		N:0					
	REF: GENERIC NO REF			N:0					
753083	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE	MOS					(EBT)		
	PN	HRS/MSC	N/A						
	SN-UNKNOWN	ENC							
	REF: EMM 75-30-02								
753101	NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE	MOS					11-AUG-2017		
	31B5759-01-X	HRS/MSC	3850	+50			5900.1	(9750.1) 9801.6	9800.1
	GF000951	ENC					4746		
REPLACE	REF: EMM 75-30-01								

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753102	NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01-X GF000987	MOS HRS/MSC	3850	+50	O:0 O:0		11-AUG-2017 5900.1	(9750.1) 9801.6	9800.1
REPLACE	REF: EMM 75-30-01	ENC			O:0		4746		
753105	NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01-X AHX000302	MOS HRS/MSC	3850	+50	O:0 O:0		11-AUG-2017 5900.1	(9750.1) 9801.6	9800.1
REPLACE	REF: EMM 75-30-01	ENC			O:0		4746		
+ 753111	NO. 1 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01-X GF000951	MOS HRS/MSC	N/A				11-AUG-2017 5900.1		
	REF: See Workcard	ENC					4746		
+ 753112	NO. 1 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01-X GF000987	MOS HRS/MSC	N/A				11-AUG-2017 5900.1		
	REF: See Workcard	ENC					4746		
+ 753115	NO. 1 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE 31B5756-01-X AHX000302	MOS HRS/MSC	N/A				11-AUG-2017 5900.1		
	REF: See Workcard	ENC					4746		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
751001	NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-04 AL1100	MOS HRS/MSC	O/C				18-MAY-2001 0		
	REF: EMM 75-10-01	ENC					0		
+ 751011	NO. 2 ENGINE - OVERHAUL - ANTI-ICING VALVE 31B5108-04 AL1100	MOS HRS/MSC	7700	+50			18-MAY-2001 0	(7700) 7747.4	7750
OVERHAUL	REF: EMM 75-10-01	ENC					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753001	NO. 2 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES	MOS					18-MAY-2001		
OVERHAUL	REF: EMM 75-30-01	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
+ 753002	NO. 2 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID	MOS					18-MAY-2001		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
+ 753003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER	MOS					18-MAY-2001		
	REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
+ 753012	NO. 2 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID	MOS					18-MAY-2001		
DISCARD	REF: EMM 75-30-02	HRS/MSC ENC	N/A				0 0		
+ 753014	NO. 2 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR	MOS					18-MAY-2001		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	N/A				0 0		
+ 753024	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR	MOS					18-MAY-2001		
	REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7747.4	7750
753081	NO. 2 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID	MOS					03-OCT-2014		
	31B4197-05	HRS/MSC			O:0		4975.6		
	ARK0094T	ENC	O/C		O:0		3712		
	REF: EMM 75-30-02				O:0				
753082	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT	MOS					(EBT)		
	PN	HRS/MSC	O/C		N:0				
	SN-UNKNOWN	ENC			N:0				
	REF: GENERIC NO REF				N:0				

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753083	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	N/A				(EBT)		
753101	NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01-X 21A654 REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50	O:0 O:0 O:0		11-AUG-2017 5904.2 4747	(9754.2) 9801.6	9804.2
REPLACE									
753102	NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01-X GF000601 REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50	O:0 O:0 O:0		11-AUG-2017 5904.2 4747	(9754.2) 9801.6	9804.2
REPLACE									
753105	NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5759-01-X GF000918 REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50	O:0 O:0 O:0		11-AUG-2017 5904.2 4747	(9754.2) 9801.6	9804.2
REPLACE									
+ 753111	NO. 2 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01-X 21A654 REF: See Workcard	MOS HRS/MSC ENC	N/A				11-AUG-2017 5904.2 4747		
+ 753112	NO. 2 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01-X GF000601 REF: See Workcard	MOS HRS/MSC ENC	N/A				11-AUG-2017 5904.2 4747		
+ 753115	NO. 2 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE 31B5759-01-X GF000918 REF: See Workcard	MOS HRS/MSC ENC	N/A				11-AUG-2017 5904.2 4747		

CHAPTER 76	ENGINE CONTROLS
ENGINE NO. 1	Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760010 (s)	NO. 1 ENGINE - DOWNLOAD ENGINE FADEC DATA PKG 35	DAYS	30				PKG 30-MAR-2020		
CUSTOMER CODE	REF:	ENC							
761101	NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS 6008016-027 098 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
761103	NO. 1 ENGINE - FADEC, ENGINE HARNESS 6008016-029 092 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
761105	NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS 6008408-033 122 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
761107	NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS 6008408-037 116 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
760010 (s)	NO. 2 ENGINE - DOWNLOAD ENGINE FADEC DATA PKG 35	DAYS	30				PKG 30-MAR-2020		
CUSTOMER CODE	REF:	ENC							
761101	NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNESS 6008016-028 097 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761103	NO. 2 ENGINE - FADEC, ENGINE HARNESS 6008016-030 112 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
761105	NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS 6008408-038 043 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
761107	NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS 6008408-032 129 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
CHAPTER 77 ENGINE INDICATING									
771001	LEFT ENGINE N1 INDICATOR 6608496-001 5790L REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			02-OCT-2013 4671.3 3380		
771002	RIGHT ENGINE N1 INDICATOR 6608496-001 5238 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2008 3136.9 1928		
771003	LEFT ENGINE N2 INDICATOR 6608508-001 1194 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-DEC-2009 3549.6 2287		
771004	RIGHT ENGINE N2 INDICATOR 6608508-001 4854L REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-JUN-2014 4947.7 3666		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772001	LEFT ENGINE ITT INDICATOR 6608505-001 5318 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
772002	RIGHT ENGINE ITT INDICATOR 6608505-001 8208 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-FEB-2007 2633.5 1489		
774001	ENGINE DIAGNOSTIC UNIT 9-361-06 F-139 REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C				20-AUG-2017 5951.6 4793		
774001A	REPLACE ENGINE DIAGNOSTIC UNIT INTERNAL BATTERY 9-361-06 F-139 REF:	MOS HRS/MSC AFL	36				30-JUL-2019 6591.1 5448	30-JUL-2022	
774002	CONTROL AND DISPLAY (CDU) UNIT 9-362-03 C107 REF: AMM 77-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
774003	LEFT ENGINE ISOLATION INTERFACE UNIT 9-343-04 C210 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
774004	RIGHT ENGINE ISOLATION INTERFACE UNIT 9-343-04 C211 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
774101	SIGNAL CONDITIONING BOX 6600504-5 0324 REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774103	LEFT ENGINE VIBRATION ACCELEROMETER 6600504-2 UNK-3327 REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
774104	RIGHT ENGINE VIBRATION ACCELEROMETER 6600504-2 0868 REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04									
+ 771001	NO. 1 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS DISCARD	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 771011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS REF: EMM 77-10-01	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 771021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 771022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR 30B1449F SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
771027	NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR 30B6150-06 CH2911 REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	O:0 O:0 O:0		08-JUL-2010 3733.5 2444	(7583.5) 7635	7633.5

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771028	NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR 30B6152-06 CH3309 REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	O:0 O:0 O:0		08-JUL-2010 3733.5 2444	(7583.5) 7635	7633.5
772011	NO. 1 ENGINE - T4.5/T6/T1 TERMINAL BOX 31B4793-01 NR001371 REF:	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		11-MAY-2009 3344 2103		
+ 772013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS 31B3876-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 772021	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX REF: EMM 77-20-01	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 772022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
+ 771001	NO. 2 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
DISCARD									
+ 771011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS REF: EMM 77-10-01	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 771021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 771022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
771027	NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	O:0 O:0 O:0		08-JUL-2010 3686.1 2398	(7536.1) 7583.5	7586.1
771028	NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	O:0 O:0 O:0		08-JUL-2010 3686.1 2398	(7536.1) 7583.5	7586.1
771041	NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				18-MAY-2001 0 0		
+ 772013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 772021	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX REF: EMM 77-20-01	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 772022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 78	EXHAUST								
780001	LEFT THRUST REVERSER								
	282-0052-515	MOS		N:0			27-JUN-2001		
	592	HRS/MSC	O/C	N:0			0		
	REF: AMM 78-30-00	AFL		N:0			0		
780002	RIGHT THRUST REVERSER								
	282-0052-517	MOS		N:0			27-JUN-2001		
	593	HRS/MSC	O/C	N:0			0		
	REF: AMM 78-30-00	AFL		N:0			0		
783001	LEFT THRUST REVERSER RELAY BOX								
	6018425-017	MOS							
	SN-UNKNOWN	HRS/MSC	O/C						
	REF: AMM 78-30-01	AFL							
7830010L EMP (s)	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION						PKG		
	PKG 29	MOS					20-AUG-2017		
		HRS/MSC	3850				5951.6		
	REF: GENERIC NO REF	AFL					4793		
7830010R EMP (s)	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION						PKG		
	PKG 30	MOS					20-AUG-2017		
		HRS/MSC	3850				5951.6		
	REF: GENERIC NO REF	AFL					4793		
7830012L EMP (s)	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE						PKG		
	PKG 29	MOS					20-AUG-2017		
		HRS/MSC	3850				5951.6		
	REF: GENERIC NO REF	AFL					4793		
7830012R EMP (s)	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE						PKG		
	PKG 30	MOS					20-AUG-2017		
		HRS/MSC	3850				5951.6		
	REF: GENERIC NO REF	AFL					4793		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783002	RIGHT THRUST REVERSER RELAY BOX 6018425-017 SN-UNKNOWN REF: AMM 78-30-01	MOS HRS/MSC AFL	O/C						
7830022 EMP (s)	PERFORM FUNCTIONAL TEST OF THRUST REVERSER HYDRAULIC CONTROL VALVE ASSEMBLY CHECK VALVES PKG 53 REF: AMM 78-30-03	MOS HRS/MSC AFL	144	+14d/-14d			PKG 27-JUN-2001 0 0		
7830038 EMP (s)	PERFORM DETAILED INSPECTION OF FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY PKG 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
7830046-002 EMP (s)	REPLACE RIGHT THRUST REVERSER * RIGHT THRUST REVERSER CARRIAGE ASSEMBLY OVER-CENTER LINK BOLTS (NAS6307U15D) (AWL*) 282-0052-517 593 REF: AMM 78-30-20	MOS HRS/MSC AFL	400				27-JUN-2001 0 0		
783005	LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-507 0322 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			10-JAN-2019 6378.3 5243		
783006	RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-507 0570 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C				16-DEC-2018 6375 5237		
7830084 EMP (s)	LUBRICATE THRUST REVERSER SECONDARY LATCH SWITCH PLUNGER, ROLLER ASSEMBLY, AND ACTUATOR PINS PKG 40 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7830085 EMP (s)	FUNCTIONAL TEST ** OF THE THRUST REVERSER WITH WHEEL SPEED DETECT INTERFACE (AWL**) PKG 42 REF: AMM 78-30-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 31-OCT-2019 6654.5 5490		
783009	THRUST REVERSER INTERFACE BOX 6018003-001 BAS5002435-01Q REF: AMM 78-30-07	MOS HRS/MSC AFL	O/C				18-OCT-2007 2773.7 1622		
783105	LEFT OUTBOARD THRUST REVERSER ACTUATOR 71334 0072 REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			30-DEC-2005 2144.4 1197		
783106	LEFT INBOARD THRUST REVERSER ACTUATOR 71334 0672R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C				12-MAR-2009 3267.6 2041		
783107	RIGHT INBOARD THRUST REVERSER ACTUATOR 282D0006-501 1016R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
783108	RIGHT OUTBOARD THRUST REVERSER ACTUATOR 282D0006-501 1009R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
783115	LEFT UPPER SECONDARY LOCK ACTUATOR 266D0486-507 1215 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
783116	RIGHT UPPER SECONDARY LOCK ACTUATOR 266D0486-507 1212 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783117	LEFT LOWER SECONDARY LOCK ACTUATOR 266D0486-507 1214 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
783118	RIGHT LOWER SECONDARY LOCK ACTUATOR 266D0486-507 1218 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
783132	LEFT OUTBOARD STANG FAIRING ASSEMBLY PN SN-UNKNOWN REF: AMM 78-30-15	MOS HRS/MSC AFL APH ACH	O/C	N:0 N:0 N:0 N:0 N:0			27-JUN-2001 0 0 0 0		
783132A	RE-INSPECT LEFT OUTBOARD STANG FAIRING ASSEMBLY IAW THRUST REVERSER SRM 54-30-00 PAGE 104 PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	-				29-JUL-2011 3974.1 2643		
U7830010A	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION REF:	MOS HRS/MSC AFL	3600	+50			20-AUG-2017 5951.6 4793	9551.6	9601.6
U7830010B	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION REF:	MOS HRS/MSC AFL	3600	+50			20-AUG-2017 5951.6 4793	9551.6	9601.6
U7830012A	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE REF:	MOS HRS/MSC AFL	3600	+50			20-AUG-2017 5951.6 4793	9551.6	9601.6



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U7830012B	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE	MOS					20-AUG-2017		
		HRS/MSC	3600	+50			5951.6	9551.6	9601.6
	REF: GENERIC NO REF	AFL					4793		
CHAPTER 79 OIL									
793001	LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR								
	6608499-001	MOS					27-JUN-2001		
	4697	HRS/MSC	O/C				0		
	REF: AMM 79-30-01	AFL					0		
793002	RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR								
	6608499-001	MOS					27-JUN-2001		
	4698	HRS/MSC	O/C				0		
	REF: AMM 79-30-01	AFL					0		
793003	LEFT ENGINE OIL PRESSURE TRANSDUCER								
	7600019-1	MOS					27-JUN-2001		
	6576-9A-94	HRS/MSC	O/C				0		
	REF: AMM 79-30-02	AFL					0		
793004	RIGHT ENGINE OIL PRESSURE TRANSDUCER								
	7600019-1	MOS					27-JUN-2001		
	6576-9A-84	HRS/MSC	O/C				0		
	REF: AMM 79-30-02	AFL					0		
793010	LEFT ENGINE OIL TEMPERATURE BULB								
	MS28034-3	MOS					27-JUN-2001		
	E7166	HRS/MSC	O/C				0		
	REF: AMM 79-30-03	AFL					0		
793011	RIGHT ENGINE OIL TEMPERATURE BULB								
	MS28034-3	MOS					27-JUN-2001		
	E7163	HRS/MSC	O/C				0		
	REF: AMM 79-30-03	AFL					0		

ENGINE NO. 1 Model : PW305A Serial # PCE-CA0307 Part # 31B4067-04

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT REF: EMM 79-20-01	MOS HRS/MSC ENC	12 1200	+25/-25			31-MAR-2020 6723 5567	31-MAR-2021 (7923) 7974.5	7948
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE REF: EMM 72-00-00	MOS HRS/MSC ENC	12 600	+50/-50			31-MAR-2020 6723 5567	31-MAR-2021 (7323) 7374.5	7373
792001	NO. 1 ENGINE - OIL PUMP 31B6167-01 40A217 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		27-JUN-2001 0 0		
792002	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER 31B5790-02 SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C				13-MAR-2009 3265.6 2041		
+ 792011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 792012	NO. 1 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER 31B5790-02 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
792035	NO. 1 ENGINE - OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		(EBT)		
+ 793001	NO. 1 ENGINE - DISCARD - CHIP DETECTOR DISCARD REF: EMM 79-30-01	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793002	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH REF: EMM 79-30-02	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
+ 793003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP REF: EMM 79-30-03	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
793005	NO. 1 ENGINE - CHIP DETECTOR 30B3756-02 SN-UNKNOWN REF: EMM 79-30-01	MOS HRS/MSC ENC	O/C						
REPLACE									
+ 793013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			17-MAY-2001 0 0	(7700) 7751.5	7750
793030	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: EMM 79-30-03	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		(EBT)		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0308 Part # 31B4067-04									
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT REF: EMM 79-20-01	MOS HRS/MSC ENC	12 1200	+25/-25			31-MAR-2020 6727.1 5568	31-MAR-2021 (7927.1) 7974.5	7952.1
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE REF: EMM 72-00-00	MOS HRS/MSC ENC	12 600	+50/-50			31-MAR-2020 6727.1 5568	31-MAR-2021 (7327.1) 7374.5	7377.1

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792001	NO. 2 ENGINE - OIL PUMP 31B6167-01 40A220 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			27-JUN-2001 0 0		
792002	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER 31B5790-02 0540 REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			13-MAR-2009 3218.7 1995		
792005	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH 30B1506 1700 REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C				18-MAY-2001 0 0		
+ 792011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 792012	NO. 2 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER 31B5790-02 0540 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
792035	NO. 2 ENGINE - OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			(EBT)		
+ 793001	NO. 2 ENGINE - DISCARD - CHIP DETECTOR REF: EMM 79-30-01	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750
+ 793002	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH REF: EMM 79-30-02	MOS HRS/MSC ENC	7700	+50			18-MAY-2001 0 0	(7700) 7747.4	7750

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP	MOS					18-MAY-2001		
	REF: EMM 79-30-03	HRS/MSC	7700	+50			0	(7700) 7747.4	7750
		ENC					0		
793005	NO. 2 ENGINE - CHIP DETECTOR	MOS					15-OCT-2018		
	30B3756-02	HRS/MSC	O/C	N:0			6238.6		
	SN-UNKNOWN	ENC		N:0			5090		
REPLACE	REF: EMM 79-30-01			N:0					
+ 793013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)	MOS					18-MAY-2001		
	PN	HRS/MSC	7700	+50			0	(7700) 7747.4	7750
	SN-UNKNOWN	ENC					0		
	REF: GENERIC NO REF								
793030	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR	MOS					(EBT)		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	ENC		N:0					
	REF: EMM 79-30-03			N:0					
CHAPTER 80	STARTING								
801001	CROSS START RELAY BOX	MOS					02-APR-2018		
	6018421-1	HRS/MSC	O/C	R:0			6168.7		
	710095	AFL		R:0			5017		
	REF: AMM 80-10-01								
801002	AIR START RELAY BOX	MOS					02-APR-2018		
	6018358-2	HRS/MSC	O/C	R:0			6168.7		
	A00774242-01	AFL		R:0			5017		
	REF: AMM 80-10-02								
801115	NO. 1 START RELAY	MOS					27-FEB-2017		
	SM400D62	HRS/MSC	O/C	N:119			5768.6		
	SN-UNKNOWN	AFL		N:3103.4			4621		
	REF:			N:3104					



Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
801116	NO. 2 START RELAY SM400D62 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:119 N:3103.4 N:3104			27-FEB-2017 5768.6 4621		
CHAPTER 85 FUEL CELL SYSTEMS									
850001	NO. 1 SPARE STARTER GENERATOR 400SG159Q 1552 REF:	MOS HRS/MSC AFL	O/C						
850002	NO. 2 SPARE STARTER GENERATOR 400SG138Q-2 1552 REF:	MOS HRS/MSC AFL	O/C						
850003	NO. 3 SPARE STARTER GENERATOR 400SG138Q 3696 REF:	MOS HRS/MSC AFL	O/C						
850010	PERFORM SCAN OF LOG BOOK PAGES AND SUBMIT TO CAMP FOR UPDATE CUSTOMER CODE REF:	DAYS HRS/MSC AFL	90				24-FEB-2020 6753.8 5595	24-MAY-2020	
CHAPTER 99 OPTIONAL KITS									
9900010 EMP (s)	PERFORM ENGINE ZONAL INSPECTION PKG 44 REF: EMP 9900010	MOS HRS/MSC AFL	36	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
9900011 EMP (s)	PERFORM EXTERIOR AIRCRAFT ZONAL INSPECTION PKG 44 REF: EMP 9900011	MOS HRS/MSC AFL	36	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
9900012 EMP (s)	PERFORM LANDING GEAR ZONAL INSPECTION PKG 44 REF: EMP 9900012	MOS HRS/MSC AFL	36	+14d/-14d			PKG 31-OCT-2019 6654.5 5490		
9900013 EMP (s)	PERFORM AFT FUSELAGE ZONAL INSPECTION PKG 45 REF: EMP 9900013	MOS HRS/MSC AFL	72	+14d/-14d			PKG 27-JUN-2001 0 0		
9900014 EMP (s)	PERFORM NOSE ZONAL INSPECTION PKG 45 REF: EMP 9900014	MOS HRS/MSC AFL	72	+14d/-14d			PKG 27-JUN-2001 0 0		
9900015 EMP (s)	PERFORM WING ZONAL INSPECTION PKG 45 REF: EMP 9900015	MOS HRS/MSC AFL	72	+14d/-14d			PKG 27-JUN-2001 0 0		
9900016 EMP (s)	PERFORM COCKPIT ZONAL INSPECTION PKG 46 REF: EMP 9900016	MOS HRS/MSC AFL	108	+14d/-14d			PKG 27-JUN-2001 0 0		
9900017 EMP (s)	PERFORM FUSELAGE ZONAL INSPECTION PKG 46 REF: EMP 9900017	MOS HRS/MSC AFL	108	+14d/-14d			PKG 27-JUN-2001 0 0		
9900032 EMP	PERFORM HEAT DAMAGE INSPECTION REF: EMP 9900032	MOS HRS/MSC AFL	A/R				27-JUN-2001 0 0		
UNSCHEDULED MAINTENANCE CHECK									

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
9900039 EMP	PERFORM HARD LANDING OR DEPARTURE FROM RUNWAY	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900039	HRS/MSC	A/R				0		
		AFL					0		
9900040 EMP	PERFORM OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900040	HRS/MSC	A/R				0		
		AFL					0		
9900041 EMP	PERFORM SEVERE TURBULENCE AND/OR MANEUVERS	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900041	HRS/MSC	A/R				0		
		AFL					0		
9900042 EMP (s)	PERFORM NO. 1 ENGINE UNSCHEDULED ENGINE CHANGE/REMOVAL VISUAL INSPECTIONS. PKG 29	MOS					PKG		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900042	HRS/MSC	A/R				20-AUG-2017		
		AFL					5951.6		
							4793		
9900042 EMP (s)	PERFORM NO. 2 ENGINE UNSCHEDULED ENGINE CHANGE/REMOVAL VISUAL INSPECTIONS. PKG 30	MOS					PKG		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900042	HRS/MSC	A/R				20-AUG-2017		
		AFL					5951.6		
							4793		
9900043 EMP	PERFORM HIGH ENERGY STOP (LANDING AND REJECTED TAKEOFF)	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900043	HRS/MSC	A/R				0		
		AFL					0		
9900044 EMP	PERFORM THRUST REVERSER	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900044	HRS/MSC	A/R				0		
		AFL					0		

Status Report

LEARJET 60 (EMP) S/N 60 232 (N211BD): 6774.5 HRS, 5614 AFL as of 31-Mar-2020

Owner: KONFARA COMPANY, LLC Operator: DISCOUNT TIRE FLIGHT DEPARTMENT

Report Date: 02-APR-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
9900045 EMP	PERFORM OVERSPEED RECOVERY LANDING GEAR INSPECTION (LANDING GEAR EXTENSION AND RETRACTION AT HIGH SPEED)	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900045	HRS/MSC AFL	A/R				0 0		
9900046 EMP	PERFORM LIGHTNING STRIKE INSPECTION	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900046	HRS/MSC AFL	A/R				0 0		
9900047 EMP	PERFORM HIGH GROUND WIND GUST INSPECTION	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900047	HRS/MSC AFL	A/R				0 0		
9900048 EMP	PERFORM PRESSURE CABIN SKIN THICKNESS MEASUREMENTS	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900048	HRS/MSC AFL	A/R				0 0		
9900050 EMP	PERFORM VOLCANIC ASH CONTAMINATION INSPECTION AND MAINTENANCE PROCEDURES	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900050	HRS/MSC AFL	A/R				0 0		
9900051 EMP	PERFORM FLAP OVERSPEED INSPECTION AND REPAIR	MOS					27-JUN-2001		
UNSCHEDULED MAINTENANCE CHECK	REF: EMP 9900051	HRS/MSC AFL	A/R				0 0		