



Aircraft Maintenance Compliance Report

N80AR

Log Date - 05-Jun-2009

Current TT 8870.4
 Current Lndgs 7611
 Current Hr Mtr 8870.4

Phone: 303-745-5588 FAX: 303-745-1507

Aircraft Make Learjet

Aircraft Model 35A

Aircraft Serial No. 35-454

Airworthiness Date 06-Nov-1981

FAR Operation 135

COMPONENT TIMES

<i>Position</i>	<i>Logbook</i>	<i>Description</i>	<i>Serial Number</i>	<i>Total Time</i>	<i>Total Cycles</i>	<i>TSO</i>	<i>CSO</i>
1	Engine	Honeywell TFE731-2-2B	P-89248	8691.2	6981	4582.4	3926
2	Engine	Honeywell TFE731-2-2B	P-89247	8606.2	6931	4555.0	3830

Due Flag Indicates Items Due Within
 100 Hrs or 50 Cyc/Lnd or 30 Days

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
05 -- INSPECTION REQUIREMENT										
051010			Complete Phase A Inspection			MM-99	300 Hrs	8780.4	9105.4 Hrs	235.0 Hrs
*	Airframe	MAN			2	12/12/2008		7561		
	Mfg#: N/A		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				12 MOS	6/16/2008	06/16/2009	-21 Days
051020			Complete Phase B Inspection			MM-99	600 Hrs	8792.9	9392.9 Hrs	522.5 Hrs
	Airframe	MAN			2	12/12/2008		7569		
	Mfg#: N/A		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				24 MOS	8/13/2008	08/13/2010	13 Mos
051030			Complete Phase C Inspection			MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Airframe	MAN			2	12/12/2008		7569		
	Mfg#: N/A		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				48 MOS	8/13/2008	08/13/2012	37 Mos
051040			Complete Phase D Inspection			MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			2	12/12/2008		7607		
	Mfg#: N/A		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				96 MOS	3/12/2009	03/12/2017	92 Mos
051048			3000 Landing Inspection			MM-99		0.0		
	Airframe	MAN			2	12/12/2008	3000 Cyc/Lnd	6027	9027 Cyc/Lnd	1416 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.] [25 Cycle Window]					1/16/2004		
051050			Major Landing Gear Inspection			MM-99		0.0		
	Airframe	MAN			2	12/12/2008	6000 Cyc/Lnd	6027	12027 Cyc/Ln	4416 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.] [25 Cycle Window]					1/16/2004		
051055			12 Year Airframe Inspection			MM-99		0.0		
	Airframe	MAN			2	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/15/2017	95 Mos
051061			12000/6000 Hour Airframe Inspection			MM-99	12000**/6000 Hr	0.0	12000.0 Hrs	3129.6 Hrs
	Airframe	MAN			2	12/12/2008		0		
	Mfg#: N/A		Notes: [12000 Initial Hour Req.] [Initial Date Req.] [25 Hour Window]					11/6/1981		
08 -- LEVELING AND WEIGHING										
080005			Weigh Aircraft & Update Flight Manual Weight/Balance Information			PSP 601-2		0.0		
*	Airframe	MAN			2	12/10/1999		0		
	Mfg#: 08-20-00-001		Notes: [Initial Date Req.] [End of Month Item]				36 MOS	11/16/2005	11/30/2008	-8 Mos

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
12 -- SERVICING										
122201.3*			No.1 Main Battery Capacity Test	G-6381ES		Q01-1100	400 Hrs	8867.0	9267.0 Hrs	396.6 Hrs
Airframe		MAN		G02344701	15	8/9/2004		7607		
			Notes: New Batteries From Aviall [800 Initial Hour Req.] [11 MOS Initial Req.] [Initial Date Req.] [1 MOS Window]				6 MOS	3/12/2009	09/12/2009	67 Days
122201.4*			No.2 Main Battery Capacity Test	G-6381ES		Q01-1100	400 Hrs	8867.0	9267.0 Hrs	396.6 Hrs
Airframe		MAN		G02840791	15	8/9/2004		7607		
			Notes: New Batteries From Aviall [800 Initial Hour Req.] [11 MOS Initial Req.] [Initial Date Req.] [1 MOS Window]				6 MOS	3/12/2009	09/12/2009	67 Days
12-23-000			Ni-Cad Emergency Power Supply Battery Inspection			MM-99	100 Hrs	8868.0	8968.0 Hrs	97.6 Hrs
*	Airframe	MAN			3	12/12/2008		7609		
	Mfg#: D1223000		Notes: Inspection c/w no defects [Initial Date Req.] [25 Hour Window] [14 DAY Window]				3 MOS	5/2/2009	07/23/2009*	16 Days
12-23-001			Ni-Cad Emergency Power Battery Discharge/Recharge			T/R 5-161		0.0		
*	Airframe	MAN			3	2/9/2009		0		
	Mfg#: D1223001		Notes: [Initial Date Req.] [14 DAY Window]				12 MOS	11/6/1981	11/06/1982	-27 Yrs
21 -- AIR CONDITIONING										
21-30-007			Perform Cabin Leak Rate Check			MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
Airframe		MAN			3	12/12/2008		7569		
	Mfg#: H2130007		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (* =Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
24 -- ELECTRICAL POWER										
24-31-015.1			Left Bendix Generator Overhaul	6608201		MM-99	2000 Hrs	7413.4	9413.4 Hrs	543.0 Hrs
Airframe	MAN				3	12/12/2008		0		
Mfg#: C2431015			Notes: [Initial Date Req.] [25 Hour Window]					11/22/2004		
24-31-015.2			Right Bendix Generator Overhaul	6608201		MM-99	2000 Hrs	7336.4	9336.4 Hrs	466.0 Hrs
Airframe	MAN				3	12/12/2008		0		
Mfg#: C2431015			Notes: [Initial Date Req.] [25 Hour Window]					10/18/2004		
24-31-016.1			Left Bendix Generator Bearing Replacement			MM-99	1050 Hrs	8439.2	9513.4 Hrs	643.0 Hrs
Airframe	MAN				4	12/12/2008		7312		
Mfg#: C2431016			Notes: [Initial Date Req.] [25 Hour Window]					4/13/2007		
24-31-016.2			Right Bendix Generator Bearing Replacement			MM-99	1050 Hrs	8439.2	9489.2 Hrs	618.8 Hrs
Airframe	MAN				4	12/12/2008		7312		
Mfg#: C2431016			Notes: [Initial Date Req.] [25 Hour Window]					4/13/2007		
24-31-017			Battery Cables & Receptacles Connector Inspection			MM-99	300 Hrs	8687.4	8987.4 Hrs	117.0 Hrs
Airframe	MAN				4	12/12/2008		7495		
Mfg#: H2431017			Notes: [Initial Date Req.] [25 Hour Window]					1/2/2008		
24-31-030.3			LH Generator Drive Spline Inspect/Lube			MM-99	1400 Hrs	8792.9	10192.9 Hrs	1322.5 Hrs
Airframe	MAN				5	12/12/2008		7569		
Mfg#: E2431030			Notes: [Initial Date Req.] [100 Hour Window]					8/13/2008		
24-31-030.4			RH Generator Drive Spline Inspect/Lube			MM-99	1400 Hrs	8780.4	10180.4 Hrs	1310.0 Hrs
Airframe	MAN				5	12/12/2008		7561		
Mfg#: E2431030			Notes: [Initial Date Req.] [100 Hour Window]					6/16/2008		
24-31-045			Right Essential A&B Bus (40 Amp) Breakers Replacement			MM-99		0.0		
Airframe	MAN				2	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
Mfg#: G2431045			Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/15/2017	95 Mos
24-31-047			Left Essential A&B Bus (40 Amp) Breakers Replacement			MM-99		0.0		
Airframe	MAN				2	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
Mfg#: G2431047			Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/15/2017	95 Mos
24-31-049			Main Bus Tie (50 Amp) Circuit Breaker Replacement			MM-99		0.0		
Airframe	MAN				2	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
Mfg#: G2431049			Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/15/2017	95 Mos
24-32-010			Battery Installation Inspection			MM-99		8867.0		
Airframe	MAN				13	12/12/2008		7607		
Mfg#: B2432010			Notes: [Initial Date Req.] [14 DAY Window]				6 MOS	3/12/2009	09/12/2009	67 Days

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
25 -- EQUIP/FURNISHINGS										
25-62-001			Drag Chute Function Test (if Installed)			MM-99		8867.0		
*	Airframe	MAN			13	12/12/2008		7607		
	Mfg#: E2562001		Notes: [Initial Date Req.] [14 DAY Window]				6 MOS	1/23/2009	07/23/2009	16 Days
25-63-001			ELT Functional Test & Battery Inspection			MM-99		8867.0		
	Airframe	MAN			4	12/12/2008		7607		
	Mfg#: J2563001		Notes: [Initial Date Req.] [End of Month Item]				12 MOS	3/12/2009	03/31/2010	8 Mos
25-64-001			Emergency Locator Transmitter Battery Replacement			MM-99		8713.1		
	Airframe	MAN			2	12/12/2008		7512		
	Mfg#: E2564001		Notes: [Initial Date Req.]					2/8/2008	01/31/2010	6 Mos
25-65-000			CVR/FDR Underwater Locator Beacon Operation Check			MM-99		8713.1		
	Airframe	MAN			4	12/12/2008		7512		
	Mfg#: F2565000		Notes: [Initial Date Req.] [14 DAY Window]				24 MOS	2/8/2008	01/31/2010*	6 Mos
25-66-000			Cockpit Voice Recorder ULB Battery Replacement			MM-99		0.0		
	Airframe	MAN			2	12/12/2008		0		
	Mfg#: F256600		Notes: [Initial Date Req.]					2/25/2004	03/25/2010	8 Mos
259001*			Life Vests Visual Inspection					8780.4		
*	Airframe	MAN						7561		
			Notes: C/W Life Vest inspection [Initial Date Req.] [End of Month Item]				12 MOS	6/16/2008	06/30/2009	-7 Days
259002*			Life Vests Recertification / Replacement					0.0		
	Airframe	MAN						0		
			Notes: [Initial Date Req.] [End of Month Item]				60 MOS	3/12/2007	03/31/2012	32 Mos
26 -- FIRE PROTECTION										
26-20-010.1			Engine Fire Extinguisher LH Container Weight Check			MM-99		600 Hrs	8791.9	9391.9 Hrs
	Airframe	MAN			13	12/12/2008		7567		
	Mfg#: Q2620010		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				24 MOS	8/4/2008	08/04/2010	13 Mos
26-20-010.2			Engine Fire Extinguisher RH Container Weight Check			MM-99		600 Hrs	8791.9	9391.9 Hrs
	Airframe	MAN			13	12/12/2008		7567		
	Mfg#: Q2620010		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				24 MOS	8/4/2008	08/04/2010	13 Mos
26-20-025.1			Engine Fire Extinguisher Left Container Hydrostatic Test			MM-99		0.0		
	Airframe	MAN			13	12/12/2008		0		
	Mfg#: Q2620025		Notes: [Initial Date Req.] [End of Month Item]				60 MOS	2/11/2005	02/28/2010	7 Mos
26-20-025.2			Engine Fire Extinguisher Right Container Hydrostatic Test			MM-99		0.0		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining	
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal	
	Airframe	MAN				13	12/12/2008	0			
	Mfg#: Q2620025		Notes: [Initial Date Req.] [End of Month Item]					60 MOS	2/11/2005	02/28/2010	7 Mos
26-20-030.1			Cockpit Fire Extinguisher Hydrostatic Test				MM-99	0.0			
	Airframe	MAN			1	12/12/2008		0			
	Mfg#: C2620030		Notes: [Initial Date Req.] [14 DAY Window]					144 MOS	6/6/2005	06/15/2017	95 Mos
26-20-030.2			Cabin Fire Extinguisher Hydrostatic Test				MM-99	0.0			
	Airframe	MAN			1	12/12/2008		0			
	Mfg#: C2620030		Notes: [Initial Date Req.] [14 DAY Window]					144 MOS	6/6/2005	06/15/2017	95 Mos
26-20-040.1			Left Bottle Left Eng Cartridge Service Life Rplcmt (HTL)				MM-99	8780.4			
	Airframe	MAN			9	12/12/2008		7561			
	Mfg#: N2620040		Notes: R&R Squib Lot # ESD 07G220-001 [Initial Date Req.] [End of Month Item]					72 MOS	6/16/2008	06/30/2014	59 Mos
26-20-040.2			Left Bottle Right Eng Cartridge Service Life Rplcmt (HTL)				MM-99	8780.4			
	Airframe	MAN			9	12/12/2008		7561			
	Mfg#: N2620040		Notes: R&R Squib p/n 13083-5, Lot ESD 07G220-001 [Initial Date Req.] [End of Month Item]					72 MOS	6/16/2008	06/30/2014	59 Mos
26-20-040.3			Right Bottle Left Eng Cartridge Service Life Rplcmt (HTL)				MM-99	8780.4			
	Airframe	MAN			9	12/12/2008		7561			
	Mfg#: N2620040		Notes: 13083-5 [Initial Date Req.] [End of Month Item]					72 MOS	6/16/2008	06/30/2014	59 Mos
26-20-040.4			Right Bottle Right Eng Cartridge Service Life Rplcmt (HTL)				MM-99	8780.4			
	Airframe	MAN			9	12/12/2008		7561			
	Mfg#: N2620040		Notes: 13083-5 [Initial Date Req.] [End of Month Item]					72 MOS	6/16/2008	06/30/2014	59 Mos
26-20-040.5			Left Bottle Left Eng Cartridge Life Limit (HTL)				MM-99	0.0			
	Airframe	MAN			9	12/12/2008		0			
	Mfg#: N2620040		Notes: Please verify date of Mfg. [Initial Date Req.] [End of Month Item]					72 MOS	3/31/2004	03/31/2010	8 Mos
26-20-040.6			Left Bottle Right Eng Cartridge Life Limit (HTL)				MM-99	0.0			
	Airframe	MAN			9	12/12/2008		0			
	Mfg#: N2620040		Notes: Please verify date of Mfg. [Initial Date Req.] [End of Month Item]					72 MOS	3/31/2004	03/31/2010	8 Mos
26-20-040.7			Right Bottle Left Eng Cartridge Life Limit (HTL)				MM-99	0.0			
	Airframe	MAN			9	12/12/2008		0			
	Mfg#: N2620040		Notes: Please verify date of Mfg. [Initial Date Req.] [End of Month Item]					72 MOS	3/31/2004	03/31/2010	8 Mos
26-20-040.8			Right Bottle Right Eng Cartridge Life Limit (HTL)				MM-99	0.0			
	Airframe	MAN			9	12/12/2008		0			
	Mfg#: N2620040		Notes: Please verify date of Mfg. [Initial Date Req.] [End of Month Item]					72 MOS	3/31/2004	03/31/2010	8 Mos
26-20-042.1			LH Engine Fire Extinguisher Pressure/Plumbing Inspection				MM-99	8867.0			
*	Airframe	MAN			10	12/12/2008		7607			
	Mfg#: P2620042		Notes: [Initial Date Req.] [14 DAY Window]					6 MOS	1/23/2009	07/23/2009	16 Days

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
26-20-042.2			RH Engine Fire Extinguisher Pressure/Plumbing Inspection			MM-99		8867.0		
*	Airframe	MAN			11	12/12/2008		7607		
	Mfg#: P2620042		Notes: [Initial Date Req.] [14 DAY Window]				6 MOS	1/23/2009	07/23/2009	16 Days
269001*			Cabin & Cockpit Portable Fire Extinguishers Weight Check					8791.9		
	Airframe	MAN						7567		
			Notes: [Initial Date Req.] [End of Month Item]				12 MOS	8/4/2008	08/31/2009	55 Days
27 -- FLIGHT CONTROLS										
27-10-009.1			Aileron Center Sector Control Cable Life Limit	2300003-17		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.2			LH Aileron Outboard Wing Control Cable Life Limit	2300003-16		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.3			RH Aileron Outboard Wing Control Cable Life Limit	2300003-16		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.4			LH Aileron Inboard Wing Control Cable Life Limit	2300003-78		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.5			RH Aileron Inboard Wing Control Cable Life Limit	2300003-77, -272		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.6			Aileron LH Fuselage Control Cable Life Limit	2300003-245		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.7			Aileron RH Fuselage Control Cable Life Limit	2300003-246		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.8			Aileron Control Wheel LH Interconnect Cable Life Limit	2300003-231		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		
	Mfg#: F2710009		Notes: [Initial Date Req.]					3/25/2004		
27-10-009.9			Aileron Control Wheel RH Interconnect Cable Life Limit	2300003-229		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN			9	12/12/2008		0		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
Mfg#: F2710009			Notes: [Initial Date Req.]					3/25/2004		
27-10-010.1	LH Aileron Drive Yoke Bolt Life Limit	NAS1104-38D	MM-99	3600 Hrs	5780.5	9380.5 Hrs	510.1 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: E2710010			Notes: [Initial Date Req.]					12/20/1997		
27-10-010.2	RH Aileron Drive Yoke Bolt Life Limit	NAS1104-38D	MM-99	3600 Hrs	5780.5	9380.5 Hrs	510.1 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: E2710010			Notes: [Initial Date Req.]					12/20/1997		
27-10-014.1	LH Aileron Center Hinge Bolt Life Limit	AN4H13A	MM-99	3600 Hrs	5780.5	9380.5 Hrs	510.1 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: E2710014			Notes: [Initial Date Req.]					12/20/1997		
27-10-014.2	RH Aileron Center Hinge Bolt Life Limit	AN4H13A	MM-99	3600 Hrs	5780.5	9380.5 Hrs	510.1 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: E2710014			Notes: [Initial Date Req.]					12/20/1997		
27-10-016.1	LH Aileron Assembly Life Limit	2392011-7	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: G2710016			Notes: [Initial Date Req.]					11/6/1981		
27-10-016.2	RH Aileron Assembly Life Limit	2392011-8	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: G2710016			Notes: [Initial Date Req.]					11/6/1981		
27-10-020.1	LH Aileron Clevis Bolt Life Limit	NAS464P4	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: E2710020			Notes: [Initial Date Req.]					11/6/1981		
27-10-020.2	RH Aileron Clevis Bolt Life Limit	NAS464P4	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			9	12/12/2008		0			
Mfg#: E2710020			Notes: [Initial Date Req.]					11/6/1981		
27-10-021.1	LH Aileron Inboard Hinge Bolt Life Limit	AN4H12A	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			10	12/12/2008		0			
Mfg#: M2710021			Notes: [Initial Date Req.]					11/6/1981		
27-10-021.2	LH Aileron Outboard Hinge Bolt Life Limit	AN4H12A	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			10	12/12/2008		0			
Mfg#: M2710021			Notes: [Initial Date Req.]					11/6/1981		
27-10-021.3	RH Aileron Inboard Hinge Bolt Life Limit	AN4H12A	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			10	12/12/2008		0			
Mfg#: M2710021			Notes: [Initial Date Req.]					11/6/1981		
27-10-021.4	RH Aileron Outboard Hinge Bolt Life Limit	AN4H12A	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			10	12/12/2008		0			
Mfg#: M2710021			Notes: [Initial Date Req.]					11/6/1981		
27-10-023.1	LH Aileron Pulley Assembly Life Limit	2324513-17	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs			
Airframe	MAN			10	12/12/2008		0			

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (*=Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
Mfg#: E2710023			Notes: [Initial Date Req.]				11/6/1981			
27-10-023.2			RH Aileron Pulley Assembly Life Limit	2324513-18		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710023			Notes: [Initial Date Req.]				11/6/1981			
27-10-025.1			LH Aileron Clevis Life Limit	2324511 or 2324517-3		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710025			Notes: [Initial Date Req.]				11/6/1981			
27-10-025.2			RH Aileron Clevis Life Limit	2324511 or 2324517-3		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710025			Notes: [Initial Date Req.]				11/6/1981			
27-10-027.1			LH Aileron Yoke Assembly Life Limit	2324511-5 or 2324518		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710027			Notes: [Initial Date Req.]				11/6/1981			
27-10-027.2			RH Aileron Yoke Assembly Life Limit	2324511-5 or 2324518		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710027			Notes: [Initial Date Req.]				11/6/1981			
27-10-029.1			LH Aileron Bearing Support Assembly Life Limit	2324510 or 2324505		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710029			Notes: [Initial Date Req.]				11/6/1981			
27-10-029.2			RH Aileron Bearing Support Assembly Life Limit	2324510 or 2324505		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710029			Notes: [Initial Date Req.]				11/6/1981			
27-10-031.1			LH Inboard Aileron Hinge Bracket Assembly Life Limit	2322530-81		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710031			Notes: [Initial Date Req.]				11/6/1981			
27-10-031.2			RH Inboard Aileron Hinge Bracket Assembly Life Limit	2322530-82		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710031			Notes: [Initial Date Req.]				11/6/1981			
27-10-031.3			LH Middle Aileron Hinge Bracket Assembly Life Limit	2322530-89		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710031			Notes: [Initial Date Req.]				11/6/1981			
27-10-031.4			RH Middle Aileron Hinge Bracket Assembly Life Limit	2322530-90		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
Mfg#: E2710031			Notes: [Initial Date Req.]				11/6/1981			
27-10-031.5			LH Outboard Aileron Hinge Bracket Assembly Life Limit	2322530-75		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
	Airframe	MAN								
	Mfg#: E2710031		Notes: [Initial Date Req.]					0		
								11/6/1981		
27-10-031.6			RH Outboard Aileron Hinge Bracket Assembly Life Limit	2322530-76		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN								
	Mfg#: E2710031		Notes: [Initial Date Req.]		10	12/12/2008		0		
								11/6/1981		
27-20-012.1			LH Rudder Control System Cable Replacement	2300003-243		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN								
	Mfg#: F2720012		Notes: [Initial Date Req.] [25 Hour Window]		3	12/12/2008		0		
								3/25/2004		
27-20-012.2			RH Rudder Control System Cable Replacement	2300003-243		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN								
	Mfg#: F2720012		Notes: [Initial Date Req.] [25 Hour Window]		3	12/12/2008		0		
								3/25/2004		
27-20-018			Rudder Assembly Life Limit	2633001		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN								
	Mfg#: E2720018		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		
27-20-021			Rudder Hinge Bolts (3) Life Limit	NAS144A23 & AN4H11A		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN								
	Mfg#: E2720021		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		
27-20-023			Rudder Lower Bearing Assembly Life Limit	2312040		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN								
	Mfg#: E2720023		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		
27-20-024			Upper Rudder Hinge Assembly Life Limit	2331030		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN								
	Mfg#: E2720024		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		
27-20-025			Center Rudder Hinge Assembly Life Limit	2331031		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN								
	Mfg#: E2720025		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		
27-21-801			Rudder Trim Tab Actuator	6608217-10 865		MM99 R76		8713.1		
	Airframe	INF						7512		
	Mfg#: 27-21-801		Notes: [Initial Date Req.]					2/8/2008		
27-30-015.1			LH Aft Elevator Control Cable Life Limit	2300003		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN								
	Mfg#: F2730015		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		
27-30-015.2			RH Aft Elevator Control Cable Life Limit	2300003		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN								
	Mfg#: F2730015		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		
27-30-015.3			LH Forward Elevator Control Cable Life Limit	2300003		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN								
	Mfg#: F2730015		Notes: [Initial Date Req.]		3	12/12/2008		0		
								11/6/1981		

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (*=Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
27-30-015.4			RH Forward Elevator Control Cable Life Limit	2300003		MM-99	2400 Hrs	7009.0	9409.0 Hrs	538.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: F2730015		Notes: [Initial Date Req.]					11/6/1981		
27-30-016.1			LH Elevator Assembly Life Limit	2434000		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730016		Notes: [Initial Date Req.]					11/6/1981		
27-30-016.2			RH Elevator Assembly Life Limit	2434000		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730016		Notes: [Initial Date Req.]					11/6/1981		
27-30-020.1			Elevator LH Outboard Hinge Brackets Life Limit	2332013-24		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730020		Notes: [Initial Date Req.]					11/6/1981		
27-30-020.2			Elevator RH Outboard Hinge Brackets Life Limit	2332013-24		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730020		Notes: [Initial Date Req.]					11/6/1981		
27-30-020.3			Elevator LH Center Hinge Brackets Life Limit	2332018-22		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730020		Notes: [Initial Date Req.]					11/6/1981		
27-30-020.4			Elevator RH Center Hinge Brackets Life Limit	2332018-22		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730020		Notes: [Initial Date Req.]					11/6/1981		
27-30-020.5			Elevator LH Inboard Hinge Brackets Life Limit	2332019-		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730020		Notes: [Initial Date Req.]					11/6/1981		
27-30-020.6			Elevator RH Inboard Hinge Brackets Life Limit	2332019-		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730020		Notes: [Initial Date Req.]					11/6/1981		
27-30-021.1			LH Elevator Bellcrank Life Limit	2331511		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730021		Notes: [Initial Date Req.]					11/6/1981		
27-30-021.2			RH Elevator Bellcrank Life Limit	2331511		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730021		Notes: [Initial Date Req.]					11/6/1981		
27-30-023			Elevator Lower Push-Pull Rod Life Limit	2331510-82		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730023		Notes: [Initial Date Req.]					11/6/1981		
27-30-023.1			LH Elevator Push-Pull Rod Life Limit	2331510-34		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN				3	12/12/2008	0		
	Mfg#: E2730023		Notes: [Initial Date Req.]					11/6/1981		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
27-30-023.2			RH Elevator Push-Pull Rod Life Limit	2331510-34		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			3	12/12/2008		0		
	Mfg#: E2730023		Notes: [Initial Date Req.]					11/6/1981		
27-30-024.1			LH Elevator Hinge Bolts Life Limit (2 ea)	(2) AN4H11A		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			3	12/12/2008		0		
	Mfg#: E2730024		Notes: [Initial Date Req.]					11/6/1981		
27-30-024.2			RH Elevator Hinge Bolts Life Limit (2 ea)	(2) AN4H11A		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			3	12/12/2008		0		
	Mfg#: E2730024		Notes: [Initial Date Req.]					11/6/1981		
27-30-027.1			Elevator Downsprung Assembly Attach Bolt Replacement	AN23-16		MM-99		0.0		
	Airframe	MAN			4	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: E2730027		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/15/2017	95 Mos
27-40-010			Horizontal Stabilizer Hinge Pin Life Limit	2331028		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			4	12/12/2008		0		
	Mfg#: E2740010		Notes: [Initial Date Req.]					11/6/1981		
27-40-011.1			Horizontal Stabilizer Actuator Lower Attach Bolt Life Limit	NAS464P6-17		MM-99		0.0		
	Airframe	MAN			4	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2740011		Notes: [Initial Date Req.]				144 MOS	6/6/2005	06/06/2017	95 Mos
27-40-011.2			Horizontal Stabilizer Actuator Upper Attach Bolt Life Limit	NAS464P6-22		MM-99		0.0		
	Airframe	MAN			4	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2740011		Notes: [Initial Date Req.]				144 MOS	6/6/2005	06/06/2017	95 Mos
27-40-021			Horizontal Stabilizer Actuator - Perform Overhaul			MM-99	600 Hrs	8792.9	9392.9 Hrs	522.5 Hrs
	Airframe	MAN			5	12/12/2008		7569		
	Mfg#: Q2740021		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		
27-50-002.1			LH Flap Outboard Nose Roller Bushing Replacement	NAS76A4		MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Airframe	MAN			10	12/12/2008		7569		
	Mfg#: E2750002		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		
27-50-002.2			RH Flap Outboard Nose Roller Bushing Replacement	NAS76A4		MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Airframe	MAN			10	12/12/2008		7569		
	Mfg#: E2750002		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		
27-50-002.3			LH Flap Inboard Nose Roller Bushing Replacement	NAS76A4		MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Airframe	MAN			10	12/12/2008		7569		
	Mfg#: E2750002		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
27-50-002.4			RH Flap Inboard Nose Roller Bushing Replacement	NAS76A4		MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Airframe	MAN			10	12/12/2008		7569		
	Mfg#: E2750002		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		
27-50-015.1			LH Flap Assembly Life Limit	2325010		MM-99	19300 Hrs	0.0	19300.0 Hrs	10429.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: E2750015		Notes: [Initial Date Req.]					11/6/1981		
27-50-015.2			RH Flap Assembly Life Limit	2325010		MM-99	19300 Hrs	0.0	19300.0 Hrs	10429.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: E2750015		Notes: [Initial Date Req.]					11/6/1981		
27-50-017.1			LH Inboard Flap Hinge Fitting Life Limit (on flap)	2625023 - (See Note)		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: F2750017		Notes: [Initial Date Req.]					11/6/1981		
27-50-017.2			RH Inboard Flap Hinge Fitting Life Limit (on flap)	2625023 - (See Note)		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: F2750017		Notes: [Initial Date Req.]					11/6/1981		
27-50-019.1			LH Outboard Flap Hinge Fitting Life Limit (on flap)	2625024 - (See Note)		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: F2750019		Notes: [Initial Date Req.]					11/6/1981		
27-50-019.2			RH Outboard Flap Hinge Fitting Life Limit (on flap)	2625024 - (See Note)		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: F2750019		Notes: [Initial Date Req.]					11/6/1981		
27-50-021.1			LH Inboard Flap Track Assembly Life Limit	2325022-16		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: E2750021		Notes: [Initial Date Req.]					11/6/1981		
27-50-021.2			RH Inboard Flap Track Assembly Life Limit	2325022-16		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: E2750021		Notes: [Initial Date Req.]					11/6/1981		
27-50-021.3			LH Outboard Flap Track Assembly Life Limit	2325022-15		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: E2750021		Notes: [Initial Date Req.]					11/6/1981		
27-50-021.4			RH Outboard Flap Track Assembly Life Limit	2325022-15		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: E2750021		Notes: [Initial Date Req.]					11/6/1981		
27-50-023.1			LH Inboard Nose Roller Track Life Limit (Flap)	2322511-27, or -57		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			10	12/12/2008		0		
	Mfg#: E2750023		Notes: [Initial Date Req.]					11/6/1981		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
27-50-023.2	Airframe	MAN	RH Inboard Nose Roller Track Life Limit (Flap)	2322511-27, or -57		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Mfg#: E2750023		Notes: [Initial Date Req.]		10	12/12/2008		0		
								11/6/1981		
27-50-024.1	Airframe	MAN	LH Outboard Nose Roller Track Life Limit (Flap)	2322512-37		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Mfg#: E2750024		Notes: [Initial Date Req.]		10	12/12/2008		0		
								11/6/1981		
27-50-024.2	Airframe	MAN	RH Outboard Nose Roller Track Life Limit (Flap)	2322512-37		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Mfg#: E2750024		Notes: [Initial Date Req.]		10	12/12/2008		0		
								11/6/1981		
27-50-034.1	Airframe	MAN	LH Wing Flap Sector Mounting Bolt Replacement			MM-99		0.0		
	Mfg#: G2750034		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]		10	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
							144 MOS	6/6/2005	06/15/2017	95 Mos
27-50-034.2	Airframe	MAN	RH Wing Flap Sector Mounting Bolt Replacement			MM-99		0.0		
	Mfg#: G2750034		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]		10	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
							144 MOS	6/6/2005	06/15/2017	95 Mos
27-50-044.1	Airframe	MAN	LH Flap Cam Follower Bearings Inspection			MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Mfg#: H2750044		Notes: [Initial Date Req.] [25 Hour Window]		12	12/12/2008		7569		
								8/13/2008		
27-50-044.2	Airframe	MAN	RH Flap Cam Follower Bearings Inspection			MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Mfg#: H2750044		Notes: [Initial Date Req.] [25 Hour Window]		12	12/12/2008		7569		
								8/13/2008		
27-60-067.1	Airframe	MAN	LH 5/16 in. Spoiler Attach Bolts (2) Life Limit	NAS464P5		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs
	Mfg#: E2760067		Notes: [Initial Date Req.]		11	12/12/2008		0		
								12/18/1992		
27-60-067.2	Airframe	MAN	RH 5/16 in. Spoiler Attach Bolts (2) Life Limit	NAS464P5		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs
	Mfg#: E2760067		Notes: [Initial Date Req.]		11	12/12/2008		0		
								12/18/1992		
27-60-068.1	Airframe	MAN	LH 5/16 in. Spoiler Pivot Bolt Life Limit	NAS464P5		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs
	Mfg#: E2760068		Notes: [Initial Date Req.]		11	12/12/2008		0		
								12/18/1992		
27-60-068.2	Airframe	MAN	RH 5/16 in. Spoiler Pivot Bolt Life Limit	NAS464P5		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs
	Mfg#: E2760068		Notes: [Initial Date Req.]		11	12/12/2008		0		
								12/18/1992		
27-60-069.1	Airframe	MAN	LH Spoiler Assembly Life Limit	2422510-137		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs
	Mfg#: E2760069		Notes: [Initial Date Req.]	W714S	11	12/12/2008		0		
								12/18/1992		
27-60-069.2			RH Spoiler Assembly Life Limit	2422510-136		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
	Airframe	MAN		W797S	11	12/12/2008		0		
	Mfg#: E2760069		Notes: [Initial Date Req.]					12/18/1992		
27-60-071.1			LH Spoiler Actuator Arm Assembly Life Limit	2422511		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs
	Airframe	MAN			11	12/12/2008		0		
	Mfg#: E2760071		Notes: [Initial Date Req.]					12/18/1992		
27-60-071.2			RH Spoiler Actuator Arm Assembly Life Limit	2422511		MM-99	9000 Hrs	3628.0	12628.0 Hrs	3757.6 Hrs
	Airframe	MAN			11	12/12/2008		0		
	Mfg#: E2760071		Notes: [Initial Date Req.]					12/18/1992		
27-60-075.1			LH Spoiler Actuator Assembly Life Limit	6600135-2 or 2417015		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			12	12/12/2008		0		
	Mfg#: E2760075		Notes: [Initial Date Req.]					11/6/1981		
27-60-075.2			RH Spoiler Actuator Assembly Life Limit	6600135-2 or 2417015		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			12	12/12/2008		0		
	Mfg#: E2760075		Notes: [Initial Date Req.]					11/6/1981		
27-60-076.1			LH Spoiler Actuator Fitting & Bolt Life Limit	BACB30MT4, BACB30N		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			11	12/12/2008		0		
	Mfg#: E2760076		Notes: [Initial Date Req.]					11/6/1981		
27-60-076.2			RH Spoiler Actuator Fitting & Bolt Life Limit	BACB30MT4, BACB30N		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			11	12/12/2008		0		
	Mfg#: E2760076		Notes: [Initial Date Req.]					11/6/1981		
28 -- FUEL										
28-12-001.1			LH Tip Tank Flapper Valves Replacement	2323006-802		MM-99		8158.9		
	Airframe	MAN			11	12/12/2008		7136		
	Mfg#: K2812001		Notes: [600 Initial Hour Req.] [Initial Date Req.] [CUSTOM FREQUENCY]					11/8/2006		
28-12-001.2			RH Tip Tank Flapper Valves Replacement	2323006-802		MM-99		8158.9		
	Airframe	MAN			11	12/12/2008		7136		
	Mfg#: K2812001		Notes: [600 Initial Hour Req.] [Initial Date Req.] [CUSTOM FREQUENCY]					11/8/2006		
28-12-003.1			Inspect Left Tip Tank Flapper Valves & Wing Structure			MM-99		8780.4		
	Airframe	MAN			12	12/12/2008		7561		
	Mfg#: M2812003		Notes: [Initial Date Req.] [14 DAY Window]				24 MOS	6/16/2008	06/16/2010	11 Mos
28-12-003.2			Inspect Right Tip Tank Flapper Valves & Wing Structure	See Remarks		MM-99		8780.4		
	Airframe	MAN			12	12/12/2008		7561		
	Mfg#: M2812003		Notes: [Initial Date Req.] [14 DAY Window]				24 MOS	6/16/2008	06/16/2010	11 Mos
28-12-011.1			LH Wing Tip Tank Structure Inspection			MM-99		8780.4		
	Airframe	MAN			13	12/12/2008		7561		
	Mfg#: L2812011		Notes: [Initial Date Req.] [14 DAY Window]				24 MOS	6/16/2008	06/16/2010	11 Mos
28-12-011.2			RH Wing Tip Tank Structure Inspection			MM-99		8780.4		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining	
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal	
	Airframe	MAN				13	12/12/2008		7561		
	Mfg#: L2812011		Notes: [Initial Date Req.] [14 DAY Window]					24 MOS	6/16/2008	06/16/2010	11 Mos
28-12-020.1			LH Inbd Wing Flapper Valve & Structure Inspection	See Remarks			MM-99		8868.0		
	Airframe	MAN				13	12/12/2008		7609		
	Mfg#: L2812020		Notes: Inspection completed no defects noted [Initial Date Req.] [14 DAY Window]					24 MOS	5/2/2009	05/02/2011	22 Mos
28-12-020.2			RH Inbd Wing Flapper Valve & Structure Inspection	See Remarks			MM-99		8868.0		
	Airframe	MAN				13	12/12/2008		7609		
	Mfg#: L2812020		Notes: Completed inspection no defects noted [Initial Date Req.] [14 DAY Window]					24 MOS	5/2/2009	05/02/2011	22 Mos
28-20-002.01			LH Wing Pump Motive Flow Hose Replacement				MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.02			RH Wing Pump Motive Flow Hose Replacement				MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.03			LH Tip Tank Motive Flow Hose Replacement				MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.04			RH Tip Tank Motive Flow Hose Replacement				MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.05			LH Center Sector Fuel Hose Replacement				MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.06			RH Center Sector Fuel Hose Replacement				MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.07			LH Center Section Cross Flow Fuel Hose Replacement	2406005-103			MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.08			RH Center Section Cross Flow Fuel Hose Replacement	2406005-6			MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.09			LH Pylon Fuel Supply Hose Replacement				MM-99		0.0		
	Airframe	MAN				1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]					144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.10			RH Pylon Fuel Supply Hose Replacement				MM-99		0.0		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.11			LH Pylon Motive Flow Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
28-20-002.12			RH Pylon Motive Flow Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2820002		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29 -- HYDRAULIC POWER										
29-00-001.01			Landing Gear System Hydraulic Pressure Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.02			Landing Gear System Hydraulic Return Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.03			LH Pylon Hydraulic Supply Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.04			RH Pylon Hydraulic Supply Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.05			LH Pylon Hydraulic Pressure Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.06			RH Pylon Hydraulic Pressure Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.07			LH Pylon Hydraulic Return Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.08			RH Pylon Hydraulic Return Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.09			LH Flap Extend Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
29-00-001.10			RH Flap Extend Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.11			LH Flap Retract Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.12			RH Flap Retract Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.13			LH Spoiler Extend Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.14			RH Spoiler Extend Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.15			LH Spoiler Retract Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.16			RH Spoiler Retract Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.17			Spoiler Pressure Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.18			Wing Section Nose Gear Extend Hyd Hose Replace			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.19			Wing Section Nose Gear Retract Hyd Hose Replace			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.20			Nose Gear Lower Extend Hyd Hose Replacement			MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.21			LH Fuselage Section Brake Pressure Hose Replacement	2307006-55		MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
29-00-001.22			RH Fuselage Section Brake Pressure Hose Replacement	2307006-110		MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
29-00-001.23			Brake Hydraulic Return Hose Replacement	2307006-109, or -82		MM-99		0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: G2900001		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
30 -- ICE/RAIN PROTECTION										
30-20-001.3			LH Nacelle Inlet Bulkhead, Plumbing, Shutoff Valve Inspect			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			5	12/12/2008		7225		
	Mfg#: E3020001		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
30-20-001.4			RH Nacelle Inlet Bulkhead, Plumbing, Shutoff Valve Inspect			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			5	12/12/2008		7225		
	Mfg#: E3020001		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
32 -- LANDING GEAR										
32-10-003.01			LH Main Door Actuator Retract Hydraulic Hose Replacement	2307006-17		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
	Airframe	MAN			6	12/12/2008		7347		
	Mfg#: G3210003		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.02			RH Main Door Actuator Retract Hydraulic Hose Replacement	2307006-18		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
	Airframe	MAN			6	12/12/2008		7347		
	Mfg#: G3210003		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.03			LH Main Door Actuator Extend Hydraulic Hose Replacement	2307006-21		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
	Airframe	MAN			6	12/12/2008		7347		
	Mfg#: G3210003		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.04			RH Main Door Actuator Extend Hydraulic Hose Replacement	2307006-22		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
	Airframe	MAN			6	12/12/2008		7347		
	Mfg#: G3210003		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.05			LH Main Door Uplatch Actuator Hydraulic Hose Replacement	2307006-102		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
	Airframe	MAN			6	12/12/2008		7347		
	Mfg#: G3210003		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.06			RH Main Door Uplatch Actuator Hydraulic Hose Replacement	2307006-102		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
	Airframe	MAN			6	12/12/2008		7347		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.07			LH Main Gear Actuator Retract Hydraulic Hose Replacement	2307006-131		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
Airframe	MAN				6	12/12/2008		7347		
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.08			RH Main Gear Actuator Retract Hydraulic Hose Replacement	2307006-131		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
Airframe	MAN				6	12/12/2008		7347		
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.09			LH Main Gear Actuator Extend Hydraulic Hose Replacement	2307006-166		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
Airframe	MAN				6	12/12/2008		7347		
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.10			RH Main Gear Actuator Extend Hydraulic Hose Replacement	2307006-166		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
Airframe	MAN				6	12/12/2008		7347		
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.11			Nose Gear Actuator Retract Hydraulic Hose Replacement	2307006-101		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
Airframe	MAN				6	12/12/2008		7347		
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.12			Nose Gear Actuator Extend Hydraulic Hose Replacement	2307006-83		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
Airframe	MAN				6	12/12/2008		7347		
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-10-003.13			Nose Gear Uplatch Actuator Hydraulic Hose Replacement	2307006-46		MM-99	1500 Hrs	8497.3	10009.0 Hrs	1138.6 Hrs
Airframe	MAN				6	12/12/2008		7347		
Mfg#: G3210003			Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	5/17/2007	05/17/2012	34 Mos
32-11-070.1			LH Main Gear Strut (Hard Surface Landings Only)	W/Cyl 2341101 or 2341100		MM-99		0.0		
Airframe	MAN				6	12/12/2008	9000 Cyc/Lnd	6027	15027 Cyc/Ln	7416 Cyc/Lnd
Mfg#: E3211070			Notes: [Initial Date Req.]					1/16/2004		
32-11-070.2			RH Main Gear Strut (Hard Surface Landings Only)	W/Cyl 2341101 or 2341100		MM-99		0.0		
Airframe	MAN				6	12/12/2008	9000 Cyc/Lnd	6027	15027 Cyc/Ln	7416 Cyc/Lnd
Mfg#: E3211070			Notes: [Initial Date Req.]					1/16/2004		
32-11-072.1			LH Main Gear Actuator Attach Pin Hard Surface Runway	2341109		MM-99		0.0		
Airframe	MAN				6	12/12/2008	9000 Cyc/Lnd	0	9000 Cyc/Lnd	1389 Cyc/Lnd
Mfg#: E3211072			Notes: [Initial Date Req.]					11/6/1981		

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (* =Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
32-11-072.2			RH Main Gear Actuator Attach Pin Hard Surface Runway	2341109		MM-99		0.0		
	Airframe	MAN			6	12/12/2008	9000 Cyc/Lnd	0	9000 Cyc/Lnd	1389 Cyc/Lnd
	Mfg#:	E3211072	Notes: [Initial Date Req.]					11/6/1981		
32-11-082			Nose Gear Strut (Hard Surface Landings Only)	2342100		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211082	Notes: [Initial Date Req.]					11/6/1981		
32-11-083			Nose Gear Actuator (Hard Surface Landings Only)	2317100		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211083	Notes: [Initial Date Req.]					11/6/1981		
32-11-084.1			LH Main Gear Actuator Pin Replacement	5441101		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211084	Notes: [Initial Date Req.]					11/6/1981		
32-11-084.2			RH Main Gear Actuator Pin Replacement	5441101		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211084	Notes: [Initial Date Req.]					11/6/1981		
32-11-085.1			LH Main Gear Actuator Pillar Assembly Replacement	2341123-18		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211085	Notes: [Initial Date Req.]					11/6/1981		
32-11-085.2			RH Main Gear Actuator Pillar Assembly Replacement	2341123-18		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211085	Notes: [Initial Date Req.]					11/6/1981		
32-11-087.1			LH Main Gear Actuator (Hard Surface Landings Only)	2327100		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211087	Notes: [Initial Date Req.]					11/6/1981		
32-11-087.2			RH Main Gear Actuator (Hard Surface Landings Only)	2327100		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#:	E3211087	Notes: [Initial Date Req.]					11/6/1981		
32-11-088.1			LH Main Gear Strut (Mixed Surface Landing) Replace	W/Cylinder 2441011		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	12000 Cyc/Lnd	0	12000 Cyc/Ln	4389 Cyc/Lnd
	Mfg#:	E3211088	Notes: [Initial Date Req.]					11/6/1981		
32-11-088.2			RH Main Gear Strut (Mixed Surface Landing) Replace	W/Cylinder 2441011		MM-99		0.0		
	Airframe	MAN			7	12/12/2008	12000 Cyc/Lnd	0	12000 Cyc/Ln	4389 Cyc/Lnd
	Mfg#:	E3211088	Notes: [Initial Date Req.]					11/6/1981		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
32-11-089			NLG Strut (Mixed Surface Landing) Replacement	2342100		MM-99		0.0		
	Airframe	MAN			8	12/12/2008	20000 Cyc/Lnd	0	20000 Cyc/Ln	12389 Cyc/Lnd
	Mfg#: E3211089		Notes: [Initial Date Req.]					11/6/1981		
32-11-099.1			Left Main Gear Strut Assy (3141100) with Cylinder Assy (6041101)			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	16500 Cyc/Lnd	0	16500 Cyc/Ln	8889 Cyc/Lnd
	Mfg#: Q3211099		Notes: [Initial Date Req.]					11/6/1981		
32-11-099.2			Right Main Gear Strut Assy (3141100) with Cylinder Assy (6041101)			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	16500 Cyc/Lnd	0	16500 Cyc/Ln	8889 Cyc/Lnd
	Mfg#: Q3211099		Notes: [Initial Date Req.]					11/6/1981		
32-33-013.1			Nose Gear Emergency Air Hose Assembly Replacement			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: L3233013		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
32-33-013.2			LH Main Gear Emergency Air Hose Assembly Replacement			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: L3233013		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
32-33-013.3			RH Main Gear Emergency Air Hose Assembly Replacement			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: L3233013		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
32-33-013.4			MLG Emergency Air Supply (Fus to Wing) Hose Assy Replacement			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: L3233013		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
32-33-013.5			LH Main Gear Door Emergency Air Hose Assembly Replacement			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: L3233013		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
32-33-013.6			RH Main Gear Door Emergency Air Hose Assembly Replacement			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: L3233013		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
32-33-013.7			Emergency Braking System Air Hose Assembly Replacement			MM-99		0.0		
	Airframe	MAN			8	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: L3233013		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
32-43-040.1			LH Outboard Strut to Wing Hyd Brake Hose Replace	2307006-35		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
	Airframe	MAN		unk	8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-43-040.2			RH Outboard Strut to Wing Hyd Brake Hose Replace	2307006-35		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-43-040.3			LH Inboard Strut to Wing Hyd Brake Hose Replace	2307006-37		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-43-040.4			RH Inboard Strut to Wing Hyd Brake Hose Replace	2307006-37		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-43-040.5			LH Inboard Strut to Wheel Hyd Brake Hose Replace	2307006-112		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-43-040.6			RH Inboard Strut to Wheel Hyd Brake Hose Replace	2307006-112		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-43-040.7			LH Outboard Strut to Wheel Hyd Brake Hose Replace	2307006-113		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-43-040.8			RH Outboard Strut to Wheel Hyd Brake Hose Replace	2307006-113		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN			8	12/12/2008		7607		
	Mfg#: G3243040		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	2/2/2009	02/02/2014	55 Mos
32-55-001			Nose Wheel Steering Actuator Inspection	6608278		MM-99	2000 Hrs	7603.2	9603.2 Hrs	732.8 Hrs
	Airframe	MAN			8	12/12/2008		0		
	Mfg#: C3255001		Notes: [Initial Date Req.] [25 Hour Window]					4/1/2005		
34 -- NAVIGATION										
340005			Pilot's Pitot Static System Certification			PSP 601-2		8820.9		
	Airframe	MAN				201	10/17/2005	7584		
	Mfg#: 34-11-00-201		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
340006			Copilot's Pitot Static System Certification			PSP 601-2		8820.9		
	Airframe	MAN				201	10/17/2005	7584		
	Mfg#: 34-11-00-201		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
340009			Pilot's Transponder Test and Inspection			PSP 601-2		8820.9		
	Airframe	MAN				202 11/15/1996		7584		
	Mfg#: 34-54-00-202		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
340010			Copilot's Transponder Test and Inspection			PSP 601-2		8820.9		
	Airframe	MAN				202 11/15/1996		7584		
	Mfg#: 34-54-00-202		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
340015			Pilot's Altimeter Certification	70310N01D01		PSP 601-2		8820.9		
	Airframe	MAN				208 9/4/1998		7584		
	Mfg#: 34-11-00-208		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
340016			Copilot's Altimeter Certification	70257N01D01 / 70257N0		PSP 601-2		8820.9		
	Airframe	MAN				208 9/4/1998		7584		
	Mfg#: 34-11-00-208		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
340017			Standby Altimeter Certification			PSP 601-2		8820.9		
	Airframe	MAN				201 11/15/1996		7584		
	Mfg#: 34-12-00-201		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
340021			Pilot's Air Data Computer Certification			PSP 601-2		8820.9		
	Airframe	MAN				201 4/29/2002		7584		
	Mfg#: 34-13-00-201		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
349001*			VOR Accuracy Check					8868.0		
*	Airframe	MAN						7609		
			Notes: [Initial Date Req.]				30 DAY	5/28/2009	06/27/2009	-10 Days
349002*			NAV Database(s) Software Expiration					8867.0		
*	Airframe	MAN						7607		
			Notes: [Initial Date Req.]				28 DAY	1/23/2009	02/20/2009	-5 Mos
349004.2.1*			Pitot-Static Sys Maintenance Checks (RVSM ICA) (24 Mo)			IFCA Doc # 30A050002		8867.0		
	Airframe	MAN				18 7/24/2004		7607		
	Mfg#: N/A		Notes: C/W during last Pitot Static RVSM Inspection [Initial Date Req.] [End of Month Item]				24 MOS	1/23/2009	01/31/2011	18 Mos
349004.2.2*			24 Month RVSM Check			IFCA Doc # 30A050002		8820.9		
	Airframe	MAN				18 7/24/2004		7584		
	Mfg#: N/A		Notes: Complied with by Precision Static FAA CRS QJAR856X [Initial Date Req.] [End of Month Item]				24 MOS	9/25/2008	09/30/2010	14 Mos
349004.2.3*			RVSM Altitude Hold Check Flight			IFCA # 30A050002		8867.0		
	Airframe	MAN				17 7/24/2004		7607		
	Mfg#: N/A		Notes: C/W After last Pitot Static RVSM Inspection [Initial Date Req.] [End of Month Item]				24 MOS	1/23/2009	01/31/2011	18 Mos
349004.3.1*			96 Month RVSM Check			IFCA Doc # 30A050002		0.0		
	Airframe	MAN				19 7/24/2004		0		
	Mfg#: N/A		Notes: [Initial Date Req.]				96 MOS	9/2/2004	09/02/2012	38 Mos
349004.4.1*			144 Month RVSM Check			IFCA Doc # 30A050002		0.0		
	Airframe	MAN				19 7/24/2004		0		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
Notes: [Initial Date Req.]							144 MOS	9/2/2004	09/02/2016	86 Mos
35 -- OXYGEN										
35-00-016	Nose Oxygen Cylinder ICC Hydrostatic Test (DOT3AA1800)			176182-02		MM-99		0.0		
	Airframe	MAN		720735	8	12/12/2008		0		
	Mfg#: J3500016		Notes: [Initial Date Req.] [End of Month Item]				60 MOS	11/30/2005	11/30/2010	16 Mos
36 -- PNEUMATIC										
36-10-043.1	Emergency Air Bottle 3 Year Visual & ICC Hydrostatic Test			2370017		MM-99		8439.2		
	Airframe	MAN		2516	10	12/12/2008		7312		
	Mfg#: N3610043		Notes: New unit installed. [Initial Date Req.] [End of Month Item]				36 MOS	4/13/2007	04/30/2010	9 Mos
36-10-043.3	Emergency Air Bottle 12 Year X-Ray Inspection			2370017		MM-99		8439.2		
	Airframe	MAN		2516	10	12/12/2008		7312		
	Mfg#: N3610043		Notes: New unit installed. [Initial Date Req.] [End of Month Item]				144 MOS	4/13/2007	04/30/2019	117 Mos
36-10-043.4	Emergency Air Bottle Extended Inspection			2370017		MM-99		8868.0		
*	Airframe	MAN		2516	10	12/12/2008		7609		
	Mfg#: N3610043		Notes: Inspected for defects and corrosion, none noted, reinstalled and reserviced bottle [180 MOS Initial Req.] [Initial Date Req.] [End of Month Item]				24 MOS	5/2/2009	01/31/2009*	-6 Mos
36-10-045.3	LH Engine High Press Bleed Air Hose & Gasket Inspection					MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			5	12/12/2008		7225		
	Mfg#: P3610045		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
36-10-045.4	RH Engine High Press Bleed Air Hose & Gasket Inspection					MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			5	12/12/2008		7225		
	Mfg#: P3610045		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
52 -- DOORS										
52-10-025	Exterior Lower Cabin Structure & Hinge Area Inspection					MM-99		8780.4		
	Airframe	MAN			7	12/12/2008		7561		
	Mfg#: L5210025		Notes: [Initial Date Req.] [14 DAY Window]				24 MOS	6/16/2008	06/16/2010	11 Mos

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
53 -- FUSELAGE										
531050			Pressure Cabin Skin Thickness Measurement				MM-99	0.0		
	Airframe	MAN			12	12/12/2008		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					11/6/1981		
53-20-006			Aft Pressure Bulkhead at Frame 22, FS421.42 Inspection				MM-99	0.0		
	Airframe	MAN			7	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: J5320006		Notes: [600 Initial Hour Req.] [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
53-22-000			Keelbeam Attach Bolts Replacement				MM-99	0.0		
	Airframe	MAN			1	12/12/2008	6000 Cyc/Lnd	6772	12772 Cyc/Ln	5161 Cyc/Lnd
	Mfg#: E5322000		Notes: [Initial Date Req.] [25 Cycle Window] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
54 -- NACELLES/PYLONS										
54-50-043.3			LH Pylon/Engine Beam Structure Inspection				MM-99	1400 Hrs	8289.7	9689.7 Hrs
	Airframe	MAN			11	12/12/2008		7225		819.3 Hrs
	Mfg#: J5450043		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
54-50-043.4			RH Pylon/Engine Beam Structure Inspection				MM-99	1400 Hrs	8289.7	9689.7 Hrs
	Airframe	MAN			11	12/12/2008		7225		819.3 Hrs
	Mfg#: J5450043		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
54-50-044.1			LH Engine Beam Support Fittings Inspection				MM-99	0.0		
	Airframe	MAN			11	12/12/2008		0		
	Mfg#: H5450044		Notes: [Initial Date Req.] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
54-50-044.2			RH Engine Beam Support Fittings Inspection				MM-99	0.0		
	Airframe	MAN			11	12/12/2008		0		
	Mfg#: J5450044		Notes: [Initial Date Req.] [14 DAY Window]				144 MOS	6/6/2005	06/06/2017	95 Mos
54-50-045.3			LH Pylon/Engine Beam Support Structure Inspection				MM-99	1400 Hrs	8289.7	9689.7 Hrs
	Airframe	MAN			12	12/12/2008		7225		819.3 Hrs
	Mfg#: J5450045		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
54-50-045.4			RH Pylon/Engine Beam Support Structure Inspection				MM-99	1400 Hrs	8289.7	9689.7 Hrs
	Airframe	MAN			12	12/12/2008		7225		819.3 Hrs
	Mfg#: J5450045		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
56 -- WINDOWS										
56-00-009			Cabin Windows - Optical Prism Inspection			MM-99		0.0		
	Airframe	MAN			7	12/12/2008		0		
	Mfg#: M5600009		Notes: Inspection requirement needs to be re-indexed to TTA following a Cabin Window replacement. [600 Initial Hour Req.] [Initial Date Req.]					11/6/1981		
56-10-023.1			Left Windshield Larascope Inspection			MM-99		0.0		
	Airframe	MAN			8	12/12/2008		0		
	Mfg#: G5610023		Notes: Inspection requirement needs to be re-indexed to TTA following Windshield replacement. [600 Initial Hour Req.] [Initial Date Req.] [25 Hour Window]					11/6/1981		
56-10-023.2			Right Windshield Larascope Inspection			MM-99		0.0		
	Airframe	MAN			8	12/12/2008		0		
	Mfg#: G5610023		Notes: Inspection requirement needs to be re-indexed to TTA following Windshield replacement. [600 Initial Hour Req.] [Initial Date Req.] [25 Hour Window]					11/6/1981		
57 -- WINGS										
57-10-035			Wing Inboard Dry Bay Inspection			MM-99		8780.4		
	Airframe	MAN			13	12/12/2008		7561		
	Mfg#: L5710035		Notes: [Initial Date Req.] [14 DAY Window]				24 MOS	6/16/2008	06/16/2010	11 Mos
57-50-046.1			LH Flap Track Support Fitting Inspection			MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Airframe	MAN			13	12/12/2008		7569		
	Mfg#: H5750046		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		
57-50-046.2			RH Flap Track Support Fitting Inspection			MM-99	1200 Hrs	8792.9	9992.9 Hrs	1122.5 Hrs
	Airframe	MAN			13	12/12/2008		7569		
	Mfg#: H5750046		Notes: [Initial Date Req.] [25 Hour Window]					8/13/2008		
71 -- POWER PLANT										
71-10-021.1			LH Nacelle Fuel Hose Replacement	2406005-26		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110021		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-021.2			RH Nacelle Fuel Hose Replacement	2406005-23		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110021		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-021.3			LH Nacelle Motive Flow Fuel Hose Replacement	2406005-25		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110021		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-021.4			RH Nacelle Motive Flow Fuel Hose Replacement	2406005-28		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		2406005-28	4	12/12/2008		7607		
	Mfg#: G7110021		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
71-10-022.1			LH Nacelle Hydraulic Pressure Hose Replacement	2406005-30		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110022		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-022.2			RH Nacelle Hydraulic Pressure Hose Replacement	2406005-27		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110022		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-022.3			LH Nacelle Hydraulic Supply Hose Replacement	2406005-16		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110022		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-022.4			RH Nacelle Hydraulic Supply Hose Replacement	2406005-4		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110022		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-022.5			LH Hydraulic Compensator Return Hose Replacement	2406005-29		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110022		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-10-022.6			RH Hydraulic Compensator Return Hose Replacement	2406005-5		MM-99	2400 Hrs	8867.0	11267.0 Hrs	2396.6 Hrs
	Airframe	MAN		NON SERIALIZED	4	12/12/2008		7607		
	Mfg#: G7110022		Notes: [Initial Date Req.] [25 Hour Window] [14 DAY Window]				60 MOS	3/12/2009	03/25/2014	56 Mos
71-20-024.3			LH Engine Mount Castings & Attachments Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			5	12/12/2008		7225		
	Mfg#: E7120024		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
71-20-024.4			RH Engine Mount Castings & Attachments Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			5	12/12/2008		7225		
	Mfg#: E7120024		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
71-20-029.1			LH Eng Mount Castings & Hardware Mag Particle Insp			MM-99		0.0		
	Airframe	MAN			6	12/12/2008		0		
	Mfg#: E7120029		Notes: [Initial Date Req.] [14 DAY Window]				144 MOS	1/16/2004	01/16/2016	78 Mos
71-20-029.2			RH Eng Mount Castings & Hardware Mag Particle Insp			MM-99		0.0		
	Airframe	MAN			6	12/12/2008		0		
	Mfg#: E7120029		Notes: [Initial Date Req.] [14 DAY Window]				144 MOS	1/16/2004	01/16/2016	78 Mos
71-20-031.3			LH Engine Mount Castings Magnetic Particle Inspection	N/A if P/N 2651034 Instal		MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (*=Overfly)	Remaining Hrs/Cyc/Cal	
Due	Logbook	App			Notes	Serial Number					Page
	Airframe	MAN				6	12/12/2008	7225			
	Mfg#: D7120031		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007			
71-20-031.4			RH Engine Mount Castings Magnetic Particle Inspection	N/A if P/N 2651034 Instal			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN				6	12/12/2008	7225			
	Mfg#: D7120031		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007			
71-20-036.1			LH Engine Forward Upper Shock Mount Cover Replace	LM-833-3			MM-99	4200 Hrs	6894.4	11094.4 Hrs	2224.0 Hrs
	Airframe	MAN				4	12/12/2008	0			
	Mfg#: K7120036		Notes: [Initial Date Req.] [200 Hour Window]					1/16/2004			
71-20-036.2			LH Engine Forward Lower Shock Mount Cover Replace	LM-833-3			MM-99	4200 Hrs	6894.4	11094.4 Hrs	2224.0 Hrs
	Airframe	MAN				4	12/12/2008	0			
	Mfg#: K7120036		Notes: [Initial Date Req.] [200 Hour Window]					1/16/2004			
71-20-036.3			RH Engine Forward Upper Shock Mount Cover Replace	LM-833-3			MM-99	4200 Hrs	6894.4	11094.4 Hrs	2224.0 Hrs
	Airframe	MAN				4	12/12/2008	0			
	Mfg#: K7120036		Notes: [Initial Date Req.] [200 Hour Window]					1/16/2004			
71-20-036.4			RH Engine Forward Lower Shock Mount Cover Replace	LM-833-3			MM-99	4200 Hrs	6894.4	11094.4 Hrs	2224.0 Hrs
	Airframe	MAN				4	12/12/2008	0			
	Mfg#: K7120036		Notes: [Initial Date Req.] [200 Hour Window]					1/16/2004			
71-20-037.1			LH Engine Aft Mount Housing Replacement	LM-833-30			MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN				5	12/12/2008	0			
	Mfg#: L7120037		Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004			
71-20-037.2			LH Engine Aft Mount Center Bonded Joint Replacement	LM-833-16			MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN				5	12/12/2008	0			
	Mfg#: L7120037		Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004			
71-20-037.3			RH Engine Aft Mount Housing Replacement	LM-833-30			MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN				5	12/12/2008	0			
	Mfg#: L7120037		Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004			
71-20-037.4			RH Engine Aft Mount Center Bonded Joint Replacement	LM-833-16			MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN				5	12/12/2008	0			
	Mfg#: L7120037		Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004			
71-20-037.5			LH Engine AFT Isolator Assembly Replacement	6600309-005			MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN				5	12/12/2008	0			
	Mfg#: L7120037		Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004			
71-20-037.6			RH Engine AFT Isolator Assembly Replacement	6600309-005			MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN				5	12/12/2008	0			

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (* =Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
Mfg#: L7120037			Notes: [Initial Date Req.] [400 Hour Window]				1/16/2004			
71-20-038.1	LH Engine Forward Mount Upper Attach Bolt Replacement		2651026	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120038			Notes: [Initial Date Req.]							
71-20-038.2	LH Engine Forward Mount Lower Attach Bolt Replacement		2651026	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120038			Notes: [Initial Date Req.]							
71-20-038.3	RH Engine Forward Mount Upper Attach Bolt Replacement		2651026	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120038			Notes: [Initial Date Req.]							
71-20-038.4	RH Engine Forward Mount Lower Attach Bolt Replacement		2651026	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120038			Notes: [Initial Date Req.]							
71-20-039.1	LH Aft Inboard Engine Attach Bolt Replacement		2651027	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120039			Notes: [Initial Date Req.]							
71-20-039.2	LH Aft Outboard Engine Attach Bolt Replacement		2652002	MM-99	20000 Hrs	8289.7	28289.7 Hrs	19419.3 Hrs		
Airframe	MAN			5	12/12/2008	7225	1/18/2007			
Mfg#: E7120039			Notes: [Initial Date Req.]							
71-20-039.3	RH Aft Inboard Engine Attach Bolt Replacement		2651027	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120039			Notes: [Initial Date Req.]							
71-20-039.4	RH Aft Outboard Engine Attach Bolt Replacement		2652002	MM-99	20000 Hrs	8289.7	28289.7 Hrs	19419.3 Hrs		
Airframe	MAN			5	12/12/2008	7225	1/18/2007			
Mfg#: E7120039			Notes: [Initial Date Req.]							
71-20-040.1	LH Engine Forward Shock Mount Upper Attach Bolt Replace		NAS1307-3H	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120040			Notes: [Initial Date Req.]							
71-20-040.2	LH Engine Forward Shock Mount Lower Attach Bolt Replace		NAS1307-3H	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		
Airframe	MAN			5	12/12/2008	0	11/6/1981			
Mfg#: E7120040			Notes: [Initial Date Req.]							
71-20-040.3	RH Engine Forward Shock Mount Upper Attach Bolt Replace		NAS1307-3H	MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120040		Notes: [Initial Date Req.]					11/6/1981		
71-20-040.4			RH Engine Forward Shock Mount Lower Attach Bolt Replace	NAS1307-3H		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120040		Notes: [Initial Date Req.]					11/6/1981		
71-20-040.5			LH Forward Upper Engine Attach Bolts Replace	6600187		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120040		Notes: [Initial Date Req.]					11/6/1981		
71-20-040.6			LH Forward Lower Engine Attach Bolts Replace	6600187		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120040		Notes: [Initial Date Req.]					11/6/1981		
71-20-040.7			RH Forward Upper Engine Attach Bolts Replace	6600187		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120040		Notes: [Initial Date Req.]					11/6/1981		
71-20-040.8			RH Forward Lower Engine Attach Bolts Replace	6600187		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120040		Notes: [Initial Date Req.]					11/6/1981		
71-20-041.1			LH Engine Aft Shock Mount Upper Attach Bolt Replace	NAS335CP23		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120041		Notes: [Initial Date Req.]					11/6/1981		
71-20-041.2			LH Engine Aft Shock Mount Lower Attach Bolt Replace	NAS335CP23		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120041		Notes: [Initial Date Req.]					11/6/1981		
71-20-041.3			RH Engine Aft Shock Mount Upper Attach Bolt Replace	NAS335CP23		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120041		Notes: [Initial Date Req.]					11/6/1981		
71-20-041.4			RH Engine Aft Shock Mount Lower Attach Bolt Replace	NAS335CP23		MM-99	20000 Hrs	0.0	20000.0 Hrs	11129.6 Hrs
	Airframe	MAN			5	12/12/2008		0		
	Mfg#: E7120041		Notes: [Initial Date Req.]					11/6/1981		
71-20-063.3			Left Fwd & Aft Engine Mount Isolators Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			7	12/12/2008		7225		
	Mfg#: Q7120063		Notes: [Initial Date Req.] [100 Hour Window]					11/18/2007		
71-20-063.4			Right Fwd & Aft Engine Mount Isolators Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			7	12/12/2008		7225		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
Mfg#: Q7120063			Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
71-20-064.1			LH Engine Forward Upper Shock Mount Bolts Replace	NAS1304-1H		MM-99	4200 Hrs	7620.8	11820.8 Hrs	2950.4 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: K7120064			Notes: [Initial Date Req.] [200 Hour Window]					6/6/2005		
71-20-064.2			LH Engine Forward Lower Shock Mount Bolts Replace	NAS1304-1H		MM-99	4200 Hrs	7620.8	11820.8 Hrs	2950.4 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: K7120064			Notes: [Initial Date Req.] [200 Hour Window]					6/6/2005		
71-20-064.3			RH Engine Forward Upper Shock Mount Bolts Replace	NAS1304-1H		MM-99	4200 Hrs	7620.8	11820.8 Hrs	2950.4 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: K7120064			Notes: [Initial Date Req.] [200 Hour Window]					6/6/2005		
71-20-064.4			RH Engine Forward Lower Shock Mount Bolts Replace	NAS1304-1H		MM-99	4200 Hrs	7620.8	11820.8 Hrs	2950.4 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: K7120064			Notes: [Initial Date Req.] [200 Hour Window]					6/6/2005		
71-20-065.1			LH Engine Forward Upper Mounting Assembly Replacement	LM-833-1		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: L7120065			Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		
71-20-065.2			LH Engine Forward Lower Mounting Assembly Replacement	LM-833-1		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: L7120065			Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		
71-20-065.3			RH Engine Forward Upper Mounting Assembly Replacement	LM-833-1		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: L7120065			Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		
71-20-065.4			RH Engine Forward Lower Mounting Assembly Replacement	LM-833-1		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			5	12/12/2008		0		
Mfg#: L7120065			Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		
71-20-066.1			LH Engine Forward Upper Shock Mount Housing Replacement	LM-833-2		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			6	12/12/2008		0		
Mfg#: L7120066			Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		
71-20-066.2			LH Engine Forward Lower Shock Mount Housing Replacement	LM-833-2		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			6	12/12/2008		0		
Mfg#: L7120066			Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (* =Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
71-20-066.3			RH Engine Forward Upper Shock Mount Housing Replacement	LM-833-2		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			6	12/12/2008		0		
	Mfg#: L7120066		Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		
71-20-066.4			RH Engine Forward Lower Shock Mount Housing Replacement	LM-833-2		MM-99	8400 Hrs	6894.4	15294.4 Hrs	6424.0 Hrs
	Airframe	MAN			6	12/12/2008		0		
	Mfg#: L7120066		Notes: [Initial Date Req.] [400 Hour Window]					1/16/2004		
71-20-067.3			Left Engine Aft Attach Bolt Fluorescent Penetrant Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			7	12/12/2008		7225		
	Mfg#: Q7120067		Notes: [1400 Initial Hour Req.] [Initial Date Req.] [100 Hour Window]					1/18/2007		
71-20-067.4			Right Engine Aft Attach Bolt Fluorescent Penetrant Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			7	12/12/2008		7225		
	Mfg#: Q7120067		Notes: [1400 Initial Hour Req.] [Initial Date Req.] [100 Hour Window]					1/18/2007		
71-20-072.1			Left Engine Aft Attach Bolt - Perform Magnetic Particle Inspection	2652002-3 & -801		MM-99	1400 Hrs	0.0	9839.2 Hrs	968.8 Hrs
	Airframe	MAN			8	12/12/2008		0		
	Mfg#: Q7120072		Notes: [Initial Date Req.] [100 Hour Window]					11/6/1981		
71-20-072.2			Right Engine Aft Attach Bolt - Perform Magnetic Particle Inspection	2652002-3 & -801		MM-99	1400 Hrs	0.0	9839.2 Hrs	968.8 Hrs
	Airframe	MAN			8	12/12/2008		0		
	Mfg#: Q7120072		Notes: [Initial Date Req.] [100 Hour Window]					11/6/1981		
72 -- ENGINES										
720005			150 to 250 Hour Engine Routine Periodic Inspection			72-02-01	150 Hrs	8687.8	8837.8 Hrs	146.6 Hrs
	Engine 1	MAN			611	9/26/2008		6977		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					3/12/2009		
720005			150 to 250 Hour Engine Routine Periodic Inspection			72-02-01	150 Hrs	8602.8	8752.8 Hrs	146.6 Hrs
	Engine 2	MAN			611	9/26/2008		6927		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					3/12/2009		
720011			300 to 400 Hour Engine Routine Periodic Inspection			72-02-01	300 Hrs	8601.2	8901.2 Hrs	210.0 Hrs
	Engine 1	MAN			611	9/26/2008		6934		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					6/16/2008		
720011			300 to 400 Hour Engine Routine Periodic Inspection			72-02-01	300 Hrs	8516.2	8816.2 Hrs	210.0 Hrs
	Engine 2	MAN			611	9/26/2008		6883		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					6/16/2008		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
720017			600 to 800 Hour Engine Routine Periodic Inspection			72-02-01	600 Hrs	8260.0	8860.0 Hrs	168.8 Hrs
	Engine 1	MAN			611	9/26/2008		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
720017			600 to 800 Hour Engine Routine Periodic Inspection			72-02-01	600 Hrs	8175.0	8775.0 Hrs	168.8 Hrs
	Engine 2	MAN			611	9/26/2008		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
720021			1000 to 1500 Hour Engine Routine Periodic Inspection			72-02-01	1400 Hrs	8260.0	9660.0 Hrs	968.8 Hrs
	Engine 1	MAN			611	9/26/2008		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window] [CUSTOM FREQUENCY]					4/13/2007		
720021			1000 to 1500 Hour Engine Routine Periodic Inspection			72-02-01	1400 Hrs	8175.0	9575.0 Hrs	968.8 Hrs
	Engine 2	MAN			611	9/26/2008		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window] [CUSTOM FREQUENCY]					4/13/2007		
720027			Engine Major Periodic Inspection	TFE731-2		TFE731-72-3105	1400 Hrs	8260.0	9660.0 Hrs	968.8 Hrs
	Engine 1	MAN		P-89248	3	6/4/1991		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					4/13/2007		
720027			Engine Major Periodic Inspection	TFE731-2		TFE731-72-3105	1400 Hrs	8175.0	9575.0 Hrs	968.8 Hrs
	Engine 2	MAN		P-89247	3	6/4/1991		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					4/13/2007		
720035			Engine Combustion Chamber Plenum Case Inspection	TFE731-2		TFE731-72-3105	1400 Hrs	8260.0	9660.0 Hrs	968.8 Hrs
	Engine 1	MAN		P-89248	3	6/4/1991		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					4/13/2007		
720035			Engine Combustion Chamber Plenum Case Inspection	TFE731-2		TFE731-72-3105	1400 Hrs	8175.0	9575.0 Hrs	968.8 Hrs
	Engine 2	MAN		P-89247	3	6/4/1991		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [100 Hour Window]					4/13/2007		
720045			Engine Compressor Zone Inspection	TFE731-2		TFE731-72-3105	4200 Hrs	8260.0	12460.0 Hrs	3768.8 Hrs
	Engine 1	MAN		P-89248	3	6/4/1991		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
720045			Engine Compressor Zone Inspection	TFE731-2		TFE731-72-3105	4200 Hrs	8175.0	12375.0 Hrs	3768.8 Hrs
	Engine 2	MAN		P-89247	3	6/4/1991		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
720055			Engine Accessory Drive Gearbox Inspection	TFE731-2		TFE731-72-3105	4200 Hrs	8260.0	12460.0 Hrs	3768.8 Hrs
	Engine 1	MAN		P-89248	3	6/4/1991		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
720055			Engine Accessory Drive Gearbox Inspection	TFE731-2		TFE731-72-3105	4200 Hrs	8175.0	12375.0 Hrs	3768.8 Hrs

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (*=Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
	Engine 2	MAN		P-89247	3	6/4/1991		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
720065			Engine Fan Support Assembly Inspection	TFE731-2		TFE731-72-3105	4200 Hrs	8260.0	12460.0 Hrs	3768.8 Hrs
	Engine 1	MAN		P-89248	4	6/4/1991		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
720065			Engine Fan Support Assembly Inspection	TFE731-2		TFE731-72-3105	4200 Hrs	8175.0	12375.0 Hrs	3768.8 Hrs
	Engine 2	MAN		P-89247	4	6/4/1991		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [200 Hour Window]					4/13/2007		
721101			Fan Driveshaft Tracking	3071955		TFE731-72-3001		0.0		
	Engine 1	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
721101			Fan Driveshaft Tracking	3071955		TFE731-72-3001		0.0		
	Engine 2	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
721109			Fan Disc Life Limit	3073563-2		TFE731-72-3001		0.0		
	Engine 1	MAN		5-03229-3643	18-19	3/9/2009	10000 Cyc/Lnd	4383	13261 Cyc/Ln	6280 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					3/8/1996		
721109			Fan Disc Life Limit	3073563-2		TFE731-72-3001		0.0		
	Engine 2	MAN		5-03229-5085	18-19	3/9/2009	10000 Cyc/Lnd	0	14338 Cyc/Ln	7407 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723101			LP Axial Compressor Tie Rod Tracking	3070065		TFE731-72-3001		0.0		
	Engine 1	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723101			LP Axial Compressor Tie Rod Tracking	3070065		TFE731-72-3001		0.0		
	Engine 2	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723103			LP Axial Compressor Tie Rod Tracking	3073049		TFE731-72-3001		0.0		
	Engine 1	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723103			LP Axial Compressor Tie Rod Tracking	3073049		TFE731-72-3001		0.0		
	Engine 2	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723105			LP Axial Compressor 1st Stage Disc Life Limit	3072395-1		TFE731-72-3001		0.0		
	Engine 1	MAN		1-12112-1516	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3019 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723105			LP Axial Compressor 1st Stage Disc Life Limit	3072395-1		TFE731-72-3001		0.0		
	Engine 2	MAN		1-12172-1303	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3069 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723109			LP Axial Compressor 2nd Stage Disc Life Limit	3072396-1		TFE731-72-3001		0.0		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
	Engine 1	MAN		1-12112-399	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3019 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723109			LP Axial Compressor 2nd Stage Disc Life Limit	3072396-1		TFE731-72-3001		0.0		
	Engine 2	MAN		9-12112-4498	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3069 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723113			LP Axial Compressor 3rd Stage Disc Life Limit	3072397-1		TFE731-72-3001		0.0		
	Engine 1	MAN		0-1211-4044	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3019 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723113			LP Axial Compressor 3rd Stage Disc Life Limit	3072397-1		TFE731-72-3001		0.0		
	Engine 2	MAN		0-12112-4098	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3069 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723119			LP Axial Compressor 4th Stage Disc Life Limit	3072398-1		TFE731-72-3001		0.0		
	Engine 1	MAN		0-03160-3685	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3019 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723119			LP Axial Compressor 4th Stage Disc Life Limit	3072398-1		TFE731-72-3001		0.0		
	Engine 2	MAN		0-12112-2015	18-19	3/9/2009	10000 Cyc/Lnd	0	10000 Cyc/Ln	3069 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723209			HP Compressor Radial Impeller Life Limit	3073394-1		TFE731-72-3001		0.0		
	Engine 1	MAN		7-23365-1146	18-19	3/9/2009	10000 Cyc/Lnd	397	10397 Cyc/Ln	3416 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					6/9/1983		
723211			HP Compressor Radial Impeller Life Limit	3073398-2		TFE731-72-3001		0.0		
	Engine 2	MAN		0-23315-458	18-19	3/9/2009	10000 Cyc/Lnd	2379	10000 Cyc/Ln	3069 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/13/1991		
723217			HP Compressor Shouldered Shaft Tracking	3071441-1		TFE731-72-3001		0.0		
	Engine 1	INF		1P-43159	18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
723217			HP Compressor Shouldered Shaft Tracking	3071441-1		TFE731-72-3001		0.0		
	Engine 2	INF		1P-43158	18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
725113			HP Turbine Disc Life Limit	3072732-2		TFE731-72-3001		0.0		
	Engine 1	MAN		5-23315-1287	18-19	3/9/2009	5200 Cyc/Lnd	4383	9583 Cyc/Lnd	2602 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					3/8/1996		
725113			HP Turbine Disc Life Limit	3072732-2		TFE731-72-3001		0.0		
	Engine 2	MAN		5-23315-1316	18-19	3/9/2009	5200 Cyc/Lnd	4338	9538 Cyc/Lnd	2607 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					3/17/1996		
725115			HP Turbine Seal Rotor (Balance Piston) Tracking	3072979-1		TFE731-72-3001		0.0		
	Engine 1	MAN		1P-34578	18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
725115			HP Turbine Seal Rotor (Balance Piston) Tracking	3072979-1		TFE731-72-3001		0.0		
	Engine 2	MAN		1P-34557	18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
725239			LP Turbine Rotating Seal Tracking	3070154		TFE731-72-3001		0.0		
	Engine 1	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
725239			LP Turbine Rotating Seal Tracking	3070154		TFE731-72-3001		0.0		
	Engine 2	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
725241			LP Turbine 1st Stage Disc Life Limit	3075830-1		TFE731-72-3001		10307.2		
	Engine 1	MAN		060322904074	18-19	3/9/2009	4400 Cyc/Lnd	7358	11758 Cyc/Ln	4777 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					3/28/2007		
725241			LP Turbine 1st Stage Disc Life Limit	3072070-5		TFE731-72-3001		0.0		
	Engine 2	MAN		5-03229-4009	18-19	3/9/2009	4400 Cyc/Lnd	4338	8738 Cyc/Lnd	1807 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					3/17/1996		
725243			LP Turbine 2nd Stage Disc Life Limit	3072069-5		TFE731-72-3001		0.0		
	Engine 1	MAN		5-03229-4013	18-19	3/9/2009	4500 Cyc/Lnd	4383	8883 Cyc/Lnd	1902 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					3/8/1996		
725243			LP Turbine 2nd Stage Disc Life Limit	3072069-5		TFE731-72-3001		0.0		
	Engine 2	MAN		5-03229-3311	18-19	3/9/2009	4500 Cyc/Lnd	4338	8838 Cyc/Lnd	1907 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					3/17/1996		
725245			LP Turbine 3rd Stage Disc Life Limit	3072068		TFE731-72-3001		0.0		
	Engine 1	MAN		0-18040-7500	18-19	3/9/2009	9500 Cyc/Lnd	0	9500 Cyc/Lnd	2519 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
725245			LP Turbine 3rd Stage Disc Life Limit	3072068-1		TFE731-72-3001		0.0		
	Engine 2	MAN		0-18040-7671	18-19	3/9/2009	9500 Cyc/Lnd	0	9500 Cyc/Lnd	2569 Cyc/Lnd
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
725247			LP Turbine Rotating Seal Tracking	3072621		TFE731-72-3001		0.0		
	Engine 1	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		
725247			LP Turbine Rotating Seal Tracking	3072621		TFE731-72-3001		0.0		
	Engine 2	INF			18-19	3/9/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]					9/17/1981		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
73 -- ENGINE FUEL/CONTROL										
730005			Engine Fuel Filter Replacement			72-02-01	600 Hrs	8260.0	8860.0 Hrs	168.8 Hrs
	Engine 1	MAN			612	3/12/2007		6685		
	Mfg#: N/A		Notes: [Initial Date Req.] [50 Hour Window] [CUSTOM FREQUENCY]					4/13/2007		
730005			Engine Fuel Filter Replacement			72-02-01	600 Hrs	8175.0	8775.0 Hrs	168.8 Hrs
	Engine 2	MAN			612	3/12/2007		6634		
	Mfg#: N/A		Notes: [Initial Date Req.] [50 Hour Window] [CUSTOM FREQUENCY]					4/13/2007		
76 -- ENGINE CONTROLS										
76-11-001.3			LH Engine Fuel Computer ITT Signal Functional Test			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			6	12/12/2008		7225		
	Mfg#: E7611001		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
76-11-001.4			RH Engine Fuel Computer ITT Signal Functional Test			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
	Airframe	MAN			6	12/12/2008		7225		
	Mfg#: E7611001		Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		

ATA			Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (* =Overfly)	Remaining Hrs/Cyc/Cal
Due	Logbook	App			Notes	Serial Number				
78 -- EXHAUST										
78-10-005.3			LH Engine Exhaust Nozzle Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
Airframe	MAN				6	12/12/2008		7225		
Mfg#: E7810005			Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
78-10-005.4			RH Engine Exhaust Nozzle Inspection			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
Airframe	MAN				6	12/12/2008		7225		
Mfg#: E7810005			Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
78-30-086-A1.1			LH Aeronca Thrust Reverser 150 Hr Periodic Inspection			45-1000	150 Hrs	8867.0	9017.0 Hrs	146.6 Hrs
Airframe	MAN				2	9/17/2004		7607		
Mfg#: P7830086			Notes: [Initial Date Req.] [50 Hour Window]					3/12/2009		
78-30-086-A1.2			RH Aeronca Thrust Reverser 150 Hr Periodic Inspection			45-1000	150 Hrs	8867.0	9017.0 Hrs	146.6 Hrs
Airframe	MAN				2	9/17/2004		7607		
Mfg#: P7830086			Notes: [Initial Date Req.] [50 Hour Window]					3/12/2009		
78-30-086-A2.1			LH Aeronca Thrust Reverser 300 Hr Periodic Inspection			45-1000	300 Hrs	8867.0	9167.0 Hrs	296.6 Hrs
Airframe	MAN				2	9/17/2004		7607		
Mfg#: P7830086			Notes: [Initial Date Req.] [100 Hour Window]					3/12/2009		
78-30-086-A2.2			RH Aeronca Thrust Reverser 300 Hr Periodic Inspection			45-1000	300 Hrs	8867.0	9167.0 Hrs	296.6 Hrs
Airframe	MAN				2	9/17/2004		7607		
Mfg#: P7830086			Notes: [Initial Date Req.] [100 Hour Window]					3/12/2009		
78-30-086-A3.1			LH Aeronca Thrust Reverser 600 Hr Periodic Inspection			45-1000	600 Hrs	8867.0	9467.0 Hrs	596.6 Hrs
Airframe	MAN				2	9/17/2004		7607		
Mfg#: P7830086			Notes: [Initial Date Req.] [200 Hour Window]					3/12/2009		
78-30-086-A3.2			RH Aeronca Thrust Reverser 600 Hr Periodic Inspection			45-1000	600 Hrs	8867.0	9467.0 Hrs	596.6 Hrs
Airframe	MAN				2	9/17/2004		7607		
Mfg#: P7830086			Notes: [Initial Date Req.] [200 Hour Window]					3/12/2009		
78-30-086-A5.1			LH Aeronca Thrust Reverser Major Periodic Inspection			45-1000	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
Airframe	MAN				2	7/15/1996		7225		
Mfg#: P7830086			Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		
78-30-086-A5.2			RH Aeronca Thrust Reverser Major Periodic Inspection			45-1000	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs
Airframe	MAN				2	7/15/1996		7225		
Mfg#: P7830086			Notes: [Initial Date Req.] [100 Hour Window]					1/18/2007		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining	
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal	
79 -- OIL											
790005			Engine Oil Change (Mobil 254/Exxon2197/BP 2197)	Post SB 72-3596 or 72-366		72-02-01	1200 Hrs	8260.0	9460.0 Hrs	768.8 Hrs	
	Engine 1	REC				311	9/26/2008	6685			
	Mfg#: N/A		Notes: [Initial Date Req.] [50 Hour Window] [CUSTOM FREQUENCY]						1/18/2007		
790005			Engine Oil Change (Mobil 254/Exxon2197/BP 2197)	Post SB 72-3596 or 72-366		72-02-01	1200 Hrs	8175.0	9375.0 Hrs	768.8 Hrs	
	Engine 2	REC				311	9/26/2008	6634			
	Mfg#: N/A		Notes: [Initial Date Req.] [50 Hour Window] [CUSTOM FREQUENCY]						1/18/2007		
80 -- STARTING											
80-10-004.3			LH Engine Starter Oil Change			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs	
	Airframe	MAN				7	12/12/2008	7225			
	Mfg#: E8010004		Notes: [Initial Date Req.] [100 Hour Window]						1/18/2007		
80-10-004.4			RH Engine Starter Oil Change			MM-99	1400 Hrs	8289.7	9689.7 Hrs	819.3 Hrs	
	Airframe	MAN				7	12/12/2008	7225			
	Mfg#: E8010004		Notes: [Initial Date Req.] [100 Hour Window]						1/18/2007		
91 -- AIRCRAFT MODIFICATION KITS (AMK)											
917501.1			AMK 75-1B R1 Doors - Replacement of Lower 24- Inch Cabin Door JAMB	2481129-1, -2		AMK 75-1B		0.0			
	Airframe	REC					3/9/2009	0			
			Notes: [Initial Date Req.]								
919105.1			AMK 91-05 R1 Installation of Electrically Heated Windshield Defog Temperature Sensors	2684153-1		AAK 91-05		0.0			
	Airframe	OPT					2/16/2009	0			
			Notes: [Initial Date Req.]								
92 -- CUSTOM CODES / ACCESSORY KITS											
928602.1			AAK 86-2 R1 Installallation of Landing Gear Actuator Down Lock Switch Connectors			AAK 86-2		0.0			
	Airframe	OPT					9/22/2008	0			
	Mfg#: N/A		Notes: [Initial Date Req.]								
928915.1			AAK 89-15 R1 Install Improved Wing Dry Bay Drains			AAK 89-15		0.0			
	Airframe	OPT					2/9/2009	0			
	Mfg#: N/A		Notes: [Initial Date Req.]								

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
93 -- SPECIAL SPARES KITS (SSK)										
930928.1			SSK 928 R1 Seal Replacement - Auxiliary Hydraulic Pump (ADEL)			SSK 928		0.0		
	Airframe	OPT	Notes: [Initial Date Req.]			5/4/2009		0		
930938.1			SSK 0938B R1 Replacement of Aileron Assembly			SSK 0938B		0.0		
	Airframe	OPT	Notes: [Initial Date Req.]			8/11/2008		0		
930976.1			SSK 976 R1 Replacement of Flap Attachment Fitting Castings			SSK 976		0.0		
	Airframe	OPT	Notes: [Initial Date Req.]			4/20/2009		0		
	Mfg#: N/A									
930980.1			SSK 0980 R1 Replacement of Air Conditioning Evaporator Assembly			SSK 0980		0.0		
	Airframe	OPT	Notes: [Initial Date Req.]			6/8/2009		0		
930995.1			SSK 0995 R1 Installation of Spare Elevators - Aircraft Equipped for 45,000 Foot Operation			SSK 0955		0.0		
	Airframe	OPT	Notes: [Initial Date Req.]			4/20/2009		0		
95 -- APU/ENG SERVICE BULLETINS										
950072-3748			SB 72-A3748 Replace Specific Identified LPC2 and LPC3 Rotor Disks			TFE731-72-A3748		8641.7		
	Engine 1	MAN	Notes: Does Not Apply to the -2B Engines [Initial Date Req.]			8/21/2008		6954		9/30/2008
950072-3748			SB 72-A3748 Replace Specific Identified LPC2 and LPC3 Rotor Disks			TFE731-72-A3748		8556.7		
	Engine 2	MAN	Notes: Does Not Apply to the -2B Engines [Initial Date Req.]			8/21/2008		6904		9/30/2008

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
97 -- AIRCRAFT SERVICE CHANGES										
979000.ST01524LA*	STC ST01524LA - Rosemount Pitot-Static Probe Installation			856NA-1 / -2	STC ST01524LA			7239.3		
Airframe	MAN							6365		
Mfg#: N/A	Notes: [Initial Date Req.]							9/2/2004		
979000.ST01525LA*	STC ST01525LA - RVSM Avionics Equipment Installation				STC ST01525LA			7239.3		
Airframe	MAN							6365		
Mfg#: N/A	Notes: [Initial Date Req.]							9/2/2004		
979000.ST01526LA*	STC ST01526LA - Approval Basis for RVSM				STC ST01526LA			7239.3		
Airframe	MAN							6365		
Mfg#: N/A	Notes: [Initial Date Req.]							9/2/2004		
98 -- CUSTOMER/SERVICE BULLETINS										
982118.3	SB 35/36-21-18 R3 Imprv Wndshld Aux Defog & Heat Sys			AAK 86-1	SB 35/36-21-18			0.0		
Airframe	OPT					8/11/2008		0		
Mfg#: N/A	Notes: [Initial Date Req.]									
982304	SB 35/36-23-4 Replacement of Cockpit Speakers				SB 35/36-23-4			0.0		
Airframe	OPT					7/14/2008		0		
	Notes: [Initial Date Req.]									
982415.1	SB 35/36-24-15 R1 Instl of Concorde Sealed LeadAcid Batt				SB 35/36-24-15			8780.4		
Airframe	OPT					3/24/2008		7561		
Mfg#: N/A	Notes: N/A Equipment not installed at this time [Initial Date Req.]							6/16/2008		
982604.1	SB 35/36-26-4 R1 Inspection / Replacement of the Engine Fire Detect Elements				SB 35/36-26-4			0.0		
Airframe	REC					8/11/2008		0		
	Notes: [Initial Date Req.]									
982816.1	SB 35/36-28-16 R1 Replace Fuel Quantity Selector Switch				SB 35/36-28-16			0.0		
Airframe	OPT					4/14/2008		0		
Mfg#: N/A	Notes: [Initial Date Req.]									
983011.3	SB 35/36-30-11 R3 Installation of High Current Capacity Wire for Pitot Heat Switch				SB 35/36-30-11			0.0		
Airframe	REC					5/5/2008		0		
Mfg#: N/A	Notes: [Initial Date Req.]									
983104	SB 35/36-31-4 Installation of Cabin Altitude Warning System (Aircraft with Auto Emergency Air)			3581206-801	SB 35/36-31-4			0.0		
Airframe	REC					1/19/2009		0		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
Notes: [Initial Date Req.]										
983216.3			SB 35/36-32-16 R3 Replacement of Left Main Landing Gear Strut Cylinder			SB 35/36-32-16		0.0		
	Airframe	OPT				7/7/2008		0		
	Mfg#: N/A		Notes: [Initial Date Req.]							
983216.3.1			SB 35/36-32-16 R3 Replacement of Right Main Landing Gear Strut Cylinder			SB 35/36-32-16		0.0		
	Airframe	OPT				7/7/2008		0		
	Mfg#: N/A		Notes: [Initial Date Req.]							
985209.3			SB 35/36-52-9 R3 Replc Cabin Door Lock Switch			SB 35/36-52-9		0.0		
	Airframe	OPT				5/19/2008		0		
	Mfg#: N/A		Notes: [Initial Date Req.]							
985311.3			SB 35/36-53-11 R3 Modification of Tailcone Ballast Weight Installation	3181021-801		SB 35/36-53-11		0.0		
	Airframe	REC				6/1/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]							
985504.1			SB 35/36-55-4 R1 Inst Doublers on Horizontal Stab Skin			SB 35/36-55-4		8780.4		
	Airframe	OPT				3/3/2008		7561		
	Mfg#: N/A		Notes: N/A SB does not apply to this serial number aircraft, effective on 35-002 thru 35-400 [Initial Date Req.]					6/16/2008		
985504.2			SB 35/36-55-4 R2 Installation of Doublers on Horizontal Stabilizer Skins	2381429-1		SB 35/36-55-4		0.0		
	Airframe	OPT				2/23/2009		0		
	Mfg#: N/A		Notes: [Initial Date Req.]							
99 -- AIRWORTHINESS DIRECTIVES										
990078			AD 82-01-05 R2 Stall Warning Accelerometer Inspection			AD 82-01-05	220 Hrs	8701.8	8921.8 Hrs	51.4 Hrs
*	Airframe	MAN				4/10/1986		7503		
	Mfg#: N/A		Notes: [Initial Date Req.]					1/11/2008		
990102.1			AD 87-02-06 LH Engine Mount Visual Inspection			AD 87-02-06	420 Hrs	8701.8	9121.8 Hrs	251.4 Hrs
	Airframe	MAN				2/6/1987		7503		
	Mfg#: N/A		Notes: [Initial Date Req.]					1/11/2008		
990102.2			AD 87-02-06 RH Engine Mount Visual Inspection			AD 87-02-06	420 Hrs	8701.8	9121.8 Hrs	251.4 Hrs
	Airframe	MAN				2/6/1987		7503		
	Mfg#: N/A		Notes: [Initial Date Req.]					1/11/2008		
990102.3			AD 87-02-06 LH Engine Mount NDT Inspection			AD 87-02-06	1500 Hrs	8289.7	9789.7 Hrs	919.3 Hrs
	Airframe	MAN				2/6/1987		7225		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
			Mfg#: N/A	Notes: Inspected affected components IAW Para A&B of AD Serviceable Serviceable [Initial Date Req.]				1/18/2007		
990102.4			AD 87-02-06 RH Engine Mount NDT Inspection			AD 87-02-06	1500 Hrs	8289.7	9789.7 Hrs	919.3 Hrs
	Airframe	MAN				2/6/1987		7225		
			Mfg#: N/A	Notes: Inspected affected components IAW Para A&B of AD Serviceable [Initial Date Req.]				1/18/2007		
990192			AD 2004-03-08 Forward Engine Beam Shear Web Inspection	Greater than 3000 hours T		AD 2004-03-08	1200 Hrs	8205.4	9405.4 Hrs	535.0 Hrs
	Airframe	MAN				3/15/2004		7169		
			Mfg#: N/A	Notes: [1200 Initial Hour Req.] [3/15/2005 Initial Date Req.]				12/8/2006		
990213			AD 2007-04-18 Standby Fuel Pump Switches Mod			AD 2007-04-18		8867.0		
	Airframe	MAN				3/23/2007		7607		
			Mfg#: N/A	Notes: Installed Service Kit for SB35/36-28-11 [3/23/2009 Initial Date Req.]				1/23/2009		
990213.1			AD 2007-04-18 Standby Fuel Pump Switches AFM Revision			AD 2007-04-18		8867.0		
	Airframe	MAN				3/23/2007		7607		
			Mfg#: N/A	Notes: Installed Service Kit for SB35/36-28-11 [3/23/2009 Initial Date Req.]				1/23/2009		
990219			AD 2007-17-17 Unsealed Gaps in the Engine Firewall			AD 2007-17-17		8820.9		
	Airframe	MAN				10/2/2007		7584		
			Mfg#: N/A	Notes: [10/2/2008 Initial Date Req.]				10/1/2008		
991094			AD 2000-15-09 HPC Impeller Eddy Current Inspection			AD 2000-15-09	4200 Hrs	8260.0	12460.0 Hrs	3768.8 Hrs
	Engine 1	MAN				10/10/2000		6685		
			Mfg#: N/A	Notes: Next due scheduled from last CZI [Initial Date Req.]				4/13/2007		
991094			AD 2000-15-09 HPC Impeller Eddy Current Inspection			AD 2000-15-09	4200 Hrs	8175.0	12375.0 Hrs	3768.8 Hrs
	Engine 2	MAN				10/10/2000		6634		
			Mfg#: N/A	Notes: Next due scheduled from last CZI [Initial Date Req.]				4/13/2007		
991100.1			AD 2005-05-15 1st Stage LPT Disk Inspection	3072070-XX or 3073013-		AD 2005-05-15	2200 Hrs	8260.0	10460.0 Hrs	1768.8 Hrs
	Engine 1	MAN				4/18/2005		6685		
			Mfg#: N/A	Notes: Next due scheduled from last MPI [2200 Initial Hour Req.] [Initial Date Req.]				4/13/2007		
991100.1			AD 2005-05-15 1st Stage LPT Disk Inspection	3072070-XX or 3073013-		AD 2005-05-15	2200 Hrs	8175.0	10375.0 Hrs	1768.8 Hrs
	Engine 2	MAN				4/18/2005		6634		
			Mfg#: N/A	Notes: Next due scheduled from last MPI [2200 Initial Hour Req.] [Initial Date Req.]				4/13/2007		
999018			AD 74-08-09 R2 Inspect Lavatory Receptacles Placards			AD 74-08-09	1000 Hrs	8614.9	9614.9 Hrs	744.5 Hrs
	Airframe	MAN				7/29/1996		7432		
				Notes: Verified proper fit of receptacle doors & proper installation & legibility of required placards [Initial Date Req.]				8/18/2007		

ATA			Description	Part Number	Source Document		Frequency	Complied With	Next Due	Remaining
Due	Logbook	App	Notes	Serial Number	Page	Date Issued	(**=Initial)	Hrs/Cyc/Date	(*=Overfly)	Hrs/Cyc/Cal
999708			AD 2009-05-05 (Effective Date: April 3, 2009) Avidyne Corporation Primary Flight Displays (PFDs) (SUPERSEDES AD 2008-06-28 R1)			AD 2009-05-05		8867.0		
	Airframe	MAN				4/3/2009		7607		
			Notes: AD does not apply by equipment, equipment not installed on this aircraft [4/18/2009 Initial Date Req.]					4/25/2009		
999711			AD 2009-05-08(Effective Date: April 20, 2009) Trimble or FreeFlight Systems 2101 Input/Output Approach Plus GPS Navigation Systems			AD 2009-05-08		0.0		
	Airframe	MAN				4/20/2009		0		
	Mfg#: N/A		Notes: [10/18/2009 Initial Date Req.]						10/18/2009	103 Days
999714.1			AD 2009-08-01 (Effective Date: May 14, 2009) Honeywell NZ-2000, IC-800, or IC-800E Navigation Computers Terminating Action (SUPERSEDES AD 2007-07-12)			AD 2009-08-01		0.0		
	Airframe	MAN				5/14/2009		0		
			Notes: [5/14/2010 Initial Date Req.]						05/14/2010	10 Mos