

OWNER: ZIVER HAVACILIK INS.SAN.TIC A.S
ADDRESS: YILDIZEVLER MAH.718, CAD. NO: 12/4
 CANKAYA ANKARA
PHONE:
FAX:

OPERATOR: ZIVER HAVACILIK INS.SAN.TIC A.S
ADDRESS: YILDIZEVLER MAH.718, CAD. NO: 12/4
 CANKAYA ANKARA
PHONE:
FAX:

ANALYST: MELVIN BRUNET
EMAIL: MELVIN.BRUNET@CAMPSYSTEMS.EU

+33-1.55.93.47.84 (DIRECT)
 +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 560-0212/TC-LAA **MODEL:** 560 - CITATION V **MANUFACTURER:** TEXTRON AVIATION INC.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	28-APR-1993	5592:57 A/C HRS	as of 19-NOV-2019	_____ A/C HRS	as of ____/____/____
		4106 AFL	as of 19-NOV-2019	_____ AFL	as of ____/____/____
		4973 ACH	as of 28-OCT-2019	_____ ACH	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: 108431/JT15D-5A **MODEL:** JT15D-5A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 23-JUN-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	3436 A/C HRS	5592:57 ENG. HRS	as of 19-NOV-2019	_____ ENG. HRS	as of ____/____/____
ENC		4106 ENC	as of 19-NOV-2019	_____ ENC	as of ____/____/____

ENGINE NO. 2 SERIAL/PART: 108435/JT15D-5A **MODEL:** JT15D-5A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 23-JUN-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	3436 A/C HRS	5592:57 ENG. HRS	as of 19-NOV-2019	_____ ENG. HRS	as of ____/____/____
ENC		4106 ENC	as of 19-NOV-2019	_____ ENC	as of ____/____/____



Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
5-12-01	PHASE 1								
	PKG 1	MOS	24				26-AUG-2019	26-AUG-2021	
		HRS/MSC	300				5545	5845	
	REF: TLMC 5-12-01	AFL					4067		
5-12-02	PHASE 2								
	PKG 2	MOS	24				26-AUG-2019	26-AUG-2021	
		HRS/MSC	300				5545	5845	
	REF: TLMC 5-12-02	AFL					4067		
5-12-03	PHASE 3								
	PKG 3	MOS	24				26-JUN-2019	26-JUN-2021	
		HRS/MSC	300				5474	5774	
	REF: TLMC 5-12-03	AFL					4015		
5-12-04	PHASE 4								
	PKG 4	MOS	24				26-JUN-2019	26-JUN-2021	
		HRS/MSC	300				5474	5774	
	REF: TLMC 5-12-04	AFL					4015		
5-12-05	PHASE 5								
	PKG 7	MOS	36				12-DEC-2017	28-OCT-2019 M	
		HRS/MSC	1200				5122	6322	
	REF: TLMC 5-12-05	AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-06	PHASE 6								
	PKG 8	DAYS					27-NOV-2017		
	REF: TLMC 5-12-06	HRS/MSC AFL	O/C						
<hr/>									
5-12-08 (s)	PHASE 8 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 10	MOS					28-APR-1993		
	REF: TLMC 5-12-08	HRS/MSC AFL	N/A				0 0		
<hr/>									
5-12-0B	PHASE B								
	PKG 15	MOS					06-AUG-2019		
	REF: TLMC 5-12-0B	HRS/MSC AFL	150				5524 4050	5674	
<hr/>									
5-12-11	PHASE 11								
	PKG 16	MOS	6				14-MAY-2019	14-NOV-2019	
	REF: TLMC 5-12-11	HRS/MSC AFL					5441 3993		
<hr/>									
5-12-13	PHASE 13								
	PKG 17	MOS					20-MAY-2009		
	REF: TLMC 5-12-13	HRS/MSC AFL	5000				4546	9546	

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-14	PHASE 14								
	PKG 18	MOS					28-APR-1993		
		HRS/MSC	12000				0		12000
	REF: TLMC 5-12-14	AFL					0		
5-12-15	PHASE 15								
	PKG 19	MOS					28-APR-1993		
		HRS/MSC	10000				0		10000
	REF: TLMC 5-12-15	AFL					0		
5-12-16	PHASE 16								
	PKG 20	MOS					28-APR-1993		
		HRS/MSC	10000				0		10000
	REF: TLMC 5-12-16	AFL					0		
5-12-17	PHASE 17								
	PKG 21	MOS					28-APR-1993		
		HRS/MSC	10000				0		10000
	REF: TLMC 5-12-17	AFL					0		
5-12-18	PHASE 18								
	PKG 22	MOS	12				11-DEC-2018		11-DEC-2019
		HRS/MSC					5384		
	REF: TLMC 5-12-18	AFL					3938		
	Note:	PHASE 56 SHOULD BE ACCOMPLISHED IN CONJUNCTION WITH THE PHASE 18. PHASE 56 ADDED PER REV 21 TO 560 MM. OCTOBER 2005							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-20 (s)	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 24	MOS	24				17-MAY-2018		
		HRS/MSC					5179		
	REF: TLMC 5-12-20	AFL					3793		
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 35	MOS	24				27-NOV-2017	27-NOV-2019	
		HRS/MSC					5121:17		
	REF: TLMC 5-12-21	AFL					3709		
5-12-28 (s)	PHASE 28 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 44	MOS	12				08-OCT-2019		
		HRS/MSC	200				5574		
	REF: TLMC 5-12-28	AFL					4090		
5-12-30	PHASE 30								
	PKG 45	MOS					10-OCT-2018		
		HRS/MSC	600				5351:24	5951:24	
	REF: TLMC 5-12-30	AFL					3910		
5-12-32	PHASE 32								
	PKG 46	MOS					28-APR-1993		
		HRS/MSC					0		
	REF: TLMC 5-12-32	AFL	15000				0	15000	

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-33	PHASE 33								
	PKG 47	MOS					28-APR-1993		
		HRS/MSC					0		
	REF: TLMC 5-12-33	AFL	15000				0		15000
<hr/>									
5-12-34	PHASE 34								
	PKG 48	MOS					28-APR-1993		
		HRS/MSC	6725				0		6725
	REF: TLMC 5-12-34	AFL					0		
<hr/>									
5-12-48 (s)	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 54	MOS	72				10-FEB-2011		
		HRS/MSC					4641		
	REF: TLMC 5-12-48	AFL					3277		
<hr/>									
5-12-49	PHASE 49								
	PKG 57	MOS	36				14-MAY-2019		14-MAY-2022
		HRS/MSC	1200				5441		6641
	REF: TLMC 5-12-49	AFL					3993		
<hr/>									
5-12-54	PHASE 54								
	PKG 63	MOS					13-MAY-2016		
		HRS/MSC	N/A				5113		
	REF: See Workcard	AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-56	PHASE 56								
	PKG 65	MOS	12				11-DEC-2018	11-DEC-2019	
		HRS/MSC					5384		
	REF: TLMC 5-12-56	AFL					3938		
<hr/>									
5-12-59	PHASE 59 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 112	MOS					11-DEC-2018		
		HRS/MSC	A/R				5384		
	REF: TLMC 5-12-59	AFL					3938		
<hr/>									
5-12-60	PHASE 60								
	PKG 68	MOS					26-JUN-2019		
		HRS/MSC	500				5474	5974	
	REF: TLMC 5-12-60	AFL					4015		
<hr/>									
5-12-61	PHASE 61								
	PKG 246	MOS					28-APR-1993		
		HRS/MSC	13200				0	13200	
	REF: TLMC 5-12-61	AFL					0		
<hr/>									
5-12-62	PHASE 62								
	PKG 247	MOS					28-APR-1993		
		HRS/MSC	15600				0	15600	
	REF: TLMC 5-12-62	AFL					0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-63	PHASE 63								
	PKG 248	MOS					28-APR-1993		
		HRS/MSC	15600				0		15600
	REF: TLMC 5-12-63	AFL					0		
5-12-64	PHASE 64								
	PKG 503	MOS	6				14-MAY-2019		14-NOV-2019
		HRS/MSC					5441		
	REF: TLMC 5-12-64	AFL					3993		
5-12-65	PHASE 65								
	PKG 501	MOS					10-JUL-2014		29-JUL-2018 M
		HRS/MSC	500/-				4972		5472
	REF: TLMC 5-12-65	AFL					3668		
		ACH					4973		
5-12-66	PHASE 66								
	PKG 502	MOS					27-NOV-2017		
		HRS/MSC	6000				5121:17		11121:17
	REF: TLMC 5-12-66	AFL					3709		
5-12-67	PHASE 67								
	PKG 504	MOS					25-SEP-2013		
		HRS/MSC	1200				4917:36		6117:36
	REF: TLMC 5-12-67	AFL					3526		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-MC	PHASE MC						AIRWORTHINES S	
	PKG 70	MOS				20-MAY-2009		
	REF: TLMC 5-12-MC	HRS/MSC AFL	1456			4546		6002
5-12-MD	PHASE MD							
	PKG 71	MOS				23-JUN-2006		
	REF: TLMC 5-12-MD	HRS/MSC AFL	2523			3436		5959
5-12-ME	PHASE ME						AIRWORTHINES S	
	PKG 72	MOS				17-FEB-2012		
	REF: TLMC 5-12-ME	HRS/MSC AFL	4450			4757:36 3380		9207:36
5-12-MF	PHASE MF						AIRWORTHINES S	
	PKG 73	MOS				23-JUN-2006		
	REF: TLMC 5-12-MF	HRS/MSC AFL	5000			3436		8436
5-12-MG (s)	PHASE MG (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)						AIRWORTHINES S	
	PKG 74	MOS				28-APR-1993		
	REF: TLMC 5-12-MG	HRS/MSC AFL	10000			0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-MI	PHASE MI							AIRWORTHINES	S
	PKG 76	MOS					10-JUL-2014		
	REF: TLMC 5-12-MI	HRS/MSC	5130				4972		10102
		AFL					3668		
5-12-MJ	PHASE MJ							AIRWORTHINES	S
	PKG 77	MOS					28-APR-1993		
	REF: TLMC 5-12-MJ	HRS/MSC	5900				0		5900
		AFL					0		
5-12-MK	PHASE MK							AIRWORTHINES	S
	PKG 78	MOS					28-APR-1993		
	REF: TLMC 5-12-MK	HRS/MSC	6725				0		6725
		AFL					0		
5-12-ML	PHASE ML							N/A BY PART	NUMBER
	PKG 249	MOS					07-JUN-2013		
	REF: TLMC 5-12-ML	HRS/MSC	N/A				4894:06		
		AFL					3507		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
C561-191010	AUDIT - DESCRIPTION CHANGE FOR ITEM CODE 561002	MOS		TSI:0			(EBT)		
AUDIT SUMMARY CHANGE FORM	REF: RCF C561	HRS/MSC - AFL		TSI:0 TSI:0					
ENGINE NO. 1 Model : JT15D-5A Serial # 108431 Part # JT15D-5A									
E15A-180423	NO. 1 ENGINE - REVIEW PWC JT15D-5A EMM REV 34.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
E15A-181022	NO. 1 ENGINE - REVIEW JT15D-5A EMM REV 35.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
ENGINE NO. 2 Model : JT15D-5A Serial # 108435 Part # JT15D-5A									
E15A-180423	NO. 2 ENGINE - REVIEW PWC JT15D-5A EMM REV 34.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
E15A-181022	NO. 2 ENGINE - REVIEW JT15D-5A EMM REV 35.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
051218	INSPECT 3 PHASE 18 LIFE VEST	MOS	12				11-DEC-2018	11-DEC-2019	
	REF:	HRS/MSC AFL					5384 3938		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051220	TEST CALIBRATION (AIR DATA COMPUTER)	MOS	24				17-MAY-2018	17-MAY-2020	
	REF:	HRS/MSC					5179		
		AFL					3793		
053100	INSPECT FLIGHT DATA RECORDER	MOS	72				23-DEC-2015	23-DEC-2021	
	REF:	HRS/MSC							
		AFL							
053101	TEST/INSPECT FDR'S UNDER WATER LOCATOR BEACON	MOS	24				27-NOV-2017	27-NOV-2019	
	REF:	HRS/MSC					5121:17		
		AFL					3709		
053102	FLIGHT TEST -PERFORM A FDR DATA VERIFICATION FLIGHT	MOS	12				12-DEC-2017	12-DEC-2018	
	REF:	HRS/MSC	2000				5122	7122	
		AFL							
053103	SELF TEST -FDR AUTOMATIC TEST AT PERFLIGHT	MOS							
	REF:	HRS/MSC	A/R						
		AFL							
053416	VERIFY AVIONICS EQUIPMENT INSTALLED RVSM	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		
053417	CHECK AIR DATA SYSTEM RVSM ACCURACY	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
053418	INSPECT CRITICAL REGION CORNER MARKINGS RVSM VISUAL	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		
053419	INSPECT CRITICAL REGION MODIFICATION COMPLIANCE PLACARD RVSM VISUAL	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		
053420	CHECK CRITICAL REGION RVSM SKIN WAVINESS	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		
053421	INSPECT CRITICAL REGION RVSM VISUAL	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		
053422	INSPECT CRITICAL REGION STENCILS AND PLACARDS RVSM VISUAL	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		
053423	INSPECT CRITICAL REGION STATIC PORT DOUBLERS RVSM VISUAL	MOS	12				11-DEC-2018	31-DEC-2019	
	REF:	HRS/MSC					5384		
		AFL					3938		
053424	CHECK IN-FLIGHT AUTOPILOT RVSM ALTITUDE HOLD	MOS	24				12-DEC-2017	31-DEC-2019	
	REF:	HRS/MSC					5122		
		AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055013	EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED CHECK	MOS		TSI:0			28-APR-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: TLMC 5-50-00	HRS/MSC	A/R	TSI:0			0		
		AFL		TSI:0			0		

A361103 (s)	VISUAL INSPECTION PRECOOLER/HEAT EXCHANGER (AIRPLANES -0539 AND ON): PHASE 54						PKG		
	PKG 63	MOS					13-MAY-2016		
	REF: AMM 36-11-05	HRS/MSC	N/A				5113		
		AFL							

ENGINE NO. 1 Model : JT15D-5A Serial # 108431 Part # JT15D-5A

057110	NO. 1 ENGINE - MINOR INSPECTION	MOS	24				17-MAY-2018	17-MAY-2020	
	REF: EMM 72-00-00	HRS/MSC	300				5179	(5479) 5479	
		ENC					3793		

ENGINE NO. 2 Model : JT15D-5A Serial # 108435 Part # JT15D-5A

057110	NO. 2 ENGINE - MINOR INSPECTION	MOS	24				17-MAY-2018	17-MAY-2020	
	REF: EMM 72-00-00	HRS/MSC	300				5179	(5479) 5479	
		ENC					3793		

CHAPTER 08 LEVELING AND WEIGHING

081251	WEIGHT AND BALANCE	MOS	48				27-MAY-2019	27-MAY-2023	
08.010	REF: GENERIC NO REF	HRS/MSC					5458		
		AFL					3999		

CHAPTER 11 PLACARDS AND MARKINGS

A113001 (s)	INSPECT INTERIOR PLACARDS, EXTERIOR PLACARDS, DECALS, MARKINGS AND IDENTIFICATION PLATE: PHASE 5						PKG		
	PKG 7,101	MOS	36				12-DEC-2017		
11.010	REF: AMM 11-00-00	HRS/MSC	1200						
		AFL							

CHAPTER 12 SERVICING

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C122100 (s)	LUBRICATE NOSE GEAR TORQUE LINKS AND UPLOCK ROLLERS: PHASE 2						PKG		
12.005	PKG 2 REF: AMM 12-21-02	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
C122101 (s)	LUBRICATE MAIN LANDING GEAR: PHASE 2						PKG		
12.005	PKG 2 REF: AMM 12-21-02	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
CHAPTER 21 AIR CONDITIONING									
211002	EMERGENCY PRESSURE VALVE								
21.020	27441482-06 7AH16 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
211004	S243 PRIMARY PRESSURE SWITCH								
21.010	1103P240-1 599 REF: AMM 21-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
211005	S244 SECONDARY PRESSURE SWITCH								
21.010	1103P240-2 555 REF: AMM 21-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
212001	INSTRUMENT PANEL FAN								
21.040	4124X SN-UNKNOWN REF: AMM 21-24-00	MOS HRS/MSC AFL	O/C	TSO:15 TSN:0			28-APR-1993 0 0		
212002	AVIONICS BAY COOLING BOX FAN								
21.050	032105 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:15 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212004	OVERHEAD CABIN FAN BC61A901-2EX 3263A REF: GENERIC NO REF	MOS HRS/MSC AFL	1000	TSN:0			26-AUG-2019 5545 4067	6545	
212006	COCKPIT DEFOGGER FAN 5703-4 0082 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSO:0			23-JUN-2006 3436	6936	
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR NYLC50466 1186 REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
212010	AVIONICS BAY VANE AXIAL BLOWER 19A827 NSN REF: AMM 21-25-00	MOS HRS/MSC AFL	O/C	TSN:0			07-MAY-2008 4224		
212011	TEMP DUCT SENSOR 27221274 10AH170 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
213001	CABIN PRESSURE INDICATOR C668511-0103 19674 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
213003	RATE OF CHANGE INDICATOR C668513-0101 W30653 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213006	CABIN ALTITUDE CONTROLLER 130620-2 12A0016 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0			06-JUL-1999 1511		
213007	NO. 1 PRIMARY OUTFLOW VALVE 103648-14 112584 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
213007	NO. 2 SECONDARY OUTFLOW VALVE 103648-14 91572 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
213009	NO. 1 FLOW CONTROL PRESSURE REGULATOR VALVE 34E16-4 GWD03843 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
213009	NO. 2 FLOW CONTROL PRESSURE REGULATOR VALVE 34E16-4 GWD03839 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
213013	PNEUMATIC RELAY 130358-1 722016 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY 782343-2 930139 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215004	AIR CYCLE MACHINE 738384-26	MOS					30-APR-2013		
21.140 OVERHAUL	200107134 REF: AMM 21-51-00	HRS/MSC AFL	5000	TSO:0			4885 3500	9885	
<p>Note: RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.</p>									
215005	ACM BYPASS VALVE 754751-2	MOS					20-FEB-2001		
21.150	200004051 REF: AMM 21-51-00	HRS/MSC AFL	O/C	TSN:0			1935		
215007	COMPRESSION ACTUATOR BYLB50907	MOS					28-APR-1993		
21.480	597 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
215008	DUCT OVERHEAT SENSOR 1173T42-1	MOS					28-APR-1993		
21.150	2360 REF: AMM 21-60-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
215009	ACM OVERHEAT SWITCH 1173T0635	MOS					17-JUN-2011		
21.150	SN-UNKNOWN REF: AMM 21-51-00	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			4657:12 3284		
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY) 1250151	MOS					(EBT)		
N/A EQUIPMENT NOT INSTALLED	2324 REF:	HRS/MSC AFL	N/R	TSI:0 TSI:0 TSI:0					

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215016	AC COMPRESSOR 1250160 1985 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:0			07-MAY-2008 4224		
21.160									
215017	AC CONDENSER 1250180-7 788 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
21.160									
215018	ACM CONTROL UNIT C35020A 1434 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
21.170									
215021	MOTOR 1250151 2324 REF:	MOS HRS/MSC AFL	O/C	TSN:0			19-JUN-2002 2322		
21.140									
215022	AFT EVAPORATOR 1250240-23 1177 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			20-OCT-2017		
21.200									
215023	FWD EVAPORATOR 1250240-22 167 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			20-OCT-2017		
21.200									
215024	PRESSURE SWITCH 1250232-4 1278 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
21.190									

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216001	CABIN TEMPERATURE SENSOR 1942T100-11	MOS					28-MAR-2001		
21.220	782 REF: AMM 21-60-00	HRS/MSC AFL	O/C	TSN:0			1956		
216002	CABIN TEMPERATURE CONTROLLER 754661-5	MOS					28-APR-1993		
21.220	91070168 REF: AMM 21-60-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
216003	DUCT TEMPERATURE SENSOR 754691-1	MOS					28-APR-1993		
21.220	92091855 REF: AMM 21-60-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
216005	CENTRIFUGAL BLOWER 3A1003-10	MOS					28-APR-1993		
21.210	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
216010	DOOR ACTUATOR MOTOR ASSEMBLY 5A3032	MOS					28-APR-1993		
21.500	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
217001	WATER SEPARATOR 738386-3	MOS					28-APR-1993		
21.230	920314 REF: AMM 21-70-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
21FO-02 560	COOLING/FREON SUPPLEMENTAL FACTORY OPTION 15A	MOS					28-APR-1993		
	FO REF:	HRS/MSC AFL	-				0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A215001 (s) 21.240	CHECK AIR CYCLE MACHINE: PHASE 2 PKG 2,4,15 REF: AMM 21-51-00	MOS HRS/MSC AFL	150				PKG 26-AUG-2019 5545 4067		
A215200 (s) N/A BY PART NUMBER	PERFORM VAPOR CYCLE COOLING SYSTEM HOUR METER CHECK (COMPRESSOR MOTORS 1134104-1, -5 OR FWA1134104-1, -5 ONLY): PHASE ML PKG 249 REF: AMM 21-52-00	MOS HRS/MSC AFL	N/A				PKG 07-JUN-2013 4894:06 3507		
A215201 (s)	PERFORM 500 COMPRESSOR HOUR MAINTENANCE CHECK ON VAPOR CYCLE COOLING SYSTEM: PHASE 65 PKG 501 REF: AMM 21-52-00	MOS HRS/MSC AFL ACH	500				PKG 10-JUL-2014 4972 3668 4973		
A215202 (s)	PERFORM 12 MONTH MAINTENANCE CHECK OF VAPOR CYCLE COOLING SYSTEM: PHASE 18 PKG 22 REF: AMM 21-52-00	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
A217001 (s) 21.270	INSPECT HUMIDITY REGULATOR: PHASE 2 PKG 2 REF: AMM 21-70-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
B210000 (s) 21.280	OPERATIONAL CHECK ENVIRONMENTAL SYSTEM: PHASE 5 PKG 7,102 REF: AMM 21-00-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B211001 (s) 21.290	OPERATIONAL TEST EMERGENCY PRESSURIZATION VALVE: PHASE 4 PKG 4 REF: AMM 21-11-00	MOS HRS/MSC AFL	24 300				PKG 26-JUN-2019 5474 4015		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B211002 (s) 21.300	OPERATIONAL TEST FLOW CONTROL SHUTOFF AND CHECK VALVES: PHASE 5 PKG 7,104 REF: AMM 21-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B211003 (s) 21.310	OPERATIONAL TEST FLOW CONTROL SHUTOFF AND CHECK VALVES: PHASE 2 PKG 2,4,15 REF: AMM 21-11-00	MOS HRS/MSC AFL	150				PKG 26-AUG-2019 5545 4067		
B211004 (s) 21.320	OPERATIONAL TEST EMERGENCY PRESSURIZATION VALVE: PHASE 4 PKG 4 REF: AMM 21-11-00	MOS HRS/MSC AFL	24 300				PKG 26-JUN-2019 5474 4015		
B212001 (s) 21.330	LEAK CHECK TAILCONE BLEED AIR LINES: PHASE 5 PKG 7,106 REF: AMM 36-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B212002 (s) 21.340	OPERATIONAL CHECK VERTICAL SCALE INSTRUMENT PANEL COOLING FAN: PHASE 5 PKG 7,108 REF: AMM 21-24-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B212003 (s) 21.350	OPERATIONAL CHECK AVIONICS BAY COOLING FANS: PHASE 5 PKG 7,102 REF: AMM 21-25-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B213000 (s) 21.360	OPERATIONAL CHECK PRESSURIZATION: PHASE 5 PKG 7,102 REF: AMM 21-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B213001 (s) 21.370	FUNCTIONAL TEST BAROMETRIC CABIN ALTITUDE PRESSURE SWITCH: PHASE 5 PKG 7,102 REF: AMM 21-31-05	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B213005 (s) 21.380	OPERATIONAL CHECK PRESSURIZATION SYSTEM: PHASE 5 PKG 7,102 REF: AMM 21-32-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B213006 (s) 21.390	FUNCTIONAL TEST OUTFLOW VALVE CABIN ALTITUDE LIMITER: PHASE 5 PKG 7,110 REF: AMM 21-32-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
C215001 (s) 21.400	CHANGE OIL AIR CYCLE MACHINE: PHASE 30 PKG 45 REF: AMM 21-51-00	MOS HRS/MSC AFL	600				PKG 10-OCT-2018 5351:24 3910		
D213001 (s) 21.410	CLEAN/REPLACE PRESSURIZATION CONTROLLER: PHASE 5 PKG 7,102 REF: AMM 21-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
D213003 (s) 21.420	REPLACE PNEUMATIC RELAY CARTRIDGE FILTER: PHASE 5 PKG 7,110 REF: AMM 21-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
D213004 (s) 21.430	CLEAN/REPLACE SOLENOID VALVE FILTER: PHASE 5 PKG 7,110 REF: AMM 21-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

CHAPTER 22 AUTO FLIGHT

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221001	NO. 1 ROLL RATE MONITOR- 4015901-920	MOS					28-APR-1993		
22.060	92091948 REF: AMM 22-11-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
221001	NO. 2 ROLL RATE MONITOR- 4015901-920	MOS					28-APR-1993		
22.060	92091947 REF: AMM 22-11-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
221008	AUTOPILOT COMPUTER 4008519-952	MOS					28-APR-1993		
22.070	93014692 REF: AMM 22-11-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
221009	AUTOPILOT CONTROL 4018639-933	MOS					17-JUN-2011		
22.040	90123386 REF: AMM 22-11-03	HRS/MSC AFL	O/C				4657:12 3284		
221010	AILERON SERVO 4006719-906	MOS					28-APR-1993		
22.010	92096121 REF: AMM 22-11-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
221010	ELEVATOR SERVO 4006719-914	MOS					28-APR-1993		
22.020	92106173 REF: AMM 22-11-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
221010	RUDDER SERVO 4006719-906	MOS					28-APR-1993		
22.030	92096122 REF: AMM 22-11-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A221001 (s)	INSPECT AILERON SERVO ACTUATOR AND MOUNT: PHASE 5						PKG		
22.010	PKG 7,104 REF: AMM 22-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A222001 (s)	INSPECT RUDDER SERVO ACTUATOR AND MOUNT: PHASE 5						PKG		
22.030	PKG 7,109 REF: AMM 22-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A223001 (s)	INSPECT ELEVATOR SERVO ACTUATOR AND MOUNT: PHASE 5						PKG		
22.020	PKG 7,110 REF: AMM 22-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B221002 (s)	PERFORM AUTOPILOT AND DISENGAGEMENT AND WARNING TEST: PHASE 5						PKG		
22.050	PKG 7,102 REF: AMM 22-11-03	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B221003 (s)	PERFORM AUTOPILOT DISENGAGEMENT AND WARNING TEST: PHASE 5						PKG		
22.080	PKG 7,102 REF: AMM 22-11-03	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 23 COMMUNICATIONS									
231010	BOTTOM VHF ANTENNA								
23.325	S65-111-309 598 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-APR-1993 0 0		
231010	TOP VHF ANTENNA								
23.325	20-200-3 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232000	INTERCOM								
23.335	400-014635-0101 117 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
232002	NO. 2 VHF COMM ANTENNA								
23.040	VF10-108-1 2057 REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
232003	NO. 1 VHF COMM ANTENNA								
23.040	VFS10-90-5 2926 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
232005	CABIN HANDSET PHONE								
23.060	400-0123-212 7641 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
232006	COCKPIT HANDSET PHONE								
23.060	400-0123-212 7470 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
232009	NO. 1 COMM CONTROL								
23.340	822-1120-005 13094 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:1505			28-JUN-1999 1505		
232009	NO. 2 COMM CONTROL								
23.340	822-1120-005 13091 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:1505			28-JUN-1999 1505		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232010	NO. 1 VHF COMMUNICATION TRANSCEIVER								
23.090	822-1113-001 37867 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C				24-JUN-2011		
232010	NO. 2 VHF COMMUNICATION TRANSCEIVER								
23.090	822-1113-001 38214 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C				24-JUN-2011		
235001	NO. 1 AUDIO AMPLIFIER								
23.100	5632-1-1 225 REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
235001	NO. 2 AUDIO AMPLIFIER								
23.100	5632-1-1 224 REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
236096	FLEXCOMM ANTENNA								
23.385	S65-1016-1 1256 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
237001	COCKPIT VOICE RECORDER								
23.120	2100-1020-00 000701476 REF: AMM 23-71-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
237004	CVR CONTROLLER								
23.110	S161-0020-00 000710289 REF: AMM 23-71-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237005	CVR MICROPHONE								
23.400	S056-0048-00 000708450 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
237006	CVR UNDERWATER LOCATOR BEACON								
23.120	DK120/90 AT113349 REF: AMM 23-71-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			12-JUN-2018 5214 3812		
237006A	REPLACE ULB (CVR) BATTERY								
23.290	PN SN-UNKNOWN REF: AMM 23-71-03	MOS HRS/MSC AFL	72	TSN:0			12-JUN-2018	30-JUN-2024	
23FO-03 560/T	INTERCOMM/CABIN FOREIGN ONLY FACTORY OPTION								
	674T FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		
A231001 (s)	INSPECT HIGH FREQUENCY ANTENNA AND TENSION UNIT: PHASE 5						PKG		
23.130	PKG 7,107 REF: AMM 23-10-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A236002 (s)	INSPECT CONTROL SURFACE BOND JUMPER: PHASE 5						PKG		
23.140	PKG 7,110 REF: AMM 20-21-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A237001 (s)	INSPECT COCKPIT VOICE RECORDER: PHASE 5						PKG		
23.120	PKG 7,106 REF: AMM 23-70-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A237003	INSPECT CVR UNDERWATER LOCATOR BEACON : PHASE 21								
23.120	DK120/90 PKG 35 AT113349 REF: AMM 23-70-00	MOS HRS/MSC AFL	24				12-JUN-2018	12-JUN-2020	
B231002 (s)	OPERATIONAL TEST HONEYWELL STANDBY CONTROL HEAD: PHASE 60 (AIRPLANES -0001 THRU -0750)						PKG		
23.150	PKG 68 REF: AMM 23-13-00	MOS HRS/MSC AFL	500				26-JUN-2019 5474 4015		
B236001 (s)	INSPECT STATIC DISCHARGE WICK: PHASE 5						PKG		
23.160	PKG 7,108 REF: AMM 23-61-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B237002	OPERATIONAL CHECK COCKPIT VOICE RECORDER: PHASE 1								
23.120	PKG 1 REF: AMM 23-70-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067	26-AUG-2021 5845	
B237004	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON : PHASE 21								
23.120	DK120/90 PKG 35 AT113349 REF: AMM 23-70-00	MOS HRS/MSC AFL	24				12-JUN-2018	12-JUN-2020	
CHAPTER 24 ELECTRICAL POWER									
242001	NO. 1 STATIC INVERTER								
24.010	SPC38B 1322 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:4907			27-OCT-2006 3651		
242001	NO. 2 STATIC INVERTER								
24.010	SPC38B 2356 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-AUG-2015 5066:48 3729		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243001	LEFT STARTER/GENERATOR 9912125-3 24.070 OVERHAUL 94016 REF: AMM 80-11-01	MOS HRS/MSC AFL	1000	TSN:0			26-AUG-2019 5545 4067	6545	
243001	RIGHT STARTER/GENERATOR 9912125-3 24.075 OVERHAUL 94121 REF: AMM 80-11-01	MOS HRS/MSC AFL	1000	TSN:0			26-AUG-2019 5545 4067	6545	
243003	NO. 1 GENERATOR CONTROL UNIT 51539-006F 24.050 92104B REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
243003	NO. 2 GENERATOR CONTROL UNIT 51539-006F 24.050 92152B REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
243004	NO. 1 AMMETER C662501-0104 24.020 740 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
243004	NO. 2 AMMETER C662501-0104 24.020 742 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
243005	DC VOLTMETER C662502-0101 24.080 1946 REF: AMM 24-32-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243007	MAIN SHIP BATTERY 30978-002 11102688 REF: AMM 24-32-00	MOS HRS/MSC AFL	O/C				22-SEP-2017		
24.030									
243008	BATTERY TEMP MONITOR- 1529-1 2017 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
24.060									
243009	BATTERY TEMP GAGE 1229-1 1829 REF: AMM 24-32-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
24.060									
243010	BATTERY TEMP SENSOR 1166-1 SN-UNKNOWN REF: AMM 24-32-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
24.060									
243011	CURRENT/VOLTAGE CONTROLLER 1301-1 1998 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
24.040									
243015	BATTERY DISCONNECT RELAY A876K CK10949 REF: AMM 24-41-01	MOS HRS/MSC AFL	O/C	TSO:49			26-MAY-1994 195		
24.090									
243016	CURRENT/VOLTAGE SENSOR 1302-1 1716A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
24.040									

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
245002	CABIN ALTITUDE SWITCH								
24.200	GB300NA161 9241312 REF: AMM 21-32-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
A242001 (s)	INSPECT NOSE AREA ELECTRICAL COMPONENTS: PHASE 5						PKG		
24.110	PKG 7,100 REF: AMM 24-00-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A245001 (s)	INSPECT CIRCUIT BREAKER PANELS: PHASE 5						PKG		
24.120	PKG 7,102 REF: AMM 24-45-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A245002 (s)	INSPECT COCKPIT SIDE CONSOLE: PHASE 5						PKG		
24.130	PKG 7,102 REF: AMM 24-45-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A245003 (s)	INSPECT AVIONICS RELAY JUNCTION BOX: PHASE 5						PKG		
24.140	PKG 7,100 REF: AMM 24-00-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A245004 (s)	INSPECT AFT POWER JUNCTION BOX: PHASE 5						PKG		
24.150	PKG 7,105 REF: AMM 24-45-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B243001 (s)	OPERATIONAL TEST DC GENERATOR SYSTEM: PHASE 4						PKG		
24.160	PKG 4 REF: AMM 24-30-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B243003	FUNCTIONAL CHECK MAIN SHIP BATTERY SAFT NI-CAD BATTERY (CAPACITY CHECK): PHASE 28 30978-002 PKG 44 11102688 REF: AMM 24-32-00	MOS HRS/MSC AFL	12 200				08-OCT-2019 5574 4090	08-OCT-2020 5774	
B244001 (s) 24.170	FUNCTIONAL TEST OVERVOLTAGE SYSTEM: PHASE 1 PKG 1 REF: AMM 24-41-02	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
256002 25.020	EMERGENCY LOCATOR TRANSMITTER 453-5000 210-07792 REF: AMM 25-61-05	MOS HRS/MSC AFL	O/C				03-JAN-2017		
256003 25.020	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY 452-0133 369629-035 REF: Expiry Date: 01-JUN-2021	MOS HRS/MSC AFL	60				03-JAN-2017	01-JUN-2021 M	
256004 25.030	NO. 1 ELT ANTENNA 110-337 284471 REF: AMM 25-61-05	MOS HRS/MSC AFL	O/C	TSN:0			20-MAY-2009 4546		
256004 25.030	NO. 2 ELT ANTENNA ELT10-177-2 1056 REF: AMM 25-61-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
256007 25.290	ELT INTERFACE 453-6500 07778 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			20-MAY-2009 4546		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25FO-01 560	LOCATOR BEACON-EMERG FACTORY OPTION 175 FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		
A251001 (s) 25.010	INSPECT PILOT AND COPILOT CREW SEAT: PHASE 5 PKG 7,110 REF: AMM 25-11-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A251002 (s) 25.040	INSPECT PILOT AND COPILOT SEAT TRACK STOPS: PHASE 5 PKG 7,110 REF: AMM 25-11-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A251004 (s) 25.050	INSPECT COCKPIT INSTRUMENT PANELS AND COMPONENTS: PHASE 5 PKG 7,108 REF: AMM 25-10-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A252001 (s) 25.060	INSPECT PASSENGER SEAT: PHASE 5 PKG 7,110 REF: AMM 25-20-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A252002 (s) 25.070	INSPECT PASSENGER SEAT TRACK STOPS: PHASE 5 PKG 7,110 REF: AMM 25-20-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A256001 (s) 25.080	INSPECT EMERGENCY EQUIPMENT: PHASE 18 PKG 22 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
A256003 (s) 25.090	INSPECT LIFE PRESERVER: PHASE 18 PKG 22 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A256004 (s) 25.310	DETAILED INSPECTION SMOKE GOGGLE ASSEMBLY: PHASE 18 PKG 22 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
A256101 (s) 25.200	VISUALLY INSPECT ARTEX C406-N EMERGENCY LOCATOR BEACON SYSTEM: PHASE 56 PKG 65 REF: AMM 25-61-05	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
A256107 (s) 26.120	DETAILED INSPECTION C406-2 (ELT) 91.207: PHASE 56 PKG 65 REF: AMM 25-61-07	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
B256001 (s) 25.100 AIRWORTHINESS	VISUALLY INSPECT EMERGENCY LOCATOR BEACON SYSTEM: PHASE 56 PKG 65 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
B256101 (s) 25.260	OPERATIONAL CHECK ARTEX C406-N EMERGENCY LOCATOR BEACON SYSTEM: PHASE 56 PKG 65 REF: AMM 25-61-05	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
B256107 (s) 26.120	FUNCTIONAL TEST C406-2 (ELT) 91.207: PHASE 56 PKG 65 REF: AMM 25-61-07	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
CHAPTER 26 FIRE PROTECTION									
261001 26.020	NO. 1 ENGINE FIRE DETECTOR SENSOR 244-18882 SN-UNKNOWN REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
261001 26.020	NO. 2 ENGINE FIRE DETECTOR SENSOR 244-18882 SN-UNKNOWN REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261002	NO. 1 FIRE DETECTOR CONTROL								
26.010	377-02808 9237008 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
261002	NO. 2 FIRE DETECTOR CONTROL								
26.010	377-02808 9241008 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
262001	AFT ENGINE FIRE BOTTLE								
26.040	898066-2 78829EK REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSO:5 TSO:0 TSO:0			22-MAR-2017		
262001	FORWARD ENGINE FIRE BOTTLE								
26.030	9912048-3 67111EK REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSO:29 TSO:0 TSO:0			26-SEP-2017		
262002	CABIN PORTABLE HALON FIRE EXTINGUISHER								
26.060	C352 A-29698032 REF: AMM 26-22-00	MOS HRS/MSC AFL	O/C				26-SEP-2017		
262002	COCKPIT PORTABLE HALON FIRE EXTINGUISHER								
26.050	C352TS E-92813494 REF: AMM 26-22-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			12-JUN-2018 5214 3812		
262003	AFT LEFT (MAX LIFE) CARTRIDGE								
26.030	AE873364 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	120	TSN:0 TSN:0			22-MAR-2017	11-OCT-2026	
LIFE LIMIT	Manufacture Date: 11-OCT-2016								

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262003	AFT RIGHT (MAX LIFE) CARTRIDGE AE873364	MOS	120				22-MAR-2017	11-OCT-2026	
26.040	SN-UNKNOWN	HRS/MSC		TSN:0					
LIFE LIMIT	REF: See Workcard	AFL		TSN:0					
	Manufacture Date: 11-OCT-2016								
262003	FORWARD LEFT (MAX LIFE) CARTRIDGE AE873364	MOS	120				19-APR-2012	01-MAR-2021	
26.030	NSN	HRS/MSC					4790:06		
LIFE LIMIT	REF: See Workcard	AFL					3402		
	Manufacture Date: 01-MAR-2011								
262003	FORWARD RIGHT (MAX LIFE) CARTRIDGE AE873364	MOS	120				19-APR-2012	01-MAR-2021	
26.040	NSN	HRS/MSC					4790:06		
LIFE LIMIT	REF: See Workcard	AFL					3402		
	Manufacture Date: 01-MAR-2011								
263005	REPLACE FORWARD LEFT (SERVICE LIFE) CARTRIDGE AE873364	MOS	96				19-APR-2012	19-APR-2020	
26.030	NSN	HRS/MSC					4790:06		
REPLACE	REF: GENERIC NO REF	AFL					3402		
263007	REPLACE FORWARD RIGHT (SERVICE LIFE) CARTRIDGE AE873364	MOS	96				19-APR-2012	19-APR-2020	
26.040	NSN	HRS/MSC					4790:06		
REPLACE	REF: GENERIC NO REF	AFL					3402		
263009	REPLACE AFT LEFT (SERVICE LIFE) CARTRIDGE AE873364	MOS	96				22-MAR-2017	22-MAR-2025	
26.030	SN-UNKNOWN	HRS/MSC							
REPLACE	REF: GENERIC NO REF	AFL							
263011	REPLACE AFT RIGHT (SERVICE LIFE) CARTRIDGE AE873364	MOS	96				22-MAR-2017	22-MAR-2025	
26.040	SN-UNKNOWN	HRS/MSC							
REPLACE	REF: GENERIC NO REF	AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A262003 26.060 05-10-25 AIRWORTHINESS	INSPECT/WEIGH CABIN PORTABLE HALON FIRE EXTINGUISHER : PHASE 18 C352 PKG 22 A-29698032 REF: AMM 26-22-00	MOS HRS/MSC AFL	12				11-DEC-2018	11-DEC-2019	
A262003 26.050 05-10-25 AIRWORTHINESS	INSPECT/WEIGH COCKPIT PORTABLE HALON FIRE EXTINGUISHER : PHASE 18 C352TS PKG 22 E-92813494 REF: AMM 26-22-00	MOS HRS/MSC AFL	12				11-DEC-2018	11-DEC-2019	
B262002 26.040	HYDROSTATIC TEST AFT ENGINE FIRE BOTTLE 898066-2 78829EK REF: AMM 26-22-00	MOS HRS/MSC AFL	60				10-OCT-2016	10-OCT-2021	
B262002 26.030	HYDROSTATIC TEST FORWARD ENGINE FIRE BOTTLE 9912048-3 67111EK REF: AMM 26-22-00	MOS HRS/MSC AFL	60				31-MAR-2015	31-MAR-2020	
B262003 26.060 05-10-25 AIRWORTHINESS	HYDROSTATIC TEST CABIN PORTABLE HALON FIRE EXTINGUISHER C352 A-29698032 REF: AMM 26-22-00	MOS HRS/MSC AFL	144				01-JUN-2014	01-JUN-2026	
B262003 26.050 05-10-25 AIRWORTHINESS	HYDROSTATIC TEST COCKPIT PORTABLE HALON FIRE EXTINGUISHER C352TS E-92813494 REF: AMM 26-22-00	MOS HRS/MSC AFL	144				04-MAY-2018	04-MAY-2030	
B262004 26.060 05-10-25 AIRWORTHINESS	EMPTY/INSPECT/RECHARGE CABIN PORTABLE HALON FIRE EXTINGUISHER : PHASE 48 C352 PKG 54 A-29698032 REF: AMM 26-22-00	MOS HRS/MSC AFL	72				01-JUN-2014	01-JUN-2020	
B262004 26.050 05-10-25 AIRWORTHINESS	EMPTY/INSPECT/RECHARGE COCKPIT PORTABLE HALON FIRE EXTINGUISHER : PHASE 48 C352TS PKG 54 E-92813494 REF: AMM 26-22-00	MOS HRS/MSC AFL	72				04-MAY-2018	04-MAY-2024	

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B262005 (s)	FUNCTIONAL TEST ENGINE FIRE EXTINGUISHER SYSTEM: PHASE 5						PKG		
26.110	PKG 7,102 REF: AMM 26-21-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 27 FLIGHT CONTROLS									
271001	AILERON TRIM ACTUATOR								
27.010	5565450-72 SN-UNKNOWN REF: AMM 27-11-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
272001	RUDDER TRIM ACTUATOR								
27.020	5565450-71 SN-UNKNOWN REF: AMM 27-21-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
273002	TRIM MIXER ACTUATOR								
27.030	44430-3657 T316 REF: AMM 27-31-07	MOS HRS/MSC AFL	O/C	TSO:0			19-JUN-1996 676		
273003	LEFT ELEVATOR TRIM ACTUATOR								
27.040	5565450-81 SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0			16-OCT-1997 1071		
273003	RIGHT ELEVATOR TRIM ACTUATOR								
27.040	5565450-82 SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
275001	FLAP CONTROL VALVE								
27.050	66720 956 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
275003	NO. 1 FLAP ACTUATOR								
27.060	1535000 208 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275003	NO. 2 FLAP ACTUATOR								
27.060	1535000 207 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
275004	LEFT WING LEFT INBOARD AFT FLAP ROLLER								
27.070	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	
275004	LEFT WING LEFT OUTBOARD AFT FLAP ROLLER								
27.070	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	
275004	LEFT WING RIGHT INBOARD AFT FLAP ROLLER								
27.075	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	
275004	LEFT WING RIGHT OUTBOARD AFT FLAP ROLLER								
27.075	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	
275004	RIGHT WING LEFT INBOARD AFT FLAP ROLLER								
27.080	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	
275004	RIGHT WING LEFT OUTBOARD AFT FLAP ROLLER								
27.080	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	
275004	RIGHT WING RIGHT INBOARD AFT FLAP ROLLER								
27.085	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275004	RIGHT WING RIGHT OUTBOARD AFT FLAP ROLLER								
27.085	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			28-APR-1993 0 0	5000	
276001	NO. 1 SPEED BRAKE ACTUATOR								
27.090	1535500-1 85 REF: AMM 27-61-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
276001	NO. 2 SPEED BRAKE ACTUATOR								
27.090	1535500-1 24 REF: AMM 27-61-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
276002	SPEED BRAKE FLAP CONTROL VALVE								
27.100	66720 961 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
276003	SAFETY SPDBK VALVE								
27.110	68930 347 REF: AMM 27-61-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
A271003 (s)	INSPECT AILERON AND AILERON TRIM TAB: PHASE 2						PKG		
27.120	PKG 2 REF: AMM 27-11-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
A271004 (s)	INSPECT CONTROL WHEEL: PHASE 1						PKG		
27.130	PKG 1 REF: AMM 27-11-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
A271005 (s)	INSPECT AILERON, RUDDER AND ELEVATOR TRIM TAB CONTROL AND INDICATOR: PHASE 1						PKG		
27.140	PKG 1 REF: AMM 27-11-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A271006 (s) 27.150	INSPECT AILERON CONTROL CABLE: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A271007 (s) 27.160	INSPECT AILERON TRIM CABLE: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A271008 (s) 27.170	INSPECT AILERON TRIM TAB ACTUATOR DISASSEMBLY: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A271014 (s) 27.180	INSPECT AILERON DRIVE BRACKET: PHASE 32 PKG 46 REF: AMM 27-11-00	MOS HRS/MSC AFL	15000	TSI:0 TSI:0 TSI:0			PKG 28-APR-1993 0 0		
A271015 (s) 27.190	INSPECT AILERON YOKE: PHASE 33 PKG 47 REF: AMM 27-11-00	MOS HRS/MSC AFL	15000	TSI:0 TSI:0 TSI:0			PKG 28-APR-1993 0 0		
A272002 (s) 27.200	INSPECT RUDDER AND RUDDER TRIM TAB: PHASE 2 PKG 2 REF: AMM 27-21-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
A272003 (s) 27.210	INSPECT RUDDER PEDALS: PHASE 5 PKG 7,111 REF: AMM 27-21-03	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A272005 (s) 27.220	INSPECT RUDDER CABLE: PHASE 5 PKG 7,111 REF: AMM 27-21-06	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A272006 (s) 27.230	INSPECT RUDDER TRIM CABLE: PHASE 5 PKG 7,111 REF: AMM 27-21-06	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A272007 (s) 27.240	INSPECT RUDDER TRIM TAB ACTUATOR DISASSEMBLY: PHASE 5 PKG 7,111 REF: AMM 27-21-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A273002 (s) 27.250	EXTERNAL INSPECTION ELEVATOR: PHASE 2 PKG 2 REF: AMM 27-31-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
A273005 (s) 27.260	INSPECT CONTROL COLUMNS: PHASE 5 PKG 7,111 REF: AMM 27-31-02	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A273006 (s) 27.270	INSPECT ELEVATOR LINKAGE: PHASE 5 PKG 7,107 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A273007 (s) 27.280	INSPECT FLAP/ELEVATOR ELECTRIC TRIM MIXER: PHASE 5 PKG 7,105 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A273008 (s) 27.290	INSPECT ELEVATOR CABLE: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A273009 (s) 27.300	INSPECT ELEVATOR TRIM CABLE: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A273010 (s) 27.310	INSPECT ELEVATOR TRIM TAB ACTUATOR DISASSEMBLY: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A275003 (s) 27.320	INSPECT FLAP PRESELECT CABLE: PHASE 5 PKG 7,111 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A275004 (s) 27.330	INSPECT FLAP: PHASE 2 PKG 2 REF: AMM 27-51-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
A275007 (s) 27.340	INSPECT FLAP BELL CRANKS: PHASE 5 PKG 7,111 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A275021 (s) 27.350	INSPECT FLAP CROSSTIE SYSTEM: PHASE 5 PKG 7,111 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A275022 (s) 27.360	INSPECT FLAP/ELEVATOR TRIM MIXER INTERCONNECT CABLE SYSTEM: PHASE 5 PKG 7,111 REF: AMM 27-31-07	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A276001 (s) 27.370	INSPECT SPEED BRAKE SYSTEM: PHASE 5 PKG 7,109 REF: AMM 27-61-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B271001 (s) 27.380	CHECK AILERON TRIM TAB: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B271002 (s) 27.390	CHECK AILERON AND AILERON TRIM TAB: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B272001 (s) 27.400	CHECK RUDDER TRIM TAB: PHASE 5 PKG 7,107 REF: AMM 27-21-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B272004 (s) 27.410	CHECK RUDDER AND RUDDER TRIM TAB TRAVEL: PHASE 5 PKG 7,111 REF: AMM 27-21-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B273003 (s) 27.420	CHECK ELEVATOR AND ELEVATOR TRIM TAB: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B273004 (s) 27.430	CHECK ELEVATOR TRIM TAB FREE PLAY: PHASE 5 PKG 7,107 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B273015 (s) 27.440	OPERATIONAL CHECK ELEVATOR ELECTRICAL TRIM MIXER SYSTEM: PHASE 1 PKG 1 REF: AMM 27-31-07	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
B275004 (s) 27.450	OPERATIONAL CHECK FLAP APPROACH WARNING SWITCH: PHASE 5 PKG 7,102 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B275006 (s) 27.460	CHECK FLAP TRAVEL: PHASE 5 PKG 7,109 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B275009 (s) 27.470	LEAK CHECK FLAP HYDRAULIC ACTUATORS: PHASE 5 PKG 7,111 REF: AMM 27-51-04	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B277001 (s) 27.480	INSPECT/OPERATIONAL CHECK CONTROL LOCK SYSTEM: PHASE 5 PKG 7,102 REF: AMM 27-71-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
C271001 (s) 27.490	LUBRICATE/CHECK AILERON TRIM TAB ACTUATOR: PHASE 2 PKG 2 REF: AMM 27-11-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
C272001 (s) 27.500	LUBRICATE/CHECK RUDDER TRIM TAB ACTUATOR: PHASE 2 PKG 2 REF: AMM 27-21-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
C273001 (s) 27.510	LUBRICATE/CHECK ELEVATOR TRIM TAB ACTUATOR: PHASE 2 PKG 2 REF: AMM 27-31-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		

CHAPTER 28

FUEL

282001 28.060	NO. 1 ELECTRIC FUEL BOOST PUMP 1C7-12 9AH109 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
282001 28.060	NO. 2 ELECTRIC FUEL BOOST PUMP 1C7-12 9AH108 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
282010 28.120	LEFT MOTIVE FUEL VALVE 3244850 B28461 REF: AMM 28-21-06	MOS HRS/MSC AFL	O/C	TSO:0			23-JUN-2006 3436		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282010	RIGHT MOTIVE FUEL VALVE								
28.120	3244850 B28019 REF: AMM 28-21-06	MOS HRS/MSC AFL	O/C	TSO:0			23-JUN-2006 3436		
284001	NO. 1 FUEL LOW LEVEL SWITCH								
28.170	L15H-3 SN-UNKNOWN REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
284001	NO. 2 FUEL LOW LEVEL SWITCH								
28.170	L15H-3 SN-UNKNOWN REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
284002	LEFT FUEL QTY COMPENSATOR								
28.160	300047-13001 16579 REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
284002	RIGHT FUEL QTY COMPENSATOR								
28.160	300047-13001 16625 REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
284007	FUEL QTY INDICATOR								
28.165	VSDL-OC403F-1 548 REF: AMM 28-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
A281001 (s)	INSPECT WING FUEL STORAGE AREA: PHASE 5						PKG		
28.200	PKG 7,109 REF: AMM 28-10-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A282002 (s)	INSPECT WING FUEL SYSTEM COMPONENT: PHASE 5						PKG		
28.210	PKG 7,109 REF: AMM 28-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B282003 (s)	OPERATIONAL CHECK FUEL SYSTEM: PHASE 5						PKG		
28.220	PKG 7,104 REF: AMM 28-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B282004 (s)	OPERATIONAL CHECK FUEL SYSTEM: PHASE 5						PKG		
28.230	PKG 7,103 REF: AMM 28-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B284001 (s)	OPERATIONAL CHECK LOW FUEL WARNING SYSTEM: PHASE 5						PKG		
28.240	PKG 7,104 REF: AMM 28-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
D282002 (s)	CHANGE FUEL FILTER ELEMENT: PHASE 5						PKG		
28.250	PKG 7,109 REF: AMM 28-21-05	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 29	HYDRAULIC POWER								
291001	MAIN HYD RESERVOIR								
29.010	40500-7 417 REF: AMM 29-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
291002	LEFT HYDRAULIC PUMP								
29.050	24195-LAA 1408 REF: AMM 29-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
291002	RIGHT HYDRAULIC PUMP								
29.050	24195-LAA 1411 REF: AMM 29-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
291005	NO. 1 CK VALVE HYDRAULIC FLOW SWITCH								
29.020	3520020100-4 3370 REF: AMM 29-11-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291005	NO. 2 CK VALVE HYDRAULIC FLOW SWITCH 3520020100-4	MOS					28-APR-1993		
29.020	3297 REF: AMM 29-11-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291007	NO. 1 MOTOR ACTUATOR VALVE AV24B1325C5	MOS					28-APR-1993		
29.120	RP10863 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291007	NO. 2 MOTOR ACTUATOR VALVE AV24B1325C5	MOS					28-APR-1993		
29.120	RP10878 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291008	THERMAL RELIEF VALVE OAS5322-3-1700	MOS					28-APR-1993		
29.030	187 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291009	PRESSURE RELIEF VALVE 4614	MOS					28-APR-1993		
29.030	1295A REF: AMM 28-11-10	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291012	SOLENOID BYPASS VALVE 61510-1	MOS					28-APR-1993		
29.040	862A REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
A291002 (s)	INSPECT HYDRAULIC SUB-PANEL: PHASE 1 PKG 1,3,15	MOS					PKG 26-AUG-2019		
29.100	REF: AMM 29-11-06	HRS/MSC AFL	150				5545 4067		
D291001 (s)	INSPECT/REPLACE HYDRAULIC FILTERS AND FILTER ELEMENT: PHASE 5 PKG 7,105	MOS					PKG 12-DEC-2017		
29.110	REF: AMM 29-11-04	HRS/MSC AFL	36 1200						

CHAPTER 30 ICE AND RAIN PROTECTION

?-Insufficient Information +-Task exists in Inspection Manual © CAMP SYSTEMS Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W (#)-RTS Pending (!)-RTS Overdue

(ENG/APU) = Engine/APU Units

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301001	LEFT TEMP CONTROL SL002 SWITCH 1173T42-3	MOS					28-APR-1993		
30.060	SN-UNKNOWN REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301001	NO. 1 OUTBRD WING DEICE BOOT P35-5D5230-01	MOS					07-MAY-2008		
30.020	MZVJ430 REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0			4224		
Note: SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.									
301001	NO. 2 OUTBRD WING DEICE BOOT P35-5D5230-02	MOS					27-NOV-2008		
30.020	MAGZ720 REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0			4403		
Note: SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.									
301001	RIGHT TEMP CONTROL SR002 SWITCH 1173T42-3	MOS					28-APR-1993		
30.060	SN-UNKNOWN REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301001	WING ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE 320495-1	MOS					28-APR-1993		
30.125	487 REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301002	NO. 1 HORIZONTAL STABILIZER DEICE BOOT P29S-5D5225-05	MOS					07-MAY-2008		
30.010	MACF240 REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0			4224		
301002	NO. 2 HORIZONTAL STABILIZER DEICE BOOT P29S-5D5225-06	MOS					07-MAY-2008		
30.010	MZYP010 REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0			4224		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301004	LEFT WING ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV 67410-2 2355ABCD REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
301004	RIGHT WING ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV 67410-2 2241ABC REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
301007	LEFT RAM AIR MODULATING TEMP CONTROL VLV 27441500-01 11AH55 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
301007	RIGHT RAM AIR MODULATING TEMP CONTROL VLV 27441500-01 11AH51 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
301008	LEFT DEICE CONTROL SLV19 VLV 3D2353-06 N12142 REF: AMM 30-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
301008	RIGHT DEICE CONTROL SLV18 VLV 3D2353-06 N12024 REF: AMM 30-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
301009	LEFT TEMP CONTROL S95 SENSOR 27431501-04 7AH95 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
301009	RIGHT TEMP CONTROL S94 SENSOR 27431501-04 7AH93 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302003	LEFT ENGINE ANTI-ICE SOLENOID VLV 67410-1 2264ABC REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
302003	RIGHT ENGINE ANTI-ICE SOLENOID VLV 67410-1 234AD REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-1993 40		
302004	LEFT ENGINE INLET TEMPERATURE S95 SWITCH 21548-2-19-6 SN-UNKNOWN REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
302004	RIGHT ENGINE INLET TEMPERATURE S94 SWITCH 21548-2-19-6 SN-UNKNOWN REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
302005	LEFT ANTI ICING VALVE 10018200A 829 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSO:0			23-JUN-2006 3436		
302005	RIGHT ANTI ICING VALVE 10018200C 300 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSO:0			22-SEP-2008 4397		
302006	LEFT BLEED VALVE ACTUATOR 800888-1 F25429 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSO:0			23-JUN-2006 3436		
302006	RIGHT BLEED VALVE ACTUATOR 800888-1 F23747 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSO:0			23-JUN-2006 3436		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
303001	LEFT PITOT TUBE								
30.210	PH502 SN-UNKNOWN REF: AMM 30-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
303001	RIGHT PITOT TUBE								
30.210	PH502 SN-UNKNOWN REF: AMM 30-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
304001	BLEED AIR MONITOR-								
30.520	1169-1 1980 REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
304002	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER								
30.270	10663A 708 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
304004	ALCOHOL WINDSHIELD ANTI-ICE PUMP								
30.290	476411 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
304005	TEMP CONTROL VALVE								
30.530	27241287 7AH32 REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
304006	ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR								
30.280	27231272-20A 10AH39 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
304007	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH								
30.250	1115P25 2064A REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		



Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304009	WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE 67410-2 1372ABCDEGK REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSO:0			07-MAY-2008 4224		
A301001 (s)	INSPECT WING HEATED LEADING EDGE BLEED AIR OUTLET HOLES: PHASE 2 PKG 2 REF: AMM 30-11-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
A301002 (s)	INSPECT WING HEATED LEADING EDGE AND PLUMBING: PHASE 5 PKG 7,109 REF: AMM 30-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A301003 (s)	INSPECT WING HEATED LEADING EDGE BLEED AIR COMPONENTS: PHASE 3 PKG 3 REF: AMM 30-11-00	MOS HRS/MSC AFL	24 300				PKG 26-JUN-2019 5474 4015		
A301004 (s)	INSPECT WING HEATED LEADING EDGE ANTI-ICE TAILCONE COMPONENTS: PHASE 5 PKG 7,105 REF: AMM 30-11-00	MOS HRS/MSC AFL	24 300				PKG 12-DEC-2017		
A301005 (s)	INSPECT WING HEATED LEADING EDGE BLEED AIR OUTLET HOLES: PHASE 2 PKG 2 REF: AMM 30-14-00	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
A301006 (s)	INSPECT WING HEATED LEADING EDGE AND PLUMBING: PHASE 5 PKG 7,109 REF: AMM 30-14-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A301008 (s)	INSPECT WING HEATED LEADING EDGE ANTI-ICE TAILCONE COMPONENTS: PHASE 5 PKG 7,105 REF: AMM 30-14-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A304001 (s) 30.380	INSPECT WINDSHIELD BLEED AIR AUGMENTER DOOR AND SHROUD: PHASE 5 PKG 7,101 REF: AMM 30-41-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A304003 (s) 30.390	INSPECT WINDSHIELD BLEED AIR CONTROLS: PHASE 5 PKG 7,108 REF: AMM 30-41-04	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A304004 (s) 30.290	INSPECT WINDSHIELD ALCOHOL RESERVOIR: PHASE 5 PKG 7,100 REF: AMM 30-42-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B301001 (s) 30.400	OPERATIONAL TEST BLEED AIR ANTI-ICE SYSTEMS: PHASE 5 PKG 7,104 REF: AMM 30-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B301003 (s) 30.420	OPERATIONAL CHECK PNEUMATIC DEICE SYSTEM: PHASE 4 PKG 4 REF: AMM 30-12-00	MOS HRS/MSC AFL	24 300				PKG 26-JUN-2019 5474 4015		
B301005 (s) 30.430	OPERATIONAL TEST BLEED AIR ANTI-ICE SYSTEMS: PHASE 5 PKG 7,104 REF: AMM 30-14-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B301006 (s) 30.440	OPERATIONAL CHECK PNEUMATIC DEICE SYSTEM: PHASE 4 PKG 4 REF: AMM 30-12-00	MOS HRS/MSC AFL	24 300				PKG 26-JUN-2019 5474 4015		
B304001 (s) 30.450	OPERATIONAL CHECK WINDSHIELD ANTI-ICE: PHASE 5 PKG 7,102 REF: AMM 30-41-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B304004 (s)	OPERATIONAL TEST WINDSHIELD ALCOHOL PUMP: PHASE 1						PKG		
30.460	PKG 1 REF: AMM 30-42-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
D304004 (s)	INSPECT/CLEAN WINDSHIELD ALCOHOL RESERVOIR FILTER: PHASE 5						PKG		
30.470	PKG 7,100 REF: AMM 30-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
312001	PILOT DIGITAL CLOCK								
31.010	M877A5V 4631 REF: AMM 31-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
313001	FLIGHT HOUR RECORDER								
31.050	C664503-0102 SN-UNKNOWN REF: AMM 31-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
313003	FDR ACCELEROMETER								
31.030	3001-01-101 1202-4907 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
313003	NO. 1 ACCELEROMETER								
31.070	7000992 6498 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
313003	NO. 2 ACCELEROMETER								
31.070	7000992 009549 REF: See Workcard	MOS HRS/MSC AFL	O/C				04-JUL-2011		
313006	FLIGHT DATA RECORDER								
31.020	S703-1000-00 00264 REF: AMM 31-30-01	MOS HRS/MSC AFL	O/C	TSO:8 TSO:0 TSO:0			22-AUG-2016		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313007	FDR UNDERWATER LOCATOR BEACON DK120 AT44794 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	TSN:0 TSN:0			22-AUG-2016	01-DEC-2022 M	
31.020 REPLACE									
313007A	BATTERY FDR UNDERWATER LOCATOR BEACON DK120 AT44794 REF: GENERIC NO REF	MOS HRS/MSC AFL	72				22-AUG-2016	01-DEC-2022 M	
31.020									
313008	FDR IMPACT SWITCH 3LO-453-3 L8013 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
31.040									
315001	MASTER WARNING ANNUNCIATOR 465-1-14 515 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
31.060									
A313001 (s)	INSPECT FLIGHT DATA RECORDER: PHASE 5 PKG 7,106 REF: AMM 31-30-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
31.020									
A313002	INSPECT FDR UNDERWATER LOCATOR BEACON : PHASE 21 DK120 PKG 35 AT44794 REF: AMM 31-30-00	MOS HRS/MSC AFL	24				27-NOV-2017 5121:17 3709	27-NOV-2019	
31.020									
B313002	OPERATIONAL TEST FDR UNDERWATER LOCATOR BEACON : PHASE 21 DK120 PKG 35 AT44794 REF: AMM 31-30-00	MOS HRS/MSC AFL	24				27-NOV-2017 5121:17 3709	27-NOV-2019	
31.020									
CHAPTER 32 LANDING GEAR									
321001	LEFT MAIN LANDING GEAR ASSEMBLY 6641000-35 43 REF: See Workcard	MOS HRS/MSC AFL		TSN:0 TSN:0			28-APR-1993 0 0		12450
32.010 LIFE LIMIT			12450						

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321002	RIGHT MAIN LANDING GEAR ASSEMBLY 6641000-36	MOS					28-APR-1993		
32.020	43	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: See Workcard	AFL	12450	TSN:0			0		12450
321003	LEFT MAIN LANDING GEAR TORQUE LINK BOLT 5541220-2	MOS					28-APR-1993		
32.030	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	10370	TSN:0			0		10370
321003	RIGHT MAIN LANDING GEAR TORQUE LINK BOLT 5541220-2	MOS					28-APR-1993		
32.030	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	10370	TSN:0			0		10370
322001	NOSE LANDING GEAR ASSEMBLY 6642000-18	MOS					28-APR-1993		
32.080	44	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-21-01	AFL	23500	TSN:0			0		23500
322002	NOSE SHIMMY DAMPER 5543001-7	MOS					27-DEC-2011		
32.100	107	HRS/MSC	O/C				4753:36		
	REF: GENERIC NO REF	AFL					3376		
322004	NOSE GEAR FORK/PISTON 6642000-3	MOS					28-APR-1993		
32.090	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-21-01	AFL	13640	TSN:0			0		13640
323001	LEFT MAIN LANDING GEAR ACTUATOR 1523100-7	MOS					07-MAY-2008		
32.160	716	HRS/MSC		TSN:0			4224		
LIFE LIMIT	REF: AMM 32-31-04	AFL	15000	TSN:0			3009		18009
323002	RIGHT MAIN LANDING GEAR ACTUATOR 1523100-8	MOS					07-MAY-2008		
32.160	704	HRS/MSC		TSN:0			4224		
LIFE LIMIT	REF: See Workcard	AFL	15000	TSN:0			3009		18009

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323003	NOSE LANDING GEAR ACTUATOR 9912120-4 1997 REF: See Workcard	MOS HRS/MSC AFL	15000	TSN:0			10-JUL-2014 4972 3668	18668	
323004	LEFT MLG UPLOCK ACTUATOR 5527504-2 1074 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
323004	NOSE UPLOCK ACTUATOR 5527504-2 1110 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
323004	RIGHT MLG UPLOCK ACTUATOR 5527504-2 1083 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 212940-2 1079 REF: Manufacture Date: 30-NOV-2018	MOS HRS/MSC AFL	288	TSO:3			12-FEB-2019 5393 3951	30-NOV-2042	
323007	LANDING GEAR CONTROL VALVE 66710 558 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
323008	DUMP VALVE OAS5319-1 291 REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323019	EMERGENCY AIR BOTTLE GAUGE								
32.190	2341128 21395A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-APR-1993 0 0		
324001	LEFT MLG WHEEL ASSEMBLY								
32.340	3-1490-1 3492 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				16-NOV-2018 5378:03 3931		
324001	RIGHT MLG WHEEL ASSEMBLY								
32.350	3-1490-1 3652 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			02-APR-2019 5427 3986		
324002	NOSE WHEEL ASSEMBLY								
32.360	3-1418 1044 REF: AMM 32-41-02	MOS HRS/MSC AFL	O/C				17-FEB-2012 4757:36 3380		
324003	LEFT MLG BRAKE ASSEMBLY								
32.230	2-1529-7 3884P REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			13-JUL-2018 5251 3838		
324004	RIGHT MLG BRAKE ASSEMBLY								
32.230	2-1529-7 2409 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			26-AUG-2019 5545 4067		
324005	LEFT MLG TIRE								
32.340	220K28-1 61542657 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			16-NOV-2018 5378:03 3931		
324005	RIGHT MLG TIRE								
32.350	220K28-1 61542656 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			02-APR-2019 5427 3986		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324006	NOSE TIRE 031-613-8 1113S00473 REF: See Workcard	MOS HRS/MSC AFL	O/C				17-FEB-2012 4757:36 3380		
324010	LEFT MLG SHUTTLE VALVE 195-183 2029 REF: AMM 32-31-08	MOS HRS/MSC AFL	O/C	TSO:0			09-MAR-2009 4489 3177		
324010	RIGHT MLG SHUTTLE VALVE 195-183 1549R REF: AMM 32-31-08	MOS HRS/MSC AFL	O/C	TSO:0			23-MAY-2009 4553 3222		
324011	LEFT MLG INBOARD BRAKE MASTER CYLINDER 95367-17 0355 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C				15-JUN-2012 4811:48 3420		
324011	RIGHT MLG INBOARD BRAKE MASTER CYLINDER 95367-9 508 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
324012	LEFT MLG OUTBOARD MASTER BRAKE CYLINDER 95367-18 1316 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0			07-MAY-2008 4224 3009		
324012	RIGHT MLG OUTBOARD MASTER BRAKE CYLINDER 95367-10 1119 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
324014	EMERGENCY AIR BRAKE VALVE 895232-0875 289 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324021	POWER BRAKE ANTISKID VALVE								
32.240	38-707-1 737 REF: AMM 32-42-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
324022	BRAKE CONTROL BOX								
32.250	42-707-1 807 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
324023	ANTISKID ACCUMULATOR								
32.260	57C57652 RH0670 REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
324024	LEFT MLG WHEEL TRANSDUCER								
32.220	40-955 2735 REF: AMM 32-42-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
324024	RIGHT MLG WHEEL TRANSDUCER								
32.220	40-955 8685 REF: AMM 32-42-07	MOS HRS/MSC AFL	O/C				08-MAY-2018 5178:39 3787		
324025	PRESSURE SWITCH								
32.320	1206P27 2041 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
324026	POWER BRAKE ASSEMBLY MOTOR								
32.300	30-2 2192 REF:	MOS HRS/MSC AFL	O/C	TSN:0			11-JUL-2006 3484		
324101	PARKING BRAKE VALVE								
32.330	95905 143 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325001	NOSE STEERING BUNGEE ASSEMBLY								
32.370	5565624-19 SN-UNKNOWN REF: AMM 32-51-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
326003	LEFT MAIN GEAR DOWN & LOCK SWITCH								
32.380	1EN118-6 SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0			16-AUG-1993 39 24		
326003	NOSE GEAR DOWN & LOCK SWITCH								
32.390	1EN118-6 SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0			16-AUG-1993 39 24		
326003	RIGHT MAIN GEAR DOWN & LOCK SWITCH								
32.380	1EN118-6 SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0			16-AUG-1993 39 24		
326005	LEFT MAIN GEAR UP & LOCKED SWITCH								
32.400	65-430087 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
326005	NOSE GEAR UP & LOCKED SWITCH								
32.410	65-430087 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
326005	RIGHT MAIN GEAR UP & LOCKED SWITCH								
32.400	65-430087 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
A320001 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF LANDING GEAR: PHASE 64						PKG		
	PKG 503	MOS HRS/MSC AFL	6				14-MAY-2019 5441 3993		
	REF: AMM 32-00-00								

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A320002 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF LANDING GEAR: PHASE 18 PKG 22	MOS	12				PKG	11-DEC-2018	
	REF: AMM 32-00-00	HRS/MSC AFL						5384 3938	
A321001 (s)	INSPECT MAIN LANDING GEAR: PHASE 2 PKG 2	MOS	24				PKG	26-AUG-2019	
32.460	REF: AMM 32-11-01	HRS/MSC AFL	300					5545 4067	
A321002 (s)	CHECK MAIN GEAR STRUT EXTENSION: PHASE 2 PKG 2	MOS	24				PKG	26-AUG-2019	
32.470	REF: AMM 32-11-01	HRS/MSC AFL	300					5545 4067	
A321003 (s)	INSPECT MAIN LANDING GEAR: PHASE 2 PKG 2	MOS	24				PKG	26-AUG-2019	
32.480	REF: AMM 32-11-02	HRS/MSC AFL	300					5545 4067	
A322001 (s)	INSPECT SHIMMY DAMPER: PHASE 2 PKG 2,4,15	MOS	24				PKG	26-AUG-2019	
32.100	REF: AMM 32-21-02	HRS/MSC AFL	300					5545 4067	
A322002 (s)	INSPECT NOSE GEAR ASSEMBLY: PHASE 2 PKG 2	MOS	24				PKG	26-AUG-2019	
32.080	REF: AMM 32-21-01	HRS/MSC AFL	300					5545 4067	
A323002 (s)	INSPECT NOSE GEAR UPLOCK: PHASE 2 PKG 2	MOS	24				PKG	26-AUG-2019	
32.490	REF: AMM 32-31-05	HRS/MSC AFL	300					5545 4067	
A323003 (s)	INSPECT EMERGENCY GEAR EXTENSION SYSTEM CABLE: PHASE 5 PKG 7,111	MOS	36				PKG	12-DEC-2017	
32.500	REF: AMM 32-31-08	HRS/MSC AFL	1200						

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A323004 (s)	INSPECT MAIN GEAR UPLOCK: PHASE 2						PKG		
32.510	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-31-05	HRS/MSC	300				5545		
		AFL					4067		
A323005 (s)	INSPECT MAIN GEAR UPLOCK: PHASE 2						PKG		
32.510	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-31-05	HRS/MSC	300				5545		
		AFL					4067		
A324001 (s)	INSPECT/SERVICE MAIN GEAR WHEEL, TIRE AND BEARING: PHASE 2						PKG		
32.520	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-41-01	HRS/MSC	300				5545		
		AFL					4067		
A324002 (s)	INSPECT/SERVICE NOSE WHEEL, TIRE AND BEARING: PHASE 2						PKG		
32.360	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-41-02	HRS/MSC	300				5545		
		AFL					4067		
A324003 (s)	INSPECT/SERVICE NOSE WHEEL, TIRE AND BEARING (WITH GRAVEL RUNWAY): PHASE 2						PKG		
32.360	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-41-02	HRS/MSC	300				5545		
		AFL					4067		
A324004 (s)	INSPECT BRAKE MASTER CYLINDER: PHASE 1						PKG		
32.360	PKG 1	MOS	24				26-AUG-2019		
	REF: AMM 32-42-02	HRS/MSC	300				5545		
		AFL					4067		
A324005 (s)	INSPECT EMERGENCY BRAKE CONTROL VALVE: PHASE 5						PKG		
32.530	PKG 7,101	MOS	36				12-DEC-2017		
	REF: AMM 32-42-09	HRS/MSC	1200						
		AFL							
A324007 (s)	INSPECT BRAKE RESERVOIR AND ANTISKID SYSTEM COMPONENTS: PHASE 5						PKG		
32.540	PKG 7,100	MOS	36				12-DEC-2017		
	REF: AMM 32-42-00	HRS/MSC	1200						
		AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A324012 (s)	INSPECT MAIN LANDING GEAR WHEEL BRAKE: PHASE 2						PKG		
32.550	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-42-01	HRS/MSC	300				5545		
		AFL					4067		
A324013 (s)	INSPECT BRAKE METERING VALVE: PHASE 2						PKG		
32.560	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-42-10	HRS/MSC	300				5545		
		AFL					4067		
A324014 (s)	INSPECT/SERVICE MAIN GEAR WHEEL, TIRE AND BEARING: PHASE 2						PKG		
32.520	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-41-01	HRS/MSC	300				5545		
		AFL					4067		
A325001 (s)	INSPECT NOSE STEERING ARM SUPPORT BRACKET, BUNGEE AND BELLCRANK: PHASE 5						PKG		
32.570	PKG 7,103	MOS	36				12-DEC-2017		
	REF: AMM 32-51-00	HRS/MSC	1200						
		AFL							
A325002 (s)	INSPECT NOSE STEERING SYSTEM CABLE: PHASE 5						PKG		
32.580	PKG 7,111	MOS	36				12-DEC-2017		
	REF: AMM 32-51-00	HRS/MSC	1200						
		AFL							
A325003 (s)	INSPECT GRAVEL RUNWAY/NOSE WHEEL SPIN-UP COMPONENTS: PHASE 2						PKG		
32.590	PKG 2,4,15	MOS					26-AUG-2019		
	REF: AMM 32-43-00	HRS/MSC	150				5545		
		AFL					4067		
A325004 (s)	INSPECT NOSE WHEEL SPIN-UP CONTROL: PHASE 2						PKG		
32.600	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 32-43-00	HRS/MSC	300				5545		
		AFL					4067		
A325009	INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK: PHASE MG								
32.090	6642000-3 PKG 74	MOS					28-APR-1993		
	SN-UNKNOWN	HRS/MSC					0		
AIRWORTHINESS	REF: AMM 32-21-01	AFL	10000				0		10000

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B324006 (s)	CHECK MAIN GEAR WHEEL BRAKES WEAR: PHASE 2 PKG 2,4,15	MOS					PKG		
32.620	REF: AMM 32-42-01	HRS/MSC AFL	150				26-AUG-2019 5545 4067		
B324008 (s)	OPERATIONAL CHECK ANTISKID BRAKE SYSTEM: PHASE 5 PKG 7,104	MOS	36				PKG		
32.630	REF: AMM 32-42-00	HRS/MSC AFL	1200				12-DEC-2017		
B324009 (s)	OPERATIONAL TEST EMERGENCY BRAKE SYSTEM: PHASE 5 PKG 7,104	MOS	36				PKG		
32.640	REF: AMM 32-42-09	HRS/MSC AFL	1200				12-DEC-2017		
B325001 (s)	FUNCTIONAL TEST NOSE WHEEL SPIN-UP SYSTEM: PHASE 5 PKG 7,104	MOS	36				PKG		
32.650	REF: AMM 32-43-00	HRS/MSC AFL	1200				12-DEC-2017		
B326001 (s)	ADJUSTMENT/TEST LANDING GEAR HYDRAULIC SYSTEMS: PHASE 2 PKG 2	MOS	24				PKG		
32.660	REF: AMM 32-01-00	HRS/MSC AFL	300				26-AUG-2019 5545 4067		
B326002 (s)	CYCLE TEST LANDING GEAR: PHASE 2 PKG 2	MOS	24				PKG		
32.670	REF: AMM 32-01-00	HRS/MSC AFL	300				26-AUG-2019 5545 4067		
B326003	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 212940-2	MOS	36					30-NOV-2018	30-NOV-2021
32.180	REF: AMM 32-31-09	HRS/MSC AFL							
B326004 (s)	PERFORM LANDING GEAR HYDRAULIC SYSTEMS TEST: PHASE 2 PKG 2	MOS	24				PKG		
32.680	REF: AMM 32-01-00	HRS/MSC AFL	300				26-AUG-2019 5545 4067		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C325013 (s)	INSPECT NOSE WHEEL INNER AXLE: PHASE 2						PKG		
32.700	PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
D324007 (s)	REPLACE ANTISKID SYSTEM MOTOR/PUMP FILTER: PHASE 5						PKG		
32.710	PKG 7,100 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
D324010 (s)	REPLACE BRAKE RESERVOIR AIR FILTER: PHASE 5						PKG		
32.720	PKG 7,100 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
D324011 (s)	CLEAN BRAKE RESERVOIR SUPPLY LINE FILTER: PHASE 5						PKG		
32.730	PKG 7,100 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
D324012 (s)	CLEAN MASTER CYLINDER IN-LINE FILTER: PHASE 5						PKG		
32.760	PKG 7,100 REF: AMM 32-42-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 33 LIGHTS									
331001	NO. 1 LIGHT PANEL DIMMER								
33.150	273-1 1019 REF: AMM 33-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
331001	NO. 2 LIGHT PANEL DIMMER								
33.150	1821-1 2178 REF: AMM 33-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
331001	NO. 3 LIGHT PANEL DIMMER								
33.150	273-1 2183 REF: AMM 33-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331011	INVT-115V EL PANEL								
33.160	EM2044-1 1687 REF: AMM 33-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
332001	INDIRECT LIGHT POWER UNIT								
33.030	AL-5112 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
332002	AFT INDIRECT LIGHTING INVERTER								
33.020	AL0581 7215 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
332002	FORWARD INDIRECT LIGHTING INVERTER								
33.010	AL5114 4882 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
334002	ROTATING/FLASHING BEACON								
33.080	01-0790044-33 00476 REF: AMM 33-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			08-OCT-2019 5574 4090		
334003	NO. 1 STROBE POWER SUPPLY								
33.090	60-2799-1 16301 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
334003	NO. 2 STROBE POWER SUPPLY								
33.090	60-2799-1 16531 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
335001	EMERGENCY BATTERY PACK								
33.080	6518109-11 SN-UNKNOWN REF: AMM 33-51-01	MOS HRS/MSC AFL	O/C	TSN:0			28-JUN-1999 1505		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A332001 (s)	INSPECT INDIRECT CABIN FLUORESCENT LIGHTING: PHASE 5						PKG		
33.100	PKG 7,103 REF: AMM 33-21-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A335001 (s)	INSPECT EMERGENCY LIGHTS, BATTERY BOX AND BATTERIES: PHASE 5						PKG		
33.110	PKG 7,101 REF: AMM 33-51-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A335002 (s)	INSPECT EMERGENCY EXIT LIGHTS: PHASE 1						PKG		
33.120	PKG 1 REF: AMM 33-51-01	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
A335003 (s)	INSPECT EMERGENCY LIGHTS, BATTERY BOX AND BATTERIES: PHASE 5						PKG		
33.130	PKG 7,101 REF: AMM 33-51-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B335001 (s)	OPERATIONAL CHECK EMERGENCY LIGHTS: PHASE 1						PKG		
33.140	PKG 1 REF: AMM 33-51-01	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
CHAPTER 34 NAVIGATION									
341001	NO. 1 AIRSPEED INDICATOR								
34.190	C661063-0107 242 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C				17-JUN-2011 4657:12 3284		
341001	NO. 2 AIRSPEED INDICATOR								
34.190	C661063-0107 141 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-JUL-2013 4914:12 3522		
341002	STANDBY ALTIMETER								
34.750	24929-013 1140 REF: AMM 34-11-00	MOS HRS/MSC AFL	O/C				30-APR-2013 4885 3500		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341005	S262 MACH/AIRSPEED WARNING SWITCH D2RA45C-28 141 REF: AMM 34-11-04	MOS HRS/MSC AFL	O/C	TSO:0			26-JUN-2000 1729		
341006	PITOT PRESSURE SWITCH D37C15 2519 REF: AMM 34-11-10	MOS HRS/MSC AFL	O/C	TSN:0			19-JUN-2002 2322		
341010	ANGLE OF ATTACK INDICATOR C11605-1 342 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
341010	RIGHT INDICATOR-AOA C11605-1 331 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
341011	ANGLE OF ATTACK STALL WARNING COMPUTER C11606-8 485 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSO:0			03-JUN-1998 1209		
341013	ANGLE OF ATTACK TRANSMITTER 1703-15 363 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
341014	ANGLE OF ATTACK INDEXER 965-0113-008 1013 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
341015	PILOT RADIO ALTIMETER ALT-55B INDICATOR 622-2937-009 2784 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341020	VNAV CONTROL 4020571-904 79110722 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
341022	OAT INDICATOR C668510-0401 2617 REF:	MOS HRS/MSC AFL	O/C	TSO:372			03-JUN-1998 1209		
341023	HONEYWELL AA300 RADIO ALT TRANSCEIVER 7002638-904 92100900 REF: AMM 34-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
341023	RIGHT INDICATOR-TAS/TEMP 7002638-904 86080525 REF:	MOS HRS/MSC AFL	O/C	TSO:0			18-FEB-2002 2209		
341035	ANGLE OF ATTACK HEAT MONITOR- 1703-147-2 347 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
342001	MAGNETIC COMPASS C660501-0301 NSN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			04-MAY-2015 5033:06 3691		
342023	RADAR CONTROLLER 7008471-803 92081592 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
342041	NO. 1 FLIGHT DIRECTOR COMPUTER 4018369-905 93016787 REF:	MOS HRS/MSC AFL	O/C				24-JUN-2011		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342041	NO. 2 FLIGHT DIRECTOR COMPUTER 4018369-905	MOS					08-DEC-2014		
34.781	89045823 REF:	HRS/MSC AFL	O/C				5004:18 3694		
342042	NO. 1 MODE FLIGHT DIRECTOR SELECTOR 4020570-905	MOS					13-JUN-2005		
34.250	91122085 REF: AMM 34-22-01	HRS/MSC AFL	O/C	TSO:0			3148		
342042	NO. 2 MODE FLIGHT DIRECTOR SELECTOR 4020570-905	MOS					13-JUN-2005		
34.250	92112152 REF: AMM 34-22-01	HRS/MSC AFL	O/C	TSO:0			3148		
342043	NO. 1 VERTICAL FLIGHT DIRECTOR GYRO 7000622-901	MOS					02-FEB-1999		
34.360	87075957 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:1234			1406		
342043	NO. 2 VERTICAL FLIGHT DIRECTOR GYRO 7000622-901	MOS					17-JUN-2011		
34.360	85025250 REF: GENERIC NO REF	HRS/MSC AFL	O/C				4657:12 3284		
342044	NO. 1 RATE OF TURN GYRO 7007453-903	MOS					28-APR-1993		
34.350	92073128 REF: AMM 34-22-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
342044	NO. 2 RATE OF TURN GYRO 7007453-903	MOS					28-APR-1993		
34.350	92083161 REF: AMM 34-22-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
342049	NO. 1 DIRECTIONAL GYRO 4020577-3	MOS					24-JUN-2011		
34.340	99076738 REF: AMM 34-21-05	HRS/MSC AFL	O/C						

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342049	NO. 2 DIRECTIONAL GYRO 4020577-3 92095279 REF: AMM 34-21-05	MOS HRS/MSC AFL	O/C				24-JUN-2011		
34.340									
342050	NO. 1 FLUX DETECTOR 2594484 97092407 REF: AMM 34-21-16	MOS HRS/MSC AFL	O/C	TSN:0			08-NOV-1997 1084		
34.390									
342050	NO. 2 FLUX DETECTOR 2594484 0609H365 REF: AMM 34-21-16	MOS HRS/MSC AFL	O/C				17-JUN-2011 4657:12 3284		
34.390									
342052	REMOTE COMPENSATOR 2593379-1 92050701 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.230									
342063	NO. 1 REMOTE COURSE CONTROL 4026206-974 92094805 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.260									
342065	STANDBY GYRO 501-1197-05 4635 REF: AMM 34-21-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.380									
342066	LEFT BOTTOM EFIS DISPLAY 7003430-901 92102794 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.905									
342066	LEFT TOP EFIS DISPLAY 7003430-901 90021589 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-JUN-2012 4811:48 3420		
34.905									

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342066	MFD 1 EFIS DISPLAY								
34.905	7003430-901 92032599 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-JUN-2011 4657:12 3284		
342066	RIGHT BOTTOM EFIS DISPLAY								
34.905	7003430-901 90112006 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:3034			14-JUN-2007 3882		
342066	RIGHT TOP EFIS DISPLAY								
34.905	7003430-901 90112012 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-JUN-2011 4657:12 3284		
342068	NO. 1 (EFIS) CONTROLLER DISPLAY								
34.310	7012977-753 91071009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
342068	NO. 2 (EFIS) CONTROLLER DISPLAY								
34.310	7012977-753 92101312 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
342069	MULTIFUNCTION DISPLAY CONTROLLER								
34.300	7007062-927 93021205 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			26-AUG-1993 42		
342069	NO. 1 INCLINOMETER								
34.320	7005400-901 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
342069	NO. 2 INCLINOMETER								
34.320	7005400-901 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342070	NO. 1 EFIS SYMBOL GENERATOR 7011672-667 87110115 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSO:606			08-JAN-2007 3686		
34.787									
342070	NO. 2 EFIS SYMBOL GENERATOR 7011672-667 92111167 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSO:0			05-JAN-2006 3352		
34.787									
342071	MFD SYMBOL GENERATOR 7011673-667 92100455 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C				26-JAN-2012 4753:36 3376		
34.789									
342072	STATIC CONVERTER 501-1318-01 3890 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.330									
342073	AFIS DATA MANAGEMENT UNIT 400-045500-0003 3882 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-JUN-2011 4657:12 3284		
34.470									
342075	NO. 1 ADAPTER-BRG INTERF 622-8613-002 146 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.370									
342075	NO. 2 ADAPTER-BRG INTERF 622-8613-002 145 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.370									
342176	PS-835 EMERGENCY POWER SUPPLY 501-1228-03 9760 REF: AMM 34-21-12	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			19-SEP-2017		
34.370									

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344003	PRIMUS 650 RADAR RECEIVER/TRANSMITTER								
34.410	7012640-901 92060979 REF: AMM 34-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			10-OCT-2018 5351:24 3910		
344021	NO. 1 RADIO MAGNETIC INDICATOR								
34.510	622-2506-008 8010 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
344021	NO. 2 RADIO MAGNETIC INDICATOR								
34.510	622-2506-008 5886 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	TSO:0			04-JUN-1995 461		
344022	RADIO ALT TRANSCEIVER								
34.110	622-2855-001 8406 REF: AMM 34-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
344023	AFT RECEIVER RADIO ALT ANTENNA								
34.120	622-0954-001 5715 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
344023	FORWARD TRANSMITTER RADIO ALT ANTENNA								
34.120	622-0954-001 5708 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
344024	GROUND PROXIMITY WARNING SYS COMPUTER								
34.430	965-1198-005 EMKGA-06923 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			27-DEC-2011 4753:36 3376		
344025	CONFIGURATION MODULE								
34.909	050-03621-0000 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345004	AFT TRANSPONDER ANTENNA								
34.420	DMNI50-2-2 50237 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345004	FORWARD TRANSPONDER ANTENNA								
34.420	DMNI50-2-2 50214 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345007	AFT DME ANTENNA								
34.520	DMNI50-2-2 50208 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345007	FORWARD DME ANTENNA								
34.520	DMNI50-2-2 50207 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345010	NO. 1 NAVIGATION ANTENNA								
34.420	DMN4-17-1B 3834 REF: AMM 34-52-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345011	NO. 1 ADF RECEIVER								
34.450	622-7382-101 1987 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345011	NO. 2 ADF RECEIVER								
34.450	622-7382-101 2087 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345012	NO. 1 ADF CONTROL								
34.450	622-6522-005 8835 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345012	NO. 2 ADF CONTROL 622-6522-005 9004 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSO:739:12			17-JUN-2011 4657:12 3284		
34.450									
345014	NO. 1 ADF ANTENNA 622-7383-001 997 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.450									
345014	NO. 2 ADF ANTENNA 622-7383-001 1031 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.450									
345017	MARKER BEACON ANTENNA DMN27-3 9345 REF: AMM 25-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.400									
345018	GLIDESLOPE ANTENNA RGS10-48 A2804 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.400									
345032	NO. 1 VHF NAV RECEIVER 622-6137-201 13550 REF: AMM 34-52-04	MOS HRS/MSC AFL	O/C	TSO:0			17-JUN-2004		
34.825									
345032	NO. 2 VHF NAV RECEIVER 622-6137-201 17462 REF: AMM 34-52-04	MOS HRS/MSC AFL	O/C				04-MAY-2015 5033:06 3691		
34.825									
345033	BOTTOM VHF NAV CONTROL 622-6521-013 13900 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
34.911									

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345033	VHF NAV CONTROL								
34.911	622-6521-013 13899 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345034	NO. 1 ATC TRANSPONDER								
34.550	066-01143-2101 M114613 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	TSO:0			07-MAY-2008 4224		
345034	NO. 2 ATC TRANSPONDER								
34.550	066-01143-2101 1100 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				03-FEB-2015 5004:48 3695		
345035	NO. 1 DME INDICATOR								
34.500	622-7318-001 3041 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345035	NO. 2 DME INDICATOR								
34.500	622-7318-001 2806 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345036	NO. 1 DME RECEIVER TRANSMITTER								
34.530	622-6263-003 12006 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345036	NO. 2 DME RECEIVER TRANSMITTER								
34.530	622-6263-003 11503 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345037	MFD CHECKLIST								
34.829	7990197-132 92101154 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345081	(AFIS)CONFIGURATION MODULE								
34.470	31990-1 11640 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
345081	NO. 1 CONFIGURATION MODULE								
34.470	31990-1 3343 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
345082	NO. 1 GNS/FMS DISPLAY								
34.857	17960-0204-0002 30311 REF: AMM 34-61-03	MOS HRS/MSC AFL	O/C				09-OCT-2015 5094 3456		
345093	GPS ANTENNA								
34.490	071-01533-0200 340443 REF: AMM 34-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
346001	TCAS PROCESSOR								
34.560	066-01146-2221 TPU67B-C42148 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C				26-OCT-2015 5098:36 3757		
346002	BOTTOM TCAS ANTENNA								
34.570	071-01548-0100 12267 REF: AMM 34-40-05	MOS HRS/MSC AFL	O/C	TSO:0			21-JUL-2005 3158		
346002	TOP TCAS ANTENNA								
34.570	071-01548-0100 12279 REF: AMM 34-40-05	MOS HRS/MSC AFL	O/C	TSO:0			21-JUL-2005 3158		
346004	CONTROL TCAS								
34.690	071-01619-0121 38 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSO:0			21-JUL-2005 3158		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346031	NO. 1 TCAS INDICATOR 066-01171-2804 32787 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-JUN-2011 4657:12 3284		
34.873									
346031	NO. 2 TCAS INDICATOR 066-01171-2804 23828 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-JUN-2011 4657:12 3284		
34.873									
34FO-01 560	0 FUEL WT INCREASE 12,200 LBS FACTORY OPTION 185J FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		
34FO-02 560	INDEXER-PILOTS ANGLE OF ATTACK FACTORY OPTION 11A FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		
34FO-05 560	ADF-2/COLLINS ADF462 ONLY W/STD COLLINS FACTORY OPTION 659C FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		
34FO-08 560/J	DME 2-COLLINS DME 42 ONLY W/STD PACKAGE FACTORY OPTION 681J FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		
34FO-09 560/X	FM SYS-5TUBE HONEYWL EFIS FACTORY OPTION 685X FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		
34FO-12 560/K	RADAR-PRIMUS 870 W/MFD FACTORY OPTION 627K FO REF:	MOS HRS/MSC AFL	-				28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A341009 (s)	PERFORM SAFE FLIGHT ANGLE-OF-ATTACK SYSTEM CHECK: PHASE 5						PKG		
34.600	PKG 7,101 REF: AMM 34-13-06	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A342001 (s)	INSPECT MAGNETIC COMPASS AND COMPASS CARD: PHASE 5						PKG		
34.620	PKG 7,101 REF: AMM 34-21-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B341001	CALIBRATION TEST NO. 1 AIRSPEED INDICATOR (AIRPLANES -0001 THRU -0259) NOT CERTIFIED FOR RVSM (FAR 91.411): PHASE 20								
34.210	C661063-0107 PKG 24 242 REF: AMM 34-11-00	MOS HRS/MSC AFL	24				17-MAY-2018 5179 3793	17-MAY-2020	
B341001	CALIBRATION TEST NO. 2 AIRSPEED INDICATOR (AIRPLANES -0001 THRU -0259) NOT CERTIFIED FOR RVSM (FAR 91.411): PHASE 20								
34.210	C661063-0107 PKG 24 141 REF: AMM 34-11-00	MOS HRS/MSC AFL	24				17-MAY-2018 5179 3793	17-MAY-2020	
B341002 (s)	OPERATIONAL TEST TELEDYNE ANGLE-OF-ATTACK SYSTEM: PHASE 5						PKG		
34.640	PKG 7,105 REF: AMM 34-13-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B341003	CALIBRATION TEST STANDBY ALTIMETER (91.411): PHASE 20								
34.761	PN PKG 24 SN-UNKNOWN REF: AMM 34-14-00	MOS HRS/MSC AFL	24				17-MAY-2018 5179 3793	17-MAY-2020	
B341005	LEAK TEST LEFT STATIC SYSTEM (FAR 91.411) AIRPLANES -0001 THRU -0259 NOT CERTIFIED FOR RVSM : PHASE 20								
34.010	PKG 24 REF: AMM 34-11-00	MOS HRS/MSC AFL	24				17-MAY-2018 5179 3793	17-MAY-2020	

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B341005	LEAK TEST RIGHT STATIC SYSTEM (FAR 91.411) AIRPLANES -0001 THRU -0259 NOT CERTIFIED FOR RVSM : PHASE 20								
34.010	PKG 24 REF: AMM 34-11-00	MOS HRS/MSC AFL	24				17-MAY-2018 5179 3793	17-MAY-2020	
B341301 (s)	OPERATIONAL CHECK TELEDYNE PRIMARY ANGLE OF ATTACK FLAP POSITION POTENIOMETER ADJUSTMENT: PHASE 5						PKG		
34.879	PKG 7,101 REF: AMM 34-13-03	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B341302 (s)	OPERATIONAL CHECK TELEDYNE SECONDARY ANGLE OF ATTACK FLAP POSITION POTENIOMETER ADJUSTMENT: PHASE 5						PKG		
34.879	PKG 7,101 REF: AMM 34-13-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B341303 (s)	PERFORM TELEDYNE ANGLE-OF-ATTACK SYSTEM FLIGHT CALIBRATION: PHASE 5						PKG		
34.881	PKG 7,101 REF: AMM 34-13-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B341304 (s)	OPERATIONAL CHECK SAFE FLIGHT ANGLE OF ATTACK SYSTEM CHECK(AIRPLANES -0056 THRU -0538) : PHASE 5						PKG		
34.881	PKG 7,101 REF: AMM 34-13-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B341308 (s)	OPERATIONAL CHECK SAFE FLIGHT ANGLE OF ATTACK SYSTEM ICE MODE CHECK(AIRPLANES -0056 THRU -0538): PHASE 2						PKG		
34.885	PKG 2,4,15 REF: AMM 34-13-02	MOS HRS/MSC AFL	150				26-AUG-2019 5545 4067		
B341310 (s)	PERFORM SAFE FLIGHT ANGLE OF ATTACK SYSTEM FLIGHT CALIBRATION(AIRPLANES -0056 THRU -0538): PHASE 5						PKG		
34.680	PKG 7,101 REF: AMM 34-13-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B342001 (s) 34.710	OPERATIONAL TEST MAGNETIC COMPASS SYSTEMS AND ADF BEARING: PHASE 5 C660501-0301 PKG 7,105 NSN REF: AMM 34-21-05	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B342003 (s) 34.370	CAPACITY TEST PS-835 EMERGENCY POWER SUPPLY : PHASE 18 501-1228-03 PKG 22 9760 REF: AMM 34-21-12	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		
B342004 (s) 34.370	PERIODIC CHECK PS-835 EMERGENCY POWER SUPPLY : PHASE 11 501-1228-03 PKG 16 9760 REF: AMM 34-21-12	MOS HRS/MSC AFL	3				PKG 14-MAY-2019 5441 3993		
B342006 (s) 34.370	PERIODIC CHECK PS-850/PS-855 EMERGENCY POWER SUPPLY : PHASE 11 PN PKG 16 SN-UNKNOWN REF: AMM 34-21-12	MOS HRS/MSC AFL	3				PKG 14-MAY-2019 5441 3993		
B345001 34.550	CALIBRATION TEST NO. 1 ATC TRANSPONDER (FAR 91.413): PHASE 20 066-01143-2101 PKG 24 M114613 REF: AMM 34-54-00	MOS HRS/MSC AFL	24				17-MAY-2018 5179 3793	17-MAY-2020	
B345001 34.550	CALIBRATION TEST NO. 2 ATC TRANSPONDER (FAR 91.413): PHASE 20 066-01143-2101 PKG 24 1100 REF: AMM 34-54-00	MOS HRS/MSC AFL	24				17-MAY-2018 5179 3793	17-MAY-2020	
CHAPTER 35	OXYGEN								
350004 35.010	HYDROSTATIC TEST OXYGEN CYLINDER 895-20077 C12050116 REF:	MOS HRS/MSC AFL	60				20-OCT-2017	20-OCT-2022	
351001 35.020	OXYGEN PRESSURE GAUGE C668512-0101 549 REF: GENERIC NO REF	MOS HRS/MSC AFL			O/C	TSN:0 TSN:0 TSN:0	28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351002	OXYGEN PRESSURE SWITCH								
35.100	P24031 1136 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
351004	COPILOT OXYGEN MASK								
35.030	174045-15 50370 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSN:4657:12 TSO:0 TSN:3284 TSO:0			17-JUN-2011 4657:12 3284		
351004	PILOT OXYGEN MASK								
35.030	174045-15 50552 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0			17-JUN-2011 4657:12 3284		
351005	OXYGEN SUPPLY REGULATOR								
35.050	172210 0132 REF:	MOS HRS/MSC AFL	O/C	TSO:0			29-JUN-2001 2061		
351006	OXYGEN CYLINDER								
35.010	895-20077 C12050116 REF:	MOS HRS/MSC AFL	180				15-DEC-2017	01-MAR-2027	
LIFE LIMIT Manufacture Date: 01-MAR-2012									
A351001 (s)	INSPECT OXYGEN SYSTEM: PHASE 5						PKG		
35.040	PKG 7,108 REF: AMM 35-00-05	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A351007 (s)	INSPECT PASSENGER OXYGEN MASKS: PHASE 18						PKG		
35.060	PKG 22 REF: AMM 35-20-00	MOS HRS/MSC AFL	12				11-DEC-2018 5384 3938		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B350006 (s)	FUNCTIONAL TEST OXYGEN SYSTEM, FLOW FUSES AND SHUTTLE VALVES: PHASE 5						PKG		
35.070	PKG 7,108 REF: AMM 35-10-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B351002 (s)	FUNCTIONAL TEST OXYGEN SYSTEM: PHASE 5						PKG		
35.080	PKG 7,108 REF: AMM 35-10-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B351003 (s)	OPERATIONAL CHECK CREW OXYGEN MASK INSPECTION, FLOW CHECK AND MICROPHONE: PHASE 5						PKG		
35.090	PKG 7,107 REF: AMM 35-10-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 36 PNEUMATIC									
361003	PNEUMATIC REGULATOR								
36.100	38E85-5C RF1961 REF: AMM 36-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
361008	NO. 1 VALVE CHECK								
36.080	1553-00-18 3291 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			10-FEB-2011 4641 3277		
361008	NO. 2 VALVE CHECK								
36.080	1H95-3 1AH38 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
A361004 (s)	INSPECT BLEED AIR CHECK VALVES: PHASE 3						PKG		
36.030	PKG 3 REF: AMM 36-11-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
A361005 (s)	LEAK CHECK ENGINE BLEED AIR BELLOWS: PHASE 4						PKG		
36.040	PKG 4 REF: AMM 36-10-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A361101 (s)	LEAK CHECK TAILCONE BLEED AIR LINES: PHASE 4						PKG		
36.160	PKG 4 REF: AMM 36-11-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
A361102 (s)	DETAILED INSPECTION TAILCONE BLEED AIR LINE PERI-SEALS: PHASE 4						PKG		
36.160	PKG 4 REF: AMM 36-11-01	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
D361100 (s)	REPLACEMENT OF SERVICE AIR SYSTEM PERI-SEAL						PKG		
36.170	PKG 7,106 REF: AMM 36-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 37 VACUUM									
D371001 (s)	CLEAN/REPLACE VACUUM REGULATOR (PRESSURE LINE): PHASE 5						PKG		
37.010	PKG 7,106 REF: AMM 37-11-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 38 WATER/WASTE									
383002	MOTOR AND PUMP TOILET								
38.010	17200-382 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0		28-APR-1993 0 0		
B383001 (s)	OPERATIONAL CHECK REFRESHMENT CENTER DRAINS: PHASE 5						PKG		
38.020	PKG 7,110 REF: AMM 38-30-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
CHAPTER 51 STD PRACTICES AND STRUCT-GENRL									
A510001 (s)	INSPECT EXTERIOR MOISTURE DRAIN HOLES: PHASE 1						PKG		
51.010	PKG 1 REF: AMM 51-10-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A510002 (s)	INSPECT EXTERIOR: PHASE 6						PKG		
51.020	PKG 8 REF: AMM 51-10-00	DAYS HRS/MSC AFL	O/C				27-NOV-2017		
CHAPTER 52 DOORS									
521001	CABIN DOOR SEAL								
52.010	S15501-1 SN-UNKNOWN REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 4657:12 3284		
A521001 (s)	INSPECT STANDARD CABIN DOOR INFLATABLE SEAL: PHASE 5						PKG		
52.030	PKG 7,101 REF: AMM 52-10-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A521003 (s)	INSPECT STANDARD CABIN DOOR: PHASE 5						PKG		
52.040	PKG 7,101 REF: AMM 52-10-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A521004 (s)	INSPECT STANDARD CABIN DOOR LOCKING PINS: PHASE 13						PKG		
52.050	PKG 17 REF: AMM 52-10-02	MOS HRS/MSC AFL	5000	TSI:0 TSI:0 TSI:0			20-MAY-2009 4546		
A521005 (s)	INSPECT STANDARD CABIN DOOR LOCKING COMPONENTS BEARING PLATES: PHASE 16						PKG		
52.060	PKG 20 REF: AMM 52-10-02	MOS HRS/MSC AFL	10000	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
A521006 (s)	INSPECT OPTIONAL ROTARY LATCHING CARGO CABIN DOOR: PHASE 1						PKG		
52.070	PKG 1 REF: AMM 52-10-04	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
A521007 (s)	VISUAL INSPECTION OPTIONAL PIN LATCHING CARGO CABIN DOOR: PHASE 5						PKG		
52.080	PKG 7,101 REF: AMM 52-10-05	MOS HRS/MSC AFL	36 1200				12-DEC-2017		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A521008 (s) 52.090	INSPECT ENTRANCE DOOR SECONDARY SEAL: PHASE 1 PKG 1,3,15 REF: AMM 52-10-01	MOS HRS/MSC AFL	150				PKG 26-AUG-2019 5545 4067		
A522002 (s) 52.100	INSPECT EMERGENCY EXIT DOOR: PHASE 5 PKG 7,100 REF: AMM 52-20-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A523001 (s) 52.110	INSPECT NOSE BAGGAGE DOOR AND LATCHES: PHASE 5 PKG 7,100 REF: AMM 52-30-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A523002 (s) 52.120	INSPECT TAILCONE DOORS: PHASE 5 PKG 7,105 REF: AMM 52-30-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A526001 (s) 52.130	INSPECT STANDARD CABIN DOOR STEP: PHASE 1 PKG 1 REF: AMM 52-60-01	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
A526002 (s) 52.140	INSPECT STANDARD CABIN DOOR COMPOSITE STEP: PHASE 1 PKG 1 REF: AMM 52-60-01	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		
B521008 (s) 52.150	OPERATIONAL TEST CABIN ENTRANCE DOOR SECONDARY SEAL: PHASE 5 PKG 7,101 REF: AMM 21-30-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
B527001 (s) 52.160	INSPECT/OPERATIONAL CHECK DOOR WARNING SYSTEM: PHASE 1 PKG 1 REF: AMM 52-70-01	MOS HRS/MSC AFL	24 300				PKG 26-AUG-2019 5545 4067		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C521002 (s)	LUBRICATE CABIN DOOR HINGE: PHASE 5						PKG		
52.170	PKG 7,101	MOS	36				12-DEC-2017		
	REF: AMM 52-10-01	HRS/MSC AFL	1200						
CHAPTER 53 FUSELAGE									
531001	LEFT NOSE LANDING GEAR TRUNNION SUPPORT								
53.080	6613056-3	MOS					28-APR-1993		
LIFE LIMIT	SN-UNKNOWN	HRS/MSC					0		
	REF: AMM 53-10-00	AFL	12050	TSN:14	14		0		12050
531001	RIGHT NOSE LANDING GEAR TRUNNION SUPPORT								
53.080	6613056-4	MOS					28-APR-1993		
LIFE LIMIT	SN-UNKNOWN	HRS/MSC					0		
	REF: AMM 53-10-00	AFL	12050	TSN:14	14		0		12050
531202	NOSE LANDING GEAR ACTUATOR FITTING								
53.070	6511105-1	MOS					28-APR-1993		
LIFE LIMIT	SN-UNKNOWN	HRS/MSC					0		
	REF: GENERIC NO REF	AFL	23500	TSN:14	14		0		23500
535000	RADOME								
53.020	6591101-7	MOS		TSN:0			17-JUN-2011		
	117	HRS/MSC	O/C	TSN:0			4657:12		
	REF: GENERIC NO REF	AFL		TSN:0			3284		
A530001 (s)	INSPECT NOSE LANDING GEAR WHEEL WELL GENERAL VISUAL (CORROSION INSPECTION): PHASE 18						PKG		
	PKG 22	MOS	12				11-DEC-2018		
	REF: AMM 53-00-00	HRS/MSC AFL					5384 3938		
A530002 (s)	NOSE LANDING GEAR WHEEL WELL GENERAL VISUAL INSPECTION (CORROSION INSPECTION): PHASE 64						PKG		
	PKG 503	MOS	6				14-MAY-2019		
	REF:	HRS/MSC AFL					5441 3993		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531001 (s)	INSPECT FORWARD SIDE OF PRESSURE BULKHEAD: PHASE 5						PKG		
53.140	PKG 7,100	MOS	36				12-DEC-2017		
	HRS/MSC		1200						
	REF: AMM 53-10-00	AFL							
A531002 (s)	INSPECT UNDERFLOOR: PHASE 5						PKG		
53.150	PKG 7,111	MOS	36				12-DEC-2017		
	HRS/MSC		1200						
	REF: AMM 53-20-08	AFL							
A531003 (s)	GENERAL INSPECTION AFT PRESSURE BULKHEAD TAILCONE: PHASE 5						PKG		
53.160	PKG 7,105	MOS	36				12-DEC-2017		
	HRS/MSC		1200						
	REF: AMM 53-20-04	AFL							
A531004 (s)	INSPECT FRONT AND REAR SPAR CARRY-THRU: PHASE 5						PKG		
53.170	PKG 7,111	MOS	36				12-DEC-2017		
	HRS/MSC		1200						
	REF: AMM 53-10-09	AFL							
A531006 (s)	INSPECT EMERGENCY EXIT DOOR FRAME: PHASE MC						PKG		
53.190	PKG 70	MOS		TSI:0			20-MAY-2009		
AIRWORTHINESS	REF: AMM 53-10-09	HRS/MSC	1456	TSI:0			4546		
		AFL		TSI:0					
A531007 (s)	INSPECT WINDSHIELD, COCKPIT SIDE WINDOW AND CABIN WINDOW FRAMES: PHASE MI						PKG		
53.200	PKG 76	MOS					10-JUL-2014		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	5130				4972		
		AFL					3668		
A531008 (s)	INSPECT FUSELAGE INTERIOR CABIN STRUCTURE: PHASE 1						PKG		
53.210	PKG 1	MOS	24				26-AUG-2019		
	HRS/MSC		300				5545		
	REF: AMM 53-10-09	AFL					4067		
A531009 (s)	INSPECT CABIN STRUCTURE: PHASE 17						PKG		
53.220	PKG 21	MOS		TSI:0			28-APR-1993		
	HRS/MSC		10000	TSI:0			0		
	REF: AMM 53-10-00	AFL		TSI:0			0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531010 (s)	INSPECT OPTIONAL CARGO DOOR AND DOOR FRAME: PHASE 5						PKG		
53.230	PKG 7	MOS	36				12-DEC-2017		
	REF: AMM 53-10-09	HRS/MSC	1200						
		AFL							
A531011 (s)	INSPECT MAIN CARRY-THRU TO WING SPAR LUGS: PHASE 67						PKG		
53.240	PKG 504	MOS					01-OCT-2013		
	REF: AMM 53-10-00	HRS/MSC	1200				4917		
		AFL					3525		
A531012 (s)	INSPECT CABIN DOOR THRESHOLD: PHASE 1						PKG		
53.250	PKG 1	MOS	24				26-AUG-2019		
	REF: AMM 53-10-09	HRS/MSC	300				5545		
		AFL					4067		
A531013 (s)	INSPECT FORWARD PRESSURE BULKHEAD ATTACH ANGLES: PHASE MK						PKG		
53.260	PKG 78	MOS		TSI:0			28-APR-1993		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC	6725	TSI:0			0		
		AFL		TSI:0			0		
A531014 (s)	INSPECT AFT PRESSURE BULKHEAD ATTACH ANGLES: PHASE MK						PKG		
53.270	PKG 78	MOS		TSI:0			28-APR-1993		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC	6725	TSI:0			0		
		AFL		TSI:0			0		
A531015 (s)	INSPECT AFT PRESSURE BULKHEAD WEB: PHASE 34						PKG		
53.280	PKG 48	MOS		TSI:0			28-APR-1993		
	REF: AMM 53-10-04	HRS/MSC	6725	TSI:0			0		
		AFL		TSI:0			0		
A531016 (s)	INSPECT CABIN DOORFRAME: PHASE 5						PKG		
53.290	PKG 7,103	MOS	36				12-DEC-2017		
	REF: AMM 53-10-00	HRS/MSC	1200						
		AFL							
A531017 (s)	INSPECT MAIN SPAR CARRY-THRU ASSEMBLY: PHASE 14						PKG		
53.300	PKG 18	MOS		TSI:0			28-APR-1993		
	REF: AMM 53-10-09	HRS/MSC	12000	TSI:0			0		
		AFL		TSI:0			0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531019 (s) 53.310	INSPECT WING ATTACH BOLT AND LUG: PHASE 5 PKG 7,109 REF: AMM 53-10-09	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A531020 (s) 53.320 AIRWORTHINESS	INSPECT FORWARD SIDE OF FORWARD PRESSURE BULKHEAD WEB: PHASE ME PKG 72 REF: AMM 53-10-00	MOS HRS/MSC AFL	4450				PKG 17-FEB-2012 4757:36 3380		
A531021 (s) 53.330 AIRWORTHINESS	INSPECT AFT SIDE OF AFT PRESSURE BULKHEAD WEB: PHASE ME PKG 72 REF: AMM 53-10-04	MOS HRS/MSC AFL	4450				PKG 17-FEB-2012 4757:36 3380		
A531023 (s) 53.460 AIRWORTHINESS	INSPECT CABIN DOOR FRAME (AIRPLANES -0046 AND ON): PHASE MF PKG 73 REF: AMM 53-10-10	MOS HRS/MSC AFL	5000				PKG 23-JUN-2006 3436		
A531037 (s) 53.350	INSPECT STUB WING SHEAR ATTACH FITTING BOLT: PHASE 5 PKG 7,109 REF: AMM 53-10-02	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A532001 (s) 53.360	INSPECT CONTROL PEDESTAL AREA: PHASE 5 PKG 7,102 REF: AMM 53-20-02	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A532002 (s) 53.370	INSPECT NOSE GEAR WHEEL WELL: PHASE 5 PKG 7,103 REF: AMM 53-10-09	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
A532003 (s) 53.380	INSPECT AFT CABIN UNDERFLOOR FOR CORROSION: PHASE 18 PKG 22 REF: AMM 53-10-09	MOS HRS/MSC AFL	12				PKG 11-DEC-2018 5384 3938		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A533001 (s)	INSPECT FUSELAGE EXTERIOR SKIN: PHASE MD						PKG		
53.390	PKG 71	MOS		TSl:0			23-JUN-2006		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	2523	TSl:0			3436		
		AFL		TSl:0					
A533003 (s)	INSPECT CABIN LOWER SKIN LONGITUDINAL SPLICE: PHASE MJ						PKG		
53.400	PKG 77	MOS		TSl:0			28-APR-1993		
AIRWORTHINESS	REF: AMM 53-30-00	HRS/MSC	5900	TSl:0			0		
		AFL		TSl:0			0		
A533006 (s)	INSPECT FUSELAGE EXTERIOR SKIN CORROSION: PHASE 5						PKG		
53.410	PKG 7,100	MOS	36				12-DEC-2017		
	REF: AMM 53-30-00	HRS/MSC	1200						
		AFL							
A533010 (s)	EDDY CURRENT INSPECTION FUSELAGE SKIN JOINT: PHASE 49						PKG		
53.420	PKG 57	MOS	36				14-MAY-2019		
	REF: AMM 53-30-00	HRS/MSC	1200				5441		
		AFL					3993		
A535001 (s)	INSPECT NOSE CAP (RADOME): PHASE 5						PKG		
53.430	PKG 7,100	MOS	36				12-DEC-2017		
	REF: AMM 53-50-00	HRS/MSC	1200						
		AFL							
A535002 (s)	INSPECT STRINGER ASSEMBLY: PHASE 5						PKG		
53.440	PKG 7,107	MOS	36				12-DEC-2017		
	REF: AMM 53-50-10	HRS/MSC	1200						
		AFL							
A553001 (s)	EXTERNAL INSPECTION VERTICAL STABILIZER: PHASE 2						PKG		
55.030	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 55-30-01	HRS/MSC	300				5545		
		AFL					4067		
B535001 (s)	CHECK RADOME: PHASE 1						PKG		
53.450	PKG 1	MOS	24				26-AUG-2019		
	REF: AMM 53-50-00	HRS/MSC	300				5545		
		AFL					4067		

CHAPTER 54 NACELLES/PYLONS

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
541001	LEFT INLET ASSEMBLY								
54.010	5552250-119 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			19-JUN-1996 676		
541001	RIGHT INLET ASSEMBLY								
54.010	5552250-120 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			19-JUN-1996 676		
A541001 (s)	INSPECT ENGINE NACELLE, PYLON AND FIREWALL: PHASE 5						PKG		
54.020	PKG 7,107 REF: AMM 54-50-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
A541002 (s)	INSPECT ENGINE SUPPORT STRUCTURES: PHASE 16						PKG		
54.030	PKG 20 REF: AMM 54-50-01	MOS HRS/MSC AFL	10000	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
CHAPTER 55 STABILIZERS									
A551001 (s)	EXTERNAL INSPECTION HORIZONTAL STABILIZER: PHASE 2						PKG		
55.010	PKG 2 REF: AMM 55-10-01	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
A551002 (s)	INSPECT VERTICAL STABILIZER AFT EDGE: PHASE 2						PKG		
55.020	PKG 2 REF: AMM 55-30-01	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
A551003 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF HORIZONTAL STABILIZER AFT SPAR AREA: PHASE 64						PKG		
	PKG 503 REF: AMM 55-10-01	MOS HRS/MSC AFL	6				14-MAY-2019 5441 3993		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A551004 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF VERTICAL STABILIZER AFT SPAR ASSEMBLY: PHASE 64						PKG		
	PKG 503	MOS	6				14-MAY-2019		
	REF: AMM 55-30-01	HRS/MSC AFL					5441 3993		
A551005 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF HORIZONTAL STABILIZER AFT SPAR AREA: PHASE 18						PKG		
	PKG 22	MOS	12				11-DEC-2018		
	REF: AMM 55-10-01	HRS/MSC AFL					5384 3938		
A551006 (s)	BORESCOPE INSPECTION OF HORIZONTAL STABILIZER RIB LOCATION: PHASE 66						PKG		
	PKG 502	MOS					27-NOV-2017		
	REF: AMM 55-10-01	HRS/MSC AFL	6000				5121:17 3709		
A553003 (s)	INSPECT VERTICAL STABILIZER FORWARD SPAR CAP STRAP: PHASE 15						PKG		
55.050	PKG 19	MOS		TSI:0			28-APR-1993		
	REF: AMM 55-30-01	HRS/MSC AFL	10000	TSI:0			0		
				TSI:0			0		
A553005 (s)	INSPECT VERTICAL STABILIZER AFT SPAR FLANGE: PHASE 15						PKG		
55.040	PKG 19	MOS					28-APR-1993		
	REF: AMM 55-30-01	HRS/MSC AFL	10000				0		
							0		
A553006 (s)	INTERNAL INSPECTION VERTICAL STABILIZER: PHASE 5						PKG		
55.070	PKG 7,107	MOS	36				12-DEC-2017		
	REF: AMM 55-30-01	HRS/MSC AFL	1200						
A553007 (s)	INSPECT VERTICAL STABILIZER AFT SPAR: PHASE 15						PKG		
55.060	PKG 19	MOS		TSI:0			28-APR-1993		
	REF: AMM 55-30-01	HRS/MSC AFL	10000	TSI:0			0		
				TSI:0			0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A553008 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF VERTICAL STABILIZER AFT SPAR ASSEMBLY: PHASE 18						PKG		
	PKG 22	MOS	12				11-DEC-2018		
	REF: AMM 55-30-01	HRS/MSC AFL					5384 3938		
A555001 (s)	INTERNAL INSPECTION HORIZONTAL STABILIZER: PHASE 5						PKG		
55.080	PKG 7,107	MOS	36				12-DEC-2017		
	REF: AMM 55-10-01	HRS/MSC AFL	1200						
CHAPTER 56 WINDOWS									
561001	NO. 1 LEFTHAND MAIN WINDSHIELD ASSY, (LH)								
56.010	E149000-9	MOS					28-APR-1993		
	2253	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-01	AFL		TSN:0			0		
561002	NO. 2 RIGHTHAND MAIN WINDSHIELD ASSY, (RH)								
56.010	E149000-10	MOS					28-APR-1993		
	2136	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-01	AFL		TSN:0			0		
561003	FOUL WEATHER WINDOW								
56.015	5511275-23	MOS					20-MAY-2009		
	N/A	HRS/MSC	O/C	TSN:0			4546		
	REF: AMM 56-10-03	AFL							
561005	LEFT INBOARD PILOTS INNER WINDOW								
56.015	5511285-5	MOS					28-APR-1993		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 56-10-02	AFL		TSN:0			0		
561005	LEFT OUTBOARD PILOTS OUTER WINDOW								
56.020	5511285-47	MOS					20-MAY-2009		
	N/A	HRS/MSC	O/C	TSN:0			4546		
	REF: AMM 56-10-02	AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561005	RIGHT INBOARD CO-PILOTS INNER WINDOW								
56.015	5511285-6 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
561005	RIGHT OUTBOARD CO-PILOTS OUTER WINDOW								
56.020	5511285-48 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	L1 CABIN DOOR WINDOW								
56.025	5512207-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	L2 CABIN WINDOW								
56.030	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	L3 CABIN WINDOW								
56.040	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	L4 CABIN WINDOW								
56.050	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	L5 CABIN WINDOW								
56.060	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	L6 CABIN WINDOW								
56.070	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562001	L7 CABIN WINDOW								
56.080	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	R 7 CABIN WINDOW								
56.080	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	R1 EMERGENCY DOOR WINDOW								
56.025	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	R2 CABIN WINDOW								
56.030	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	R3 CABIN WINDOW								
56.040	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	R4 CABIN WINDOW								
56.050	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	R5 CABIN WINDOW								
56.060	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
562001	R6 CABIN WINDOW								
56.070	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A561001 (s)	INSPECT AIRPLANE WINDOWS: PHASE 1						PKG		
56.100	PKG 1 REF: AMM 56-10-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
A561002 (s)	PRISM CHECK WINDSHIELD AND FLIGHT COMPARTMENT SIDE WINDOWS: PHASE 49						PKG		
56.110	PKG 57 REF: AMM 56-10-00	MOS HRS/MSC AFL	36 1200				14-MAY-2019 5441 3993		
A561004 (s)	PERFORM RIGHT INBOARD CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION : PHASE 59						PKG		
56.130	5511285-6 PKG 112 SN-UNKNOWN REF: AMM 56-10-00	MOS HRS/MSC AFL	A/R				11-DEC-2018 5384 3938		
A561004 (s)	PERFORM RIGHT OUTBOARD CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION : PHASE 59						PKG		
56.130	5511285-48 PKG 112 SN-UNKNOWN REF: AMM 56-10-00	MOS HRS/MSC AFL	A/R				11-DEC-2018 5384 3938		
CHAPTER 57		WINGS							
572001	LEFT AFT MLG TRUNNION FITTING ASSEMBLY								
57.010	5522710-15 SN-UNKNOWN REF:	MOS HRS/MSC AFL	25800				28-APR-1993 0 0		25800
LIFE LIMIT					TSN:0 TSN:0				
572001	LEFT FORWARD MLG TRUNNION FITTING ASSEMBLY								
57.030	6522057-5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	25800				28-APR-1993 0 0		25800
LIFE LIMIT					TSN:0 TSN:0				
572001	RIGHT AFT MLG TRUNNION FITTING ASSEMBLY								
57.020	5522710-15 SN-UNKNOWN REF:	MOS HRS/MSC AFL	25800				28-APR-1993 0 0		25800
LIFE LIMIT					TSN:0				
572001	RIGHT FORWARD MLG TRUNNION FITTING ASSEMBLY								
57.040	6522057-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	25800				28-APR-1993 0 0		25800
LIFE LIMIT					TSN:0 TSN:0				

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
574003	LEFT MLG SIDE BRACE SUPPORT FITTING 6522047-1	MOS					28-APR-1993		
57.050	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	25800	TSN:0			0		25800
574004	RIGHT MLG SIDE BRACE SUPPORT FITTING 6522047-2	MOS					28-APR-1993		
57.060	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	25800	TSN:0			0		25800
575002	RIGHT INBOARD FLAP 6525130-22	MOS					01-JUL-1999		
57.080	128C	HRS/MSC	O/C	TSO:0			1505		
	REF: AMM 27-51-01	AFL							
A570001 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF MAIN LANDING GEAR WHEEL WELL: PHASE 64 PKG 503	MOS	6				14-MAY-2019		
	REF: AMM 57-00-00	HRS/MSC					5441		
		AFL					3993		
A570002 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF MAIN LANDING GEAR WHEEL WELL: PHASE 18 PKG 22	MOS	12				11-DEC-2018		
	REF: AMM 57-00-00	HRS/MSC					5384		
		AFL					3938		
A570003 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF AFT WING SPAR AREA: PHASE 64 PKG 503	MOS	6				14-MAY-2019		
	REF: AMM 57-00-00	HRS/MSC					5441		
		AFL					3993		
A570004 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF AFT WING SPAR AREA: PHASE 18 PKG 22	MOS	12				11-DEC-2018		
	REF: AMM 57-00-00	HRS/MSC					5384		
		AFL					3938		
A571004 (s)	INSPECT WING LOWER LEADING EDGE OUTBOAD OF WS 91.073: PHASE 5 PKG 7,109	MOS	36				12-DEC-2017		
57.090	REF: AMM 57-00-00	HRS/MSC	1200						
		AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A571005 (s)	INSPECT INBOARD LOWER MAIN WING SPAR CAP AND STRAP INSPECTION (AIRPLANES -0001 THRU -0538): PHASE 61						PKG		
57.150	PKG 246	MOS		TSl:0			28-APR-1993		
	REF: AMM 57-00-00	HRS/MSC	13200	TSl:0			0		
		AFL		TSl:0			0		
A571007 (s)	INSPECT OUTBOARD LOWER MAIN WING SPAR CAP AND STRAP: PHASE 62						PKG		
57.170	PKG 247	MOS		TSl:0			28-APR-1993		
	REF: AMM 57-00-00	HRS/MSC	15600	TSl:0			0		
		AFL		TSl:0			0		
A571008 (s)	INSPECT INBOARD LOWER REAR WING SPAR CAP: PHASE 63						PKG		
57.180	PKG 248	MOS		TSl:0			28-APR-1993		
	REF: AMM 57-00-00	HRS/MSC	15600	TSl:0			0		
		AFL		TSl:0			0		
A571009 (s)	INSPECT OUTBOARD LOWER REAR WING SPAR CAP: PHASE 63						PKG		
57.190	PKG 248	MOS		TSl:0			28-APR-1993		
	REF: AMM 57-00-00	HRS/MSC	15600	TSl:0			0		
		AFL		TSl:0			0		
A573001 (s)	INSPECT WINGS: PHASE 5						PKG		
57.110	PKG 7,109	MOS	36				12-DEC-2017		
	REF: AMM 57-00-00	HRS/MSC	1200						
		AFL							
A573003 (s)	INSPECT JACK PADS: PHASE 14						PKG		
57.120	PKG 18	MOS		TSl:0			28-APR-1993		
	REF: AMM 57-00-00	HRS/MSC	12000	TSl:0			0		
		AFL		TSl:0			0		
A574005 (s)	INSPECT FLAP BELL CRANK ATTACH POINTS: PHASE 2						PKG		
57.130	PKG 2	MOS	24				26-AUG-2019		
	REF: AMM 57-20-01	HRS/MSC	300				5545		
		AFL					4067		
A575001 (s)	INSPECT FLAPS: PHASE 5						PKG		
57.140	PKG 7,109	MOS	36				12-DEC-2017		
	REF: AMM 57-00-00	HRS/MSC	1200						
		AFL							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 71 POWER PLANT									
712001	LEFT ENGINE AFT ISOLATOR								
71.010	9912455-2 2635 REF:	MOS HRS/MSC AFL	3500	TSO:0			15-SEP-2014 4982 3676	8482	
712001	RIGHT ENGINE AFT ISOLATOR								
71.010	9912455-2 2631 REF:	MOS HRS/MSC AFL	3500	TSO:0			15-SEP-2014 4982 3676	8482	
712002	LEFT BOTTOM FORWARD ENGINE ISOLATOR								
71.030	LM420SA5-1 2666 REF:	MOS HRS/MSC AFL	3500	TSN:0			23-JUN-2006 3436	6936	
712002	LEFT TOP FORWARD ENGINE ISOLATOR								
71.020	LM420SA5-1 2298 REF:	MOS HRS/MSC AFL	3500	TSN:0			23-JUN-2006 3436	6936	
712002	RIGHT BOTTOM FORWARD ENGINE ISOLATOR								
71.030	LM420SA5-1 2303 REF:	MOS HRS/MSC AFL	3500	TSN:0			23-JUN-2006 3436	6936	
712002	RIGHT TOP FORWARD ENGINE ISOLATOR								
71.020	LM420SA5-1 2389 REF:	MOS HRS/MSC AFL	3500	TSN:0			23-JUN-2006 3436	6936	
71EN1	NO. 1 ENGINE								
71.EN1	JT15D-5A 108431 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C	TSO:0			23-JUN-2006 3436		
71EN2	NO. 2 ENGINE								
71.EN2	JT15D-5A 108435 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C	TSO:0			23-JUN-2006 3436		



Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A711000 (s)	GENERAL INSPECTION ENGINE: PHASE 4						PKG		
71.050	PKG 4 REF: AMM 71-01-04	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
A711001 (s)	GENERAL INSPECTION ENGINE: PHASE 4						PKG		
71.060	PKG 4 REF: AMM 71-01-05	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
A711006 (s)	INSPECT ENGINE INLET INNER AND OUTER DUCT(AIRPLANES -0001 THRU -0538) : PHASE 4						PKG		
71.080	PKG 4 REF: AMM 71-11-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
A711007 (s)	INSPECT ENGINE INLET INNER AND OUTER DUCT(AIRPLANES 0539 AND ON): PHASE 4						PKG		
71.110	PKG 4 REF: AMM 71-11-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
ENGINE NO. 1 Model : JT15D-5A Serial # 108431 Part # JT15D-5A									
710010	NO. 1 ENGINE - OVERHAUL								
	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500		TSI:0		23-JUN-2006 3436		(6936) 6936
710020	NO. 1 ENGINE - HOT SECTION INSPECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1800				13-MAY-2016 5112 3700		(6912) 6912
710030	NO. 1 ENGINE - TURBINE WASH								
	REF: EMM 71-00-00	DAYS HRS/MSC ENC	A/R		TSI:0 TSI:0		0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724001	NO. 1 ENGINE - COMBUSTOR LINER 3119770-01 3L855 REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C				13-MAY-2016 5112 3700		
ENGINE NO. 2 Model : JT15D-5A Serial # 108435 Part # JT15D-5A									
710010	NO. 2 ENGINE - OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			23-JUN-2006 3436	(6936) 6936	
710020	NO. 2 ENGINE - HOT SECTION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	1800				13-MAY-2016 5112 3700	(6912) 6912	
710030	NO. 2 ENGINE - TURBINE WASH REF: EMM 71-00-00	DAYS HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
724001	NO. 2 ENGINE - COMBUSTOR LINER 3119770-01 7K986 REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C				13-MAY-2016 5112 3700		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : JT15D-5A Serial # 108431 Part # JT15D-5A									
720010	NO. 1 ENGINE - OIL ANALYSIS REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720100	NO. 1 ENGINE - ENGINE OVERTEMPERATURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
UNSCHEDULED MAINTENANCE CHECK									

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720110	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS							
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720120	NO. 1 ENGINE - LOSS OF OIL	MOS							
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720130	NO. 1 ENGINE - ENGINE OVERSPEED	MOS							
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720140	NO. 1 ENGINE - ENGINE WINDMILLING	MOS							
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720150	NO. 1 ENGINE - ENGINE IMMERSION IN WATER	MOS							
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720160	NO. 1 ENGINE - ENGINE DROPPED DURING HANDLING	MOS							
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720170	NO. 1 ENGINE - LIGHTNING STRIKE	MOS							
	UNSCHEДУLED MAINTENANCE CHECK	HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720180	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS							
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720190	NO. 1 ENGINE - HEAVY/HARD LANDING	MOS							
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720200	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS							
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720210	NO. 1 ENGINE - STARTER GENERATOR FAIL INDICATION	MOS							
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720220	NO. 1 ENGINE - HYDRAULIC PUMP FAILURE	MOS							
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
721010	NO. 1 ENGINE - ACESSORY DRIVE GEAR BOX 3031170 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
722001	NO. 1 ENGINE - OIL PUMP 3104289-01 27A050 REF: EMM 72-60-02	MOS HRS/MSC ENC	O/C				10-FEB-2011 4641 3279		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722607	NO. 1 ENGINE - LOW COMPRESSOR HUB 3037911 56A599	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	TSN:2476				(12002) 12002	
723001	NO. 1 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY 3102814-01 SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
723010	NO. 1 ENGINE - INSPECT LP COMPRESSOR BYPASS STATOR RETAINING RIVETS REF: EMM 72-30-01	MOS HRS/MSC ENC	N/R				24-MAR-2015 4918 3681		
723020	NO. 1 ENGINE - LOW BOOST COMPRESSOR HUB 3038312 57A043	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	TSN:2476				(14002) 14002	
723705	NO. 1 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK 3022212 60A788	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	TSN:2476				(14002) 14002	
724006	NO. 1 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK 3036113 59A129	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	TSN:2476				(14002) 14002	
724706	NO. 1 ENGINE - HIGH TURBINE ROTOR DISK 3036411 57A458	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
	REF: GENERIC NO REF	ENC	10526	TSN:2476				(10528) 10528	
724707	NO. 1 ENGINE - HIGH TURBINE BLADES 3029601 SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
	REF: GENERIC NO REF	ENC							

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3039555 5E617	MOS HRS/MSC ENC					23-JUN-2006 3436		
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	TSN:2476			2478	(12002) 12002	
ENGINE NO. 2 Model : JT15D-5A Serial # 108435 Part # JT15D-5A									
720010	NO. 2 ENGINE - OIL ANALYSIS	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
REF: EMM 72-00-00									
+ 720100	NO. 2 ENGINE - ENGINE OVERTEMPERATURE	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00								
+ 720110	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00								
+ 720120	NO. 2 ENGINE - LOSS OF OIL	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00								
+ 720130	NO. 2 ENGINE - ENGINE OVERSPEED	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00								
+ 720140	NO. 2 ENGINE - ENGINE WINDMILLING	MOS HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			28-APR-1993 0 0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00								

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720150	NO. 2 ENGINE - ENGINE IMMERSION IN WATER	MOS		TSI:0			28-APR-1993		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720160	NO. 2 ENGINE - ENGINE DROPPED DURING HANDLING	MOS		TSI:0			28-APR-1993		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720170	NO. 2 ENGINE - LIGHTNING STRIKE	MOS		TSI:0			28-APR-1993		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720180	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS		TSI:0			28-APR-1993		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720190	NO. 2 ENGINE - HEAVY/HARD LANDING	MOS		TSI:0			28-APR-1993		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720200	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS		TSI:0			28-APR-1993		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720210	NO. 2 ENGINE - STARTER GENERATOR FAIL INDICATION	MOS		TSI:0			28-APR-1993		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 72-00-00	ENC		TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK								

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720220	NO. 2 ENGINE - HYDRAULIC PUMP FAILURE	MOS		TSI:0			28-APR-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
721010	NO. 2 ENGINE - ACCESSORY DRIVE GEAR BOX	MOS					23-JUN-2006		
	3031170 SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSO:0			3436		
722001	NO. 2 ENGINE - OIL PUMP	MOS					10-FEB-2011		
	3104289-01 BA138 REF: EMM 72-60-02	HRS/MSC ENC	O/C				4641 3279		
722607	NO. 2 ENGINE - LOW COMPRESSOR HUB	MOS					23-JUN-2006		
LIFE LIMIT	3037911 57A028 REF: GENERIC NO REF	HRS/MSC ENC	12000	TSN:2476			3436 2478	(12002) 12002	
723001	NO. 2 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY	MOS					23-JUN-2006		
	3102814-01 SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSO:0			3436		
723010	NO. 2 ENGINE - INSPECT LP COMPRESSOR BYPASS STATOR RETAINING RIVETS	MOS					24-MAR-2015		
	REF: EMM 72-30-01	HRS/MSC ENC	N/R				5016:12 3707		
723020	NO. 2 ENGINE - LOW BOOST COMPRESSOR HUB	MOS					23-JUN-2006		
LIFE LIMIT	3038312 57A044 REF: GENERIC NO REF	HRS/MSC ENC	14000	TSN:2476			3436 2478	(14002) 14002	
723705	NO. 2 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK	MOS					23-JUN-2006		
LIFE LIMIT	3022212 60A932 REF: GENERIC NO REF	HRS/MSC ENC	14000	TSN:2476			3436 2478	(14002) 14002	

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724006	NO. 2 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK 3036113 59A290	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	TSN:2476				(14002) 14002	
724706	NO. 2 ENGINE - HIGH TURBINE ROTOR DISK 3036411 49A057	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
	REF: GENERIC NO REF	ENC	10526	TSN:2476				(10528) 10528	
724707	NO. 2 ENGINE - HIGH TURBINE BLADES 3029601 SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
	REF: GENERIC NO REF	ENC							
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 3039555 5E615	MOS HRS/MSC ENC					23-JUN-2006 3436 2478		
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	TSN:2476				(12002) 12002	
CHAPTER 73 ENGINE FUEL AND CONTROL									
731004	NO. 1 LOW FUEL PRESSURE SWITCH 1103P92	MOS HRS/MSC					28-APR-1993 0		
73.030	SN-UNKNOWN REF: AMM 28-42-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
731004	NO. 2 LOW FUEL PRESSURE SWITCH 1103P0448	MOS HRS/MSC					19-JUN-2002 2322		
73.030	5223 REF: AMM 28-42-00	HRS/MSC AFL	O/C	TSN:0					
733002	FUEL FLOW/QUANTITY INDICATOR VSDL-OC208E	MOS HRS/MSC					24-MAY-1997 906		
73.010	276C REF:	HRS/MSC AFL	O/C	TSO:274					
733003	NO. 1 FUEL FLOW TRANSMITER 3268014-0201	MOS HRS/MSC					28-APR-1993 0		
73.040	1960D REF: AMM 73-30-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733003	NO. 2 FUEL FLOW TRANSMITER								
73.040	3268014-0201 2052D REF: AMM 73-30-00	MOS HRS/MSC AFL	O/C	TSN:0			02-JUN-1997 925		
ENGINE NO. 1 Model : JT15D-5A Serial # 108431 Part # JT15D-5A									
731001	NO. 1 ENGINE - FUEL PUMP								
	717100 474 REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731002	NO. 1 ENGINE - FLOW DIVIDER VALVE								
	26395-2 185 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731005	NO. 1 ENGINE - BLEED CONTROL VALVE								
	800831-1-001-L7 92080479 REF: EMM 73-10-13	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731006	NO. 1 ENGINE - EFCU WIRING HARNESS								
	3112429-01 AA1305 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731020	NO. 1 ENGINE - FUEL-OIL COOLER								
	11438-001J 988 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731025	NO. 1 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER								
	11438-001J 988 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0			0 0	(6936) 6936 M	
731030	NO. 1 ENGINE - MOTIVE FLOW VALVE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731035	NO. 1 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0			0 0	(6936) 6936 M	
731060	NO. 1 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
731065	NO. 1 ENGINE - BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731085	NO. 1 ENGINE - SCHEDULE MODULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731090	NO. 1 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE 26395-2 185 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0			0 0	(6936) 6936 M	
732001	NO. 1 ENGINE - FUEL CONTROL UNIT 3244851-5 C30021 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
732005	NO. 1 ENGINE - N1 SPEED SENSOR 3100335-01 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0			28-APR-1993 0 0		
732006	NO. 1 ENGINE - BOTTOM N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732006	NO. 1 ENGINE - TOP N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0			28-APR-1993 0 0		
732060	NO. 1 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
732065	NO. 1 ENGINE - MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
ENGINE NO. 2 Model : JT15D-5A Serial # 108435 Part # JT15D-5A									
731001	NO. 2 ENGINE - FUEL PUMP 717100 455 REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731002	NO. 2 ENGINE - FLOW DIVIDER VALVE 26395-2 412 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731005	NO. 2 ENGINE - BLEED CONTROL VALVE 800831-1-001-L7 92070423 REF: EMM 73-10-13	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731006	NO. 2 ENGINE - EFCU WIRING HARNESS 3112429-01 AA1303 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
731020	NO. 2 ENGINE - FUEL-OIL COOLER 11438-001J 1057 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731025	NO. 2 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER 11438-001J 1057 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			28-APR-1993 0 0	(6936) 6936 M	
731030	NO. 2 ENGINE - MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-1993 0 0		
731035	NO. 2 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			28-APR-1993 0 0	(6936) 6936 M	
731060	NO. 2 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
731065	NO. 2 ENGINE - BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-1993 0 0		
731085	NO. 2 ENGINE - SCHEDULE MODULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-1993 0 0		
731090	NO. 2 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE 26395-2 412 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			28-APR-1993 0 0	(6936) 6936 M	
732001	NO. 2 ENGINE - FUEL CONTROL UNIT 3244851-5 C30007 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732005	NO. 2 ENGINE - N1 SPEED SENSOR 3100335-01 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
732006	NO. 2 ENGINE - BOTTOM N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
732006	NO. 2 ENGINE - TOP N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
732060	NO. 2 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
732065	NO. 2 ENGINE - MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-1993 0 0		

CHAPTER 74 IGNITION

B742001 (s)	OPERATIONAL CHECK ENGINE IGNITERS: PHASE 2						PKG		
74.010	PKG 2,4,15 REF: AMM 74-31-00	MOS HRS/MSC AFL	150				26-AUG-2019 5545 4067		

ENGINE NO. 1 Model : JT15D-5A Serial # 108431 Part # JT15D-5A

741001	NO. 1 ENGINE - INBOARD IGNITION EXCITER 9049770-3 97444209 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
--------	---	-----------------------	-----	-------	--	--	---------------------	--	--

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741001	NO. 1 ENGINE - OUTBOARD IGNITION EXCITER 9049770-3 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
741030	NO. 1 ENGINE - VISUAL INSPECT INBOARD IGNITION EXCITER 9049770-3 97444209 REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
741030	NO. 1 ENGINE - VISUAL INSPECT OUTBOARD IGNITION EXCITER 9049770-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
742001	NO. 1 ENGINE - INBOARD IGNITER PLUG 9044810-1 NNA15170223 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			20-NOV-2015 4809		
742001	NO. 1 ENGINE - OUTBOARD IGNITER PLUG 9044810-1 NNA15170219 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			20-NOV-2015 4809		
742002	NO. 1 ENGINE - INBOARD IGNITER PLUG CABLE 53067-21 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
742003	NO. 1 ENGINE - OUTBOARD IGNITER PLUG CABLE 53067-38.5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		

ENGINE NO. 2 Model : JT15D-5A Serial # 108435 Part # JT15D-5A

741001	NO. 2 ENGINE - INBOARD IGNITION EXCITER 9049770-3 NNA06174069 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0			23-JUN-2006 3436		
--------	--	-----------------------	-----	-------	--	--	---------------------	--	--

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741001	NO. 2 ENGINE - OUTBOARD IGNITION EXCITER 9049770-3 NNA06194952 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0			23-JUN-2006 3436		
741030	NO. 2 ENGINE - VISUAL INSPECT INBOARD IGNITION EXCITER 9049770-3 NNA06174069 REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
741030	NO. 2 ENGINE - VISUAL INSPECT OUTBOARD IGNITION EXCITER 9049770-3 NNA06194952 REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5121 3709	27-NOV-2019 (5421) 5421	
742001	NO. 2 ENGINE - INBOARD IGNITER PLUG 9044810-1 NNA15170215 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			20-NOV-2015 5119		
742001	NO. 2 ENGINE - OUTBOARD IGNITER PLUG 9044810-1 NNA15040030 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			17-MAY-2018 5179 3793		
742002	NO. 2 ENGINE - INBOARD IGNITER PLUG CABLE 53067-21 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		
742003	NO. 2 ENGINE - OUTBOARD IGNITER PLUG CABLE 53067-38.5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			23-JUN-2006 3436		

CHAPTER 76 ENGINE CONTROLS

761002	SYNCHRONIZER CONTROL BOX 213693	MOS					19-JUN-2002		
76.100	13207271 REF: AMM 76-12-00	HRS/MSC AFL	O/C	TSN:0			2322		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761003	ENGINE SYNC ACTUATOR								
76.050	5485-066 2488451J REF: AMM 76-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
B761500 (s)	OPERATIONAL CHECK THROTTLE SWITCH: PHASE 2						PKG		
76.075	PKG 2 REF: AMM 76-15-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
CHAPTER 77		ENGINE INDICATING							
771004	N1 FAN TACHOMETER INDICATOR								
77.010	VSDL-OC410AE 415CA REF: AMM 77-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
771005	N2 TURBINE TACHOMETER INDICATOR								
77.020	9912147-28 247CA REF: AMM 77-12-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-JUL-2013 4914:12 3522		
772001	INTERSTAGE TURBINE TEMPERATURE (ITT) INDICATOR								
77.030	VSDL-OC419H 831A REF: AMM 77-21-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
CHAPTER 78		EXHAUST							
783001	LEFT ENGINE THRUST REVERSER ASSEMBLY								
78.040	262-0001-501 2806 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783001	RIGHT ENGINE THRUST REVERSER ASSEMBLY								
78.040	262-0001-503 2823 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783002	LEFT ENGINE THRUST REVERSER CONTROL VALVE								
78.050	65680 1825 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783002	RIGHT ENGINE THRUST REVERSER CONTROL VALVE								
78.050	65680 1835 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783003	LEFT ENGINE THRUST REVERSER ISOLATION VALVE								
78.060	13027-4 2566 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783003	RIGHT ENGINE THRUST REVERSER ISOLATION VALVE								
78.060	13027-4 2570 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783005	LEFT THRUST REVERSER UPPER DOOR ASSEMBLY								
78.200	202-0001-503 2806 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783005	RIGHT THRUST REVERSER UPPER DOOR ASSEMBLY								
78.200	202-0001-504 2823 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783006	LEFT THRUST REVERSER LOWER DOOR ASSEMBLY								
78.210	202-0002-505 2806 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783006	RIGHT THRUST REVERSER LOWER DOOR ASSEMBLY								
78.210	202-0002-506 2823 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783007	LEFT THRUST REVERSER UPPER MECHANISM 225-0007-513	MOS					28-APR-1993		
78.220	2806 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
783007	RIGHT THRUST REVERSER UPPER MECHANISM 225-0007-513	MOS					28-APR-1993		
78.220	2823 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
783008	LEFT THRUST REVERSER LOWER MECHANISM 225-0007-515	MOS					28-APR-1993		
78.230	2806 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
783008	RIGHT THRUST REVERSER LOWER MECHANISM 225-0007-515	MOS					28-APR-1993		
78.230	2823 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
783009	LEFT THRUST REVERSER FAN DUCT 225-0014-507	MOS					28-APR-1993		
78.240	2806 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
783009	RIGHT THRUST REVERSER FAN DUCT 225-0014-508	MOS					28-APR-1993		
78.240	2823 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
783010	LEFT INBOARD THRUST REVERSER ACTUATOR 62270	MOS					28-APR-1993		
78.020	3624 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
783010	LEFT OUTBOARD THRUST REVERSER ACTUATOR 62270	MOS					28-APR-1993		
78.030	3639 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783010	RIGHT INBOARD THRUST REVERSER ACTUATOR								
78.020	62270 3617 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783010	RIGHT OUTBOARD THRUST REVERSER ACTUATOR								
78.030	62270 3573 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783011	LEFT EXHAUST NOZZLE CONE								
78.320	225-0016-513-V4 SN-UNKNOWN REF: AMM 78-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
783011	RIGHT EXHAUST NOZZLE CONE								
78.320	225-0016-513-V4 SN-UNKNOWN REF: AMM 78-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
A783002 (s)	INSPECT THRUST REVERSER: PHASE 4						PKG		
78.070	PKG 4 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		
A783003 (s)	INSPECT THRUST REVERSER ELECTRICAL JUNCTION BOX: PHASE 5						PKG		
78.080	PKG 7,105 REF: AMM 78-31-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017		
B783002 (s)	OPERATIONAL CHECK THRUST REVERSERS: PHASE 2 (AIRCRAFT -0001 THRU -0538)						PKG		
78.090	PKG 2 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
B783101 (s)	FUNCTIONAL TEST THRUST REVERSER STOW LIMIT SWITCH(AIRPLANES -0002 THRU -0538): PHASE 4						PKG		
78.270	PKG 4 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				26-JUN-2019 5474 4015		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C783002 (s)	LUBRICATE THRUST REVERSER ACTUATING MECHANISM: PHASE 2						PKG		
78.290	PKG 2,4,15 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
C783003 (s)	LUBRICATE THRUST REVERSER ACTUATING MECHANISM(USE D-5100NS LUBRICATION METHOD): PHASE 2						PKG		
78.300	PKG 2,4,15 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				26-AUG-2019 5545 4067		
C783004 (s)	LUBRICATE THRUST REVERSER ACTUATING MECHANISM -PIVOT BALL(USE THE C5A LUBRICATION METHOD FOR SLIDER): PHASE 30						PKG		
78.310	PKG 45 REF: AMM 78-31-00	MOS HRS/MSC AFL	600				10-OCT-2018 5351:24 3910		
CHAPTER 79 OIL									
793001	OIL TEMP INDICATOR								
79.010	VSDL-OC219F 965BA REF: AMM 79-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
793002	LEFT ENGINE OIL TEMPERATURE TRANSMITTER								
79.030	102-00083 366 REF: AMM 79-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
793002	RIGHT ENGINE OIL TEMPERATURE TRANSMITTER								
79.030	102-00083 295 REF: AMM 79-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
793003	OIL PRESSURE INDICATOR								
79.080	VSDL-OC204N 140A REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSO:0			22-NOV-1996 841		

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793004	LEFT ENGINE OIL PRESSURE TRANSMITTER								
79.020	123479 47690 REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
793004	RIGHT ENGINE OIL PRESSURE TRANSMITTER								
79.020	123479 51002 REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSN:0			27-AUG-1997 1031		
793006	LEFT ENGINE LOW OIL PRESSURE SWITCH								
79.040	1103P89-2 SN-UNKNOWN REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-1993 0 0		
793006	RIGHT ENGINE LOW OIL PRESSURE SWITCH								
79.040	1103P89-2 495 REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSN:0			21-AUG-1996 749		
A793001 (s)	INSPECT ENGINE OIL FILTER: PHASE 2						PKG		
79.050	PKG 2,4,15 REF: AMM 79-31-00	MOS HRS/MSC AFL	150				26-AUG-2019 5545 4067		

ENGINE NO. 1 Model : JT15D-5A Serial # 108431 Part # JT15D-5A

792010	NO. 1 ENGINE - CHANGE OIL								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C				10-FEB-2011 4641 3279		
792020	NO. 1 ENGINE - CLEAN/REPLACE OIL FILTER								
	REF: EMM 79-20-01	MOS HRS/MSC ENC	150				13-JUL-2018 5251 3838	(5401) 5401	

ENGINE NO. 2 Model : JT15D-5A Serial # 108435 Part # JT15D-5A

Status Report

560 - CITATION V S/N 560-0212 (TC-LAA): 5592:57 HRS, 4106 AFL as of 19-Nov-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 19-NOV-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792010	NO. 2 ENGINE - CHANGE OIL REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C				10-FEB-2011 4641 3279		
792020	NO. 2 ENGINE - CLEAN/REPLACE OIL FILTER REF: EMM 79-20-01	MOS HRS/MSC ENC	150				13-JUL-2018 5251 3838	(5401) 5401	
CHAPTER 80 STARTING									
A801001 (s)	INSPECT LUCAS AEROSPACE STARTER-GENERATOR BRUSHES: PHASE 4 PKG 4	MOS HRS/MSC AFL	24 300				PKG 26-JUN-2019 5474 4015		
80.010	REF: AMM 80-11-01								
B801002 (s)	OPERATIONAL CHECK STARTER DISENGAGE SYSTEM: PHASE 5 PKG 7,106	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017		
80.020	REF: AMM 80-11-01								