

OWNER: ZIVER HAVACILIK INS.SAN.TIC A.S
ADDRESS: YILDIZEVLER MAH.718, CAD. NO: 12/4
 CANKAYA ANKARA
PHONE:
FAX:

OPERATOR: ZIVER HAVACILIK INS.SAN.TIC A.S
ADDRESS: YILDIZEVLER MAH.718, CAD. NO: 12/4
 CANKAYA ANKARA
PHONE:
FAX:

ANALYST: MELVIN BRUNET +33-1.55.93.47.84 (DIRECT)
EMAIL: MELVIN.BRUNET@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 560-0216/TC-LAB **MODEL:** 560 - CITATION V **MANUFACTURER:** TEXTRON AVIATION INC.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 17-MAY-1993		5211:15 A/C HRS	as of 28-OCT-2019	_____ A/C HRS	as of ____/____/____
		3911 AFL	as of 28-OCT-2019	_____ AFL	as of ____/____/____
		0 ACH	as of 28-OCT-2019	_____ ACH	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: 108441/JT15D-5A **MODEL:** JT15D-5A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 07-SEP-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	3493 A/C HRS	5211:15 ENG. HRS	as of 28-OCT-2019	_____ ENG. HRS	as of ____/____/____
ENC		3911 ENC	as of 28-OCT-2019	_____ ENC	as of ____/____/____

ENGINE NO. 2 SERIAL/PART: 108445/JT15D-5A **MODEL:** JT15D-5A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 07-SEP-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	3493 A/C HRS	5211:15 ENG. HRS	as of 28-OCT-2019	_____ ENG. HRS	as of ____/____/____
ENC		3911 ENC	as of 28-OCT-2019	_____ ENC	as of ____/____/____



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
5-12-01	PHASE 1							
	PKG 1	MOS	24			16-MAR-2018	16-MAR-2020	
		HRS/MSC	300			5027	5327	
	REF: TLMC 5-12-01	AFL				3753		
5-12-02	PHASE 2							
	PKG 2	MOS	24			16-MAR-2018	16-MAR-2020	
		HRS/MSC	300			5027	5327	
	REF: TLMC 5-12-02	AFL				3753		
5-12-03	PHASE 3							
	PKG 3	MOS	24			27-NOV-2017	27-NOV-2019	
		HRS/MSC	300			5022:17	5322:17	
	REF: TLMC 5-12-03	AFL				3749		
5-12-04	PHASE 4							
	PKG 4	MOS	24			27-NOV-2017	27-NOV-2019	
		HRS/MSC	300			5022:17	5322:17	
	REF: TLMC 5-12-04	AFL				3749		
5-12-05	PHASE 5							
	PKG 7	MOS	36			12-DEC-2017	20-DEC-2019 M	
		HRS/MSC	1200			5022:17	6222:17	
	REF: TLMC 5-12-05	AFL				3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-06	PHASE 6								
	PKG 8	DAYS					27-NOV-2017		
	REF: TLMC 5-12-06	HRS/MSC AFL	O/C						
5-12-0B	PHASE B								
	PKG 15	MOS					08-AUG-2018		
	REF: TLMC 5-12-0B	HRS/MSC AFL	150				5114:38 3835		5264:38
5-12-11	PHASE 11								
	PKG 16	MOS	6				27-NOV-2018		27-MAY-2019
	REF: TLMC 5-12-11	HRS/MSC AFL					5196:23 3898		
5-12-13	PHASE 13								
	PKG 17	MOS					18-MAR-2014		
	REF: TLMC 5-12-13	HRS/MSC AFL	5000				4833:25 3558		9833:25
5-12-14	PHASE 14								
	PKG 18	MOS					17-MAY-1993		
	REF: TLMC 5-12-14	HRS/MSC AFL	12000				0 0		12000



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-15	PHASE 15							
	PKG 19	MOS				17-MAY-1993		
		HRS/MSC	10000			0		10000
	REF: TLMC 5-12-15	AFL				0		
5-12-16	PHASE 16							
	PKG 20	MOS				17-MAY-1993		
		HRS/MSC	10000			0		10000
	REF: TLMC 5-12-16	AFL				0		
5-12-17	PHASE 17							
	PKG 21	MOS				17-MAY-1993		
		HRS/MSC	10000			0		10000
	REF: TLMC 5-12-17	AFL				0		
5-12-18	PHASE 18							
	PKG 22	MOS	12			27-NOV-2018		27-NOV-2019
		HRS/MSC				5196:23		
	REF: TLMC 5-12-18	AFL				3898		
	Note: PHASE 56 SHOULD BE ACCOMPLISHED IN CONJUNCTION WITH THE PHASE 18. PHASE 56 ADDED PER REV 21 TO 560 MM. OCTOBER 2005							
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)							
	PKG 24	MOS	24			24-MAY-2018		24-MAY-2020
		HRS/MSC				5079:30		
	REF: TLMC 5-12-20	AFL				3802		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 35	MOS	24				24-MAY-2018		24-MAY-2020
		HRS/MSC					5079:30		
	REF: TLMC 5-12-21	AFL					3802		
5-12-28 (s)	PHASE 28 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 44	MOS	12				17-OCT-2019		
		HRS/MSC	100				5211:13		
	REF: TLMC 5-12-28	AFL					3911		
5-12-30	PHASE 30								
	PKG 45	MOS					25-MAR-2012		
		HRS/MSC	600				4634:42		5234:42
	REF: TLMC 5-12-30	AFL					3404		
5-12-32	PHASE 32								
	PKG 46	MOS					17-MAY-1993		
		HRS/MSC					0		
	REF: TLMC 5-12-32	AFL	15000				0		15000
5-12-33	PHASE 33								
	PKG 47	MOS					17-MAY-1993		
		HRS/MSC					0		
	REF: TLMC 5-12-33	AFL	15000				0		15000



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-34	PHASE 34								
	PKG 48	MOS					17-MAY-1993		
		HRS/MSC	6725				0		6725
	REF: TLMC 5-12-34	AFL					0		
<hr/>									
5-12-48 (s)	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 54	MOS	72				18-JAN-2011		
		HRS/MSC					4515		
	REF: TLMC 5-12-48	AFL					3326		
<hr/>									
5-12-49	PHASE 49								
	PKG 57	MOS	36				14-MAY-2019		
		HRS/MSC	1200				5211		14-MAY-2022
	REF: TLMC 5-12-49	AFL					3911		6411
<hr/>									
5-12-54	PHASE 54								
	PKG 63	MOS					11-JUN-2015		
		HRS/MSC	N/A				4977		
	REF: See Workcard	AFL					3680		
<hr/>									
5-12-56	PHASE 56								
	PKG 65	MOS	12				27-NOV-2018		
		HRS/MSC					5196:23		27-NOV-2019
	REF: TLMC 5-12-56	AFL					3898		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-59	PHASE 59 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
	PKG 112	MOS					08-AUG-2018		
		HRS/MSC	A/R				5114:38		
	REF: TLMC 5-12-59	AFL					3835		
5-12-60	PHASE 60								
	PKG 68	MOS					18-MAR-2014		
		HRS/MSC	500				4838		5338
	REF: TLMC 5-12-60	AFL					3562		
5-12-61	PHASE 61								
	PKG 246	MOS					17-MAY-1993		
		HRS/MSC	13200				0		13200
	REF: TLMC 5-12-61	AFL					0		
5-12-62	PHASE 62								
	PKG 247	MOS					17-MAY-1993		
		HRS/MSC	15600				0		15600
	REF: TLMC 5-12-62	AFL					0		
5-12-63	PHASE 63								
	PKG 248	MOS					17-MAY-1993		
		HRS/MSC	15600				0		15600
	REF: TLMC 5-12-63	AFL					0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-64	PHASE 64							
	PKG 503	MOS	6			27-NOV-2018	27-MAY-2019	
	REF: TLMC 5-12-64	HRS/MSC AFL				5196:23 3898		
5-12-65	PHASE 65							
	PKG 501	MOS				02-SEP-2014		
	REF: TLMC 5-12-65	HRS/MSC AFL ACH	500			4874 3598	?	?
5-12-66	PHASE 66							
	PKG 502	MOS				27-NOV-2017		
	REF: TLMC 5-12-66	HRS/MSC AFL	6000			5022:17 3749	11022:17	
5-12-67	PHASE 67							
	PKG 504	MOS				27-NOV-2013		
	REF: TLMC 5-12-67	HRS/MSC AFL	1200			4822:47 3550	6022:47	
5-12-MC	PHASE MC						AIRWORTHINES S	
	PKG 70	MOS				03-JUL-2009		
	REF: TLMC 5-12-MC	HRS/MSC AFL	1456			4511	5967	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-MD	PHASE MD								
	PKG 71	MOS					03-JUL-2009		
		HRS/MSC	2523				4511		7034
	REF: TLMC 5-12-MD	AFL							
5-12-ME	PHASE ME								AIRWORTHINESS
	PKG 72	MOS					21-FEB-2012		
		HRS/MSC	4450				4621:54		9071:54
	REF: TLMC 5-12-ME	AFL					3396		
5-12-MF	PHASE MF								AIRWORTHINESS
	PKG 73	MOS					23-JAN-2013		
		HRS/MSC	5000				4749:24		9749:24
	REF: TLMC 5-12-MF	AFL					3482		
5-12-MG (s)	PHASE MG (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								AIRWORTHINESS
	PKG 74	MOS					17-MAY-1993		
		HRS/MSC					0		
	REF: TLMC 5-12-MG	AFL	10000				0		
5-12-MI	PHASE MI								AIRWORTHINESS
	PKG 76	MOS					01-JUL-2015		
		HRS/MSC	5130				4957:52		10087:52
	REF: TLMC 5-12-MI	AFL					3681		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-12-MJ	PHASE MJ							AIRWORTHINES S	
	PKG 77	MOS					17-MAY-1993		
	REF: TLMC 5-12-MJ	HRS/MSC AFL	5900				0 0		5900
5-12-MK	PHASE MK							AIRWORTHINES S	
	PKG 78	MOS					17-MAY-1993		
	REF: TLMC 5-12-MK	HRS/MSC AFL	6725				0 0		6725
5-12-ML	PHASE ML							N/A BY PART NUMBER	
	PKG 249	MOS							
	REF: TLMC 5-12-ML	HRS/MSC AFL	N/A						



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
C561-191010	AUDIT - DESCRIPTION CHANGE FOR ITEM CODE 561002	MOS		TSI:0			(EBT)		
AUDIT SUMMARY CHANGE FORM	REF: RCF C561	HRS/MSC - AFL		TSI:0 TSI:0					
NEW REQUIREMENT ADDED ON 10-OCT-2019 (EFFECTIVE: 10-OCT-2019). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.									
ENGINE NO. 1 Model : JT15D-5A Serial # 108441 Part # JT15D-5A									
E15A-180423	NO. 1 ENGINE - REVIEW PWC JT15D-5A EMM REV 34.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
E15A-181022	NO. 1 ENGINE - REVIEW JT15D-5A EMM REV 35.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
ENGINE NO. 2 Model : JT15D-5A Serial # 108445 Part # JT15D-5A									
E15A-180423	NO. 2 ENGINE - REVIEW PWC JT15D-5A EMM REV 34.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
E15A-181022	NO. 2 ENGINE - REVIEW JT15D-5A EMM REV 35.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E15A	HRS/MSC - ENC							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
053100	INSPECT FLIGHT DATA RECORDER	MOS	72				20-MAY-2011	20-MAY-2017	
	REF:	HRS/MSC AFL					4534 3335		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
053101	TEST/INSPECT FDR'S UNDER WATER LOCATOR BEACON	MOS	24				11-JUN-2015 4977 3680	11-JUN-2017	
	REF:	HRS/MSC AFL							
053102	FLIGHT TEST -PERFORM A FDR DATA VERIFICATION FLIGHT	MOS	12				13-DEC-2018 5202 3906	13-DEC-2019 7202	
	REF:	HRS/MSC AFL	2000						
053103	SELF TEST -FDR AUTOMATIC TEST AT PERFLIGHT	MOS					15-JUN-2011 4559:42 3350		
	REF:	HRS/MSC AFL	A/R						
053416	VERIFY AVIONICS EQUIPMENT INSTALLED RVSM	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							
053417	CHECK AIR DATA SYSTEM RVSM ACCURACY	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							
053418	INSPECT CRITICAL REGION CORNER MARKINGS RVSM VISUAL	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							
053419	INSPECT CRITICAL REGION MODIFICATION COMPLIANCE PLACARD RVSM VISUAL	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
053420	CHECK CRITICAL REGION RVSM SKIN WAVINESS	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							
053421	INSPECT CRITICAL REGION RVSM VISUAL	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							
053422	INSPECT CRITICAL REGION STENCILS AND PLACARDS RVSM VISUAL	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							
053423	INSPECT CRITICAL REGION STATIC PORT DOUBLERS RVSM VISUAL	MOS	12				27-NOV-2018 5196:23 3898	30-NOV-2019	
	REF:	HRS/MSC AFL							
053424	CHECK IN-FLIGHT AUTOPILOT RVSM ALTITUDE HOLD	MOS	24				27-NOV-2018 5196:23 3898	30-NOV-2020	
	REF:	HRS/MSC AFL							
055013	EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED CHECK	MOS		TSI:0			17-MAY-1993		
	REF: TLMC 5-50-00	HRS/MSC AFL	A/R	TSI:0 TSI:0			0 0		
	UNSCHEDULED MAINTENANCE CHECK								
A361103 (s)	VISUAL INSPECTION PRECOOLER/HEAT EXCHANGER (AIRPLANES -0539 AND ON): PHASE 54	PKG 63					11-JUN-2015 4977 3680		
	REF: AMM 36-11-05	MOS HRS/MSC AFL	N/A						

ENGINE NO. 1 Model : JT15D-5A Serial # 108441 Part # JT15D-5A



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057110	NO. 1 ENGINE - MINOR INSPECTION								
		MOS	24				27-NOV-2017	27-NOV-2019	
		HRS/MSC	300				5022	(5322) 5322	
	REF: EMM 72-00-00	ENC					3744		

ENGINE NO. 2 Model : JT15D-5A Serial # 108445 Part # JT15D-5A

057110	NO. 2 ENGINE - MINOR INSPECTION								
		MOS	24				27-NOV-2017	27-NOV-2019	
		HRS/MSC	300				5015	(5315) 5315	
	REF: EMM 72-00-00	ENC							

CHAPTER 08 LEVELING AND WEIGHING

081251	WEIGHT AND BALANCE								
		MOS	48				24-SEP-2019	24-SEP-2023	
08.010		HRS/MSC							
	REF: GENERIC NO REF	AFL							

CHAPTER 11 PLACARDS AND MARKINGS

A113001 (s)	INSPECT INTERIOR PLACARDS, EXTERIOR PLACARDS, DECALS, MARKINGS AND IDENTIFICATION PLATE: PHASE 5						PKG		
	PKG 7,101	MOS	36				12-DEC-2017		
11.010		HRS/MSC	1200				5022:17		
	REF: AMM 11-00-00	AFL					3749		

CHAPTER 12 SERVICING

C122100 (s)	LUBRICATE NOSE GEAR TORQUE LINKS AND UPLOCK ROLLERS: PHASE 2						PKG		
	PKG 2	MOS	24				16-MAR-2018		
12.005		HRS/MSC	300						
	REF: AMM 12-21-02	AFL							

C122101 (s)	LUBRICATE MAIN LANDING GEAR: PHASE 2						PKG		
	PKG 2	MOS	24				16-MAR-2018		
12.005		HRS/MSC	300						
	REF: AMM 12-21-02	AFL							

CHAPTER 21 AIR CONDITIONING



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211002	EMERGENCY PRESSURE VALVE 27441482-06	MOS					17-MAY-1993		
21.020	10AH22 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
211004	S243 PRIMARY PRESSURE SWITCH 1103P240-1	MOS					17-MAY-1993		
21.010	634 REF: AMM 21-11-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
211005	S244 SECONDARY PRESSURE SWITCH 1103P240-2	MOS					17-MAY-1993		
21.010	656 REF: AMM 21-11-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212001	INSTRUMENT PANEL FAN 4124X	MOS					17-MAY-1993		
21.040	SN-UNKNOWN REF: AMM 21-24-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212002	AVIONICS BAY COOLING BOX FAN 032105	MOS					17-MAY-1993		
21.050	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212004	OVERHEAD CABIN FAN BC61A901-2	MOS					03-JUL-2009		
21.060	1058A REF: GENERIC NO REF	HRS/MSC AFL	1000	TSO:0			4511	5511	
212006	COCKPIT DEFOGGER FAN 5703-4	MOS					29-AUG-2006		
21.070 REPLACE/OVERHAUL	1456 REF: GENERIC NO REF	HRS/MSC AFL	3500	TSO:0			3493	6993	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR NYLC50466	MOS					17-MAY-1993		
21.030	1128 REF: AMM 21-21-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212010	AVIONICS BAY VANE AXIAL BLOWER 19A827	MOS					17-MAY-1993		
21.050	SN-UNKNOWN REF: AMM 21-25-00	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
212011	TEMP DUCT SENSOR 27221274	MOS					17-MAY-1993		
21.450	10AH139 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213001	CABIN PRESSURE INDICATOR C668511-0103	MOS					17-MAY-1993		
21.090	19546 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213003	RATE OF CHANGE INDICATOR C668513-0101	MOS					17-MAY-1993		
21.090	W30276 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
213006	CABIN ALTITUDE CONTROLLER 130620-2	MOS					10-JAN-2014		
21.080	30-264 REF: See Workcard	HRS/MSC AFL	O/C				4836:06 3560		
213007	NO. 1 PRIMARY OUTFLOW VALVE 103648-14	MOS					17-MAY-1993		
21.130	112579 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213007	NO. 2 SECONDARY OUTFLOW VALVE								
21.130	103648-14 112592 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
213009	NO. 1 FLOW CONTROL PRESSURE REGULATOR VALVE								
21.120	34E16-4 GWD04572 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
213009	NO. 2 FLOW CONTROL PRESSURE REGULATOR VALVE								
21.120	34E16-4 GWD04570 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
213013	PNEUMATIC RELAY								
21.110	130358-1 612012 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY								
21.180	782343-2 930140 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
215004	AIR CYCLE MACHINE								
21.140 OVERHAUL	738384-26 890979 REF: AMM 21-51-00	MOS HRS/MSC AFL	5000	TSO:0			03-JUL-2009 4511	9511	
	Note:	RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.							
215005	ACM BYPASS VALVE								
21.150	754751-2 90081063 REF: AMM 21-51-00	MOS HRS/MSC AFL	O/C	TSO:0			07-JUN-2001 2026		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215007	COMPRESSION ACTUATOR								
21.480	BYLB50907 590 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
215008	DUCT OVERHEAT SENSOR								
21.150	1173T42-1 2409 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
215009	ACM OVERHEAT SWITCH								
21.150	1173T0635 2252 REF: AMM 21-51-00	MOS HRS/MSC AFL	O/C	TSN:0			07-JUL-2009 4511		
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY)								
N/A EQUIPMENT NOT INSTALLED	1250151 2014 REF:	MOS HRS/MSC AFL	N/R	TSI:0 TSI:0 TSI:0			(EBT)		
215016	AC COMPRESSOR								
21.160	1250160 1990 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:0			24-JUN-2008 4133		
215017	AC CONDENSER								
21.160	1250180-7 1621 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
215018	ACM CONTROL UNIT								
21.170	C35020A 1447 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215021	MOTOR 1250151 2014 REF:	MOS HRS/MSC AFL	O/C	TSO:0			24-JUL-2002 2274		
215022	AFT EVAPORATOR 1250240-23 165 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			20-OCT-2017		
215023	FWD EVAPORATOR 1250240-22 162 REF: AMM 21-52-00	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			20-OCT-2017		
215024	PRESSURE SWITCH 1250232-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
216001	CABIN TEMPERATURE SENSOR 1942T100-11 113 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	TSN:0			14-NOV-2003 2587		
216002	CABIN TEMPERATURE CONTROLLER 754661-5 92119055 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
216003	DUCT TEMPERATURE SENSOR 754691-1 92091861 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216005	CENTRIFUGAL BLOWER								
21.210	3A1003-10 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
216010	DOOR ACTUATOR MOTOR ASSEMBLY								
21.500	5A3032 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
217001	WATER SEPARATOR								
21.230	738386-3 921112 REF: AMM 21-70-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
21FO-02 560	COOLING/FREON SUPPLEMENTAL FACTORY OPTION								
	15A FO REF:	MOS HRS/MSC AFL	-				17-MAY-1993 0 0		
A215001 (s)	CHECK AIR CYCLE MACHINE: PHASE 2						PKG		
21.240	PKG 2,4,15 REF: AMM 21-51-00	MOS HRS/MSC AFL	150				08-AUG-2018 5114:38 3835		
A215200 (s)	PERFORM VAPOR CYCLE COOLING SYSTEM HOUR METER CHECK (COMPRESSOR MOTORS 1134104-1, -5 OR FWA1134104-1, -5 ONLY): PHASE ML						PKG		
N/A BY PART NUMBER	PKG 249 REF: AMM 21-52-00	MOS HRS/MSC AFL	N/A	TSl:0 TSl:0 TSl:0			17-MAY-1993 0 0		
A215201 (s)	PERFORM 500 COMPRESSOR HOUR MAINTENANCE CHECK ON VAPOR CYCLE COOLING SYSTEM: PHASE 65						PKG		
	PKG 501 REF: AMM 21-52-00	MOS HRS/MSC AFL ACH	500				02-SEP-2014 4874 3598		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A215202 (s)	PERFORM 12 MONTH MAINTENANCE CHECK OF VAPOR CYCLE COOLING SYSTEM: PHASE 18 PKG 22	MOS	12				PKG 27-NOV-2018 5196:23 3898		
	REF: AMM 21-52-00	HRS/MSC AFL							
A217001 (s)	INSPECT HUMIDITY REGULATOR: PHASE 2 PKG 2	MOS	24				PKG 16-MAR-2018		
21.270	REF: AMM 21-70-00	HRS/MSC AFL	300						
B210000 (s)	OPERATIONAL CHECK ENVIRONMENTAL SYSTEM: PHASE 5 PKG 7,102	MOS	36				PKG 12-DEC-2017 5022:17 3749		
21.280	REF: AMM 21-00-00	HRS/MSC AFL	1200						
B211001 (s)	OPERATIONAL TEST EMERGENCY PRESSURIZATION VALVE: PHASE 4 PKG 4	MOS	24				PKG 27-NOV-2017 5022:17 3749		
21.290	REF: AMM 21-11-00	HRS/MSC AFL	300						
B211002 (s)	OPERATIONAL TEST FLOW CONTROL SHUTOFF AND CHECK VALVES: PHASE 5 PKG 7,104	MOS	36				PKG 12-DEC-2017 5022:17 3749		
21.300	REF: AMM 21-11-00	HRS/MSC AFL	1200						
B211003 (s)	OPERATIONAL TEST FLOW CONTROL SHUTOFF AND CHECK VALVES: PHASE 2 PKG 2,4,15	MOS	150				PKG 08-AUG-2018 5114:38 3835		
21.310	REF: AMM 21-11-00	HRS/MSC AFL							
B211004 (s)	OPERATIONAL TEST EMERGENCY PRESSURIZATION VALVE: PHASE 4 PKG 4	MOS	24				PKG 26-OCT-2017		
21.320	REF: AMM 21-11-00	HRS/MSC AFL	300						



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B212001 (s) 21.330	LEAK CHECK TAILCONE BLEED AIR LINES: PHASE 5 PKG 7,106 REF: AMM 36-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B212002 (s) 21.340	OPERATIONAL CHECK VERTICAL SCALE INSTRUMENT PANEL COOLING FAN: PHASE 5 PKG 7,108 REF: AMM 21-24-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B212003 (s) 21.350	OPERATIONAL CHECK AVIONICS BAY COOLING FANS: PHASE 5 PKG 7,102 REF: AMM 21-25-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B213000 (s) 21.360	OPERATIONAL CHECK PRESSURIZATION: PHASE 5 PKG 7,102 REF: AMM 21-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B213001 (s) 21.370	FUNCTIONAL TEST BAROMETRIC CABIN ALTITUDE PRESSURE SWITCH: PHASE 5 PKG 7,102 REF: AMM 21-31-05	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B213005 (s) 21.380	OPERATIONAL CHECK PRESSURIZATION SYSTEM: PHASE 5 PKG 7,102 REF: AMM 21-32-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B213006 (s) 21.390	FUNCTIONAL TEST OUTFLOW VALVE CABIN ALTITUDE LIMITER: PHASE 5 PKG 7,110 REF: AMM 21-32-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C215001 (s)	CHANGE OIL AIR CYCLE MACHINE: PHASE 30						PKG		
21.400	PKG 45 REF: AMM 21-51-00	MOS HRS/MSC AFL	600				25-MAR-2012 4634:42 3404		
D213001 (s)	CLEAN/REPLACE PRESSURIZATION CONTROLLER: PHASE 5						PKG		
21.410	PKG 7,102 REF: AMM 21-31-00	MOS HRS/MSC AFL	1200				12-DEC-2017 5022:17 3749		
D213003 (s)	REPLACE PNEUMATIC RELAY CARTRIDGE FILTER: PHASE 5						PKG		
21.420	PKG 7,110 REF: AMM 21-31-00	MOS HRS/MSC AFL	1200				12-DEC-2017 5022:17 3749		
D213004 (s)	CLEAN/REPLACE SOLENOID VALVE FILTER: PHASE 5						PKG		
21.430	PKG 7,110 REF: AMM 21-31-00	MOS HRS/MSC AFL	1200				12-DEC-2017 5022:17 3749		
CHAPTER 22 AUTO FLIGHT									
221001	NO. 1 ROLL RATE MONITOR-								
22.060	4015901-920 92101955 REF: AMM 22-11-02	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0		17-MAY-1993 0 0		
221001	NO. 2 ROLL RATE MONITOR-								
22.060	4015901-920 92111959 REF: AMM 22-11-02	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0		17-MAY-1993 0 0		
221008	AUTOPILOT COMPUTER								
22.070	4008519-952 91044550 REF: AMM 22-11-02	MOS HRS/MSC AFL	O/C		TSO:151		30-MAY-2000 1713		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221009	AUTOPILOT CONTROL 4018639-933 9301682 REF: AMM 22-11-03	MOS HRS/MSC AFL	O/C				03-JUN-2011 4541:36 3341		
221010	AILERON SERVO 4006719-906 92076025 REF: AMM 22-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
221010	ELEVATOR SERVO 4006719-914 92106171 REF: AMM 22-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
221010	RUDDER SERVO 4006719-906 92075999 REF: AMM 22-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
A221001 (s)	INSPECT AILERON SERVO ACTUATOR AND MOUNT: PHASE 5 PKG 7,104 REF: AMM 22-11-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A222001 (s)	INSPECT RUDDER SERVO ACTUATOR AND MOUNT: PHASE 5 PKG 7,109 REF: AMM 22-11-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A223001 (s)	INSPECT ELEVATOR SERVO ACTUATOR AND MOUNT: PHASE 5 PKG 7,110 REF: AMM 22-11-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B221002 (s)	PERFORM AUTOPILOT AND DISENGAGEMENT AND WARNING TEST: PHASE 5						PKG		
22.050	PKG 7,102 REF: AMM 22-11-03	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B221003 (s)	PERFORM AUTOPILOT DISENGAGEMENT AND WARNING TEST: PHASE 5						PKG		
22.080	PKG 7,102 REF: AMM 22-11-03	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
CHAPTER 23 COMMUNICATIONS									
231010	BOTTOM VHF ANTENNA								
23.325	S65-111-309 583 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
231010	TOP VHF ANTENNA								
23.325	20-200-3 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
232000	INTERCOM								
23.335	400-014635-0101 119 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
232002	NO. 2 VHF COMM ANTENNA								
23.040	VFS10-90-5 152 REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSN:0			24-JUL-2002 2274		
232003	NO. 1 VHF COMM ANTENNA								
23.040	VFS10-90-5 2946 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232005	CABIN HANDSET PHONE								
23.060	400-0123-212 7814 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
232006	COCKPIT HANDSET PHONE								
23.060	400-0123-212 7759 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
232009	NO. 1 COMM CONTROL								
23.340	822-1120-005 13174 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:1503			27-JUL-1999 1503		
232009	NO. 2 COMM CONTROL								
23.340	822-1120-005 1986 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0			19-SEP-2003 2572		
232010	NO. 1 VHF COMMUNICATION TRANSCEIVER								
23.090	822-1113-001 38197 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSN:0			27-JUL-1999 1503		
232010	NO. 2 VHF COMMUNICATION TRANSCEIVER								
23.090	822-1113-001 38208 REF: AMM 23-13-00	MOS HRS/MSC AFL	O/C	TSN:0			27-JUL-1999 1503		
235001	NO. 1 AUDIO AMPLIFIER								
23.100	5632-1-1 222 REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
235001	NO. 2 AUDIO AMPLIFIER								
23.100	5632-1-1 223 REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
236096	FLEXCOMM ANTENNA								
23.385	S65-1016-1 1255 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
237001	COCKPIT VOICE RECORDER								
23.120	2100-1020-00 00706980 REF: AMM 23-71-02	MOS HRS/MSC AFL	O/C				31-MAY-2011 4535:30 3337		
237004	CVR CONTROLLER								
23.110	S161-0020-00 000710288 REF: AMM 23-71-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-MAY-2011 4535:30 3337		
237005	CVR MICROPHONE								
23.400	S056-0048-00 000709141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-MAY-2011 4535:30 3337		
237006	CVR UNDERWATER LOCATOR BEACON								
23.120	DK120/90 AT102603 REF: AMM 23-71-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			12-JUN-2018 5083 3804		
237006A	REPLACE ULB (CVR) BATTERY								
23.290	PN SN-UNKNOWN REF: AMM 23-71-03	MOS HRS/MSC AFL	72	TSN:0			12-JUN-2018	01-JAN-2025 M	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237010	CVR IMPACT SWITCH								
23.300	3LO-453-3 92485 REF: AMM 23-71-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-MAY-2011 0 0		
23FO-03 560/T	INTERCOMM/CABIN FOREIGN ONLY FACTORY OPTION								
	674T FO REF:	MOS HRS/MSC AFL	-				17-MAY-1993 0 0		
A231001 (s)	INSPECT HIGH FREQUENCY ANTENNA AND TENSION UNIT: PHASE 5						PKG		
23.130	PKG 7,107 REF: AMM 23-10-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A236002 (s)	INSPECT CONTROL SURFACE BOND JUMPER: PHASE 5						PKG		
23.140	PKG 7,110 REF: AMM 20-21-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A237001 (s)	INSPECT COCKPIT VOICE RECORDER: PHASE 5						PKG		
23.120	PKG 7,106 REF: AMM 23-70-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A237003	INSPECT CVR UNDERWATER LOCATOR BEACON : PHASE 21								
23.120	DK120/90 PKG 35 AT102603 REF: AMM 23-70-00	MOS HRS/MSC AFL	24				12-JUN-2018	12-JUN-2020	
B231002 (s)	OPERATIONAL TEST HONEYWELL STANDBY CONTROL HEAD: PHASE 60 (AIRPLANES -0001 THRU -0750)						PKG		
23.150	PKG 68 REF: AMM 23-13-00	MOS HRS/MSC AFL	500	TSI:0 TSI:0 TSI:0			18-MAR-2014 4838 3562		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B236001 (s)	INSPECT STATIC DISCHARGE WICK: PHASE 5						PKG		
23.160	PKG 7,108 REF: AMM 23-61-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B237002 (s)	OPERATIONAL CHECK COCKPIT VOICE RECORDER: PHASE 1						PKG		
23.120	PKG 1 REF: AMM 23-70-00	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
B237004	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON : PHASE 21								
23.120	DK120/90 PKG 35 AT102603 REF: AMM 23-70-00	MOS HRS/MSC AFL	24				12-JUN-2018	12-JUN-2020	
CHAPTER 24 ELECTRICAL POWER									
242001	NO. 1 STATIC INVERTER								
24.010	SPC38B 1493 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:641			27-OCT-2006 3536		
242001	NO. 2 STATIC INVERTER								
24.010	SPC38B 2036 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0			19-SEP-2003 2572		
243001	LEFT STARTER/GENERATOR								
24.070 OVERHAUL	23085-004-1 92310 REF: AMM 80-11-01	MOS HRS/MSC AFL	1000	TSO:33:42			08-JUN-2011 4544:42 3343	5511	
243001	RIGHT STARTER/GENERATOR								
24.075 OVERHAUL	9912125-3 96116 REF: AMM 80-11-01	MOS HRS/MSC AFL	1000	TSO:0			18-MAY-2018 5077:50 3798	6077:50	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243003	NO. 1 GENERATOR CONTROL UNIT								
24.050	51539-006F 92130B REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243003	NO. 2 GENERATOR CONTROL UNIT								
24.050	51539-006F 92132B REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243004	NO. 1 AMMETER								
24.020	C662501-0104 787 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243004	NO. 2 AMMETER								
24.020	C662501-0104 789 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243005	DC VOLTMETER								
24.080	C662502-0101 J97391 REF: AMM 24-32-00	MOS HRS/MSC AFL	O/C	TSN:0			17-AUG-1998 1247		
243007	MAIN SHIP BATTERY								
24.030	30978-002 11100561 REF: AMM 24-32-00	MOS HRS/MSC AFL	O/C				22-SEP-2017		
243008	BATTERY TEMP MONITOR-								
24.060	1529-1 2096 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243009	BATTERY TEMP GAGE								
24.060	1229-1 1825 REF: AMM 24-32-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243010	BATTERY TEMP SENSOR								
24.060	1166-1 SN-UNKNOWN REF: AMM 24-32-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243011	CURRENT/VOLTAGE CONTROLLER								
24.040	1301-1 1977 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243015	BATTERY DISCONNECT RELAY								
24.090	A876K CK67606 REF: AMM 24-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
243016	CURRENT/VOLTAGE SENSOR								
24.040	1302-1 1832 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
245002	CABIN ALTITUDE SWITCH								
24.200	GB300NA161 0710758 REF: AMM 21-32-00	MOS HRS/MSC AFL	O/C	TSN:0			20-MAY-2011 4534 3335		
A242001 (s)	INSPECT NOSE AREA ELECTRICAL COMPONENTS: PHASE 5						PKG		
24.110	PKG 7,100 REF: AMM 24-00-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A245001 (s) 24.120	INSPECT CIRCUIT BREAKER PANELS: PHASE 5 PKG 7,102 REF: AMM 24-45-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A245002 (s) 24.130	INSPECT COCKPIT SIDE CONSOLE: PHASE 5 PKG 7,102 REF: AMM 24-45-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A245003 (s) 24.140	INSPECT AVIONICS RELAY JUNCTION BOX: PHASE 5 PKG 7,100 REF: AMM 24-00-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A245004 (s) 24.150	INSPECT AFT POWER JUNCTION BOX: PHASE 5 PKG 7,105 REF: AMM 24-45-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B243001 (s) 24.160	OPERATIONAL TEST DC GENERATOR SYSTEM: PHASE 4 PKG 4 REF: AMM 24-30-00	MOS HRS/MSC AFL	24 300				PKG 27-NOV-2017 5022:17 3749		
B243002	FUNCTIONAL CHECK MAIN SHIP BATTERY MARATHON NI-CAD BATTERY (CAPACITY CHECK): PHASE 28 30978-002 PKG 44 11100561 REF: AMM 24-32-00	MOS HRS/MSC AFL	12 200				17-OCT-2019 5211:13 3911	17-OCT-2020 5411:13	
B244001 (s) 24.170	FUNCTIONAL TEST OVERVOLTAGE SYSTEM: PHASE 1 PKG 1 REF: AMM 24-41-02	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018 5027 3753		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D243003 (s)	INSPECT MAIN SHIP BATTERY LEAD ACID BATTERY: PHASE 55						PKG		
24.190	30978-002 PKG 64 11100561 REF: AMM 24-35-00	MOS HRS/MSC AFL	12 600				28-JUL-2017		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
256002	EMERGENCY LOCATOR TRANSMITTER								
25.020	453-5000-999 210-00256 REF: AMM 25-61-05	MOS HRS/MSC AFL	O/C	TSR:1 TSN:390 TSR:0 TSN:348 TSR:0			02-SEP-2016		
256003	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY								
25.020	452-0133 366960-048 REF:	MOS HRS/MSC AFL	60	TSN:0 TSN:0			02-SEP-2016	01-OCT-2020 M	
256004	NO. 1 ELT ANTENNA								
25.030	110-337 287549 REF: AMM 25-61-05	MOS HRS/MSC AFL	O/C	TSN:0			03-JUL-2009 4511		
256004	NO. 2 ELT ANTENNA								
25.030	ELT10-177-2 UNK. REF: AMM 25-61-05	MOS HRS/MSC AFL	O/C	TSN:0			03-JUL-2009 4511		
256010	NO. 1 LIFE VEST								
25.300	PO723E105P E361478 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSO:6 TSO:0 TSO:0			30-OCT-2017	30-APR-2022	
256010	NO. 2 LIFE VEST								
25.300	PO723E105P 12031080015 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSO:6 TSO:0 TSO:0			30-OCT-2017	30-APR-2022	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256010	NO. 3 LIFE VEST PO1074-207 17062090019 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			30-OCT-2017	01-JUL-2027 M	
25.300									
256010	NO. 4 LIFE VEST PO1074-207 17062090018 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			30-OCT-2017	01-JUL-2027 M	
25.300									
256010	NO. 5 LIFE VEST P01074-207 17062090017 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			30-OCT-2017	01-JUL-2027 M	
25.300									
256010	NO. 6 LIFE VEST P01074-207 17062090020 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			30-OCT-2017	01-JUL-2027 M	
25.300									
256010	NO. 7 LIFE VEST P01074-207 17062090016 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			30-OCT-2017	01-JUL-2027 M	
25.300									
256010	NO. 8 LIFE VEST P01074-207 17062090015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2017	01-JUL-2027 M	
25.300									
25FO-01 560	LOCATOR BEACON-EMERG FACTORY OPTION 175 FO REF:	MOS HRS/MSC AFL	-				17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A251001 (s)	INSPECT PILOT AND COPILOT CREW SEAT: PHASE 5						PKG		
25.010	PKG 7,110 REF: AMM 25-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A251002 (s)	INSPECT PILOT AND COPILOT SEAT TRACK STOPS: PHASE 5						PKG		
25.040	PKG 7,110 REF: AMM 25-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A251004 (s)	INSPECT COCKPIT INSTRUMENT PANELS AND COMPONENTS: PHASE 5						PKG		
25.050	PKG 7,108 REF: AMM 25-10-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A252001 (s)	INSPECT PASSENGER SEAT: PHASE 5						PKG		
25.060	PKG 7,110 REF: AMM 25-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A252002 (s)	INSPECT PASSENGER SEAT TRACK STOPS: PHASE 5						PKG		
25.070	PKG 7,110 REF: AMM 25-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A256001 (s)	INSPECT EMERGENCY EQUIPMENT: PHASE 18						PKG		
25.080	PKG 22 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
A256003 (s)	INSPECT LIFE PRESERVER: PHASE 18						PKG		
25.090	PKG 22 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A256004 (s)	DETAILED INSPECTION SMOKE GOGGLE ASSEMBLY: PHASE 18						PKG		
25.310	PKG 22 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
A256101 (s)	VISUALLY INSPECT ARTEX C406-N EMERGENCY LOCATOR BEACON SYSTEM: PHASE 56						PKG		
25.200	PKG 65 REF: AMM 25-61-05	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
A256107 (s)	DETAILED INSPECTION C406-2 (ELT) 91.207: PHASE 56						PKG		
26.120	PKG 65 REF: AMM 25-61-07	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
B256001 (s)	VISUALLY INSPECT EMERGENCY LOCATOR BEACON SYSTEM: PHASE 56						PKG		
25.100 AIRWORTHINESS	PKG 65 REF: AMM 25-60-00	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
B256101 (s)	OPERATIONAL CHECK ARTEX C406-N EMERGENCY LOCATOR BEACON SYSTEM: PHASE 56						PKG		
25.260	PKG 65 REF: AMM 25-61-05	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
B256107 (s)	FUNCTIONAL TEST C406-2 (ELT) 91.207: PHASE 56						PKG		
26.120	PKG 65 REF: AMM 25-61-07	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		

CHAPTER 26 FIRE PROTECTION

261001	NO. 1 ENGINE FIRE DETECTOR SENSOR								
26.020	244-18882 SN-UNKNOWN REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0		17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261001	NO. 2 ENGINE FIRE DETECTOR SENSOR 244-18882	MOS					17-MAY-1993		
26.020	SN-UNKNOWN REF: AMM 26-11-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
261002	NO. 1 FIRE DETECTOR CONTROL 377-02808	MOS					17-MAY-1993		
26.010	9225030 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
261002	NO. 2 FIRE DETECTOR CONTROL 377-02808	MOS					17-MAY-1993		
26.010	9247006 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
262001	AFT ENGINE FIRE BOTTLE 9912048-3	MOS					26-SEP-2017		
26.040	18057C1 REF: AMM 26-21-01	HRS/MSC AFL	O/C	TSO:4 TSO:0 TSO:0					
262001	FORWARD ENGINE FIRE BOTTLE 9912048-3	MOS					06-APR-2017		
26.030	11422C1 REF: AMM 26-21-01	HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0					
262002	CABIN PORTABLE HALON FIRE EXTINGUISHER C352	MOS					26-SEP-2017		
26.060	A-29698035 REF: AMM 26-22-00	HRS/MSC AFL	O/C						
262002	COCKPIT PORTABLE HALON FIRE EXTINGUISHER C352	MOS					26-SEP-2017		
26.050	A-35314327 REF: AMM 26-22-00	HRS/MSC AFL	O/C						



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262003	AFT LEFT (MAX LIFE) CARTRIDGE								
	M873364-1	MOS	180	TSN:7			20-MAY-2011	25-OCT-2025	
26.030	02042	HRS/MSC					4534		
LIFE LIMIT	REF: See Workcard	AFL					3335		
	Manufacture Date: 25-OCT-2010	ACH							
262003	AFT RIGHT (MAX LIFE) CARTRIDGE								
	M873364-1	MOS	180	TSN:7			20-MAY-2011	25-OCT-2025	
26.040	02028	HRS/MSC					4534		
LIFE LIMIT	REF: See Workcard	AFL					3335		
	Manufacture Date: 25-OCT-2010								
262003	FORWARD LEFT (MAX LIFE) CARTRIDGE								
	PN	MOS	120				06-APR-2017	12-JAN-2027	
26.030	SN-UNKNOWN	HRS/MSC		TSO:0					
LIFE LIMIT	REF: See Workcard	AFL		TSO:0					
	Manufacture Date: 12-JAN-2017								
262003	FORWARD RIGHT (MAX LIFE) CARTRIDGE								
	PN	MOS	120				06-APR-2017	12-JAN-2027	
26.040	SN-UNKNOWN	HRS/MSC		TSO:0					
LIFE LIMIT	REF: See Workcard	AFL		TSO:0					
	Manufacture Date: 12-JAN-2017								
263005	REPLACE FORWARD LEFT (SERVICE LIFE) CARTRIDGE								
	PN	MOS	96				06-APR-2017	06-APR-2025	
26.030	SN-UNKNOWN	HRS/MSC							
REPLACE	REF: GENERIC NO REF	AFL							
263007	REPLACE FORWARD RIGHT (SERVICE LIFE) CARTRIDGE								
	PN	MOS	96				06-APR-2017	06-APR-2025	
26.040	SN-UNKNOWN	HRS/MSC							
REPLACE	REF: GENERIC NO REF	AFL							
263009	REPLACE AFT LEFT (SERVICE LIFE) CARTRIDGE								
	M873364-1	MOS	144				20-MAY-2011	20-MAY-2023	
26.030	02042	HRS/MSC							
REPLACE	REF: GENERIC NO REF	AFL							



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
263011	REPLACE AFT RIGHT (SERVICE LIFE) CARTRIDGE M873364-1	MOS	144				20-MAY-2011	20-MAY-2023	
26.040	02028	HRS/MSC					4534		
REPLACE	REF: GENERIC NO REF	AFL					3335		
A262003	INSPECT/WEIGH CABIN PORTABLE HALON FIRE EXTINGUISHER : PHASE 18 C352 PKG 22	MOS	12				21-NOV-2018	21-NOV-2019	
26.060	A-29698035	HRS/MSC							
05-10-25 AIRWORTHINESS	REF: AMM 26-22-00	AFL							
A262003	INSPECT/WEIGH COCKPIT PORTABLE HALON FIRE EXTINGUISHER : PHASE 18 C352 PKG 22	MOS	12				21-NOV-2018	21-NOV-2019	
26.050	A-35314327	HRS/MSC							
05-10-25 AIRWORTHINESS	REF: AMM 26-22-00	AFL							
B262002	HYDROSTATIC TEST AFT ENGINE FIRE BOTTLE 9912048-3	MOS	60				05-MAY-2017	05-MAY-2022	
26.040	18057C1	HRS/MSC							
	REF: AMM 26-22-00	AFL							
B262002	HYDROSTATIC TEST FORWARD ENGINE FIRE BOTTLE 9912048-3	MOS	60				12-JAN-2017	01-JAN-2022 M	
26.030	11422C1	HRS/MSC							
	REF: AMM 26-22-00	AFL							
B262003	HYDROSTATIC TEST CABIN PORTABLE HALON FIRE EXTINGUISHER C352	MOS	144				01-DEC-2014	01-DEC-2026	
26.060	A-29698035	HRS/MSC							
05-10-25 AIRWORTHINESS	REF: AMM 26-22-00	AFL							
B262003	HYDROSTATIC TEST COCKPIT PORTABLE HALON FIRE EXTINGUISHER C352	MOS	144				01-JAN-2014	01-JAN-2026	
26.050	A-35314327	HRS/MSC							
05-10-25 AIRWORTHINESS	REF: AMM 26-22-00	AFL							
B262004	EMPTY/INSPECT/RECHARGE CABIN PORTABLE HALON FIRE EXTINGUISHER : PHASE 48 C352 PKG 54	MOS	72				01-DEC-2014	01-DEC-2020	
26.060	A-29698035	HRS/MSC							
05-10-25 AIRWORTHINESS	REF: AMM 26-22-00	AFL							



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B262004	EMPTY/INSPECT/RECHARGE COCKPIT PORTABLE HALON FIRE EXTINGUISHER : PHASE 48								
26.050	C352 PKG 54 A-35314327 REF: AMM 26-22-00	MOS HRS/MSC AFL	72				01-JAN-2014	01-JAN-2020	
05-10-25 AIRWORTHINESS									
B262005 (s)	FUNCTIONAL TEST ENGINE FIRE EXTINGUISHER SYSTEM: PHASE 5								
26.110	PKG 7,102 REF: AMM 26-21-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
CHAPTER 27 FLIGHT CONTROLS									
271001	AILERON TRIM ACTUATOR								
27.010	5565450-72 SN-UNKNOWN REF: AMM 27-11-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
272001	RUDDER TRIM ACTUATOR								
27.020	5565450-71 SN-UNKNOWN REF: AMM 27-21-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
273002	TRIM MIXER ACTUATOR								
27.030	44430-3657 T319 REF: AMM 27-31-07	MOS HRS/MSC AFL	O/C	TSO:0			18-JUL-1996 627		
273003	LEFT ELEVATOR TRIM ACTUATOR								
27.040	5565450-81 SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0			13-OCT-1997 980		
273003	RIGHT ELEVATOR TRIM ACTUATOR								
27.040	5565450-82 SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
275001	FLAP CONTROL VALVE								
27.050	66720 969 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275003	NO. 1 FLAP ACTUATOR								
27.060	1535000 230 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
275003	NO. 2 FLAP ACTUATOR								
27.060	1535000 219 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
275004	LEFT WING LEFT INBOARD AFT FLAP ROLLER								
27.070	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0		5000
275004	LEFT WING LEFT OUTBOARD AFT FLAP ROLLER								
27.070	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0		5000
275004	LEFT WING RIGHT INBOARD AFT FLAP ROLLER								
27.075	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0		5000
275004	LEFT WING RIGHT OUTBOARD AFT FLAP ROLLER								
27.075	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0		5000
275004	RIGHT WING LEFT INBOARD AFT FLAP ROLLER								
27.080	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0		5000
275004	RIGHT WING LEFT OUTBOARD AFT FLAP ROLLER								
27.080	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0		5000



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275004	RIGHT WING RIGHT INBOARD AFT FLAP ROLLER								
27.085	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0	5000	
275004	RIGHT WING RIGHT OUTBOARD AFT FLAP ROLLER								
27.085	CC50380 SN-UNKNOWN REF: AMM 27-51-04	MOS HRS/MSC AFL	5000	TSN:0 TSN:0			17-MAY-1993 0 0	5000	
276001	NO. 1 SPEED BRAKE ACTUATOR								
27.090	1535500-1 87 REF: AMM 27-61-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
276001	NO. 2 SPEED BRAKE ACTUATOR								
27.090	1535500-1 103 REF: AMM 27-61-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
276002	SPEED BRAKE FLAP CONTROL VALVE								
27.100	66720 971 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
276003	SAFETY SPDBK VALVE								
27.110	68930 350 REF: AMM 27-61-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
A271003 (s)	INSPECT AILERON AND AILERON TRIM TAB: PHASE 2						PKG		
27.120	PKG 2 REF: AMM 27-11-00	MOS HRS/MSC AFL	24 300				16-MAR-2018		
A271004 (s)	INSPECT CONTROL WHEEL: PHASE 1						PKG		
27.130	PKG 1 REF: AMM 27-11-00	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A271005 (s) 27.140	INSPECT AILERON, RUDDER AND ELEVATOR TRIM TAB CONTROL AND INDICATOR: PHASE 1 PKG 1 REF: AMM 27-11-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018 5027 3753		
A271006 (s) 27.150	INSPECT AILERON CONTROL CABLE: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A271007 (s) 27.160	INSPECT AILERON TRIM CABLE: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A271008 (s) 27.170	INSPECT AILERON TRIM TAB ACTUATOR DISASSEMBLY: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A271014 (s) 27.180	INSPECT AILERON DRIVE BRACKET: PHASE 32 PKG 46 REF: AMM 27-11-00	MOS HRS/MSC AFL	15000		TSI:0 TSI:0 TSI:0		PKG 17-MAY-1993 0 0		
A271015 (s) 27.190	INSPECT AILERON YOKE: PHASE 33 PKG 47 REF: AMM 27-11-00	MOS HRS/MSC AFL	15000		TSI:0 TSI:0 TSI:0		PKG 17-MAY-1993 0 0		
A272002 (s) 27.200	INSPECT RUDDER AND RUDDER TRIM TAB: PHASE 2 PKG 2 REF: AMM 27-21-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A272003 (s) 27.210	INSPECT RUDDER PEDALS: PHASE 5 PKG 7,111 REF: AMM 27-21-03	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A272005 (s) 27.220	INSPECT RUDDER CABLE: PHASE 5 PKG 7,111 REF: AMM 27-21-06	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A272006 (s) 27.230	INSPECT RUDDER TRIM CABLE: PHASE 5 PKG 7,111 REF: AMM 27-21-06	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A272007 (s) 27.240	INSPECT RUDDER TRIM TAB ACTUATOR DISASSEMBLY: PHASE 5 PKG 7,111 REF: AMM 27-21-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A273002 (s) 27.250	EXTERNAL INSPECTION ELEVATOR: PHASE 2 PKG 2 REF: AMM 27-31-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A273005 (s) 27.260	INSPECT CONTROL COLUMNS: PHASE 5 PKG 7,111 REF: AMM 27-31-02	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A273006 (s) 27.270	INSPECT ELEVATOR LINKAGE: PHASE 5 PKG 7,107 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A273007 (s) 27.280	INSPECT FLAP/ELEVATOR ELECTRIC TRIM MIXER: PHASE 5 PKG 7,105 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A273008 (s) 27.290	INSPECT ELEVATOR CABLE: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A273009 (s) 27.300	INSPECT ELEVATOR TRIM CABLE: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A273010 (s) 27.310	INSPECT ELEVATOR TRIM TAB ACTUATOR DISASSEMBLY: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A275003 (s) 27.320	INSPECT FLAP PRESELECT CABLE: PHASE 5 PKG 7,111 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A275004 (s) 27.330	INSPECT FLAP: PHASE 2 PKG 2 REF: AMM 27-51-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A275007 (s) 27.340	INSPECT FLAP BELL CRANKS: PHASE 5 PKG 7,111 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A275021 (s) 27.350	INSPECT FLAP CROSSTIE SYSTEM: PHASE 5 PKG 7,111 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A275022 (s) 27.360	INSPECT FLAP/ELEVATOR TRIM MIXER INTERCONNECT CABLE SYSTEM: PHASE 5 PKG 7,111 REF: AMM 27-31-07	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A276001 (s) 27.370	INSPECT SPEED BRAKE SYSTEM: PHASE 5 PKG 7,109 REF: AMM 27-61-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B271001 (s) 27.380	CHECK AILERON TRIM TAB: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B271002 (s) 27.390	CHECK AILERON AND AILERON TRIM TAB: PHASE 5 PKG 7,111 REF: AMM 27-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B272001 (s) 27.400	CHECK RUDDER TRIM TAB: PHASE 5 PKG 7,107 REF: AMM 27-21-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B272004 (s) 27.410	CHECK RUDDER AND RUDDER TRIM TAB TRAVEL: PHASE 5 PKG 7,111 REF: AMM 27-21-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B273003 (s) 27.420	CHECK ELEVATOR AND ELEVATOR TRIM TAB: PHASE 5 PKG 7,111 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B273004 (s) 27.430	CHECK ELEVATOR TRIM TAB FREE PLAY: PHASE 5 PKG 7,107 REF: AMM 27-31-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B273015 (s) 27.440	OPERATIONAL CHECK ELEVATOR ELECTRICAL TRIM MIXER SYSTEM: PHASE 1 PKG 1 REF: AMM 27-31-07	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018 5027 3753		
B275004 (s) 27.450	OPERATIONAL CHECK FLAP APPROACH WARNING SWITCH: PHASE 5 PKG 7,102 REF: AMM 27-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B275006 (s)	CHECK FLAP TRAVEL: PHASE 5						PKG		
27.460	PKG 7,109	MOS	36				12-DEC-2017		
	REF: AMM 27-51-00	HRS/MSC	1200				5022:17		
		AFL					3749		
B275009 (s)	LEAK CHECK FLAP HYDRAULIC ACTUATORS: PHASE 5						PKG		
27.470	PKG 7,111	MOS	36				12-DEC-2017		
	REF: AMM 27-51-04	HRS/MSC	1200				5022:17		
		AFL					3749		
B277001 (s)	INSPECT/OPERATIONAL CHECK CONTROL LOCK SYSTEM: PHASE 5						PKG		
27.480	PKG 7,102	MOS	36				12-DEC-2017		
	REF: AMM 27-71-00	HRS/MSC	1200				5022:17		
		AFL					3749		
C271001 (s)	LUBRICATE/CHECK AILERON TRIM TAB ACTUATOR: PHASE 2						PKG		
27.490	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 27-11-00	HRS/MSC	300						
		AFL							
C272001 (s)	LUBRICATE/CHECK RUDDER TRIM TAB ACTUATOR: PHASE 2						PKG		
27.500	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 27-21-00	HRS/MSC	300						
		AFL							
C273001 (s)	LUBRICATE/CHECK ELEVATOR TRIM TAB ACTUATOR: PHASE 2						PKG		
27.510	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 27-31-00	HRS/MSC	300						
		AFL							
CHAPTER 28	FUEL								
282001	NO. 1 ELECTRIC FUEL BOOST PUMP								
28.060	1C7-12	MOS					17-MAY-1993		
	9AH128	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-01	AFL		TSN:0			0		
282001	NO. 2 ELECTRIC FUEL BOOST PUMP								
28.060	1C7-12	MOS					17-MAY-1993		
	9AH133	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 28-21-01	AFL		TSN:0			0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282010	LEFT MOTIVE FUEL VALVE								
28.120	3244850-1 B 28463 REF: AMM 28-21-06	MOS HRS/MSC AFL	O/C	TSO:0			07-SEP-2006 3493		
282010	RIGHT MOTIVE FUEL VALVE								
28.120	3244850-1 B 28242 REF: AMM 28-21-06	MOS HRS/MSC AFL	O/C	TSO:0			07-SEP-2006 3493		
284001	NO. 1 FUEL LOW LEVEL SWITCH								
28.170	L15H-3 SN-UNKNOWN REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
284001	NO. 2 FUEL LOW LEVEL SWITCH								
28.170	L15H-3 SN-UNKNOWN REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
284002	LEFT FUEL QTY COMPENSATOR								
28.160	300047-13001 16599 REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
284002	RIGHT FUEL QTY COMPENSATOR								
28.160	300047-13001 16598 REF: AMM 28-44-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
284007	FUEL QTY INDICATOR								
28.165	VSDL-OC403F-1 563 REF: AMM 28-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
A281001 (s)	INSPECT WING FUEL STORAGE AREA: PHASE 5						PKG		
28.200	PKG 7,109 REF: AMM 28-10-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A282002 (s)	INSPECT WING FUEL SYSTEM COMPONENT: PHASE 5						PKG		
28.210	PKG 7,109 REF: AMM 28-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B282003 (s)	OPERATIONAL CHECK FUEL SYSTEM: PHASE 5						PKG		
28.220	PKG 7,104 REF: AMM 28-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B282004 (s)	OPERATIONAL CHECK FUEL SYSTEM: PHASE 5						PKG		
28.230	PKG 7,103 REF: AMM 28-20-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B284001 (s)	OPERATIONAL CHECK LOW FUEL WARNING SYSTEM: PHASE 5						PKG		
28.240	PKG 7,104 REF: AMM 28-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
D282002 (s)	CHANGE FUEL FILTER ELEMENT: PHASE 5						PKG		
28.250	PKG 7,109 REF: AMM 28-21-05	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
CHAPTER 29	HYDRAULIC POWER								
291001	MAIN HYD RESERVOIR								
29.010	40500-7 420 REF: AMM 29-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
291002	LEFT HYDRAULIC PUMP								
29.050	24195-LAA 1429 REF: AMM 29-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
291002	RIGHT HYDRAULIC PUMP								
29.050	24195-LAA 1430 REF: AMM 29-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291005	NO. 1 CK VALVE HYDRAULIC FLOW SWITCH 3520020100-4	MOS					17-MAY-1993		
29.020	3275 REF: AMM 29-11-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291005	NO. 2 CK VALVE HYDRAULIC FLOW SWITCH 3520020100-4	MOS					17-MAY-1993		
29.020	3299 REF: AMM 29-11-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291007	NO. 1 MOTOR ACTUATOR VALVE AV24B1325C5	MOS					17-MAY-1993		
29.120	RP10886 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291007	NO. 2 MOTOR ACTUATOR VALVE AV24B1325C5	MOS					17-MAY-1993		
29.120	P21133 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291008	THERMAL RELIEF VALVE OAS5322-3-1700	MOS					17-MAY-1993		
29.030	275 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291009	PRESSURE RELIEF VALVE 4614	MOS					17-MAY-1993		
29.030	1322A REF: AMM 28-11-10	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
291012	SOLENOID BYPASS VALVE 61510-1	MOS					17-MAY-1993		
29.040	1057A REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
A291002 (s)	INSPECT HYDRAULIC SUB-PANEL: PHASE 1 PKG 1,3,15	MOS					PKG 08-AUG-2018		
29.100	REF: AMM 29-11-06	HRS/MSC AFL	150				5114:38 3835		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D291001 (s)	INSPECT/REPLACE HYDRAULIC FILTERS AND FILTER ELEMENT: PHASE 5						PKG		
29.110	PKG 7,105 REF: AMM 29-11-04	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
CHAPTER 30 ICE AND RAIN PROTECTION									
301001	LEFT TEMP CONTROL SL002 SWITCH								
30.060	1173T42-3 SN-UNKNOWN REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
301001	NO. 1 OUTBRD WING DEICE BOOT								
30.020	35-5D5230-01 395HB REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
Note: SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.									
301001	NO. 2 OUTBRD WING DEICE BOOT								
30.020	35-5D5230-02 MT37300 REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0			14-APR-2002 2186		
Note: SL560-57-01 IS MANDATORY AND NEEDS TO BE INCORPORATED WHEN DE-ICE BOOTS ARE REMOVED.									
301001	RIGHT TEMP CONTROL SR002 SWITCH								
30.060	1173T42-3 SN-UNKNOWN REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
301001	WING ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE								
30.125	1H123-1 1AJ7 REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
301002	NO. 1 HORIZONTAL STABILIZER DEICE BOOT								
30.010	29S-5D5225-03 229CT REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301002	NO. 2 HORIZONTAL STABILIZER DEICE BOOT 29S-5D5225-04	MOS					17-MAY-1993		
30.010	244LT REF: AMM 30-12-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301004	LEFT WING ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV 67410-2	MOS					17-MAY-1993		
30.090	2278ABC REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301004	RIGHT WING ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV 67410-2	MOS					17-MAY-1993		
30.090	2276ABC REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301007	LEFT RAM AIR MODULATING TEMP CONTROL VLV 27441500-01	MOS					17-MAY-1993		
30.080	1AJ6 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301007	RIGHT RAM AIR MODULATING TEMP CONTROL VLV 27441500-01	MOS					17-MAY-1993		
30.080	1AJ4 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301008	LEFT DEICE CONTROL SLV19 VLV 3D2353-06	MOS					17-MAY-1993		
30.040	N12140 REF: AMM 30-12-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301008	RIGHT DEICE CONTROL SLV18 VLV 3D2353-06	MOS					17-MAY-1993		
30.040	N12114 REF: AMM 30-12-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
301009	LEFT TEMP CONTROL S95 SENSOR 27431501-04	MOS					17-MAY-1993		
30.070	7AH107 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301009	RIGHT TEMP CONTROL S94 SENSOR 27431501-04	MOS					17-MAY-1993		
30.070	7AH84 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
302003	LEFT ENGINE ANTI-ICE SOLENOID VLV 67410-1	MOS					25-AUG-1993		
30.170	2339AD REF: AMM 30-21-01	HRS/MSC AFL	O/C	TSN:0					
302003	RIGHT ENGINE ANTI-ICE SOLENOID VLV 67410-1	MOS					28-SEP-1993		
30.170	1891AD REF: AMM 30-21-01	HRS/MSC AFL	O/C	TSO:0			36		
302004	LEFT ENGINE INLET TEMPERATURE S95 SWITCH 21548-2-19-6	MOS					17-MAY-1993		
30.200	SN-UNKNOWN REF: AMM 30-21-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
302004	RIGHT ENGINE INLET TEMPERATURE S94 SWITCH 21548-2-19-6	MOS					17-MAY-1993		
30.200	SN-UNKNOWN REF: AMM 30-21-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
302005	LEFT ANTI ICING VALVE 10018200C	MOS					22-SEP-2008		
30.490	893 REF: AMM 30-21-01	HRS/MSC AFL	O/C	TSO:0			4293		
302005	RIGHT ANTI ICING VALVE 10018200D	MOS					26-NOV-2015		
30.490	204 REF: AMM 30-21-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			5017 3718		
302006	LEFT BLEED VALVE ACTUATOR 800888-1	MOS					07-SEP-2006		
30.500	F 25429 REF: AMM 30-21-01	HRS/MSC AFL	O/C	TSO:0			3493		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302006	RIGHT BLEED VALVE ACTUATOR 800888-1 F 26357 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSO:0			07-SEP-2006 3493		
303001	LEFT PITOT TUBE PH502 SN-UNKNOWN REF: AMM 30-31-00	MOS HRS/MSC AFL	O/C	TSN:0			18-FEB-1998 1053		
303001	RIGHT PITOT TUBE PH502 SN-UNKNOWN REF: AMM 30-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
304001	BLEED AIR MONITOR- 1169-1 2004 REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
304002	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER 10663A 698 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
304004	ALCOHOL WINDSHIELD ANTI-ICE PUMP 476411 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
304005	TEMP CONTROL VALVE 27241287 7BA69P REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C				01-JUN-2012 4653:36 3414		
304006	ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR 27231272-20A 1AJ9 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304007	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH 1115P25 2043A REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
304009	WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE 67410-2 G1998 REF: AMM 30-41-00	MOS HRS/MSC AFL	O/C	TSO:0			27-JUL-1999 1503		
A301001 (s)	INSPECT WING HEATED LEADING EDGE BLEED AIR OUTLET HOLES: PHASE 2 PKG 2 REF: AMM 30-11-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A301002 (s)	INSPECT WING HEATED LEADING EDGE AND PLUMBING: PHASE 5 PKG 7,109 REF: AMM 30-11-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A301003 (s)	INSPECT WING HEATED LEADING EDGE BLEED AIR COMPONENTS: PHASE 3 PKG 3 REF: AMM 30-11-00	MOS HRS/MSC AFL	24 300				PKG 27-NOV-2017 5022:17 3749		
A301004 (s)	INSPECT WING HEATED LEADING EDGE ANTI-ICE TAILCONE COMPONENTS: PHASE 5 PKG 7,105 REF: AMM 30-11-00	MOS HRS/MSC AFL	24 300				PKG 12-DEC-2017 5022:17 3749		
A301005 (s)	INSPECT WING HEATED LEADING EDGE BLEED AIR OUTLET HOLES: PHASE 2 PKG 2 REF: AMM 30-14-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A301006 (s)	INSPECT WING HEATED LEADING EDGE AND PLUMBING: PHASE 5 PKG 7,109 REF: AMM 30-14-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A301008 (s)	INSPECT WING HEATED LEADING EDGE ANTI-ICE TAILCONE COMPONENTS: PHASE 5						PKG		
30.360	PKG 7,105 REF: AMM 30-14-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A304001 (s)	INSPECT WINDSHIELD BLEED AIR AUGMENTER DOOR AND SHROUD: PHASE 5						PKG		
30.380	PKG 7,101 REF: AMM 30-41-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A304003 (s)	INSPECT WINDSHIELD BLEED AIR CONTROLS: PHASE 5						PKG		
30.390	PKG 7,108 REF: AMM 30-41-04	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A304004 (s)	INSPECT WINDSHIELD ALCOHOL RESERVOIR: PHASE 5						PKG		
30.290	PKG 7,100 REF: AMM 30-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B301001 (s)	OPERATIONAL TEST BLEED AIR ANTI-ICE SYSTEMS: PHASE 5						PKG		
30.400	PKG 7,104 REF: AMM 30-11-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B301003 (s)	OPERATIONAL CHECK PNEUMATIC DEICE SYSTEM: PHASE 4						PKG		
30.420	PKG 4 REF: AMM 30-12-00	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
B301005 (s)	OPERATIONAL TEST BLEED AIR ANTI-ICE SYSTEMS: PHASE 5						PKG		
30.430	PKG 7,104 REF: AMM 30-14-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B301006 (s)	OPERATIONAL CHECK PNEUMATIC DEICE SYSTEM: PHASE 4						PKG		
30.440	PKG 4 REF: AMM 30-12-00	MOS HRS/MSC AFL	24 300				26-OCT-2017		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B304001 (s)	OPERATIONAL CHECK WINDSHIELD ANTI-ICE: PHASE 5						PKG		
30.450	PKG 7,102 REF: AMM 30-41-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B304004 (s)	OPERATIONAL TEST WINDSHIELD ALCOHOL PUMP: PHASE 1						PKG		
30.460	PKG 1 REF: AMM 30-42-00	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
D304004 (s)	INSPECT/CLEAN WINDSHIELD ALCOHOL RESERVOIR FILTER: PHASE 5						PKG		
30.470	PKG 7,100 REF: AMM 30-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		

CHAPTER 31 INDICATING/RECORDING SYSTEMS

312001	PILOT DIGITAL CLOCK								
31.010	M877A5V 4904 REF: AMM 31-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
313001	FLIGHT HOUR RECORDER								
31.050	C664503-0102 SN-UNKNOWN REF: AMM 31-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
313003	FDR ACCELEROMETER								
31.030	3001-01-101-2 0703-5731 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2011 0 0		
313003	NO. 1 ACCELEROMETER								
31.070	7000992 6520 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
313003	NO. 2 ACCELEROMETER								
31.070	7000992 6517 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-JUN-2011 4544:42 3343		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313006	FLIGHT DATA RECORDER								
31.020	S703-1000-00 01094 REF: AMM 31-30-01	MOS HRS/MSC AFL	O/C				20-MAY-2011 4534 3335		
313007	FDR UNDERWATER LOCATOR BEACON								
31.020 REPLACE	DK120/90 AT102402 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	TSN:0			12-JUN-2018 5083 3804	12-JUN-2024	
313007A	BATTERY FDR UNDERWATER LOCATOR BEACON								
31.020	DK120/90 AT102402 REF: GENERIC NO REF	MOS HRS/MSC AFL	72				12-JUN-2018	01-JAN-2025 M	
315001	MASTER WARNING ANNUNCIATOR								
31.060	465-1-14 531 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
A313001 (s)	INSPECT FLIGHT DATA RECORDER: PHASE 5						PKG		
31.020	PKG 7,106 REF: AMM 31-30-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A313002	INSPECT FDR UNDERWATER LOCATOR BEACON : PHASE 21								
31.020	DK120/90 PKG 35 AT102402 REF: AMM 31-30-00	MOS HRS/MSC AFL	24				12-JUN-2018	12-JUN-2020	
B313002	OPERATIONAL TEST FDR UNDERWATER LOCATOR BEACON : PHASE 21								
31.020	DK120/90 PKG 35 AT102402 REF: AMM 31-30-00	MOS HRS/MSC AFL	24				12-JUN-2018	12-JUN-2020	
CHAPTER 32	LANDING GEAR								
321001	LEFT MAIN LANDING GEAR ASSEMBLY								
32.010	6641000-35 47 REF: See Workcard	MOS HRS/MSC AFL		TSN:0 TSN:0			17-MAY-1993 0 0		12450



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321002	RIGHT MAIN LANDING GEAR ASSEMBLY 6641000-36	MOS					17-MAY-1993		
32.020	47	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: See Workcard	AFL	12450	TSN:0			0		12450
321003	LEFT MAIN LANDING GEAR TORQUE LINK BOLT 5541220-2	MOS					17-MAY-1993		
32.030	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	10370	TSN:0			0		10370
321003	RIGHT MAIN LANDING GEAR TORQUE LINK BOLT 5541220-2	MOS					17-MAY-1993		
32.030	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	10370	TSN:0			0		10370
322001	NOSE LANDING GEAR ASSEMBLY 6642000-26	MOS					17-MAY-1993		
32.080	3	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-21-01	AFL	23500	TSN:0			0		23500
322002	NOSE SHIMMY DAMPER 5543001-7	MOS					22-NOV-2011		
32.100	57	HRS/MSC	O/C				4600:06		
	REF: GENERIC NO REF	AFL					3379		
322004	NOSE GEAR FORK/PISTON 6642000-3	MOS					17-MAY-1993		
32.090	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-21-01	AFL	13640	TSN:0			0		13640
323001	LEFT MAIN LANDING GEAR ACTUATOR 1523100-3	MOS					17-MAY-1993		
32.160	1008B	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-31-04	AFL	15000	TSN:0			0		15000
323002	RIGHT MAIN LANDING GEAR ACTUATOR 1523100-4	MOS					17-MAY-1993		
32.160	1054B	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: See Workcard	AFL	15000	TSN:0			0		15000



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323003	NOSE LANDING GEAR ACTUATOR 1523200-9 32.170 1784 LIFE LIMIT	MOS HRS/MSC AFL	15000	TSN:0			07-JUL-2009 4511 3325	18325	
323004	LEFT MLG UPLOCK ACTUATOR 5527504-2 WMP3711 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			18-JAN-2011 4515 3326		
323004	NOSE UPLOCK ACTUATOR 5527504-2 578 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
323004	RIGHT MLG UPLOCK ACTUATOR 5527504-2 WMP3693 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			18-JAN-2011 4515 3326		
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 212940-2 1004 REF: Manufacture Date: 28-FEB-2018	MOS HRS/MSC AFL	288	TSO:1			16-MAR-2018 5027 3753	28-FEB-2042	
323007	LANDING GEAR CONTROL VALVE 66710 521 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
323008	DUMP VALVE OAS5319-1 298 REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
323019	EMERGENCY AIR BOTTLE GAUGE 2341128 51393A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324001	LEFT MLG WHEEL ASSEMBLY								
32.340	3-1490-1 4057 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			27-SEP-2018 5164 3873		
324001	RIGHT MLG WHEEL ASSEMBLY								
32.350	3-1490-1 3256 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				13-APR-2018 5036:31 3760		
324002	NOSE WHEEL ASSEMBLY								
32.360	3-1418 3755 REF: AMM 32-41-02	MOS HRS/MSC AFL	O/C				18-MAR-2014 4838 3562		
324003	LEFT MLG BRAKE ASSEMBLY								
32.230	2-1529-7 1137 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C				29-SEP-2014 4880 3604		
324004	RIGHT MLG BRAKE ASSEMBLY								
32.230	2-1529-7 1960 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C				13-APR-2018 5036:31 3760		
324005	LEFT MLG TIRE								
32.340	220K28-1 80292675 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			27-SEP-2018 5164 3873		
324005	RIGHT MLG TIRE								
32.350	220K28-1 32542849 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				13-APR-2018 5036:31 3760		
324006	NOSE TIRE								
32.360	031-613-8 1108S00172 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			18-MAR-2014 4838 3562		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324010	LEFT MLG SHUTTLE VALVE								
32.210	195-183 3471 REF: AMM 32-31-08	MOS HRS/MSC AFL	O/C	TSO:0			05-SEP-2008 4248 3121		
324010	RIGHT MLG SHUTTLE VALVE								
32.210	195-183 3090 REF: AMM 32-31-08	MOS HRS/MSC AFL	O/C	TSO:0			05-SEP-2008 4248 3121		
324011	LEFT MLG INBOARD BRAKE MASTER CYLINDER								
32.280	95367-9 617 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324011	RIGHT MLG INBOARD BRAKE MASTER CYLINDER								
32.290	95367-9 552 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324012	LEFT MLG OUTBOARD MASTER BRAKE CYLINDER								
32.280	95367-10 1040 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324012	RIGHT MLG OUTBOARD MASTER BRAKE CYLINDER								
32.290	95367-10 1065 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324014	EMERGENCY AIR BRAKE VALVE								
32.330	895232-0875 304 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324019	BRAKE PRESS PUMP ASSEMBLY								
32.310	634343 5442 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324021	POWER BRAKE ANTISKID VALVE								
32.240	38-707-1 736 REF: AMM 32-42-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324022	BRAKE CONTROL BOX								
32.250	42-707-1 804 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324023	ANTISKID ACCUMULATOR								
32.260	57C57652 RH0668 REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324024	LEFT MLG WHEEL TRANSDUCER								
32.220	40-955 2786 REF: AMM 32-42-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324024	RIGHT MLG WHEEL TRANSDUCER								
32.220	40-955 2858 REF: AMM 32-42-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324025	PRESSURE SWITCH								
32.320	1206P27 2043 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
324026	POWER BRAKE ASSEMBLY MOTOR								
32.300	MP50B1 2857 REF:	MOS HRS/MSC AFL	O/C	TSO:0			29-AUG-2006 3493		
324101	PARKING BRAKE VALVE								
32.330	20800-6 0884A REF:	MOS HRS/MSC AFL	O/C	TSN:0			07-JUN-2001 2026		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325001	NOSE STEERING BUNGEE ASSEMBLY								
32.370	5565624-19 SN-UNKNOWN REF: AMM 32-51-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
326003	LEFT MAIN GEAR DOWN & LOCK SWITCH								
32.380	1EN118-6 SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0			17-MAY-1993 5 7		
326003	NOSE GEAR DOWN & LOCK SWITCH								
32.390	1EN118-6 SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0			17-MAY-1993 5 7		
326003	RIGHT MAIN GEAR DOWN & LOCK SWITCH								
32.380	1EN118-6 SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0			17-MAY-1993 5 7		
326005	LEFT MAIN GEAR UP & LOCKED SWITCH								
32.400	65-430087 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
326005	NOSE GEAR UP & LOCKED SWITCH								
32.410	65-430087 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
326005	RIGHT MAIN GEAR UP & LOCKED SWITCH								
32.400	65-430087 207501130 REF:	MOS HRS/MSC AFL	O/C	TSN:0			24-JUL-2001 2052 1683		
A320001 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF LANDING GEAR: PHASE 64						PKG		
	PKG 503 REF: AMM 32-00-00	MOS HRS/MSC AFL	6				27-NOV-2018 5196:23 3898		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A320002 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF LANDING GEAR: PHASE 18 PKG 22	MOS	12				PKG 27-NOV-2018 5196:23 3898		
	REF: AMM 32-00-00	HRS/MSC AFL							
A321001 (s)	INSPECT MAIN LANDING GEAR: PHASE 2 PKG 2	MOS	24				PKG 16-MAR-2018		
32.460	REF: AMM 32-11-01	HRS/MSC AFL	300						
A321002 (s)	CHECK MAIN GEAR STRUT EXTENSION: PHASE 2 PKG 2	MOS	24				PKG 16-MAR-2018		
32.470	REF: AMM 32-11-01	HRS/MSC AFL	300						
A321003 (s)	INSPECT MAIN LANDING GEAR: PHASE 2 PKG 2	MOS	24				PKG 16-MAR-2018		
32.480	REF: AMM 32-11-02	HRS/MSC AFL	300						
A322001 (s)	INSPECT SHIMMY DAMPER: PHASE 2 PKG 2,4,15	MOS	24				PKG 08-AUG-2018 5114:38 3835		
32.100	REF: AMM 32-21-02	HRS/MSC AFL	300						
A322002 (s)	INSPECT NOSE GEAR ASSEMBLY: PHASE 2 PKG 2	MOS	24				PKG 16-MAR-2018		
32.080	REF: AMM 32-21-01	HRS/MSC AFL	300						
A323002 (s)	INSPECT NOSE GEAR UPLOCK: PHASE 2 PKG 2	MOS	24				PKG 16-MAR-2018		
32.490	REF: AMM 32-31-05	HRS/MSC AFL	300						
A323003 (s)	INSPECT EMERGENCY GEAR EXTENSION SYSTEM CABLE: PHASE 5 PKG 7,111	MOS	36				PKG 12-DEC-2017 5022:17 3749		
32.500	REF: AMM 32-31-08	HRS/MSC AFL	1200						



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A323004 (s)	INSPECT MAIN GEAR UPLOCK: PHASE 2						PKG		
32.510	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 32-31-05	HRS/MSC	300						
		AFL							
A323005 (s)	INSPECT MAIN GEAR UPLOCK: PHASE 2						PKG		
32.510	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 32-31-05	HRS/MSC	300						
		AFL							
A324001 (s)	INSPECT/SERVICE MAIN GEAR WHEEL, TIRE AND BEARING: PHASE 2						PKG		
32.520	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 32-41-01	HRS/MSC	300						
		AFL							
A324002 (s)	INSPECT/SERVICE NOSE WHEEL, TIRE AND BEARING: PHASE 2						PKG		
32.360	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 32-41-02	HRS/MSC	300						
		AFL							
A324003 (s)	INSPECT/SERVICE NOSE WHEEL, TIRE AND BEARING (WITH GRAVEL RUNWAY): PHASE 2						PKG		
32.360	PKG 2	MOS	24				16-MAR-2018		
	REF: AMM 32-41-02	HRS/MSC	300						
		AFL							
A324004 (s)	INSPECT BRAKE MASTER CYLINDER: PHASE 1						PKG		
32.360	PKG 1	MOS	24				16-MAR-2018		
	REF: AMM 32-42-02	HRS/MSC	300				5027		
		AFL					3753		
A324005 (s)	INSPECT EMERGENCY BRAKE CONTROL VALVE: PHASE 5						PKG		
32.530	PKG 7,101	MOS	36				12-DEC-2017		
	REF: AMM 32-42-09	HRS/MSC	1200				5022:17		
		AFL					3749		
A324007 (s)	INSPECT BRAKE RESERVOIR AND ANTISKID SYSTEM COMPONENTS: PHASE 5						PKG		
32.540	PKG 7,100	MOS	36				12-DEC-2017		
	REF: AMM 32-42-00	HRS/MSC	1200				5022:17		
		AFL					3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A324012 (s) 32.550	INSPECT MAIN LANDING GEAR WHEEL BRAKE: PHASE 2 PKG 2 REF: AMM 32-42-01	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A324013 (s) 32.560	INSPECT BRAKE METERING VALVE: PHASE 2 PKG 2 REF: AMM 32-42-10	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A324014 (s) 32.520	INSPECT/SERVICE MAIN GEAR WHEEL, TIRE AND BEARING: PHASE 2 PKG 2 REF: AMM 32-41-01	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A325001 (s) 32.570	INSPECT NOSE STEERING ARM SUPPORT BRACKET, BUNGEE AND BELLCRANK: PHASE 5 PKG 7,103 REF: AMM 32-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A325002 (s) 32.580	INSPECT NOSE STEERING SYSTEM CABLE: PHASE 5 PKG 7,111 REF: AMM 32-51-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A325003 (s) 32.590	INSPECT GRAVEL RUNWAY/NOSE WHEEL SPIN-UP COMPONENTS: PHASE 2 PKG 2,4,15 REF: AMM 32-43-00	MOS HRS/MSC AFL	150				PKG 08-AUG-2018 5114:38 3835		
A325004 (s) 32.600	INSPECT NOSE WHEEL SPIN-UP CONTROL: PHASE 2 PKG 2 REF: AMM 32-43-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
A325009 32.090 AIRWORTHINESS	INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK: PHASE MG 6642000-3 PKG 74 SN-UNKNOWN REF: AMM 32-21-01	MOS HRS/MSC AFL	10000				17-MAY-1993 0 0	10000	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B324006 (s) 32.620	CHECK MAIN GEAR WHEEL BRAKES WEAR: PHASE 2 PKG 2,4,15 REF: AMM 32-42-01	MOS HRS/MSC AFL	150				PKG 08-AUG-2018 5114:38 3835		
B324008 (s) 32.630	OPERATIONAL CHECK ANTISKID BRAKE SYSTEM: PHASE 5 PKG 7,104 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B324009 (s) 32.640	OPERATIONAL TEST EMERGENCY BRAKE SYSTEM: PHASE 5 PKG 7,104 REF: AMM 32-42-09	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B325001 (s) 32.650	FUNCTIONAL TEST NOSE WHEEL SPIN-UP SYSTEM: PHASE 5 PKG 7,104 REF: AMM 32-43-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B326001 (s) 32.660	ADJUSTMENT/TEST LANDING GEAR HYDRAULIC SYSTEMS: PHASE 2 PKG 2 REF: AMM 32-01-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
B326002 (s) 32.670	CYCLE TEST LANDING GEAR: PHASE 2 PKG 2 REF: AMM 32-01-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		
B326003 32.180	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 212940-2 1004 REF: AMM 32-31-09	MOS HRS/MSC AFL	36				01-FEB-2018	01-FEB-2021	
B326004 (s) 32.680	PERFORM LANDING GEAR HYDRAULIC SYSTEMS TEST: PHASE 2 PKG 2 REF: AMM 32-01-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C325013 (s)	INSPECT NOSE WHEEL INNER AXLE: PHASE 2						PKG		
32.700	PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	24 300				16-MAR-2018		
D324007 (s)	REPLACE ANTISKID SYSTEM MOTOR/PUMP FILTER: PHASE 5						PKG		
32.710	PKG 7,100 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
D324010 (s)	REPLACE BRAKE RESERVOIR AIR FILTER: PHASE 5						PKG		
32.720	PKG 7,100 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
D324011 (s)	CLEAN BRAKE RESERVOIR SUPPLY LINE FILTER: PHASE 5						PKG		
32.730	PKG 7,100 REF: AMM 32-42-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
D324012 (s)	CLEAN MASTER CYLINDER IN-LINE FILTER: PHASE 5						PKG		
32.760	PKG 7,100 REF: AMM 32-42-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
CHAPTER 33 LIGHTS									
331001	NO. 1 LIGHT PANEL DIMMER								
33.150	273-1 2038 REF: AMM 33-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
331001	NO. 2 LIGHT PANEL DIMMER								
33.150	273-1 208200053 REF: AMM 33-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			10-FEB-2012 4615:48 3391		
331001	NO. 3 LIGHT PANEL DIMMER								
33.150	273-1 2052 REF: AMM 33-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331011	INVT-115V EL PANEL								
33.160	EM2044-1 1640 REF: AMM 33-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
332001	INDIRECT LIGHT POWER UNIT								
33.030	AL-5112 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
332002	AFT INDIRECT LIGHTING INVERTER								
33.020	AL0581 10263 REF:	MOS HRS/MSC AFL	O/C				22-JUN-2012 4674:12 3432		
332002	FORWARD INDIRECT LIGHTING INVERTER								
33.010	AL5114 4992 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
334002	ROTATING/FLASHING BEACON								
33.080	30-2140-1 255 REF: AMM 33-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
334003	NO. 1 STROBE POWER SUPPLY								
33.090	60-2799-1 17852 REF:	MOS HRS/MSC AFL	O/C	TSO:0			24-JUN-2008 4133		
334003	NO. 2 STROBE POWER SUPPLY								
33.090	60-2799-1 16617 REF:	MOS HRS/MSC AFL	O/C				10-MAY-2013 4794:24 3526		
335001	EMERGENCY BATTERY PACK								
33.080	CBS28 6712 REF: AMM 33-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			22-MAY-2014 4858:30 3577		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A332001 (s)	INSPECT INDIRECT CABIN FLUORESCENT LIGHTING: PHASE 5						PKG		
33.100	PKG 7,103 REF: AMM 33-21-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A335001 (s)	INSPECT EMERGENCY LIGHTS, BATTERY BOX AND BATTERIES: PHASE 5						PKG		
33.110	PKG 7,101 REF: AMM 33-51-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A335002 (s)	INSPECT EMERGENCY EXIT LIGHTS: PHASE 1						PKG		
33.120	PKG 1 REF: AMM 33-51-01	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
A335003 (s)	INSPECT EMERGENCY LIGHTS, BATTERY BOX AND BATTERIES: PHASE 5						PKG		
33.130	PKG 7,101 REF: AMM 33-51-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B335001 (s)	OPERATIONAL CHECK EMERGENCY LIGHTS: PHASE 1						PKG		
33.140	PKG 1 REF: AMM 33-51-01	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
CHAPTER 34 NAVIGATION									
341001	NO. 1 AIRSPEED INDICATOR								
34.190	C661063-0107 W20255 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C				12-AUG-2013 4821:24 3548		
341001	NO. 2 AIRSPEED INDICATOR								
34.190	C661063-0107 226 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C				20-MAY-2011 4534 3335		
341002	STANDBY ALTIMETER								
34.750	570-24929-013 1585 REF: AMM 34-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-JUL-2007 3709 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341005	S262 MACH/AIRSPEED WARNING SWITCH								
34.170	D45C31 933 REF: AMM 34-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			18-JAN-2011 4515 3326		
341006	PITOT PRESSURE SWITCH								
34.751	D37C15 SN-UNKNOWN REF: AMM 34-11-10	MOS HRS/MSC AFL	O/C	TSN:0			07-JUL-2004 2865		
341010	ANGLE OF ATTACK INDICATOR								
34.050	C11605-1 350 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
341010	RIGHT INDICATOR-AOA								
	C11605-1 348 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
341011	ANGLE OF ATTACK STALL WARNING COMPUTER								
34.070	C11606-8 133 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSO:0			16-JUN-1998 1203		
341013	ANGLE OF ATTACK TRANSMITTER								
34.080	1703-15 383 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
341014	ANGLE OF ATTACK INDEXER								
34.060	965-0113-008 1012 REF: AMM 34-13-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
341015	PILOT RADIO ALTIMETER ALT-55B INDICATOR								
34.100	622-2937-009 2758 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341020	VNAV CONTROL 4020571-904 91072449 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				24-MAR-2014 4838 3562		
341022	OAT INDICATOR C668510-0401 2576 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
341035	ANGLE OF ATTACK HEAT MONITOR- 1703-147-2 348 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342001	MAGNETIC COMPASS C660501-0301 SN-UNKNOWN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342023	RADAR CONTROLLER 7008471-803 92091641 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342041	NO. 1 FLIGHT DIRECTOR COMPUTER 4018369-905 90046116 REF:	MOS HRS/MSC AFL	O/C				01-JUL-2014 4859:54 3580		
342041	NO. 2 FLIGHT DIRECTOR COMPUTER 4018369-905 79121511 REF:	MOS HRS/MSC AFL	O/C				01-JUL-2014 4859:54 3580		
342042	NO. 1 MODE FLIGHT DIRECTOR SELECTOR 4020570-905 89101778 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSO:0			11-JUN-2008 4133		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342042	NO. 2 MODE FLIGHT DIRECTOR SELECTOR 4020570-905 92112155 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342043	NO. 1 VERTICAL FLIGHT DIRECTOR GYRO 7000622-901 93027284 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:1002			08-JUL-2003 2498		
342043	NO. 2 VERTICAL FLIGHT DIRECTOR GYRO 7000622-901 87075957 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-JUN-2011 4544:42 3343		
342044	NO. 1 RATE OF TURN GYRO 7007453-903 92082892 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342044	NO. 2 RATE OF TURN GYRO 7007453-903 92083179 REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342049	NO. 1 DIRECTIONAL GYRO 4020577-3 92105284 REF: AMM 34-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342049	NO. 2 DIRECTIONAL GYRO 4020577-3 92035177 REF: AMM 34-21-05	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			03-JUL-2014 4861:54 3584		
342050	NO. 1 FLUX DETECTOR 2594484 92010016 REF: AMM 34-21-16	MOS HRS/MSC AFL	O/C	TSO:1770			25-SEP-2006 3528		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342050	NO. 2 FLUX DETECTOR								
34.390	2594484 87044717 REF: AMM 34-21-16	MOS HRS/MSC AFL	O/C				18-MAR-2014 4838 3562		
342052	REMOTE COMPENSATOR								
34.230	2593379-1 92110894 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342063	NO. 1 REMOTE COURSE CONTROL								
34.260	4026206-973 92114868 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342064	STANDBY GYRO POWER SUPPLY								
34.720	501-1228-03 1176 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			27-NOV-2018 5196:23 3898		
342065	STANDBY GYRO								
34.380	501-1197-05 4711 REF: AMM 34-21-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342066	LEFT BOTTOM EFIS DISPLAY								
34.905	7003430-901 92112873 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342066	LEFT TOP EFIS DISPLAY								
34.905	7003430-901 90112006 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-JUN-2011 4541:36 3341		
342066	MFD 1 EFIS DISPLAY								
34.905	7003430-901 90102816 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-JUN-2011 4541:36 3341		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342066	RIGHT BOTTOM EFIS DISPLAY 7003430-901 93043013 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:4133			20-JUN-2008 4133		
342066	RIGHT TOP EFIS DISPLAY 7003430-901 90021607 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-JUN-2011 4541:36 3341		
342068	NO. 1 (EFIS) CONTROLLER DISPLAY 7012977-753 92061237 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342068	NO. 2 (EFIS) CONTROLLER DISPLAY 7012977-753 92061240 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342069	MULTIFUNCTION DISPLAY CONTROLLER 7007062-927 90110866 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-JAN-2014 4836:06 3560		
342069	NO. 1 INCLINOMETER 7005400-901 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342069	NO. 2 INCLINOMETER 7005400-901 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342070	NO. 1 EFIS SYMBOL GENERATOR 7011672-667 90010379 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSO:60			12-NOV-2007 3868		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342070	NO. 2 EFIS SYMBOL GENERATOR								
34.787	7011672-667 91090746 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSO:2596			05-JUL-2007 3709		
342071	MFD SYMBOL GENERATOR								
34.789	7011673-667 91050322 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSO:0			19-DEC-2000 1883		
342072	STATIC CONVERTER								
34.330	501-1318-01 3899 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342073	AFIS DATA MANAGEMENT UNIT								
34.470	400-045500-0003 X150 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-MAY-2015 4970:12 3671		
342075	NO. 1 ADAPTER-BRG INTERF								
	622-8613-002 147 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
342075	NO. 2 ADAPTER-BRG INTERF								
	622-8613-002 178 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
344003	PRIMUS 650 RADAR RECEIVER/TRANSMITTER								
34.410	7012640-901 92111056 REF: AMM 34-40-03	MOS HRS/MSC AFL	O/C	TSR:0 TSO:2772 TSR:0 TSR:0			20-MAY-2011 4534 3335		
344021	NO. 1 RADIO MAGNETIC INDICATOR								
34.510	622-2506-008 7482 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344021	NO. 2 RADIO MAGNETIC INDICATOR 622-2506-008 8009 REF: AMM 34-52-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
344022	NO. 2 TRANSCEIVER-RADIO ALT 622-1365-002 5718 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
344022	RADIO ALT TRANSCEIVER 622-2855-001 8389 REF: AMM 34-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
344023	AFT RECEIVER RADIO ALT ANTENNA 622-0954-001 5723 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
344023	FORWARD TRANSMITTER RADIO ALT ANTENNA 622-0954-001 5722 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
344024	GROUND PROXIMITY WARNING SYS COMPUTER 965-1198-005 07456 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C				22-NOV-2011 4600:06 3379		
344025	CONFIGURATION MODULE 050-03621-0000 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2011 0 0		
345004	FORWARD TRANSPONDER ANTENNA DMNI50-2-2 51177 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0			01-SEP-1993 17		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345007	AFT DME ANTENNA								
34.520	DMNI50-2-2 53337 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345007	FORWARD DME ANTENNA								
34.520	DMNI50-2-2 53334 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345010	NO. 1 NAVIGATION ANTENNA								
34.420	DMN4-17-1B 3924 REF: AMM 34-52-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345011	NO. 1 ADF RECEIVER								
34.450	622-7382-101 1970 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345011	NO. 2 ADF RECEIVER								
34.450	622-7382-101 2102 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345012	NO. 1 ADF CONTROL								
34.450	622-6522-005 3231 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C				08-DEC-2014 4900:30 3622		
345012	NO. 2 ADF CONTROL								
34.450	622-6522-005 6968 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSO:0			05-JUL-2007 3709		
345014	NO. 1 ADF ANTENNA								
34.450	622-7383-001 1053 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345014	NO. 2 ADF ANTENNA								
34.450	622-7383-001 1052 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345017	MARKER BEACON ANTENNA								
34.400	DMN27-3 9317 REF: AMM 25-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345018	GLIDESLOPE ANTENNA								
34.400	RGS10-48 2809 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345032	NO. 1 VHF NAV RECEIVER								
34.825	622-6137-201 SN-UNKNOWN REF: AMM 34-52-04	MOS HRS/MSC AFL	O/C	TSO:0			07-JUL-2004 2865		
345032	NO. 2 VHF NAV RECEIVER								
34.825	622-6137-201 17668 REF: AMM 34-52-04	MOS HRS/MSC AFL	O/C	TSO:0			11-MAR-2004 2705		
345033	BOTTOM VHF NAV CONTROL								
34.911	622-6521-013 13237 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345033	VHF NAV CONTROL								
34.911	622-6521-013 13913 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345034	NO. 1 ATC TRANSPONDER								
34.550	066-01143-2101 1105 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	TSO:0			16-AUG-2005 3257		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345034	NO. 2 ATC TRANSPONDER 066-01143-2101 1121 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	TSO:0			16-AUG-2005 3257		
345035	NO. 1 DME INDICATOR 622-7318-001 1207 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			22-OCT-2012 4734:36 3470		
345035	NO. 2 DME INDICATOR 622-7318-001 1GRHW REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C				04-NOV-2013 4827:24 3553		
345036	NO. 1 DME RECEIVER TRANSMITTER 622-6263-003 11892 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345036	NO. 2 DME RECEIVER TRANSMITTER 622-6263-003 11959 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345037	MFD CHECKLIST 7990197-132 92121165 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
345081	(AFIS)CONFIGURATION MODULE 31990-1 11643 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2011 4534 3335		
345081	NO. 1 CONFIGURATION MODULE 31990-1 3411 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345082	NO. 1 GNS/FMS DISPLAY 17960-0204-0002 MM2310 REF: AMM 34-61-03	MOS HRS/MSC AFL	O/C				09-OCT-2015 5008 3714		
345093	GPS ANTENNA 071-01533-0200 SN-UNKNOWN REF: AMM 34-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2011 4534 3335		
346001	TCAS PROCESSOR 066-01146-2221 TPU67B-C41957 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C				06-NOV-2015 4995:48		
346002	BOTTOM TCAS ANTENNA 071-01548-0100 12244 REF: AMM 34-40-05	MOS HRS/MSC AFL	O/C	TSO:0			16-AUG-2005 3257		
346002	TOP TCAS ANTENNA 071-01548-0100 12249 REF: AMM 34-40-05	MOS HRS/MSC AFL	O/C	TSO:0			16-AUG-2005 3257		
346004	CONTROL TCAS 071-01619-0121 41 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSO:0			16-AUG-2005 3257		
346031	NO. 1 TCAS INDICATOR 066-01171-2704 23829 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-MAY-2011 4534 3335		
346031	NO. 2 TCAS INDICATOR 066-01171-2804 29330 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0			16-AUG-2005 3257		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34FO-01 560	0 FUEL WT INCREASE 12,200 LBS FACTORY OPTION 185J FO REF:	MOS HRS/MSC - AFL					17-MAY-1993 0 0		
34FO-02 560	INDEXER-PILOTS ANGLE OF ATTACK FACTORY OPTION 11A FO REF:	MOS HRS/MSC - AFL					17-MAY-1993 0 0		
34FO-05 560	ADF-2/COLLINS ADF462 ONLY W/STD COLLINS FACTORY OPTION 659C FO REF:	MOS HRS/MSC - AFL					17-MAY-1993 0 0		
34FO-08 560/J	DME 2-COLLINS DME 42 ONLY W/STD PACKAGE FACTORY OPTION 681J FO REF:	MOS HRS/MSC - AFL					17-MAY-1993 0 0		
34FO-09 560/X	FM SYS-5TUBE HONEYWL EFIS FACTORY OPTION 685X FO REF:	MOS HRS/MSC - AFL					17-MAY-1993 0 0		
34FO-12 560/K	RADAR-PRIMUS 870 W/MFD FACTORY OPTION 627K FO REF:	MOS HRS/MSC - AFL					17-MAY-1993 0 0		
A341009 (s) 34.600	PERFORM SAFE FLIGHT ANGLE-OF-ATTACK SYSTEM CHECK: PHASE 5 PKG 7,101 REF: AMM 34-13-06	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A341012 (s) 34.610	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES -0001 THRU -0259 CERTIFIED FOR RVSM): PHASE 20 PKG 24 REF: See Workcard	MOS HRS/MSC AFL	24				PKG 24-MAY-2018 5079:30 3802		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A342001 (s) 34.620	INSPECT MAGNETIC COMPASS AND COMPASS CARD: PHASE 5 PKG 7,101 REF: AMM 34-21-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B341002 (s) 34.640	OPERATIONAL TEST TELEDYNE ANGLE-OF-ATTACK SYSTEM: PHASE 5 PKG 7,105 REF: AMM 34-13-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B341003 34.761	CALIBRATION TEST STANDBY ALTIMETER (91.411): PHASE 20 PN PKG 24 SN-UNKNOWN REF: AMM 34-14-00	MOS HRS/MSC AFL	24				24-MAY-2018	24-MAY-2020	
B341005 34.010	LEAK TEST LEFT STATIC SYSTEM (FAR 91.411) AIRPLANES -0001 THRU -0259 NOT CERTIFIED FOR RVSM : PHASE 20 PKG 24 REF: AMM 34-11-00	MOS HRS/MSC AFL	24				24-MAY-2018 5079:30 3802	24-MAY-2020	
B341005 34.010	LEAK TEST RIGHT STATIC SYSTEM (FAR 91.411) AIRPLANES -0001 THRU -0259 NOT CERTIFIED FOR RVSM : PHASE 20 PKG 24 REF: AMM 34-11-00	MOS HRS/MSC AFL	24				24-MAY-2018 5079:30 3802	24-MAY-2020	
B341011 (s) 34.941	CALIBRATION TEST NO. 1 AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0001 THRU -0259 CERTIFIED FOR RVSM: PHASE 20 7000700-948 PKG 24 91094926 REF: AMM 34-11-07	MOS HRS/MSC AFL	24				24-MAY-2018		
B341011 (s) 34.941	CALIBRATION TEST NO. 2 AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0001 THRU -0259 CERTIFIED FOR RVSM: PHASE 20 PN PKG 24 SN-UNKNOWN REF: AMM 34-11-07	MOS HRS/MSC AFL	24				24-MAY-2018		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B341301 (s)	OPERATIONAL CHECK TELEDYNE PRIMARY ANGLE OF ATTACK FLAP POSITION POTENIOMETER ADJUSTMENT: PHASE 5						PKG		
34.879	PKG 7,101 REF: AMM 34-13-03	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B341302 (s)	OPERATIONAL CHECK TELEDYNE SECONDARY ANGLE OF ATTACK FLAP POSITION POTENIOMETER ADJUSTMENT: PHASE 5						PKG		
34.879	PKG 7,101 REF: AMM 34-13-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B341303 (s)	PERFORM TELEDYNE ANGLE-OF-ATTACK SYSTEM FLIGHT CALIBRATION: PHASE 5						PKG		
34.881	PKG 7,101 REF: AMM 34-13-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B341304 (s)	OPERATIONAL CHECK SAFE FLIGHT ANGLE OF ATTACK SYSTEM CHECK(AIRPLANES -0056 THRU -0538) : PHASE 5						PKG		
34.881	PKG 7,101 REF: AMM 34-13-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B341308 (s)	OPERATIONAL CHECK SAFE FLIGHT ANGLE OF ATTACK SYSTEM ICE MODE CHECK(AIRPLANES -0056 THRU -0538): PHASE 2						PKG		
34.885	PKG 2,4,15 REF: AMM 34-13-02	MOS HRS/MSC AFL	150				08-AUG-2018 5114:38 3835		
B341310 (s)	PERFORM SAFE FLIGHT ANGLE OF ATTACK SYSTEM FLIGHT CALIBRATION(AIRPLANES -0056 THRU -0538): PHASE 5						PKG		
34.680	PKG 7,101 REF: AMM 34-13-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B342001 (s)	OPERATIONAL TEST MAGNETIC COMPASS SYSTEMS AND ADF BEARING: PHASE 5						PKG		
34.710	C660501-0301 PKG 7,105 SN-UNKNOWN REF: AMM 34-21-05	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B342003 (s) 34.370	CAPACITY TEST PS-835 EMERGENCY POWER SUPPLY : PHASE 18 PN PKG 22 SN-UNKNOWN REF: AMM 34-21-12	MOS HRS/MSC AFL	12				PKG 27-NOV-2018 5196:23 3898		
B342004 (s) 34.370	PERIODIC CHECK PS-835 EMERGENCY POWER SUPPLY : PHASE 11 PN PKG 16 SN-UNKNOWN REF: AMM 34-21-12	MOS HRS/MSC AFL	3				PKG 27-NOV-2018 5196:23 3898		
B345001 34.550	CALIBRATION TEST NO. 1 ATC TRANSPONDER (FAR 91.413): PHASE 20 066-01143-2101 PKG 24 1105 REF: AMM 34-54-00	MOS HRS/MSC AFL	24				24-MAY-2018	24-MAY-2020	
B345001 34.550	CALIBRATION TEST NO. 2 ATC TRANSPONDER (FAR 91.413): PHASE 20 066-01143-2101 PKG 24 1121 REF: AMM 34-54-00	MOS HRS/MSC AFL	24				24-MAY-2018	24-MAY-2020	
CHAPTER 35 OXYGEN									
350004 35.010	HYDROSTATIC TEST OXYGEN CYLINDER 895-20077 ALT281-18575 REF:	MOS HRS/MSC AFL	60				21-AUG-2015	21-AUG-2020	
351001 35.020	OXYGEN PRESSURE GAUGE C668512-0101 560 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
351002 35.100	OXYGEN PRESSURE SWITCH P24031 1119 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
351004 35.030	COPILOT OXYGEN MASK 174045-15 50441 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351004	PILOT OXYGEN MASK 174045-15 50384 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0			03-JUN-2011 4541:36 3341		
351005	OXYGEN SUPPLY REGULATOR 172170-01 407 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
351006	OXYGEN CYLINDER 895-20077 ALT281-18575 REF:	MOS HRS/MSC AFL	180				21-SEP-2017	01-FEB-2022 M	
A351001 (s)	INSPECT OXYGEN SYSTEM: PHASE 5 PKG 7,108 REF: AMM 35-00-05	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A351007 (s)	INSPECT PASSENGER OXYGEN MASKS: PHASE 18 PKG 22 REF: AMM 35-20-00	MOS HRS/MSC AFL	12				PKG 27-NOV-2018 5196:23 3898		
B350006 (s)	FUNCTIONAL TEST OXYGEN SYSTEM, FLOW FUSES AND SHUTTLE VALVES: PHASE 5 PKG 7,108 REF: AMM 35-10-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B351002 (s)	FUNCTIONAL TEST OXYGEN SYSTEM: PHASE 5 PKG 7,108 REF: AMM 35-10-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
B351003 (s)	OPERATIONAL CHECK CREW OXYGEN MASK INSPECTION, FLOW CHECK AND MICROPHONE: PHASE 5 PKG 7,107 REF: AMM 35-10-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		

CHAPTER 36

PNEUMATIC



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361003	PNEUMATIC REGULATOR								
36.100	38E85-5C RF1977 REF: AMM 36-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
361008	NO. 1 VALVE CHECK								
36.080	1553-00-18 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0			18-JUL-1996 627		
361008	NO. 2 VALVE CHECK								
36.080	1553-00-18 3387 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			07-JUL-2009 4511		
A361004 (s)	INSPECT BLEED AIR CHECK VALVES: PHASE 3						PKG		
36.030	PKG 3 REF: AMM 36-11-00	MOS HRS/MSC AFL	24 300				03-OCT-2017		
A361005 (s)	LEAK CHECK ENGINE BLEED AIR BELLOWS: PHASE 4						PKG		
36.040	PKG 4 REF: AMM 36-10-00	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
A361101 (s)	LEAK CHECK TAILCONE BLEED AIR LINES: PHASE 4						PKG		
36.160	PKG 4 REF: AMM 36-11-00	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
A361102 (s)	DETAILED INSPECTION TAILCONE BLEED AIR LINE PERI-SEALS: PHASE 4						PKG		
36.160	PKG 4 REF: AMM 36-11-01	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
D361100 (s)	REPLACEMENT OF SERVICE AIR SYSTEM PERI-SEAL						PKG		
36.170	PKG 7,106 REF: AMM 36-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		

CHAPTER 37 VACUUM



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D371001 (s)	CLEAN/REPLACE VACUUM REGULATOR (PRESSURE LINE): PHASE 5						PKG		
37.010	PKG 7,106 REF: AMM 37-11-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
CHAPTER 38 WATER/WASTE									
383002	MOTOR AND PUMP TOILET								
38.010	17200-382 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
B383001 (s)	OPERATIONAL CHECK REFRESHMENT CENTER DRAINS: PHASE 5						PKG		
38.020	PKG 7,110 REF: AMM 38-30-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
CHAPTER 51 STD PRACTICES AND STRUCT-GENRL									
A510001 (s)	INSPECT EXTERIOR MOISTURE DRAIN HOLES: PHASE 1						PKG		
51.010	PKG 1 REF: AMM 51-10-00	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
A510002 (s)	INSPECT EXTERIOR: PHASE 6						PKG		
51.020	PKG 8 REF: AMM 51-10-00	DAYS HRS/MSC AFL	O/C				27-NOV-2017		
CHAPTER 52 DOORS									
521001	CABIN DOOR SEAL								
52.010	S15501-1 SN-UNKNOWN REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2011 4534 3335		
521003	SECONDARY DOOR SEAL								
52.180	5511230-96 SN-UNKNOWN REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2011 4534 3335		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A521001 (s)	INSPECT STANDARD CABIN DOOR INFLATABLE SEAL: PHASE 5						PKG		
52.030	PKG 7,101	MOS	36				12-DEC-2017		
	REF: AMM 52-10-01	HRS/MSC	1200				5022:17		
		AFL					3749		
A521003 (s)	INSPECT STANDARD CABIN DOOR: PHASE 5						PKG		
52.040	PKG 7,101	MOS	36				12-DEC-2017		
	REF: AMM 52-10-01	HRS/MSC	1200				5022:17		
		AFL					3749		
A521004 (s)	INSPECT STANDARD CABIN DOOR LOCKING PINS: PHASE 13						PKG		
52.050	PKG 17	MOS					18-MAR-2014		
	REF: AMM 52-10-02	HRS/MSC	5000				4833:25		
		AFL					3558		
A521005 (s)	INSPECT STANDARD CABIN DOOR LOCKING COMPONENTS BEARING PLATES: PHASE 16						PKG		
52.060	PKG 20	MOS		TSI:0			17-MAY-1993		
	REF: AMM 52-10-02	HRS/MSC	10000	TSI:0			0		
		AFL		TSI:0			0		
A521006 (s)	INSPECT OPTIONAL ROTARY LATCHING CARGO CABIN DOOR: PHASE 1						PKG		
52.070	PKG 1	MOS	24				16-MAR-2018		
	REF: AMM 52-10-04	HRS/MSC	300				5027		
		AFL					3753		
A521007 (s)	VISUAL INSPECTION OPTIONAL PIN LATCHING CARGO CABIN DOOR: PHASE 5						PKG		
52.080	PKG 7,101	MOS	36				12-DEC-2017		
	REF: AMM 52-10-05	HRS/MSC	1200				5022:17		
		AFL					3749		
A521008 (s)	INSPECT ENTRANCE DOOR SECONDARY SEAL: PHASE 1						PKG		
52.090	PKG 1,3,15	MOS					08-AUG-2018		
	REF: AMM 52-10-01	HRS/MSC	150				5114:38		
		AFL					3835		
A522002 (s)	INSPECT EMERGENCY EXIT DOOR: PHASE 5						PKG		
52.100	PKG 7,100	MOS	36				12-DEC-2017		
	REF: AMM 52-20-01	HRS/MSC	1200				5022:17		
		AFL					3749		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A523001 (s)	INSPECT NOSE BAGGAGE DOOR AND LATCHES: PHASE 5						PKG		
52.110	PKG 7,100 REF: AMM 52-30-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A523002 (s)	INSPECT TAILCONE DOORS: PHASE 5						PKG		
52.120	PKG 7,105 REF: AMM 52-30-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A526001 (s)	INSPECT STANDARD CABIN DOOR STEP: PHASE 1						PKG		
52.130	PKG 1 REF: AMM 52-60-01	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
A526002 (s)	INSPECT STANDARD CABIN DOOR COMPOSITE STEP: PHASE 1						PKG		
52.140	PKG 1 REF: AMM 52-60-01	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
B521008 (s)	OPERATIONAL TEST CABIN ENTRANCE DOOR SECONDARY SEAL: PHASE 5						PKG		
52.150	PKG 7,101 REF: AMM 21-30-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B527001 (s)	INSPECT/OPERATIONAL CHECK DOOR WARNING SYSTEM: PHASE 1						PKG		
52.160	PKG 1 REF: AMM 52-70-01	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
C521002 (s)	LUBRICATE CABIN DOOR HINGE: PHASE 5						PKG		
52.170	PKG 7,101 REF: AMM 52-10-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
CHAPTER 53	FUSELAGE								
531001	LEFT NOSE LANDING GEAR TRUNNION SUPPORT								
53.080	6613056-3 SN-UNKNOWN REF: AMM 53-10-00	MOS HRS/MSC AFL					17-MAY-1993 0		
LIFE LIMIT			12050	TSN:0			0	12050	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
531001	RIGHT NOSE LANDING GEAR TRUNNION SUPPORT 6613056-4 SN-UNKNOWN	MOS HRS/MSC AFL					17-MAY-1993 0 0		
53.080	REF: AMM 53-10-00		12050	TSN:0					12050
531202	NOSE LANDING GEAR ACTUATOR FITTING 6511105-1 SN-UNKNOWN	MOS HRS/MSC AFL					17-MAY-1993 0 0		
53.070	REF: GENERIC NO REF		23500	TSN:0					23500
A530001 (s)	INSPECT NOSE LANDING GEAR WHEEL WELL GENERAL VISUAL (CORROSION INSPECTION): PHASE 18 PKG 22	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
A530002 (s)	NOSE LANDING GEAR WHEEL WELL GENERAL VISUAL INSPECTION (CORROSION INSPECTION): PHASE 64 PKG 503	MOS HRS/MSC AFL	6				27-NOV-2018 5196:23 3898		
A531001 (s)	INSPECT FORWARD SIDE OF PRESSURE BULKHEAD: PHASE 5 PKG 7,100	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
53.140	REF: AMM 53-10-00								
A531002 (s)	INSPECT UNDERFLOOR: PHASE 5 PKG 7,111	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
53.150	REF: AMM 53-20-08								
A531003 (s)	GENERAL INSPECTION AFT PRESSURE BULKHEAD TAILCONE: PHASE 5 PKG 7,105	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
53.160	REF: AMM 53-20-04								
A531004 (s)	INSPECT FRONT AND REAR SPAR CARRY-THRU: PHASE 5 PKG 7,111	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
53.170	REF: AMM 53-10-09								



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531006 (s)	INSPECT EMERGENCY EXIT DOOR FRAME: PHASE MC						PKG		
	PKG 70	MOS		TSI:0			03-JUL-2009		
53.190		HRS/MSC	1456	TSI:0			4511		
AIRWORTHINESS	REF: AMM 53-10-09	AFL		TSI:0					
A531007 (s)	INSPECT WINDSHIELD, COCKPIT SIDE WINDOW AND CABIN WINDOW FRAMES: PHASE MI						PKG		
	PKG 76	MOS					01-JUL-2015		
53.200		HRS/MSC	5130				4957:52		
AIRWORTHINESS	REF: AMM 53-30-00	AFL					3681		
A531008 (s)	INSPECT FUSELAGE INTERIOR CABIN STRUCTURE: PHASE 1						PKG		
	PKG 1	MOS	24				16-MAR-2018		
53.210		HRS/MSC	300				5027		
	REF: AMM 53-10-09	AFL					3753		
A531009 (s)	INSPECT CABIN STRUCTURE: PHASE 17						PKG		
	PKG 21	MOS		TSI:0			17-MAY-1993		
53.220		HRS/MSC	10000	TSI:0			0		
	REF: AMM 53-10-00	AFL		TSI:0			0		
A531010 (s)	INSPECT OPTIONAL CARGO DOOR AND DOOR FRAME: PHASE 5						PKG		
	PKG 7	MOS	36				12-DEC-2017		
53.230		HRS/MSC	1200				5022:17		
	REF: AMM 53-10-09	AFL					3749		
A531011 (s)	INSPECT MAIN CARRY-THRU TO WING SPAR LUGS: PHASE 67						PKG		
	PKG 504	MOS					27-NOV-2013		
53.240		HRS/MSC	1200				4822:47		
	REF: AMM 53-10-00	AFL					3550		
A531012 (s)	INSPECT CABIN DOOR THRESHOLD: PHASE 1						PKG		
	PKG 1	MOS	24				16-MAR-2018		
53.250		HRS/MSC	300				5027		
	REF: AMM 53-10-09	AFL					3753		
A531013 (s)	INSPECT FORWARD PRESSURE BULKHEAD ATTACH ANGLES: PHASE MK						PKG		
	PKG 78	MOS		TSI:0			17-MAY-1993		
53.260		HRS/MSC	6725	TSI:0			0		
AIRWORTHINESS	REF: AMM 53-10-00	AFL		TSI:0			0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531014 (s)	INSPECT AFT PRESSURE BULKHEAD ATTACH ANGLES: PHASE MK						PKG		
53.270	PKG 78	MOS		TSI:0			17-MAY-1993		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC AFL	6725	TSI:0 TSI:0			0 0		
A531015 (s)	INSPECT AFT PRESSURE BULKHEAD WEB: PHASE 34						PKG		
53.280	PKG 48	MOS		TSI:0			17-MAY-1993		
	REF: AMM 53-10-04	HRS/MSC AFL	6725	TSI:0 TSI:0			0 0		
A531016 (s)	INSPECT CABIN DOORFRAME: PHASE 5						PKG		
53.290	PKG 7,103	MOS	36				12-DEC-2017		
	REF: AMM 53-10-00	HRS/MSC AFL	1200				5022:17 3749		
A531017 (s)	INSPECT MAIN SPAR CARRY-THRU ASSEMBLY: PHASE 14						PKG		
53.300	PKG 18	MOS		TSI:0			17-MAY-1993		
	REF: AMM 53-10-09	HRS/MSC AFL	12000	TSI:0 TSI:0			0 0		
A531019 (s)	INSPECT WING ATTACH BOLT AND LUG: PHASE 5						PKG		
53.310	PKG 7,109	MOS	36				12-DEC-2017		
	REF: AMM 53-10-09	HRS/MSC AFL	1200				5022:17 3749		
A531020 (s)	INSPECT FORWARD SIDE OF FORWARD PRESSURE BULKHEAD WEB: PHASE ME						PKG		
53.320	PKG 72	MOS					21-FEB-2012		
AIRWORTHINESS	REF: AMM 53-10-00	HRS/MSC AFL	4450				4621:54 3396		
A531021 (s)	INSPECT AFT SIDE OF AFT PRESSURE BULKHEAD WEB: PHASE ME						PKG		
53.330	PKG 72	MOS					21-FEB-2012		
AIRWORTHINESS	REF: AMM 53-10-04	HRS/MSC AFL	4450				4621:54 3396		
A531023 (s)	INSPECT CABIN DOOR FRAME (AIRPLANES -0046 AND ON): PHASE MF						PKG		
53.460	PKG 73	MOS					23-JAN-2013		
AIRWORTHINESS	REF: AMM 53-10-10	HRS/MSC AFL	5000				4749:24 3482		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A531037 (s) 53.350	INSPECT STUB WING SHEAR ATTACH FITTING BOLT: PHASE 5 PKG 7,109 REF: AMM 53-10-02	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A532001 (s) 53.360	INSPECT CONTROL PEDESTAL AREA: PHASE 5 PKG 7,102 REF: AMM 53-20-02	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A532002 (s) 53.370	INSPECT NOSE GEAR WHEEL WELL: PHASE 5 PKG 7,103 REF: AMM 53-10-09	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A532003 (s) 53.380	INSPECT AFT CABIN UNDERFLOOR FOR CORROSION: PHASE 18 PKG 22 REF: AMM 53-10-09	MOS HRS/MSC AFL	12				PKG 27-NOV-2018 5196:23 3898		
A533001 (s) 53.390 AIRWORTHINESS	INSPECT FUSELAGE EXTERIOR SKIN: PHASE MD PKG 71 REF: AMM 53-30-00	MOS HRS/MSC AFL	2523	TSI:0 TSI:0 TSI:0			PKG 03-JUL-2009 4511		
A533003 (s) 53.400 AIRWORTHINESS	INSPECT CABIN LOWER SKIN LONGITUDINAL SPLICE: PHASE MJ PKG 77 REF: AMM 53-30-00	MOS HRS/MSC AFL	5900	TSI:0 TSI:0 TSI:0			PKG 17-MAY-1993 0 0		
A533006 (s) 53.410	INSPECT FUSELAGE EXTERIOR SKIN CORROSION: PHASE 5 PKG 7,100 REF: AMM 53-30-00	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A533010 (s) 53.420	EDDY CURRENT INSPECTION FUSELAGE SKIN JOINT: PHASE 49 PKG 57 REF: AMM 53-30-00	MOS HRS/MSC AFL	36 1200				PKG 14-MAY-2019 5211 3911		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A535001 (s)	INSPECT NOSE CAP (RADOME): PHASE 5						PKG		
53.430	PKG 7,100 REF: AMM 53-50-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A535002 (s)	INSPECT STRINGER ASSEMBLY: PHASE 5						PKG		
53.440	PKG 7,107 REF: AMM 53-50-10	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A553001 (s)	EXTERNAL INSPECTION VERTICAL STABILIZER: PHASE 2						PKG		
55.030	PKG 2 REF: AMM 55-30-01	MOS HRS/MSC AFL	24 300				16-MAR-2018		
B535001 (s)	CHECK RADOME: PHASE 1						PKG		
53.450	PKG 1 REF: AMM 53-50-00	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
CHAPTER 54	NACELLES/PYLONS								
541001	LEFT INLET ASSEMBLY								
54.010	5552250-119 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSO:0			05-JUL-1994 225		
541001	RIGHT INLET ASSEMBLY								
54.010	6595120-2W SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSO:0			29-OCT-1994 272		
A541001 (s)	INSPECT ENGINE NACELLE, PYLON AND FIREWALL: PHASE 5						PKG		
54.020	PKG 7,107 REF: AMM 54-50-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A541002 (s)	INSPECT ENGINE SUPPORT STRUCTURES: PHASE 16						PKG		
54.030	PKG 20 REF: AMM 54-50-01	MOS HRS/MSC AFL	10000	TSI:0 TSI:0 TSI:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 55	STABILIZERS								
A551001 (s)	EXTERNAL INSPECTION HORIZONTAL STABILIZER: PHASE 2						PKG		
55.010	PKG 2 REF: AMM 55-10-01	MOS HRS/MSC AFL	24 300				16-MAR-2018		
A551002 (s)	INSPECT VERTICAL STABILIZIER AFT EDGE: PHASE 2						PKG		
55.020	PKG 2 REF: AMM 55-30-01	MOS HRS/MSC AFL	24 300				16-MAR-2018		
A551003 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF HORIZONTAL STABILIZER AFT SPAR AREA: PHASE 64						PKG		
	PKG 503 REF: AMM 55-10-01	MOS HRS/MSC AFL	6				27-NOV-2018 5196:23 3898		
A551004 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF VERTICAL STABILIZER AFT SPAR ASSEMBLY: PHASE 64						PKG		
	PKG 503 REF: AMM 55-30-01	MOS HRS/MSC AFL	6				27-NOV-2018 5196:23 3898		
A551005 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF HORIZONTAL STABILIZER AFT SPAR AREA: PHASE 18						PKG		
	PKG 22 REF: AMM 55-10-01	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
A551006 (s)	BORESCOPE INSPECTION OF HORIZONTAL STABILIZER RIB LOCATION: PHASE 66						PKG		
	PKG 502 REF: AMM 55-10-01	MOS HRS/MSC AFL	6000				27-NOV-2017 5022:17 3749		
A553003 (s)	INSPECT VERTICAL STABILIZIER FORWARD SPAR CAP STRAP: PHASE 15						PKG		
55.050	PKG 19 REF: AMM 55-30-01	MOS HRS/MSC AFL	10000	TSI:0 TSI:0 TSI:0			17-MAY-1993 0 0		
A553005 (s)	INSPECT VERTICAL STABILIZER AFT SPAR FLANGE: PHASE 15						PKG		
55.040	PKG 19 REF: AMM 55-30-01	MOS HRS/MSC AFL	10000				17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A553006 (s) 55.070	INTERNAL INSPECTION VERTICAL STABILIZER: PHASE 5 PKG 7,107 REF: AMM 55-30-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
A553007 (s) 55.060	INSPECT VERTICAL STABILIZER AFT SPAR: PHASE 15 PKG 19 REF: AMM 55-30-01	MOS HRS/MSC AFL	10000	TSI:0 TSI:0 TSI:0			PKG 17-MAY-1993 0 0		
A553008 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF VERTICAL STABILIZER AFT SPAR ASSEMBLY: PHASE 18 PKG 22 REF: AMM 55-30-01	MOS HRS/MSC AFL	12				PKG 27-NOV-2018 5196:23 3898		
A555001 (s) 55.080	INTERNAL INSPECTION HORIZONTAL STABILIZER: PHASE 5 PKG 7,107 REF: AMM 55-10-01	MOS HRS/MSC AFL	36 1200				PKG 12-DEC-2017 5022:17 3749		
CHAPTER 56	WINDOWS								
561001 56.010	NO. 1 LEFTHAND MAIN WINDSHIELD ASSY, (LH) E149000-9 2327 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
561002 56.010	NO. 2 RIGHTHAND MAIN WINDSHIELD ASSY, (RH) E149000-10 2216 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
561003 56.015	FOUL WEATHER WINDOW 5511275-7 SN-UNKNOWN REF: AMM 56-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
561005 56.015	LEFT INBOARD PILOTS INNER WINDOW 5511285-5 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561005	LEFT OUTBOARD PILOTS OUTER WINDOW								
56.020	5511285-3 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
561005	RIGHT INBOARD CO-PILOTS INNER WINDOW								
56.015	5511285-6 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
561005	RIGHT OUTBOARD CO-PILOTS OUTER WINDOW								
56.020	5511285-78 NSN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0			24-JUN-2008 4133		
562001	L1 CABIN DOOR WINDOW								
56.025	5512207-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	L2 CABIN WINDOW								
56.030	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	L3 CABIN WINDOW								
56.040	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	L4 CABIN WINDOW								
56.050	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	L5 CABIN WINDOW								
56.060	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562001	L6 CABIN WINDOW								
56.070	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	L7 CABIN WINDOW								
56.080	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	R 7 CABIN WINDOW								
56.080	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	R1 EMERGENCY DOOR WINDOW								
56.025	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	R2 CABIN WINDOW								
56.030	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	R3 CABIN WINDOW								
56.040	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	R4 CABIN WINDOW								
56.050	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
562001	R5 CABIN WINDOW								
56.060	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562001	R6 CABIN WINDOW								
56.070	5511260-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
A561001 (s)	INSPECT AIRPLANE WINDOWS: PHASE 1						PKG		
56.100	PKG 1 REF: AMM 56-10-00	MOS HRS/MSC AFL	24 300				16-MAR-2018 5027 3753		
A561002 (s)	PRISM CHECK WINDSHIELD AND FLIGHT COMPARTMENT SIDE WINDOWS: PHASE 49						PKG		
56.110	PKG 57 REF: AMM 56-10-00	MOS HRS/MSC AFL	36 1200				14-MAY-2019 5211 3911		
A561004 (s)	PERFORM RIGHT INBOARD CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION : PHASE 59						PKG		
56.130	5511285-6 PKG 112 SN-UNKNOWN REF: AMM 56-10-00	MOS HRS/MSC AFL	A/R				08-AUG-2018 5114:38 3835		
A561004 (s)	PERFORM RIGHT OUTBOARD CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION : PHASE 59						PKG		
56.130	5511285-78 PKG 112 NSN REF: AMM 56-10-00	MOS HRS/MSC AFL	A/R				08-AUG-2018 5114:38 3835		
CHAPTER 57 WINGS									
572001	LEFT AFT MLG TRUNNION FITTING ASSEMBLY								
57.010	5522710-15 SN-UNKNOWN REF:	MOS HRS/MSC AFL	25800	TSN:0 TSN:0			17-MAY-1993 0 0		25800
572001	LEFT FORWARD MLG TRUNNION FITTING ASSEMBLY								
57.030	6522057-5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	25800	TSN:0			17-MAY-1993 0 0		25800
572001	RIGHT AFT MLG TRUNNION FITTING ASSEMBLY								
57.020	5522710-15 SN-UNKNOWN REF:	MOS HRS/MSC AFL	25800	TSN:0			17-MAY-1993 0 0		25800



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
572001	RIGHT FORWARD MLG TRUNNION FITTING ASSEMBLY 6522057-6 SN-UNKNOWN	MOS HRS/MSC AFL	25800	TSN:0			17-MAY-1993 0 0		25800
57.040 LIFE LIMIT	REF:								
574003	LEFT MLG SIDE BRACE SUPPORT FITTING 6522047-1 SN-UNKNOWN	MOS HRS/MSC AFL	25800	TSN:0 TSN:0			17-MAY-1993 0 0		25800
57.050 LIFE LIMIT	REF:								
574004	RIGHT MLG SIDE BRACE SUPPORT FITTING 6522047-2 SN-UNKNOWN	MOS HRS/MSC AFL	25800	TSN:0 TSN:0			17-MAY-1993 0 0		25800
57.060 LIFE LIMIT	REF:								
A570001 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF MAIN LANDING GEAR WHEEL WELL: PHASE 64 PKG 503	MOS HRS/MSC AFL	6				27-NOV-2018 5196:23 3898		
	REF: AMM 57-00-00								
A570002 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF MAIN LANDING GEAR WHEEL WELL: PHASE 18 PKG 22	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
	REF: AMM 57-00-00								
A570003 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF AFT WING SPAR AREA: PHASE 64 PKG 503	MOS HRS/MSC AFL	6				27-NOV-2018 5196:23 3898		
	REF: AMM 57-00-00								
A570004 (s)	GENERAL VISUAL INSPECTION (CORROSION INSPECTION) OF AFT WING SPAR AREA: PHASE 18 PKG 22	MOS HRS/MSC AFL	12				27-NOV-2018 5196:23 3898		
	REF: AMM 57-00-00								
A571004 (s)	INSPECT WING LOWER LEADING EDGE OUTBOARD OF WS 91.073: PHASE 5 PKG 7,109	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
57.090	REF: AMM 57-00-00								



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A571005 (s)	INSPECT INBOARD LOWER MAIN WING SPAR CAP AND STRAP INSPECTION (AIRPLANES -0001 THRU -0538): PHASE 61						PKG		
57.150	PKG 246 REF: AMM 57-00-00	MOS HRS/MSC AFL	13200	TSI:0 TSI:0 TSI:0			17-MAY-1993 0 0		
A571007 (s)	INSPECT OUTBOARD LOWER MAIN WING SPAR CAP AND STRAP: PHASE 62						PKG		
57.170	PKG 247 REF: AMM 57-00-00	MOS HRS/MSC AFL	15600	TSI:0 TSI:0 TSI:0			17-MAY-1993 0 0		
A571008 (s)	INSPECT INBOARD LOWER REAR WING SPAR CAP: PHASE 63						PKG		
57.180	PKG 248 REF: AMM 57-00-00	MOS HRS/MSC AFL	15600	TSI:0 TSI:0 TSI:0			17-MAY-1993 0 0		
A571009 (s)	INSPECT OUTBOARD LOWER REAR WING SPAR CAP: PHASE 63						PKG		
57.190	PKG 248 REF: AMM 57-00-00	MOS HRS/MSC AFL	15600	TSI:0 TSI:0 TSI:0			17-MAY-1993 0 0		
A573001 (s)	INSPECT WINGS: PHASE 5						PKG		
57.110	PKG 7,109 REF: AMM 57-00-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
A573003 (s)	INSPECT JACK PADS: PHASE 14						PKG		
57.120	PKG 18 REF: AMM 57-00-00	MOS HRS/MSC AFL	12000	TSI:0 TSI:0 TSI:0			17-MAY-1993 0 0		
A574005 (s)	INSPECT FLAP BELL CRANK ATTACH POINTS: PHASE 2						PKG		
57.130	PKG 2 REF: AMM 57-20-01	MOS HRS/MSC AFL	24 300				16-MAR-2018		
A575001 (s)	INSPECT FLAPS: PHASE 5						PKG		
57.140	PKG 7,109 REF: AMM 57-00-00	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		

CHAPTER 71 POWER PLANT



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712001	LEFT ENGINE AFT ISOLATOR LM420SA6 1612 REF:	MOS HRS/MSC AFL	3500	TSN:0			29-AUG-2006 3493	6993	
712001	RIGHT ENGINE AFT ISOLATOR LM420SA6 1608 REF:	MOS HRS/MSC AFL	3500	TSO:0			29-AUG-2006 3493	6993	
712002	LEFT BOTTOM FORWARD ENGINE ISOLATOR LM420SA5-1 2695 REF:	MOS HRS/MSC AFL	3500	TSO:0			29-AUG-2006 3493	6993	
712002	LEFT TOP FORWARD ENGINE ISOLATOR LM420SA5-1 2401 REF:	MOS HRS/MSC AFL	3500	TSO:0			29-AUG-2006 3493	6993	
712002	RIGHT BOTTOM FORWARD ENGINE ISOLATOR LM420SA5-1 2460 REF:	MOS HRS/MSC AFL	3500	TSO:0			29-AUG-2006 3493	6993	
712002	RIGHT TOP FORWARD ENGINE ISOLATOR LM420SA5-1 2708 REF:	MOS HRS/MSC AFL	3500	TSO:0			29-AUG-2006 3493	6993	
71EN1	NO. 1 ENGINE JT15D-5A 108441 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C	TSO:0			07-SEP-2006 3493		
71EN2	NO. 2 ENGINE JT15D-5A 108445 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C	TSO:0			07-SEP-2006 3493		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A711000 (s)	GENERAL INSPECTION ENGINE: PHASE 4						PKG		
71.050	PKG 4 REF: AMM 71-01-04	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
A711001 (s)	GENERAL INSPECTION ENGINE: PHASE 4						PKG		
71.060	PKG 4 REF: AMM 71-01-05	MOS HRS/MSC AFL	24 300				26-OCT-2017		
A711006 (s)	INSPECT ENGINE INLET INNER AND OUTER DUCT(AIRPLANES -0001 THRU -0538) : PHASE 4						PKG		
71.080	PKG 4 REF: AMM 71-11-00	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
A711007 (s)	INSPECT ENGINE INLET INNER AND OUTER DUCT(AIRPLANES 0539 AND ON): PHASE 4						PKG		
71.110	PKG 4 REF: AMM 71-11-00	MOS HRS/MSC AFL	24 300				26-NOV-2015 5017 3718		

ENGINE NO. 1	Model : JT15D-5A	Serial # 108441	Part # JT15D-5A
710010	NO. 1 ENGINE - OVERHAUL		
		MOS HRS/MSC ENC	3500
	REF: GENERIC NO REF		
			TSI:0 TSI:0
			07-SEP-2006 3493
			(6993) 6993
710020	NO. 1 ENGINE - HOT SECTION INSPECTION		
		MOS HRS/MSC ENC	1750
	REF: EMM 72-00-00		
			11-SEP-2006 3493
			(5243) 5243
710030	NO. 1 ENGINE - TURBINE WASH		
		DAYS HRS/MSC ENC	A/R
	REF: EMM 71-00-00		
			TSI:0 TSI:0 TSI:0
			17-MAY-1993 0 0
724001	NO. 1 ENGINE - COMBUSTOR LINER		
	3119771-01 2H036 REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C
			TSO:0
			07-SEP-2006 3493



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 2 Model : JT15D-5A Serial # 108445 Part # JT15D-5A									
710010	NO. 2 ENGINE - OVERHAUL	MOS		TSI:0			07-SEP-2006		
	REF: GENERIC NO REF	HRS/MSC ENC	3500	TSI:0			3493	(6993) 6993	
710020	NO. 2 ENGINE - HOT SECTION INSPECTION	MOS					11-SEP-2006		
	REF: EMM 72-00-00	HRS/MSC ENC	1750				3493	(5243) 5243	
710030	NO. 2 ENGINE - TURBINE WASH	DAYS		TSI:0			17-MAY-1993		
	REF: EMM 71-00-00	HRS/MSC ENC	A/R	TSI:0			0		
724001	NO. 2 ENGINE - COMBUSTOR LINER	MOS					07-SEP-2006		
	3119771-01 PWV041791JT REF: EMM 72-40-01	HRS/MSC ENC	O/C	TSO:0			3493		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : JT15D-5A Serial # 108441 Part # JT15D-5A									
720010	NO. 1 ENGINE - OIL ANALYSIS	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0			0		
+ 720100	NO. 1 ENGINE - ENGINE OVERTEMPERATURE	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK			TSI:0			0		
+ 720110	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0			0		
	UNSCHEDULED MAINTENANCE CHECK			TSI:0			0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720120	NO. 1 ENGINE - LOSS OF OIL	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720130	NO. 1 ENGINE - ENGINE OVERSPEED	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720140	NO. 1 ENGINE - ENGINE WINDMILLING	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720150	NO. 1 ENGINE - ENGINE IMMERSION IN WATER	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720160	NO. 1 ENGINE - ENGINE DROPPED DURING HANDLING	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720170	NO. 1 ENGINE - LIGHTNING STRIKE	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720180	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720190	NO. 1 ENGINE - HEAVY/HARD LANDING	MOS		TSI:0			17-MAY-1993		
		HRS/MSC	A/R	TSI:0			0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720200	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS		TSI:0			17-MAY-1993		
		HRS/MSC	A/R	TSI:0			0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720210	NO. 1 ENGINE - STARTER GENERATOR FAIL INDICATION	MOS		TSI:0			17-MAY-1993		
		HRS/MSC	A/R	TSI:0			0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	ENC		TSI:0			0		
+ 720220	NO. 1 ENGINE - HYDRAULIC PUMP FAILURE	MOS		TSI:0			17-MAY-1993		
		HRS/MSC	A/R	TSI:0			0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	ENC		TSI:0			0		
721010	NO. 1 ENGINE - ACCESSORY DRIVE GEAR BOX	MOS					07-SEP-2006		
	3031170	HRS/MSC	O/C	TSO:0			3493		
	NSN								
	REF: GENERIC NO REF	ENC							
722001	NO. 1 ENGINE - OIL PUMP	MOS					07-SEP-2006		
	3104289-01	HRS/MSC	O/C	TSO:0			3493		
	15A560								
	REF: EMM 72-60-02	ENC							
722607	NO. 1 ENGINE - LOW COMPRESSOR HUB	MOS					07-SEP-2006		
	3037911	HRS/MSC					3493		
	59A538								
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	TSN:2601			2654		(12053) 12053



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723001	NO. 1 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY 3102814-01 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
723010	NO. 1 ENGINE - INSPECT LP COMPRESSOR BYPASS STATOR RETAINING RIVETS REF: EMM 72-30-01	MOS HRS/MSC ENC	300				11-JUN-2015 4959	(5259) 5259	
723020	NO. 1 ENGINE - LOW BOOST COMPRESSOR HUB 3038312 57A048 REF: GENERIC NO REF	MOS HRS/MSC ENC	14000	TSN:2601			07-SEP-2006 3493 2654	(14053) 14053	
LIFE LIMIT									
723705	NO. 1 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK 3022212 62A182 REF: GENERIC NO REF	MOS HRS/MSC ENC	14000	TSN:2601			07-SEP-2006 3493 2654	(14053) 14053	
LIFE LIMIT									
724006	NO. 1 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK 3036113 61A535 REF: GENERIC NO REF	MOS HRS/MSC ENC	14000	TSN:2601			07-SEP-2006 3493 2654	(14053) 14053	
LIFE LIMIT									
724706	NO. 1 ENGINE - HIGH TURBINE ROTOR DISK 3036411 60A689 REF: GENERIC NO REF	MOS HRS/MSC ENC	10526	TSN:2601			07-SEP-2006 3493 2654	(10579) 10579	
LIFE LIMIT									
724707	NO. 1 ENGINE - HIGH TURBINE BLADES 3029601 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
LIFE LIMIT									
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3039555 5E826 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:2601			07-SEP-2006 3493 2654	(12053) 12053	
LIFE LIMIT									

ENGINE NO. 2 Model : JT15D-5A Serial # 108445 Part # JT15D-5A



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720010	NO. 2 ENGINE - OIL ANALYSIS	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720100	NO. 2 ENGINE - ENGINE OVERTEMPERATURE	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720110	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720120	NO. 2 ENGINE - LOSS OF OIL	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720130	NO. 2 ENGINE - ENGINE OVERSPEED	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720140	NO. 2 ENGINE - ENGINE WINDMILLING	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
	UNSCHEDULED MAINTENANCE CHECK								
+ 720150	NO. 2 ENGINE - ENGINE IMMERSION IN WATER	MOS		TSI:0			17-MAY-1993		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
	UNSCHEDULED MAINTENANCE CHECK								



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720160	NO. 2 ENGINE - ENGINE DROPPED DURING HANDLING	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720170	NO. 2 ENGINE - LIGHTNING STRIKE	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720180	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720190	NO. 2 ENGINE - HEAVY/HARD LANDING	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720200	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720210	NO. 2 ENGINE - STARTER GENERATOR FAIL INDICATION	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		
+ 720220	NO. 2 ENGINE - HYDRAULIC PUMP FAILURE	MOS		TSI:0			17-MAY-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 72-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0			0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721010	NO. 2 ENGINE - ACESSORY DRIVE GEAR BOX 3031170 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
722001	NO. 2 ENGINE - OIL PUMP 3104289-01 15A540 REF: EMM 72-60-02	MOS HRS/MSC ENC	O/C				18-JAN-2011 4515 3379		
722607	NO. 2 ENGINE - LOW COMPRESSOR HUB 3037911 59A543 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:2601			07-SEP-2006 3493 2654	(12053) 12053	
723001	NO. 2 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY 3102814-01 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
723010	NO. 2 ENGINE - INSPECT LP COMPRESSOR BYPASS STATOR RETAINING RIVETS REF: EMM 72-30-01	MOS HRS/MSC ENC	300				11-JUN-2015 4977	(5277) 5277	
723020	NO. 2 ENGINE - LOW BOOST COMPRESSOR HUB 3038312 59A549 REF: GENERIC NO REF	MOS HRS/MSC ENC	14000	TSN:2601			07-SEP-2006 3493 2654	(14053) 14053	
723705	NO. 2 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK 3022212 61A097 REF: GENERIC NO REF	MOS HRS/MSC ENC	14000	TSN:2601			07-SEP-2006 3493 2654	(14053) 14053	
724006	NO. 2 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK 3036113 58A196 REF: GENERIC NO REF	MOS HRS/MSC ENC	14000	TSN:2601			07-SEP-2006 3493 2654	(14053) 14053	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724706	NO. 2 ENGINE - HIGH TURBINE ROTOR DISK 3036411 60A691 REF: GENERIC NO REF	MOS HRS/MSC ENC	10526	TSN:2601			07-SEP-2006 3493 2654	(10579) 10579	
724707	NO. 2 ENGINE - HIGH TURBINE BLADES 3029601 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 3039555 5E825 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:2601			07-SEP-2006 3493 2654	(12053) 12053	
CHAPTER 73 ENGINE FUEL AND CONTROL									
731004	NO. 1 LOW FUEL PRESSURE SWITCH 1103P92 SN-UNKNOWN REF: AMM 28-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
731004	NO. 2 LOW FUEL PRESSURE SWITCH 1103P92 SN-UNKNOWN REF: AMM 28-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
733002	FUEL FLOW/QUANTITY INDICATOR VSDL-OC208E 984A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
733003	NO. 1 FUEL FLOW TRANSMITER 3268014-0201 0119D REF: AMM 73-30-00	MOS HRS/MSC AFL	O/C	TSO:0			12-OCT-2001 2108		
733003	NO. 2 FUEL FLOW TRANSMITER 3268014-0201 1848D REF: AMM 73-30-00	MOS HRS/MSC AFL	O/C	TSO:0			07-JUN-2001 2026		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1	Model : JT15D-5A	Serial # 108441	Part # JT15D-5A						
731001	NO. 1 ENGINE - FUEL PUMP 717101-1 0240 REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731002	NO. 1 ENGINE - FLOW DIVIDER VALVE 26395-2 58 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731005	NO. 1 ENGINE - BLEED CONTROL VALVE 800831-1-001-L7 92100236 REF: EMM 73-10-13	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731006	NO. 1 ENGINE - EFCU WIRING HARNESS 3112429-01 AA1646 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731020	NO. 1 ENGINE - FUEL-OIL COOLER 14438-000 1131 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731025	NO. 1 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER 14438-000 1131 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			17-MAY-1993 0 0	(6993) 6993 M	
731030	NO. 1 ENGINE - MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
731035	NO. 1 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			17-MAY-1993 0 0	(6993) 6993 M	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731060	NO. 1 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5022 3744	27-NOV-2019 (5322) 5322	
731065	NO. 1 ENGINE - BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
731085	NO. 1 ENGINE - SCHEDULE MODULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
731090	NO. 1 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE 26395-2 58 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			17-MAY-1993 0 0	(6993) 6993 M	
732001	NO. 1 ENGINE - FUEL CONTROL UNIT 3244851-10 B29248N REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSO:0			11-APR-2007 3634		
732005	NO. 1 ENGINE - N1 SPEED SENSOR 3100335-01 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
732006	NO. 1 ENGINE - BOTTOM N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
732006	NO. 1 ENGINE - TOP N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732025	NO. 1 ENGINE - VISUAL INSPECT ELECTRONIC CONTROL COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5022 3744	27-NOV-2019 (5322) 5322	
732045	NO. 1 ENGINE - ELECTRONIC BLEED VALVE CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
732050	NO. 1 ENGINE - VISUAL INSPECT ELECTRONIC BLEED VALVE CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5022 3744	27-NOV-2019 (5322) 5322	
732060	NO. 1 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5022 3744	27-NOV-2019 (5322) 5322	
732065	NO. 1 ENGINE - MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
ENGINE NO. 2 Model : JT15D-5A Serial # 108445 Part # JT15D-5A									
731001	NO. 2 ENGINE - FUEL PUMP 717101-1 0486 REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731002	NO. 2 ENGINE - FLOW DIVIDER VALVE 26395-2 15 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731005	NO. 2 ENGINE - BLEED CONTROL VALVE 800831-1-001-L7 C94091230 REF: EMM 73-10-13	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731006	NO. 2 ENGINE - EFCU WIRING HARNESS 3112429-01 AA1647 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731020	NO. 2 ENGINE - FUEL-OIL COOLER D2397-10A JM/PW048322 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
731025	NO. 2 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER D2397-10A JM/PW048322 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			17-MAY-1993 0 0	(6993) 6993 M	
731030	NO. 2 ENGINE - MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
731035	NO. 2 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			17-MAY-1993 0 0	(6993) 6993 M	
731060	NO. 2 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5015	27-NOV-2019 (5315) 5315	
731065	NO. 2 ENGINE - BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
731085	NO. 2 ENGINE - SCHEDULE MODULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731090	NO. 2 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE 26395-2 15 REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	TSI:0 TSI:0			17-MAY-1993 0 0	(6993) 6993 M	
732001	NO. 2 ENGINE - FUEL CONTROL UNIT 3244851-9 B29434 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSO:0			05-JUL-2007 3709		
732005	NO. 2 ENGINE - N1 SPEED SENSOR 3100335-01 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
732006	NO. 2 ENGINE - BOTTOM N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
732006	NO. 2 ENGINE - TOP N2 SPEED SENSOR 3032997 SN-UNKNOWN REF: EMM 73-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
732007	NO. 2 ENGINE - IDLE SOLENOID ASSEMBLY 3242737 38271 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0			05-OCT-1993 36		
732025	NO. 2 ENGINE - VISUAL INSPECT ELECTRONIC CONTROL COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5015	27-NOV-2019 (5315) 5315	
732045	NO. 2 ENGINE - ELECTRONIC BLEED VALVE CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732050	NO. 2 ENGINE - VISUAL INSPECT ELECTRONIC BLEED VALVE CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5015	27-NOV-2019 (5315) 5315	
732060	NO. 2 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5015	27-NOV-2019 (5315) 5315	
732065	NO. 2 ENGINE - MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			17-MAY-1993 0 0		
CHAPTER 74 IGNITION									
B742001 (s)	OPERATIONAL CHECK ENGINE IGNITERS: PHASE 2 PKG 2,4,15 REF: AMM 74-31-00	MOS HRS/MSC AFL	150				PKG 08-AUG-2018 5114:38 3835		
74.010									
ENGINE NO. 1 Model : JT15D-5A Serial # 108441 Part # JT15D-5A									
741001	NO. 1 ENGINE - INBOARD IGNITION EXCITER 9049770-3 99461294 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
741001	NO. 1 ENGINE - OUTBOARD IGNITION EXCITER 9049770-3 99461299 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
741030	NO. 1 ENGINE - VISUAL INSPECT INBOARD IGNITION EXCITER 9049770-3 99461294 REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5022 3744	27-NOV-2019 (5322) 5322	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741030	NO. 1 ENGINE - VISUAL INSPECT OUTBOARD IGNITION EXCITER 9049770-3 99461299 REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5022 3744	27-NOV-2019 (5322) 5322	
742001	NO. 1 ENGINE - INBOARD IGNITER PLUG 9044810-1 NNA13490099 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			18-MAR-2014 4839:30 3693		
742001	NO. 1 ENGINE - OUTBOARD IGNITER PLUG 9044810-1 NNA14040077 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			18-MAR-2014 4839:30 3693		
742002	NO. 1 ENGINE - INBOARD IGNITER PLUG CABLE 53067-21 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
742003	NO. 1 ENGINE - OUTBOARD IGNITER PLUG CABLE 53300-2 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
ENGINE NO. 2 Model : JT15D-5A Serial # 108445 Part # JT15D-5A									
741001	NO. 2 ENGINE - INBOARD IGNITION EXCITER 9049770-3 NNA06288239 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
741001	NO. 2 ENGINE - OUTBOARD IGNITION EXCITER 9049770-3 97433208 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
741030	NO. 2 ENGINE - VISUAL INSPECT INBOARD IGNITION EXCITER 9049770-3 NNA06288239 REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5015	27-NOV-2019 (5315) 5315	



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741030	NO. 2 ENGINE - VISUAL INSPECT OUTBOARD IGNITION EXCITER 9049770-3 97433208 REF: GENERIC NO REF	MOS HRS/MSC ENC	24 300				27-NOV-2017 5015	27-NOV-2019 (5315) 5315	
742001	NO. 2 ENGINE - INBOARD IGNITER PLUG 9044810-1 NNA13490100 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			18-MAR-2014 4836:30 3724		
742001	NO. 2 ENGINE - OUTBOARD IGNITER PLUG 9044810-1 NNA14040081 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			18-MAR-2014 4836:30 3724		
742002	NO. 2 ENGINE - INBOARD IGNITER PLUG CABLE 53067-21 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
742003	NO. 2 ENGINE - OUTBOARD IGNITER PLUG CABLE 53067-38.5 NSN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0			07-SEP-2006 3493		
CHAPTER 76 ENGINE CONTROLS									
761002	SYNCHRONIZER CONTROL BOX 213693 1158313 REF: AMM 76-12-00	MOS HRS/MSC AFL	O/C	TSO:0			21-JUL-2000 1742		
761003	ENGINE SYNC ACTUATOR 5485-066 2484050J REF: AMM 76-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
B761500 (s)	OPERATIONAL CHECK THROTTLE SWITCH: PHASE 2 PKG 2 REF: AMM 76-15-00	MOS HRS/MSC AFL	24 300				PKG 16-MAR-2018		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 77 ENGINE INDICATING									
771004	N1 FAN TACHOMETER INDICATOR								
77.010	VSDL-OC410AE 394 REF: AMM 77-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
771005	N2 TURBINE TACHOMETER INDICATOR								
77.020	DDL-OC110B 410CBA REF: AMM 77-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
772001	INTERSTAGE TURBINE TEMPERATURE (ITT) INDICATOR								
77.030	VSDL-OC419H 842A REF: AMM 77-21-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
CHAPTER 78 EXHAUST									
783001	LEFT ENGINE THRUST REVERSER ASSEMBLY								
78.040	262-0001-501 2868 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783001	RIGHT ENGINE THRUST REVERSER ASSEMBLY								
78.040	262-0001-503 2869 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783002	LEFT ENGINE THRUST REVERSER CONTROL VALVE								
78.050	65680 1862 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783002	RIGHT ENGINE THRUST REVERSER CONTROL VALVE								
78.050	65680 1876 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783003	LEFT ENGINE THRUST REVERSER ISOLATION VALVE								
78.060	13027-4 2453 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783003	RIGHT ENGINE THRUST REVERSER ISOLATION VALVE								
78.060	13027-4 2586 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783005	LEFT THRUST REVERSER UPPER DOOR ASSEMBLY								
78.200	202-0001-503 2868 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783005	RIGHT THRUST REVERSER UPPER DOOR ASSEMBLY								
78.200	202-0001-504 2869 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783006	LEFT THRUST REVERSER LOWER DOOR ASSEMBLY								
78.210	202-0002-505 2868 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783006	RIGHT THRUST REVERSER LOWER DOOR ASSEMBLY								
78.210	202-0002-506 2869 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783007	LEFT THRUST REVERSER UPPER MECHANISM								
78.220	225-0007-513 2868 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783007	RIGHT THRUST REVERSER UPPER MECHANISM								
78.220	225-0007-513 2869 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783008	LEFT THRUST REVERSER LOWER MECHANISM								
78.230	225-0007-515 2868 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783008	RIGHT THRUST REVERSER LOWER MECHANISM								
78.230	225-0007-515 2869 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783009	LEFT THRUST REVERSER FAN DUCT								
78.240	225-0014-507 2868 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783009	RIGHT THRUST REVERSER FAN DUCT								
78.240	225-0014-508 2869 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783010	LEFT INBOARD THRUST REVERSER ACTUATOR								
78.020	62270 3665 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783010	LEFT OUTBOARD THRUST REVERSER ACTUATOR								
78.030	62270 3696 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783010	RIGHT INBOARD THRUST REVERSER ACTUATOR								
78.020	62270 3680 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
783010	RIGHT OUTBOARD THRUST REVERSER ACTUATOR								
78.030	62270 3681 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783012	LEFT ENGINE EXHAUST NOZZLE								
78.010	225-0016-515-V5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			21-NOV-1995 493		
783012	RIGHT ENGINE EXHAUST NOZZLE								
78.010	225-0016-515-V5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			21-NOV-1995 493		
A783002 (s)	INSPECT THRUST REVERSER: PHASE 4						PKG		
78.070	PKG 4 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
A783003 (s)	INSPECT THRUST REVERSER ELECTRICAL JUNCTION BOX: PHASE 5						PKG		
78.080	PKG 7,105 REF: AMM 78-31-02	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		
B783002 (s)	OPERATIONAL CHECK THRUST REVERSERS: PHASE 2 (AIRCRAFT -0001 THRU -0538)						PKG		
78.090	PKG 2 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				16-MAR-2018		
B783101 (s)	FUNCTIONAL TEST THRUST REVERSER STOW LIMIT SWITCH(AIRPLANES -0002 THRU -0538): PHASE 4						PKG		
78.270	PKG 4 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
C783002 (s)	LUBRICATE THRUST REVERSER ACTUATING MECHANISM: PHASE 2						PKG		
78.290	PKG 2,4,15 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				08-AUG-2018 5114:38 3835		
C783003 (s)	LUBRICATE THRUST REVERSER ACTUATING MECHANISM(USE D-5100NS LUBRICATION METHOD): PHASE 2						PKG		
78.300	PKG 2,4,15 REF: AMM 78-31-00	MOS HRS/MSC AFL	24 300				08-AUG-2018 5114:38 3835		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C783004 (s)	LUBRICATE THRUST REVERSER ACTUATING MECHANISM -PIVOT BALL(USE THE C5A LUBRICATION METHOD FOR SLIDER): PHASE 30						PKG		
78.310	PKG 45 REF: AMM 78-31-00	MOS HRS/MSC AFL	600				25-MAR-2012 4634:42 3404		
CHAPTER 79 OIL									
793001	OIL TEMP INDICATOR								
79.010	VSDL-OC219F 964BA REF: AMM 79-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
793002	LEFT ENGINE OIL TEMPERATURE TRANSMITTER								
79.030	102-00083 311 REF: AMM 79-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
793002	RIGHT ENGINE OIL TEMPERATURE TRANSMITTER								
79.030	102-00083 183 REF: AMM 79-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
793003	OIL PRESSURE INDICATOR								
79.080	VSDL-OC204N 519A REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSO:131			29-MAY-1997 905		
793004	LEFT ENGINE OIL PRESSURE TRANSMITTER								
79.020	123479 48006 REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
793004	RIGHT ENGINE OIL PRESSURE TRANSMITTER								
79.020	123479 47707 REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSO:1031			27-AUG-1997 943		
793006	LEFT ENGINE LOW OIL PRESSURE SWITCH								
79.040	1103P89-2 SN-UNKNOWN REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		



Status Report

560 - CITATION V S/N 560-0216 (TC-LAB): 5211:15 HRS, 3911 AFL as of 28-Oct-2019

Owner/Operator: ZIVER HAVACILIK INS.SAN.TIC A.S

Report Date: 28-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793006	RIGHT ENGINE LOW OIL PRESSURE SWITCH								
79.040	1103P89-2 SN-UNKNOWN REF: AMM 79-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-MAY-1993 0 0		
A793001 (s)	INSPECT ENGINE OIL FILTER: PHASE 2						PKG		
79.050	PKG 2,4,15 REF: AMM 79-31-00	MOS HRS/MSC AFL	150				08-AUG-2018 5114:38 3835		
ENGINE NO. 1 Model : JT15D-5A Serial # 108441 Part # JT15D-5A									
792010	NO. 1 ENGINE - CHANGE OIL								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C				18-JAN-2011 4515 3379		
ENGINE NO. 2 Model : JT15D-5A Serial # 108445 Part # JT15D-5A									
792010	NO. 2 ENGINE - CHANGE OIL								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C				18-JAN-2011 4515 3379		
CHAPTER 80 STARTING									
A801001 (s)	INSPECT LUCAS AEROSPACE STARTER-GENERATOR BRUSHES: PHASE 4						PKG		
80.010	PKG 4 REF: AMM 80-11-01	MOS HRS/MSC AFL	24 300				27-NOV-2017 5022:17 3749		
B801002 (s)	OPERATIONAL CHECK STARTER DISENGAGE SYSTEM: PHASE 5						PKG		
80.020	PKG 7,106 REF: AMM 80-11-01	MOS HRS/MSC AFL	36 1200				12-DEC-2017 5022:17 3749		