

**OWNER:** LANSERIA JET CENTRE  
**ADDRESS:** P.O. BOX 458  
 LANSERIA 1748  
**PHONE:**  
**FAX:**

**OPERATOR:** LANSERIA JET CENTRE  
**ADDRESS:** P.O. BOX 458  
 LANSERIA 1748  
**PHONE:**  
**FAX:**

**ANALYST:** NEIL SANDVIK  
**EMAIL:** NSANDVIK@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)  
 316-462-2442 (FAX)  
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

**AIRCRAFT SERIAL/REGNO:** RB-68/ZS-BDG      **MODEL:** PREMIER I      **MANUFACTURER:** TEXTRON AVIATION INC.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	15-MAY-2003	2116.4 A/C HRS	as of 15-JUL-2019	_____ A/C HRS	as of ____/____/____
		1810 AFL	as of 15-JUL-2019	_____ AFL	as of ____/____/____
		439.6 ACH	as of 16-MAR-2015	_____ ACH	as of ____/____/____

**ENGINE NO. 1 SERIAL/PART:** 105043/56000      **MODEL:** FJ44-2A      **MANUFACTURER:** WILLIAMS INTERNATIONAL

INSTALLED ON 07-FEB-2003		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2116.4 ENG. HRS	as of 15-JUL-2019	_____ ENG. HRS	as of ____/____/____
0 ENC		1801 ENC	as of 15-JUL-2019	_____ ENC	as of ____/____/____

**ENGINE NO. 2 SERIAL/PART:** 105044/56000      **MODEL:** FJ44-2A      **MANUFACTURER:** WILLIAMS INTERNATIONAL

INSTALLED ON 07-FEB-2003		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2116.4 ENG. HRS	as of 15-JUL-2019	_____ ENG. HRS	as of ____/____/____
0 ENC		1801 ENC	as of 15-JUL-2019	_____ ENC	as of ____/____/____



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>									
051001	SCHEDULED A INSPECTION								
	PKG 6	MOS					08-MAR-2018		
		HRS/MSC	600	+20			2033.9	2633.9	2653.9
	REF: AMM 05-20-02	AFL					1745		
051002	SCHEDULED B INSPECTION								
	PKG 7	MOS					14-MAR-2012		
		HRS/MSC	1200	+20			1254.5	2454.5	2474.5
	REF: AMM 05-20-03	AFL					1138		
<b>ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000</b>									
052001	NO. 1 ENGINE - FJ44 CHECK 1								
	PKG 1 in PKG 2	MOS					08-MAR-2018		
		HRS/MSC	300				2033.9	(2333.9) 2333.9	
	REF: See Workcard	ENC					1736		
052002	NO. 1 ENGINE - FJ44 CHECK 2								
	PKG 2	MOS					08-MAR-2018		
		HRS/MSC	600				2033.9	(2633.9) 2633.9	
	REF: See Workcard	ENC					1736		
052003	NO. 1 ENGINE - FJ44 CHECK 3								
	PKG 3	MOS					11-OCT-2002		
		HRS/MSC	15000		-12500		0	(2500) 2500	
	REF: See Workcard	ENC					0		
	THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS								
052004	NO. 1 ENGINE - FJ44 CHECK 4								
	PKG 4	MOS					11-OCT-2002		
		HRS/MSC	15000		-10000		0	(5000) 5000	
	REF: See Workcard	ENC					0		
	THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS								
052005	NO. 1 ENGINE - FJ44 CHECK 5								
	PKG 5	MOS					11-OCT-2002		
		HRS/MSC	15000		-7500		0	(7500) 7500	
	REF: See Workcard	ENC					0		
	THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS								
052006	NO. 1 ENGINE - FJ44 CHECK 6								
	PKG 6	MOS					11-OCT-2002		
		HRS/MSC	15000		-5000		0	(10000) 10000	
	REF: See Workcard	ENC					0		
	THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS								
052007	NO. 1 ENGINE - FJ44 CHECK 7								
	PKG 7	MOS					11-OCT-2002		
		HRS/MSC	15000		-2500		0	(12500) 12500	
	REF: See Workcard	ENC					0		
	THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS								

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
052008	NO. 1 ENGINE - FJ44 CHECK 8 PKG 8	MOS HRS/MSC ENC	15000				11-OCT-2002 0 0	(15000) 15000	
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS									
052009	NO. 1 ENGINE - FJ44 CHECK 9 PKG 9	MOS HRS/MSC ENC	17500				11-OCT-2002 0 0	(17500) 17500 M	
REF: See Workcard									
052010	NO. 1 ENGINE - FJ44 CHECK 10 PKG 10	MOS HRS/MSC ENC	20000				11-OCT-2002 0 0	(20000) 20000 M	
REF: See Workcard									
<b>ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000</b>									
052001	NO. 2 ENGINE - FJ44 CHECK 1 PKG 1 in PKG 2	MOS HRS/MSC ENC	300				08-MAR-2018 2033.9 1736	(2333.9) 2333.9	
REF: See Workcard									
052002	NO. 2 ENGINE - FJ44 CHECK 2 PKG 2	MOS HRS/MSC ENC	600				08-MAR-2018 2033.9 1736	(2633.9) 2633.9	
REF: See Workcard									
052003	NO. 2 ENGINE - FJ44 CHECK 3 PKG 3	MOS HRS/MSC ENC	15000	-12500			11-OCT-2002 0 0	(2500) 2500	
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS									
052004	NO. 2 ENGINE - FJ44 CHECK 4 PKG 4	MOS HRS/MSC ENC	15000	-10000			11-OCT-2002 0 0	(5000) 5000	
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS									
052005	NO. 2 ENGINE - FJ44 CHECK 5 PKG 5	MOS HRS/MSC ENC	15000	-7500			11-OCT-2002 0 0	(7500) 7500	
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS									
052006	NO. 2 ENGINE - FJ44 CHECK 6 PKG 6	MOS HRS/MSC ENC	15000	-5000			11-OCT-2002 0 0	(10000) 10000	
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS									
052007	NO. 2 ENGINE - FJ44 CHECK 7 PKG 7	MOS HRS/MSC ENC	15000	-2500			11-OCT-2002 0 0	(12500) 12500	
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W  
(ENG/APU) = Engine/APU Units

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
052008	NO. 2 ENGINE - FJ44 CHECK 8 PKG 8	MOS HRS/MSC ENC	15000			11-OCT-2002 0 0	(15000) 15000	
REF: See Workcard THE PACKAGE IS IN A "TRUE PROGRESSIVE" SET AND THE SET REQUIREMENT IS 2500 HRS								
052009	NO. 2 ENGINE - FJ44 CHECK 9 PKG 9	MOS HRS/MSC ENC	17500			11-OCT-2002 0 0	(17500) 17500 M	
052010	NO. 2 ENGINE - FJ44 CHECK 10 PKG 10	MOS HRS/MSC ENC	20000			11-OCT-2002 0 0	(20000) 20000 M	
<b>CHAPTER 12</b>	<b>SERVICING</b>							
SPC24	200 HOUR LUBRICATION SERVICING PKG 8	MOS HRS/MSC AFL	12 200	+20		15-JUL-2019 2116.4 1810	15-JUL-2020 2316.4	2336.4
REF: AMM 12-20-02								
SPC25	600 HOUR LUBRICATION SERVICING PKG 9	MOS HRS/MSC AFL	600	+20		24-APR-2014 1615.5 1440	2215.5	2235.5
REF: AMM 12-20-02								

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00 INFORMATION</b>									
PM39-160701	REVIEW PREMIER I/IA MODEL 390 AMM REV. A43						(EBT)		
		MOS							
		HRS/MSC -							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF PM39</b>	AFL							
<b>ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000</b>									
E082-160620	NO. 1 ENGINE - REVIEW FJ44-2A LM REV 39						(EBT)		
		MOS							
		HRS/MSC -							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E082</b>	ENC							
E082-160920	NO. 1 ENGINE - REVIEW FJ44-2A LM REV40						(EBT)		
		MOS							
		HRS/MSC -							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E082</b>	ENC							
<b>ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000</b>									
E082-160620	NO. 2 ENGINE - REVIEW FJ44-2A LM REV 39						(EBT)		
		MOS							
		HRS/MSC -							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E082</b>	ENC							
E082-160920	NO. 2 ENGINE - REVIEW FJ44-2A LM REV40						(EBT)		
		MOS							
		HRS/MSC -							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF E082</b>	ENC							
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>									
05-SA-COA-1	RENEWAL OF SOUTH AFRICAN CERTIFICATE OF AIRWORTHINESS								
		MOS	12				30-MAY-2019	30-MAY-2020	
		HRS/MSC							
	<b>REF:</b>	AFL							

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-SA-COA-2	RENEWAL OF SOUTH AFRICAN	RADIO LICENCE							
		MOS	12				15-JUL-2019	31-JUL-2020	
	REF:	HRS/MSC					2116.4		
		AFL					1810		
051001	SUBMIT ANNUAL INSPECTION REPORT FORM CA43-02 TO THE SACAA								
		MOS	12				15-JUL-2019	15-JUL-2020	
SACAA	REF:	HRS/MSC					2116.4		
		AFL					1810		
051002	RENEWAL CERTIFICATE OF AIRWORTHINESS ANNUAL CURRENCY								
		MOS	12				30-MAY-2019	30-MAY-2020	
	REF:	HRS/MSC							
		AFL							
051003	RENEW RADIO STATION LICENSE								
		MOS	12				30-MAY-2019	31-MAY-2020	
SACAA	REF:	HRS/MSC							
		AFL							
05UNS1	ACCOMPLISH UNSCHEDULED LIGHTNING STRIKE INSPECTION								
05.040		MOS					15-MAY-2003		
	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		
05UNS2	ACCOMPLISH UNSCHEDULED HARD LANDING INSPECTION								
05.050		MOS					15-MAY-2003		
	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		
05UNS3	ACCOMPLISH UNSCHEDULED TURBULENT AIR INSPECTION								
05.060		MOS					15-MAY-2003		
	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05UNS4	ACCOMPLISH UNSCHEDULED FOREIGN OBJECT DAMAGE INSPECTION								
05.070	REF: AMM 05-50-00	MOS HRS/MSC AFL	A/R				15-MAY-2003 0 0		
05UNS5	ACCOMPLISH UNSCHEDULED HIGH DRAG/SIDE LOAD INSPECTION								
05.080	REF: AMM 05-50-00	MOS HRS/MSC AFL	A/R				15-MAY-2003 0 0		
05UNS6	ACCOMPLISH UNSCHEDULED OPERATION IN OR AROUND VOLCANIC ASH INSPECTION								
05.090 UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05-50-00	MOS HRS/MSC AFL	A/R				15-MAY-2003 0 0		
05UNS7	ACCOMPLISH UNSCHEDULED AIRSPEED (OVERSPEED) LIMITATION EXCEEDANCE INSPECTION								
	REF:	MOS HRS/MSC AFL	A/R				15-MAY-2003 0 0		
700A15 (s)	INSPECT NOSE LANDING GEAR UPPER DRAG BRACE						PKG		
	PKG 7	MOS HRS/MSC AFL	1200				15-MAY-2003 0 0		
	REF:								
<b>CHAPTER 08</b>	<b>LEVELING AND WEIGHING</b>								
081000	REWEIGH AIRCRAFT								
		MOS HRS/MSC AFL	60				10-OCT-2014 1737	<b>10-OCT-2019</b>	
<b>SACAA</b>	REF:						1532		
<b>CHAPTER 12</b>	<b>SERVICING</b>								

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 123C01 (s)	LUBRICATE RUDDER, ELEVATOR AND AILERON TRIM TAB PIANO HINGE						PKG		
12.070	PKG 8	MOS					15-JUL-2019		
	REF:	HRS/MSC	200	+20			2116.4		
		AFL					1810		
127A01 (s)	LUBRICATE NOSE LANDING GEAR LUBRICATIONS POINTS						PKG		
	PKG 8	MOS					15-JUL-2019		
	REF: AMM 12-20-01	HRS/MSC	200				2116.4		
		AFL					1810		
127B01 (s)	LUBRICATE LEFT MAIN LANDING GEAR LUBRICATION POINTS						PKG		
	PKG 8	MOS					15-JUL-2019		
	REF: AMM 12-20-01	HRS/MSC	200				2116.4		
		AFL					1810		
127C01 (s)	LUBRICATE RIGHT MAIN LANDING GEAR LUBRICATION POINTS						PKG		
	PKG 8	MOS					15-JUL-2019		
	REF: AMM 12-20-01	HRS/MSC	200				2116.4		
		AFL					1810		
200A02 (s)	LUBRICATE COCKPIT SECTION ZONE 210 - ABOVE FLOOR						PKG		
12.010	PKG 9	MOS					24-APR-2014		
	REF: AMM 12-20-01	HRS/MSC	600	+20/-20			1615.5		
		AFL					1440		
200D01 (s)	LUBRICATE MID FUSELAGE ZONE 230 - WING-TO-FUSELAGE FAIRING						PKG		
12.040	PKG 6,7,9	MOS					08-MAR-2018		
	REF: AMM 12-20-02	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 300A11 (s)	LUBRICATE AFT FUSELAGE ZONE 310 AFT PRESSURE BULKHEAD						PKG		
12.050	PKG 6,7,9	MOS					08-MAR-2018		
	REF: AMM 12-20-02	HRS/MSC	600				2033.9		
		AFL					1745		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300B01 (s)	LUBRICATE ZONE 320 VERTICAL STABILIZER PKG 6,7,9	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
12.060	REF: AMM 12-20-02	AFL							
300C01 (s)	LUBRICATE ZONE 330 HORIZONTAL STABILIZER PKG 6,7,9	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
12.130	REF:	AFL							
+ 500C02 (s)	LUBRICATE LEFT WING ZONE 500/600, 530/630, 540/640 - FLIGHT CONTROLS (600 HOURS) PKG 6,9	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
12.090	REF: AMM 12-20-02	AFL							
600C02 (s)	LUBRICATE RIGHT WING ZONE 600, 630, 640 - FLIGHT CONTROLS (600 HOURS) PKG 6,9	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
12.090	REF: AMM 12-20-02	AFL							
+ 700A01 (s)	LUBRICATE FORWARD FUSELAGE ZONE 710 - NOSE WHEEL WELL PKG 6,9	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
12.100	REF: AMM 12-20-02	AFL							
+ 700B01 (s)	LUBRICATE LEFT WING ZONE 720 LEFT MAIN LANDING GEAR PKG 6,7,9	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
12.110	REF:	AFL							
+ 700C01 (s)	LUBRICATE RIGHT WING ZONE 730 RIGHT MAIN LANDING GEAR PKG 6,7,9	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
12.110	REF:	AFL							

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
800A01 (s)	LUBRICATE ZONE 830 PASSENGER DOOR, ZONE 840 EMERGENCY EXIT, ZONE 850 LEFT BAGGAGE AND ZONE 860 RIGHT AVIONICS DOOR						PKG		
12.160	PKG 6,9	MOS					08-MAR-2018		
	REF: AMM 12-20-02	HRS/MSC AFL	600	+20/-20			2033.9 1745		
<b>CHAPTER 20 STANDARD PRACTICES - AIRFRAME</b>									
100D06 (s)	RESISTANCE CHECK ELECTRICAL BOND - NOSE AVIONICS ZONE 120						PKG		
	PKG 7	MOS					14-MAR-2012		
	REF: AMM 20-13-00	HRS/MSC AFL	1200				1254.5 1138		
100E11 (s)	RESISTANCE CHECK ELECTRICAL BOND - RADOME ZONE 110						PKG		
	PKG 7	MOS					14-MAR-2012		
	REF: AMM 20-13-00	HRS/MSC AFL	1200				1254.5 1138		
200A15 (s)	RESISTANCE CHECK ELECTRICAL BOND - COCKPIT ZONE 210						PKG		
	PKG 7	MOS					14-MAR-2012		
	REF: AMM 20-13-00	HRS/MSC AFL	1200				1254.5 1138		
200B11 (s)	RESISTANCE TEST ELECTRICAL BOND - CABIN ZONE 220						PKG		
	PKG 7	MOS					14-MAR-2012		
	REF: AMM 20-13-00	HRS/MSC AFL	1200				1254.5 1138		
200C20 (s)	RESISTANCE CHECK ELECTRICAL BOND - WING TO FUSELAGE ZONE 230						PKG		
	PKG 7	MOS					14-MAR-2012		
	REF: See Workcard	HRS/MSC AFL	1200				1254.5 1138		
200C21 (s)	RESISTANCE CHECK ELECTRICAL BOND - ANTENNAS						PKG		
	PKG 7	MOS					14-MAR-2012		
	REF: AMM 20-13-00	HRS/MSC AFL	1200				1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300A48 (s)	RESISTANCE CHECK PKG 7 REF: AMM 20-13-00	ELECTRICAL BOND - EMPENNAGE ZONE 310 AFT AVIONICS COMPARTMENT MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
300A49 (s)	RESISTANCE CHECK PKG 7 REF: AMM 20-13-00	ELECTRICAL BOND - EMPENNAGE ZONE 310 TAILCONE MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
300B16 (s)	RESISTANCE CHECK PKG 7 REF: AMM 20-13-00	ELECTRICAL BOND - EMPENNAGE ZONE 320 VERTICAL STABILIZER MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
300C19 (s)	RESISTANCE CHECK PKG 7 REF: AMM 20-13-00	ELECTRICAL BOND - EMPENNAGE ZONE 330 HORIZONTAL STABILIZER MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
500A11 (s)	RESISTANCE CHECK PKG 7 REF: AMM 20-13-00	ELECTRICAL BOND - ZONES 500/600 WINGS MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
600A10 (s)	RESISTANCE CHECK PKG 7 REF: AMM 20-13-00	ELECTRICAL BOND - ZONES 500/600 WINGS MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
<b>CHAPTER 21 AIR CONDITIONING</b>									
100A11 (s)	INSPECT COCKPIT PKG 7 REF: See Workcard	EVAPORATOR BLOWER - FORWARD - MOTOR BRUSHES MOS HRS/MSC AFL	1200	+20/-20			PKG 14-MAR-2012 1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
100B01 (s)	INSPECT ENVIRONMENTAL SYSTEM - AFT PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
+ 100B02 (s) 21.030	INSPECT CABIN BLEED AIR FLAPPER CHECK VALVE PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
+ 100B03 (s) 21.020	INSPECT COCKPIT BLEED AIR FLAPPER CHECK VALVE PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
100B14	VISUALLY INSPECT CABIN BLEED AIR FLAPPER CHECK VALVE REF:	MOS HRS/MSC AFL	6000	+20			15-MAY-2003 0 0	6000	6020
100B15	VISUALLY INSPECT COCKPIT BLEED AIR FLAPPER CHECK VALVE REF:	MOS HRS/MSC AFL	6000	+20			15-MAY-2003 0 0	6000	6020
+ 100B16	VISUAL INSPECT AFT COCKPIT BLEED AIR FLAPPER CHECK VALVE REF: AMM 21-20-03	MOS HRS/MSC AFL	6000	+20			(EBT) 6000	6020	
200A03 (s)	INSPECT FORWARD ENVIROMENTAL SYSTEM PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
200B03	INSPECT LEFT HAND SECONDARY OUTFLOW VALVE 5202-00-3 PKG 6 0363A REF: AMM 21-30-02	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745	2633.9	2653.9
+ 200B03	INSPECT RIGHT HAND PRIMARY OUTFLOW VALVE 5201-00-7 PKG 6 0625A REF: AMM 21-30-02	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745	2633.9	2653.9
200B10 (s)	INSPECT CABIN EVAPORATOR BLOWER - AFT - MOTOR BRUSHES PKG 7 REF: GENERIC CMM	MOS HRS/MSC AFL	1200				PKG 14-MAR-2012 1254.5 1138		
+ 200D02 (s)	INSPECT COCKPIT BLEED AIR DUCT PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			PKG 14-MAR-2012 1254.5 1138		
210001	LEFT HAND HEAT EXCHANGER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
210002	RIGHT HAND HEAT EXCHANGER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
211101	NO. 1 BLEED AIR CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211102	NO. 2 BLEED AIR CONTROL UNIT								
21.300	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
211111	LEFT HAND TEMPERATURE SENSOR								
21.310	PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
211112	RIGHT HAND TEMPERATURE SENSOR								
21.310	PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
212001	3-WAY SOLENOID VALVE								
21.320	PN SN-UNKNOWN REF: AMM 52-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
212011	LEFT HAND BI-LEVEL FLOW CONTROL VALVE								
21.060	390-385035-0003 0227 REF: AMM 21-20-06	MOS HRS/MSC AFL	O/C				30-AUG-2014 1682.4 1488		
212012	RIGHT HAND BI-LEVEL FLOW CONTROL VALVE								
21.060	390-385035-0003 0225 REF: AMM 21-20-06	MOS HRS/MSC AFL	O/C				30-AUG-2014 1682.4 1488		
212021	THREE WAY VALVE								
21.330	PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213021	PRESSURIZATION CONTROLLER								
21.340	PN SN-UNKNOWN REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
213031	MATRIX SWITCH								
21.350	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
213041	BAROMETRIC PRESSURE SWITCH								
21.360	PN SN-UNKNOWN REF: AMM 21-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215025	COMPRESSOR DRIVE MODULE								
21.370	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215030	AIR CONDITIONING COMPRESSOR								
21.160	PN SN-UNKNOWN REF: AMM 21-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215040	AIR CONDITION CONDENSER								
21.180	PN SN-UNKNOWN REF: AMM 21-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215043	RIGHT HAND PRIMARY OUTFLOW VALVE								
21.190	5201-00-7 0625A REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C				03-APR-2014 1615.5 1440		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215044	LEFT HAND SECONDARY OUTFLOW VALVE								
21.195	5202-00-3 0363A REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C				13-APR-2014 1615.5 1440		
215051	SOFT START MODULE								
21.380	PN SN-UNKNOWN REF: AMM 21-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215061	COCKPIT REFRIGERANT SOLENOID VALVE								
21.390	PN SN-UNKNOWN REF: AMM 21-50-17	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215065	CABIN REFRIGERANT SOLENOID VALVE								
21.395	PN SN-UNKNOWN REF: AMM 21-50-17	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215071	FLIGHT DECK EVAPORATOR COIL								
21.115	PN SN-UNKNOWN REF: AMM 21-50-19	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215091	CABIN COIL EVAPORATOR								
21.125	PN SN-UNKNOWN REF: AMM 21-50-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
215095	EVAPORATOR								
21.135	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216001	CABIN TEMPERATURE CONTROLLER								
21.400	PN SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216002	COCKPIT TEMPERATURE CONTROLLER								
21.400	PN SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216011	LEFT HAND TEMPERATURE SWITCH								
21.410	PN SN-UNKNOWN REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216012	RIGHT HAND TEMPERATURE SWITCH								
21.410	PN SN-UNKNOWN REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216021	COCKPIT (555750) VENT DUCT TEMPERATURE SENSOR								
21.420	PN SN-UNKNOWN REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216022	CABIN VENT DUCT TEMPERATURE SENSOR								
21.430	PN SN-UNKNOWN REF: AMM 21-60-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216032	COCKPIT TEMPERATURE SENSOR								
21.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216033	CABIN TEMPERATURE SENSOR								
21.440	PN SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216041	BAGGAGE HEAT CONTROLLER								
21.450	PN SN-UNKNOWN REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216045	BAGGAGE HEAT BLOWER								
21.460	PN SN-UNKNOWN REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
216051	NO. 1 MODULATING VALVE								
21.470	1300330-3 752 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C				10-OCT-2018 2077.7 1779		
216052	NO. 2 MODULATING VALVE								
21.470	PN SN-UNKNOWN REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 300A13 (s)	INSPECT AFT FUSELAGE BAGGAGE COMPARTMENT HEAT SYSTEM						PKG		
21.210	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A14 (s)	INSPECT BLEED AIR FLAPPER CHECK VALVES - TWO LOCATIONS						PKG		
21.040	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300A18 (s)	INSPECT RAM AIR DORSAL CHECK VALVES PKG 6	MOS					PKG		
21.220	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A19 (s)	INSPECT BLOWER DUCT CHECK VALVES PKG 6	MOS					PKG		
21.230	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A20 (s)	INSPECT BLEED AIR HEAT EXCHANGERS PKG 6	MOS					PKG		
21.240	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A21 (s)	INSPECT BLEED AIR HEAT EXCHANGER BLOWER MOTOR PKG 6	MOS					PKG		
21.250	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A42	INSPECT AIR CONDITIONING COMPRESSOR MOTOR AIR CONDITIONING COMPRESSOR MOTOR PN SN-UNKNOWN	MOS						04-SEP-2013	
21.170	REF: See Workcard	HRS/MSC AFL ACH	600				1480 1327 310.5		910.5
300A46	INSPECT AIR CONDITIONING CONDENSER BLOWER MOTOR AIR CONDITIONING CONDENSER BLOWER MOTOR BRUSHES	MOS						04-SEP-2013	
21.480	390-385034-0001 214 REF: See Workcard	HRS/MSC AFL ACH	1200				1480 1327 310.5		1510.5

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300A47	INSPECT BLEED AIR HEAT EXCHANGER BLOWER MOTOR BRUSHES								
21.490	390-385034-0001 094 REF: See Workcard	MOS HRS/MSC AFL	3600	+20			14-MAR-2012 1255 1139	4855	4875
+ OPS03 (s)	OPERATIONAL TEST CABIN ALTITUDE HIGH SWITCH						PKG		
21.080	PKG 7 REF: AMM 21-30-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
OPS04	FUNCTIONAL TEST OF THE PRESSURIZATION MODE (DUMP) SWITCH								
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	MOS HRS/MSC AFL	800					2415.5 M	
OPS04	FUNCTIONAL TEST LEFT HAND SECONDARY OUTFLOW VALVE								
21.195	5202-00-3 0363A REF: GENERIC NO REF	MOS HRS/MSC AFL	800	+20/-20			13-APR-2014 1615.5 1440	2415.5	2435.5
<b>AIRWORTHINESS</b>									
+ OPS04	FUNCTIONAL TEST RIGHT HAND PRIMARY OUTFLOW VALVE								
21.190	5201-00-7 0625A REF: See Workcard	MOS HRS/MSC AFL	800	+20/-20			24-APR-2014 1615.5 1440	2415.5	2435.5
<b>AIRWORTHINESS</b>									
+ SPC17	CHANGE FORWARD ENVIRONMENTAL SYSTEM EVAPORATOR FILTER AND CHECK DRAIN								
21.130	REF: GENERIC NO REF	MOS HRS/MSC AFL	12 200	+20			15-JUL-2019 2116.4 1810	15-JUL-2020 2316.4	2336.4
+ SPC18	CHANGE AFT ENVIRONMENTAL SYSTEM EVAPORATOR FILTER								
21.150	REF: GENERIC NO REF	MOS HRS/MSC AFL	12 200	+20			15-JUL-2019 2116.4 1810	15-JUL-2020 2316.4	2336.4

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
TBO09	FORWARD COCKPIT EVAPORATOR BLOWER								
21.110 OVERHAUL	390-385024-0005 477 REF: AMM 21-50-20	MOS HRS/MSC AFL	1600	TSN:0			10-APR-2014 1615.5 1440	3215.5	
TBO11	AFT CABIN EVAPORATOR BLOWER								
21.120 OVERHAUL	390-385024-0005 218 REF: GENERIC CMM	MOS HRS/MSC AFL	1600	TSN:0			10-APR-2014 1615.5 1440	3215.5	
TBO13	AIR CONDITIONING CONDENSER BLOWER MOTOR								
21.200 OVERHAUL	390-385034-0001 214 REF:	MOS HRS/MSC AFL ACH	2400	TSN:0 TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0 0	2400	
TBO15	BLEED AIR HEAT EXCHANGER BLOWER MOTOR								
21.250 OVERHAUL	390-385034-0001 094 REF: AMM 21-60-11	MOS HRS/MSC AFL	7200	TSO:0 TSO:0 TSO:0			15-MAY-2003 0 0	7200	
TBO18	AIR CONDITIONING COMPRESSOR MOTOR								
21.170 OVERHAUL	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL ACH	2000	TSN:0 TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0 0	2000	
<b>CHAPTER 22</b>	<b>AUTO FLIGHT</b>								
221001	ELEVATOR SERVO MOUNT								
22.010	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

## Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221002	ELEVATOR SERVO								
22.010	PN SN-UNKNOWN REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
221011	RUDDER SERVO MOUNT								
22.020	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
221012	RUDDER SERVO								
22.020	PN SN-UNKNOWN REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
221021	AILERON SERVO MOUNT								
22.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
221022	AILERON SERVO								
22.030	PN SN-UNKNOWN REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
221051	AUXILIARY ROLL TRIM CONTROLLER								
22.040	PN SN-UNKNOWN REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
<b>CHAPTER 23 COMMUNICATIONS</b>									
231001	UPPER VHF COMM ANTENNA								
23.020	PN SN-UNKNOWN REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231002	LOWER VHF COMM ANTENNA								
23.020	PN SN-UNKNOWN REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231011	NO. 1 VHF COMM TRANSCEIVER								
23.030	PN SN-UNKNOWN REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231012	NO. 2 VHF COMM TRANSCEIVER								
23.030	PN SN-UNKNOWN REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231015	HF RECEIVER								
23.110	PN SN-UNKNOWN REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231021	CTL-23 CONTROL								
23.040	PN SN-UNKNOWN REF: AMM 23-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231101	HF (KCU 951) CONTROLLER								
23.130	PN SN-UNKNOWN REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231301	RADIO TELEPHONE ANTENNA								
23.050	PN SN-UNKNOWN REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231311	FLITEPHONE								
23.060	PN SN-UNKNOWN REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231313	NO. 1 DATA ACQUISITION UNIT								
23.100	PN SN-UNKNOWN REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
231314	NO. 2 DATA ACQUISITION UNIT								
23.100	PN SN-UNKNOWN REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
235001	NO. 1 AUDIO AMP								
23.070	PN SN-UNKNOWN REF: AMM 23-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
235002	NO. 2 AUDIO AMP								
23.070	PN SN-UNKNOWN REF: AMM 23-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
235011	PA AMP								
23.080	PN SN-UNKNOWN REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
235013	HF POWER (KAC 952) AMP								
23.120	PN SN-UNKNOWN REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237001	COCKPIT VOICE RECORDER								
23.010	PN SN-UNKNOWN REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
237002	TEST COCKPIT VOICE RECORDER (CVR) OPERATIONAL TEST								
SACAA	REF:	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
237014	UNDERWATER LOCATOR BEACON								
23.010	DK-120 DU49948 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-APR-2014 1615.5 1440		
+ 237016	TEST UNDERWATER LOCATOR BEACON BATTERY AND UNIT								
23.010	REF: AMM 23-70-00	MOS HRS/MSC AFL	24	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2020	01-JUL-2020
237017	REPLACE UNDERWATER LOCATOR BEACON BATTERY								
23.010 MANDATORY	DK-120 DU49948 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+30d/-30d			11-APR-2014 1615.5 1440	11-APR-2020	11-MAY-2020
237021	IMPACT SWITCH								
23.090	PN SN-UNKNOWN REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
<b>CHAPTER 24</b>	<b>ELECTRICAL POWER</b>								
240001	STATIC INVERTER								
24.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243001	LEFT HAND GENERATOR CONTROL UNIT								
24.110	PN SN-UNKNOWN REF: AMM 24-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
243002	RIGHT HAND GENERATOR CONTROL UNIT								
24.110	PN SN-UNKNOWN REF: AMM 24-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
243003	LEFT HAND GROUND FAULT TRANSFORMER								
24.150	PN SN-UNKNOWN REF: AMM 24-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
243005	RIGHT HAND GROUND FAULT TRANSFORMER								
24.150	PN SN-UNKNOWN REF: AMM 24-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
245001	DC/AC INVERTER								
24.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
246001	NO. 1 AC/DC INVERTER								
24.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
246002	NO. 2 AC/DC INVERTER								
24.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246003	NO. 3 AC/DC INVERTER								
24.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 300A22	INSPECT MAIN BATTERY								
24.050	RG-380E/44 PKG 6 40812150 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745	2633.9	2653.9
+ 300A23 (s)	INSPECT GROUNDING POINT OF LEFT/RIGHT GENERATORS BATTERY AND EXTERNAL POWER						PKG		
24.015	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A24 (s)	INSPECT MAIN POWER BOX						PKG		
24.080	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 400A02	INSPECT NO. 1 ENGINE STARTER/GENERATOR								
24.020	390-389001-0001 PKG 6 369AB REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20	-15.9		08-MAR-2018 2033.9 1745	2618	2638
400A03	INSPECT NO. 1 ENGINE STARTER/GENERATOR BRUSHES								
	390-389001-0001 369AB REF: See Workcard	MOS HRS/MSC AFL	800	+20			24-APR-2014 1615.5 1440	2415.5	2435.5
+ 400B02	INSPECT NO. 2 ENGINE STARTER/GENERATOR								
24.030	390-389001-0001 PKG 6 604AB REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20	-15.9		08-MAR-2018 2033.9 1745	2618	2638

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
400B03	INSPECT NO. 2 ENGINE STARTER/GENERATOR BRUSHES 390-389001-0001 604AB REF: See Workcard	MOS HRS/MSC AFL	800	+20			01-JUN-2018 2060.4 1768	2860.4	2880.4
+ OPS05	OPERATIONAL TEST ELECTRICAL SYSTEM LATENT FAILURE	MOS HRS/MSC AFL	2400	+200			15-MAY-2003 0 0	2400	2600
24.040 AIRWORTHINESS	REF: AMM 24-30-00								
SPC10	PERFORM LEVEL TEST OF STANDBY POWER SUPPLY	MOS HRS/MSC AFL	A/R				29-MAY-2017 1955.7 1689		
24.160	REF: GENERIC CMM								
SPC13	ENERGY LEVEL TEST STANDBY BATTERY STANDBY POWER SUPPLY BATTERY	MOS HRS/MSC AFL	12	+30d/-30d			15-MAY-2019 2116.4 1810	15-MAY-2020	14-JUN-2020
24.140	REF: GENERIC CMM								
+ SPC22	CAPACITY CHECK MAIN BATTERY	MOS HRS/MSC AFL	6				15-MAY-2019 2116.4 1810	15-NOV-2019	
24.050	RG-380E/44 40812150 REF: GENERIC CMM								
TBO16	NO. 1 ENGINE STARTER/GENERATOR	MOS HRS/MSC AFL	1400		TSO:0 TSO:0 TSO:0		857	2257	
24.020 OVERHAUL	390-389001-0001 369AB REF: GENERIC NO REF								
TBO16	NO. 2 ENGINE STARTER/GENERATOR	MOS HRS/MSC AFL	1400		TSO:0 TSO:0 TSO:0		1344.8	2744.8	
24.030 OVERHAUL	390-389001-0001 604AB REF: GENERIC NO REF								

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
TBO17	MAIN BATTERY								
24.050	RG-380E/44	MOS	48	TSN:0			29-JUL-2016	29-JUL-2020	
<b>REPLACE</b>	40812150 REF: GENERIC CMM	HRS/MSC AFL		TSN:0 TSN:0			1853.4 1619		
TBO19	STANDBY BATTERY								
24.100	390-384027-0001	MOS	48	TSO:0			15-MAY-2019	15-MAY-2023	
	1230 REF: AMM 24-30-05	HRS/MSC AFL		TSO:0 TSO:0			2116.4 1810		
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>									
+ 200A08 (s)	INSPECT FLIGHT CREW SEATS						PKG		
25.010	PKG 6	MOS					08-MAR-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 200B05 (s)	INSPECT SEAT ATTACHMENT						PKG		
25.030	PKG 7	MOS					14-MAR-2012		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+20/-20			1254.5 1138		
256001	EMERGENCY LOCATOR TRANSMITTER								
25.040	453-5000	MOS					10-APR-2013		
	05753 REF: AMM 25-60-01	HRS/MSC AFL	O/C						
256004	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
256011	ELT BLADE ANTENNA								
25.080	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256021	EMERGENCY EXIT PULL HANDLE								
25.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
256041	PILOT LIFE VEST								
25.110	P01074-101 9101130058 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2016 1853.4 1619		
256042	COPILOT LIFE VEST								
25.110	P01074-101 9090840068 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2015 1764.9 1556		
256051	NO. 1 LIFE VEST								
25.120	P01074-101 9101130038 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2016 1853.4 1619		
256052	NO. 2 LIFE VEST								
25.120	P01074-101 9090840056 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2016 1853.4 1619		
256053	NO. 3 LIFE VEST								
25.130	P01074-101 9090840003 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2016 1853.4 1619		
256054	NO. 4 LIFE VEST								
25.130	P01074-101 9101130060 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2016 1853.4 1619		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256055	NO. 5 LIFE VEST P01074-101 9101130030 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2016 1853.4 1619		
256056	NO. 6 LIFE VEST P0723E105PW H629820 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-JUN-2018 2060.4 1768		
256200	ELT BENCH TEST  REF:	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
257021	MUFFIN FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
SPC02	REPLACE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY BATTERY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE				29-MAY-2017 1955.7 1689	01-JUL-2022 M	
SPC04	RECERTIFY COPILOT LIFE VEST GA-12 P01074-101 9090840068 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		
SPC04	RECERTIFY NO. 1 LIFE VEST GA-12 P01074-101 9101130038 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
SPC04	RECERTIFY NO. 2 LIFE VEST	GA-12							
25.120	P01074-101 9090840056 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		
SPC04	RECERTIFY NO. 3 LIFE VEST	GA-12							
25.130	P01074-101 9090840003 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		
SPC04	RECERTIFY NO. 4 LIFE VEST	GA-12							
25.130	P01074-101 9101130060 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		
SPC04	RECERTIFY NO. 5 LIFE VEST	GA-12							
25.140	P01074-101 9101130030 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		
SPC04	RECERTIFY NO. 6 LIFE VEST	GA-12							
25.140	P0723E105PW H629820 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		
SPC04	RECERTIFY PILOT LIFE VEST	GA-12							
25.110	P01074-101 9101130058 REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				19-MAY-2016 1853.4 1619		
SPC06	RECERTIFY COPILOT LIFE VEST								
25.110	P01074-101 9090840068 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
SPC06	RECERTIFY NO. 1 LIFE VEST P01074-101 9101130038 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023
25.120									
SPC06	RECERTIFY NO. 2 LIFE VEST P01074-101 9090840056 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023
25.120									
SPC06	RECERTIFY NO. 3 LIFE VEST P01074-101 9090840003 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023
25.130									
SPC06	RECERTIFY NO. 4 LIFE VEST P01074-101 9101130060 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023
25.130									
SPC06	RECERTIFY NO. 5 LIFE VEST P01074-101 9101130030 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023
25.140									
SPC06	RECERTIFY NO. 6 LIFE VEST P0723E105PW H629820 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023
25.140									
SPC06	RECERTIFY PILOT LIFE VEST P01074-101 9101130058 REF: GENERIC CMM	MOS HRS/MSC AFL	60	+30d/-30d			01-JUN-2018 2060.4 1768	01-JUN-2023	01-JUL-2023
25.110									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
SPC07	CHECK FIRST AID KIT								
25.070	REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+30d/-30d			15-JUL-2019 2116.4 1810	15-JUL-2020	14-AUG-2020
+ SPC15	INSPECT EMERGENCY LOCATOR TRANSMITTER			EMERGENCY LOCATOR TRANSMITTER FAR 91.207(D)					
25.040	453-5000 05753 REF: See Workcard	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
<b>CHAPTER 26 FIRE PROTECTION</b>									
+ 200A01	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER								
26.060 MANDATORY	C352TS E68635225 REF: GENERIC NO REF	MOS HRS/MSC AFL	144				08-MAR-2018	08-MAR-2030	
261001	FIRE DETECTION CONTROLLER								
26.070	PN SN-UNKNOWN REF: AMM 26-10-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
262001	ENGINE FIRE EXTINGUISHER								
26.040	PN-UNKNOWN SN-UNKNOWN REF: AMM 26-20-01	MOS HRS/MSC AFL	O/C				11-APR-2014 1615.5 1440		
262010	ENGINE NO. 1 FIRE EXTINGUISHER CARTRIDGE								
26.040 LIFE LIMIT	13083-5 1145 REF: AMM 26-20-02 Manufacture Date: 01-OCT-2017	MOS HRS/MSC AFL	72		TSN:0 TSN:0		08-MAR-2018 2033.9 1745	01-OCT-2023	

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262011	ENGINE NO. 2 FIRE EXTINGUISHER CARTRIDGE 13083-5	MOS	72				08-MAR-2018	08-MAR-2024	
26.040	1157	HRS/MSC		TSN:0			2033.9		
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 26-20-02	AFL		TSN:0			1745		
	Manufacture Date: 08-MAR-2018								
+ 262013	REPLACE ENGINE NO. 1 FIRE EXTINGUISHER CARTRIDGE (DATE OF SERVICE) 13083-5	MOS	48				08-MAR-2018	08-MAR-2022	
26.040	1145	HRS/MSC							
<b>SERVICE LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	AFL							
262014	REPLACE ENGINE NO. 2 FIRE EXTINGUISHER CARTRIDGE (DATE OF SERVICE) 13083-5	MOS	48				08-MAR-2018	08-MAR-2022	
26.040	1157	HRS/MSC					2033.9		
<b>SERVICE LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	AFL					1745		
262101	PORTABLE FIRE EXTINGUISHER C352TS	MOS		TSN:0			08-MAR-2018		
26.060	E68635225	HRS/MSC	O/C	TSN:0			2033.9		
	<b>REF:</b> AMM 26-20-03	AFL		TSN:0			1745		
+ 300A26	VISUAL AND OPERATIONAL CHECK OF ENGINE FIRE EXTINGUISHING PLUMBING	MOS					26-MAY-2016		
26.040		HRS/MSC	1200	+20			1853.4	3053.4	3073.4
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					1619		
300A26I	INSPECT LEFT ENGINE FIRE EXTINGUISHER	MOS					26-MAY-2016		
		HRS/MSC	1200	+20			1853.4	3053.4	3073.4
<b>AIRWORTHINESS</b>	<b>REF:</b>	AFL					1619		
+ 300A26I	INSPECT RIGHT ENGINE FIRE EXTINGUISHER	MOS					26-MAY-2016		
		HRS/MSC	1200	+20			1853.4	3053.4	3073.4
<b>AIRWORTHINESS</b>	<b>REF:</b>	AFL					1619		
+ 300A27 (s)	INSPECT BLEED AIR LEAK DETECTION SENSING ELEMENTS						PKG		
26.010	PKG 6	MOS					08-MAR-2018		
		HRS/MSC	600	+20/-20			2033.9		
	<b>REF:</b> GENERIC NO REF	AFL					1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 400A04 (s)	INSPECT NO. 1 ENGINE FIRE DETECTION LOOP AND TUBING						PKG		
26.020	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 400B04 (s)	INSPECT NO. 2 ENGINE FIRE DETECTION LOOP AND TUBING						PKG		
26.020	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ LIMITS01	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER								
26.040 <b>MANDATORY</b>	PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	60				15-MAY-2019	<b>01-MAR-2024 M</b>	
LIMITS03	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER								
26.060 <b>MANDATORY</b>	C352TS E68635225 REF: GENERIC NO REF	MOS HRS/MSC AFL	144				08-MAR-2018	<b>08-MAR-2030</b>	
+ OPS06	OPERATIONAL TEST FIRE DETECTION CONTROLLER AND SENSOR CABLE								
26.030	REF: AMM 26-10-00	MOS HRS/MSC AFL	1200	+20			14-MAR-2012 1255 1139	<b>2455</b>	2475
+ OPS07	VISUAL AND OPERATIONAL CHECK OF ENGINE FIRE EXTINGUISHING PLUMBING								
26.050 <b>AIRWORTHINESS</b>	REF: AMM 26-20-00	MOS HRS/MSC AFL	1200	+20/-20			26-MAY-2016 1853.4 1619	<b>3053.4</b>	3073.4
+ SPC08	WEIGHT CHECK PORTABLE FIRE EXTINGUISHER								
26.060 <b>MANDATORY</b>	REF: AMM 26-20-00	MOS HRS/MSC AFL	12				15-MAY-2019	<b>15-MAY-2020</b>	
<b>CHAPTER 27 FLIGHT CONTROLS</b>									
+ 100A01 (s)	INSPECT FLIGHT CONTROL PULLEYS AND BRACKETS						PKG		
27.160	PKG 7 REF: AMM 20-14-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 100A02 (s)	INSPECT FLIGHT CONTROL CABLES PKG 7	MOS HRS/MSC AFL	1200	+20/-20			PKG 14-MAR-2012 1254.5 1138		
27.150	REF: AMM 20-14-00								
+ 100A03 (s)	INSPECT RUDDER PEDALS PKG 7	MOS HRS/MSC AFL	1200	+20/-20			PKG 14-MAR-2012 1254.5 1138		
27.260	REF: AMM 27-00-00								
+ 100B04 (s)	INSPECT FLIGHT CONTROL CABLES PKG 7	MOS HRS/MSC AFL	1200	+20/-20			PKG 14-MAR-2012 1254.5 1138		
27.720	REF: AMM 20-14-00								
+ 100B05 (s)	INSPECT FLIGHT CONTROL PULLEYS AND BRACKETS PKG 7	MOS HRS/MSC AFL	1200	+20/-20			PKG 14-MAR-2012 1254.5 1138		
27.710	REF: AMM 20-14-00								
+ 100B06 (s)	CHECK AILERON CONTROL CABLES PKG 6	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.030	REF: AMM 20-14-00								
100B12 (s)	CHECK ELEVATOR CONTROL CABLES PKG 6	MOS HRS/MSC AFL	600				PKG 08-MAR-2018 2033.9 1745		
27.355	REF: AMM 27-00-00								
100B13 (s)	CHECK RUDDER CONTROL CABLES PKG 6	MOS HRS/MSC AFL	600				PKG 08-MAR-2018 2033.9 1745		
27.255	REF: AMM 27-00-00								
+ 200A10 (s)	INSPECT CONTROL COLUMN PKG 6	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.130	REF: AMM 20-14-00								

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 200A11 (s)	INSPECT RUDDER PEDALS PKG 6	MOS					PKG		
27.190	REF: AMM 27-20-00	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 200D03 (s)	CHECK AILERON AUTOPILOT SERVO BRIDLE CABLE PKG 6	MOS					PKG		
27.020	REF: AMM 20-14-00	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
270001	LEFT PILOT POSITION SENSOR PN	MOS						15-MAY-2003	
27.730	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
270002	RIGHT CO-PILOT POSITION SENSOR PN	MOS						15-MAY-2003	
27.730	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
270011	LEFT CONTROL WHEEL PN	MOS						15-MAY-2003	
27.740	SN-UNKNOWN REF: AMM 27-10-10	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
270012	RIGHT CONTROL WHEEL PN	MOS						15-MAY-2003	
27.740	SN-UNKNOWN REF: AMM 27-10-10	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
271001	LEFT AILERON TRIM TAB ACTUATOR PN	MOS						15-MAY-2003	
27.750	SN-UNKNOWN REF: AMM 27-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
271002	RIGHT AILERON TRIM TAB ACTUATOR PN	MOS						15-MAY-2003	
27.750	SN-UNKNOWN REF: AMM 27-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271011	LEFT AILERON								
27.760	PN SN-UNKNOWN REF: AMM 27-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
271012	RIGHT AILERON								
27.760	PN SN-UNKNOWN REF: AMM 27-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
272001	RUDDER								
27.250	PN SN-UNKNOWN REF: AMM 27-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
272005	RUDDER TRIM TAB								
27.230	PN SN-UNKNOWN REF: AMM 27-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
272011	RUDDER TRIM TAB ACTUATOR								
27.780	PN SN-UNKNOWN REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
272021	LEFT INBOARD RUDDER BOOST PRESSURE TRANSDUCER								
27.790	PN SN-UNKNOWN REF: AMM 27-20-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
272022	LEFT OUTBOARD RUDDER BOOST PRESSURE TRANSDUCER								
27.790	PN SN-UNKNOWN REF: AMM 27-20-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
272031	RIGHT INBOARD RUDDER BOOST PRESSURE TRANSDUCER								
27.800	PN SN-UNKNOWN REF: AMM 27-20-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272032	RIGHT OUTBOARD RUDDER BOOST PRESSURE TRANSDUCER								
27.800	PN SN-UNKNOWN REF: AMM 27-20-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
272041	VERTICAL STABILIZER ASSEMBLY								
27.770	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
273001	LEFT ELEVATOR								
27.290	PN SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
273002	RIGHT ELEVATOR								
27.290	PN SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
273011	ELEVATOR TAB GEARBOX								
27.810	PN SN-UNKNOWN REF: AMM 27-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
273101	LEFT AOA TRANSMITTER								
27.820	PN SN-UNKNOWN REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
273102	RIGHT AOA TRANSMITTER								
27.820	PN SN-UNKNOWN REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
274001	PITCH TRIM CONTROL UNIT								
27.830	PN SN-UNKNOWN REF: AMM 27-40-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274006	UPPER YOKE SCISSOR FITTING								
27.460	PN SN-UNKNOWN REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
274007	LOWER YOKE SCISSOR FITTING								
27.470	PN SN-UNKNOWN REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
274011	HORIZONTAL STABILIZER ASSEMBLY								
27.840	PN SN-UNKNOWN REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
274020	HORIZONTAL CENTER FITTING								
27.490	PN SN-UNKNOWN REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
274021	LEFT HORIZONTAL STABILIZER POTENTIOMETER								
27.850	PN SN-UNKNOWN REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
274022	RIGHT HORIZONTAL STABILIZER POTENTIOMETER								
27.850	PN SN-UNKNOWN REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275001	FLAP POTENTIOMETER								
27.860	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275011	FLAP CONTROL UNIT								
27.860	PN SN-UNKNOWN REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275021	LEFT OUTBOARD FLAP ASSEMBLY								
27.870	PN SN-UNKNOWN REF: AMM 27-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275022	RIGHT OUTBOARD FLAP ASSEMBLY								
27.870	PN SN-UNKNOWN REF: AMM 27-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275023	LEFT INBOARD FLAP ASSEMBLY								
27.880	PN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275024	RIGHT INBOARD FLAP ASSEMBLY								
27.880	PN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275041	LEFT NO. 1 FLAP ACTUATOR								
27.890	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275042	LEFT NO. 2 FLAP ACTUATOR								
27.890	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275043	LEFT NO. 3 FLAP ACTUATOR								
27.890	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275044	LEFT NO.5 FLAP ACTUATOR								
27.890	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275061	RIGHT NO. 1 FLAP ACTUATOR								
27.900	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275062	RIGHT NO. 2 FLAP ACTUATOR								
27.900	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275063	RIGHT NO. 3 FLAP ACTUATOR								
27.900	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
275064	RIGHT NO. 5 FLAP ACTUATOR								
27.900	PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276001	SPOILER CONTROL UNIT								
27.910	PN SN-UNKNOWN REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276011	LEFT SPOILER (ROLL CONTROL) PANEL								
27.920	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276012	RIGHT SPOILER (ROLL CONTROL) PANEL								
27.920	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276021	LEFT SPOILER SPEED BRAKE PANEL								
27.930	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276022	RIGHT SPOILER SPEED BRAKE PANEL								
27.930	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276031	SPOILER CONTROL MODULE								
27.940	PN SN-UNKNOWN REF: AMM 27-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276041	LEFT UPLOCK RELEASE ACTUATOR								
27.950	PN SN-UNKNOWN REF: AMM 27-60-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276042	RIGHT UPLOCK RELEASE ACTUATOR								
27.950	PN SN-UNKNOWN REF: AMM 27-60-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276051	LEFT LIFT DUMP ACTUATOR								
27.960	PN SN-UNKNOWN REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276052	RIGHT LIFT DUMP ACTUATOR								
27.960	PN SN-UNKNOWN REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276061	LEFT BLOWDOWN ACTUATOR								
27.970	PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276062	RIGHT BLOWDOWN ACTUATOR								
27.970	PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276071	LEFT ROLL SPOILER ACTUATOR								
27.980	PN SN-UNKNOWN REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276072	RIGHT ROLL SPOILER ACTUATOR								
27.980	PN SN-UNKNOWN REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276081	LEFT SPOILER POSITION SENSOR								
27.990	PN SN-UNKNOWN REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276082	RIGHT SPOILER POSITION SENSOR								
27.990	PN SN-UNKNOWN REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276091	LEFT SPOILER (LIFT DUMP) PANEL								
27.995	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
276092	RIGHT SPOILER (LIFT DUMP) PANEL								
27.995	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 300A02	VISUAL CHECK ELEVATOR AND ATTACHMENT STRUCTURE								
27.300		MOS HRS/MSC AFL	48 1200	+30d/-30d +20/-20			29-MAY-2017 1955.7 1689	29-MAY-2021 3155.7	28-JUN-2021 3175.7
<b>AIRWORTHINESS</b>	REF: AMM 27-30-00								
+ 300A04	VISUAL CHECK LOWER YOKE SCISSOR FITTING								
27.470	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	48 1200	+30d/-30d +20/-20			08-MAR-2018 2033.9 1745	08-MAR-2022 3233.9	07-APR-2022 3253.9

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300A04	VISUAL CHECK UPPER YOKE SCISSOR FITTING								
	PN	MOS	48	+30d/-30d			08-MAR-2018	<b>08-MAR-2022</b>	07-APR-2022
27.460	SN-UNKNOWN	HRS/MSC	1200	+20/-20			2033.9	<b>3233.9</b>	3253.9
<b>AIRWORTHINESS</b>	<b>REF:</b>	AFL					1745		
+ 300A05	INSPECT PITCH TRIM ACTUATOR, ATTACHMENT BOLTS, UPPER BUSHING AND STRUCTURE								
		MOS					26-MAY-2016		
27.480		HRS/MSC	400	+20/-20			1853.4	<b>2253.4</b>	2273.4
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-40-00	AFL					1619		
+ 300A06	VISUAL CHECK RUDDER ATTACHMENT STRUCTURE								
		MOS	48	+30d/-30d			29-MAY-2017	<b>29-MAY-2021</b>	28-JUN-2021
27.250		HRS/MSC	1200	+20/-20			1955.7	<b>3155.7</b>	3175.7
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					1689		
+ 300A09	VISUAL/EDDY CURRENT INSPECT CENTER HORIZONTAL FITTING								
		MOS					20-MAY-2016		
27.500		HRS/MSC	6000	+20/-20			1853.4	<b>7853.4</b>	7873.4
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-10-01	AFL					1619		
+ 300A28 (s)	INSPECT RUDDER/ELEVATOR FLIGHT CONTROL CABLES						PKG		
	PKG 6	MOS					08-MAR-2018		
27.240		HRS/MSC	600	+20/-20			2033.9		
	<b>REF:</b> AMM 20-14-00	AFL					1745		
+ 300B02 (s)	INSPECT RUDDER						PKG		
	PKG 6	MOS					08-MAR-2018		
27.250		HRS/MSC	600	+20/-20			2033.9		
	<b>REF:</b> AMM 27-20-01	AFL					1745		
+ 300B03 (s)	INSPECT RUDDER TRIM TAB						PKG		
	PKG 6	MOS					08-MAR-2018		
27.230		HRS/MSC	600	+20/-20			2033.9		
	<b>REF:</b> AMM 27-20-02	AFL					1745		
+ 300B04 (s)	INSPECT RUDDER TRIM ACTUATOR AND LINKAGE						PKG		
	PKG 6	MOS					08-MAR-2018		
27.210		HRS/MSC	600	+20/-20			2033.9		
	<b>REF:</b> AMM 27-20-03	AFL					1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300B05 (s)	INSPECT RUDDER TRIM TAB HINGE PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.230	REF: AMM 27-20-02	HRS/MSC AFL							
+ 300B06 (s)	INSPECT RUDDER HINGES PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.180	REF: AMM 27-20-02	HRS/MSC AFL							
+ 300B07 (s)	INSPECT RUDDER AUTOPILOT SERVO AND BRIDLE CABLE PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.170	REF: AMM 20-14-00	HRS/MSC AFL							
+ 300B08 (s)	INSPECT RUDDER QUADRANT, BELLCRANK, STOP BOLTS, TORQUE TUBE, RUDDER COUNTER BALANCE AND CENTERING SPRING PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.200	REF: AMM 20-14-00	HRS/MSC AFL							
+ 300B09 (s)	PERFORM RUDDER TRIM TAB FREEPLAY INSPECTION PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.220	REF: AMM 27-20-00	HRS/MSC AFL							
+ 300B10 (s)	INSPECT ELEVATOR AUTOPILOT SERVO AND BRIDLE CABLES PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.310	REF: AMM 20-14-00	HRS/MSC AFL							
+ 300B11 (s)	INSPECT ELEVATOR CABLES PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.320	REF: AMM 20-14-00	HRS/MSC AFL							
+ 300B12 (s)	INSPECT ELEVATOR TRIM TAB SYSTEM, ELEVATOR QUADRANT, PUSHROD, CONNECTING BOLTS, AND STOP BOLTS PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.330	REF: AMM 20-14-00	HRS/MSC AFL							

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300B13 (s)	INSPECT VERTICAL STABILIZER FRONT AND REAR SPAR ATTACHMENT PKG 7	MOS					PKG		
55.020	REF: GENERIC NO REF	HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
300B17 (s)	INSPECT RUDDER CABLE TENSION PKG 6	MOS					PKG		
	REF: AMM 20-14-00	HRS/MSC AFL	600				08-MAR-2018 2033.9 1745		
+ 300C02 (s)	INSPECT ELEVATOR CONTROL LINKAGE PKG 6	MOS					PKG		
27.340	REF: AMM 27-00-00	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C03	INSPECT PITCH TRIM ACTUATOR SYSTEM, PITCHTRIM ACTUATOR, ATTACHMENT BOLTS, UPPER BUSHINGS, AND STRUCTURE	MOS					PKG		
27.450 <b>AIRWORTHINESS</b>	REF: AMM 27-40-00	HRS/MSC AFL	400	+20/-20			26-MAY-2016 1853.4 1619	<b>2253.4</b>	2273.4
+ 300C04 (s)	INSPECT ELEVATOR PKG 6	MOS					PKG		
27.350	REF: AMM 27-30-00	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C05 (s)	INSPECT ELEVATOR HINGES AND HINGE BOLTS PKG 6	MOS					PKG		
27.360	REF: AMM 27-30-00	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C06 (s)	INSPECT ELEVATOR TRIM TAB SYSTEM - ELEVATOR TRIM TABS AND HINGES PKG 6	MOS					PKG		
27.370	REF: AMM 27-30-00	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C07	VISUAL CHECK ELEVATOR TRIM TAB SYSTEM	MOS					PKG		
27.380 <b>AIRWORTHINESS</b>	REF: AMM 27-30-00	HRS/MSC AFL	400	+20/-20			08-MAR-2018 2033.9 1745	<b>2433.9</b>	2453.9



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300C09 (s)	INSPECT ELEVATOR TRIM TAB SYSTEM - ELEVATOR TRIM TAB GEAR BOXES						PKG		
27.390	PKG 6 REF: AMM 27-30-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C10 (s)	INSPECT ELEVATOR TRIM TAB SYSTEM - ELEVATOR TRIM TAB JACK SCREW						PKG		
27.400	PKG 6 REF: AMM 27-30-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C11 (s)	INSPECT ELEVATOR TRIM TAB JACK SCREW FLEX SHAFT						PKG		
27.410	PKG 6 REF: AMM 27-30-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C12 (s)	VISUALLY CHECK AFT PIVOT FITTING ASSEMBLY						PKG		
27.520	PKG 7 REF:	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 300C17 (s)	INSPECT HORIZONTAL ATTACHMENT PIN						PKG		
27.530	PKG 7 REF:	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 500B02	EDDY CURRENT LEFT WING SPARS 2 (WSTA 50.50 TO 90.00)								
<b>AIRWORTHINESS</b>	REF: AMM 20-26-00	MOS HRS/MSC AFL	6000	+20/-20			15-MAY-2003 0 0	<b>6000</b>	6020
+ 500C01 (s)	INSPECT LEFT WING FLAP DOORS (540LL, 540NL, 230HL)						PKG		
27.570	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 500C03 (s)	INSPECT LEFT WING SPOILER HYDRAULIC LINES						PKG		
27.640	PKG 6 REF: AMM 27-60-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 500C04 (s)	INSPECT LEFT WING AILERON CABLES						PKG		
27.060	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	REF: AMM 20-14-00	HRS/MSC AFL							
+ 500C06 (s)	INSPECT LEFT WING AILERON AUTOPILOT SERVO AND CABLE						PKG		
27.080	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	REF: AMM 20-14-00	HRS/MSC AFL							
+ 500C07	INSPECT LEFT AILERON TRIM TAB SYSTEM						(EBT)		
	REF: See Workcard	MOS	400	+20				2433.9 M	2453.9
		HRS/MSC AFL							
+ 500C08 (s)	INSPECT LEFT WING AILERON TRIM TAB						PKG		
27.090	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	REF: AMM 27-10-00	HRS/MSC AFL							
+ 500C09 (s)	INSPECT LEFT WING AILERON HINGES AND ATTACH POINTS						PKG		
27.100	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	REF: AMM 27-10-01	HRS/MSC AFL							
+ 500C10	INSPECT LEFT WING AILERON TRIM TAB SYSTEM - AILERON TRIM TAB								
27.120		MOS	3600	+200			15-MAY-2003 0	3600	3800
<b>AIRWORTHINESS</b>	REF: AMM 27-10-02	HRS/MSC AFL					0		
+ 500C11	INSPECT LEFT WING AILERON TRIM TAB SYSTEM - AILERON TRIM ACTUATOR								
27.140		MOS	3600	+200			15-MAY-2003 0	3600	3800
<b>AIRWORTHINESS</b>	REF: AMM 27-10-03	HRS/MSC AFL					0		
+ 500C12 (s)	INSPECT LEFT WING AILERON DRY BAY (530LL)						PKG		
27.070	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	REF: AMM 20-14-00	HRS/MSC AFL							

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 500C13 (s)	INSPECT LEFT WING FLAP PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
27.580	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20					
+ 500C15	INSPECT LEFT WING FLAP ACTUATOR ATTACHMENTS - FLAP ACTUATORS PKG 6	MOS	12				15-MAY-2019 2116.4 1810	<b>15-MAY-2020</b> <b>2316.4</b>	2336.4
27.590	REF: GENERIC NO REF	HRS/MSC AFL	200	+20/-20					
<b>AIRWORTHINESS</b>									
+ 500C16 (s)	INSPECT LEFT WING FLAP ACTUATOR WIRING PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
27.600	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20					
+ 500C17 (s)	INSPECT LEFT WING FLAP ROLLERS PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
27.610	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20					
+ 500C19 (s)	INSPECT LEFT WING SPOILERS PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
27.650	REF: AMM 27-00-00	HRS/MSC AFL	600	+20/-20					
+ 500C20 (s)	INSPECT LEFT WING SPOILER HINGES PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
27.660	REF: AMM 27-00-00	HRS/MSC AFL	600	+20/-20					
+ 500C21 (s)	INSPECT LEFT WING SPOILER DRY BAY (530EL) PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
27.680	REF: AMM 27-60-00	HRS/MSC AFL	600	+20/-20					
+ 500C22 (s)	INSPECT LEFT WING SPOILER ACTUATOR PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
27.700	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20					

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 500C23 (s)	INSPECT LEFT WING SPOILER BLOWDOWN ACTUATOR						PKG		
27.670	PKG 7	MOS					14-MAR-2012		
	REF: AMM 27-00-00	HRS/MSC	1200				1254.5		
		AFL					1138		
+ 500C24	INSPECT LEFT WING LIFT DUMP ACTUATOR								
27.690		MOS					08-MAR-2018		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC	1000	+20/-20	-1.9		2033.9	<b>3032</b>	3052
		AFL					1745		
+ 600C01 (s)	INSPECT RIGHT WING FLAP DOORS (640LL, 640NL, 230KR)						PKG		
27.570	PKG 6	MOS					08-MAR-2018		
	REF: See Workcard	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 600C03 (s)	INSPECT RIGHT WING SPOILER HYDRAULIC LINES						PKG		
27.640	PKG 6	MOS					08-MAR-2018		
	REF: AMM 27-60-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 600C04 (s)	INSPECT RIGHT WING AILERON CABLES						PKG		
27.060	PKG 6	MOS					08-MAR-2018		
	REF: AMM 20-14-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 600C07	INSPECT RIGHT AILERON TRIM TAB SYSTEM								
27.110		MOS					08-MAR-2018		
	REF: AMM 27-00-00	HRS/MSC	400	+20			2033.9	<b>2433.9</b>	2453.9
		AFL					1745		
+ 600C08 (s)	INSPECT RIGHT WING AILERON TRIM TAB						PKG		
27.090	PKG 6	MOS					08-MAR-2018		
	REF: AMM 27-10-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 600C09 (s)	INSPECT RIGHT WING AILERON HINGES AND ATTACH POINTS						PKG		
27.100	PKG 6	MOS					08-MAR-2018		
	REF: AMM 27-10-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 600C10	INSPECT RIGHT WING AILERON TRIM TAB SYSTEM - AILERON TRIM TAB								
27.120		MOS					15-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-10-02	HRS/MSC AFL	3600	+200			0 0	<b>3600</b>	3800
+ 600C11	INSPECT RIGHT WING AILERON TRIM TAB SYSTEM - AILERON TRIM ACTUATOR								
27.140		MOS					15-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-10-03	HRS/MSC AFL	3600	+200			0 0	<b>3600</b>	3800
+ 600C12 (s)	INSPECT RIGHT WING AILERON DRY BAY (630LL)						PKG		
27.070	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b> AMM 20-14-00	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 600C13 (s)	INSPECT RIGHT WING FLAP						PKG		
27.580	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 600C15	INSPECT RIGHT WING FLAP ACTUATOR ATTACHMENTS - FLAP ACTUATORS								
27.590		MOS	12				15-MAY-2019	<b>15-MAY-2020</b>	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	200	+20/-20			2116.4 1810	<b>2316.4</b>	2336.4
+ 600C16 (s)	INSPECT RIGHT WING FLAP ACTUATOR WIRING						PKG		
27.600	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 600C17 (s)	INSPECT RIGHT WING FLAP ROLLERS						PKG		
27.610	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 600C18 (s)	INSPECT RIGHT WING FLAP POSITION TRANSMITTER						PKG		
27.620	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 600C19 (s)	INSPECT RIGHT WING SPOILERS PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.650	REF: AMM 27-00-00	HRS/MSC AFL							
+ 600C20 (s)	INSPECT RIGHT WING SPOILER HINGES PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.660	REF: GENERIC NO REF	HRS/MSC AFL							
+ 600C21 (s)	INSPECT RIGHT WING SPOILER DRY BAY (630EL) PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.680	REF: AMM 27-00-00	HRS/MSC AFL							
+ 600C22 (s)	INSPECT RIGHT WING SPOILER ACTUATOR PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.700	REF: GENERIC NO REF	HRS/MSC AFL							
+ 600C23 (s)	INSPECT RIGHT WING SPOILER BLOWDOWN ACTUATOR PKG 7	MOS	1200				PKG 14-MAR-2012 1254.5 1138		
27.670	REF: AMM 27-00-00	HRS/MSC AFL							
+ 600C24	INSPECT RIGHT WING LIFT DUMP ACTUATOR PKG 6	MOS	1000	+20/-20			08-MAR-2018 2033.9 1745	3032	3052
27.690	REF: GENERIC NO REF	HRS/MSC AFL			-1.9				
<b>AIRWORTHINESS</b>									
LIMITS07	PITCH TRIM ACTUATOR 390-386004-0005 0036	MOS	6000				26-MAY-2016 1853.4 1619	7853.4	
27.440	REF: AMM 27-40-02	HRS/MSC AFL			TSO:0 TSO:0 TSO:0				
<b>MANDATORY</b>									
+ OPS08 (s)	ADJUSTMENT/CHECK AILERON SYSTEM PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.010	REF: AMM 27-10-00	HRS/MSC AFL							

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ OPS09 (s)	FUNCTIONAL TEST ROLL TRIM PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.050	REF: AMM 27-10-00	HRS/MSC AFL							
+ OPS10 (s)	FUNCTIONAL CHECK RUDDER SYSTEM PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.040	REF: AMM 27-20-00	HRS/MSC AFL							
+ OPS11	OPERATIONAL TEST RUDDER BOOST	MOS	800	+20/-20			29-APR-2014 1615.5 1440	2415.5	2435.5
27.270	REF: AMM 27-20-00	HRS/MSC AFL							
<b>AIRWORTHINESS</b>									
+ OPS12 (s)	OPERATIONAL TEST RUDDER SYSTEM PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.280	REF: AMM 27-20-00	HRS/MSC AFL							
+ OPS13 (s)	FUNCTIONAL TEST ELEVATOR PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.420	REF: AMM 27-30-00	HRS/MSC AFL							
OPS14 (s)	OPERATIONAL TEST G SWITCH PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.430	REF: AMM 27-31-00	HRS/MSC AFL							
+ OPS15 (s)	OPERATIONAL CHECK HORIZONTAL STABILIZERS NORMAL PKG 6	MOS	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
27.550	REF: AMM 27-40-00	HRS/MSC AFL							
+ OPS16	OPERATIONAL TEST TAKE-OFF CONFIGURATION WARNING	MOS	12	+20/-20			15-MAY-2019 2116.4 1810	15-MAY-2020 2316.4	2336.4
27.560	REF: AMM 27-40-00	HRS/MSC AFL	200						
<b>AIRWORTHINESS</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ OPS17 (s)	FUNCTIONAL TEST FLAP SYSTEM						PKG		
27.630	PKG 6 REF: AMM 27-50-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
<b>CHAPTER 28 FUEL</b>									
+ 200D04 (s)	REPLACE FUEL DISTRIBUTION FILTER ELEMENTS						PKG		
28.070	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
281001	REFUEL/DEFUEL ADAPTER								
28.110	PN SN-UNKNOWN REF: AMM 28-10-10	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
281011	PRECHECK VALVE								
28.120	PN SN-UNKNOWN REF: AMM 28-10-11	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
281021	FUEL CAP								
28.130	PN SN-UNKNOWN REF: AMM 28-10-10	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
281071	NO. 1 OUTBOARD CHECK VALVE								
28.140	PN SN-UNKNOWN REF: AMM 28-10-04	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
281072	NO. 2 OUTBOARD CHECK VALVE								
28.140	PN SN-UNKNOWN REF: AMM 28-10-04	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
281081	LEFT WING FORWARD INBOARD FLOAT CHECK VALVE								
28.150	PN SN-UNKNOWN REF: AMM 28-10-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281082	LEFT WING AFT INBOARD FLOAT CHECK VALVE								
28.150	PN SN-UNKNOWN REF: AMM 28-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
281083	RIGHT WING FORWARD FLOAT VALVE								
28.160	PN SN-UNKNOWN REF: AMM 28-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
281084	RIGHT WING AFT FLOAT VALVE								
28.160	PN SN-UNKNOWN REF: AMM 28-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
281091	NO. 1 OUTBOARD FLOAT CHECK VALVE								
28.170	PN SN-UNKNOWN REF: AMM 28-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
281092	NO. 2 OUTBOARD FLOAT CHECK VALVE								
28.170	PN SN-UNKNOWN REF: AMM 28-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282011	NO. 1 FUEL FILTER								
28.180	PN SN-UNKNOWN REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282012	NO. 2 FUEL FILTER								
28.180	PN SN-UNKNOWN REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282041	NO. 1 FUEL SHUTOFF VALVE								
28.190	PN SN-UNKNOWN REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282042	NO. 2 FUEL SHUTOFF VALVE								
28.190	PN SN-UNKNOWN REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282051	NO. 1 FUEL BOOST PUMP								
28.200	PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282052	NO. 2 FUEL BOOST PUMP								
28.200	PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282061	NO. 1 MAIN TANK JET PUMP								
28.210	PN SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282062	NO. 2 MAIN TANK JET PUMP								
28.210	PN SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282071	NO. 1 TRANSFER JET PUMP								
28.220	PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282072	NO. 2 TRANSFER JET PUMP								
28.220	PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282081	LEFT REFUEL/DEFUEL VALVE ASSEMBLY								
28.300	PN SN-UNKNOWN REF: AMM 28-10-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282082	RIGHT REFUEL/DEFUEL VALVE ASSEMBLY								
28.300	PN SN-UNKNOWN REF: AMM 28-10-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282091	LEFT PILOT CUTOFF VALVE ASSEMBLY								
28.310	PN SN-UNKNOWN REF: AMM 28-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282092	RIGHT PILOT CUTOFF VALVE ASSEMBLY								
28.310	PN SN-UNKNOWN REF: AMM 28-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
282101	WING CROSS TRANSFER PUMP								
28.090	PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284001	NO. 1 FUEL QUANTITY INDICATOR								
28.230	PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284002	NO. 2 FUEL QUANTITY INDICATOR								
28.230	PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284011	LEFT NO. 1 FUEL PROBE								
28.240	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284012	LEFT NO. 2 FUEL PROBE								
28.240	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284013	LEFT NO. 3 FUEL PROBE								
28.240	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284014	LEFT NO. 4 FUEL PROBE								
28.240	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284021	RIGHT NO. 1 FUEL PROBE								
28.250	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284022	RIGHT NO. 2 FUEL PROBE								
28.250	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284023	RIGHT NO. 3 FUEL PROBE								
28.250	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284024	RIGHT NO. 4 FUEL PROBE								
28.250	PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284041	NO. 1 LOW LEVEL SENSOR								
28.260	PN SN-UNKNOWN REF: AMM 28-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284042	NO. 2 LOW LEVEL SENSOR								
28.260	PN SN-UNKNOWN REF: AMM 28-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284051	NO. 1 FUEL PRESSURE SWITCH								
28.270	PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284052	NO. 2 FUEL PRESSURE SWITCH								
28.270	PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284061	CROSS TRANSFER FLOW SWITCH								
28.280	PN SN-UNKNOWN REF: AMM 28-40-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284071	LEFT PRESSURE RELIEF VALVE								
28.290	PN SN-UNKNOWN REF: AMM 28-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
284072	RIGHT PRESSURE RELIEF VALVE								
28.290	PN SN-UNKNOWN REF: AMM 28-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 500D02 (s)	INSPECT LEFT FUEL DIVERTER VALVE (520DL)						PKG		
28.080	PKG 7 REF: AMM 28-20-13	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 500D03 (s)	INSPECT LEFT FUEL VENT SYSTEM VALVES						PKG		
28.030	PKG 7 REF: AMM 28-10-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 500D04 (s)	INSPECT LEFT FUEL VENT SYSTEM TUBES/HOSES						PKG		
28.040	PKG 7 REF: AMM 28-10-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 500D05 (s)	INSPECT LEFT FLAME ARRESTOR (VENT LINE)						PKG		
28.050	PKG 7 REF: AMM 28-10-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 500D06 (s)	INSPECT LEFT PRESSURE AND VACUUM RELIEF VALVE						PKG		
28.060	PKG 7 REF: AMM 28-10-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
500D10 (s)	INSPECT LEFT WING FUEL DRAIN VALVES						PKG		
57.200	PKG 7 REF: See Workcard	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 600D02 (s)	INSPECT RIGHT FUEL DIVERTER VALVE (620DL)						PKG		
28.080	PKG 7 REF: AMM 28-20-13	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 600D03 (s)	INSPECT RIGHT FUEL VENT SYSTEM VALVES						PKG		
28.030	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 600D04 (s)	INSPECT RIGHT FUEL VENT SYSTEM TUBES/HOSES						PKG		
28.040	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 600D05 (s)	INSPECT RIGHT FLAME ARRESTOR (VENT LINE)						PKG		
28.050	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 600D06 (s)	INSPECT RIGHT PRESSURE AND VACUUM RELIEF VALVE						PKG		
28.060	PKG 7 REF: See Workcard	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
600D10 (s)	INSPECT RIGHT WING FUEL DRAIN VALVES						PKG		
57.200	PKG 7 REF: See Workcard	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ OPS18 (s)	OPERATIONAL TEST FUEL INDICATING SYSTEM						PKG		
28.100	PKG 7 REF: AMM 28-40-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
<b>CHAPTER 29 HYDRAULIC POWER</b>									
290001	NO. 1 SHUT-OFF VALVE								
29.040	PN SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
290002	NO. 2 SHUT-OFF VALVE								
29.040	PN SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
291001	HYDRAULIC PACKAGE								
29.010	PN SN-UNKNOWN REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
291011	NO. 1 ENGINE HYDRAULIC PUMP								
29.070	PN SN-UNKNOWN REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
291012	NO. 2 ENGINE HYDRAULIC PUMP								
29.070	PN SN-UNKNOWN REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
293001	HYDRAULIC PRESSURE INDICATOR								
29.050	PN SN-UNKNOWN REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300A29 (s)	INSPECT HYDRAULIC PACKAGE						PKG		
29.010	PKG 6 REF: AMM 29-10-02	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A30 (s)	INSPECTION/CHECK HYDRAULIC PACKAGE INLET AIR FILTER/CHECK VALVE						PKG		
29.010	PKG 6 REF: AMM 29-10-11	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ SPC23	REPLACE HYDRAULIC PACKAGE PRESSURE AND RETURN FILTERS								
29.030 <b>AIRWORTHINESS</b>	REF: GENERIC CMM	MOS HRS/MSC AFL	400	+20/-20			08-MAR-2018 2033.9 1745	<b>2433.9</b>	2453.9
<b>CHAPTER 30 ICE AND RAIN PROTECTION</b>									
+ 100E06	INSPECT FRONT AND SIDE WINDSHIELDS								
30.160 <b>AIRWORTHINESS</b>	REF: AMM 30-40-00	MOS HRS/MSC AFL	12 200	+20			15-MAY-2019 2116.4 1810	<b>15-MAY-2020</b> <b>2316.4</b>	2336.4
200D06 (s)	INSPECT ANTI-ICE DUCTS						PKG		
30.010	PKG 7 REF: AMM 30-10-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 300A31 (s)	INSPECT ANTI-ICE CROSS FEED VALVE						PKG		
30.020	PKG 6 REF: AMM 30-10-01	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C14 (s)	INSPECT ENERGY STORAGE BANK						PKG		
30.030	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C18	REPLACE LEFT NO. 1 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
30.100 <b>MANDATORY</b>	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0	<b>5400</b>	



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300C18	REPLACE LEFT NO. 10 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE LEFT NO. 11 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE LEFT NO. 12 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE LEFT NO. 2 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE LEFT NO. 3 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE LEFT NO. 4 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE LEFT NO. 5 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE LEFT NO. 6 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300C18	REPLACE LEFT NO. 7 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
<b>MANDATORY</b>									
+ 300C18	REPLACE LEFT NO. 8 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
<b>MANDATORY</b>									
+ 300C18	REPLACE LEFT NO. 9 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
<b>MANDATORY</b>									
300C18	REPLACE RIGHT NO. 1 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
30.100 <b>MANDATORY</b>									
+ 300C18	REPLACE RIGHT NO. 10 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
<b>MANDATORY</b>									
+ 300C18	REPLACE RIGHT NO. 11 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
<b>MANDATORY</b>									
+ 300C18	REPLACE RIGHT NO. 12 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
<b>MANDATORY</b>									
+ 300C18	REPLACE RIGHT NO. 2 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5400				15-MAY-2003 0 0		5400
<b>MANDATORY</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300C18	REPLACE RIGHT NO. 3 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE RIGHT NO. 4 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE RIGHT NO. 5 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE RIGHT NO. 6 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE RIGHT NO. 7 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE RIGHT NO. 8 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
+ 300C18	REPLACE RIGHT NO. 9 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	5400				0		5400
<b>MANDATORY</b>	<b>REF:</b> See Workcard	AFL					0		
301001	ANTI-ICE CROSSFEED VALVE								
	PN	MOS		TSN:0			15-MAY-2003		
30.020	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	<b>REF:</b> AMM 30-10-01	AFL		TSN:0			0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301011	NO. 1 EJECTOR PUMP								
30.190	PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
301012	NO. 2 EJECTOR PUMP								
30.190	PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
301021	DE-ICING CONTROL UNIT								
30.200	PN SN-UNKNOWN REF: AMM 30-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
301031	LEFT HAND PRESSURE REGULATOR AND SOLENOID VALVE								
30.040	PN SN-UNKNOWN REF: AMM 30-10-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
301032	RIGHT HAND PRESSURE REGULATOR AND SOLENOID VALVE								
30.040	PN SN-UNKNOWN REF: AMM 30-10-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
301101	NO. 1 HORIZONTAL DE-ICE LEADING EDGE ASSEMBLY								
30.210	PN SN-UNKNOWN REF: AMM 30-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
301102	NO. 2 HORIZONTAL DE-ICE LEADING EDGE ASSEMBLY								
30.210	PN SN-UNKNOWN REF: AMM 30-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
301111	NO. 1 ENERGY STORAGE BANK								
30.230	PN SN-UNKNOWN REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301112	NO. 2 ENERGY STORAGE BANK								
30.230	PN SN-UNKNOWN REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301120	LEFT NO. 1 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301121	LEFT NO. 10 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301122	LEFT NO. 11 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301123	LEFT NO. 12 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301124	LEFT NO. 2 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301125	LEFT NO. 3 REPLACE ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301126	LEFT NO. 4 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 301127	LEFT NO. 5 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301128	LEFT NO. 6 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301129	LEFT NO. 7 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301130	LEFT NO. 8 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301131	LEFT NO. 9 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301132	RIGHT NO. 1 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301133	RIGHT NO. 10 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 301134	RIGHT NO. 11 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 301135	RIGHT NO. 12 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 301136	RIGHT NO. 2 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 301137	RIGHT NO. 3 RIGHT ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 301138	RIGHT NO. 4 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 301139	RIGHT NO. 5 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 301140	RIGHT NO. 6 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 301141	RIGHT NO. 7 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
+ 301142	RIGHT NO. 8 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 301143	RIGHT NO. 9 ELECTROMAGNETIC EXPULSIVE DEICE (EMED) ACTUATOR								
	PN	MOS		TSN:0			15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
308001	NO. 1 ICE DETECTOR								
	PN	MOS		TSN:0			15-MAY-2003		
30.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-80-01	AFL		TSN:0			0		
308002	NO. 2 ICE DETECTOR								
	PN	MOS		TSN:0			15-MAY-2003		
30.220	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 30-80-01	AFL		TSN:0			0		
+ OPS20	OPERATIONAL TEST WING ANTI-ICE CROSS FEED VALVE AND ANTI-ICE SWITCHES								
		MOS					08-MAR-2018		
30.180		HRS/MSC	400	+20/-20			2033.9	2433.9	2453.9
<b>AIRWORTHINESS</b>	REF: AMM 30-10-00	AFL					1745		
+ OPS21	OPERATIONAL TEST STRUCTURE OVER TEMPERATURE SWITCH								
		MOS					15-MAY-2003		
30.070		HRS/MSC	3600	+200			0	3989.3	M 4189.3
<b>AIRWORTHINESS</b>	REF: AMM 30-10-00	AFL					0		
+ OPS22	OPERATIONAL TEST LEADING EDGE OVER TEMPERATURE SWITCH								
		MOS					15-MAY-2003		
30.080		HRS/MSC	3600	+200			0	3989.3	M 4189.3
<b>AIRWORTHINESS</b>	REF: AMM 30-10-00	AFL					0		
+ OPS23 (s)	OPERATIONAL TEST AUTO MODE						PKG		
	PKG 7	MOS					14-MAR-2012		
30.090		HRS/MSC	1200	+20/-20			1254.5		
	REF: AMM 30-11-00	AFL					1138		
+ OPS24 (s)	OPERATIONAL TEST MANUAL MODE (EMED)						PKG		
	PKG 7	MOS					14-MAR-2012		
30.090		HRS/MSC	1200	+20/-20			1255		
<b>AIRWORTHINESS</b>	REF: AMM 30-11-00	AFL					1139		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ OPS26 (s)	OPERATIONAL CHECK TT2 SENSOR						PKG		
30.120	PKG 6 REF: AMM 30-20-01	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ OPS27	OPERATIONAL TEST ENGINE ANTI-ICE PRESSURE SWITCH						15-MAY-2003		
30.130 <b>AIRWORTHINESS</b>	REF: AMM 30-20-01	MOS HRS/MSC AFL	3600	+200			0 0	<b>3600</b>	<b>3800</b>
+ OPS28 (s)	OPERATIONAL TEST PITOT STATIC PROBE HEAT						PKG		
30.140	PKG 6 REF: AMM 30-30-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ OPS30 (s)	OPERATIONAL TEST FRONT AND SIDE WINDSHIELD HEAT						PKG		
30.170	PKG 6 REF: AMM 30-40-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
<b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b>									
310000	DOWNLOAD FLIGHT DATA RECORDER (FDR)								
	REF:	MOS HRS/MSC AFL	N/A						
311011	CABIN BRIEFER								
31.180	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		
311013	DIFFERENTIAL PRESSURE GAUGE INDICATOR								
31.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		
311041	PITCH TRIM INDICATOR								
31.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
311051	RUDDER TRIM INDICATOR								
31.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
311061	ROLL TRIM INDICATOR								
31.050	PN SN-UNKNOWN REF: AMM 27-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
311071	FLAP INDICATOR								
31.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
311075	ANNUNCIATOR								
31.080	PN SN-UNKNOWN REF: AMM 31-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
311091	NO. 1 DC LOAD INDICATOR								
31.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
311092	NO. 2 DC LOAD INDICATOR								
31.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
311097	DC VOLTMETER								
31.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314001	MAINTENANCE DIAGNOSTIC COMPUTER								
31.100	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314011	ICC-3000 COMPUTER								
31.110	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314021	IEC-3001 CARD CAGE								
31.120	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314031	NO. 1 PWR-3000 CARD CAGE								
31.130	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314032	NO. 2 PWR-3000 CARD CAGE								
31.130	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314041	NO. 1 IOC-3100 CARD CAGE								
31.140	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314042	NO. 2 IOC-3100 CARD CAGE								
31.140	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314051	NO. 1 DATA CONCENTRATOR UNIT								
31.150	PN SN-UNKNOWN REF: AMM 31-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314052	NO. 2 DATA CONCENTRATOR UNIT								
31.150	PN SN-UNKNOWN REF: AMM 31-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314061	NO. 1 OPTION CONTROL MODULE								
31.160	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
314062	NO. 2 OPTION CONTROL MODULE								
31.160	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
315001	AURAL WARNING GENERATOR								
31.170	PN SN-UNKNOWN REF: AMM 31-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ OPS31	TEST FLAPS AND SPOILERS TAKEOFF CONFIGURATION WARNING								
31.020		MOS HRS/MSC AFL	12 200 +20/-20				15-JUL-2019 2116.4 1810	<b>15-JUL-2020</b> <b>2316.4</b>	2336.4
<b>AIRWORTHINESS</b>	REF: AMM 31-50-00								
+ OPS37	CHECK DCU AURAL WARNING								
31.010		MOS HRS/MSC AFL	12 200 +20/-20				15-MAY-2019 2116.4 1810	<b>15-MAY-2020</b> <b>2316.4</b>	2336.4
<b>AIRWORTHINESS</b>	REF: AMM 31-40-02								
<b>CHAPTER 32</b>	<b>LANDING GEAR</b>								
+ 100A04 (s)	INSPECT BRAKE CONTROL CABLE, LINKAGE, AND CONNECTORS - PARKING BRAKE						PKG		
32.240	PKG 7 REF: AMM 32-40-00	MOS HRS/MSC AFL	1200 +20/-20				14-MAR-2012 1254.5 1138		
+ 100A05 (s)	INSPECT STEERING BELLCRANKS AND PUSHRODS						PKG		
32.340	PKG 7 REF: AMM 32-50-00	MOS HRS/MSC AFL	1200 +20/-20				14-MAR-2012 1254.5 1138		
+ 100A06 (s)	INSPECT LANDING GEAR ALTERNATE EXTENSION CABLES						PKG		
32.100	PKG 7 REF: AMM 32-30-00	MOS HRS/MSC AFL	1200 +20/-20				14-MAR-2012 1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 100A07 (s)	INSPECT LANDING GEAR ALTERNATE EXTENSION FORWARD QUADRANT PKG 7	MOS					PKG		
32.020	REF: AMM 32-30-00	HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 100A08 (s)	INSPECT BRAKE LINKAGE PKG 7	MOS					PKG		
32.250	REF: AMM 32-40-00	HRS/MSC AFL	N/A				14-MAR-2012 1254.5 1138		
+ 100B07 (s)	INSPECT LANDING GEAR ALTERNATE EXTENSION CABLES PKG 7	MOS					PKG		
32.010	REF: AMM 32-30-00	HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 200D07 (s)	INSPECT BRAKE ASSEMBLIES - BRAKE SYSTEM PKG 6	MOS					PKG		
32.320	REF: AMM 32-40-00	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 200D08	INSPECT ANTI-SKID SYSTEM	MOS							
<b>AIRWORTHINESS</b>	REF: AMM 32-40-00	HRS/MSC AFL	400	+20			19-MAY-2016 1853.4 1619	<b>2253.4</b>	2273.4
320001	LANDING GEAR CONTROL PN	MOS							
32.410	SN-UNKNOWN REF: AMM 32-30-01	HRS/MSC AFL	O/C				15-MAY-2003 0 0		
320011	LANDING GEAR SELECTOR VALVE PN	MOS							
32.420	SN-UNKNOWN REF: AMM 32-30-02	HRS/MSC AFL	O/C				15-MAY-2003 0 0		
321001	LEFT MAIN LANDING GEAR DOOR ACTUATOR PN	MOS							
32.430	SN-UNKNOWN REF: AMM 32-30-11	HRS/MSC AFL	O/C				15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321002	RIGHT MAIN LANDING GEAR DOOR ACTUATOR								
32.430	PN SN-UNKNOWN REF: AMM 32-30-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
321011	LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	390-810001-0001 1023201ICT REF: AMM 32-10-01	MOS HRS/MSC AFL	O/C				19-MAY-2011		
321012	RIGHT MAIN LANDING GEAR ASSEMBLY								
32.070	390-810001-0002 07090202 REF: AMM 32-10-01	MOS HRS/MSC AFL	O/C				19-MAY-2011		
321021	LEFT MAIN LANDING GEAR RESTRICTOR								
32.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
321022	RIGHT MAIN LANDING GEAR RESTRICTOR								
32.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
321031	LEFT MAIN LANDING GEAR UPLOCK CABLE ASSEMBLY								
32.450	PN SN-UNKNOWN REF: AMM 32-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
321032	RIGHT MAIN LANDING GEAR UPLOCK CABLE ASSEMBLY								
32.450	PN SN-UNKNOWN REF: AMM 32-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
321041	LEFT MAIN LANDING GEAR DOOR UPLOCK CABLE ASSEMBLY								
32.460	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321042	RIGHT MAIN LANDING GEAR DOOR UPLOCK CABLE ASSEMBLY								
32.460	PN SN-UNKNOWN REF: AMM 32-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
321052	VALVE PACKAGE CABLE ASSEMBLY								
32.650	PN SN-UNKNOWN REF: AMM 32-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
322001	NOSE LANDING GEAR DOWNLOCK ACTUATOR								
32.470	PN SN-UNKNOWN REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
322011	NOSE LANDING GEAR ASSY								
32.480	390-820001-0001 07310201ICT REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C				19-MAY-2011		
323001	NOSE LANDING GEAR RETRACT ACTUATOR								
32.490	PN SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323011	NOSE LANDING GEAR UPLOCK RELEASE ACTUATOR								
32.500	PN SN-UNKNOWN REF: AMM 32-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323021	NOSE LANDING GEAR UPLOCK ASSEMBLY								
32.180	PN SN-UNKNOWN REF: AMM 32-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323031	LEFT MAIN LANDING GEAR UPLOCK RELEASE ACTUATOR								
32.510	PN SN-UNKNOWN REF: AMM 32-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323032	RIGHT MAIN LANDING GEAR UPLOCK RELEASE ACTUATOR								
32.510	PN SN-UNKNOWN REF: AMM 32-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323041	LEFT MAIN LANDING GEAR DOOR UPLOCK ACTUATOR								
32.520	PN SN-UNKNOWN REF: AMM 32-30-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323042	RIGHT MAIN LANDING GEAR DOOR UPLOCK ACTUATOR								
32.520	PN SN-UNKNOWN REF: AMM 32-30-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323051	LEFT MAIN LANDING GEAR RETRACT ACTUATOR								
32.210	PN SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323052	RIGHT MAIN LANDING GEAR RETRACT ACTUATOR								
32.210	PN SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323061	MAIN LANDING GEAR EXTEND VALVE								
32.530	PN SN-UNKNOWN REF: AMM 32-30-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
323071	MAIN LANDING GEAR EMERGENCY CABLE ASSEMBLY								
32.540	PN SN-UNKNOWN REF: AMM 32-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
324001	POWER BRAKE VALVE								
32.550	PN SN-UNKNOWN REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324011	HYDRAULIC ACCUMULATOR								
32.560	PN SN-UNKNOWN REF: AMM 32-40-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
324021	PARKING BRAKE VALVE								
32.570	PN SN-UNKNOWN REF: AMM 32-40-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
324031	NOSE LANDING GEAR WHEEL								
32.580	18-1682 0150 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				12-MAR-2018 2033.9 1745		
324041	NOSE LANDING GEAR TIRE								
32.580	019-611-0 3344S00334 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-MAR-2018 2033.9 1745		
324051	LEFT MAIN LANDING GEAR WHEEL ASSY								
32.590	3-1576 0488 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-MAR-2018 2033.9 1745		
324052	RIGHT MAIN LANDING GEAR WHEEL ASSY								
32.600	3-1576 0391 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-FEB-2017 1920.7 1666		
324061	LEFT MAIN LANDING GEAR TIRE								
32.590	026-618-0 633R00133 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-MAR-2018 2033.9 1745		
324062	RIGHT MAIN LANDING GEAR TIRE								
32.600	026-618-0 5293R00248 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			10-FEB-2017 1920.7 1666		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324071	LEFT MAIN LANDING GEAR BRAKE ASSEMBLY								
32.660	390-388103-0007 0424 REF: AMM 32-40-03	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			15-SEP-2015 1788.8 1572		
324072	RIGHT MAIN LANDING GEAR BRAKE ASSEMBLY								
32.660	390-388103-0007 0570 REF: AMM 32-40-03	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			15-SEP-2015 1788.8 1572		
324101	ANTI-SKID CONTROL UNIT								
32.610	PN SN-UNKNOWN REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
325001	NOSE LANDING GEAR STEERING DAMPENER								
32.620	PN SN-UNKNOWN REF: AMM 32-50-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
32NDT1	NDT INSPECT NOSE LANDING GEAR WHEEL								
32.580	18-1682 0150 REF: CMM 32-47-25	MOS HRS/MSC AFL	T/C				12-MAR-2018 2033.9 1745		
32NDT2	NDT INSPECT LEFT MAIN LANDING GEAR WHEEL ASSY								
32.590	3-1576 0488 REF: CMM 32-45-27	MOS HRS/MSC AFL	T/C				12-MAR-2018 2033.9 1745		
32NDT3	NDT INSPECT RIGHT MAIN LANDING GEAR WHEEL ASSY								
32.600	3-1576 0391 REF: CMM 32-45-27	MOS HRS/MSC AFL	T/C				10-FEB-2017 1920.7 1666		
+ 700A03 (s)	INSPECT NOSE LANDING GEAR STRUT ASSEMBLY								
32.110	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 700A04 (s)	INSPECT NOSE LANDING GEAR DRAG STRUT ASSEMBLY						PKG		
32.140	PKG 6	MOS					08-MAR-2018		
	REF: AMM 32-20-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 700A05 (s)	INSPECT NOSE LANDING GEAR SHIMMY DAMPER						PKG		
32.150	PKG 6	MOS					08-MAR-2018		
	REF: AMM 32-20-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 700A06 (s)	INSPECT NOSE LANDING GEAR UPLOCK RELEASE ACTUATOR ALTERNATE EXTENSION CABLE						PKG		
32.170	PKG 6	MOS					08-MAR-2018		
	REF: AMM 32-30-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 700A07 (s)	INSPECT NOSE LANDING GEAR UPLOCK ASSEMBLY						PKG		
32.180	PKG 6	MOS					08-MAR-2018		
	REF: AMM 32-30-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 700A10 (s)	INSPECT NOSE WHEEL STEERING SYSTEM						PKG		
32.350	PKG 6	MOS					08-MAR-2018		
	REF: AMM 32-50-00	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 700A12 (s)	INSPECT NOSE LANDING GEAR WHEEL WELL						PKG		
32.160	PKG 6	MOS					08-MAR-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 700A13	VISUAL AND NDI (MAGNETIC PARTICLE) OF NOSE LANDING GEAR STRUCTURE								
32.130		MOS					15-MAY-2003		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	HRS/MSC	6000	+20			0	<b>6000</b>	6020
		AFL	5000				0	<b>5000</b>	
700A14 (s)	INSPECT NOSE LANDING GEAR WHEEL WELL						PKG		
	PKG 6	MOS					08-MAR-2018		
	REF:	HRS/MSC	600				2033.9		
		AFL					1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 700B05 (s)	INSPECT LEFT MAIN LANDING GEAR STRUT ASSEMBLY						PKG		
32.030	PKG 6 REF: AMM 12-10-25	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 700B06 (s)	INSPECT LEFT MAIN WHEEL WELL AND GEAR WIRING HARNESSSES						PKG		
32.370	PKG 6 REF: AMM 32-60-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 700B07 (s)	INSPECT LEFT MAIN LANDING GEAR LANDING GEAR ALTERNATE EXTENSION SYSTEM						PKG		
32.190	PKG 6 REF: AMM 32-30-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 700B17 (s)	INSPECT LEFT LANDING GEAR SQUAT SWITCH						PKG		
32.390	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
700B18 (s)	INSPECT LEFT MAIN LANDING GEAR AND INBOARD DOOR UPLOCK HOOKS AND ASSEMBLIES						PKG		
	PKG 6 REF:	MOS HRS/MSC AFL	600				08-MAR-2018 2033.9 1745		
+ 700B21	VISUAL AND NDI(MAGNETIC PARTICLE) LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	390-810001-0001 1023201ICT REF: GENERIC NO REF	MOS HRS/MSC AFL	6000	+20			15-MAY-2003 0 0	6000 5000	6020
<b>AIRWORTHINESS</b>			5000						
700B22 (s)	INSPECT LEFT LANDING GEAR WHEEL WELL						PKG		
	PKG 6 REF:	MOS HRS/MSC AFL	600				08-MAR-2018 2033.9 1745		
+ 700C05 (s)	INSPECT RIGHT MAIN LANDING GEAR STRUT ASSEMBLY						PKG		
32.030	PKG 6 REF: AMM 12-10-25	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 700C06 (s)	INSPECT RIGHT MAIN WHEEL WELL AND GEAR WIRING HARNESSSES						PKG		
32.370	PKG 6 REF: AMM 32-60-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 700C07 (s)	INSPECT RIGHT MAIN LANDING GEAR LANDING GEAR ALTERNATE EXTENSION SYSTEM						PKG		
32.190	PKG 6 REF: AMM 32-30-13	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 700C17 (s)	INSPECT RIGHT LANDING GEAR SQUAT SWITCH						PKG		
32.390	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 700C18 (s)	INSPECT RIGHT MAIN LANDING GEAR AND INBOARD DOOR UPLOCK HOOKS AND ASSEMBLIES						PKG		
32.380	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 700C20	VISUAL AND NDI(MAGNETIC PARTICLE) LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	390-810001-0002 07090202 REF: GENERIC NO REF	MOS HRS/MSC AFL	6000	+20			15-MAY-2003 0 0	6000 5000	6020
<b>AIRWORTHINESS</b>			5000						
700C21 (s)	INSPECT RIGHT LANDING GEAR WHEEL WELL						PKG		
	PKG 6 REF:	MOS HRS/MSC AFL	600				08-MAR-2018 2033.9 1745		
+ OPS32 (s)	FUNCTIONAL TEST LANDING GEAR ALTERNATE EXTENSION SYSTEM						PKG		
32.230	PKG 6 REF: AMM 32-30-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ OPS33	PERFORM TEST OF EMERGENCY BRAKE SYSTEM								
32.310	REF: AMM 32-40-00	MOS HRS/MSC AFL	400	+20			08-MAR-2018 2033.9 1745	2433.9	2453.9

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ OPS34	TEST ANTI-SKID BRAKE								
32.330		MOS					19-MAY-2016		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-40-00</b>	HRS/MSC AFL	400	+20/-20			1853.4 1619	<b>2253.4</b>	2273.4
SPC09	INSPECTION LEFT MAIN LANDING GEAR BRAKE								
32.640		MOS					15-MAY-2003		
	<b>REF:</b>	HRS/MSC AFL	A/R				0 0		
SPC09	INSPECTION RIGHT MAIN LANDING GEAR BRAKE								
32.640		MOS					15-MAY-2003		
	<b>REF:</b>	HRS/MSC AFL	A/R				0 0		
<b>CHAPTER 33 LIGHTS</b>									
331001	NO. 1 INCANDESCENT DIMMER								
33.090	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	<b>REF: GENERIC NO REF</b>	AFL					0		
331002	NO. 2 INCANDESCENT DIMMER								
33.090	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	<b>REF: GENERIC NO REF</b>	AFL					0		
331015	AFT ANTI-COLLISION LIGHT								
33.020	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	<b>REF: AMM 33-40-03</b>	AFL					0		
331016	LEFT ANTI-COLLISION (STROBE) LIGHT								
33.030	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	<b>REF: See Workcard</b>	AFL					0		
331017	RIGHT ANTI-COLLISION (STROBE) LIGHT								
33.040	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	<b>REF: See Workcard</b>	AFL					0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334001	LEFT WING STROBE POWER SUPPLY								
33.100	PN SN-UNKNOWN REF: AMM 33-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
334003	LIGHTING SWITCH CONTROLLER								
33.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
334101	LEFT LANDING LIGHT								
33.130	PN SN-UNKNOWN REF: AMM 33-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
334102	RIGHT LANDING LIGHT								
33.130	PN SN-UNKNOWN REF: AMM 33-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
335010	EMERGENCY EXIT (SELF-ILLUMINATING) SIGN								
33.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
335015	FORWARD PARTITION (SELF-ILLUMINATING) SIGN								
33.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ LIMITS04	INSPECT EMERGENCY EXIT SIGN (SELF-ILLUMINATING)								
33.080	REF: AMM 33-50-00	MOS HRS/MSC AFL	12	+30d/-30d			15-MAY-2019	15-MAY-2020	14-JUN-2020
<b>MANDATORY</b>									
+ LIMITS04	INSPECT FORWARD PARTITION (SELF-ILLUMINATING ON AFT SIDE)								
33.120	REF: AMM 33-50-00	MOS HRS/MSC AFL	12	+30d/-30d			15-JUL-2019	15-JUL-2020	14-AUG-2020
<b>MANDATORY</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ OPS42 (s)	FUNCTIONAL TEST AFT ANTI-COLLISION LIGHT						PKG		
33.020	PKG 7	MOS					14-MAR-2012		
	REF: GENERIC CMM	HRS/MSC	1200	+20/-20			1254.5		
		AFL					1138		
+ OPS43 (s)	FUNCTIONAL TEST LEFT ANTI-COLLISION LIGHT						PKG		
33.030	PKG 7	MOS					14-MAR-2012		
	REF: GENERIC CMM	HRS/MSC	1200	+20/-20			1254.5		
		AFL					1138		
+ OPS44 (s)	FUNCTIONAL TEST RIGHT ANTI-COLLISION LIGHT						PKG		
33.040	PKG 7	MOS					14-MAR-2012		
	REF: GENERIC CMM	HRS/MSC	1200	+20/-20			1254.5		
		AFL					1138		
<b>CHAPTER 34 NAVIGATION</b>									
+ 100C04 (s)	INSPECT PITOT AND STATIC LINES AND CONNECTIONS - LEFT BAGGAGE COMPARTMENT						PKG		
34.020	PKG 6	MOS					08-MAR-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 100D01 (s)	INSPECT PITOT AND STATIC LINE CONNECTIONS - RIGHT AVIONICS COMPARTMENT						PKG		
34.030	PKG 6	MOS					08-MAR-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
100E10	INSPECT RVSM CONTOUR								
34.500		MOS	12	+30d/-30d			15-JUL-2019	15-JUL-2020	14-AUG-2020
	REF: AMM 34-10-10	HRS/MSC					2116.4		
		AFL					1810		
340000	RECERTIFY VOR EQUIPMENT								
		MOS	12				15-MAY-2019	15-MAY-2020	
<b>SACAA</b>	<b>REF:</b>	HRS/MSC					2116.4		
		AFL					1810		
340001	UPPER COAXIAL SWITCH								
34.070	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 34-54-01	AFL					0		
							0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340002	LOWER COAXIAL SWITCH								
34.070	PN SN-UNKNOWN REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
340003	PERFORM FEDERAL AVIATION ADMINISTRATION'S (FAA) REDUCED VERTICAL SEPARATION MINIMUM (RVSM) MONITORING								
FAA	REF:	MOS HRS/MSC AFL	A/R				15-MAY-2003 0 0		
340004	PITOT STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION								
SACAA	REF:	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
340005	AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION								
SACAA	REF:	MOS HRS/MSC AFL	24				01-JUN-2018 2060.4 1768	01-JUN-2020	
340011	STANDBY COMPASS								
34.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
340021	MAGNETIC COMPASS								
34.090	PN SN-UNKNOWN REF: AMM 34-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
340A21	COMPASS SWING PER SA-CATS 43 GMR 43-02-18								
	REF:	MOS HRS/MSC AFL	12				01-JUN-2018 2060.4 1768	01-JUN-2019	
341001	NO. 1 AIR DATA COMPUTER								
34.050	PN SN-UNKNOWN REF: AMM 34-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341002	NO. 2 AIR DATA COMPUTER								
34.050	PN SN-UNKNOWN REF: AMM 34-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341003	FUNCTIONAL TEST AIR DATA SYSTEM								
SACAA	REF:	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
341025	STANDBY ALTIMETER								
34.100	PN SN-UNKNOWN REF: AMM 34-12-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341031	NO. 1 EXTERNAL COMPENSATION UNIT								
34.110	PN SN-UNKNOWN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341032	NO. 2 EXTERNAL COMPENSATION UNIT								
34.110	PN SN-UNKNOWN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341041	NO. 1 AHC 3000 AHRS UNIT								
34.120	PN SN-UNKNOWN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341042	NO. 2 AHC 3000 AHRS UNIT								
34.120	PN SN-UNKNOWN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341047	ALT-4000 TRANSMITTER								
34.130	PN SN-UNKNOWN REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341051	NO. 1 ADAPTIVE FLIGHT DISPLAY								
34.140	PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341052	NO. 2 ADAPTIVE FLIGHT DISPLAY								
34.140	PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341061	ADAPTIVE FLIGHT DISPLAY CENTER								
34.140	PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341071	NO. 1 CONTROL DISPLAY UNIT								
34.150	PN SN-UNKNOWN REF: AMM 34-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341072	NO. 2 CONTROL DISPLAY UNIT								
34.150	PN SN-UNKNOWN REF: AMM 34-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341081	WEATHER RADAR (RTA-800) ANTENNA								
34.160	PN SN-UNKNOWN REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341091	AIRSPEED INDICATOR								
34.170	PN SN-UNKNOWN REF: AMM 34-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341093	MMT-3010 MOUNT								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341100	TEST PITOT STATIC PRESSURE SYSTEM	MOS	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
<b>SACAA</b>	<b>REF:</b>	HRS/MSC AFL							
341101	NO. 1 PITOT VALVE	MOS		TSN:0			15-MAY-2003		
34.180	PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
341102	NO. 2 PITOT VALVE	MOS		TSN:0			15-MAY-2003		
34.180	PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
341111	OAT PROBE	MOS		TSN:0			15-MAY-2003		
34.190	PN SN-UNKNOWN <b>REF:</b> AMM 34-13-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
341121	NO. 1 PITOT STATIC PROBE	MOS		TSN:0			15-MAY-2003		
34.200	PN SN-UNKNOWN <b>REF:</b> AMM 34-12-07	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
341122	NO. 2 PITOT STATIC PROBE	MOS		TSN:0			15-MAY-2003		
34.200	PN SN-UNKNOWN <b>REF:</b> AMM 34-12-07	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
341201	NO. 1 NAV ANTENNA	MOS		TSN:0			15-MAY-2003		
34.210	PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
341202	NO. 2 NAV ANTENNA	MOS		TSN:0			15-MAY-2003		
34.210	PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341211	PHASING COUPLER								
34.220	PN SN-UNKNOWN REF: AMM 34-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341221	STANDBY AIRSPEED INDICATOR								
34.230	PN SN-UNKNOWN REF: AMM 34-12-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
341800	CALIBRATION / RECERIFICATION AIR SPEED INDICATOR (ASI)								
<b>SACAA</b>	<b>REF:</b>	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	<b>15-MAY-2020</b>	
342011	UPPER FLUX DETECTOR								
34.240	PN SN-UNKNOWN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
342012	LOWER FLUX DETECTOR								
34.240	PN SN-UNKNOWN REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
342031	ATTITUDE INDICATOR								
34.250	PN SN-UNKNOWN REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
342041	VERTICAL SPEED INDICATOR								
34.260	PN SN-UNKNOWN REF: AMM 34-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
342400	COMPASS SWING								
	<b>REF:</b>	MOS HRS/MSC AFL	12				01-JUN-2018 2060.4 1768	<b>01-JUN-2019</b>	

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
343001	NO. 1 COUPLER								
34.270	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
343002	NO. 2 COUPLER								
34.270	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
343003	NO. 3 COUPLER								
34.270	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
343021	MARKER BEACON ANTENNA								
34.280	PN SN-UNKNOWN REF: AMM 34-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
343031	GLIDESLOPE ANTENNA								
34.290	PN SN-UNKNOWN REF: AMM 34-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
343041	NO. 1 VIR-432 NAV RECEIVER								
34.300	PN SN-UNKNOWN REF: AMM 34-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
343042	NO. 2 VIR-432 NAV RECEIVER								
34.300	PN SN-UNKNOWN REF: AMM 34-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
343100	INSPECT AND TEST OPERATION OF ILS RECEIVER								
SACAA	REF:	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344001	UPPER TCAS ANTENNA								
34.310	PN SN-UNKNOWN REF: AMM 34-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
344002	LOWER TCAS ANTENNA								
34.310	PN SN-UNKNOWN REF: AMM 34-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
344011	UPPER TRANSPONDER ANTENNA								
34.320	PN SN-UNKNOWN REF: AMM 34-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
344012	LOWER TRANSPONDER ANTENNA								
34.320	PN SN-UNKNOWN REF: AMM 34-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
344021	TCAS TRANSMITTER								
34.330	822-1294-002 142460 REF: AMM 34-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
344031	TCAS COAX KIT								
34.340	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
344301	RADIO ALTIMETER RECEIVER ANTENNA								
34.350	PN SN-UNKNOWN REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
344302	RADIO ALTIMETER TRANSMITTER ANTENNA								
34.350	PN SN-UNKNOWN REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345001	NO. 1 ATC TRANSPONDER 622-9210-005 111HG REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				04-MAR-2013 1417.6 1275		
345002	NO. 2 ATC TRANSPONDER 622-9210-005 111HK REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C				04-MAR-2013 1417.6 1275		
345011	SINGLE ADF ANTENNA PN SN-UNKNOWN REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345012	DUAL ADF ANTENNA PN SN-UNKNOWN REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345021	NO. 1 DME ANTENNA PN SN-UNKNOWN REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345022	NO. 2 DME ANTENNA PN SN-UNKNOWN REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345031	NO. 1 DME 622-7309-101 12C3V REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345032	NO. 2 DME 622-7309-101 10L7R REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345041	NO. 1 GPS ANTENNA								
34.400	PN SN-UNKNOWN REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345042	NO. 2 GPS ANTENNA								
34.400	PN SN-UNKNOWN REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345051	NO. 1 GLOBAL POSITIONING SYSTEM								
34.410	PN SN-UNKNOWN REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345052	NO. 2 GLOBAL POSITIONING SYSTEM								
34.410	PN SN-UNKNOWN REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345061	SINGLE ADF-462 TRANSCEIVER								
34.360	622-7382-101 10THT REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345062	DUAL ADF-462 TRANSCEIVER								
34.360	PN SN-UNKNOWN REF: AMM 34-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
345500	INSPECT AND TEST OPERATION OF DME								
SACAA	REF:	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
345700	TEST ADF SENSE ANTENNA FOR INSULATION RESISTANCE								
SACAA	REF:	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346001	NO. 1 DCP-3000 DISPLAY CONTROL PANEL								
34.420	PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346002	NO. 2 DCP-3000 DISPLAY CONTROL PANEL								
34.420	PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346011	NO. 1 FLIGHT GUIDANCE COMPUTER								
34.430	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346012	NO. 2 FLIGHT GUIDANCE COMPUTER								
34.430	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346021	NO. 1 CONFIGURATION STRAPPING UNIT								
34.440	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346022	NO. 2 CONFIGURATION STRAPPING UNIT								
34.440	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346031	NO. 1 FLIGHT MANAGEMENT COMPUTER								
34.450	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346032	NO. 2 FLIGHT MANAGEMENT COMPUTER								
34.450	PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346041	SDD-640C SENSOR DISPLAY DRIVE								
34.460	PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346061	ENHANCED GROUND PROXIMITY WARNING UNIT								
34.470	PN SN-UNKNOWN REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346071	429 COMPUTER								
34.480	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
346081	DATA BASE UNIT								
34.490	PN SN-UNKNOWN REF: AMM 34-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ OPS38	OPERATIONAL TEST REVERSION SWITCHES								
34.010		MOS HRS/MSC AFL	12 200	+20/-20			15-MAY-2019 2116.4 1810	15-MAY-2020 2316.4	2336.4
<b>AIRWORTHINESS</b>	REF: AMM 34-00-01								
SPC03	RECERTIFY STANDBY ALTIMETER								
34.100	PN SN-UNKNOWN REF: AMM 34-12-00	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
<b>MANDATORY</b>									
SPC05	RECERTIFY NO. 1 AIR DATA COMPUTER								
34.050	PN SN-UNKNOWN REF: AMM 34-11-02	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
<b>MANDATORY</b>									
SPC05	RECERTIFY NO. 2 AIR DATA COMPUTER								
34.050	PN SN-UNKNOWN REF: AMM 34-11-02	MOS HRS/MSC AFL	12				15-MAY-2019 2116.4 1810	15-MAY-2020	
<b>MANDATORY</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
SPC11	RECERTIFY NO. 1 ATC TRANSPONDER								
34.040	622-9210-005	MOS	12				15-MAY-2019	15-MAY-2020	
<b>MANDATORY</b>	111HG REF: AMM 34-54-00	HRS/MSC AFL					2116.4 1810		
SPC11	RECERTIFY NO. 2 ATC TRANSPONDER								
34.040	622-9210-005	MOS	12				15-MAY-2019	15-MAY-2020	
<b>MANDATORY</b>	111HK REF: AMM 34-54-00	HRS/MSC AFL					2116.4 1810		
SPC12	RECERTIFY NO. 1 PITOT STATIC SYSTEM								
34.520		MOS	12				15-MAY-2019	15-MAY-2020	
<b>MANDATORY</b>	REF: AMM 34-12-00	HRS/MSC AFL					2116.4 1810		
SPC12	RECERTIFY NO. 2 PITOT STATIC SYSTEM								
34.520		MOS	12				15-MAY-2019	15-MAY-2020	
<b>MANDATORY</b>	REF: AMM 34-12-00	HRS/MSC AFL					2116.4 1810		
+ SPC16	DRAIN LEFT PITOT/STATIC SYSTEM								
34.020		MOS	12				15-MAY-2019	15-MAY-2020	
	REF: AMM 34-12-00	HRS/MSC AFL	200	+20			2116.4 1810	2316.4	2336.4
+ SPC16	DRAIN RIGHT PITOT/STATIC SYSTEM								
34.030		MOS	12				15-MAY-2019	15-MAY-2020	
	REF: AMM 34-12-00	HRS/MSC AFL	200	+20			2116.4 1810	2316.4	2336.4
<b>CHAPTER 35</b>	<b>OXYGEN</b>								
+ 100C02 (s)	INSPECT OXYGEN SYSTEM						PKG		
35.010	PKG 6	MOS	600	+20/-20			08-MAR-2018		
	REF: AMM 12-10-30	HRS/MSC AFL					2033.9 1745		
+ 200A12 (s)	INSPECT FLIGHT CREW OXYGEN SYSTEM						PKG		
35.020	PKG 6	MOS	600	+20/-20			08-MAR-2018		
	REF: AMM 35-10-01	HRS/MSC AFL					2033.9 1745		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 200B07 (s)	INSPECT OXYGEN MASK AND HOSES PKG 6	MOS					PKG 08-MAR-2018		
35.050	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
350001	OXYGEN PRESSURE TRANSDUCER PN	MOS		TSN:0			15-MAY-2003		
35.060	SN-UNKNOWN REF: AMM 35-10-08	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350011	OXYGEN SHUTOFF VALVE PN	MOS		TSN:0			15-MAY-2003		
35.070	SN-UNKNOWN REF: AMM 35-10-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
350101	OXYGEN BOTTLE 101-384207-13	MOS	180	TSN:10			11-DEC-2017	11-FEB-2032	
35.010	ALT281-37371 REF: AMM 35-10-04	HRS/MSC AFL		TSN:0 TSN:0			2005.3 1723		
	<b>LIFE LIMIT</b>								
351011	NO. 1 CREW STATION OXYGEN BOX PN	MOS		TSN:0			15-MAY-2003		
35.090	SN-UNKNOWN REF: AMM 35-10-10	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
351012	NO. 2 CREW STATION OXYGEN BOX PN	MOS		TSN:0			15-MAY-2003		
35.090	SN-UNKNOWN REF: AMM 35-10-10	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
351021	OVERBOARD DISCHARGE INDICATOR PN	MOS		TSN:0			15-MAY-2003		
35.100	SN-UNKNOWN REF: AMM 35-10-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
351031	OXYGEN PRESSURE GAUGE PN	MOS		TSN:0			15-MAY-2003		
35.110	SN-UNKNOWN REF: AMM 35-10-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351035	OXYGEN PRESSURE INDICATOR								
35.120	PN SN-UNKNOWN REF: AMM 35-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
352020	CABIN OXYGEN CONTROL SOLENOID VALVE								
35.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
LIMITS12	HYDROSTATIC TEST OXYGEN BOTTLE KEVLAR FIBER BOTTLE P/N 101-384200-11 (40 CUBIC-FEET)								
	101-384207-13 ALT281-37371 REF:	MOS HRS/MSC AFL	N/A				11-DEC-2017 2005.3 1723		
<b>MANDATORY</b>									
+ LIMITS13	HYDROSTATIC TEST OXYGEN BOTTLE KEVLAR FIBER BOTTLE P/N 101-384207-13 (77 CUBIC-FEET)								
35.010	101-384207-13 ALT281-37371 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				01-MAR-2017	<b>01-MAR-2022</b>	
LIMITS14	HYDROSTATIC TEST OXYGEN BOTTLE CARBON FIBER BOTTLE P/N 101-384207-23 (77 CUBIC-FEET)								
	101-384207-13 ALT281-37371 REF:	MOS HRS/MSC AFL	N/A				11-DEC-2017 2005.3 1723		
<b>MANDATORY</b>									
+ OPS39 (s)	FUNCTIONAL TEST OXYGEN SYSTEM								
35.010	PKG 6 REF: AMM 35-00-00	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
SPC14	#1 PASSENGER OXYGEN MASK								
35.130	174095-58 N/A REF: GENERIC NO REF	MOS HRS/MSC AFL	96	TSN:0 TSN:0 TSN:0			24-APR-2014 1615.5 1440	<b>24-APR-2022</b>	
<b>OVERHAUL</b>									
SPC14	#2 PASSENGER OXYGEN MASK								
35.130	174095-58 N/A REF: GENERIC NO REF	MOS HRS/MSC AFL	96	TSN:0 TSN:0 TSN:0			24-APR-2014 1615.5 1440	<b>24-APR-2022</b>	
<b>OVERHAUL</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
SPC14	#3 PASSENGER OXYGEN MASK								
35.140	174095-58	MOS	96	TSN:0			24-APR-2014	24-APR-2022	
<b>OVERHAUL</b>	N/A REF: GENERIC NO REF	HRS/MSC AFL		TSN:0 TSN:0			1615.5 1440		
SPC14	#4 PASSENGER OXYGEN MASK								
35.140	174095-58	MOS	96	TSN:0			24-APR-2014	24-APR-2022	
<b>OVERHAUL</b>	N/A REF: GENERIC NO REF	HRS/MSC AFL		TSN:0 TSN:0			1615.5 1440		
SPC14	#5 PASSENGER OXYGEN MASK								
35.150	174095-58	MOS	96	TSN:0			24-APR-2014	24-APR-2022	
<b>OVERHAUL</b>	N/A REF: GENERIC NO REF	HRS/MSC AFL		TSN:0 TSN:0			1615.5 1440		
SPC14	#6 PASSENGER OXYGEN MASK								
35.150	174095-58	MOS	96	TSN:0			24-APR-2014	24-APR-2022	
<b>OVERHAUL</b>	N/A REF: GENERIC NO REF	HRS/MSC AFL		TSN:0 TSN:0			1615.5 1440		
SPC14	LAVATORY PASSENGER OXYGEN MASK								
35.160	174095-58	MOS	96	TSN:0			24-APR-2014	24-APR-2022	
<b>OVERHAUL</b>	N/A REF: GENERIC NO REF	HRS/MSC AFL		TSN:0 TSN:0			1615.5 1440		
SPC26	NO. 1 CREW OXYGEN MASK OVERHAUL								
35.080	174252-13	MOS	72	TSO:0			23-APR-2014	23-APR-2020	
<b>OVERHAUL</b>	07245 REF: AMM 35-10-01	HRS/MSC AFL		TSO:0 TSO:0			1615.5 1440		
SPC26	NO. 2 CREW OXYGEN MASK OVERHAUL								
35.080	174252-13	MOS	72	TSO:0			23-APR-2014	23-APR-2020	
<b>OVERHAUL</b>	05700 REF: AMM 35-10-01	HRS/MSC AFL		TSO:0 TSO:0			1615.5 1440		
TBO06	OXYGEN REGULATOR								
35.010	172400-14	MOS	60	TSO:0			11-DEC-2017	11-DEC-2022	
<b>OVERHAUL</b>	3904 REF: GENERIC NO REF	HRS/MSC AFL		TSO:0 TSO:0			2005.3 1723		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
TBO07	REPLACE CABIN OXYGEN CONTROL SOLENOID VALVE O-RINGS								
35.040		MOS	48	+30d/-30d			08-MAR-2018 2033.9 1745	08-MAR-2022	07-APR-2022
	REF: GENERIC CMM	HRS/MSC AFL							
<b>CHAPTER 36</b>		<b>PNEUMATIC</b>							
361001	PNEUMATIC PRESSURE REGULATOR								
36.010	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 35-10-01	AFL			TSN:0		0		
SPC19	DRAIN MOISTURE FROM PNEUMATIC DRAIN LINE								
36.020		MOS	12				15-MAY-2019	15-MAY-2020	
		HRS/MSC	200	+20			2116.4	2316.4	2336.4
	REF: GENERIC NO REF	AFL					1810		
<b>CHAPTER 38</b>		<b>WATER/WASTE</b>							
200A06 (s)	INSPECT RELIEF TUBE						PKG		
	PKG 6	MOS					08-MAR-2018		
		HRS/MSC	600				2033.9		
	REF: GENERIC NO REF	AFL					1745		
<b>CHAPTER 39</b>		<b>ELECTRICAL PANELS, PARTS AND INSTRUMENTS</b>							
391001	NO. 1 FLIGHT GUIDANCE PANEL								
39.010	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
391002	NO. 2 FLIGHT GUIDANCE PANEL								
39.010	PN	MOS					15-MAY-2003		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
<b>CHAPTER 52</b>		<b>DOORS</b>							
+ 200C01	VISUAL/A-SCAN CHECK PASSENGER DOOR								
52.010		MOS					15-MAY-2003		
		HRS/MSC	2400	+200			0	2400	2600
<b>AIRWORTHINESS</b>	REF: AMM 52-10-01	AFL					0		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 200C03	VISUAL CHECK EMERGENCY EXIT HATCH								
52.040		MOS					15-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF: AMM 52-20-01</b>	HRS/MSC AFL	6000	+200			0 0	<b>6000</b>	6200
+ 200C06 (s)	VISUAL CHECK PASSENGER DOOR AND STEPS						PKG		
52.010	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	<b>REF: AMM 52-10-01</b>	HRS/MSC AFL							
+ 200C07 (s)	INSPECT PASSENGER DOOR LATCH MECHANISM						PKG		
52.010	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	<b>REF: AMM 52-10-01</b>	HRS/MSC AFL							
+ 200C08 (s)	INSPECT PASSENGER DOOR						PKG		
52.010	PKG 7	MOS	1200	+20/-20			14-MAR-2012 1254.5 1138		
	<b>REF: AMM 52-10-01</b>	HRS/MSC AFL							
+ 200C09 (s)	INSPECT FUSELAGE DOOR LAND						PKG		
52.010	PKG 6	MOS	600	+20/-20			08-MAR-2018 2033.9 1745		
	<b>REF: AMM 52-10-01</b>	HRS/MSC AFL							
+ 200C10 (s)	INSPECT EMERGENCY EXIT HATCH SEALS						PKG		
52.040	PKG 7	MOS	1200	+20/-20			14-MAR-2012 1254.5 1138		
	<b>REF: AMM 52-20-01</b>	HRS/MSC AFL							
+ 200C11 (s)	INSPECT EMERGENCY EXIT HATCH DOOR FRAME AND WINDOW INSTALLATION						PKG		
52.040	PKG 7	MOS	1200	+20/-20			14-MAR-2012 1254.5 1138		
	<b>REF: AMM 52-20-01</b>	HRS/MSC AFL							
+ 200C12 (s)	INSPECT EMERGENCY EXIT HATCH FUSELAGE OPENING PERIMETER						PKG		
52.040	PKG 7	MOS	1200	+20/-20			14-MAR-2012 1254.5 1138		
	<b>REF: AMM 52-20-01</b>	HRS/MSC AFL							

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 200C13 (s)	INSPECT EMERGENCY EXIT HATCH LATCHING MECHANISM						PKG		
52.040	PKG 7 REF: AMM 52-20-01	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 300A33 (s)	INSPECT AFT FUSELAGE BAGGAGE COMPARTMENT						PKG		
52.050	PKG 7 REF: AMM 52-30-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
521001	PASSENGER DOOR								
52.010	PN SN-UNKNOWN REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
521011	CABIN DOOR KEY								
52.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
522001	EMERGENCY EXIT HATCH								
52.040	PN SN-UNKNOWN REF: AMM 52-20-01	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
523001	AFT BAGGAGE & AVIONICS DOOR KEY								
52.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
523011	RIGHT AFT AVIONICS DOOR KEY								
52.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
524001	FORWARD BAGGAGE & AVIONICS DOOR KEY								
52.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
800A02 (s)	INSPECT AFT BAGGAGE DOOR, LATCH, SWITCHES AND SEALS						PKG		
52.150	PKG 6	MOS	600	+20/-20			08-MAR-2018		
	REF: AMM 52-30-00	HRS/MSC AFL					2033.9 1745		
800A03 (s)	INSPECT AFT AVIONICS DOOR, LATCH, SWITCHES AND SEALS						PKG		
52.150	PKG 6	MOS	600	+20/-20			08-MAR-2018		
	REF: AMM 52-30-00	HRS/MSC AFL					2033.9 1745		
800A04 (s)	INSPECT AFT BAGGAGE DOOR LATCH PINS (4 LOCATIONS)						PKG		
52.160	PKG 6	MOS	600	+20/-20			08-MAR-2018		
	REF: AMM 52-30-05	HRS/MSC AFL					2033.9 1745		
800A05 (s)	INSPECT AFT AVIONICS DOOR LATCH PINS (4 LOCATIONS)						PKG		
52.160	PKG 6	MOS	600	+20/-20			08-MAR-2018		
	REF: AMM 52-30-05	HRS/MSC AFL					2033.9 1745		
800A06 (s)	ADJUSTMENT/TEST FORWARD AND AFT BAGGAGE/AVIONICS DOORS						PKG		
52.170	PKG 6	MOS	600	+20/-20			08-MAR-2018		
	REF: AMM 52-70-00	HRS/MSC AFL					2033.9 1745		
+ 800A07	EDDY CURRENT INSPECT AFT BAGGAGE AND AVIONICS DOOR LATCH PINS (4 EACH SIDE)								
52.140		MOS	6000	+200			15-MAY-2003		
<b>AIRWORTHINESS</b>	REF: AMM 52-30-05	HRS/MSC AFL					0 0	<b>6000</b>	<b>6200</b>
+ OPS40 (s)	OPERATIONAL TEST PASSENGER DOOR WARNING SYSTEM						PKG		
52.030	PKG 7	MOS	1200	+20/-20			14-MAR-2012		
	REF: AMM 52-10-01	HRS/MSC AFL					1254.5 1138		
<b>CHAPTER 53</b>	<b>FUSELAGE</b>								
+ 100B08 (s)	INSPECT MOISTURE DRAIN HOLES AND VALVES						PKG		
53.010	PKG 7	MOS	1200	+20/-20			14-MAR-2012		
	REF: AMM 06-20-00	HRS/MSC AFL					1254.5 1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 100B09 (s)	INSPECT WING SPIGOT FITTING INTERIOR REINFORCEMENTS						PKG		
53.030	PKG 7	MOS					14-MAR-2012		
	REF: AMM 57-10-02	HRS/MSC	1200	+20/-20			1254.5		
		AFL					1138		
+ 100B10 (s)	INSPECT FORWARD AND AFT WING ATTACHMENT FITTINGS REINFORCEMENTS						PKG		
53.040	PKG 7	MOS					14-MAR-2012		
	REF: GENERIC NO REF	HRS/MSC	1200	+20/-20			1254.5		
		AFL					1138		
100B11 (s)	INSPECT/LUBRICATE WING SPIGOT						PKG		
53.330	PKG 6	MOS					08-MAR-2018		
	REF: See Workcard	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 100C01	INSPECT LEFT BAGGAGE COMPARTMENT FORWARD PRESSURE BULKHEAD								
53.050		MOS	96	+30d/-30d			14-MAR-2012	<b>14-MAR-2020</b>	13-APR-2020
<b>AIRWORTHINESS</b>	REF: AMM 53-10-01	HRS/MSC	2400	+200			1255	<b>3655</b>	3855
		AFL					1139		
+ 100C05 (s)	INSPECT LEFT BAGGAGE COMPARTMENT NOSE KEEL						PKG		
53.200	PKG 6	MOS					08-MAR-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 100D03	INSPECT RIGHT AVIONICS COMPARTMENT FORWARD PRESSURE BULKHEAD								
53.060		MOS	96	+30d/-30d			14-MAR-2012	<b>14-MAR-2020</b>	13-APR-2020
<b>AIRWORTHINESS</b>	REF: AMM 53-10-01	HRS/MSC	2400	+200			1255	<b>3655</b>	3855
		AFL					1139		
+ 100D04 (s)	INSPECT RIGHT AVIONICS COMPARTMENT NOSE KEEL						PKG		
53.210	PKG 6	MOS					08-MAR-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+20/-20			2033.9		
		AFL					1745		
+ 100E02 (s)	INSPECT FUSELAGE SKIN - STRUCTURAL DAMAGE						PKG		
53.070	PKG 7	MOS					14-MAR-2012		
	REF: GENERIC NO REF	HRS/MSC	1200	+20/-20			1254.5		
		AFL					1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 100E04 (s)	INSPECT RADOME DETERIORATION (REMOVED)						PKG		
53.240	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 100E05 (s)	INSPECT RADOME ANTENNA (REMOVED)						PKG		
53.240	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 200B01	VISUAL OF AFT PRESSURE BULKHEAD								
53.100 <b>AIRWORTHINESS</b>	REF: AMM 53-10-03	MOS HRS/MSC AFL	2400	+200			15-MAY-2003 0 0	<b>2400</b>	2600
+ 200B08 (s)	INSPECT FLOOR PANELS						PKG		
53.230	PKG 7 REF: AMM 06-50-01	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 200C02	VISUAL CHECK OF FORWARD FUSELAGE SHELL AND FORWARD TO AFT SPLICE								
53.080 <b>AIRWORTHINESS</b>	REF: AMM 53-10-02	MOS HRS/MSC AFL	2400	+200			15-MAY-2003 0 0	<b>2400</b>	2600
+ 200C15 (s)	INSPECT FUSELAGE SKIN						PKG		
53.110	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 200D10 (s)	INSPECT FUSELAGE AND WING ATTACHMENT FITTINGS						PKG		
53.120	PKG 6,7 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300A07	VISUAL CHECK OF AFT FUSELAGE SHEL								
53.130 <b>AIRWORTHINESS</b>	REF: AMM 53-30-03	MOS HRS/MSC AFL	2400	+200			15-MAY-2003 0 0	<b>2400</b>	2600

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300A10	EDDY CURRENT INSPECT VERTICAL TAIL AFT SPAR (BOLT REMOVAL REQUIRED)								
53.170	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	10000				15-MAY-2003 0 0	10000	
<b>AIRWORTHINESS</b>									
+ 300A37 (s)	INSPECT AFT FUSELAGE SKIN						PKG		
53.020	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 300A38 (s)	INSPECT FORWARD ENGINE CARRY-THROUGH BEAM						PKG		
53.180	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 300A40 (s)	INSPECT MOISTURE DRAIN PATH						PKG		
53.190	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
530001	PYLON ASSEMBLY								
53.260	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		
531001	FORWARD FUSELAGE ASSEMBLY								
53.270	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		
531011	NOSE STRUCTURE								
53.280	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		
531046	AFT FUSELAGE SHELL								
53.130	PN SN-UNKNOWN REF: AMM 53-30-02	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
531049	EMPENNAGE								
53.290	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
531050	EMPENNAGE FITTING								
53.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
531052	FORWARD CANTED BULKHEAD								
53.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
531055	AFT CANTED BULKHEAD								
53.160	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
531057	VERTICAL TAIL AFT SPAR								
53.170	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
532001	AFT PRESSURE BULKHEAD								
53.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
532011	COCKPIT FLOOR STRUCTURE								
53.300	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
532021	NO. 1 CABIN FLOOR STRUCTURE								
53.310	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
532022	NO. 2 CABIN FLOOR STRUCTURE								
53.310	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
533001	TAILCONE								
53.320	PN SN-UNKNOWN REF: AMM 53-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
535001	RADOME								
53.240	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		

## CHAPTER 54 NACELLES/PYLONS

+ 400A12 (s)	INSPECT NO. 1 ENGINE PYLON SKIN						PKG		
54.010	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 400A14 (s)	INSPECT NO. 1 ENGINE PYLON NACELLE SEAL						PKG		
54.020	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 400B12 (s)	INSPECT NO. 2 ENGINE PYLON SKIN						PKG		
54.010	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 400B14 (s)	INSPECT NO. 2 ENGINE PYLON NACELLE SEAL						PKG		
54.020	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		

## CHAPTER 55 STABILIZERS



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300B14 (s)	INSPECT VERTICAL STABILIZER SKIN AND LEADING EDGE						PKG		
55.030	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300B15 (s)	INSPECT FORWARD AND AFT DORSAL FIN						PKG		
55.040	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 300C15 (s)	INSPECT HORIZONTAL STABILIZER SKIN AND LEADING EDGE						PKG		
55.010	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
<b>CHAPTER 56 WINDOWS</b>									
+ 100E07	VISUAL/EDDY CURRENT INSPECT FRONT AND SIDE WINDSHIELD CLAMPS								
56.010 <b>AIRWORTHINESS</b>	REF: AMM 56-00-00	MOS HRS/MSC AFL	6000	+200			15-MAY-2003 0 0	<b>6000</b>	6200
+ 100E08	VISUAL CHECK WINDSHIELDS AND WINDOWS								
56.020 <b>AIRWORTHINESS</b>	REF: AMM 56-00-00	MOS HRS/MSC AFL	2400	+200			15-MAY-2003 0 0	<b>2400</b>	2600
+ 100E09 (s)	INSPECT WINDSHIELD FRAMES						PKG		
56.030	PKG 6 REF: AMM 56-00-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 200C18 (s)	INSPECT CABIN WINDOW						PKG		
56.040	PKG 6 REF: AMM 56-00-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
561001	LEFT WINDSHIELD ASSY								
56.050	PN SN-UNKNOWN REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C				15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561002	RIGHT WINDSHIELD ASSY								
56.050	PN SN-UNKNOWN REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
561011	LEFT COCKPIT SIDE WINDOW								
56.060	PN SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
561012	RIGHT COCKPIT SIDE WINDOW								
56.060	PN SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
<b>CHAPTER 57 WINGS</b>									
+ 200C14 (s)	INSPECT WING FUSELAGE FAIRINGS						PKG		
57.010	PKG 6 REF: AMM 06-50-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 500A01	EDDY CURRENT LEFT WING CENTER LINE RIB AND SPLICE PLATE								
57.020	REF: AMM 57-10-01	MOS HRS/MSC AFL	216 6000	+30d/-30d +200			15-MAY-2003 0 0	15-MAY-2021 6000	14-JUN-2021 6200
+ 500A02	VISUAL INSPECT LEFT WING BOLTS AND ATTACH LINKS								
57.040	REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+200			15-JUL-2019 2116.4 1810	3316.4	3516.4
+ 500A03	BORESCOPE LEFT WING AND FUSELAGE SPIGOT FITTINGS								
57.030	REF: AMM 57-10-02	MOS HRS/MSC AFL	14400				15-MAY-2003 0 0	14400	
+ 500A04	VISUAL INSPECT LEFT WING AUXILIARY SPAR AND BULKHEAD ATTACHMENT FITTINGS								
57.050	REF: GENERIC NO REF	MOS HRS/MSC AFL	216 6000	+30d/-30d +200			15-MAY-2003 0 0	15-MAY-2021 6000	14-JUN-2021 6200
<b>AIRWORTHINESS</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 500A08 (s)	INSPECT NO. 1 WING TIP ASSEMBLY PKG 6	MOS					PKG 08-MAR-2018		
57.120	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 500A09 (s)	INSPECT LEFT WING LEADING EDGE PKG 6	MOS					PKG 08-MAR-2018		
57.130	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
500A12	PERFORM NDI(EDDY CURRENT) OF LEFT LOWER WING SKIN JACK PAD HOLE LOCATION THRU SPAR FLANGE	MOS					15-MAY-2003		
	REF: AMM 57-10-03	HRS/MSC AFL	3600				0 0	3600	
+ 500B01	EDDY CURRENT LEFT WING SPARS 1 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
57.160	REF: GENERIC NO REF	HRS/MSC AFL	12000	+20/-20			0 0	12000	12020
<b>AIRWORTHINESS</b>									
+ 500B03	EDDY CURRENT LEFT WING SPARS 3 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
	REF: AMM 20-26-00	HRS/MSC AFL	6000	+20/-20			0 0	6000	6020
<b>AIRWORTHINESS</b>									
+ 500B04	EDDY CURRENT LEFT WING SPARS 4 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
	REF: AMM 20-26-00	HRS/MSC AFL	12000	+20/-20			0 0	12000	12020
<b>AIRWORTHINESS</b>									
+ 500B05	EDDY CURRENT LEFT WING SPARS 5 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
	REF: AMM 20-26-00	HRS/MSC AFL	12000	+20/-20			0 0	12000	12020
<b>AIRWORTHINESS</b>									
+ 500B06	EDDY CURRENT LEFT WING SPARS 6 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
	REF: See Workcard	HRS/MSC AFL	6000	+20/-20			0 0	6000	6020
<b>AIRWORTHINESS</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 500C14 (s)	INSPECT LEFT WING FLAP TRACKS PKG 6	MOS					PKG		
57.150	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 500D07 (s)	INSPECT LEFT WING RIBS, SPARS, STRINGERS AND SKINS PKG 7	MOS					PKG		
57.080	REF: GENERIC NO REF	HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 500D08 (s)	INSPECT LEFT WING RIB AT BL 00 PKG 7	MOS					PKG		
57.090	REF: GENERIC NO REF	HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
500D09 (s)	INSPECT LEFT WING FUEL STORAGE SEALANT PKG 7	MOS					PKG		
57.190	REF:	HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
571001	NO. 1 SKELETON WING ASSEMBLY PN	MOS							
57.180	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
571002	NO. 2 SKELETON WING ASSEMBLY PN	MOS							
57.180	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
572001	NO. 1 WING TIP ASSEMBLY PN	MOS							
57.120	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
572002	NO. 2 WING TIP ASSEMBLY PN	MOS							
57.120	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
573001	NO. 1 WING PANEL ASSEMBLY								
57.170	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
573002	NO. 2 WING PANEL ASSEMBLY								
57.170	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
+ 600A01	EDDY CURRENT RIGHT WING CENTERLINE RIB AND SPLICE PLATE								
57.020	REF: AMM 57-10-01	MOS HRS/MSC AFL	216 6000	+30d/-30d +200			15-MAY-2003 0 0	15-MAY-2021 6000	14-JUN-2021 6200
+ 600A02	VISUAL CHECK RIGHT WING BOLTS AND ATTACH LINKS								
57.040	REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+200			15-JUL-2019 2116.4 1810	3316.4	3516.4
+ 600A03	VISUAL INSPECT RIGHT WING AUXILIARY SPAR AND BULKHEAD ATTACHMENT FITTINGS								
57.050	REF: GENERIC NO REF	MOS HRS/MSC AFL	216 6000	+30d/-30d +200			15-MAY-2003 0 0	15-MAY-2021 6000	14-JUN-2021 6200
<b>AIRWORTHINESS</b>									
+ 600A07 (s)	INSPECT NO. 2 WING TIP ASSEMBLY								
57.120	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
+ 600A08 (s)	INSPECT RIGHT WING LEADING EDGE								
57.130	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			PKG 08-MAR-2018 2033.9 1745		
600A11	PERFORM NDI(EDDY CURRENT) OF RIGHT LOWER WING SKIN JACK PAD HOLE LOCATION THRU SPAR FLANGE								
	REF: AMM 57-10-03	MOS HRS/MSC AFL	3600				15-MAY-2003 0 0	3600	

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 600B01	EDDY CURRENT RIGHT WING SPARS 1 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
57.160		HRS/MSC	12000	+20/-20			0	12000	12020
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 600B02	EDDY CURRENT RIGHT WING SPARS 2 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
		HRS/MSC	6000	+20/-20			0	6000	6020
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 600B03	EDDY CURRENT RIGHT WING SPARS 3 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
		HRS/MSC	6000	+20/-20			0	6000	6020
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
600B04	EDDY CURRENT RIGHT WING SPARS 4 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
		HRS/MSC	12000	+20/-20			0	12000	12020
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 600B05	EDDY CURRENT RIGHT WING SPARS 5 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
		HRS/MSC	12000	+20/-20			0	12000	12020
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
+ 600B06	EDDY CURRENT RIGHT WING SPARS 6 (WSTA 50.50 TO 90.00)	MOS					15-MAY-2003		
		HRS/MSC	6000	+20/-20			0	6000	6020
	<b>REF:</b> AMM 57-00-00	AFL					0		
+ 600C14 (s)	INSPECT RIGHT WING FLAP TRACKS						PKG		
57.150	PKG 6	MOS					08-MAR-2018		
		HRS/MSC	600	+20/-20			2033.9		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					1745		
+ 600D07 (s)	INSPECT RIGHT WING RIBS, SPARS, STRINGERS AND SKINS						PKG		
57.080	PKG 7	MOS					14-MAR-2012		
		HRS/MSC	1200	+20/-20			1254.5		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					1138		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 600D08 (s)	INSPECT RIGHT WING RIB AT BL 00						PKG		
57.090	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
600D09 (s)	INSPECT RIGHT WING FUEL STORAGE SEALANT						PKG		
57.190	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 700B19 (s)	INSPECT LEFT WING SKID RAIL STRUCTURE						PKG		
57.110	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 700B20 (s)	INSPECT LEFT MAIN GEAR STRUT TRUNNION AND WING TRUNNION						PKG		
57.100	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 700C19 (s)	INSPECT RIGHT MAIN GEAR STRUT TRUNNION AND WING TRUNNION						PKG		
57.100	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ SPC20	CHECK LEFT WING LEADING EDGE DRAIN HOLES								
57.140	REF:	MOS HRS/MSC AFL	12 200	+20			15-MAY-2019 2116.4 1810	15-MAY-2020 2316.4	2336.4
+ SPC20	CHECK RIGHT WING LEADING EDGE DRAIN HOLES								
57.140	REF:	MOS HRS/MSC AFL	12 200	+20			15-MAY-2019 2116.4 1810	15-MAY-2020 2316.4	2336.4
<b>CHAPTER 71 POWER PLANT</b>									
+ 300A44	VISUAL/EDDY CURRENT INSPECT NO. 1 AFT NO. 1 ENGINE AFT FITTING								
71.070	REF: AMM 54-50-01	MOS HRS/MSC AFL	12000	+200			15-MAY-2003 0 0	12000	12200
<b>AIRWORTHINESS</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300A44	VISUAL/EDDY CURRENT INSPECT NO. 1 FORWARD NO. 1 ENGINE FORWARD FITTING								
71.060		MOS					15-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 54-50-01	HRS/MSC AFL	12000	+200			0 0	<b>12000</b>	12200
+ 300A44	VISUAL/EDDY CURRENT INSPECT NO. 2 AFT NO. 2 ENGINE AFT FITTING								
71.070		MOS					15-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 54-50-01	HRS/MSC AFL	12000	+200			0 0	<b>12000</b>	12200
+ 300A44	VISUAL/EDDY CURRENT INSPECT NO. 2 FORWARD NO. 2 ENGINE FORWARD FITTING								
71.060		MOS					15-MAY-2003		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 54-50-01	HRS/MSC AFL	12000	+200			0 0	<b>12000</b>	12200
+ 400A08 (s)	INSPECT NO. 1 ENGINE PYLON FIRE WALL						PKG		
71.030	PKG 7	MOS					14-MAR-2012		
	<b>REF:</b> AMM 71-00-00	HRS/MSC AFL	1200	+20/-20			1254.5 1138		
+ 400A13 (s)	INSPECT NO. 1 ENGINE BLEED AIR DUCTS						PKG		
71.040	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b>	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 400A15 (s)	INSPECT NO. 1 ENGINE ISOLATOR MOUNTS						PKG		
71.110	PKG 7	MOS					14-MAR-2012		
	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	1200	+20/-20			1254.5 1138		
+ 400A16 (s)	INSPECT NO. 1 ENGINE INLET						PKG		
71.120	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		
+ 400A17 (s)	CHECK NO. 1 ENGINE ASSESSORY DRAIN TUBES						PKG		
71.140	PKG 6	MOS					08-MAR-2018		
	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	600	+20/-20			2033.9 1745		



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
400A35 (s)	VISUALLY INSPECT LEFT ENGINE LINES, TUBES, CABLES AND HARNESSSES						PKG		
05.030	PKG 6 REF: AMM 71-00-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 400B08 (s)	INSPECT NO. 2 ENGINE PYLON FIRE WALL						PKG		
71.030	PKG 7 REF: AMM 71-00-00	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 400B13 (s)	INSPECT NO. 2 ENGINE BLEED AIR DUCTS						PKG		
71.040	PKG 6 REF:	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 400B15 (s)	INSPECT NO. 2 ENGINE ISOLATOR MOUNTS						PKG		
71.110	PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+20/-20			14-MAR-2012 1254.5 1138		
+ 400B16 (s)	INSPECT NO. 2 ENGINE INLET						PKG		
71.120	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 400B17 (s)	CHECK NO. 2 ENGINE ASSESSORY DRAIN TUBES						PKG		
71.140	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
400B33 (s)	VISUALLY INSPECT RIGHT ENGINE LINES, TUBES, CABLES AND HARNESSSES						PKG		
05.030	PKG 6 REF: AMM 71-00-00	MOS HRS/MSC AFL	600	+20/-20			08-MAR-2018 2033.9 1745		
+ 710121	NO. 1 ENGINE UPPER FORWARD ISOLATOR MOUNT								
71.080	PN SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC AFL	2500		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		2500
<b>MANDATORY</b>									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710122	NO. 2 ENGINE UPPER FORWARD ISOLATOR MOUNT								
71.080	PN SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC AFL	2500	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0	2500	
710123	NO. 1 ENGINE LOWER FORWARD ISOLATOR MOUNT								
71.090	PN SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC AFL	2500	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0	2500	
710124	NO. 2 ENGINE LOWER FORWARD ISOLATOR MOUNT								
71.090	PN SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC AFL	2500	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0	2500	
710125	NO. 1 ENGINE AFT ISOLATOR MOUNT								
71.095	PN SN-UNKNOWN REF: AMM 71-20-02	MOS HRS/MSC AFL	2500	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0	2500	
710126	NO. 2 ENGINE AFT ISOLATOR MOUNT								
71.095	PN SN-UNKNOWN REF: AMM 71-20-02	MOS HRS/MSC AFL	2500	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0	2500	
716001	NO. 1 ENGINE INLET ASSEMBLY								
71.120	PN SN-UNKNOWN REF: AMM 71-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
716002	NO. 2 ENGINE INLET ASSEMBLY								
71.120	PN SN-UNKNOWN REF: AMM 71-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	56000 105043 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C	TSN:0 TSN:0 TSN:0			07-FEB-2003 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN2	NO. 2 ENGINE								
71.EN2	56000 105044 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C	TSN:0 TSN:0 TSN:0			07-FEB-2003 0 0		
LIMITS11	REPLACE LEFT ENGINE HYDRAULIC PUMP (P/N 390-580035-1 OR P/N 390-580035-5) TUBE								
29.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
OPS41	PERFORM NO. 1 ENGINE PERFORM WILLIAMS INTERNATIONAL CHECK 1 AND PERFORM A LEAK CHECK OF THE HYDRAULIC PACK								
	REF:	MOS HRS/MSC AFL	300	+20			29-MAY-2017 1955.7 1689	2255.7	2275.7
OPS41	PERFORM NO. 2 ENGINE PERFORM WILLIAMS INTERNATIONAL CHECK 1 AND PERFORM A LEAK CHECK OF THE HYDRAULIC PACK								
	REF:	MOS HRS/MSC AFL	300	+20			29-MAY-2017 1955.7 1689	2255.7	2275.7
<b>CHAPTER 72 ENGINE</b>									
ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000									
722010	NO. 1 ENGINE - IP (STAGE 1&2) VANE ASSEMBLY								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723001	NO. 1 ENGINE - FAN ROTOR								
LIFE LIMIT	65502 AU00225 REF: See Workcard	MOS HRS/MSC ENC	10000	TSN:1296			13-MAY-2013 1440.3 1296	(10000)	10009
+ 723003 (s)	NO. 1 ENGINE - PHYSICALLY INSPECT FAN ROTOR FOR DAMAGE AND CLEANLINESS (FEEL WITH FINGERS)						PKG		
	65502 PKG 2 AU00225 REF: LM 72-31-20	MOS HRS/MSC ENC	600	+30/-30			08-MAR-2018 2033.9 1736		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723010	NO. 1 ENGINE - HP COMPRESSOR ROTOR 61964 HW13517	MOS HRS/MSC ENC					13-MAY-2013 1440.3 1296		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF		6000	TSN:1296				<b>(6000) 6009</b>	
723015	NO. 1 ENGINE - IP COMPRESSOR ROTOR 61968 AU01554	MOS HRS/MSC ENC					13-MAY-2013 1440.3 1296		
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF		8000	TSN:1296				<b>(8000) 8009</b>	
723019	NO. 1 ENGINE - INTERSTAGE HOUSING ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
<b>REF:</b> GENERIC NO REF									
723021 (s)	NO. 1 ENGINE - VISUALLY INSPECT THE INSTALLED SPINNER PKG 2	MOS HRS/MSC ENC	600	+30/-30			PKG 08-MAR-2018 2033.9 1736		
<b>REF:</b> LM 72-30-10									
723022	NO. 1 ENGINE - DIFFUSER CASE ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
<b>REF:</b> GENERIC NO REF									
723028	NO. 1 ENGINE - BEARING NO.1 HOUSING PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
<b>REF:</b> GENERIC NO REF									
723036	NO. 1 ENGINE - STAGE 3 IP ROTOR STATOR PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
<b>REF:</b> GENERIC NO REF									
723037	NO. 1 ENGINE - FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
<b>REF:</b> GENERIC NO REF									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723061	NO. 1 ENGINE - HIGH PRESSURE SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723092	NO. 1 ENGINE - COMPLETE LP SHAFT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
724035	NO. 1 ENGINE - HP TURBINE COMBUSTER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
724036	NO. 1 ENGINE - COMBUSTION COVER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
724040	NO. 1 ENGINE - REAR FUEL SLINGER SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
724045	NO. 1 ENGINE - SEAL AND FUEL SLINGER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
725010	NO. 1 ENGINE - HP TURBINE DISK 59387 RRL7LD13005 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	TSN:1296			13-MAY-2013 1440.3 1296	(8000) 8009	
725016	NO. 1 ENGINE - NOZZLE, 2ND LP TURBINE HOUSING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725020	NO. 1 ENGINE - 1ST LP TURBINE DISK 55531 RRL7S02724	MOS HRS/MSC ENC	10000	TSN:1296			13-MAY-2013 1440.3 1296	(10000) 10009	
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF								
725030	NO. 1 ENGINE - 2ND LP TURBINE DISK 55534 RRL7S02707	MOS HRS/MSC ENC	10000	TSN:1296			13-MAY-2013 1440.3 1296	(10000) 10009	
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF								
726011	NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
<b>REF:</b> See Workcard									
<b>ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000</b>									
722010	NO. 2 ENGINE - IP (STAGE 1&2) VANE ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
<b>REF:</b> GENERIC NO REF									
723001	NO. 2 ENGINE - FAN ROTOR 65502 AU00226	MOS HRS/MSC ENC	10000	TSN:1296			13-MAY-2013 1440.3 1296	(10000) 10009	
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard								
+ 723003 (s)	NO. 2 ENGINE - PHYSICALLY INSPECT FAN ROTOR FOR DAMAGE AND CLEANLINESS (FEEL WITH FINGERS) 65502 PKG 2 AU00226	MOS HRS/MSC ENC	600	+30/-30			PKG 08-MAR-2018 2033.9 1736		
<b>REF:</b> LM 72-31-20									
723010	NO. 2 ENGINE - HP COMPRESSOR ROTOR 61964 HW14042	MOS HRS/MSC ENC	6000	TSN:1296			13-MAY-2013 1440.3 1296	(6000) 6009	
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF								
723015	NO. 2 ENGINE - IP COMPRESSOR ROTOR 61968 AU01584	MOS HRS/MSC ENC	8000	TSN:1296			13-MAY-2013 1440.3 1296	(8000) 8009	
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF								

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723019	NO. 2 ENGINE - INTERSTAGE HOUSING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723021 (s)	NO. 2 ENGINE - VISUALLY INSPECT THE INSTALLED SPINNER PKG 2 REF: LM 72-30-10	MOS HRS/MSC ENC	600	+30/-30			PKG 08-MAR-2018 2033.9 1736		
723022	NO. 2 ENGINE - DIFFUSER CASE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723028	NO. 2 ENGINE - BEARING NO.1 HOUSING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723036	NO. 2 ENGINE - STAGE 3 IP ROTOR STATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723037	NO. 2 ENGINE - FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723061	NO. 2 ENGINE - HIGH PRESSURE SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
723092	NO. 2 ENGINE - COMPLETE LP SHAFT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724035	NO. 2 ENGINE - HP TURBINE COMBUSTER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
724036	NO. 2 ENGINE - COMBUSTION COVER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
724040	NO. 2 ENGINE - REAR FUEL SLINGER SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
724045	NO. 2 ENGINE - SEAL AND FUEL SLINGER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
725010	NO. 2 ENGINE - HP TURBINE DISK 59387 RRL7LD12185 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	TSN:1296			13-MAY-2013 1440.3 1296	(8000) 8009	
725016	NO. 2 ENGINE - NOZZLE, 2ND LP TURBINE HOUSING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
725020	NO. 2 ENGINE - 1ST LP TURBINE DISK 55531 RRL7S02745 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:1296			13-MAY-2013 1440.3 1296	(10000) 10009	
725030	NO. 2 ENGINE - 2ND LP TURBINE DISK 55534 RRL7S02770 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:1296			13-MAY-2013 1440.3 1296	(10000) 10009	



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726011	NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY								
	PN	MOS		TSN:0			11-OCT-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
732001	NO. 1 ENGINE ECU								
	PN	MOS		TSN:0			15-MAY-2003		
73.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 73-20-01	AFL		TSN:0			0		
732002	NO. 2 ENGINE ECU								
	PN	MOS		TSN:0			15-MAY-2003		
73.050	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 73-20-01	AFL		TSN:0			0		
733001	NO. 1 ENGINE FUEL FLOW TRANSMITTER								
	PN	MOS		TSN:0			15-MAY-2003		
73.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 73-30-01	AFL		TSN:0			0		
733002	NO. 2 ENGINE FUEL FLOW TRANSMITTER								
	PN	MOS		TSN:0			15-MAY-2003		
73.010	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 73-30-01	AFL		TSN:0			0		
TBO04	NO. 1 ENGINE DRIVEN HIGH PRESSURE FUEL PUMP								
	PN	MOS		TSN:0			15-MAY-2003		
73.020	SN-UNKNOWN	HRS/MSC	3500	TSN:0			0		3500
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL		TSN:0			0		
TBO04	NO. 2 ENGINE DRIVEN HIGH PRESSURE FUEL PUMP								
	PN	MOS		TSN:0			15-MAY-2003		
73.030	SN-UNKNOWN	HRS/MSC	3500	TSN:0			0		3500
<b>OVERHAUL</b>	REF: GENERIC NO REF	AFL		TSN:0			0		
ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000									

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731001	NO. 1 ENGINE - FUEL PUMP 59863 YYK0164 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	4000	+100			15-MAY-2003 0 0	(4000) 4000	4100
<b>OVERHAUL</b>									
+ 731010 (s)	NO. 1 ENGINE - VISUALLY INSPECT AND CLEAN FUEL START NOZZLE AND START NOZZLE ADAPTER PKG 1 ,2 <b>REF:</b> LM 73-12-01	MOS HRS/MSC ENC	300	+30			08-MAR-2018 2033.9 1736		
+ 731015 (s)	NO. 1 ENGINE - CHECK FUEL START NOZZLE SPRAY PATTERN PKG 1 ,2 <b>REF:</b> LM 73-12-01	MOS HRS/MSC ENC	300	+30			08-MAR-2018 2033.9 1736		
731020 (s)	NO. 1 ENGINE - REPLACE UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY AND HMU-TO-OIL COOLER FUEL TUBE ASSEMBLY (RENTAL ENGINES ONLY) PKG 2 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	A/R				08-MAR-2018 2033.9 1736		
731025 (s)	NO. 1 ENGINE - CHANGE FUEL PUMP FILTER <b>REF:</b> See Workcard	MOS HRS/MSC ENC	600	+30			08-MAR-2018 2033.9 1736		
731046	NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C				11-OCT-2002 0 0		
732101	NO. 1 ENGINE - ELECTRONIC CONTROL UNIT 63256 LH2A0218 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	O/C				11-AUG-2011 TSO:0 TSO:0 TSO:0		
732104 (s)	NO. 1 ENGINE - PERFORM ECU P AMBIENT CHECK PKG 2 <b>REF:</b> LM 73-24-01	MOS HRS/MSC ENC	600	+30/-30			08-MAR-2018 2033.9 1736		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 732105 (s)	NO. 1 ENGINE - OPERATIONAL CHECK 63256 PKG 1 ,2 LH2A0218 REF: LM 71-00-00	ELECTRONIC CONTROL UNIT OF THE EFCU IN MANUAL MODE MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
732401	NO. 1 ENGINE - FUEL CONTROL (HMU) UNIT 8063-735 RF13180845 REF: See Workcard	MOS HRS/MSC ENC	4000	+100	TSN:1853.4		23-SEP-2016 1853.4 1610	(4000) 4000	4100
<b>OVERHAUL</b>									
<b>ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000</b>									
731001	NO. 2 ENGINE - FUEL PUMP 59863 YYK0186 REF: See Workcard	MOS HRS/MSC ENC	4000	+100	TSO:0 TSO:0 TSO:0		15-MAY-2003 0 0	(4000) 4000	4100
<b>OVERHAUL</b>									
+ 731010 (s)	NO. 2 ENGINE - VISUALLY INSPECT AND CLEAN FUEL START NOZZLE AND START NOZZLE ADAPTER PKG 1 ,2 REF: LM 73-12-01	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
+ 731015 (s)	NO. 2 ENGINE - CHECK FUEL START NOZZLE SPRAY PATTERN PKG 1 ,2 REF: LM 73-12-01	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
731020 (s)	NO. 2 ENGINE - REPLACE UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY AND HMU-TO-OIL COOLER FUEL TUBE ASSEMBLY (RENTAL ENGINES ONLY) PKG 2 REF: See Workcard	MOS HRS/MSC ENC	A/R				PKG 08-MAR-2018 2033.9 1736		
731025 (s)	NO. 2 ENGINE - CHANGE FUEL PUMP FILTER REF: See Workcard	MOS HRS/MSC ENC	600	+30			08-MAR-2018 2033.9 1736		
731046	NO. 2 ENGINE - FUEL MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732101	NO. 2 ENGINE - ELECTRONIC CONTROL UNIT 63256 LH2A0166 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			11-AUG-2011		
732104 (s)	NO. 2 ENGINE - PERFORM ECU P AMBIENT CHECK PKG 2 REF: LM 73-24-01	MOS HRS/MSC ENC	600	+30/-30			PKG 08-MAR-2018 2033.9 1736		
+ 732105 (s)	NO. 2 ENGINE - OPERATIONAL CHECK ELECTRONIC CONTROL UNIT OF THE EFCU IN MANUAL MODE 63256 PKG 1 ,2 LH2A0166 REF: LM 71-00-00	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
732401	NO. 2 ENGINE - FUEL CONTROL (HMU) UNIT 8063-735 RF13104225 REF: See Workcard	MOS HRS/MSC ENC	4000	+100	TSN:1853.4		23-SEP-2016 1853.4 1610	(4000) 4000	4100
<b>OVERHAUL</b>									
<b>CHAPTER 74 IGNITION</b>									
ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000									
741010	NO. 1 ENGINE - INBOARD IGNITION EXCITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
741020	NO. 1 ENGINE - OUTBOARD IGNITION EXCITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2002 0 0		
+ 742037 (s)	NO. 1 ENGINE - REMOVE/VISUALLY INSPECT IGNITER PLUGS PKG 1 ,2 REF: LM 74-22-01	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 742040 (s)	NO. 1 ENGINE - OPERATIONAL TEST PKG 1,2 REF: LM 74-00-10	IGNITION SYSTEM MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
742050 (s)	NO. 1 ENGINE - DIMENSIONALLY INSPECT PKG 1,2 REF: See Workcard	IGNITER PLUGS MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
742201	NO. 1 ENGINE - INBOARD IGNITOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		
742202	NO. 1 ENGINE - OUTBOARD IGNITOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		
ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000									
741010	NO. 2 ENGINE - INBOARD IGNITION EXCITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		
741020	NO. 2 ENGINE - OUTBOARD IGNITION EXCITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		
+ 742037 (s)	NO. 2 ENGINE - REMOVE/VISUALLY INSPECT PKG 1,2 REF: LM 74-22-01	IGNITER PLUGS MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
+ 742040 (s)	NO. 2 ENGINE - OPERATIONAL TEST PKG 1,2 REF: LM 74-00-10	IGNITION SYSTEM MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742050 (s)	NO. 2 ENGINE - DIMENSIONALLY INSPECT PKG 1 ,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
742201	NO. 2 ENGINE - INBOARD IGNITOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		
742202	NO. 2 ENGINE - OUTBOARD IGNITOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		

**CHAPTER 75 AIR**

751001	NO. 1 ENGINE ANTI ICE VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		
751002	NO. 2 ENGINE ANTI ICE VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-MAY-2003 0 0		

**ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000**

+ 753010 (s)	NO. 1 ENGINE - INSPECT ACCELERATION BLEED SYSTEM PKG 2 REF: LM 75-30-01	MOS HRS/MSC ENC	600	+30/-30			PKG 08-MAR-2018 2033.9 1736		
753020	NO. 1 ENGINE - HP COMPRESSOR COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		11-OCT-2002 0 0		

**ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000**

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753010 (s)	NO. 2 ENGINE - INSPECT ACCELERATION BLEED SYSTEM PKG 2	MOS					PKG 08-MAR-2018 2033.9 1736		
	REF: LM 75-30-01	HRS/MSC ENC	600	+30/-30					
753020	NO. 2 ENGINE - HP COMPRESSOR COVER ASSY PN SN-UNKNOWN	MOS					11-OCT-2002 0 0		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0					
<b>CHAPTER 76 ENGINE CONTROLS</b>									
+ 100A09 (s)	INSPECT POWER CONTROL CABLES - COCKPIT SECTION-BELOW FLOORS PKG 7	MOS					PKG 14-MAR-2012 1254.5 1138		
76.030	REF: GENERIC NO REF	HRS/MSC AFL	1200	+20/-20					
+ 200A13 (s)	INSPECT THRUST LEVER/THROTTLE QUADRANT LEVER PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
76.010	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20					
+ 200A14 (s)	INSPECT POWER CONTROL CABLES - COCKPIT SECTION-ABOVE FLOORS PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
76.040	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20					
+ 300A39 (s)	INSPECT POWER CONTROL CABLES - AFT FUSELAGE PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
76.050	REF: GENERIC NO REF	HRS/MSC AFL	600	+20/-20					
+ 400A18 (s)	CHECK NO. 1 ENGINE POWER CONTROL CABLE PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
76.020	REF: AMM 76-10-02	HRS/MSC AFL	600	+20/-20					
+ 400B18 (s)	CHECK NO. 2 ENGINE POWER CONTROL CABLE PKG 6	MOS					PKG 08-MAR-2018 2033.9 1745		
76.020	REF: AMM 76-10-02	HRS/MSC AFL	600	+20/-20					

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 77 ENGINE INDICATING</b>									
<b>ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000</b>									
771005	NO. 1 ENGINE - N1 DUAL MAGNETIC SPEED SENSOR								
	PN	MOS		TSN:0				11-OCT-2002	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: GENERIC NO REF	ENC		TSN:0				0	
771015	NO. 1 ENGINE - N2 DUAL MAGNETIC SPEED SENSOR								
	PN	MOS		TSN:0				11-OCT-2002	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: GENERIC NO REF	ENC		TSN:0				0	
772005	NO. 1 ENGINE - TT2 SENSOR								
	PN	MOS		TSN:0				11-OCT-2002	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: See Workcard	ENC		TSN:0				0	
+ 772010 (s)	NO. 1 ENGINE - INSPECT/FUNCTIONAL CHECK TT2 SENSOR HEATER ELEMENT								
	PN PKG 1 ,2	MOS						PKG	
	SN-UNKNOWN	HRS/MSC	300	+30/-30				08-MAR-2018	
	REF: See Workcard	ENC						2033.9	
								1736	
<b>ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000</b>									
771005	NO. 2 ENGINE - N1 DUAL MAGNETIC SPEED SENSOR								
	PN	MOS		TSN:0				11-OCT-2002	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: GENERIC NO REF	ENC		TSN:0				0	
771015	NO. 2 ENGINE - N2 DUAL MAGNETIC SPEED SENSOR								
	PN	MOS		TSN:0				11-OCT-2002	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: GENERIC NO REF	ENC		TSN:0				0	
772005	NO. 2 ENGINE - TT2 SENSOR								
	PN	MOS		TSN:0				11-OCT-2002	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: See Workcard	ENC		TSN:0				0	



# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 772010 (s)	NO. 2 ENGINE - INSPECT/FUNCTIONAL CHECK PN PKG 1 ,2 SN-UNKNOWN REF: See Workcard	TT2 SENSOR		HEATER ELEMENT			PKG 08-MAR-2018 2033.9 1736		
<b>CHAPTER 78 EXHAUST</b>									
781001	NO. 1 ENGINE EXHAUST NOZZLE ASSEMBLY PN SN-UNKNOWN REF: AMM 78-10-01	MOS HRS/MSC AFL					TSN:0 TSN:0 TSN:0	15-MAY-2003 0 0	
78.020		O/C							
781002	NO. 2 ENGINE EXHAUST NOZZLE ASSEMBLY PN SN-UNKNOWN REF: AMM 78-10-01	MOS HRS/MSC AFL					TSN:0 TSN:0 TSN:0	15-MAY-2003 0 0	
78.020		O/C							
<b>CHAPTER 79 OIL</b>									
793001	NO. 1 ENGINE OIL PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 79-30-01	MOS HRS/MSC AFL					TSN:0 TSN:0 TSN:0	15-MAY-2003 0 0	
79.010		O/C							
793002	NO. 2 ENGINE OIL PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 79-30-01	MOS HRS/MSC AFL					TSN:0 TSN:0 TSN:0	15-MAY-2003 0 0	
79.010		O/C							
793003	NO. 1 ENGINE OIL TEMPERATURE BULB PN SN-UNKNOWN REF: AMM 79-30-03	MOS HRS/MSC AFL					TSN:0 TSN:0 TSN:0	15-MAY-2003 0 0	
79.020		O/C							
793004	NO. 2 ENGINE OIL TEMPERATURE BULB PN SN-UNKNOWN REF: AMM 79-30-03	MOS HRS/MSC AFL					TSN:0 TSN:0 TSN:0	15-MAY-2003 0 0	
79.020		O/C							

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793005	NO. 1 ENGINE OIL PRESSURE TRANSDUCER								
79.030	PN SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
793006	NO. 2 ENGINE OIL PRESSURE TRANSDUCER								
79.030	PN SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-MAY-2003 0 0		
<b>ENGINE NO. 1 Model : FJ44-2A Serial # 105043 Part # 56000</b>									
+ 792010 (s)	NO. 1 ENGINE - REMOVE OIL FILTER AND SUBMIT FOR ANALYSIS						PKG		
	PKG 1 ,2 REF: LM 72-00-05	MOS HRS/MSC ENC	300	+30			08-MAR-2018 2033.9 1736		
+ 792015 (s)	NO. 1 ENGINE - INSTALL NEW OIL FILTER						PKG		
	PKG 1 ,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			08-MAR-2018 2033.9 1736		
+ 792020 (s)	NO. 1 ENGINE - REMOVE/INSPECT MAGNETIC CHIP COLLECTORS						PKG		
	PKG 1 ,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			08-MAR-2018 2033.9 1736		
+ 792025 (s)	NO. 1 ENGINE - CHANGE OIL						PKG		
	PKG 2 REF: LM 72-00-03	MOS HRS/MSC ENC	600	+30/-30			08-MAR-2018 2033.9 1736		
792401	NO. 1 ENGINE - LUBE AND SCAVENGE PUMP								
OVERHAUL	63123 WL01511 REF: See Workcard	MOS HRS/MSC ENC	5000	+100	TSO:0 TSO:0 TSO:0		15-MAY-2003 0 0	(5000) 5000	5100

**ENGINE NO. 2 Model : FJ44-2A Serial # 105044 Part # 56000**

# Status Report

PREMIER I S/N RB-68 (ZS-BDG): 2116.4 HRS, 1810 AFL as of 15-Jul-2019

Owner/Operator: LANSERIA JET CENTRE

Report Date: 18-JUL-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 792010 (s)	NO. 2 ENGINE - REMOVE OIL FILTER AND SUBMIT FOR ANALYSIS PKG 1 ,2 REF: LM 72-00-05	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
+ 792015 (s)	NO. 2 ENGINE - INSTALL NEW OIL FILTER PKG 1 ,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
+ 792020 (s)	NO. 2 ENGINE - REMOVE/INSPECT MAGNETIC CHIP COLLECTORS PKG 1 ,2 REF: See Workcard	MOS HRS/MSC ENC	300	+30			PKG 08-MAR-2018 2033.9 1736		
+ 792025 (s)	NO. 2 ENGINE - CHANGE OIL PKG 2 REF: LM 72-00-03	MOS HRS/MSC ENC	600	+30/-30			PKG 08-MAR-2018 2033.9 1736		
792401	NO. 2 ENGINE - LUBE AND SCAVENGE PUMP 63123 WL01512 REF: See Workcard	MOS HRS/MSC ENC	5000	+100	TSO:0 TSO:0 TSO:0		15-MAY-2003 0 0	(5000) 5000	5100
<b>OVERHAUL</b>									