



Status Report

HONDAJET HA-420

S/N 42000063 N829DL

OWNER: FRAYER JETS 8, LLC
ADDRESS: 208 W. I-240 SERVICE ROAD
OKLAHOMA CITY OK 73139
OFFICE:
FAX:

OPERATOR: WORLD CLASS JET, LLC DBA
LEVIATE JE
ADDRESS: 7701 LEMMON AVE
DALLAS TX 75209
OFFICE: (972) 777-1025
FAX:

ANALYST: JOSH FARR
EMAIL: JFARR@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL / REGNO: 42000063/N829DL	MODEL: HONDAJET HA-420	MANUFACTURER: HONDA AIRCRAFT COMPANY, INC.
CERTIFICATION DATE: 23-JUN-2017		LAST ACTUALS: 1715.1 A/C HRS as of 23-SEP-2025 1561 AFL as of 23-SEP-2025	
ENGINE NO. 1	SERIAL / PART: 883207/HJ1-17201-120-003	MODEL: HF120-H1A	MANUFACTURER: GE HONDA AERO ENGINES
INSTALLED ON: 21-MAY-2024		LAST ACTUALS: 1654.6 ENG. HRS as of 23-SEP-2025 1350 ENC as of 23-SEP-2025	
1490 ENG. HRS 1550.5 A/C HRS			
1350 ENC			
ENGINE NO. 2	SERIAL / PART: 883208/HJ1-17201-120-004	MODEL: HF120-H1A	MANUFACTURER: GE HONDA AERO ENGINES
INSTALLED ON: 26-MAY-2017		LAST ACTUALS: 1715.1 ENG. HRS as of 23-SEP-2025 1561 ENC as of 23-SEP-2025	
0 ENG. HRS 0 A/C HRS			
0 ENC			



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H120-160915	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 5							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-160915	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 5							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-161215	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV6							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-161215	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV6							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-180316	NO. 1 ENGINE - REVIEW HF120-H1A LMM TR 05-0010							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H120-180316	NO. 2 ENGINE - REVIEW HF120-H1A LMM TR 05-0010							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-181215	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 14							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-181215	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 14							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190315	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 15							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190315	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 15							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H120-190424	NO. 1 ENGINE - REVIEW HF120-H1A LMM TR 05-0012							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190424	NO. 2 ENGINE - REVIEW HF120-H1A LMM TR 05-0012							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190517	NO. 1 ENGINE - REVIEW HF120-H1A LMM TR 05-0013							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190517	NO. 2 ENGINE - REVIEW HF120-H1A LMM TR 05-0013							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190615	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 16							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H120-190615	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 16							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190915	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 17							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-190915	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 17							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-191215	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 18							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-191215	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 18							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H120-200218	NO. 1 ENGINE - REVIEW HF120-H1A LMM TR 05-0014							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-200218	NO. 2 ENGINE - REVIEW HF120-H1A LMM TR 05-0014							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-200315	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 19							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-200315	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 19							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-200615	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 20							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H120-200615	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 20							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-200721	NO. 1 ENGINE - REVIEW HF120-H1A LMM TR 05-0015							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-200721	NO. 2 ENGINE - REVIEW HF120-H1A LMM TR 05-0015							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								
H120-230315	NO. 1 ENGINE - REVIEW HF120-H1A LMM REV 27							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								WO#: FAMQ0152
H120-230315	NO. 2 ENGINE - REVIEW HF120-H1A LMM REV 27							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF H120PROC. REF: RCF H120								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H420-160129	REVIEW HONDAJET HA-420 ALM REVISION A1							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-160129-SUPP	REVIEW HONDAJET HA-420 ALM REVISION A1 SUPPLEMENTAL REVISION SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	23-Jun-17	-	TAC 0				REQUIREMENT CHANGE FORMS
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-160630	REVIEW HONDAJET HA-420 ALM REVISION A2							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-160701	REVIEW HONDAJET HA-420 ALM REVISION A3							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-160930	REVIEW HONDAJET HA-420 ALM REVISION A4							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H420-170131	REVIEW HONDAJET HA-420 ALM REVISION B1							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-180115	REVIEW HONDAJET HA-420 ALM REV C							Service ATA:00
	MOS/MSC	18-Jun-18	-					REQUIREMENT CHANGE FORMS
	HRS	231.4						
	AFL	221						
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-180501	REVIEW HONDAJET HA-420 ALM REV C1							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-181015	REVIEW HONDAJET HA-420 ALM REV D							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-190220	REVIEW HONDAJET HA-420 AUDIT SUMMARY CHANGE FORM H420-190220							Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H420-190228	REVIEW HONDAJET HA-420 AUDIT SUMMARY CHANGE FORM H420-190228							Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-190320	REVIEW HONDAJET HA-420 AUDIT SUMMARY CHANGE FORM H420-190320							Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-200429	REVIEW HONDAJET HA-420 AUDIT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-200630	REVIEW HONDA JET ALM REVISION E							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
H420-230115	REVIEW HONDAJET HA420 ALM REVISION H							Service ATA:00
	MOS/MSC	02-Jun-23	-					REQUIREMENT CHANGE FORMS
	HRS	1161.9						
	AFL	1084						
PROC. REF: RCF H420PROC. REF: RCF H420								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
H420-230630	REVIEW HONDAJET HA-420 ALIM REVISION H1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF H420PROC. REF: RCF H420								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-11-07-200-801	NO. 1 ENGINE - TIME LIMITED DISPATCH WITH CONTROL SYSTEM FAULTS							Service ATA:05
	MOS/MSC	26-May-17	A/R	TAC 0				AIRWORTHINESS
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: LMM 05-11-07PROC. REF: LMM 05-11-07								
05-11-07-200-801	NO. 2 ENGINE - TIME LIMITED DISPATCH WITH CONTROL SYSTEM FAULTS							Service ATA:05
	MOS/MSC	26-May-17	A/R	TAC 0				AIRWORTHINESS
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: LMM 05-11-07PROC. REF: LMM 05-11-07								
05CA0520001	600 HOUR SCHEDULED INSPECTIONS (CHECKS)							Package ATA:05
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM 05-20-00PROC. REF: ALIM 05-20-00								
05CA0520002	1200 HOUR SCHEDULED INSPECTIONS (CHECKS)							Package ATA:05
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)		2361.9	2421.9	646.8 (+60)	
	AFL	1084						
								PKG:6
PROC. REF: ALIM 05-20-00PROC. REF: ALIM 05-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05CA0550001	DO THE HARD / OVERWEIGHT LANDING INSPECTION.							Service ATA:05
	MOS/MSC	23-Jun-17	A/R	TAC 0				UNSCHEDULED MAINTENANCE CHECK
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: ALIM 05-50-00PROC. REF: ALIM 05-50-00								
05CA0550002	DO THE OVERSPEED INSPECTION.							Service ATA:05
	MOS/MSC	23-Jun-17	A/R	TAC 0				UNSCHEDULED MAINTENANCE CHECK
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: ALIM 05-50-00PROC. REF: ALIM 05-50-00								
05CA0550003	DO THE DANGEROUS AIR TURBULENCE OR UNAPPROVED MANEUVERS INSPECTION							Service ATA:05
	MOS/MSC	23-Jun-17	A/R	TAC 0				UNSCHEDULED MAINTENANCE CHECK
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: ALIM 05-50-00PROC. REF: ALIM 05-50-00								
05CA0550004	DO THE LIGHTNING STRIKE INSPECTION							Service ATA:05
	MOS/MSC	23-Jun-17	A/R	TAC 0				UNSCHEDULED MAINTENANCE CHECK
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: ALIM 05-50-00PROC. REF: ALIM 05-50-00								
05CA0550005	DO THE FOREIGN OBJECT DAMAGE INSPECTION							Service ATA:05
	MOS/MSC	23-Jun-17	A/R	TAC 0				UNSCHEDULED MAINTENANCE CHECK
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: ALIM 05-50-00PROC. REF: ALIM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05CA0550006	DO THE COLD WEATHER INSPECTION							Service ATA:05
	MOS/MSC	23-Jun-17	A/R	TAC 0				UNSCHEDULED MAINTENANCE CHECK
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: ALIM 05-50-00PROC. REF: ALIM 05-50-00								
05CA0560001	AIRCRAFT STRUCTURE LIFE LIMIT							Service ATA:05
	MOS	23-Jun-17		TAC 0				AIRWORTHINESS
	HRS	0						
	AFL	0	3000		3000		1439	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05CA0560010	AIRCRAFT STRUCTURE LIFE LIMIT							Component ATA:05
PN:PN	MOS/MSC	23-Jun-17	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05HA0500102	ZONES 500/600 OF THE FUEL TANK INTERNAL SYSTEM VENT VALVES, VENT DRAINS, FUEL QUANTITY PROBES AND ALL WIRE HARNESSES - VISUAL INSPECTION							Service ATA:05
	MOS	23-Jun-17		TAC 0				AIRWORTHINESS
	HRS	0	2400 (+60/-60)		2400	2460	684.9 (+60)	
	AFL	0		TAC 0				
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
05HA2031102	DO A VISUAL INSPECTION OF THE INTERNAL WING FUEL TANK SEALANT WITH PARTICULAR ATTENTION TO SEALANT FILLETS AND FASTENER SEAL CAPS IN POTENTIAL LIGHTNING ATTACHMENT ZONES PER GREEN HASHED AREAS ON WINGS SHOWN IN FIGURES 601 AND 602 IN SECTION 05-60-00.							Service ATA:05
	MOS	23-Jun-17		TAC 0				
	HRS	0	2400 (+60/-60)		2400	2460	684.9 (+60)	
	AFL	0		TAC 0				
PROC. REF: AMM 20-31-12, ALIM INTROPROC. REF: AMM 20-31-12, ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 08 - LEVELING AND WEIGHING								
08CU0820000 ^U	REWEIGH ON SCALE REWEIGH AIRCRAFT IAW 135.185 (NOT CALCULATED)							Service ATA:08
	MOS	17-Jul-24	36		31-Jul-27		598 d	CUSTOMER CODE
	HRS							
	AFL							
ATA 12 - SERVICING								
12CA1211121	TAKE / TEST A HYDRAULIC FLUID SAMPLE MIL-PRF-87257							Service ATA:12
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 12-11-12PROC. REF: AMM 12-11-12								
12HA1221102	LUBRICATE LEFT MAIN LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION							Service ATA:12
	MOS	20-Jun-24						
	HRS	1601.9	150 (+10%/-10%)		1751.9	1766.9	36.8 (+15)	
	AFL	1449						
								WO#: FAMQ0152
PROC. REF: AMM 12-21-12, AMM 12-21-12, AMM 12-21-12PROC. REF: AMM 12-21-12, AMM 12-21-12, AMM 12-21-12								
12HA1221102	LUBRICATE NOSE LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION							Service ATA:12
	MOS	20-Jun-24						
	HRS	1601.9	150 (+10%/-10%)		1751.9	1766.9	36.8 (+15)	
	AFL	1449						
								WO#: FAMQ0152
PROC. REF: AMM 12-21-12, AMM 12-21-12, AMM 12-21-12PROC. REF: AMM 12-21-12, AMM 12-21-12, AMM 12-21-12								
12HA1221102	LUBRICATE RIGHT MAIN LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION							Service ATA:12
	MOS	20-Jun-24						
	HRS	1601.9	150 (+10%/-10%)		1751.9	1766.9	36.8 (+15)	
	AFL	1449						
								WO#: FAMQ0152
PROC. REF: AMM 12-21-12, AMM 12-21-12, AMM 12-21-12PROC. REF: AMM 12-21-12, AMM 12-21-12, AMM 12-21-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
12HA1227101A	^S	LUBRICATE COCKPIT FLIGHT CONTROL CABLES						Service ATA:12
	MOS	23-Jun-17						
	HRS	0	600 (+60/-60)					
	AFL	0						
								PKG:1
PROC. REF: AMM 12-21-12PROC. REF: AMM 12-21-12								
12HA1227101B	^S	LUBRICATE FLIGHT CONTROL CABLES IN WING						Service ATA:12
	MOS	23-Jun-17						
	HRS	0	600 (+60/-60)					
	AFL	0						
								PKG:1
PROC. REF: AMM 12-21-12PROC. REF: AMM 12-21-12								
12HA1227101C	^S	LUBRICATE CABIN FLIGHT CONTROL CABLES						Service ATA:12
	MOS	23-Jun-17						
	HRS	0	600 (+60/-60)					
	AFL	0						
								PKG:1
PROC. REF: AMM 12-21-12PROC. REF: AMM 12-21-12								
12HA1227101D	^S	LUBRICATE AFT BAGGAGE AND TAIL FLIGHT CONTROL CABLES						Service ATA:12
	MOS	23-Jun-17						
	HRS	0	600 (+60/-60)					
	AFL	0						
								PKG:1
PROC. REF: AMM 12-21-12PROC. REF: AMM 12-21-12								
ATA 20 - STANDARD PRACTICES - AIRFRAME								
20HA2031102		DO A VISUAL INSPECTION OF THE WING FUEL TANK INTERNAL COMPONENTS.						Service ATA:20
	MOS	23-Jun-17		TAC 0				
	HRS	0	2400 (+60/-60)		2400	2460	684.9 (+60)	
	AFL	0		TAC 0				
PROC. REF: AMM 20-31-12, ALIM INTROPROC. REF: AMM 20-31-12, ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21CA2121001	LEFT COCKPIT INSTRUMENT PANEL GASPER							Component ATA:21
PN:HJ1-12121-225-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:184660115	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21CA2121002	RIGHT COCKPIT INSTRUMENT PANEL GASPER							Component ATA:21
PN:HJ1-12121-225-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:184660116	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
21CA2131101	BLEED AIR SYSTEM / VAPOR CYCLE SYSTEM CONTROLLER							Component ATA:21
PN:HJ1-12155-301-019	MOS/MSC	09-Apr-21	O/C					
SN:00252	HRS	311.8		TSN 6.3				
	AFL	291		TSN 5				
PROC. REF: AMM 21-31-10, AMM 21-31-10PROC. REF: AMM 21-31-10, AMM 21-31-10								
21CA2131113	PRIMARY OUTFLOW REGULATOR; DELTA-P LIMITERS & ALTITUDE LIMITER - FUNCTIONALPERFORMANCE TEST							Component ATA:21
PN:5851-00-15	MOS	03-Feb-23		TSO 0				AIRWORTHINESS
SN:0082A	HRS	1014.6	2400	TSO 0	3414.6		1699.5	
	AFL	965		TSO 0				
PROC. REF: AMM 21-31-11, AMM 21-31-11, AMM 21-31-12, AMM 21-31-12PROC. REF: AMM 21-31-11, AMM 21-31-11, AMM 21-31-12, AMM 21-31-12								
21CA2131115	SECONDARY OUTFLOW REGULATOR; DELTA-P LIMITERS & ALTITUDE LIMITER - FUNCTIONAL PERFORMANCE TEST							Component ATA:21
PN:HJ1-12130-310-003	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:68	HRS	0	2400	TSN 0	2400		684.9	
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-11, AMM 21-31-11, AMM 21-31-12, AMM 21-31-12PROC. REF: AMM 21-31-11, AMM 21-31-11, AMM 21-31-12, AMM 21-31-12								
21CA2131117	REPLACE - SECONDARY OUTFLOW VALVE FILTER P/N HJ1-12130-310-XXX (SEE SECTION 05-60-00)							Component ATA:21
PN:PN	MOS	23-Jun-17		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	2400 (+60/-60)	TSN 0	2400	2460	684.9 (+60)	
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-13, AMM 21-31-13PROC. REF: AMM 21-31-13, AMM 21-31-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21CA2131141	CABIN PRESSURIZATION DATA UNIT							Component ATA:21
PN:HJ1-12130-303-011	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:83	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-14, AMM 21-31-14PROC. REF: AMM 21-31-14, AMM 21-31-14								
21CA2151101	COMPRESSOR DRIVE MODULE ASSEMBLY							Component ATA:21
PN:HJ1-12151-410-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:176	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10, AMM 21-51-10PROC. REF: AMM 21-51-10, AMM 21-51-10								
21CA2151121	COCKPIT EVAPORATOR ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-12, AMM 21-51-12PROC. REF: AMM 21-51-12, AMM 21-51-12								
21CA2151131	CABIN EVAPORATOR ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-13, AMM 21-51-13PROC. REF: AMM 21-51-13, AMM 21-51-13								
21CA2161101	SIDELEDGE ASSY, RHS TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-10, AMM 21-61-10PROC. REF: AMM 21-61-10, AMM 21-61-10								
21CA2161102	CABINET TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-10, AMM 21-61-10PROC. REF: AMM 21-61-10, AMM 21-61-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21HA0500102	^S	DO THE VISUAL INSPECTION OF VCS COMPONENTS.						Service ATA:21
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
21HA0500104	^S	DO THE VISUAL INSPECTION OF THE ECS AND VCS DRAINS.						Service ATA:21
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
21HA0500105	^S	DO THE VISUAL INSPECTION OF THE HEAT EXCHANGER AND VAPOR CYCLE SYSTEMS.						Service ATA:21
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
21HA0500106	^S	DO THE VISUAL INSPECTION OF THE PRIMARY AND SECONDARY OUTFLOW VALVES.						Service ATA:21
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 21-31-11, ALIM INTROPROC. REF: AMM 21-31-11, ALIM INTRO								
21HA2130101	^S	DO THE CABIN PRESSURIZATION LEAK TEST.						Service ATA:21
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01								
21HA2130103	DO THE FUNCTIONAL TEST OF THE CABIN PRESSURIZATION AND CONTROL SYSTEM. NOTE: ACCOMPLISH AFTER SYSTEM COMPONENT REMOVAL AND REPLACEMENT TASKS IN SECTION 05-10-00 AND 05-60-00							Service ATA:21
	MOS	23-Jun-17		TAC 0				
	HRS	0	2400 (+60/-60)		2400	2460	684.9 (+60)	
	AFL	0		TAC 0				
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02								
21HA2150101 ^S	DO THE OPERATIONAL TEST OF THE VAPOR CYCLE SYSTEM.							Service ATA:21
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01								
21HA2150102 ^S	DO THE LEAK TEST OF THE VCS.							Service ATA:21
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 21-50-02, CMM 21-00-41PROC. REF: AMM 21-50-02, CMM 21-00-41								
ATA 22 - AUTO FLIGHT								
22CA2210000	GSA9000 YAW SERVO							Component ATA:22
PN:011-02213-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2JL006127	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-12, AMM 22-11-12PROC. REF: AMM 22-11-12, AMM 22-11-12								
22CA2210002	GSA9000 ROLL SERVO							Component ATA:22
PN:011-02213-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2JL006156	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-11, AMM 22-11-11PROC. REF: AMM 22-11-11, AMM 22-11-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22CA2210003	GSA9000 PITCH SERVO							Component ATA:22
PN:011-02213-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2JL006438	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-10, AMM 22-11-10PROC. REF: AMM 22-11-10, AMM 22-11-10								
22CA2212101	AUTOMATIC FLIGHT CONTROL SYSTEM - GMC715/725 PANEL							Component ATA:22
PN:011-01430-20	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2ZY005038	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-12-10, AMM 22-12-10PROC. REF: AMM 22-12-10, AMM 22-12-10								
22CA2213101	GTA82 TRIM SYNC ADAPTER							Component ATA:22
PN:011-00960-20	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1A2000895	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-13-10, AMM 22-13-10, AMM 22-14-10, AMM 22-14-10PROC. REF: AMM 22-13-10, AMM 22-13-10, AMM 22-14-10, AMM 22-14-10								
22CA2213102	GTA82 TRIM SYNC ADAPTER							Component ATA:22
PN:011-00960-20	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1A2000909	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-13-10, AMM 22-13-10, AMM 22-14-10, AMM 22-14-10PROC. REF: AMM 22-13-10, AMM 22-13-10, AMM 22-14-10, AMM 22-14-10								
22CA2213103	GTA82 TRIM SYNC ADAPTER							Component ATA:22
PN:011-00960-20	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1A2000941	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-13-10, AMM 22-13-10, AMM 22-14-10, AMM 22-14-10PROC. REF: AMM 22-13-10, AMM 22-13-10, AMM 22-14-10, AMM 22-14-10								
22CA2241101	STICK SHAKER ACTUATOR							Component ATA:22
PN:0050N1	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:7585	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-41-10, AMM 22-41-10PROC. REF: AMM 22-41-10, AMM 22-41-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22HA0500101	DO THE VISUAL INSPECTION OF THE PILOT AND CO-PILOT YOKE SWITCHES.							Service ATA:22
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
22HA0500102	DO THE VISUAL INSPECTION OF THE AFCS CONTROLLER.							Service ATA:22
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
22HA0500105	DO THE OPERATIONAL TEST OF THE YAW SERVO.							Service ATA:22
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 22-00-01PROC. REF: AMM 22-00-01								

ATA 23 - COMMUNICATIONS

23CA2310001	LEFT HAND MICROPHONE							Component ATA:23
PN:903-1341	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1514552	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23CA2310002	RIGHT HAND MICROPHONE							Component ATA:23
PN:903-1341	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1514557	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23CA2311101	LOWER / #1 VHF/DME ANTENNA							Component ATA:23
PN:VL10-856	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:106	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-10, AMM 23-11-10PROC. REF: AMM 23-11-10, AMM 23-11-10								
23CA2311102	UPPER / #2 VHF/DME ANTENNA							Component ATA:23
PN:VL10-856	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:117	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-10, AMM 23-11-10PROC. REF: AMM 23-11-10, AMM 23-11-10								
23CA2312101	VHF DATA ANTENNA							Component ATA:23
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-12, AMM 23-11-12PROC. REF: AMM 23-11-12, AMM 23-11-12								
23CA2312102	LRU, COM XCVR, GDR 66							Component ATA:23
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23CA2322001	DATA UNIT, GDL59							Component ATA:23
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-16, AMM 23-11-16PROC. REF: AMM 23-11-16, AMM 23-11-16								
23CA2322101	S-BAND WIFI BLADE ANTENNA							Component ATA:23
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-21-12, AMM 23-21-12PROC. REF: AMM 23-21-12, AMM 23-21-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23CA2351101	LEFT AUDIO-GMA36 CONTROL PANEL							Component ATA:23
PN:011-01793-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1HF007245	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-10, AMM 23-51-10PROC. REF: AMM 23-51-10, AMM 23-51-10								
23CA2351102	RIGHT AUDIO-GMA36 CONTROL PANEL							Component ATA:23
PN:011-01793-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1HF006959	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-10, AMM 23-51-10PROC. REF: AMM 23-51-10, AMM 23-51-10								
23CA2381001	ELT 406AF W/STRAP COMPACT BASE							Component ATA:23
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23CA2381002	ELT PROGRAMMING DONGLE							Component ATA:23
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
23CU231312 ^U	600 HR AVANCE GENERAL VISUAL INSPECTION							Service ATA:23
	MOS							
	HRS		600 (+60/-60)		1800 (M)	1860	84.9 (+60)	
	AFL							
23HA0500101	DO THE VISUAL INSPECTION OF THE COCKPIT COMMUNICATION SYSTEM.							Service ATA:23
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
WO#: FAMQ0152								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24CA2421101	LEFT BUS A 60HZ INVERTER							Component ATA:24
PN:1215-20	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2475	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-21-10, AMM 24-21-10PROC. REF: AMM 24-21-10, AMM 24-21-10								
24CA2421102	RIGHT BUS B 60HZ INVERTER							Component ATA:24
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-21-10, AMM 24-21-10PROC. REF: AMM 24-21-10, AMM 24-21-10								
24CA2430011	NO. 1 MAIN SHIP (LEAD ACID) BATTERY							Component ATA:24
PN:RG-390ES	MOS/MSC	30-Jul-25	O/C	TSN 0				
SN:41409891	HRS	1677.2		TSN 0				
	AFL	1530		TSN 0				
PROC. REF: AMM 24-31-11, AMM 24-31-11PROC. REF: AMM 24-31-11, AMM 24-31-11								
24CA2430011	NO. 2 MAIN SHIP (LEAD ACID) BATTERY							Component ATA:24
PN:RG-390ES	MOS/MSC	30-Jul-25	O/C	TSN 0				
SN:41409892	HRS	1677.2		TSN 0				
	AFL	1530		TSN 0				
PROC. REF: AMM 24-31-11, AMM 24-31-11PROC. REF: AMM 24-31-11, AMM 24-31-11								
24CA2430013	NO. 1 MAIN SHIP (LEAD ACID) BATTERY MAIN SHIP (LEAD ACID) BATTERY CAPACITY CHECK							Service ATA:24
PN:RG-390ES	MOS	30-Jul-25	6 (+1m/-1m)		30-Jan-26 (M)	28-Feb-26	51 d (+29)	
SN:41409891	HRS	1677.2						
	AFL	1530						
PROC. REF: AMM 12-11-18, CMM 24-30-71PROC. REF: AMM 12-11-18, CMM 24-30-71								
24CA2430013	NO. 2 MAIN SHIP (LEAD ACID) BATTERY MAIN SHIP (LEAD ACID) BATTERY CAPACITY CHECK							Service ATA:24
PN:RG-390ES	MOS	30-Jul-25	6 (+1m/-1m)		30-Jan-26 (M)	28-Feb-26	51 d (+29)	
SN:41409892	HRS	1677.2						
	AFL	1530						
PROC. REF: AMM 12-11-18, CMM 24-30-71PROC. REF: AMM 12-11-18, CMM 24-30-71								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24CA2430121	OVERHAUL LEFT STARTER GENERATOR							Service ATA:24
PN:HJ1-12435-101-002	MOS	02-Jun-23						OVERHAUL
SN:0573	HRS	1161.9	1200 (+60/-60)		2361.9	2421.9	646.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 24-31-13, AMM 24-31-13, CMM 24-30-12PROC. REF: AMM 24-31-13, AMM 24-31-13, CMM 24-30-12								
24CA2430121	OVERHAUL RIGHT STARTER GENERATOR							Service ATA:24
PN:HJ1-12435-101-002	MOS	02-Jun-23						OVERHAUL
SN:0574	HRS	1161.9	1200 (+60/-60)		2361.9	2421.9	646.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 24-31-13, AMM 24-31-13, CMM 24-30-12PROC. REF: AMM 24-31-13, AMM 24-31-13, CMM 24-30-12								
24CA2430122	LEFT STARTER GENERATOR BRUSH INSPECTION. - VISUAL INSPECT							Service ATA:24
PN:HJ1-12435-101-002	MOS	02-Jun-23						
SN:0573	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTRO, CMM 24-30-25PROC. REF: ALIM INTRO, CMM 24-30-25								
24CA2430122	RIGHT STARTER GENERATOR BRUSH INSPECTION. - VISUAL INSPECT							Service ATA:24
PN:HJ1-12435-101-002	MOS	02-Jun-23						
SN:0574	HRS	1161.9	600 (+10%/-10%)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTRO, CMM 24-30-25PROC. REF: ALIM INTRO, CMM 24-30-25								
24CA2430127	LEFT STARTER GENERATOR							Component ATA:24
PN:HJ1-12435-101-002	MOS/MSC	02-Jun-23	O/C	TSN 7				
SN:0573	HRS	1161.9		TSN 0				
	AFL	1084		TSN 0				
								WO#: FAMQ0152
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24CA2430128	RIGHT STARTER GENERATOR							Component ATA:24
PN:HJ1-12435-101-002	MOS/MSC	02-Jun-23	O/C	TSN 7				
SN:0574	HRS	1161.9		TSN 0				
	AFL	1084		TSN 0				
								WO#: FAMQ0152
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								
24CA2431101	LEFT GENERATOR CONTROL UNIT							Component ATA:24
PN:HJ1-12436-101-013	MOS/MSC	01-Feb-19	O/C	TSN 20				
SN:149	HRS	310.7		TSN 310.7				
	AFL	290		TSN 290				
PROC. REF: AMM 24-31-10, AMM 24-31-10PROC. REF: AMM 24-31-10, AMM 24-31-10								
24CA2431102	RIGHT GENERATOR CONTROL UNIT							Component ATA:24
PN:HJ1-12436-101-013	MOS/MSC	01-Feb-19	O/C	TSN 0				
SN:0118	HRS	310.7		TSN 0				
	AFL	290		TSN 0				
PROC. REF: AMM 24-31-10, AMM 24-31-10PROC. REF: AMM 24-31-10, AMM 24-31-10								
24CA2431121	LEFT TOROID GROUND FAULT TRANSFORMER							Component ATA:24
PN:76844-1	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1347	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-12, AMM 24-31-12PROC. REF: AMM 24-31-12, AMM 24-31-12								
24CA2431122	RIGHT TOROID GROUND FAULT TRANSFORMER							Component ATA:24
PN:76844-1	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1348	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-12, AMM 24-31-12PROC. REF: AMM 24-31-12, AMM 24-31-12								
24CA2435001	LEFT STARTER GENERATOR V-BAND COUPLING							Component ATA:24
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24CA2435002	RIGHT STARTER GENERATOR V-BAND COUPLING							Component ATA:24
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								
24CA2435003	LEFT STARTER GENERATOR QAD SEAL							Component ATA:24
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								
24CA2435004	RIGHT STARTER GENERATOR QAD SEAL							Component ATA:24
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								
24CA2435005	LEFT STARTER GENERATOR QAD ADAPTER							Component ATA:24
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								
24CA2435006	RIGHT STARTER GENERATOR QAD ADAPTER							Component ATA:24
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-13, AMM 24-31-13PROC. REF: AMM 24-31-13, AMM 24-31-13								
24CA2461101	LEFT POWER DISTRIBUTION UNIT							Component ATA:24
PN:HJ1-12460-103-005	MOS/MSC	22-Sep-23	O/C	TSR 4				
SN:1824800097	HRS	1371.1		TSR 0				
	AFL	1262		TSR 0				
PROC. REF: AMM 24-61-10, AMM 24-61-10PROC. REF: AMM 24-61-10, AMM 24-61-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24CA2461102	RIGHT POWER DISTRIBUTION UNIT							Component ATA:24
PN:HJ1-12460-104-003	MOS/MSC	08-Jan-19	O/C					
SN:1601900002	HRS	311.8		TSR 19.3				
	AFL	291		TSR 21				
PROC. REF: AMM 24-61-10, AMM 24-61-10PROC. REF: AMM 24-61-10, AMM 24-61-10								
24CA2462101	LEFT CIRCUIT BREAKER PANEL							Component ATA:24
PN:HJ1-12461-101-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1635500061	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-62-10, AMM 24-62-10PROC. REF: AMM 24-62-10, AMM 24-62-10								
24CA2462102	RIGHT CIRCUIT BREAKER PANEL							Component ATA:24
PN:HJ1-12461-102-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1700500002	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-62-10, AMM 24-62-10PROC. REF: AMM 24-62-10, AMM 24-62-10								
24CA2463101	AFT PRESSURE BULKHEAD ELECTRICAL DISCONNECT FITTING - REPLACE							Component ATA:24
PN:PN	MOS	EFF		TSN 0				
SN:UNKNOWN	HRS			TSN 0				
	AFL	EFF	10200	TSN 0	10200 *		8639	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24CA2463102	LOWER FUSELAGE ELECTRICAL DISCONNECT FITTING - REPLACE							Component ATA:24
PN:PN	MOS	EFF		TSN 0				
SN:UNKNOWN	HRS			TSN 0				
	AFL	EFF	3000	TSN 0	3000 *		1439	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
24HA0500101	DO THE VISUAL INSPECTION OF THE COCKPIT SIDE CONSOLES AND CIRCUIT BREAKERS.							Service ATA:24
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24HA0500102	DO THE VISUAL INSPECTION OF THE MAIN BATTERY INSTALLATIONS							Service ATA:24
	MOS/MSC	30-Jul-25	N/A					
	HRS	1677.2						
	AFL	1530						
								WO#: FAMQ0152
24HA0500103	DO THE VISUAL INSPECTION OF THE PDUS, PDU CIRCUIT BREAKERS, AND ELECTRICAL COMPONENTS IN THE FORWARD FAIRING.							Service ATA:24
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
24HA0500105	DO THE VISUAL INSPECTION OF THE POWER INVERTER.							Service ATA:24
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9		Adj 38.1				
	AFL	1084						
								WO#: FAMQ0152
24HA0500106	DO A VISUAL INSPECTION OF THE EXTERNAL POWER RECEPTACLE AREA.							Service ATA:24
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
24HA0500107	DO THE VISUAL INSPECTION OF THE ELECTRICAL POWER SYSTEM COMPONENTS, WIRES AND HARNESSSES.							Service ATA:24
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24HA0500108	DO THE VISUAL INSPECTION OF THE ELECTRICAL POWER SYSTEM COMPONENTS, WIRES AND HARNESSSES.							Service ATA:24
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
24HA0500109	DO THE VISUAL INSPECTION OF THE ELECTRICAL POWER SYSTEM COMPONENTS, WIRES AND HARNESSSES.							Service ATA:24
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9		Adj 38.1				
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
24HA0500110	DO THE VISUAL INSPECTION OF THE ELECTRICAL POWER SYSTEM COMPONENTS, WIRES AND HARNESSSES.							Service ATA:24
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
24HA0500111	DO A VISUAL INSPECTION OF THE WIRING AND CONNECTIONS FOR THE FADEC.							Service ATA:24
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
PROC. REF: AMM 24-00-01PROC. REF: AMM 24-00-01								WO#: FAMQ0152
24HA2400101	ELECTRICAL POWER SYSTEM: BUS TIE CONTACT SWITCH - OPERATIONAL TEST							Service ATA:24
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
PROC. REF: AMM 24-00-01PROC. REF: AMM 24-00-01								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24HA2400101	ELECTRICAL POWER SYSTEM: CABIN POWER SWITCH CONTACT - OPERATIONAL TEST							Service ATA:24
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 24-00-01PROC. REF: AMM 24-00-01								
ATA 25 - EQUIPMENT/FURNISHINGS								
25CA2500001	(ELT) EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:S1851501-01	MOS/MSC	07-Mar-25	O/C	TSN 0				
SN:TM0000304044	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 25-61-10, AMM 25-61-10PROC. REF: AMM 25-61-10, AMM 25-61-10								
25CA2511111	LEFT PILOT-CREW SEAT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-11, AMM 25-11-11, CMM 25-11-74PROC. REF: AMM 25-11-11, AMM 25-11-11, CMM 25-11-74								
25CA2511112	RIGHT CO-PILOT CREW SEAT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-11, AMM 25-11-11, CMM 25-11-74PROC. REF: AMM 25-11-11, AMM 25-11-11, CMM 25-11-74								
25CA2521001	CABIN LIGHTING SWITCH PANEL							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25CA2521101	SIDE FACING SEAT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-21-10, AMM 25-21-10, CMM 25-25-88PROC. REF: AMM 25-21-10, AMM 25-21-10, CMM 25-25-88								
25CA2521111	NO. 1 LEFT CABIN SEAT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-11, AMM 25-21-11PROC. REF: AMM 25-21-11, AMM 25-21-11								
25CA2521112	NO. 1 RIGHT CABIN SEAT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-11, AMM 25-21-11PROC. REF: AMM 25-21-11, AMM 25-21-11								
25CA2521113	NO. 2 LEFT CABIN SEAT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-11, AMM 25-21-11PROC. REF: AMM 25-21-11, AMM 25-21-11								
25CA2521114	NO. 2 RIGHT CABIN SEAT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-11, AMM 25-21-11PROC. REF: AMM 25-21-11, AMM 25-21-11								
25CA2525731	PASSENGER SEAT RESTRAINTS P/N 3ARF11XXX							Service ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)	Adj 7.4	2369.3	2429.3	654.2 (+60)	
	AFL	1084						
PROC. REF: CMM 25-25-73PROC. REF: CMM 25-25-73								
WO#: FAMQ0152								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25CA2560011	NO. 1 LEFT CABIN LIFE PRESERVER							Component ATA:25
PN:P01202-101	MOS/MSC	09-Apr-21	O/C	TSR 0				
SN:20110540030	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560012	NO. 1 RIGHT CABIN LIFE PRESERVER							Component ATA:25
PN:P01202-101	MOS/MSC	09-Apr-21	O/C	TSR 0				
SN:20110540018	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560013	NO. 2 LEFT CABIN LIFE PRESERVER							Component ATA:25
PN:P01202-101	MOS/MSC	09-Apr-21	O/C	TSR 0				
SN:20110540022	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560014	NO. 2 RIGHT CABIN LIFE PRESERVER							Component ATA:25
PN:P01202-101	MOS/MSC	09-Apr-21	O/C	TSR 0				
SN:20110540031	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560015	LEFT PILOT LIFE PRESERVER							Component ATA:25
PN:P01202-101C	MOS/MSC	09-Apr-21	O/C	TSN 5				
SN:20110530030	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560016	RIGHT CO-PILOT LIFE PRESERVER							Component ATA:25
PN:P01202-101C	MOS/MSC	09-Apr-21	O/C	TSN 5				
SN:20110530024	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25CA2560017	EXECUTIVE SIDE FACING LIFE PRESERVER							Component ATA:25
PN:P01202-101	MOS/MSC	09-Apr-21	O/C	TSN 5				
SN:20110540026	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560021	NO. 1 LEFT PASSENGER LIFE PRESERVER (OPTIONAL EQUIPMENT) P/N P01202-XXX - INSPECTION							Service ATA:25
PN:P01202-101	MOS	09-Apr-21	60 (+30d/-30d)		01-Nov-25 (M)	01-Dec-25	OVD	
SN:20110540030	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560022	NO. 1 RIGHT PASSENGER LIFE PRESERVER (OPTIONAL EQUIPMENT) P/N P01202-XXX - INSPECTION							Service ATA:25
PN:P01202-101	MOS	09-Apr-21	60 (+30d/-30d)		01-Nov-25 (M)	01-Dec-25	OVD	
SN:20110540018	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560023	NO. 2 LEFT PASSENGER LIFE PRESERVER (OPTIONAL EQUIPMENT) P/N P01202-XXX - INSPECTION							Service ATA:25
PN:P01202-101	MOS	09-Apr-21	60 (+30d/-30d)		01-Nov-25 (M)	01-Dec-25	OVD	
SN:20110540022	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560024	NO. 2 RIGHT PASSENGER LIFE PRESERVER (OPTIONAL EQUIPMENT) P/N P01202-XXX - INSPECTION							Service ATA:25
PN:P01202-101	MOS	09-Apr-21	60 (+30d/-30d)		01-Nov-25 (M)	01-Dec-25	OVD	
SN:20110540031	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560025	PILOT LIFE PRESERVER (OPTIONAL EQUIPMENT) P/N P01202-XXX - INSPECTION							Service ATA:25
PN:P01202-101C	MOS	09-Apr-21	60 (+30d/-30d)		01-Nov-25 (M)	01-Dec-25	OVD	
SN:20110530030	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25CA2560026	CO-PILOT LIFE PRESERVER (OPTIONAL EQUIPMENT) P/N P01202-XXX - INSPECTION							Service ATA:25
PN:P01202-101C	MOS	09-Apr-21	60 (+30d/-30d)		01-Nov-25 (M)	01-Dec-25	OVD	
SN:20110530024	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560027	EXECUTIVE SIDE FACING LIFE PRESERVER (OPTIONAL EQUIPMENT) P/N P01202-XXX - INSPECTION							Service ATA:25
PN:P01202-101	MOS	09-Apr-21	60 (+30d/-30d)		01-Nov-25 (M)	01-Dec-25	OVD	
SN:20110540026	HRS	311.8						
	AFL	291						
PROC. REF: CMM 25-60-35PROC. REF: CMM 25-60-35								
25CA2560111	LIFE RAFT							Component ATA:25
PN:PN	MOS/MSC	23-Jun-17	N/A	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: CMM 25-60-20PROC. REF: CMM 25-60-20								
25CA2560121	LIFE RAFT (OPTIONAL EQUIPMENT) P/N RO425-XXX - INSPECTION							Service ATA:25
PN:PN	MOS/MSC	23-Jun-17	N/A	TAC 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: CMM 25-60-20PROC. REF: CMM 25-60-20								
25CA2561111	ELT TRANSMITTER ANTENNA							Component ATA:25
PN:ELT10-696-1	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:288	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-11, AMM 25-61-11PROC. REF: AMM 25-61-11, AMM 25-61-11								
25CA2563062	ELT BATTERY (REPLACE) P/N 0141823							Component ATA:25
PN:S1840510-01	MOS	02-Jun-23	72	TSN 23	01-Apr-28 (M)		843 d	DISCARD
SN:TM0000226197	HRS	1161.9		TSN 0				
	AFL	1084		TSN 0				
Expiry Date: : 01-Apr-28								WO#: FAMQ0152
PROC. REF: CMM 25-63-08PROC. REF: CMM 25-63-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25HA0500101 ^S	REMOVE ALL CABIN SEATS, CABINETS, PARTITIONS AND FLOORBOARDS. DO THE VISUAL INSPECTION OF THE ATTACHING STRUCTURE AND SURROUNDING AREAS.						Service	ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 25-21-26, AMM 25-21-26, AMM 25-21-27, AMM 25-21-27, ALIM INTROPROC. REF: AMM 25-21-26, AMM 25-21-26, AMM 25-21-27, AMM 25-21-27, ALIM INTRO								
25HA0500102 ^S	REMOVE THE CREW SEATS AND FLOORBOARDS IN COCKPIT. DO THE VISUAL INSPECTION OF THE ATTACHING STRUCTURE AND SURROUNDING AREAS.						Service	ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500103 ^S	DO THE VISUAL INSPECTION OF THE FLASHLIGHT, FIRE EXTINGUISHER AND OPTIONAL FIRST AID KIT.						Service	ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500104 ^S	DO THE VISUAL INSPECTION OF THE CREW AND PASSENGER SEATS FOR CONDITION AND OPERATION.						Service	ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTRO, CMM 25-11-74, CMM 25-25-73, CMM 25-12-58PROC. REF: ALIM INTRO, CMM 25-11-74, CMM 25-25-73, CMM 25-12-58								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25HA0500105	^S	DO THE VISUAL INSPECTION OF THE CREW AND CABIN OVERHEAD PANELS.						Service ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500106	^S	DO THE VISUAL INSPECTION OF THE CABINET ASSEMBLIES.						Service ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500107	^S	DO THE VISUAL INSPECTION OF THE CREW SEAT TRACKS AND LUGS.						Service ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500108	^S	DO THE VISUAL INSPECTION OF THE LAVATORY VANITY.						Service ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500109	^S	DO THE VISUAL INSPECTION OF THE LAVATORY CABINETS.						Service ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500110	^S	DO THE VISUAL INSPECTION OF THE INTERIOR PLACARDS SHOWN IN SECTION 2 OF THE AFM						Service ATA:25
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA0500111		DO A VISUAL INSPECTION OF THE FUSELAGE SUB FLOOR AREA ELECTRICAL HARNESSSES FOR CHAFING AND CONDUIT CONDITION IN WIRE TRAY OPENED LIPPED AREAS. DO THE VISUAL INSPECTION OF THE FUSELAGE MOISTURE DRAIN PATH.						Service ATA:25
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
25HA2560102		EMERGENCY LOCATOR TRANSMITTER FUNCTIONAL TEST. P/N S185X501-XX (KIT S1840510-02)						Service ATA:25
PN:S1851501-01	MOS	07-Mar-25	12 (+30d/-30d)		07-Mar-26	06-Apr-26	87 d (+30)	
SN:TM0000304044	HRS							
	AFL							
Test Date: : 07-Mar-25								WO#: FAMQ0152
PROC. REF: AMM 25-60-01, CMM 25-63-08PROC. REF: AMM 25-60-01, CMM 25-63-08								
25HA2563062		EMERGENCY LOCATOR TRANSMITTER SELF-TEST (ELT) P/N S182X502-XX, S185X501-XX						Service ATA:25
PN:S1851501-01	MOS	07-Mar-25	6 (+30d/-30d)		07-Sep-25	07-Oct-25	OVD	
SN:TM0000304044	HRS							
	AFL							
Test Date: : 07-Mar-25								
PROC. REF: AMM 25-60-01, CMM 25-63-08PROC. REF: AMM 25-60-01, CMM 25-63-08								
ATA 26 - FIRE PROTECTION								
26CA2611101		LEFT ENGINE FIRE DETECTION SENSOR						Component ATA:26
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-10, AMM 26-11-10PROC. REF: AMM 26-11-10, AMM 26-11-10								
26CA2611102	RIGHT ENGINE FIRE DETECTION SENSOR							Component ATA:26
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-10, AMM 26-11-10PROC. REF: AMM 26-11-10, AMM 26-11-10								
26CA2621101	LEFT ENGINE FIRE SUPPRESSION BOTTLE							Component ATA:26
PN:HJ1-12620-100-001	MOS/MSC	09-Apr-21	O/C	TSN 44, TSO 3				
SN:0222D	HRS	311.8		TSO 0				
	AFL	291		TSO 0				
PROC. REF: AMM 26-21-10, AMM 26-21-10PROC. REF: AMM 26-21-10, AMM 26-21-10								
26CA2621101	RIGHT ENGINE FIRE SUPPRESSION BOTTLE							Component ATA:26
PN:HJ1-12620-100-001	MOS/MSC	24-Sep-22	O/C	TSN 0				
SN:0563E	HRS	804.4		TSN 0				
	AFL	778		TSN 0				
PROC. REF: AMM 26-21-10, AMM 26-21-10PROC. REF: AMM 26-21-10, AMM 26-21-10								
26CA2621102	LEFT ENGINE FIRE SUPPRESSION BOTTLE - HYDROSTATIC TEST							Service ATA:26
PN:HJ1-12620-100-001	MOS	21-Jan-21	60 (+30d/-30d)		21-Jan-26	20-Feb-26	42 d (+30)	
SN:0222D	HRS							
	AFL							
HydroCheck Date: : 21-Jan-21								
PROC. REF: AMM 26-21-10, AMM 26-21-10, CMM 26-22-02PROC. REF: AMM 26-21-10, AMM 26-21-10, CMM 26-22-02								
26CA2621102	RIGHT ENGINE FIRE SUPPRESSION BOTTLE - HYDROSTATIC TEST							Service ATA:26
PN:HJ1-12620-100-001	MOS	01-Sep-22	60 (+30d/-30d)		01-Sep-27	01-Oct-27	630 d (+30)	
SN:0563E	HRS							
	AFL							
HydroCheck Date: : 01-Sep-22								
PROC. REF: AMM 26-21-10, AMM 26-21-10, CMM 26-22-02PROC. REF: AMM 26-21-10, AMM 26-21-10, CMM 26-22-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26CA2621103	LEFT ENGINE FIRE BOTTLE CARTRIDGE - REPLACE							Component ATA:26
PN:CT01400-1	MOS	09-Apr-21	144		01-Aug-29		1330 d	LIFE LIMIT
SN:00332	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
Manufacture Date:: 01-Aug-17								
PROC. REF: AMM 26-21-10, AMM 26-21-10PROC. REF: AMM 26-21-10, AMM 26-21-10								
26CA2621103	RIGHT ENGINE FIRE BOTTLE CARTRIDGE - REPLACE							Component ATA:26
PN:CT01400-1	MOS	24-Sep-22	144		01-Nov-26		326 d	LIFE LIMIT
SN:00068	HRS	804.4						
	AFL	778						
Manufacture Date:: 01-Nov-14								
PROC. REF: AMM 26-21-10, AMM 26-21-10PROC. REF: AMM 26-21-10, AMM 26-21-10								
26CA2631101	FWD HANDHELD FIRE EXTINGUISHER							Component ATA:26
PN:RT A1200	MOS	02-Jun-23	144	TSN 0	30-Jun-34 (M)		3124 d	REPLACE
SN:D58318193	HRS	1161.9		TSN 0				
	AFL	1084		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
26HA0500102	DO THE VISUAL INSPECTION OF THE FIRE DETECTOR ELEMENT FOR ROUTING AND CONNECTION. VERIFY THAT THE FIRE DETECTOR IS NOT RUBBING ON OTHER COMPONENTS.							Service ATA:26
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
PROC. REF: AMM 26-11-10, AMM 26-11-10PROC. REF: AMM 26-11-10, AMM 26-11-10								WO#: FAMQ0152
26HA0500103 ^S	DO THE VISUAL INSPECTION OF THE ENGINE NACELLE ELECTRICAL HARNESS ASSEMBLIES.							Service ATA:26
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26HA0500105	DO THE VISUAL INSPECTION OF THE FIRE SUPPRESSION BOTTLE. INSPECTION LIMITS ARE AS FOLLOWS: DENTS DEEPER THAN 0.062 INCH. SCRATCHES DEEPER THAN 0.005 INCH OR LONGER THAN 2 INCHES. DENTS AND SCRATCHES EXCEEDING THESE LIMITS ARE CAUSE FOR REPLACEMENT.							Service ATA:26
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
26HA0500106	DO THE DETAILED VISUAL INSPECTION OF THE LEFT FIRE SUPPRESSION DISCHARGE TUBE FOR FOREIGN OBJECTS. REMOVE THE FIRE SUPPRESSION DISCHARGE TUBE TO PERFORM THIS INSPECTION. THIS TASK IS TO BE IN CONJUNCTION WITH THE ENGINE FIRE BOTTLE HYDROSTATIC TEST; INSPECTION TASK CODE 26CA2621102							Service ATA:26
PN:HJ1-12620-100-001	MOS	09-Apr-21	60 (+30d/-30d)		09-Apr-26	09-May-26	120 d (+30)	
SN:0222D	HRS	311.8						
	AFL	291						
PROC. REF: AMM 26-21-10, AMM 26-21-10PROC. REF: AMM 26-21-10, AMM 26-21-10								
26HA0500106	DO THE DETAILED VISUAL INSPECTION OF THE RIGHT FIRE SUPPRESSION DISCHARGE TUBE FOR FOREIGN OBJECTS. REMOVE THE FIRE SUPPRESSION DISCHARGE TUBE TO PERFORM THIS INSPECTION. THIS TASK IS TO BE IN CONJUNCTION WITH THE ENGINE FIRE BOTTLE HYDROSTATIC TEST; INSPECTION TASK CODE 26CA2621102							Service ATA:26
	MOS	23-Jun-17	60 (+30d/-30d)		09-Apr-26 (M)	09-May-26	120 d (+30)	
	HRS	0						
	AFL	0						
PROC. REF: AMM 26-21-10, AMM 26-21-10PROC. REF: AMM 26-21-10, AMM 26-21-10								
26HA0500107	LEFT - FIRE SUPPRESSION NOZZLE AND DISCHARGE TUBE - DETAILED VISUAL INSPECTION							Service ATA:26
	MOS	02-Jun-23	60		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	3000		4161.9	4221.9	2446.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 26-21-10, AMM 26-21-10PROC. REF: AMM 26-21-10, AMM 26-21-10								
26HA2600101 ^S	DO THE FUNCTIONAL TEST OF THE FIRE DETECTION AND SUPPRESSION SYSTEM.							Service ATA:26
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						

PKG:6
WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: AMM 26-00-01PROC. REF: AMM 26-00-01								
26HA2600103	HEAT CHECK OF THE FIRE DETECTOR ELEMENT AT ENGINE REMOVAL. MEGGITT CMM 26-10-60 - FUNCTIONAL TEST							Service ATA:26
	MOS	EFF						
	HRS	EFF	5000 (+60/-60)		5000 *	5060	3284.9 (+60)	
	AFL							
PROC. REF: AMM 26-11-10, AMM 26-11-10PROC. REF: AMM 26-11-10, AMM 26-11-10								
26HA2600104 ^S	FIRE DETECTOR AND FIRE SUPPRESSION BOTTLE INDICATIONS - FUNCTIONAL TEST							Service ATA:26
	MOS	20-Jun-24						AIRWORTHINESS
	HRS	1601.9	1200 (+60/-60)					
	AFL	1449						
								PKG:6
PROC. REF: AMM 26-00-01, AMM 26-00-01PROC. REF: AMM 26-00-01, AMM 26-00-01								WO#: 81318,FAMQ0152
26HA2620101	FWD HANDHELD FIRE EXTINGUISHER VISUAL INSPECTION P/N RT A1200 OR 337TS (OPTIONAL) (F.S. 140.70 LEFT SIDE)							Service ATA:26
PN:RT A1200	MOS	20-Jun-25	12 (+30d/-30d)		20-Jun-26 (M)	20-Jul-26	192 d (+30)	
SN:D58318193	HRS	1677.2						
	AFL	1530						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
ATA 27 - FLIGHT CONTROLS								
27CA2711121	LEFT PILOT CREW CONTROL YOKE							Component ATA:27
PN:HJ1-12701-225-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:85	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-12, AMM 27-11-12PROC. REF: AMM 27-11-12, AMM 27-11-12								
27CA2711122	RIGHT CO-PILOT CONTROL YOKE							Component ATA:27
PN:HJ1-12701-225-010	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:78	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-12, AMM 27-11-12PROC. REF: AMM 27-11-12, AMM 27-11-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27CA2712111	LEFT AILERON TRIM ACTUATOR							Component ATA:27
PN:HJ1-12711-801-015	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:107	HRS	0	3000	TSN 0	3000		1284.9	
	AFL	0	3000	TSN 0	3000		1439	
PROC. REF: AMM 27-12-11, AMM 27-12-11PROC. REF: AMM 27-12-11, AMM 27-12-11								
27CA2712112	RIGHT AILERON TRIM ACTUATOR							Component ATA:27
PN:HJ1-12711-801-016	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:114	HRS	0	3000	TSN 0	3000		1284.9	
	AFL	0	3000	TSN 0	3000		1439	
PROC. REF: AMM 27-12-11, AMM 27-12-11PROC. REF: AMM 27-12-11, AMM 27-12-11								
27CA2721181	YAW GSM 9100 SERVO							Component ATA:27
PN:011-02214-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2Q7006101	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: CMM 190-00303-85PROC. REF: CMM 190-00303-85								
27CA2721182	PITCH GSM 9100 SERVO							Component ATA:27
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: CMM 190-00303-85PROC. REF: CMM 190-00303-85								
27CA2721183	ROLL GSM 9100 SERVO							Component ATA:27
PN:011-02214-10	MOS/MSC	02-Jun-23	O/C	TSN 15				
SN:2Q7008447	HRS	1161.9		TSN 0				
	AFL	1084		TSN 0				
PROC. REF: CMM 190-00303-85PROC. REF: CMM 190-00303-85								
27CA2721184	YAW SERVO DRIVESHAFT SEAL P/N GSM 9100 - DETAILED INSPECTION							Service ATA:27
PN:011-02214-10	MOS	23-Jun-17	240 (+30d/-30d)		23-Jun-37	23-Jul-37	4213 d (+30)	
SN:2Q7006101	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: CMM 190-00303-85PROC. REF: CMM 190-00303-85								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27CA2721185	PITCH SERVO DRIVESHAFT SEAL P/N GSM 9100 - DETAILED INSPECTION							Service ATA:27
PN:PN	MOS	23-Jun-17	240 (+30d/-30d)		23-Jun-37	23-Jul-37	4213 d (+30)	
SN:UNKNOWN	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: CMM 190-00303-85PROC. REF: CMM 190-00303-85								
27CA2721186	ROLL SERVO DRIVESHAFT SEAL P/N GSM 9100 - DETAILED INSPECTION							Service ATA:27
PN:011-02214-10	MOS	02-Jun-23	240 (+30d/-30d)		02-Jun-43	02-Jul-43	6383 d (+30)	
SN:2Q7008447	HRS	1161.9						
	AFL	1084						
PROC. REF: CMM 190-00303-85PROC. REF: CMM 190-00303-85								
27CA2722112	RUDDER TRIM ACTUATOR							Component ATA:27
PN:HJ1-12721-501-015	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:49	HRS	0	3000	TSN 0	3000		1284.9	
	AFL	0	3000	TSN 0	3000		1439	
PROC. REF: AMM 27-22-12, AMM 27-22-12PROC. REF: AMM 27-22-12, AMM 27-22-12								
27CA2731211	CONTROL COLUMN SUB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-21, AMM 27-31-21PROC. REF: AMM 27-31-21, AMM 27-31-21								
27CA2732111	LEFT ELEVATOR TRIM ACTUATOR							Component ATA:27
PN:HJ1-12731-530-001	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:87	HRS	0	3000	TSN 0	3000		1284.9	
	AFL	0	3000	TSN 0	3000		1439	
PROC. REF: AMM 27-32-11, AMM 27-32-11PROC. REF: AMM 27-32-11, AMM 27-32-11								
27CA2732112	RIGHT ELEVATOR TRIM ACTUATOR							Component ATA:27
PN:HJ1-12731-530-002	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:93	HRS	0	3000	TSN 0	3000		1284.9	
	AFL	0	3000	TSN 0	3000		1439	
PROC. REF: AMM 27-32-11, AMM 27-32-11PROC. REF: AMM 27-32-11, AMM 27-32-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27CA2751111	LEFT FLAP ACTUATOR							Component ATA:27
PN:HJ1-12750-810-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:147	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-11, AMM 27-51-11PROC. REF: AMM 27-51-11, AMM 27-51-11								
27CA2751112	RIGHT FLAP ACTUATOR							Component ATA:27
PN:HJ1-12750-810-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:61	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-11, AMM 27-51-11PROC. REF: AMM 27-51-11, AMM 27-51-11								
27CA2751191	COCKPIT FLAP CONTROL LEVER							Component ATA:27
PN:HJ1-12750-210-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:69	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-21, AMM 27-51-21PROC. REF: AMM 27-51-21, AMM 27-51-21								
27CA2760001	LH SPEED BRAKE ASSEMBLY							Component ATA:27
PN:HJ1-12760-200-011	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:JT168922	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-61-11, AMM 27-61-11PROC. REF: AMM 27-61-11, AMM 27-61-11								
27CA2760002	RH SPEED BRAKE ASSEMBLY							Component ATA:27
PN:HJ1-12760-300-011	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:JT168641	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-61-11, AMM 27-61-11PROC. REF: AMM 27-61-11, AMM 27-61-11								
27CA2761111	SPEED BRAKE ACTUATOR (OPTIONAL EQUIPMENT)							Component ATA:27
PN:HJ1-12761-101-013	MOS/MSC	27-Feb-23	O/C	TSN 0				
SN:AKN00260	HRS	1051.1		TSN 0				
	AFL	1000		TSN 0				
PROC. REF: AMM 27-61-11, AMM 27-61-11PROC. REF: AMM 27-61-11, AMM 27-61-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27HA0500101	^S	DO THE VISUAL INSPECTION OF THE WIRING, AND FLIGHT CONTROL CABLES.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500102	^S	DO THE VISUAL INSPECTION OF THE CONTROL COLUMNS.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500103	^S	DO THE VISUAL INSPECTION OF THE RUDDER PEDALS FOR GENERAL CONDITION.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500104	^S	DO THE VISUAL INSPECTION OF THE FORWARD AND AFT RUDDER SECTORS.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500105	^S	DO THE VISUAL INSPECTION OF THE RUDDER TORQUE TUBE (MOUNT, PLATES, RIBS AND FITTINGS), UPPER AND LOWER.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500106	^S	DO THE VISUAL INSPECTION OF THE RUDDER TRIM ACTUATOR.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500107	^S	DO THE VISUAL INSPECTION OF THE HORIZONTAL STABILIZER AND ATTACHING STRUCTURE.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500108	^S	DO THE VISUAL INSPECTION OF THE ELEVATOR, TRIM TAB, ACTUATOR AND WIRING.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500109	^S	DO THE VISUAL INSPECTION OF THE ELEVATOR BELLCRANK STOPS, BOLTS AND BEARINGS.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27HA0500110	^S	DO THE VISUAL INSPECTION OF ELEVATOR TORQUE TUBES, BEARINGS AND ACTUATING RODS.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500111	^S	DO THE VISUAL INSPECTION OF FLIGHT CONTROL CABLES, PULLEYS, SECTORS, BEARINGS, AND PUSHRODS.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500112	^S	DO THE VISUAL INSPECTION OF THE AILERON TRIM SYSTEM.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500113	^S	DO THE VISUAL INSPECTION OF THE FLAPS AND FLAP ACTUATORS.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500114	^S	DO THE VISUAL INSPECTION OF THE REAR SPAR AND ATTACHED WIRE BUNDLES AND ELECTRICAL CONNECTORS.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500115	^S	DO THE VISUAL INSPECTION OF THE SPEED BRAKE EQUIPMENT AND ATTACHING HARDWARE. (OPTIONAL EQUIPMENT).						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500116	^S	DO THE VISUAL INSPECTION OF THE TAILCONE AREA AND SPEED BRAKE PANELS, WITH THE SPEED BRAKE OPENED. (OPTIONAL EQUIPMENT).						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA0500117	^S	DO THE VISUAL INSPECTION OF THE WING GROUND SPOILERS EQUIPMENT AND ATTACHING HARDWARE.						Service ATA:27
	MOS/MSC	23-Jun-17	N/A					
	HRS	0						
	AFL	0						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
27HA2710102	^S	DO THE MEASUREMENT OF THE AILERON CONTROL CABLE TENSIONS AND CONTROL SURFACE TRAVEL.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 27-10-01PROC. REF: AMM 27-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27HA2711102	AILERON TRIM TAB BACKLASH - DETAILED INSPECTION							Service ATA:27
	MOS	24-Oct-23						AIRWORTHINESS
	HRS	1452.2	300		1752.2		37.1	
	AFL	1321						
PROC. REF: AMM 27-10-01PROC. REF: AMM 27-10-01								WO#: 81318,FAMQ0152
27HA2720101 ^S	DO THE MEASUREMENT OF THE RUDDER CONTROL CABLE TENSIONS AND CONTROL SURFACE TRAVEL.							Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								PKG:1 WO#: FAMQ0152
27HA2721103	RUDDER TRIM TAB BACKLASH - DETAILED INSPECTION							Service ATA:27
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								WO#: 81318,FAMQ0152
27HA2730101 ^S	DO THE MEASUREMENT OF THE ELEVATOR CONTROL CABLE TENSIONS AND CONTROL SURFACE TRAVEL.							Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								PKG:1 WO#: FAMQ0152
27HA2731103	ELEVATOR TRIM TAB BACKLASH - DETAILED INSPECTION							Service ATA:27
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								WO#: 81318,FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27HA2750102	^S	DO THE OPERATIONAL TEST OF THE FLAP SYSTEM.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								PKG:1 WO#: FAMQ0152
27HA2750103		LEFT FLAP BALL SCREW - DETAILED INSPECTION						Service ATA:27
PN:HJ1-12750-810-009	MOS	02-Jun-23						AIRWORTHINESS
SN:147	HRS	1161.9	600		1761.9		46.8	
	AFL	1084						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								WO#: FAMQ0152
27HA2750103		RIGHT FLAP BALL SCREW - DETAILED INSPECTION						Service ATA:27
PN:HJ1-12750-810-009	MOS	02-Jun-23						AIRWORTHINESS
SN:61	HRS	1161.9	600		1761.9		46.8	
	AFL	1084						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								WO#: FAMQ0152
27HA2760101	^S	DO THE OPERATIONAL TEST OF THE SPEED BRAKES.						Service ATA:27
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 27-51-11, AMM 27-51-11, AMM 27-60-01PROC. REF: AMM 27-51-11, AMM 27-51-11, AMM 27-60-01								PKG:6 WO#: FAMQ0152
ATA 28 - FUEL								
28CA2800001		LEFT FUEL MOTIVE HOSE						Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-00, AMM 28-00-00PROC. REF: AMM 28-00-00, AMM 28-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2800002	RIGHT FUEL MOTIVE HOSE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-00, AMM 28-00-00PROC. REF: AMM 28-00-00, AMM 28-00-00								
28CA2800051	SURGE TANK FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-13, AMM 28-12-13PROC. REF: AMM 28-12-13, AMM 28-12-13								
28CA2811003	LEFT FLOAT OPERATED VALVE							Component ATA:28
PN:HJ1-12810-164-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:153	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-19, AMM 28-11-19PROC. REF: AMM 28-11-19, AMM 28-11-19								
28CA2811003	RIGHT FLOAT OPERATED VALVE							Component ATA:28
PN:HJ1-12810-164-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:154	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-19, AMM 28-11-19PROC. REF: AMM 28-11-19, AMM 28-11-19								
28CA2811100	AFT FUSELAGE BLADDER TANK							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-10, AMM 28-11-10PROC. REF: AMM 28-11-10, AMM 28-11-10								
28CA2811101	CENTER BLADDER TANK							Component ATA:28
PN:HJ1-12810-401-003	MOS/MSC	01-Feb-19	O/C	TSN 0				
SN:17-62593	HRS	310.7		TSN 0				
	AFL	290		TSN 0				
PROC. REF: AMM 28-11-10, AMM 28-11-10PROC. REF: AMM 28-11-10, AMM 28-11-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2811103	LEFT OUTBOARD BLADDER TANK							Component ATA:28
PN:HJ1-12810-402-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:16-77637	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-10, AMM 28-11-10PROC. REF: AMM 28-11-10, AMM 28-11-10								
28CA2811104	RIGHT OUTBOARD BLADDER TANK							Component ATA:28
PN:HJ1-12810-402-004	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:16-77683	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-10, AMM 28-11-10PROC. REF: AMM 28-11-10, AMM 28-11-10								
28CA2811105	LEFT COLLECTOR TANK							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2811106	RIGHT COLLECTOR TANK							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2811131	FUEL FILLER ADAPTER							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-13, AMM 28-11-13PROC. REF: AMM 28-11-13, AMM 28-11-13								
28CA2811132	FUEL FILLER CAP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-15, AMM 28-11-15PROC. REF: AMM 28-11-15, AMM 28-11-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2811141	MOTOR OPERATED SHUTOFF VALVE							Component ATA:28
PN:HJ1-12810-501-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:74	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-14, AMM 28-11-14PROC. REF: AMM 28-11-14, AMM 28-11-14								
28CA2811160	FUSELAGE 3 INCH BLADDER TANK FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2811161	NO. 1 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811162	NO. 1 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811163	NO. 2 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811164	NO. 2 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2811165	NO. 3 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811166	NO. 3 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811167	NO. 4 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811168	NO. 4 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811169	NO. 5 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811170	NO. 5 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2811171	NO. 6 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811172	NO. 6 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811173	NO. 7 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811174	NO. 7 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811175	NO. 8 LEFT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								
28CA2811176	NO. 8 RIGHT WING 2 INCH FLAPPER VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-16, AMM 28-11-16PROC. REF: AMM 28-11-16, AMM 28-11-16								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2811178	RIGHT FLOAT DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2811179	LEFT FLOAT DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2811181	NO.1 CENTER TANK DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-18, AMM 28-11-18PROC. REF: AMM 28-11-18, AMM 28-11-18								
28CA2811182	NO.2 CENTER TANK DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-18, AMM 28-11-18PROC. REF: AMM 28-11-18, AMM 28-11-18								
28CA2811183	NO.3 CENTER TANK DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-18, AMM 28-11-18PROC. REF: AMM 28-11-18, AMM 28-11-18								
28CA2811184	NO. 1 LEFT INBOARD FUEL WING DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2811185	NO. 1 RIGHT INBOARD FUEL WING DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18								
28CA2811187	NO. 2 LEFT INBOARD FUEL WING DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18								
28CA2811187	NO. 2 RIGHT INBOARD FUEL WING DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18PROC. REF: AMM 28-11-17, AMM 28-11-17, AMM 28-11-18, AMM 28-11-18								
28CA2811191	LEFT FUEL LEVEL CONTROL FLOAT VALVE							Component ATA:28
PN:HJ1-12810-372-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:205	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-19, AMM 28-11-19PROC. REF: AMM 28-11-19, AMM 28-11-19								
28CA2811192	RIGHT FUEL LEVEL CONTROL FLOAT VALVE							Component ATA:28
PN:HJ1-12810-372-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:193	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-19, AMM 28-11-19PROC. REF: AMM 28-11-19, AMM 28-11-19								
28CA2811193	CENTER FUEL LEVEL CONTROL FLOAT VALVE							Component ATA:28
PN:HJ1-12810-372-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:195	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-19, AMM 28-11-19PROC. REF: AMM 28-11-19, AMM 28-11-19								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2812101	POS/NEG PRESSURE RELIEF VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-10, AMM 28-12-10PROC. REF: AMM 28-12-10, AMM 28-12-10								
28CA2812111	NO. 1 FLAME ARRESTOR							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-11, AMM 28-12-11PROC. REF: AMM 28-12-11, AMM 28-12-11								
28CA2812112	NO. 2 FLAME ARRESTOR							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-11, AMM 28-12-11PROC. REF: AMM 28-12-11, AMM 28-12-11								
28CA2812131	FUEL FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-13, AMM 28-12-13PROC. REF: AMM 28-12-13, AMM 28-12-13								
28CA2812141	NO. 1 VENT FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-14, AMM 28-12-14PROC. REF: AMM 28-12-14, AMM 28-12-14								
28CA2812142	NO. 2 VENT FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-14, AMM 28-12-14PROC. REF: AMM 28-12-14, AMM 28-12-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2812143	NO. 3 VENT FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-14, AMM 28-12-14PROC. REF: AMM 28-12-14, AMM 28-12-14								
28CA2812144	NO. 4 VENT FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-14, AMM 28-12-14PROC. REF: AMM 28-12-14, AMM 28-12-14								
28CA2821000	LATCHING VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2821001	NO. 1 5/8 INCH LATCHING SOLENOID VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2821002	NO. 2 5/8 INCH LATCHING SOLENOID VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2821003	NO. 3 5/8 INCH LATCHING SOLENOID VALVE							Component ATA:28
PN:HJ1-12820-108-007	MOS/MSC	02-Mar-18	O/C	TSN 0				
SN:151	HRS	145.5		TSN 0				
	AFL	141		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2821101	LEFT ELECTRIC BOOST PUMP							Component ATA:28
PN:HJ1-12820-103-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:150	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-10, AMM 28-21-10PROC. REF: AMM 28-21-10, AMM 28-21-10								
28CA2821102	RIGHT ELECTRIC BOOST PUMP							Component ATA:28
PN:HJ1-12820-103-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:139	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-10, AMM 28-21-10PROC. REF: AMM 28-21-10, AMM 28-21-10								
28CA2821111	LEFT 3/4 INCH STRAINER							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11								
28CA2821111	RIGHT 3/4 INCH STRAINER							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11PROC. REF: AMM 28-21-11, AMM 28-21-11								
28CA2821121	LEFT MAIN EJECTOR PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2821122	RIGHT MAIN EJECTOR PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2821141	LEFT TEMPERATURE SENSOR							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-14, AMM 28-21-14PROC. REF: AMM 28-21-14, AMM 28-21-14								
28CA2821141	RIGHT TEMPERATURE SENSOR							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-14, AMM 28-21-14PROC. REF: AMM 28-21-14, AMM 28-21-14								
28CA2821151	NO. 1 LH 5/8 INCH IN-LINE COLLECTOR TANK CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821152	NO. 1 RH 5/8 INCH IN-LINE COLLECTOR TANK CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821153	NO. 2 LH 5/8 INCH IN-LINE COLLECTOR TANK CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821154	NO. 2 RH 5/8 INCH IN-LINE COLLECTOR TANK CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2821155	NO. 3 LH 5/8 INCH IN-LINE COLLECTOR TANK CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821156	NO. 3 RH 5/8 INCH IN-LINE COLLECTOR TANK CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821157	MAIN EJECTOR PUMP OUTLET 5/8 INCH IN-LINE CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821158	EPB OUTLET 5/8 INCH IN-LINE CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821159	MOTIVE FLOW TUBE 5/8 INCH IN-LINE CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-15, AMM 28-21-15PROC. REF: AMM 28-21-15, AMM 28-21-15								
28CA2821171	LEFT FUEL FEED HOSE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-00, AMM 28-00-00PROC. REF: AMM 28-00-00, AMM 28-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2821172	RIGHT FUEL FEED HOSE							Component ATA:28
PN:HJ1-12821-132-001	MOS/MSC	09-Apr-22	O/C	TSN 0				
SN:D5626	HRS	569.3		TSN 0				
	AFL	567		TSN 0				
PROC. REF: AMM 28-00-00, AMM 28-00-00PROC. REF: AMM 28-00-00, AMM 28-00-00								
28CA2821181	LEFT EJECTOR TRANSFER PUMP							Component ATA:28
PN:HJ1-12820-205-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:131	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-18, AMM 28-21-18PROC. REF: AMM 28-21-18, AMM 28-21-18								
28CA2821182	RIGHT EJECTOR TRANSFER PUMP							Component ATA:28
PN:HJ1-12820-205-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:132	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-18, AMM 28-21-18PROC. REF: AMM 28-21-18, AMM 28-21-18								
28CA2821191	NO. 1 LEFT EJECTOR SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-19, AMM 28-21-19PROC. REF: AMM 28-21-19, AMM 28-21-19								
28CA2821192	NO. 1 RIGHT EJECTOR SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-19, AMM 28-21-19PROC. REF: AMM 28-21-19, AMM 28-21-19								
28CA2821193	NO. 2 LEFT EJECTOR SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-19, AMM 28-21-19PROC. REF: AMM 28-21-19, AMM 28-21-19								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2821194	NO. 2 RIGHT EJECTOR SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-19, AMM 28-21-19PROC. REF: AMM 28-21-19, AMM 28-21-19								
28CA2821195	NO. 3 LEFT EJECTOR SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-19, AMM 28-21-19PROC. REF: AMM 28-21-19, AMM 28-21-19								
28CA2821196	NO. 3 RIGHT EJECTOR SCAVENGE PUMP							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-19, AMM 28-21-19PROC. REF: AMM 28-21-19, AMM 28-21-19								
28CA2821201	LEFT ELECTRIC BOOST PUMP CONTROLLER							Component ATA:28
PN:HJ1-12820-104-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:141	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-20, AMM 28-21-20PROC. REF: AMM 28-21-20, AMM 28-21-20								
28CA2821202	RIGHT ELECTRIC BOOST PUMP CONTROLLER							Component ATA:28
PN:HJ1-12820-104-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:140	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-20, AMM 28-21-20PROC. REF: AMM 28-21-20, AMM 28-21-20								
28CA2821221	LEFT PRESSURE TRANSDUCER							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-22, AMM 28-21-22PROC. REF: AMM 28-21-22, AMM 28-21-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2821222	RIGHT PRESSURE TRANSDUCER							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-22, AMM 28-21-22PROC. REF: AMM 28-21-22, AMM 28-21-22								
28CA2841101	FUSELAGE FUEL (F1) PROBE							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-10, AMM 28-41-10PROC. REF: AMM 28-41-10, AMM 28-41-10								
28CA2841111	FUSELAGE FUEL PROBE HARNESS							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-11, AMM 28-41-11PROC. REF: AMM 28-41-11, AMM 28-41-11								
28CA2841131	FUEL QTY SIGNAL CONDITIONER							Component ATA:28
PN:HJ1-12840-101-009	MOS/MSC	21-Jul-25	O/C					
SN:1708600001	HRS	1677.2						
	AFL	1530						
PROC. REF: AMM 28-41-13, AMM 28-41-13PROC. REF: AMM 28-41-13, AMM 28-41-13								
28CA2842101	LEFT WING FUEL QUANTITY PROBE HARNESS							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-10, AMM 28-42-10PROC. REF: AMM 28-42-10, AMM 28-42-10								
28CA2842102	RIGHT WING FUEL QUANTITY PROBE HARNESS							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-10, AMM 28-42-10PROC. REF: AMM 28-42-10, AMM 28-42-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2842111	NO. 1 LEFT WING TANK PROBE (LW1)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								
28CA2842112	NO. 1 RIGHT WING TANK PROBE (RW1)							Component ATA:28
PN:HJ1-12840-105-001	MOS/MSC	21-Jul-25	O/C	TSN 0				
SN:DTDK561	HRS	1677.2		TSN 0				
	AFL	1530		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								
28CA2842113	NO. 2 LEFT WING TANK PROBE (LW2)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								
28CA2842114	NO. 2 RIGHT WING TANK PROBE (RW2)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								
28CA2842115	NO. 3 LEFT WING TANK PROBE (LW3)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								
28CA2842116	NO. 3 RIGHT WING TANK PROBE (RW3)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2842117	NO. 4 LEFT WING TANK PROBE (LW4)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								
28CA2842118	NO. 4 RIGHT WING TANK PROBE (RW4)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-11, AMM 28-42-11PROC. REF: AMM 28-42-11, AMM 28-42-11								
28CA2842119	LEFT WING COLLECTOR TANK COMPENSATOR PROBE (LWC)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2842120	RIGHT WING COLLECTOR TANK COMPENSATOR PROBE (RWC)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2842121	NO. 1 FLUID LEVEL-12.5 INCH OPTICAL SENSOR							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-12, AMM 28-42-12PROC. REF: AMM 28-42-12, AMM 28-42-12								
28CA2842122	NO. 2 FLUID LEVEL-12.5 INCH OPTICAL SENSOR							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-12, AMM 28-42-12PROC. REF: AMM 28-42-12, AMM 28-42-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28CA2842140	NO. 1 CARRY-THROUGH TANK PROBE (CTL)							Component ATA:28
PN:HJ1-12840-103-001	MOS/MSC	21-Jul-25	O/C	TSN 0				
SN:DTCC510	HRS	1677.2		TSN 0				
	AFL	1530		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2842141	NO. 2 CARRY-THROUGH TANK PROBE (CTA)							Component ATA:28
PN:HJ1-12840-125-003	MOS/MSC	21-Jul-25	O/C	TSN 0				
SN:DTAW540	HRS	1677.2		TSN 0				
	AFL	1530		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2842142	NO. 3 CARRY-THROUGH TANK PROBE (CTF)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2842143	NO. 4 CARRY-THROUGH TANK PROBE (CTR)							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
28CA2842151	CENTER WING FUEL PROBE HARNESS							Component ATA:28
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-42-15, AMM 28-42-15PROC. REF: AMM 28-42-15, AMM 28-42-15								
28HA0500101	DO AN EXTERNAL VISUAL INSPECTION OF THE FUEL DRAINS.							Service ATA:28
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9		Adj 38.1				
	AFL	1084						
WO#: FAMQ0152								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28HA0500102	DO A VISUAL INSPECTION OF THE FUEL PLACARDS.							Service ATA:28
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
28HA0500103	DO A VISUAL INSPECTION OF THE FUEL LINES IN THE PYLON.							Service ATA:28
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
28HA0500104	DO A VISUAL INSPECTION OF THE ELECTRIC BOOST PUMP CONTROLLER.							Service ATA:28
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9		Adj 38.1				
	AFL	1084						
								WO#: FAMQ0152
28HA0500105	SURGE TANK FLOAT SWITCH - DETAILED INSPECTION							Service ATA:28
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 28-00-05PROC. REF: AMM 28-00-05								
28HA0500111	FUEL VENT OPTICAL SENSOR (2F9389) - DETAILED INSPECTION							Service ATA:28
	MOS/MSC	23-Jun-17	N/A					
	HRS	0						
	AFL	0						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 28-00-01, AMM 28-00-05PROC. REF: AMM 28-00-01, AMM 28-00-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28HA0500112	LOW LEVEL SENSORS - FUNCTIONAL TEST (PN HJ1-12840-202-001)							Service ATA:28
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	1200 (+60/-60)		2361.9	2421.9	646.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 28-00-03PROC. REF: AMM 28-00-03								
28HA2800103	DO THE OPERATIONAL TEST OF THE FUEL DISTRIBUTION SYSTEM.							Service ATA:28
	MOS	23-Jun-17		TAC 0				
	HRS	0	2400 (+60/-60)		2400	2460	684.9 (+60)	
	AFL	0		TAC 0				
PROC. REF: AMM 28-00-01PROC. REF: AMM 28-00-01								
28HA2800104	FUEL SYSTEM TEST; VENT VALVES (PN HJ1-12810-141-003), VENT DRAINS (PN HJ1-12842-142-001) - FUNCTIONAL TEST							Service ATA:28
	MOS	23-Jun-17		TAC 0				AIRWORTHINESS
	HRS	0	2400 (+60/-60)		2400	2460	684.9 (+60)	
	AFL	0		TAC 0				
PROC. REF: AMM 28-00-02PROC. REF: AMM 28-00-02								
28HA2840102	FUEL INDICATING SYSTEM; FUEL QUANTITY SIGNAL CONDITIONER (FQSC) - OPERATIONAL TEST							Service ATA:28
	MOS	21-Jul-25						AIRWORTHINESS
	HRS	1677.2	2400 (+60/-60)		4077.2	4137.2	2362.1 (+60)	
	AFL	1530						
								WO#: FAMQ0152
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
ATA 29 - HYDRAULIC POWER								
29CA2900001	HYDRAULIC VOLUME COMPENSATOR							Component ATA:29
PN:HJ1-13243-301-011	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:AWB00186	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29CA2900004	ECOLOGY BOTTLE							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
29CA2911001	NO. 1 MAIN HYDRAULIC PRESSURE SENSOR							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-31-11, AMM 29-31-11PROC. REF: AMM 29-31-11, AMM 29-31-11								
29CA2911002	NO. 2 MAIN HYDRAULIC PRESSURE SENSOR							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-31-11, AMM 29-31-11PROC. REF: AMM 29-31-11, AMM 29-31-11								
29CA2911004	HYDRAULIC RESERVOIR AND FILTER MODULE ASSEMBLY PRESSURE SENSOR							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-31-11, AMM 29-31-11PROC. REF: AMM 29-31-11, AMM 29-31-11								
29CA2911005	MAIN HYDRAULIC PRESSURE SENSOR							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-31-11, AMM 29-31-11PROC. REF: AMM 29-31-11, AMM 29-31-11								
29CA2911006	HYDRAULIC PUMP ASSEMBLY							Component ATA:29
PN:HJ1-12913-101-009	MOS/MSC	27-Jul-21	O/C	TSR 0				
SN:MX810101A	HRS			TSR 0				
	AFL	328		TSR 0				
PROC. REF: AMM 29-11-12, AMM 29-11-12PROC. REF: AMM 29-11-12, AMM 29-11-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29CA2911025	MAIN HYDRAULIC SYSTEM ACCUMULATOR TANK							Component ATA:29
PN:HJ1-12911-101-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1030	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-11, AMM 29-11-11PROC. REF: AMM 29-11-11, AMM 29-11-11								
29CA2911101	MAIN HYDRAULIC RESERVOIR							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-10, AMM 29-11-10PROC. REF: AMM 29-11-10, AMM 29-11-10								
29CA2911102	HYDRAULIC RESERVOIR AND FILTER MODULE							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-10, AMM 29-11-10PROC. REF: AMM 29-11-10, AMM 29-11-10								
29CA2911141	HYDRAULIC SYSTEM UNION RESERVOIR CHECK VALVE							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-14, AMM 29-11-14PROC. REF: AMM 29-11-14, AMM 29-11-14								
29CA2911151	HYDRAULIC SYSTEM T BULKHEAD ON RUN CHECK VALVE							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-15, AMM 29-11-15PROC. REF: AMM 29-11-15, AMM 29-11-15								
29CA2911161	HYDRAULIC SYSTEM T SWIVEL ON RUN CHECK VALVE							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-11-16, AMM 29-11-16PROC. REF: AMM 29-11-16, AMM 29-11-16								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29CA2911171	REPLACE HYDRAULIC FILTERS P/N 0711311-861, ACA902F815							Service ATA:29
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 29-11-17, AMM 29-11-17PROC. REF: AMM 29-11-17, AMM 29-11-17								
29CA2921101	NO. 1 ASSY, PRESSURE, AUX HYD ACCUMULATOR							Component ATA:29
PN:HJ1-12921-101-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:ETN00171	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-21-10, AMM 29-21-10PROC. REF: AMM 29-21-10, AMM 29-21-10								
29CA2921101	NO. 2 ASSY, PRESSURE, AUX HYD ACCUMULATOR							Component ATA:29
PN:HJ1-12921-101-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:ETN00100	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-21-10, AMM 29-21-10PROC. REF: AMM 29-21-10, AMM 29-21-10								
29CA2921111	AUXILIARY HYDRAULIC DUMP VALVE							Component ATA:29
PN:HJ1-12921-201-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:58	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-21-11, AMM 29-21-11PROC. REF: AMM 29-21-11, AMM 29-21-11								
29CA2931101	MAIN HYDRAULIC PRESSURE SWITCH							Component ATA:29
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-31-10, AMM 29-31-10PROC. REF: AMM 29-31-10, AMM 29-31-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29HA0500103 ^S	DO A VISUAL INSPECTION OF THE HYDRAULIC PUMP.							Service ATA:29
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
29HA0500105	DO A VISUAL INSPECTION OF ALL HYDRAULIC PLUMBING.							Service ATA:29
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)	Adj 38.1	2400	2460	684.9 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
29HA0500108 ^S	DO A VISUAL INSPECTION OF THE HYDRAULIC MODULE, RESERVOIR, MAIN ACCUMULATOR, BRAKE ACCUMULATOR, ELECTRICAL HARNESSES AND CONDUIT.							Service ATA:29
	MOS	23-Jun-17						
	HRS	0	1200 (+60/-60)					
	AFL	0						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6
29HA0500109 ^S	DO A VISUAL INSPECTION OF THE EMERGENCY ACCUMULATOR AND PLUMBING.							Service ATA:29
	MOS	23-Jun-17						
	HRS	0	1200 (+60/-60)					
	AFL	0						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6
29HA2900107	HYDRAULIC POWER SYSTEM - FUNCTIONAL TEST							Service ATA:29
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
PROC. REF: AMM 29-00-01, AMM 29-00-01PROC. REF: AMM 29-00-01, AMM 29-00-01								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30CA3011001	LH DE-ICE ASSEMBLY							Component ATA:30
PN:HJ1-13010-510-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:CX0061	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-10, AMM 30-12-10PROC. REF: AMM 30-12-10, AMM 30-12-10								
30CA3011002	RH DE-ICE ASSEMBLY							Component ATA:30
PN:HJ1-13010-510-008	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:CX0064	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-10, AMM 30-12-10PROC. REF: AMM 30-12-10, AMM 30-12-10								
30CA3011101	LEFT WING ANTI-ICE (WAIV) CHECK VALVE							Component ATA:30
PN:HJ1-13010-611-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:167A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-10, AMM 30-11-10PROC. REF: AMM 30-11-10, AMM 30-11-10								
30CA3011102	RIGHT WING ANTI-ICE (WAIV) CHECK VALVE							Component ATA:30
PN:HJ1-13010-611-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:168A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-10, AMM 30-11-10PROC. REF: AMM 30-11-10, AMM 30-11-10								
30CA3011111	WING ANTI-ICE CROSS (WAIXV) FLOW VALVE							Component ATA:30
PN:HJ1-13010-621-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:65	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-11, AMM 30-11-11PROC. REF: AMM 30-11-11, AMM 30-11-11								
30CA3011131	LEFT WING ANTI-ICE LEAK DETECTION SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-13, AMM 30-11-13PROC. REF: AMM 30-11-13, AMM 30-11-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30CA3011132	RIGHT WING ANTI-ICE LEAK DETECTION SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-13, AMM 30-11-13PROC. REF: AMM 30-11-13, AMM 30-11-13								
30CA3011141	LEFT NO. 1 ANTI-ICE WING TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-14, AMM 30-11-14PROC. REF: AMM 30-11-14, AMM 30-11-14								
30CA3011142	RIGHT NO. 1 ANTI-ICE WING TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-14, AMM 30-11-14PROC. REF: AMM 30-11-14, AMM 30-11-14								
30CA3011143	LEFT NO. 2 ANTI-ICE WING TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-14, AMM 30-11-14PROC. REF: AMM 30-11-14, AMM 30-11-14								
30CA3011144	RIGHT NO. 2 ANTI-ICE WING TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-14, AMM 30-11-14PROC. REF: AMM 30-11-14, AMM 30-11-14								
30CA3012102	DE-ICE CONTROL UNIT							Component ATA:30
PN:HJ1-13010-521-017	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:84	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-10, AMM 30-12-10PROC. REF: AMM 30-12-10, AMM 30-12-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30CA3012112	ENERGY STORAGE BANK							Component ATA:30
PN:HJ1-13010-522-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:52	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-11, AMM 30-12-11PROC. REF: AMM 30-12-11, AMM 30-12-11								
30CA3021131	LEFT NO. 1 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								
30CA3021132	LEFT NO. 2 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								
30CA3021133	LEFT NO. 3 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								
30CA3021134	LEFT NO. 4 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								
30CA3021135	RIGHT NO. 1 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30CA3021136	RIGHT NO. 2 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								
30CA3021137	RIGHT NO. 3 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								
30CA3021138	RIGHT NO. 4 COWL ANTI-ICE OVER-TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-13, AMM 30-21-13PROC. REF: AMM 30-21-13, AMM 30-21-13								
30CA3041101	LEFT WINDSHIELD CONTROL UNIT							Component ATA:30
PN:HJ1-13040-210-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:140	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-10, AMM 30-41-10PROC. REF: AMM 30-41-10, AMM 30-41-10								
30CA3041102	RIGHT WINDSHIELD CONTROL UNIT							Component ATA:30
PN:HJ1-13040-210-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:141	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-10, AMM 30-41-10PROC. REF: AMM 30-41-10, AMM 30-41-10								
30CA3081103	LEFT ICE DETECTOR PROBE							Component ATA:30
PN:0871ND4-1	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:0871ND4-1-0161	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-81-10, AMM 30-81-10PROC. REF: AMM 30-81-10, AMM 30-81-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30CA3081104	RIGHT ICE DETECTOR PROBE							Component ATA:30
PN:0871ND4-1	MOS/MSC	24-Aug-18	O/C					
SN:0871ND4-1-0191	HRS	303.1						
	AFL	284						
PROC. REF: AMM 30-81-10, AMM 30-81-10PROC. REF: AMM 30-81-10, AMM 30-81-10								
30HA0500101	DO A VISUAL INSPECTION OF ALL ICE AND RAIN PROTECTION TUBING, COUPLINGS, SENSORS, AND CLAMPS.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)	Adj 38.1	2400	2460	684.9 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
30HA0500102 ^S	DO A VISUAL INSPECTION OF THE WING ANTI-ICE SYSTEM COMPONENTS.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
30HA0500103 ^S	DO A VISUAL INSPECTION OF THE HORIZONTAL TAIL ICE PROTECTION SYSTEM.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
30HA3010101	WING ICE PROTECTION SYSTEM - OPERATIONAL TEST							Service ATA:30
	MOS	24-Oct-23						AIRWORTHINESS
	HRS	1452.2	300 (+10%/-10%)		1752.2	1782.2	37.1 (+30)	
	AFL	1321						
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01								WO#: 81318,FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30HA3010102	DO THE OPERATIONAL TEST OF HORIZONTAL TAIL ICE PROTECTION SYSTEM.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)		2361.9	2421.9	646.8 (+60)	
	AFL	1084						
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								WO#: FAMQ0152
30HA3010104	DO THE OPERATIONAL TEST OF THE WING ICE PROTECTION SYSTEM. (EFFECTIVITY: 42000011 THRU 42000125) NOTE: ACCOMPLISHMENT OF THIS AMM TASK SATISFIES THE REQUIREMENTS OF BOTH INSPECTION TASK 30HA3010104 IN THIS SECTION AND TASK 30HA3010101 IN SECTION 05-60-00.							Service ATA:30
	MOS	24-Oct-23						
	HRS	1452.2	300 (+10%/-10%)		1752.2	1782.2	37.1 (+30)	
	AFL	1321						
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01								WO#: FAMQ0152
30HA3010105 ^S	DO THE OPERATIONAL TEST OF THE WING ICE PROTECTION SYSTEM. (EFFECTIVITY: 42000126 AND AFTER) NOTE: ACCOMPLISHMENT OF THIS AMM TASK SATISFIES THE REQUIREMENTS OF BOTH INSPECTION TASK 30HA3010105 IN THIS SECTION AND TASK 30HA3010103 IN SECTION 05-60.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01								PKG:1 WO#: FAMQ0152
30HA3020101 ^S	DO THE OPERATIONAL TEST OF THE ENGINE INLET ICE PROTECTION SYSTEM.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30HA3020102	BLEED AIR LEAK DETECTION SYSTEM (OVER TEMPERATURE SWITCH) - FUNCTIONAL TEST							Service ATA:30
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02								
30HA3040101	WINDSHIELD TEMPERATURE SENSING SYSTEM - FUNCTIONAL TEST							Service ATA:30
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 30-40-01, AMM 30-40-01PROC. REF: AMM 30-40-01, AMM 30-40-01								
30HA3040103 ^S	DO THE FUNCTIONAL TEST OF THE WINDSHIELD HEAT CONTROL SYSTEM. NOTE: ACCOMPLISHMENT OF THIS AMM TASK SATISFIES THE REQUIREMENTS OF BOTH INSPECTION TASK 30HA3040103 IN THIS SECTION AND TASK 30HA3040101 IN SECTION 05-60.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 30-40-01, AMM 30-40-01PROC. REF: AMM 30-40-01, AMM 30-40-01								
30HA3080101 ^S	DO THE OPERATIONAL TEST OF THE ICE DETECTOR SYSTEM.							Service ATA:30
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31CA3111101	LEFT GTC 570/575 TOUCH SCREEN CONTROLLER DISPLAY							Component ATA:31
PN:011-01924-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1MB506641	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-10, AMM 31-11-10PROC. REF: AMM 31-11-10, AMM 31-11-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31CA3111102	RIGHT GTC 570/575 TOUCH SCREEN CONTROLLER DISPLAY							Component ATA:31
PN:011-01924-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1MB506642	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-10, AMM 31-11-10PROC. REF: AMM 31-11-10, AMM 31-11-10								
31CA3111111	OXYGEN AND PRESSURIZATION PANEL							Component ATA:31
PN:HJ1-13100-106-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:4201900AA0081	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-11, AMM 31-11-11PROC. REF: AMM 31-11-11, AMM 31-11-11								
31CA3111121	PHASE III ELECTRICAL PANEL							Component ATA:31
PN:HJ1-13100-107-009	MOS/MSC	02-Jun-23	O/C	TSN 90				
SN:4201700AA0064	HRS	1161.9		TSN 0				
	AFL	1084		TSN 0				
PROC. REF: AMM 31-11-12, AMM 31-11-12PROC. REF: AMM 31-11-12, AMM 31-11-12								
31CA3111122	ELECTRICAL PANEL							Component ATA:31
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-12, AMM 31-11-12PROC. REF: AMM 31-11-12, AMM 31-11-12								
31CA3111131	LEFT ANNUNCIATOR PANEL							Component ATA:31
PN:HJ1-13100-105-007	MOS/MSC	04-Oct-21	O/C					
SN:4201500AA0111	HRS	361.4						
	AFL	348						
PROC. REF: AMM 31-11-13, AMM 31-11-13PROC. REF: AMM 31-11-13, AMM 31-11-13								
31CA3111132	RIGHT ANNUNCIATOR PANEL							Component ATA:31
PN:HJ1-13100-105-007	MOS/MSC	20-Jul-22	O/C	TSN 0				
SN:4201500AA0500	HRS	744.6		TSN 0				
	AFL	707		TSN 0				
PROC. REF: AMM 31-11-13, AMM 31-11-13PROC. REF: AMM 31-11-13, AMM 31-11-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31CA3111141	PHASE III LANDING GEAR CONTROL LEVER & ELT PANEL							Component ATA:31
PN:HJ1-13100-110-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:4201800AA0076	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-14, AMM 31-11-14PROC. REF: AMM 31-11-14, AMM 31-11-14								
31CA3111171	AUTOFLIGHT CONTROL SYSTEM SERVO POWER PANEL							Component ATA:31
PN:HJ1-13100-104-015	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:4201400AA0077	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-17, AMM 31-11-17PROC. REF: AMM 31-11-17, AMM 31-11-17								
31CA3111181	MASTER FIRE WARNING FIRE PANEL							Component ATA:31
PN:HJ1-13100-103-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:4201600AA0038	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-18, AMM 31-11-18PROC. REF: AMM 31-11-18, AMM 31-11-18								
31CA3111221	ENGINE START PANEL							Component ATA:31
PN:HJ1-13100-111-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:4202300AA0005	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-22, AMM 31-11-22PROC. REF: AMM 31-11-22, AMM 31-11-22								
31CA3111231	AFT CENTER PEDESTAL PHASE III PANEL							Component ATA:31
PN:HJ1-13100-112-013	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:4202200AA0044	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-23, AMM 31-11-23PROC. REF: AMM 31-11-23, AMM 31-11-23								
31CA3121001	NO. 1 GEA71 INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:46722725	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31CA3121002	NO. 2 GEA71 INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:46723054	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
31CA3121003	NO. 3 GEA71 INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:46723114	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
31CA3121101	LEFT GSD41 DATA CONCENTRATOR UNIT							Component ATA:31
PN:011-01457-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:16906795	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-21-10, AMM 31-21-10PROC. REF: AMM 31-21-10, AMM 31-21-10								
31CA3121102	RIGHT GSD41 DATA CONCENTRATOR UNIT							Component ATA:31
PN:011-01457-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:16906796	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-21-10, AMM 31-21-10PROC. REF: AMM 31-21-10, AMM 31-21-10								
31CA3131001	VOICE / DATA (CVR / FDR) (OPTIONAL EQUIPMENT) RECORDER							Component ATA:31
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-10, AMM 31-31-10, CMM 23-70-08PROC. REF: AMM 31-31-10, AMM 31-31-10, CMM 23-70-08								
31CA3131002	REMOTE MICROPHONE							Component ATA:31
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-12, AMM 31-31-12PROC. REF: AMM 31-31-12, AMM 31-31-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31CA3131003	MICROPHONE AMPLIFIER							Component ATA:31
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-11, AMM 31-31-11PROC. REF: AMM 31-31-11, AMM 31-31-11								
31CA3131004	REPLACE - 1605-01-00 CVR/FDR COMPONENT BATTERY (7905012 DK120/90)							Component ATA:31
PN:PN	MOS/MSC	23-Jun-17	N/A	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
								WO#: FAMQ0152
PROC. REF: CMM 03-TM-0063PROC. REF: CMM 03-TM-0063								
31CA3131005	1605-01-00 CVR/FDR COMPONENTS BATTERY (7905012 DK120/90) AND BEACON (DK120/90) - CLEAN AND TEST							Service ATA:31
	MOS/MSC	23-Jun-17	N/A					NOT INSTALLED
	HRS	0						
	AFL	0						
PROC. REF: CMM 23-70-08, CMM 23-70-08, CMM 03-TM-0063PROC. REF: CMM 23-70-08, CMM 23-70-08, CMM 03-TM-0063								
31CA3131006	REPLACE - 1605-01-00 CVR/FDR COMPONENT BATTERY (DK290/XX)							Component ATA:31
PN:PN	MOS	EFF	72	TSN 0	30-Jun-29 *		1298 d	LIFE LIMIT
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: CMM 03-TM-0063PROC. REF: CMM 03-TM-0063								
31CA3161101	LEFT PFD-MFD-GDU1400 DISPLAY							Component ATA:31
PN:011-01910-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1F1005685	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-10, AMM 31-61-10, AMM 31-61-11, AMM 31-61-11PROC. REF: AMM 31-61-10, AMM 31-61-10, AMM 31-61-11, AMM 31-61-11								
31CA3161102	RIGHT PFD-MFD-GDU1400 DISPLAY							Component ATA:31
PN:011-01910-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1F1005694	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-10, AMM 31-61-10, AMM 31-61-11, AMM 31-61-11PROC. REF: AMM 31-61-10, AMM 31-61-10, AMM 31-61-11, AMM 31-61-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31CA3161103	CENTER PFD-MFD-GDU1400 DISPLAY							Component ATA:31
PN:011-01910-00	MOS/MSC	01-Feb-19	O/C					
SN:1F1005289	HRS	310.7						
	AFL	290						
PROC. REF: AMM 31-61-10, AMM 31-61-10, AMM 31-61-11, AMM 31-61-11PROC. REF: AMM 31-61-10, AMM 31-61-10, AMM 31-61-11, AMM 31-61-11								
31HA0500101	DO A VISUAL INSPECTION OF THE INSTRUMENT PANEL, INSTRUMENTS, AND PEDESTAL EQUIPMENT.							Service ATA:31
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
ATA 32 - LANDING GEAR								
32CA3200001	LEFT MLG SIDE BRACE ACTUATOR ASSEMBLY PIN							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-15, AMM 32-31-15PROC. REF: AMM 32-31-15, AMM 32-31-15								
32CA3200002	RIGHT MLG SIDE BRACE ACTUATOR ASSEMBLY PIN							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-15, AMM 32-31-15PROC. REF: AMM 32-31-15, AMM 32-31-15								
32CA3200003	DRESSED NOSE GEAR							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3200005	NO. 1 LEFT MLG SWIVEL FITTING							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32CA3200006	NO. 1 RIGHT MLG SWIVEL FITTING							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32CA3200007	NO. 2 LEFT MLG SWIVEL FITTING							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32CA3200008	NO. 2 RIGHT MLG SWIVEL FITTING							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32CA3200009	LEFT MLG DRESSED SIDE BRACE ACTUATOR							Component ATA:32
PN:HJ1-13210-100-015	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP0090	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-15, AMM 32-31-15PROC. REF: AMM 32-31-15, AMM 32-31-15								
32CA3200010	RIGHT MLG DRESSED SIDE BRACE ACTUATOR							Component ATA:32
PN:HJ1-13210-100-016	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP0086	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-15, AMM 32-31-15PROC. REF: AMM 32-31-15, AMM 32-31-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3211001	LEFT MAIN LANDING GEAR SHOCK ABSORBER							Component ATA:32
PN:HJ1-13213-100-009	MOS/MSC	15-Mar-24	O/C	TSO 10				
SN:SPC00102	HRS	1476.8		TSO 0				
	AFL	1340		TSO 0				
PROC. REF: AMM 32-11-11, AMM 32-11-11PROC. REF: AMM 32-11-11, AMM 32-11-11								
32CA3211002	RIGHT MAIN LANDING GEAR SHOCK ABSORBER							Component ATA:32
PN:HJ1-13213-100-010	MOS/MSC	22-Sep-23	O/C	TSO 9				
SN:SPC0022	HRS	1371.1		TSO 0				
	AFL	1262		TSO 0				
PROC. REF: AMM 32-11-11, AMM 32-11-11PROC. REF: AMM 32-11-11, AMM 32-11-11								
32CA3211003	LEFT MLG ARM AND AXLE							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-14, AMM 32-11-14PROC. REF: AMM 32-11-14, AMM 32-11-14								
32CA3211004	RIGHT MLG ARM AND AXLE							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-14, AMM 32-11-14PROC. REF: AMM 32-11-14, AMM 32-11-14								
32CA3211005	LEFT MLG TRAILING ARM							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-14, AMM 32-11-14PROC. REF: AMM 32-11-14, AMM 32-11-14								
32CA3211006	RIGHT MLG TRAILING ARM							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-14, AMM 32-11-14PROC. REF: AMM 32-11-14, AMM 32-11-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3211103	LEFT MAIN LANDING GEAR SYSTEM							Component ATA:32
PN:HJ1-13210-000-033	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPC0050	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-10, AMM 32-11-10PROC. REF: AMM 32-11-10, AMM 32-11-10								
32CA3211104	RIGHT MAIN LANDING GEAR SYSTEM							Component ATA:32
PN:HJ1-13210-000-034	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPC0016	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-10, AMM 32-11-10PROC. REF: AMM 32-11-10, AMM 32-11-10								
32CA3221003	NLG SIDE BRACE ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-15, AMM 32-31-15PROC. REF: AMM 32-31-15, AMM 32-31-15								
32CA3221101	NLG DRESSED SHOCK STRUT							Component ATA:32
PN:HJ1-13221-000-017	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP0092	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-10, AMM 32-21-10PROC. REF: AMM 32-21-10, AMM 32-21-10								
32CA3231001	EMERGENCY / PARK BRAKE VALVE ASSY UNION							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-12, AMM 32-41-12PROC. REF: AMM 32-41-12, AMM 32-41-12								
32CA3231002	PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3231101	NLG DRESSED SIDE BRACE ACTUATOR							Component ATA:32
PN:HJ1-13233-200-017	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP0092	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-10, AMM 32-31-10PROC. REF: AMM 32-31-10, AMM 32-31-10								
32CA3231112	NOSE LANDING GEAR UPLOCK ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-11, AMM 32-31-11PROC. REF: AMM 32-31-11, AMM 32-31-11								
32CA3231121	LANDING GEAR CONTROL UNIT							Component ATA:32
PN:HJ1-13230-101-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP00076	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-12, AMM 32-31-12PROC. REF: AMM 32-31-12, AMM 32-31-12								
32CA3231131	NLG RETRACTION FLOW CONTROL VALVE							Component ATA:32
PN:HJ1-13233-001-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:84	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32CA3231132	LEFT MLG EXTENSION FLOW CONTROL VALVE							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-13, AMM 32-31-13PROC. REF: AMM 32-31-13, AMM 32-31-13								
32CA3231133	RIGHT MLG EXTENSION FLOW CONTROL VALVE							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-13, AMM 32-31-13PROC. REF: AMM 32-31-13, AMM 32-31-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3231134	LEFT MLG RETRACTION FLOW CONTROL VALVE							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-13, AMM 32-31-13PROC. REF: AMM 32-31-13, AMM 32-31-13								
32CA3231135	RIGHT MLG RETRACTION FLOW CONTROL VALVE							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-13, AMM 32-31-13PROC. REF: AMM 32-31-13, AMM 32-31-13								
32CA3231142	LEFT INBD MLG DOOR ACTUATOR							Component ATA:32
PN:HJ1-13232-100-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP0078	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-14, AMM 32-31-14PROC. REF: AMM 32-31-14, AMM 32-31-14								
32CA3231143	RIGHT INBD MLG DOOR ACTUATOR							Component ATA:32
PN:HJ1-13232-100-010	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP0087	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-14, AMM 32-31-14PROC. REF: AMM 32-31-14, AMM 32-31-14								
32CA3231151	LEFT MLG SIDE BRACE ACTUATOR							Component ATA:32
PN:HJ1-13233-100-019	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SPP0090	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-15, AMM 32-31-15PROC. REF: AMM 32-31-15, AMM 32-31-15								
32CA3231152	RIGHT MLG SIDE BRACE ACTUATOR							Component ATA:32
PN:HJ1-13233-100-022	MOS/MSC	22-Sep-23	O/C	TSO 5				
SN:SPP0212	HRS	1371.1		TSO 0				
	AFL	1262		TSO 0				
PROC. REF: AMM 32-31-15, AMM 32-31-15PROC. REF: AMM 32-31-15, AMM 32-31-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3231161	LANDING GEAR CONTROL SYSTEM LEVER							Component ATA:32
PN:HJ1-13230-102-011	MOS/MSC	09-Apr-21	O/C					
SN:0115	HRS	311.8		TSN 180.5				
	AFL	291		TSN 185				
PROC. REF: AMM 32-31-16, AMM 32-31-16PROC. REF: AMM 32-31-16, AMM 32-31-16								
32CA3232001	LEFT MAIN LANDING GEAR INBOARD DOOR EXTENSION RESTRICTOR FITTING							Component ATA:32
PN:HJ1-13232-001-001	MOS	02-Jun-23		TSN 13				AIRWORTHINESS
SN:0646	HRS	1161.9	1200	TSN 0	2361.9		646.8	
	AFL	1084		TSN 0				
								WO#: FAMQ0152
PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14								
32CA3232002	RIGHT MAIN LANDING GEAR INBOARD DOOR EXTENSION RESTRICTOR FITTING							Component ATA:32
PN:HJ1-13232-001-001	MOS	02-Jun-23		TSN 13				AIRWORTHINESS
SN:0647	HRS	1161.9	1200	TSN 0	2361.9		646.8	
	AFL	1084		TSN 0				
								WO#: FAMQ0152
PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14								
32CA3232003	LEFT MAIN LANDING GEAR INBOARD DOOR RETRACTION RESTRICTOR FITTING							Component ATA:32
PN:HJ1-13232-002-001	MOS	02-Jun-23		TSN 13				AIRWORTHINESS
SN:0664	HRS	1161.9	1200	TSN 0	2361.9		646.8	
	AFL	1084		TSN 0				
								WO#: FAMQ0152
PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14								
32CA3232004	RIGHT MAIN LANDING GEAR INBOARD DOOR RETRACTION RESTRICTOR FITTING							Component ATA:32
PN:HJ1-13232-002-001	MOS	02-Jun-23		TSN 13				AIRWORTHINESS
SN:0655	HRS	1161.9	1200	TSN 0	2361.9		646.8	
	AFL	1084		TSN 0				
								WO#: FAMQ0152
PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14PROC. REF: AMM 32-31-14, AMM 32-31-14, AMM 32-31-14, AMM 32-31-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3241011	LEFT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:90006365	MOS/MSC	10-May-24	O/C	TSR 0				
SN:MAY16-0294	HRS	1548.2		TSR 0				
	AFL	1400		TSN 620, TSR 0				
PROC. REF: AMM 32-41-11, AMM 32-41-11PROC. REF: AMM 32-41-11, AMM 32-41-11								
32CA3241012	RIGHT MAIN LANDING GEAR WHEEL							Component ATA:32
PN:90006365	MOS/MSC	24-Mar-24	O/C	TSN 8				
SN:OCT21-0652	HRS	1487.1		TSN 230.6				
	AFL	1348		TSN 193				
PROC. REF: AMM 32-41-11, AMM 32-41-11PROC. REF: AMM 32-41-11, AMM 32-41-11								
32CA3241023	NOSE LANDING GEAR WHEEL							Component ATA:32
PN:90006367	MOS/MSC	14-Jul-23	O/C					
SN:JAN17-0162	HRS	1256.5						
	AFL	1155		TSN 700				
PROC. REF: AMM 32-41-10, AMM 32-41-10PROC. REF: AMM 32-41-10, AMM 32-41-10								
32CA3241041	LEFT MAIN LANDING GEAR TIRE							Component ATA:32
PN:M19402	MOS/MSC	10-May-24	O/C	TSN 0				
SN:3101B157	HRS	1548.2		TSN 0				
	AFL	1400		TSN 0				
PROC. REF: AMM 32-41-11, AMM 32-41-11PROC. REF: AMM 32-41-11, AMM 32-41-11								
32CA3241042	RIGHT MAIN LANDING GEAR TIRE							Component ATA:32
PN:M19402	MOS/MSC	28-Apr-25	O/C	TSN 0, TSR 0				
SN:2115B104	HRS	1671.6		TSN 0				
	AFL	1523		TSN 0				
PROC. REF: AMM 32-41-11, AMM 32-41-11PROC. REF: AMM 32-41-11, AMM 32-41-11								
32CA3241043	NOSE LANDING GEAR TIRE							Component ATA:32
PN:M19301	MOS/MSC	14-Jul-23	O/C	TSN 0				
SN:2097B030	HRS	1256.5		TSN 0				
	AFL	1155		TSN 0				
PROC. REF: AMM 32-41-10, AMM 32-41-10PROC. REF: AMM 32-41-10, AMM 32-41-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3241121	BRAKE SYSTEM EMERGENCY / PARK BRAKE VALVE							Component ATA:32
PN:HJ1-13243-401-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:AWB00119	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-12, AMM 32-41-12PROC. REF: AMM 32-41-12, AMM 32-41-12								
32CA3241161	BRAKE SYSTEM ANTI-SKID CONTROL UNIT							Component ATA:32
PN:HJ1-13241-101-001	MOS/MSC	10-May-21	O/C	TSR 0				
SN:167	HRS	323		TSR 0				
	AFL	306		TSR 0				
PROC. REF: AMM 32-41-16, AMM 32-41-16PROC. REF: AMM 32-41-16, AMM 32-41-16								
32CA3241171	LEFT BRAKE SYSTEM ANTISKID TRANSDUCER CONTROL							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-17, AMM 32-41-17PROC. REF: AMM 32-41-17, AMM 32-41-17								
32CA3241172	RIGHT BRAKE SYSTEM ANTISKID TRANSDUCER CONTROL							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-17, AMM 32-41-17PROC. REF: AMM 32-41-17, AMM 32-41-17								
32CA3241173	POWER BRAKE AND ANTISKID BRAKE VALVE							Component ATA:32
PN:HJ1-13243-101-009	MOS/MSC	01-Feb-18	O/C	TSR 0				
SN:185	HRS	87		TSR 0				
	AFL	89		TSR 0				
PROC. REF: AMM 32-42-11, AMM 32-42-11PROC. REF: AMM 32-42-11, AMM 32-42-11								
32CA3241181	LEFT MAIN LANDING GEAR BRAKE							Component ATA:32
PN:90006366	MOS/MSC	24-Mar-24	O/C	TSO 0				
SN:SEP19-0449	HRS	1487.1		TSO 0				
	AFL	1348		TSO 0				
PROC. REF: AMM 32-41-18, AMM 32-41-18PROC. REF: AMM 32-41-18, AMM 32-41-18								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3241182	RIGHT MAIN LANDING GEAR BRAKE							Component ATA:32
PN:90006366	MOS/MSC	24-Mar-24	O/C	TSO 0				
SN:OCT16-0239	HRS	1487.1		TSO 0				
	AFL	1348		TSO 0				
PROC. REF: AMM 32-41-18, AMM 32-41-18PROC. REF: AMM 32-41-18, AMM 32-41-18								
32CA3241191	NO. 1 LEFT BRAKE SYSTEM MASTER CYLINDER							Component ATA:32
PN:HJ1-13243-201-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:AWB00223	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-19, AMM 32-41-19PROC. REF: AMM 32-41-19, AMM 32-41-19								
32CA3241192	NO. 1 RIGHT BRAKE SYSTEM MASTER CYLINDER							Component ATA:32
PN:HJ1-13243-201-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:AWB00224	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-19, AMM 32-41-19PROC. REF: AMM 32-41-19, AMM 32-41-19								
32CA3241193	NO. 2 LEFT BRAKE SYSTEM MASTER CYLINDER							Component ATA:32
PN:HJ1-13243-201-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:AWB00225	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-19, AMM 32-41-19PROC. REF: AMM 32-41-19, AMM 32-41-19								
32CA3241194	NO. 2 RIGHT BRAKE SYSTEM MASTER CYLINDER							Component ATA:32
PN:HJ1-13243-201-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:AWB00226	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-19, AMM 32-41-19PROC. REF: AMM 32-41-19, AMM 32-41-19								
32CA3241463	LEFT MAIN WHEEL ASSEMBLY P/N 90006365 - PERFORM VISUAL AND NDT INSPECTION							Service ATA:32
PN:90006365	MOS	10-May-24						
SN:MAY16-0294	HRS	1548.2						
	AFL	1400	750		2150		589	
PROC. REF: AMM 32-44-01, CMM 32-41-46PROC. REF: AMM 32-44-01, CMM 32-41-46								

WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3241464	RIGHT MAIN WHEEL ASSEMBLY P/N 90006365 - PERFORM VISUAL AND NDT INSPECTION							Service ATA:32
PN:90006365	MOS	14-Jul-23						
SN:OCT21-0652	HRS	1256.5						
	AFL	1155	750		1905		344	
PROC. REF: AMM 32-44-01, CMM 32-41-46PROC. REF: AMM 32-44-01, CMM 32-41-46								
32CA3241467	LEFT MAIN LANDING GEAR WHEEL ASSEMBLY - OVERHAUL							Service ATA:32
PN:90006365	MOS	10-May-24						OVERHAUL
SN:MAY16-0294	HRS	1548.2						
	AFL	1400	1500	TAC 620	2280		719	
PROC. REF: CMM 32-41-46PROC. REF: CMM 32-41-46								
32CA3241467	RIGHT MAIN LANDING GEAR WHEEL ASSEMBLY - OVERHAUL							Service ATA:32
PN:90006365	MOS	14-Jul-23						OVERHAUL
SN:OCT21-0652	HRS	1256.5						
	AFL	1155	1500		2655		1094	
PROC. REF: CMM 32-41-46PROC. REF: CMM 32-41-46								
32CA3241474	NOSE WHEEL ASSEMBLY P/N 90006367 - VISUAL AND NDT INSPECTION							Service ATA:32
PN:90006367	MOS	14-Jul-23						
SN:JAN17-0162	HRS	1256.5						
	AFL	1155	750		1905		344	
PROC. REF: AMM 32-44-01, CMM 32-46-45PROC. REF: AMM 32-44-01, CMM 32-46-45								
32CA3241477	NOSE WHEEL ASSEMBLY P/N 90006367 - OVERHAUL							Service ATA:32
PN:90006367	MOS	14-Jul-23						OVERHAUL
SN:JAN17-0162	HRS	1256.5						
	AFL	1155	1500		2655		1094	
PROC. REF: CMM 32-46-45PROC. REF: CMM 32-46-45								
32CA3242012	BRAKE SYSTEM CHECK VALVE - UNION							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32CA3242013	NO. 1 BRAKE SYSTEM VOLUME COMPENSATOR							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-13, AMM 32-42-13PROC. REF: AMM 32-42-13, AMM 32-42-13								
32CA3242013	NO. 2 BRAKE SYSTEM VOLUME COMPENSATOR							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-13, AMM 32-42-13PROC. REF: AMM 32-42-13, AMM 32-42-13								
32CA3251101	LANDING GEAR CONTROL VALVE							Component ATA:32
PN:HJ1-13234-101-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:AKN00086	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-10, AMM 32-42-10PROC. REF: AMM 32-42-10, AMM 32-42-10								
32CA3251122	NOSE WHEEL STEERING CONTROL UNIT							Component ATA:32
PN:HJ1-13251-111-011	MOS/MSC	28-Apr-25	O/C	TSR 0				
SN:SPP10116	HRS	1671.6		TSR 0				
	AFL	1523		TSR 0				
PROC. REF: AMM 32-51-12, AMM 32-51-12PROC. REF: AMM 32-51-12, AMM 32-51-12								
32CA3251131	LEFT NOSE STEERING TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32CA3251132	RIGHT NOSE STEERING TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
32HA0500104 ^S	DO A VISUAL INSPECTION OF THE NLG GEAR UPLOCK ASSEMBLY.							Service ATA:32
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
32HA0500105 ^S	DO A VISUAL INSPECTION OF THE NLG WEIGHT-ON-WHEELS SWITCH.							Service ATA:32
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
32HA0500107	DO A VISUAL INSPECTION OF THE MASTER CYLINDERS.							Service ATA:32
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)	Adj 38.1	2400	2460	684.9 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
32HA0500113 ^S	DO THE LANDING GEAR RIGGING PROCEDURE STEP 1. F. (2)							Service ATA:32
	MOS	23-Jun-17						
	HRS	0	1200 (+60/-60)					
	AFL	0						
								PKG:6
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32HA0500114 ^S	DO A VISUAL INSPECTION OF THE MLG WEIGHT-ON-WHEELS SWITCH, SHOCK ABSORBER AND INBOARD DOOR ACTUATORS, SIDE BRACE ACTUATORS, ELECTRICAL HARNESES AND CONDUIT.							Service ATA:32
	MOS	23-Jun-17						
	HRS	0	600 (+60/-60)					
	AFL	0						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:1
32HA3200103	EMERGENCY EXTENSION SYSTEM & NOSE LANDING GEAR UPLOCK - FUNCTIONAL TEST							Service ATA:32
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
PROC. REF: AMM 32-00-01, AMM 32-00-02PROC. REF: AMM 32-00-01, AMM 32-00-02								WO#: FAMQ0152
32HA3240101 ^S	DO THE FUNCTIONAL TEST OF THE BRAKE PRESSURE.							Service ATA:32
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								PKG:1 WO#: FAMQ0152
32HA3240102	LANDING GEAR LATENT FAILURES, DIGITAL ANTI-SKID CONTROL UNIT (DACU) ANNUNCIATION - FUNCTIONAL TEST							Service ATA:32
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								WO#: FAMQ0152
32HA3250102 ^S	DO THE FUNCTIONAL TEST OF THE NOSEWHEEL STEERING SYSTEM.							Service ATA:32
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01								PKG:1 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33CA3311001	COCKPIT CONSOLE LIGHT							Component ATA:33
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-11-10, AMM 33-11-10PROC. REF: AMM 33-11-10, AMM 33-11-10								
33CA3311002	PILOT MAP LIGHT							Component ATA:33
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-11-10, AMM 33-11-10PROC. REF: AMM 33-11-10, AMM 33-11-10								
33CA3311003	CO-PILOT MAP LIGHT							Component ATA:33
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-11-10, AMM 33-11-10PROC. REF: AMM 33-11-10, AMM 33-11-10								
33CA3341001	GROUND RECOGNITION LIGHT							Component ATA:33
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-44-10, AMM 33-44-10PROC. REF: AMM 33-44-10, AMM 33-44-10								
33CA3341101	LEFT TAXI LANDING LIGHT							Component ATA:33
PN:01-0790497-02	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:234	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-10, AMM 33-41-10PROC. REF: AMM 33-41-10, AMM 33-41-10								
33CA3341102	RIGHT TAXI LANDING LIGHT							Component ATA:33
PN:01-0790497-02	MOS/MSC	01-Feb-19	O/C	TSN 0				
SN:00180	HRS	310.7		TSN 0				
	AFL	290		TSN 0				
PROC. REF: AMM 33-41-10, AMM 33-41-10PROC. REF: AMM 33-41-10, AMM 33-41-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33CA3341111	LEFT TAXI RECOGNITION LIGHT							Component ATA:33
PN:01-0790485-01	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:233	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-11, AMM 33-41-11PROC. REF: AMM 33-41-11, AMM 33-41-11								
33CA3341112	RIGHT TAXI RECOGNITION LIGHT							Component ATA:33
PN:01-0790485-01	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:234	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-11, AMM 33-41-11PROC. REF: AMM 33-41-11, AMM 33-41-11								
33CA3341121	LEFT WING ICE INSPECTION LIGHT							Component ATA:33
PN:01-0771330-03	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-12, AMM 33-41-12PROC. REF: AMM 33-41-12, AMM 33-41-12								
33CA3341122	RIGHT WING ICE INSPECTION LIGHT							Component ATA:33
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-12, AMM 33-41-12PROC. REF: AMM 33-41-12, AMM 33-41-12								
33CA3341141	LEFT LIGHTING CONTROL UNIT							Component ATA:33
PN:HJ1-13300-101-011	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:185516-21-1	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-14, AMM 33-41-14PROC. REF: AMM 33-41-14, AMM 33-41-14								
33CA3341142	RIGHT LIGHTING CONTROL UNIT							Component ATA:33
PN:HJ1-13300-101-011	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:185516-21-2	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-14, AMM 33-41-14PROC. REF: AMM 33-41-14, AMM 33-41-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33CA3342101	LEFT ANTI-COLLISION/POSITION LIGHT							Component ATA:33
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-10, AMM 33-42-10PROC. REF: AMM 33-42-10, AMM 33-42-10								
33CA3342102	RIGHT ANTI-COLLISION/POSITION LIGHT							Component ATA:33
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-10, AMM 33-42-10PROC. REF: AMM 33-42-10, AMM 33-42-10								
33CA3343111	CURRENT SOURCE FLASHER							Component ATA:33
PN:01-0771234-03	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:483	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-11, AMM 33-43-11PROC. REF: AMM 33-43-11, AMM 33-43-11								
33CA3343112	TAIL AC/POS LIGHT							Component ATA:33
PN:01-0790482-02	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:254	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-11, AMM 33-43-11PROC. REF: AMM 33-43-11, AMM 33-43-11								
33CA3344111	TAXI-RECOG LIGHTS FLASHER							Component ATA:33
PN:01-0771375-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:216	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-44-11, AMM 33-44-11PROC. REF: AMM 33-44-11, AMM 33-44-11								
33HA0500101	DO A VISUAL INSPECTION OF THE COCKPIT OVERHEAD LIGHTS.							Service ATA:33
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33HA0500102	DO A VISUAL INSPECTION OF THE CABIN OVERHEAD, ENTRY, LAVATORY LIGHTS AND LENSES.							Service ATA:33
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
33HA0500103 ^S	DO A VISUAL INSPECTION OF THE LANDING/TAXI LIGHTS AND LENSES.							Service ATA:33
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
33HA0500104	DO A VISUAL INSPECTION OF THE POSITION LIGHTS, BEACON AND LENSES.							Service ATA:33
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
33HA0500105	DO A VISUAL INSPECTION OF THE LOGO AND WING INSPECTION LIGHTS (OPTIONAL EQUIPMENT).							Service ATA:33
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
33HA3300102	DO THE OPERATIONAL TEST OF THE EXTERIOR LIGHTS.							Service ATA:33
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 33-00-01PROC. REF: AMM 33-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-10-00 ^U	UPDATE NAV DATABASE							Service ATA:34
	DAYS	25-Sep-25	28		30-Oct-25 (M)		OVD	CUSTOMER CODE
	HRS	1715.1						
	AFL	1561						
34-10-01 ^U	UPDATE CHART DATABASE							Service ATA:34
	DAYS	25-Sep-25	14		16-Oct-25 (M)		OVD	CUSTOMER CODE
	HRS	1715.1						
	AFL	1561						
34CA3400000	LEFT INTEGRATED AVIONICS COMPUTER (GIA UNIT)							Component ATA:34
PN:011-01105-40	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2DC003185	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-00-00, AMM 34-00-00PROC. REF: AMM 34-00-00, AMM 34-00-00								
34CA3400001	RIGHT INTEGRATED AVIONICS COMPUTER (GIA UNIT)							Component ATA:34
PN:011-01105-40	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2DC003193	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-00-00, AMM 34-00-00PROC. REF: AMM 34-00-00, AMM 34-00-00								
34CA3400023	STANDBY INSTRUMENT DISPLAY							Component ATA:34
PN:40001-01-02	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:M037985	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-12, AMM 34-21-12PROC. REF: AMM 34-21-12, AMM 34-21-12								
34CA3400025	ENHANCED TCAS PROCESSOR							Component ATA:34
PN:011-02571-00	MOS/MSC	04-Oct-21	O/C					
SN:28P007235	HRS	361.4						
	AFL	348						
PROC. REF: AMM 34-41-13, AMM 34-41-13PROC. REF: AMM 34-41-13, AMM 34-41-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34CA3411102	LEFT MULTI-FUNCT AIR DATA PROBE							Component ATA:34
PN:2015T-1B	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:0144	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-10, AMM 34-11-10PROC. REF: AMM 34-11-10, AMM 34-11-10								
34CA3411103	RIGHT MULTI-FUNCT AIR DATA PROBE							Component ATA:34
PN:2015T-1B	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:0117	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-10, AMM 34-11-10PROC. REF: AMM 34-11-10, AMM 34-11-10								
34CA3411111	STANDBY AIR DATA PROBE							Component ATA:34
PN:100564-100-000	MOS/MSC	29-Mar-17	O/C	TSN 0				
SN:1001063	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-11, AMM 34-11-11PROC. REF: AMM 34-11-11, AMM 34-11-11								
34CA3421101	LEFT HAND GRS77 AHRs							Component ATA:34
PN:011-00868-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:42034720	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-10, AMM 34-21-10PROC. REF: AMM 34-21-10, AMM 34-21-10								
34CA3421102	RIGHT HAND GRS77 AHRs							Component ATA:34
PN:011-00868-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:42034721	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-10, AMM 34-21-10PROC. REF: AMM 34-21-10, AMM 34-21-10								
34CA3421111	LEFT GMU44 MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1CM019203	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-11, AMM 34-21-11PROC. REF: AMM 34-21-11, AMM 34-21-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34CA3421112	RIGHT GMU44 MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1CM019183	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-11, AMM 34-21-11PROC. REF: AMM 34-21-11, AMM 34-21-11								
34CA3421131	STANDBY MHS MAGNETOMETER							Component ATA:34
PN:19004-10-01	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:M037221	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-13, AMM 34-21-13PROC. REF: AMM 34-21-13, AMM 34-21-13								
34CA3431001	LEFT VHF NAVIGATION BLADE ANTENNA (VOR/LOC/GS)							Component ATA:34
PN:CI 120-1-L	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:503705	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34CA3431002	RIGHT VHF NAVIGATION BLADE ANTENNA (VOR/LOC/GS)							Component ATA:34
PN:CI 120-1-L	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:503706	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34CA3431004	POWER COMBINER							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34CA3431005	2 IN, 1 OUT POWER COMBINER							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34CA3431111	MARKER BEACON							Component ATA:34
PN:MB10-715-3	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:82	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-11, AMM 34-31-11PROC. REF: AMM 34-31-11, AMM 34-31-11								
34CA3431121	DUAL VOR, DUAL G/S DIPLEXER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-12, AMM 34-31-12PROC. REF: AMM 34-31-12, AMM 34-31-12								
34CA3431131	VOR-LOC-GS ANTENNA SYSTEM							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-13, AMM 34-31-13PROC. REF: AMM 34-31-13, AMM 34-31-13								
34CA3431141	GA37, GPS WAAS / XM ANTENNA							Component ATA:34
PN:013-00245-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:13573	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-14, AMM 34-31-14PROC. REF: AMM 34-31-14, AMM 34-31-14								
34CA3431142	GPS WAAS-GA36 ANTENNA							Component ATA:34
PN:013-00244-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:13462	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-14, AMM 34-31-14PROC. REF: AMM 34-31-14, AMM 34-31-14								
34CA3431151	DUAL MARKER BEACON COUPLER							Component ATA:34
PN:DMB20-20	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:5055	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-15, AMM 34-31-15PROC. REF: AMM 34-31-15, AMM 34-31-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34CA3441001	GRA 5500 RADAR RT ALTIMETER							Component ATA:34
PN:011-02537-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:2F8005446	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-41-11, AMM 34-41-11PROC. REF: AMM 34-41-11, AMM 34-41-11								
34CA3441121	NO. 1 RADIO ALTIMETER ANTENNA							Component ATA:34
PN:S67-2002	MOS/MSC	17-Sep-25	O/C	TSN 0				
SN:543-120178	HRS	1707.6		TSN 0				
	AFL	1554		TSN 0				
PROC. REF: AMM 34-41-12, AMM 34-41-12PROC. REF: AMM 34-41-12, AMM 34-41-12								
34CA3441122	NO. 2 RADIO ALTIMETER ANTENNA							Component ATA:34
PN:S67-2002	MOS/MSC	17-Sep-25	O/C	TSN 0				
SN:543-119223	HRS	1707.6		TSN 0				
	AFL	1554		TSN 0				
PROC. REF: AMM 34-41-12, AMM 34-41-12PROC. REF: AMM 34-41-12, AMM 34-41-12								
34CA3442101	XM WEATHER-GDL69A DATALINK							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-10, AMM 34-42-10PROC. REF: AMM 34-42-10, AMM 34-42-10								
34CA3442102	WX RDR, GWX70 ANTENNA ARRAY							Component ATA:34
PN:117-00254-01	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-10, AMM 34-42-10PROC. REF: AMM 34-42-10, AMM 34-42-10								
34CA3442103	WX RDR, GWX70 ANTENNA BASE							Component ATA:34
PN:011-01768-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1DP007225	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-10, AMM 34-42-10PROC. REF: AMM 34-42-10, AMM 34-42-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34CA3451001	DME TRANSCEIVER							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-10, AMM 34-51-10PROC. REF: AMM 34-51-10, AMM 34-51-10								
34CA3452111	NO. 1 TRANSPONDER							Component ATA:34
PN:006-B0172-14	MOS/MSC	12-Apr-23	O/C					
SN:84813453	HRS	1131.1						
	AFL	1064						
PROC. REF: CMM 190-01597-00PROC. REF: CMM 190-01597-00								
34CA3452112	NO. 2 TRANSPONDER							Component ATA:34
PN:011-00779-21	MOS/MSC	29-Mar-17	O/C	TSN 0				
SN:84813123	HRS	0		TSN 0				
	AFL	0		TSN 0				
								WO#: FAMQ0152
PROC. REF: CMM 190-01597-00PROC. REF: CMM 190-01597-00								
34CA3452121	TRANSPONDER L-BAND ANTENNA							Component ATA:34
PN:L10-611-14	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:7908	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-12, AMM 34-52-12PROC. REF: AMM 34-52-12, AMM 34-52-12								
34CA3452131	NO. 1 COAXIAL SWITCH							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-13, AMM 34-52-13PROC. REF: AMM 34-52-13, AMM 34-52-13								
34CA3452132	NO. 2 COAXIAL SWITCH							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-13, AMM 34-52-13PROC. REF: AMM 34-52-13, AMM 34-52-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34CA3453101	AUTOMATIC DIRECTION FINDER (ADF) RECEIVER							Component ATA:34
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-10, AMM 34-53-10PROC. REF: AMM 34-53-10, AMM 34-53-10								
34CA3453111	UPPER GA58 ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:124013207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-11, AMM 34-53-11PROC. REF: AMM 34-53-11, AMM 34-53-11								
34CA3453112	LOWER GA58 ANTENNA							Component ATA:34
PN:011-01346-00	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:124013252	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-11, AMM 34-53-11PROC. REF: AMM 34-53-11, AMM 34-53-11								
34HA0500101 ^S	DO A VISUAL INSPECTION OF THE NAVIGATION SYSTEM ANTENNAS.							Service ATA:34
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:1 WO#: FAMQ0152
34HA0500102	DO A VISUAL INSPECTION OF THE NAVIGATION SYSTEM EQUIPMENT AND RACKS.							Service ATA:34
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34HA0500103	DO THE VISUAL INSPECTION OF THE ANTENNA, ANTENNA MOUNTS AND CABLES.							Service ATA:34
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)	Adj 38.1	2400	2460	684.9 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
34HA3400101	DO THE FUNCTIONAL TEST OF THE LEFT INTEGRATED AVIONICS COMPUTER							Service ATA:34
PN:011-01105-40	MOS/MSC	02-Jun-23	N/A					
SN:2DC003185	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 34-00-02PROC. REF: AMM 34-00-02								
34HA3400101 ^S	DO THE FUNCTIONAL TEST OF THE RIGHT INTEGRATED AVIONICS COMPUTER							Service ATA:34
PN:011-01105-40	MOS	02-Jun-23						
SN:2DC003193	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 34-00-02PROC. REF: AMM 34-00-02								
34HA3400104	TRAFFIC COLLISION AVOIDANCE SYSTEM - FUNCTIONAL TEST							Service ATA:34
PN:011-02571-00	MOS	02-Jun-23						AIRWORTHINESS
SN:28P007235	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 34-00-02PROC. REF: AMM 34-00-02								
34HA3410102	DO THE FUNCTIONAL TEST OF THE PRIMARY AIR DATA SYSTEM. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:2015T-1B	MOS	07-Mar-25	24		07-Mar-27		452 d	AIRWORTHINESS
SN:0144	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 34-00-02, AMM 34-00-02PROC. REF: AMM 34-00-02, AMM 34-00-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34HA3410102	DO THE FUNCTIONAL TEST OF THE STANDBY AIR DATA SYSTEM. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:2015T-1B	MOS	07-Mar-25	24		07-Mar-27		452 d	AIRWORTHINESS
SN:0117	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 34-00-02, AMM 34-00-02PROC. REF: AMM 34-00-02, AMM 34-00-02								
34HA3410103	DO THE FUNCTIONAL TEST OF THE NO. 1 TRANSPONDER. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:006-B0172-14	MOS	07-Mar-25	24		07-Mar-27 (M)		452 d	
SN:84813453	HRS	1660.1						
	AFL	1508						
PROC. REF: AMM 34-00-02PROC. REF: AMM 34-00-02								
34HA3410103	DO THE FUNCTIONAL TEST OF THE NO. 2 TRANSPONDER. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:011-00779-21	MOS	07-Mar-25	24		07-Mar-27 (M)		452 d	
SN:84813123	HRS	1660.1						
	AFL	1508						
PROC. REF: AMM 34-00-02PROC. REF: AMM 34-00-02								
34HA3410107	STANDBY AIR DATA & AIRSPEED SYSTEM - FUNCTIONAL TEST							Service ATA:34
PN:100564-100-000	MOS	12-Apr-23						
SN:1001063	HRS	1131.1	10000 (+60/-60)		11131.1	11191.1	9416 (+60)	
	AFL	1064						
PROC. REF: AMM 34-00-02, AMM 34-00-02PROC. REF: AMM 34-00-02, AMM 34-00-02								
34HA3411102	DO THE ALIGNMENT INSPECTION OF THE AIR DATA PROBES FOR RVSM.							Service ATA:34
	MOS	07-Mar-25	24 (+30d/-30d)	Adj 3d	07-Mar-27 (M)	06-Apr-27	452 d (+30)	RVSM
	HRS	1660.1						
	AFL	1508						
PROC. REF: AMM 34-11-00PROC. REF: AMM 34-11-00								
ATA 35 - OXYGEN								
35CA3500000	OVER-PRESSURE INDICATOR							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-04, AMM 35-00-04PROC. REF: AMM 35-00-04, AMM 35-00-04								
35CA3500002	PILOT SMOKE GOGGLE							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-14, AMM 35-11-14PROC. REF: AMM 35-11-14, AMM 35-11-14								
35CA3500004	CO-PILOT SMOKE GOGGLE							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-14, AMM 35-11-14PROC. REF: AMM 35-11-14, AMM 35-11-14								
35CA3500011	OXYGEN BOTTLE (P/N HJ1-13500-150-XXX) - REPLACE							Component ATA:35
PN:HJ1-13500-150-011	MOS	09-Apr-21	180		01-Mar-29		1177 d	LIFE LIMIT
SN:C16010688	HRS	311.8						
	AFL	291						
Manufacture Date:: 01-Mar-14								
PROC. REF: AMM 35-00-01, AMM 35-00-01, CMM 35-28-95PROC. REF: AMM 35-00-01, AMM 35-00-01, CMM 35-28-95								
35CA3500014	OXYGEN BOTTLE (P/N HJ1-13500-150-XXX), INSPECT ANDHYDROSTATICALLY TEST							Service ATA:35
PN:HJ1-13500-150-011	MOS	01-Dec-20	60 (+30d/-30d)		01-Dec-25 (M)	31-Dec-25	TOL (+21 d)	
SN:C16010688	HRS							
	AFL							
PROC. REF: AMM 35-00-01, AMM 35-00-01, CMM 35-28-95PROC. REF: AMM 35-00-01, AMM 35-00-01, CMM 35-28-95								
35CA3500015	OXYGEN REGULATOR (P/N HJ1-13500-150-XXX, 805982-XX), OVERHAUL							Service ATA:35
PN:HJ1-13500-150-011	MOS	09-Apr-21	60 (+30d/-30d)		09-Apr-26	09-May-26	120 d (+30)	
SN:C16010688	HRS	311.8						
	AFL	291						
PROC. REF: AMM 35-00-01, AMM 35-00-01, CMM 35-28-95PROC. REF: AMM 35-00-01, AMM 35-00-01, CMM 35-28-95								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35CA3500023	OXYGEN BOTTLE TRANSDUCER							Component ATA:35
PN:HJ1-13500-151-005	MOS/MSC	09-Apr-21	O/C	TSO 0				
SN:20131321	HRS	311.8		TSO 0				
	AFL	291		TSO 0				
PROC. REF: AMM 35-00-02, AMM 35-00-02PROC. REF: AMM 35-00-02, AMM 35-00-02								
35CA3500051	CREW AND PASSENGER OXYGEN CABLE							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05, AMM 35-00-05PROC. REF: AMM 35-00-05, AMM 35-00-05								
35CA3511001	PILOT MASK STORAGE BOX							Component ATA:35
PN:HJ1-13510-219-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SE84920	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-13, AMM 35-11-13PROC. REF: AMM 35-11-13, AMM 35-11-13								
35CA3511002	CO-PILOT MASK STORAGE BOX							Component ATA:35
PN:HJ1-13510-219-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:SE84931	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-13, AMM 35-11-13PROC. REF: AMM 35-11-13, AMM 35-11-13								
35CA3511101	CABIN ALTITUDE SWITCH							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-10, AMM 35-11-10PROC. REF: AMM 35-11-10, AMM 35-11-10								
35CA3511111	CABIN OXYGEN PRESSURE SWITCH							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-11, AMM 35-11-11PROC. REF: AMM 35-11-11, AMM 35-11-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35CA3511112	COCKPIT OXYGEN PRESSURE SWITCH							Component ATA:35
PN:HJ1-13500-203-009	MOS/MSC	02-Jun-23	O/C					
SN:0177	HRS	1161.9		TSN 0				
	AFL	1084		TSN 0				
PROC. REF: AMM 35-11-11, AMM 35-11-11PROC. REF: AMM 35-11-11, AMM 35-11-11								
35CA3511121	CABIN CONTROL VALVE							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-12, AMM 35-11-12PROC. REF: AMM 35-11-12, AMM 35-11-12								
35CA3511130	CO-PILOT CREW OXYGEN MASK - REPLACE OR OVERHAUL MASK							Component ATA:35
PN:HJ1-13510-203-001	MOS	28-Dec-21	72 (+30d/-30d)	TSO 0	28-Dec-27	27-Jan-28	748 d (+30)	OVERHAUL
SN:B103480	HRS	449.2		TSO 0				
	AFL	470		TSO 0				
PROC. REF: AMM 35-11-13, AMM 35-11-13PROC. REF: AMM 35-11-13, AMM 35-11-13								
35CA3511130	PILOT CREW OXYGEN MASK - REPLACE OR OVERHAUL MASK							Component ATA:35
PN:HJ1-13510-203-001	MOS	28-Dec-21	72 (+30d/-30d)	TSO 0	28-Dec-27	27-Jan-28	748 d (+30)	OVERHAUL
SN:B103476	HRS	449.2		TSO 0				
	AFL	470		TSO 0				
PROC. REF: AMM 35-11-13, AMM 35-11-13PROC. REF: AMM 35-11-13, AMM 35-11-13								
35CA3521101	POSITION 1A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-103	MOS/MSC	09-Apr-21	O/C	TSN 12				
SN:D20040796	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521102	POSITION 1B PASSENGER MASK (OPTIONAL EQUIPMENT) DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	N/A	TSN 0				
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35CA3521103	POSITION 2A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-103	MOS/MSC	09-Apr-21	O/C	TSN 12				
SN:D20040808	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521104	POSITION 2B PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-103	MOS/MSC	09-Apr-21	O/C	TSN 12				
SN:D20040897	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521105	POSITION 3A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-103	MOS/MSC	09-Apr-21	O/C	TSN 12				
SN:D20040805	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521106	POSITION 3B PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-103	MOS/MSC	09-Apr-21	O/C	TSN 12				
SN:D20040809	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521107	POSITION 4A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-103	MOS/MSC	09-Apr-21	O/C	TSN 12				
SN:D20040798	HRS	311.8		TSN 0				
	AFL	291		TSN 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521108	POSITION 4B PASSENGER MASK (OPTIONAL EQUIPMENT) DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - SERVICE LIFE							Component ATA:35
PN:PN	MOS/MSC	23-Jun-17	N/A	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35CA3521121	POSITION 1A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-103	MOS	07-Mar-25	24 (+30d/-30d)		07-Mar-27	06-Apr-27	452 d (+30)	
SN:D20040796	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521122	POSITION 1B PASSENGER MASK (OPTIONAL EQUIPMENT) DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:PN	MOS/MSC	23-Jun-17	N/A					
SN:UNKNOWN	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521123	POSITION 2A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-103	MOS	07-Mar-25	24 (+30d/-30d)		07-Mar-27	06-Apr-27	452 d (+30)	
SN:D20040808	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521124	POSITION 2B PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-103	MOS	07-Mar-25	24 (+30d/-30d)		07-Mar-27	06-Apr-27	452 d (+30)	
SN:D20040897	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521125	POSITION 3A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-103	MOS	07-Mar-25	24 (+30d/-30d)		07-Mar-27	06-Apr-27	452 d (+30)	
SN:D20040805	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521126	POSITION 3B PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-103	MOS	07-Mar-25	24 (+30d/-30d)		07-Mar-27	06-Apr-27	452 d (+30)	
SN:D20040809	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35CA3521127	POSITION 4A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-103	MOS	07-Mar-25	24 (+30d/-30d)		07-Mar-27	06-Apr-27	452 d (+30)	
SN:D20040798	HRS	1655.6						
	AFL	1504						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35CA3521128	POSITION 4B PASSENGER MASK (OPTIONAL EQUIPMENT) DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION							Service ATA:35
PN:PN	MOS/MSC	23-Jun-17	N/A					NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35HA0500101	VISUAL INSPECTION OF THE PASSENGER OXYGEN SYSTEM (BROKEN FILLER CAP)							Service ATA:35
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
35HA0500102	DO A VISUAL INSPECTION OF THE CREW SMOKE GOGGLES.							Service ATA:35
	MOS	02-Jun-23						
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
35HA0500105	DO A VISUAL INSPECTION OF THE CABIN OXYGEN SYSTEM.							Service ATA:35
	MOS	02-Jun-23						
	HRS	1161.9	2400 (+60/-60)	Adj 38.1	3600	3660	1884.9 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35HA0500106	DO A VISUAL INSPECTION OF THE OXYGEN SYSTEM IN THE NOSE TO INCLUDE THE BOTTLE, TUBES, REGULATORS AND GAUGES NOTE: ACCOMPLISHMENT OF THIS AMM TASK SATISFIES THE REQUIREMENTS OF BOTH INSPECTION TASK 35HA0500106 IN THIS SECTION AND TASK 35HA0500101 IN SECTION 05-60.							Service ATA:35
	MOS	02-Jun-23	60		02-Jun-28		905 d	
	HRS	1161.9						
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
35HA3500101	FUNCTIONAL CHECK OF THE PASSENGER OXYGEN SYSTEM (GENERAL)							Service ATA:35
	MOS	02-Jun-23	24		07-Mar-27 (M)		452 d	AIRWORTHINESS
	HRS	1161.9						
	AFL	1084						
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01								WO#: FAMQ0152
35HA3500102	FUNCTIONAL CHECK OF THE PASSENGER OXYGEN SYSTEM (OXYGEN SERVICE PANEL LEAK, WITH CAP REMOVED AT SERVICE PANEL)							Service ATA:35
	MOS	02-Jun-23	24		07-Mar-27 (M)		452 d	AIRWORTHINESS
	HRS	1161.9						
	AFL	1084						
PROC. REF: AMM 35-00-02PROC. REF: AMM 35-00-02								WO#: FAMQ0152
35HA3500103	PASSENGER OXYGEN SYSTEM (LOW PRESSURE ERRONEOUS INDICATION) - FUNCTIONAL TEST							Service ATA:35
	MOS	02-Jun-23	60		07-Mar-27 (M)		452 d	AIRWORTHINESS
	HRS	1161.9						
	AFL	1084						
PROC. REF: AMM 35-00-01, AMM 35-00-03PROC. REF: AMM 35-00-01, AMM 35-00-03								WO#: FAMQ0152
35HA3521150	FLEXIBLE OXYGEN HOSES (P/N HJ1-13520-306-003, HJ1-13520-309-005) - REPLACE							Component ATA:35
PN:HJ1-13520-309-005	MOS	12-Jan-17	120 (+30d/-30d)	TSN 0	12-Jan-27	11-Feb-27	398 d (+30)	
SN:55117-04	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35HA3521151	FLEXIBLE OXYGEN HOSES (P/N HJ1-13520-306-003, HJ1-13520-309-005) - REPLACE							Component ATA:35
PN:HJ1-13520-306-003	MOS	12-Jan-17	120 (+30d/-30d)	TSN 0	12-Jan-27	11-Feb-27	398 d (+30)	
SN:55115-04	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01								
35HA3521155	FLEXIBLE OXYGEN HOSES (P/N HJ1-13520-306-003, HJ1-13520-309-005) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-309-005	MOS	09-Apr-22	60 (+30d/-30d)		09-Apr-27	09-May-27	485 d (+30)	
SN:55117-04	HRS	569.3						
	AFL	567						
PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01								
35HA3521156	FLEXIBLE OXYGEN HOSES (P/N HJ1-13520-306-003, HJ1-13520-309-005) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-306-003	MOS	09-Apr-22	60 (+30d/-30d)		09-Apr-27	09-May-27	485 d (+30)	
SN:55115-04	HRS	569.3						
	AFL	567						
PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01PROC. REF: AMM 35-00-06, AMM 35-00-06, CMM 35-01-01								
35HA3521201	POSITION 1 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-302-001	MOS	23-Jun-17	240 (+30d/-30d)	TSN 0	01-Jan-36	31-Jan-36	3674 d (+30)	LIFE LIMIT
SN:D16010479	HRS							
	AFL							
Manufacture Date:: 01-Jan-16								
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35HA3521202	POSITION 2 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-001	MOS	23-Jun-17	240 (+30d/-30d)	TSN 0	01-Oct-35	31-Oct-35	3582 d (+30)	LIFE LIMIT
SN:D15100439	HRS							
	AFL							
Manufacture Date:: 01-Oct-15								
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35HA3521203	POSITION 3 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-301-001	MOS	23-Jun-17	240 (+30d/-30d)	TSN 0	01-Oct-35	31-Oct-35	3582 d (+30)	LIFE LIMIT
SN:D15100756	HRS							
	AFL							
Manufacture Date:: 01-Oct-15								
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35HA3521204	POSITION 4 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - SERVICE LIFE							Component ATA:35
PN:HJ1-13520-302-001	MOS	23-Jun-17	240 (+30d/-30d)	TSN 0	01-Jan-36	31-Jan-36	3674 d (+30)	LIFE LIMIT
SN:D16010478	HRS							
	AFL							
Manufacture Date:: 01-Jan-16								
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35HA3521221	POSITION 1 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-302-001	MOS	12-Jun-25	48 (+30d/-30d)	Adj -2d	10-Jun-29	10-Jul-29	1278 d (+30)	
SN:D16010479	HRS	1671.9						
	AFL	1524						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35HA3521222	POSITION 2 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-001	MOS	12-Jun-25	48 (+30d/-30d)	Adj -2d	10-Jun-29	10-Jul-29	1278 d (+30)	
SN:D15100439	HRS	1671.9						
	AFL	1524						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								
35HA3521223	POSITION 3 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-301-001	MOS	12-Jun-25	48 (+30d/-30d)	Adj -2d	10-Jun-29	10-Jul-29	1278 d (+30)	
SN:D15100756	HRS	1671.9						
	AFL	1524						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35HA3521224	POSITION 4 PASSENGER MASK DEPLOYMENT MANIFOLD PLATE (P/N HA5-000000 AND HA6-000000) - VISUAL INSPECTION							Service ATA:35
PN:HJ1-13520-302-001	MOS	12-Jun-25	48 (+30d/-30d)	Adj -2d	10-Jun-29	10-Jul-29	1278 d (+30)	
SN:D16010478	HRS	1671.9						
	AFL	1524						
PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22PROC. REF: AMM 35-21-10, AMM 35-21-10, CMM 35-20-22								

ATA 36 - PNEUMATIC

36CA3611003	NO. 1 LEFT (BALD) WING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

36CA3611004	NO. 1 RIGHT (BALD) WING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

36CA3611005	NO. 2 LEFT (BALD) WING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

36CA3611006	NO. 2 RIGHT (BALD) WING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

36CA3611007	NO. 1 LEFT BALD WING TO BODY FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3611008	NO. 1 RIGHT BALD WING TO BODY FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36CA3611009	NO. 2 LEFT BALD WING TO BODY FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36CA3611010	NO. 2 RIGHT BALD WING TO BODY FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36CA3611011	NO. 3 BALD WING TO BODY FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36CA3611012	NO. 4 BALD WING TO BODY FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36CA3611013	SERVICE AIR PRESSURE REGULATING VALVE							Component ATA:36
PN:HJ1-13603-621-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:48	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
36CA3611014	LEFT (CAIV) COWL ANTI-ICE VALVE						Component	ATA:36
PN:HJ1-13605-701-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:139	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-10, AMM 30-21-10PROC. REF: AMM 30-21-10, AMM 30-21-10								
36CA3611015	RIGHT (CAIV) COWL ANTI-ICE VALVE						Component	ATA:36
PN:HJ1-13605-701-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:140	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-10, AMM 30-21-10PROC. REF: AMM 30-21-10, AMM 30-21-10								
36CA3611101	NO. 1 TEMPERATURE MODULATING VALVE						Component	ATA:36
PN:HJ1-13601-401-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:282	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-10, AMM 36-11-10PROC. REF: AMM 36-11-10, AMM 36-11-10								
36CA3611102	NO. 2 TEMPERATURE MODULATING VALVE						Component	ATA:36
PN:HJ1-13601-401-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:283	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-10, AMM 36-11-10PROC. REF: AMM 36-11-10, AMM 36-11-10								
36CA3611111	GROUND COOLING FAN						Component	ATA:36
PN:HJ1-13601-501-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:220	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-11, AMM 36-11-11PROC. REF: AMM 36-11-11, AMM 36-11-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3611121	HEAT EXCHANGER ASSEMBLY							Component ATA:36
PN:HJ1-13602-510-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:170	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-12, AMM 36-11-12PROC. REF: AMM 36-11-12, AMM 36-11-12								
36CA3611141	NO. 1 BI-LEVEL FLOW CONTROL SHUTOFF VALVE							Component ATA:36
PN:HJ1-13603-611-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:133	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-14, AMM 36-11-14PROC. REF: AMM 36-11-14, AMM 36-11-14								
36CA3611142	NO. 2 BI-LEVEL FLOW CONTROL SHUTOFF VALVE							Component ATA:36
PN:HJ1-13603-611-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:134	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-14, AMM 36-11-14PROC. REF: AMM 36-11-14, AMM 36-11-14								
36CA3611151	NO. 1 WING TO BODY BLEED AIR CHECK VALVE							Component ATA:36
PN:HJ1-13603-654-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:174	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-15, AMM 36-11-15PROC. REF: AMM 36-11-15, AMM 36-11-15								
36CA3611152	NO. 2 WING TO BODY BLEED AIR CHECK VALVE							Component ATA:36
PN:HJ1-13603-654-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:175	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-15, AMM 36-11-15PROC. REF: AMM 36-11-15, AMM 36-11-15								
36CA3611153	CABIN BLEED AIR CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-15, AMM 36-11-15PROC. REF: AMM 36-11-15, AMM 36-11-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3611161	NO. 1 CABIN CHECK VALVE							Component ATA:36
PN:HJ1-13604-301-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:241	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-16, AMM 36-11-16PROC. REF: AMM 36-11-16, AMM 36-11-16								
36CA3611162	NO. 2 CABIN CHECK VALVE							Component ATA:36
PN:HJ1-13604-301-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:242	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-16, AMM 36-11-16PROC. REF: AMM 36-11-16, AMM 36-11-16								
36CA3611171	PLENUM							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-17, AMM 36-11-17PROC. REF: AMM 36-11-17, AMM 36-11-17								
36CA3611191	NO. 1 FAN AIR VALVE CONTROLLER							Component ATA:36
PN:HJ1-13604-601-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:237	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-19, AMM 36-11-19PROC. REF: AMM 36-11-19, AMM 36-11-19								
36CA3611192	NO. 2 FAN AIR VALVE CONTROLLER							Component ATA:36
PN:HJ1-13604-601-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:238	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-19, AMM 36-11-19PROC. REF: AMM 36-11-19, AMM 36-11-19								
36CA3611211	LEFT HIGH PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:HJ1-13601-701-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:0039A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-21, AMM 36-11-21PROC. REF: AMM 36-11-21, AMM 36-11-21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3611212	RIGHT HIGH PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:HJ1-13601-701-003	MOS/MSC	08-Aug-17	O/C					
SN:0128A	HRS	13.7						
	AFL	12						
PROC. REF: AMM 36-11-21, AMM 36-11-21PROC. REF: AMM 36-11-21, AMM 36-11-21								
36CA3611221	RAM AIR CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-22, AMM 36-11-22PROC. REF: AMM 36-11-22, AMM 36-11-22								
36CA3611231	BAS MUFFLER DUCT							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-23, AMM 36-11-23PROC. REF: AMM 36-11-23, AMM 36-11-23								
36CA3611261	LEFT NACELLE PRESSURE-REGULATING SHUT-OFF (NPRSOV) VALVE							Component ATA:36
PN:HJ1-13607-701-007	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:167	HRS	0	2400	TSN 0	2400		684.9	
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-26, AMM 36-11-26PROC. REF: AMM 36-11-26, AMM 36-11-26								
36CA3611262	RIGHT NACELLE PRESSURE-REGULATING SHUT-OFF (NPRSOV) VALVE							Component ATA:36
PN:HJ1-13607-701-007	MOS	23-Jun-17		TSN 0				AIRWORTHINESS
SN:172	HRS	0	2400	TSN 0	2400		684.9	
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-26, AMM 36-11-26PROC. REF: AMM 36-11-26, AMM 36-11-26								
36CA3611271	LEFT FAN AIR VALVE							Component ATA:36
PN:HJ1-13604-701-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:142	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-27, AMM 36-11-27PROC. REF: AMM 36-11-27, AMM 36-11-27								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3611272	RIGHT FAN AIR VALVE							Component ATA:36
PN:HJ1-13604-701-009	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:143	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-27, AMM 36-11-27PROC. REF: AMM 36-11-27, AMM 36-11-27								
36CA3611281	LEFT PRE-COOLER							Component ATA:36
PN:HJ1-13602-701-005	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:T0025	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-28, AMM 36-11-28PROC. REF: AMM 36-11-28, AMM 36-11-28								
36CA3611282	RIGHT PRE-COOLER							Component ATA:36
PN:HJ1-13602-701-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:T0031	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-28, AMM 36-11-28PROC. REF: AMM 36-11-28, AMM 36-11-28								
36CA3611291	NO. 1 BAS LEAK DETECTION CONTROL UNIT							Component ATA:36
PN:HJ1-13600-001-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:748	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-29, AMM 36-11-29PROC. REF: AMM 36-11-29, AMM 36-11-29								
36CA3611292	NO. 2 BAS LEAK DETECTION CONTROL UNIT							Component ATA:36
PN:HJ1-13600-001-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:780	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-29, AMM 36-11-29PROC. REF: AMM 36-11-29, AMM 36-11-29								
36CA3611293	NO. 3 BAS LEAK DETECTION CONTROL UNIT							Component ATA:36
PN:HJ1-13600-001-001	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:781	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-29, AMM 36-11-29PROC. REF: AMM 36-11-29, AMM 36-11-29								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3611294	NO. 4 BAS LEAK DETECTION CONTROL UNIT							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-29, AMM 36-11-29PROC. REF: AMM 36-11-29, AMM 36-11-29								
36CA3611295	NO. 5 BAS LEAK DETECTION CONTROL UNIT							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-29, AMM 36-11-29PROC. REF: AMM 36-11-29, AMM 36-11-29								
36CA3621101	NO. 1 BALD - TAILCONE SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-10, AMM 36-21-10PROC. REF: AMM 36-21-10, AMM 36-21-10								
36CA3621102	NO. 2 BALD - TAILCONE SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-10, AMM 36-21-10PROC. REF: AMM 36-21-10, AMM 36-21-10								
36CA3621111	NO. 1 BALD - AFT FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-11, AMM 36-21-11PROC. REF: AMM 36-21-11, AMM 36-21-11								
36CA3621112	NO. 2 BALD - AFT FAIRING SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-11, AMM 36-21-11PROC. REF: AMM 36-21-11, AMM 36-21-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3621121	NO. 1 FAN AIR VALVE TEMPERATURE SENSOR							Component ATA:36
PN:HJ1-13602-708-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:452	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-12, AMM 36-21-12PROC. REF: AMM 36-21-12, AMM 36-21-12								
36CA3621122	NO. 2 FAN AIR VALVE TEMPERATURE SENSOR							Component ATA:36
PN:HJ1-13602-708-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:445	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-12, AMM 36-21-12PROC. REF: AMM 36-21-12, AMM 36-21-12								
36CA3621123	NO. 3 FAN AIR VALVE TEMPERATURE SENSOR							Component ATA:36
PN:HJ1-13602-708-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:499	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-12, AMM 36-21-12PROC. REF: AMM 36-21-12, AMM 36-21-12								
36CA3621124	NO. 4 FAN AIR VALVE TEMPERATURE SENSOR							Component ATA:36
PN:HJ1-13602-708-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:500	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-12, AMM 36-21-12PROC. REF: AMM 36-21-12, AMM 36-21-12								
36CA3621125	NO. 5 FAN AIR VALVE TEMPERATURE SENSOR							Component ATA:36
PN:HJ1-13602-708-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:501	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-12, AMM 36-21-12PROC. REF: AMM 36-21-12, AMM 36-21-12								
36CA3621126	NO. 6 FAN AIR VALVE TEMPERATURE SENSOR							Component ATA:36
PN:HJ1-13602-708-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:502	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-12, AMM 36-21-12PROC. REF: AMM 36-21-12, AMM 36-21-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3621131	NO. 1 (BALD) PYLON SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-13, AMM 36-21-13PROC. REF: AMM 36-21-13, AMM 36-21-13								
36CA3621132	NO. 2 (BALD) PYLON SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-13, AMM 36-21-13PROC. REF: AMM 36-21-13, AMM 36-21-13								
36CA3621133	NO. 3 (BALD) PYLON SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-13, AMM 36-21-13PROC. REF: AMM 36-21-13, AMM 36-21-13								
36CA3621134	NO. 4 (BALD) PYLON SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-13, AMM 36-21-13PROC. REF: AMM 36-21-13, AMM 36-21-13								
36CA3621141	NO. 1 TEMPERATURE, TMV SENSOR SWITCH							Component ATA:36
PN:HJ1-13605-401-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:319	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-14, AMM 36-21-14PROC. REF: AMM 36-21-14, AMM 36-21-14								
36CA3621142	NO. 2 TEMPERATURE, TMV SENSOR SWITCH							Component ATA:36
PN:HJ1-13605-401-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:320	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-14, AMM 36-21-14PROC. REF: AMM 36-21-14, AMM 36-21-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36CA3621151	NO. 1 MANIFOLD COWL ANTI-ICE PRESSURE SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-15, AMM 36-21-15PROC. REF: AMM 36-21-15, AMM 36-21-15								
36CA3621152	NO. 2 MANIFOLD COWL ANTI-ICE PRESSURE SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-15, AMM 36-21-15PROC. REF: AMM 36-21-15, AMM 36-21-15								
36CA3621153	NO. 3 MANIFOLD COWL ANTI-ICE PRESSURE SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-15, AMM 36-21-15PROC. REF: AMM 36-21-15, AMM 36-21-15								
36CA3621154	NO. 4 MANIFOLD COWL ANTI-ICE PRESSURE SENSOR							Component ATA:36
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-15, AMM 36-21-15PROC. REF: AMM 36-21-15, AMM 36-21-15								
36CA3621161	NO. 1 OVER-TEMPERATURE, TMV SENSOR							Component ATA:36
PN:HJ1-13605-402-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:255	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-16, AMM 36-21-16PROC. REF: AMM 36-21-16, AMM 36-21-16								
36CA3621162	NO. 2 OVER-TEMPERATURE, TMV SENSOR							Component ATA:36
PN:HJ1-13605-402-003	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:256	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-21-16, AMM 36-21-16PROC. REF: AMM 36-21-16, AMM 36-21-16								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36HA0500101	^S	DO A VISUAL INSPECTION OF THE PNEUMATIC AND ENGINE BLEED AIR SYSTEM LINES, VALVES AND DUCTS.						Service ATA:36
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
36HA0500102	^S	DO A VISUAL INSPECTION OF THE GROUND COOLING FAN AND DUCT.						Service ATA:36
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
36HA0500103	^S	DO A VISUAL INSPECTION OF THE BLEED AIR LEAK DETECTION SYSTEM.						Service ATA:36
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
36HA0500104		DO THE INSPECTION OF THE CABIN CHECK VALVES.						Service ATA:36
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)	Adj 38.1	2400	2460	684.9 (+60)	
	AFL	1084						
PROC. REF: AMM 36-00-01PROC. REF: AMM 36-00-01								WO#: FAMQ0152
36HA3600101		OPERATIONAL TEST - MANIFOLD TEMPERATURE SENSOR						Service ATA:36
	MOS/MSC	02-Jun-23	N/A					AIRWORTHINESS
	HRS	1161.9						
	AFL	1084						
PROC. REF: AMM 36-00-01PROC. REF: AMM 36-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36HA3600102	DO THE OPERATIONAL TEST OF THE PNEUMATIC SYSTEM NOTE: ACCOMPLISHMENT OF THIS AMM TASK SATISFIES THE REQUIREMENTS OF BOTH INSPECTION TASK 36HA3600102 IN THIS SECTION AND TASK 36HA3600101 IN SECTION 05-60.							Service ATA:36
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
PROC. REF: AMM 36-00-01PROC. REF: AMM 36-00-01								WO#: FAMQ0152
36HA3600103	NO. 1 ENGINE - HEAT CHECK OF THE FIRE DETECTOR ELEMENT AT ENGINE REMOVAL. MEGGITT CMM 26-10-60							Service ATA:36
	MOS	23-Jun-17						AIRWORTHINESS
	HRS	0	5000		5000		3284.9	
	AFL	0						
PROC. REF: AMM 26-11-10, AMM 26-11-10, CMM 26-10-60PROC. REF: AMM 26-11-10, AMM 26-11-10, CMM 26-10-60								
36HA3600103	NO. 2 ENGINE - HEAT CHECK OF THE FIRE DETECTOR ELEMENT AT ENGINE REMOVAL. MEGGITT CMM 26-10-60							Service ATA:36
	MOS	23-Jun-17						AIRWORTHINESS
	HRS	0	5000		5000		3284.9	
	AFL	0						
PROC. REF: AMM 26-11-10, AMM 26-11-10, CMM 26-10-60PROC. REF: AMM 26-11-10, AMM 26-11-10, CMM 26-10-60								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
38CA3820001	TOILET							Component ATA:38
PN:HJ1-13820-301-013	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:U6034	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-31-10, AMM 38-31-10PROC. REF: AMM 38-31-10, AMM 38-31-10								
38HA0500106 ^S	DO A VISUAL INSPECTION OF THE TOILET'S EXTERNAL/INTERNAL SERVICING PLUMBING, UNDER FLOOR BOARDS FOR LEAKS IN THE LAVATORY AREA AND FILL ADAPTOR AND CAP.							Service ATA:38
	MOS	23-Jun-17						
	HRS	0	1200 (+60/-60)					
	AFL	0						
								PKG:6
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
38HA3800101 ^S	DO THE OPERATIONAL TEST OF THE WATER SYSTEM.							Service ATA:38
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 38-00-01PROC. REF: AMM 38-00-01								
ATA 51 - STD PRACTICES AND STRUCT-GENRL								
51HA5180101	ELECTRICAL POWER BONDING AND GROUNDING PROCEDURE - FUNCTIONAL CHECK							Service ATA:51
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 51-81-10PROC. REF: AMM 51-81-10								
ATA 52 - DOORS								
52CA5211111	UPPER LATCH V DOOR PRESSURE SEAL							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52CA5211113	UPPER LATCH DRAIN VALVE V SEAL							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
52CA5211115	EMERGENCY EXIT DOOR SEAL							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-21-10, AMM 52-21-10PROC. REF: AMM 52-21-10, AMM 52-21-10								
52CA5211117	MAIN ENTRY DOOR OUTBOARD PRESSURE SEAL - REPLACE							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-11-12, AMM 52-11-12PROC. REF: AMM 52-11-12, AMM 52-11-12								
52CA5211119	CABIN ENTRY DOOR, INBD SEAL							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-11-13, AMM 52-11-13PROC. REF: AMM 52-11-13, AMM 52-11-13								
52CA5211122	REPLACE O-RINGS (M83248/1-228 MED) AND (MS29513-234 EED).							Service ATA:52
	MOS/MSC	23-Jun-17	O/C					
	HRS	0		TAC 0				
	AFL	0						
PROC. REF: AMM 52-11-11, AMM 52-11-11PROC. REF: AMM 52-11-11, AMM 52-11-11								
52CA5211130	MAIN ENTRY DOOR (MED) HINGE PLATE FASTENERS - REPLACE							Service ATA:52
	MOS	EFF						
	HRS							
	AFL	EFF	9000		9000 *		7439	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52CA5211181	MAIN ENTRY DOOR AIRSTAIR ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-11-18, AMM 52-11-18PROC. REF: AMM 52-11-18, AMM 52-11-18								
52CA5211210	DOOR ASSIST ASSY - MED							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-11-16, AMM 52-11-16PROC. REF: AMM 52-11-16, AMM 52-11-16								
52CA5211211	MAIN ENTRY DOOR ASSIST SPRING - REPLACE							Component ATA:52
PN:PN	MOS	23-Jun-17		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	3000	TSN 0	3000		1439	
PROC. REF: AMM 52-11-21, AMM 52-11-21PROC. REF: AMM 52-11-21, AMM 52-11-21								
52CA5221111	EMERGENCY EXIT DOOR ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-21-11, AMM 52-21-11PROC. REF: AMM 52-21-11, AMM 52-21-11								
52CA5231001	AFT BAGGAGE DOOR ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-10, AMM 52-31-10PROC. REF: AMM 52-31-10, AMM 52-31-10								
52CA5231002	FWD BAGGAGE DOOR ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-32-10, AMM 52-32-10PROC. REF: AMM 52-32-10, AMM 52-32-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52CA5232121	NOSE BAGGAGE DOOR UPPER AFT LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-32-12, AMM 52-32-12PROC. REF: AMM 52-32-12, AMM 52-32-12								
52CA5232122	NOSE BAGGAGE DOOR LOWER AFT LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-32-12, AMM 52-32-12PROC. REF: AMM 52-32-12, AMM 52-32-12								
52CA5232123	NOSE BAGGAGE DOOR LOWER FWD LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-32-12, AMM 52-32-12PROC. REF: AMM 52-32-12, AMM 52-32-12								
52CA5232124	NOSE BAGGAGE DOOR UPPER FWD LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-32-12, AMM 52-32-12PROC. REF: AMM 52-32-12, AMM 52-32-12								
52CA5232125	NO. 1 AFT BAGGAGE DOOR LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-11, AMM 52-31-11PROC. REF: AMM 52-31-11, AMM 52-31-11								
52CA5232126	NO. 2 AFT BAGGAGE DOOR LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-11, AMM 52-31-11PROC. REF: AMM 52-31-11, AMM 52-31-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52CA5232127	NO. 3 AFT BAGGAGE DOOR LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-11, AMM 52-31-11PROC. REF: AMM 52-31-11, AMM 52-31-11								
52CA5232128	NO. 4 AFT BAGGAGE DOOR LATCH ASSY							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-11, AMM 52-31-11PROC. REF: AMM 52-31-11, AMM 52-31-11								
52CA5241001	LAVATORY SERVICE DOOR							Component ATA:52
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-42-10, AMM 52-42-10PROC. REF: AMM 52-42-10, AMM 52-42-10								
52HA0500107 ^S	DO A VISUAL INSPECTION OF THE AFT BAGGAGE DOOR SEAL AND BLEED HOLES SHALL BE OPEN.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
52HA0500108 ^S	DO A VISUAL INSPECTION OF THE AFT BAGGAGE DOOR LATCHES AND HINGES.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52HA0500109 ^S	DO A VISUAL INSPECTION OF THE NOSE GEAR DOORS, HARDWARE, AND ACTUATION MECHANISM.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
52HA0500110 ^S	DO A VISUAL INSPECTION OF THE MAIN GEAR DOORS, HARDWARE AND ACTUATORS.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
52HA0500111	VENT PATH FROM THE FORWARD BAGGAGE AREA TO THE NOSE LANDING GEAR BAY AND RADOME AND UNDER FLOOR AREA - VISUAL INSPECTION							Service ATA:52
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600		1761.9		46.8	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
52HA0500112 ^S	DO A VISUAL INSPECTION OF THE SERVICE DOOR LANDS, LATCHES, HINGES AND CENTERING DEVICES.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
52HA0500113	MAIN ENTRY DOOR LOWER HINGE PIN - DETAILED INSPECTION							Service ATA:52
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600		1761.9		46.8	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 52-11-20, AMM 52-11-20PROC. REF: AMM 52-11-20, AMM 52-11-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52HA0500114	^S	DO THE MAIN LANDING GEAR INBOARD DOOR PRE-LOAD CHECK.						Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
52HA0500115	^S	DO THE FUNCTIONAL TEST OF THE JT CONNECTOR ACCESS DOORS (433BR, 443BL).						Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
52HA0500116	^S	DO A VISUAL INSPECTION OF THE MAIN ENTRY DOOR STOPS, POSTS, HINGES, BAYONETS, LATCHES, O-RINGS, SEALS, LOWER HINGE ATTACHMENT. INSPECT THE SIX BLEED HOLES IN THE MAIN ENTRY DOOR (MED) RING FRAME (INNER) COMMON TO THE PRESSURE SEAL BASE						Service ATA:52
	MOS	23-Jun-17						
	HRS	0	1200 (+60/-60)					
	AFL	0						
								PKG:6
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
52HA0500117	^S	DO A VISUAL INSPECTION OF THE EMERGENCY EXIT DOOR, STOPS, POSTS, HINGES, BAYONETS, LATCHES, O-RINGS AND SEALS						Service ATA:52
	MOS	23-Jun-17						
	HRS	0	600 (+60/-60)					
	AFL	0						
								PKG:1
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52HA1221101 ^S	LUBRICATE THE FUSELAGE DOORS (MAIN ENTRY DOOR AND EMERGENCY EXIT DOOR).							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 12-21-12PROC. REF: AMM 12-21-12								
52HA5210101 ^S	DO THE OPERATIONAL TEST OF THE MAIN ENTRY DOOR.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01								
52HA5210102 ^S	DO THE FUNCTIONAL TEST OF THE MAIN ENTRY DOOR LATCH/LOCK HANDLE.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 52-10-02PROC. REF: AMM 52-10-02								
52HA5210103	MAIN ENTRY DOOR (MED) WARNING SYSTEM; INCLUDING MED SWITCHES - FUNCTIONAL TEST							Service ATA:52
	MOS	02-Jun-23						AIRWORTHINESS
	HRS	1161.9	600 (+60/-60)		1761.9	1821.9	46.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: AMM 52-10-03PROC. REF: AMM 52-10-03								
52HA5220101 ^S	DO THE FUNCTIONAL TEST OF THE EMERGENCY EXIT DOOR LATCH HANDLE.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52HA5230101 ^S	DO THE FUNCTIONAL TEST OF THE FORWARD BAGGAGE DOOR.							Service ATA:52
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: AMM 52-30-02PROC. REF: AMM 52-30-02								
ATA 53 - FUSELAGE								
53CA5311001	RADOME ASSEMBLY							Component ATA:53
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-14-10, AMM 53-14-10PROC. REF: AMM 53-14-10, AMM 53-14-10								
53CA5311002	RUDDER FAIRING							Component ATA:53
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53CA5311003	FWD L/H FAIRING							Component ATA:53
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53CA5311004	FWD R/H FAIRING							Component ATA:53
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53CA5311005	TRAILING EDGE FAIRING							Component ATA:53
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
53HA0500101	DO A VISUAL INSPECTION OF THE RADOME AND DRAIN HOLES.							Service ATA:53
	MOS	02-Jun-23	60 (+30d/-30d)					
	HRS	1161.9	2400 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
53HA0500102	DO A VISUAL INSPECTION OF THE RADOME LIGHTNING DIVERTER STRIPS.							Service ATA:53
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
53HA0500103	DO A VISUAL INSPECTION OF THE FORWARD/AFT PRESSURE BULKHEADS.							Service ATA:53
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
53HA0500104	DO A VISUAL INSPECTION OF FUSELAGE STRINGERS, INNER SKIN AND FLOOR STRUCTURE.							Service ATA:53
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53HA0500105	DO A VISUAL INSPECTION OF THE FUSELAGE FAIRINGS, DRAIN HOLES, AND VENT SYSTEM.							Service ATA:53
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
53HA0500106	DO A VISUAL INSPECTION OF THE WING ATTACH AREA.							Service ATA:53
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
53HA0500107 ^S	DO A VISUAL INSPECTION OF THE TAIL CONE AT FS 415 AND AFT.							Service ATA:53
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
53HA0500108 ^S	DO A VISUAL INSPECTION OF THE FUSELAGE EXTERIOR SKIN.							Service ATA:53
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
53HA0500109	DO A VISUAL INSPECTION OF THE FUSELAGE BILGE DRAINS.							Service ATA:53
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)	Adj 38.1	2400	2460	684.9 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53HA0500110 ^S	DO A VISUAL INSPECTION OF THE AFT SERVICE BAY HYDRAULIC SYSTEM, ENVIRONMENTAL SYSTEM; FLIGHT CONTROLS SYSTEMS AND ELECTRICAL EQUIPMENT, WIRE CONNECTIONS.							Service ATA:53
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
53HA5300103	DO THE INSPECTION OF THE FORWARD FUSELAGE AND THE RVSM CRITICAL ZONE.							Service ATA:53
	MOS	05-May-25	24 (+30d/-30d)		05-May-27 (M)	04-Jun-27	511 d (+30)	RVSM
	HRS	1671.6						
	AFL	1523						
PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01								
ATA 54 - NACELLES/PYLONS								
54CA5400001	LEFT ENGINE PYLON ASSEMBLY							Component ATA:54
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 54-11-10, AMM 54-11-10PROC. REF: AMM 54-11-10, AMM 54-11-10								
54CA5400002	RIGHT ENGINE PYLON ASSEMBLY							Component ATA:54
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 54-11-10, AMM 54-11-10PROC. REF: AMM 54-11-10, AMM 54-11-10								
54CA5410003	LH FWD PYLON THERMAL BLANKET							Component ATA:54
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54CA5410004	RH FWD PYLON THERMAL BLANKET							Component ATA:54
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
54CA5410005	LEFT ENGINE MOUNT ACCESS COVER							Component ATA:54
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
54CA5410006	RIGHT ENGINE MOUNT ACCESS COVER							Component ATA:54
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
54HA0500102	DO A VISUAL INSPECTION OF THE FIRE SEALS, FORWARD AND AFT FIREWALLS, PYLON FIREWALL AND FORWARD PYLON FIREWALL BLANKET. ENSURE GAP IN SEAL, JUST AFT OF STARTER/ GENERATOR VENT IS OPEN.							Service ATA:54
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
54HA0500103	DO A VISUAL INSPECTION OF THE PYLON AND FIREWALL DRAIN LINES, DRAINS AND VENTS.							Service ATA:54
	MOS	02-Jun-23						
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54HA0500104	^S	DO A VISUAL INSPECTION OF THE PRECOOLER OUTLET DUCTS.						Service ATA:54
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
54HA0500105		DO A VISUAL INSPECTION OF THE INTERIOR AND EXTERIOR AREAS OF PYLON.						Service ATA:54
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
54HA0500106	^S	DO A VISUAL INSPECTION OF THE PYLON ATTACHMENT POINTS.						Service ATA:54
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
54HA0500107		DO A VISUAL INSPECTION OF THE PYLON WIRE HARNESSSES.						Service ATA:54
	MOS/MSC	02-Jun-23	N/A					
	HRS	1161.9						
	AFL	1084						
								WO#: FAMQ0152
ATA 55 - STABILIZERS								
55CA5512113		LEFT ELEVATOR BALANCED ASSY, EMP						Component ATA:55
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 55-21-12, AMM 55-21-12PROC. REF: AMM 55-21-12, AMM 55-21-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55CA5512114	RIGHT ELEVATOR BALANCED ASSY, EMP							Component ATA:55
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 55-21-12, AMM 55-21-12PROC. REF: AMM 55-21-12, AMM 55-21-12								
55CA5541111	EMPENNAGE RUDDER BALANCED ASSEMBLY							Component ATA:55
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 55-41-11, AMM 55-41-11PROC. REF: AMM 55-41-11, AMM 55-41-11								
55HA0500101	DO A VISUAL INSPECTION OF THE VERTICAL STABILIZER, ATTACHMENTS TO THE STABILIZER, SPARS, BULKHEADS, FRAMES, FAIRING, AND FITTINGS. FLIGHT CONTROL REMOVAL IS NOT REQUIRED.							Service ATA:55
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
55HA0500102 ^S	DO A VISUAL INSPECTION OF THE ELEVATOR ASSEMBLY INCLUDING TRIM TAB, ELEVATOR AND ATTACHING PARTS.							Service ATA:55
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
55HA0500103 ^S	DO A VISUAL INSPECTION OF THE RUDDER ASSEMBLY INCLUDING TRIM TAB AND ATTACHING PARTS.							Service ATA:55
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55HA0500104 ^S	DO A VISUAL INSPECTION OF THE HORIZONTAL STABILIZER VORTEX GENERATORS, 21 PER SIDE. (EFFECTIVITY: 42000011 THROUGH 42000125, UNLESS SB-420-55-001 HAS BEEN COMPLIED WITH).							Service ATA:55
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
55HA5522101	DO A VISUAL INSPECTION OF THE ELEVATOR LEADING EDGE CUFFS/HINGE COVERS FOR ATTACHMENT. (EFFECTIVITY: 42000011 THROUGH 42000041 UNLESS SB-420-55-001 HAS BEEN COMPLIED WITH)							Service ATA:55
	MOS/MSC	23-Jun-17	N/A	TAC 0				NOT APPLICABLE
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
ATA 56 - WINDOWS								
56CA5611101	LEFT WINDSHIELD ASSEMBLY							Component ATA:56
PN:HJ1-15610-020-001	MOS/MSC	09-Apr-21	O/C	TSO 0				
SN:747N	HRS	311.8		TSO 0				
	AFL	291		TSO 0				
PROC. REF: AMM 56-11-10, AMM 56-11-10PROC. REF: AMM 56-11-10, AMM 56-11-10								
56CA5611102	RIGHT WINDSHIELD ASSEMBLY							Component ATA:56
PN:HJ1-15610-020-002	MOS/MSC	09-Apr-21	O/C	TSO 0				
SN:950N	HRS	311.8		TSO 0				
	AFL	291		TSO 0				
PROC. REF: AMM 56-11-10, AMM 56-11-10PROC. REF: AMM 56-11-10, AMM 56-11-10								
56CA5611103	LEFT COCKPIT SIDE WINDOW							Component ATA:56
PN:HJ1-15610-010-010	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:706	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56CA5611104	RIGHT COCKPIT SIDE WINDOW							Component ATA:56
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11								
56CA5611111	LEFT WINDSHIELD FASTENERS - REPLACE							Service ATA:56
	MOS	EFF						
	HRS							
	AFL	EFF	10000		10000 *		8439	
PROC. REF: AMM 56-11-10, AMM 56-11-10PROC. REF: AMM 56-11-10, AMM 56-11-10								
56CA5611112	RIGHT WINDSHIELD FASTENERS - REPLACE							Service ATA:56
	MOS	EFF						
	HRS							
	AFL	EFF	10000		10000 *		8439	
PROC. REF: AMM 56-11-10, AMM 56-11-10PROC. REF: AMM 56-11-10, AMM 56-11-10								
56CA5611113	LEFT COCKPIT SIDE WINDOW - REPLACE							Service ATA:56
	MOS	EFF						
	HRS							
	AFL	EFF	14000		14000 *		12439	
PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11								
56CA5611114	RIGHT COCKPIT SIDE WINDOW - REPLACE							Service ATA:56
	MOS	EFF						
	HRS							
	AFL	EFF	14000		14000 *		12439	
PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11PROC. REF: AMM 56-11-11, AMM 56-11-11, AMM 56-11-11, AMM 56-11-11								
56CA5621101	CABIN WINDOW							Component ATA:56
PN:HJ1-15620-010-031	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1830	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56CA5621102	CABIN WINDOW							Component ATA:56
PN:HJ1-15620-010-033	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1108	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								
56CA5621103	CABIN WINDOW							Component ATA:56
PN:HJ1-15620-010-033	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1839	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								
56CA5621104	CABIN WINDOW							Component ATA:56
PN:HJ1-15620-010-033	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1840	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								
56CA5621105	CABIN WINDOW							Component ATA:56
PN:HJ1-15620-010-031	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1831	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								
56CA5621106	CABIN WINDOW							Component ATA:56
PN:HJ1-15620-010-033	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1841	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								
56CA5621107	CABIN WINDOW							Component ATA:56
PN:HJ1-15620-010-033	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:1843	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56CA5621108	CABIN EMERGENCY EXIT WINDOW							Component ATA:56
PN:HJ1-15620-010-027	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:IMDG4-01	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-21-10, AMM 56-21-10PROC. REF: AMM 56-21-10, AMM 56-21-10								
56HA0500101 ^S	DO A VISUAL INSPECTION OF THE COCKPIT WINDSHIELDS.							Service ATA:56
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
56HA0500102 ^S	DO A VISUAL INSPECTION OF THE WINDSHIELDS AND FRAMES.							Service ATA:56
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
56HA0500103 ^S	DO A VISUAL INSPECTION OF THE CABIN WINDOWS.							Service ATA:56
	MOS	02-Jun-23						
	HRS	1161.9	600 (+60/-60)					
	AFL	1084						
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
ATA 57 - WINGS								
57CA5700001	UPPER LEFT MACH-COS WING SKIN							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57CA5700002	UPPER RIGHT MACH-COS WING SKIN							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5700003	LOWER LEFT COS WING SKIN							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5700004	LOWER RIGHT COS WING SKIN							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5700005	FORWARD LEFT LINKAGE SET							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5700006	FORWARD RIGHT LINKAGE SET							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5700007	AFT LEFT LINKAGE SET							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57CA5700008	AFT RIGHT LINKAGE SET							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710001	WING JOIN ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710002	LEFT LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-21-10, AMM 57-21-10PROC. REF: AMM 57-21-10, AMM 57-21-10								
57CA5710003	RIGHT LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-21-10, AMM 57-21-10PROC. REF: AMM 57-21-10, AMM 57-21-10								
57CA5710004	LEFT WING TIP LIGHT							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-21-12, AMM 57-21-12PROC. REF: AMM 57-21-12, AMM 57-21-12								
57CA5710005	RIGHT WING TIP LIGHT							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-21-12, AMM 57-21-12PROC. REF: AMM 57-21-12, AMM 57-21-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57CA5710006	LEFT WINGLET							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-22-10, AMM 57-22-10PROC. REF: AMM 57-22-10, AMM 57-22-10								
57CA5710007	RIGHT WINGLET							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-22-10, AMM 57-22-10PROC. REF: AMM 57-22-10, AMM 57-22-10								
57CA5710008	LEFT WING TRAILING EDGE							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-21-11, AMM 57-21-11PROC. REF: AMM 57-21-11, AMM 57-21-11								
57CA5710009	RIGHT WING TRAILING EDGE							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-21-11, AMM 57-21-11PROC. REF: AMM 57-21-11, AMM 57-21-11								
57CA5710010	LEFT AILERON							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710011	RIGHT AILERON							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57CA5710012	LEFT FLAP/VANE							Component ATA:57
PN:HJ1-15753-110-029	MOS/MSC	15-Mar-24	O/C	TSR 9				
SN:LMI00067	HRS	1476.8		TSR 0				
	AFL	1340		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710013	RIGHT FLAP/VANE							Component ATA:57
PN:HJ1-15753-110-028	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710014	LEFT FLAP FAIRING							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-51-10, AMM 57-51-10PROC. REF: AMM 57-51-10, AMM 57-51-10								
57CA5710015	RIGHT FLAP FAIRING							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-51-10, AMM 57-51-10PROC. REF: AMM 57-51-10, AMM 57-51-10								
57CA5710016	NO. 1 WING JOIN ACCESS PANEL							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710017	NO. 2 WING JOIN ACCESS PANEL							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57CA5710018	NO. 3 WING JOIN ACCESS PANEL							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710019	NO. 4 WING JOIN ACCESS PANEL							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710020	NO. 5 WING JOIN ACCESS PANEL							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710021	NO. 6 WING JOIN ACCESS PANEL							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710022	LEFT WING TORQUE BOX							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
57CA5710023	RIGHT WING TORQUE BOX							Component ATA:57
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57HA0500101	DO AN EXTERNAL VISUAL INSPECTION OF THE SKIN, RIVETS, DRAINS, AND ATTACHMENTS ON THE WING.							Service ATA:57
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
57HA0500102 ^S	DO A VISUAL INSPECTION OF THE WINGLET, DRAIN HOLE AND VORTEX GENERATORS INSTALLATION. (EFFECTIVITY: 42000012 THROUGH 42000125, UNLESS SB-420-55-001 HAS BEEN COMPLIED WITH)							Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
57HA0500103 ^S	DO A VISUAL INSPECTION OF THE FLAP FAIRINGS AND DRAIN HOLES.							Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
57HA0500104 ^S	DO AN EXTERNAL VISUAL INSPECTION OF THE WING LEADING EDGE.							Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152
57HA0500105 ^S	DO AN EXTERNAL VISUAL INSPECTION OF THE WING INSPECTION PANELS AND UPPER TRAILING EDGE SKINS.							Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
57HA0500107	^S	DO A VISUAL INSPECTION OF THE FLAP ASSEMBLY INCLUDING VANES AND FLAP ATTACHING PARTS.						Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
57HA0500108	^S	DO A VISUAL INSPECTION OF THE AILERON ASSEMBLY INCLUDING TRIM TAB AND ATTACHING PARTS.						Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
57HA0500109	^S	DO A VISUAL INSPECTION OF THE EXTERIOR PLACARDS SHOWN IN SECTION 2 OF THE AFM.						Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
57HA0500110	^S	DO A VISUAL INSPECTION OF THE WING DRY BAY ELECTRICAL HARNESSSES. REMOVE PANELS 521FB, 621FB, 521EB, AND 621EB FOR ACCESS.						Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57HA0500111	DO A VISUAL INSPECTION OF THE MAIN LANDING GEAR WHEEL WELL SKIN, SPARS AND RIBS.							Service ATA:57
	MOS	02-Jun-23	60 (+30d/-30d)		02-Jun-28	02-Jul-28	905 d (+30)	
	HRS	1161.9	2400 (+60/-60)		3561.9	3621.9	1846.8 (+60)	
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								WO#: FAMQ0152
57HA0500112 ^S	DO A VISUAL INSPECTION OF THE WING VORTEX GENERATORS AND BUMPS.							Service ATA:57
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								PKG:6 WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 70 - STANDARD PRACTICES - ENGINES								
70-31-00-970-801	NO. 1 ENGINE - PERFORMANCE CHECK - MONITOR AND RECORD SPECIFIED ENGINE DATA							Service ATA:70
	MOS	25-Sep-25	1		31-Oct-25 (M)		OVD	
	HRS	1654.6						
	ENC	1508						
								WO#: FAMQ0152
70-31-00-970-801	NO. 2 ENGINE - PERFORMANCE CHECK - MONITOR AND RECORD SPECIFIED ENGINE DATA							Service ATA:70
	MOS	26-Aug-25	1		31-Oct-25 (M)		OVD	
	HRS	1715.1						
	ENC	1561						
								WO#: FAMQ0152
70-31-00-970-802	NO. 1 ENGINE - RECORD ALL ENGINE RELATED FAULT MESSAGES							Service ATA:70
	MOS/MSC	26-May-17	E/C	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
70-31-00-970-802	NO. 2 ENGINE - RECORD ALL ENGINE RELATED FAULT MESSAGES							Service ATA:70
	MOS/MSC	26-May-17	E/C	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
ATA 71 - POWER PLANT								
71CA7100001	LEFT MANIFOLD							Component ATA:71
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71CA7100001	RIGHT MANIFOLD							Component ATA:71
PN:PN	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
71CA7120001	LEFT UPPER ENGINE ISOLATORS (P/N HJ1-15413-213-005) - REPLACE							Component ATA:71
PN:PN	MOS	23-Jun-17		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	5500 (+60/-60)	TSN 0	5500	5560	3784.9 (+60)	
	AFL	0		TSN 0				
PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63								
71CA7120002	RIGHT UPPER ENGINE ISOLATORS (P/N HJ1-15413-213-005) - REPLACE							Component ATA:71
PN:PN	MOS	23-Jun-17		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	5500 (+60/-60)	TSN 0	5500	5560	3784.9 (+60)	
	AFL	0		TSN 0				
PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63								
71CA7120003	LEFT LOWER ENGINE ISOLATORS (P/N HJ1-15413-213-005) - REPLACE							Component ATA:71
PN:PN	MOS	23-Jun-17		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	5500 (+60/-60)	TSN 0	5500	5560	3784.9 (+60)	
	AFL	0		TSN 0				
PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63								
71CA7120004	RIGHT LOWER ENGINE ISOLATORS (P/N HJ1-15413-213-005) - REPLACE							Component ATA:71
PN:PN	MOS	23-Jun-17		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0	5500 (+60/-60)	TSN 0	5500	5560	3784.9 (+60)	
	AFL	0		TSN 0				
PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63PROC. REF: AMM 71-00-00, AMM 71-00-00, CMM 71-20-63								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:HJ1-17201-120-003	MOS/MSC	21-May-24	E/C					
SN:883207	HRS	1550.5						
WC#: 71.EN1	AFL	1403						
PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:HJ1-17201-120-004	MOS/MSC		E/C					
SN:883208	HRS							
WC#: 71.EN2	AFL							
PROC. REF: AMM 71-00-00, AMM 71-00-00PROC. REF: AMM 71-00-00, AMM 71-00-00								
71HA0500101	DO A VISUAL INSPECTION OF THE ENGINE VIBRATION ISOLATORS.							Service ATA:71
	MOS/MSC	02-Jun-23	E/R					
	HRS	1161.9	2500 (+60/-60)		3661.9	3721.9	1946.8 (+60)	
	AFL	1084						
								WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
ATA 72 - ENGINE								
72-00-00-200-801	NO. 1 ENGINE - PRE-FLIGHT INSPECTION OF ENGINE							Service ATA:72
	MOS/MSC	26-May-17	PF/F	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
72-00-00-200-801	NO. 2 ENGINE - PRE-FLIGHT INSPECTION OF ENGINE							Service ATA:72
	MOS/MSC	26-May-17	PF/F	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
72-00-00-200-802	NO. 1 ENGINE - BORESCOPE INSPECTION OF ENGINE							Service ATA:72
	MOS	02-Aug-24						
	HRS	1565	600		(2165) 2225.5		510.4	
	ENC	1420						
								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-200-802	NO. 2 ENGINE - BORESCOPE INSPECTION OF ENGINE							Service ATA:72
	MOS	15-Mar-24						
	HRS	1476.8	600		(2076.8) 2076.8		361.7	
	ENC	1340						
								WO#: FAMQ0152
72-00-00-200-804	NO. 1 ENGINE - DETAILED INSPECTION INNER SURFACE OF FAN CASE							Service ATA:72
	MOS	05-May-25						MANDATORY
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152
72-00-00-200-804	NO. 2 ENGINE - DETAILED INSPECTION INNER SURFACE OF FAN CASE							Service ATA:72
	MOS	05-May-25						MANDATORY
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
								WO#: FAMQ0152
72-00-00-200-805	NO. 1 ENGINE - DETAILED INSPECTION OF EXPOSED ENGINE							Service ATA:72
	MOS	05-May-25						
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152
72-00-00-200-805	NO. 2 ENGINE - DETAILED INSPECTION OF EXPOSED ENGINE							Service ATA:72
	MOS	05-May-25						
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
								WO#: FAMQ0152
72-00-00-200-806	NO. 1 ENGINE - DETAILED INSPECTION OF THE CORE INNER DUCT ASSEMBLY							Service ATA:72
	MOS	05-May-25						
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152
72-00-00-200-806	NO. 2 ENGINE - DETAILED INSPECTION OF THE CORE INNER DUCT ASSEMBLY							Service ATA:72
	MOS	05-May-25						
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
								WO#: FAMQ0152
72-00-00-550-801	NO. 1 ENGINE - PRESERVATION OF THE ENGINE							Service ATA:72
	MOS/MSC	10-Jan-20	A/R					
	HRS	311.8						
	ENC	291						
72-00-00-550-801	NO. 2 ENGINE - PRESERVATION OF THE ENGINE							Service ATA:72
	MOS/MSC	10-Jan-20	A/R					
	HRS	311.8						
	ENC	291						
72-00-00-620-013	NO. 1 ENGINE - 90 DAY SHORT TERM PRESERVATION OF AN ENGINE							Service ATA:72
	DAYS/MSC	14-Aug-21	A/R					
	HRS							
	ENC							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-620-013	NO. 2 ENGINE - 90 DAY SHORT TERM PRESERVATION OF AN ENGINE							Service ATA:72
	DAYS/MSC	14-Aug-21	A/R					
	HRS							
	ENC							
72-00-00-810-802	NO. 1 ENGINE - TROUBLE SHOOT (CAS) CREW ALERTING SYSTEM							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
72-00-00-810-802	NO. 2 ENGINE - TROUBLE SHOOT (CAS) CREW ALERTING SYSTEM							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
72-21-00-280-005	NO. 1 ENGINE - TIME BETWEEN OVERHAUL (TBO)							Service ATA:72
	MOS	26-May-17		TAC 0				OVERHAUL
	HRS	0	3750		(3750) 3810.5		2095.4	
	ENC	0		TAC 0				
72-21-00-280-005	NO. 2 ENGINE - TIME BETWEEN OVERHAUL (TBO)							Service ATA:72
	MOS	26-May-17		TAC 0				OVERHAUL
	HRS	0	3750		(3750) 3750		2034.9	
	ENC	0		TAC 0				
72-21-00-280-009	NO. 1 ENGINE - HOT SECTION INSPECTION (HSI)							Service ATA:72
	MOS	26-May-17		TAC 0				
	HRS	0	2500	TAC 0	(2500) 2560.5		845.4	
	ENC	0		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-21-00-280-009	NO. 2 ENGINE - HOT SECTION INSPECTION (HSI)							Service ATA:72
	MOS	26-May-17		TAC 0				
	HRS	0	2500	TAC 0	(2500) 2500		784.9	
	ENC	0		TAC 0				
72-21-01-210-801	NO. 1 ENGINE - VISUAL INSPECTION LOW PRESSURE SHAFT PIECE-PART EXPOSURE							Service ATA:72
PN:15721-Q0A-0000	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
SN:FHTJ0340	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-01PROC. REF: OHM 72-21-01								
72-21-01-210-801	NO. 2 ENGINE - VISUAL INSPECTION LOW PRESSURE SHAFT PIECE-PART EXPOSURE							Service ATA:72
PN:15721-Q0A-0000	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
SN:FHTJ0335	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-01PROC. REF: OHM 72-21-01								
72-21-01-240-801	NO. 1 ENGINE - MAGNETIC PARTICLE INSPECT LOW PRESSURE SHAFT PIECE-PART EXPOSURE							Service ATA:72
PN:15721-Q0A-0000	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
SN:FHTJ0340	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-01PROC. REF: OHM 72-21-01								
72-21-01-240-801	NO. 2 ENGINE - MAGNETIC PARTICLE INSPECT LOW PRESSURE SHAFT PIECE-PART EXPOSURE							Service ATA:72
PN:15721-Q0A-0000	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
SN:FHTJ0335	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-01PROC. REF: OHM 72-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-21-02-210-801	NO. 1 ENGINE - VISUAL INSPECTION FAN BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-02PROC. REF: OHM 72-21-02								
72-21-02-210-801	NO. 2 ENGINE - VISUAL INSPECTION FAN BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-02PROC. REF: OHM 72-21-02								
72-21-02-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION FAN BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-02PROC. REF: OHM 72-21-02								
72-21-02-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION FAN BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-02PROC. REF: OHM 72-21-02								
72-21-02-250-801	NO. 1 ENGINE - EDDY CURRENT INSPECTION FAN BLISK PIECE-PART EXPOSURE (ECI OF THE BORE)							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-02PROC. REF: OHM 72-21-02								
72-21-02-250-801	NO. 2 ENGINE - EDDY CURRENT INSPECTION FAN BLISK PIECE-PART EXPOSURE (ECI OF THE BORE)							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-21-02PROC. REF: OHM 72-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-21-02-900-801	NO. 1 ENGINE - FAN BLISK							Component ATA:72
PN:15111-Q0A-E000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS2764	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15053		13492	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-21-02-900-801	NO. 2 ENGINE - FAN BLISK							Component ATA:72
PN:15111-Q0A-E000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS2934	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15000		13439	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-22-02-210-801	NO. 1 ENGINE - VISUAL INSPECTION STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-02PROC. REF: OHM 72-22-02								
72-22-02-210-801	NO. 2 ENGINE - VISUAL INSPECTION STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-02PROC. REF: OHM 72-22-02								
72-22-02-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-02PROC. REF: OHM 72-22-02								
72-22-02-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: OHM 72-22-02PROC. REF: OHM 72-22-02								
72-22-02-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-02PROC. REF: OHM 72-22-02								
72-22-02-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-02PROC. REF: OHM 72-22-02								
72-22-02-900-801	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK							Component ATA:72
PN:15311-Q0A-0300	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS3011	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15053		13492	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-22-02-900-801	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR ROTOR BLISK							Component ATA:72
PN:15311-Q0A-0300	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS3018	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15000		13439	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-22-03-210-801	NO. 1 ENGINE - VISUAL INSPECTION STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-03PROC. REF: OHM 72-22-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-22-03-210-801	NO. 2 ENGINE - VISUAL INSPECTION STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-03PROC. REF: OHM 72-22-03								
72-22-03-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-03PROC. REF: OHM 72-22-03								
72-22-03-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-03PROC. REF: OHM 72-22-03								
72-22-03-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-03PROC. REF: OHM 72-22-03								
72-22-03-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-22-03PROC. REF: OHM 72-22-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-22-03-900-801	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY							Component ATA:72
PN:15321-Q0A-0100	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS2627	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15053		13492	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-22-03-900-801	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR ROTOR ASSEMBLY							Component ATA:72
PN:15321-Q0A-0100	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS3257	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15000		13439	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-23-02-210-801	NO. 1 ENGINE - VISUAL INSPECTION INTERMEDIATE (IM) CASE ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-23-02PROC. REF: OHM 72-23-02								
72-23-02-210-801	NO. 2 ENGINE - VISUAL INSPECTION INTERMEDIATE (IM) CASE ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-23-02PROC. REF: OHM 72-23-02								
72-23-02-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION INTERMEDIATE (IM) CASE ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-23-02PROC. REF: OHM 72-23-02								
72-23-02-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION INTERMEDIATE (IM) CASE ASSEMBLY PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: OHM 72-23-02PROC. REF: OHM 72-23-02								
72-23-02-900-801	NO. 1 ENGINE - INTERMEDIATE (IM) CASE ASSEMBLY							Component ATA:72
PN:11110-Q0A-G000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:SPK99ATS	HRS	0		TSN 0				
	ENC	0	22490	TSN 0	(22490) 22543		20982	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-23-02-900-801	NO. 2 ENGINE - INTERMEDIATE (IM) CASE ASSEMBLY							Component ATA:72
PN:11110-Q0A-G000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:SPK998HN	HRS	0		TSN 0				
	ENC	0	22490	TSN 0	(22490) 22490		20929	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-21-900-801	NO. 1 ENGINE - LOW PRESSURE SHAFT							Component ATA:72
PN:15721-Q0A-0000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:FHTJ0340	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15053		13492	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-50-21-900-801	NO. 2 ENGINE - LOW PRESSURE SHAFT							Component ATA:72
PN:15721-Q0A-0000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:FHTJ0335	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15000		13439	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-00-280-801	NO. 1 ENGINE - REPLACE HPT NO. 1 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-801	NO. 2 ENGINE - REPLACE HPT NO. 1		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-802	NO. 1 ENGINE - REPLACE HPT NO. 2		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-802	NO. 2 ENGINE - REPLACE HPT NO. 2		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-803	NO. 1 ENGINE - REPLACE HPT NO. 3		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-803	NO. 2 ENGINE - REPLACE HPT NO. 3		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-804	NO. 1 ENGINE - REPLACE HPT NO. 4		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-804	NO. 2 ENGINE - REPLACE HPT NO. 4		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-805	NO. 1 ENGINE - REPLACE HPT NO. 5		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-805	NO. 2 ENGINE - REPLACE HPT NO. 5		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-806	NO. 1 ENGINE - REPLACE HPT NO. 6		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-806	NO. 2 ENGINE - REPLACE HPT NO. 6		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-807	NO. 1 ENGINE - REPLACE HPT NO. 7		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-807	NO. 2 ENGINE - REPLACE HPT NO. 7		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-808	NO. 1 ENGINE - REPLACE HPT NO. 8		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-808	NO. 2 ENGINE - REPLACE HPT NO. 8		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-809	NO. 1 ENGINE - REPLACE HPT NO. 9		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-809	NO. 2 ENGINE - REPLACE HPT NO. 9		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-810	NO. 1 ENGINE - REPLACE HPT NO. 10		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-810	NO. 2 ENGINE - REPLACE HPT NO. 10		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-811	NO. 1 ENGINE - REPLACE HPT NO. 11		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-811	NO. 2 ENGINE - REPLACE HPT NO. 11		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-812	NO. 1 ENGINE - REPLACE HPT NO. 12		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-812	NO. 2 ENGINE - REPLACE HPT NO. 12		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-813	NO. 1 ENGINE - REPLACE HPT NO. 13		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-813	NO. 2 ENGINE - REPLACE HPT NO. 13		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-814	NO. 1 ENGINE - REPLACE HPT NO. 14		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-814	NO. 2 ENGINE - REPLACE HPT NO. 14		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-815	NO. 1 ENGINE - REPLACE HPT NO. 15		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-815	NO. 2 ENGINE - REPLACE HPT NO. 15		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-816	NO. 1 ENGINE - REPLACE HPT NO. 16		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-816	NO. 2 ENGINE - REPLACE HPT NO. 16		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-817	NO. 1 ENGINE - REPLACE HPT NO. 17		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-817	NO. 2 ENGINE - REPLACE HPT NO. 17		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-818	NO. 1 ENGINE - REPLACE HPT NO. 18		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-818	NO. 2 ENGINE - REPLACE HPT NO. 18		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-819	NO. 1 ENGINE - REPLACE HPT NO. 19		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-819	NO. 2 ENGINE - REPLACE HPT NO. 19		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-820	NO. 1 ENGINE - REPLACE HPT NO. 20		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-820	NO. 2 ENGINE - REPLACE HPT NO. 20		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-821	NO. 1 ENGINE - REPLACE HPT NO. 21		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-821	NO. 2 ENGINE - REPLACE HPT NO. 21		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-822	NO. 1 ENGINE - REPLACE HPT NO. 22		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-822	NO. 2 ENGINE - REPLACE HPT NO. 22		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-823	NO. 1 ENGINE - REPLACE HPT NO. 23		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-823	NO. 2 ENGINE - REPLACE HPT NO. 23		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-824	NO. 1 ENGINE - REPLACE HPT NO. 24		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-824	NO. 2 ENGINE - REPLACE HPT NO. 24		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-825	NO. 1 ENGINE - REPLACE HPT NO. 25		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-825	NO. 2 ENGINE - REPLACE HPT NO. 25		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-826	NO. 1 ENGINE - REPLACE HPT NO. 26		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-826	NO. 2 ENGINE - REPLACE HPT NO. 26		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-827	NO. 1 ENGINE - REPLACE HPT NO. 27		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-827	NO. 2 ENGINE - REPLACE HPT NO. 27		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-828	NO. 1 ENGINE - REPLACE HPT NO. 28		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-828	NO. 2 ENGINE - REPLACE HPT NO. 28		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-829	NO. 1 ENGINE - REPLACE HPT NO. 29 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-829	NO. 2 ENGINE - REPLACE HPT NO. 29 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-830	NO. 1 ENGINE - REPLACE HPT NO. 30 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-830	NO. 2 ENGINE - REPLACE HPT NO. 30 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-831	NO. 1 ENGINE - REPLACE HPT NO. 31 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-831	NO. 2 ENGINE - REPLACE HPT NO. 31		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-832	NO. 1 ENGINE - REPLACE HPT NO. 32		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-832	NO. 2 ENGINE - REPLACE HPT NO. 32		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-833	NO. 1 ENGINE - REPLACE HPT NO. 33		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-833	NO. 2 ENGINE - REPLACE HPT NO. 33		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-834	NO. 1 ENGINE - REPLACE HPT NO. 34 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-834	NO. 2 ENGINE - REPLACE HPT NO. 34 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-835	NO. 1 ENGINE - REPLACE HPT NO. 35 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-835	NO. 2 ENGINE - REPLACE HPT NO. 35 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-836	NO. 1 ENGINE - REPLACE HPT NO. 36 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-836	NO. 2 ENGINE - REPLACE HPT NO. 36 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-837	NO. 1 ENGINE - REPLACE HPT NO. 37 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-837	NO. 2 ENGINE - REPLACE HPT NO. 37 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-838	NO. 1 ENGINE - REPLACE HPT NO. 38 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-838	NO. 2 ENGINE - REPLACE HPT NO. 38 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-839	NO. 1 ENGINE - REPLACE HPT NO. 39 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-839	NO. 2 ENGINE - REPLACE HPT NO. 39 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-840	NO. 1 ENGINE - REPLACE HPT NO. 40 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-840	NO. 2 ENGINE - REPLACE HPT NO. 40 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-841	NO. 1 ENGINE - REPLACE HPT NO.41 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-841	NO. 2 ENGINE - REPLACE HPT NO.41			BLADE				Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-842	NO. 1 ENGINE - REPLACE HPT NO. 42			BLADE				Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-842	NO. 2 ENGINE - REPLACE HPT NO. 42			BLADE				Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-843	NO. 1 ENGINE - REPLACE HPT NO. 43			BLADE				Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-843	NO. 2 ENGINE - REPLACE HPT NO. 43			BLADE				Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-844	NO. 1 ENGINE - REPLACE HPT NO. 44 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-844	NO. 2 ENGINE - REPLACE HPT NO. 44 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-845	NO. 1 ENGINE - REPLACE HPT NO. 45 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-845	NO. 2 ENGINE - REPLACE HPT NO. 45 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-846	NO. 1 ENGINE - REPLACE HPT NO. 46 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-846	NO. 2 ENGINE - REPLACE HPT NO. 46 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-847	NO. 1 ENGINE - REPLACE HPT NO.47 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-847	NO. 2 ENGINE - REPLACE HPT NO.47 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-848	NO. 1 ENGINE - REPLACE HPT NO. 48 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-848	NO. 2 ENGINE - REPLACE HPT NO. 48 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-849	NO. 1 ENGINE - REPLACE HPT NO. 49		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-849	NO. 2 ENGINE - REPLACE HPT NO. 49		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-850	NO. 1 ENGINE - REPLACE HPT NO. 50		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-850	NO. 2 ENGINE - REPLACE HPT NO. 50		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-851	NO. 1 ENGINE - REPLACE HPT NO. 51		BLADE					Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-851	NO. 2 ENGINE - REPLACE HPT NO. 51 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-852	NO. 1 ENGINE - REPLACE HPT NO. 52 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-852	NO. 2 ENGINE - REPLACE HPT NO. 52 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-00-280-853	NO. 1 ENGINE - REPLACE HPT NO. 53 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-853	NO. 2 ENGINE - REPLACE HPT NO. 53 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-00-280-854	NO. 1 ENGINE - REPLACE HPT NO. 54 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2560.5 * (M)		845.4	
	ENC			TAC 0				
72-51-00-280-854	NO. 2 ENGINE - REPLACE HPT NO. 54 BLADE							Service ATA:72
	MOS	EFF		TAC 0				
	HRS	EFF	2500	TAC 0	(2500) 2500 * (M)		784.9	
	ENC			TAC 0				
72-51-02-210-801	NO. 1 ENGINE - VISUAL INSPECTION HIGH PRESSURE TURBINE SHAFT PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-02PROC. REF: OHM 72-51-02								
72-51-02-210-801	NO. 2 ENGINE - VISUAL INSPECTION HIGH PRESSURE TURBINE SHAFT PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-02PROC. REF: OHM 72-51-02								
72-51-02-240-801	NO. 1 ENGINE - MAGNETIC PARTICLE INSPECT HIGH PRESSURE TURBINE SHAFT PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-02PROC. REF: OHM 72-51-02								
72-51-02-240-801	NO. 2 ENGINE - MAGNETIC PARTICLE INSPECT HIGH PRESSURE TURBINE SHAFT PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: OHM 72-51-02PROC. REF: OHM 72-51-02								
72-51-02-900-801	NO. 1 ENGINE - HIGH PRESSURE SHAFT							Component ATA:72
PN:17721-Q0A-0000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:FHTJ0273	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15053		13492	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-02-900-801	NO. 2 ENGINE - HIGH PRESSURE SHAFT							Component ATA:72
PN:17721-Q0A-0000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:FHTJ0275	HRS	0		TSN 0				
	ENC	0	15000	TSN 0	(15000) 15000		13439	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-03-210-801	NO. 1 ENGINE - VISUAL INSPECTION HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								
72-51-03-210-801	NO. 2 ENGINE - VISUAL INSPECTION HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								
72-51-03-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-03-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								
72-51-03-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								
72-51-03-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								
72-51-03-250-801	NO. 1 ENGINE - EDDY CURRENT INSPECTION HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE (ECI OF THE BORE)							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								
72-51-03-250-801	NO. 2 ENGINE - EDDY CURRENT INSPECTION HIGH PRESSURE CENTRIFUGAL COMPRESSOR IMPELLER PIECE-PART EXPOSURE (ECI OF THE BORE)							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-03PROC. REF: OHM 72-51-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-03-900-801	NO. 1 ENGINE - HIGH PRESSURE CENTRIFUGAL COMPRESSOR ROTOR IMPELLER							Component ATA:72
PN:17511-Q0A-0200	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS2982	HRS	0		TSN 0				
	ENC	0	11900	TSN 0	(11900) 11953		10392	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-03-900-801	NO. 2 ENGINE - HIGH PRESSURE CENTRIFUGAL COMPRESSOR ROTOR IMPELLER							Component ATA:72
PN:17511-Q0A-0200	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:ACIS3238	HRS	0		TSN 0				
	ENC	0	11900	TSN 0	(11900) 11900		10339	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-04-210-801	NO. 1 ENGINE - VISUAL INSPECTION STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-210-801	NO. 2 ENGINE - VISUAL INSPECTION STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-250-801	NO. 1 ENGINE - EDDY CURRENT INSPECTION STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE (ECI OF THE BORE)							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-250-801	NO. 2 ENGINE - EDDY CURRENT INSPECTION STAGE 1 HIGH PRESSURE TURBINE DISK PIECE-PART EXPOSURE (ECI OF THE BORE)							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-04PROC. REF: OHM 72-51-04								
72-51-04-900-801	NO. 1 ENGINE - STAGE 1 HIGH PRESSURE TURBINE DISK							Component ATA:72
PN:2514M29P01	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:TMT3AT48	HRS	0		TSN 0				
	ENC	0	9200	TSN 0	(9200) 9253		7692	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-04-900-801	NO. 2 ENGINE - STAGE 1 HIGH PRESSURE TURBINE DISK							Component ATA:72
PN:2514M29P01	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:TMT3AT32	HRS	0		TSN 0				
	ENC	0	9200	TSN 0	(9200) 9200		7639	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-05-210-801	NO. 1 ENGINE - VISUAL INSPECTION THRUST PISTON DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-05PROC. REF: OHM 72-51-05								
72-51-05-210-801	NO. 2 ENGINE - VISUAL INSPECTION THRUST PISTON DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-05PROC. REF: OHM 72-51-05								
72-51-05-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK THRUST PISTON DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-05PROC. REF: OHM 72-51-05								
72-51-05-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK THRUST PISTON DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-05PROC. REF: OHM 72-51-05								
72-51-05-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION THRUST PISTON DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-05PROC. REF: OHM 72-51-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-05-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION THRUST PISTON DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-05PROC. REF: OHM 72-51-05								
72-51-05-900-801	NO. 1 ENGINE - THRUST PISTON DISK							Component ATA:72
PN:17811-Q0A-0500	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:APV9656F	HRS	0		TSN 0				
	ENC	0	7400	TSN 0	(7400) 7453		5892	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-05-900-801	NO. 2 ENGINE - THRUST PISTON DISK							Component ATA:72
PN:17811-Q0A-0500	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:APV9657F	HRS	0		TSN 0				
	ENC	0	7400	TSN 0	(7400) 7400		5839	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-11-210-801	NO. 1 ENGINE - VISUAL INSPECTION AFT TURBINE RETAINER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-11PROC. REF: OHM 72-51-11								
72-51-11-210-801	NO. 2 ENGINE - VISUAL INSPECTION AFT TURBINE RETAINER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-11PROC. REF: OHM 72-51-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-51-11-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK AFT TURBINE RETAINER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-11PROC. REF: OHM 72-51-11								
72-51-11-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK AFT TURBINE RETAINER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-11PROC. REF: OHM 72-51-11								
72-51-11-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION AFT TURBINE RETAINER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-11PROC. REF: OHM 72-51-11								
72-51-11-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION AFT TURBINE RETAINER PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-51-11PROC. REF: OHM 72-51-11								
72-51-11-900-801	NO. 1 ENGINE - AFT TURBINE RETAINER							Component ATA:72
PN:18741-Q0A-0200	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:TMT1AM21	HRS	0		TSN 0				
	ENC	0	11600	TSN 0	(11600) 11653		10092	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-51-11-900-801	NO. 2 ENGINE - AFT TURBINE RETAINER							Component ATA:72
PN:18741-Q0A-0200	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:TMT1AM24	HRS	0		TSN 0				
	ENC	0	11600	TSN 0	(11600) 11600		10039	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-53-03-210-801	NO. 1 ENGINE - VISUAL INSPECTION LOW PRESSURE TURBINE SUPPORT DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-03PROC. REF: OHM 72-53-03								
72-53-03-210-801	NO. 2 ENGINE - VISUAL INSPECTION LOW PRESSURE TURBINE SUPPORT DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-03PROC. REF: OHM 72-53-03								
72-53-03-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK LOW PRESSURE TURBINE SUPPORT DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-03PROC. REF: OHM 72-53-03								
72-53-03-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK LOW PRESSURE TURBINE SUPPORT DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-03PROC. REF: OHM 72-53-03								
72-53-03-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION LOW PRESSURE TURBINE SUPPORT DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-03PROC. REF: OHM 72-53-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-53-03-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION LOW PRESSURE TURBINE SUPPORT DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-03PROC. REF: OHM 72-53-03								
72-53-03-900-801	NO. 1 ENGINE - LOW PRESSURE TURBINE SUPPORT DISK							Component ATA:72
PN:16310-Q0A-A000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:TMT1KT48	HRS	0		TSN 0				
	ENC	0	7300	TSN 0	(7300) 7353		5792	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-53-03-900-801	NO. 2 ENGINE - LOW PRESSURE TURBINE SUPPORT DISK							Component ATA:72
PN:16310-Q0A-A000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:TMT1KT96	HRS	0		TSN 0				
	ENC	0	7300	TSN 0	(7300) 7300		5739	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-53-04-210-801	NO. 1 ENGINE - VISUAL INSPECTION STAGE 2 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-04PROC. REF: OHM 72-53-04								
72-53-04-210-801	NO. 2 ENGINE - VISUAL INSPECTION STAGE 2 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-04PROC. REF: OHM 72-53-04								
72-53-04-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK STAGE 2 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: OHM 72-53-04PROC. REF: OHM 72-53-04								
72-53-04-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK STAGE 2 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-04PROC. REF: OHM 72-53-04								
72-53-04-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 2 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-04PROC. REF: OHM 72-53-04								
72-53-04-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 2 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-04PROC. REF: OHM 72-53-04								
72-53-04-900-801	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISK							Component ATA:72
PN:16231-Q0A-0100	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:TM1RG07	HRS	0		TSN 0				
	ENC	0	10200	TSN 0	(10200) 10253		8692	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-53-04-900-801	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISK							Component ATA:72
PN:16231-Q0A-0100	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:BBCD0481	HRS	0		TSN 0				
	ENC	0	10200	TSN 0	(10200) 10200		8639	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-53-07-210-801	NO. 1 ENGINE - VISUAL INSPECTION STAGE 1 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-07PROC. REF: OHM 72-53-07								
72-53-07-210-801	NO. 2 ENGINE - VISUAL INSPECTION STAGE 1 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-07PROC. REF: OHM 72-53-07								
72-53-07-220-801	NO. 1 ENGINE - DIMENSIONAL CHECK STAGE 1 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-07PROC. REF: OHM 72-53-07								
72-53-07-220-801	NO. 2 ENGINE - DIMENSIONAL CHECK STAGE 1 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-07PROC. REF: OHM 72-53-07								
72-53-07-230-801	NO. 1 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 1 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-07PROC. REF: OHM 72-53-07								
72-53-07-230-801	NO. 2 ENGINE - FLUORESCENT PENETRANT INSPECTION STAGE 1 LOW PRESSURE TURBINE DISK PIECE-PART EXPOSURE							Service ATA:72
	MOS/MSC	26-May-17	A/R	TAC 0				MANDATORY
	HRS	0		TAC 0				
	ENC	0		TAC 0				
PROC. REF: OHM 72-53-07PROC. REF: OHM 72-53-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-53-07-900-801	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISK ASSEMBLY							Component ATA:72
PN:16130-Q0A-0000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:BBCD0487	HRS	0		TSN 0				
	ENC	0	10400	TSN 0	(10400) 10453		8892	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-53-07-900-801	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISK ASSEMBLY							Component ATA:72
PN:16130-Q0A-0000	MOS	26-May-17		TSN 0				LIFE LIMIT
SN:BBCD0495	HRS	0		TSN 0				
	ENC	0	10400	TSN 0	(10400) 10400		8839	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72HA0500101 ^S	DO A VISUAL INSPECTION OF THE NACELLE / COWLING AREA, SKINS, DOORS, LATCHES AND FASTENERS.							Service ATA:72
	MOS	02-Jun-23						
	HRS	1161.9	1200 (+60/-60)					
	AFL	1084						
								PKG:6 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
72HA0500102 ^S	DO A VISUAL INSPECTION OF THE ENGINE INLET AND INLET LIP, LINER, AND LINER DRAINS. (EFFECTIVITY: 42000011, 42000126 AND AFTER)							Service ATA:72
	MOS/MSC	23-Jun-17	N/A	TAC 0				
	HRS	0		TAC 0				
	AFL	0		TAC 0				
								PKG:1 WO#: FAMQ0152
PROC. REF: ALIM INTROPROC. REF: ALIM INTRO								
72HAGHAEA	REVIEW AND DO THE ENGINE MAINTENANCE PROGRAM.							Service ATA:72
	MOS/MSC	23-Jun-17	A/R	TAC 0				
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-00-00-200-801	NO. 1 ENGINE - DETAILED INSPECTION MECHANICAL FUEL SHUTOFF SYSTEM (MFSS)							Service ATA:73
	MOS	05-May-25						MANDATORY
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152
73-00-00-200-801	NO. 2 ENGINE - DETAILED INSPECTION MECHANICAL FUEL SHUTOFF SYSTEM (MFSS)							Service ATA:73
	MOS	05-May-25						MANDATORY
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
								WO#: FAMQ0152
73-00-00-440-802	NO. 1 ENGINE - OVERHAUL/REPLACE THE FUEL PUMP METERING UNIT (FPMU)							Service ATA:73
	MOS	EFF		TAC 0				OVERHAUL
	HRS	EFF	2500	TAC 0	(2500) 2560.5 *		845.4	
	ENC			TAC 0				
73-00-00-440-802	NO. 2 ENGINE - OVERHAUL/REPLACE THE FUEL PUMP METERING UNIT (FPMU)							Service ATA:73
	MOS	EFF		TAC 0				OVERHAUL
	HRS	EFF	2500	TAC 0	(2500) 2500 *		784.9	
	ENC			TAC 0				
73-00-00-610-801	NO. 1 ENGINE - REPLACE FUEL FILTER							Service ATA:73
	MOS	05-May-25						
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-00-00-610-801	NO. 2 ENGINE - REPLACE FUEL FILTER							Service ATA:73
	MOS	05-May-25						
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
								WO#: FAMQ0152
73-21-01-900-801	NO. 1 ENGINE - FPMU ASSEMBLY							Component ATA:73
PN:24100-Q0A-F000	MOS/MSC	09-Apr-22	O/C	TSR 0				
SN:CGW0205J	HRS	569.3		TSR 0				
	ENC	567		TSR 0				
73-21-01-900-801	NO. 2 ENGINE - FPMU ASSEMBLY							Component ATA:73
PN:24100-Q0A-F000	MOS/MSC	09-Apr-22	O/C	TSR 0				
SN:CGW0204J	HRS	569.3		TSR 0				
	ENC	567		TSR 0				
ATA 74 - IGNITION								
74-00-00-440-801	NO. 1 ENGINE - REPLACE 4 OCLOCK IGNITER PLUG							Service ATA:74
PN:31111-Q0A-0000	MOS	05-May-25						
SN:UNLTW940	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152
74-00-00-440-801	NO. 1 ENGINE - REPLACE 8 OCLOCK IGNITER PLUG							Service ATA:74
PN:31111-Q0A-0000	MOS	05-May-25						
SN:UNLTW941	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-00-00-440-801	NO. 2 ENGINE - REPLACE 4 OCLOCK IGNITER PLUG							Service ATA:74
PN:31111-Q0A-0000	MOS	05-May-25						
SN:UNLTW939	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
WO#: FAMQ0152								
74-00-00-440-801	NO. 2 ENGINE - REPLACE 8 OCLOCK IGNITER PLUG							Service ATA:74
PN:31111-Q0A-0000	MOS	05-May-25						
SN:UNLTW942	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
WO#: FAMQ0152								
74-00-40-900-801	NO. 1 ENGINE - 8 OCLOCK IGNITER PLUG							Component ATA:74
PN:31111-Q0A-0000	MOS/MSC	02-Jun-23	O/C	TSN 2				
SN:UNLTW941	HRS	1161.9		TSN 0				
	ENC	1084		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
74-00-40-900-801	NO. 2 ENGINE - 8 OCLOCK IGNITER PLUG							Component ATA:74
PN:31111-Q0A-0000	MOS/MSC	02-Jun-23	O/C	TSN 2				
SN:UNLTW942	HRS	1161.9		TSN 0				
	ENC	1084		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
74-00-70-900-801	NO. 1 ENGINE - 4 OCLOCK IGNITER PLUG							Component ATA:74
PN:31111-Q0A-0000	MOS/MSC	02-Jun-23	O/C	TSN 2				
SN:UNLTW940	HRS	1161.9		TSN 0				
	ENC	1084		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-00-70-900-801	NO. 2 ENGINE - 4 OCLOCK IGNITER PLUG							Component ATA:74
PN:31111-Q0A-0000	MOS/MSC	02-Jun-23	O/C	TSN 2				
SN:UNLW939	HRS	1161.9		TSN 0				
	ENC	1084		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

ATA 76 - ENGINE CONTROLS

76CA7600001	THROTTLE QUADRANT ASSEMBLY (TQA) W SPEED							Component ATA:76
PN:HJ1-17600-101-007	MOS/MSC	23-Jun-17	O/C	TSN 0				
SN:88	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-12-10, AMM 76-12-10PROC. REF: AMM 76-12-10, AMM 76-12-10								

ATA 77 - ENGINE INDICATING

77-00-00-750-801	NO. 1 ENGINE - TEST ENGINE VIBRATION DETECTION SYSTEM							Service ATA:77
	MOS	05-May-25						
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
WO#: FAMQ0152								

77-00-00-750-801	NO. 2 ENGINE - TEST ENGINE VIBRATION DETECTION SYSTEM							Service ATA:77
	MOS	05-May-25						
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
WO#: FAMQ0152								

ATA 79 - OIL

79-00-00-200-801	NO. 1 ENGINE - DETAILED INSPECTION CHIP DETECTOR							Service ATA:79
	MOS	05-May-25						
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
WO#: FAMQ0152								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-00-00-200-801	NO. 2 ENGINE - DETAILED INSPECTION CHIP DETECTOR							Service ATA:79
	MOS	05-May-25						
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
WO#: FAMQ0152								
79-00-00-610-801	NO. 1 ENGINE - CHECK OIL LEVEL							Service ATA:79
	MOS/MSC	26-May-17	BF/F	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
79-00-00-610-801	NO. 2 ENGINE - CHECK OIL LEVEL							Service ATA:79
	MOS/MSC	26-May-17	BF/F	TAC 0				
	HRS	0		TAC 0				
	ENC	0		TAC 0				
79-00-00-610-802	NO. 1 ENGINE - REPLACE ENGINE OIL							Service ATA:79
	MOS	05-May-25						
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
WO#: FAMQ0152								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
79-00-00-610-802	NO. 2 ENGINE - REPLACE ENGINE OIL							Service ATA:79
	MOS	05-May-25						
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
WO#: FAMQ0152								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: HONDAJET HA-420 Serial: 42000063 RegNo: N829DL HRS: 1715.1 AFL: 1561 As Of: 23-Sep-2025

10-Dec-2025 07:40 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-00-00-610-803	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER							Service ATA:79
	MOS	05-May-25						
	HRS	1611.1	600		(2211.1) 2271.6		556.5	
	ENC	1470						
								WO#: FAMQ0152
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
79-00-00-610-803	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER							Service ATA:79
	MOS	05-May-25						
	HRS	1671.6	600		(2271.6) 2271.6		556.5	
	ENC	1523						
								WO#: FAMQ0152
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								