



Status Report

LEARJET 60XR

S/N 60 410 N824LM

OWNER: CROWN AIRWAYS, LLC
ADDRESS: 9431 FOSTER WHEELER ROAD
DANSVILLE NY 14437

OPERATOR: INTEGRA JET, LLC
ADDRESS: 9431 FOSTER WHEELER ROAD
DANSVILLE NY 14437

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: PATRICK VITAMVAS
EMAIL: PVITAMVAS@CAMPSYSTEMS.COM

+1-316-462-2484 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL/REGNO: 60 410/N824LM	MODEL: LEARJET 60XR	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 01-MAR-2012		LAST ACTUALS: 3223.9 A/C HRS as of 01-MAY-2025 2319 AFL as of 01-MAY-2025 1276 APH as of 02-MAY-2025 845.4 ACH as of 28-JAN-2019	
APU	SERIAL/PART: SP-E100536/4503134	MODEL: T-20G-10C3A (CIMMS)	MANUFACTURER: HAMILTON SUNDSTRAND CORPORATION
INSTALLED ON: 04-JUN-2024 1219 APU HRS 0 A/C HRS 2696 APUS		LAST ACTUALS: 1276 APU HRS as of 02-MAY-2025 2778 APUS as of 02-MAY-2025	
ENGINE NO. 1	SERIAL/PART: PCE-CA0682/31B4067-04	MODEL: PW305A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 28-MAR-2019 2762.6 ENG. HRS 2762.6 A/C HRS 1914 ENC		LAST ACTUALS: 3223.9 ENG. HRS as of 01-MAY-2025 2319 ENC as of 01-MAY-2025	
ENGINE NO. 2	SERIAL/PART: PCE-CA0681/31B4067-04	MODEL: PW305A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 28-MAR-2019 2762.6 ENG. HRS 2762.6 A/C HRS 1914 ENC		LAST ACTUALS: 3223.9 ENG. HRS as of 01-MAY-2025 2319 ENC as of 01-MAY-2025	



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
CI60-161006	REVIEW LEARJET 60 AMM REVISION A15							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI60PROC. REF: RCF CI60								
CI60-161011	REVIEW LEARJET 60 EINSPECTOR REVISION 2016.10.11							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI60PROC. REF: RCF CI60								
EC24-160516	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-160516	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-170116	NO. 1 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EC24-170116	NO. 2 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-180214	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-180214	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
REG-00-00-01 ^U	RENEW AIRCRAFT REGISTRATION							Service ATA:00
	MOS	25-Sep-23	36		31-Dec-27 (M)		955 d	
	HRS							
	AFL							
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-A1	PHASE A1-300 HOUR							Package ATA:05
	MOS	04-Apr-25	12 (+14d/-14d)	Adj -12d	23-Mar-26	06-Apr-26	307 d (+14)	
	HRS	3222.8	300 (+25/-25)		3522.8	3547.8	298.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-01PROC. REF: AMM 5-10-01								
PKG:1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-02-A2	PHASE A2-300 HOUR							Package ATA:05
	MOS	04-Apr-25	12 (+14d/-14d)	Adj -12d	23-Mar-26	06-Apr-26	307 d (+14)	
	HRS	3222.8	300 (+25/-25)		3522.8	3547.8	298.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-02PROC. REF: AMM 5-10-02								PKG:2
05-10-03-A3	PHASE A3-300 HOUR							Package ATA:05
	MOS	04-Apr-25	12 (+14d/-14d)	Adj -12d	23-Mar-26	06-Apr-26	307 d (+14)	
	HRS	3222.8	300 (+25/-25)		3522.8	3547.8	298.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-03PROC. REF: AMM 5-10-03								PKG:3
05-10-04-A4	PHASE A4-300 HOUR							Package ATA:05
	MOS	04-Apr-25	12 (+14d/-14d)	Adj -12d	23-Mar-26	06-Apr-26	307 d (+14)	
	HRS	3222.8	300 (+25/-25)		3522.8	3547.8	298.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-04PROC. REF: AMM 5-10-04								PKG:4
05-10-05-A5	PHASE A5-300 HOUR							Package ATA:05
	MOS	04-Apr-25	12 (+14d/-14d)	Adj -12d	23-Mar-26	06-Apr-26	307 d (+14)	
	HRS	3222.8	300 (+25/-25)		3522.8	3547.8	298.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-05PROC. REF: AMM 5-10-05								PKG:5
05-10-06-A6	PHASE A6-300 HOUR							Package ATA:05
	MOS	04-Apr-25	12 (+14d/-14d)	Adj -12d	23-Mar-26	06-Apr-26	307 d (+14)	
	HRS	3222.8	300 (+25/-25)		3522.8	3547.8	298.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-06PROC. REF: AMM 5-10-06								PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-07-B1	PHASE B1-600 HOUR							Package ATA:05
	MOS	04-Apr-25	24 (+14d/-14d)	Adj -29d	06-Mar-27	20-Mar-27	655 d (+14)	
	HRS	3222.8	600 (+25/-25)		3822.8	3847.8	598.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-07PROC. REF: AMM 5-10-07								PKG:7
05-10-08-B2	PHASE B2-600 HOUR							Package ATA:05
	MOS	04-Apr-25	24 (+14d/-14d)	Adj -29d	06-Mar-27	20-Mar-27	655 d (+14)	
	HRS	3222.8	600 (+25/-25)		3822.8	3847.8	598.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-08PROC. REF: AMM 5-10-08								PKG:8
05-10-09-B3	PHASE B3-600 HOUR							Package ATA:05
	MOS	04-Apr-25	24 (+14d/-14d)	Adj -29d	06-Mar-27	20-Mar-27	655 d (+14)	
	HRS	3222.8	600 (+25/-25)		3822.8	3847.8	598.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-09PROC. REF: AMM 5-10-09								PKG:9
05-10-10-B4	PHASE B4-600 HOUR							Package ATA:05
	MOS	04-Apr-25	24 (+14d/-14d)	Adj -29d	06-Mar-27	20-Mar-27	655 d (+14)	
	HRS	3222.8	600 (+25/-25)		3822.8	3847.8	598.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-10PROC. REF: AMM 5-10-10								PKG:10
05-10-11-B5	PHASE B5-600 HOUR							Package ATA:05
	MOS	04-Apr-25	24 (+14d/-14d)	Adj -29d	06-Mar-27	20-Mar-27	655 d (+14)	
	HRS	3222.8	600 (+25/-25)		3822.8	3847.8	598.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-11PROC. REF: AMM 5-10-11								PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-12-B6	PHASE B6-600 HOUR							Package ATA:05
	MOS	04-Apr-25	24 (+14d/-14d)	Adj -29d	06-Mar-27	20-Mar-27	655 d (+14)	
	HRS	3222.8	600 (+25/-25)		3822.8	3847.8	598.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-12PROC. REF: AMM 5-10-12								PKG:12
05-10-13-C1	PHASE C1-1200 HOUR							Package ATA:05
	MOS	04-Apr-25	48 (+14d/-14d)	Adj -29d	06-Mar-29	20-Mar-29	1386 d (+14)	
	HRS	3222.8	1200 (+25/-25)		4422.8	4447.8	1198.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-13PROC. REF: AMM 5-10-13								PKG:13
05-10-14-C2	PHASE C2-1200 HOUR							Package ATA:05
	MOS	04-Apr-25	48 (+14d/-14d)	Adj -29d	06-Mar-29	20-Mar-29	1386 d (+14)	
	HRS	3222.8	1200 (+25/-25)		4422.8	4447.8	1198.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-14PROC. REF: AMM 5-10-14								PKG:14
05-10-15-C3	PHASE C3-1200 HOUR							Package ATA:05
	MOS	04-Apr-25	48 (+14d/-14d)	Adj -29d	06-Mar-29	20-Mar-29	1386 d (+14)	
	HRS	3222.8	1200 (+25/-25)		4422.8	4447.8	1198.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-15PROC. REF: AMM 5-10-15								PKG:15
05-10-16-C4	PHASE C4-1200 HOUR							Package ATA:05
	MOS	04-Apr-25	48 (+14d/-14d)	Adj -29d	06-Mar-29	20-Mar-29	1386 d (+14)	
	HRS	3222.8	1200 (+25/-25)		4422.8	4447.8	1198.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-16PROC. REF: AMM 5-10-16								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-17-C5	PHASE C5-1200 HOUR							Package ATA:05
	MOS	04-Apr-25	48 (+14d/-14d)	Adj -29d	06-Mar-29	20-Mar-29	1386 d (+14)	
	HRS	3222.8	1200 (+25/-25)		4422.8	4447.8	1198.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-17PROC. REF: AMM 5-10-17								PKG:17
05-10-18-C6	PHASE C6-1200 HOUR							Package ATA:05
	MOS	04-Apr-25	48 (+14d/-14d)	Adj -29d	06-Mar-29	20-Mar-29	1386 d (+14)	
	HRS	3222.8	1200 (+25/-25)		4422.8	4447.8	1198.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-18PROC. REF: AMM 5-10-18								PKG:18
05-10-19-D1	PHASE D1-2400 HOUR							Package ATA:05
	MOS	04-Apr-25	96 (+14d/-14d)	Adj -29d	06-Mar-33	20-Mar-33	2847 d (+14)	
	HRS	3222.8	2400 (+25/-25)		5622.8	5647.8	2398.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-19PROC. REF: AMM 5-10-19								PKG:19
05-10-20-D2	PHASE D2-2400 HOUR							Package ATA:05
	MOS	04-Apr-25	96 (+14d/-14d)	Adj -29d	06-Mar-33	20-Mar-33	2847 d (+14)	
	HRS	3222.8	2400 (+25/-25)		5622.8	5647.8	2398.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-20PROC. REF: AMM 5-10-20								PKG:20
05-10-21-D3	PHASE D3-2400 HOUR							Package ATA:05
	MOS	04-Apr-25	96 (+14d/-14d)	Adj -29d	06-Mar-33	20-Mar-33	2847 d (+14)	
	HRS	3222.8	2400 (+25/-25)		5622.8	5647.8	2398.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-21PROC. REF: AMM 5-10-21								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-22-D4	PHASE D4-2400 HOUR							Package ATA:05
	MOS	04-Apr-25	96 (+14d/-14d)	Adj -29d	06-Mar-33	20-Mar-33	2847 d (+14)	
	HRS	3222.8	2400 (+25/-25)		5622.8	5647.8	2398.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-22PROC. REF: AMM 5-10-22								PKG:22
05-10-23-D5	PHASE D5-2400 HOUR							Package ATA:05
	MOS	04-Apr-25	96 (+14d/-14d)	Adj -29d	06-Mar-33	20-Mar-33	2847 d (+14)	
	HRS	3222.8	2400 (+25/-25)		5622.8	5647.8	2398.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-23PROC. REF: AMM 5-10-23								PKG:23
05-10-24-D6	PHASE D6 2400 HOUR							Package ATA:05
	MOS	04-Apr-25	96 (+14d/-14d)	Adj -29d	06-Mar-33	20-Mar-33	2847 d (+14)	
	HRS	3222.8	2400 (+25/-25)		5622.8	5647.8	2398.9 (+25)	
	AFL	2317						
PROC. REF: AMM 5-10-24PROC. REF: AMM 5-10-24								PKG:24
05-10-25-3000 LDG	3000 LANDING							Package ATA:05
	MOS	01-Mar-12						
	HRS	0						
	AFL	0	3000 (+25/-25)		3000	3025	681 (+25)	
PROC. REF: AMM 5-10-25PROC. REF: AMM 5-10-25								PKG:25
05-10-26-6000 LDG	MAJOR LANDING GEAR							Package ATA:05
	MOS	01-Mar-12						
	HRS	0						
	AFL	0	6000 (+25/-25)		6000	6025	3681 (+25)	
PROC. REF: AMM 5-10-26PROC. REF: AMM 5-10-26								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-27-12 YR	12 YEAR AIRFRAME							Package ATA:05
	MOS	16-Apr-24	144 (+14d/-14d)	Adj -46d	01-Mar-36	15-Mar-36	3938 d (+14)	
	HRS	3150						
	AFL	2264	6000 (+25/-25)		8264	8289	5945 (+25)	
PROC. REF: AMM 05-10-27, AMM 5-10-27PROC. REF: AMM 05-10-27, AMM 5-10-27								PKG:27
05-10-28-12000 HR	12000 HOUR AIRFRAME							Package ATA:05
	MOS	01-Mar-12						
	HRS	0	T:12000 (+25/-25)		12000	12025	8776.1 (+25)	
	AFL	0						
PROC. REF: AMM 5-10-28PROC. REF: AMM 5-10-28								PKG:28
05-50-02	PERFORM HARD LANDING OR DEPARTURE FROM RUNWAY MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-03	PERFORM OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT) MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	15-Feb-24	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	3131.2						
	AFL	2250						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-04	PERFORM SEVERE TURBULENCE AND/OR MANEUVERS MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-05 ^S	PERFORM NO. 1 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								PKG:29
05-50-05 ^S	PERFORM NO. 2 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								PKG:30
05-50-06	PERFORM HIGH ENERGY STOP (LANDING AND REJECTED TAKEOFF) MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-07	PERFORM PERFORM THRUST REVERSER INSPECTION FOR SLAM-STOW OR HIGH THRUST EMERGENCY STOW OPERATION (REFER TO 78-40-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-08	PERFORM OVERSPEED RECOVERY LANDING GEAR INSPECTION (LANDING GEAR EXTENSION AND RETRACTION AT HIGH SPEED) (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-09	PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-10	PERFORM HIGH GROUND WIND GUST INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-11	PERFORM HEAT DAMAGE INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-12	PERFORM PRESSURE CABIN SKIN THICKNESS MEASUREMENTS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-13	PERFORM FLAP INSPECTION AFTER CONTAMINATED RUNWAY TAKEOFF OR LANDING (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-14	PERFORM VOLCANIC ASH INSPECTION AND MAINTENANCE PROCEDURES (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-15	MAINTENANCE PROCEDURES ON AIRCRAFT EXTERIOR SURFACE WITHIN SALT INFLUENCED ENVIRONMENTS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-16	PERFORM FLAP OVERSPEED INSPECTION AND REPAIR (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	01-Mar-12	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-17	PERFORM FOREIGN OBJECT DAMAGE INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
	AFL							
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-PATS-490001	APU - INSPECT APU PER MANUFACTURERS INSTRUCTIONS							Service ATA:05
	MOS	04-Apr-25						
	HRS	1276	200		1476		200	
	APUS	2776						
PROC. REF: SMM 49-11-03PROC. REF: SMM 49-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-PATS-490002	APU - ANNUAL INSPECTION OF APU MOUNTS FOR LOOSENESS & DAMAGE							Service ATA:05
	MOS	04-Apr-25	12		04-Apr-26		319 d	
	HRS	1276						
	APUS	2776						
PROC. REF: SMM 49-11-03PROC. REF: SMM 49-11-03								
05-PATS-490005	VISUALLY INSPECT ALL MOUNT PARTS AND FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE							Service ATA:05
	MOS	28-May-21						
	HRS	2876	3000		5876		2652.1	
	AFL	2014						
	APH	1079	3000		4079		2803	
PROC. REF: GENERIC NO REF, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-11-03								
05-PATS-490006	PERFORM EXHAUST & INLET DOUBLER FRAMES & STRINGERS							Service ATA:05
	MOS	01-Mar-12						
	HRS	0	10000		10000		6776.1	
	AFL	0						
PROC. REF: GENERIC NO REF, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-11-03								
05-PATS-490007	APU - DRAIN EPA SUMP							Service ATA:05
	MOS/MSC	22-Nov-17	O/C					
	HRS	846						
	APUS	1806						
05-T20G-490001	APU - PERFORM OIL LEVEL CHECK							Service ATA:05
	MOS	02-May-25	1		02-Jun-25		13 d	
	HRS	1276						
	APUS	2778						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-490002	APU - CHECK EXTERNAL FUEL AND OIL LEAKAGE, AIR INLET AND EXHAUST DUCTS FOR OBSTRUCTION AND ATTACHING BOLTS AND SCREWS FOR ATTACHMENT AND SECURITY							Service ATA:05
	MOS	16-Apr-24						
	HRS	1212	500		1712		436	
	APUS							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490003	APU - PERFORM APU OIL & FILTER CHANGE							Service ATA:05
	MOS	16-Apr-24	24		16-Apr-26		331 d	
	HRS	1212	500		1712		436	
	APUS							
PROC. REF: MM 49-20-00, MM 49-20-00PROC. REF: MM 49-20-00, MM 49-20-00								
05-T20G-HS-490004	APU - VISUAL INSPECTION ENGINE HARNESS							Service ATA:05
	MOS	04-Apr-25						
	HRS	1276	500		1776		500	
	APUS	2776						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490005	APU - INSPECT IGNITER PLUG							Service ATA:05
PN:PN-UNKNOWN	MOS	04-Apr-25						
SN:UNKNOWN	HRS	1276	500		1776		500	
	APUS	2776						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490006	APU - INSPECT COMBUSTOR FUEL DRAIN LINE							Service ATA:05
	MOS	04-Apr-25						
	HRS	1276	500		1776		500	
	APUS	2776						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490007	APU - INSPECT OIL OVERFILL TUBE ASSEMBLY FOR CLEANLINESS AND OBSTRUCTIONS							Service ATA:05
	MOS	04-Apr-25						
	HRS	1276	500		1776		500	
	APUS	2776						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-T20G-HS-490010	APU - INSPECT APU HOUSING, COVERS AND BRACKETS							Service ATA:05
	MOS	04-Apr-25						
	HRS	1276	500		1776		500	
	APUS	2776						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490011	APU - REPLACE FUEL INLET FILTER							Service ATA:05
	MOS	16-Apr-24	24		16-Apr-26		331 d	
	HRS	1212	500		1712		436	
	APUS							
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
052000	NO. 1 ENGINE - MINOR INSPECTION ITEMS							Package ATA:05
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -48d	27-Feb-26	13-Mar-26	283 d (+14)	
	HRS	3150	600 (+25/-25)		(3750) 3750	3775	526.1 (+25)	
	ENC	2264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
052000	NO. 2 ENGINE - MINOR INSPECTION ITEMS							Package ATA:05
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -48d	27-Feb-26	13-Mar-26	283 d (+14)	
	HRS	3150	600 (+25/-25)		(3750) 3750	3775	526.1 (+25)	
	ENC	2264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
055002	NO. 1 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055002	NO. 2 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055003	NO. 1 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055003	NO. 2 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055004	NO. 1 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055004	NO. 2 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055005	NO. 1 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055005	NO. 2 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055008	NO. 1 ENGINE - ENGINE OPERATION IN VISIBLE, REPORTED OR SUSPECTED VOLCANIC ASH							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055008	NO. 2 ENGINE - ENGINE OPERATION IN VISIBLE, REPORTED OR SUSPECTED VOLCANIC ASH							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055009	NO. 1 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055009	NO. 2 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055010	NO. 1 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055010	NO. 2 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055011	NO. 1 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055011	NO. 2 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055012	NO. 1 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	14-Jun-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055012	NO. 2 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	29-May-11	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
ATA 08 - LEVELING AND WEIGHING								
082000	WEIGHT AND BALANCE							Service ATA:08
	MOS	16-Apr-24	36		16-Apr-27		696 d	
	HRS							
	AFL							
PROC. REF: AMM 08-20-00PROC. REF: AMM 08-20-00								
ATA 11 - PLACARDS AND MARKINGS								
11-30-00-601 ^U	GENERAL VISUAL INSPECTION OF CABIN PLACARDS							Service ATA:11
	MOS	04-Apr-25						STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
T1130001 ^S CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS. (REFER TO 11-30-00.)								Service ATA:11
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 11-30-00PROC. REF: AMM 11-30-00								
PKG:20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
121005	PERFORM NOSE AND MAIN TIRE PRESSURE CHECKS							Service ATA:12
	MOS/MSC	03-Feb-18	A/R					
	HRS	2517.1						
	AFL	1720						
PROC. REF: AMM 12-10-05PROC. REF: AMM 12-10-05								
D1221001 ^S	LUBRICATE NOSE LANDING GEAR ACTUATOR - LUBRICATE ATTACH FITTING. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PKG:5								
D1221002 ^S	LUBRICATE NOSE LANDING GEAR ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PKG:11								
D1221006 ^S	INSPECT THRUST REVERSERS - LUBRICATE IDLER LINKS AND DRIVE LINKS. (REFER TO 12-21-04)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-04PKG:3								
D1221010 ^S	LUBRICATE MAIN LANDING GEAR AFT TRUNNION PIN. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PKG:5								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
D1221011 ^S	LUBRICATE MAIN LANDING GEAR FORWARD TRUNNION PIN. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
D1221012 ^S	LUBRICATE MAIN LANDING GEAR TORQUE LINK BUSHINGS. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
D1221013 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR STRUT ATTACH POINT. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
F1221008 ^S	LUBRICATE MAIN LANDING GEAR DOOR ACTUATOR (48C48608) PISTON ROD FELT WIPER. (REFER TO 12-21-01).							Service ATA:12
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:11
G1221004 ^S	LUBRICATE NOSE LANDING GEAR DOORS HINGES. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
G1221005 ^S	LUBRICATE MAIN LANDING GEAR DOORS HINGES. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
G1221007 ^S	LUBRICATE NOSE LANDING GEAR UPLATCH ACTUATOR PISTON ROD FELT WIPERS. (REFER TO 12-21-01).							Service ATA:12
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:11
G1221019 ^S	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221020 ^S	LUBRICATE SINGLE POINT REFUELING ACCESS DOOR HINGES. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221021 ^S	LUBRICATE EMERGENCY EXIT/BAGGAGE DOOR HINGES AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
G1221023 ^S	LUBRICATE TOILET SERVICING DOOR HINGE. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221024 ^S	LUBRICATE TAILCONE EQUIPMENT DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221025 ^S	LUBRICATE TAILCONE BAGGAGE DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221029 ^S	INSPECT LOWER NACELLE - LUBRICATE HINGES. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:3
G1221030 ^S	LUBRICATE OXYGEN SERVICING ACCESS DOOR HINGE. (REFER TO 12-21-03)							Service ATA:12
	MOS	16-Apr-24	12 (+14d/-14d)					
	HRS	3150	300 (+25/-25)					
	AFL	2264						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
G1230000 ^S	INSPECT ALCOHOL ANTI-ICE TANK - CHECK FOR QUANTITY OF FLUID. (REFER TO 12-10-08)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-10-08PROC. REF: AMM 12-10-08								PKG:2
H1221003 ^S	LUBRICATE NOSE LANDING GEAR ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.)							Service ATA:12
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:17
H1221028 ^S	LUBRICATE UPPER AND LOWER ENTRY DOORS HINGES AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:12
L1221017 ^S	LUBRICATE FLAP CAM FOLLOWERS. (REFER TO 12-21-02)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:4
L1221036 ^S	LUBRICATE SPOILER ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-02).							Service ATA:12
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
M1221038 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) WING ATTACH POINTS. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
M1221040 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.)							Service ATA:12
	MOS	23-Mar-21	48 (+14d/-14d)					
	HRS	2858.6	1200 (+25/-25)					
	AFL	2000						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:17
M1221041 ^S	INSPECT THRUST REVERSERS - LUBRICATE GUIDE RODS. (REFER TO 12-21-04)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:3
P1210051 ^S	CHECK NOSE GEAR SHOCK STRUT FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-03)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03								PKG:5
P1210052 ^S	CHECK MAIN GEAR SHOCK STRUTS FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-04)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
P1210053 ^S	INSPECT EMERGENCY AIR PRESSURE GAUGE - CHECK FOR PROPER AIR PRESSURE (1800 TO 3000 PSI). (REFER TO 12-10-07)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-10-07PROC. REF: AMM 12-10-07								PKG:1
P1210054 ^S	INSPECT OXYGEN PRESSURE GAUGE - CHECK FOR PROPER INFLATION (1500 TO 1850 PSI). (REFER TO 12-10-09)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-10-09PROC. REF: AMM 12-10-09								PKG:1
P1210055 ^S	CHECK NOSE AND MAIN TIRES FOR PROPER INFLATION. (REFER TO 12-10-05)							Service ATA:12
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: AMM 12-10-05PROC. REF: AMM 12-10-05								PKG:5
P1210056 ^S	INSPECT HYDRAULIC AND THRUST REVERSER ACCUMULATORS - CHECK ACCUMULATOR PRECHARGE (850 PSI). (REFER TO 12-21-04)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-10-01PROC. REF: AMM 12-10-01								PKG:3
P1221043 ^S	LUBRICATE NOSE LANDING GEAR TRUNNION PINS. (REFER TO 12-21-01)							Service ATA:12
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
R1221039 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 2327100) PISTON ROD FELT WIPER. (REFER TO 12-21-01).							Service ATA:12
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:11
X1221045 ^S	LUBRICATE R/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184)							Service ATA:12
	MOS/MSC	16-Apr-24	N/A					
	HRS	3150						
	AFL	2264						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:2
X1221046 ^S	LUBRICATE L/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184)							Service ATA:12
	MOS/MSC	16-Apr-24	N/A					
	HRS	3150						
	AFL	2264						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:2
ATA 20 - STANDARD PRACTICES - AIRFRAME								
206100 ^U	PERFORM PRECIPITATION STATIC (P-STATIC) TEST							Service ATA:20
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
ATA 21 - AIR CONDITIONING								
05-10-29-L2150053	FUNCTION TEST REFRIGERATION SYSTEM PRESSURE SWITCH							Service ATA:21
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 21-50-05PROC. REF: AMM 21-50-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
05-10-29-U2130007		PERFORM CABIN LEAK RATE CHECK						Service ATA:21
	MOS	06-Mar-17						
	HRS	2336.1	1200 (+25/-25)		3536.1	3561.1	312.2 (+25)	
	AFL	1563						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								
212001		COCKPIT AIR CHECK VALVE						Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01								
212003		LEFT CABIN AIR CHECK VALVE						Component ATA:21
PN:60160-11	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7023	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								
212004		RIGHT CABIN AIR CHECK VALVE						Component ATA:21
PN:60160-11	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7030	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								
212005		LEFT CABIN OVERHEAD DIFFUSER						Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03								
212006		RIGHT CABIN OVERHEAD DIFFUSER						Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212008	FWD EVAPORATOR BLOWER ASSEMBLY							Component ATA:21
PN:66-0251-4	MOS/MSC	18-Jun-15	O/C	TSO 0				
SN:6602514-034	HRS	1700.9		TSO 0				
	AFL	1134		TSO 0				
PROC. REF: AMM 21-51-08PROC. REF: AMM 21-51-08								
212101	CABIN EVAPORATOR BLOWER							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01								
212104	COCKPIT EVAPORATOR BLOWER							Component ATA:21
PN:BC80H-4	MOS/MSC	26-Oct-23	O/C	TSO 0				
SN:2275AB	HRS			TSO 0				
	AFL	2221		TSO 0				
PROC. REF: AMM 21-21-04PROC. REF: AMM 21-21-04								
212105	COCKPIT BLOWER CONTROL BOX ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-05PROC. REF: AMM 21-21-05								
212155	LEFT BLEED AIR MUFFLER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212156	RIGHT BLEED AIR MUFFLER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
212201	LEFT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-01PROC. REF: AMM 21-22-01								
212202	RIGHT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-01PROC. REF: AMM 21-22-01								
212205	AVIONICS COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-02PROC. REF: AMM 21-22-02								
213001	PRIMARY OUTFLOW VALVE							Component ATA:21
PN:103780-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:70-C0256	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01								
213002	SECONDARY OUTFLOW VALVE							Component ATA:21
PN:103780-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:39-B0417	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02								
213003	CABIN AIR PRESSURE SELECTOR							Component ATA:21
PN:2119828-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:21B0425	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213004	CABIN PRESSURE CONTROLLER							Component ATA:21
PN:2119830-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:31-F0425	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04								
213005	MANUAL PRESSURE CONTROLLER							Component ATA:21
PN:4222152-1001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1443F	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-05PROC. REF: AMM 21-30-05								
213006	AIR FILTER							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06								
213008	PRESSURIZATION MODE SWITCH							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-08PROC. REF: AMM 21-30-08								
213009	EMERGENCY DEPRESSURIZATION SWITCH							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-09PROC. REF: AMM 21-30-09								
213010	CABIN PRESSURE INDICATOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-10PROC. REF: AMM 21-30-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213011	VACUUM REGULATOR							Component ATA:21
PN:131402-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1748D	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-11PROC. REF: AMM 21-30-11								
213012	VACUUM PUMP							Component ATA:21
PN:131410-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:100-1860	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-12PROC. REF: AMM 21-30-12								
213013	VACUUM CHECK VALVE							Component ATA:21
PN:130158-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:20-4746	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-13PROC. REF: AMM 21-30-13								
213101	LEFT EMERGENCY PRESSURIZATION VALVE							Component ATA:21
PN:61700-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1295	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01								
213102	RIGHT EMERGENCY PRESSURIZATION VALVE							Component ATA:21
PN:61700-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1297	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01								
213103	LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH							Component ATA:21
PN:2E37C-30	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1028	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
213104	RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH							Component ATA:21
PN:2E37C-30	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1036	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02								
213105	LEFT CONDITIONED AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03								
213106	RIGHT CONDITIONED AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03								
213107	POSITIVE VENTILATION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04								
214001	FLOW CONTROL VALVE							Component ATA:21
PN:320335-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:668	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-40-01PROC. REF: AMM 21-40-01								
214002	HEAT EXCHANGER							Component ATA:21
PN:AA 1417-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:A287	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-40-02PROC. REF: AMM 21-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
214101	COCKPIT HEATER							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-01PROC. REF: AMM 21-41-01								
214102	COCKPIT DIVERTER DOOR SOLENOID							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02								
214103	COCKPIT DIVERTER DOOR RESISTOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-03PROC. REF: AMM 21-41-03								
214104	COCKPIT DIVERTER DOOR THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-04PROC. REF: AMM 21-41-04								
214201	LEFT AUXILIARY CABIN HEATER							Component ATA:21
PN:7026-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0389	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-01PROC. REF: AMM 21-42-01								
214202	RIGHT AUXILIARY CABIN HEATER							Component ATA:21
PN:7026-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0402	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-01PROC. REF: AMM 21-42-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
214203	AUXILIARY HEAT OVERTEMPERATURE MONITOR BOX							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-02PROC. REF: AMM 21-42-02								
215001	AIR CONDITIONING COMPRESSOR							Component ATA:21
PN:JBS222-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:K52649	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-01, AMM 21-51-01PROC. REF: AMM 21-50-01, AMM 21-51-01								
215003	CONDENSER							Component ATA:21
PN:RA 1209-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7608061-1	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-03, AMM 21-51-04PROC. REF: AMM 21-50-03, AMM 21-51-04								
215004	RECEIVER/DRYER							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-04, AMM 21-51-05PROC. REF: AMM 21-50-04, AMM 21-51-05								
215006	COCKPIT EVAPORATOR							Component ATA:21
PN:66-0250-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:K52494	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-06, AMM 21-51-07PROC. REF: AMM 21-50-06, AMM 21-51-07								
215007	FREON COMPRESSOR DRIVE (R134) MOTOR							Component ATA:21
PN:ES61134-3	MOS	03-Feb-18		TSO 0				OVERHAUL
SN:076	HRS	2517.1		TSO 0				
	AFL	1720		TSO 0				
	ACH	737.7	2000 (+25/-25)	TSO 0	2737.7	2762.7	1892.3 (+25)	
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215007A	INSPECT/REPLACE FREON COMPRESSOR DRIVE (R134) MOTOR BRUSHES - 05-10-29-K2150036							Service ATA:21
PN:ES61134-3	MOS	03-Feb-18						
SN:076	HRS	2517.1						
	AFL	1720						
	ACH	737.7	1200 (+25/-25)		1937.7	1962.7	1092.3 (+25)	
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02								
215008	COCKPIT EVAPORATOR PRESSURE REGULATOR VALVE							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08								
215009	CABIN EVAPORATOR							Component ATA:21
PN:66-0260-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:K53719	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10, AMM 21-50-09PROC. REF: AMM 21-51-10, AMM 21-50-09								
215010	CABIN EXPANSION VALVE							Component ATA:21
PN:ES26105-1	MOS/MSC	11-Aug-21	O/C	TSN 0				
SN:UNKNOWN	HRS	2892.3		TSN 0				
	AFL	2032		TSN 0				
PROC. REF: AMM 21-50-10, AMM 21-51-11PROC. REF: AMM 21-50-10, AMM 21-51-11								
215012	FREON MOTOR CONTROL BOX							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-12, AMM 21-51-13PROC. REF: AMM 21-50-12, AMM 21-51-13								
215014	K62 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14PROC. REF: AMM 21-50-13, AMM 21-51-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215015	K63 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14PROC. REF: AMM 21-50-13, AMM 21-51-14								
215016	FREON MOTOR DIFFERENTIAL CURRENT SENSOR							Component ATA:21
PN:268-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3X8RF	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-14, AMM 21-51-15PROC. REF: AMM 21-50-14, AMM 21-51-15								
215017	COMPRESSOR MOTOR HOURMETER							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-16, AMM 21-51-03PROC. REF: AMM 21-50-16, AMM 21-51-03								
215017A	CHECK AND RECORD COMPRESSOR MOTOR HOURMETER TIME							Service ATA:21
PN:PN	MOS/MSC	01-Mar-12	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215031	ABSOLUTE PRESSURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215049	COCKPIT EXPANSION VALVE							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-07, AMM 21-51-09PROC. REF: AMM 21-50-07, AMM 21-51-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215120	CONDENSER FAN							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02								
216002	CREW TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02								
216003	CABIN TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02								
216004	TEMPERATURE CONTROL INDICATOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03								
216005	COCKPIT TEMPERATURE CONTROLLER							Component ATA:21
PN:625734-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:625734-01303	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04								
216006	CABIN TEMPERATURE CONTROLLER							Component ATA:21
PN:625734-2	MOS/MSC	04-Sep-14	O/C					
SN:073C-1037	HRS	1217.8						
	AFL	826						
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216007	COCKPIT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216008	CABIN TEMPERATURE SENSOR							Component ATA:21
PN:627962-1	MOS/MSC	06-Mar-17	O/C					
SN:627962-51438	HRS	2340.8						
	AFL	1566						
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216009	COCKPIT TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216010	CABIN TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:6600231-1	MOS/MSC	04-Sep-14	O/C					
SN:7042	HRS	1217.8						
	AFL	826						
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216011	COCKPIT SKIN TEMPERATURE SENSOR							Component ATA:21
PN:625704-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:120C-7940	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06								
216012	CABIN SKIN TEMPERATURE SENSOR							Component ATA:21
PN:625704-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:120C-7941	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216013	COCKPIT TEMPERATURE CONTROL VALVE							Component ATA:21
PN:3291290-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:836	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07								
216014	CABIN TEMPERATURE CONTROL VALVE							Component ATA:21
PN:3291290-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:828	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07								
216015	COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR							Component ATA:21
PN:124904-1-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7723	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08								
216016	CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR							Component ATA:21
PN:124904-1-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7738	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08								
216017	SERVO AIR PRESSURE REGULATOR							Component ATA:21
PN:60810-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1467	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09								
216018	COCKPIT AIR DISTRIBUTION CHECK VALVE							Component ATA:21
PN:3202078-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1432	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216019	CABIN AIR DISTRIBUTION CHECK VALVE							Component ATA:21
PN:3202188-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:817	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10								
216020	COCKPIT DUCT TEMPERATURE SENSOR							Component ATA:21
PN:627962-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:23667	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11								
216021	CABIN DUCT TEMPERATURE SENSOR							Component ATA:21
PN:627962-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:23668	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11								
216022	COCKPIT DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-12PROC. REF: AMM 21-60-12								
216023	CABIN DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-12PROC. REF: AMM 21-60-12								
216024	CLIMATE CONTROL BOX							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-13PROC. REF: AMM 21-60-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216025	PILOT ELECTRICAL EQUIPMENT BOX							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-14PROC. REF: AMM 21-60-14								
216101	CABIN TEMPERATURE INDICATOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-01PROC. REF: AMM 21-61-01								
216102	CABIN TEMPERATURE INDICATOR SENSOR							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-02PROC. REF: AMM 21-61-02								
218105	LEFT TRANSITION DUCT ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10PROC. REF: AMM 21-51-10								
218106	RIGHT TRANSITION DUCT ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10PROC. REF: AMM 21-51-10								
E2130005 ^S	BORESCOPE INSPECTION PRIMARY AND SECONDARY OUTFLOW VALVE POPPETS AND SEATS FOR CONTAMINATION. (REFER TO 21-30-00).							Service ATA:21
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								

PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
E2130064 ^S	REMOVE AND REPLACE CABIN AIR FILTER. (REFER TO 21-30-06).							Service ATA:21
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06								PKG:13
H2132004 ^S	PERFORM FUNCTIONAL TEST OF EMERGENCY PRESSURIZATION SYSTEM. (REFER TO 21-31-00)							Service ATA:21
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00								PKG:7
H2150000 ^S	INSPECT REFRIGERATION (AIR CONDITIONING) SYSTEM COMPONENTS INSTALLATION FOR PROPER V-BELT TENSION, SECURITY OF MOUNTING, AND GENERAL CONDITION. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND SHAFT)							Service ATA:21
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 12-10-06, AMM 21-50-01, AMM 21-51-01PROC. REF: AMM 12-10-06, AMM 21-50-01, AMM 21-51-01								PKG:9
K2150006 ^S	PERFORM REFRIGERATION COMPRESSOR MOTOR BRUSH WEAR INSPECTION. (REFER TO 21-50-02)							Service ATA:21
	MOS	27-Apr-23	24 (+14d/-14d)					
	HRS	3073	600 (+25/-25)					
	AFL	2202						
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02								PKG:9
L2150048 ^S	FUNCTIONAL TEST OF REFRIGERATION SYSTEM PRESSURE SWITCH. (REFER TO 21-50-05.)							Service ATA:21
	MOS	06-Mar-17	96 (+14d/-14d)					
	HRS	2340.8	2400 (+25/-25)					
	AFL	1566						
PROC. REF: AMM 21-50-05PROC. REF: AMM 21-50-05								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
N2131010 ^S	FUNCTIONAL TEST OF CABIN PRESSURE WARNING SYSTEM. (REFER TO 21-30-00.)							Service ATA:21
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:13
N2144000 ^S	FUNCTIONAL TEST OF TAILCONE BAGGAGE COMPARTMENT HEATING SYSTEM. (REFER TO 21-44-00.)							Service ATA:21
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-44-00PROC. REF: AMM 21-44-00								PKG:21
N2150017 ^S	PERFORM A FLUORESCENT PENETRANT INSPECTION OF THE AIR CONDITIONER COMPRESSOR MOTOR FAN BLADES. PARTICULAR ATTENTION SHOULD BE GIVEN TO THE FAN BLADES IN THE AREA OF THE HUB. (REFER TO NDI MANUAL [NDI-2], PART 5, 21-50-01.)							Service ATA:21
	MOS	23-Mar-21	48 (+14d/-14d)					
	HRS	2858.6	1200 (+25/-25)					
	AFL	2000						
PROC. REF: NDT 21-50-01PROC. REF: NDT 21-50-01								PKG:15
P2130070 ^S	FUNCTIONAL TEST OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)							Service ATA:21
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:13
T2120001 ^S	INSPECT RAM AIR DUCTING AND HEAT EXCHANGER FRO SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:21
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
T2130012 ^S	PERFORM FUNCTIONAL TEST OF PRESSURIZATION SYSTEM VACUUM PUMP HEATING ELEMENT. (REFER TO 21-30-12)							Service ATA:21
	MOS	23-Mar-21	24 (+14d/-14d)					
	HRS	2858.6	600 (+25/-25)					
	AFL	2000						
PROC. REF: AMM 21-30-12PROC. REF: AMM 21-30-12								PKG:8
T2130069 ^S	PERFORM OPERATIONAL CHECK OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)							Service ATA:21
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:7
T2142002 ^S	FUNCTIONAL TEST OF AUXILIARY CABIN HEAT SYSTEM. (REFER TO 21-42-00.)							Service ATA:21
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 21-42-00PROC. REF: AMM 21-42-00								PKG:13
T2144010 ^S	VISUALLY INSPECT TAILCONE BAGGAGE COMPARTMENT HEATER BLANKETS. (REFER TO 5-10-00.)							Service ATA:21
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
ATA 22 - AUTO FLIGHT								
221001	AUTOPILOT CONTROLLER							Component ATA:22
PN:6608507-003	MOS/MSC	06-Mar-17	O/C	TSR 0				
SN:80086	HRS	2340.8		TSR 0				
	AFL	1566		TSR 0				
PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221002	AUTOPILOT ELECTRICAL BOX							Component ATA:22
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02								
221003	PITCH SERVO ACTUATOR							Component ATA:22
PN:622-5027-102	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:44VHR	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03								
221004	PITCH SERVO MOUNT							Component ATA:22
PN:622-5029-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3V17B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04								
221005	AUTOPITCH TRIM AMPLIFIER BOX ASSEMBLY							Component ATA:22
PN:5418419-009	MOS/MSC	28-Apr-15	O/C	TSO 0				
SN:A00861377-01	HRS	1631.7		TSO 0				
	AFL	1086		TSO 0				
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05								
221006	ROLL SERVO ACTUATOR							Component ATA:22
PN:622-5027-102	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3W89Y	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06								
221007	ROLL DISCONNECT RELAY BOX							Component ATA:22
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221008	YAW DISCONNECT RELAY BOX							Component ATA:22
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-08PROC. REF: AMM 22-10-08								
221009	YAW SERVO ACTUATOR							Component ATA:22
PN:622-5027-102	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:44VHV	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-09PROC. REF: AMM 22-10-09								
221010	YAW SERVO MOUNT							Component ATA:22
PN:622-5029-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3V1HG	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-10PROC. REF: AMM 22-10-10								
221011	ROLL SERVO MOUNT							Component ATA:22
PN:622-5029-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3V17B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-11PROC. REF: AMM 22-10-11								
221012	REMOTE TUNING RELAY BOX							Component ATA:22
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-12PROC. REF: AMM 22-10-12								
221013	NO. 1 FLIGHT GUIDANCE COMPUTER							Component ATA:22
PN:822-1108-041	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-14PROC. REF: AMM 22-10-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221014	NO. 2 FLIGHT GUIDANCE COMPUTER							Component ATA:22
PN:822-1108-041	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-14PROC. REF: AMM 22-10-14								
222001	MACH TRIM COMPUTER							Component ATA:22
PN:501-1132-04	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:80129	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-01PROC. REF: AMM 22-20-01								
222002	MACH TRIM ADAPTER							Component ATA:22
PN:902-1-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3MMVW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-02PROC. REF: AMM 22-20-02								
222003	MACH TRIM POSITION (FOLLOW UP) SENSOR							Component ATA:22
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-03PROC. REF: AMM 22-20-03								
225001	YAW FORCE INTERFACE BOX							Component ATA:22
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01								
225002	PILOT FORCE SENSOR							Component ATA:22
PN:3454-101-650	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1334527	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
225003	COPILOT FORCE SENSOR							Component ATA:22
PN:3454-101-650	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1329365	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02								
H2211034 ^S	CHECK ROLL SERVO CABLE TENSION. (REFER TO 22-10-11.)							Service ATA:22
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 22-10-11PROC. REF: AMM 22-10-11								
H2211039 ^S	CHECK PITCH SERVO AND YAW SERVO CABLE TENSION. (REFER TO 22-10-04 AND 22-10-10.)							Service ATA:22
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 22-10-04, AMM 22-10-10PROC. REF: AMM 22-10-04, AMM 22-10-10								
T2211022 ^S	CHECK YAW SERVO CABLE FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR CONDITION AND SECURITY.							Service ATA:22
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T2212022 ^S	INSPECT ELEVATOR SERVO CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR GENERAL CONDITION AND SECURITY.							Service ATA:22
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231101	NO. 1 VHF TRANSCEIVER							Component ATA:23
PN:822-1115-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:45XDM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01								
231102	NO. 2 VHF TRANSCEIVER							Component ATA:23
PN:822-1115-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:45X5Y	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01								
231103	NO. 1 VHF ANTENNA							Component ATA:23
PN:VF10-347	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6041	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02								
231104	NO. 2 VHF ANTENNA							Component ATA:23
PN:VF10-347	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6087	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02								
231121	AERO M SATCOM ANTENNA							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231180	NO. 1 HF AUDIO AMPLIFIER							Component ATA:23
PN:064-01072-0101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:KPA1052-4546	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231181	NO. 2 HF AUDIO AMPLIFIER							Component ATA:23
PN:064-01072-0101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:KPA1052-5244	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231192	HF ANTENNA LEADTHRU INSULATOR							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-03PROC. REF: AMM 23-12-03								
231201	NO. 1 HF RECEIVER/EXCITER							Component ATA:23
PN:064-10173-0102	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:KRX1053-5136	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-01PROC. REF: AMM 23-12-01								
231202	NO. 2 HF RECEIVER/EXCITER							Component ATA:23
PN:064-10173-0102	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:KRX1053-5640	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-01PROC. REF: AMM 23-12-01								
231203	PRIMARY POWER AMPLIFIER/ANTENNA COUPLER							Component ATA:23
PN:064-10174-0101	MOS/MSC	28-May-21	O/C	TSN 110				
SN:KAC1052-4844	HRS	2876		TSN 2876				
	AFL	2014		TSN 2014				
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231203A	PERFORM PRIMARY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM							Service ATA:23
PN:064-10174-0101	MOS	04-Apr-25	12 (+14d/-14d)		04-Apr-26	18-Apr-26	319 d (+14)	SMM
SN:KAC1052-4844	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 23-12-08PROC. REF: AMM 23-12-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231204	STANDBY POWER AMPLIFIER/ANTENNA COUPLER							Component ATA:23
PN:064-10174-0101	MOS/MSC	28-May-21	O/C	TSN 110				
SN:KAC1052-5150	HRS	2876		TSN 2876				
	AFL	2014		TSN 2014				
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231204A	PERFORM STANDBY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM.							Service ATA:23
PN:064-10174-0101	MOS	04-Apr-25	12 (+14d/-14d)		04-Apr-26	18-Apr-26	319 d (+14)	SMM
SN:KAC1052-5150	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 23-12-08PROC. REF: AMM 23-12-08								
231205	HF ANTENNA							Component ATA:23
PN:5489123-2	MOS/MSC	16-Oct-15	O/C	TSN 0				
SN:UNKNOWN	HRS	1816.3		TSN 0				
	AFL	1240		TSN 0				
PROC. REF: AMM 23-12-03PROC. REF: AMM 23-12-03								
231207	NO. 1 HF CONTROL UNIT							Component ATA:23
PN:071-01605-0101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2202	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04								
231208	NO. 2 HF CONTROL UNIT							Component ATA:23
PN:071-01605-0101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2003	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04								
231209	HF AUDIO ADAPTER							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-05PROC. REF: AMM 23-12-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231210	HF COMMUNICATION FUSE BOX ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-06PROC. REF: AMM 23-12-06								
231211	(CBR8) HF REMOTE CIRCUIT BREAKER							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-07PROC. REF: AMM 23-12-07								
231212	UPPER HF POWER AMPLIFIER							Component ATA:23
PN:064-10172-0101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:KPA1052-4546	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231213	LOWER HF POWER AMPLIFIER							Component ATA:23
PN:064-10172-0101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:KPA1052-5244	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231271	HF GROUND ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231401	SELCAL CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-01PROC. REF: AMM 23-14-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231402	SELCAL DECODER							Component ATA:23
PN:2800-0012-105	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1108G008	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-02PROC. REF: AMM 23-14-02								
231403	SELCAL SONALERT							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-03PROC. REF: AMM 23-14-03								
231501	PASSENGER BRIEFER CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-01PROC. REF: AMM 23-15-01								
231502	PASSENGER BRIEFER COMPUTER							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-02PROC. REF: AMM 23-15-02								
232001	FLIGHT PHONE / DATA SYSTEM TRANSCEIVER (INMARSAT-SITCOM)							Component ATA:23
PN:405040A	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232002 ^U	FLIGHT PHONE / DATA SYSTEM SBU CONFIGURATION MODULE							Component ATA:23
PN:P12083-001	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232003 ^U	FLIGHT PHONE / DATA SYSTEM WIFI ROUTER							Component ATA:23
PN:P12083-001	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
232004 ^U	FLIGHT PHONE / DATA SYSTEM AMPLIFIER SWIFT BROADBAND HPA / LNA DIPLEXER							Component ATA:23
PN:405016A	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS							
	AFL							
232005	FLIGHT PHONE / DATA SYSTEM ANTENNA							Component ATA:23
PN:405006A-PMA	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232010	#1 FLIGHT PHONE CABIN HANDSET							Component ATA:23
PN:P12793-001	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232015	#2 FLIGHT PHONE CABIN HANDSET							Component ATA:23
PN:P12793-001	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232020 ^U	FLIGHT PHONE COCKPIT HANDSET							Component ATA:23
PN:P12248-001	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232105	(#3) VHF DATA LINK TRANSCEIVER							Component ATA:23
PN:822-1468-302	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01								
232110	COMMUNICATION MANAGEMENT (CMU) UNIT							Component ATA:23
PN:822-1739-003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3XGKY	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232111	CMU EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233001	LEFT FORWARD CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:091100326	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233002	RIGHT FORWARD CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:091100323	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233003	LEFT AFT CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:091100322	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233004	RIGHT AFT CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:091100324	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233005	PASSENGER SPEAKER AMPLIFIER							Component ATA:23
PN:303--548	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:021100166	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02								
233023	FORWARD WOOFER, CABIN SPEAKER							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233024	AFT WOOFER, CABIN SPEAKER							Component ATA:23
PN:EN-W-60-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:041100373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233030	CONFIGURATION MODULE							Component ATA:23
PN:P13242-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:80438812	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233040	INFRARED REMOTE CONTROL							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233075	CABIN DISPLAY							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233084	FORWARD 15.1 LCD COLOR DISPLAY							Component ATA:23
PN:LCD-9151-201-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233085	FORWARD VIDEO MONITOR-							Component ATA:23
PN:LCD-9151-201-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:031100012	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233086	AFT VIDEO MONITOR-							Component ATA:23
PN:LCD-9151-201-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:031100237	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233088	AFT 15.1 LCD COLOR DISPLAY							Component ATA:23
PN:AI-LCD151-01-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:031100237	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233101	STEREO ANTENNA							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-01PROC. REF: AMM 23-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233105	AUDIO DISTRIBUTION MODULE							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-05PROC. REF: AMM 23-31-05								
233106	LEFT DIGITAL SELECTOR MODULE							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-06PROC. REF: AMM 23-31-06								
233107	RIGHT DIGITAL SELECTOR MODULE							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-06PROC. REF: AMM 23-31-06								
234101	INTERPHONE AUDIO AMPLIFIER							Component ATA:23
PN:MODEL 204	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:71409	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-41-01PROC. REF: AMM 23-41-01								
235001	PILOT AUDIO CONTROL PANEL							Component ATA:23
PN:802-009	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2296	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01								
235002	COPILOT AUDIO CONTROL PANEL							Component ATA:23
PN:802-009	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2533	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
235003	LEFT AUDIO AMPLIFIER							Component ATA:23
PN:700-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:71756	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-02PROC. REF: AMM 23-50-02								
235004	RIGHT AUDIO AMPLIFIER							Component ATA:23
PN:700-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:73679	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-02PROC. REF: AMM 23-50-02								
237001	COCKPIT VOICE (CVR) RECORDER							Component ATA:23
PN:1603-02-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2533	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01								
237002	CVR REMOTE MICROPHONE AMPLIFIER							Component ATA:23
PN:1635-02	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:431	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03								
237003	CVR REMOTE AREA MICROPHONE							Component ATA:23
PN:16301-01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3301	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-04PROC. REF: AMM 23-70-04								
237004	CVR INERTIA SWITCH							Component ATA:23
PN:3L0-453/8	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:92534	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237021	CVR UNDERWATER LOCATOR (ULB) BEACON							Component ATA:23
PN:DK120	MOS/MSC	14-Jan-16	O/C	TSN 46				
SN:SC71446	HRS	1976.1		TSN 1976.1				
	AFL	1331		TSN 1331				
PROC. REF: AMM 25-63-00PROC. REF: AMM 25-63-00								
237021A	CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY							Service ATA:23
PN:DK120	MOS	16-Apr-24	24 (+14d/-14d)		16-Apr-26	30-Apr-26	331 d (+14)	
SN:SC71446	HRS							
	AFL							
PROC. REF: AMM 25-63-00PROC. REF: AMM 25-63-00								
237021B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000							Service ATA:23
PN:DK120	MOS/MSC	13-Jul-20	DUE		01-Jun-26 (M)		377 d	
SN:SC71446	HRS	2802						
	AFL	1952						
PROC. REF: AMM 25-63-00PROC. REF: AMM 25-63-00								
237032	AUDIO/VIDEO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-41-01PROC. REF: AMM 23-41-01								
238001	NO. 1 RADIO TUNING (RTU) UNIT							Component ATA:23
PN:822-0730-438	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4683B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01								
238002	NO. 2 RADIO TUNING (RTU) UNIT							Component ATA:23
PN:822-0730-438	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4686B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
239007	NO. 1 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
239008	NO. 2 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
239009	NO. 3 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
239015	ORDINANCE SIGN SWITCH							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
239016	AUDIO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-41-01PROC. REF: AMM 23-41-01								
E2360010 ^S	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00)							Service ATA:23
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								

PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
E2360011	^S	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00)						Service ATA:23
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:6
H2360021	^S	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.)						Service ATA:23
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:22
P2360022	^S	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.)						Service ATA:23
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:24
ATA 24 - ELECTRICAL POWER								
05-10-29-B2432010		INSPECT MAIN AIRCRAFT BATTERY INSTALLATION						Service ATA:24
	MOS	04-Apr-25	6 (+14d/-14d)	Adj 12d	16-Oct-25	30-Oct-25	149 d (+14)	
	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
05-10-29-H2431017		PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION						Service ATA:24
	MOS	04-Apr-25						
	HRS	3222.8	300 (+25/-25)		3522.8	3547.8	298.9 (+25)	
	AFL	2317						
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-25-00 ^U GENERAL VISUAL INSPECTION OF THE SIXTY-HERTZ POWER SYSTEM COMPONENTS AND WIRING.								
	MOS	31-Mar-22	48		31-Mar-26		315 d	Service ATA:24
	HRS	2973.4	1200		4173.4		949.5	STLMC
	AFL	2090						
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								
242001 LEFT PRIMARY AC POWER INVERTER								
PN:501-1666-01	MOS/MSC	01-Mar-12	O/C	TSN 0				Component ATA:24
SN:80259	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								
242002 RIGHT SECONDARY AC POWER INVERTER								
PN:6608483-1	MOS/MSC	28-Mar-16	O/C					Component ATA:24
SN:80142	HRS	2061.6						
	AFL	1377						
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								
242003 POWER MONITOR INDICATOR								
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				Component ATA:24
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242005 ISOLATION PARALLELING BOX								
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				Component ATA:24
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242009 NO. 1 GROUND FAULT TRANSFORMER								
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				Component ATA:24
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242010	NO. 2 GROUND FAULT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242016	GENERATOR CONTROL PANEL							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-02PROC. REF: AMM 24-30-02								
242031	DC AMMETER SENSOR							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
242032	NO. 1 DC CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:41VTJ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
242033	NO. 2 DC CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:41WFD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
242081	1200 VA, 115 VAC, 60 HZ INVERTER							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242505	GROUND FAULT INTERRUPTER							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242507	60HZ POWER SYSTEM ANEROID SWITCH							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243001	NO. 1 STARTER/GENERATOR							Component ATA:24
PN:400SG138Q	MOS/MSC	01-Nov-24	O/C	TSO 17				
SN:1241XL	HRS			TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01								
243001A	OVERHAUL NO. 1 STARTER/GENERATOR - (Y2431025)							Service ATA:24
PN:400SG138Q	MOS	01-Nov-24						OVERHAUL
SN:1241XL	HRS	3207.7	1000 (+25/-25)		4207.7	4232.7	983.8 (+25)	
	AFL	2306						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243002	NO. 2 STARTER/GENERATOR							Component ATA:24
PN:400SG138Q-2	MOS/MSC	11-Jan-24	O/C	TSO 7				
SN:1347	HRS	3118.3		TSO 0				
	AFL	2239		TSO 0				
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01								
243002A	OVERHAUL NO. 2 STARTER/GENERATOR - (Y2431025)							Service ATA:24
PN:400SG138Q-2	MOS	11-Jan-24						OVERHAUL
SN:1347	HRS	3118.3	1000 (+25/-25)		4118.3	4143.3	894.4 (+25)	
	AFL	2239						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243003	APU STARTER/GENERATOR							Component ATA:24
PN:400SG159Q	MOS/MSC	22-Oct-18	O/C	TSO 1				
SN:3147	HRS	2663.5		TSO 0				
	AFL	1852		TSO 0				
PROC. REF: GENERIC NO REF, SMM 49-11-02PROC. REF: GENERIC NO REF, SMM 49-11-02								
243003A	OVERHAUL/REPLACE APU STARTER/GENERATOR BRUSHES							Service ATA:24
PN:400SG159Q	MOS	22-Oct-18						
SN:3147	HRS	2663.5						
	AFL	1852						
	APH	973	1000		1973		697	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243005	LEFT (GCU) GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG505-16B	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:50485	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-03PROC. REF: AMM 24-30-03								
243006	RIGHT (GCU) GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG505-16B	MOS/MSC	09-Feb-24	O/C	TSR 9				
SN:1267B	HRS	3131.2		TSR 0				
	AFL	2249		TSR 0				
PROC. REF: AMM 24-30-03PROC. REF: AMM 24-30-03								
243007	A11 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								
243008	2A11 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243009	A12 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6452	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								
243010	2A12 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6581	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								
243011	LEFT DC AMMETER CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:41VTJ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
243012	RIGHT DC AMMETER CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:41WFD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
243049	UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY							Component ATA:24
PN:RG-380E/60L	MOS/MSC	16-Oct-23	O/C	TSN 1				VENDOR RECOMMENDED
SN:70029464	HRS	3089.5		TSN 0				
	AFL	2219		TSN 0				
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
243049B	CAPACITY CHECK UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS	04-Apr-25	6		04-Oct-25		137 d	
SN:70029464	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 12-22-00PROC. REF: AMM 12-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243050	LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY							Component ATA:24
PN:RG-380E/60L	MOS/MSC	16-Oct-23	O/C	TSN 1				VENDOR RECOMMENDED
SN:70029466	HRS	3089.5		TSN 0				
	AFL	2219		TSN 0				
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
243050B	CAPACITY CHECK LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS	04-Apr-25	6		04-Oct-25		137 d	
SN:70029466	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 12-22-00PROC. REF: AMM 12-22-00								
243055	EMERGENCY POWER (24VDC TO 5VDC) CONVERTER							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243062	NO. 1 EMERGENCY POWER BATTERY							Component ATA:24
PN:100-2410-06	MOS/MSC	04-Apr-25	O/C	TSO 6				
SN:0707701	HRS	3222.8		TSO 0				
	AFL	2317		TSO 0				
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243063	NO. 2 EMERGENCY POWER BATTERY							Component ATA:24
PN:501-1712-02	MOS/MSC	28-May-21	O/C					
SN:81532	HRS	2876						
	AFL	2014						
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243063A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010							Service ATA:24
PN:501-1712-02	MOS	04-Apr-25	6 (+14d/-14d)	Adj 13d	17-Oct-25	31-Oct-25	150 d (+14)	
SN:81532	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243063B	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015							Service ATA:24
PN:501-1712-02	MOS	04-Apr-25	12 (+14d/-14d)	Adj -45d	18-Feb-26	04-Mar-26	274 d (+14)	
SN:81532	HRS	3222.8						
	AFL	2317						
PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170								
243103	BATTERY TEMPERATURE INDICATOR							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-03PROC. REF: AMM 24-31-03								
243200	PERFORM NO. 1 EMERGENCY POWER BATTERY OPERATIONAL CHECK (XL2410) (IRN Y2431061)							Service ATA:24
PN:100-2410-06	MOS	04-Apr-25	12 (+14d/-14d)		04-Apr-26	18-Apr-26	319 d (+14)	
SN:0707701	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243301	NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK							Component ATA:24
PN:M6088352-025	MOS/MSC	16-Mar-18	O/C	TSR 0				
SN:A02047840-01	HRS	2534.7		TSR 0				
	AFL	1732		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243301A	CHARGE NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030							Service ATA:24
PN:M6088352-025	MOS	04-Apr-25	12 (+14d/-14d)	Adj -45d	18-Feb-26	04-Mar-26	274 d (+14)	
SN:A02047840-01	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 12-23-02PROC. REF: AMM 12-23-02								
243302	NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK							Component ATA:24
PN:M6088352-025	MOS/MSC	16-Mar-18	O/C	TSR 0				
SN:A04047840-01	HRS	2534.7		TSR 0				
	AFL	1732		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243302A	CHARGE NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030							Service ATA:24
PN:M6088352-025	MOS	04-Apr-25	12 (+14d/-14d)	Adj -45d	18-Feb-26	04-Mar-26	274 d (+14)	
SN:A04047840-01	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 12-23-02PROC. REF: AMM 12-23-02								
244002	GROUND POWER MONITOR-							Component ATA:24
PN:6018828-002	MOS/MSC	18-Jun-18	O/C	TSN 0				
SN:UNKNOWN	HRS	2585.9		TSN 0				
	AFL	1775		TSN 0				
PROC. REF: AMM 24-40-02PROC. REF: AMM 24-40-02								
245001	PILOT CIRCUIT BREAKER PANEL							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-01PROC. REF: AMM 24-50-01								
245002	COPILOT CIRCUIT BREAKER PANEL							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-01PROC. REF: AMM 24-50-01								
245003	LEFT OVERLOAD (CBR2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-03PROC. REF: AMM 24-50-03								
245004	RIGHT OVERLOAD (CBR2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-03PROC. REF: AMM 24-50-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
AA2432003 ^S	PERFORM OPERATIONAL CHECK OF AC POWER SYSTEM							Service ATA:24
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 24-20-00PROC. REF: AMM 24-20-00								PKG:19
H2400004 ^S	INSPECT PEDESTAL INTERIOR WIRING FOR WIRE ROUTING, CLEARANCES, DETERIORATION, AND GENERAL CONDITION.							Service ATA:24
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
H2432001 ^S	OPERATIONAL CHECK EMERGENCY DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-51-00.)							Service ATA:24
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 24-51-00PROC. REF: AMM 24-51-00								PKG:13
H2450021 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service ATA:24
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:19
P2400008 ^S	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCE, AND GENERAL CONDITION (THAT PORTION VISIBLE THROUGH WHEEL WELLS).							Service ATA:24
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
Q2400006 ^S	PERFORM INSPECTION OF ALL 4 AWG OR GREATER ELECTRICAL CABLES. VERIFY THERE IS NO HEAT DAMAGE TO THE LARGE GAUGE WIRE TERMINAL CONNECTIONS TO THE POWER DISTRIBUTION ASSEMBLY. INSPECT CONNECTORS AND TERMINAL LUGS FOR CONDITION AND SECURITY. INSPECT CABLE ROUTING TO						Service	ATA:24
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T2400003 ^S	INSPECT ELECTRICAL WIRING, HYDRAULIC, AND PNEUMATIC LINES UNDER FLOORBOARDS FOR EVIDENCE OF LEAKAGE, SECURITY OF CLAMPS, AND CONDITION. (REFER TO 5-10-00.)						Service	ATA:24
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
T2400009 ^S	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCES SECURITY, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)						Service	ATA:24
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
T2432000 ^S	OPERATIONAL CHECK OF DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-50-00.)						Service	ATA:24
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 24-50-00PROC. REF: AMM 24-50-00								PKG:19
T2450020 ^S	CHECK SWITCH AND CIRCUIT BREAKER PANELS FOR GENERAL CONDITION. ENSURE MARKINGS ARE CLEAR AND READABLE.						Service	ATA:24
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-00-00-601	^U	GENERAL VISUAL INSPECTION OF THE PASSENGER AND LAVATORY COMPARTMENT CABINETS, HEADLINER, WINDOW PANELS, BULKHEADS, SIDELEDGES, TABLES, AND CARPETING						Service ATA:25
	MOS	04-Apr-25						STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
25-00-00-602	^U	INSPECT INTERIOR CABINET DRAWER AND DOOR LATCHES FOR WEAR, CONDITION, SECURITY OF ATTACHMENT IN THE STOWED POSITION, AND PROPER OPERATION						Service ATA:25
	MOS	16-Apr-24	36		16-Apr-27		696 d	STLMC
	HRS							
	AFL							
25-00-00-604	^U	INSPECT THE GALLEY, POTTY, AND LAVATORY FOR SPILLAGE						Service ATA:25
	MOS	28-Mar-19						STLMC
	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
25-00-00-605	^U	CHECK THE OPERATION, LATCHING AND SEALING OF THE WASTE CONTAINER COMPARTMENTS						Service ATA:25
	MOS	28-Mar-19						STLMC
	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
25-00-00-606	^U	CHECK THE OPERATION OF THE AFT PARTITION DOOR HOLD-OPEN LATCH						Service ATA:25
	MOS	04-Apr-25						STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
25-20-00-601	^U	GENERAL VISUAL INSPECTION OF THE PASSENGER SEAT RESTRAINTS						Service ATA:25
	MOS	04-Apr-25						STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-30-00-601	U	GENERAL VISUAL INSPECTION OF ACCESSIBLE AREAS AROUND THE GALLEY						Service ATA:25
	MOS	28-Mar-19						STLMC
	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
25-30-00-603	U	GENERAL VISUAL INSPECTION OF THE HOT LIQUID CONTAINER						Service ATA:25
	MOS	01-Mar-12						STLMC
	HRS	0	4800		4800		1576.1	
	AFL	0						
25-40-00-601	U	GENERAL VISUAL INSPECTION OF ACCESSIBLE AREAS AROUND THE LAVATORY						Service ATA:25
	MOS	28-Mar-19						STLMC
	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
25-60-00-601	U	DETAILED INSPECTION OF LIFE VESTS						Service ATA:25
	MOS	04-Apr-25						STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
25-60-00-602	U	RESTORATION OF THE LIFE VESTS						Service ATA:25
	MOS	01-Mar-12	120		01-Mar-26 (M)		285 d	STLMC
	HRS	0						
	AFL	0						
250000	STEREO/PAGE AMPLIFIER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
251001	PILOT CREW SEAT							Component ATA:25
PN:3A213-0007-02-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:63521	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-01PROC. REF: AMM 25-10-01								
251002	COPILOT CREW SEAT							Component ATA:25
PN:3A213-0008-02-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:63035	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-01PROC. REF: AMM 25-10-01								
251005	PILOT LIGHTED CHART HOLDER							Component ATA:25
PN:10-62-01	MOS/MSC	28-Mar-12	O/C					
SN:6683	HRS	12.3						
	AFL	11						
PROC. REF: AMM 25-10-05PROC. REF: AMM 25-10-05								
251006	COPILOT LIGHTED CHART HOLDER							Component ATA:25
PN:10-62-01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6525	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-05PROC. REF: AMM 25-10-05								
252001	LEFT FORWARD PASSENGER SEAT							Component ATA:25
PN:2524.014.01-3146B.100	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:110228-07	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252002	RIGHT FORWARD PASSENGER SEAT							Component ATA:25
PN:2524.014.01-3146B.100	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:110228-11	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252003	LEFT MID PASSENGER SEAT							Component ATA:25
PN:2524.014.01-3146B.100	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:110228-09	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252004	RIGHT MID PASSENGER SEAT							Component ATA:25
PN:2524.014.01-3146B.100	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:110228-10	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252005	LEFT AFT PASSENGER SEAT							Component ATA:25
PN:2524.014.01-3146B.100	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:110228-08	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252007	RIGHT PASSENGER DIVAN							Component ATA:25
PN:2523.574.01.02.100	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:110228-12	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252025	RIGHT LOWER DIFFUSER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-03PROC. REF: AMM 25-20-03								
252027	LEFT LOWER DIFFUSER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-20-03PROC. REF: AMM 25-20-03								
253007	LEFT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253009	LEFT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253010	RIGHT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253012	RIGHT FORWARD COLD CATHODE LAMP INVERTER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253052	VOLTAGE REGULATOR							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
255050	MICROWAVE OVEN							Component ATA:25
PN:400-1338-02-L	MOS/MSC	03-Feb-18	O/C	TSR 1				
SN:11-07-48877	HRS	2517.1		TSR 0				
	AFL	1720		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
255050A	ANNUAL INSPECTION MICROWAVE OVEN M100367ICT-SMM-1 (25-35-13)							Service ATA:25
PN:400-1338-02-L	MOS	04-Apr-25	12		04-Apr-26		319 d	
SN:11-07-48877	HRS	3222.8						
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
255050B	OPERATIONAL CHECK MICROWAVE OVEN AND BAROMETRIC SWITCH							Service ATA:25
PN:400-1338-02-L	MOS	28-Mar-19						STLMC
SN:11-07-48877	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256001	(ELT) EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:453-5000-(366)	MOS/MSC	14-Jan-17	O/C	TSN 58				
SN:170-14034	HRS	2311.2		TSN 2311.2				
	AFL	1547		TSN 1547				
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01								
256001A	INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:453-5000-(366)	MOS	04-Apr-25	12 (+14d/-14d)		04-Apr-26	18-Apr-26	319 d (+14)	
SN:170-14034	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 25-62-00PROC. REF: AMM 25-62-00								
256001B	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - 05-11-00-L2564000							Service ATA:25
PN:452-0133	MOS/MSC	04-Apr-25	DUE		01-Feb-30 (M)		1718 d	
SN:1001730-004	HRS	3222.8						
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256001D	REGISTRATION RENEWAL (ELT) EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:453-5000-(366)	MOS	16-Oct-24	24		16-Oct-26		514 d	
SN:170-14034	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: GENERIC NO REF, CMM NOAA/SARSATPROC. REF: GENERIC NO REF, CMM NOAA/SARSAT								
256003	ELT CONTROLLER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256010	ELT/NAV INTERFACE							Component ATA:25
PN:453-6500	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:08779	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256061	NO. 1 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:16090470015	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256061A	INSPECT NO. 1 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		13-Sep-26 (M)		481 d	
SN:16090470015	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256062	NO. 2 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:16090470156	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256062A	INSPECT NO. 2 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		13-Sep-26 (M)		481 d	
SN:16090470156	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256063	NO. 3 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:16090470163	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256063A	INSPECT NO. 3 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		13-Sep-26 (M)		481 d	
SN:16090470163	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256064	NO. 4 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:16090470144	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256064A	INSPECT NO. 4 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		13-Sep-26 (M)		481 d	
SN:16090470144	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256065	NO. 5 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:16090470067	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256065A	INSPECT NO. 5 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		13-Sep-26 (M)		481 d	
SN:16090470067	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256066	NO. 6 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:17030560245	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256066A	INSPECT NO. 6 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		10-Mar-27 (M)		659 d	
SN:17030560245	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256067	NO. 7 LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:16090470126	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256067A	INSPECT NO. 7 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		13-Sep-26 (M)		481 d	
SN:16090470126	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256068	LAVATORY LIFE VEST							Component ATA:25
PN:P01074-201	MOS/MSC	28-Nov-17	O/C					
SN:17030560361	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256068A	INSPECT LAVATORY LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201	MOS		120		10-Mar-27 (M)		659 d	
SN:17030560361	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256071	PILOT LIFE VEST							Component ATA:25
PN:P01074-201C	MOS/MSC	28-Nov-17	O/C					
SN:16110650036	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256071A	INSPECT PILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201C	MOS		120		08-Nov-26 (M)		537 d	
SN:16110650036	HRS							
	AFL							
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256072	COPILOT LIFE VEST							Component ATA:25
PN:P01074-201C	MOS/MSC	28-Nov-17	O/C					
SN:15102670030	HRS	2516.3						
	AFL	1719						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256072A	INSPECT COPILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:P01074-201C	MOS		120		30-Oct-25 (M)		163 d	
SN:15102670030	HRS							
	AFL							
PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00								
256074 ^U	FIRST AID KIT (PRIMARY)							Component ATA:25
PN:19434606700	MOS/MSC	07-Dec-23	O/C					
SN:FAK120723-1	HRS	3106.8						
	AFL	2232						
256074A ^U	INTEGRA JET FIRST AID KIT REPLACEMENT (PRIMARY)							Service ATA:25
	MOS	07-Dec-23	24		07-Dec-25		201 d	
	HRS	3106.8						
	AFL	2232						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256076	FIRST AID (SPARE)							Component ATA:25
PN:19434606700	MOS/MSC	07-Dec-23	O/C					
SN:FAK120723-2	HRS	3106.8						
	AFL	2232						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256076A	INTEGRA JET FIRST AID KIT REPLACEMENT (SPARE)							Service ATA:25
PN:19434606700	MOS	07-Dec-23	24		07-Dec-25		201 d	
SN:FAK120723-2	HRS	3106.8						
	AFL	2232						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256078 ^U	INTEGRA JET FLARE GUN KIT							Component ATA:25
PN:584	MOS/MSC	07-Dec-23	O/C					
SN:012238	HRS	3106.8						
	AFL	2232						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256078A ^U	INTEGRA JET FLARE GUN CARTRIDGE REPLACEMENT							Service ATA:25
PN:584	MOS	07-Dec-23	36		31-Oct-26 (M)		529 d	
SN:012238	HRS	3106.8						
	AFL	2232						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256080 ^U	LIFE RAFT							Component ATA:25
PN:1015FASA-6K4-1-150	MOS/MSC	30-Sep-24	O/C	TSO 0				
SN:10UL-02790	HRS			TSO 0				
	AFL			TSO 0				
256080A ^U	RECERTIFY LIFE RAFT LIFE RAFT IAW MANUFACTURERS INSTRUCTIONS							Service ATA:25
	MOS	30-Sep-24	12 (+14d/-14d)		01-Feb-27 (M)	15-Feb-27	622 d (+14)	
	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256080C ^U	LIFE RAFT ELT REGISTRATION							Component ATA:25
PN:SRB406	MOS	16-Oct-24	24	TSN 1	16-Oct-26 (M)		514 d	
SN:149562	HRS							
	AFL							
256202	ELT ANTENNA							Component ATA:25
PN:110-337	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:348136	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								
256410	(ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:452-0133	MOS/MSC	04-Apr-25	O/C	TSN 5				
SN:1001730-004	HRS	3222.8		TSN 0				
	AFL	2317		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
257101	NOSE AVIONICS EXHAUST BLOWER							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-71-01PROC. REF: AMM 25-71-01								
258010	AIRSHOW DIGITAL INTERFACE UNIT							Component ATA:25
PN:920055	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:42N3M	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258011	COCKPIT CONTROL - AIRSHOW UNIT							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258012	AIRSHOW FLIGHT DECK CONTROLLER							Component ATA:25
PN:922000-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:42FPT	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258014	FORWARD AIRSHOW COLOR MONITOR-							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258015	AFT AIRSHOW COLOR MONITOR-							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258017	AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258020	AIRSHOW 400 VIDEO SWITCH PANEL							Component ATA:25
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
25LSC ^U	LUGGAGE SCALE CALIBRATION							Service ATA:25
	MOS	22-Jul-24	12		31-Aug-25 (M)		103 d	
	HRS	3175.3						
	AFL	2283						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25SCALE ^U	LUGGAGE SCALE							Component ATA:25
PN:11050W	MOS/MSC	22-Jul-24	O/C	TSN 0				
SN:410-ALS-6	HRS	3175.3		TSN 0				
	AFL	2283		TSN 0				
E2510010 ^S	INSPECT CREW SEATS AND SEAT BELTS FOR OPERATION, SECURITY OF MOUNTING, AND GENERAL CONDITION							Service ATA:25
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
N2571002 ^S	PERFORM FUNCTIONAL TEST OF NOSE AVIONICS COMPARTMENT EXHAUST BLOWERS AND THEIR RESPECTIVE CONTROL TEMPERATURE SWITCHES. (REFER TO 25-71-01.)							Service ATA:25
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 25-71-01PROC. REF: AMM 25-71-01								PKG:14
P2520007 ^S	INSPECT CABIN SEATS AND SEAT BELTS FOR CONDITION; BAGGAGE COMPARTMENT, STOWAGE CABINETS, STOWAGE CABINET LATCHES, RUGS, HEADLINER, AND SIDE PANELS FOR SECURITY AND CONDITION.							Service ATA:25
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2
U2510005 ^S	GENERAL VISUAL INSPECTION GLARESHIELD, HEADLINER, AND TRIM STRIPS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:25
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
U2540004 ^S	INSPECT ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.							Service ATA:25
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:8
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

ATA 26 - FIRE PROTECTION

261001	NO. 1 FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:377-02833	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1033-239	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								

261002	NO. 2 FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:377-02833	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1033-248	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								

261006	TAILCONE BLEED AIR OVERHEAT (E267) CONTROL BOX							Component ATA:26
PN:35009-20	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D6259	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02								

261007	TAILCONE BLEED AIR OVERHEAT (E268) CONTROL BOX							Component ATA:26
PN:PN	MOS/MSC	01-Mar-12	-	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02								

261008	TAILCONE BLEED AIR OVERHEAT (E269) CONTROL BOX							Component ATA:26
PN:PN	MOS/MSC	01-Mar-12	-	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02								
261051	NO. 1 TEE DOUBLE CHECK VALVE							Component ATA:26
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05								
261052	NO. 2 TEE DOUBLE CHECK VALVE							Component ATA:26
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05								
261207	BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY							Component ATA:26
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01								
262013	FORWARD FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:32700004-1	MOS/MSC	28-May-21	O/C	TSN 110, TSO 0				
SN:21497C1	HRS	2876		TSN 2876, TSO 0				
	AFL	2014		TSN 2014, TSO 0				
PROC. REF: AMM 26-21-03PROC. REF: AMM 26-21-03								
262013A	CHECK FORWARD FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY (REF TO 05-10-00)							Service ATA:26
PN:32700004-1	MOS	04-Apr-25	6 (+14d/-14d)		04-Oct-25	18-Oct-25	137 d (+14)	
SN:21497C1	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262013C	HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:32700004-1	MOS	21-May-21	60 (+14d/-14d)	Adj -14d	07-May-26	21-May-26	352 d (+14)	
SN:21497C1	HRS							
	AFL							
HydroCheck Date: : 21-May-21								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262014	AFT FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:32700004-1	MOS/MSC	28-May-21	O/C	TSO 0				
SN:20530C1	HRS	2876		TSO 0				
	AFL	2014		TSO 0				
PROC. REF: AMM 26-21-03PROC. REF: AMM 26-21-03								
262014A	CHECK AFT FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 05-10-00)							Service ATA:26
PN:32700004-1	MOS	04-Apr-25	6 (+14d/-14d)		04-Oct-25	18-Oct-25	137 d (+14)	
SN:20530C1	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								
262014C	HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:32700004-1	MOS	21-May-21	60 (+14d/-14d)	Adj -14d	07-May-26	21-May-26	352 d (+14)	
SN:20530C1	HRS							
	AFL							
HydroCheck Date: : 21-May-21								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262036	FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Component ATA:26
PN:AE30903823	MOS	28-May-21	72 (+14d/-14d)	TSN 1	28-Apr-27	12-May-27	708 d (+14)	SERVICE LIFE LIMIT
SN:877	HRS	2876		TSN 0				
	AFL	2014		TSN 0				
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262036A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Service ATA:26
PN:AE30903823	MOS	06-Apr-21	108 (+14d/-14d)		06-Apr-30	20-Apr-30	1782 d (+14)	LIFE LIMIT
SN:877	HRS							
	AFL							
		Manufacture Date:: 06-Apr-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								
262037	AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Component ATA:26
PN:AE30903823	MOS	28-May-21	72 (+14d/-14d)	TSN 1	28-Apr-27	12-May-27	708 d (+14)	SERVICE LIFE LIMIT
SN:856	HRS	2876		TSN 0				
	AFL	2014		TSN 0				
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								
262037A	REPLACE AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Service ATA:26
PN:AE30903823	MOS	06-Apr-21	108 (+14d/-14d)		06-Apr-30	20-Apr-30	1782 d (+14)	LIFE LIMIT
SN:856	HRS							
	AFL							
		Manufacture Date:: 06-Apr-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								
262038	FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB							Component ATA:26
PN:AE30903823	MOS	28-May-21	72 (+14d/-14d)	TSN 1	28-Apr-27	12-May-27	708 d (+14)	SERVICE LIFE LIMIT
SN:879	HRS	2876		TSN 0				
	AFL	2014		TSN 0				
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								
262038A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB							Service ATA:26
PN:AE30903823	MOS	06-Apr-21	108 (+14d/-14d)		06-Apr-30	20-Apr-30	1782 d (+14)	LIFE LIMIT
SN:879	HRS							
	AFL							
		Manufacture Date:: 06-Apr-21						
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262039	AFT ENGINE FIRE EXTINGUISHER AFT SQUIB							Component ATA:26
PN:AE30903823	MOS	28-May-21	72 (+14d/-14d)	TSN 1	28-Apr-27	12-May-27	708 d (+14)	SERVICE LIFE LIMIT
SN:868	HRS	2876		TSN 0				
	AFL	2014		TSN 0				
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								
262039A	REPLACE AFT ENGINE FIRE EXTINGUISHER AFT SQUIB							Service ATA:26
PN:AE30903823	MOS	06-Apr-21	108 (+14d/-14d)		06-Apr-30	20-Apr-30	1782 d (+14)	LIFE LIMIT
SN:868	HRS							
	AFL							
Manufacture Date:: 06-Apr-21								
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								
262041	PILOT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:A344	MOS/MSC	27-Apr-23	O/C	TSN 10				
SN:H-09443534	HRS	3073		TSN 0				
	AFL	2202		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262041A ^U	WEIGHT CHECK PILOT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	04-Apr-25	12		04-Apr-26		319 d	STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service ATA:26
PN:A344	MOS	01-Jun-22	144 (+14d/-14d)		01-Jun-34	15-Jun-34	3299 d (+14)	
SN:H-09443534	HRS							
	AFL							
HydroCheck Date: : 01-Jun-22								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262041C ^U	RESTORATION PILOT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	27-Apr-23	72		27-Apr-29		1438 d	STLMC
	HRS	3073						
	AFL	2202						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262042	COPILOT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:A344	MOS/MSC	27-Apr-23	O/C	TSN 10				
SN:H-09443533	HRS	3073		TSN 0				
	AFL	2202		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262042A ^U	WEIGHT CHECK COPILOT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	04-Apr-25	12		04-Apr-26		319 d	STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service ATA:26
PN:A344	MOS	01-Jun-22	144 (+14d/-14d)		01-Jun-34	15-Jun-34	3299 d (+14)	
SN:H-09443533	HRS							
	AFL							
HydroCheck Date: : 01-Jun-22								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262042C ^U	RESTORATION COPILOT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	27-Apr-23	72		27-Apr-29		1438 d	STLMC
	HRS	3073						
	AFL	2202						
262045	NO. 1 ENGINE FIRE - PULL SWITCH							Component ATA:26
PN:865201-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:905	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262046	NO. 2 ENGINE FIRE - PULL SWITCH							Component ATA:26
PN:865201-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:908	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01								
262050	APU FIRE EXTINGUISHER							Component ATA:26
PN:50-1200	MOS/MSC	30-Jul-17	O/C					
SN:10-1016	HRS	2497.8						
	AFL	1691						
PROC. REF: GENERIC NO REF, SMM 49-61-01PROC. REF: GENERIC NO REF, SMM 49-61-01								
262050C	INSPECT APU FIRE EXTINGUISHER WEIGHT CHECK AND REPLACE AS NECESSARY							Service ATA:26
PN:50-1200	MOS	04-Apr-25	12		04-Apr-26		319 d	
SN:10-1016	HRS	3222.8						
	AFL	2317						
WeightCheck Date : : 04-Apr-25								
PROC. REF: GENERIC NO REF, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-11-03								
262050D	CONTINUITY CHECK APU FIRE EXTINGUISHER PRESSURE SWITCH IAW SAFECRAFT CMM 26-20-02							Service ATA:26
PN:50-1200	MOS	04-Apr-25	12		04-Apr-26		319 d	
SN:10-1016	HRS	3222.8						
	AFL	2317						
PROC. REF: GENERIC NO REF, CMM 26-20-02PROC. REF: GENERIC NO REF, CMM 26-20-02								
262051	CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:C352	MOS/MSC	27-Apr-23	O/C	TSN 11				
SN:H-20651429	HRS	3073		TSN 0				
	AFL	2202		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262051A ^U	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	04-Apr-25	12		04-Apr-26		319 d	STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service ATA:26
PN:C352	MOS	01-May-22	144 (+14d/-14d)		01-May-34	15-May-34	3268 d (+14)	
SN:H-20651429	HRS							
	AFL							
HydroCheck Date: : 01-May-22								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262051C ^U	RESTORATION CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS	27-Apr-23	72		27-Apr-29		1438 d	STLMC
	HRS	3073						
	AFL	2202						
262057	APU FIRE BOTTLE SQUIB							Component ATA:26
PN:30900000M	MOS	18-Feb-20	60	TSN 0	01-Mar-29 (M)		1381 d	LIFE LIMIT
SN:3903WK	HRS	2780.2		TSN 0				
	AFL	1939		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-61-04, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-61-04, SMM 49-11-03								
26INSP ^U	LITHIUM BATTERY FIRE PROTECTION BAG AND GLOVE ANNUAL INSPECTION							Service ATA:26
PN:FP-CON-LG-HD	MOS	04-Apr-25	12		04-Apr-26		319 d	
SN:40547	HRS	3222.8						
	AFL	2317						
26LBFBG ^U	LITHIUM BATTERY FIRE PROTECTION BAG AND GLOVE							Component ATA:26
PN:FP-CON-LG-HD	MOS/MSC	06-Aug-20	O/C					
SN:40547	HRS							
	AFL							
26REPL ^U	LITHIUM BATTERY FIRE PROTECTION BAG AND GLOVE UNIT REPLACEMENT							Service ATA:26
PN:FP-CON-LG-HD	MOS	06-Aug-20	144		06-Aug-32		2635 d	
SN:40547	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
H2610010 ^S	INSPECT FIREWALL AND ACCESSORY GEARBOX FIRE DETECTOR ELEMENTS FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION.						Service	ATA:26
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
H2620020 ^S	DISCONNECT PLUMBING FROM THE FIRE EXTINGUISHER TWO-WAY CHECK VALVE ASSEMBLY. INSPECT FOR FREEDOM OF MOVEMENT OF THE TWO-WAY CHECK VALVE, EVIDENCE OF DEFECTS, WEAR, AND CORROSION. REPLACE VALVE CAP O-RING. (REFER TO 26-21-05.)						Service	ATA:26
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05								PKG:21
P2620041 ^S	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2
Q2620010 ^S	PERFORM WEIGHT CHECK OF FIRE EXTINGUISHER CONTAINERS. AFTER INSTALLATION OF CONTAINERS, PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM. (REFER TO 26-21-00).						Service	ATA:26
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								PKG:9
T2614000 ^S	PERFORM FUNCTIONAL TEST OF BAGGAGE COMPARTMENT SMOKE DETECTOR SYSTEM. (REFER TO 26-12-00)						Service	ATA:26
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 26-12-00PROC. REF: AMM 26-12-00								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
T2620045 ^S	INSPECT COPILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE							Service ATA:26
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
T2620045 ^S	INSPECT PILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.							Service ATA:26
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
U2610020A ^S	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT							Service ATA:26
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:29
U2610020B ^S	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT							Service ATA:26
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:30
ATA 27 - FLIGHT CONTROLS								
05-10-29-H2750044L	PERFORM DETAILED INSPECTION OF THE LEFT FLAP CAM FOLLOWER BEARING							Service ATA:27
	MOS	06-Mar-17						
	HRS	2340.8	1200 (+25/-25)		3540.8	3565.8	316.9 (+25)	
	AFL	1566						
PROC. REF: AMM 5-10-00PROC. REF: AMM 5-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-10-29-H2750044R	PERFORM DETAILED INSPECTION OF THE RIGHT FLAP CAM FOLLOWER BEARING							Service ATA:27
	MOS	06-Mar-17						
	HRS	2340.8	1200 (+25/-25)		3540.8	3565.8	316.9 (+25)	
	AFL	1566						
PROC. REF: AMM 5-10-00PROC. REF: AMM 5-10-00								
05-11-00-E2710010L	REPLACE LEFT * AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	3600		3600		376.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710010R	REPLACE RIGHT * AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	3600		3600		376.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710013L	* REPLACE LEFT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	3600		3600		376.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710013R	* REPLACE RIGHT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	3600		3600		376.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710020L	REPLACE LEFT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2710020R	REPLACE RIGHT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710022L	* REPLACE LEFT AILERON SECTOR (5425105) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-10PROC. REF: AMM 27-10-10								
05-11-00-E2710022R	* REPLACE RIGHT AILERON SECTOR (5425105) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-10PROC. REF: AMM 27-10-10								
05-11-00-E2710024L	* REPLACE LEFT AILERON CLEVIS (2324517) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710024R	* REPLACE RIGHT AILERON CLEVIS (2324517) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710026L	REPLACE LEFT * AILERON YOKE ASSEMBLY (2324511) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2710026R	REPLACE RIGHT * AILERON YOKE ASSEMBLY (2324511) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710028L	REPLACE LEFT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710028R	REPLACE RIGHT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710031L	REPLACE LEFT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2710031R	REPLACE RIGHT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2720020	REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2720022	REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-20-09PROC. REF: AMM 27-20-09								
05-11-00-E2720026	REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2730021L	REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-E2730021R	REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-E2730022L	REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-E2730022R	REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2730024L	REPLACE LEFT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2730024R	REPLACE RIGHT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2740010	REPLACE * HORIZONTAL STABILIZER HINGE PIN (2331028) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01								
05-11-00-E2750002L	REPLACE LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)							Service ATA:27
	MOS	06-Mar-17						
	HRS	2340.8	1200 (+25/-25)		3540.8	3565.8	316.9 (+25)	
	AFL	1566						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-E2750002R	REPLACE RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)							Service ATA:27
	MOS	06-Mar-17						
	HRS	2340.8	1200 (+25/-25)		3540.8	3565.8	316.9 (+25)	
	AFL	1566						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-E2750035L	REPLACE LEFT * FLAP SECTOR (2625031) (AWL*)							Service ATA:27
	MOS	01-Mar-12						
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2750035R	REPLACE RIGHT * FLAP SECTOR (2625031) (AWL*)							Service ATA:27
	MOS	01-Mar-12						
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-E2760059L	REPLACE LEFT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
05-11-00-E2760059R	REPLACE RIGHT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
05-11-00-E2760061L	REPLACE LEFT * SPOILER ACTUATOR ARM (2422511) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760061R	REPLACE RIGHT * SPOILER ACTUATOR ARM (2422511) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760062L	REPLACE LEFT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2760062R	REPLACE RIGHT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760063L	REPLACE LEFT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760063R	REPLACE RIGHT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760064LI	REPLACE LEFT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760064LO	REPLACE LEFT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760064RI	REPLACE RIGHT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2760064RO	REPLACE RIGHT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	4500		4500		1276.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-F2710036	REPLACE * PRIMARY AILERON CONTROL CABLES (AWL*)							Service ATA:27
	MOS	06-Mar-17						LIFE LIMIT
	HRS	2336.1	2400		4736.1		1512.2	
	AFL	1563						
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07								
05-11-00-F2720029	REPLACE PRIMARY RUDDER CONTROL CABLES							Service ATA:27
	MOS	06-Mar-17						
	HRS	2336.1	2400 (+25/-25)		4736.1	4761.1	1512.2 (+25)	
	AFL	1563						
PROC. REF: AMM 27-20-10PROC. REF: AMM 27-20-10								
05-11-00-F2730030	REPLACE * PRIMARY ELEVATOR CONTROL SYSTEM CABLES (AWL*)							Service ATA:27
	MOS	06-Mar-17						LIFE LIMIT
	HRS	2336.1	2400		4736.1		1512.2	
	AFL	1563						
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								
05-11-00-G2740011	REPLACE * HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6) (AWL*)							Service ATA:27
	MOS	16-Apr-24	144		16-Apr-36		3984 d	LIFE LIMIT
	HRS							
	AFL	2264	6000		8264		5945	
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								
05-11-00-G2750034L	REPLACE LEFT WING FLAP SECTOR MOUNTING BOLT							Service ATA:27
	MOS	16-Apr-24	144 (+14d/-14d)	Adj -46d	01-Mar-36	15-Mar-36	3938 d (+14)	
	HRS							
	AFL	2264	6000 (+25/-25)		8264	8289	5945 (+25)	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-G2750034R	REPLACE RIGHT WING FLAP SECTOR MOUNTING BOLT							Service ATA:27
	MOS	16-Apr-24	144 (+14d/-14d)	Adj -46d	01-Mar-36	15-Mar-36	3938 d (+14)	
	HRS							
	AFL	2264	6000 (+25/-25)		8264	8289	5945 (+25)	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750027LI	REPLACE LEFT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750027LO	REPLACE LEFT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750027RI	REPLACE RIGHT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750027RO	REPLACE RIGHT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750028	REPLACE * INBOARD NOSE ROLLER TRACK (2322511) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-L2750029	REPLACE * OUTBOARD NOSE ROLLER TRACK (2322512) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750033L	REPLACE LEFT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	10000		10000		7681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750033R	REPLACE RIGHT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	10000		10000		7681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-M2710021LI	REPLACE LEFT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-M2710021LO	REPLACE LEFT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-M2710021RI	REPLACE RIGHT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-M2710021RO	REPLACE RIGHT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-M2730031	REPLACE * HINGE ASSEMBLIES (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD)(LOCATED ON HORIZONTAL STABILIZER ASSEMBLY) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-M2750049LI	REPLACE LEFT INBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-M2750049LO	REPLACE LEFT OUTBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-M2750049RI	REPLACE RIGHT INBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-M2750049RO	REPLACE RIGHT OUTBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-N2750025	REPLACE * INBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625023) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750026	REPLACE * OUTBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625024) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750031	REPLACE * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-1 THRU-8) (AWL*)							Service ATA:27
	MOS/MSC	01-Mar-12	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750032	REPLACE * UPPER FLAP SECTOR BRACKET ASSEMBLY (6022511-1, -2, -801, AND -802) (AWL*)							Service ATA:27
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750051	REPLACE * INBOARD FLAP HINGE FITTING (P/N 6025022) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750052	REPLACE * OUTBOARD FLAP HINGE FITTING (P/N 6025021) (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-R2750050L	REPLACE LEFT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-R2750050R	REPLACE RIGHT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-R2760079L	REPLACE LEFT LEFT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	10000		10000		6776.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-R2760079R	REPLACE RIGHT RIGHT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)							Service ATA:27
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	10000		10000		6776.1	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
27-51-06-082	LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-082	LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-082	RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-082	RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-085	LEFT FLAP LEADING EDGE RIB							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-085	RIGHT FLAP LEADING EDGE RIB							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
270505	TRIM SWITCH PANEL ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01								
271013	AILERON TRIM TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271015	LEFT AILERON BALANCE TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-03PROC. REF: AMM 27-10-03								
271016	RIGHT AILERON BALANCE TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-03PROC. REF: AMM 27-10-03								
271019	AILERON TRIM ACTUATOR							Component ATA:27
PN:2R6203B	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:B0273	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-11PROC. REF: AMM 27-10-11								
271025	PILOT CONTROL WHEEL							Component ATA:27
PN:2415151-019	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3028	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-01PROC. REF: AMM 27-10-01								
271026	COPILOT CONTROL WHEEL							Component ATA:27
PN:2415151-020	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3000	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-01PROC. REF: AMM 27-10-01								
271027	PILOT CONTROL COLUMN							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-06PROC. REF: AMM 27-30-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271028	COPILOT CONTROL COLUMN							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-06PROC. REF: AMM 27-30-06								
271031	AILERON TRIM TAB ACTUATOR POTENTIOMETER							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-12PROC. REF: AMM 27-10-12								
271126	AILERON TRIM POSITION INDICATOR							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271131	LEFT AILERON POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:81319	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-06PROC. REF: AMM 27-10-06								
271132	RIGHT AILERON POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:81329	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-06PROC. REF: AMM 27-10-06								
271701	* LEFT AILERON ASSEMBLY (AWL*)							Component ATA:27
PN:2424000-325	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:W882	HRS	0	20000	TSN 0	20000		16776.1	
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271702	* RIGHT AILERON ASSEMBLY (AWL*)							Component ATA:27
PN:2424000-322	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:W851	HRS	0	20000	TSN 0	20000		16776.1	
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
272001	* RUDDER ASSEMBLY (AWL*)							Component ATA:27
PN:5433000-021	MOS	28-Mar-12						LIFE LIMIT
SN:W648	HRS	12.3	20000	TSN 12.3	20000		16776.1	
	AFL	11		TSN 11				
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								
272005	AFT RUDDER SECTOR							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-09PROC. REF: AMM 27-20-09								
272007	RUDDER TRIM TAB							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-02PROC. REF: AMM 27-20-02								
272013	RUDDER TRIM TAB ACTUATOR							Component ATA:27
PN:2R6204B	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:B0220	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03								
272020	RUDDER TRIM TAB POTENTIOMETER							Component ATA:27
PN:P30LS0GJS102KAG222	MOS/MSC	06-Mar-17	O/C	TSN 0				
SN:UNKNOWN	HRS	2336.1		TSN 0				
	AFL	1563		TSN 0				
PROC. REF: AMM 27-20-04PROC. REF: AMM 27-20-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272026	RUDDER TRIM INDICATOR							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-06PROC. REF: AMM 27-20-06								
272031	PILOT RUDDER PEDAL ACTUATOR							Component ATA:27
PN:EM423-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1008	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-07PROC. REF: AMM 27-20-07								
272032	COPILOT RUDDER PEDAL ACTUATOR							Component ATA:27
PN:EM423-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1001	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-07PROC. REF: AMM 27-20-07								
273001	* LEFT ELEVATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2434000-177	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:W844	HRS	0	20000	TSN 0	20000		16776.1	
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
273002	* RIGHT ELEVATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2434000-178	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:W182	HRS	0	20000	TSN 0	20000		16776.1	
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
2730036	ELEVATOR BELLCRANKS - PERFORM EDDY CURRENT INSPECTION							Service ATA:27
	MOS	16-Dec-21	96		16-Dec-29		1671 d	
	HRS	2931.7	2400		5331.7		2107.8	
	AFL	2060						
PROC. REF: NDT 27-30-01PROC. REF: NDT 27-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273013		STALL WARNING COMPUTER					Component	ATA:27
PN:54301-3L MOD A	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:M3501	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02								
273017		PILOT STICK SHAKER					Component	ATA:27
PN:EM20-7	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1224A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03								
273018		COPILOT STICK SHAKER					Component	ATA:27
PN:EM20-7	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1201A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03								
273101		PILOT STALL WARNING TRANSDUCER					Component	ATA:27
PN:25147A-12	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:DTE9519	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01								
273102		COPILOT STALL WARNING TRANSDUCER					Component	ATA:27
PN:25147A-12	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:DTE9512	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01								
273105		PILOT ANGLE-OF-ATTACK (AOA) INDICATOR					Component	ATA:27
PN:6608515-2	MOS/MSC	06-Mar-17	O/C	TSR 0				
SN:060566	HRS	2340.8		TSR 0				
	AFL	1566		TSR 0				
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273106	COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR							Component ATA:27
PN:152LV608	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11040010	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04								
273110	ANGLE-OF-ATTACK (AOA) VANE							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-05PROC. REF: AMM 27-31-05								
274001	HORIZONTAL STABILIZER							Component ATA:27
PN:2332000-60	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W519	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01								
274003	HORIZONTAL STABILIZER ACTUATOR CONTROLLER							Component ATA:27
PN:EM2079-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1391A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-03PROC. REF: AMM 27-40-03								
274010	TRIM-IN-MOTION DETECTOR							Component ATA:27
PN:231-1-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3YPGD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01								
274013	HORIZONTAL STABILIZER ACTUATOR							Component ATA:27
PN:5435005-028	MOS	31-Mar-22		TSO 0				OVERHAUL
SN:299	HRS	2973.4	600 (+25/-25)	TSO 0	3573.4	3598.4	349.5 (+25)	
	AFL	2090		TSO 0				
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
274062	PITCH TRIM INDICATOR							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04								
274070	STABILIZER POSITION SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11736	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-06PROC. REF: AMM 27-40-06								
274072	STABILIZER POSITION SENSOR							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275001	* LEFT FLAP ASSEMBLY (AWL*)							Component ATA:27
PN:6025010-041	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:W1640	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		7681	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
275002	* RIGHT FLAP ASSEMBLY (AWL*)							Component ATA:27
PN:6025010-042	MOS	06-Mar-17		TSR 0				LIFE LIMIT
SN:W1636	HRS	2340.8		TSR 0				
	AFL	1566	10000	TSN 0, TSR 0	11566		9247	
	APH							
	ACH							
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
275005	LEFT LOWER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275005	LEFT UPPER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275005	RIGHT LOWER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275005	RIGHT UPPER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
2750058	* LEFT FLAP LEADING EDGE RIB - REPLACE (AWL*)							Service ATA:27
	MOS/MSC	01-Mar-12	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	01-Mar-12	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	01-Mar-12	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* RIGHT FLAP LEADING EDGE RIB - REPLACE (AWL*)							Service ATA:27
	MOS/MSC	01-Mar-12	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	01-Mar-12	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	01-Mar-12	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
275010	FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275012	FLAP POSITION POTENTIOMETER							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-09PROC. REF: AMM 27-50-09								
275019	LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11705	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05								
275020	RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11706	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05								
275021	LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:2625045-042	MOS/MSC	08-Apr-12	O/C					
SN:UNKNOWN	HRS	25.8						
	AFL	20						
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								
275022	RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:2625045-040	MOS/MSC	08-Apr-12	O/C					
SN:UNKNOWN	HRS	25.8						
	AFL	20						
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								
275031	FLAP CONTROL (FLAP/SPOILER) VALVE							Component ATA:27
PN:65770	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1254A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07								
275036	FLAP RESTRICTOR VALVE							Component ATA:27
PN:2R1047-0312	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2340	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275037	LEFT FLAP ACTUATOR							Component ATA:27
PN:95906-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0735	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08								
275038	RIGHT FLAP ACTUATOR							Component ATA:27
PN:95906-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0736	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08								
275200	FLAP POSITION INDICATOR							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-10PROC. REF: AMM 27-50-10								
275213	FLAP PRESSURE RELIEF VALVE							Component ATA:27
PN:AN6245A4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:19320	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-13PROC. REF: AMM 27-50-13								
275217	FLAP ACTUATION CHECK VALVE							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-12PROC. REF: AMM 27-50-12								
276001	* LEFT SPOILER ASSEMBLY (AWL*)							Component ATA:27
PN:2422510-169	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:W2162	HRS	0	4500	TSN 0	4500		1276.1	
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
276002	* RIGHT SPOILER ASSEMBLY (AWL*)							Component ATA:27
PN:2422510-170	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:W2171	HRS	0	4500	TSN 0	4500		1276.1	
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
276005	LEFT SPOILER FLOW CONTROL SERVO VALVE							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								
276006	RIGHT SPOILER FLOW CONTROL SERVO VALVE							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								
276010	SPOILER COMPUTER							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02								
276013	* LEFT SPOILER ACTUATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2417015-5	MOS	29-Jul-15		TSN 0				LIFE LIMIT
SN:2841	HRS	1743.5	10000	TSN 0	11743.5		8519.6	
	AFL	1168		TSN 0				
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
276014	* RIGHT SPOILER ACTUATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2417015-5	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:2705	HRS	0	10000	TSN 0	10000		6776.1	
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
276037	LEFT SPOILER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:81338	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07								
276038	RIGHT SPOILER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:81285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07								
276043	SPOILER POTENTIOMETER							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09								
276049	SPOILER POSITION INDICATOR							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10								
276128	SPOILER MANIFOLD VALVE							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								
276265	WHEEL SPEED DETECTION BOX							Component ATA:27
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-12PROC. REF: AMM 27-60-12								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
AB2700049 ^S	REMOVE ALL PANELS REQUIRED TO GAIN ACCESS TO CABLES, PULLEYS, SECTORS, AND ASSOCIATED EQUIPMENT. VISUALLY INSPECT ACCESSIBLE PORTIONS OF FLIGHT CONTROLS FOR PROPER CONDITION, CABLE CLEARANCE, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO FLIGHT CONTROL CABLE CLEARANCES AT FUEL CROSSOVER TUBES.						Service	ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
E2700031 ^S	CHECK ELEVATOR AND RUDDER CONTROL CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEY, PULLEY BRACKETS, AND GUARDS FOR SECURITY AND GENERAL CONDITION.						Service	ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
E2700032 ^S	INSPECT CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION.						Service	ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
E2710005 ^S	HOLD CONTROL WHEEL INA FIXED POSITION AND APPLY UP AND DOWN LOADS ON THE AILERON TRAILING EDGE. OBSERVE AILERON DRIVE ASSEMBLY AREA FOR WEAR IN SHAFT KEYWAYS, FAILURE OF BEARINGS, AND AILERON YOKE SLIPPAGE.						Service	ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
E2730025 ^S	INSPECT CONTROL COLUMNS (INCLUDING CONTROL WHEELS AND BOOTS) FOR CONDITION, PROPER OPERATION, AND CLEARANCES.						Service	ATA:27
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H2700018 ^S	VISUALLY INSPECT SPOILER, FLAP, AILERON, AND AILERON TRIM TAB ELECTRICAL BONDING JMPERS FRO SECURITY AND GENERAL CONDITION.						Service	ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10
H2700021 ^S	INSPECT THE RUDDER AND ELEVATOR BALANCE WEIGHT INSTALLATIONS AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUC						Service	ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
H2700024 ^S	INSPECT THE AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUCTURE.						Service	ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
H2710032 ^S	CHECK AILERON, RUDDER, AND ELEVATOR CONTROL SYSTEM CABLE TENSIONS. (REFER TO 27-10-00, 27-20-00 AND 27-30-00.)						Service	ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 27-10-00, AMM 27-20-00, AMM 27-30-00PROC. REF: AMM 27-10-00, AMM 27-20-00, AMM 27-30-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H2731000 ^S	PERFORM STALL WARNING SYSTEM FUNCTIONAL TEST. (REFER TO 27-31-00)							Service ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00								PKG:7
P2700050 ^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.							Service ATA:27
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
P2700055 ^S	VISUALLY INSPECT ELEVATOR, RUDDER, AND RUDDER TRIM TAB ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION.							Service ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
P2700057 ^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.							Service ATA:27
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4
P2710044 ^S	CHECK AILERON AND FLAP SYSTEM CONTROL CABLE TENSIONS. (REFER TO 27-10-00 AND 27-50-00.)							Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 27-10-00, AMM 27-50-00PROC. REF: AMM 27-10-00, AMM 27-50-00								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
P2710045 ^S	REMOVE CONTROL WHEEL SECTOR AND TURNBUCKLE COVERPLATE FROM CONTROL COLUMN. MOVE CONTROL WHEEL TO BOTH EXTREME RIGHT AND LEFT WHILE INSPECTING FOR FRAYED OR DAMAGED CABLES.						Service	ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
P2710046 ^S	DISASSEMBLE CONTROL COLUMN AS REQUIRED TO INSPECT PULLEYS, BEARINGS, ELECTRICAL WIRING FOR PROPER ROUTING AND CHAFING, AND CONTROL COLUMNS FOR GENERAL CONDITION.						Service	ATA:27
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:19
P2760003 ^S	INSPECT SPOILER ACTUATOR INSTALLATION FOR SECURITY, SUPPORT STRUCTURE CRACKS, AND GENERAL CONDITION.						Service	ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10
Q2700051 ^S	INSPECT RUDDER AND ELEVATOR CONTROLS (INCLUDING DOWNSPRING INSTALLATION WHEN INSTALLED AND PUSH-PULL TUBES) FOR PROPER OPERATION, GENERAL CONDITION AND SECURITY.						Service	ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
T2700017 ^S	INSPECT STRUCTURE, PULLEY BRACKETS, AND CONTROLS UNDER FLOORBOARDS FROM PEDESTAL AND CONTROL COLUMN AFT TO FRAME 24 FOR OPERATION, CLEARANCES, CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO THE ELEVATOR PULLEY BRACKET CUTOUT AREA RADIUS FOR CRACKS. (S						Service	ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2700052	^S	USING THE PROPER COCKPIT CONTROLS, CHECK FLAPS, SPOILERS, HORIZONTAL STABILIZER, AND TRIM TABS FOR PROPER OPERATION AND ACCURATE INDICATION.						Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 27-40-00, AMM 27-50-00, AMM 27-60-00PROC. REF: AMM 27-40-00, AMM 27-50-00, AMM 27-60-00								PKG:13
T2700056	^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.						Service ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
T2700058	^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.						Service ATA:27
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
T2700059	^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.						Service ATA:27
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
T2700060	^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.						Service ATA:27
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T2710042 ^S	INSPECT AILERON AND AILERON TABS AND DRIVE MECHANISM FOR SECURITY, OPERATION, AND GENERAL CONDITION.							Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:16
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								
T2720027 ^S	INSPECT RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS FOR SECURITY, PROPER OPERATION, AND CLEARANCES.							Service ATA:27
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:20
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T2730029 ^S	CHECK CONTROL COLUMN ASSEMBLY FREE PLAY. (REFER TO 27-30-06.)							Service ATA:27
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:20
PROC. REF: AMM 27-30-06PROC. REF: AMM 27-30-06								
T2731075 ^S	FUNCTIONAL TEST OF STALL WARNING ALTITUDE SWITCHES. (REFER TO 27-31-00.)							Service ATA:27
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:19
PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00								
T2760030 ^S	INSPECT SPOILER AND HINGE INSTALLATION FOR SECURITY, CRACKS, AND GENERAL CONDITION.							Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:16
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2760031 ^S	INSPECT SPOILER CENTER ANGLE BRACKET RIVETS, LOWER SKIN CENTER RIB AND SUBSPAR RIVETS FOR EVIDENCE OF WORKING. WITH SPOILERS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO SPOILER TRAILING EDGE. CHECK MOTION AT CENTER HINGE. INSPECT SPOILER ACTUATOR MECHANISM AND							Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
T2760040 ^S	FUNCTIONAL TEST OF SPOILER RESTRICTOR BYPASS VALVE COMPUTER CIRCUITRY AND WIRING. (REFER TO 27-60-03.)							Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								PKG:16
T2760084 ^S	VISUAL INSPECTION SPOILER CENTER ANGLE BRACKET RIVETS AND UPPER AND LOWER SKIN CENTER RIB AREA. (REFER TO 5-10-00.)							Service ATA:27
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4
U2700033 ^S	INSPECT ALL CABLES, PULLEYS, SECTORS, AND PULLEY GUARD FOR PROPER OPERATION AND GENERAL CONDITION. PARTICULAR ATTENTION SHOULD BE GIVEN TO THOSE AREAS OF CABLES THAT PASS OVER PULLEYS, SECTORS, OR THROUGH FAIRLEADS.							Service ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10
U2710006 ^S	RUDDER TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK. (REFER TO 27-20-02.)							Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 27-20-02PROC. REF: AMM 27-20-02								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
U2710033 ^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK.							Service ATA:27
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								PKG:16
U2710034 ^S	GENERAL VISUAL INSPECTION AILERON TRIM TAB INSTALLATION. (REFER TO 5-10-00.)							Service ATA:27
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4
U2710035 ^S	GENERAL VISUAL INSPECTION RUDDER TRIM TAB INSTALLATION. (REFER TO 5-10-00)							Service ATA:27
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:6
U2731050 ^S	VISUAL INSPECTION ANGLE-OF-ATTACK VANES. (REFER TO 5-10-00)							Service ATA:27
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2
W2700062 ^S	CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. (REFER TO 5-10-00.)							Service ATA:27
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
05-10-29-L2812002L	INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602							Service ATA:28
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -47d	28-Feb-26	14-Mar-26	284 d (+14)	
	HRS	3150						
	AFL	2264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812002R	INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602							Service ATA:28
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -57d	18-Feb-26	04-Mar-26	274 d (+14)	
	HRS	3150						
	AFL	2264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812010L	INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA							Service ATA:28
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -57d	18-Feb-26	04-Mar-26	274 d (+14)	
	HRS	3150						
	AFL	2264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812010R	INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA							Service ATA:28
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -57d	18-Feb-26	04-Mar-26	274 d (+14)	
	HRS	3150						
	AFL	2264						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812020L	INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION							Service ATA:28
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -57d	18-Feb-26	04-Mar-26	274 d (+14)	
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812020R	INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION							Service ATA:28
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -57d	18-Feb-26	04-Mar-26	274 d (+14)	
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
05-10-29-T2820012	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS							Service ATA:28
	MOS/MSC	23-Mar-21	-					
	HRS	2858.6						
	AFL	2000						
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								
05-11-00-G2820003	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AIRCRAFT (PRESSURE)							Service ATA:28
	MOS	16-Apr-24	144 (+14d/-14d)	Adj -46d	01-Mar-36	15-Mar-36	3938 d (+14)	
	HRS							
	AFL	2264	6000 (+25/-25)		8264	8289	5945 (+25)	
PROC. REF: AMM 28-00-00PROC. REF: AMM 28-00-00								
280002	FUEL CONTROL SWITCH PANEL ASEMBLY							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-02PROC. REF: AMM 28-00-02								
280003	LEFT WING DEFUEL VALVE							Component ATA:28
PN:72DA0021	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0273	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-03PROC. REF: AMM 28-00-03								
280004	RIGHT WING DEFUEL VALVE							Component ATA:28
PN:72DA0021	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:-224	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-03PROC. REF: AMM 28-00-03								
281007	LEFT CHECK, CROSSFLOW VALVE							Component ATA:28
PN:P100-533	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-120988	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05PROC. REF: AMM 28-14-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281008	RIGHT CHECK, CROSSFLOW VALVE							Component ATA:28
PN:P100-533	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-120994	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05PROC. REF: AMM 28-14-05								
281201	AFT FUSELAGE FUEL CELL							Component ATA:28
PN:501847	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:T000066	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281202	FORWARD FUSELAGE FUEL CELL							Component ATA:28
PN:501848	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:T0001222	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02								
281283	FUSELAGE DRAIN VALVE							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281301	LEFT WING FUEL VENT FLOAT VALVE							Component ATA:28
PN:6600346-2	MOS/MSC	16-Apr-24	O/C					
SN:4035	HRS							
	AFL							
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01								
281302	RIGHT WING FUEL VENT FLOAT VALVE							Component ATA:28
PN:35C15G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4586	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281303	FUSELAGE FUEL VENT FLOAT VALVE							Component ATA:28
PN:35C15G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4577	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01								
281305	LEFT WING FLAME ARRESTOR							Component ATA:28
PN:9909018-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:588	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-03PROC. REF: AMM 28-13-03								
281306	RIGHT WING FLAME ARRESTOR							Component ATA:28
PN:9909018-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:588	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-03PROC. REF: AMM 28-13-03								
281307	LEFT FUEL CELL PRESSURE RELIEF VALVE							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-07PROC. REF: AMM 28-13-07								
281308	RIGHT FUEL CELL PRESSURE RELIEF VALVE							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-07PROC. REF: AMM 28-13-07								
281309	FUSELAGE FLAME ARRESTOR							Component ATA:28
PN:9909018-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:588	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-09PROC. REF: AMM 28-13-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281401	LEFT FUSELAGE CELL TRANSFER PUMP							Component ATA:28
PN:2380060-052	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C4613	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-01PROC. REF: AMM 28-14-01								
281402	RIGHT FUSELAGE CELL TRANSFER PUMP							Component ATA:28
PN:2380060-052	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C4736	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-01PROC. REF: AMM 28-14-01								
281403	LEFT INBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281404	RIGHT INBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281405	LEFT CENTER WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281406	RIGHT CENTER WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281407	LEFT OUTBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281408	RIGHT OUTBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281409	LEFT SCAVENGE PUMP							Component ATA:28
PN:2380060-053	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C4749	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-03PROC. REF: AMM 28-14-03								
281410	RIGHT SCAVENGE PUMP							Component ATA:28
PN:2380060-053	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C4748	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-03PROC. REF: AMM 28-14-03								
281411	LEFT FUEL TRANSFER VALVE							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-04PROC. REF: AMM 28-14-04								
281412	RIGHT FUEL TRANSFER VALVE							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-04PROC. REF: AMM 28-14-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281413	CROSSFLOW VALVE							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05PROC. REF: AMM 28-14-05								
281414	FUSELAGE HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L14F-110	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:213	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-07PROC. REF: AMM 28-14-07								
281415	LEFT FUEL TRANSFER PRESSURE INDICATING SWITCH							Component ATA:28
PN:P17M-42	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1524	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-06PROC. REF: AMM 28-14-06								
281416	RIGHT FUEL TRANSFER PRESSURE INDICATING SWITCH							Component ATA:28
PN:7600002-3	MOS/MSC	17-Apr-12	O/C					
SN:1599	HRS	34.5						
	AFL	27						
PROC. REF: AMM 28-14-06PROC. REF: AMM 28-14-06								
281417	LEFT WING HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	14-Sep-18	O/C	TSN 0				
SN:1691	HRS	2636.7		TSN 0				
	AFL	1832		TSN 0				
PROC. REF: AMM 28-14-08PROC. REF: AMM 28-14-08								
281418	RIGHT WING HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	07-Sep-18	O/C	TSN 0				
SN:1698	HRS	2629.8		TSN 0				
	AFL	1828		TSN 0				
PROC. REF: AMM 28-14-08PROC. REF: AMM 28-14-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281419	LEFT WING LOW-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:909	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-09PROC. REF: AMM 28-14-09								
281420	RIGHT WING LOW-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:898	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-09PROC. REF: AMM 28-14-09								
281421	FUEL FILL AND TRANSFER BOX							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-10PROC. REF: AMM 28-14-10								
282001	LEFT INBOARD JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01								
282002	RIGHT INBOARD JET PUMP							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01								
2820021	WHEEL WELL AND KEEL BEAM AREA - PERFORM DETAILED VISUAL INSPECTION OF FUEL TUBE FERRULE ENDS (UNDERNEATH COUPLING ASSEMBLIES) BETWEEN FS 346 AND FS 421 (FRAMES 24 AND 31) FOR EVIDENCE OF FATIGUE CRACKS, CORROSION OR OTHER DEGRADATION							Service ATA:28
	MOS	01-Nov-24	36 (+14d/-14d)	Adj -14d	18-Oct-27	01-Nov-27	881 d (+14)	
	HRS							
	AFL							
PROC. REF: AMM 28-20-00PROC. REF: AMM 28-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282003	LEFT STANDBY PUMP							Component ATA:28
PN:2380060-051	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C4758	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02								
282004	RIGHT STANDBY PUMP							Component ATA:28
PN:2380060-051	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C4760	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02								
282005	LEFT FUEL FILTER ASSEMBLY							Component ATA:28
PN:31B1616-01	MOS/MSC	30-Nov-16	O/C	TSN 0				
SN:UNKNOWN	HRS	2243.5		TSN 0				
	AFL	1515		TSN 0				
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								
282006	RIGHT FUEL FILTER ASSEMBLY							Component ATA:28
PN:31B1616-01	MOS/MSC	30-Nov-16	O/C	TSN 0				
SN:UNKNOWN	HRS	2243.5		TSN 0				
	AFL	1515		TSN 0				
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								
282007	LEFT ENGINE FUEL SHUTOFF VALVE							Component ATA:28
PN:EM91-42	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11-0221184	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								
282008	RIGHT ENGINE FUEL SHUTOFF VALVE							Component ATA:28
PN:EM91-42	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-1007251	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282009	LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE							Component ATA:28
PN:6600354-4	MOS/MSC	10-Dec-12	O/C					
SN:04-050548	HRS	217.7						
	AFL	172						
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282010	RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE							Component ATA:28
PN:EM91-41	MOS/MSC	20-Oct-23	O/C	TSR 0				
SN:08-0919221	HRS			TSR 0				
	AFL	2221		TSR 0				
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282011	LEFT ENGINE RELIEF VALVE							Component ATA:28
PN:4P168	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-030923	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07								
282012	RIGHT ENGINE RELIEF VALVE							Component ATA:28
PN:4P168	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-030935	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07								
282013	FUEL CONTROL RELAY PANEL							Component ATA:28
PN:6018810-006	MOS/MSC	06-Sep-12	O/C	TSR 0				
SN:A01860657-01	HRS	126.5		TSR 0				
	AFL	95		TSR 0				
PROC. REF: AMM 28-20-08PROC. REF: AMM 28-20-08								
282015	LEFT WING PILOT VALVE							Component ATA:28
PN:2780610-103	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2549	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282016	RIGHT WING PILOT VALVE							Component ATA:28
PN:2780610-103	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09								
282017	LEFT WING REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780614-104	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1632	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10								
282018	RIGHT WING REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780614-104	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1636	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10								
282019	FUSELAGE PILOT VALVE							Component ATA:28
PN:2780610-103	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2543	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11								
282020	FUSELAGE VENT VALVE							Component ATA:28
PN:2780612-104	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:998	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12								
282021	REFUELING CHECK VALVE							Component ATA:28
PN:2780623-102	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:828	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-13PROC. REF: AMM 28-20-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282022	FUSELAGE REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780624-103	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:948	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14								
282023	FUEL SOLENOID VALVE							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15								
282024	PRESSURE REFUELING ADAPTER							Component ATA:28
PN:2780609-102	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:942	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-16PROC. REF: AMM 28-20-16								
282025	LEFT PRECHECK VALVE							Component ATA:28
PN:2780615-103	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1788	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-17PROC. REF: AMM 28-20-17								
282026	RIGHT PRECHECK VALVE							Component ATA:28
PN:2780615-103	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1779	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-17PROC. REF: AMM 28-20-17								
282027	PRESSURE REFUELING CONTROL PANEL							Component ATA:28
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-18PROC. REF: AMM 28-20-18								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284001	LEFT INBOARD WING (MT5) FUEL PROBE							Component ATA:28
PN:2326014-016	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10101311	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284002	RIGHT INBOARD WING (MT6) FUEL PROBE							Component ATA:28
PN:2326014-12	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11020825	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284003	LEFT OUTBOARD WING (MT7) FUEL PROBE							Component ATA:28
PN:2326014-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10102384	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284004	RIGHT OUTBOARD WING (MT8) FUEL PROBE							Component ATA:28
PN:2326014-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10102372	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284005	LEFT INBOARD WING EXTENSION STA 189 (MT9) FUEL PROBE							Component ATA:28
PN:2826003-6	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10111712	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284006	RIGHT INBOARD WING EXTENSION STA 189 (MT10) FUEL PROBE							Component ATA:28
PN:2826003-6	MOS/MSC	28-Mar-12	O/C					
SN:12011741	HRS	12.3						
	AFL	11						
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284007	LEFT OUTBOARD WING EXTENSION STA 244 (MT11) FUEL PROBE							Component ATA:28
PN:2826003-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10121687	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284008	RIGHT OUTBOARD WING EXTENSION STA 244 (MT12) FUEL PROBE							Component ATA:28
PN:2826003-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11021699	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284009	FUSELAGE (MT18) FUEL PROBE							Component ATA:28
PN:0118KTU01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:FP033935	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284011	LEFT ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:28
PN:1G134-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4537	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
284012	RIGHT ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:28
PN:1G134-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4512	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
284013	FUEL QUANTITY INDICATOR							Component ATA:28
PN:2323-01-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:FM8500	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
E2820010 ^S	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS. ON AIRCRAFT EQUIPPED WITH PAPER FILTERS, REMOVE AND REPLACE FILTERS. (REFER TO 28-20-04)							Service ATA:28
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								PKG:3
H2812060 ^S	OPERATIONAL CHECK OF WING LOW FUEL WARNING SYSTEM. (REFER TO 28-14-00.)							Service ATA:28
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 28-14-00PROC. REF: AMM 28-14-00								PKG:16
H2820020 ^S	PERFORM OPERATIONAL CHECK OF FUEL SUPPLY SHUTOFF VALVE AND HYDRAULIC SUPPLY SHUTOFF VALVES. (REFER TO 28-20-05 AND 29-10-01)							Service ATA:28
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 28-20-05, AMM 29-10-01PROC. REF: AMM 28-20-05, AMM 29-10-01								PKG:7
T2812070 ^S	OPERATIONAL CHECK OF FUEL CROSSFLOW VALVE AND MOTIVE FLOW CONTROL VALVES. (REFER TO 28-14-00 AND 28-20-00.)							Service ATA:28
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 28-20-00, AMM 28-14-00PROC. REF: AMM 28-20-00, AMM 28-14-00								PKG:22
T2814021 ^S	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES. (REFER TO 28-13-07.)							Service ATA:28
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 28-13-07PROC. REF: AMM 28-13-07								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
T2814039 ^S	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK VACUUM RELIEF VALVES. (REFER TO 28-13-06.)							Service ATA:28
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 28-13-06PROC. REF: AMM 28-13-06								PKG:14
T2820001 ^S	VISUALLY INSPECT FUEL PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.) CHECK FUEL DRAINS FOR OPERATION.							Service ATA:28
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
T2820004 ^S	INSPECT LOWER INBOARD GEAR DOORS AND CHECK ENTIRE KEELBEAM AND WHEEL WELL AREA FOR FUEL OR HYDRAULIC LEAKS, PLUMBING FOR ROUTING, CLEARANCES, SECURITY OF CLAMPS, AND GENERAL CONDITION.							Service ATA:28
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17
ATA 29 - HYDRAULIC POWER								
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES(EXCLUDING HOSES FOR THE LANDING GEAR AND THE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)							Service ATA:29
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-L2910020	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS							Service ATA:29
	MOS/MSC	19-May-12	O/C					
	HRS	55.2						
	AFL	44						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
290002	HYDRAULIC PRESSURE REGULATOR							Component ATA:29
PN:55950-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0344	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-02PROC. REF: AMM 29-00-02								
290003	HYDRAULIC RESERVOIR							Component ATA:29
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-03PROC. REF: AMM 29-00-03								
290005	PRESSURE REGULATOR CHECK VALVE							Component ATA:29
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-05PROC. REF: AMM 29-00-05								
291001	LEFT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE							Component ATA:29
PN:AV24B1119B	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-0727223	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01								
291002	RIGHT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE							Component ATA:29
PN:AV24B1119B	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:06-0322311	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01								
291003	LEFT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:66137	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:K0890AB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291004	RIGHT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:66137	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:K0857AB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02								
291005	HYDRAULIC PRESSURE FILTER ASSEMBLY							Component ATA:29
PN:AC-9607F-10Y4	MOS/MSC	13-Oct-15	O/C					
SN:UNKNOWN	HRS	1812.9						
	AFL	1236						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
291006	HYDRAULIC RETURN FILTER ASSEMBLY							Component ATA:29
PN:M8815/1A-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0089	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
291007	HYDRAULIC SYSTEM ACCUMULATOR							Component ATA:29
PN:MS28700-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:8423-12980T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04								
291008	HYDRAULIC THRUST REVERSER ACCUMULATOR							Component ATA:29
PN:MS28700-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:8424-20871T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04								
291010	HYDRAULIC GROUND SERVICE PANEL							Component ATA:29
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291015	HYDRAULIC RELIEF VENT VALVE							Component ATA:29
PN:2380103-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-091578	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291020	HYDRAULIC RESERVOIR RELIEF VALVE							Component ATA:29
PN:5120T-8TT-20	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11-1201182	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								
291220	THRUST REVERSER ISOLATION VALVE							Component ATA:29
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-27PROC. REF: AMM 78-30-27								
291225	HYDRAULIC PRESSURE RELIEF VALVE							Component ATA:29
PN:5120T8TT20	MOS/MSC	23-Mar-21	O/C	TSN 25				
SN:N/A	HRS	2858.6		TSN 0				
	AFL	2000		TSN 0				
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								
292001	AUXILIARY HYDRAULIC PUMP							Component ATA:29
PN:6600248-1	MOS/MSC	15-Nov-17	O/C	TSO 0				
SN:SN01947	HRS	2516.3		TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01								
293001	HYDRAULIC PRESSURE MT15 TRANSDUCER							Component ATA:29
PN:124058-3000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:42504	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293002	AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730626	MOS/MSC	15-Nov-17	O/C	TSN 0				
SN:H1869	HRS	2516.3		TSN 0				
	AFL	1719		TSN 0				
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02								
293003	HYDRAULIC PRESSURE INDICATOR							Component ATA:29
PN:820-665	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:608	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03								
293005	LEFT HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730635	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D988	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04								
293006	RIGHT HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730635	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D978	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04								
293010	HYDRAULIC SYSTEM PRESSURE GAUGE							Component ATA:29
PN:S-218-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1762	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-05PROC. REF: AMM 29-30-05								
293015	THRUST REVERSER HYDRAULIC PRESSURE GAUGE							Component ATA:29
PN:S-218-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1759	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-05PROC. REF: AMM 29-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
H2910009 ^S	REMOVE AND CLEAN OR REPLACE AUXILIARY HYDRAULIC PUMP FILTER. (REFER TO 29-20-02.)							Service ATA:29
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02								PKG:15
P2910023 ^S	INSPECT HYDRAULIC RESERVOIR FILLER FILTER ELEMENT AND REPLACE IF REQUIRED. (REFER TO 29-00-04.)							Service ATA:29
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
Q2910019 ^S	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS. (REFER TO 29-10-03).							Service ATA:29
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								PKG:9
S2900004 ^S	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR PRESSURE RELIEF VALVE. (REFER TO 29-00-08.)							Service ATA:29
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								PKG:15
S2900005 ^S	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR VACUUM RELIEF VALVE. (REFER TO 29-00-08.)							Service ATA:29
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
S2910008 ^S	REMOVE HYDRAULIC RESERVOIR REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02.)						Service	ATA:29
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 29-00-01PROC. REF: AMM 29-00-01								PKG:15
S2910025 ^S	REMOVE HYDRAULIC RESERVOIR PRESSURE REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02)						Service	ATA:29
	MOS	27-Apr-23	24 (+14d/-14d)					
	HRS	3073	600 (+25/-25)					
	AFL	2202						
PROC. REF: AMM 29-00-01, AMM 29-00-02PROC. REF: AMM 29-00-01, AMM 29-00-02								PKG:9
T2900000 ^S	VISUALLY INSPECT HYDRAULIC PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.)						Service	ATA:29
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
W2910024 ^S	INSPECT HYDRAULIC FILTERS (PRESSURE AND RETURN) DIFFERENTIAL PRESSURE INDICATORS FOR BYPASS INDICATION.						Service	ATA:29
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								PKG:3
ATA 30 - ICE AND RAIN PROTECTION								
300001	COPILOT ELECTRICAL EQUIPMENT BOX						Component	ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-00-01PROC. REF: AMM 30-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301001	WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE							Component ATA:30
PN:15E51-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:DUK0110	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01								
301002	WING RT10 ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								
301003	WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								
301004	WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								
301005	WING OVERHEAT WARNING THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								
301006	WING TEMPERATURE INDICATOR							Component ATA:30
PN:820-685	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:769	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-04PROC. REF: AMM 30-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301007	LEFT WING ANTI-ICE BYPASS VALVE							Component ATA:30
PN:27441482-13	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5BG16	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								
301008	RIGHT WING ANTI-ICE BYPASS VALVE							Component ATA:30
PN:27441482-13	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5BG13	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05, AMM 30-10-06PROC. REF: AMM 30-10-05, AMM 30-10-06								
301009	LEFT WING BLEED AIR OVERHEAT SWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06								
301010	RIGHT WING BLEED AIR OVERHEAT SWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06								
301011	WING UNDERHEAT WARNING SWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07								
301014	WING ANTI-ICE VALVE							Component ATA:30
PN:6600259-3	MOS/MSC	16-Oct-15	O/C	TSN 0				
SN:255	HRS	1816.3		TSN 0				
	AFL	1240		TSN 0				
PROC. REF: AMM 30-10-05, AMM 30-10-08PROC. REF: AMM 30-10-05, AMM 30-10-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301015	LEFT WING ANTI-ICE CHECK VALVE							Component ATA:30
PN:1H95-8	MOS/MSC	28-Mar-19	O/C	TSN 6				
SN:7BR7	HRS	2762.6		TSN 0				
	AFL	1914		TSN 0				
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08								
301016	RIGHT WING ANTI-ICE CHECK VALVE							Component ATA:30
PN:1H95-8	MOS/MSC	28-Mar-19	O/C	TSN 48				
SN:2BM8	HRS	2762.6		TSN 0				
	AFL	1914		TSN 0				
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08								
301101	HORIZONTAL STABILIZER ANTI-ICE CONTROLLER							Component ATA:30
PN:807-1-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3RW2J	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-01PROC. REF: AMM 30-11-01								
301103	LEFT HORIZONTAL STABILIZER HEAT BLANKET (BOOT)							Component ATA:30
PN:4065-3481	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10-36891	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02PROC. REF: AMM 30-11-02								
301104	RIGHT HORIZONTAL STABILIZER HEAT BLANKET (BOOT)							Component ATA:30
PN:4065-3481	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11-55027	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-02PROC. REF: AMM 30-11-02								
301109	CBR9 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:106891	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03PROC. REF: AMM 30-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301110	CBR10 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:106982	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03PROC. REF: AMM 30-11-03								
301111	CBR11 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:106985	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03PROC. REF: AMM 30-11-03								
302101	LEFT NACELLE ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:27441482-09	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1BG7	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-01PROC. REF: AMM 30-21-01								
302102	RIGHT NACELLE ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:27441482-09	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4BG9	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-01PROC. REF: AMM 30-21-01								
302103	LEFT NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:7600020-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5515TW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02								
302104	RIGHT NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:7600020-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5516TW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
303001	LEFT PITOT HEAT MONITOR-							Component ATA:30
PN:76248-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3954	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
303002	RIGHT PITOT HEAT MONITOR-							Component ATA:30
PN:76248-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3898	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
303003	STANDBY PITOT HEAT MONITOR-							Component ATA:30
PN:76248-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3895	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
304001	WINDSHIELD ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:55510	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2933	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01								
304002	WINDSHIELD ANTI-ICE MODULATING VALVE							Component ATA:30
PN:27241287-12	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2BG3	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-02PROC. REF: AMM 30-40-02								
304003	WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE							Component ATA:30
PN:27441500	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2933	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-03PROC. REF: AMM 30-40-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304004	WINDSHIELD ANTI-ICE HEAT EXCHANGER							Component ATA:30
PN:5F295-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1217	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-04PROC. REF: AMM 30-40-04								
304005	WINDSHIELD ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:27431501-09	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1BG2	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-05PROC. REF: AMM 30-40-05								
304007	LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								
304008	RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								
304009	LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								
304010	RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304101	ALCOHOL SUPPLY TANK ASSEMBLY							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-01PROC. REF: AMM 30-41-01								
304102	ALCOHOL ANTI-ICE FLOAT SWITCH							Component ATA:30
PN:L14F7Y	MOS/MSC	14-Oct-14	O/C	TSN 0				
SN:1131	HRS	1274.4		TSN 0				
	AFL	882		TSN 0				
PROC. REF: AMM 30-41-02PROC. REF: AMM 30-41-02								
304104	ALCOHOL PRESSURE RELIEF VALVE							Component ATA:30
PN:4P152-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1652	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-04PROC. REF: AMM 30-41-04								
304105	ANTI-ICE THREE-WAY SHUTOFF VALVE							Component ATA:30
PN:56360-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1958	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-05PROC. REF: AMM 30-41-05								
304106	ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE							Component ATA:30
PN:6608257-1	MOS/MSC	23-Mar-21	O/C					
SN:560	HRS	2858.6						
	AFL	2000						
PROC. REF: AMM 30-41-06PROC. REF: AMM 30-41-06								
304203	WINDSHIELD DEFOG RELAY BOX							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-03PROC. REF: AMM 30-42-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
308001	LEFT ICE DETECT LAMP							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01								
308002	RIGHT ICE DETECT LAMP							Component ATA:30
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01								
G3010001 ^S	OPERATIONAL CHECK WING ANTI-ICE CHECK VALVE. (REFER TO 30-10-08).							Service ATA:30
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08								
H3020002 ^S	REMOVE INLET COWL ACCESS PANEL. VISUALLY INSPECT ANTI-ICE PLUMBING CONNECTOR FOR CONDITION, SECURITY, AND EVIDENCE OF LEAKAGE. (REFER TO 5-10-00)							Service ATA:30
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3020003 ^S	REMOVE UPPER ENGINE ACCESS COWL AND PERFORM A VISUAL INSPECTION OF NACELLE ANTI-ICE PLUMBING AND ALOCHOL PRESSURE LINE. (REFER TO 5-10-00)							Service ATA:30
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
T3040004 ^S	INSPECT WINDSHIELD DEFOG DUCTS AND EXTERNAL OUTLETS FOR SECURITY, CONTOUR, AND INTEGRITY OF SEALANT TO WINDSHIELD. CHECK THAT THE EXTERNAL ANTI-ICE NOZZLES ARE CLEAR OF OBSTRUCTIONS.							Service ATA:30
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
T3040008 ^S	FUNCTIONAL TEST OF WINDSHIELD ANTI-ICE SYSTEM TIMER CIRCUIT. (REFER TO 30-40-00.)							Service ATA:30
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								PKG:19
T3050003 ^S	OPERATIONAL CHECK OF ALCOHOL ANTI-ICE SYSTEM. (REFER TO 30-41-00.)							Service ATA:30
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 30-41-00PROC. REF: AMM 30-41-00								PKG:14
T3050009 ^S	CLEAN ALCOHOL ANTI-ICE FILTER ELEMENT. REPLACE FILTER ELEMENT IF MADE OF PAPER. (REFER TO 30-41-03.)							Service ATA:30
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 30-41-03PROC. REF: AMM 30-41-03								PKG:14
U3020001A ^S	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION							Service ATA:30
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:29

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
U3020001B ^S	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION							Service ATA:30
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
								PKG:30
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 31 - INDICATING/RECORDING SYSTEMS								
311006	TEST SWITCH PANEL ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-06PROC. REF: AMM 31-10-06								
311007	PILOT DISPLAY CONTROL (DCP) PANEL							Component ATA:31
PN:822-2117-202	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:45R0F	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-07PROC. REF: AMM 31-10-07								
311008	COPILOT DISPLAY CONTROL (DCP) PANEL							Component ATA:31
PN:822-2117-202	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:45R0G	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-07PROC. REF: AMM 31-10-07								
311009	LEFT CURSOR CONTROL (CCP) PANEL							Component ATA:31
PN:822-1746-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:462TD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-09PROC. REF: AMM 31-10-09								
311010	RIGHT CURSOR CONTROL (CCP) PANEL							Component ATA:31
PN:822-1746-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:462TC	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-10-09PROC. REF: AMM 31-10-09								
312001	PILOT CREW CLOCK							Component ATA:31
PN:M877	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:20569	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01								
312002	COPILOT CREW CLOCK							Component ATA:31
PN:M877	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:20576	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01								
313001	FLIGHT DATA (FDR) RECORDER							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313018	FDR INERTIA SWITCH							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313103	MULTI-AXIAL ACCELEROMETER							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
314002	IAPS CARD CAGE							Component ATA:31
PN:822-2018-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:48D8H	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-40-02PROC. REF: AMM 31-40-02								
314004	IAPS ENVIRONMENTAL (IEC) CONTROLLER							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-04PROC. REF: AMM 31-40-04								
314007	NO. 1 OPTIONS CONTROL MODULE							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-08PROC. REF: AMM 31-40-08								
314008	NO. 2 OPTIONS CONTROL MODULE							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-08PROC. REF: AMM 31-40-08								
314011	1A PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314012	2A PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314013	1B PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314014	2B PWR-851A POWER SUPPLY CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314021	1A FLIGHT CONTROL CARD							Component ATA:31
PN:822-1484-228	MOS/MSC	28-Mar-12	O/C					
SN:44D5R	HRS	12.3						
	AFL	11						
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314022	2A FLIGHT CONTROL CARD							Component ATA:31
PN:822-1484-228	MOS/MSC	28-Mar-12	O/C					
SN:44D6B	HRS	12.3						
	AFL	11						
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314031	1B FLIGHT MANAGEMENT - FMC 851C CARD							Component ATA:31
PN:822-0891-034	MOS/MSC	31-Mar-22	O/C	TSR 2				
SN:3B7LM	HRS	2973.4		TSR 0				
	AFL	2090		TSR 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314032	2B FLIGHT MANAGEMENT - FMC 851C CARD							Component ATA:31
PN:822-0891-034	MOS/MSC	28-Mar-12	O/C					
SN:4807C	HRS	12.3						
	AFL	11						
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314033	1B FLIGHT MANAGEMENT - FMC 852C CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314034	2B FLIGHT MANAGEMENT - FMC 852C CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314041	1A INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:822-1361-322	MOS/MSC	28-Mar-12	O/C					
SN:3J6TH	HRS	12.3						
	AFL	11						
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								
314042	2A INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:822-1361-322	MOS/MSC	28-Mar-12	O/C					
SN:46N2P	HRS	12.3						
	AFL	11						
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								
314043	1B INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								
314044	2B INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								
314047	NO. 1 CONFIGURATION STRAPPING (CSU) UNIT							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-40-05PROC. REF: AMM 31-40-05								
314048	NO. 2 CONFIGURATION STRAPPING (CSU) UNIT							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-05PROC. REF: AMM 31-40-05								
314101	DATA ACQUISITION UNIT							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01								
314110	MINI-FLIGHT DATA ACQUISITION (MFDAU) UNIT							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01								
315101	AURAL WARNING CONTROL UNIT							Component ATA:31
PN:883-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2348	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01								
315102	TONE GENERATOR							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-02PROC. REF: AMM 31-51-02								
315103	AURAL WARNING MIXER							Component ATA:31
PN:1882-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:903	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-51-03PROC. REF: AMM 31-51-03								
315201	GLARESHIELD ANNUNCIATOR PANEL							Component ATA:31
PN:828-1-18	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:208130057	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-52-01PROC. REF: AMM 31-52-01								
315203	MASTER CAUTION/WARNING TRIGGER UNIT ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-52-03PROC. REF: AMM 31-52-03								
316001	PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316002	COPILOT EFD-871 ELECTRONIC FLIGHT DISPLAY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316003	MULTIFUNCTION DISPLAY							Component ATA:31
PN:822-1753-020	MOS/MSC	28-Apr-15	O/C					
SN:33RXL	HRS	1631.7						
	AFL	1086						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316004	MULTIFUNCTION DISPLAY							Component ATA:31
PN:822-1753-020	MOS/MSC	28-Mar-12	O/C					
SN:3V12M	HRS	12.3						
	AFL	11						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316005	PILOT EFIS CONTROL PANEL							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02								
316006	COPILOT EFIS CONTROL PANEL							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02								
316007	LEFT OUTBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:822-1084-020	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-04PROC. REF: AMM 31-60-04								
316008	LEFT INBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:822-1084-020	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-04PROC. REF: AMM 31-60-04								
316009	RIGHT INBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:822-1084-020	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-04PROC. REF: AMM 31-60-04								
316010	RIGHT OUTBOARD ADAPTIVE FLIGHT DISPLAY							Component ATA:31
PN:822-1084-020	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-60-04PROC. REF: AMM 31-60-04								
316011	NO. 1 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316012	NO. 2 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316013	NO. 3 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316014	NO. 4 DISPLAY IMT-871 TRAY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316101	SENSOR DISPLAY UNIT							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01PROC. REF: AMM 31-61-01								
316102	SENSOR DISPLAY DRIVER UNIT							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-61-02PROC. REF: AMM 31-61-02								
316201	NO. 1 FILE SERVER (FSU) UNIT							Component ATA:31
PN:822-1543-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:48W2K	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-01PROC. REF: AMM 31-62-01								
316202	NO. 2 FILE SERVER (FSU) UNIT							Component ATA:31
PN:822-1543-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:48WBL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-01PROC. REF: AMM 31-62-01								
316203	NO. 1 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-03PROC. REF: AMM 31-62-03								
316204	NO. 2 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-03PROC. REF: AMM 31-62-03								
316301	MAINTENANCE WARNING PANEL ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-63-01PROC. REF: AMM 31-63-01								
31INTERL ^U	INTEGRA LR-60 ANNUNCIATOR PANEL LEFT & RIGHT PHOTOCELL OPS CHECK							Service ATA:31
	MOS	16-Apr-24	24		16-Apr-26		331 d	
	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
P3151001 ^S	PERFORM OPERATIONAL CHECK OF THE AUTOPILOT AURAL WARNING. (REFER TO 31-51-00) (EFFECTIVE ON AIRCRAFT 60-307, 60-319 AND SUBSEQUENT)							Service ATA:31
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 31-51-00PROC. REF: AMM 31-51-00								PKG:1
P3160001 ^S	PERFORM OPERATIONAL CHECK OF THE ELECTRONIC FLIGHT INSTRUCMENT SYSTEM (EFIS). (REFER TO 31-60-03)							Service ATA:31
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 31-60-03PROC. REF: AMM 31-60-03								PKG:7
T3110000 ^S	INSPECT EQUIPMENT INSTALLATIONS BETWEEN FORWARD PRESSURE BULKHEAD AND INSTRUMENT PANEL FOR SECURITY OF MOUNTING, WIRE ROUTING, AND CLEARANCES OF WIRING AND PLUMBING.							Service ATA:31
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:19
U3100001 ^S	GENERAL VISUAL INSPECTION INSTRUMENT PANEL (REFER TO 5-10-00.)							Service ATA:31
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
ATA 32 - LANDING GEAR								
05-11-00-E3211066	REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4)							Service ATA:32
	MOS	01-Mar-12						
	HRS	0						
	AFL	0	6000 (+25/-25)		6000	6025	3681 (+25)	
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-E3211074L	REPLACE LEFT * MLG UPPER BEARINGS (6041104) (AWL*)							Service ATA:32
	MOS/MSC	01-Mar-12	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211074R	REPLACE RIGHT * MLG UPPER BEARINGS (6041104) (AWL*)							Service ATA:32
	MOS/MSC	01-Mar-12	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211084L	REPLACE LEFT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)							Service ATA:32
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211084R	REPLACE RIGHT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)							Service ATA:32
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		17681	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211090L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)							Service ATA:32
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211090R	REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)							Service ATA:32
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-E3211092L	REPLACE LEFT * MLG UPPER BEARING (7600839) (AWL*)							Service ATA:32
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211092R	REPLACE RIGHT * MLG UPPER BEARING (7600839) (AWL*)							Service ATA:32
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211093L	REPLACE LEFT * MLG LOWER BEARING (6041105) (AWL*)							Service ATA:32
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211093R	REPLACE RIGHT * MLG LOWER BEARING (6041105) (AWL*)							Service ATA:32
	MOS	28-Mar-19						LIFE LIMIT
	HRS	2762.6						
	AFL	1914	6000		7914		5595	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR							Service ATA:32
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-G3233007	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS							Service ATA:32
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-G3243040	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN WHEEL WELL AREA							Service ATA:32
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-U3211091L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)							Service ATA:32
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-U3211091R	REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)							Service ATA:32
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		3681	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
321001	* LEFT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*)							Component ATA:32
PN:6041100-049	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:058	HRS	0		TSN 0				
	AFL	0	16500	TSN 0	16500		14181	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
321002	* RIGHT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*)							Component ATA:32
PN:6041100-050	MOS	28-Mar-19		TSN 84, TSR 0				LIFE LIMIT
SN:058	HRS	2762.6		TSN 2762.6, TSR 0				
	AFL	1914	16500	TSN 1914, TSR 0	16500		14181	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
321003	* LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)							Component ATA:32
PN:PN	MOS	01-Mar-12		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		3681	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321004	* RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)							Component ATA:32
PN:PN	MOS	01-Mar-12		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		3681	
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321005	* LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)							Component ATA:32
PN:PN	MOS	01-Mar-12		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		3681	
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321006	* RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)							Component ATA:32
PN:PN	MOS	01-Mar-12		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		3681	
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321501	LEFT HYDRAULIC, GEAR RETRACTION RESTRICTOR							Component ATA:32
PN:1R3665-035	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D7527	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321502	RIGHT HYDRAULIC, GEAR RETRACTION RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321511	LEFT HYDRAULIC, GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321512	RIGHT HYDRAULIC, GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:1R3665-059	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D2379	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321515	LEFT HYDRAULIC RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321516	RIGHT HYDRAULIC RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322001	* NOSE GEAR STRUT ASSEMBLY (AWL*)							Component ATA:32
PN:2342100-036	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:023	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		7681	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
322002	NOSE LANDING GEAR & STEERING ASSEMBLY STRUT							Component ATA:32
PN:2342003-109	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:023	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		7681	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
323019	LEFT MAIN LANDING GEAR SQUAT SWITCH							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-30-03PROC. REF: AMM 32-30-03								
323020	RIGHT MAIN LANDING GEAR SQUAT SWITCH							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-03PROC. REF: AMM 32-30-03								
323031	* LEFT MAIN LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:6600264-008	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:1434	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		17681	
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
323032	* RIGHT MAIN LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:7535-8	MOS	11-Aug-21						LIFE LIMIT
SN:1616A	HRS	2892.3						
	AFL	2032	20000		20000 (M)		17681	
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
323036 ^U	LEFT MAIN LANDING GEAR ACTUATOR ATTACH PIN							Component ATA:32
PN:5441101-1	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		17681	
323037 ^U	RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PIN							Component ATA:32
PN:5441101-1	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		17681	
323043	LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR							Component ATA:32
PN:6600085-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-31-03PROC. REF: AMM 32-31-03								
323044	RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR							Component ATA:32
PN:6600085-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-03PROC. REF: AMM 32-31-03								
323052	LANDING GEAR CONTROL PANEL ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-06PROC. REF: AMM 32-30-06								
323055	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6641	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
323056	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	22-Nov-15	O/C	TSN 0				
SN:6970	HRS	1881.7		TSN 0				
	AFL	1282		TSN 0				
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
323057	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6552	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-04PROC. REF: AMM 32-33-04								
323058	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6640	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-33-04PROC. REF: AMM 32-33-04								
323073	* NOSE LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:2317100-018	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:EAI-031	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		7681	
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
323079	NOSE LANDING GEAR UPLOCK ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	06-Mar-17	O/C	TSN 0				
SN:6936	HRS	2340.8		TSN 0				
	AFL	1566		TSN 0				
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02								
323080	UPLOCK, NOSE LANDING GEAR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6633	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-05PROC. REF: AMM 32-33-05								
323098	GEAR DOOR CONTROL VALVE							Component ATA:32
PN:65760	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1498	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-08PROC. REF: AMM 32-30-08								
323099	SELECT, LANDING GEAR VALVE							Component ATA:32
PN:48C48641	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0131T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-05PROC. REF: AMM 32-30-05								
323105	NOSE LANDING GEAR SHUTTLE VALVE							Component ATA:32
PN:2SV0614	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4954	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323110	NOSE LANDING GEAR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4954	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323205	LEFT MAIN LANDING GEAR EXTEND SHUTTLE VALVE							Component ATA:32
PN:92465	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4897	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323210	RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE							Component ATA:32
PN:92465	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4947	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323222	* LEFT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*)							Component ATA:32
PN:2341123-17	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		17681	
PROC. REF: AMM 32-31-05PROC. REF: AMM 32-31-05								
323223	* RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*)							Component ATA:32
PN:2341123-17	MOS	01-Mar-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		17681	
PROC. REF: AMM 32-31-05PROC. REF: AMM 32-31-05								
323305	LEFT MAIN LANDING GEAR DOOR SHUTTLE VALVE							Component ATA:32
PN:95930	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1447	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323310	RIGHT MAIN LANDING GEAR DOOR SHUTTLE VALVE							Component ATA:32
PN:95930	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1432	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323315	LEFT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323320	RIGHT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323401	AFT EMERGENCY GEAR BLOWDOWN EXTENSION VALVE							Component ATA:32
PN:53620-6	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2582	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-02PROC. REF: AMM 32-33-02								
323402	FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE							Component ATA:32
PN:53620-6	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2579	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-03PROC. REF: AMM 32-33-03								
323405	LEFT CHECK, FREEFALL VALVE							Component ATA:32
PN:7600833-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:NSN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-33-01PROC. REF: AMM 32-33-01								
323406	RIGHT CHECK, FREEFALL VALVE							Component ATA:32
PN:7600833-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0418	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-01PROC. REF: AMM 32-33-01								
323409	UPPER EMERGENCY GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:6R7742S-0135	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2582	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323410	LOWER EMERGENCY GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:6R7742S-0135	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2579	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323430	NO. 1 EMERGENCY AIR BLOWDOWN SHUTTLE VALVE							Component ATA:32
PN:95930	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1447	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324001	NOSE TIRE							Component ATA:32
PN:184F10-2	MOS/MSC	15-Feb-24	O/C	TSN 24				
SN:20250597	HRS	3131.2		TSN 0				
	AFL	2250		TSN 0				
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
324007	ASSEMBLY, NOSE WHEEL							Component ATA:32
PN:9544207-4	MOS/MSC	15-Feb-24	O/C	TSO 23				
SN:SEP10-10910	HRS	3131.2		TSO 0				
	AFL	2250		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
324013	NO. 1 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	15-Feb-24	O/C	TSN 14				
SN:23490521	HRS	3131.2		TSN 0				
	AFL	2250		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324014	NO. 2 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	15-Feb-24	O/C	TSN 12				
SN:30320409	HRS	3131.2		TSN 0				
	AFL	2250		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324015	NO. 3 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	04-Apr-25	O/C	TSN 16				
SN:33310452	HRS	3222.8		TSN 0				
	AFL	2317		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324016	NO. 4 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	15-Feb-24	O/C	TSN 8				
SN:31380560	HRS	3131.2		TSN 0				
	AFL	2250		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324020	NOSE TIRE PRESSURE SENSOR							Component ATA:32
PN:83-216-01	MOS/MSC	03-Feb-18	O/C	TSN 3				
SN:249084-6582	HRS	2517.1		TSN 0				
	AFL	1720		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324021	NO. 1 TIRE PRESSURE SENSOR							Component ATA:32
PN:83-216-01	MOS/MSC	03-Feb-18	O/C	TSN 3				
SN:249084-6580	HRS	2517.1		TSN 0				
	AFL	1720		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324022	NO. 2 TIRE PRESSURE SENSOR							Component ATA:32
PN:83-216-01	MOS/MSC	03-Feb-18	O/C	TSN 3				
SN:249084-6521	HRS	2517.1		TSN 0				
	AFL	1720		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324023	NO. 3 TIRE PRESSURE SENSOR							Component ATA:32
PN:83-216-01	MOS/MSC	04-Oct-24	O/C					
SN:NSN	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324024	NO. 4 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324037	NO. 1 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	15-Feb-24	O/C	TSO 6				
SN:AUG06-2289	HRS	3131.2		TSO 0				
	AFL	2250		TSO 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324037A	NDT INSPECT NO. 1 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC	15-Feb-24	O/C					
SN:AUG06-2289	HRS	3131.2						
	AFL	2250						
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324038	NO. 2 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	15-Feb-24	O/C	TSO 3				
SN:OCT99-1205	HRS	3131.2		TSO 0				
	AFL	2250		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324038A	NDT INSPECT NO. 2 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC	15-Feb-24	O/C					
SN:OCT99-1205	HRS	3131.2						
	AFL	2250						
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324039	NO. 3 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	04-Apr-25	O/C	TSO 35				
SN:AUG06-2293	HRS							
	AFL							
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324039A	NDT INSPECT NO. 3 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC		O/C					
SN:AUG06-2293	HRS							
	AFL							
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324040	NO. 4 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	15-Feb-24	O/C					
SN:SEPT10-3157	HRS	3131.2						
	AFL	2250						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324040A	NDT INSPECT NO. 4 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC	15-Feb-24	O/C					
SN:SEPT10-3157	HRS	3131.2						
	AFL	2250						
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324048	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:6600518-003	MOS/MSC	16-Apr-24	O/C					
SN:JAN04-0124	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324049	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:6600518-003	MOS/MSC	16-Apr-24	O/C					
SN:DEC03-0092	HRS							
	AFL							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324050	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:6600518-003	MOS/MSC	16-Apr-24	O/C					
SN:OCT11-1507	HRS							
	AFL							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324051	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:6600518-003	MOS/MSC	16-Apr-24	O/C					
SN:OCT09-1224	HRS							
	AFL							
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324061	NO. 1 POWER BRAKE, PILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2364	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324062	NO. 2 POWER BRAKE, PILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2395	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324063	NO. 1 POWER BRAKE, COPILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2330	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324064	NO. 2 POWER BRAKE, COPILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2331	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324085	NO. 1 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:98482-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0057	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324086	NO. 2 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:98482-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0075	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324109	NO. 3 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:98482-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0069	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324110	NO. 4 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:98482-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0062	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324133	AFT PARKING BRAKE VALVE							Component ATA:32
PN:95993-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0409	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04								
324134	FWD PARKING BRAKE VALVE							Component ATA:32
PN:95993-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0416	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04								
324145	NO. 1 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324146	NO. 2 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324147	NO. 3 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324148	NO. 4 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324169	LEFT ANTI-SKID VALVE							Component ATA:32
PN:39-309-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2821	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								
324170	RIGHT ANTI-SKID VALVE							Component ATA:32
PN:39-309-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2811A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								
324175	ANTI-SKID CONTROL							Component ATA:32
PN:42-379-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1973B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03								
324413	PARK BRAKE ANNUNCIATOR BOX ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-06PROC. REF: AMM 32-42-06								
324501	EMERGENCY BRAKE CONTROL VALVE							Component ATA:32
PN:63500-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:620A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-01PROC. REF: AMM 32-43-01								
324505	LEFT MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D19266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324510	RIGHT MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D19249	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324601	NO. 1 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D19257	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324602	NO. 2 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D19265	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324603	NO. 3 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D10267	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324604	NO. 4 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D19269	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
325001	NOSE WHEEL STEERING ACTUATOR							Component ATA:32
PN:501-1711-02	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:80129	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-05PROC. REF: AMM 32-50-05								
325005	NOSE WHEEL STEERING COMPUTER							Component ATA:32
PN:501-1708-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:80126	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04								
325015	LEFT RUDDER POSITION SENSOR							Component ATA:32
PN:501-1123-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:81242	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03								
325016	RIGHT RUDDER POSITION SENSOR							Component ATA:32
PN:501-1123-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:81265	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03								
325019	NOSE WHEEL STEERING ACTUATOR GEARBOX							Component ATA:32
PN:3142020-005	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:062	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02								
325020	NOSE WHEEL STEERING FOLLOW UP ASSEMBLY							Component ATA:32
PN:6087101-003-602	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:096	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-05PROC. REF: AMM 32-50-05								
325024	RIGHT NOSE WHEEL STEERING FOLLOWUP							Component ATA:32
PN:CU41096004-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5330	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01								
325025	LEFT NOSE WHEEL STEERING FOLLOWUP							Component ATA:32
PN:CU41096004-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5329	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01								
325628	AFT EMERGENCY GEAR CONTROL VALVE							Component ATA:32
PN:6600078-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326011	SQUAT SWITCH RELAY BOX							Component ATA:32
PN:6018325-008	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-07PROC. REF: AMM 32-30-07								
E3230020 ^S	INSPECT LANDING GEAR SQUAT SWITCHES FOR CONDITION.							Service ATA:32
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E3242000 ^S	INSPECT NOSE AND MAIN TIRES FOR WEAR, CUTS, ABRASIONS, AND FLAT SPOTS. CHECK CHINE CONDITION ON CHINED TIRE. (REFER TO 32-40-00)							Service ATA:32
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: AMM 32-40-00PROC. REF: AMM 32-40-00								
E3243010 ^S	INSPECT BRAKE ASSEMBLIES FO RWEAR, CRACKS, HYDRAULIC LEAKS, AND RELEASE.							Service ATA:32
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
E3244020 ^S	REMOVE AND CLEAN ANTI-SKID VALVE FILTERS. (REFER TO 32-42-01).							Service ATA:32
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								PKG:11
G3200000 ^S	PERFORM VISUAL INSPECTION OF LANDING GEAR SHOCK STRUTS FOR LEAKS AND GENERAL CONDITION. VISUALLY INSPECT LANDING GEAR SHOCK STRUTS AND LANDING GEAR ACTUATOR ATTACH POINTS FOR SECURITY AND GERNAL CONDITION. (REFER TO 5-10-00)							Service ATA:32
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5
H3210000 ^S	VISUALLY INSPECT MAIN AND NOSE LANDING GEAR STRUT ASSEMBLIES, ACTUATORS, FASTENERS, AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT NOSE GEAR ACTUATOR ATTACH BRACKET IN THE AREA AROUND THE GREASE FITTING. INSPECT FOR CRACKS EM							Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17
H3211010 ^S	INSPECT MAIN LANDING GEAR TORQUE LINKS FOR LOOSENESS.							Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17
H3211020 ^S	INSPECT INTERIOR AND EXTERIOR OF MAIN LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-11-00.)							Service ATA:32
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								PKG:23

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3221000	^S	INSPECT NOSE GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION.						Service ATA:32
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
H3221010	^S	INSPECT INTERIOR AND EXTERIOR OF NOSE LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-21-00.)						Service ATA:32
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								PKG:23
H3230000	^S	INSPECT LANDING GEAR ELECTRICAL WIRING FOR ROUTING AND GENERAL CONDITION.						Service ATA:32
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
H3230010	^S	PERFORM LANDING GEAR RETRACTION AND EXTENSION CHECK. CHECK AUTOMATIC BRAKE SNUBBING AND LANDING LIGHTS FOR RETRACT CUTOFF. (REFER TO 32-30-00.)						Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								PKG:17
H3230021	^S	INSPECT LANDING GEAR SQUAT SWITCHES FOR PROPER OPERATION AND CONDITION. (REFER TO 32-30-03.)						Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3231014 ^S	INSPECT MAIN GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FASTEMER CONDITION, AND PERMANENT DEFORMATION.							Service ATA:32
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
H3232002 ^S	INSPECT NOSE GEAR ACTUATOR BOOT AND HYDRAULIC PLUMBING FOR SECURITY AND GENERAL CONDITION.							Service ATA:32
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
H3233000 ^S	VISUALLY INSPECT GEAR FREE FALL, GEAR BLOW DOWN, AND EMERGENCY BRAKE VALVES AND FITTINGS FOR SECURITY OF ATTACHMENT. (REFER TO 5-10-00.)							Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
H3233012 ^S	PERFORM EMERGENCY AIR EXTENSION SYSTEM AND EMERGENCY BRAKE SYSTEM PLUMBING LEAKAGE CHECK. (REFER TO 32-33-00 AND 32-43-00.)							Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-33-00, AMM 32-43-00PROC. REF: AMM 32-33-00, AMM 32-43-00								PKG:17
H3243000 ^S	INSPECT BRAKE LINES FOR ROUTING AND LEAKS, MLG AND DOOR ACTUATOR ATTACH POINTS FOR SECURITY, AND STRUT HINGE POINTS FOR GENERAL CONDITION.							Service ATA:32
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3243023 ^S	INSPECT POWER BRAKE VALVES FOR SECURITY, OPERATION, AND LEAKS. ENSURE POWER BRAKE VALVE LEVER CONTACTS MECHANICAL STOP. (REFER TO 32-41-02.)							Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:14
H3243030 ^S	FUNCTIONAL TEST OF HYDRAULIC BRAKE FUSES. (REFER TO 32-41-03.)							Service ATA:32
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								PKG:23
N3243024 ^S	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.							Service ATA:32
	MOS	23-Mar-21	24 (+14d/-14d)					
	HRS	2858.6	600 (+25/-25)					
	AFL	2000						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:8
N3243050 ^S	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.							Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:14
Q3242001 ^S	OPERATIONAL CHECK ANTI-SKID VALVES (REFER TO 32-42-00)							Service ATA:32
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-42-00PROC. REF: AMM 32-42-00								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
T3211030 ^S	REMOVE AND REPLACE RETAINER RING LOCKSCREW FROM NOSE LANDING GEAR STRUT (P/N AN500A6-10).							Service ATA:32
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								PKG:11
T3231040 ^S	INSPECT MAIN LANDING GEAR DOOR ACTUATORS AND HINGES FOR SECURITY AND GENERAL CONDITION.							Service ATA:32
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
W3232003 ^S	NOSE LANDING GEAR FREE FALL UPLATCH ACTUATOR - PERFORM DETAILED CHECK. (REFER TO 32-33-05.)							Service ATA:32
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 32-33-05PROC. REF: AMM 32-33-05								PKG:17
ATA 33 - LIGHTS								
33-00-00-601 ^U	OPERATIONAL TEST OF THE PASSENGER COMPARTMENT LIGHTS							Service ATA:33
	MOS	04-Apr-25						STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
33-24-00-601 ^U	OPERATIONAL TEST OF THE ORDINANCE SIGNS							Service ATA:33
	MOS	04-Apr-25						STLMC
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-40-01 ^U	LH H-STAB LOGO LIGHT							Component ATA:33
PN:DA-27	MOS/MSC	19-Sep-18	O/C	TSN 2				
SN:UNKNOWN	HRS	2639.7						
	AFL	1834						
33-40-02 ^U	RH H-STAB LOGO LIGHT							Component ATA:33
PN:DA-27	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
33-50-00-601 ^U	GENERAL VISUAL INSPECTION OF THE EMERGENCY LIGHTING SYSTEM COMPONENTS							Service ATA:33
	MOS	17-Jan-17						STLMC
	HRS	2316.9	4800		7116.9		3893	
	AFL	1551						
331201	LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY							Component ATA:33
PN:6900115-000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6575	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02PROC. REF: AMM 33-12-02								
331202	RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY							Component ATA:33
PN:6900115-000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:6473	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02PROC. REF: AMM 33-12-02								
331303	QUAD EL (ELECTROLUMINESCENT) POWER SUPPLY							Component ATA:33
PN:SDA 16	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:593	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-13-03PROC. REF: AMM 33-13-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331311	PILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331312	COPILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331313	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331314	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331401	PILOT DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2594	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331402	COPILOT DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2588	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331403	CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2563	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331404	PEDESTAL DIMMING CONTROL BOX							Component ATA:33
PN:LT-48E	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10849	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331405	FUEL QUANTITY INDICATOR DIMMING CONTROL BOX							Component ATA:33
PN:LT-48E	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:10837	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331406	CDU LAMP DIMMING CONTROL BOX							Component ATA:33
PN:LT-48E	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331407	INSTRUMENT BACKLIGHTING FUSE BOX							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-02PROC. REF: AMM 33-14-02								
331601	LEFT ACS DIMMER CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331602	RIGHT ACS DIMMER CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331701	LEFT AFT LIGHT DIMMING (E215) CONTROL BOX							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-17-01PROC. REF: AMM 33-17-01								
331801	LEFT FORWARD LIGHT DIMMING (AE9) CONTROL BOX							Component ATA:33
PN:2618262-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-18-01PROC. REF: AMM 33-18-01								
331802	RIGHT LIGHT DIMMING (2AE9) CONTROL BOX							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-18-01PROC. REF: AMM 33-18-01								
332001	OVERHEAD INDIRECT LIGHTING (PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332002	OVERHEAD INDIRECT LIGHTING (2PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
332003	OVERHEAD INDIRECT LIGHTING (3PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332004	OVERHEAD INDIRECT LIGHTING (4PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332005	OVERHEAD INDIRECT LIGHTING (5PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332006	OVERHEAD INDIRECT LIGHTING (6PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332007	OVERHEAD INDIRECT LIGHTING (7PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332009	INDIRECT LIGHTING CONTROL							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-09PROC. REF: AMM 33-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
332010	ALTERNATE/MOMENTARY SWITCHING MODULE							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
332014	ZONE BACK LIGHTING CONTROL							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-14PROC. REF: AMM 33-20-14								
334101	LEFT LANDING AND TAXI LIGHT							Component ATA:33
PN:Q4681	MOS/MSC	25-Oct-18	O/C	TSN 0				
SN:UNKNOWN	HRS	2665.5		TSN 0				
	AFL	1856		TSN 0				
PROC. REF: AMM 33-41-01PROC. REF: AMM 33-41-01								
334102	RIGHT LANDING AND TAXI LIGHT							Component ATA:33
PN:Q4681	MOS/MSC	03-Oct-18	O/C	TSN 0				
SN:UNKNOWN	HRS	2648.7		TSN 0				
	AFL	1841		TSN 0				
PROC. REF: AMM 33-41-01PROC. REF: AMM 33-41-01								
334201	LEFT NAVIGATION LIGHT							Component ATA:33
PN:01-0770963-04	MOS/MSC	04-Sep-13	O/C	TSN 0				
SN:UNKNOWN	HRS	565.1		TSN 0				
	AFL	423		TSN 0				
PROC. REF: AMM 33-42-01PROC. REF: AMM 33-42-01								
334202	RIGHT NAVIGATION LIGHT							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01PROC. REF: AMM 33-42-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334203	TAIL NAVIGATION LIGHT							Component ATA:33
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-02PROC. REF: AMM 33-42-02								
334301	UPPER STROBE/BEACON LIGHT							Component ATA:33
PN:GE 16386-9-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1414577	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								
334302	LOWER STROBE/BEACON LIGHT							Component ATA:33
PN:GE 16386-9-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1443055	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								
334401	WING ICE INSPECTION LIGHT							Component ATA:33
PN:GLJ-140	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:12567	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-44-01PROC. REF: AMM 33-44-01								
334501	RECOGNITION LIGHT							Component ATA:33
PN:PN-UNKNOWN	MOS/MSC	14-Oct-14	O/C	TSN 0				
SN:UNKNOWN	HRS	1274.4		TSN 0				
	AFL	882		TSN 0				
PROC. REF: AMM 33-45-01PROC. REF: AMM 33-45-01								
334502	RECOGNITION LIGHT PULSE CONTROL UNIT							Component ATA:33
PN:2400-25-4-4	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-45-02PROC. REF: AMM 33-45-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
335001	EMERGENCY EXIT LIGHTING PANEL							Component ATA:33
PN:M6088221-012	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
335505	PILOT FLASHLIGHT							Component ATA:33
PN:P4-01-0030	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
335505A	REPLACE PILOT FLASHLIGHT BATTERIES							Service ATA:33
PN:P4-01-0030	MOS/MSC	01-Mar-12	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
335506	COPILOT FLASHLIGHT							Component ATA:33
PN:P4-01-0030	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
335506A	REPLACE COPILOT FLASHLIGHT BATTERIES							Service ATA:33
PN:P4-01-0030	MOS/MSC	01-Mar-12	A/R					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P3310004 ^S	CHECK OPERATION OF INTERIOR LIGHTING SYSTEMS							Service ATA:33
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
P3340012 ^S	CHECK OPERATION OF EXTERIOR LIGHTING SYSTEMS							Service ATA:33
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
ATA 34 - NAVIGATION								
05-10-29-W3411025	FUNCTIONAL TEST AIR DATA SYSTEM							Service ATA:34
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -47d	28-Feb-26	14-Mar-26	284 d (+14)	
	HRS							
	AFL							
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00								
05-10-30-RVSM-W3411015	PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00)							Service ATA:34
	MOS	04-Apr-25	12 (+14d/-14d)		04-Apr-26	18-Apr-26	319 d (+14)	
	HRS	3222.8						
	AFL	2317						
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00								
34-00-FAR-91.411	RECERTIFY PITOT-STATIC SYSTEM							Service ATA:34
	MOS	16-Apr-24	24		16-Apr-26		331 d	
	HRS							
	AFL							
PROC. REF: GENERIC NO REF, FAR FAR 91.411PROC. REF: GENERIC NO REF, FAR FAR 91.411								
340001-RVSM	RVSM AGHME HEIGHT MONITORING DUE EVERY 1000 HRS OR 24 MOS WHICHEVER IS THE LATER							Service ATA:34
	MOS	21-Feb-22						
	HRS	2965.6	1000		3965.6		741.7	
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341020	LEFT PITOT/STATIC PROBE							Component ATA:34
PN:856KR7	MOS	14-Jan-16		TSN 46				LIFE LIMIT
SN:230203	HRS	1976.1	15000 (+25/-25)	TSN 1976.1	15000	15025	11776.1 (+25)	
	AFL	1331		TSN 1331				
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341020A	VERIFY LEFT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016							Service ATA:34
PN:856KR7	MOS	16-Apr-24	24 (+14d/-14d)	Adj -47d	28-Feb-26	14-Mar-26	284 d (+14)	
SN:230203	HRS							
	AFL							
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341020B	DETAILED VISUAL INSPECTION LEFT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064							Service ATA:34
PN:856KR7	MOS	16-Apr-24	24 (+14d/-14d)	Adj -47d	28-Feb-26	14-Mar-26	284 d (+14)	
SN:230203	HRS							
	AFL							
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341025	RIGHT PITOT/STATIC PROBE							Component ATA:34
PN:856KR8	MOS	14-Jan-16		TSN 46				LIFE LIMIT
SN:267238	HRS	1976.1	15000 (+25/-25)	TSN 1976.1	15000	15025	11776.1 (+25)	
	AFL	1331		TSN 1331				
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341025A	VERIFY RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016							Service ATA:34
PN:856KR8	MOS	16-Apr-24	24 (+14d/-14d)	Adj -47d	28-Feb-26	14-Mar-26	284 d (+14)	
SN:267238	HRS							
	AFL							
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341025B	DETAILED VISUAL INSPECTION RIGHT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064							Service ATA:34
PN:856KR8	MOS	16-Apr-24	24 (+14d/-14d)	Adj -16d	31-Mar-26	14-Apr-26	315 d (+14)	
SN:267238	HRS							
	AFL							
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341026	STANDBY PITOT/STATIC PROBE							Component ATA:34
PN:856KR8	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:267237	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341105	PILOT RIGHT STATIC SHUTOFF VALVE							Component ATA:34
PN:AF56C-384	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0568T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								
341106	COPILOT RIGHT STATIC SHUTOFF VALVE							Component ATA:34
PN:AF56C-384	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0564T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								
341107	PILOT LEFT STATIC SHUTOFF VALVE							Component ATA:34
PN:AF56C-386	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0780T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								
341108	COPILOT LEFT STATIC SHUTOFF VALVE							Component ATA:34
PN:AF56C-386	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0784T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								
341133	NO. 1 LOWER (ADC) AIR DATA COMPUTER							Component ATA:34
PN:822-0389-629	MOS/MSC	03-Feb-18	O/C					
SN:3WHJH	HRS	2517.1						
	AFL	1720						
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341133A	RECERTIFY NO. 1 LOWER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM							Service ATA:34
PN:822-0389-629	MOS	16-Apr-24	24		16-Apr-26		331 d	
SN:3WHJH	HRS							
	AFL							
Calibration Date: : 16-Apr-24								
PROC. REF: FAR FAR 91.411, AMM 34-17-00PROC. REF: FAR FAR 91.411, AMM 34-17-00								
341134	NO. 2 UPPER (ADC) AIR DATA COMPUTER							Component ATA:34
PN:822-0389-629	MOS/MSC	03-Feb-18	O/C					
SN:3WHTP	HRS	2517.1						
	AFL	1720						
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01								
341134A	RECERTIFY NO. 2 UPPER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM							Service ATA:34
PN:822-0389-629	MOS	16-Apr-24	24		16-Apr-26		331 d	
SN:3WHTP	HRS							
	AFL							
Calibration Date: : 16-Apr-24								
PROC. REF: FAR FAR 91.411, AMM 34-17-00PROC. REF: FAR FAR 91.411, AMM 34-17-00								
341220	INTEGRATED / ELECTRONIC STANDBY INDICATOR SYSTEM 3 IN 1 GAUGE							Component ATA:34
PN:501-1860-0103	MOS/MSC	17-Jan-17	O/C	TSN 58				
SN:3431	HRS							
	AFL							
PROC. REF: AMM 34-19-01PROC. REF: AMM 34-19-01								
341220A	RECERTIFY INTEGRATED / ELECTRONIC STANDBY INDICATOR SYSTEM 3 IN 1 GAUGE							Service ATA:34
PN:501-1860-0103	MOS	16-Apr-24	24		16-Apr-26		331 d	
SN:3431	HRS							
	AFL							
PROC. REF: AMM 34-19-01PROC. REF: AMM 34-19-01								
341222	ESIS CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341225	STANDBY AIRSPEED INDICATOR							Component ATA:34
PN:2C131 (02B7C9)	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01								
341401	RADIO ALTIMETER TRANSCEIVER							Component ATA:34
PN:822-0615-205	MOS/MSC	25-Feb-15	O/C					
SN:1YF4D	HRS							
	AFL							
PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01								
341402	RADIO ALTIMETER CONVERTER							Component ATA:34
PN:622-7209-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02								
341403	AFT RADIO ALTIMETER ANTENNA							Component ATA:34
PN:622-0954-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4749	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-03PROC. REF: AMM 34-14-03								
341404	FORWARD RADIO ALTIMETER ANTENNA							Component ATA:34
PN:622-0954-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4751	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-03PROC. REF: AMM 34-14-03								
341703	FORWARD SIGNAL INTERFACE ADAPTER							Component ATA:34
PN:622-9732-003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:481BL	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02								
341704	AFT SIGNAL INTERFACE ADAPTER							Component ATA:34
PN:622-9732-003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4817M	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02								
341705	PILOT AIR DATA REFERENCE PANEL							Component ATA:34
PN:622-9500-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-03PROC. REF: AMM 34-17-03								
341706	COPILOT AIR DATA REFERENCE PANEL							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-03PROC. REF: AMM 34-17-03								
341707	TAT SENSOR PROBE							Component ATA:34
PN:102AU1AG	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:B3373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-04PROC. REF: AMM 34-17-04								
341709	PRIMARY ADC SWITCHING UNIT							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-06PROC. REF: AMM 34-17-06								
341710	SECONDARY ADC SWITCHING UNIT							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-17-06PROC. REF: AMM 34-17-06								
341801	STANDBY MACH/AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01								
342001	MAGNETIC COMPASS MAGNETOMETER							Component ATA:34
PN:C2350-L4-M23-5	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C407	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342025	AHRS COOLING FAN							Component ATA:34
PN:011035	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342055	NO. 1 FLUX DETECTOR UNIT							Component ATA:34
PN:622-5812-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:100300	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02								
342056	NO. 2 FLUX DETECTOR UNIT							Component ATA:34
PN:622-5812-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:100296	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02								
342057	NO. 1 INTERNAL COMPENSATOR (ICU-85) UNIT							Component ATA:34
PN:622-6189-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-26-04PROC. REF: AMM 34-26-04								
342058	NO. 2 INTERNAL COMPENSATOR (ICU-85) UNIT							Component ATA:34
PN:622-6189-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-04PROC. REF: AMM 34-26-04								
342301	STANDBY GYRO							Component ATA:34
PN:501-1197-05	MOS/MSC	01-Mar-12	N/A	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01								
342401	MAGNETIC COMPASS							Component ATA:34
PN:C2350-L4-M23-5	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C407	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-24-01PROC. REF: AMM 34-24-01								
342410	NO. 1 ATTITUDE/HEADING (AHC-85E) COMPUTER							Component ATA:34
PN:822-1110-002	MOS/MSC	21-Feb-18	O/C	TSR 70				
SN:228GR	HRS	2519.2		TSR 2493.4				
	AFL	1722		TSR 1702				
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342411	NO. 2 ATTITUDE/HEADING (AHC-85E) COMPUTER							Component ATA:34
PN:822-1110-002	MOS/MSC	21-Feb-18	O/C	TSN 71				
SN:46KJT	HRS	2519.2		TSN 2519.2				
	AFL	1722		TSN 1722				
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342412	NO. 1 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:34
PN:822-1200-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-26-06PROC. REF: AMM 34-26-06								
342413	NO. 2 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:34
PN:822-1200-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-06PROC. REF: AMM 34-26-06								
342501	STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR							Component ATA:34
PN:501-1567-02	MOS/MSC	01-Mar-12	N/A	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-25-01PROC. REF: AMM 34-25-01								
342605	AUXILIARY SWITCHING UNIT							Component ATA:34
PN:6018141-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03								
343007	MARKER BEACON (37X-2) ANTENNA							Component ATA:34
PN:522-0854-069	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04								
344007	NO. 1 GPS							Component ATA:34
PN:822-2189-002	MOS/MSC	28-Mar-12	O/C					
SN:4BNYX	HRS	12.3						
	AFL	11						
PROC. REF: AMM 34-54-02PROC. REF: AMM 34-54-02								
344008	NO. 2 GPS							Component ATA:34
PN:822-2189-002	MOS/MSC	28-Mar-12	O/C					
SN:4BP0F	HRS	12.3						
	AFL	11						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344111	LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA							Component ATA:34
PN:622-8973-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:42840	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344112	UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA							Component ATA:34
PN:622-8973-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:41948	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344143	TCAS (TTR-4000) PROCESSOR							Component ATA:34
PN:822-1294-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:175744	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01								
344151	STORMSCOPE PROCESSOR							Component ATA:34
PN:78-8060-6086-5	MOS/MSC	19-May-12	O/C					
SN:81442	HRS	55.2						
	AFL	44						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344153	STORMSCOPE DISPLAY							Component ATA:34
PN:78-8060-5900-8	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344155	STORMSCOPE ANTENNA							Component ATA:34
PN:78-8051-9200-8	MOS/MSC	01-Aug-12	O/C	TSN 0				
SN:83028	HRS	102.7		TSN 0				
	AFL	74		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344171	NO. 1 VHF/NAV ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:12195	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
344176	NO. 2 VHF/NAV ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:12196	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
344201	EFIS RADAR (ERP) PANEL							Component ATA:34
PN:6608222-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-07PROC. REF: AMM 34-61-07								
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA							Component ATA:34
PN:622-8440-004	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01								
344220	AV200 WSI ANTENNA							Component ATA:34
PN:305394	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344225	AV200 WSI SATELLITE RECEIVER							Component ATA:34
PN:305391-000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344226	WSI RECEIVER MOUNT TRAY							Component ATA:34
PN:305453-000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344513	TAWES COMPUTER							Component ATA:34
PN:3010-00-00	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344515	TAWES CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344520	TERRAIN AWARENESS ISOLATION BOX							Component ATA:34
PN:M6088265-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344806	WEATHER RADAR INDICATOR							Component ATA:34
PN:622-8440-003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344807	PILOT EFIS RADAR CONTROL PANEL							Component ATA:34
PN:1015-1-11	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-61-07PROC. REF: AMM 34-61-07								
344808	COPILOT EFIS RADAR CONTROL PANEL							Component ATA:34
PN:1015-1-11	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-07PROC. REF: AMM 34-61-07								
345001	NO. 1 ADF (ADF-462) RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:451LM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01								
345002	NO. 2 ADF (ADF-462) RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:451MH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01								
345005	ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER							Component ATA:34
PN:965-0976-040-226-226	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:EMK5-32457	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01								
345010	AUX GPWS/WINDSHEAR INDICATOR							Component ATA:34
PN:M6088303-003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345011	NO. 1 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3YDRX	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01								
345012	NO. 2 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:485JD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01								
345013	ADF, DUAL (ANT-462B) ANTENNA							Component ATA:34
PN:622-7384-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:463YM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-02PROC. REF: AMM 34-57-02								
345021	NO. 1 VHF (VIR 432) RECEIVER							Component ATA:34
PN:622-7194-201	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:451WX	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01PROC. REF: AMM 34-51-01								
345022	NO. 2 VHF (VIR 432) RECEIVER							Component ATA:34
PN:622-7194-201	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:451WJ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01PROC. REF: AMM 34-51-01								
345031	NO. 1 NAVIGATION COMPUTER							Component ATA:34
PN:822-1110-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:46KJT	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-06PROC. REF: AMM 34-61-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345032	NO. 2 NAVIGATION COMPUTER							Component ATA:34
PN:822-1110-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:46KJR	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-06PROC. REF: AMM 34-61-06								
345043	LEFT NAVIGATION (BLADE) ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:12195	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345044	RIGHT NAVIGATION (BLADE) ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:12196	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345045	NO. 1 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345046	NO. 2 VHF/NAV ANTENNA							Component ATA:34
PN:DMN4-15	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345079	PRIMARY ATC TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	28-Mar-19	O/C	TSO 1				
SN:26GDC	HRS	2762.6		TSO 0				
	AFL	1914		TSO 0				
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345079A	TEST/INSPECT PRIMARY ATC TRANSPONDER							Service ATA:34
PN:622-9210-501	MOS	16-Apr-24	24		16-Apr-26		331 d	
SN:26GDC	HRS							
	AFL							
Calibration Date: : 16-Apr-24								
PROC. REF: AMM 34-56-00, FAR FAR 91.413PROC. REF: AMM 34-56-00, FAR FAR 91.413								
345080	SECONDARY ATC TRANSPONDER							Component ATA:34
PN:622-9210-501	MOS/MSC	28-Mar-19	O/C	TSO 1				
SN:1L8NH	HRS	2762.6		TSO 0				
	AFL	1914		TSO 0				
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01								
345080A	TEST/INSPECT SECONDARY ATC TRANSPONDER							Service ATA:34
PN:622-9210-501	MOS	16-Apr-24	24		16-Apr-26		331 d	
SN:1L8NH	HRS							
	AFL							
Calibration Date: : 16-Apr-24								
PROC. REF: AMM 34-56-00, FAR FAR 91.413PROC. REF: AMM 34-56-00, FAR FAR 91.413								
345085	NO. 1 ATC TRANSPONDER CONTROL ADAPTER							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-03PROC. REF: AMM 34-56-03								
345086	NO. 2 ATC TRANSPONDER CONTROL ADAPTER							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-03PROC. REF: AMM 34-56-03								
345091	NO. 1 TRANSPONDER ANTENNA							Component ATA:34
PN:C1110-60-30	MOS/MSC	06-Mar-17	O/C	TSN 0				
SN:499071	HRS	2340.8		TSN 0				
	AFL	1566		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-56-02PROC. REF: AMM 34-56-02								
345092	NO. 2 TRANSPONDER ANTENNA							Component ATA:34
PN:CI100-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:345079	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-02PROC. REF: AMM 34-56-02								
345108	ADF PRIMARY ANTENNA							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-02PROC. REF: AMM 34-57-02								
345604	#2 MODE (S) TRANSPONDER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-02PROC. REF: AMM 34-56-02								
345605	NO. 1 DME ANTENNA							Component ATA:34
PN:CI100-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:345087	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-02PROC. REF: AMM 34-55-02								
345606	NO. 2 DME ANTENNA							Component ATA:34
PN:CI100-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:345074	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-02PROC. REF: AMM 34-55-02								
346004	DATA BASE - DBU-4000 UNIT							Component ATA:34
PN:622-9865-002	MOS/MSC	10-Jun-23	O/C	TSR 0				
SN:3RH8P	HRS			TSR 0				
	AFL			TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-60-04PROC. REF: AMM 34-60-04								
346005	HEADING SPEED ALTITUDE (HSA) CONTROL PANEL							Component ATA:34
PN:6034080011	MOS/MSC	30-Oct-12	O/C	TSO 0				
SN:A01817822	HRS	176.4		TSO 0				
	AFL	137		TSO 0				
PROC. REF: AMM 34-60-05PROC. REF: AMM 34-60-05								
346007	DATA LOAD (DLP) PANEL							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-07PROC. REF: AMM 34-60-07								
346011	NO. 1 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:822-0891-034	MOS/MSC	12-Aug-24	O/C	TSR 3				
SN:4F1KPH	HRS			TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 34-60-09PROC. REF: AMM 34-60-09								
346012	NO. 2 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:822-0891-034	MOS/MSC	12-Aug-24	O/C	TSR 1				
SN:352CY	HRS			TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 34-60-09PROC. REF: AMM 34-60-09								
346015	NO. 1 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:822-0884-364	MOS/MSC	19-Jun-23	O/C					
SN:42YVBC	HRS							
	AFL							
PROC. REF: AMM 34-60-01, AMM 34-61-01PROC. REF: AMM 34-60-01, AMM 34-61-01								
346016	NO. 2 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:822-0884-364	MOS/MSC	19-Jun-23	O/C					
SN:49DVH	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-60-01, AMM 34-61-01PROC. REF: AMM 34-60-01, AMM 34-61-01								
346021	PRIMARY FMS DATA TRANSFER (DTU) UNIT							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-04PROC. REF: AMM 34-61-04								
346022	SECONDARY FMS DATA TRANSFER (DTU) UNIT							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-04PROC. REF: AMM 34-61-04								
346025	NO. 1 FMS CONFIGURATION MODULE							Component ATA:34
PN:10171	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346026	NO. 2 FMS CONFIGURATION MODULE							Component ATA:34
PN:10171	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346031	PILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:822-0328-004	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-03, AMM 34-61-03PROC. REF: AMM 34-60-03, AMM 34-61-03								
346032	COPILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:822-0328-004	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-60-03, AMM 34-61-03PROC. REF: AMM 34-60-03, AMM 34-61-03								
346041	COURSE HEADING PANEL							Component ATA:34
PN:622-7397-006	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-02, AMM 34-61-02PROC. REF: AMM 34-60-02, AMM 34-61-02								
346055	CONFIGURATION, AFIS MODULE							Component ATA:34
PN:31990-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346071	UNILINK CONFIGURATION MODULE							Component ATA:34
PN:10651	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346090	AFIS DATA MANAGEMENT UNIT							Component ATA:34
PN:400-045500-0003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346091	DATA TRANSFER, AFIS UNIT							Component ATA:34
PN:15655-0101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346092	(#3) VHF ANTENNA							Component ATA:34
PN:VF10-347	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
347510	FORWARD GPS ANTENNA							Component ATA:34
PN:822-2189-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:4BNYX	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
347511	WAAS GPS ANTENNA							Component ATA:34
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
34VORC ^U	VOR/VOT CHECK							Service ATA:34
	MOS	04-Apr-25	12		30-Apr-26		345 d	
	HRS	3222.8						
	AFL	2317						
H3411010 ^S	INSPECT PITOT TUBES, STATIC AND PITOT LINES, DRAIN LINES, AND WIRING FOR CONDITION AND SECURITY. CHECK STATIC PORTS AND PITOT/STAIC PROBES FOR DISTORTION. CHECK OPERATION OF DRAIN VALVES. (REFER TO 34-11-02)							Service ATA:34
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								PKG:8
H3411012 ^S	INSPECT AIR TEMPERATURE SENSOR OR AIR DATA COMPUTER STATIC, PITOT, AND DRAIN LINES FOR CONDITION AND SECURITY. CHECK OPERATION OF DRAIN VALVES.							Service ATA:34
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
H3411031 ^S	PERFORM FUNCTIONAL TEST OF STATIC SHUTOFF (ISOLATION) VALVES. (REFER TO 34-11-00)							Service ATA:34
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 34-11-00PROC. REF: AMM 34-11-00								PKG:7
K3411061 ^S	PITOT-STATIC PROBE HEATING CURRENT SENSING RELAY - PERFORM FUNCTIONAL TEST. (REFER TO 30-30-01)							Service ATA:34
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								PKG:7
P3400004 ^S	INSPECT NOSE COMPARTMENT FROM THE FORWARD SIDE OF THE FORWARD PRESSURE BULKHEAD, FORWARD, FOR CLEANLINESS. ELECTRONIC AND ELECTRICAL EQUIPMENT AND ANTENNA INSTALLATIONS FOR SECURITY OF MOUNTING AND GENERAL CONDITION. WIRE BUNDLE AND PLUMBING ROUTING FOR SECURIT							Service ATA:34
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
T3453003 ^S	INSPECT ANTENNA INSTALLATIONS FOR SECURITY, CORROSION, AND PROPER TENSION OF HF ANTENNA WIRE. (REFER TO 23-12-03.)							Service ATA:34
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
U3411014 ^S	INSPECT PITOT STATIC PROBES - PERFORM PITOT-STATIC PROBE DRAIN HOLE CHECK. (REFER TO 34-11-02)							Service ATA:34
	MOS	04-Apr-25	12 (+14d/-14d)					
	HRS	3222.8	300 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-20-00-601	U	RESTORATION OF THE PASSENGER OXYGEN MASKS						Service ATA:35
	MOS	28-Mar-19						STLMC
	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
35-20-00-602 U FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM								
	MOS	28-Mar-19						STLMC
	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
35-20-00-603 U GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS								
	MOS	28-Mar-19						STLMC
	HRS	2762.6	600		3362.6		138.7	
	AFL	1914						
35-30-00-601 U DETAILED VISUAL INSPECTION OF THE PROTECTIVE BREATHING EQUIPMENT (PBE)								
	MOS	01-Jul-22						STLMC
	HRS	3030.1	600		3630.1		406.2	
	AFL	2143						
35-30-00-602 U DISCARD OF THE PROTECTIVE BREATHING EQUIPMENT (PBE)								
	MOS	01-Mar-12	240		01-Mar-32		2477 d	STLMC
	HRS	0						
	AFL	0						
350004 DORSAL OXYGEN SYSTEM PRESSURE TRANSDUCER								
PN:124058-2000	MOS/MSC	01-Mar-12	O/C	TSN 0				Component ATA:35
SN:43222	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-02PROC. REF: AMM 35-00-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350006	DORSAL OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY							Component ATA:35
PN:172180	MOS/MSC	28-Mar-12	O/C					
SN:0972	HRS	12.3						
	AFL	11						
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03								
350008	DORSAL OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:820-707	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0480	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-04PROC. REF: AMM 35-00-04								
351001	PILOT OXYGEN MASK							Component ATA:35
PN:174262-11	MOS/MSC	17-Aug-23	O/C	TSO 0				
SN:03087	HRS	3093.4		TSO 0				
	AFL	2221		TSO 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351001A	OVERHAUL PILOT OXYGEN MASK							Service ATA:35
PN:174262-11	MOS	28-Jul-23	72 (+14d/-14d)		28-Jul-29	11-Aug-29	1530 d (+14)	
SN:03087	HRS							
	AFL							
OverHaul Date:: 28-Jul-23								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
351002	COPILOT OXYGEN MASK							Component ATA:35
PN:174262-11	MOS/MSC	17-Aug-23	O/C	TSO 0				
SN:19151	HRS	3093.4		TSO 0				
	AFL	2221		TSO 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351002A	OVERHAUL COPILOT OXYGEN MASK							Service ATA:35
PN:174262-11	MOS	31-Jul-23	72 (+14d/-14d)		31-Jul-29	14-Aug-29	1533 d (+14)	
SN:19151	HRS							
	AFL							
OverHaul Date:: 31-Jul-23								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
351025	OXYGEN SYSTEM PRESSURE SWITCH							Component ATA:35
PN:P24028	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7035	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-07PROC. REF: AMM 35-00-07								
351071	PILOT CREW OXYGEN MASK BOX							Component ATA:35
PN:833-812-01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11070805	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351072	COPILOT CREW OXYGEN MASK BOX							Component ATA:35
PN:833-812-01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11070807	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
352007	DORSAL OXYGEN CYLINDER							Component ATA:35
PN:176194-76	MOS	16-Apr-24	288 (+14d/-14d)	TSN 115	30-Sep-38 (M)	14-Oct-38	4881 d (+14)	LIFE LIMIT
SN:639285402	HRS							
	AFL							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01								
352007A	HYDROSTATIC TEST DORSAL OXYGEN CYLINDER							Service ATA:35
PN:176194-76	MOS	16-Apr-24	36 (+14d/-14d)	Adj -46d	01-Mar-27	15-Mar-27	650 d (+14)	
SN:639285402	HRS							
	AFL							
HydroCheck Date: : 16-Apr-24								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
352027	PASSENGER OXYGEN CONTROL VALVE							Component ATA:35
PN:P21004-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0312	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-20-03PROC. REF: AMM 35-20-03								
352031	FORWARD SELECTOR, OXYGEN VALVE							Component ATA:35
PN:ZVC256	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05								
352032	AFT SELECTOR, OXYGEN VALVE							Component ATA:35
PN:ZVC256	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05								
352033	RIGHT AFT SELECTOR, OXYGEN VALVE							Component ATA:35
PN:ZVC179	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-06PROC. REF: AMM 35-00-06								
352040	PROTECTIVE BREATHING (PBE) EQUIPMENT							Component ATA:35
PN:802300-14	MOS	28-May-21	120 (+14d/-14d)		01-Apr-31	15-Apr-31	2142 d (+14)	LIFE LIMIT
SN:E21040074	HRS	2876		TSN 0				
	AFL	2014		TSN 0				
Manufacture Date:: 01-Apr-21								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353001	L1 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-812-02	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11070173	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
353002	R1 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-812-02	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11070175	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353003	L2 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-812-01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11070805	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353004	R3 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-812-02	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11040945	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353005	L3 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-812-02	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11080481	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353006	R4 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-812-02	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11070168	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353007	R2 OXYGEN MASK DROP BOX							Component ATA:35
PN:833-812-01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:D11070807	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
H3500020 ^S	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY.							Service ATA:35
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
P3510020 ^S	ON AIRCRAFT EQUIPPED WITH E.R.O.S. AVIATION CREW MASKS, PERFORM FUNCTIONAL TEST OF OXYGEN MASK. (REFER TO 35-10-01.)							Service ATA:35
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								PKG:13
T3500000 ^S	FUNCTIONAL TEST OF OXYGEN SYSTEM. (REFER TO 35-00-00.)							Service ATA:35
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00								PKG:14
T3500010 ^S	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY.							Service ATA:35
	MOS	23-Mar-21	48 (+14d/-14d)					
	HRS	2858.6	1200 (+25/-25)					
	AFL	2000						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
T3500040 ^S	CHECK CREW MEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) FOIL POUCH FOR VACUUM SEAL INTEGRITY. IF VACUUM SEAL IS BROKEN, REPLACE EQUIPMENT.							Service ATA:35
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
05-11-00-W3610011		REPLACE ENGINE BLEED AIR CHECK VALVES						Service ATA:36
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								
360001		REPLACE LEFT ENGINE PYLON BLEED AIR SEALS						Service ATA:36
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01								
360002		REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS						Service ATA:36
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01								
360003		REPLACE TAILCONE BLEED AIR SEALS (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) (REFER TO 36-10-01)						Service ATA:36
	MOS/MSC	01-Mar-12	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01								
361001		NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE						Component ATA:36
PN:10E87-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:DUK0307	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04								
361002		NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE						Component ATA:36
PN:10E87-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:DUK0313	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361007	LEFT MIXING VALVE CONTROL BOX							Component ATA:36
PN:5418553-19	MOS/MSC	26-Oct-23	O/C	TSR 7				
SN:A01997248-1	HRS			TSR 0				
	AFL	2221		TSR 0				
PROC. REF: AMM 36-10-05PROC. REF: AMM 36-10-05								
361008	RIGHT MIXING VALVE CONTROL BOX							Component ATA:36
PN:5418553-019	MOS/MSC	02-Feb-24	O/C	TSR 6				
SN:L06009923-01	HRS			TSR 0				
	AFL	2245		TSR 0				
PROC. REF: AMM 36-10-05PROC. REF: AMM 36-10-05								
361011	LEFT BLEED AIR MIXING VALVE							Component ATA:36
PN:1H106-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5BG18	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02								
361012	RIGHT BLEED AIR MIXING VALVE							Component ATA:36
PN:1H106-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:5BG17	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02								
361013	NO. 1 BLEED AIR CHECK VALVE							Component ATA:36
PN:6C1005	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3792	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								
361014	NO. 2 BLEED AIR CHECK VALVE							Component ATA:36
PN:6C1005	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3809	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361017	NO. 1 BLEED AIR (1 1/4) CHECK VALVE							Component ATA:36
PN:6600210-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361018	NO. 2 BLEED AIR (1 1/4) CHECK VALVE							Component ATA:36
PN:6600210-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361037	* NO. 1 EMERGENCY AIR BOTTLE (AWL*)							Component ATA:36
PN:6600194-008	MOS	27-Apr-23	180	TSR 33	31-Jul-32		2629 d	SCRAP
SN:0371	HRS	3073		TSR 271				
	AFL	2202		TSR 250				
Manufacture Date:: 31-Jul-17								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361037A	PERFORM * NO. 1 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST							Service ATA:36
PN:6600194-008	MOS	09-Mar-23	36 (+14d/-14d)		09-Mar-26	23-Mar-26	293 d (+14)	
SN:0371	HRS							
	AFL							
HydroCheck Date: : 09-Mar-23								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361037B	X-RAY INSPECT * NO. 1 EMERGENCY AIR BOTTLE							Service ATA:36
PN:6600194-008	MOS	31-Jul-17	T:108 (+14d/-14d)		31-Jul-26	14-Aug-26	437 d (+14)	
SN:0371	HRS							
	AFL							
X-Ray Date: : 31-Jul-17								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361038	* NO. 2 EMERGENCY AIR BOTTLE (AWL *)							Component ATA:36
PN:6600194-008	MOS	27-Apr-23	180	TSR 33	29-Jul-32		2627 d	SCRAP
SN:0618	HRS	3073		TSR 271				
	AFL	2202		TSR 250				
Manufacture Date:: 29-Jul-17								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361038A	PERFORM * NO. 2 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST							Service ATA:36
PN:6600194-008	MOS	09-Mar-23	36 (+14d/-14d)		09-Mar-26	23-Mar-26	293 d (+14)	
SN:0618	HRS							
	AFL							
HydroCheck Date: : 09-Mar-23								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361038B	PERFORM * NO. 2 EMERGENCY AIR BOTTLE X-RAY INSPECTION							Service ATA:36
PN:6600194-008	MOS	29-Jul-17	T:108 (+14d/-14d)		29-Jul-26	12-Aug-26	435 d (+14)	
SN:0618	HRS							
	AFL							
X-Ray Date: : 29-Jul-17								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361125	LEFT TAILCONE BLEED AIR CHECK VALVE							Component ATA:36
PN:M942-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1565	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361126	RIGHT TAILCONE BLEED AIR CHECK VALVE							Component ATA:36
PN:M942-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1558	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362001	LANDING GEAR/BRAKE AIR PRESSURE INDICATOR							Component ATA:36
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01								
362003	PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER							Component ATA:36
PN:124058-5000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:43128	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								
362004	SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER							Component ATA:36
PN:124058-5000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:43122	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								
362011	NO. 1 ENGINE HI-LIMIT BLEED AIR THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03								
362012	NO. 2 ENGINE HI-LIMIT BLEED AIR THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03								
362019	NO. 1 INBOARD OVERHEAT SWITCH							Component ATA:36
PN:M2-001-559	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:000506	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362020	NO. 2 INBOARD OVERHEAT SWITCH							Component ATA:36
PN:M2-001-559	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:000538	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3620001 ^S	FUNCTIONAL TEST OF PYLON OVERHEAT THERMOSTAT, DUCT TEMPERATURE SENSOR, AND ELECTRICAL SYSTEM. (REFER TO 36-20-03 AND 36-20-04.)							Service ATA:36
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 36-20-03, AMM 36-20-04PROC. REF: AMM 36-20-03, AMM 36-20-04								PKG:21
J3610037 ^S	VISUALLY INSPECT HIGH PRESSURE BLEED AIR CHECK VALVES							Service ATA:36
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								PKG:21
L3610039 ^S	PERFORM OPERATIONAL CHECK OF BLLED AIR CHECK VALVES. (REFER TO 36-10-03).							Service ATA:36
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								PKG:9
U3610044 ^S	GENERAL VISUAL INSPECTION BLEED AIR DUCTING (INCLUDING CLAMPS AND VALVES). (REFER TO 5-10-00)							Service ATA:36
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
381009	FORWARD TOILET DRAIN, HEATED MAST							Component ATA:38
PN:116393-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3051	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-32-01PROC. REF: AMM 38-32-01								
381010	AFT TOILET DRAIN, HEATED MAST							Component ATA:38
PN:116393-101	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:3064	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-32-01PROC. REF: AMM 38-32-01								
381020	TOILET WATER PUMP							Component ATA:38
PN:42510-0000	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381030	TOILET TIMER							Component ATA:38
PN:9060-2	MOS/MSC	11-Nov-15	O/C					
SN:UNKNOWN	HRS	1863.2						
	AFL	1270						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381050	TOILET MACERATOR							Component ATA:38
PN:5300-1	MOS/MSC	04-Oct-24	O/C	TSN 0				
SN:M8170	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381060	LAVATORY ON-DEMAND WATER SYSTEM VOLTAGE REGULATOR							Component ATA:38
PN:T2688253-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
381070	LAVATORY SINK PUMP							Component ATA:38
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
382015	NO. 1 HOT WATER TANK							Component ATA:38
PN:H60XWC-0401-01	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:102	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
383101	LAVATORY TOILET ASSEMBLY							Component ATA:38
PN:9060-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:U4409	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-31-01PROC. REF: AMM 38-31-01								
ATA 44 - CABIN SYSTEMS								
44-10-00-601 ^U	FUNCTIONAL TEST OF THE PASSENGER ADDRESS SYSTEM							Service ATA:44
	MOS	04-Apr-25					STLMC	
	HRS	3222.8	300		3522.8		298.9	
	AFL	2317						
442401	XM RADIO RECEIVER							Component ATA:44
PN:CI 429-410	MOS/MSC	28-Mar-12	O/C					
SN:367517	HRS	12.3						
	AFL	11						
PROC. REF: AMM 34-54-01PROC. REF: AMM 34-54-01								
442403	GPS/XM ANTENNA							Component ATA:44
PN:CI 429-410	MOS/MSC	28-Mar-12	O/C					
SN:369163	HRS	12.3						
	AFL	11						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 45 - CENTRAL MAINT SYSTEM								
451001	MAINTENANCE DIAGNOSTIC (MDC) COMPUTER							Component ATA:45
PN:822-1987-005	MOS/MSC	19-Jun-23	O/C	TSO 0				
SN:2854L	HRS			TSO 0				
	AFL			TSO 0				
PROC. REF: AMM 45-10-00PROC. REF: AMM 45-10-00								
ATA 49 - AIRBORNE AUXILIARY POWER								
490101	COCKPIT APU CONTROL PANEL							Component ATA:49
PN:201-6-035-9	MOS/MSC	10-Jun-15	O/C					
SN:4024-1	HRS	1686.8						
	AFL	1127						
PROC. REF: GENERIC NO REF, SMM 49-01-01PROC. REF: GENERIC NO REF, SMM 49-01-01								
490102	APU RELAY BOX							Component ATA:49
PN:201-6-028-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:003456	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-02PROC. REF: GENERIC NO REF, SMM 49-01-02								
490103	(ESU / DESU) ELECTRONIC SEQUENCE UNIT							Component ATA:49
PN:4506191	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0132	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-03, SMM 49-01-04PROC. REF: GENERIC NO REF, SMM 49-01-03, SMM 49-01-04								
490105	APU (GCU) GENERATOR CONTROL UNIT							Component ATA:49
PN:GCSG505-16G	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:50317	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-05PROC. REF: GENERIC NO REF, SMM 49-01-05								
490106	BITE ANNUNCIATOR BOX							Component ATA:49
PN:161212-100	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:AA0034	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-06PROC. REF: GENERIC NO REF, SMM 49-01-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
490109	UPPER CURRENT TRANSFORMER							Component ATA:49
PN:CTSG-700	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-09PROC. REF: GENERIC NO REF, SMM 49-01-09								
490110	LOWER CURRENT TRANSFORMER							Component ATA:49
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
490111	CURRENT SENSOR							Component ATA:49
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-10PROC. REF: GENERIC NO REF, SMM 49-01-10								
492001	APU - COMBUSTOR HOUSING ASSEMBLY							Component ATA:49
PN:160541-102	MOS/MSC	03-Jun-24	O/C	TSN 0				
SN:NSN	HRS	1219		TSN 0				
	APUS			TSN 0				
492002	APU - APU EXHAUST THERMOCOUPLE							Component ATA:49
PN:PN	MOS/MSC	08-Dec-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492020	APU - IGNITER							Component ATA:49
PN:PN-UNKNOWN	MOS/MSC	04-Apr-25	O/C	TSN 0				
SN:UNKNOWN	HRS	1276		TSN 0				
	APUS	2776		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
492201	APU - ROTOR BEARING							Component ATA:49
PN:161623-1	MOS/MSC	29-Dec-10	O/C					
SN:H053	HRS	1		TSN 1				
	APUS	11		TSN 11				
492202	APU - ROTOR BEARING							Component ATA:49
PN:161623-1	MOS/MSC	29-Dec-10	O/C					
SN:H054	HRS	1		TSN 1				
	APUS	11		TSN 11				
492300	APU - PRESSURE (LOW OIL) SWITCH							Component ATA:49
PN:PN	MOS/MSC	08-Dec-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492320	APU - SPEED (MAGNETIC PICK-UP) SENSOR							Component ATA:49
PN:169080-1	MOS/MSC	14-Jan-16	O/C	TSN 0				
SN:UNKNOWN	HRS			TSN 0				
	APUS			TSN 0				
493001	APU - FUEL CONTROL							Component ATA:49
PN:4502863D	MOS/MSC	08-Dec-11	O/C					
SN:10-11-07	HRS	1						
	APUS	9						
493003	APU - PUMP ASSEMBLY, FUEL CONTROL							Component ATA:49
PN:161627-3	MOS/MSC	08-Dec-11	O/C					
SN:V02-T0057	HRS	1						
	APUS	9						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493005	APU - FUEL ATOMIZER INTERCONNECT HARNESS							Component ATA:49
PN:4505684	MOS/MSC	29-Dec-10	O/C					
SN:1034	HRS	1		TSN 1				
	APUS	11		TSN 11				
493007	APU - ASSEMBLY, FUEL ATOMIZER							Component ATA:49
PN:PN	MOS/MSC	02-Dec-15	O/C					
SN:UNKNOWN	HRS							
	APUS							
493055	APU - ATOMIZER CUP MOTOR							Component ATA:49
PN:4953094	MOS/MSC	29-Dec-10	O/C					
SN:M107	HRS	1		TSN 1				
	APUS	11		TSN 11				
493101	APU FUEL SHUTOFF VALVE							Component ATA:49
PN:EM91-41	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11-032384	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-31-01PROC. REF: GENERIC NO REF, SMM 49-31-01								
493102	APU - FUEL PUMP							Component ATA:49
PN:PN-UNKNOWN	MOS/MSC	28-Oct-14	O/C					
SN:UNKNOWN	HRS							
	APUS							
493102	APU FUEL BOOST PUMP							Component ATA:49
PN:PN-UNKNOWN	MOS/MSC	28-Oct-14	O/C					
SN:UNKNOWN	HRS	1304.6						
	AFL	914						
PROC. REF: GENERIC NO REF, SMM 49-31-02PROC. REF: GENERIC NO REF, SMM 49-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
494001	APU - IGNITION EXCITER							Component ATA:49
PN:4951302	MOS/MSC	29-Dec-10	O/C					
SN:J10290002	HRS	1		TSN 1				
	APUS	11		TSN 11				
495001	APU - TURBINE WHEEL							Component ATA:49
PN:164253-3	MOS	29-Dec-10						LIFE LIMIT
SN:HA990	HRS	1		TSN 1				
	APUS	11	3500	TSN 11	3500		722	
495005	APU - COMPRESSOR WHEEL							Component ATA:49
PN:160915-4	MOS	29-Dec-10						LIFE LIMIT
SN:H345B	HRS	1		TSN 1				
	APUS	11	7000	TSN 11	7000		4222	
496103	APU FIRE HORN							Component ATA:49
PN:430-M1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-61-03PROC. REF: GENERIC NO REF, SMM 49-61-03								
497010	APU - HOURMETER/EVENT COUNTER INDICATOR							Component ATA:49
PN:PN	MOS/MSC	08-Dec-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
498010	EXHAUST (APU) DUCT							Component ATA:49
PN:801-6-015-9	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
49APU1	APU							Component ATA:49
PN:4503134	MOS/MSC	04-Jun-24	E/C					
SN:SP-E100536	HRS							
WC#: 49.APU1	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 52 - DOORS								
05-10-29-L5210025	VISUAL INSPECTION EXTERIOR LWR DOOR STRUCTURE/HINGE FOR CORROSION							Service ATA:52
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -57d	18-Feb-26	04-Mar-26	274 d (+14)	
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
521001	UPPER PASSENGER/CREW DOOR							Component ATA:52
PN:5410501-132	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W355	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00PROC. REF: AMM 52-10-00								
521002	LOWER PASSENGER/CREW DOOR							Component ATA:52
PN:5410536-036	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W460	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00PROC. REF: AMM 52-10-00								
521003	UPPER PASSENGER/CREW DOOR HANDLE							Component ATA:52
PN:4260-5	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1032165	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-02PROC. REF: AMM 52-10-02								
521004	UPPER PASSENGER/CREW DOOR LOCK ASSEMBLY							Component ATA:52
PN:AS000848	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:SG5974047	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-03PROC. REF: AMM 52-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
5210054	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE - REPLACE							Service ATA:52
	MOS/MSC		N/A					
	HRS							
	AFL	EFF						
PROC. REF: AMM 52-10-02, AMM 52-20-02PROC. REF: AMM 52-10-02, AMM 52-20-02								
521006	UPPER PASSENGER/CREW DOOR DAMPER							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-06PROC. REF: AMM 52-10-06								
521008	LOWER PASSENGER/CREW DOOR HANDLE							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-08PROC. REF: AMM 52-10-08								
521010	FORWARD PASSENGER/CREW LOWER DOOR CABLE							Component ATA:52
PN:6015550-007	MOS/MSC	23-Apr-20	O/C	TSN 0				
SN:N/A	HRS	2801.2		TSN 0				
	AFL	1949		TSN 0				
PROC. REF: AMM 52-10-10PROC. REF: AMM 52-10-10								
521011	AFT PASSENGER/CREW LOWER DOOR CABLE							Component ATA:52
PN:6015550-002	MOS/MSC	29-Oct-19	O/C	TSN 0				
SN:UNKNOWN	HRS	2778.5		TSN 0				
	AFL	1936		TSN 0				
PROC. REF: AMM 52-10-10PROC. REF: AMM 52-10-10								
521012	LOWER PASSENGER/CREW DOOR DAMPER							Component ATA:52
PN:1025-9400-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1317	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
522000	EMERGENCY EXIT / BAGGAGE DOOR							Component ATA:52
PN:6011501-016	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W424	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								
522002	EMERGENCY EXIT / BAGGAGE DOOR HANDLE							Component ATA:52
PN:4261-5	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1020779	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-02PROC. REF: AMM 52-20-02								
522005	PASSENGER DOOR FORWARD SNUBBER							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-15PROC. REF: AMM 52-10-15								
522006	PASSENGER DOOR AFT SNUBBER							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-15PROC. REF: AMM 52-10-15								
522007	EMERGENCY EXIT DOOR FORWARD SNUBBER							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07								
522008	EMERGENCY EXIT DOOR AFT SNUBBER							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
522025	EMERGENCY EXIT/BAGGAGE DAMPER							Component ATA:52
PN:12754-0012-003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								
522032	EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY							Component ATA:52
PN:LA6600405-30	MOS/MSC	14-Mar-19	O/C	TSN 0				
SN:I0014	HRS	2762.6		TSN 0				
	AFL	1914		TSN 0				
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06								
522032A	PRISM CHECK EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY 05-10-29-M5600008							Service ATA:52
PN:LA6600405-30	MOS	14-Mar-19						
SN:I0014	HRS	2762.6	T:600 (+25/-25)		3362.6	3387.6	138.7 (+25)	
	AFL	1914						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
523101	TAILCONE BAGGAGE DOOR							Component ATA:52
PN:5412500-021	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W344	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-01PROC. REF: AMM 52-31-01								
523102	TAILCONE BAGGAGE HANDLE							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-01PROC. REF: AMM 52-31-01								
524001	PERFORM AFT AVIONICS DOOR GAP AND MISMATCH INSPECTION (RVSM) (REFER TO 52-40-01)							Service ATA:52
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -47d	28-Feb-26	14-Mar-26	284 d (+14)	
	HRS							
	AFL							
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
524003	LEFT FORWARD NOSE AVIONICS DOOR							Component ATA:52
PN:6010430-003-903	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524004	RIGHT FORWARD NOSE AVIONICS DOOR							Component ATA:52
PN:6010430-003-903	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524005	LEFT AFT NOSE AVIONICS DOOR							Component ATA:52
PN:6010430-003-903	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524006	RIGHT AFT NOSE AVIONICS DOOR							Component ATA:52
PN:6010430-003-903	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524007	TAILCONE AVIONICS DOOR							Component ATA:52
PN:5412500-021	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W344	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02								
527005	CREW DOOR WARNING BOX ASSEMBLY							Component ATA:52
PN:5418316-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-70-05PROC. REF: AMM 52-70-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
527006	EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY							Component ATA:52
PN:5418316-10	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-70-05PROC. REF: AMM 52-70-05								
528001	LEFT INBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528002	RIGHT INBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528003	LEFT OUTBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528004	RIGHT OUTBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528101	LEFT NOSE LANDING GEAR DOOR							Component ATA:52
PN:5410450-19	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:60-410	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
528102	RIGHT NOSE LANDING GEAR DOOR							Component ATA:52
PN:5410450-20	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:60-410	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01								
AA5210056 ^S	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION							Service ATA:52
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PKG:18								
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								
E5220010 ^S	EMERGENCY EXIT/BAGGAGE DOOR HINGE INSTALLATION FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT HINGE INSTALLATIONS WHILE RACKING THE DOOR WITH ALTERNATING LOADS.							Service ATA:52
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PKG:18								
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								
E5220020 ^S	EMERGENCY EXIT/BAGGAGE DOOR HANDLE AND CONTROL ASSEMBLY FREE PLAY CHECK. OPEN DOOR AND REMOVE UPHOLSETRY TO GAIN ACCESS TO ROD CONTROL ASSEMBLY. RESTRAIN THE DOOR PINS AND MOVE THE EMERGENCY EXIT/BAGGAGE DOOR HANDLE TOWARD THE CLOSED POSITION AND THEN TO							Service ATA:52
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PKG:18								
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								
E5280002 ^S	VISUALLY INSPECT TAILCONE AVIONICS AND BAGGAGE DOOR ELECTRICAL BONDING JUMPERS, WHEN INSTALLED, FOR SECURITY AND GENERAL CONDITION							Service ATA:52
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PKG:6								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
H5210020 ^S	UPPER AND LOWER DOOR HINGE INSTALLATIONS FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT EDGES OF HINGE INSTALLATION WHILE RACKING THE DOORS WITH ALTERNATING LOADS. IF HINGE INSTALLATION CONDITION REQUIRES A MORE THO							Service ATA:52
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:24
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5210040 ^S	CLEAN ARM GUIDES OF PASSENGER/CREW UPPER DOOR AND VISUALLY CHECK FOR CRACKS. (SEE FIGURE 1.)							Service ATA:52
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5210060 ^S	INSPECT ENTIRE LENGTH OF LOWER DOOR CABLES FOR EVIDENCE OF FRAYING OR OTHER DAMAGE. DOOR ACCESS PANELS MUST BE REMOVED. (REFER TO 52-10-10)							Service ATA:52
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:12
PROC. REF: AMM 52-10-10PROC. REF: AMM 52-10-10								
H5210065 ^S	CLEAN LATCH ARM OF PASSENGER/CREW LOWER DOOR AND VISUALLY INSPECT FOR CRACKS. (SEE FIGURE 1.)							Service ATA:52
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5210086 ^S	CHECK LOWER CABIN DOOR MECHANISM. OPEN UPPER AND LOWER CABIN DOORS. MOVE LOWER DOOR HANLE TOWARD THE DOOR PIN MOVEMENT. CHECK FOR SECURITY AND FREE PLAY IN MECHANISM. EXCESSIVE FREE PLAY MAY BE DUE TO MECHANISM FAILURE, EXCESSIVE WEAR, OR DEFORMATION. CHECK DOO							Service ATA:52
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5230020 ^S	INSPECT TAILCONE EQUIPMENT ACCESS AND TAILCONE BAGGAGE COMPARTMENT DOOR SEALS FOR CUTS, ADHESION, AND ABRASION; LOCKING MECHANISM FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.						Service	ATA:52
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:12
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5280001 ^S	VISUALLY INSPECT INBOARD AND OUTBOARD MAIN LANDING GEAR DOOR BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)						Service	ATA:52
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P5210042 ^S	INSPECT CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR SEALS FOR ADHESIONS, CUTS, AND ABRASION; LATCH FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.						Service	ATA:52
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:12
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T5230011 ^S	VISUALLY INSPECT AVIONICS DOORS, HINGES, AND FASTENERS FOR GENERAL CONDITION, PROPER FIT, SEALS, ELECTRICAL BONDING, AND GENERAL CONDITION.						Service	ATA:52
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:14
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
T5240002 ^S	VISUAL INSPECTION SINGLE POINT REFUELING DOOR. (REFER TO 5-10-00)							Service ATA:52
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
T5280000 ^S	VISUALLY INSPECT EMERGENCY EXIT/BAGGAGE DOOR ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00).							Service ATA:52
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
T5280003 ^S	VISUALLY INSPECT NOSE AVIONICS DOOR AND NOSE LANDING GEAR DOOR ELECTRICAL BONDING JUMPERS FRO SECURITY AND GENERAL CONDITION.							Service ATA:52
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
ATA 53 - FUSELAGE								
05-10-29-Y5331017	INSPECTION OF UPPER FUSELAGE SKIN UNDER THE AFT OXYGEN LINE FAIRING							Service ATA:53
	MOS	EFF	144 (+14d/-14d)		06-Oct-28 *	20-Oct-28	1235 d (+14)	
	HRS							
	AFL							
PROC. REF: AMM 53-50-06PROC. REF: AMM 53-50-06								
05-10-30-RVSM-N5313000	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (RVSM) (REFER TO 53-11-01)							Service ATA:53
	MOS	16-Apr-24	24 (+14d/-14d)	Adj -47d	28-Feb-26	14-Mar-26	284 d (+14)	
	HRS							
	AFL							
PROC. REF: AMM 53-11-01PROC. REF: AMM 53-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
05-11-00-T5322000	REPLACE KEELBEAM ATTACHMENT BOLTS							Service ATA:53
	MOS	16-Apr-24	144 (+14d/-14d)	Adj -46d	01-Mar-36	15-Mar-36	3938 d (+14)	
	HRS							
	AFL	2264	6000 (+25/-25)		8264	8289	5945 (+25)	
PROC. REF: AMM 53-10-02PROC. REF: AMM 53-10-02								
531001	AFT PRESSURE BULKHEAD							Component ATA:53
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-10-01PROC. REF: AMM 53-10-01								
534001	NO. 1 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:6011153-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								
534002	NO. 2 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:6011153-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								
534003	NO. 1 ENGINE AFT ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:6011173-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								
534004	NO. 2 ENGINE AFT ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:6011173-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
535001	RADOME							Component ATA:53
PN:5410420-30	MOS/MSC	29-Jul-15	O/C					
SN:0051	HRS	1743.5						
	AFL	1168						
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01								
535089	LEFT DELTA FIN ASSEMBLY							Component ATA:53
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-50-04PROC. REF: AMM 53-50-04								
535090	RIGHT DELTA FIN ASSEMBLY							Component ATA:53
PN:6012108-810	MOS/MSC	06-Mar-17	O/C	TSN 0				
SN:UNKNOWN	HRS	2340.8		TSN 0				
	AFL	1566		TSN 0				
PROC. REF: AMM 53-50-04PROC. REF: AMM 53-50-04								
G5321021 ^S	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. VISUALLY INSPECT FLOOR PANEL WHICH SUPPORTS THE ELECTRICAL EQUIPMENT AND FRAMES 25, 26, AND 26A FOR CORROSION AND ANY OTHER DAMAGE.							Service ATA:53
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
H5311000 ^S	INSPECT NOSE GEAR SUPPORT INSTALLATION FOR SECURITY, FASTENER CONDITION, PANEL FATIGUE CRACKS, PERMANENT DEFORMATION AT TRUNNION FITTINGS, ACTUATOR ATTACHMENT SUPPORT STRUCTURE AREAS, AND GENERAL CONDITION.							Service ATA:53
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H5314031 ^S	FRAMING MEMBERS OF PASSENGER/CREW AND EMERGENCY EXIT/BAGGAGE DOORS AND SURROUNDING FUSELAGESTRUCTURE FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION.							Service ATA:53
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
H5321014 ^S	IF INSTALLED, INSPECT ACCESSIBLE AREAS AROUND THE GALLEY, POTTY, AND LAVATORY FOR EVIDENCE OF SPILLAGE. INVESTIGATE FURTHER IF EVIDENCE OF SPILLAGE IS FOUND.							Service ATA:53
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
H5321039 ^S	VISUALLY INSPECT LOWER LONGERON IN REGION OF WING FOR FATIGUE CRACKS, PERMANENT DEFORMATION, AND GENERAL CONDITION.							Service ATA:53
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
H5321049 ^S	VISUALLY INSPECT OVERWING CUTOUT RADIUS AT FS 346 AND FS 421 (FRAMES 24 AND 31 FUSELAGE SKIN PANELS). (REFER TO 5-10-00.)							Service ATA:53
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
H5321050 ^S	INSPECT ACCESSIBLE PORTIONS OF LOWER CAP OF THE FRAME 26A AREA, AND ADJACENT FLOOR STRUCTURE, FRAME 24-26A. VISUALLY INSPECT FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:53
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H5323011 ^S	INSPECT CORNER OF DOORS FOR FASTENER SECURITY AND GENERAL CONDITION.							Service ATA:53
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
H5331010 ^S	INSPECT BULKHEADS, FRAMES, AND STIFFENERS IN THE TAILCONE FOR FASTENER SECURITY, CRACKS, AND GENERAL CONDITION.							Service ATA:53
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
H5331020 ^S	INSPECT CANTED BULKHEADS AND LOWER VERTICAL STABILIZER ATTACHMENTS IN THE AFT TAILCONE FOR FASTENER SECURITY AND PERMANENT DEFORMATION AT BULKHEADS AND SPAR ASSEMBLIES.							Service ATA:53
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
N5323010 ^S	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)							Service ATA:53
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2
N5323012 ^S	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)							Service ATA:53
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
P5320008 ^S	INSPECT CENTER PEDESTAL AND EQUIPMENT FOR SECURITY AND GENERAL CONDITION. SPOILER, THROTTLE, AND FLAP CONTROLS FOR GENERAL CONDITION AND SERVICEABILITY.						Service	ATA:53
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
S5230021 ^S	OPERATIONAL CHECK OF TAILCONE BAGGAGE AND TAILCONE ACCESS DOOR WARNING SYSTEMS. (REFER TO 52-70-00).						Service	ATA:53
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 52-70-00PROC. REF: AMM 52-70-00								PKG:12
S5323158 ^S	INSPECT EXTERIOR OF THE SKIN, GIVING PARTICULAR ATTENTION TO LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR FASTENER CONDITION, FATIGUE CRACKS, AND GENERAL SPLICE CONDITION.						Service	ATA:53
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
T5321013 ^S	INSPECT ACCESSIBLE PORTION OF FRAME 26A AREA VISIBLE THROUGH WHEEL WELLS FOR FATIGUE CRACKS, PERMANENT DEFORMATION, SECURITY, AND GENERAL CONDITION.						Service	ATA:53
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
T5321093 ^S	INSPECT TAILCONE BAGGAGE COMPARTMENT UPHOLSTERY FOR CUTS, TEARS , AND GENERAL CONDITION.						Service	ATA:53
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
U5331012	* REMOVE ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS AND GENERAL CONDITION. (AWL*)							Service ATA:53
	MOS	07-Jan-22	49		07-Feb-26		263 d	AIRWORTHINESS
	HRS	2932.1						
	AFL	2062						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U5360005 ^S	GENERAL VISUAL INSPECTION RADOME AND LIGHTNING DIVERter STRIPS. (REFER TO 5-10-00)							Service ATA:53
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:2
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 54 - NACELLES/PYLONS								
H5450000 ^S	CHECK PYLON FIREWALLS FOR CRACKS, CONDITION OF FIREWALL SEALANT, SECURITY OF HYDRAULIC AND FUEL CONNECTIONS, ELECTRICAL AND MECHANICAL FEED-THROUGHS, AND CONDITION OF BLEED AIR FLANGE GASKETS.							Service ATA:54
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
K5450010 ^S	INSPECT PYLON BEAMS FOR CRACKS, FASTENER CONDITION, ATTACHMENT TO FUSELGAE FRAMES, AND GENERAL CONDITION OF FITTINGS. REMOVE UPPER AND LOWER PYLON ACCESS COVERS FOR COMPLETE INSPECTION.							Service ATA:54
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:15
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 55 - STABILIZERS								
553001	VERTICAL STABILIZER							Component ATA:55
PN:5431000-030	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W609	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
AD5510095 ^S	HORIZONTAL STABILIZER (WITH ELEVATOR REMOVED) – PERFORM DETAILED VISUAL INSPECTION OF THE HORIZONTAL STABILIZER REAR SPAR AND ASSOCIATED STRUCTURE FROM BL 65.60 TO BL 81.00 FOR DEFORMATION, CORROSION, LOOSE OR WORKING FASTENERS AND FATIGUE CRACKS							Service ATA:55
	MOS	16-Apr-24	144					
	HRS	3150						
	AFL	2264	6000					
								PKG:27
E5510040 ^S	WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCTURE ATTACHING BOLTS, AND BOLT RETAINERS FOR WEAR, LOOSENE							Service ATA:55
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5520010 ^S	WITH CONTROL COLUMN FIXED, APPLY ALTERNATE UP AND DOWN LOADS TO THE ELEVATOR TRAILING EDGE. INSPECT EACH ELEVATOR HINGE LOCATION FOR LOOSENESS, FREE PLAY, FATIGUE CRACKS, AND GENERAL SECURITY.							Service ATA:55
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5540010 ^S	WITH RUDDER PEDALS RESTRAINED, APPLY ALTERNATING LEFT AND RIGHT LOADS TO THE RUDDER TRAILING EDGE. OBSERVE RUDDER HINGE FITTING ATTACHMENTS FOR LOOSENESS, FREE PLAY, AND GENERAL SECURITY.							Service ATA:55
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H5510031 ^S	REMOVE ACCESS PANELS AND INSPECT UPPER AND LOWER FLANGES OF HORIZONTAL STABILIZER RIBS AT RIGHT AND LEFT BUTT LINE 19.4 FOR CRACKS.						Service	ATA:55
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
H5510035 ^S	INSPECT HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS (INCLUDING ATTACH BOLTS), SUPPORT STRUCTURE, AND ATTACH BOLT RETAINING CLIPS (IF INSTALLED) FOR CRACKS, FASTENER CONDITION, SECURITY, WEAR, AND GENERAL CONDITION.						Service	ATA:55
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
H5520000 ^S	ELEVATOR: WITH PUSH-PULL TUBES DISCONNECTED FROM ELEVATOR BELLCRANKS, MOVE EACH ELEVATOR SURFACE THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR SMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, RUST OR CORROSION, TURNING ON BOLT RATHER THAN BEA						Service	ATA:55
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
H5530001 ^S	VERTICAL STABILIZER FOR CRACKS, FASTENER CONDITION, AND SECURITY AT ATTACH POINTS, AND STRUCTURE IN AREA OF HORIZONTAL STABILIZER ATTACH FITTINGS.						Service	ATA:55
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H5540011 ^S	RUDDER: WITH CABLES DISCONNECTED AT AFT BELLCRANK LOCATION, MOVE RUDDER THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR AMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, TURNING ON BOLT RATHER THAN BEARING, RUST OR CORROSION, AND GENERAL CONDITI						Service	ATA:55
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
H5560001 ^S	VISUALLY INSPECT THE DELTA FIN SURFACES. REMOVE TAILCONE ACCESS COVERS AND VISUALLY INSPECT SUPPORT STRUCTURE FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, PERMANENT DEFORMATION, AND CORROSION. INSPECT UPPER AND LOWER SURFACES, PAYING PARTICULAR ATTENTION TO THE TAILCON						Service	ATA:55
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
P5510089 ^S	CONDUCT A THOROUGH EXTERNAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER FORWARD AND REAR SPAR CAPS (UPPER AND LOWER) FOR CORROSION, INTEGRITY OF PAINT, AND GENERAL CONDITION. (ELEVATOR REMOVAL NOT REQUIRED.) (REFER TO 5-10-00)						Service	ATA:55
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:6
T5500002 ^S	INSPECT RUDDER, RUDDER TAB, AND ELEVATOR HINGE POINTS FOR EVIDENCE OF WEAR, SECURITY, AND GENERAL CONDITION. WHEN INSTALLING VERTICAL STABILIZER AFT FAIRING, ENSURE THAT ELEVATOR TO FAIRING CLEARANCE IS 0.31 (+0.12) INCH [7.9 (+3) MM].						Service	ATA:55
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
U5500000	^S	GENERAL VISUAL INSPECTION FILLETS, FAIRINGS, AND SKINS. (REFER TO 5-10-00)						Service ATA:55
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:6
U5560000	^S	GENERAL VISUAL INSPECTION DELTA FINS. (REFER TO 5-10-00)						Service ATA:55
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
ATA 56 - WINDOWS								
05-10-29-C5610022L		LEFT WINDSHIELD PRISM CHECK						Service ATA:56
PN:6600394-003	MOS/MSC	18-Oct-13	C/C					
SN:703	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-10-01PROC. REF: NDT 56-10-01								
05-10-29-C5610022R		RIGHT WINDSHIELD PRISM CHECK						Service ATA:56
PN:6600394-004	MOS/MSC	06-Mar-17	C/C					
SN:758	HRS	2340.8						
	AFL	1566						
PROC. REF: NDT 56-10-01PROC. REF: NDT 56-10-01								
561001		LEFT WINDSHIELD ASSY						Component ATA:56
PN:6600394-003	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:703	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
561002	RIGHT WINDSHIELD ASSY							Component ATA:56
PN:6600394-004	MOS/MSC	06-Mar-17	O/C	TSN 0				
SN:758	HRS	2340.8		TSN 0				
	AFL	1566		TSN 0				
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01								
561009	LEFT COCKPIT CREW WINDOW							Component ATA:56
PN:6600512-001	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:292	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
561010	RIGHT COCKPIT CREW WINDOW							Component ATA:56
PN:6600512-002	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
562011	LEFT NO. 1 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562011A	PRISM CHECK LEFT NO. 1 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562013	LEFT NO. 2 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562013A	PRISM CHECK LEFT NO. 2 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562015	LEFT NO. 3 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562015A	PRISM CHECK LEFT NO. 3 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562017	LEFT NO. 4 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562017A	PRISM CHECK LEFT NO. 4 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562019	LEFT NO. 5 CABIN WINDOW							Component ATA:56
PN:LA6600405-19	MOS/MSC	06-Mar-17	O/C	TSN 0				
SN:2439	HRS	2340.8		TSN 0				
	AFL	1566		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562019A	PRISM CHECK LEFT NO. 5 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:LA6600405-19	MOS/MSC	06-Mar-17	C/C					
SN:2439	HRS	2340.8						
	AFL	1566						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562022	RIGHT NO. 1 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562022A	PRISM CHECK RIGHT NO. 1 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562024	RIGHT NO. 2 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562024A	PRISM CHECK RIGHT NO. 2 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562026	RIGHT NO. 3 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562026A	PRISM CHECK RIGHT NO. 3 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562028	RIGHT NO. 4 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562028A	PRISM CHECK RIGHT NO. 4 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562030	RIGHT NO. 5 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562030A	PRISM CHECK RIGHT NO. 5 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	18-Oct-13	C/C					
SN:UNKNOWN	HRS	615.4		Adj -15.4				
	AFL	466						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
H5610024 ^S	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE) A. CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS. B. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING,							Service ATA:56
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						

PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5620000 ^S	PERFORM AN EXTERNAL VISUAL INSPECTION OF THE CABIN WINDOWS AND RETAINERS FOR GENERAL CONDITION, SECURITY, AND CLEANLINESS. INSPECT INTERNAL AND EXTERNAL SURFACES OF THE CABIN WINDOWS FOR SCRATCHES, PITS, OR OTHER DAMAGE. (REFER TO 56-20-01)							Service ATA:56
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:8
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
T5610002 ^S	INSPECT INTERIOR AND EXTERIOR OF WINDSHIELD FOR CRAZING, INCLUDING VISIBLE PORTION UNDER RETAINERS FOR CRACKS, CLEANLINESS, SECURITY, AND GENERAL CONDITION. AREA UNDER ANTI-ICE DUCT SHALL BE INSPECTED BY VIEWING THE EPOXY-PRIMED OUTER SURFACE OF THE WINDSHIELD FR							Service ATA:56
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:14
PROC. REF: AMM 12-24-00, AMM 12-25-00PROC. REF: AMM 12-24-00, AMM 12-25-00								
T5620007 ^S	CABIN WINDOWS: USING PRISM TECHNIQUES, INSPECT WINDOWS FOR CRACKS, CHIPS, DELAMINATION, OR OTHER DAMAGE. THIS INSPECTION IS ALSO CAPABLE OF VISUALLY ASSESSING THE CONDITION OF THE ATTACHING FASTENERS. BROWN DISCOLORATIONS IN THE AREA OF THE FASTENERS MAY							Service ATA:56
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:24
ATA 57 - WINGS								
05-10-29-L5720012L	PERFORM LEFT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	01-Mar-12						
	HRS	0						
	AFL	0	T:10000 (+25/-25)		10000	10025	7681 (+25)	
PROC. REF: NDT 57-40-03PROC. REF: NDT 57-40-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
05-10-29-L5720012R	PERFORM RIGHT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	01-Mar-12						
	HRS	0						
	AFL	0	T:10000 (+25/-25)		10000	10025	7681 (+25)	
PROC. REF: NDT 57-40-03PROC. REF: NDT 57-40-03								
570001	LEFT WING							Component ATA:57
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01PROC. REF: AMM 57-00-01								
570002	RIGHT WING							Component ATA:57
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01PROC. REF: AMM 57-00-01								
572001	LEFT WINGLET ASSEMBLY							Component ATA:57
PN:2822650-43	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:518	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-01PROC. REF: AMM 57-20-01								
5720013 ^S	LEFT FLAP LOWER SECTOR SUPPORT BRACKET - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: NDT 57-40-04PROC. REF: NDT 57-40-04								PKG:10
5720013 ^S	RIGHT FLAP LOWER SECTOR SUPPORT BRACKET - PERFORM EDDY CURRENT INSPECTION.							Service ATA:57
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: NDT 57-40-04PROC. REF: NDT 57-40-04								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
572002	RIGHT WINGLET ASSEMBLY							Component ATA:57
PN:2822650-44	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:529	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-01PROC. REF: AMM 57-20-01								
572003	LEFT WING LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-02PROC. REF: AMM 57-20-02								
572004	RIGHT WING LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-02PROC. REF: AMM 57-20-02								
572025	LEFT FRONT WINGLET SPAR FITTING							Component ATA:57
PN:6022621-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:58	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
572026	RIGHT FRONT WINGLET SPAR FITTING							Component ATA:57
PN:6022621-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:71	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
572027	LEFT AFT WINGLET SPAR FITTING							Component ATA:57
PN:6022622-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:85	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
572028	RIGHT AFT WINGLET SPAR FITTING							Component ATA:57
PN:6022622-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:74	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5720010 ^S	INSPECT FLAP SECTOR SUPPORT BRACKETS AND FLAP ACTUATOR SUPPORT FLAP BRACKET FOR CRACKS, DISTORTION, INTERFERENCE, AND FASTENER CONDITION. (REFER TO 57-40-03).							Service ATA:57
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: AMM 57-40-03PROC. REF: AMM 57-40-03								
PKG:16								
E5750020 ^S	WITH FLAPS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO FLAP TRAILING EDGE. INSPECT INBOARD AND OUTBOARD FLAP TRACKS AND NOSE ROLLER SUPPORT STRUCTURE CRACKS, DISTORTION, FASTENER CONDITION, EVIDENCE OF CHAFING OR INTERFERENCE, AND GENERAL SECURITY.							Service ATA:57
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
PKG:16								
E5750030 ^S	INSPECT FLAP NOSE ROLLER BUSHINGS. REPLACE FLAP NOSE ROLLER IF WORN TO A DIAMETER LESS THAN 0.744 INCH. REPLACE FLAP NOSE ROLLER TRACK IF SLOT EXCEEDS 0.775 INCH AT ANY POINT WITH FLAPS FULLY EXTENDED. ENSURE THAT A POSITIVE CLEARANCE EXISTS BETWEEN NOSE ROLLERS							Service ATA:57
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
PKG:16								
E5750060 ^S	CLEAN AND VISUALLY INSPECT FLAP ATTACH FITTING (CASTINGS ATTACHED TO FLAP SPAR) FOR CRACKS. (REFER TO 5-10-00.) (SEE FIGURE 3.)							Service ATA:57
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
PKG:16								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
E5770010 ^S	INSPECT SPOILER CENTER HINGE BRACKETS (ATTACHED TO WING SPAR 8) FOR CRACKS EMANATING FROM THE BOLT HOLE AND/OR BRACKET BEND RELIEF. INSPECT BOLT HOLE FOR ELONGATION OR DISTORTION.							Service ATA:57
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10
H5750000 ^S	INSPECT TRAILING EDGE REGION OF WING FOR LOCAL DEFORMATION AFFECTING NORMAL USAGE OF FLAP ANDAILERON.							Service ATA:57
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:22
J5720011 ^S	FLAP SUPPORT FITTING (ALUMINUM, P/N 6022521-1 THRU 6022521-8) - OERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-40-02.)							Service ATA:57
	MOS	23-Mar-21	48 (+14d/-14d)					
	HRS	2858.6	1200 (+25/-25)					
	AFL	2000						
PROC. REF: NDT 57-40-02PROC. REF: NDT 57-40-02								PKG:16
K5730012 ^S	DETAILED INSPECTIONAILERON BRUSH SEALS. (REFER TO 57-30-07)							Service ATA:57
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: AMM 57-30-07PROC. REF: AMM 57-30-07								PKG:4
N5700004 ^S	VISUAL INSPECTION WING SURFACE, WING TO FUSELAGE FAIRING AND WINGLET EXTERIOR. (REFER TO 5-10-00)							Service ATA:57
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710140 ^S	REMOVE UPPER WING-TO-FUSELAGE FAIRINGS AND INSPECT WING SKINS, WING TO FUSELAGE ATTACH FITTINGS, AND ADJACENT STRUCTURE FOR CORROSION, FASTENER SECURITY, CRACKS, PERMANENT DEFORMATION, PROTECTIVE COATING, AND GENERAL CONDITION. EXAMINE EXPOSED EDGE OF HONEYCOMB							Service ATA:57
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P5710141 ^S	INSPECT WING-TO-FUSELAGE ATTACH POINTS FOR SECURITY (THAT PORTION VISIBLE THROUGH WHEEL WELLS).							Service ATA:57
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:23
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P5710144 ^S	INSPECT WHEEL WELL AND CENTER SECTION OF WING FOR GENERAL CONDITION OF SKIN, SPARS, ATTACH FITTINGS AND SUPPORTING STRUCTURE, LANDING GEAR RIB, AND TRUNNION FITTINGS. CHECK FOR DEFORMATION, FATIGUE CRACKS, PROTECTIVE FINISH CONDITION, AND GENERAL SECURITY.							Service ATA:57
	MOS	04-Apr-25	96 (+14d/-14d)					
	HRS	3222.8	2400 (+25/-25)					
	AFL	2317						
								PKG:23
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P5710146 ^S	INSPECT UPPER PORTION OF BL 0.0 RIB CAP, JUST FORWARD OF SPAR 7. INSPECT FOR ANY EVIDENCE OF CORROSION, PRIMER BLISTERING, AND CONDITION OF PRIMER SURFACE. (SEE FIGURE 2.)							Service ATA:57
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:16
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P5750050 ^S	INSPECT FLAP UPPER AND LOWER SURFACES FOR SKIN CRACKS, LOOSE RIVETS, AND OTHER DAMAGE. CHECK NOSE ROLLERS FOR FREEDOM OF ROTATION. PAY PARTICULAR ATTENTION TO NOSE ROLLER SUPPORT STRUCTURE FOR CRACKS.							Service ATA:57
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U5720071 ^S	GENERAL VISUAL INSPECTION STALL FENCES, STALL STRIPS, WING STALL TRIANGLES, AND BOUNDARY LAYER ENERGIZERS. (REFER TO 5-10-00.)							Service ATA:57
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:4
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

ATA 70 - STANDARD PRACTICES - ENGINES

700010	LEFT ENGINE INSPECTION-AIRFRAME ITEMS						Package	ATA:70
	MOS	01-Mar-12						
	HRS	0	3600 (+50)		3600	3650	376.1 (+50)	
	AFL	0						
								PKG:29
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
700020	RIGHT ENGINE INSPECTION-AIRFRAME ITEMS						Package	ATA:70
	MOS	01-Mar-12						
	HRS	0	3600 (+50)		3600	3650	376.1 (+50)	
	AFL	0						
								PKG:30
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

ATA 71 - POWER PLANT

05-11-00-E7120049L	REPLACE * NO. 1 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)						Service	ATA:71
	MOS	01-Mar-12					LIFE LIMIT	
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
05-11-00-E7120049R	REPLACE * NO. 2 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)						Service	ATA:71
	MOS	01-Mar-12					LIFE LIMIT	
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-11-00-G7110021L	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA							Service ATA:71
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00PROC. REF: AMM 28-00-00								
05-11-00-G7110021R	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA							Service ATA:71
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00PROC. REF: AMM 28-00-00								
05-11-00-G7110022L	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)							Service ATA:71
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-G7110022R	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)							Service ATA:71
	MOS/MSC	01-Mar-12	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-M7120048L	REPLACE NO. 1 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)							Service ATA:71
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-11-00-M7120048R	REPLACE NO. 2 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)							Service ATA:71
	MOS	01-Mar-12						LIFE LIMIT
	HRS	0	20000		20000		16776.1	
	AFL	0						
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE							Service ATA:71
	MOS	14-Jun-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE							Service ATA:71
	MOS	29-May-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION							Service ATA:71
	MOS	14-Jun-11						INSPECT
	HRS	0	3600 (+50)		(3600) 3600	3650	376.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION							Service ATA:71
	MOS	29-May-11						INSPECT
	HRS	0	3600 (+50)		(3600) 3600	3650	376.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS							Service ATA:71
	MOS	04-Apr-17						
	HRS	2387.8	1200 (+25/-25)		(3587.8) 3587.8	3612.8	363.9 (+25)	
	ENC	1591						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS							Service ATA:71
	MOS	04-Apr-17						
	HRS	2387.8	1200 (+25/-25)		(3587.8) 3587.8	3612.8	363.9 (+25)	
	ENC	1591						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR							Service ATA:71
	MOS	01-Jul-22						
	HRS	3030.1	600 (+25/-25)		(3630.1) 3630.1	3655.1	406.2 (+25)	
	ENC	2143						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR							Service ATA:71
	MOS	01-Jul-22						
	HRS	3030.1	600 (+25/-25)		(3630.1) 3630.1	3655.1	406.2 (+25)	
	ENC	2143						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID							Service ATA:71
PN:30B7178-03	MOS	04-Jun-22						
SN:AGJ12430972	HRS	3022.8	3600 (+400)		(6622.8) 6622.8	7022.8	3398.9 (+400)	
	ENC	2132	3600		(5732) 5732		3413	
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID							Service ATA:71
PN:30B7178-03	MOS	04-Jun-22						
SN:AGJ12430970	HRS	3022.8	3600 (+400)		(6622.8) 6622.8	7022.8	3398.9 (+400)	
	ENC	2132	3600		(5732) 5732		3413	
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
05-P&W-710020	NO. 1 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR							Service ATA:71
	MOS	14-Jun-11						
	HRS	0	3600 (+50)		(3600) 3600	3650	376.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710020	NO. 2 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR							Service ATA:71
	MOS	29-May-11						
	HRS	0	3600 (+50)		(3600) 3600	3650	376.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
710000	NO. 1 ENGINE - COMPRESSOR WASH							Service ATA:71
	MOS/MSC	14-Jun-11	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
710000	NO. 2 ENGINE - COMPRESSOR WASH							Service ATA:71
	MOS/MSC	29-May-11	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710050	NO. 1 ENGINE - RUN ENGINES							Service ATA:71
	MOS/MSC	14-Jun-11	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
710050	NO. 2 ENGINE - RUN ENGINES							Service ATA:71
	MOS/MSC	29-May-11	A/R					
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
711005	LEFT ENGINE INLET COWL							Component ATA:71
PN:282-0211-505	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0109-100	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-05PROC. REF: AMM 71-10-05								
711006	RIGHT ENGINE INLET COWL							Component ATA:71
PN:282-0211-507	MOS/MSC	29-Oct-19	O/C	TSR 3				
SN:LR0108-150A	HRS	2778.5		TSR 0				
	AFL	1936		TSR 0				
PROC. REF: AMM 71-10-05PROC. REF: AMM 71-10-05								
711011	LEFT ENGINE UPPER ACCESS COWL							Component ATA:71
PN:266-0208-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0107-300	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								
711012	RIGHT ENGINE UPPER ACCESS COWL							Component ATA:71
PN:266-0208-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0107-350	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711013	LEFT ENGINE LOWER ACCESS COWL							Component ATA:71
PN:266-0209-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0108-400	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								
711014	RIGHT ENGINE LOWER ACCESS COWL							Component ATA:71
PN:266-0209-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0108-450	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								
711015	LEFT ENGINE PYLON APRON ASSEMBLY							Component ATA:71
PN:266-0213-511	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0107-510	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-15PROC. REF: AMM 71-10-15								
711016	RIGHT ENGINE PYLON APRON ASSEMBLY							Component ATA:71
PN:266-0213-512	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0108-560	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-15PROC. REF: AMM 71-10-15								
711021	LEFT ENGINE OUTER FAN DUCT							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-20PROC. REF: AMM 71-10-20								
711022	RIGHT ENGINE OUTER FAN DUCT							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-20PROC. REF: AMM 71-10-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711023	LEFT ENGINE LEFT FORWARD CORE COWL							Component ATA:71
PN:266-0261-501	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0220-710	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711024	RIGHT ENGINE LEFT FORWARD CORE COWL							Component ATA:71
PN:266-0261-501	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0215-720	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711025	LEFT ENGINE RIGHT FORWARD CORE COWL							Component ATA:71
PN:266-0261-503	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0214-720	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711026	RIGHT ENGINE RIGHT FORWARD CORE COWL							Component ATA:71
PN:PN266-0261-503	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0215-720	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711027	LEFT ENGINE UPPER AFT CORE COWL							Component ATA:71
PN:266-0263-511	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0212-740	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711028	RIGHT ENGINE UPPER AFT CORE COWL							Component ATA:71
PN:266-0263-511	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0213-740	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711029	LEFT ENGINE LOWER AFT CORE COWL							Component ATA:71
PN:266-0263-509	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0214-730	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711030	RIGHT ENGINE LOWER AFT CORE COWL							Component ATA:71
PN:266-0263-509	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0215-730	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
712001	LEFT ENGINE FORWARD INTERMEDIATE FITTING							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-01PROC. REF: AMM 71-20-01								
712002	RIGHT ENGINE FORWARD INTERMEDIATE FITTING							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-01PROC. REF: AMM 71-20-01								
712005	LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR							Component ATA:71
PN:LM439SA2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LK1836	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712006	RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR							Component ATA:71
PN:LM439SA2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LK1865	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712007	LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR							Component ATA:71
PN:LM439SA3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LK1791	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712008	RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR							Component ATA:71
PN:LM439SA3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LK1809	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712009	LEFT ENGINE FORWARD MOUNT YOKE							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712010	RIGHT ENGINE FORWARD MOUNT YOKE							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712011	LEFT ENGINE AFT VIBRATION ISOLATOR							Component ATA:71
PN:LM439SA1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LK1230	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712012	RIGHT ENGINE AFT VIBRATION ISOLATOR							Component ATA:71
PN:LM439SA1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LK1216	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712013	LEFT ENGINE UPPER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712014	RIGHT ENGINE UPPER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712015	LEFT ENGINE LOWER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712016	RIGHT ENGINE LOWER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
715020	NO. 1 ENGINE - ENGINE WIRE HARNESS							Component ATA:71
PN:30B3089-03	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:EMA3D50468	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
715020	NO. 2 ENGINE - ENGINE WIRE HARNESS							Component ATA:71
PN:30B3089-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:EMA3D49790	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
715025	NO. 1 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR							Component ATA:71
PN:30B3088-02	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:0667	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								
715025	NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR							Component ATA:71
PN:30B3088-02	MOS/MSC	29-May-11	O/C	TSN 0				
SN:0666	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:31B4067-04	MOS/MSC	28-Mar-19	E/C					
SN:PCE-CA0682	HRS	2762.6						
WC#: 71.EN1	AFL	1914						
PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:31B4067-04	MOS/MSC	28-Mar-19	E/C					
SN:PCE-CA0681	HRS	2762.6						
WC#: 71.EN2	AFL	1914						
PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00								
E7100004 ^S	VISUAL INSPECTION OF ALL BLEED AIR DUCTS, LINES, HOSES, AND ELECTRICAL WIRING IN THE ENGINE NACELLE. INSPECT FOR SECURITY, CLAMPING, ROUTING, CLEARANCE, EVIDENCE OF LEAKS, AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:71
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:3
E7100016 ^S	INSPECT HOLD OPEN RODS FOR SECURITY OF INSTALLATION AND EVIDENCE OF DAMAGE.							Service ATA:71
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:3

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E7100020	^S	REMOVE IGNITER ACCESS PANEL AND INSPECT CORE COWL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.						Service ATA:71
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:3
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E7100022	^S	INSPECT IGNITER ACCESS PANEL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.						Service ATA:71
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:3
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E7100030	^S	INSPECT FUEL, HYDRAULIC, FIRE EXTINGUISHER, AND DRAIN LINES, CONTROLS CONNECTIONS, COUPLINGS, AND ACCESSORIES FOR LOOSE OR FAILED FASTENERS, CHAFING WEAR, ROUTING, PROPER SAFETY, SECURITY OF MOUNTING, AND EVIDENCE OF DAMAGE. INSPECT SHIELDED FADEC ELECTRICAL HAR						Service ATA:71
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:3
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
M7120068A		INSPECT NO. 1 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS						Service ATA:71
	MOS	01-Mar-12						
	HRS	0	3600 (+25/-25)		3600	3625	376.1 (+25)	
	AFL	0						
PROC. REF: AMM 71-20-05, AMM 71-20-10PROC. REF: AMM 71-20-05, AMM 71-20-10								
M7120068B		INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS						Service ATA:71
	MOS	01-Mar-12						
	HRS	0	3600 (+25/-25)		3600	3625	376.1 (+25)	
	AFL	0						
PROC. REF: AMM 71-20-05, AMM 71-20-10PROC. REF: AMM 71-20-05, AMM 71-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
T7100010	^S	INSPECT UPPER COWL DOOR AND APRON FOR FAILED FASTENERS, SECURITY, AND EVIDENCES OF DAMAGE. INSPECT BONDING JUMPERS ACROSS COWLING HINGES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR AND APRON FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY						Service ATA:71
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:15
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7100012	^S	INSPECT LOWER COWL DOOR INNER AND OUTER SKINS AND SEALS FOR EVIDENCE OF DAMAGE. INSPECT LATCH ASSEMBLIES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY AROUND THE HEADS OF FASTENERS AND ALONG						Service ATA:71
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:15
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7100018	^S	GENERAL VISUAL INSPECTION FAN DUCT OUTER SKIN AND ATTACHMENT. (REFER TO 5-10-00)						Service ATA:71
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U7100014	^S	GENERAL VISUAL INSPECTION OIL FILLER DOOR. (REFER TO 5-10-00)						Service ATA:71
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U7110032	^S	GENERAL VISUAL INSPECTION GENERATOR INLET DUCT SEAL. (REFER TO 5-10-00)						Service ATA:71
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:3
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
U7110041 ^S	GENERAL VISUAL INSPECTION NACELLE OUTER SKIN ATTACHMENT. (REFER TO 5-10-00)							Service ATA:71
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
U7110042 ^S	GENERAL VISUAL INSPECTION NACELLE LIP ASSEMBLY AND INNER BARREL. (REFER TO 5-10-00)							Service ATA:71
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
ATA 72 - ENGINE								
720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION							Service ATA:72
	MOS	14-Jun-11	T:180 (+12m)		14-Jun-26	14-Jun-27	390 d (+365)	
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION							Service ATA:72
	MOS	29-May-11	T:180 (+12m)		29-May-26	29-May-27	374 d (+365)	
	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
720010 ^S	NO. 1 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720010 ^S	NO. 2 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720015 ^S	NO. 1 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL							Service ATA:72
	MOS	16-Apr-24	24					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
720015 ^S	NO. 2 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL							Service ATA:72
	MOS	16-Apr-24	24					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
720020 ^S	NO. 1 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720020 ^S	NO. 2 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720030 ^S	NO. 1 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720030 ^S	NO. 2 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720040 ^S	NO. 1 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720040 ^S	NO. 2 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720050 ^S	NO. 1 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720050 ^S	NO. 2 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720060 ^S	NO. 1 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720060 ^S	NO. 2 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720070 ^S	NO. 1 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720070 ^S	NO. 2 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720080 ^S	NO. 1 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720080 ^S	NO. 2 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720090 ^S	NO. 1 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640)							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720090 ^S	NO. 2 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640)							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720095	NO. 1 ENGINE - DISCARD LP COMPRESSOR NO. 1 FAN BLADE							Service ATA:72
PN:PN	MOS	14-Jun-11						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	ENC	0	15000		(15000) 15000		12681	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720095	NO. 2 ENGINE - DISCARD LP COMPRESSOR NO. 1 FAN BLADE							Service ATA:72
PN:PN	MOS	29-May-11						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	ENC	0	15000		(15000) 15000		12681	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720100 ^S	NO. 1 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720100 ^S	NO. 2 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720110 ^S	NO. 1 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720110 ^S	NO. 2 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720120 ^S	NO. 1 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720120 ^S	NO. 2 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720130 ^S	NO. 1 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720130 ^S	NO. 2 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720140 ^S	NO. 1 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP						Service	ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720140 ^S	NO. 2 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720150 ^S	NO. 1 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720150 ^S	NO. 2 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720160 ^S	NO. 1 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720160 ^S	NO. 2 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720170 ^S	NO. 1 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
720170 ^S	NO. 2 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
720180 ^S	NO. 1 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720180 ^S	NO. 2 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720190 ^S	NO. 1 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720190 ^S	NO. 2 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720200 ^S	NO. 1 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720200 ^S	NO. 2 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720210 ^S	NO. 1 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720210 ^S	NO. 2 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720220 ^S	NO. 1 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720220 ^S	NO. 2 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720230 ^S	NO. 1 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720230 ^S	NO. 2 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720240 ^S	NO. 1 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720240 ^S	NO. 2 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720250 ^S	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE.							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720250 ^S	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE.							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720260 ^S	NO. 1 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720260 ^S	NO. 2 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720270 ^S	NO. 1 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 75-30-03, EMM 77-20-02, EMM 75-30-03PROC. REF: EMM 75-30-03, EMM 77-20-02, EMM 75-30-03								PKG:1
720270 ^S	NO. 2 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 75-30-03, EMM 77-20-02, EMM 75-30-03PROC. REF: EMM 75-30-03, EMM 77-20-02, EMM 75-30-03								PKG:1
720280 ^S	NO. 1 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720280 ^S	NO. 2 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720290 ^S	NO. 1 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY.							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720290 ^S	NO. 2 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY.							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720300 ^S	NO. 1 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720300 ^S	NO. 2 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720310 ^S	NO. 1 ENGINE - SPARK IGNITERS, OPERATIONAL TEST							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720310 ^S	NO. 2 ENGINE - SPARK IGNITERS, OPERATIONAL TEST							Service ATA:72
	MOS	16-Apr-24	36					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723001	NO. 1 ENGINE - FAN HUB							Component ATA:72
PN:30B2256	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:A00305RN	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		9681	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723001	NO. 2 ENGINE - FAN HUB							Component ATA:72
PN:30B2256	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:A002YR6T	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		9681	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723002	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:31B5237-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:BDAA003A164	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723002	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:31B5237-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:BDAA003A163	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723003	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:30B4565-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:A002WT5N	HRS	0		TSN 0				
	ENC	0		TSN 0	(7000) 7000 (M)		4681	
	ACCCYC	0	7000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723003	NO. 2 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:30B4565-01	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:A002W2TX	HRS	0		TSN 0				
	ENC	0		TSN 0	(7000) 7000 (M)		4681	
	ACCCYC	0	7000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723004	NO. 1 ENGINE - PRESSURE CHECK IMPELLER SHROUD							Service ATA:72
	MOS/MSC	14-Jun-11	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723004	NO. 2 ENGINE - PRESSURE CHECK IMPELLER SHROUD							Service ATA:72
	MOS/MSC	29-May-11	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723005	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR							Component ATA:72
PN:30B6551-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:TXA1C3405	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		9681	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723005	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR							Component ATA:72
PN:30B6551-01	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:TXA1C3261	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		9681	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723005A	NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)							Service ATA:72
PN:30B6551-01	MOS/MSC	14-Jun-11	N/A					NOT APPLICABLE
SN:TXA1C3405	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
723005A	NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)							Service ATA:72
PN:30B6551-01	MOS/MSC	29-May-11	N/A					NOT APPLICABLE
SN:TXA1C3261	HRS	0						
	ENC	0						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
723008	NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR							Component ATA:72
PN:30B4745-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:56B313	HRS	0		TSN 0				
	ENC	0		TSN 0	(8500) 8500 (M)		6181	
	ACCCYC	0	8500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723008	NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR							Component ATA:72
PN:30B4745-01	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:56B303	HRS	0		TSN 0				
	ENC	0		TSN 0	(8500) 8500 (M)		6181	
	ACCCYC	0	8500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723008A	NO. 1 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM							Service ATA:72
PN:30B4745-01	MOS/MSC	14-Jun-11	O/C					
SN:56B313	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723008A	NO. 2 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM							Service ATA:72
PN:30B4745-01	MOS/MSC	29-May-11	O/C					
SN:56B303	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723027	NO. 1 ENGINE - LOW COMPRESSOR SHAFT							Component ATA:72
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723027	NO. 2 ENGINE - LOW COMPRESSOR SHAFT							Component ATA:72
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723040	NO. 1 ENGINE - LP COMPRESSOR - NO. 1 FAN BLADE							Component ATA:72
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723040	NO. 2 ENGINE - LP COMPRESSOR - NO. 1 FAN BLADE							Component ATA:72
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724010	NO. 1 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:72
	MOS/MSC	14-Jun-11	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724010	NO. 2 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:72
	MOS/MSC	29-May-11	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725001	NO. 1 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING							Component ATA:72
PN:30B3012CL01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:HLAC024	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725001	NO. 2 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING							Component ATA:72
PN:30B3012CL01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:HLAC011	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725003	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:31A1026-03	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:MAG19501	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03PROC. REF: EMM 72-50-03								
725003	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:31A1026-03	MOS/MSC	29-May-11	O/C	TSN 0				
SN:MAG19499	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03PROC. REF: EMM 72-50-03								
725101	NO. 1 ENGINE - STAGE 1 TURBINE DISC							Component ATA:72
PN:30B2981-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:A00305RX	HRS	0		TSN 0				
	ENC	0		TSN 0	(3100) 3100 (M)		781	
	ACCCYC	0	3100	TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725101	NO. 2 ENGINE - STAGE 1 TURBINE DISC							Component ATA:72
PN:30B2981-01	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:A002YEBP	HRS	0		TSN 0				
	ENC	0		TSN 0	(3100) 3100 (M)		781	
	ACCCYC	0	3100	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725102	NO. 1 ENGINE - STAGE 2 TURBINE DISC							Component ATA:72
PN:30B2912-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:A003082D	HRS	0		TSN 0				
	ENC	0		TSN 0	(3300) 3300 (M)		981	
	ACCCYC	0	3300	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725102	NO. 2 ENGINE - STAGE 2 TURBINE DISC							Component ATA:72
PN:30B2912-01	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:A002YYPC	HRS	0		TSN 0				
	ENC	0		TSN 0	(3300) 3300 (M)		981	
	ACCCYC	0	3300	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725103	NO. 1 ENGINE - STAGE 3 TURBINE DISC							Component ATA:72
PN:30A1853	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:MAA13326	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		7681	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725103	NO. 2 ENGINE - STAGE 3 TURBINE DISC							Component ATA:72
PN:30A1853	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:MAA13332	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		7681	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725104	NO. 1 ENGINE - STAGE 4 TURBINE DISC							Component ATA:72
PN:30A1854	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:MAA13626	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		7681	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725104	NO. 2 ENGINE - STAGE 4 TURBINE DISC							Component ATA:72
PN:30A1854	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:MAA13622	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		7681	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725105	NO. 1 ENGINE - STAGE 5 TURBINE DISC							Component ATA:72
PN:30A1855	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:MAA40902	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		7681	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725105	NO. 2 ENGINE - STAGE 5 TURBINE DISC							Component ATA:72
PN:30A1855	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:MAA40898	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		7681	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725107	NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2748-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:A002Y2WD	HRS	0		TSN 0				
	ENC	0		TSN 0	(4800) 4800 (M)		2481	
	ACCCYC	0	4800	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725107	NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2748-01	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:A002Y2WB	HRS	0		TSN 0				
	ENC	0		TSN 0	(4800) 4800 (M)		2481	
	ACCCYC	0	4800	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725109	NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B6726-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:A002TWRW	HRS	0		TSN 0				
	ENC	0		TSN 0	(3142) 3142 (M)		823	
	ACCCYC	0	4400	TSN 0			1153	
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725109	NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B6726-01	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:A002YHC6	HRS	0		TSN 0				
	ENC	0		TSN 0	(3142) 3142 (M)		823	
	ACCCYC	0	4400	TSN 0			1153	
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725111	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL							Component ATA:72
PN:30B2793-01	MOS	14-Jun-11		TSN 0				LIFE LIMIT
SN:AWE014244	HRS	0		TSN 0				
	ENC	0		TSN 0	(4000) 4000 (M)		1681	
	ACCCYC	0	4000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725111	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL							Component ATA:72
PN:PN	MOS	29-May-11		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0	(4000) 4000 (M)		1681	
	ACCCYC	0	4000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
726001	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING							Component ATA:72
PN:30B4808-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:A0030T2W	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								
726001	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING							Component ATA:72
PN:30B4808-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:A002YYM1	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)							Service ATA:72
	MOS	14-Jun-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
726011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)							Service ATA:72
	MOS	29-May-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
727001	NO. 1 ENGINE - COMBUSTION CHAMBER LINER							Component ATA:72
PN:30B6146-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:A003041C	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01, EMM 72-40-01PROC. REF: EMM 72-40-01, EMM 72-40-01								
727001	NO. 2 ENGINE - COMBUSTION CHAMBER LINER							Component ATA:72
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01, EMM 72-40-01PROC. REF: EMM 72-40-01, EMM 72-40-01								
727001A	NO. 1 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER							Service ATA:72
PN:30B6146-01	MOS	14-Jun-11						
SN:A003041C	HRS	0	3600 (+50)		(3600) 3600	3650	376.1 (+50)	
	ENC	0						
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727001A	NO. 2 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER							Service ATA:72
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	3600 (+50)		(3600) 3600	3650	376.1 (+50)	
	ENC	0						
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
727002	NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:30B4561-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:A00301AC	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01, EMM 72-40-01PROC. REF: EMM 72-40-01, EMM 72-40-01								
727002	NO. 2 ENGINE - INNER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:30B4561-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:A00301AB	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01, EMM 72-40-01PROC. REF: EMM 72-40-01, EMM 72-40-01								
727003	NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:30B6146-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:A003041C	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01, EMM 72-40-01PROC. REF: EMM 72-40-01, EMM 72-40-01								
727003	NO. 2 ENGINE - OUTER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:30B6146-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:A002YT18	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01, EMM 72-40-01PROC. REF: EMM 72-40-01, EMM 72-40-01								
ATA 73 - ENGINE FUEL AND CONTROL								
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT							Service ATA:73
	MOS	04-Apr-25	12		04-Apr-26		319 d	
	HRS	3222.8	1200 (+25/-25)		(4422.8) 4422.8	4447.8	1198.9 (+25)	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
	ENC	2317						
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
05-P&W-730001	NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT							Service ATA:73
	MOS	04-Apr-25	12		04-Apr-26		319 d	
	HRS	3222.8	1200 (+25/-25)		(4422.8) 4422.8	4447.8	1198.9 (+25)	
	ENC	2317						
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
05-P&W-730005	NO. 1 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE							Service ATA:73
	MOS	01-Oct-15						
	HRS	1812.9	1800 (+600/-600)		(3612.9) 3612.9	4212.9	389 (+600)	
	ENC	1236						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
05-P&W-730005	NO. 2 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE							Service ATA:73
	MOS	01-Oct-15						
	HRS	1812.9	1800 (+600/-600)		(3612.9) 3612.9	4212.9	389 (+600)	
	ENC	1236						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731001	NO. 1 ENGINE - FUEL PUMP							Component ATA:73
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731001	NO. 2 ENGINE - FUEL PUMP							Component ATA:73
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731002	NO. 1 ENGINE - MOTIVE FLOW VALVE							Component ATA:73
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
731002	NO. 2 ENGINE - MOTIVE FLOW VALVE							Component ATA:73
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
731003	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH							Component ATA:73
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
731003	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH							Component ATA:73
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
731004	NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	01-Oct-15	O/C	TSO 0				
SN:1AAK1685	HRS	1812.9		TSO 0				
	ENC	1236		TSO 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731004	NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	01-Oct-15	O/C	TSO 0				
SN:1XS06418	HRS	1812.9		TSO 0				
	ENC	1236		TSO 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731005	NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	01-Oct-15	O/C	TSO 0				
SN:1AAP0542	HRS	1812.9		TSO 0				
	ENC	1236		TSO 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731005	NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE							Component ATA:73
PN:31B5832-04	MOS/MSC	01-Oct-15	O/C	TSO 0				
SN:1UTO3741	HRS	1812.9		TSO 0				
	ENC	1236		TSO 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731010	NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY							Component ATA:73
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731010	NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY							Component ATA:73
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731011 ^S	NO. 1 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY							Service ATA:73
	MOS	16-Apr-24	24					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 73-10-05, EMM 73-10-04PROC. REF: EMM 73-10-05, EMM 73-10-04								PKG:1
731011 ^S	NO. 2 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY							Service ATA:73
	MOS	16-Apr-24	24					
	HRS	3150	600					
	ENC	2264						
PROC. REF: EMM 73-10-05, EMM 73-10-04PROC. REF: EMM 73-10-05, EMM 73-10-04								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731012	NO. 1 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP							Service ATA:73
PN:PN	MOS/MSC	14-Jun-11	N/A					OVERHAUL
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731012	NO. 2 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP							Service ATA:73
PN:PN	MOS/MSC	29-May-11	N/A					OVERHAUL
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH							Service ATA:73
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH							Service ATA:73
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731014	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY							Service ATA:73
	MOS	14-Jun-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731014	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY							Service ATA:73
	MOS	29-May-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY)							Service ATA:73
PN:PN	MOS/MSC	14-Jun-11	N/A					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY)							Service ATA:73
PN:PN	MOS/MSC	29-May-11	N/A					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731023	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK							Service ATA:73
PN:30B6023-05	MOS	14-Jun-11						
SN:30148	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731023	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK							Service ATA:73
PN:30B6023-05	MOS	29-May-11						
SN:30145	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731024	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY							Service ATA:73
	MOS	14-Jun-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731024	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY							Service ATA:73
	MOS	29-May-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731025	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE							Service ATA:73
PN:31B5131-03	MOS	14-Jun-11						
SN:9959517247	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731025	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE							Service ATA:73
PN:31B5131-03	MOS	29-May-11						
SN:9959517248	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731026	NO. 1 ENGINE - FUEL WASTE EJECTOR							Component ATA:73
PN:30B6023-05	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:30148	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731026	NO. 2 ENGINE - FUEL WASTE EJECTOR							Component ATA:73
PN:30B6023-05	MOS/MSC	29-May-11	O/C	TSN 0				
SN:30145	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
731044	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - INLET							Service ATA:73
	MOS	14-Jun-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731044	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - INLET							Service ATA:73
	MOS	29-May-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731045	NO. 1 ENGINE - DISCARD - FUEL SHUT-OFF CABLE							Service ATA:73
	MOS	14-Jun-11						DISCARD
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731045	NO. 2 ENGINE - DISCARD - FUEL SHUT-OFF CABLE							Service ATA:73
	MOS	29-May-11						DISCARD
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731051	NO. 1 ENGINE - FUEL START & DUMP VALVE							Component ATA:73
PN:31B5131-03	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:9959517247	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731051	NO. 2 ENGINE - FUEL START & DUMP VALVE							Component ATA:73
PN:31B5131-03	MOS/MSC	29-May-11	O/C	TSN 0				
SN:9959517248	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731055	NO. 1 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF							Service ATA:73
	MOS	14-Jun-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731055	NO. 2 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF							Service ATA:73
	MOS	29-May-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
732001	NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL							Component ATA:73
PN:30B5059-04	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:17299809	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
732001	NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL							Component ATA:73
PN:8060-527	MOS/MSC	13-Feb-16	O/C	TSO 0				
SN:15462326	HRS	2019.1		TSO 0				
	ENC	1350		TSO 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
732002	NO. 1 ENGINE - REPLACE TRIM PLUG							Service ATA:73
	MOS	28-May-21	120		28-May-31		2199 d	
	HRS	2876						
	ENC	2014						
PROC. REF: EMM 70-00-00, EMM 73-20-02PROC. REF: EMM 70-00-00, EMM 73-20-02								
732002	NO. 2 ENGINE - REPLACE TRIM PLUG							Service ATA:73
	MOS	28-May-21	120		28-May-31		2199 d	
	HRS	2876						
	ENC	2014						
PROC. REF: EMM 70-00-00, EMM 73-20-02PROC. REF: EMM 70-00-00, EMM 73-20-02								
732003	NO. 1 ENGINE - ELECTRICAL FRONT HARNESS							Component ATA:73
PN:30B7462-02	MOS/MSC	04-Jun-22	O/C					
SN:EFC00481	HRS	3022.8						
	ENC	2132						
PROC. REF: EMM 73-20-03, EMM 73-20-03PROC. REF: EMM 73-20-03, EMM 73-20-03								
732003	NO. 2 ENGINE - ELECTRICAL FRONT HARNESS							Component ATA:73
PN:30B7462-02	MOS/MSC	04-Jun-22	O/C					
SN:EFC00461	HRS	3022.8						
	ENC	2132						
PROC. REF: EMM 73-20-03, EMM 73-20-03PROC. REF: EMM 73-20-03, EMM 73-20-03								
732004	NO. 1 ENGINE - ELECTRICAL REAR HARNESS							Component ATA:73
PN:31B3766-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:EMA150733	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
732004	NO. 2 ENGINE - ELECTRICAL REAR HARNESS							Component ATA:73
PN:31B3766-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:EMA159394	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
732005	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC							Component ATA:73
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-02PROC. REF: EMM 73-20-02								
732005	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL EEC							Component ATA:73
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-02PROC. REF: EMM 73-20-02								
732011	NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU							Service ATA:73
PN:30B5059-04	MOS/MSC	14-Jun-11	N/A					
SN:17299809	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732011	NO. 2 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU							Service ATA:73
PN:8060-527	MOS/MSC	29-May-11	N/A					
SN:15462326	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC							Service ATA:73
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC							Service ATA:73
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR)							Service ATA:73
PN:30B3089-03	MOS	14-Jun-11						
SN:EMA3D50468	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR)							Service ATA:73
PN:30B3089-01	MOS	29-May-11						
SN:EMA3D49790	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732021	NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU							Service ATA:73
PN:30B5059-04	MOS	14-Jun-11						
SN:17299809	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
732021	NO. 2 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU							Service ATA:73
PN:8060-527	MOS	29-May-11						
SN:15462326	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732101	NO. 1 ENGINE - ENGINE FADEC							Component ATA:73
PN:822821-6-004	MOS/MSC	05-Nov-13	O/C	TSO 0				
SN:09022977	HRS	644.3		TSO 0				
	ENC	490		TSO 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
732101	NO. 2 ENGINE - ENGINE FADEC							Component ATA:73
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
732102	NO. 1 ENGINE - TRIM PLUG							Component ATA:73
PN:PN	MOS/MSC	28-May-21	O/C	TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	2876		TSN 0				
	ENC	2014		TSN 0				
PROC. REF: EMM 73-20-02PROC. REF: EMM 73-20-02								
732102	NO. 2 ENGINE - TRIM PLUG							Component ATA:73
PN:PN	MOS/MSC	28-May-21	O/C	TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	2876		TSN 0				
	ENC	2014		TSN 0				
PROC. REF: EMM 73-20-02PROC. REF: EMM 73-20-02								
733010	DUAL FUEL FLOW CONVERTER							Component ATA:73
PN:10540B08F07	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:11071252A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03								
733101	LEFT ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:7600021-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:605809	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
733102	RIGHT ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:7600021-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:605812	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01								
733103	LEFT ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02								
733104	RIGHT ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02								
ATA 74 - IGNITION								
741001	NO. 1 ENGINE - NO. 1 IGNITION EXCITER							Component ATA:74
PN:31B4636-02	MOS/MSC	23-Mar-21	O/C	TSO 1				
SN:95400149	HRS	2858.6		TSO 0				
	ENC	2000		TSO 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741001	NO. 2 ENGINE - NO. 1 IGNITION EXCITER							Component ATA:74
PN:31B5168-01	MOS/MSC	26-Feb-14	O/C	TSN 0				
SN:UNKNOWN	HRS	902.4		TSN 0				
	ENC	615		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741002	NO. 1 ENGINE - NO. 2 IGNITION EXCITER							Component ATA:74
PN:31B4636-02	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:NNA11170114	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741002	NO. 2 ENGINE - NO. 2 IGNITION EXCITER							Component ATA:74
PN:31B5168-01	MOS/MSC	26-Feb-14	O/C	TSN 0				
SN:UNKNOWN	HRS	902.4		TSN 0				
	ENC	615		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741003	NO. 1 ENGINE - NO. 1 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741003	NO. 2 ENGINE - NO. 1 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741004	NO. 1 ENGINE - NO. 2 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741004	NO. 2 ENGINE - NO. 2 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX							Service ATA:74
PN:31B4636-02	MOS	23-Mar-21						
SN:95400149	HRS	2858.6	7200 (+50)		(10058.6) 10058.6	10108.6	6834.7 (+50)	
	ENC	2000						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX							Service ATA:74
PN:31B5168-01	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX							Service ATA:74
PN:31B4636-02	MOS	14-Jun-11						
SN:NNA11170114	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX							Service ATA:74
PN:31B5168-01	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES							Service ATA:74
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES							Service ATA:74
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES							Service ATA:74
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES							Service ATA:74
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741031	NO. 1 ENGINE - REPLACE - NO. 1 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	14-Jun-11						REPLACE
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741031	NO. 2 ENGINE - REPLACE - NO. 1 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	29-May-11						REPLACE
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741032	NO. 1 ENGINE - REPLACE - NO. 2 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	14-Jun-11						REPLACE
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741032	NO. 2 ENGINE - REPLACE - NO. 2 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	29-May-11						REPLACE
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
742025	NO. 1 ENGINE - NO. 1 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	03-Feb-18	O/C	TSN 0				
SN:UNKNOWN	HRS	2517.1		TSN 0				
	ENC	1720		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
742025	NO. 2 ENGINE - NO. 1 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	13-Feb-16	O/C	TSN 0				
SN:UNKNOWN	HRS	2019.1		TSN 0				
	ENC	1350		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
742026	NO. 1 ENGINE - NO. 2 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	03-Feb-18	O/C	TSN 0				
SN:UNKNOWN	HRS	2517.1		TSN 0				
	ENC	1720		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
742026	NO. 2 ENGINE - NO. 2 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	13-Feb-16	O/C	TSN 0				
SN:UNKNOWN	HRS	2019.1		TSN 0				
	ENC	1350		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
743003	ENGINE WARNING LIGHT BOX							Component ATA:74
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 74-30-03PROC. REF: AMM 74-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
751001	NO. 1 ENGINE - ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:31B5108-04	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:AL1630	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								
751001	NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:31B5108-04	MOS/MSC	29-May-11	O/C	TSN 0				
SN:AL1629	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								
751011	NO. 1 ENGINE - OVERHAUL - ANTI-ICING VALVE							Service ATA:75
PN:31B5108-04	MOS	14-Jun-11						OVERHAUL
SN:AL1630	HRS	0	7200 (+50)	(7200) 7200 (M)	7250	3976.1 (+50)		
	ENC	0						
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								
751011	NO. 2 ENGINE - OVERHAUL - ANTI-ICING VALVE							Service ATA:75
PN:31B5108-04	MOS	29-May-11						OVERHAUL
SN:AL1629	HRS	0	7200 (+50)	(7200) 7200 (M)	7250	3976.1 (+50)		
	ENC	0						
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								
753001	NO. 1 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES							Service ATA:75
	MOS	14-Jun-11						OVERHAUL
	HRS	0	7200 (+50)	(7200) 7200 (M)	7250	3976.1 (+50)		
	ENC	0						
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753001	NO. 2 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES							Service ATA:75
	MOS	29-May-11						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753002	NO. 1 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS	14-Jun-11						DISCARD
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753002	NO. 2 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS	29-May-11						DISCARD
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER							Service ATA:75
	MOS	14-Jun-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER							Service ATA:75
	MOS	29-May-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753004	NO. 1 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR							Component ATA:75
PN:31B5255-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:SAU11-008	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753004	NO. 2 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR							Component ATA:75
PN:31B5255-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:SAU11-005	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753005	NO. 1 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753005	NO. 2 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753012	NO. 1 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS/MSC	14-Jun-11	N/A					DISCARD
	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753012	NO. 2 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS/MSC	29-May-11	N/A					DISCARD
	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753014	NO. 1 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR							Service ATA:75
PN:PN	MOS/MSC	14-Jun-11	N/A					DISCARD
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753014	NO. 2 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR							Service ATA:75
PN:PN	MOS/MSC	29-May-11	N/A					DISCARD
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753024	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR							Service ATA:75
PN:31B5255-01	MOS	14-Jun-11						
SN:SAU11-008	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753024	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR							Service ATA:75
PN:31B5255-01	MOS	29-May-11						
SN:SAU11-005	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753081	NO. 1 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID							Component ATA:75
PN:30B7178-03	MOS/MSC	04-Jun-22	O/C	TSN 0				
SN:AGJ12430972	HRS	3022.8		TSN 0				
	ENC	2132		TSN 0				
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753081	NO. 2 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID							Component ATA:75
PN:30B7178-03	MOS/MSC	04-Jun-22	O/C	TSN 0				
SN:AGJ12430970	HRS	3022.8		TSN 0				
	ENC	2132		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753082	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT							Component ATA:75
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753082	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT							Component ATA:75
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753083	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE							Service ATA:75
PN:PN	MOS/MSC	14-Jun-11	N/A					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753083	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE							Service ATA:75
PN:PN	MOS/MSC	29-May-11	N/A					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753101	NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS			TSN 0				REPLACE
SN:AHX018013	HRS	EFF	3600 (+50)	TSN 0	(3600) 3600 *	3650	376.1 (+50)	
	ENC			TSN 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753101	NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS			TSN 0				REPLACE
SN:AHX018343	HRS	EFF	3600 (+50)	TSN 0	(3600) 3600 *	3650	376.1 (+50)	
	ENC			TSN 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753102	NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS			TSN 0				REPLACE
SN:GF000736	HRS	EFF	3600 (+50)	TSN 0	(3600) 3600 *	3650	376.1 (+50)	
	ENC			TSN 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753102	NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5759-01	MOS			TSN 0				REPLACE
SN:AHX018345	HRS	EFF	3600 (+50)	TSN 0	(3600) 3600 *	3650	376.1 (+50)	
	ENC			TSN 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753105	NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE							Component ATA:75
PN:31B5756-01	MOS			TSN 0				REPLACE
SN:AHX018040	HRS	EFF	3600 (+50)	TSN 0	(3600) 3600 *	3650	376.1 (+50)	
	ENC			TSN 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753105	NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE							Component ATA:75
PN:31B5756-01	MOS			TSN 0				REPLACE
SN:AHX018035	HRS	EFF	3600 (+50)	TSN 0	(3600) 3600 *	3650	376.1 (+50)	
	ENC			TSN 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753111	NO. 1 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	14-Jun-11	N/A					
SN:AHX018013	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753111	NO. 2 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	29-May-11	N/A					
SN:AHX018343	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753112	NO. 1 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	14-Jun-11	N/A					
SN:GF000736	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753112	NO. 2 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5759-01	MOS/MSC	29-May-11	N/A					
SN:AHX018345	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753115	NO. 1 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE							Service ATA:75
PN:31B5756-01	MOS/MSC	14-Jun-11	N/A					
SN:AHX018040	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753115	NO. 2 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE							Service ATA:75
PN:31B5756-01	MOS/MSC	29-May-11	N/A					
SN:AHX018035	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
754001	NO. 1 ENGINE - PRESSURE P3 TRANSDUCER							Component ATA:75
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-03, EMM 75-30-03PROC. REF: EMM 75-30-03, EMM 75-30-03								
754001	NO. 2 ENGINE - PRESSURE P3 TRANSDUCER							Component ATA:75
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-03, EMM 75-30-03PROC. REF: EMM 75-30-03, EMM 75-30-03								
ATA 76 - ENGINE CONTROLS								
761001	THROTTLE/THRUST REVERSER QUADRANT ASSEMBLY							Component ATA:76
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01								
761003	LEFT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER							Component ATA:76
PN:3A2-244	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02								
761004	RIGHT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER							Component ATA:76
PN:3A2-245	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02								
761101	NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS							Component ATA:76
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
761101	NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNESS							Component ATA:76
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761103	NO. 1 ENGINE - FADEC, ENGINE HARNESS							Component ATA:76
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761103	NO. 2 ENGINE - FADEC, ENGINE HARNESS							Component ATA:76
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761105	NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761105	NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761107	NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
761107	NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761201	ENGINE FADEC SLAVE/MASTER SWITCH							Component ATA:76
PN:64AT11-3D	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-12-01PROC. REF: AMM 76-12-01								
E7614000 ^S	FUNCTIONAL TEST OF APR (AUTOMATIC PERFORMANCE RESERVE) SYSTEM. (REFER TO 76-14-00)							Service ATA:76
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
PROC. REF: AMM 76-14-00PROC. REF: AMM 76-14-00								
H7611007 ^S	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS FOR SECURITY AND GENERAL CONDITION. REMOVAL OF UPPER COWLING IS REQUIRED FOR THIS INSPECTION. (REFER TO 5-10-00)							Service ATA:76
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
J7611006 ^S	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS FOR SECURITY AND GENERAL CONDITION, INCLUDING THE SHIELDED HARNESSES ROUTED TO THE FADEC MAINTENANCE PANEL. PAY PARTICULAR ATTENTION TO SIGNS OF CHAFING AGAINST STRUCTURE ADJACENT TO ELECTRICAL BONDING CLAMP LOCATIONS. (							Service ATA:76
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771001	LEFT ENGINE N1 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-10-01PROC. REF: AMM 77-10-01								
771001	NO. 1 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS							Service ATA:77
	MOS	14-Jun-11						DISCARD
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771001	NO. 2 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS							Service ATA:77
	MOS	29-May-11						DISCARD
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771002	RIGHT ENGINE N1 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-10-01PROC. REF: AMM 77-10-01								
771003	LEFT ENGINE N2 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-10-02PROC. REF: AMM 77-10-02								
771004	RIGHT ENGINE N2 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
PROC. REF: AMM 77-10-02PROC. REF: AMM 77-10-02								
771011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS							Service ATA:77
	MOS	14-Jun-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS							Service ATA:77
	MOS	29-May-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771012	LEFT DATA CONCENTRATOR (DCU) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771012	RIGHT DATA CONCENTRATOR (DCU) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771014	LEFT ENGINE DATA CONCENTRATOR (EDC) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771014	RIGHT ENGINE DATA CONCENTRATOR (EDC) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771027	NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	14-Jun-11	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771027	NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	29-May-11	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771028	NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	14-Jun-11	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771028	NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	29-May-11	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771040	NO. 1 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771040	NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771041	NO. 1 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771041	NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
772001	LEFT ENGINE ITT INDICATOR							Component ATA:77
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-20-01PROC. REF: AMM 77-20-01								
772002	RIGHT ENGINE ITT INDICATOR							Component ATA:77
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-20-01PROC. REF: AMM 77-20-01								
772010	NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNESS							Component ATA:77
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
772010	NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNESS							Component ATA:77
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
772013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
772014	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02								
772014	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02								
772015	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02								
772015	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 77 - ENGINE INDICATING									
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02									
772021	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX							Service	ATA:77
PN:PN	MOS	14-Jun-11							
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)		
	ENC	0							
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01									
772021	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX							Service	ATA:77
PN:PN	MOS	29-May-11							
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)		
	ENC	0							
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01									
772022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS							Service	ATA:77
PN:PN	MOS	14-Jun-11							
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)		
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
772022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS							Service	ATA:77
PN:PN	MOS	29-May-11							
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)		
	ENC	0							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
774001	ENGINE DIAGNOSTIC UNIT							Component	ATA:77
PN:9-361-06	MOS/MSC	25-Apr-25	O/C	TSN 321, TSR 1					
SN:F6	HRS	3222.8		TSR 0					
	AFL	2317		TSR 0					
PROC. REF: AMM 77-40-01PROC. REF: AMM 77-40-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
774001A ^U	REPLACE ENGINE DIAGNOSTIC UNIT INTERNAL BATTERY							Service ATA:77
PN:9-361-06	MOS/MSC	25-Apr-25	36 / DUE		25-Apr-28		1071 d	REPLACE
SN:F6	HRS	3222.8						
	AFL	2317						
774002	CONTROL AND DISPLAY (CDU) UNIT							Component ATA:77
PN:9-362-03	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C308	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-02PROC. REF: AMM 77-40-02								
774003	LEFT ENGINE ISOLATION INTERFACE UNIT							Component ATA:77
PN:9-343-04	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C564	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-03PROC. REF: AMM 77-40-03								
774004	RIGHT ENGINE ISOLATION INTERFACE UNIT							Component ATA:77
PN:9-343-04	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:C559	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-03PROC. REF: AMM 77-40-03								
774101	SIGNAL CONDITIONING BOX							Component ATA:77
PN:251-502-000-202	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:AF49904	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01								
774103	LEFT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:CE569VM301	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2075	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
774104	RIGHT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:CE569VM301	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:2053	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								
ATA 78 - EXHAUST								
780001	LEFT THRUST REVERSER							Component ATA:78
PN:282-0052-519	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0107-201	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-05PROC. REF: AMM 78-30-05								
780002	RIGHT THRUST REVERSER							Component ATA:78
PN:282-0052-521	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:LR0107-251	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-05PROC. REF: AMM 78-30-05								
783001	LEFT THRUST REVERSER RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-01PROC. REF: AMM 78-30-01								
783002	RIGHT THRUST REVERSER RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-01PROC. REF: AMM 78-30-01								
783005	LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT							Component ATA:78
PN:282D0007-507	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0905	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-03PROC. REF: AMM 78-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783006	RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT							Component ATA:78
PN:282D0007-507	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:0903	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-03PROC. REF: AMM 78-30-03								
783008	HYDRAULIC CONTROL RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-06PROC. REF: AMM 78-30-06								
783009	THRUST REVERSER INTERFACE BOX							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-07PROC. REF: AMM 78-30-07								
783013	LEFT ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
783014	RIGHT ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
783015	LEFT ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783016	RIGHT ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
783025	LEFT ENGINE THRUST REVERSER SWITCH CABLE							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25PROC. REF: AMM 78-30-25								
783026	RIGHT ENGINE THRUST REVERSER SWITCH CABLE							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25PROC. REF: AMM 78-30-25								
783105	LEFT OUTBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1785R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								
783106	LEFT INBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1784R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								
783107	RIGHT INBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1790R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783108	RIGHT OUTBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:282D0006-501	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1791R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								
783115	LEFT UPPER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:266D0486-507	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1995	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								
783116	RIGHT UPPER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:266D0486-507	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1987	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								
783117	LEFT LOWER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:266D0486-507	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1996	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								
783118	RIGHT LOWER SECONDARY LOCK ACTUATOR							Component ATA:78
PN:266D0486-507	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:1989	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								
783132	LEFT OUTBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783132A ^U	INSPECT LEFT OUTBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D							Service ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783136	RIGHT OUTBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783136A ^U	INSPECT RIGHT OUTBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D							Service ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783142	LEFT INBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783142A ^U	INSPECT LEFT INBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D							Service ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783146	RIGHT INBOARD STANG FAIRING ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783146A ^U	INSPECT RIGHT INBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D							Service ATA:78
PN:PN	MOS/MSC	01-Mar-12	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
E7830038 ^S	DETAILED INSPECTION THRUST REVERSERS FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 78-30-00.)							Service ATA:78
	MOS	04-Apr-25	48 (+14d/-14d)					
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:15
PROC. REF: AMM 78-30-00PROC. REF: AMM 78-30-00								
M7830084 ^S	INSPECT THRUST REVERSER SECONDARY LATCH - LUBRICATE LATCH SWITCH PLUNGERS, ROLLER ASSEMBLY, AND ACTUATOR PINS. (REFER TO 12-21-04)							Service ATA:78
	MOS	04-Apr-25	12					
	HRS	3222.8	300					
	AFL	2317						
								PKG:3
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								
T7830014 ^S	VISUAL INSPECTION OF THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION. (REFER TO 5-10-00)							Service ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830016 ^S	VISUAL INSPECTION OF THRUST REVERSER ACTUATOR FOR HYDRAULIC LEAKS, DAMAGED PUSHROD, DAMAGED FLEXIBLE HOSES, AND SECURITY OF INSTALLATION. (REFER TO 5-10-00)							Service ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
T7830018 ^S	VISUAL INSPECTION OF HYDRAULIC CONTROL UNITS, PRESSURE SWITCH, CHECK VALVES, AND HYDRAULIC LINES FOR LEAKAGE, CLEANLINESS, SECURITY OF INSTALLATION, AND CONDITION OF ECLECTRICAL COMPONENTS. (REFER TO 5-10-00)						Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T7830020 ^S	VISUAL INSPECTION OF STOW AND DEPLOY SWITCHES FOR SECURITY OF INSTALLATION AND CONDITION OF ELECTRICAL COMPONENTS. VISUALLY INSPECT SHIELDED ELECTRICAL THRUST REVERSER HARNESS FOR CONDITION. (REFER TO 5-10-00)						Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T7830026 ^S	VISUAL INSPECTION OF THRUST REVERSER DRIVER LINKS(EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT.) INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)						Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T7830028 ^S	VISUAL INSPECTION OF THRUST REVERSER OVERCENTER LINK (EIGHT PER AIRCRAFT) AND OVERCENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)						Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T7830030 ^S	VISUAL INSPECTION OF THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATI						Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830032	^S	VISUAL INSPECTION OF THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS. (REFER TO 5-10-00)					Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830034	^S	VISUAL INSPECTION OF THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS. (REFER TO 5-10-00)					Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830039	^S	VISUAL INSPECTION OF FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 5-10-00)					Service	ATA:78
	MOS	04-Apr-25	24 (+14d/-14d)					
	HRS	3222.8	600 (+25/-25)					
	AFL	2317						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830085	^S	FUNCTIONAL TEST ** OF THE THRUST REVERSER WITH WHEEL SPEED DETECT INTERFACE. (REFER TO 78-30-00.) (AWL**)					Service	ATA:78
	MOS	04-Apr-25	48 (+14d/-14d)	Adj -29d				
	HRS	3222.8	1200 (+25/-25)					
	AFL	2317						
								PKG:15
PROC. REF: AMM 78-30-00PROC. REF: AMM 78-30-00								
U7830010A	^S	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION					Service	ATA:78
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
								PKG:29

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U7830010B ^S	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION							Service ATA:78
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
								PKG:30
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U7830012A ^S	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE							Service ATA:78
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
								PKG:29
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U7830012B ^S	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE							Service ATA:78
	MOS	01-Mar-12						
	HRS	0	3600 (+50)					
	AFL	0						
								PKG:30
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 79 - OIL								
05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT							Service ATA:79
	MOS	04-Apr-25	12		04-Apr-26		319 d	
	HRS	3222.8	1200 (+25/-25)		(4422.8) 4422.8	4447.8	1198.9 (+25)	
	ENC	2317						
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT							Service ATA:79
	MOS	04-Apr-25	12		04-Apr-26		319 d	
	HRS	3222.8	1200 (+25/-25)		(4422.8) 4422.8	4447.8	1198.9 (+25)	
	ENC	2317						
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE							Service ATA:79
	MOS	04-Apr-25	12		04-Apr-26		319 d	
	HRS	3222.8	600 (+50/-50)		(3822.8) 3822.8	3872.8	598.9 (+50)	
	ENC	2317						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE							Service ATA:79
	MOS	04-Apr-25	12		04-Apr-26		319 d	
	HRS	3222.8	600 (+50/-50)		(3822.8) 3822.8	3872.8	598.9 (+50)	
	ENC	2317						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
792001	NO. 1 ENGINE - OIL PUMP							Component ATA:79
PN:30B6825-01	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:EC01A003A257	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								
792001	NO. 2 ENGINE - OIL PUMP							Component ATA:79
PN:30B6825-01	MOS/MSC	29-May-11	O/C	TSN 0				
SN:EC01A003A234	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792002	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER							Component ATA:79
PN:31B5790-02	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:2858	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
792002	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER							Component ATA:79
PN:31B5790-02	MOS/MSC	29-May-11	O/C	TSN 0				
SN:2863	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
792005	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH							Component ATA:79
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
792005	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH							Component ATA:79
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
792010	NO. 1 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH							Component ATA:79
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792010	NO. 2 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH							Component ATA:79
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH							Service ATA:79
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH							Service ATA:79
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792012	NO. 1 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER							Service ATA:79
PN:31B5790-02	MOS	14-Jun-11						
SN:2858	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792012	NO. 2 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER							Service ATA:79
PN:31B5790-02	MOS	29-May-11						
SN:2863	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792020	NO. 1 ENGINE - OIL PUMP HOUSING							Component ATA:79
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792020	NO. 2 ENGINE - OIL PUMP HOUSING							Component ATA:79
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								
792035	NO. 1 ENGINE - OIL FILTER BYPASS SWITCH							Component ATA:79
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792035	NO. 2 ENGINE - OIL FILTER BYPASS SWITCH							Component ATA:79
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
793001	LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01								
793001	NO. 1 ENGINE - DISCARD - CHIP DETECTOR							Service ATA:79
	MOS	28-Mar-22						DISCARD
	HRS	2973.4	7200 (+50)		(10173.4) 10173.4	10223.4	6949.5 (+50)	
	ENC	2090						
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793001	NO. 2 ENGINE - DISCARD - CHIP DETECTOR							Service ATA:79
	MOS	29-May-11						DISCARD
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793002	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH							Service ATA:79
	MOS	14-Jun-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-02PROC. REF: EMM 79-30-02								
793002	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH							Service ATA:79
	MOS	29-May-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-02PROC. REF: EMM 79-30-02								
793002	RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:PN	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01								
793003	LEFT ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:APTE-250L-1000-225D	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7887-10-138	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02								
793003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP							Service ATA:79
	MOS	14-Jun-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP							Service ATA:79
	MOS	29-May-11						
	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								
793004	RIGHT ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:APTE-250L-1000-225D	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:7887-10-146	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02								
793005	NO. 1 ENGINE - CHIP DETECTOR							Component ATA:79
PN:30B3756-02	MOS/MSC	28-Mar-22	O/C					REPLACE
SN:UNKNOWN	HRS	2973.4						
	ENC	2090						
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793005	NO. 2 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				REPLACE
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793010	LEFT ENGINE OIL TEMPERATURE BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W6136	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								
793011	RIGHT ENGINE OIL TEMPERATURE BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:W6137	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)							Service ATA:79
PN:PN	MOS	14-Jun-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
793013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)							Service ATA:79
PN:PN	MOS	29-May-11						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	3976.1 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
793030	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	14-Jun-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								
793030	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	29-May-11	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: LEARJET 60XR Serial: 60 410 RegNo: N824LM HRS: 3223.9 AFL: 2319 As Of: 01-May-2025

20-May-2025 10:19 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 80 - STARTING								
801001	CROSS START RELAY BOX							Component ATA:80
PN:6018421-1	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 80-10-01PROC. REF: AMM 80-10-01								
801002	AIR START RELAY BOX							Component ATA:80
PN:6018358-2	MOS/MSC	01-Mar-12	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 80-10-02PROC. REF: AMM 80-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task